



**Halton Basement Flooding Analysis**

Draft Rehabilitation List  
 Figure 2  
 Priority Areas 6 and 7

	Priority Areas
	Sanitary Sewers
<b>Recommended Works</b>	
	Full Length Open Cut Replacement
	Full Length Trenchless Lining
	Trenchless Spot Repair

0 500 m

