Report

Phase One Environmental Site Assessment

441 Maple Avenue, Burlington, Ontario

Project No. 0025-001.01
January 9, 2019

Prepared for:

Better Life Retirement Residence Inc.
768 Highland Blade Road
Newmarket, ON, L3X 1P3

Prepared by:

BlueFrog
Environmental Consulting Inc.
Suite 156 - 700 Third Line,
Oakville, ON, L6L 4B1
416.407.9769

1.0 Executive Summary

BlueFrog Environmental Consulting Inc. (BlueFrog) was retained by Better Life Retirement Residence Inc. (Client) to complete a Phase One Environmental Site Assessment (ESA) of the phase one property located at 441 Maple Avenue, Burlington, Ontario (hereinafter referred to as the Site).

This ESA was completed in accordance with Ontario Regulation 153/04, Records of Site Condition – Part XV.1 of the Environmental Protection Act, as amended, which is administered by the Ontario Ministry of the Environment and Climate Change (MOECC).

We understand the work is being conducted in support of property redevelopment. The current land use of the property is residential/parkland/institutional, and the future intended land use is residential/parkland/institutional; as such, with no intended change of land use, a Record of Site Condition (RSC) would not be required in accordance with Ontario Regulation 153/04.

The objective of the ESA was to: identify potentially contaminating activities (PCAs) at the Site and in the phase one study area that may have impacted soil and groundwater at the Site; and identify areas of potential environmental concern (APECs) at the Site and associated potential contaminants of concern (PCOCs) caused by the PCAs.

The assessment comprised a review of historical information pertaining to the Site and phase one study area, interviews with Site representative(s) and regulatory personnel where available, a Site visit, and preparation of this report that documents the findings.

This Work performed was approved by email dated November 24, 2018. This Report has been prepared by BlueFrog, based on fieldwork conducted by BlueFrog, for the sole benefit and use by Better Life Retirement Residence Inc. In performing this Work, BlueFrog has relied in good faith on information provided by others and has assumed that the information provided by those individuals is both complete and accurate. This Work was performed to current industry standard practice for similar environmental work, within the relevant jurisdiction and same locale. The findings presented herein should be considered within the context of the scope of work; further, they are considered valid only at the time the Report was produced.

This Executive Summary is not intended to be a stand-alone document, but a summary of findings as described in the following Report. It is intended to be used in conjunction with the scope of services and limitations described therein.

Findings

The Site is approximately 0.28 hectares located in a predominately residential area of Burlington about 80 metres north on Lakeshore Blvd. and 200 metres north of Lake Ontario. The resident properties in the area include a variety of single and multi unit properties. Some commercial buildings are located to the east, on the east Side of Brock Ave, (Brock Street is parallel to Maple one block to the east).

The Site building was constructed in 1969 (originally as a motel); additions were constructed in 1978 and in 1995. The building is two stories with a partial basement and crawlspace having a current building footprint of

approximately 1400 m2. The building has been occupied by Maple Villa Long Term Care Centre since 1972. Prior to 1969, the Site was likely used for residential and/or agricultural land.

Potential Environmental Concerns

The following PCAs were identified from the records review and the Site which may be contributing to on-Site Areas of Potential Environmental Concern:

On-Site

- A fuel oil UST was formerly located near the southwest corner of the building. The UST was removed in 1992 and was reportedly intact with no apparent leakage.
- A hydraulic elevator was located on-Site, based on the interviews and Site observations, hydraulic oil leaks have occurred.
- A pad mounted transformer was located near the northwest corner of the Site. There was no evidence of staining in the area of the transformer and it is unlikely to have contributed to an APEC at the Site.

Off-Site (phase one study area)

- A railway line was formerly located adjacent to the Site (from prior to 1910 to the late 1900s), the area of the railway line is now a parking area, located to the east of the Site and is leased by Maple Villa Long Term Care Centre.

Other PCAs (if any) that have occurred within the phase one study area are not considered to be contributing to an APEC, based on the distance from the phase one property, absent contaminant pathways, the direction of local groundwater flow, and mobility and/or persistence of the associated potential contaminants of concern

Discussion

According to O. Reg. 153, a RSC is not required at this time.

Based on the 2018 groundwater assessment at the Site, there were no MECP Table 3 groundwater exceedances in the Site samples collected from three monitoring wells located near the perimeter of the Site that may suggest an environmental issue.

Based on the groundwater data, the above discussed potential environmental concerns (former fuel oil UST, the hydraulic elevator, or former adjacent railway) are likely limited minor localized impacted areas (if any). It is understood that the development plans for the Site include three levels of underground parking, so any impacted areas would be addressed at that time.

Designated substances may be present in on-Site building materials. If present, designated substances can pose potential health concerns to building occupants. If renovation or demolition of the building is planned, designated substances should be managed in accordance with applicable regulations.

Table of Contents

1.0 Executive Summary i

2.0 Introduction and Objectives 5

2.1 Phase One Property Information 5

3.0 Scope of Investigation 6

4.0 Records Review 6

4.1 General 6

4.1.1 Phase One Study Area Determination 6

4.1.2 First Developed Land Use 6

4.1.3 Fire Insurance Plans 6

4.1.4 Chain of Title 7

4.1.5 Environmental Reports 7

4.2 Environmental Source Information 8

4.2.1 Freedom of Information Request 8

4.2.2 Regulatory Information 9

4.3 Physical Setting Sources 9

4.3.1 Aerial Photographs 9

4.3.2 Topography, Hydrogeology, and Geology 10

4.3.3 Fill Materials 10

4.3.4 Water Bodies and Areas of Natural Significance 10

4.3.5 Well Records 11

4.4 Site Operating Records 11

5.0 Interviews 11

6.0 Site Reconnaissance 12

6.1 General Requirements 12

6.2 Specific Observations at the Phase One Property 12

6.2.1 Investigation of Structures 12

6.2.2 Surface Features 14

6.2.3 Utilities 15

6.2.4 Enhanced Investigation Property 15

6.3 Investigation of the Phase One Study Area 16

6.4 Written Description of the Investigation 16

7.0 Review and Evaluation of Information 17

7.1 Current and Past Uses 17

7.2 Potentially Contaminating Activity 17

7.3 Areas of Potential Environmental Concern 18
7.4 Phase I ESA Conceptual Site Model 18

8.0 Conclusions 20
8.1 Whether Phase Two is Required Before RSC Submitted 20
8.2 RSC Based on Phase One ESA Alone 20
8.3 Signatures 20

9.0 References 21

Tables (within text)

Table 1 Site Information 6
Table 2 Aerial Photographs 9
Table 3 Topographic Details 10
Table 4 Water Bodies and Areas of Natural Significance 10
Table 5 Site Visit Details 12
Table 6 Observations of On-Site Building(s) / Structure(s) 13
Table 7 Assessment of Special Attention Items On-Site 14
Table 8 Surface Features Observed at the Site 14
Table 9 Details of Utilities 15
Table 10 Details of Enhanced Investigation 15
Table 11 Current and Past Uses 17
Table 12 Areas of Potential Environmental Concern 18

Figures

Figure 1 Site Location and Regional Topography
Figure 2 Site Plan and Surrounding Land Use
Figure 3 Phase One Conceptual Site Model

Appendices

Appendix A Site and/or Survey Plans
Appendix B Mapping
Appendix C Site Photographs
Appendix D Aerial Photographs
Appendix E Historical Records

2.0 Introduction and Objectives

BlueFrog Environmental Consulting Inc. (BlueFrog) was retained by Better Life Retirement Residence Inc. to complete a Phase One Environmental Site Assessment (ESA) of the phase one property located at 441 Maple Avenue, Burlington, Ontario (hereinafter referred to as the Site).

We understand the work is being conducted in support of property redevelopment. The current land use of the property is residential/parkland/institutional and the future intended land use is residential/parkland/institutional; as such, with no intended change of land use, a Record of Site Condition would not be required in accordance with Ontario Regulation 153/04.

The objective of the ESA was to: identify potentially contaminating activities (PCAs) at the Site and in the phase one study area that may have impacted soil and groundwater at the Site; and, identify areas of potential environmental concern (APECs) at the Site and associated potential contaminants of concern (PCOCs) caused by the PCAs.

The assessment comprised a review of historical information pertaining to the Site and phase one study area, interviews with Site representative(s) and regulatory personnel where available, a Site visit, and preparation of this report that documents the findings.

This Work performed was approved by email dated November 24, 2018. This Report has been prepared by BlueFrog, based on fieldwork conducted by BlueFrog, for the sole benefit and use by Better Life Retirement Residence Inc. In performing this Work, BlueFrog has relied in good faith on information provided by others and has assumed that the information provided by those individuals is both complete and accurate. This Work was performed to current industry standard practice for similar environmental work, within the relevant jurisdiction and same locale. The findings presented herein should be considered within the context of the scope of work; further, they are considered valid only at the time the Report was produced.

2.1 Phase One Property Information

The Site is approximately 0.28 hectares in size consisting of a two-storey building occupied by Maple Villa Long Term Care Centre. The building was originally constructed in 1969 with building additions constructed in 1978 and 1995, having a total building footprint of approximately 1400 m^2. The area east of the building is used by Maple Villa Long Term Care Centre for parking and domestic waste storage, however, is leased and not considered part of the Site.

A current plan of survey prepared and signed by an Ontario Land Surveyor, and Site plans are provided in **Appendix A.**

The regional topography and Site location are shown on **Figure 1** and on the Ontario Base Map included in **Appendix B**.

Key aspects of the Site were documented by photographs and are included in **Appendix C**.

Aerial photographs are reproduced in **Appendix D**.

Specific details of the Site information are provided in the table below.

Table 1 Site Information

Item	Comments
Municipal address	441 Maple Avenue, Burlington, Ontario
Property identification number (PIN)	07083-0059(LT)
Legal Description	Part of Lots 64, 65, 66, 67, 77 & 78 Registered Plan 65 Being in the City of Burlington, Regional Municipality of Halton.
Owner Contact Information	2435481 Ontario Inc.
ESA prepared for	Better Life Retirement Residence Inc., 768 Highland Blade Road, Newmarket, ON, L3X 1P3

3.0 Scope of Investigation

This ESA was completed in accordance with Ontario Regulation 153/04, Records of Site Condition – Part XV.1 of the Environmental Protection Act, as amended, administered by the Ontario Ministry of the Environment and Climate Change (MOECC), and involved the following main activities:

- Conducting a review of historical information pertaining to the Site and phase one study area;
- Conducting interviews with available persons having knowledge of the Site;
- Conducting a Site visit to make specific observations at the Site and, from publicly accessible areas the phase one study area;
- Reviewing and evaluating the information; and
- Preparing this report documenting the activities, findings, and conclusions of the phase one ESA.

4.0 Records Review

4.1 General

4.1.1 Phase One Study Area Determination

The phase one study area was comprised of the phase one property and all properties located wholly or partly within 250 m of the boundary of the phase one property. Based on the identified contaminants of concern (if any) and geologic and hydrogeological features in the area, properties located greater than 250 m from the boundary of the phase one property were not included in the phase one study area.

4.1.2 First Developed Land Use

The first developed land use of the Site (i.e. the presence of a building/structure or occurrence of a PCA) based on the records reviewed, was in the 1930s.

4.1.3 Fire Insurance Plans

Fire insurance records were requested from Environmental Risk Information Services (ERIS) and was searched by Enviroscan Opta Information Intelligence; a copy of the findings has been included in **Appendix E**.

Fire Insurance plans were obtained from 1910, 1932, and 1971. An insurance inspection reports was obtained from 1987. In summary:

- In 1910, Maple Avenue was present and was formerly called Hamilton Road or Sand Road. There were no buildings present on the Site. The Site address was not provided however the property to the south was number 90. Buildings were present to the north and south, however, the use of was not described. The grand trunk railway was located adjacent to the east of the site.
- In 1932, there were no buildings present on the Site. The Site address was not provided however the property to the north was 12 Maple Avenue. The area appeared to be residentially developed, a lumber mill was located approximately 250 meters north of the site.
- In 1971, the Site was described as 441 Maple Avenue. A building was located on the Site that and was described as a nursing home (this was consistent southern portion of the current day building). Adjacent properties where apartment buildings to the north and south and a railway to the east.
- The 1987 inspection report indicated the building was two-story occupied by a nursing home. Constructed in 1960/7 and the building was heated by gas fired hot water.

The *Catalogue of Canadian Fire Insurance Plans 1875-1975* (Dubrieul, L. and Woods, C., 2002) was referred and identified plans located in various libraries for the City of Burlington (which may include the Site) dated between 1904 and 1971. Fire insurance plans for all parts of the phase one property were obtained and reviewed.

4.1.4 Chain of Title

A chain of title detailing names and dates of owners from the first developed last use to present was completed by Domson's Title search Inc. and is included with a current deed in **Appendix E**. Leases and easements registered to the title were also searched. The information is detailed in Section 6.1 Current and Past Uses, in summary:

- 2435481 Ontario Inc. has been the owner of the since 2015.
- The Site was owned by various private individuals from 1798 to 2015. Ownership also included Simson Construction Limited (1962 to 1970) and various holding companies (1994 to 2015).

City directory information was requested from ERIS for the Site and certain neighbouring properties. A copy of the directory is provided in **Appendix E**. In summary:

- The period 1957 to 2011 was assessed by reviewing directory entries approximately every 5 years in that period.
- The Site was first listed in 1965 Maple Villa Hotel and was listed as Maple Villa Nursing Home/Long Term Care Center between 1975 and 2011.
- Historical uses of neighbouring properties searched were residential.

4.1.5 Environmental Reports

The following previous environmental reports were available for review and are summarized as follows.

- *Phase I Environmental Assessment, 441 Maple Avenue, Burlington, Ontario,* prepared by Trow Consulting Engineers Ltd. for Maple Villa Nursing Home, dated April 29, 1994.
    - The report was prepared by Trow Consulting Engineers Ltd (Trow) dated April 29, 1994. The report identified the former fuel oil UST as an environmental concern and potential issues with

asbestos, leaded paint, PCBs in electrical fixtures due to the age of the Site building. No other issues of concern were identified by Trow in their report.

- *Letter Correspondence from Trow to CMHC Re: Phase I Environmental Assessment, 441 Maple Avenue, Burlington, Ontario,* dated April 25, 1995.
    - Based on Trow's letter, the fuel oil UST was removed by MacKenzie Excavation in November 1992. MacKenzie reported the tank was intact with no apparent leakage. Consequently, environmental testing was not recommended by Trow.
- *Geotechnical Investigation and Engineering Design Report, 441 Maple Avenue, Burlington, Ontario,* prepared by Terraprobe for Mr. Sam Badawi, dated December 18, 2017.
    - Four boreholes were drilled, one advanced to a depth or 17.3 metres below grade and the other three to a maximum depth of 6.7 mbgs, terminating in shale.
    - Groundwater was measured in the monitoring wells between 3.7 mbgs and 3.9 mbgs. A Site-specific groundwater flow direction was not determined, however since Lake Ontario is located to eh south east, groundwater flow is considered to be to the southeast.
    - The stratigraphy encountered was fill overlying silt which extended to the shale located about 3 m below grade.
    - A copy of Terraprobe's Site plan detailing the locations of the monitoring wells is included in Appendix A.
- *Groundwater Sampling, 441 Maple Avenue, Burlington, Ontario,* prepared by BlueFrog for Better Life Retirement Residence Inc., dated December 28, 2017.
    - Three existing monitoring wells on Site were sampled, one was understood to be located downgradient of the area where the former fuel oil UST was located. Prior to sampling each monitoring well was developed by removing three well volumes of groundwater or until the monitoring wells were considered dry. Once the groundwater in the monitoring wells had recharged the groundwater in the monitoring wells was samples and submitted to Maxxam Analytical for analysis. The samples were analysed for benzene, toluene, ethylbenzene, xylene (BTEX) and petroleum hydrocarbons (PHCs)-fractions F1 to F4. The results were compared to Ministry of Environment Conservation and Parks (MECP) O. Reg. 153/04 Table 3 standards; there were no exceedances to the standards in the three groundwater samples submitted for analyse for the Site.

4.2 Environmental Source Information

4.2.1 Freedom of Information Request

During a 1994 Phase I ESA Assessment for the Site, information was requested from the Ontario Ministry of Environment and Energy and the Ontario Ministry of Commercial Relations (Fuels Safety Branch); no records were found.

A formal request for reports was made to the MOECC through a Freedom of Information and Protection Act (FOI) search. A reply from the MOECC has not yet been received. If information received is found to affect the findings of this report, the information will be presented under a separate cover.

4.2.2 Regulatory Information

An ERIS EcoLog Database Report was obtained that includes regulatory information from provincial, federal, and private database entries (including those relevant to documents listed in O. Reg. 153/04, Schedule D, 3.(2)7) pertaining to the Site and phase one study area. The EcoLog Database Report including a description of the databases searched and records found, is provided in **Appendix E.** Pertinent details are summarized below.

- There are no records found for the site.
- Sigmund Publishing Ltd., located 40 m east of the Site at 431 Brock Road, was a publishing and printing company established in 1953.

Other activities that may have been identified at the neighbouring properties are not considered to have contributed to potential contamination at the Site, based on the distance from the Site, absent contaminant pathways, the direction of local groundwater flow, and mobility and/or persistence of the associated potential contaminants of concern.

4.3 Physical Setting Sources

4.3.1 Aerial Photographs

Aerial photographs obtained from National Air Photo Library are reproduced in **Appendix C**. A summary of the review is provided in the table below. General features were noted with respect to land uses, structures, drainage, disturbed soil, and possible evidence of environmental concerns. The scale and attendant resolution of the photographs typically did not permit detailed study of the Site and neighbouring properties.

Table 2 Aerial Photographs

Year	Site	Surrounding Properties
1931	The Site appears to be undeveloped or agricultural land.	Maple Avenue was located adjacent to the east beyond which was agricultural and residential properties. Adjacent properties were residential to the north and south, and a railway line to the east, beyond which was Brock avenue and residential properties.
1950	The site is tree-covered, a building, likely a residence, was located at the site.	Additional residential development was present, an industrial property (possibly a lumberyard) was located 120 m north of the Site.
1965	The original motel building was present at the Site.	Apartment buildings were located on the adjacent properties to the north and south.
1974	Similar to 1965	Similar to 1965
1986	An addition was constructed to the north of the on-Site building.	Additional residential apartment development and commercial development was present to the east of Brock Road
2005	Similar to 1986.	The railway line previously identified adjacent to the Site was no longer present. The area was now utilized as a parking area for the Site.
2018	Similar to 2005.	Similar to 2005.

4.3.2 Topography, Hydrogeology, and Geology

The Table below summarizes the information obtained from regional topographic (Ontario Base Map series, see **Figure 1**), geological, and soil maps. This information can assist in approximating groundwater flow directions that can influence the migration of possible contaminants in the vicinity of the Site. The records reviewed revealed the following topographic, geologic and hydrogeological information:

Table 3 Topographic Details

Feature	Comments
Elevation	Approximately 85 meters above sea level.
Nearest surface water body	Lake Ontario, located 180 m southeast of the Site.
Interpreted groundwater flow direction	Groundwater flow direction is inferred to be southeast, towards Lake Ontario. Site-specific hydrogeological information is not known other than the depth to groundwater (Previous Reports Section 3.1.5) was measured at depths ranging from 3.7 m bgs to 3.9 m bgs).
Surficial soils	Surficial soils in the area are described as Lacustrine deposits: sand, gravelly sand and gravel nearshore and beach deposits. (Ontario Geological Survey, Quaternary Geology). Site-specific soil stratigraphy information (Previous Reports Section 3.1.5) is fill overlying silt which extended to the shale located about 3 m below grade.
Bedrock	The bedrock in the area is described as: shale, limestone, dolostone, and siltstone (Ontario Geological Survey, Bedrock Geology of Ontario). Site-specific bedrock stratigraphy Site-specific soil stratigraphy information (Previous Reports Section 3.1.5) encountered shale bedrock at approximately 3 m below grade.

4.3.3 Fill Materials

There was no evidence of disturbed soil or fill materials located on the Site.

4.3.4 Water Bodies and Areas of Natural Significance

The following documents were reviewed in order to identify water bodies and areas of natural significance within the phase one study area were; the results of their review are summarized in the table below:

- Topographic Maps;
- The Ministry of Natural Resources, interactive map of natural heritage areas (included in **Appendix B**);
- The official plan and/or zoning maps for the local municipality;
- The Niagara Escarpment Planning and Development Act; and
- The Oak Ridges Moraine Conservation Act.

Table 4 Water Bodies and Areas of Natural Significance

Feature	Comments
Waterbodies	Lake Ontario, located 180 m southeast
Provincial parks	None identified.
Conservation reserves	None identified.

Areas of natural and scientific interest	None identified.
Provincially significant wetlands	None identified.
Significant habitat of threatened or endangered species	None identified.
Wilderness areas	None identified.
Municipal environmentally significant areas	None identified.
Niagara Escarpment natural or protection area	None identified.
Oak Ridges Moraine natural core or natural linkage area	None identified.
Municipal environmentally significant areas	None identified.
Niagara Escarpment natural or protection area	None identified.
Oak Ridges Moraine natural core or natural linkage area	None identified.

4.3.5 Well Records

The MOECC Water Well Information System (WWIS) was searched by EcoLog. EcoLog also searched for well records submitted under the Oil, Gas and Salt Resources Act. The search results for the phase one study area are provided in Appendix C and are summarized below:

- A total of two well records were identified.
- The well locations are provided in the EcoLog report as Universal Transverse Mercator (UTM) coordinates.
- The overburden encountered in the wells varied and included fill overlying clay.
- The bedrock was predominantly shale, and initially encountered at depths ranging from 2.4 mbgs to 3.4 mbgs.
- The depth to the static water level after drilling (which may not be the water table) was not indicated.

4.4 Site Operating Records

The Site is not an enhanced investigation (i.e. has never been used in whole or in part for: an industrial use, as a garage, as a bulk liquid dispensing facility, including a gasoline outlet, or for the operation of dry cleaning equipment); as such, a review of Site operating records was not applicable to this assessment.

5.0 Interviews

An interview was conducted with Barb Goetz, Administrator of Maple Villa Long Term Care Center, who has been familiar with the Site for 32 years. Pertinent information obtained from the interview is as follows:

- The building was constructed in 1969; additions were constructed in 1978 and in 1995. The building is two stories with a partial basement and crawlspace.
- The Building has been used as a long term care facility since 1972, previous to that it was used as a motel.
- The building is heated by natural gas fired, hot water radiant heat. Boilers are located in the rooftop utility room.

- A diesel backup generator is located in the rooftop utility room.
- The building was formerly heated by fuel oil, boilers were located in the basement. The fuel oil UST was removed in 1992. The fuel oil tank was located near the southwest corner of the building. It is likely the tank was located between the building and Maple Avenue; when the tank was removed, there was no disturbance or repair to the asphalt.
- The building is cooled by roof top units, ceiling units in corridors, incremental units, and two wall units.
- The building has two elevators, one of which is a hydraulic elevator which was found to be leaking in 2014, and was repaired.

A comparison of the reviewed records to the information obtained from the interviews resulted in no discrepancies that would affect the findings of this phase one ESA. The information obtained from the interviews is generally considered to be valid.

6.0 Site Reconnaissance

6.1 General Requirements

A visual survey of the Site was completed by a BlueFrog representative, supervised by the undersigned QP.

Neighbouring properties and the phase one ESA study area were observed from publicly accessible sidewalks and roadways. Preliminary information obtained from the records review was considered prior to conducting the Site visit.

Photographs showing various areas of the Site and neighbouring properties documenting APECs, relevant structures, and areas of disturbed soil, etc., if any, including written descriptions for each are provided in **Appendix B**.

A summary of the Site visit details is provided in the following table.

Table 5 Site Visit Details

Item	Comments
Site Visit Date/ length of assessment	December 5, 2018 / two hours
Site description and use	The Site is occupied by Maple Villa Long Term Care Centre.
Weather conditions	Sunny.
Limitations	None.

6.2 Specific Observations at the Phase One Property

6.2.1 Investigation of Structures

Structures on the phase one property were investigated and summarized in the tables below.

Table 6 Observations of On-Site Building(s) / Structure(s)

Item	Comments
General description	Use: Long Term Care Facility Construction date: 1969 with building additions constructed in 1978 (north) and 1995. Number of storeys: Two. Basement levels and below ground structures: A partial basement and crawl space beneath the western portion of the building.
Entry and exit points	Man access doors were used to enter/exit the building. There were no bay doors or other types of entryways.
Heating and Cooling Systems	The building is heated by natural gas fired hot water radiant heat. The boilers are located in the rooftop mechanical room above the eastern portion of the building. The buildings are cooled by A/C units roof top units, ceiling units in corridors, incremental units, and two wall units. Evidence of former system: The boilers were formerly located in the basement of the building and were fired by fuel oil; the fuel oil tank was removed in 1992; there were no evident cuts in the asphalt observed.
Stains or corrosions	A minor leak of hydraulic fluid in the rooftop elevator room was evident.
Drains, pits and Sumps	There were no drains or sumps other than for water; two stormwater sumps were observed in the basement.
Unidentified Substances	None observed.
Above and below ground storage tanks including evidence of fill/vent pipes	A pad mounted diesel generator was located in the rooftop utility room. A reservoir for diesel fuel was located beneath the generator and is filled by jerrycan. A vent pipe for the generator was located was located outside of the rooftop utility room.
Other	A hydraulic elevator was located at the eastern portion of the building. The hydraulic oil reservoir was located in the rooftop elevator room. The elevator was found to be leaking in 2014, and was repaired, during the Site visit, hydraulic fluid was observed adjacent to the elevator on the floor of the rooftop mechanical room.

Table 7 Assessment of Special Attention Items On-Site

Special Attention Item	Comments
Asbestos-Containing Materials (ACMs)	Due to the year of construction of the on-Site buildings (1969) the presence of asbestos containing building materials is possible. Applicable Regulation: O.Reg. 278/05 – Designated Substance – Asbestos on Construction Projects and in Buildings and Repair Operations.
Polychlorinated Biphenyls (PCBs)	Due to the year of construction of the on-Site building (1969) the presence of PCBs in electrical equipment and hydraulic equipment is possible. Applicable Regulation: O.Reg. 362, R.R.O. 1990 – Waste Management – PCBs; SOR/2008-273 – PCB Regulations.
Lead-Based Materials	Due to the year of construction of the on-Site building (1969), the presence of lead-based paints is possible. Lead based paint sampling (see Section 3.4 Previous Reports) did not identify any paints containing lead. Applicable Regulation: SOR/2005-109 – Surface Coating Material Regulation.
Urea Formaldehyde Foam Insulation (UFFI)	None observed or reported by the Site Representative. Applicable Regulation: Canadian Federal Hazardous Products Act, R.S., 1985, c. H-3.
Ozone-Depleting Substances (ODSs)	Equipment or refrigerants potentially containing ozone depleting substances observed during the Site visit included HVAC units and refrigerators. O.Reg. 356, R.R.O. 1990 – Ozone Depleting Substances.
Microbial Contamination (Mould)	None observed or reported by the Site Representative.
Noise and Vibration	None observed or reported by the Site Representative.
Odours	None observed or reported by the Site Representative.
Radon	The Government of Canada Radon Guideline for indoor air concentration in dwellings is 200 Bq/m^3. The concentration of indoor radon levels at the Site are not known. According to a report by Health Canada (March 2012), 4.9 % of homes tested in the Halton region were found to have radon concentrations above 200 Bq/m^3. Canadian Guidelines for the Management of Naturally Occurring Radioactive Materials (NORM) (2013).

6.2.2 Surface Features

The following tables summarizes the surface features observed at the Site.

Table 8 Surface Features Observed at the Site

Surface Feature	Comments
Ground cover	Ground cover is generally asphalt, there are landscaped areas at the front of the building along Maple Avenue and south of the building. The topography of the Site is generally flat with some sloping downwards to the east in the rear parking area.
Stained materials	None observed or reported by the Site Representative.
Stressed vegetation	None observed or reported by the Site Representative.
Fill material	None observed or reported by the Site Representative.
Water courses, ditches or standing water	None observed or reported by the Site Representative.

Wells	Monitoring wells were observed at the Site consistent with those described in the Geotechnical Report (see Section 3.1.5, Previous Reports). Additional monitoring well locations were also observed at the Site, including in the area of the UST.
Railway lines	None observed and no evidence of former railway line on-Site.

6.2.3 Utilities

The following table summarizes the utilities observed on-Site.

Table 9 Details of Utilities

Utility	Comments
Wastewater/Sewage Works	The Site is serviced by the municipal sanitary system.
Water	The Site serviced by the municipal potable water system.
Stormwater	Stormwater at the Site drains by natural infiltration and/or overland flow to on-Site catch basins then directed off-Site to the municipal sewer system.
Electricity	The area of the Site is serviced by electrical cables. A pad mounted transformer was located near the northwest corner of the building; no evidence of staining was present. An additional pad mounted transformer was located to the southwest corner of the Site; no evidence of staining was present.
Natural Gas	The Site is serviced by natural gas.
Waste Management	Domestic wastes are stored in bins located at the northeast corner of the Site and are removed three times per week by a contractor. There were no other non-domestic wastes or hazardous wastes observed to be stored or reported to be removed from the property

6.2.4 Enhanced Investigation Property

Based on the records review and Site reconnaissance, the phase one property is not an enhanced investigation property as it has never been used in whole or in part for: an industrial use, as a garage, as a bulk liquid dispensing facility, including a gasoline outlet, or for the operation of dry cleaning equipment.

A summary of the enhanced investigations carried out for the phase one property is provided in the table below.

Table 10 Details of Enhanced Investigation

Utility	Comments
Site Operations	Not applicable.
Hazardous materials	Not applicable.
products manufactured	Not applicable.
by-products and wastes	Not applicable.
raw materials	Not applicable.
drums, totes and bins	Not applicable.
oil/water separators	Not applicable.

vehicle and equipment maintenance areas	Not applicable.
Spills	Not applicable.
liquid discharge points	Not applicable.
Operations	Not applicable.
Hydraulic lift equipment	Not applicable.

6.3 Investigation of the Phase One Study Area

Neighbouring properties were observed during the Site visit from publicly accessible locations. Current uses of properties adjacent to the Site are presented on **Figure 2**; Land uses were primarily residential.

Water bodies observed included: Lake Ontario, located 180 m southeast of the Site.

There were no areas of natural significance observed.

The following PCAs were observed off-Site:

- A pad mounted transformer was located on the south adjacent property near the southwest corner of the Site (PCA #55 Transformer Manufacturing, Processing and Use). There was no evidence of staining in the area of the transformer and it is unlikely to have contributed to and APEC at the Site.

6.4 Written Description of the Investigation

The Site reconnaissance was conducted by visiting and observing the phase one property and publicly accessible portions of the phase one study area. Preliminary information obtained from the records review was considered prior to conducting the Site reconnaissance. The details of the phase one Site reconnaissance are provided in previous sections of this report.

The following PCAs were observed on-Site:

- A pad mounted transformer was located near the northwest corner of the Site. There was no evidence of staining in the area of the transformer and it is unlikely to have contributed to and APEC at the Site.
- A hydraulic elevator was located on-Site. The elevator was found to be leaking in 2014, and was repaired, during the Site visit, hydraulic fluid was observed adjacent to the elevator on the floor of the rooftop mechanical room.

There following off-site PCAs were observed:

- A pad mounted transformer was located near the northwest corner of the Site. There was no evidence of staining in the area of the transformer and it is unlikely to have contributed to and APEC at the Site.

7.0 Review and Evaluation of Information

7.1 Current and Past Uses

Based on the records review, interviews and Site reconnaissance, the following table presents a summary of the uses of the phase one property from the first developed land use to the present time.

Table 11 Current and Past Uses

Year	Owner	Description/Property Use	Observations
1878 to 1930s	Various private individuals	Agricultural/Undeveloped	Fire insurance plans from 1910 and 1932 show no development at the Site.
1930s to 1960s	Various private individuals	Residential	Aerial photographs from 1950 indicate a building, likely a residence, was located at the site
1962 to 1970	Simson Construction; and various private individuals	Commercial/ Motel	Aerial photographs from 1965 indicate the original motel building was present at the Site.
1970 to 1994 1994 to 2015 2015	Various private individuals Holding Companies; and Various private individuals 2435481 Ontario Inc.	Residential/ Maple Villa Long Term Care Centre	The 1971 fire insurance plan and 1987 inspection report describe a nursing home at the Site.

7.2 Potentially Contaminating Activity

The following PCAs were identified from the records review and the Site:

On-Site

- A fuel oil UST was formerly located near the southwest corner of the building. The UST was removed in 1992 and was reportedly intact with no apparent leakage.
- A hydraulic elevator was located on-Site. Based on the interviews the elevator was found to be leaking in 2014 and was repaired; during the Site visit, hydraulic fluid was observed adjacent to the elevator on the floor of the rooftop mechanical room.
- A pad mounted transformer was located near the northwest corner of the Site. There was no evidence of staining in the area of the transformer and it is unlikely to have contributed to and APEC at the Site.

Off-Site (phase one study area)

- A railway was formerly located adjacent to the Site (from prior to 1910 to the late 1900s), the area of the railway is now a parking area, part of which is leased by the Site.

Other PCAs (if any) that have occurred within the phase one study area are not considered to be contributing to an APEC, based on the distance from the phase one property, absent contaminant pathways, the direction of local groundwater flow, and mobility and/or persistence of the associated potential contaminants of concern. Including those specifically discussed in this report as described below:

- A pad mounted transformer was located near the northwest corner of the Site. There was no evidence of staining in the area of the transformer.
- A lumber mill was located approximately 250 meters north of the site (as shown in the 1932 fire insurance plan).
- Sigmund Publishing Ltd., located 40 m east of the Site at 431 Brock Road, was a publishing and printing company established in 1953.

7.3 Areas of Potential Environmental Concern

Based on the review of available information and the Site reconnaissance, APECs exist at the phase one property. The APECs, PCAs, and associated PCOCs summarized in the table below.

PCOCs contributing to an APEC were selected based on the type of PCA, the distance from the Site, the direction of local groundwater flow, and mobility and/or persistence of the associated PCOC.

Table 12 Areas of Potential Environmental Concern

APEC	Location of APEC	PCA	Location of PCA	PCOCs	Media Potentially Impacted
APEC 1	Area of the former fuel oil UST located near the southwest corner of the building.	PCA i (#28 Gasoline and Associated Products Storage in Fixed Tanks)	On-Site. Area of the former fuel oil UST located near the southwest corner of the building.	petroleum hydrocarbons (PHCs)	Soil
APEC 2	East property line	PCA ii (#46 Rail Yards, Tracks and Spurs)	Off-Site. Former railway tracks located adjacent (to the east) of the Site.	Metals; polychlorinated biphenyls (PCBs); sodium adsorption ratio (SAR); polycyclic aromatic hydrocarbons (PAHs); petroleum hydrocarbons (PHCs)	soil
APEC 3	Beneath the west portion of the on-Site building	PCA iii (other hydraulic elevator with known leaks)	Hydraulic elevator located in the west portion of the building	iii (other hydraulic elevator with known leaks)	soil

7.4 Phase I ESA Conceptual Site Model

The phase one conceptual Site model in plan view is presented on **Figure 3** and; the figure details the following:

- existing buildings and structures on-Site;
- water bodies and areas of natural significance;

- roads (including names);
- areas where any PCA has occurred, and locations of tanks in the phase one study area;
- APECs;
- drinking water wells at the phase one property; and,
- uses of properties adjacent to the phase one property.

Underground utilities were identified at the phase one property. Underground utilities can affect the distribution and transport of contaminants.

There were no uncertainties or lack of information that could affect the validity of the model.

8.0 Conclusions

We understand the work is being conducted in support of property redevelopment. The current land use of the property is residential/parkland/institutional and the future intended land use is residential/parkland/institutional; as such, with no intended change of land use, a Record of Site Condition would not be required in accordance with Ontario Regulation 153/04.

We understand that the development plans for the Site include three levels of underground parking, so any minor localized impact related to the UST or the hydraulic elevator, or adjacent railway would be addressed at that time. Based on previous groundwater assessment at the Site, there were no MECP Table 3 groundwater exceedances in the Site samples collected that may suggest an environmental issue.

Designated substances may be present in on-Site building materials. If present, designated substances can pose potential health concerns to building occupants. If renovation or demolition of the building is planned, designated substances should be managed in accordance with applicable regulations.

8.1 Whether Phase Two is Required Before RSC Submitted

We understand the work is being conducted in support of property redevelopment. The current land use of the property is residential/parkland/institutional, and the future intended land use is residential/parkland/institutional; as such, with no intended change of land use, a Record of Site Condition would not be required in accordance with Ontario Regulation 153/04.

8.2 RSC Based on Phase One ESA Alone

We understand the work is being conducted in support of property redevelopment. The current land use of the property is residential/parkland/institutional, and the future intended land use is residential/parkland/institutional; as such, with no intended change of land use, a Record of Site Condition would not be required in accordance with Ontario Regulation 153/04.

8.3 Signatures

We trust that the above information meets your present needs. Statement of qualifications for the undersigned are available on request. Please do not hesitate to contact us if you have any questions or comments.

Report prepared by:
BlueFrog Environmental Consulting Inc.



Julia Pejic, B.A.Sc
Project Manager

Report reviewed by:
BlueFrog Environmental Consulting Inc.



Gerry Parrott, P.Geo
Founder

9.0 References

Dubrieul, L., Woods, C. (2002). Catalogue of Canadian Fire Insurance Plans 1875-1975. Ottawa: National Library of Canada Cataloguing in Publication.

Google Earth. [Accessed December 1, 2018]


Health Canada. March 2012. Cross Canada Survey of Radon Concentrations in Homes. Final Report.

Niagara Escarpment Plan [Map]. (2005). Ontario: Queens Printer for Ontario.

Ontario Geological Survey 2011. 1:250 000 scale bedrock geology of Ontario; Ontario Geological Survey, Miscellaneous Release---Data 126-Revision 1.

Ontario Geological Survey 2000. 1:1 000 000 scale Quaternary geology, seamless coverage of the Province of Ontario; Ontario Geological Survey, Data Set 14---Revised.

Figures



Legend

Site Boundary

N

1:3000

0 24 48 72 96 120m

0025-001.01	January, 2019	Figure 1

Phase One ESA
441 Maple Avenue, Burlington, Ontario

Site Location and Regional Topography

BlueFrog Environmental Consulting Inc.

Better Life
Retirement
Residence Inc.



Legend

Site Boundary

N

1:2000

0 24 32 48 64 80m


0025-001.01	January, 2019	Figure 2

Phase One ESA
441 Maple Avenue, Burlington, Ontario

Site Plan and Surrounding Land

BlueFrog Environmental Consulting Inc.

Better Life
Retirement
Residence Inc.



Site Feature	Comments
Elevation	Approximately 85 meters above sea level.
Nearest surface body of water	Lake Ontario, located 180m southeast of the site
Interpreted groundwater flow direction	Groundwater flow direction is inferred to be southeast, towards Lake Ontario. Site-specific hydrogeological information is not known other than the depth to groundwater (previous reports section 3.1.5) was measured at depths ranging from 3.7 m bgs to 3.9 m bgs.
Surficial soils	Surficial soils in the area are described as Lacustrine deposits: sand, gravelly sand and gravel nearshore and beach deposits. (Ontario Geological Survey, Quaternary Geology). Site-specific soil stratigraphy information (Previous Reports Section 3.1.5) is fill overlying silt which extended to the shale located about 3 m below grade.
Bedrock	The bedrock in the area is described as: shale, limestone, dolostone, and siltstone (Ontario Geological Survey, Bedrock Geology of Ontario). Site-specific bedrock stratigraphy Site-specific soil stratigraphy information (Previous Reports Section 3.1.5) encountered shale bedrock at approximately 3 m below grade.

PCA	APEC	PCOCs
i (#28 Gasoline and Associated Products Storage in Fixed Tanks)	1-soil in the area of the former fuel oil UST	PHCs
ii (#46 Rail Yards, Tracks and Spurs)	2-surface soil at near the east property line, adjacent to the former off-site railway	PHCs, metals
iii (other hydraulic elevator with known leaks)	3-soil in the vicinity of the hydraulic elevator	PHCs
iv, v (#55 Transformer Manufacturing, Processing and Use)	Not considered to contribute to an APEC	Not applicable
vi (#59 Wood Treating and Preservative Facility and Bulk Storage of Treated and Preserved Wood Products)	Not considered to contribute to an APEC	Not applicable

Legend

- Study Area
- Site Boundary

N

1:3000

0 30 60 90 120 150m

0025-001.01	January, 2019	Figure 3

Phase One ESA
441 Maple Avenue,
Burlington, Ontario

Phase One Conceptual Site Model

BlueFrog Environmental Consulting Inc.

Better Life Retirement Residence Inc.

Appendix A
Site and/or Survey Plans


PLAN BEING PART 1
MUST BE READ IN CONJUNCTION WITH SURVEY REPORT (BEING PART 2)
BEARING COMPARISON NOTE:
FOR BEARING COMPARISONS, BEARINGS ON PLAN 20R-11069 HAVE BEEN ROTATED BY THE ANGLE 00°06'46" COUNTER-CLOCKWISE
PART 3
PLAN 20R-9047
PIN 07083-0062 (LT)
N34°28'27"W (P1)
N36°10'56"W (P1 & MEAS)
14.36
N32°43'36"W (P1)
N32°38'37"W
22.47
N=566.95 (P1 & SET)
N30°39'05"W (P1 & MEAS)
Arc=1.91
LOT 63
LOT 64
LOT 65
LOT 66
REGISTERED
PLAN
PART 1, PLAN 20R-7466
PIN 07083-0059 (LT)
PIN 07083-0060 (LT)
LOT 79
LOT 78
LOT 77
LOT 76
65
PART 2, 20R-11069
PART 1, 20R-11069
PART 5
20R-11069
PART 4
PART 3
PLAN 20R 11069
PIN 07083-0058 (LT)
2 STOREY STUCCO BUILDING #441
FRAME GAZEBO
6 STOREY BRICK APARTMENT BUILDING #455
PART 22, 20R-1215
PART 23
20R-1215
PART 21
20R-1215
PART 20
20R-1215
PART 20
20R-4538
N41°36'54"E (P1 & MEAS)
N42°22'14"E (P1 & MEAS)
N42°22'14"E (P1)
N42°22'14"E (P1 & MEAS)
N42°22'14"E (P1 & MEAS)
N42°22'14"E (P1 & MEAS

Appendix B
Mapping


MINISTRY OF NATURAL RESOURCES AND FORESTRY

Ontario


Make a Topographic Map

Site: 441 Maple Avenue, Burlington, Ontario

Notes:
Project No. 0025-001.01



Legend



0 0.8 km

Projection: Web Mercator

N



The Ontario Ministry of Natural Resources and Forestry shall not be liable in any way for the use of, or reliance upon, this map or any information on this map. This map should not be used for: navigation, a plan of survey, routes, nor locations.

© Queen's Printer for Ontario, 2015

Imagery Copyright Notices: Ontario Ministry of Natural Resources and Forestry; NASA Landsat Program; First Base Solutions Inc.; Aéro-Photo (1961) Inc.; DigitalGlobe Inc.; U.S. Geological Survey.

© Copyright for Ontario Parcel data is held by Queen's Printer for Ontario and its licensors and may not be reproduced without permission.


Ontario

Ministry of Natural Resources and Forestry

Make-a-Map: Natural Heritage Areas

Site: 441 Maple Avenue, Burlington, Ontraio

Notes: Project No. 0025-001.01



Legend

- Assessment Parcel
- Woodland
- Conservation Reserve
- Provincial Park
- Natural Heritage System
- Ecoregion

Wetland
- Provincially Significant Wetland Evaluated
- Non - Provincially Significant Wetland Evaluated
- Unevaluated Wetland

Area of Natural Heritage & Scientific Interest (ANSI)
- Provincially Significant Life Science ANSI
- Provincially Significant Earth Science ANSI

Greenbelt Plan
- Boundary
- River Valley Connections

Land Use Designations
- Protected Countryside
- Towns and Villages
- Hamlets
- Urban River Valley
- Specialty Crop Area

Niagara Escarpment Plan (NEP)
- Boundary
- Parks and Open Space System

Land Use Designations
- Escarpment Natural Area
- Escarpment Protection Area
- Escarpment Rural Area
- Mineral Resource Extraction Area
- Escarpment Recreation Area
- Urban Area
- Minor Urban Centre

Oak Ridges Moraine Conservation Plan (ORM)
- Boundary

Land Use Designations
- Natural Core Area
- Natural Linkage Area
- Countryside Area
- Rural Settlement
- Palgrave Estates Residential Community
- Settlement Area

0.3 0 0.17 0.3 Kilometers



This map should not be relied on as a precise indicator of routes or locations, nor as a guide to navigation. The Ontario Ministry of Natural Resources and Forestry(OMNRF) shall not be liable in any way for the use of, or reliance upon, this map or any information on this map.

© Queen's Printer for Ontario, 2014

Imagery Copyright Notices: DRAPE © Aéro-Photo (1961) Inc., 2008 - 2009
GTA 2005 / SWOOP 2006 / Simcoe-Muskoka-Dufferin © FirstBase Solutions, 2005 / 2006 / 2008

© Copyright for Ontario Parcel data is held by Queen's Printer for Ontario and its licensors [2013] and may not be reproduced without permission. THIS IS NOT A PLAN OF SURVEY.

Appendix C
Site Photographs



Photo 1: The Site (looking north).




Photo 2: The Site (looking northeast).




Photo 3: The Site parking area and waste disposal area (looking north).



Photo 4: The Site, southern portion (looking northwest).



Photo 5: Basement utility room.



Photo 6: Crawlspace adjacent to basement utility room.



Photo 7: Rooftop.



Photo 8: Diesel generator in rooftop mechanical room.




Photo 9: Boilers and hot water heaters in rooftop mechanical room.




Photo 10: Hydraulic elevator and oil spill/staining.

Appendix D
Aerial Photographs



Photo Year: 1931

Source: National Air Photo Library



Photo Year: 1950

Source: National Air Photo Library



Photo Year: 1965

Source: National Air Photo Library



Photo Year: 1974

Source: National Air Photo Library



Photo Year: 1986

Source: National Air Photo Library



Photo Year: 2005

Source: National Air Photo Library



Photo Year: 2018

Source: National Air Photo Library

Appendix E
Historical Records



opta
INFORMATION INTELLIGENCE

enviroscan







An SCM Company

175 Commerce Valley Drive W
Markham, Ontario L3T 7Z3

T: 905-882-6300
W: www.optaintel.ca

Report Completed By:

Sunita

Site Address:

441 Maple Avenue Burlington Ont

Project No:

20181128007

Opta Order ID:

55935

Requested by:

Eleanor Goolab
ERIS

Date Completed:

12/4/2018 2:56:49 PM

Project Name: 441 Maple Avenue Burlington


Project #: 20181128007
P.O. #: 0025001.01

ENVIROSCAN Report

Search Area: 441 Maple Avenue Burlington Ont

Requested by:
Eleanor Goolab
Date Completed: 12/04/2018 14:56:49

enviroscan
OPTA INFORMATION INTELLIGENCE



This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

Opta Historical Environmental Services Enviroscan™ Terms and Conditions

Report

The documents (hereinafter referred to as the "Documents") to be released as part of the report (hereinafter referred to as the "Report") to be delivered to the purchaser as set out above are documents in Opta's records relating to the described property (hereinafter referred to as the "Property"). Opta makes no representations or warranties respecting the Documents whatsoever, including, without limitation, with respect to the completeness, accuracy or usefulness of the Documents, and does not represent or warrant that these are the only plans and reports prepared in association with the Property or in Opta's possession at the time of Report delivery to the purchaser. The Documents are current as of the date(s) indicated on them. Interpretation of the Documents, if any, is by inference based upon the information which is apparent and obvious on the face of the Documents only. Opta does not represent, warrant or guarantee that interpretations other than those referred to do not exist from other sources. The Report will be prepared for use by the purchaser of the services as shown above hereof only.

Disclaimer

Opta disclaims responsibility for any losses or damages of any kind whatsoever, whether consequential or other, however caused, incurred or suffered, arising directly or indirectly as a result of the services (which services include, but are not limited to, the preparation of the Report provided hereunder), including but not limited to, any losses or damages arising directly or indirectly from any breach of contract, fundamental or otherwise, from reliance on Opta Reports or from any tortious acts or omissions of Opta's agents, employees or representatives.

Entire Agreement

The parties hereto acknowledge and agree to be bound by the terms and conditions hereof. The request form constitutes the entire agreement between the parties pertaining to the subject matter hereof and supersedes all prior and contemporaneous agreements, negotiations and discussions, whether oral or written, and there are no representations or warranties, or other agreements between the parties in connection with the subject matter hereof except as specifically set forth herein. No supplement, modification, waiver, or termination of the request shall be binding, unless confirmed in writing by the parties hereto.

Governing Document

In the event of any conflicts or inconsistencies between the provisions hereof and the Reports, the rights and obligations of the parties shall be deemed to be governed by the request form, which shall be the paramount document.

Law

This agreement shall be governed by and construed in accordance with the laws of the Province of Ontario and the laws of Canada applicable therein.

ENVIROSCAN Report

Report Index

OPTA INFORMATION INTELLIGENCE

Page	Report Title
6	(1910) Volume: Ontario Firemap: 6
8	(1932) Volume: Ontario Firemap: 4
10	(1932) Volume: Ontario Firemap: 4
12	(1932) Volume: Ontario Firemap: 4
14	(1932) Volume: Ontario Firemap: 4
16	(1971) Volume: Burlington Firemap: 54
18	(1971) Volume: Burlington Firemap: 55
20	(1971) Volume: Burlington Firemap: 57
22	(1971) Volume: Burlington Firemap: 58
24	(1971) Volume: Burlington Firemap: 59
26	(1971) Volume: Burlington Firemap: 59
27	(1987) COPE Report - 1987 MAPLE VILLA NURSING HOME 441 MAPLE AV BURLINGTON ON L7S 1L8 Reference No: 10380034 (distance = 18 metres*)

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



Project Name: 441 Maple Avenue Burlington

Project #: 20181128007
P.O. #: 0025001.01

ENVIROSCAN Report

1910 Volume: Ontario Firemap: 6
Burlington Plan: 293 (1910)
Sheet: 6 (1910)

Requested by:
Eleanor Goolab
Date Completed: 12/04/2018 14:56:49

enviroscan
OPTA INFORMATION INTELLIGENCE

FIP Locator Map
The detailed FIP is on the following page




This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

ENVIROSCAN Report

1910 Volume: Ontario Firemap: 6
Burlington Plan: 293 (1910)
Sheet: 6 (1910)

opta INFORMATION INTELLIGENCE
OPTA INFORMATION INTELLIGENCE



Project Name: 441 Maple Avenue Burlington

Project #: 20181128007
P.O. #: 0025001.01

ENVIROSCAN Report

1932 Volume: Ontario Firemap: 4
Burlington Plan: 295 (1924)
Sheet: 4 (1932)

Requested by:
Eleanor Goolab
Date Completed: 12/04/2018 14:56:49


enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

FIP Locator Map
The detailed FIP is on the following page



1932 Volume: Ontario Firemap: 4
Burlington Plan: 295 (1924)
Sheet: 4 (1932)



Project Name: 441 Maple Avenue Burlington

Project #: 20181128007
P.O. #: 0025001.01


ENVIROSCAN Report

1932 Volume: Ontario Firemap: 4
Burlington Plan: 295 (1924)
Sheet: 4 (1932)

Requested by:
Eleanor Goolab
Date Completed: 12/04/2018 14:56:49

enviroscan
OPTA INFORMATION INTELLIGENCE

FIP Locator Map
The detailed FIP is on the following page



This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

ENVIROSCAN Report

1932 Volume: Ontario Firemap: 4
Burlington Plan: 295 (1924)
Sheet: 4 (1932)

Requested by:
Eleanor Goolab
Date Completed: 12/04/2018 14:56:49

opta
INFORMATION INTELLIGENCE
OPTA INFORMATION INTELLIGENCE



Project Name: 441 Maple Avenue Burlington

Project #: 20181128007
P.O. #: 0025001.01

ENVIROSCAN Report

1932 Volume: Ontario Firemap: 4
Burlington Plan: 295 (1924)
Sheet: 4 (1932)

Requested by:
Eleanor Goolab
Date Completed: 12/04/2018 14:56:49

enviroscan
OPTA INFORMATION INTELLIGENCE

FIP Locator Map
The detailed FIP is on the following page




This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

ENVIROSCAN Report

1932 Volume: Ontario Firemap: 4
Burlington Plan: 295 (1924)
Sheet: 4 (1932)

Requested by:
Eleanor Goolab
Date Completed: 12/04/2018 14:56:49

opta INFORMATION INTELLIGENCE
OPTA INFORMATION INTELLIGENCE



Project Name: 441 Maple Avenue Burlington

Project #: 20181128007
P.O. #: 0025001.01

ENVIROSCAN Report

1932 Volume: Ontario Firemap: 4
Burlington Plan: 295 (1924)
Sheet: 4 (1932)

Requested by:
Eleanor Goolab
Date Completed: 12/04/2018 14:56:49

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

FIP Locator Map
The detailed FIP is on the following page




ENVIROSCAN Report

1932 Volume: Ontario Firemap: 4
Burlington Plan: 295 (1924)
Sheet: 4 (1932)

Requested by:
Eleanor Goolab
Date Completed: 12/04/2018 14:56:49

OPTA INFORMATION INTELLIGENCE



Project Name: 441 Maple Avenue Burlington

Project #: 20181128007
P.O. #: 0025001.01


ENVIROSCAN Report

1971 Volume: Burlington Firemap: 54
Burlington Plan: 296 (1971)
Sheet: 54 (1971)

Requested by:
Eleanor Goolab
Date Completed: 12/04/2018 14:56:49

enviroscan
OPTA INFORMATION INTELLIGENCE


FIP Locator Map
The detailed FIP is on the following page



This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

ENVIROSCAN Report

1971 Volume: Burlington Firemap: 54
Burlington Plan: 296 (1971)
Sheet: 54 (1971)



Project Name: 441 Maple Avenue Burlington

Project #: 20181128007
P.O. #: 0025001.01


ENVIROSCAN Report

1971 Volume: Burlington Firemap: 55
Burlington Plan: 296 (1971)
Sheet: 55 (1971)

Requested by:
Eleanor Goolab
Date Completed: 12/04/2018 14:56:49


enviroscan
OPTA INFORMATION INTELLIGENCE

FIP Locator Map
The detailed FIP is on the following page



This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

1971 Volume: Burlington Firemap: 55
Burlington Plan: 296 (1971)
Sheet: 55 (1971)



This plan is the property of the CANADIAN UNDERWRITERS' ASSOCIATION, (unauthorized reproduction prohibited) and is loaned on the following conditions: that the plan is to be kept in good order, that it is to be used only in connection with business of Companies, Members of the Canadian Underwriters' Association and is to be returned on request to the CANADIAN UNDERWRITERS' ASSOCIATION.

COPYRIGHT REGISTERED AT OTTAWA
BY THE
CANADIAN UNDERWRITERS' ASSOCIATION

Project Name: 441 Maple Avenue Burlington

Project #: 20181128007
P.O. #: 0025001.01

ENVIROSCAN Report


1971 Volume: Burlington Firemap: 57
Burlington Plan: 296 (1971)
Sheet: 57 (1971)


Requested by:
Eleanor Goolab
Date Completed: 12/04/2018 14:56:49

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

FIP Locator Map
The detailed FIP is on the following page




57
1163 A
1163
CONTINUED ABOVE
BURLINGTON, ONT.
OCTOBER 1971
57
This plan is the property of the CANADIAN UNDERWRITERS' ASSOCIATION, (unauthorized reproduction prohibited) and is loaned on the following conditions: that the plan is to be kept in good order, that it is to be used only in connection with business of Companies, Members of the Canadian Underwriters' Assoc ation and is to be returned on request to the CANADIAN UNDERWRITERS' ASSOCIATION.
COPYRIGHT REGISTERED AT OTTAWA
BY THE
CANADIAN UNDERWRITERS' ASSOCIATION
139
Underground Parking
Auto 1st
Ramp Down
Auto
NORTH SHORE TOWERS APTS.
REINF. CONC. FRAME, BK ON CB WALLS, CONC. FLRS & RF.
1171
1183
1182
1230
1240
1249
1259
NORTH SHORE BLVD. E.
DEPARTMENT OF TRANSPORT & COMMUNICATIONS
BK ON CB WALLS, CONC FLR & RF.
Office
JOSEPH BRANT MEMORIAL HOSPITAL
REINF. CONC. FRAME, BK ON TILE WALLS, CONC. FLRS. & RF.
21
Offices
Coffee Shop 1st
Stores 1st
Water Cooler on Rf.
Canopy
Diesel Rm.
Maint Bf.
Paint Spray
Kitchen 2ND
Cafeteria & Auditorium 2ND
Conc. Retaining Wall
Liquid Air
JOSEPH BRANT MUSEUM
LAKESHORE RD. (LATE: BEACH RD.) (HWY 20)
C.N.R.
116
Lake Ontario
SCALE 100 FEET TO 1 INCH

Project Name: 441 Maple Avenue Burlington

Project #: 20181128007
P.O. #: 0025001.01


ENVIROSCAN Report

1971 Volume: Burlington Firemap: 58
Burlington Plan: 296 (1971)
Sheet: 58 (1971)

Requested by:
Eleanor Goolab
Date Completed: 12/04/2018 14:56:49

enviroscan
OPTA INFORMATION INTELLIGENCE


FIP Locator Map
The detailed FIP is on the following page



This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

ENVIROSCAN Report

1971 Volume: Burlington Firemap: 58
Burlington Plan: 296 (1971)
Sheet: 58 (1971)



Project Name: 441 Maple Avenue Burlington

Project #: 20181128007
P.O. #: 0025001.01


ENVIROSCAN Report

1971 Volume: Burlington Firemap: 59
Burlington Plan: 296 (1971)
Sheet: 59 (1971)

Requested by:
Eleanor Goolab
Date Completed: 12/04/2018 14:56:49

enviroscan
OPTA INFORMATION INTELLIGENCE


FIP Locator Map
The detailed FIP is on the following page



This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

1971 Volume: Burlington Firemap: 59
Burlington Plan: 296 (1971)
Sheet: 59 (1971)

opta
INFORMATION INTELLIGENCE
OPTA INFORMATION INTELLIGENCE



Project Name: 441 Maple Avenue Burlington

Project #: 20181128007
P.O. #: 0025001.01


ENVIROSCAN Report

1971 Volume: Burlington Firemap: 59
Burlington Plan: 296 (1971)
Sheet: 59 (1971)

Requested by:
Eleanor Goolab
Date Completed: 12/04/2018 14:56:49

enviroscan
OPTA INFORMATION INTELLIGENCE


FIP Locator Map
The detailed FIP is on the following page



This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

ENVIROSCAN Report

1971 Volume: Burlington Firemap: 59
Burlington Plan: 296 (1971)
Sheet: 59 (1971)



This plan is the property of the CANADIAN UNDERWRITERS' ASSOCIATION, (unauthorized reproduction prohibited) and is loaned on the following conditions: that the plan is to be kept in good order, that it is to be used only in connection with business of Companies, Members of the Canadian Underwriters' Association and is to be returned on request to the CANADIAN UNDERWRITERS' ASSOCIATION.

COPYRIGHT REGISTERED AT OTTAWA
BY THE
CANADIAN UNDERWRITERS' ASSOCIATION

enviroscan
OPTA INFORMATION INTELLIGENCE

AIS Ref No.: 10380034

1987

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

INSURERS' ADVISORY ORGANIZATION 2008-Oct-31
CONFIDENTIAL - FOR USE OF MEMBERS ONLY 12:16 [Fri]
NOT FOR GENERAL DISTRIBUTION

COPE (Construction, Occupancy, Protection, Exposure) REPORT

Risk: MAPLE VILLA NURSING HOME
441 MAPLE AVENUE
BURLINGTON,ONTARIO
L7S 1L8

Reference No. 10380034 / Building No. 01

(Surveyed By M. CANARIO on 28-SEP-87)

Please note that the information contained in this report was gathered during a physical inspection of the risk by an IAO Loss Control Representative.

If you wish to obtain building or contents rates for this risk, please refer to the Rate Card in the list of products available for this risk. Please call the IAO Help Desk or your local IAO Representative for help in obtaining a rate for this risk, or do it yourself by going to www.iao.ca and using the New X-rate to generate a new rate yourself.

IAO reports, prepared in compliance with commonly accepted risk control standards existing at the time services are rendered, are developed from an inspection of the premises and/or from data supplied by or on behalf of the Purchaser. IAO does not purport to list all hazards. While changes and modifications referred to in the reports are designed to upgrade protection and loss prevention of the premises, IAO assumes no responsibility for management and control of these activities. IAO will not be responsible to the Purchaser for any loss or damages, whether consequential or other, however caused, incurred or suffered, as a result of the service being provided.

------ CODING ------

Industry Code:	807	- Senitaris, Convalescent Homes, Homes for the Aged
Construction Code:	1	- Fire Resistive
Risk Classification:	NS	- Non-Sprinklered
Protection Code:	2	- Non-Sprinklered, Fully Protected, Gr 3
Combustibility	L2	

------ BRIEF DESCRIPTION ------

THIS IS A 2 STOREY AND BST CBBF BLDG WITH
CONC & WD JOIST FLRS & CONC & WD JOIST ROOF
OCCUPIED AS A NURSING HOME WITH KITCHEN-APP
CO2 SYSTEM. MUN PROT IS STD FOR FUS CLASS 3.
PRIV PROT IS NON STD. HOUSEKEEPING IS GOOD.
CIRCUIT BREAKERS ARE USED. THE BST IS
SPRINKLERED.

------ COMMENTS ------

THIS RISK IS GOOD IN CLASS.
DESIRABLE IMPROVEMENTS:
1. PROVIDE A "40B,C" RATED EXTINGUISHER
IN THE KITCHEN.

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



ENVIROSCAN Report

COPE Report - 1987 MAPLE VILLA NURSING HOME
441 MAPLE AV BURLINGTON ON L7S 1L8
Reference No: 10380034

Requested by:
Eleanor Goolab
Date Completed: 12/04/2018 14:56:49

OPTA INFORMATION INTELLIGENCE

AIS Ref No.: 10380034

1987

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

------ CONSTRUCTION ------

WALLS - MASONRY:
100% CBBF WALLS 300mm Thick C-2 Type: W-1

MASONRY and FIRE RESISTIVE FLOOR and ROOFS:
66% PRECAST CONC FLRS AND RF Hours: 3.00 Listed? U Type: D-1

FLOORS & ROOFS - COMBUSTIBLE:
34% WD JOIST FLRS AND ROOF C-2

------ SECONDARY CONSTRUCTION ------

HEIGHT:
Number of Storeys: 2
Basements: P

Combustible Storeys Without Grade Access: 0

VERTICAL OPENINGS:
B-2 MAS ENCL. Comb.: L2 Const.: 1
Type: Masonry (V-1) 2Hrs-Walls/ 1.5Hrs-Doors

AREA:

Grade: 1009 m2 Total: 2260 m2 Effective: 1009 m2

L1, L2 Area 100%

ROOF SURFACE:
100 % APPROVED

COMBUSTIBLE CONCEALED SPACES:
100 % ATTIC SPACE

BUILDING CONDITION:
GOOD Type C-.

Year Built: 1960/7 Air Conditioning: 20% WINDOW

Basement: FINISHED

Elevators: 2 PASSENGER

COMMON HAZARDS: 7211A2 - FWA GAS FIRED
7211A1 - GAS FIRED HOT WATER

------ PROTECTION ------

MUNICIPAL PROTECTION:
Distance from Hydrants: STANDARD Congested Area: NO
Distance to Fire Hall: STANDARD Accessibility: GOOD
FUS Protection Class: 03
Revised Class: 03
IAO Protection Class: 03

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

N
W E
S

ENVIROSCAN Report

COPE Report - 1987 MAPLE VILLA NURSING HOME
441 MAPLE AV BURLINGTON ON L7S 1L8
Reference No: 10380034

Requested by:
Eleanor Goolab
Date Completed: 12/04/2018 14:56:49

enviroscan
OPTA INFORMATION INTELLIGENCE

AIS Ref No.: 10380034

1987

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

INTERNAL PROTECTION:
MANUAL FIRE FIGHTING EQUIPMENT: Portable Fire Extinguishers
Standpipe and Hose

AUTOMATED FIRE DETECTION SYSTEMS:
FIRE ALARM SYSTEM

PARTIALLY AUTOMATED SPRINKLER SYSTEMS:
Location: SPRINKLERED BST
Area (sq. m): 11 Area Covered: 30%

------ EXPOSURE ------

NONE NOTED:

------ OCCUPANCY - MAPLE VILLA NURSING HOME ------

Industry Code: 807 - Senitaris, Convalescent Homes, Homes for the

Occupancy: 5263 - NURSING HOME

Location: B-2 Area: 2260 m2 100.0% of Total

Combustibility Code: L2 - Limited Combustibility
Susceptibility Code: S1 - Minimal Damage

Special Hazard: 7305A1B - CKNG WITH APPRVD SYSTM

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



CHAIN OF TITLE REPORT

Project # 0025-001.01
Address: 441 Maple Avenue, Burlington
Legal Description: Part Lots 64, 65, 77 & 78 Plan 65 Parts 2 & 3 20R20090

PIN# 07083-0114 (LT)

Searched at: Milton
LRO #: 20

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
	Patent	14 02 1798	Crown	Capt. Joseph BRANT
30	Deed	27 09 1831	Joseph Brant	William John Simcoe KERR
293	Deed	03 12 1869	William John Simcoe Kerr	James McMURRAY
328	Deed	15 01 1870	James McMurray	Benjamin EAGER
1330	Deed	11 07 1874	Benjamin Eager	James E. EAGER
1400	Deed	14 10 1874	James E. Eager	Richard P. STREET
2277	Deed	04 05 1878	Richard P. Street	Henry FOSTER
6318	Deed	21 10 1899	Henry Foster - Estate	Henry Thomson FOSTER
11045	Deed	03 10 1942	Henry Thomson Foster - Estate	Paul Allen FISHER

Cont'd on Page 2

CHAIN OF TITLE REPORT

Project #	0025-001.01	**Searched at:**	Milton
Address:	441 Maple Avenue, Burlington	**LRO #:**	20
Legal Description:	Part Lots 64, 65, 77 & 78 Plan 65 Parts 2 & 3 20R20090		
PIN#	07083-0114 (LT)		

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
11458	Deed	28 04 1944	Paul Allen Fisher	John William BEARD & Frances G. BEARD
12528	Deed	01 06 1946	Paul Allen Fisher	John William BEARD & Frances G. BEARD
13274	Deed	08 10 1946	John William Beard Frances G. Beard	William Edward VARDY
126741	Deed	31 07 1961	John William Beard - Estate Frances G. Glover (Beard)	Werner SIMSON
92865	Deed	01 09 1961	Werner Simson	William HOURIGAN
136950	Deed	01 05 1962	William Edward Vardy	Simson Construction Limited
289835	Deed (Pt lots 64, 65, 77 & 78)	10 03 1970	Werner Simson	Robert TINDALE Alfred THIBODEAU William JOHNSTON
289837	Deed (Pt lots 64 & 78)	10 03 1970	Simson Construction Limited	Robert TINDALE Alfred THIBODEAU William JOHNSTON William HOURIGAN

Cont'd on page 3

CHAIN OF TITLE REPORT

Project #	0025-001.01	**Searched at:**	Milton	
Address:	441 Maple Avenue, Burlington	**LRO #:**	20	Page 3
Legal Description:	Part Lots 64, 65, 77 & 78 Plan 65 Parts 2 & 3 20R20090			
PIN#	07083-0114 (LT)			

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
330670	Deed	11 02 1972	William Hourigan	Robert M. TINDALE Alfred E. THIBODEAU William M. JOHNSTON
830997	Easement	07 11 1994	Robert M. Tindale, William M. Johnston & Alfred E. Thibodeau	Westphalen Holdings Limited
832760	Deed	16 12 1994	Robert M. Tindale	Dallov Holdings Limited
837668	Vesting Order	08 05 1995	Supreme Court of Ontario (Robert M. Tindale - estate)	Depositors' Credit Corporation Ltd.
838158	Deed	24 05 1995	Depositors' Credit Corporation Ltd.	Dallov Holdings Limited
HR1252052	Deed	09 03 2015	William M. Johnston - estate	Theresa JOHNSTON
HR1256622	Easement	31 03 2015	Dallov Holdings Limited Alfred E. Thibodeau Theresa Johnston	Yubat Holdings Inc.
HR1256979	Deed **(Present Owner)**	01 04 2015	Dallov Holdings Limited Alfred E. Thibodeau Theresa Johnston	**2435481 Ontario Inc.**

PROPERTY DESCRIPTION: PT LTS 64,65,77,78, PL 65 PTS 2,3 20R20090. S/T 830997 OVER PT 2 20R20090; TOGETHER WITH AN EASEMENT OVER PT 1 20R20090 AS IN 830998; SUBJECT TO AN EASEMENT OVER PT 2 20R20091 IN FAVOUR OF PT LT 79, PL65, PT 1 20R7466 AS IN HR1256622; TOGETHER WITH AN EASEMENT OVER PT 1 20R20091 AS IN HR1256623; CITY OF BURLINGTON

PROPERTY REMARKS: FOR THE PURPOSE OF THE QUALIFIER THE DATE OF REGISTRATION OF ABSOLUTE TITLE IS 2015.03.30.

ESTATE/QUALIFIER:
FEE SIMPLE
LT ABSOLUTE PLUS

RECENTLY:
RE-ENTRY FROM 07083-0059

PIN CREATION DATE:
2015/03/30

OWNERS' NAMES
2435481 ONTARIO INC.

CAPACITY SHARE

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
** PRINTOUT INCLUDES ALL DOCUMENT TYPES AND DELETED INSTRUMENTS SINCE 2015/03/30 **						
**SUBJECT TO SUBSECTION 44(1) OF THE LAND TITLES ACT, EXCEPT PARAGRAPHS 3 AND 14 AND *						
** PROVINCIAL SUCCESSION DUTIES AND EXCEPT PARAGRAPH 11 AND ESCHEATS OR FORFEITURE **						
** TO THE CROWN UP TO THE DATE OF REGISTRATION WITH AN ABSOLUTE TITLE. **						
119980	1961/01/25	BYLAW				C
289835	1970/03/10	TRANSFER		*** DELETED AGAINST THIS PROPERTY ***	TINDALE, ROBERT M. THIBODEAU, ALFRED E. JOHNSTON, WILLIAM M.	
289837	1970/03/10	TRANSFER		*** DELETED AGAINST THIS PROPERTY ***	TINDALE, ROBERT M. HOURIGAN, WILLIAM E. THIBODEAU, ALFRED E. JOHNSTON, WILLIAM M.	
330670	1972/02/11	TRANSFER		*** DELETED AGAINST THIS PROPERTY ***	TINDALE, ROBERT M. THIBODEAU, ALFRED E. JOHNSTON, WILLIAM M.	
445530	1976/12/09	AGREEMENT			THE CORPORATION OF THE CITY OF BURLINGTON	C
830997	1994/11/07	TRANSFER EASEMENT	$2	TINDALE, ROBERT M. THIBODEAU, ALFRED E. JOHNSTON, WILLIAM M.	WESTPHALEN HOLDINGS LIMITED	C
832760	1994/12/16	TRANSFER		*** DELETED AGAINST THIS PROPERTY ***	DALLOV HOLDINGS LIMITED	


NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
838158	1995/05/24	TRANSFER		*** DELETED AGAINST THIS PROPERTY ***	DALLOV HOLDINGS LIMITED	
838586	1995/05/24	AGREEMENT			THE CORPORATION OF THE CITY OF BURLINGTON	C
838768	1995/06/07	CHARGE		*** DELETED AGAINST THIS PROPERTY ***	CIBC MORTGAGE CORPORATION	
838769	1995/06/07	ASSIGNMENT GENERAL		*** DELETED AGAINST THIS PROPERTY ***		
840675	1995/07/25	NOTICE		*** DELETED AGAINST THIS PROPERTY ***		
840752	1995/07/27	ASSIGNMENT GENERAL				C
	REMARKS: 840675					
HR1252052	2015/03/09	TRANSMISSION-LAND		*** DELETED AGAINST THIS PROPERTY *** JOHNSTON, WILLIAM M. (DECEASED)	JOHNSTON, THERESA JOHNSTON, WILLIAM M. - ESTATE	
20R20090	2015/03/30	PLAN REFERENCE				C
HR1256127	2015/03/30	APL ABSOLUTE TITLE		DALLOV HOLDINGS LIMITED THIBODEAU, ALFRED E. JOHNSTON, THERESA		C
20R20091	2015/03/30	PLAN REFERENCE				C
HR1256622	2015/03/31	TRANSFER EASEMENT	$2	DALLOV HOLDINGS LIMITED THIBODEAU, ALFRED E. JOHNSTON, THERESA	YUBAT HOLDINGS INC.	C
	REMARKS: PLANNING ACT STATEMENTS.					
HR1256629	2015/03/31	APL (GENERAL)		*** COMPLETELY DELETED *** DALLOV HOLDINGS LIMITED THIBODEAU, ALFRED E. JOHNSTON, THERESA		
	REMARKS: DELETE 840675					
HR1256979	2015/04/01	TRANS PERSONAL REP	$2,000,000	DALLOV HOLDINGS LIMITED JOHNSTON, THERESA	2435481 ONTARIO INC.	C

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
				THIBODEAU, ALFRED E.		
	REMARKS: PLANNING ACT STATEMENTS.					
HR1256996	2015/04/01	CHARGE	$5,000,000	2435481 ONTARIO INC.	MERIDIAN CREDIT UNION LIMITED	C
HR1257005	2015/04/01	NO ASSGN RENT GEN		2435481 ONTARIO INC.	MERIDIAN CREDIT UNION LIMITED	C
	REMARKS: HR1256996.					
HR1273996	2015/06/16	DISCH OF CHARGE		*** COMPLETELY DELETED *** CANADIAN IMPERIAL BANK OF COMMERCE		
	REMARKS: 838768.					
HR1592359	2018/12/13	NOTICE	$2	2435481 ONTARIO INC.	EMSHIH DEVELOPMENTS INC. SHIH, MICHAEL	C

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.



ServiceOntario

PRINTED ON 24 DEC, 2018 AT 09:47:25
FOR BERTUCCI1

SCALE

0 30 meters

PROPERTY INDEX MAP

HALTON(No. 20)

LEGEND

FREEHOLD PROPERTY	
LEASEHOLD PROPERTY	
LIMITED INTEREST PROPERTY	
CONDOMINIUM PROPERTY	
RETIRED PIN (MAP UPDATE PENDING)	
PROPERTY NUMBER	0449
BLOCK NUMBER	08050
GEOGRAPHIC FABRIC	——
EASEMENT	- - - -

THIS IS NOT A PLAN OF SURVEY

NOTES

REVIEW THE TITLE RECORDS FOR COMPLETE PROPERTY INFORMATION AS THIS MAP MAY NOT REFLECT RECENT REGISTRATIONS

THIS MAP WAS COMPILED FROM PLANS AND DOCUMENTS RECORDED IN THE LAND REGISTRATION SYSTEM AND HAS BEEN PREPARED FOR PROPERTY INDEXING PURPOSES ONLY

FOR DIMENSIONS OF PROPERTIES BOUNDARIES SEE RECORDED PLANS AND DOCUMENTS

ONLY MAJOR EASEMENTS ARE SHOWN

REFERENCE PLANS UNDERLYING MORE RECENT REFERENCE PLANS ARE NOT ILLUSTRATED

Ontario

© Queen's Printer for Ontario, 2018

LRO Annotation

Executions clear Johnston, William M. cert#25427046−9176265B. Apr7/15 TWendover

Properties

PIN 07083 − 0114 LT *Interest/Estate* Fee Simple
Description PT LTS 64,65,77,78, PL 65 PTS 2,3 20R20090. S/T 830997 OVER PT 2 20R20090; TOGETHER WITH AN EASEMENT OVER PT 1 20R20090 AS IN 830998; CITY OF BURLINGTON
Address 441 MAPLE AVENUE
BURLINGTON

Consideration

Consideration $2,000,000.00

Transferor(s)

The transferor(s) hereby transfers the land to the transferee(s).

Name DALLOV HOLDINGS LIMITED
Address for Service 441 Maple Avenue
Burlington, Ontario

I, Alfred E. Thibodeau, President, have the authority to bind the corporation.
This document is not authorized under Power of Attorney by this party.

Name JOHNSTON, THERESA
Address for Service 441 Maple Avenue
Burlington, Ontario

This document is not authorized under Power of Attorney by this party.

Name THIBODEAU, ALFRED E.
Address for Service 441 Maple Avenue
Burlington, Ontario

This document is not authorized under Power of Attorney by this party.

Transferee(s) *Capacity* *Share*

Name 2435481 ONTARIO INC.
Address for Service 19 Richvalley Crescent
Richmond Hill, Ontario
L4E 4C8

Statements

The personal representative has the authority to transfer the land under the terms of the will, if any, the Estates Administration Act and the Succession Law Reform Act.

This transfer is authorized by Court Superior Court of Justice, under file no. 4101/02, dated 2002/05/29 and is still in full force and effect.

Title to the land is not subject to spousal rights under the Family Law Act

The debts of the deceased are paid in full

Schedule: I Alfred E. Thibodeau state I am at least 18 years of age and I am not a spouse and this document is not authorized under a Power of Attorney by this party. I, Alfred E. Thibodeau, President, have the authority to bind the corporation, Dallov Holdigs Limited, and this document is not authorized under a Power of Attorney by this party.

STATEMENT OF THE TRANSFEROR (S): The transferor(s) verifies that to the best of the transferor's knowledge and belief, this transfer does not contravene the Planning Act.

STATEMENT OF THE SOLICITOR FOR THE TRANSFEROR (S): I have explained the effect of the Planning Act to the transferor(s) and I have made inquiries of the transferor(s) to determine that this transfer does not contravene that Act and based on the information supplied by the transferor(s), to the best of my knowledge and belief, this transfer does not contravene that Act. I am an Ontario solicitor in good standing.

STATEMENT OF THE SOLICITOR FOR THE TRANSFEREE (S): I have investigated the title to this land and to abutting land where relevant and I am satisfied that the title records reveal no contravention as set out in the Planning Act, and to the best of my knowledge and belief this transfer does not contravene the Planning Act. I act independently of the solicitor for the transferor(s) and I am an Ontario solicitor in good standing.

Signed By

Karmel Sakran	411 Guelph Line, P.O. Box 400 Burlington L7R 3Y3	acting for Transferor(s)	Signed	2015 04 01

Tel 905−639−1222

Fax 905−632−6977

I am the solicitor for the transferor(s) and I am not one and the same as the solicitor for the transferee(s).

I have the authority to sign and register the document on behalf of the Transferor(s).

Joseph Walter Jacques Laurion	41 Wellington Street East Aurora L4G 1H6	acting for Transferee(s)	Signed	2015 04 01

Tel 9058412222

Fax 9058413388

I am the solicitor for the transferee(s) and I am not one and the same as the solicitor for the transferor(s).

I have the authority to sign and register the document on behalf of the Transferee(s).

Submitted By

LAURION LAW OFFICE	41 Wellington Street East Aurora L4G 1H6	2015 04 01

Tel 9058412222

Fax 9058413388

Fees/Taxes/Payment

Statutory Registration Fee	$60.00
Provincial Land Transfer Tax	$0.00
Total Paid	$60.00

LAND TRANSFER TAX STATEMENTS

In the matter of the conveyance of: 07083 − 0114 PT LTS 64,65,77,78, PL 65 PTS 2,3 20R20090. S/T 830997 OVER PT 2 20R20090; TOGETHER WITH AN EASEMENT OVER PT 1 20R20090 AS IN 830998; CITY OF BURLINGTON

BY: DALLOV HOLDINGS LIMITED
JOHNSTON, THERESA
THIBODEAU, ALFRED E.

TO: 2435481 ONTARIO INC.

1. SAMER EL−FASHNY

I am

- ☐ (a) A person in trust for whom the land conveyed in the above−described conveyance is being conveyed;
- ☐ (b) A trustee named in the above−described conveyance to whom the land is being conveyed;
- ☐ (c) A transferee named in the above−described conveyance;
- ☐ (d) The authorized agent or solicitor acting in this transaction for _____ described in paragraph(s) (_) above.
- ☑ (e) The President, Vice−President, Manager, Secretary, Director, or Treasurer authorized to act for 2435481 ONTARIO INC. described in paragraph(s) (c) above.
- ☐ (f) A transferee described in paragraph() and am making these statements on my own behalf and on behalf of _____who is my spouse described in paragraph(_) and as such, I have personal knowledge of the facts herein deposed to.

3. **The total consideration for this transaction is allocated as follows:**

(a) Monies paid or to be paid in cash	0.00
(b) Mortgages (i) assumed (show principal and interest to be credited against purchase price)	0.00
(ii) Given Back to Vendor	0.00
(c) Property transferred in exchange (detail below)	0.00
(d) Fair market value of the land(s)	0.00
(e) Liens, legacies, annuities and maintenance charges to which transfer is subject	0.00
(f) Other valuable consideration subject to land transfer tax (detail below)	0.00
(g) Value of land, building, fixtures and goodwill subject to land transfer tax (total of (a) to (f))	0.00
(h) VALUE OF ALL CHATTELS −items of tangible personal property	0.00
(i) Other considerations for transaction not included in (g) or (h) above	0.00
(j) Total consideration	0.00

4.

Explanation for nominal considerations:

s) other: Land Transfer Tax was paid in HR1256811

The land is subject to an encumbrance which has been paid in full, but for which a discharge has not yet been registered.

PROPERTY Information Record

A. Nature of Instrument: Transfer By Personal Representative

LRO 20 Registration No. HR1256979 Date: 2015/04/01

B. Property(s): PIN 07083 − 0114 Address 441 MAPLE AVENUE BURLINGTON Assessment Roll No −

C. Address for Service: 19 Richvalley Crescent
Richmond Hill, Ontario
L4E 4C8

D. (i) Last Conveyance(s): PIN 07083 − 0114 Registration No. HR1256811

(ii) Legal Description for Property Conveyed: Same as in last conveyance? Yes ☑ No ☐ Not known ☐

E. Tax Statements Prepared By: Joseph Walter Jacques Laurion
41 Wellington Street East
Aurora L4G 1H6

ENVIRONMENTAL RISK INFORMATION SERVICE

Head Office: 80 Valleybrook Dr, Toronto, ON M3B 2S9
Physical Address: 38 Lesmill Rd, Toronto, ON M3B 2T5
Phone: 416-510-5204 • Fax: 416-510-5133
info@erisinfo.com • www.erisinfo.com

City Directory Information Source
Vernon's Burlington, Ancaster, Dundas, Stoney Creek, Waterdown, Ontario City Directory

PROJECT NUMBER: 20181128007	
Site Address:	441 Maple Avenue, Burlington, Ontario
Year: 2011	
Site Listing:	-Maple Villa Long Term Care Center
Adjacent Properties:	
421 Maple Avenue	-Multi-Tenant Residential
442 Maple Avenue	-Multi-Tenant Residential
454 Maple Avenue	-Res (3 Tenants)
455 Maple Avenue	-Multi-Tenant Residential

430 Brock Avenue	-No Address Listed

PROJECT NUMBER: 20181128007	
Site Address:	441 Maple Avenue, Burlington, Ontario
Year: 2005	
Site Listing:	-Maple Villa Long Term Care Center
Adjacent Properties:	
421 Maple Avenue	-Multi-Tenant Residential
442 Maple Avenue	-Multi-Tenant Residential
454 Maple Avenue	-Res (3 Tenants)
455 Maple Avenue	-Multi-Tenant Residential
430 Brock Avenue	-No Address Listed

PROJECT NUMBER: 20181128007	

Site Address:	441 Maple Avenue, Burlington, Ontario
Year: 2000	
Site Listing:	-Maple Villa Long Term Care Center
Adjacent Properties:	
421 Maple Avenue	-Multi-Tenant Residential
442 Maple Avenue	-Multi-Tenant Residential
454 Maple Avenue	-Res (2 Tenants)
455 Maple Avenue	-Multi-Tenant Residential
430 Brock Avenue	-No Address Listed

PROJECT NUMBER: 20181128007	
Site Address:	441 Maple Avenue, Burlington, Ontario
Year: 1996	
Site Listing:	-Maple Villa Nursing Home

Adjacent Properties:	
421 Maple Avenue	-Multi-Tenant Residential
442 Maple Avenue	-Address Not Listed
454 Maple Avenue	-Res (1 Tenant)
455 Maple Avenue	-Multi-Tenant Residential
430 Brock Avenue	-No Address Listed

PROJECT NUMBER: 20181128007	
Site Address:	441 Maple Avenue, Burlington, Ontario
Year: 1990	
Site Listing:	-Maple Villa Nursing Home
Adjacent Properties:	
421 Maple Avenue	-Multi-Tenant Residential

442 Maple Avenue	-Address Not Listed
454 Maple Avenue	-Res (2 Tenants)
455 Maple Avenue	-Multi-Tenant Residential
430 Brock Avenue	-No Address Listed

PROJECT NUMBER: 20181128007	
Site Address:	441 Maple Avenue, Burlington, Ontario
Year: 1985	
Site Listing:	-Maple Villa Nursing Home
Adjacent Properties:	
421 Maple Avenue	-Multi-Tenant Residential
442 Maple Avenue	-Address Not Listed
454 Maple Avenue	-Res (2 Tenants)
455 Maple Avenue	-Multi-Tenant Residential

430 Brock Avenue	-No Address Listed

PROJECT NUMBER: 20181128007	
Site Address:	441 Maple Avenue, Burlington, Ontario
Year: 1980	
Site Listing:	-Maple Villa Nursing Home
Adjacent Properties:	
421 Maple Avenue	-Multi-Tenant Residential
442 Maple Avenue	-Address Not Listed
454 Maple Avenue	-Res (1 Tenant)
455 Maple Avenue	-Multi-Tenant Residential
430 Brock Avenue	-No Address Listed

PROJECT NUMBER: 20181128007	

Site Address:	441 Maple Avenue, Burlington, Ontario
Year: 1975	
Site Listing:	-Maple Villa Nursing Home
Adjacent Properties:	
421 Maple Avenue	-Multi-Tenant Residential
442 Maple Avenue	-Address Not Listed
454 Maple Avenue	-Res (3 Tenants)
455 Maple Avenue	-Multi-Tenant Residential
430 Brock Avenue	-No Address Listed

PROJECT NUMBER: 20181128007	
Site Address:	441 Maple Avenue, Burlington, Ontario
Year: 1970	
Site Listing:	-Maple Villa Htl

	-Res (1 Tenant)
Adjacent Properties:	
421 Maple Avenue	-Multi-Tenant Residential
442 Maple Avenue	-Address Not Listed
454 Maple Avenue	-Res (3 Tenants)
455 Maple Avenue	-Multi-Tenant Residential
430 Brock Avenue	-No Address Listed

PROJECT NUMBER: 20181128007	
Site Address:	441 Maple Avenue, Burlington, Ontario
Year: 1965	
Site Listing:	-Maple Villa Htl -Res (1 Tenant)
Adjacent Properties:	

421 Maple Avenue	-Address Not Listed
442 Maple Avenue	-Address Not Listed
454 Maple Avenue	-Res (1 Tenant)
455 Maple Avenue	-Multi-Tenant Residential
430 Brock Avenue	-No Address Listed

PROJECT NUMBER: 20181128007	
Site Address:	441 Maple Avenue, Burlington, Ontario
Year: 1960	
Site Listing:	-Address Not Listed
Adjacent Properties:	
421 Maple Avenue	-Res (1 Tenant)
442 Maple Avenue	-Address Not Listed
454 Maple Avenue	-Res (2 Tenants)

455 Maple Avenue	-Address Not Listed
430 Brock Avenue	-No Address Listed

PROJECT NUMBER: 20181128007	
Site Address:	441 Maple Avenue, Burlington, Ontario
Year: 1957	
Site Listing:	-Address Not Listed
Adjacent Properties:	
421 Maple Avenue	-Address Not Listed
442 Maple Avenue	-Address Not Listed
454 Maple Avenue	-Res (1 Tenant)
455 Maple Avenue	-Address Not Listed
430 Brock Avenue	-No Address Listed

-All listings for businesses were listed as they are in the city directory.

-Listings that are residential are listed as “residential” with the number of tenants. The name of the residential tenant is not listed in the above city directory

Burlington, Ontario is listed from 1957 to 2011 within the City Directory Archives*

ENVIRONMENTAL RISK INFORMATION SERVICES

DATABASE REPORT

Project Property:	*441 Maple Avenue, Burlington* *441 Maple Avenue* *Burlington ON L7S 1L8*
Project No:	*0025-001.01*
Report Type:	*Standard Express Report*
Order No:	*20181128007*
Requested by:	*Blue Frog Consulting*
Date Completed:	*November 28, 2018*

Environmental Risk Information Services
A division of Glacier Media Inc.
P: 1.866.517.5204
E: info@erisinfo.com

www.erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....6
Executive Summary: Site Report Summary - Surrounding Properties.....7
Executive Summary: Summary By Data Source.....13
Map.....21
Aerial.....22
Topographic Map.....23
Detail Report.....24
Unplottable Summary.....55
Unplottable Report.....68
Appendix: Database Descriptions.....158
Definitions.....167

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Limited Partnership ("ERIS") using various sources of information, including information provided by Federal and Provincial government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report(s) are protected by copyright owned by ERIS Information Limited Partnership. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:	*441 Maple Avenue, Burlington* *441 Maple Avenue Burlington ON L7S 1L8*
Project No:	*0025-001.01*

Coordinates:

Latitude:	*43.319943*
Longitude:	*-79.802892*
UTM Northing:	*4,797,040.69*
UTM Easting:	*597,066.94*
UTM Zone:	*UTM Zone 17T*

Elevation: *272 FT*
82.89 M

Order Information:

Order No:	*20181128007*
Date Requested:	*November 28, 2018*
Requested by:	*Blue Frog Consulting*
Report Type:	*Standard Express Report*

Historical/Products:

City Directory Search	*CD - Subject Site plus 5 Adjacent Properties*
Insurance Products	*Fire Insurance Maps/Inspection Reports/Site Plans*

Executive Summary: Report Summary

Database	Name	Searched	Project Property	Within 0.25 km	Total
AAGR	Abandoned Aggregate Inventory	Y	0	0	0
AGR	Aggregate Inventory	Y	0	0	0
AMIS	Abandoned Mine Information System	Y	0	0	0
ANDR	Anderson's Waste Disposal Sites	Y	0	0	0
AUWR	Automobile Wrecking & Supplies	Y	0	0	0
BORE	Borehole	Y	0	26	26
CA	Certificates of Approval	Y	0	3	3
CFOT	Commercial Fuel Oil Tanks	Y	0	0	0
CHEM	Chemical Register	Y	0	0	0
CNG	Compressed Natural Gas Stations	Y	0	0	0
COAL	Inventory of Coal Gasification Plants and Coal Tar Sites	Y	0	0	0
CONV	Compliance and Convictions	Y	0	0	0
CPU	Certificates of Property Use	Y	0	0	0
DRL	Drill Hole Database	Y	0	0	0
DRYCLEANERS	Dry Cleaning Facilities	Y	0	0	0
EASR	Environmental Activity and Sector Registry	Y	0	1	1
EBR	Environmental Registry	Y	0	1	1
ECA	Environmental Compliance Approval	Y	0	1	1
EEM	Environmental Effects Monitoring	Y	0	0	0
EHS	ERIS Historical Searches	Y	0	11	11
EIIS	Environmental Issues Inventory System	Y	0	0	0
EMHE	Emergency Management Historical Event	Y	0	0	0
EXP	List of TSSA Expired Facilities	Y	0	0	0
FCON	Federal Convictions	Y	0	0	0
FCS	Contaminated Sites on Federal Land	Y	0	0	0
FOFT	Fisheries & Oceans Fuel Tanks	Y	0	0	0
FST	Fuel Storage Tank	Y	0	0	0
FSTH	Fuel Storage Tank - Historic	Y	0	0	0
GEN	Ontario Regulation 347 Waste Generators Summary	Y	0	10	10
GHG	Greenhouse Gas Emissions from Large Facilities	Y	0	0	0
HINC	TSSA Historic Incidents	Y	0	0	0
IAFT	Indian & Northern Affairs Fuel Tanks	Y	0	0	0
INC	TSSA Incidents	Y	0	1	1
LIMO	Landfill Inventory Management Ontario	Y	0	0	0
MINE	Canadian Mine Locations	Y	0	0	0
MISA PENALTY	Environmental Penalty Annual Report	Y	0	0	0

Database	Name	Searched	Project Property	Within 0.25 km	Total
MNR	Mineral Occurrences	Y	0	0	0
NATE	National Analysis of Trends in Emergencies System (NATES)	Y	0	0	0
NCPL	Non-Compliance Reports	Y	0	0	0
NDFT	National Defense & Canadian Forces Fuel Tanks	Y	0	0	0
NDSP	National Defense & Canadian Forces Spills	Y	0	0	0
NDWD	National Defence & Canadian Forces Waste Disposal Sites	Y	0	0	0
NEBI	National Energy Board Pipeline Incidents	Y	0	0	0
NEBW	National Energy Board Wells	Y	0	0	0
NEES	National Environmental Emergencies System (NEES)	Y	0	0	0
NPCB	National PCB Inventory	Y	0	0	0
NPRI	National Pollutant Release Inventory	Y	0	0	0
OGW	Oil and Gas Wells	Y	0	0	0
OOGW	Ontario Oil and Gas Wells	Y	0	0	0
OPCB	Inventory of PCB Storage Sites	Y	0	0	0
ORD	Orders	Y	0	0	0
PAP	Canadian Pulp and Paper	Y	0	0	0
PCFT	Parks Canada Fuel Storage Tanks	Y	0	0	0
PES	Pesticide Register	Y	0	0	0
PINC	TSSA Pipeline Incidents	Y	0	2	2
PRT	Private and Retail Fuel Storage Tanks	Y	0	0	0
PTTW	Permit to Take Water	Y	0	0	0
REC	Ontario Regulation 347 Waste Receivers Summary	Y	0	0	0
RSC	Record of Site Condition	Y	0	0	0
RST	Retail Fuel Storage Tanks	Y	0	0	0
SCT	Scott's Manufacturing Directory	Y	0	3	3
SPL	Ontario Spills	Y	0	3	3
SRDS	Wastewater Discharger Registration Database	Y	0	0	0
TANK	Anderson's Storage Tanks	Y	0	0	0
TCFT	Transport Canada Fuel Storage Tanks	Y	0	0	0
VAR	TSSA Variances for Abandonment of Underground Storage Tanks	Y	0	0	0
WDS	Waste Disposal Sites - MOE CA Inventory	Y	0	0	0
WDSH	Waste Disposal Sites - MOE 1991 Historical Approval Inventory	Y	0	0	0
WWIS	Water Well Information System	Y	0	2	2
	Total:		0	64	64

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number

No records found in the selected databases for the project property.

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
1	EHS		455 Maple Avenue Burlington ON	WNW/25.2	0.29	24
2	BORE		ON	ENE/71.0	-1.11	24
3	BORE		ON	NW/75.0	0.93	24
4	BORE		ON	E/78.0	-1.00	25
5	BORE		ON	ESE/92.2	-1.93	25
6	BORE		ON	NW/95.3	1.40	26
7	BORE		ON	E/109.0	-2.09	26
8	BORE		ON	ESE/111.2	-2.07	27
9	WWIS		BURLINGTON ON ***Well ID:*** 7255142	SE/113.5	-1.48	27
10	BORE		ON	SE/119.1	-1.11	30
11	INC		1249 NORTH SHORE BOULEVARD EAST, BURLINGTON ON	SSW/124.1	0.83	30
12	EHS		1249 North Shore Blvd E Burlington ON L7S1C4	SSW/130.9	0.43	31

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
13	EHS		1249 North Shore Boulevard East Burlington ON L7S 2L7	SSW/131.3	0.03	32
13	EHS		1249 North Shore Boulevard East Burlington ON L7S 2L7	SSW/131.3	0.03	32
14	SCT	SIGMUND PUBLISHING LTD	431 BROCK AVE BURLINGTON ON L7S 1M8	NE/134.3	-0.16	32
15	BORE		ON	NNW/145.9	1.96	32
16	BORE		ON	SSE/146.0	-0.96	33
17	EHS		439 Brock Avenue Burlington ON L7S 1M8	NE/149.0	0.09	33
17	SCT	DEE SIGNS	439 BROCK AVE BURLINGTON ON L7S 1M8	NE/149.0	0.09	33
17	SCT	Dee Signs	439 Brock Ave Burlington ON L7S 1M8	NE/149.0	0.09	34
18	BORE		ON	ENE/151.0	-1.72	34
19	BORE		ON	NW/159.3	1.96	35
20	PINC		N W CONER OF ELGIN AND BROCK, BURLINGTON ON	N/159.8	1.42	35
21	EHS		Lakeshore Rd. W Burlington ON	SSE/162.5	-1.96	36
22	SPL	Joseph Brant Memorial Hospital<UNOFFICIAL>	1270 North Shore Bvld Burlington ON	S/170.8	-1.00	36

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
23	BORE		ON	SW/177.2	0.82	36
24	EHS		472 Brock Ave Burlington ON L7S1N1	NNW/180.4	1.68	37
25	EASR	DESTARON RESIDENTIAL INC.	480 MAPLE AVE BURLINGTON ON L7S 1M4	W/181.1	1.96	37
26	BORE		ON	NNW/186.5	1.96	37
27	BORE		ON	SSW/192.2	0.29	38
27	SPL	PUC	1237 NORTH SHORE BLVD. TRANSFORMER BURLINGTON CITY ON	SSW/192.2	0.29	38
28	CA	Burlington Cultural Centre	1333 Lakeshore Rd Burlington ON L7S 1A9	NE/197.6	-0.41	39
28	EBR	Burlington Cultural Centre	1333 Lakeshore Road Burlington, Regional Municipality of Halton L7S 1A9 CITY OF BURLINGTON ON	NE/197.6	-0.41	39
28	ECA	Burlington Cultural Centre	1333 Lakeshore Rd Burlington ON L7S 1A9	NE/197.6	-0.41	40
28	GEN	BURLINGTON ART CENTRE	1333 LAKESHORE ROAD BURLINGTON ON L7S 1A9	NE/197.6	-0.41	40
28	GEN	BURLINGTON ART CENTRE	1333 LAKESHORE ROAD BURLINGTON ON L7S 1A9	NE/197.6	-0.41	40
28	GEN	BURLINGTON ART CENTRE	1333 LAKESHORE ROAD BURLINGTON ON L7S 1A9	NE/197.6	-0.41	40

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
28	GEN	BURLINGTON ART CENTRE	1333 LAKESHORE ROAD BURLINGTON ON L7S 1A9	NE/197.6	-0.41	41
28	GEN	BURLINGTON ART CENTRE	1333 LAKESHORE ROAD BURLINGTON ON L7S 1A9	NE/197.6	-0.41	41
28	GEN	BURLINGTON ART CENTRE	1333 LAKESHORE ROAD BURLINGTON ON	NE/197.6	-0.41	41
28	GEN	ART GALLERY OF BURLINGTON	1333 LAKESHORE ROAD BURLINGTON ON L7S 1A9	NE/197.6	-0.41	41
28	GEN	ART GALLERY OF BURLINGTON	1333 LAKESHORE ROAD BURLINGTON ON L7S 1A9	NE/197.6	-0.41	42
28	GEN	ART GALLERY OF BURLINGTON	1333 LAKESHORE ROAD BURLINGTON ON L7S 1A9	NE/197.6	-0.41	42
28	GEN	ART GALLERY OF BURLINGTON	1333 LAKESHORE ROAD BURLINGTON ON L7S 1A9	NE/197.6	-0.41	42
29	BORE		ON	WNW/202.2	1.98	43
30	BORE		ON	ESE/202.8	-5.52	43
31	BORE		ON	NW/208.3	3.00	44
32	BORE		ON	SSW/210.6	1.98	44
33	EHS		Brock Avenue, between Elgin Street and Ontario Street Burlington ON	NNW/215.8	1.96	45
34	BORE		ON	WNW/218.4	2.96	45

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
35	PINC		1292 ONTARIO ST, BURLINGTON ON	NW/223.7	2.52	46
36	BORE		ON	SSE/225.5	-2.27	46
37	BORE		ON	SSE/228.3	-2.55	47
38	BORE		ON	WNW/233.8	2.99	48
39	EHS		490 Brock Avenue Burlington ON	NNW/234.5	1.96	48
39	EHS		490 Brock Avenue Burlington ON	NNW/234.5	1.96	48
39	EHS		490 Brock Avenue Burlington ON	NNW/234.5	1.96	48
40	BORE		ON	SSE/235.0	-3.29	49
41	SPL	Union Gas Limited	466 Nelson Ave. Burlington ON	N/237.0	1.96	49
42	CA	R.M. OF HALTON	NELSON AVE/LAKESHORE RD. BURLINGTON CITY ON	ENE/241.6	-0.73	50
42	CA	R.M. OF HALTON	NELSON AVE/LAKESHORE RD. BURLINGTON CITY ON	ENE/241.6	-0.73	50
43	WWIS		ON ***Well ID:*** 7292310	NNW/245.8	1.96	50
44	BORE		ON	SSE/247.5	-3.04	53

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
45	BORE		ON	WNW/250.0	2.96	54

Executive Summary: Summary By Data Source

BORE - Borehole

A search of the BORE database, dated 1875-Jul 2014 has found that there are 26 BORE site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	ON	NW	75.05	3
	ON	NW	95.29	6
	ON	NNW	145.95	15
	ON	NW	159.30	19
	ON	SW	177.17	23
	ON	NNW	186.46	26
	ON	SSW	192.17	27
	ON	WNW	202.19	29
	ON	NW	208.29	31
	ON	SSW	210.57	32

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	ON	WNW	218.35	34
	ON	WNW	233.81	38
	ON	WNW	249.99	45

Lower Elevation	Address	Direction	Distance (m)	Map Key
	ON	ENE	71.03	2
	ON	E	77.97	4
	ON	ESE	92.20	5
	ON	E	109.05	7
	ON	ESE	111.20	8
	ON	SE	119.06	10
	ON	SSE	146.04	16
	ON	ENE	150.97	18

ON	ESE	202.80	30
ON	SSE	225.49	36
ON	SSE	228.34	37
ON	SSE	234.96	40
ON	SSE	247.49	44

CA - Certificates of Approval

A search of the CA database, dated 1985-Oct 30, 2011* has found that there are 3 CA site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
Burlington Cultural Centre	1333 Lakeshore Rd Burlington ON L7S 1A9	NE	197.56	28
R.M. OF HALTON	NELSON AVE/LAKESHORE RD. BURLINGTON CITY ON	ENE	241.55	42
R.M. OF HALTON	NELSON AVE/LAKESHORE RD. BURLINGTON CITY ON	ENE	241.55	42

EASR - Environmental Activity and Sector Registry

A search of the EASR database, dated Oct 2011-Oct 31, 2018 has found that there are 1 EASR site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
DESTARON RESIDENTIAL INC.	480 MAPLE AVE BURLINGTON ON L7S 1M4	W	181.11	25

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key

EBR - Environmental Registry

A search of the EBR database, dated 1994-Oct 31, 2018 has found that there are 1 EBR site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
Burlington Cultural Centre	1333 Lakeshore Road Burlington, Regional Municipality of Halton L7S 1A9 CITY OF BURLINGTON ON	NE	197.56	28

ECA - Environmental Compliance Approval

A search of the ECA database, dated Oct 2011-Oct 31, 2018 has found that there are 1 ECA site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
Burlington Cultural Centre	1333 Lakeshore Rd Burlington ON L7S 1A9	NE	197.56	28

EHS - ERIS Historical Searches

A search of the EHS database, dated 1999-Oct 31, 2018 has found that there are 11 EHS site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	455 Maple Avenue Burlington ON	WNW	25.15	1
	1249 North Shore Blvd E Burlington ON L7S1C4	SSW	130.94	12
	1249 North Shore Boulevard East Burlington ON L7S 2L7	SSW	131.30	13
	1249 North Shore Boulevard East Burlington ON L7S 2L7	SSW	131.30	13

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	439 Brock Avenue Burlington ON L7S 1M8	NE	149.04	17
	472 Brock Ave Burlington ON L7S1N1	NNW	180.44	24
	Brock Avenue, between Elgin Street and Ontario Street Burlington ON	NNW	215.82	33
	490 Brock Avenue Burlington ON	NNW	234.46	39
	490 Brock Avenue Burlington ON	NNW	234.46	39
	490 Brock Avenue Burlington ON	NNW	234.46	39

Lower Elevation	Address	Direction	Distance (m)	Map Key
	Lakeshore Rd. W Burlington ON	SSE	162.54	21

GEN - Ontario Regulation 347 Waste Generators Summary

A search of the GEN database, dated 1986-June 30, 2018 has found that there are 10 GEN site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
BURLINGTON ART CENTRE	1333 LAKESHORE ROAD BURLINGTON ON L7S 1A9	NE	197.56	28
BURLINGTON ART CENTRE	1333 LAKESHORE ROAD BURLINGTON ON L7S 1A9	NE	197.56	28
ART GALLERY OF BURLINGTON	1333 LAKESHORE ROAD BURLINGTON ON L7S 1A9	NE	197.56	28

BURLINGTON ART CENTRE	1333 LAKESHORE ROAD BURLINGTON ON L7S 1A9	NE	197.56	28
BURLINGTON ART CENTRE	1333 LAKESHORE ROAD BURLINGTON ON	NE	197.56	28
ART GALLERY OF BURLINGTON	1333 LAKESHORE ROAD BURLINGTON ON L7S 1A9	NE	197.56	28
ART GALLERY OF BURLINGTON	1333 LAKESHORE ROAD BURLINGTON ON L7S 1A9	NE	197.56	28
BURLINGTON ART CENTRE	1333 LAKESHORE ROAD BURLINGTON ON L7S 1A9	NE	197.56	28
ART GALLERY OF BURLINGTON	1333 LAKESHORE ROAD BURLINGTON ON L7S 1A9	NE	197.56	28
BURLINGTON ART CENTRE	1333 LAKESHORE ROAD BURLINGTON ON L7S 1A9	NE	197.56	28

INC - TSSA Incidents

A search of the INC database, dated Feb 28, 2017 has found that there are 1 INC site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	1249 NORTH SHORE BOULEVARD EAST, BURLINGTON ON	SSW	124.14	11

PINC - TSSA Pipeline Incidents

A search of the PINC database, dated Feb 28, 2017 has found that there are 2 PINC site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	N W CONER OF ELGIN AND BROCK, BURLINGTON ON	N	159.82	20

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	1292 ONTARIO ST, BURLINGTON ON	NW	223.65	35

SCT - Scott's Manufacturing Directory

A search of the SCT database, dated 1992-Mar 2011* has found that there are 3 SCT site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
Dee Signs	439 Brock Ave Burlington ON L7S 1M8	NE	149.04	17
DEE SIGNS	439 BROCK AVE BURLINGTON ON L7S 1M8	NE	149.04	17

Lower Elevation	Address	Direction	Distance (m)	Map Key
SIGMUND PUBLISHING LTD	431 BROCK AVE BURLINGTON ON L7S 1M8	NE	134.32	14

SPL - Ontario Spills

A search of the SPL database, dated 1988-Jul 2018 has found that there are 3 SPL site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
PUC	1237 NORTH SHORE BLVD. TRANSFORMER BURLINGTON CITY ON	SSW	192.17	27
Union Gas Limited	466 Nelson Ave. Burlington ON	N	237.01	41


Lower Elevation	Address	Direction	Distance (m)	Map Key
Joseph Brant Memorial Hospital<UNOFFICIAL>	1270 North Shore Bvld Burlington ON	S	170.78	22

WWIS - Water Well Information System

A search of the WWIS database, dated Dec 31, 2017 has found that there are 2 WWIS site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	ON ***Well ID:*** 7292310	NNW	245.79	43

Lower Elevation	Address	Direction	Distance (m)	Map Key
	BURLINGTON ON ***Well ID:*** 7255142	SE	113.50	9



Map : 0.25 Kilometer Radius

Order No: 20181128007

Address: 441 Maple Avenue, Burlington, ON L7S 1L8 CA

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation

- Expressway
- Principal Highway
- Secondary Highway
- Major Road
- Local road
- Trail
- Proposed Road
- Ferry Route/Ice Road

- Industrial and Resource - Regions
- Main Line
- Sidetrack
- Transit Line
- Abandoned Line

- National Park
- Provincial or Territorial Park
- Other Park
- Golf Course or Driving Range
- Park or Sports Field
- Other Recreation Area

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership

79°48'W

43°19'30"N



43°19'30"N

Aerial (2017)

Address: 441 Maple Avenue, Burlington, ON L7S 1L8 CA

Source: ESRI World Imagery


Order No: 20181128007

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

© ERIS Information Limited Partnership

79°48'W

43°19'30"N



43°19'30"N

Topographic Map

Address: 441 Maple Avenue, Burlington, ON L7S 1L8 CA

Source: ESRI World Topographic Map

Order No: 20181128007

ERIS ENVIRONMENTAL RISK INFORMATION SERVICES

© ERIS Information Limited Partnership

Detail Report

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	1 of 1	WNW/25.2	83.2 / 0.29	455 Maple Avenue Burlington ON	EHS

Order No:	20111007028	**Nearest Intersection:**	Lakeshore Rd & Bellview Street
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	10/17/2011	**Search Radius (km):**	0.25
Date Received:	10/7/2011 12:33:39 PM	**X:**	-79.803171
Previous Site Name:		**Y:**	43.320042
Lot/Building Size:			
Additional Info Ordered:			

2	1 of 1	ENE/71.0	81.8 / -1.11

ON — BORE

Borehole ID:	622138	**Type:**	Borehole
Use:	Water Supply	**Status:**	
Drill Method:	Power auger	**UTM Zone:**	17
Easting:	597135	**Northing:**	4797063
Location Accuracy:		**Orig. Ground Elev m:**	81.8
Elev. Reliability Note:		**DEM Ground Elev m:**	81.7
Total Depth m:	3.5	**Primary Name:**	
Township:		**Concession:**	
Lot:		**Municipality:**	
Completion Date:	AUG-1962	**Static Water Level:**	-999.9
Primary Water Use:	Municipal	**Sec. Water Use:**	

--Details--

Stratum ID:	218424566	**Top Depth(m):**	0.0
Bottom Depth(m):	0.2	**Stratum Desc:**	SOIL. AGE POST-GLACIAL.
Stratum ID:	218424567	**Top Depth(m):**	0.2
Bottom Depth(m):	3.0	**Stratum Desc:**	SILT,CLAY. VARI-COLOURED,STIFF, AGE GLACIAL.
Stratum ID:	218424568	**Top Depth(m):**	3.0
Bottom Depth(m):	3.5	**Stratum Desc:**	BEDROCK,SHALE. RED,HARD,AGE UNDIFFERENTIATED.0000502300050 SOFT,

3	1 of 1	NW/75.0	83.8 / 0.93

ON — BORE

Borehole ID:	623507	**Type:**	Borehole
Use:	Geotechnical/Geological Investigation	**Status:**	
Drill Method:	Power auger	**UTM Zone:**	17
Easting:	597025	**Northing:**	4797103
Location Accuracy:		**Orig. Ground Elev m:**	82.9
Elev. Reliability Note:		**DEM Ground Elev m:**	84
Total Depth m:	-999	**Primary Name:**	
Township:		**Concession:**	
Lot:		**Municipality:**	
Completion Date:	MAY-1963	**Static Water Level:**	-999.9

Primary Water Use:	Not Used	**Sec. Water Use:**	

--Details--

Stratum ID:	218429751	**Top Depth(m):**	0.0
Bottom Depth(m):	3.0	**Stratum Desc:**	TILL,CLAY,SILT,SHALERED,GLACIAL,HARD, LAYERED, AGE GLACIAL.
Stratum ID:	218429752	**Top Depth(m):**	3.0
Bottom Depth(m):	4.4	**Stratum Desc:**	BEDROCK,SHALE. GREEN,BROKEN,AGE ORDOVICIAN.
Stratum ID:	218429753	**Top Depth(m):**	4.4
Bottom Depth(m):		**Stratum Desc:**	REFUSAL OF ENTRY. 0000004400090

---

4 ***1 of 1*** ***E/78.0*** ***81.9 / -1.00*** ***ON*** ***BORE***

Borehole ID:	623369	**Type:**	Borehole
Use:	Geotechnical/Geological Investigation	**Status:**	
Drill Method:	Power auger	**UTM Zone:**	17
Easting:	597145	**Northing:**	4797033
Location Accuracy:		**Orig. Ground Elev m:**	82.3
Elev. Reliability Note:		**DEM Ground Elev m:**	81.8
Total Depth m:	3.8	**Primary Name:**	
Township:		**Concession:**	
Lot:		**Municipality:**	
Completion Date:	FEB-1964	**Static Water Level:**	-999.9
Primary Water Use:	Not Used	**Sec. Water Use:**	

--Details--

Stratum ID:	218429246	**Top Depth(m):**	0.0
Bottom Depth(m):	0.3	**Stratum Desc:**	SOIL. AGE POST-GLACIAL.
Stratum ID:	218429247	**Top Depth(m):**	0.3
Bottom Depth(m):	0.8	**Stratum Desc:**	SILT,CLAY,ORGANIC, GRAVEL. AGE GLACIAL.
Stratum ID:	218429248	**Top Depth(m):**	0.8
Bottom Depth(m):	3.7	**Stratum Desc:**	TILL,CLAY,SILT, GRAVEL. GREEN,GLACIAL,HARD, AGE GLACIAL.
Stratum ID:	218429249	**Top Depth(m):**	3.7
Bottom Depth(m):	3.8	**Stratum Desc:**	BEDROCK,SHALE. RED,AGE ORDOVICIAN. 00000009000250550012060O

---

5 ***1 of 1*** ***ESE/92.2*** ***81.0 / -1.93*** ***ON*** ***BORE***

Borehole ID:	890456	**Type:**	Borehole
Use:	Geotechnical/Geological Investigation	**Status:**	Decommissioned
Drill Method:	Diamond Drill	**UTM Zone:**	17
Easting:	597145	**Northing:**	4796992
Location Accuracy:		**Orig. Ground Elev m:**	75.3
Elev. Reliability Note:		**DEM Ground Elev m:**	83.2
Total Depth m:	15.5	**Primary Name:**	
Township:	NELSON	**Concession:**	BRANTS BLOCK
Lot:		**Municipality:**	
Completion Date:	07-MAY-1963	**Static Water Level:**	-999.9
Primary Water Use:		**Sec. Water Use:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--

Stratum ID:	8501698	***Top Depth(m):***	0.0
Bottom Depth(m):	3.0	***Stratum Desc:***	Organic silt and fine sand, soft, brown with organics
Stratum ID:	8501699	***Top Depth(m):***	3.0
Bottom Depth(m):	13.9	***Stratum Desc:***	Clay, soft to medium stiff, red. Brown
Stratum ID:	8501700	***Top Depth(m):***	13.9
Bottom Depth(m):	15.5	***Stratum Desc:***	Red shale bedrock

---

6 ***1 of 1*** ***NW/95.3*** ***84.3 / 1.40*** ***ON*** ***BORE***

Borehole ID:	623506	***Type:***	Borehole
Use:	Geotechnical/Geological Investigation	***Status:***	
Drill Method:	Power auger	***UTM Zone:***	17
Easting:	596995	***Northing:***	4797103
Location Accuracy:		***Orig. Ground Elev m:***	82.9
Elev. Reliability Note:		***DEM Ground Elev m:***	84.5
Total Depth m:	-999	***Primary Name:***	
Township:		***Concession:***	
Lot:		***Municipality:***	
Completion Date:	MAY-1963	***Static Water Level:***	-999.9
Primary Water Use:	Not Used	***Sec. Water Use:***	

--Details--

Stratum ID:	218429749	***Top Depth(m):***	0.0
Bottom Depth(m):	3.0	***Stratum Desc:***	TILL,CLAY,SILT,SHALERED,GLACIAL,HARD, LAYERED, AGE GLACIAL.
Stratum ID:	218429750	***Top Depth(m):***	3.0
Bottom Depth(m):		***Stratum Desc:***	REFUSAL OF ENTRY. 0000006300050, AGE

---

7 ***1 of 1*** ***E/109.0*** ***80.8 / -2.09*** ***ON*** ***BORE***

Borehole ID:	622137	***Type:***	Borehole
Use:	Water Supply	***Status:***	
Drill Method:	Power auger	***UTM Zone:***	17
Easting:	597175	***Northing:***	4797023
Location Accuracy:		***Orig. Ground Elev m:***	81.3
Elev. Reliability Note:		***DEM Ground Elev m:***	81.4
Total Depth m:	4.4	***Primary Name:***	
Township:		***Concession:***	
Lot:		***Municipality:***	
Completion Date:	AUG-1962	***Static Water Level:***	-999.9
Primary Water Use:	Municipal	***Sec. Water Use:***	

--Details--

Stratum ID:	218424561	***Top Depth(m):***	0.0
Bottom Depth(m):	0.2	***Stratum Desc:***	SOIL. AGE POST-GLACIAL.
Stratum ID:	218424562	***Top Depth(m):***	0.2
Bottom Depth(m):	0.9	***Stratum Desc:***	SILT,SAND. BROWN,LOOSE,AGE GLACIAL.
Stratum ID:	218424563	***Top Depth(m):***	0.9
Bottom Depth(m):	2.4	***Stratum Desc:***	SILT,CLAY,GRAVEL. GREEN,STIFF,GRANULAR, AGE GLACIAL.
Stratum ID:	218424564	***Top Depth(m):***	2.4

Bottom Depth(m):	2.9	**Stratum Desc:**	CLAY. GREEN,VERY SOFT,AGE GLACIAL.
Stratum ID:	218424565	**Top Depth(m):**	2.9
Bottom Depth(m):	4.4	**Stratum Desc:**	BEDROCK,SHALE,CLAY. RED,VERY HARD, AGE UNDIFFERENTIATED. 00005007000300120008002200095192000 15

---

8 **1 of 1** **ESE/111.2** **80.8 / -2.07** **ON** **BORE**

Borehole ID:	623370	**Type:**	Borehole
Use:	Geotechnical/Geological Investigation	**Status:**	
Drill Method:	Power auger	**UTM Zone:**	17
Easting:	597175	**Northing:**	4797013
Location Accuracy:		**Orig. Ground Elev m:**	82.3
Elev. Reliability Note:		**DEM Ground Elev m:**	81.6
Total Depth m:	4.1	**Primary Name:**	
Township:		**Concession:**	
Lot:		**Municipality:**	
Completion Date:	FEB-1964	**Static Water Level:**	-999.9
Primary Water Use:	Not Used	**Sec. Water Use:**	

--Details--

Stratum ID:	218429250	**Top Depth(m):**	0.0
Bottom Depth(m):	0.2	**Stratum Desc:**	SOIL. MAN-MADE,AGE POST-GLACIAL.
Stratum ID:	218429251	**Top Depth(m):**	0.2
Bottom Depth(m):	2.4	**Stratum Desc:**	FILL,SILT,SAND MEDIUM TO COARSE. BROWN,MAN-MADE, AGE POST-GLACIAL.
Stratum ID:	218429252	**Top Depth(m):**	2.4
Bottom Depth(m):	4.0	**Stratum Desc:**	TILL,CLAY,SILT, GRAVEL. GLACIAL,VERY SOFT,AGE GLACIAL.
Stratum ID:	218429253	**Top Depth(m):**	4.0
Bottom Depth(m):	4.1	**Stratum Desc:**	BEDROCK,SHALE. RED,AGE ORDOVICIAN. 00080020

---

9 **1 of 1** **SE/113.5** **81.4 / -1.48** **BURLINGTON ON** **WWIS**

Well ID:	7255142	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring	**Date Received:**	12/30/2015
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Observation Wells	**Abandonment Rec:**	
Water Type:		**Contractor:**	7472
Casing Material:		**Form Version:**	7
Audit No:	Z224525	**Owner:**	
Tag:	A192541	**Street Name:**	NORTH SHORE BLVD. E. & LAKESHORE RD. (NORTHWEST CORNER APPROX. 15 W OF LAKESHORE)
Construction Method:		**County:**	HALTON
Elevation (m):		**Municipality:**	BURLINGTON CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	

Clear/Cloudy:

Bore Hole Information

Bore Hole ID:	1005850664	***Elevation:***	82.47
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	597139
Code OB Desc:		***Org CS:***	UTM83
Open Hole:		***North83:***	4796953
Cluster Kind:		***UTMRC:***	4
Date Completed:	05-NOV-15	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1005962625
Layer:	3
Color:	7
General Color:	RED
Mat1:	17
Most Common Material:	SHALE
Mat2:	
Other Materials:	
Mat3:	73
Other Materials:	HARD
Formation Top Depth:	8
Formation End Depth:	10
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005962624
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	08
Most Common Material:	FINE SAND
Mat2:	11
Other Materials:	GRAVEL
Mat3:	79
Other Materials:	PACKED
Formation Top Depth:	2
Formation End Depth:	8
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005962623
Layer:	1
Color:	2
General Color:	GREY
Mat1:	11

Most Common Material:	GRAVEL
Mat2:	11
Other Materials:	GRAVEL
Mat3:	73
Other Materials:	HARD
Formation Top Depth:	0
Formation End Depth:	2
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005962633
Layer:	2
Plug From:	5
Plug To:	10
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005962632
Layer:	1
Plug From:	0
Plug To:	5
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1005962631
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1005962622
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005962628
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	5
Casing Diameter:	2
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1005962629
Layer:	1
Slot:	10
Screen Top Depth:	5
Screen End Depth:	10

Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.5

Water Details

Water ID:	1005962627
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1005962626
Diameter:	8.5
Depth From:	0
Depth To:	10
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

10 ***1 of 1*** ***SE/119.1*** ***81.8 / -1.11*** ***ON*** ***BORE***

Borehole ID:	622136	**Type:**	Borehole
Use:	Water Supply	**Status:**	
Drill Method:	Power auger	**UTM Zone:**	17
Easting:	597135	**Northing:**	4796943
Location Accuracy:		**Orig. Ground Elev m:**	81.4
Elev. Reliability Note:		**DEM Ground Elev m:**	82.3
Total Depth m:	4	**Primary Name:**	
Township:		**Concession:**	
Lot:		**Municipality:**	
Completion Date:	AUG-1962	**Static Water Level:**	-999.9
Primary Water Use:	Municipal	**Sec. Water Use:**	

--Details--

Stratum ID:	218424556	**Top Depth(m):**	0.0
Bottom Depth(m):	0.3	**Stratum Desc:**	SOIL. SURFACE,AGE POST-GLACIAL.
Stratum ID:	218424557	**Top Depth(m):**	0.3
Bottom Depth(m):	0.8	**Stratum Desc:**	SILT,SAND. BROWN,AMORPHOUS,AGE GLACIAL.
Stratum ID:	218424558	**Top Depth(m):**	0.8
Bottom Depth(m):	1.8	**Stratum Desc:**	SILT. BROWN,COMPACT,AGE GLACIAL.
Stratum ID:	218424559	**Top Depth(m):**	1.8
Bottom Depth(m):	2.4	**Stratum Desc:**	SILT,CLAY. STIFF,AGE GLACIAL.
Stratum ID:	218424560	**Top Depth(m):**	2.4
Bottom Depth(m):	4.0	**Stratum Desc:**	CLAY,SHALE. RED,HARD,AGE GLACIAL. 0001002200025006000600120008010 4

---

11 ***1 of 1*** ***SSW/124.1*** ***83.7 / 0.83*** ***1249 NORTH SHORE BOULEVARD EAST, BURLINGTON ON*** ***INC***

Incident No:	1553158

Incident ID:	
Attribute Category:	FS-Perform L1 Incident Insp
Status Code:	
Incident Location:	1249 NORTH SHORE BOULEVARD EAST, BURLINGTON - CO RELEASE
Drainage System:	
Sub Surface Contam.:	
Aff. Prop. Use Water:	
Contam. Migrated:	
Contact Natural Env.:	
Near Body of Water:	
Approx. Quant. Rel.:	
Equipment Model:	
Serial No:	
Residential App. Type:	
Commercial App. Type:	
Industrial App. Type:	
Institutional App. Type:	
Venting Type:	
Vent Connector Mater:	
Vent Chimney Mater:	
Pipeline Type:	
Pipeline Involved:	
Pipe Material:	
Depth Ground Cover:	
Regulator Location:	
Regulator Type:	
Operation Pressure:	
Liquid Prop Make:	
Liquid Prop Model:	
Liquid Prop Serial No:	
Equipment Type:	
Cylinder Capacity:	
Cylinder Capac. Units:	
Cylinder Material Type:	
Tank Capacity:	
Fuels Occurence Type:	CO Release
Fuel Type Involved:	Natural Gas
Date of Occurence:	2015/01/10 00:00:00
Time of Occurence:	NULL
Occur Insp Start Date:	2015/01/12 00:00:00
Any Health Impact:	No
Any Environmental Impact:	No
Was Service Interrupted:	Yes
Was Property Damaged:	No
Operation Type Involved:	Multi-unit Residential
Enforcement Policy:	NULL
Prc Escalation Required:	NULL
Task No:	5318234
Notes:	
Occurence Narrative:	NULL
Tank Material Type:	
Tank Storage Type:	
Tank Location Type:	
Pump Flow Rate Capac:	
Liquid Prop Notes:	

12	1 of 1	SSW/130.9	83.3 / 0.43	1249 North Shore Blvd E Burlington ON L7S1C4	EHS

Order No:	20150501087	**Nearest Intersection:**	
Status:	C	**Municipality:**	Burlington
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	08-MAY-15	**Search Radius (km):**	.25
Date Received:	01-MAY-15	**X:**	-79.803342

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Previous Site Name: | **Y:** 43.318811
Lot/Building Size:
Additional Info Ordered:

---

13 *1 of 2* *SSW/131.3* *82.9 / 0.03*

1249 North Shore Boulevard East
Burlington ON L7S 2L7

EHS

Order No:	20180907054	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	12-SEP-18	**Search Radius (km):**	.25
Date Received:	07-SEP-18	**X:**	-79.803277
Previous Site Name:		**Y:**	43.318795
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

---

13 *2 of 2* *SSW/131.3* *82.9 / 0.03*

1249 North Shore Boulevard East
Burlington ON L7S 2L7

EHS

Order No:	20180907054	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	12-SEP-18	**Search Radius (km):**	.25
Date Received:	07-SEP-18	**X:**	-79.803277
Previous Site Name:		**Y:**	43.318795
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

---

14 *1 of 1* *NE/134.3* *82.7 / -0.16*

SIGMUND PUBLISHING LTD
431 BROCK AVE
BURLINGTON ON L7S 1M8

SCT

Established:	1953
Plant Size (ft²):	0
Employment:	1

--Details--

Description:	PERIODICALS: PUBLISHING, OR PUBLISHING & PRINTING
SIC/NAICS Code:	2721

---

15 *1 of 1* *NNW/145.9* *84.8 / 1.96*

ON

BORE

Borehole ID:	623699	**Type:**	Borehole
Use:	Geotechnical/Geological Investigation	**Status:**	
Drill Method:	Diamond Drill	**UTM Zone:**	17
Easting:	597005	**Northing:**	4797173
Location Accuracy:		**Orig. Ground Elev m:**	82.9
Elev. Reliability Note:		**DEM Ground Elev m:**	85.1
Total Depth m:	5.2	**Primary Name:**	
Township:		**Concession:**	
Lot:		**Municipality:**	
Completion Date:	JUL-1964	**Static Water Level:**	-999.9
Primary Water Use:	Not Used	**Sec. Water Use:**	

--Details--

Stratum ID:	218430569	**Top Depth(m):**	0.9

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Bottom Depth(m):	2.0	**Stratum Desc:**	TILL,CLAY. RED,GLACIAL,HARD,AGE GLACIAL.
Stratum ID:	218430570	**Top Depth(m):**	2.0
Bottom Depth(m):	5.2	**Stratum Desc:**	BEDROCK,SHALE. RED,AGE UNDIFFERENTIATED. 00000020000301100
Stratum ID:	218430568	**Top Depth(m):**	0.0
Bottom Depth(m):	0.9	**Stratum Desc:**	CLAY,SAND. BROWN,COMPACT, AGE POST-GLACIAL.

---

16 | **1 of 1** | **SSE/146.0** | **81.9 / -0.96** | **ON** | **BORE**

Borehole ID:	622135	**Type:**	Borehole
Use:	Water Supply	**Status:**	
Drill Method:	Power auger	**UTM Zone:**	17
Easting:	597115	**Northing:**	4796903
Location Accuracy:		**Orig. Ground Elev m:**	83
Elev. Reliability Note:		**DEM Ground Elev m:**	81.7
Total Depth m:	5.9	**Primary Name:**	
Township:		**Concession:**	
Lot:		**Municipality:**	
Completion Date:	AUG-1962	**Static Water Level:**	-999.9
Primary Water Use:	Municipal	**Sec. Water Use:**	

--Details--

Stratum ID:	218424552	**Top Depth(m):**	0.0
Bottom Depth(m):	0.3	**Stratum Desc:**	SOIL. AGE POST-GLACIAL.
Stratum ID:	218424553	**Top Depth(m):**	0.3
Bottom Depth(m):	1.2	**Stratum Desc:**	SILT,SAND-FINE TO MEDIUM. BROWN,COMPACT,AGE GLACIAL.
Stratum ID:	218424554	**Top Depth(m):**	1.2
Bottom Depth(m):	5.0	**Stratum Desc:**	SILT,CLAY,SAND. GREEN,COMPACT,AGE GLACIAL.
Stratum ID:	218424555	**Top Depth(m):**	5.0
Bottom Depth(m):	5.9	**Stratum Desc:**	BEDROCK,SHALE. RED,VERY DENSE, AGE UNDIFFERENTIATED. 00010010000400200000 0

---

17 | **1 of 3** | **NE/149.0** | **83.0 / 0.09** | **439 Brock Avenue**
Burlington ON L7S 1M8 | **EHS**

Order No:	20111130026	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	12/9/2011 3:59:52 PM	**Search Radius (km):**	0.25
Date Received:	11/30/2011 3:59:52 PM	**X:**	-79.801869
Previous Site Name:		**Y:**	43.320763
Lot/Building Size:			
Additional Info Ordered:			

---

17 | **2 of 3** | **NE/149.0** | **83.0 / 0.09** | **DEE SIGNS**
439 BROCK AVE
BURLINGTON ON L7S 1M8 | **SCT**

Established: 1993

Plant Size (ft²): 800
Employment: 2

--Details--
Description: SIGNS & ADVERTISING SPECIALTIES
SIC/NAICS Code: 3993

Description: DURABLE GOODS, N.E.C.
SIC/NAICS Code: 5099

---

17 ***3 of 3*** ***NE/149.0*** ***83.0 / 0.09*** ***Dee Signs*** ***439 Brock Ave*** ***Burlington ON L7S 1M8*** ***SCT***

Established: 1993
Plant Size (ft²): 1400
Employment:

--Details--
Description: All Other Miscellaneous Wood Product Manufacturing
SIC/NAICS Code: 321999

Description: Commercial Screen Printing
SIC/NAICS Code: 323113

Description: Sign Manufacturing
SIC/NAICS Code: 339950

Description: All Other Miscellaneous Manufacturing
SIC/NAICS Code: 339990

---

18 ***1 of 1*** ***ENE/151.0*** ***81.2 / -1.72*** ***ON*** ***BORE***

Borehole ID:	622679	***Type:***	Borehole
Use:	Geotechnical/Geological Investigation	***Status:***	
Drill Method:	Power auger	***UTM Zone:***	17
Easting:	597215	***Northing:***	4797073
Location Accuracy:		***Orig. Ground Elev m:***	80.8
Elev. Reliability Note:		***DEM Ground Elev m:***	80.7
Total Depth m:	6.5	***Primary Name:***	
Township:		***Concession:***	
Lot:		***Municipality:***	
Completion Date:	FEB-1967	***Static Water Level:***	-999.9
Primary Water Use:	Not Used	***Sec. Water Use:***	

--Details--

Stratum ID:	218426657	***Top Depth(m):***	0.0
Bottom Depth(m):	1.2	***Stratum Desc:***	SAND,SILT-MEDIUM. BROWN,COMPACT,GRANULAR, AGE GLACIAL.
Stratum ID:	218426658	***Top Depth(m):***	1.2
Bottom Depth(m):	2.7	***Stratum Desc:***	CLAY,SILT,SAND MEDIUM. BROWN,VERY HARD,UNIFORM, AGE GLACIAL.
Stratum ID:	218426659	***Top Depth(m):***	2.7
Bottom Depth(m):	4.0	***Stratum Desc:***	CLAY,SILT,SAND MEDIUM. GREEN,VERY HARD,UNIFORM, AGE GLACIAL.

Stratum ID:	218426660	**Top Depth(m):**	4.0
Bottom Depth(m):	4.7	**Stratum Desc:**	SILT,SAND,CLAY. RED,VERY DENSE,GRANULAR, AGE GLACIAL.
Stratum ID:	218426661	**Top Depth(m):**	4.7
Bottom Depth(m):	6.5	**Stratum Desc:**	BEDROCK,SHALE. RED,SOFT,AGE UNDIFFERENTIATED. 023 017 011 0003812000

19 **1 of 1** **NW/159.3** **84.8 / 1.96** **ON** **BORE**

Borehole ID:	623698	**Type:**	Borehole
Use:	Geotechnical/Geological Investigation	**Status:**	
Drill Method:	Diamond Drill	**UTM Zone:**	17
Easting:	596945	**Northing:**	4797143
Location Accuracy:		**Orig. Ground Elev m:**	83.5
Elev. Reliability Note:		**DEM Ground Elev m:**	85.2
Total Depth m:	4.4	**Primary Name:**	
Township:		**Concession:**	
Lot:		**Municipality:**	
Completion Date:	JUL-1964	**Static Water Level:**	-999.9
Primary Water Use:	Not Used	**Sec. Water Use:**	

--Details--

Stratum ID:	218430565	**Top Depth(m):**	0.0
Bottom Depth(m):	1.1	**Stratum Desc:**	SAND,SILT,LOAM. BROWN,LOOSE,AGE POST-GLACIAL.
Stratum ID:	218430566	**Top Depth(m):**	1.1
Bottom Depth(m):	2.9	**Stratum Desc:**	TILL,CLAY,SAND. RED,GLACIAL,HARD,AGE GLACIAL.
Stratum ID:	218430567	**Top Depth(m):**	2.9
Bottom Depth(m):	4.4	**Stratum Desc:**	BEDROCK,SHALE. AGE UNDIFFERENTIATED. 0000000800035060 GLACIAL

20 **1 of 1** **N/159.8** **84.3 / 1.42** **N W CONER OF ELGIN AND BROCK, BURLINGTON ON** **PINC**

Incident ID:		**Health Impact:**	
Incident No:	987392	**Environment Impact:**	
Type:	FS-Pipeline Incident	**Property Damage:**	Yes
Status Code:	Pipeline Damage Reason Est	**Service Interupt:**	
Fuel Occurrence Tp:		**Enforce Policy:**	Yes
Fuel Type:		**Public Relation:**	
Tank Status:	RC Established	**Pipeline System:**	
Task No:	4231214	**Depth:**	
Spills Action Centre:		**Pipe Material:**	
Method Details:	E-mail	**PSIG:**	
Fuel Category:	Natural Gas	**Attribute Category:**	FS-Perform P-line Inc Invest
Date of Occurrence:		**Regualtor Location:**	
Occurrence Start Date:	2013/05/21		
Operation Type:			
Pipeline Type:			
Regulator Type:			
Summary:	N W CONER OF ELGIN AND BROCK, BURLINGTON - 2" PIPELINE HIT		
Reported By:	ldevay@uniongas.com		
Affiliation:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Occurrence Desc:
Damage Reason: No notification made to the one call center
Notes:

---

21 **1 of 1** **SSE/162.5** **80.9 / -1.96** **Lakeshore Rd. W**
Burlington ON
EHS

Order No:	20091111012	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	11/19/2009	**Search Radius (km):**	0.25
Date Received:	11/11/2009	**X:**	-79.80188
Previous Site Name:		**Y:**	43.31868
Lot/Building Size:			
Additional Info Ordered:			

---

22 **1 of 1** **S/170.8** **81.9 / -1.00** **Joseph Brant Memorial Hospital<UNOFFICIAL>**
1270 North Shore Blvd
Burlington ON
SPL

Ref No:	1060-7TK72R	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:		**Client Type:**	
Year:		**Sector Type:**	Motor Vehicle
Incident Cause:	Discharge Or Bypass To A Watercourse	**Source Type:**	
Incident Event:		**Nearest Watercourse:**	
Contaminant Code:		**Site Name:**	outside emergency doors<UNOFFICIAL>
Contaminant Name:	FUEL (N.O.S.)	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site County/District:**	
Contaminant UN No 1:		**Site Postal Code:**	
Contaminant Qty:	0 other - see incident description	**Site Region:**	
Environment Impact:	Confirmed	**Site Municipality:**	Burlington
Nature of Impact:	Surface Water Pollution	**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	
Health/Env Conseq:		**Easting:**	
MOE Response:	No Field Response	**Site Geo Ref Accu:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Meth:**	
MOE Reported Dt:	7/1/2009	**Site Map Datum:**	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:	Watercourse Spills		
Incident Reason:	Unknown - Reason not determined		
Incident Summary:	Joseph Brant MH: fuel to cb. clning. Burlington		

---

23 **1 of 1** **SW/177.2** **83.7 / 0.82**
ON
BORE

Borehole ID:	622390	**Type:**	Borehole
Use:	Geotechnical/Geological Investigation	**Status:**	
Drill Method:	Power auger	**UTM Zone:**	17
Easting:	596945	**Northing:**	4796913
Location Accuracy:		**Orig. Ground Elev m:**	82.7
Elev. Reliability Note:		**DEM Ground Elev m:**	84.9
Total Depth m:	-999	**Primary Name:**	
Township:		**Concession:**	
Lot:		**Municipality:**	
Completion Date:	DEC-1969	**Static Water Level:**	-999.9
Primary Water Use:	Not Used	**Sec. Water Use:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--

Stratum ID:	218425401	***Top Depth(m):***	0.0
Bottom Depth(m):	0.2	***Stratum Desc:***	SOIL. AGE POST-GLACIAL.
Stratum ID:	218425402	***Top Depth(m):***	0.2
Bottom Depth(m):	2.1	***Stratum Desc:***	SAND-FINE TO MEDIUM.BROWN,COMPACT,UNIFORM, AGE GLACIAL.
Stratum ID:	218425403	***Top Depth(m):***	2.1
Bottom Depth(m):	4.6	***Stratum Desc:***	TILL,CLAY,SILT. GREEN,GLACIAL,FIRM,UNIFORM, AGE GLACIAL.
Stratum ID:	218425404	***Top Depth(m):***	4.6
Bottom Depth(m):	4.6	***Stratum Desc:***	BEDROCK,SHALE. AGE UNDIFFERENTIATED.
Stratum ID:	218425405	***Top Depth(m):***	4.6
Bottom Depth(m):		***Stratum Desc:***	REFUSAL OF ENTRY. 0000601500070007000400SHALE.

---

24 ***1 of 1*** ***NNW/180.4*** ***84.6 / 1.68*** ***472 Brock Ave Burlington ON L7S1N1*** ***EHS***

Order No:	20150724022	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Custom Report	***Client Prov/State:***	ON
Report Date:	29-JUL-15	***Search Radius (km):***	.25
Date Received:	24-JUL-15	***X:***	-79.80346
Previous Site Name:		***Y:***	43.321514
Lot/Building Size:			
Additional Info Ordered:			

---

25 ***1 of 1*** ***W/181.1*** ***84.8 / 1.96*** ***DESTARON RESIDENTIAL INC. 480 MAPLE AVE BURLINGTON ON L7S 1M4*** ***EASR***

Approval No:	R-010-1110433449	***SWP Area Name:***	Halton
Status:	REGISTERED	***MOE District:***	Halton-Peel
Date:	2018-05-03	***City:***	BURLINGTON
Record Type:	EASR	***Latitude:***	43.32
Link Source:	MOFA	***Longitude:***	-79.805
Full Address:			
Project Type:	Air Emissions		
Approval Type:	EASR-Air Emissions		
Full PDF Link:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2060183		

---

26 ***1 of 1*** ***NNW/186.5*** ***84.8 / 1.96*** ***ON*** ***BORE***

Borehole ID:	623700	***Type:***	Borehole
Use:	Geotechnical/Geological Investigation	***Status:***	
Drill Method:	Diamond Drill	***UTM Zone:***	17
Easting:	596975	***Northing:***	4797203
Location Accuracy:		***Orig. Ground Elev m:***	83.2
Elev. Reliability Note:		***DEM Ground Elev m:***	85.4
Total Depth m:	3.4	***Primary Name:***	
Township:		***Concession:***	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Lot:		**Municipality:**	
Completion Date:	JUL-1964	**Static Water Level:**	-999.9
Primary Water Use:	Not Used	**Sec. Water Use:**	

--Details--

Stratum ID:	218430571	**Top Depth(m):**	0.0
Bottom Depth(m):	1.5	**Stratum Desc:**	CLAY,SAND. BROWN,COMPACT, AGE POST-GLACIAL.
Stratum ID:	218430572	**Top Depth(m):**	1.5
Bottom Depth(m):	1.8	**Stratum Desc:**	TILL,CLAY. RED,GLACIAL,HARD,AGE GLACIAL.
Stratum ID:	218430573	**Top Depth(m):**	1.8
Bottom Depth(m):	3.4	**Stratum Desc:**	BEDROCK,SHALE. RED,AGE UNDIFFERENTIATED. 00000012000500850

---

27 **1 of 2** **SSW/192.2** **83.2 / 0.29** **ON** **BORE**

Borehole ID:	622388	**Type:**	Borehole
Use:	Geotechnical/Geological Investigation	**Status:**	
Drill Method:	Power auger	**UTM Zone:**	17
Easting:	596995	**Northing:**	4796863
Location Accuracy:		**Orig. Ground Elev m:**	82.9
Elev. Reliability Note:		**DEM Ground Elev m:**	84.7
Total Depth m:	-999	**Primary Name:**	
Township:		**Concession:**	
Lot:		**Municipality:**	
Completion Date:	DEC-1969	**Static Water Level:**	-999.9
Primary Water Use:	Not Used	**Sec. Water Use:**	

--Details--

Stratum ID:	218425389	**Top Depth(m):**	0.0
Bottom Depth(m):	0.6	**Stratum Desc:**	FILL. AGE POST-GLACIAL.
Stratum ID:	218425390	**Top Depth(m):**	0.6
Bottom Depth(m):	1.7	**Stratum Desc:**	SAND,SILT. RED,VERY LOOSE,UNIFORM, AGE GLACIAL.
Stratum ID:	218425391	**Top Depth(m):**	1.7
Bottom Depth(m):	4.7	**Stratum Desc:**	TILL,CLAY,SILT, GRAVEL. GREEN,GLACIAL,COMPACT,UNIFORM,AGE GLACIAL.
Stratum ID:	218425392	**Top Depth(m):**	4.7
Bottom Depth(m):	4.8	**Stratum Desc:**	BEDROCK,SHALE. SOFT,AGE UNDIFFERENTIATED.
Stratum ID:	218425393	**Top Depth(m):**	4.8
Bottom Depth(m):		**Stratum Desc:**	REFUSAL OF ENTRY. 00020002000550220028

---

27 **2 of 2** **SSW/192.2** **83.2 / 0.29** **PUC** **SPL**

1237 NORTH SHORE BLVD. TRANSFORMER
BURLINGTON CITY ON

Ref No:	65725	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	1/3/1992	**Client Type:**	
Year:		**Sector Type:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Incident Cause:	OTHER CONTAINER LEAK	**Source Type:**	
Incident Event:		**Nearest Watercourse:**	
Contaminant Code:		**Site Name:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site County/District:**	
Contaminant UN No 1:		**Site Postal Code:**	
Contaminant Qty:		**Site Region:**	
Environment Impact:	CONFIRMED	**Site Municipality:**	14101
Nature of Impact:	Soil Contamination	**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
Health/Env Conseq:		**Easting:**	
MOE Response:		**Site Geo Ref Accu:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Meth:**	
MOE Reported Dt:	1/3/1992	**Site Map Datum:**	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	EQUIPMENT FAILURE		
Incident Summary:	PUC -TRANSFORMER OIL TO GROUND FROM PAD-MOUNT TRANSFORMER LEAK.		

---

28 | **1 of 13** | **NE/197.6** | **82.5 / -0.41** | **Burlington Cultural Centre**
1333 Lakeshore Rd
Burlington ON L7S 1A9 | **CA**

Certificate #:	0730-8ASRWJ
Application Year:	2010
Issue Date:	11/26/2010
Approval Type:	Air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

---

28 | **2 of 13** | **NE/197.6** | **82.5 / -0.41** | **Burlington Cultural Centre**
1333 Lakeshore Road Burlington, Regional Municipality of Halton L7S 1A9 CITY OF BURLINGTON
ON | **EBR**

EBR Registry No.:	010-7490	**Proposal Date:**	August 07, 2009
Ministry Ref. No.:	2400-7UES5L	**Notice Pub Date:**	December 02, 2010
Notice Type:	Instrument Decision	**Year:**	2009
Company Name:	Burlington Cultural Centre		
Proponent Name:			
Proposal Address:	1333 Lakeshore Road, Burlington Ontario, Canada L7S 1A9		
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)		
Location Other:			
URL:			

Location:

1333 Lakeshore Road Burlington, Regional Municipality of Halton L7S 1A9 CITY OF BURLINGTON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
28	3 of 13	NE/197.6	82.5 / -0.41	Burlington Cultural Centre 1333 Lakeshore Rd Burlington ON L7S 1A9	ECA

Approval No: 0730-8ASRWJ
Approval Date: 2010-11-26
Status: Approved
Record Type: ECA
Link Source: IDS
Approval Type: ECA-AIR
Project Type: AIR
Address: 1333 Lakeshore Rd
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2400-7UES5L-14.pdf

SWP Area Name: Halton
MOE District: Halton-Peel
City: Burlington
Longitude: -79.80031
Latitude: 43.3208429999999

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
28	4 of 13	NE/197.6	82.5 / -0.41	BURLINGTON ART CENTRE 1333 LAKESHORE ROAD BURLINGTON ON L7S 1A9	GEN

Generator No.: ON2663200
Status:
Approval Years: 01,02,03,04,05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code: 8364
SIC Description: REC./CULTURE ADMIN.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 264
Waste Description: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
28	5 of 13	NE/197.6	82.5 / -0.41	BURLINGTON ART CENTRE 1333 LAKESHORE ROAD BURLINGTON ON L7S 1A9	GEN

Generator No.: ON2663200
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 611690
SIC Description: All Other Schools and Instruction

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 264
Waste Description: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
28	6 of 13	NE/197.6	82.5 / -0.41	BURLINGTON ART CENTRE 1333 LAKESHORE ROAD BURLINGTON ON L7S 1A9	GEN

Generator No.: ON2663200
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 611690
SIC Description: All Other Schools and Instruction

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Waste Code: 264
Waste Description: PHOTOPROCESSING WASTES

---

28 ***7 of 13*** ***NE/197.6*** ***82.5 / -0.41*** ***BURLINGTON ART CENTRE***
1333 LAKESHORE ROAD
BURLINGTON ON L7S 1A9 ***GEN***

Generator No.: ON2663200
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 611690
SIC Description: All Other Schools and Instruction

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 264
Waste Description: PHOTOPROCESSING WASTES

---

28 ***8 of 13*** ***NE/197.6*** ***82.5 / -0.41*** ***BURLINGTON ART CENTRE***
1333 LAKESHORE ROAD
BURLINGTON ON L7S 1A9 ***GEN***

Generator No.: ON2663200
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 611690
SIC Description: All Other Schools and Instruction

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 264
Waste Description: PHOTOPROCESSING WASTES

---

28 ***9 of 13*** ***NE/197.6*** ***82.5 / -0.41*** ***BURLINGTON ART CENTRE***
1333 LAKESHORE ROAD
BURLINGTON ON ***GEN***

Generator No.: ON2663200
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 611690
SIC Description: ALL OTHER SCHOOLS AND INSTRUCTION

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 264
Waste Description: PHOTOPROCESSING WASTES

---

28 ***10 of 13*** ***NE/197.6*** ***82.5 / -0.41*** ***ART GALLERY OF BURLINGTON***
1333 LAKESHORE ROAD ***GEN***

BURLINGTON ON L7S 1A9

Generator No.:	ON2663200	***PO Box No.:***	
Status:		***Country:***	Canada
Approval Years:	2016	***Choice of Contact:***	CO_OFFICIAL
Contam. Facility:	No	***Co Admin:***	HEATHER BORSELLINO
MHSW Facility:	No	***Phone No. Admin:***	905-632-7796 Ext.307
SIC Code:	611690		
SIC Description:	ALL OTHER SCHOOLS AND INSTRUCTION		

--Details--

Waste Code:	264
Waste Description:	PHOTOPROCESSING WASTES

---

28 ***11 of 13*** ***NE/197.6*** ***82.5 / -0.41*** ***GEN***

ART GALLERY OF BURLINGTON
1333 LAKESHORE ROAD
BURLINGTON ON L7S 1A9

Generator No.:	ON2663200	***PO Box No.:***	
Status:		***Country:***	Canada
Approval Years:	2015	***Choice of Contact:***	CO_OFFICIAL
Contam. Facility:	No	***Co Admin:***	HEATHER BORSELLINO
MHSW Facility:	No	***Phone No. Admin:***	905-632-7796 Ext.307
SIC Code:	611690		
SIC Description:	ALL OTHER SCHOOLS AND INSTRUCTION		

--Details--

Waste Code:	264
Waste Description:	PHOTOPROCESSING WASTES

---

28 ***12 of 13*** ***NE/197.6*** ***82.5 / -0.41*** ***GEN***

ART GALLERY OF BURLINGTON
1333 LAKESHORE ROAD
BURLINGTON ON L7S 1A9

Generator No.:	ON2663200	***PO Box No.:***	
Status:		***Country:***	Canada
Approval Years:	2014	***Choice of Contact:***	CO_ADMIN
Contam. Facility:	No	***Co Admin:***	HEATHER BORSELLINO
MHSW Facility:	No	***Phone No. Admin:***	905-632-7796 Ext.307
SIC Code:	611690		
SIC Description:	ALL OTHER SCHOOLS AND INSTRUCTION		

--Details--

Waste Code:	264
Waste Description:	PHOTOPROCESSING WASTES

---

28 ***13 of 13*** ***NE/197.6*** ***82.5 / -0.41*** ***GEN***

ART GALLERY OF BURLINGTON
1333 LAKESHORE ROAD
BURLINGTON ON L7S 1A9

Generator No.:	ON2663200	***PO Box No.:***	
Status:	Registered	***Country:***	Canada
Approval Years:	As of Jun 2018	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No. Admin:***	
SIC Code:			
SIC Description:			

--Details--
Waste Code: 264 T
Waste Description: Photoprocessing wastes

Waste Code: 264 L
Waste Description: Photoprocessing wastes

---

29 ***1 of 1*** ***WNW/202.2*** ***84.9 / 1.98*** ***ON*** ***BORE***

Borehole ID: 624199
Use: Geotechnical/Geological Investigation
Drill Method: Power auger
Easting: 596875
Location Accuracy:
Elev. Reliability Note:
Total Depth m: 3.2
Township:
Lot:
Completion Date: NOV-1963
Primary Water Use: Not Used

Type: Borehole
Status:
UTM Zone: 17
Northing: 4797103
Orig. Ground Elev m: 85.6
DEM Ground Elev m: 85.4
Primary Name:
Concession:
Municipality:
Static Water Level: -999.9
Sec. Water Use:

--Details--
Stratum ID: 218432881
Bottom Depth(m): 0.2
Top Depth(m): 0.0
Stratum Desc: SOIL. AGE POST-GLACIAL.

Stratum ID: 218432882
Bottom Depth(m): 1.0
Top Depth(m): 0.2
Stratum Desc: SILT,SAND-MEDIUM. BROWN,VERY LOOSE,AGE GLACIAL.

Stratum ID: 218432883
Bottom Depth(m): 1.7
Top Depth(m): 1.0
Stratum Desc: TILL,SILT,SAND,CLAY.BROWN,GLACIAL,HARD, AGE GLACIAL.

Stratum ID: 218432884
Bottom Depth(m): 3.2
Top Depth(m): 1.7
Stratum Desc: TILL,SILT,SAND,CLAY.GREEN,GLACIAL,HARD, AGE GLACIAL.
00008003000330250005507O

---

30 ***1 of 1*** ***ESE/202.8*** ***77.4 / -5.52*** ***ON*** ***BORE***

Borehole ID: 623657
Use: Geotechnical/Geological Investigation
Drill Method: Diamond Drill
Easting: 597245
Location Accuracy:
Elev. Reliability Note:
Total Depth m: 6.8
Township:
Lot:
Completion Date: MAY-1969
Primary Water Use: Not Used

Type: Borehole
Status:
UTM Zone: 17
Northing: 4796943
Orig. Ground Elev m: 79.5
DEM Ground Elev m: 78.4
Primary Name:
Concession:
Municipality:
Static Water Level: -999.9
Sec. Water Use:

--Details--
Stratum ID: 218430436
Bottom Depth(m): 0.5
Top Depth(m): 0.0
Stratum Desc: FILL,SAND,GRAVEL. BLACK,COMPACT, AGE POST-GLACIAL.

Stratum ID:	218430437	**Top Depth(m):**	0.5
Bottom Depth(m):	2.1	**Stratum Desc:**	CLAY,SILT,GRAVEL. BROWN,VERY SOFT,AGE GLACIAL.
Stratum ID:	218430438	**Top Depth(m):**	2.1
Bottom Depth(m):	6.8	**Stratum Desc:**	BEDROCK,SHALE, LIMESTONE. RED,WEATHERED, AGE UNDIFFERENTIATED. 0000001000016060

---

31 ***1 of 1*** ***NW/208.3*** ***85.9 / 3.00*** ***ON*** ***BORE***

Borehole ID:	623984	**Type:**	Borehole
Use:	Geotechnical/Geological Investigation	**Status:**	
Drill Method:	Power auger	**UTM Zone:**	17
Easting:	596915	**Northing:**	4797183
Location Accuracy:		**Orig. Ground Elev m:**	87.4
Elev. Reliability Note:		**DEM Ground Elev m:**	85.5
Total Depth m:	11.1	**Primary Name:**	
Township:		**Concession:**	
Lot:		**Municipality:**	
Completion Date:	MAY-1968	**Static Water Level:**	-999.9
Primary Water Use:	Not Used	**Sec. Water Use:**	

--Details--

Stratum ID:	218431726	**Top Depth(m):**	0.0
Bottom Depth(m):	0.3	**Stratum Desc:**	SOIL. LOOSE,AGE POST-GLACIAL.
Stratum ID:	218431727	**Top Depth(m):**	0.3
Bottom Depth(m):	1.2	**Stratum Desc:**	SILT,SAND. BROWN,LACUSTRINE,LOOSE, AGE GLACIAL.
Stratum ID:	218431728	**Top Depth(m):**	1.2
Bottom Depth(m):	5.2	**Stratum Desc:**	TILL,SILT,CLAY, GRAVEL. BROWN,GLACIAL,VERY HARD, AGE GLACIAL.
Stratum ID:	218431729	**Top Depth(m):**	5.2
Bottom Depth(m):	5.6	**Stratum Desc:**	SILT,CLAY. GREEN,GLACIAL,VERY HARD, LAMINATED,AGE GLACIAL.
Stratum ID:	218431730	**Top Depth(m):**	5.6
Bottom Depth(m):	7.6	**Stratum Desc:**	TILL,SILT,CLAY, GRAVEL. BROWN,GLACIAL,VERY HARD, AGE GLACIAL.
Stratum ID:	218431731	**Top Depth(m):**	7.6
Bottom Depth(m):	11.1	**Stratum Desc:**	BEDROCK,SHALE. RED,WEATHERED, AGE UNDIFFERENTIATED. 015009023 016 016011018000

---

32 ***1 of 1*** ***SSW/210.6*** ***84.9 / 1.98*** ***ON*** ***BORE***

Borehole ID:	622389	**Type:**	Borehole
Use:	Geotechnical/Geological Investigation	**Status:**	
Drill Method:	Power auger	**UTM Zone:**	17
Easting:	596955	**Northing:**	4796863
Location Accuracy:		**Orig. Ground Elev m:**	83.5
Elev. Reliability Note:		**DEM Ground Elev m:**	85.1
Total Depth m:	-999	**Primary Name:**	
Township:		**Concession:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Lot:		**Municipality:**	
Completion Date:	DEC-1969	**Static Water Level:**	-999.9
Primary Water Use:	Not Used	**Sec. Water Use:**	

--Details--

Stratum ID:	218425394	**Top Depth(m):**	0.0
Bottom Depth(m):	0.2	**Stratum Desc:**	SOIL. AGE POST-GLACIAL.
Stratum ID:	218425395	**Top Depth(m):**	0.2
Bottom Depth(m):	1.2	**Stratum Desc:**	SAND. BROWN,LOOSE,UNIFORM, AGE GLACIAL.
Stratum ID:	218425396	**Top Depth(m):**	1.2
Bottom Depth(m):	2.1	**Stratum Desc:**	SAND,SILT. BROWN,COMPACT,UNIFORM, AGE GLACIAL.
Stratum ID:	218425397	**Top Depth(m):**	2.1
Bottom Depth(m):	3.7	**Stratum Desc:**	SAND-MEDIUM,SILT. BROWN,DENSE,UNIFORM, AGE GLACIAL.
Stratum ID:	218425398	**Top Depth(m):**	3.7
Bottom Depth(m):	4.6	**Stratum Desc:**	CLAY,SILT. GREEN,STIFF,UNIFORM, AGE GLACIAL.
Stratum ID:	218425399	**Top Depth(m):**	4.6
Bottom Depth(m):	4.9	**Stratum Desc:**	BEDROCK,SHALE. AGE UNDIFFERENTIATED.
Stratum ID:	218425400	**Top Depth(m):**	4.9
Bottom Depth(m):		**Stratum Desc:**	REFUSAL OF ENTRY. 00006006000400110007004000120013000700

---

33 **1 of 1** **NNW/215.8** **84.8 / 1.96** **Brock Avenue, between Elgin Street and Ontario Street**
Burlington ON **EHS**

Order No:	20100622054	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	7/5/2010	**Search Radius (km):**	0.25
Date Received:	6/22/2010	**X:**	-79.803494
Previous Site Name:		**Y:**	43.321836
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

---

34 **1 of 1** **WNW/218.4** **85.8 / 2.96** **ON** **BORE**

Borehole ID:	624196	**Type:**	Borehole
Use:	Geotechnical/Geological Investigation	**Status:**	
Drill Method:	Power auger	**UTM Zone:**	17
Easting:	596865	**Northing:**	4797123
Location Accuracy:		**Orig. Ground Elev m:**	85.6
Elev. Reliability Note:		**DEM Ground Elev m:**	85.3
Total Depth m:	3	**Primary Name:**	
Township:		**Concession:**	
Lot:		**Municipality:**	
Completion Date:	NOV-1963	**Static Water Level:**	-999.9
Primary Water Use:	Not Used	**Sec. Water Use:**	

--Details--

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Stratum ID:	218432871	**Top Depth(m):**	0.0
Bottom Depth(m):	0.2	**Stratum Desc:**	SOIL. AGE POST-GLACIAL.
Stratum ID:	218432872	**Top Depth(m):**	0.2
Bottom Depth(m):	0.9	**Stratum Desc:**	SILT,SAND. BROWN,LOOSE,AGE GLACIAL.
Stratum ID:	218432873	**Top Depth(m):**	0.9
Bottom Depth(m):	3.0	**Stratum Desc:**	TILL,SILT,SAND, GRAVEL. BROWN,GLACIAL,HARD, AGE GLACIAL. 00008005000300200000DENSE

---

35 **1 of 1** **NW/223.7** **85.4 / 2.52** **1292 ONTARIO ST, BURLINGTON ON** **PINC**

Incident ID:		**Health Impact:**	
Incident No:	1711618	**Environment Impact:**	
Type:	FS-Pipeline Incident	**Property Damage:**	Yes
Status Code:	Pipeline Damage Reason Est	**Service Interupt:**	
Fuel Occurrence Tp:		**Enforce Policy:**	No
Fuel Type:		**Public Relation:**	
Tank Status:	RC Established	**Pipeline System:**	
Task No:	5849360	**Depth:**	
Spills Action Centre:		**Pipe Material:**	
Method Details:	E-mail	**PSIG:**	
Fuel Category:	Natural Gas	**Attribute Category:**	FS-Perform P-line Inc Invest
Date of Occurrence:		**Regualtor Location:**	
Occurrence Start Date:	2015/10/31		
Operation Type:			
Pipeline Type:			
Regulator Type:			
Summary:	1292 ONTARIO ST, BURLINGTON-PIPELINE STRIKE-4"		
Reported By:	Faye Wang- Union Gas		
Affiliation:			
Occurrence Desc:			
Damage Reason:	None of the above, Please Explain		
Notes:			

---

36 **1 of 1** **SSE/225.5** **80.6 / -2.27** **ON** **BORE**

Borehole ID:	621945	**Type:**	Borehole
Use:	Geotechnical/Geological Investigation	**Status:**	
Drill Method:	Power auger	**UTM Zone:**	17
Easting:	597125	**Northing:**	4796823
Location Accuracy:		**Orig. Ground Elev m:**	82.8
Elev. Reliability Note:		**DEM Ground Elev m:**	80.8
Total Depth m:	6.4	**Primary Name:**	
Township:		**Concession:**	
Lot:		**Municipality:**	
Completion Date:	MAR-1967	**Static Water Level:**	-999.9
Primary Water Use:	Not Used	**Sec. Water Use:**	

--Details--

Stratum ID:	218423409	**Top Depth(m):**	0.0
Bottom Depth(m):	0.1	**Stratum Desc:**	SOIL. MAN-MADE,AGE POST-GLACIAL.
Stratum ID:	218423410	**Top Depth(m):**	0.1
Bottom Depth(m):	0.6	**Stratum Desc:**	FILL,SAND,GRAVEL. MAN-MADE,GRANULAR, AGE POST-GLACIAL.

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Stratum ID:	218423411	**Top Depth(m):**	0.6
Bottom Depth(m):	2.6	**Stratum Desc:**	SAND-MEDIUM,SILT. BROWN,LOOSE,GRANULAR, AGE GLACIAL.
Stratum ID:	218423412	**Top Depth(m):**	2.6
Bottom Depth(m):	3.2	**Stratum Desc:**	SAND,CLAY. BROWN,LOOSE,GRANULAR, AGE GLACIAL.
Stratum ID:	218423413	**Top Depth(m):**	3.2
Bottom Depth(m):	5.1	**Stratum Desc:**	CLAY,SILT. GREEN,SOFT,UNIFORM, AGE GLACIAL.
Stratum ID:	218423414	**Top Depth(m):**	5.1
Bottom Depth(m):	6.4	**Stratum Desc:**	BEDROCK,SHALE. RED,HARD,WEATHERED, AGE UNDIFFERENTIATED. 00167086F

37 **1 of 1** **SSE/228.3** **80.3 / -2.55** **ON** **BORE**

Borehole ID:	621941	**Type:**	Borehole
Use:	Geotechnical/Geological Investigation	**Status:**	
Drill Method:	Power auger	**UTM Zone:**	17
Easting:	597135	**Northing:**	4796823
Location Accuracy:		**Orig. Ground Elev m:**	82.4
Elev. Reliability Note:		**DEM Ground Elev m:**	80.6
Total Depth m:	6.5	**Primary Name:**	
Township:		**Concession:**	
Lot:		**Municipality:**	
Completion Date:	MAR-1967	**Static Water Level:**	-999.9
Primary Water Use:	Not Used	**Sec. Water Use:**	

--Details--

Stratum ID:	218423380	**Top Depth(m):**	0.0
Bottom Depth(m):	0.1	**Stratum Desc:**	SOIL.
Stratum ID:	218423381	**Top Depth(m):**	0.1
Bottom Depth(m):	0.4	**Stratum Desc:**	SAND-MEDIUM. BROWN,LOOSE,GRANULAR, AGE GLACIAL.
Stratum ID:	218423382	**Top Depth(m):**	0.4
Bottom Depth(m):	2.3	**Stratum Desc:**	SAND-MEDIUM,SILT. BROWN,LOOSE,GRANULAR, AGE GLACIAL.
Stratum ID:	218423383	**Top Depth(m):**	2.3
Bottom Depth(m):	2.7	**Stratum Desc:**	SAND-MEDIUM. BROWN,LOOSE,GRANULAR, AGE GLACIAL.
Stratum ID:	218423384	**Top Depth(m):**	2.7
Bottom Depth(m):	4.6	**Stratum Desc:**	CLAY,SILT. VERY SOFT,UNIFORM,AGE GLACIAL.
Stratum ID:	218423385	**Top Depth(m):**	4.6
Bottom Depth(m):	4.9	**Stratum Desc:**	BEDROCK,SHALE,CLAY. RED,VERY SOFT,WEATHERED, AGE UNDIFFERENTIATED.
Stratum ID:	218423386	**Top Depth(m):**	4.9
Bottom Depth(m):	6.5	**Stratum Desc:**	BEDROCK,SHALE. RED,HARD,WEATHERED, AGE UNDIFFERENTIATED. 0015002500160040

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	1 of 1	WNW/233.8	85.9 / 2.99	ON	BORE

Borehole ID: 624198
Use: Geotechnical/Geological Investigation
Drill Method: Power auger
Easting: 596845
Location Accuracy:
Elev. Reliability Note:
Total Depth m: 3.5
Township:
Lot:
Completion Date: NOV-1963
Primary Water Use: Not Used

Type: Borehole
Status:
UTM Zone: 17
Northing: 4797113
Orig. Ground Elev m: 85.6
DEM Ground Elev m: 85.5
Primary Name:
Concession:
Municipality:
Static Water Level: -999.9
Sec. Water Use:

--Details--

Stratum ID: 218432878
Bottom Depth(m): 0.2
Top Depth(m): 0.0
Stratum Desc: SOIL. AGE POST-GLACIAL.

Stratum ID: 218432879
Bottom Depth(m): 1.5
Top Depth(m): 0.2
Stratum Desc: SILT,SAND-MEDIUM. BROWN,DENSE,AGE GLACIAL.

Stratum ID: 218432880
Bottom Depth(m): 3.5
Top Depth(m): 1.5
Stratum Desc: TILL,SILT,SAND,CLAY.BROWN,GLACIAL,HARD, AGE GLACIAL. 0000801000048035,GLACIAL

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	1 of 3	NNW/234.5	84.8 / 1.96	490 Brock Avenue Burlington ON	EHS

Order No: 20170510052
Status: C
Report Type: Standard Report
Report Date: 16-MAY-17
Date Received: 10-MAY-17
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Title Searches; City Directory; Aerial Photos

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.804141
Y: 43.321847

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	2 of 3	NNW/234.5	84.8 / 1.96	490 Brock Avenue Burlington ON	EHS

Order No: 20170510052
Status: C
Report Type: Standard Report
Report Date: 16-MAY-17
Date Received: 10-MAY-17
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Title Searches; City Directory; Aerial Photos

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.804141
Y: 43.321847

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	3 of 3	NNW/234.5	84.8 / 1.96	490 Brock Avenue Burlington ON	EHS

Order No: 20170510052
Status: C
Report Type: Standard Report
Report Date: 16-MAY-17
Date Received: 10-MAY-17

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.804141

Previous Site Name: ***Y:*** 43.321847
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Title Searches; City Directory; Aerial Photos

---

40 ***1 of 1*** ***SSE/235.0*** ***79.6 / -3.29*** ***ON*** ***BORE***

Borehole ID:	621944	***Type:***	Borehole
Use:	Geotechnical/Geological Investigation	***Status:***	
Drill Method:	Power auger	***UTM Zone:***	17
Easting:	597155	***Northing:***	4796823
Location Accuracy:		***Orig. Ground Elev m:***	82.1
Elev. Reliability Note:		***DEM Ground Elev m:***	80.2
Total Depth m:	5.8	***Primary Name:***	
Township:		***Concession:***	
Lot:		***Municipality:***	
Completion Date:	MAR-1967	***Static Water Level:***	-999.9
Primary Water Use:	Not Used	***Sec. Water Use:***	

--Details--

Stratum ID:	218423402	***Top Depth(m):***	0.0
Bottom Depth(m):	0.2	***Stratum Desc:***	SOIL. MAN-MADE,AGE POST-GLACIAL.
Stratum ID:	218423403	***Top Depth(m):***	0.2
Bottom Depth(m):	0.8	***Stratum Desc:***	FILL,SAND,GRAVEL. MAN-MADE,COMPACT,GRANULAR, AGE POST-GLACIAL.
Stratum ID:	218423404	***Top Depth(m):***	0.8
Bottom Depth(m):	2.0	***Stratum Desc:***	SAND-MEDIUM,SILT. BROWN,LOOSE,GRANULAR, AGE GLACIAL.
Stratum ID:	218423405	***Top Depth(m):***	2.0
Bottom Depth(m):	2.3	***Stratum Desc:***	SAND,CLAY. BROWN,LOOSE,GRANULAR, AGE GLACIAL.
Stratum ID:	218423406	***Top Depth(m):***	2.3
Bottom Depth(m):	4.3	***Stratum Desc:***	CLAY,SILT,GRAVEL. GREEN,SOFT,UNIFORM, AGE GLACIAL.
Stratum ID:	218423407	***Top Depth(m):***	4.3
Bottom Depth(m):	5.0	***Stratum Desc:***	BEDROCK,SHALE,CLAY. RED,VERY SOFT,WEATHERED, AGE UNDIFFERENTIATED.
Stratum ID:	218423408	***Top Depth(m):***	5.0
Bottom Depth(m):	5.8	***Stratum Desc:***	BEDROCK,SHALE. RED,VERY SOFT,WEATHERED, AGE UNDIFFERENTIATED. 0014005000165020

---

41 ***1 of 1*** ***N/237.0*** ***84.8 / 1.96*** ***Union Gas Limited 466 Nelson Ave. Burlington ON*** ***SPL***

Ref No:	0465-B244SP	***Discharger Report:***	
Site No:	NA	***Material Group:***	
Incident Dt:	2018/06/25	***Client Type:***	Corporation
Year:		***Sector Type:***	Miscellaneous Communal
Incident Cause:		***Source Type:***	Pipeline/Components
Incident Event:	Leak/Break	***Nearest Watercourse:***	
Contaminant Code:	35	***Site Name:***	Line Strike Site<UNOFFICIAL>
Contaminant Name:	NATURAL GAS (METHANE)	***Site Address:***	466 Nelson Ave.

Contaminant Limit 1:		**Site District Office:**	Halton-Peel
Contam Limit Freq 1:		**Site County/District:**	Regional Municipality of Halton
Contaminant UN No 1:	1075	**Site Postal Code:**	
Contaminant Qty:	0 other - see incident description	**Site Region:**	Central
Environment Impact:		**Site Municipality:**	Burlington
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:	Air	**Northing:**	
Health/Env Conseq:	2 - Minor Environment	**Easting:**	
MOE Response:	No	**Site Geo Ref Accu:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Meth:**	
MOE Reported Dt:	2018/06/25	**Site Map Datum:**	
Dt Document Closed:	2018/06/29		
Agency Involved:			
SAC Action Class:	TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill		
Incident Reason:	Operator/Human Error		
Incident Summary:	TSSA FSB: 1.25" Plastic IP Line Strike, Made Safe		

42 | ***1 of 2*** | ***ENE/241.6*** | ***82.2 / -0.73*** | ***R.M. OF HALTON NELSON AVE/LAKESHORE RD. BURLINGTON CITY ON*** | ***CA***

Certificate #:	7-0649-97-
Application Year:	97
Issue Date:	7/10/1997
Approval Type:	Municipal water
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

42 | ***2 of 2*** | ***ENE/241.6*** | ***82.2 / -0.73*** | ***R.M. OF HALTON NELSON AVE/LAKESHORE RD. BURLINGTON CITY ON*** | ***CA***

Certificate #:	3-0845-97-
Application Year:	97
Issue Date:	7/11/1997
Approval Type:	Municipal sewage
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

43 | ***1 of 1*** | ***NNW/245.8*** | ***84.8 / 1.96*** | ***ON*** | ***WWIS***

Well ID:	7292310	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring	**Date Received:**	8/11/2017

Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Observation Wells	**Abandonment Rec:**	
Water Type:		**Contractor:**	7472
Casing Material:		**Form Version:**	7
Audit No:	Z259506	**Owner:**	
Tag:	A227455	**Street Name:**	ONTARIO ST BROCK AVE
Construction Method:		**County:**	HALTON
Elevation (m):		**Municipality:**	BURLINGTON CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1006705749	**Elevation:**	85.42
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596960
Code OB Desc:		**Org CS:**	UTM83
Open Hole:		**North83:**	4797262
Cluster Kind:		**UTMRC:**	4
Date Completed:	18-MAY-17	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1006845594
Layer:	1
Color:	7
General Color:	RED
Mat1:	01
Most Common Material:	FILL
Mat2:	05
Other Materials:	CLAY
Mat3:	79
Other Materials:	PACKED
Formation Top Depth:	0
Formation End Depth:	11
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006845595
Layer:	2
Color:	7
General Color:	RED
Mat1:	17
Most Common Material:	SHALE
Mat2:	

Other Materials:
Mat3: 73
Other Materials: HARD
Formation Top Depth: 11
Formation End Depth: 52
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006845603
Layer: 1
Plug From: 0
Plug To: 41
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006845604
Layer: 2
Plug From: 41
Plug To: 52
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1006845602
Method Construction Code: 6
Method Construction: Boring
Other Method Construction: DIAMOND

Pipe Information

Pipe ID: 1006845593
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006845599
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 42
Casing Diameter: .8
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1006845600
Layer: 1
Slot: 10
Screen Top Depth: 42
Screen End Depth: 52
Screen Material: 5
Screen Depth UOM: ft

Screen Diameter UOM: inch
Screen Diameter: 1

Water Details

Water ID: 1006845598
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1006845597
Diameter: 3
Depth From: 11
Depth To: 52
Hole Depth UOM: ft
Hole Diameter UOM: inch

Hole Diameter

Hole ID: 1006845596
Diameter: 6
Depth From: 0
Depth To: 11
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

44 **1 of 1** **SSE/247.5** **79.8 / -3.04** **ON** **BORE**

Borehole ID: 621940
Use: Geotechnical/Geological Investigation
Drill Method: Power auger
Easting: 597135
Location Accuracy:
Elev. Reliability Note:
Total Depth m: 6.1
Township:
Lot:
Completion Date: MAR-1967
Primary Water Use: Not Used
Type: Borehole
Status:
UTM Zone: 17
Northing: 4796803
Orig. Ground Elev m: 82.4
DEM Ground Elev m: 80.5
Primary Name:
Concession:
Municipality:
Static Water Level: -999.9
Sec. Water Use:

--Details--

Stratum ID: 218423373
Bottom Depth(m): 0.2
Top Depth(m): 0.0
Stratum Desc: SOIL. MAN-MADE,AGE POST-GLACIAL.

Stratum ID: 218423374
Bottom Depth(m): 0.5
Top Depth(m): 0.2
Stratum Desc: FILL,SAND. MAN-MADE,LOOSE,GRANULAR, AGE POST-GLACIAL.

Stratum ID: 218423375
Bottom Depth(m): 0.8
Top Depth(m): 0.5
Stratum Desc: CONCRETE. MAN-MADE,AGE POST-GLACIAL.

Stratum ID: 218423376
Bottom Depth(m): 2.4
Top Depth(m): 0.8
Stratum Desc: SAND-MEDIUM,SILT. BROWN,LOOSE,GRANULAR, AGE GLACIAL.

Stratum ID: 218423377
Top Depth(m): 2.4

Bottom Depth(m):	2.9	**Stratum Desc:**	SAND,CLAY. BROWN,LOOSE,GRANULAR, AGE GLACIAL.
Stratum ID:	218423378	**Top Depth(m):**	2.9
Bottom Depth(m):	4.5	**Stratum Desc:**	CLAY,SILT,GRAVEL. SOFT,UNIFORM,AGE GLACIAL.
Stratum ID:	218423379	**Top Depth(m):**	4.5
Bottom Depth(m):	6.1	**Stratum Desc:**	BEDROCK,SHALE. RED,HARD,WEATHERED, AGE UNDIFFERENTIATED. 00147060030

45 **1 of 1** **WNW/250.0** **85.8 / 2.96** **ON** **BORE**

Borehole ID:	624197	**Type:**	Borehole
Use:	Geotechnical/Geological Investigation	**Status:**	
Drill Method:	Power auger	**UTM Zone:**	17
Easting:	596835	**Northing:**	4797133
Location Accuracy:		**Orig. Ground Elev m:**	86
Elev. Reliability Note:		**DEM Ground Elev m:**	85.5
Total Depth m:	3.6	**Primary Name:**	
Township:		**Concession:**	
Lot:		**Municipality:**	
Completion Date:	NOV-1963	**Static Water Level:**	-999.9
Primary Water Use:	Not Used	**Sec. Water Use:**	

--Details--

Stratum ID:	218432874	**Top Depth(m):**	0.0
Bottom Depth(m):	0.2	**Stratum Desc:**	SOIL. AGE POST-GLACIAL.
Stratum ID:	218432875	**Top Depth(m):**	0.2
Bottom Depth(m):	2.4	**Stratum Desc:**	SILT,SAND. BROWN,DENSE,AGE GLACIAL.
Stratum ID:	218432876	**Top Depth(m):**	2.4
Bottom Depth(m):	3.4	**Stratum Desc:**	TILL,SILT,SAND,CLAY.BROWN,GLACIAL,HARD, AGE GLACIAL.
Stratum ID:	218432877	**Top Depth(m):**	3.4
Bottom Depth(m):	3.6	**Stratum Desc:**	TILL,SILT,SAND,CLAY.GREEN,GLACIAL,HARD, AGE GLACIAL. 00008010000800220011 0029

Unplottable Summary

Total: 254 Unplottable sites

DB	Company Name/Site Name	Address	City	Postal
CA	CITY	MAPLEWOOD DR. E.	BURLINGTON ON	
CA	R.M. OF HALTON	LAKESHORE RD/SHELBOURNE PLACE	OAKVILLE TOWN ON	
CA	R.M. OF HALTON	LAKESHORE RD.	BURLINGTON CITY ON	
CA	R.M. OF HALTON	PINE COVE RD./LAKESHORE RD.	BURLINGTON CITY ON	
CA	431789 ONTARIO LTD.	MAPLE CROSSING	BURLINGTON CITY ON	
CA	431789 ONTARIO LTD.	MAPLE CROSSING MAPLE SUBD.	BURLINGTON CITY ON	
CA	R.M. OF HALTON MAPLEGROVE RD.	LAKESHORE RD.	OAKVILLE TOWN ON	
CA	R.M. OF HALTON	BRANT ST/LAKESHORE RD/BATH ST.	OAKVILLE ON	
CA	Multinational Five Investments Limited	Geographic Township of Nelson	Burlington ON	
CA	The Regional Municipality of Halton	From Lakeshore Road to New St	Burlington ON	
CA	REG.MUN.OF HALTON	LAKESHORE RD.	OAKVILLE ON	
CA	BURLINGTON CITY	LAKESHORE RD.	BURLINGTON CITY ON	
CA	R.M. OF HALTON - SPRING GARDEN RD.	LAKESHORE RD.W/WILLOWRIDGE CT.	OAKVILLE TOWN ON	
CA	R.M. OF HALTON - GOODRAM DR.	LAKESHORE RD./WALKERS LINE	BURLINGTON CITY ON	
CA	OAKVILLE TOWN-LOTS 1 & 2, CONC. III & IV	LAKESHORE ROAD E./KINGSFORD	OAKVILLE TOWN ON	
CA	BEACHWOOD DEV. LTD.	INTERNAL RD. LAKESHORE RD.	BURLINGTON CITY ON	
CA	431789 ONTARIO LIMITEDC/O WINZEN REAL	MAPLE CROSSING DEVELOP.	BURLINGTON CITY ON	
CA	R.M. OF HALTON - RANDALL STREET	REYNOLDS ST./LAKESHORE RD.	OAKVILLE TOWN ON	

CA	Association of Conservation Authorities of Ontario	Various Sites Across Province of Ontario	Oakville ON
CA	The Corporation of the Town of Oakville	Chartwell Road, Lakeshore Road, Michael Terrace	Oakville ON
CA	The Regional Municipality of Halton	Lakeshore Road	Burlington ON
CA	The Corporation of the Town of Oakville	Water Street from south of Lakeshore Road to Navy St	Oakville ON
CA	The Corporation of the Town of Oakville	Burgundy Drive, Lakeshore Road and Lavender Lane	Oakville ON
CA	The Corporation of the Town of Oakville	Lakeshore Road between Great Lakes Boulevard and Mississauga St	Oakville ON
CA	ROSART PROPERTIES INC.	MAPLE AVE.	BURLINGTON ON
CA		Lots 13, 14 & 15, Nelson Industrial Park	Burlington ON
CA	GREEN BROOK CORPORATION IN TRUST	NORTH SHORE BLVD. E. (SWM)	BURLINGTON CITY ON
CA	ROSART PROPERTIES INC.	ROSART RESTAURANT MAPLE AVE.	BURLINGTON CITY ON
CA	R.M. OF HALTON	SENECA AVE./LAKESHORE RD.	BURLINGTON CITY ON
CA	431789 ONTARIO LTD.C/O WINZEN REAL ESTAT	MAPLES TOWNHOUSES	BURLINGTON CITY ON
CA	R.M. OF HALTON	INGLEWOOD DR./LAKESHORE RD.E.	BURLINGTON CITY ON
CA	431789 ONTARIO LIMITED	DRIVEWAY "A" THE MAPLES	BURLINGTON CITY ON
CA	712101 ONTARIO LTD.-PT. LOT 3, 4 & 5	LAKESHORE TOWNHOUSES	BURLINGTON CITY ON
CA	WINZEN BURLINGTON DEVELOPMENTS LTD.	MAPLE CROSSING BLVD.	BURLINGTON CITY ON
CA	R.M. OF HALTON	LAKESHORE RD. E.	OAKVILLE TOWN ON
CA	OAKVILLE TOWN	KERR ST/JOHN ST/LAKESHORE RD.	OAKVILLE TOWN ON
CA	The Regional Municipality of Halton	Lakeshore Road	Oakville ON
CA	FALCO PROPERTY - PT. LOT 4, CONC. 2 SDS	GLENDOR AVENUE, NELSON TWP.	BURLINGTON CITY ON
CA	WINZEN BURLINGTON DEVELOPMENTS LTD.	MAPLE CROSSING	BURLINGTON CITY ON
CA	R.M. OF HALTON	LAKESHORE RD.	OAKVILLE TOWN ON

CA	CASADOR CONSTRUCTION LTD.	MAPLE AVE./MAPLE EST. SUBD.	BURLINGTON CITY ON
CA	431789 ONTARIO LTD.	MAPLE CROSSING	BURLINGTON CITY ON
CA	The Corporation of the Town of Oakville	Lakeshore Rd W	Oakville ON
CA	APPLEBY COLLEGE	LAKESHORE RD. W.	OAKVILLE ON
CA	Main Sewage Pumping Station Overflow	N. side of Lakeshore Rd., E. of Woodhaven Park Dr.	Oakville ON
CA	K. FIELD RESOURCES LIMITED	ST.A/LAKESHORE RD.E.	OAKVILLE TOWN ON
CA	BURLINGTON CITY-PT. LOT 49/RP 99	RICHMOND RD./MAPLE AVE./HAGER	BURLINGTON CITY ON
CA	BURLINGTON CITY BELLVIEW ST.	MAPLE AVE.	BURLINGTON CITY ON
CA	R.M. OF HALTON LAKESHORE RD.	EASEMENT LAKESHORE RD.	OAKVILLE TOWN ON
CA	431789 ONTARIO LTD. WINZEN REAL ESTATE	DRIVEWAY MAPLE CROSSING BLVD.	BURLINGTON CITY ON
CA	The Regional Municipality of Halton	Fruitland Ave. from Lakeshore Rd. to Lakeland Cres. & Lakeland Cres. from Lakesh	Burlington ON
CA	The Regional Municipality of Halton	from Lakeshore Road to Ontario Street	Oakville ON
CA	TOWN	LAKESHORE RD.	OAKVILLE ON
CA	431789 ONTARIO LIMITED	MAPLE CROSSING BLVD.	BURLINGTON CITY ON
CA	R.M. OF HALTON	LAKESHORE RD./GOODRAM DR.	BURLINGTON CITY ON
CA	R.M. OF HALTON	LAKESHORE RD. E.	OAKVILLE TOWN ON
CA	BURLINGTON CITY	SENECA AVE./LAKESHORE RD.	BURLINGTON CITY ON
CA	R.M. OF HALTON - HAGER AVENUE	RICHMOND RD./MAPLE AVE.	BURLINGTON CITY ON
CA	MAGIC HOME BUILDERS	MAPLE CROSSING BLVD.	BURLINGTON CITY ON
CA	R.M. OF HALTON	LAKESHORE RD. EAST/KINGSFORD	OAKVILLE TOWN ON
CA	OAKVILLE TOWN XREF-7-0429-86	LAKESHORE ROAD FILE PR-976	OAKVILLE TOWN ON
CA	R.M. OF HALTON XREF 3-0737-86	LAKESHORE RD. E.	OAKVILLE TOWN ON

CA	BURLINGTON CITY	LAKESHORE RD.	BURLINGTON CITY ON
CA	Petro-Canada	Various Sites Across Province of Ontario	Oakville ON
CA	R.M. OF HALTON	LAKESHORE RD.	OAKVILLE TOWN ON
CA		Lakeshore Road	Oakville ON
CA	1118059 ONTARIO INC.	HOLLYWOOD AVE./LAKESHORE RD.	OAKVILLE TOWN ON
CA	1118059 ONTARIO INC.	HOLLYWOOD AVE./LAKESHORE RD.	OAKVILLE TOWN ON
CA	BURLINGTON CITY	LAKESHORE RD/GOODRAM DR/APPLEB	BURLINGTON CITY ON
CA	R.M. OF HALTON LAKESHORE RD. E.	LAKESHORE RD. E.	OAKVILLE TOWN ON
CA	R.M. OF HALTON	NELSON STREET	OAKVILLE TOWN ON
CA	SAGEBROOK INVESTMENTS	INTERNAL RD. LAKESHORE RD.	BURLINGTON CITY ON
CA	R.M. OF HALTON - INGLEWOOD DR.	LAKESHORE RD./WALKERS LINE	BURLINGTON CITY ON
CA	MAGIC HOME BUILDERS INC. SOUTHPOINTE COM	MAPLE CROSSING BLVD.	BURLINGTON CITY ON
CA	OAKVILLE TOWN LAKESHORE RD. E.	LAKESHORE RD.E.	OAKVILLE TOWN ON
CA	BRONTE CREEK DEVELOPMENTS LTD.	LAKESHORE R. W. P.S. FORCEMAIN	OAKVILLE TOWN ON
CA	431789 ONTARIO LIMITED	DRIVEWAY MAPLE CROSSING BLVD.	BURLINGTON CITY ON
CA	OAKVILLE TOWN	LAKESHORE RD. W.	OAKVILLE TOWN ON
CA	R.M. OF HALTON	BRANT ST/LAKESHORE RD/BATH ST.	OAKVILLE ON
CA	The Regional Municipality of Halton	From Lakeshore Road to Burnet Rd	Oakville ON
CA	Hanson Brick Ltd./Briques Hanson Ltee	Concession 1, Former Township of Nelson	Burlington ON
CA	Petro-Canada	Various Sites Across Province of Ontario	Oakville ON
CA	Petro-Canada Inc.	Various Sites Across Province of Ontario	Oakville ON
CA	Multinational Five Investments Limited	Geographic Township of Nelson	Burlington ON

CA	Chelster Hall Company Ltd.	1134, 1150, 1158 Lakeshore Road East	Oakville ON
CA	The Regional Municipality of Halton	Regina Dr	Burlington ON
CA	K. FIELD RESOURCES LIMITED	ST.A/LAKESHORE RD.E.	OAKVILLE TOWN ON
CA	NORTHAMPTON GARDENS LTD.	LOTS 38 & 40/BELLVIEW CRES.	BURLINGTON CITY ON
CA	R.M. OF HALTON	09RST ST./LAKESHORE RD.	OAKVILLE TOWN ON
CA	R.M. OF HALTON	BURLINGTON AVE/ONT.ST/BIRCH AV	BURLINGTON CITY ON
CA	R.M. OF HALTON	BURLINGTON AVE/ONT.ST/BIRCH AV	BURLINGTON CITY ON
CA	R.M. OF HALTON	LAKESHORE RD. E.	OAKVILLE TOWN ON
CA	712101 ONTARIO LTD.-PT LOT 3, 4 & 5	LAKESHORE TOWNHOUSES	BURLINGTON CITY ON
CA	FALCO PROPERTY-PT. LOT 4, CONC. 2 SDS	BENSON DRIVE, NELSON TWP.	BURLINGTON CITY ON
CA	431789 ONTARIO LIMITED	DRIVEWAY "A" "THE MAPLES"	BURLINGTON CITY ON
CA	OAKVILLE TOWN	LAKESHORE RD. E.	OAKVILLE TOWN ON
CA	The Corporation of the City of Burlington	From Lakeshore Road to New St	Burlington ON
CA	The Corporation of the Town of Oakville	Pine Avenue, Maple Avenue, Allan Street	Oakville ON
CA		Lakeshore Road	Burlington ON
CA		Brock Avenue Right-of-way	Burlington ON
CPU	O.R.E. Development Corporation	3230 Mainway, Lot 15, Registered Plan 1055, former the Township of Nelson, Burlington, Ontario, Regional Municipality of Halton CITY OF BURLINGTON	ON
EBR	General Electric Canada Incorporated	Mobile Unit Burlington Ontario Burlington	ON
EBR	Siemens Westinghouse Inc.	Part Lot 19, Designated Part 2 on Plan 20R-13876 Burlington Ontario Burlington	ON
EBR	2246763 Ontario Inc.	Mobile facility operating throughout the Province of Ontario CITY OF BURLINGTON	ON
EBR	Ford Motor Company of Canada Limited	The Canadian Road Oakville Ontario L6J 5C9 Oakville	ON
EBR	Burlington Technologies Inc.	Lot:42 Conc:4 Burlington Ontario L7L 5P2 Burlington	ON

EBR	Ford Motor Co. of Canada Ltd.	Ford Motor Company, Ontario Truck Plant - Body Shop TOWN OF OAKVILLE	ON
EBR	Specialized Welding and Fabrications Limited	Part of Lot 22, Concession 2 Oakville Ontario Oakville	ON
EBR	Central Remediation Services Inc.	816 Mayfield Road West RR 4 Georgetown, Ontario L7G 4S7 TOWN OF OAKVILLE	ON
EBR	OMG Catalysts Canada Corp.	Lot: Conc: Burlington Ontario L7R 3Y8 Burlington	ON
EBR	DMC-2 Canada Corporation	Lot: Conc: Burlington Ontario L7R 3Y8 Burlington	ON
EBR	Kerr Cadillac Pontiac Buick Inc.	410 South Service Road West Oakville Ontario L6J 5C1 Oakville	ON
EBR	Ontario Regulation 155/07, amending Ontario Regulation 482/73, made under the	Ontario Planning and Development Act, 1994.	ON
EBR	2246763 Ontario Inc.	Mobile facility operating throughout Ontario CITY OF BURLINGTON	ON
EBR	Atotech Canada Limited	Plan M265, Part Block 2, RP 20R7780, Parts 1 & 2 Burlington Ontario Burlington	ON
EBR	General Electric Canada Inc.	Pt Lt 12, Conc 3 SDS, Lot 113, 114 Oakville Ontario L6J 2X6 Oakville	ON
EBR	Ford Motor Company of Canada Limited	The Canadian Road Oakville Ontario L6J 5C9 TOWN OF OAKVILLE	ON
EBR	Amhil Enterprises	5330 Mainway Drive Burlington Ontario Burlington	ON
EBR	OMG Catalysts Canada Corp.	Lot: Conc: Burlington Ontario L7R 3Y8 Burlington	ON
EBR	Ford Motor Company of Canada	The Canadian Road Oakville Ontario Oakville	ON
EBR	Ford Motor Company of Canada Limited	The Canadian Road Oakville Ontario L6J 5C9 Oakville	ON
EBR	David Brown Union Pumps (Canada), Limited	4211 Mainway Burlington Ontario Burlington	ON
EBR	DMC-2 Canada Corporation	4261 Mainway Drive Burlington Ontario Burlington	ON
EBR	Ford Motor Company of Canada	The Canadian Road Oakville Ontario Oakville	ON
EBR	OMG Catalysts Canada Corp.	Lot: Conc: Burlington Ontario L7R 3Y8 Burlington	ON
EBR	Rice Tool & Manufacturing Inc.	Lots 13, 14 & 15, Nelson Industrial Park Burlington Ontario Burlington	ON
EBR	Ontario Concrete Products Inc.	Lot:34, 35 Conc:3 SDS, Trafalgar Oakville Ontario Oakville	ON

EBR	ALS Canada Ltd.	5420 Mainway Drive, Unit 5 & 6 Burlington Ontario L7L 6A4 Burlington	ON	
EBR	Ford Motor Company of Canada	The Canadian Road Oakville Ontario L6J 5C9 Oakville	ON	
ECA	The Regional Municipality of Halton	Maplewood Dr	Burlington ON	L6M 3L1
ECA	Suncor Energy Inc.	Various Locations in Ontario	Oakville ON	L6L 6N5
ECA	Suncor Energy Inc., Suncor Energy Products Inc., and 1277136 Alberta Ltd.	Various locations in Ontario	Oakville ON	L6L 6N5
ECA	Hydro One Networks Inc.	559 Maplegrove Rd	Oakville ON	M5G 2P5
ECA	The Regional Municipality of Halton	Lakeshore Road	Burlington ON	L6M 3L1
ECA	The Corporation of the Town of Oakville	Pine Avenue Maple Avenue Allan St	Oakville ON	
ECA	Suncor Energy Inc., Suncor Energy Products Inc., and 1277136 Alberta Ltd.	Various locations in Ontario	Oakville ON	L6L 6N5
ECA	The Regional Municipality of Halton	Lakeshore Road	Oakville ON	L6M 3L1
ECA	The Regional Municipality of Halton	Lakeshore Road	Burlington ON	L6M 3L1
ECA	Petro-Canada	Various Sites Across Province of Ontario	Oakville ON	L6L 6N5
ECA	The Corporation of the City of Burlington	Brant Street and Lakeshore Road South portion of intersection, entrance to Spencer Smith Park	Burlington ON	L7R 3Z6
ECA	The Regional Municipality of Halton	Maplehurst Avenue (Right of Way)	Oakville ON	L6M 3L1
ECA	Joseph Brant Memorial Hospital	1230 North Shore Boulevard East	Burlington ON	L7S 1W7
ECA	Suncor Energy Inc., Suncor Energy Products Inc., and 1277136 Alberta Ltd.	Various locations in Ontario	Oakville ON	L6L 6N5
ECA	Colborne Court Estates Inc.	1077 Lakeshore Road East	Oakville ON	L4Z 3K7
ECA	The Regional Municipality of Halton	Lakeshore Road	Burlington ON	L6M 3L1
ECA	Petro-Canada Inc.	Various Sites Across Province of Ontario	Oakville ON	L6L 6N5
ECA	The Regional Municipality of Halton	Fruitland Ave. from Lakeshore Rd. to Lakeland Cres. & Lakeland Cres. from Lakeshore Rd. to Fruitland Ave	Burlington ON	L6M 3L1
ECA	The Regional Municipality of Halton	Brock Ave	Burlington ON	L6M 3L1

ECA	Petro-Canada	Various Sites Across Province of Ontario	Oakville ON	L6L 6N5
ECA	Union Gas Limited	Various Sites Across Province of Ontario	Oakville ON	N7M 5M1
ECA	Suncor Energy Inc., Suncor Energy Products Inc., and 1277136 Alberta Ltd.	Various Locations in Ontario	Oakville ON	L6L 6N5
ECA	The Regional Municipality of Halton	Jones Street (Lakeshore Road to Marine Drive)	Oakville ON	L6M 3L1
ECA	Suncor Energy Inc., Suncor Energy Products Inc., and 1277136 Alberta Ltd.	Various Locations in Ontario	Oakville ON	L6L 6N5
ECA	The Corporation of the City of Burlington	Lakeshore Rd (North Shore Road to 1000m south of intersection)	Burlington ON	L7R 3Z6
ECA	Association of Conservation Authorities of Ontario	Various Sites Across Province of Ontario	Oakville ON	L3Y 4W3
ECA	The Regional Municipality of Halton	Lakeshore Road and Rebecca Street Doral Drive, Randall Street, Dunn Street and Trafalgar Street	Oakville ON	L6M 3L1
ECA	Suncor Energy Inc.	Various locations in Ontario	Oakville ON	L6L 6N5
ECA	The Regional Municipality of Halton	Regina Dr	Burlington ON	L6M 3L1
ECA	Suncor Energy Inc., Suncor Energy Products Inc., and 1277136 Alberta Ltd.	Various Locations in Ontario	Oakville ON	L6L 6N5
ECA	Rice Tool & Manufacturing Inc.	Lots 13, 14 & 15, Nelson Industrial Park	Burlington ON	L7P 2J7
GEN	UHTHOFF QUARRY COMPANY	NELSON AGGREGATE CO-C/O BOX 1070, STN B QUARRY-WEST STREET NORTH, RR #4	BURLINGTON ON	L7P 3S9
GEN	FACCA INCORPORATED	INTERSECTION OF LAKESHORE RD AND EASTPORT DR	BURLINGTON ON	L7S 1A2
GEN	HALTON, REGIONAL MUNICIPALITY OF	BURLINGTON SKYWAY WASTEWATER TREATMENT PLANT - 1125 LAKESHORE ROAD	Burlington ON	L7S 1A8
GEN	Hydro One Networks Inc.	Oakville Transformer Station 559 Maplegrove Road	Oakville ON	L6J 4W3
GEN	Hydro One Networks Inc.	Oakville Transformer Station 559 Maplegrove Road	Oakville ON	L6J 4W3
GEN	Hydro One Networks Inc.	Oakville Transformer Station 559 Maplegrove Road	Oakville ON	L6J 4W3
GEN	FACCA INCORPORATED	INTERSECTION OF LAKESHORE RD AND EASTPORT DR	BURLINGTON ON	
GEN	Metrolinx	Mi. 31.28 on the Lakeshore West Rail Corridor	Burlington ON	L7R2Y4

GEN	LINCOLN QUARRY COMPANY	NELSON AGGREGATE CO-C/O BOX 1070, STN B QUARRY-YONGE ST. OFF MOUNTAIN RD.	BURLINGTON ON	L7P 3S9
GEN	SUNCOR ENERGY PRODUCTS PARTNERSHIP	Lakeshore Blvd. West & Great Lakes Blvd.	Oakville ON	NANANA
GEN	HALTON, REGIONAL MUNICIPALITY OF	BURLINGTON SKYWAY WASTEWATER TREATMENT PLANT - 1125 LAKESHORE ROAD	Burlington ON	L7S 1A8
GEN	FACCA INCORPORATED	INTERSECTION OF LAKESHORE RD AND EASTPORT DR	BURLINGTON ON	L7S 1A2
GEN	Hydro One Networks Inc.	Oakville Transformer Station 559 Maplegrove Road	Oakville ON	L6J 4W3
GEN	Trans-Northern Pipelines Inc.	Maple Grove Rd & Royal Windsor Dr	Oakville ON	L6J 0B2
NCPL	Hanson Brick Ltd.	Concession 1, Former Township of Nelson	Burlington ON	
NPCB	FORD MOTOR CO. OF CANADA LTD.	ONTARIO TRUCK PLANT	OAKVILLE ON	
PES	MAPLEGROVE HOME HARDWARE	7-511 MAPLE GROVE VILLAGE SHOPPING CTR	OAKVILLE ON	L6J4W3
PTTW	805681 Ontario Ltd.	Lot: 3, Concession: 5 Twp Nelson, Burlington, City, Regional Municipality of Halton CITY OF BURLINGTON	ON	
PTTW	Burlington Golf and Country Club, Limited	Burlington Golf and Country Club 422 North Shore Boulevard East Lots 2 and 3, Concession Broken Front City of Burlington, Regional Municipality of Halton,	Ontario CITY OF BURLINGTON ON	
PTTW	Oakville Executive Golf Club	Part of Lot 22 and 23, Concession 2, N.D.S. Oakville Ontario L9T 2X8 TOWN OF OAKVILLE	ON	
PTTW	Camisle Golf Course	Lot 19 and 20, Concession 2NDS, Township of Nelson, City of Burlington CITY OF BURLINGTON	ON	
RST	PETRO-CANADA	FAIRVIEW & MAPLE	BURLINGTON ON	L7S1Y3
SPL	UNKNOWN	LAKE ONTARIO BRONTE HARBOUR	OAKVILLE TOWN ON	
SPL	MARINE VESSEL	LAKE ONTARIO	OAKVILLE TOWN ON	
SPL	UNKNOWN	LAKE ONTARIO BRONTE HARBOR MARINA	OAKVILLE TOWN ON	
SPL	UNKNOWN	LAKE ONTARIO - OUTFALL AT END OF BRANT ST.	BURLINGTON CITY ON	
SPL	HALTON REGION	LAKE ONTARIO	OAKVILLE TOWN ON	
SPL	HALTON, REGIONAL MUNICIPALITY	AT 1155 NORTH SHORE RD. SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS)	BURLINGTON CITY ON	

SPL	OAKVILLE HYDRO	MAPLEGROVE MALL (AT CORNWALL BEHIND FOOD CITY) TRANSFORMER	OAKVILLE TOWN ON
SPL	UNKNOWN	KENWOOD AVENUE AT LAKESHORE RD W REAR OF LAKESIDE PLAZA	BURLINGTON CITY ON
SPL		LAKE ONTARIO \	OAKVILLE TOWN ON
SPL	HALTON, REGIONAL MUNICIPALITY	LAKE ONTARIO NAVY STREET PUMPING STATION SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS)	OAKVILLE TOWN ON
SPL	UNKNOWN	LAKE ONTARIO TANNERY PARK, KERR STREET	OAKVILLE TOWN ON
SPL	PLIBRICO CANADA LIMITED	CREEK BEHIND NELSON HIGH SCHOOL BURLINGTON PLANT 4355 FAIRVIEW STREET	BURLINGTON CITY ON
SPL		Navy Street and Walker St off of Lakeshore Rd	Oakville ON
SPL		Roseland Creek between Spruce Street and Lake Ontario<UNOFFICIAL>	Burlington ON
SPL	CONTRACTOR	LAKE ONTARIO (N.O.S.)	OAKVILLE TOWN ON
SPL	HALTON, REGIONAL MUNICIPALITY	LAKE ONTARIO SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS)	BURLINGTON CITY ON
SPL	HALTON, REGIONAL MUNICIPALITY	LAKE ONTARIO SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS)	BURLINGTON CITY ON
SPL	CONTRACTOR	LAKE ONTARIO SPENCER SMITH PARK (N.O.S.)	BURLINGTON CITY ON
SPL	HALTON, REGIONAL MUNICIPALITY	LAKE ONTARIO NEAR FIRST STREET SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS)	OAKVILLE TOWN ON
SPL	HALTON, REGIONAL MUNICIPALITY	MAIN ST. & AGNES ACTON, ONTARIO SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS)	OAKVILLE TOWN ON
SPL	MCASPHALT INDUSTRIES	LAKE ONTARIO AT PETRO-CANADA DOCK BARGE	OAKVILLE TOWN ON
SPL	The Regional Municipality of Halton	Pumping Stn #4 - Main break on North Shore Blvd.<UNOFFICIAL>	Burlington ON
SPL		NELSON CREEK AT NEW STREET<UNOFFICIAL>	Burlington ON
SPL	UNKNOWN	LAKE ONTARIO, BRONTE HARBOUR	OAKVILLE TOWN ON
SPL	PRIVATE OWNER	LAKE ONTARIO, OAKVILLE HARBOUR PLEASURE CRAFT	OAKVILLE TOWN ON
SPL	UNKNOWN	MAPLE GROVE, CATCH BASIN	OAKVILLE TOWN ON
SPL	MAPLE LEAF CARTAGE	SHAW & LAKESHORE TRANSPORT TRUCK (CARGO)	OAKVILLE TOWN ON

SPL	PLEASURE CRAFT	LAKE ONTARIO INVALID ENTRY - CHOOSE ANOTHER	OAKVILLE TOWN ON
SPL	HALTON, REGIONAL MUNICIPALITY	LAKE ONTARIO SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS)	OAKVILLE TOWN ON
SPL	UNKNOWN	LAKE ONTARIO	OAKVILLE TOWN ON
SPL	BURLINGTON HYDRO-ELECTRIC COMM	LAKESHORE RD .5 K/M WEST OF WALKERS LINE TRANSFORMER	BURLINGTON CITY ON
SPL	UNKNOWN	LAKE ONTARIO VIA STORM SEWER TRAFALGAR ROAD/LAKESHORE ROAD EAST	OAKVILLE TOWN ON
SPL	PLIBRICO CANADA LIMITED	LAKE ONTARIO SHOREACRES CR.,SECORD LANE & LAKESHORE BURLINGTON PLANT 4355 FAIRVIEW STREET	BURLINGTON CITY ON
SPL	Union Gas Limited	537 North Shore Blvd E.	Burlington ON
SPL	Rankin Construction Inc.	Lakeshore Rd. at Sheldon Creek in Oakville <UNOFFICIAL>	Oakville ON
SPL	Rotomill<UNOFFICIAL>; The Corporation of the City of Burlington	MAPLE AVE N FROM LAKESHORE TO WEST ON PLAINS RD TO NORTH ON WATERDOWN RD<UNOFFICIAL>	Burlington ON
SPL		LAKESHORE AND BELLHAVEN<UNOFFICIAL>	Burlington ON
SPL	UNKNOWN	LAKE ONTARIO	BURLINGTON CITY ON
SPL	UNKNOWN	LAKE ONTARIO	OAKVILLE TOWN ON
SPL	UNKNOWN	LAKE ONTARIO, WEST OUTFALL FROM WATERSEDGE PARK	OAKVILLE TOWN ON
SPL	HALTON, REGIONAL MUNICIPALITY	MORRISON CREEK/LAKE ONTARIO/MORRISON HEIGHTS PUMPING STATION. SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS)	OAKVILLE TOWN ON
SPL	HALTON, REGIONAL MUNICIPALITY	LAKE ONTARIO, PUMPING STATION SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS)	OAKVILLE TOWN ON
SPL	Union Gas Limited	601 North Shore Blvd,	Burlington ON
SPL	1277136 Alberta Ltd.	Lakeshore Road	Oakville ON
SPL	TERRATEC ENVIRONMENTAL LTD.	AREA CREEK, SW OAKVILLE WPCP (EAST OF THIRD AND LAKESHORE) TANK TRUCK (CARGO)	OAKVILLE TOWN ON
SPL	UNKNOWN	LAKE ONTARIO IN BURLINGTON HARBOUR	BURLINGTON CITY ON
SPL	MCASPHALT INDUSTRIES	LAKE ONTARIO PETRO-CANADA DOCK BARGE	OAKVILLE TOWN ON

SPL		2463 Lakeshore Rd	Oakville ON
SPL		Bronte Creek & Ontario Street	Oakville ON
SPL	Miller Waste Systems Inc.	near Lakeshore Dr E and Alexander Dr	Oakville ON
SPL	HALTON, REGIONAL MUNICIPALITY	LAKE ONTARIO. OAKVILLE WTP.	OAKVILLE TOWN ON
SPL	HALTON, REGIONAL MUNICIPALITY	LAKE ONTARIO & SIXTEEN MILE CREEK SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS)	BURLINGTON CITY ON
SPL	UNKNOWN	LAKE ONTARIO	OAKVILLE TOWN ON
SPL	OAKVILLE HYDRO	LAKE ONTARIO TRANSFORMER	OAKVILLE TOWN ON
SPL	The Regional Municipality of Halton	108 Maplegrove Rd	Oakville ON
SPL	Union Gas Limited	134 Maple Grove Ave.	Oakville ON
SPL	Cole Engineering Group Ltd.	Lakeshore Road & Willow Ridge Crescent - 43.418620, -79.689945	Oakville ON
SPL	To be determined<UNOFFICIAL>	cb and Old Lakeshore Rd<UNOFFICIAL>	Burlington ON
SPL	CONTRACTOR	LAKE ONTARIO, FROM APPLEBY CREEK BEHIND LORD ELGIN SCHOOL (N.O.S.)	BURLINGTON CITY ON
SPL	HALTON, REGIONAL MUNICIPALITY	TO CREEK & LAKE ONTARIO FROM PUMPING STATION #5, 374 NORTH SHORE BLVD. SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS)	BURLINGTON CITY ON
SPL	MSO CONSTRUCTION	PARK 200' WEST OF CAIRN CROFT AND SOUTH OF LAKESHORE TO MORRISON CREEK. TANK TRUCK (CARGO)	OAKVILLE TOWN ON
SPL		b/t Randall St and Lakeshore Rd W Bridges	Oakville ON
SPL	CONTRACTOR	LAKE ONTARIO AT BRONTE HARBOUR (N.O.S.)	OAKVILLE TOWN ON
SPL	HALTON, REGIONAL MUNICIPALITY	LAKE ONTARIO, FROM THE MID-HALTON PUMPING STATION ON NORTH SERVICE RD. SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS)	OAKVILLE TOWN ON
SPL		Western Lake Ontario	Burlington ON
SPL		Outfall in Nelson Park just south of Longmoor	Burlington ON
SPL	UNKNOWN	SHOREACRES CREEK BETWEEN NELSON ARENA AND NELSON HIGH SCHOOL.	BURLINGTON CITY ON

SPL		Lake Ontario (just south of Oakville)	Oakville ON
SPL	Union Gas Limited	Corner of Lakeshore Rd and Great Lakes Blvd	Oakville ON
WWIS			OAKVILLE ON
WWIS			BURLINGTON ON
WWIS			Burlington ON

Unplottable Report

Site: ***CITY***
MAPLEWOOD DR. E. BURLINGTON ON

Database: ***CA***

Certificate #:	3-0211-85-006
Application Year:	85
Issue Date:	3/26/85
Approval Type:	Municipal sewage
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Site: ***R.M. OF HALTON***
LAKESHORE RD/SHELBOURNE PLACE OAKVILLE TOWN ON

Database: ***CA***

Certificate #:	3-0120-97-
Application Year:	97
Issue Date:	2/21/1997
Approval Type:	Municipal sewage
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Site: ***R.M. OF HALTON***
LAKESHORE RD. BURLINGTON CITY ON

Database: ***CA***

Certificate #:	7-0215-87-
Application Year:	87
Issue Date:	3/24/1987
Approval Type:	Municipal water
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Site: ***R.M. OF HALTON***
PINE COVE RD./LAKESHORE RD. BURLINGTON CITY ON

Database: ***CA***

Certificate #:	7-0825-94-
Application Year:	94

Issue Date: 8/22/1994
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***431789 ONTARIO LTD.***
MAPLE CROSSING BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-0328-86-
Application Year: 86
Issue Date: 5/14/1986
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***431789 ONTARIO LTD.***
MAPLE CROSSING MAPLE SUBD. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0507-86-
Application Year: 86
Issue Date: 5/15/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON MAPLEGROVE RD.***
LAKESHORE RD. OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 3-2176-87-
Application Year: 87
Issue Date: 12/23/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON***
BRANT ST/LAKESHORE RD/BATH ST. OAKVILLE ON

Database: ***CA***

Certificate #: 7-0306-98-
Application Year: 98
Issue Date: 5/7/1998
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Multinational Five Investments Limited***
Geographic Township of Nelson Burlington ON

Database: ***CA***

Certificate #: 6085-7HRKZY
Application Year: 2008
Issue Date: 8/26/2008
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Regional Municipality of Halton***
From Lakeshore Road to New St Burlington ON

Database: ***CA***

Certificate #: 7846-837RG9
Application Year: 2010
Issue Date: 3/3/2010
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***REG.MUN.OF HALTON***
LAKESHORE RD. OAKVILLE ON

Database: ***CA***

Certificate #: 7-0446-85-006
Application Year: 85
Issue Date: 6/21/85
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:

Contaminants:
Emission Control:

Site: ***BURLINGTON CITY***
LAKESHORE RD. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0826-89-
Application Year: 89
Issue Date: 5/16/1989
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON - SPRING GARDEN RD.***
LAKESHORE RD.W/WILLOWRIDGE CT. OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 7-1376-91-
Application Year: 91
Issue Date: 11/4/1991
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON - GOODRAM DR.***
LAKESHORE RD./WALKERS LINE BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-0555-92-
Application Year: 92
Issue Date: 6/16/1992
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***OAKVILLE TOWN-LOTS 1 & 2, CONC. III & IV***
LAKESHORE ROAD E./KINGSFORD OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 3-1095-90-
Application Year: 90
Issue Date: 6/26/1990
Approval Type: Municipal sewage
Status: Approved
Application Type:

Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BEACHWOOD DEV. LTD.***
INTERNAL RD. LAKESHORE RD. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0441-86-
Application Year: 86
Issue Date: 4/22/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***431789 ONTARIO LIMITEDC/O WINZEN REAL***
MAPLE CROSSING DEVELOP. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0728-87-
Application Year: 87
Issue Date: 5/22/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON - RANDALL STREET***
REYNOLDS ST./LAKESHORE RD. OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 7-0092-92-
Application Year: 92
Issue Date: 2/12/1992
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Association of Conservation Authorities of Ontario***
Various Sites Across Province of Ontario Oakville ON

Database: ***CA***

Certificate #: 9790-6XBLZC

Application Year: 2007
Issue Date: 4/27/2007
Approval Type: Waste Management Systems
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Corporation of the Town of Oakville***
Chartwell Road, Lakeshore Road, Michael Terrace Oakville ON

Database: ***CA***

Certificate #: 5806-64EKXB
Application Year: 2004
Issue Date: 9/1/2004
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Regional Municipality of Halton***
Lakeshore Road Burlington ON

Database: ***CA***

Certificate #: 2034-64ZPCP
Application Year: 2004
Issue Date: 9/22/2004
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Corporation of the Town of Oakville***
Water Street from south of Lakeshore Road to Navy St Oakville ON

Database: ***CA***

Certificate #: 7567-8C8J99
Application Year: 2010
Issue Date: 12/23/2010
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Corporation of the Town of Oakville***
Burgundy Drive, Lakeshore Road and Lavender Lane Oakville ON

Database: ***CA***

Certificate #: 0390-6RSR8W
Application Year: 2006
Issue Date: 7/24/2006
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Corporation of the Town of Oakville***
Lakeshore Road between Great Lakes Boulevard and Mississauga St Oakville ON

Database: ***CA***

Certificate #: 0287-86ALHJ
Application Year: 2010
Issue Date: 6/10/2010
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***ROSART PROPERTIES INC.***
MAPLE AVE. BURLINGTON ON

Database: ***CA***

Certificate #: 7-0655-85-006
Application Year: 85
Issue Date: 8/6/85
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site:
Lots 13, 14 & 15, Nelson Industrial Park Burlington ON

Database: ***CA***

Certificate #: 2002-4RXM52
Application Year: 00
Issue Date: 12/15/00
Approval Type: Industrial air
Status: Approved
Application Type: New Certificate of Approval
Client Name: Rice Tool & Manufacturing Inc.
Client Address: 2247 Harold Road
Client City: Burlington
Client Postal Code: L7P 2J7

Project Description: This is an application for an Air Certificate of Approval for four new exhaust fans and stacks that exhaust to atmosphere and service two new combination parts washer/dryer machines. Each parts washer/dryer machine will have two exhaust stacks, one stack will exhaust natural gas combustion emissions from a small boiler attached to each machine; the other exhaust stack will exhaust the parts washer/dryer machine.

Contaminants:
Emission Control:

Site: ***GREEN BROOK CORPORATION IN TRUST***
NORTH SHORE BLVD. E. (SWM) BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0343-97-
Application Year: 97
Issue Date: 5/1/1997
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***ROSART PROPERTIES INC.***
ROSART RESTAURANT MAPLE AVE. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-1453-87-
Application Year: 87
Issue Date: 9/23/1987
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON***
SENECA AVE./LAKESHORE RD. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0386-93-
Application Year: 93
Issue Date: 5/4/1993
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***431789 ONTARIO LTD.C/O WINZEN REAL ESTAT***
MAPLES TOWNHOUSES BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-1220-86-
Application Year: 86
Issue Date: 10/7/1986

Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON***
INGLEWOOD DR./LAKESHORE RD.E. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-0532-93-
Application Year: 93
Issue Date: 6/30/1993
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***431789 ONTARIO LIMITED***
DRIVEWAY "A" THE MAPLES BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-0569-86-
Application Year: 86
Issue Date: 6/13/1986
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***712101 ONTARIO LTD.-PT. LOT 3, 4 & 5***
LAKESHORE TOWNHOUSES BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0580-90-
Application Year: 90
Issue Date: 4/25/1990
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***WINZEN BURLINGTON DEVELOPMENTS LTD.***

Database: ***CA***

MAPLE CROSSING BLVD. BURLINGTON CITY ON

Certificate #: 3-0283-88-
Application Year: 88
Issue Date: 3/11/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON***
LAKESHORE RD. E. OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 3-0188-87-
Application Year: 87
Issue Date: 3/4/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***OAKVILLE TOWN***
KERR ST/JOHN ST/LAKESHORE RD. OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 3-0310-96-
Application Year: 96
Issue Date: 4/17/1996
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Regional Municipality of Halton***
Lakeshore Road Oakville ON

Database: ***CA***

Certificate #: 2073-7CTHD8
Application Year: 2008
Issue Date: 3/18/2008
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:

Emission Control:

Site: ***FALCO PROPERTY - PT. LOT 4, CONC. 2 SDS***
GLENDOR AVENUE, NELSON TWP. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-0368-91-
Application Year: 91
Issue Date: 4/19/1991
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***WINZEN BURLINGTON DEVELOPMENTS LTD.***
MAPLE CROSSING BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-0259-88-
Application Year: 88
Issue Date: 3/11/1988
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON***
LAKESHORE RD. OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 7-1294-86-
Application Year: 86
Issue Date: 11/4/1986
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***CASADOR CONSTRUCTION LTD.***
MAPLE AVE./MAPLE EST. SUBD. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-0464-93-
Application Year: 93
Issue Date: 6/25/1993
Approval Type: Municipal water
Status: Revised
Application Type:
Client Name:

Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***431789 ONTARIO LTD.***
MAPLE CROSSING BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0456-86-
Application Year: 86
Issue Date: 5/14/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Corporation of the Town of Oakville***
Lakeshore Rd W Oakville ON

Database: ***CA***

Certificate #: 3876-7GMQRA
Application Year: 2008
Issue Date: 7/18/2008
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***APPLEBY COLLEGE***
LAKESHORE RD. W. OAKVILLE ON

Database: ***CA***

Certificate #: 7-0467-85-006
Application Year: 85
Issue Date: 6/21/85
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Main Sewage Pumping Station Overflow***
N. side of Lakeshore Rd., E. of Woodhaven Park Dr. Oakville ON

Database: ***CA***

Certificate #: 3-1513-85-876
Application Year: 00

Issue Date: 2/22/00
Approval Type: Municipal & Private sewage
Status: Approved
Application Type: Notice
Client Name: Corporation of the Regional Municipality of Halton
Client Address: 1151 Bronte Road
Client City: Oakville
Client Postal Code: L6M 3L1
Project Description: Commissioning Rebecca Street Wastewater Storage Tank
Contaminants:
Emission Control:

Site: ***K. FIELD RESOURCES LIMITED***
ST.A/LAKESHORE RD.E. OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 7-0811-99-
Application Year: 99
Issue Date: 10/6/1999
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BURLINGTON CITY-PT. LOT 49/RP 99***
RICHMOND RD./MAPLE AVE./HAGER BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0424-91-
Application Year: 91
Issue Date: 5/1/1991
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BURLINGTON CITY BELLVIEW ST.***
MAPLE AVE. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0408-89-
Application Year: 89
Issue Date: 3/22/1989
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON LAKESHORE RD.***
EASEMENT LAKESHORE RD. OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 3-0251-86-
Application Year: 86
Issue Date: 9/4/1987
Approval Type: Municipal sewage
Status: Cancelled
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***431789 ONTARIO LTD. WINZEN REAL ESTATE***
DRIVEWAY MAPLE CROSSING BLVD. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-1608-86-
Application Year: 86
Issue Date: 1/19/1987
Approval Type: Municipal sewage
Status: Approved in 1987
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Regional Municipality of Halton***
Fruitland Ave. from Lakeshore Rd. to Lakeland Cres. & Lakeland Cres. from Lakesh Burlington ON

Database: ***CA***

Certificate #: 1661-83NPJ2
Application Year: 2010
Issue Date: 3/29/2010
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Regional Municipality of Halton***
from Lakeshore Road to Ontario Street Oakville ON

Database: ***CA***

Certificate #: 0811-6K5PD6
Application Year: 2005
Issue Date: 12/20/2005
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:

Contaminants:
Emission Control:

Site: ***TOWN***
LAKESHORE RD. OAKVILLE ON

Database: ***CA***

Certificate #: 3-0836-85-006
Application Year: 85
Issue Date: 8/9/85
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***431789 ONTARIO LIMITED***
MAPLE CROSSING BLVD. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-0535-87-
Application Year: 87
Issue Date: 5/11/1987
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON***
LAKESHORE RD./GOODRAM DR. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-1113-94-
Application Year: 94
Issue Date: 11/18/1994
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON***
LAKESHORE RD. E. OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 7-0153-87-
Application Year: 87
Issue Date: 3/4/1987
Approval Type: Municipal water
Status: Approved
Application Type:

Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BURLINGTON CITY***
SENECA AVE./LAKESHORE RD. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0244-94-
Application Year: 94
Issue Date: 3/28/1994
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON - HAGER AVENUE***
RICHMOND RD./MAPLE AVE. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-0396-91-
Application Year: 91
Issue Date: 4/25/1991
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***MAGIC HOME BUILDERS***
MAPLE CROSSING BLVD. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-0468-89-
Application Year: 89
Issue Date: 4/6/1989
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON***
LAKESHORE RD. EAST/KINGSFORD OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 7-0911-90-

Application Year: 90
Issue Date: 6/26/1990
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***OAKVILLE TOWN XREF-7-0429-86***
LAKESHORE ROAD FILE PR-976 OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 3-0737-86-
Application Year: 86
Issue Date: 6/13/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON XREF 3-0737-86***
LAKESHORE RD. E. OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 3-0578-86-
Application Year: 86
Issue Date: 6/13/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BURLINGTON CITY***
LAKESHORE RD. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0463-87-
Application Year: 87
Issue Date: 4/15/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Petro-Canada***
Various Sites Across Province of Ontario Oakville ON

Database: ***CA***

Certificate #: 3016-5ZBQQB
Application Year: 2005
Issue Date: 11/2/2005
Approval Type: Industrial Sewage Works
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON***
LAKESHORE RD. OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 3-0907-85-866
Application Year: 85
Issue Date: 1/9/87
Approval Type: Municipal sewage
Status: Received in 1985, Issued in 1986
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site:
Lakeshore Road Oakville ON

Database: ***CA***

Certificate #: 4104-4NPNGU
Application Year: 00
Issue Date: 8/31/00
Approval Type: Municipal & Private water
Status: Approved
Application Type: New Certificate of Approval
Client Name: Corporation of the Regional Municipality of Halton
Client Address: 1151 Bronte Road
Client City: Oakville
Client Postal Code: L6M 3L1
Project Description: Construction of watermains on Lakeshore Road West from Burloak Road to Mississaga Street
Contaminants:
Emission Control:

Site: ***1118059 ONTARIO INC.***
HOLLYWOOD AVE./LAKESHORE RD. OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 3-0291-96-
Application Year: 96
Issue Date: 4/12/1996
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:

Project Description:
Contaminants:
Emission Control:

Site: ***1118059 ONTARIO INC.***
HOLLYWOOD AVE./LAKESHORE RD. OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 7-0267-96-
Application Year: 96
Issue Date: 4/12/1996
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BURLINGTON CITY***
LAKESHORE RD/GOODRAM DR/APPLEB BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0058-95-
Application Year: 95
Issue Date: 2/6/1995
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON LAKESHORE RD. E.***
LAKESHORE RD. E. OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 7-0431-88-
Application Year: 88
Issue Date: 4/13/1988
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON***
NELSON STREET OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 7-0607-86-
Application Year: 86
Issue Date: 6/10/1986
Approval Type: Municipal water
Status: Approved

Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***SAGEBROOK INVESTMENTS***
INTERNAL RD. LAKESHORE RD. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-0222-86-
Application Year: 86
Issue Date: 4/2/1986
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON - INGLEWOOD DR.***
LAKESHORE RD./WALKERS LINE BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0676-92-
Application Year: 92
Issue Date: 6/16/1992
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***MAGIC HOME BUILDERS INC. SOUTHPOINTE COM***
MAPLE CROSSING BLVD. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0479-89-
Application Year: 89
Issue Date: 3/29/1989
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***OAKVILLE TOWN LAKESHORE RD. E.***
LAKESHORE RD.E. OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 3-0532-88-
Application Year: 88
Issue Date: 5/10/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BRONTE CREEK DEVELOPMENTS LTD.***
LAKESHORE R. W. P.S. FORCEMAIN OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 3-0371-88-
Application Year: 88
Issue Date: 4/6/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***431789 ONTARIO LIMITED***
DRIVEWAY MAPLE CROSSING BLVD. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-1617-86-
Application Year: 86
Issue Date: 9/12/1990
Approval Type: Municipal sewage
Status: Cancelled
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***OAKVILLE TOWN***
LAKESHORE RD. W. OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 3-1556-86-
Application Year: 86
Issue Date: 10/22/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON***
BRANT ST/LAKESHORE RD/BATH ST. OAKVILLE ON

Database: ***CA***

Certificate #: 3-0474-98-
Application Year: 98
Issue Date: 5/7/1998
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Regional Municipality of Halton***
From Lakeshore Road to Burnet Rd Oakville ON

Database: ***CA***

Certificate #: 7389-7UGHKF
Application Year: 2009
Issue Date: 8/4/2009
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Hanson Brick Ltd./Briques Hanson Ltee***
Concession 1, Former Township of Nelson Burlington ON

Database: ***CA***

Certificate #: 5414-8ETKBD
Application Year: 2011
Issue Date: 4/1/2011
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Petro-Canada***
Various Sites Across Province of Ontario Oakville ON

Database: ***CA***

Certificate #: 3016-5ZBQQB
Application Year: 2004
Issue Date: 10/15/2004
Approval Type: Industrial Sewage Works
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:

Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Petro-Canada Inc.***
Various Sites Across Province of Ontario Oakville ON

Database: ***CA***

Certificate #: 6118-7KFR63
Application Year: 2008
Issue Date: 10/17/2008
Approval Type: Industrial Sewage Works
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Multinational Five Investments Limited***
Geographic Township of Nelson Burlington ON

Database: ***CA***

Certificate #: 7783-7TPNPF
Application Year: 2009
Issue Date: 7/7/2009
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Chelster Hall Company Ltd.***
1134, 1150, 1158 Lakeshore Road East Oakville ON

Database: ***CA***

Certificate #: 1333-5FLRKV
Application Year: 2002
Issue Date: 11/6/2002
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Regional Municipality of Halton***
Regina Dr Burlington ON

Database: ***CA***

Certificate #: 1245-6ZHHF8
Application Year: 2007
Issue Date: 4/3/2007
Approval Type: Municipal and Private Sewage Works

Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***K. FIELD RESOURCES LIMITED***
ST.A/LAKESHORE RD.E. OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 3-1186-99-
Application Year: 99
Issue Date: 10/6/1999
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***NORTHAMPTON GARDENS LTD.***
LOTS 38 & 40/BELLVIEW CRES. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0653-99-
Application Year: 99
Issue Date: 6/22/1999
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON***
09RST ST./LAKESHORE RD. OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 7-0903-97-
Application Year: 97
Issue Date: 9/15/1997
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON***
BURLINGTON AVE/ONT.ST/BIRCH AV BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0002-95-
Application Year: 95
Issue Date: 1/10/1995
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON***
BURLINGTON AVE/ONT.ST/BIRCH AV BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-0001-95-
Application Year: 95
Issue Date: 1/10/1995
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON***
LAKESHORE RD. E. OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 7-0429-86-
Application Year: 86
Issue Date: 6/13/1986
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***712101 ONTARIO LTD.-PT LOT 3, 4 & 5***
LAKESHORE TOWNHOUSES BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-0490-90-
Application Year: 90
Issue Date: 4/25/1990
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***FALCO PROPERTY-PT. LOT 4, CONC. 2 SDS***
BENSON DRIVE, NELSON TWP. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0422-91-
Application Year: 91
Issue Date: 4/19/1991
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***431789 ONTARIO LIMITED***
DRIVEWAY "A" "THE MAPLES" BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0815-86-
Application Year: 86
Issue Date: 7/3/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***OAKVILLE TOWN***
LAKESHORE RD. E. OAKVILLE TOWN ON

Database: ***CA***

Certificate #: 3-0364-87-
Application Year: 87
Issue Date: 4/8/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Corporation of the City of Burlington***
From Lakeshore Road to New St Burlington ON

Database: ***CA***

Certificate #: 3187-88PGYP
Application Year: 2010
Issue Date: 9/2/2010
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:

Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Corporation of the Town of Oakville***
Pine Avenue, Maple Avenue, Allan Street Oakville ON

Database: ***CA***

Certificate #: 0400-5F6GTA
Application Year: 2002
Issue Date: 10/24/2002
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site:
Lakeshore Road Burlington ON

Database: ***CA***

Certificate #: 3366-56PGG2
Application Year: 02
Issue Date: 1/28/02
Approval Type: Municipal & Private water
Status: Approved
Application Type: New Certificate of Approval
Client Name: The Corporation of the Regional Municipality of Halton
Client Address: 1151 Bronte Road
Client City: Oakville
Client Postal Code: L6M 3L1
Project Description: This application is for approval to install watermain on Lakeshore Road
Contaminants:
Emission Control:

Site:
Brock Avenue Right-of-way Burlington ON

Database: ***CA***

Certificate #: 4087-4PYRT8
Application Year: 00
Issue Date: 10/20/00
Approval Type: Municipal & Private water
Status: Approved
Application Type: New Certificate of Approval
Client Name: Corporation of the Regional Municipality of Halton
Client Address: 1151 Bronte Road
Client City: Oakville
Client Postal Code: L6M 3L1
Project Description: watermain construction on Brock Avenue (PR-1980)
Contaminants:
Emission Control:

Site: ***O.R.E. Development Corporation***
3230 Mainway, Lot 15, Registered Plan 1055, former the Township of Nelson, Burlington, Ontario, Regional Municipality of Halton CITY OF BURLINGTON ON

Database: ***CPU***

EBR Registry No.: 010-8527
Ministry Ref. No.: 6631-7RQGKZ
Proposal Date: December 07, 2009
Notice Date: February 12, 2010

Notice Type: Instrument Decision ***Year:*** 2009
Company Name: O.R.E. Development Corporation
Proponent Name:
Proposal Address: 3230 Main Way, Burlington Ontario, Canada L7M 1A5
Instrument Type: (EPA s. 168.6) - Certificate of Property Use
URL:

Location:

3230 Mainway, Lot 15, Registered Plan 1055, former the Township of Nelson, Burlington, Ontario, Regional Municipality of Halton CITY OF BURLINGTON

Site: ***General Electric Canada Incorporated***
Mobile Unit Burlington Ontario Burlington ON

Database: ***EBR***

EBR Registry No.: IA06E0289 ***Proposal Date:*** March 13, 2006
Ministry Ref. No.: 1202-6MHR8J ***Notice Pub Date:*** December 10, 2008
Notice Type: Instrument Decision ***Year:*** 2006
Company Name: General Electric Canada Incorporated
Proponent Name:
Proposal Address: 1150 Walkers Line, Burlington Ontario, L7M 1V2
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:
URL:

Location:

Mobile Unit Burlington Ontario Burlington

Site: ***Siemens Westinghouse Inc.***
Part Lot 19, Designated Part 2 on Plan 20R-13876 Burlington Ontario Burlington ON

Database: ***EBR***

EBR Registry No.: IA01E0679 ***Proposal Date:*** May 15, 2001
Ministry Ref. No.: 7666-4WRHTX ***Notice Pub Date:*** August 17, 2001
Notice Type: Instrument Decision ***Year:*** 2001
Company Name: Siemens Westinghouse Inc.
Proponent Name:
Proposal Address: 30 Milton Avenue, Hamilton Ontario, L8N 3K2
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:
URL:

Location:

Part Lot 19, Designated Part 2 on Plan 20R-13876 Burlington Ontario Burlington

---

Site: ***2246763 Ontario Inc.***
Mobile facility operating throughout the Province of Ontario CITY OF BURLINGTON ON

Database: ***EBR***

EBR Registry No.: 013-3195 ***Proposal Date:*** June 28, 2018
Ministry Ref. No.: 8346-AZ3RJ5 ***Notice Pub Date:*** June 28, 2018
Notice Type: Instrument Proposal ***Year:*** 2018
Company Name: 2246763 Ontario Inc.
Proponent Name:
Proposal Address: 889 Fraser Drive 101 Burlington Ontario Canada L7L 4X8
Instrument Type: Environmental Compliance Approval (project type: air) - EPA Part II.1-air
Location Other:
URL:

Location:

Mobile facility operating throughout the Province of Ontario CITY OF BURLINGTON

Site: ***Ford Motor Company of Canada Limited***
The Canadian Road Oakville Ontario L6J 5C9 Oakville ON

Database: ***EBR***

EBR Registry No.: IA05E0860
Ministry Ref. No.: 9650-6CVKY5
Notice Type: Instrument Decision
Company Name: Ford Motor Company of Canada Limited
Proponent Name:
Proposal Address: Oakville Assembly Plant, P.O. Box 1300, Oakville Ontario, L6J 5C9
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:
URL:
Proposal Date: May 30, 2005
Notice Pub Date: December 16, 2005
Year: 2005

Location:

The Canadian Road Oakville Ontario L6J 5C9 Oakville

Site: ***Burlington Technologies Inc.***
Lot:42 Conc:4 Burlington Ontario L7L 5P2 Burlington ON

Database: ***EBR***

EBR Registry No.: IA05E0262
Ministry Ref. No.: 5274-69TQQ6
Notice Type: Instrument Decision
Company Name: Burlington Technologies Inc.
Proponent Name:
Proposal Address: 920 Century Drive, Burlington Ontario, L7L 5P2
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:
URL:
Proposal Date: March 02, 2005
Notice Pub Date: June 06, 2006
Year: 2005

Location:

Lot:42 Conc:4 Burlington Ontario L7L 5P2 Burlington

Site: ***Ford Motor Co. of Canada Ltd.***
Ford Motor Company, Ontario Truck Plant - Body Shop TOWN OF OAKVILLE ON

Database: ***EBR***

EBR Registry No.: IA8E1544
Ministry Ref. No.: 8354398
Notice Type: Instrument Decision
Company Name: Ford Motor Co. of Canada Ltd.
Proponent Name:
Proposal Address: Oakville Assembly Plant, The Canadian Road, P.O. Box 1300, Oakville Ontario, L6J 5C9
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:
URL:
Proposal Date: November 06, 1998
Notice Pub Date: January 28, 1999
Year: 1998

Location:

Ford Motor Company, Ontario Truck Plant - Body Shop TOWN OF OAKVILLE

Site: ***Specialized Welding and Fabrications Limited***
Part of Lot 22, Concession 2 Oakville Ontario Oakville ON

Database: ***EBR***

EBR Registry No.: IA01E0643
Ministry Ref. No.: 4442-4WHNYQ
Notice Type: Instrument Decision
Company Name: Specialized Welding and Fabrications Limited
Proponent Name:
Proposal Date: May 07, 2001
Notice Pub Date: February 19, 2002
Year: 2001

Proposal Address: 1173 North Service Road West, Unit D6 to D10, Oakville Ontario, L6M 2V9
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:
URL:

Location:

Part of Lot 22, Concession 2 Oakville Ontario Oakville

Site: ***Central Remediation Services Inc.*** ***Database:*** ***EBR***
816 Mayfield Road West RR 4 Georgetown, Ontario L7G 4S7 TOWN OF OAKVILLE ON

EBR Registry No.: IA7E1651 ***Proposal Date:*** December 05, 1997
Ministry Ref. No.: A680277 ***Notice Pub Date:*** September 11, 2001
Notice Type: Instrument Decision ***Year:*** 1997
Company Name: Central Remediation Services Inc.
Proponent Name:
Proposal Address: 2651 Fonthill Drive, Oakville Ontario, L6J 7H5
Instrument Type: (EPA s. 27) - Approval for a waste disposal site.
Location Other:
URL:

Location:

816 Mayfield Road West RR 4 Georgetown, Ontario L7G 4S7 TOWN OF OAKVILLE

Site: ***OMG Catalysts Canada Corp.*** ***Database:*** ***EBR***
Lot: Conc: Burlington Ontario L7R 3Y8 Burlington ON

EBR Registry No.: IA03E0872 ***Proposal Date:*** September 25, 2003
Ministry Ref. No.: 7054-5NKQXD ***Notice Pub Date:*** January 22, 2004
Notice Type: Instrument Decision ***Year:*** 2003
Company Name: OMG Catalysts Canada Corp.
Proponent Name:
Proposal Address: PO Box 5097 Stn LCD 1, Burlington Ontario, L7R 3Y8
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:
URL:

Location:

Lot: Conc: Burlington Ontario L7R 3Y8 Burlington

Site: ***DMC-2 Canada Corporation*** ***Database:*** ***EBR***
Lot: Conc: Burlington Ontario L7R 3Y8 Burlington ON

EBR Registry No.: IA01E0612 ***Proposal Date:*** May 01, 2001
Ministry Ref. No.: 2355-4WASFE ***Notice Pub Date:*** February 13, 2002
Notice Type: Instrument Decision ***Year:*** 2001
Company Name: DMC-2 Canada Corporation
Proponent Name:
Proposal Address: 4261 Mainway Drive,, Burlington Ontario, L7R 3Y8
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:
URL:

Location:

Lot: Conc: Burlington Ontario L7R 3Y8 Burlington

Site: ***Kerr Cadillac Pontiac Buick Inc.***
410 South Service Road West Oakville Ontario L6J 5C1 Oakville ON

Database: ***EBR***

EBR Registry No.: IA01E0603
Ministry Ref. No.: 6017-4WAJP6
Notice Type: Instrument Decision
Company Name: Kerr Cadillac Pontiac Buick Inc.
Proponent Name:
Proposal Address: 410 South Service Road West, Oakville Ontario, L6J 5C1
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:
URL:

Proposal Date: April 30, 2001
Notice Pub Date: October 11, 2001
Year: 2001

Location:

410 South Service Road West Oakville Ontario L6J 5C1 Oakville

---

Site: ***Ontario Regulation 155/07, amending Ontario Regulation 482/73, made under the Ontario Planning and Development Act, 1994. ON***

Database: ***EBR***

EBR Registry No.: 010-0661
Ministry Ref. No.: O. Reg. 155/07
Notice Type: Information Notice
Company Name: Ontario Regulation 155/07, amending Ontario Regulation 482/73, made under the Ontario Planning and Development Act, 1994.
Proponent Name:
Proposal Address:
Instrument Type:
Location Other:
URL:

Proposal Date:
Notice Pub Date: June 04, 2007
Year:

Location:

CITY OF BURLINGTON

Site: ***2246763 Ontario Inc.***
Mobile facility operating throughout Ontario CITY OF BURLINGTON ON

Database: ***EBR***

EBR Registry No.: 013-3193
Ministry Ref. No.: 8344-AZ3R7J
Notice Type: Instrument Proposal
Company Name: 2246763 Ontario Inc.
Proponent Name:
Proposal Address: 889 Fraser Drive 101 Burlington Ontario Canada L7L 4X8
Instrument Type: Environmental Compliance Approval (project type: air) - EPA Part II.1-air
Location Other:
URL:

Proposal Date: June 28, 2018
Notice Pub Date: June 28, 2018
Year: 2018

Location:

Mobile facility operating throughout Ontario CITY OF BURLINGTON

Site: ***Atotech Canada Limited***
Plan M265, Part Block 2, RP 20R7780, Parts 1 & 2 Burlington Ontario Burlington ON

Database: ***EBR***

EBR Registry No.: IA01E0210
Ministry Ref. No.: 5334-4TWK7C
Notice Type: Instrument Decision
Company Name: Atotech Canada Limited
Proponent Name:
Proposal Address: 1180 Corporate Drive, Burlington Ontario, L7L 5R6
Instrument Type: (EPA s. 27) - Approval for a waste disposal site.

Proposal Date: February 13, 2001
Notice Pub Date: August 19, 2002
Year: 2001

Location Other:
URL:

Location:

Plan M265, Part Block 2, RP 20R7780, Parts 1 & 2 Burlington Ontario Burlington

---

Site: ***General Electric Canada Inc.***
Pt Lt 12, Conc 3 SDS, Lot 113, 114 Oakville Ontario L6J 2X6 Oakville ON

Database: ***EBR***

EBR Registry No.:	IA01E1281	***Proposal Date:***	September 06, 2001
Ministry Ref. No.:	1063-52APQY	***Notice Pub Date:***	November 29, 2001
Notice Type:	Instrument Decision	***Year:***	2001
Company Name:	General Electric Canada Inc.		
Proponent Name:			
Proposal Address:	2300 Meadowvale Blvd., Mississauga Ontario, L5N 5P9		
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)		
Location Other:			
URL:			

Location:

Pt Lt 12, Conc 3 SDS, Lot 113, 114 Oakville Ontario L6J 2X6 Oakville

---

Site: ***Ford Motor Company of Canada Limited***
The Canadian Road Oakville Ontario L6J 5C9 TOWN OF OAKVILLE ON

Database: ***EBR***

EBR Registry No.:	IA00E1348	***Proposal Date:***	August 17, 2000
Ministry Ref. No.:	8051-4N9QRL	***Notice Pub Date:***	February 27, 2002
Notice Type:	Instrument Decision	***Year:***	2000
Company Name:	Ford Motor Company of Canada Limited		
Proponent Name:			
Proposal Address:	Oakville Assembly Plant, P.O. Box 1300, Oakville Ontario, L6J 5C9		
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)		
Location Other:			
URL:			

Location:

The Canadian Road Oakville Ontario L6J 5C9 TOWN OF OAKVILLE

Site: ***Amhil Enterprises***
5330 Mainway Drive Burlington Ontario Burlington ON

Database: ***EBR***

EBR Registry No.:	IA01E1555	***Proposal Date:***	November 07, 2001
Ministry Ref. No.:	5167-548TJC	***Notice Pub Date:***	May 13, 2002
Notice Type:	Instrument Decision	***Year:***	2001
Company Name:	Amhil Enterprises		
Proponent Name:			
Proposal Address:	400 Traders Boulevard East, Mississauga Ontario, L4Z 1W7		
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)		
Location Other:			
URL:			

Location:

5330 Mainway Drive Burlington Ontario Burlington

Site: ***OMG Catalysts Canada Corp.***
Lot: Conc: Burlington Ontario L7R 3Y8 Burlington ON

Database: ***EBR***

EBR Registry No.: IA02E1532
Ministry Ref. No.: 6718-5G42DH
Notice Type: Instrument Decision
Company Name: OMG Catalysts Canada Corp.
Proponent Name:
Proposal Address: PO Box 5097 Stn LCD 1, Burlington Ontario, L7R 3Y8
Instrument Type: (OWRA s. 53(1)) - Approval for sewage works
Location Other:
URL:
Proposal Date: December 04, 2002
Notice Pub Date: March 07, 2003
Year: 2002

Location:

Lot: Conc: Burlington Ontario L7R 3Y8 Burlington

Site: ***Ford Motor Company of Canada***
The Canadian Road Oakville Ontario Oakville ON

Database: ***EBR***

EBR Registry No.: IT03E0081
Ministry Ref. No.: 2003-000224
Notice Type: Instrument Decision
Company Name: Ford Motor Company of Canada
Proponent Name:
Proposal Address: The Canadian Road, P.O. Box 2000, OAKVILLE Ontario, L6J 5E4
Instrument Type:
Location Other:
URL:
Proposal Date: October 14, 2003
Notice Pub Date: January 22, 2004
Year: 2003

Location:

The Canadian Road Oakville Ontario Oakville

Site: ***Ford Motor Company of Canada Limited***
The Canadian Road Oakville Ontario L6J 5C9 Oakville ON

Database: ***EBR***

EBR Registry No.: IA03E1009
Ministry Ref. No.: 0328-5PAKMG
Notice Type: Instrument Decision
Company Name: Ford Motor Company of Canada Limited
Proponent Name:
Proposal Address: Oakville Assembly Plant, P.O. Box 1300, Oakville Ontario, L6J 5C9
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:
URL:
Proposal Date: July 14, 2003
Notice Pub Date: September 02, 2003
Year: 2003

Location:

The Canadian Road Oakville Ontario L6J 5C9 Oakville

Site: ***David Brown Union Pumps (Canada), Limited***
4211 Mainway Burlington Ontario Burlington ON

Database: ***EBR***

EBR Registry No.: IA02E0605
Ministry Ref. No.: 5696-5AMSTN
Notice Type: Instrument Decision
Company Name: David Brown Union Pumps (Canada), Limited
Proponent Name:
Proposal Address: 4211 Mainway, Burlington Ontario, L7L 5N9
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:
URL:
Proposal Date: June 14, 2002
Notice Pub Date: November 26, 2002
Year: 2002

Location:

4211 Mainway Burlington Ontario Burlington

Site: ***DMC-2 Canada Corporation*** ***Database:*** ***EBR***
4261 Mainway Drive Burlington Ontario Burlington ON

EBR Registry No.:	IA01E1773	***Proposal Date:***	December 27, 2001
Ministry Ref. No.:	5495-55TQYN	***Notice Pub Date:***	May 23, 2002
Notice Type:	Instrument Decision	***Year:***	2001
Company Name:	DMC-2 Canada Corporation		
Proponent Name:			
Proposal Address:	4261 Mainway Drive,, Burlington Ontario, L7R 3Y8		
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)		
Location Other:			
URL:			

Location:

4261 Mainway Drive Burlington Ontario Burlington

Site: ***Ford Motor Company of Canada*** ***Database:*** ***EBR***
The Canadian Road Oakville Ontario Oakville ON

EBR Registry No.:	IA02E0378	***Proposal Date:***	May 17, 2002
Ministry Ref. No.:	4397-58MN44	***Notice Pub Date:***	July 26, 2002
Notice Type:	Instrument Decision	***Year:***	2002
Company Name:	Ford Motor Company of Canada		
Proponent Name:			
Proposal Address:	The Canadian Road, P.O. Box 2000, OAKVILLE Ontario, L6J 5E4		
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)		
Location Other:			
URL:			

Location:

The Canadian Road Oakville Ontario Oakville

Site: ***OMG Catalysts Canada Corp.*** ***Database:*** ***EBR***
Lot: Conc: Burlington Ontario L7R 3Y8 Burlington ON

EBR Registry No.:	IA03E0876	***Proposal Date:***	June 18, 2003
Ministry Ref. No.:	9230-5NKQT7	***Notice Pub Date:***	November 03, 2003
Notice Type:	Instrument Decision	***Year:***	2003
Company Name:	OMG Catalysts Canada Corp.		
Proponent Name:			
Proposal Address:	PO Box 5097 Stn LCD 1, Burlington Ontario, L7R 3Y8		
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)		
Location Other:			
URL:			

Location:

Lot: Conc: Burlington Ontario L7R 3Y8 Burlington

Site: ***Rice Tool & Manufacturing Inc.*** ***Database:*** ***EBR***
Lots 13, 14 & 15, Nelson Industrial Park Burlington Ontario Burlington ON

EBR Registry No.:	IA00E1105	***Proposal Date:***	July 06, 2000
Ministry Ref. No.:	8648-4LYJF7	***Notice Pub Date:***	January 03, 2001

Notice Type: Instrument Decision ***Year:*** 2000
Company Name: Rice Tool & Manufacturing Inc.
Proponent Name:
Proposal Address: 2247 Harold Road, Burlington Ontario, L7P 2J7
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:
URL:

Location:

Lots 13, 14 & 15, Nelson Industrial Park Burlington Ontario Burlington

---

Site: ***Ontario Concrete Products Inc.***
Lot:34, 35 Conc:3 SDS, Trafalgar Oakville Ontario Oakville ON

Database: ***EBR***

EBR Registry No.: IA02E0516 ***Proposal Date:*** June 05, 2002
Ministry Ref. No.: 6365-5ARJVK ***Notice Pub Date:*** May 09, 2003
Notice Type: Instrument Decision ***Year:*** 2002
Company Name: Ontario Concrete Products Inc.
Proponent Name:
Proposal Address: PO Box 84018, Burlington Ontario, L7L 6S2
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:
URL:

Location:

Lot:34, 35 Conc:3 SDS, Trafalgar Oakville Ontario Oakville

Site: ***ALS Canada Ltd.***
5420 Mainway Drive, Unit 5 & 6 Burlington Ontario L7L 6A4 Burlington ON

Database: ***EBR***

EBR Registry No.: IA05E0669 ***Proposal Date:*** June 24, 2005
Ministry Ref. No.: 8279-6BVKVQ ***Notice Pub Date:*** October 27, 2006
Notice Type: Instrument Decision ***Year:*** 2005
Company Name: ALS Canada Ltd.
Proponent Name:
Proposal Address: 5420 Mainway Drive, Unit 5 & 6, Burlington Ontario, L7L 6A4
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:
URL:

Location:

5420 Mainway Drive, Unit 5 & 6 Burlington Ontario L7L 6A4 Burlington

---

Site: ***Ford Motor Company of Canada***
The Canadian Road Oakville Ontario L6J 5C9 Oakville ON

Database: ***EBR***

EBR Registry No.: IA02E0546 ***Proposal Date:*** June 10, 2002
Ministry Ref. No.: 0456-5ALSWE ***Notice Pub Date:*** September 20, 2002
Notice Type: Instrument Decision ***Year:*** 2002
Company Name: Ford Motor Company of Canada
Proponent Name:
Proposal Address: The Canadian Road, P.O. Box 2000, OAKVILLE Ontario, L6J 5E4
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:
URL:

Location:

The Canadian Road Oakville Ontario L6J 5C9 Oakville

Site: ***The Regional Municipality of Halton***
Maplewood Dr Burlington ON L6M 3L1

Database: ***ECA***

Approval No:	4822-6A6QJ8	***SWP Area Name:***	
Approval Date:	2005-03-08	***MOE District:***	
Status:	Approved	***City:***	
Record Type:	ECA	***Longitude:***	
Link Source:	IDS	***Latitude:***	
Approval Type:	ECA-Municipal Drinking Water Systems		
Project Type:	Municipal Drinking Water Systems		
Address:	Maplewood Dr		
Full Address:			
Full PDF Link:			

Site: ***Suncor Energy Inc.***
Various Locations in Ontario Oakville ON L6L 6N5

Database: ***ECA***

Approval No:	3551-9CBRQP	***SWP Area Name:***	
Approval Date:	2013-10-31	***MOE District:***	
Status:	Revoked and/or Replaced	***City:***	Oakville
Record Type:	ECA	***Longitude:***	
Link Source:	IDS	***Latitude:***	
Approval Type:	ECA-INDUSTRIAL SEWAGE WORKS		
Project Type:	INDUSTRIAL SEWAGE WORKS		
Address:	Various Locations in Ontario		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/6352-9ADQSN-14.pdf		

Site: ***Suncor Energy Inc., Suncor Energy Products Inc., and 1277136 Alberta Ltd.***
Various locations in Ontario Oakville ON L6L 6N5

Database: ***ECA***

Approval No:	8007-9W2J9W	***SWP Area Name:***	
Approval Date:	2015-05-05	***MOE District:***	
Status:	Revoked and/or Replaced	***City:***	Oakville
Record Type:	ECA	***Longitude:***	
Link Source:	IDS	***Latitude:***	
Approval Type:	ECA-INDUSTRIAL SEWAGE WORKS		
Project Type:	INDUSTRIAL SEWAGE WORKS		
Address:	Various locations in Ontario		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/8589-9KAJYF-14.pdf		

Site: ***Hydro One Networks Inc.***
559 Maplegrove Rd Oakville ON M5G 2P5

Database: ***ECA***

Approval No:	7619-85ZNVN	***SWP Area Name:***	
Approval Date:	2010-06-10	***MOE District:***	
Status:	Approved	***City:***	Oakville
Record Type:	ECA	***Longitude:***	
Link Source:	IDS	***Latitude:***	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Address:	559 Maplegrove Rd		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/9816-854K73-14.pdf		

Site: ***The Regional Municipality of Halton***
Lakeshore Road Burlington ON L6M 3L1

Database: ***ECA***

Approval No:	2034-64ZPCP	***SWP Area Name:***	

Approval Date:	2004-09-22	***MOE District:***	
Status:	Approved	***City:***	Burlington
Record Type:	ECA	***Longitude:***	
Link Source:	IDS	***Latitude:***	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Address:	Lakeshore Road		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/1364-64WUSN-14.pdf		

Site: ***The Corporation of the Town of Oakville***
Pine Avenue Maple Avenue Allan St Oakville ON

Database: ***ECA***

Approval No:	0400-5F6GTA	***SWP Area Name:***	
Approval Date:	2002-10-24	***MOE District:***	
Status:	Approved	***City:***	Oakville
Record Type:	ECA	***Longitude:***	
Link Source:	IDS	***Latitude:***	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Address:	Pine Avenue Maple Avenue Allan St		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/4044-5F2HDQ-14.pdf		

Site: ***Suncor Energy Inc., Suncor Energy Products Inc., and 1277136 Alberta Ltd.***
Various locations in Ontario Oakville ON L6L 6N5

Database: ***ECA***

Approval No:	8054-AWEQVH	***SWP Area Name:***	
Approval Date:	2018-03-01	***MOE District:***	
Status:	Approved	***City:***	
Record Type:	ECA	***Longitude:***	
Link Source:	IDS	***Latitude:***	
Approval Type:	ECA-INDUSTRIAL SEWAGE WORKS		
Project Type:	INDUSTRIAL SEWAGE WORKS		
Address:	Various locations in Ontario		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/7140-AQ9KMN-14.pdf		

Site: ***The Regional Municipality of Halton***
Lakeshore Road Oakville ON L6M 3L1

Database: ***ECA***

Approval No:	2073-7CTHD8	***SWP Area Name:***	
Approval Date:	2008-03-18	***MOE District:***	
Status:	Approved	***City:***	Oakville
Record Type:	ECA	***Longitude:***	
Link Source:	IDS	***Latitude:***	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Address:	Lakeshore Road		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/3437-7CPJ7C-14.pdf		

Site: ***The Regional Municipality of Halton***
Lakeshore Road Burlington ON L6M 3L1

Database: ***ECA***

Approval No:	3366-56PGG2	***SWP Area Name:***	
Approval Date:	2002-01-28	***MOE District:***	
Status:	Approved	***City:***	
Record Type:	ECA	***Longitude:***	
Link Source:	IDS	***Latitude:***	
Approval Type:	ECA-Municipal and Private Water Works		
Project Type:	Municipal and Private Water Works		
Address:	Lakeshore Road		

Full Address:
Full PDF Link:

Site: ***Petro-Canada***
Various Sites Across Province of Ontario Oakville ON L6L 6N5

Database: ***ECA***

Approval No:	3016-5ZBQQB	***SWP Area Name:***	Lakehead
Approval Date:	2004-10-15	***MOE District:***	Thunder Bay
Status:	Revoked and/or Replaced	***City:***	Oakville
Record Type:	ECA	***Longitude:***	
Link Source:	IDS	***Latitude:***	
Approval Type:	ECA-INDUSTRIAL SEWAGE WORKS		
Project Type:	INDUSTRIAL SEWAGE WORKS		
Address:	Various Sites Across Province of Ontario		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/2635-5WCSPF-14.pdf		

Site: ***The Corporation of the City of Burlington***
Brant Street and Lakeshore Road South portion of intersection, entrance to Spencer Smith Park Burlington ON L7R 3Z6

Database: ***ECA***

Approval No:	9449-AVGTUV	***SWP Area Name:***	
Approval Date:	2018-02-26	***MOE District:***	
Status:	Approved	***City:***	
Record Type:	ECA	***Longitude:***	
Link Source:	IDS	***Latitude:***	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Address:	Brant Street and Lakeshore Road South portion of intersection, entrance to Spencer Smith Park		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/5143-AU7MUP-14.pdf		

Site: ***The Regional Municipality of Halton***
Maplehurst Avenue (Right of Way) Oakville ON L6M 3L1

Database: ***ECA***

Approval No:	7630-AGELV9	***SWP Area Name:***	
Approval Date:	2016-12-13	***MOE District:***	
Status:	Approved	***City:***	Oakville
Record Type:	ECA	***Longitude:***	
Link Source:	IDS	***Latitude:***	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Address:	Maplehurst Avenue (Right of Way)		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/3487-AG2QRJ-14.pdf		

Site: ***Joseph Brant Memorial Hospital***
1230 North Shore Boulevard East Burlington ON L7S 1W7

Database: ***ECA***

Approval No:	5391-6VMKAF	***SWP Area Name:***	Halton
Approval Date:	2006-11-21	***MOE District:***	Halton-Peel
Status:	Approved	***City:***	Burlington
Record Type:	ECA	***Longitude:***	-79.80317
Link Source:	IDS	***Latitude:***	43.3180769999999
Approval Type:	ECA-AIR		
Project Type:	AIR		
Address:	1230 North Shore Boulevard East		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/4674-6S5HTJ-14.pdf		

Site: ***Suncor Energy Inc., Suncor Energy Products Inc., and 1277136 Alberta Ltd.***
Various locations in Ontario Oakville ON L6L 6N5

Database: ***ECA***

Approval No: 7737-9W2KCW
Approval Date: 2015-05-05
Status: Approved
Record Type: ECA
Link Source: IDS
Approval Type: ECA-INDUSTRIAL SEWAGE WORKS
Project Type: INDUSTRIAL SEWAGE WORKS
Address: Various locations in Ontario
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/6016-9KAJMN-14.pdf
SWP Area Name:
MOE District:
City: Oakville
Longitude:
Latitude:

Site: ***Colborne Court Estates Inc.***
1077 Lakeshore Road East Oakville ON L4Z 3K7
Database: ***ECA***

Approval No: 5182-4V9J7N
Approval Date: 2001-03-28
Status: Approved
Record Type: ECA
Link Source: IDS
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Address: 1077 Lakeshore Road East
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/5748-4V7Q7D-14.pdf
SWP Area Name: Halton
MOE District: Halton-Peel
City: Oakville
Longitude: -79.65749
Latitude: 43.45599

Site: ***The Regional Municipality of Halton***
Lakeshore Road Burlington ON L6M 3L1
Database: ***ECA***

Approval No: 2782-64ZPQU
Approval Date: 2004-09-22
Status: Approved
Record Type: ECA
Link Source: IDS
Approval Type: ECA-Municipal Drinking Water Systems
Project Type: Municipal Drinking Water Systems
Address: Lakeshore Road
Full Address:
Full PDF Link:
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:

Site: ***Petro-Canada Inc.***
Various Sites Across Province of Ontario Oakville ON L6L 6N5
Database: ***ECA***

Approval No: 6118-7KFR63
Approval Date: 2008-10-17
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
Approval Type: ECA-INDUSTRIAL SEWAGE WORKS
Project Type: INDUSTRIAL SEWAGE WORKS
Address: Various Sites Across Province of Ontario
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3172-7CTPSR-14.pdf
SWP Area Name:
MOE District:
City: Oakville
Longitude:
Latitude:

Site: ***The Regional Municipality of Halton***
Fruitland Ave. from Lakeshore Rd. to Lakeland Cres. & Lakeland Cres. from Lakeshore Rd. to Fruitland Ave
Burlington ON L6M 3L1
Database: ***ECA***

Approval No: 1661-83NPJ2
Approval Date: 2010-03-29
Status: Approved
Record Type: ECA
Link Source: IDS
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
SWP Area Name:
MOE District:
City: Burlington
Longitude:
Latitude:

Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Address: Fruitland Ave. from Lakeshore Rd. to Lakeland Cres. & Lakeland Cres. from Lakeshore Rd. to Fruitland Ave
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3423-83FTH6-14.pdf

---

Site: ***The Regional Municipality of Halton***
Brock Ave Burlington ON L6M 3L1

Database: ***ECA***

Approval No: 4087-4PYRT8
Approval Date: 2000-10-20
Status: Approved
Record Type: ECA
Link Source: IDS
Approval Type: ECA-Municipal and Private Water Works
Project Type: Municipal and Private Water Works
Address: Brock Ave
Full Address:
Full PDF Link:

SWP Area Name:
MOE District:
City:
Longitude:
Latitude:

Site: ***Petro-Canada***
Various Sites Across Province of Ontario Oakville ON L6L 6N5

Database: ***ECA***

Approval No: 3016-5ZBQQB
Approval Date: 2005-11-02
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
Approval Type: ECA-INDUSTRIAL SEWAGE WORKS
Project Type: INDUSTRIAL SEWAGE WORKS
Address: Various Sites Across Province of Ontario
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/0744-6FSHZZ-14.pdf

SWP Area Name: Lakehead
MOE District: Thunder Bay
City: Oakville
Longitude:
Latitude:

Site: ***Union Gas Limited***
Various Sites Across Province of Ontario Oakville ON N7M 5M1

Database: ***ECA***

Approval No: 1949-7KRMC5
Approval Date: 2011-03-16
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
Approval Type: ECA-AIR
Project Type: AIR
Address: Various Sites Across Province of Ontario
Full Address:
Full PDF Link:

SWP Area Name:
MOE District:
City: Oakville
Longitude:
Latitude:

Site: ***Suncor Energy Inc., Suncor Energy Products Inc., and 1277136 Alberta Ltd.***
Various Locations in Ontario Oakville ON L6L 6N5

Database: ***ECA***

Approval No: 0828-9DGMQK
Approval Date: 2013-11-26
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
Approval Type: ECA-INDUSTRIAL SEWAGE WORKS
Project Type: INDUSTRIAL SEWAGE WORKS
Address: Various Locations in Ontario
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/1381-9ALR6V-14.pdf

SWP Area Name:
MOE District:
City: Oakville
Longitude:
Latitude:

Site: ***The Regional Municipality of Halton***

Database:

Jones Street (Lakeshore Road to Marine Drive) Oakville ON L6M 3L1 ***ECA***

Approval No:	4354-5QVHUV	***SWP Area Name:***	
Approval Date:	2003-09-02	***MOE District:***	
Status:	Approved	***City:***	
Record Type:	ECA	***Longitude:***	
Link Source:	IDS	***Latitude:***	
Approval Type:	ECA-Municipal Drinking Water Systems		
Project Type:	Municipal Drinking Water Systems		
Address:	Jones Street (Lakeshore Road to Marine Drive)		
Full Address:			
Full PDF Link:			

Site: ***Suncor Energy Inc., Suncor Energy Products Inc., and 1277136 Alberta Ltd.***
Various Locations in Ontario Oakville ON L6L 6N5
Database: ***ECA***

Approval No:	3352-9A3GTX	***SWP Area Name:***	
Approval Date:	2013-07-30	***MOE District:***	
Status:	Revoked and/or Replaced	***City:***	Oakville
Record Type:	ECA	***Longitude:***	
Link Source:	IDS	***Latitude:***	
Approval Type:	ECA-INDUSTRIAL SEWAGE WORKS		
Project Type:	INDUSTRIAL SEWAGE WORKS		
Address:	Various Locations in Ontario		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/0006-94QQ48-14.pdf		

Site: ***The Corporation of the City of Burlington***
Lakeshore Rd (North Shore Road to 1000m south of intersection) Burlington ON L7R 3Z6
Database: ***ECA***

Approval No:	9682-9YHLL9	***SWP Area Name:***	
Approval Date:	2015-07-23	***MOE District:***	
Status:	Approved	***City:***	Burlington
Record Type:	ECA	***Longitude:***	
Link Source:	IDS	***Latitude:***	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Address:	Lakeshore Rd (North Shore Road to 1000m south of intersection)		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/8508-9T9LHD-14.pdf		

Site: ***Association of Conservation Authorities of Ontario***
Various Sites Across Province of Ontario Oakville ON L3Y 4W3
Database: ***ECA***

Approval No:	9790-6XBLZC	***SWP Area Name:***	
Approval Date:	2007-04-27	***MOE District:***	
Status:	Revoked and/or Replaced	***City:***	Oakville
Record Type:	ECA	***Longitude:***	
Link Source:	IDS	***Latitude:***	
Approval Type:	ECA-WASTE MANAGEMENT SYSTEMS		
Project Type:	WASTE MANAGEMENT SYSTEMS		
Address:	Various Sites Across Province of Ontario		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/6611-6U8LZN-14.pdf		

Site: ***The Regional Municipality of Halton***
Lakeshore Road and Rebecca Street Doral Drive, Randall Street, Dunn Street and Trafalgar Street Oakville ON L6M 3L1
Database: ***ECA***

Approval No:	8828-A4MKV4	***SWP Area Name:***	
Approval Date:	2015-12-02	***MOE District:***	
Status:	Approved	***City:***	Oakville
Record Type:	ECA	***Longitude:***	
Link Source:	IDS	***Latitude:***	

Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Address: Lakeshore Road and Rebecca Street Doral Drive, Randall Street, Dunn Street and Trafalgar Street
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/5580-A3RLFQ-14.pdf

---

Site: ***Suncor Energy Inc.***
Various locations in Ontario Oakville ON L6L 6N5

Database: ***ECA***

Approval No: 8558-AAHJMW
Approval Date: 2016-07-22
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City: Oakville
Longitude:
Latitude:
Approval Type: ECA-INDUSTRIAL SEWAGE WORKS
Project Type: INDUSTRIAL SEWAGE WORKS
Address: Various locations in Ontario
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7637-A67RNM-14.pdf

---

Site: ***The Regional Municipality of Halton***
Regina Dr Burlington ON L6M 3L1

Database: ***ECA***

Approval No: 1245-6ZHHF8
Approval Date: 2007-04-03
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City: Burlington
Longitude:
Latitude:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Address: Regina Dr
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3586-6ZFRMC-14.pdf

---

Site: ***Suncor Energy Inc., Suncor Energy Products Inc., and 1277136 Alberta Ltd.***
Various Locations in Ontario Oakville ON L6L 6N5

Database: ***ECA***

Approval No: 4635-98ULLG
Approval Date: 2013-06-24
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City: Oakville
Longitude:
Latitude:
Approval Type: ECA-INDUSTRIAL SEWAGE WORKS
Project Type: INDUSTRIAL SEWAGE WORKS
Address: Various Locations in Ontario
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/8881-94QQB7-14.pdf

---

Site: ***Rice Tool & Manufacturing Inc.***
Lots 13, 14 & 15, Nelson Industrial Park Burlington ON L7P 2J7

Database: ***ECA***

Approval No: 2002-4RXM52
Approval Date: 2000-12-15
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City: Burlington
Longitude:
Latitude:
Approval Type: ECA-AIR
Project Type: AIR
Address: Lots 13, 14 & 15, Nelson Industrial Park
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/8648-4LYJF7-14.pdf

---

Site: ***UHTHOFF QUARRY COMPANY***
NELSON AGGREGATE CO-C/O BOX 1070, STN B QUARRY-WEST STREET NORTH, RR #4 BURLINGTON ON L7P 3S9

Database: ***GEN***

Generator No.:	ON0476402	***PO Box No.:***	
Status:		***Country:***	
Approval Years:	86,87	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No. Admin:***	
SIC Code:	0812		
SIC Description:	LIMESTONE QUARRIES		

--Details--

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 221
Waste Description: LIGHT FUELS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Site: ***FACCA INCORPORATED***
INTERSECTION OF LAKESHORE RD AND EASTPORT DR BURLINGTON ON L7S 1A2

Database: ***GEN***

Generator No.:	ON3154377	***PO Box No.:***	
Status:		***Country:***	Canada
Approval Years:	2014	***Choice of Contact:***	CO_ADMIN
Contam. Facility:	No	***Co Admin:***	Ryan Wilbur
MHSW Facility:	No	***Phone No. Admin:***	519-819-9412 Ext.
SIC Code:	238990		
SIC Description:	ALL OTHER SPECIALTY TRADE CONTRACTORS		

--Details--

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 253
Waste Description: EMULSIFIED OILS

Site: ***HALTON, REGIONAL MUNICIPALITY OF***
BURLINGTON SKYWAY WASTEWATER TREATMENT PLANT - 1125 LAKESHORE ROAD Burlington ON L7S 1A8

Database: ***GEN***

Generator No.:	ON0277106	***PO Box No.:***	
Status:		***Country:***	Canada
Approval Years:	2014	***Choice of Contact:***	CO_OFFICIAL
Contam. Facility:	No	***Co Admin:***	Gary Tuff
MHSW Facility:	No	***Phone No. Admin:***	905-825-6000 Ext.7731
SIC Code:	221320		
SIC Description:	SEWAGE TREATMENT FACILITIES		

--Details--

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 222
Waste Description: HEAVY FUELS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 268
Waste Description: AMINES

Waste Code: 113
Waste Description: ACID WASTE - OTHER METALS

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 243
Waste Description: PCBS

Waste Code: 221
Waste Description: LIGHT FUELS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Site: ***Hydro One Networks Inc.***
Oakville Transformer Station 559 Maplegrove Road Oakville ON L6J 4W3

Database: ***GEN***

Generator No.: ON7305877
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 221122
SIC Description: ELECTRIC POWER DISTRIBUTION

PO Box No.:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Mike Harvey
Phone No. Admin: 866-782-4489 Ext.

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 243
Waste Description: PCBS

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Site: ***Hydro One Networks Inc.***
Oakville Transformer Station 559 Maplegrove Road Oakville ON L6J 4W3

Database: ***GEN***

Generator No.: ON7305877
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 221122
SIC Description: ELECTRIC POWER DISTRIBUTION

PO Box No.:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Mike Harvey
Phone No. Admin: 866-782-4489 Ext.

--Details--
Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 243
Waste Description: PCBS

Site: ***Hydro One Networks Inc.***
Oakville Transformer Station 559 Maplegrove Road Oakville ON L6J 4W3

Database: ***GEN***

Generator No.: ON7305877
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 221122
SIC Description: ELECTRIC POWER DISTRIBUTION

PO Box No.:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Mike Harvey
Phone No. Admin: 866-782-4489 Ext.

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 243
Waste Description: PCBS

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Site: ***FACCA INCORPORATED***
INTERSECTION OF LAKESHORE RD AND EASTPORT DR BURLINGTON ON

Database: ***GEN***

Generator No.: ON3154377
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 238990
SIC Description: ALL OTHER SPECIALTY TRADE CONTRACTORS

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 253
Waste Description: EMULSIFIED OILS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Site: ***Metrolinx***
Mi. 31.28 on the Lakeshore West Rail Corridor Burlington ON L7R2Y4

Database: ***GEN***

Generator No.: ON6810005
Status: Registered
Approval Years: As of Jun 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country: Canada
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 146 L
Waste Description: Other specified inorganic sludges, slurries or solids

Site: ***LINCOLN QUARRY COMPANY***
NELSON AGGREGATE CO-C/O BOX 1070, STN B QUARRY-YONGE ST. OFF MOUNTAIN RD. BURLINGTON ON L7P 3S9

Database: ***GEN***

Generator No.:	ON0476400	***PO Box No.:***	
Status:		***Country:***	
Approval Years:	86,87,88	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No. Admin:***	
SIC Code:	0812		
SIC Description:	LIMESTONE QUARRIES		

--Details--

Waste Code:	213
Waste Description:	PETROLEUM DISTILLATES
Waste Code:	221
Waste Description:	LIGHT FUELS
Waste Code:	252
Waste Description:	WASTE OILS & LUBRICANTS

Site: ***SUNCOR ENERGY PRODUCTS PARTNERSHIP***
Lakeshore Blvd. West & Great Lakes Blvd. Oakville ON NANANA

Database: ***GEN***

Generator No.:	ON4768941	***PO Box No.:***	
Status:	Registered	***Country:***	Canada
Approval Years:	As of Jun 2018	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No. Admin:***	
SIC Code:			
SIC Description:			

--Details--

Waste Code:	146 L
Waste Description:	Other specified inorganic sludges, slurries or solids
Waste Code:	221 I
Waste Description:	Light fuels
Waste Code:	146 I
Waste Description:	Other specified inorganic sludges, slurries or solids

---

Site: ***HALTON, REGIONAL MUNICIPALITY OF***
BURLINGTON SKYWAY WASTEWATER TREATMENT PLANT - 1125 LAKESHORE ROAD Burlington ON L7S 1A8

Database: ***GEN***

Generator No.:	ON0277106	***PO Box No.:***	
Status:		***Country:***	Canada
Approval Years:	2016	***Choice of Contact:***	CO_OFFICIAL
Contam. Facility:	No	***Co Admin:***	Gary Tuff
MHSW Facility:	No	***Phone No. Admin:***	905-825-6000 Ext.7731
SIC Code:	221320		
SIC Description:	SEWAGE TREATMENT FACILITIES		

--Details--

Waste Code:	252
Waste Description:	WASTE OILS & LUBRICANTS
Waste Code:	268
Waste Description:	AMINES
Waste Code:	221

Waste Description: LIGHT FUELS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 113
Waste Description: ACID WASTE - OTHER METALS

Waste Code: 267
Waste Description: ORGANIC ACIDS

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 222
Waste Description: HEAVY FUELS

Waste Code: 243
Waste Description: PCBS

Site: ***FACCA INCORPORATED***
INTERSECTION OF LAKESHORE RD AND EASTPORT DR BURLINGTON ON L7S 1A2

Database: ***GEN***

Generator No.: ON3154377
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 238990
SIC Description: ALL OTHER SPECIALTY TRADE CONTRACTORS

PO Box No.:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Ryan Wilbur
Phone No. Admin: 519-819-9412 Ext.

--Details--
Waste Code: 253
Waste Description: EMULSIFIED OILS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Site: ***Hydro One Networks Inc.***
Oakville Transformer Station 559 Maplegrove Road Oakville ON L6J 4W3

Database: ***GEN***

Generator No.: ON7305877
Status: Registered
Approval Years: As of Jun 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country: Canada
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--

Waste Code: 243 D
Waste Description: PCB

Waste Code: 251 T
Waste Description: Waste oils/sludges (petroleum based)

Waste Code: 251 L
Waste Description: Waste oils/sludges (petroleum based)

Waste Code: 146 L
Waste Description: Other specified inorganic sludges, slurries or solids

---

Site: ***Trans-Northern Pipelines Inc.***
Maple Grove Rd & Royal Windsor Dr Oakville ON L6J 0B2

Database: ***GEN***

Generator No.: ON8029215
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country: Canada
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 146 L
Waste Description: Other specified inorganic sludges, slurries or solids

---

Site: ***Hanson Brick Ltd.***
Concession 1, Former Township of Nelson Burlington ON

Database: ***NCPL***

Year: 2010
Discharge Type: Industrial Sewage
Sector: Miscellaneous Industrial
District Area: Halton-Peel
Type of Concern: CofA/Permit Non-Compliance
Contaminant: OIL & GREASE
Status Report:

--Details--
Incident Date: 5/31/2010
Incident Start Date: 5/1/2010
Incident End Date: 5/31/2010
Limit/Unit/Freq: 10 mg/L / /mon
Quantity Min/Max: 11/11
Ministry Action: Assessment Complete - Incident Resolved
Facility Action: Other

Incident Date: 9/30/2010
Incident Start Date: 9/1/2010
Incident End Date: 9/30/2010
Limit/Unit/Freq: 10 mg/L / /mon
Quantity Min/Max: 10.1/10.1
Ministry Action: Assessment Complete - Incident Resolved
Facility Action: Other

Incident Date: 11/30/2010
Incident Start Date: 11/1/2010
Incident End Date: 11/30/2010
Limit/Unit/Freq: 10 mg/L / /mon
Quantity Min/Max: 14/14
Ministry Action: Assessment Complete - Incident Resolved
Facility Action: Other

Company Code: O0300F
Industry: OTHER
Site Status: POTENTIAL FOR INSPECTION (TR)
Transaction Date: 5/25/2000
Inspection Date:

--Details--
Label: OR21295
Serial No.:
PCB Type/Code: ASKAREL/ASKAREL
Location:
Item/State: TRANSFORMER/FULL
No. of Items: 1
Manufacturer:
Status: IN-USE
Contents: 842 L

Label: OR21303
Serial No.:
PCB Type/Code: ASKAREL/ASKAREL
Location:
Item/State: TRANSFORMER/FULL
No. of Items: 1
Manufacturer:
Status: IN-USE
Contents: 978 L

Label: OR21302
Serial No.:
PCB Type/Code: ASKAREL/ASKAREL
Location:
Item/State: TRANSFORMER/FULL
No. of Items: 1
Manufacturer:
Status: IN-USE
Contents: 978 L

Label: OR21301
Serial No.:
PCB Type/Code: ASKAREL/ASKAREL
Location:
Item/State: TRANSFORMER/FULL
No. of Items: 1
Manufacturer:
Status: IN-USE
Contents: 978 L

Label: OR21300
Serial No.:
PCB Type/Code: ASKAREL/ASKAREL
Location:
Item/State: TRANSFORMER/FULL
No. of Items: 1
Manufacturer:
Status: IN-USE
Contents: 679 L

Label: OR21299
Serial No.:
PCB Type/Code: ASKAREL/ASKAREL
Location:
Item/State: TRANSFORMER/FULL
No. of Items: 1
Manufacturer:
Status: IN-USE
Contents: 679 L

Label: OR21296
Serial No.:
PCB Type/Code: ASKAREL/ASKAREL
Location:
Item/State: TRANSFORMER/FULL
No. of Items: 1
Manufacturer:
Status: IN-USE
Contents: 842 L

Label: OR21294
Serial No.:
PCB Type/Code: ASKAREL/ASKAREL
Location:
Item/State: TRANSFORMER/FULL
No. of Items: 1
Manufacturer:
Status: IN-USE
Contents: 1318 L

Label: OR21293
Serial No.:
PCB Type/Code: ASKAREL/ASKAREL
Location:
Item/State: TRANSFORMER/FULL
No. of Items: 1
Manufacturer:
Status: IN-USE
Contents: 1318 L

Label: OR21298
Serial No.:
PCB Type/Code: ASKAREL/ASKAREL
Location:
Item/State: TRANSFORMER/FULL
No. of Items: 1
Manufacturer:
Status: IN-USE
Contents: 842 L

Site: ***MAPLEGROVE HOME HARDWARE***
7-511 MAPLE GROVE VILLAGE SHOPPING CTR OAKVILLE ON L6J4W3

Database: ***PES***

Licence No: 09954
Detail Licence No:
Licence Type Code: 23
Licence Type: Active Limited Vendors
Licence Class: 01
Licence Control:
Trade Name:
Post Office Box:
Lot:
Concession:
Region:
District:
County:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Oper Phone Area Cd: 905
Ext:
Oper Phone No: 3380284
Proponent Ext:

Site: ***805681 Ontario Ltd.***
Lot: 3, Concession: 5 Twp Nelson, Burlington, City, Regional Municipality of Halton CITY OF BURLINGTON ON

Database: ***PTTW***

EBR Registry No.: 010-8633
Ministry Ref. No.: 3508-7YQL8S
Notice Type: Instrument Decision
Company Name: 805681 Ontario Ltd.
Proponent Name:
Proposal Address: 5377 Walkers Line, Burlington Ontario, Canada L6T 2X6

Proposal Date: December 18, 2009
Notice Date: July 26, 2010
Year: 2009

Instrument Type: (OWRA s. 34) - Permit to Take Water
Location Other:
URL:

Location:

Lot: 3, Concession: 5 Twp Nelson, Burlington, City, Regional Municipality of Halton CITY OF BURLINGTON

Site: ***Burlington Golf and Country Club, Limited***
Burlington Golf and Country Club 422 North Shore Boulevard East Lots 2 and 3, Concession Broken Front City of Burlington, Regional Municipality of Halton, Ontario CITY OF BURLINGTON ON

Database: ***PTTW***

EBR Registry No.: 011-7085
Ministry Ref. No.: 4550-8XLPWX
Notice Type: Instrument Decision
Company Name: Burlington Golf and Country Club, Limited
Proponent Name:
Proposal Address: 422 North Shore Boulevard East, Burlington Ontario, Canada L7T 3Z9
Instrument Type: (OWRA s. 34) - Permit to Take Water
Location Other:
URL:
Proposal Date: August 29, 2012
Notice Date: December 03, 2012
Year: 2012

Location:

Burlington Golf and Country Club 422 North Shore Boulevard East Lots 2 and 3, Concession Broken Front City of Burlington, Regional Municipality of Halton, Ontario CITY OF BURLINGTON

Site: ***Oakville Executive Golf Club***
Part of Lot 22 and 23, Concession 2, N.D.S. Oakville Ontario L9T 2X8 TOWN OF OAKVILLE ON

Database: ***PTTW***

EBR Registry No.: IA05E1992
Ministry Ref. No.: 4678-6KJHUN
Notice Type: Instrument Decision
Company Name: Oakville Executive Golf Club
Proponent Name:
Proposal Address: 4414 Fourth Line Road, R.R. #4, Milton Ontario, L9T 2X8
Instrument Type: (OWRA s. 34) - Permit to Take Water
Location Other:
URL:
Proposal Date: December 29, 2005
Notice Date: March 10, 2006
Year: 2005

Location:

Part of Lot 22 and 23, Concession 2, N.D.S. Oakville Ontario L9T 2X8 TOWN OF OAKVILLE

Site: ***Camisle Golf Course***
Lot 19 and 20, Concession 2NDS, Township of Nelson, City of Burlington CITY OF BURLINGTON ON

Database: ***PTTW***

EBR Registry No.: IA04E1260
Ministry Ref. No.: 5074-642PC8
Notice Type: Instrument Decision
Company Name: Camisle Golf Course
Proponent Name:
Proposal Address: R.R. #3, 2120 No. 2 Sideroad, Campbellville Ontario, L0P 1B0
Instrument Type: (OWRA s. 34) - Permit to Take Water
Location Other:
URL:
Proposal Date: August 27, 2004
Notice Date: October 12, 2004
Year: 2004

Location:

Lot 19 and 20, Concession 2NDS, Township of Nelson, City of Burlington CITY OF BURLINGTON

Site: ***PETRO-CANADA***
FAIRVIEW & MAPLE BURLINGTON ON L7S1Y3

Database: ***RST***

Headcode:	01186800
Headcode Desc:	SERVICE STATIONS GASOLINE OIL & NATURAL
Phone:	9053333898
List Name:	
Description:	

Site: ***UNKNOWN***
LAKE ONTARIO BRONTE HARBOUR OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	74906	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	8/18/1992	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	UNKNOWN	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	14403
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	HALTON REGION, CITY OF OAKVILLE
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	8/18/1992	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	UNKNOWN		
Incident Summary:	PAINT SHEEN IN BRONTE HARBOUR- SOURCE NOT DETERMINED		

Site: ***MARINE VESSEL***
LAKE ONTARIO OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	40467	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	9/8/1990	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	OTHER CAUSE (N.O.S.)	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	14403
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	C.C.G.
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	9/8/1990	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	INTENTIONAL/PLANNED		

Incident Summary: VESSEL CANADIAN OLYMPIC COAL DUST TO LAKE ONTARIO

Site: ***UNKNOWN***
LAKE ONTARIO BRONTE HARBOR MARINA OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	38758	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	8/5/1990	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	WASTEWATER DISCHARGE TO WATERCOURSE	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	14403
Nature of Impact:		***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	8/5/1990	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	UNKNOWN		
Incident Summary:	UNKNOWN QTY FUEL OIL OR GASOLINE TO BRONTE HARBOUR MARINA.		

Site: ***UNKNOWN***
LAKE ONTARIO - OUTFALL AT END OF BRANT ST. BURLINGTON CITY ON

Database: ***SPL***

Ref No:	31611	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	3/4/1990	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	UNKNOWN	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	14101
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	WORKS
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	3/4/1990	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	UNKNOWN		
Incident Summary:	EST. 2 L DIESEL FUEL DUMPED TO STORM SEWER & LAKE ONTARIO.		

Site: ***HALTON REGION***
LAKE ONTARIO OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	35750	***Discharger Report:***	

Site No:		***Material Group:***	
Incident Dt:	6/3/1990	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	WASTEWATER DISCHARGE TO WATERCOURSE	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	14403
Nature of Impact:		***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	6/3/1990	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	POWER INTERRUPTION		
Incident Summary:	REGION OF HALTON PUMPING STN. - 2 HR. BYPASS OF SEWAGE TO LAKE ONTARIO.		

Site: ***HALTON, REGIONAL MUNICIPALITY***
AT 1155 NORTH SHORE RD. SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS) BURLINGTON CITY ON

Database: ***SPL***

Ref No:	199554	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	4/30/2001	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	OTHER CONTAINER LEAK	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	Possible	***Site Municipality:***	14101
Nature of Impact:	Soil contamination	***Site Lot:***	
Receiving Medium:	Land	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	4/30/2001	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	ERROR		
Incident Summary:	HALTON R.M. - 225 L OF DIGESTED SEWAGE SLUDGE TO GROUND FROM TRUCK.		

Site: ***OAKVILLE HYDRO***
MAPLEGROVE MALL (AT CORNWALL BEHIND FOOD CITY) TRANSFORMER OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	103578	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	8/4/1994	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	COOLING SYSTEM LEAK	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	

Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	14403
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	LAND / WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	F.D. HALTON R.M.
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	8/4/1994	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	FIRE/EXPLOSION		
Incident Summary:	OAKVILLE HYDRO: 800L TRANSFORMER OIL TO GROUND& SEWER DUE TO FIRE.		

Site: ***UNKNOWN***
KENWOOD AVENUE AT LAKESHORE RD W REAR OF LAKESIDE PLAZA BURLINGTON CITY ON

Database: ***SPL***

Ref No:	111062	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	3/18/1995	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	OTHER CONTAINER LEAK	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	14101
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	BURLINGTON CITY WORKS
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	3/18/1995	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	ERROR		
Incident Summary:	UNKNOWN SOURCE- 28 L COOKING OIL TO ASPHALT, NONE TO DRAINS:WORKS		

Site:
LAKE ONTARIO \ OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	134146	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	11/10/1996	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:		***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:		***Site Municipality:***	14403
Nature of Impact:		***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	

MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	11/11/1996	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:			
Incident Summary:			

Site: ***HALTON, REGIONAL MUNICIPALITY***
LAKE ONTARIO NAVY STREET PUMPING STATION SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS) OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	47028	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	2/26/1991	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	WASTEWATER DISCHARGE TO WATERCOURSE	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	14403
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	2/26/1991	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	EQUIPMENT FAILURE		
Incident Summary:	HALTON R.M.: 225 L SEWAGEBYPASS FROM PUMPING STN. DUE TO MECHANICAL PROBLEM		

Site: ***UNKNOWN***
LAKE ONTARIO TANNERY PARK, KERR STREET OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	173483	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	10/5/1999	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	WASTEWATER DISCHARGE TO WATERCOURSE	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	14403
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	OAKVILLE F.D, TOWN OF OAKVILLE,
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	10/5/1999	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			

Incident Reason: INTENTIONAL/PLANNED
Incident Summary: TANNERY PARK: SPILL OF PAINT TO LAKE ONTARIO COMING FROM CATCH BASIN.

Site: ***PLIBRICO CANADA LIMITED***
CREEK BEHIND NELSON HIGH SCHOOL BURLINGTON PLANT 4355 FAIRVIEW STREET BURLINGTON CITY ON

Database: ***SPL***

Ref No:	74025	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	8/2/1992	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	OTHER CONTAINER LEAK	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	14101
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	FIRE DEPARTMENT, REGIONAL SPILLS
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	8/2/1992	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	VANDALISM		
Incident Summary:	PLIBRICO CANADA LTD.: 150 L CUTTING OIL SPILLEDTO CREEK		

Site:
Navy Street and Walker St off of Lakeshore Rd Oakville ON

Database: ***SPL***

Ref No:	8235-8PCMPQ	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	12/8/2011	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:		***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	Oakville Marina Harbour<UNOFFICIAL>
Contaminant Name:		***Site Address:***	Navy Street and Walker St off of Lakeshore Rd
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:		***Site Municipality:***	Oakville
Nature of Impact:		***Site Lot:***	
Receiving Medium:	Sewage - Municipal/Private and Commercial	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:	No Field Response	***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	12/8/2011	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:	Pollution Incident Reports (PIRs) and ¿Other¿ calls		
Incident Reason:			
Incident Summary:	Pollution Hotline:Oakville Marina oil to L Ontario		

Site:
Roseland Creek between Spruce Street and Lake Ontario<UNOFFICIAL> Burlington ON

Database: ***SPL***

Ref No:	6228-6ZPTKC	***Discharger Report:***	

Site No:		***Material Group:***	Other
Incident Dt:		***Client Type:***	
Year:		***Sector Type:***	Unknown
Incident Cause:	Unknown	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:	98	***Site Name:***	Roseland Creek between Spruce Street and Lake Ontario<UNOFFICIAL>
Contaminant Name:	Unknown	***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:	unknown unknown	***Site Region:***	
Environment Impact:	Confirmed	***Site Municipality:***	Burlington
Nature of Impact:	Surface Water Pollution	***Site Lot:***	
Receiving Medium:	Water	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:	No Field Response	***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	3/27/2007	***Site Map Datum:***	
Dt Document Closed:	4/4/2007		
Agency Involved:			
SAC Action Class:			
Incident Reason:	Unknown - Reason not determined		
Incident Summary:	Unknown bluish substance in Roseland Creek		

Site: ***CONTRACTOR***
LAKE ONTARIO (N.O.S.) OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	87587	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	6/25/1993	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	OTHER CAUSE (N.O.S.)	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	14403
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	WORKS
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	6/25/1993	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	INTENTIONAL/PLANNED		
Incident Summary:	RAINBOW DECOR CONTRACTOR-2L WASTE PAINT THINNER TOLAKE ONTARIO, BOOMED.		

Site: ***HALTON, REGIONAL MUNICIPALITY***
LAKE ONTARIO SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS) BURLINGTON CITY ON

Database: ***SPL***

Ref No:	124961	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	4/13/1996	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	WASTEWATER DISCHARGE TO WATERCOURSE	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	

Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	14101
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	4/15/1996	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	EQUIPMENT FAILURE		
Incident Summary:	HALTON REGION: BYPASS RAW UNCHLOR FROM PUMPING STN DUE TO PUMP FAILURE.		

Site: ***HALTON, REGIONAL MUNICIPALITY***
LAKE ONTARIO SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS) BURLINGTON CITY ON

Database: ***SPL***

Ref No:	137521	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	2/22/1997	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	WASTEWATER DISCHARGE TO WATERCOURSE	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	14101
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	2/23/1997	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	EQUIPMENT FAILURE		
Incident Summary:	HALTON REGION: SECONDARY SEWAGE BYPASS DUE TO LIFTGATE FAILURE.		

Site: ***CONTRACTOR***
LAKE ONTARIO SPENCER SMITH PARK (N.O.S.) BURLINGTON CITY ON

Database: ***SPL***

Ref No:	99651	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	3/28/1994	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	OTHER CONTAINER LEAK	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	14101
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	LAND / WATER	***Site Conc:***	
Receiving Env:		***Northing:***	

Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	4/5/1994	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	EQUIPMENT FAILURE		
Incident Summary:	BACKENTRY - MCNALLY CONST. - DIESEL FUEL TO LAKE FROM EQUIPMENT.		

Site: ***HALTON, REGIONAL MUNICIPALITY***
LAKE ONTARIO NEAR FIRST STREET SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS) OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	96845	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	2/26/1994	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	WASTEWATER DISCHARGE TO WATERCOURSE	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	14403
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	2/26/1994	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	UNKNOWN		
Incident Summary:	HALTON REGION - SEWAGE TO LAKE ONTARIO FROM PUMPING STATION		

Site: ***HALTON, REGIONAL MUNICIPALITY***
MAIN ST. & AGNES ACTON, ONTARIO SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS) OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	78486	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	8/24/1992	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	WASTEWATER DISCHARGE TO WATERCOURSE	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	14403
Nature of Impact:		***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	8/25/1992	***Site Map Datum:***	
Dt Document Closed:			

Agency Involved:
SAC Action Class:
Incident Reason: EQUIPMENT FAILURE
Incident Summary: BACKENTRY - HALTON R.M. PUMP. STN. SEWAGE BYPASS DUE TO EQUIPMENT FAILURE.

Site: ***MCASPHALT INDUSTRIES***
LAKE ONTARIO AT PETRO-CANADA DOCK BARGE OAKVILLE TOWN ON

Database: SPL

Ref No:	42688	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	10/27/1990	**Client Type:**	
Year:		**Sector Type:**	
Incident Cause:	OTHER CONTAINER LEAK	**Source Type:**	
Incident Event:		**Nearest Watercourse:**	
Contaminant Code:		**Site Name:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site County/District:**	
Contaminant UN No 1:		**Site Postal Code:**	
Contaminant Qty:		**Site Region:**	
Environment Impact:	POSSIBLE	**Site Municipality:**	14403
Nature of Impact:	Water course or lake	**Site Lot:**	
Receiving Medium:	WATER	**Site Conc:**	
Receiving Env:		**Northing:**	
Health/Env Conseq:		**Easting:**	CCG
MOE Response:		**Site Geo Ref Accu:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Meth:**	
MOE Reported Dt:	10/27/1990	**Site Map Datum:**	

Dt Document Closed:
Agency Involved:
SAC Action Class:
Incident Reason: ERROR
Incident Summary: MCASPHALT INDUSTRIES: 10 BARRELS OF OIL SPILLEDAT PETRO-CANADA DOCK

Site: ***The Regional Municipality of Halton***
Pumping Stn #4 - Main break on North Shore Blvd.<UNOFFICIAL> Burlington ON

Database: SPL

Ref No:	6872-6KAPEX	**Discharger Report:**	0
Site No:		**Material Group:**	Waste
Incident Dt:	12/21/2005	**Client Type:**	
Year:		**Sector Type:**	Other Plant - Sewage Municipal
Incident Cause:	Other Discharges	**Source Type:**	
Incident Event:		**Nearest Watercourse:**	
Contaminant Code:		**Site Name:**	Pumping Stn #4 - Main break on North Shore Blvd.<UNOFFICIAL>
Contaminant Name:	SEWAGE,RAW UNCHLORINATED	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	Halton-Peel
Contam Limit Freq 1:		**Site County/District:**	
Contaminant UN No 1:		**Site Postal Code:**	
Contaminant Qty:		**Site Region:**	
Environment Impact:	Not Anticipated	**Site Municipality:**	Burlington
Nature of Impact:	Soil Contamination; Surface Water Pollution	**Site Lot:**	
Receiving Medium:	Land & Water	**Site Conc:**	
Receiving Env:		**Northing:**	
Health/Env Conseq:		**Easting:**	
MOE Response:		**Site Geo Ref Accu:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Meth:**	
MOE Reported Dt:	12/21/2005	**Site Map Datum:**	

Dt Document Closed:
Agency Involved:
SAC Action Class: Sewage Bypasses / Overflows
Incident Reason: Unknown - Reason not determined
Incident Summary: Pumping Stn #4 - Force Main Break

Site:

Database: SPL

NELSON CREEK AT NEW STREET<UNOFFICIAL> Burlington ON

Ref No:	2863-6Q5MMV	***Discharger Report:***	
Site No:		***Material Group:***	Wastes
Incident Dt:	5/25/2006	***Client Type:***	
Year:		***Sector Type:***	Unknown
Incident Cause:	Discharge Or Bypass To A Watercourse	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:	46	***Site Name:***	
Contaminant Name:	FOAM	***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	Halton-Peel
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:	Not specified m3	***Site Region:***	
Environment Impact:	Possible	***Site Municipality:***	Burlington
Nature of Impact:	Surface Water Pollution	***Site Lot:***	
Receiving Medium:	Water	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	5/25/2006	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	Unknown - Reason not determined		
Incident Summary:	Ukn src: Foaming in Nelson Creek		

Site: ***UNKNOWN***
LAKE ONTARIO, BRONTE HARBOUR OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	129360	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	7/17/1996	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	OTHER CONTAINER LEAK	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	14403
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	WORKS, FD
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	7/18/1996	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	UNKNOWN		
Incident Summary:	UNKNOWN SOURCE-4L DIESEL INTO HARBOUR, SORBED UP TO THE EXTENT PRACTICAL.		

Site: ***PRIVATE OWNER***
LAKE ONTARIO, OAKVILLE HARBOUR PLEASURE CRAFT OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	143441	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	7/12/1997	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	WATERCRAFT SINKING	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	

Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	14403
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	TOWN OF OAKVILLE
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	7/12/1997	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	UNKNOWN		
Incident Summary:	PLEASURE CRAFT-UKN QTY FLUIDS TO HARBOUR FROM SUNKEN BOAT,BOOMED.		

Site: ***UNKNOWN***
MAPLE GROVE, CATCH BASIN OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	80650	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	//	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	UNKNOWN	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	14403
Nature of Impact:		***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	12/31/1992	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	INTENTIONAL/PLANNED		
Incident Summary:	BACKENTRY-2400 PPM OF PCBFOUND IN CATCHBASIN ON MAPLE GROVE CLEANUP ORDER		

Site: ***MAPLE LEAF CARTAGE***
SHAW & LAKESHORE TRANSPORT TRUCK (CARGO) OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	71198	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	5/27/1992	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	OTHER CONTAINER LEAK	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	14403
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	

Health/Env Conseq:		***Easting:***	POLICE, WORKS, MOE
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	5/27/1992	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	EQUIPMENT FAILURE		
Incident Summary:	MAPLE LEAF FOODS - 203 L KITCHEN GREASE ONTO ROAD WHEN BARREL TIPPED-OVER.		

Site: ***PLEASURE CRAFT***
LAKE ONTARIO INVALID ENTRY - CHOOSE ANOTHER OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	78490	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	9/21/1992	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	WATERCRAFT SINKING	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	14403
Nature of Impact:		***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	OAKVILLE PUBLIC WORKS
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	9/21/1992	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	NEGLIGENCE (APPARENT)		
Incident Summary:	BACKENTRY - 20L GASOLINE TO WATER FROM SUNKEN PLEASURE CRAFT.		

Site: ***HALTON, REGIONAL MUNICIPALITY***
LAKE ONTARIO SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS) OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	122861	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	1/21/1996	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	WASTEWATER DISCHARGE TO WATERCOURSE	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	14403
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	1/21/1996	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	POWER INTERRUPTION		

Incident Summary: HALTON R.M.,LAKEWOOD P.S.SEWAGE BYPASS DUE TO POWER FAILURE.

Site: ***UNKNOWN***
LAKE ONTARIO OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	55534	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	8/12/1991	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	UNKNOWN	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	14403
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	8/12/1991	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	UNKNOWN		
Incident Summary:	SMALL OIL SLICK ON LAKE ONTARIO IN OAKVILLE		

Site: ***BURLINGTON HYDRO-ELECTRIC COMM***
LAKESHORE RD .5 K/M WEST OF WALKERS LINE TRANSFORMER BURLINGTON CITY ON

Database: ***SPL***

Ref No:	66512	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	1/28/1992	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	COOLING SYSTEM LEAK	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	14101
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND / WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	HYDRO,WORKS,FD.
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	1/28/1992	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	ERROR		
Incident Summary:	BURLINGTON HYDRO-90 L. TRANSFROMER OIL TO GRND, 5 L. TO SEWER,CLEANED-UP.		

Site: ***UNKNOWN***
LAKE ONTARIO VIA STORM SEWER TRAFALGAR ROAD/LAKESHORE ROAD EAST OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	116795	***Discharger Report:***	
Site No:		***Material Group:***	

Incident Dt:	8/5/1995	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	UNKNOWN	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	14403
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	LAND / WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	FD, HALTON REG.
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	8/5/1995	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	UNKNOWN		
Incident Summary:	DIESEL FUEL IN SEWER SYS-TEM,OUTFALL & LAKE ONT. FD, WORKS, SOURCE UNKNOWN		

Site: ***PLIBRICO CANADA LIMITED***
LAKE ONTARIO SHOREACRES CR.,SECORD LANE & LAKESHORE BURLINGTON PLANT 4355 FAIRVIEW STREET BURLINGTON CITY ON

Database: ***SPL***

Ref No:	55264	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	8/7/1991	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	OTHER CONTAINER LEAK	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	14101
Nature of Impact:	Fish kill	***Site Lot:***	
Receiving Medium:	LAND / WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	REGION, MOE, CITY OF BURLINGTON
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	8/7/1991	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	EQUIPMENT FAILURE		
Incident Summary:	PLIBRICO - <180L MINERAL OIL (WASTE) TO GROUND CREEK AND LAKE ONTARIO		

Site: ***Union Gas Limited***
537 North Shore Blvd E. Burlington ON

Database: ***SPL***

Ref No:	8382-AZJT83	***Discharger Report:***	
Site No:	NA	***Material Group:***	
Incident Dt:	2018/06/08	***Client Type:***	Corporation
Year:		***Sector Type:***	Miscellaneous Communal
Incident Cause:		***Source Type:***	Valve/Fitting/Piping
Incident Event:	Leak/Break	***Nearest Watercourse:***	
Contaminant Code:	35	***Site Name:***	Half Inch IP Plastic Line Strike <UNOFFICIAL>
Contaminant Name:	NATURAL GAS (METHANE)	***Site Address:***	537 North Shore Blvd E.
Contaminant Limit 1:		***Site District Office:***	Halton-Peel
Contam Limit Freq 1:		***Site County/District:***	Regional Municipality of Halton

Contaminant UN No 1:	1075	***Site Postal Code:***	
Contaminant Qty:	0 other - see incident description	***Site Region:***	Central
Environment Impact:		***Site Municipality:***	Burlington
Nature of Impact:		***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:	Air	***Northing:***	
Health/Env Conseq:	2 - Minor Environment	***Easting:***	
MOE Response:	No	***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	2018/06/08	***Site Map Datum:***	
Dt Document Closed:	2018/06/16		
Agency Involved:			
SAC Action Class:	TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill		
Incident Reason:	Operator/Human Error		
Incident Summary:	TSSA/FSB: 1/2" IP Plastic Line Strike - Made Safe		

Site: ***Rankin Construction Inc.***
Lakeshore Rd. at Sheldon Creek in Oakville <UNOFFICIAL> Oakville ON

Database: ***SPL***

Ref No:	1234-7JZUNV	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:		***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	Pipe Or Hose Leak	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:	44	***Site Name:***	Lakeshore Rd. at Sheldon Creek in Oakville <UNOFFICIAL>
Contaminant Name:	SEWAGE,RAW UNCHLORINATED	***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	Halton-Peel
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:	450 L	***Site Region:***	
Environment Impact:	Not Anticipated	***Site Municipality:***	Oakville
Nature of Impact:		***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:	No Field Response	***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	10/1/2008	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:	Land Spills		
Incident Reason:	Error- Operator error		
Incident Summary:	Rankin Construction - <450 L of sewage to ground.		

Site: ***Rotomill<UNOFFICIAL>; The Corporation of the City of Burlington***
MAPLE AVE N FROM LAKESHORE TO WEST ON PLAINS RD TO NORTH ON WATERDOWN RD<UNOFFICIAL>
Burlington ON

Database: ***SPL***

Ref No:	3633-63T4SS	***Discharger Report:***	
Site No:		***Material Group:***	Oil
Incident Dt:	8/12/2004	***Client Type:***	
Year:		***Sector Type:***	Other
Incident Cause:	Other Discharges	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:	13	***Site Name:***	MAPLE AVE N FROM LAKESHORE TO WEST ON PLAINS RD
Contaminant Name:	DIESEL FUEL	***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	Halton-Peel
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:	200 L	***Site Region:***	Central
Environment Impact:	Possible	***Site Municipality:***	Burlington
Nature of Impact:	Surface Water Pollution	***Site Lot:***	
Receiving Medium:	Water	***Site Conc:***	
Receiving Env:		***Northing:***	

Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	8/12/2004	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:	Spill to Land		
Incident Reason:	Unknown - Reason not determined		
Incident Summary:	Rotomill - Diesel Spill to Roadways		

Site: ***Database:*** ***SPL***

LAKESHORE AND BELLHAVEN<UNOFFICIAL> Burlington ON

Ref No:	1527-5SF3AV	***Discharger Report:***	
Site No:		***Material Group:***	Waste
Incident Dt:	10/17/2003	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:		***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:	44	***Site Name:***	LAKESHORE AND BELLHAVEN<UNOFFICIAL>
Contaminant Name:	SEWAGE,RAW UNCHLORINATED	***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	Halton-Peel
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	Central
Environment Impact:		***Site Municipality:***	Burlington
Nature of Impact:		***Site Lot:***	
Receiving Medium:	Land	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	10/17/2003	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:			
Incident Summary:	Halton Region-Sewage Forcemain Break.		

Site: ***UNKNOWN*** ***Database:*** ***SPL***

LAKE ONTARIO BURLINGTON CITY ON

Ref No:	153568	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	12/11/1990	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	UNKNOWN	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	14101
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	12/11/1990	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	UNKNOWN		

Incident Summary: UNKNOWN SOURCE:OIL SHEEN NOTICED ON LAKE ONTARIO..

Site: ***UNKNOWN***
LAKE ONTARIO OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	91928	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	10/2/1993	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	UNKNOWN	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	14403
Nature of Impact:		***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	CCG.
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	10/2/1993	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			

Incident Reason: UNKNOWN
Incident Summary: VERY LIGHT OIL SHEEN IN LAKE ONTARIO, BREAKING UPSOURCE UNKNOWN, CCG.

Site: ***UNKNOWN***
LAKE ONTARIO, WEST OUTFALL FROM WATERSEDGE PARK OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	125420	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	4/23/1996	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	UNKNOWN	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	14403
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	OAKVILLE WORKS
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	4/23/1996	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			

Incident Reason: UNKNOWN
Incident Summary: UNK SRC-RESIDENT REPORTS OIL TO LAKE ONT FROM OUT-FALL.WORKS RESPONDED.

Site: ***HALTON, REGIONAL MUNICIPALITY***
MORRISON CREEK/LAKE ONTARIO/MORRISON HEIGHTS PUMPING STATION. SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS) OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	110452	***Discharger Report:***	

Site No:		***Material Group:***	
Incident Dt:	2/28/1995	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	WASTEWATER DISCHARGE TO WATERCOURSE	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	14403
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	3/1/1995	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	POWER INTERRUPTION		
Incident Summary:	HALTON REG.,MORRISON HGTSPUMPING STN- RAW SEWAGE BYPASS, POWER OUTAGE.		

Site: ***HALTON, REGIONAL MUNICIPALITY***
LAKE ONTARIO, PUMPING STATION SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS) OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	179686	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	4/18/2000	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	WASTEWATER DISCHARGE TO WATERCOURSE	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	14403
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	4/18/2000	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	DAMAGE BY MOVING EQUIPMENT		
Incident Summary:	HALTON REGION- BY-PASS OF 200 IG RAW CHLORINATED SEWAGE. BROKEN FORCEMAIN.		

Site: ***Union Gas Limited***
601 North Shore Blvd, Burlington ON

Database: ***SPL***

Ref No:	1588-9WBLLL	***Discharger Report:***	
Site No:	NA	***Material Group:***	
Incident Dt:	5/8/2015	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	Leak/Break	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:	35	***Site Name:***	Residental Site<UNOFFICIAL>

Contaminant Name:	NATURAL GAS (METHANE)	***Site Address:***	601 North Shore Blvd,
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:	0 other - see incident description	***Site Region:***	
Environment Impact:		***Site Municipality:***	Burlington
Nature of Impact:	Air	***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:	N	***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	5/8/2015	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:	Air Spills - Gases and Vapours		
Incident Reason:	Operator/Human Error		
Incident Summary:	Union gas, Line strike, made safe		

Site: ***1277136 Alberta Ltd.***
Lakeshore Road Oakville ON

Database: ***SPL***

Ref No:	3337-A83RTR	***Discharger Report:***	
Site No:	NA	***Material Group:***	
Incident Dt:	2016/03/15	***Client Type:***	
Year:		***Sector Type:***	Unknown / N/A
Incident Cause:		***Source Type:***	
Incident Event:	Leak/Break	***Nearest Watercourse:***	Lake Ontario
Contaminant Code:	15	***Site Name:***	Suncor Energy Dock - Lake Ontario <UNOFFICIAL>
Contaminant Name:	ENGINE OIL	***Site Address:***	Lakeshore Road
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:	1 L	***Site Region:***	
Environment Impact:		***Site Municipality:***	Oakville
Nature of Impact:		***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:	Land; Surface Water; Source Water Zone	***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:	No	***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	2016/03/15	***Site Map Datum:***	
Dt Document Closed:	2016/06/04		
Agency Involved:			
SAC Action Class:	Watercourse Spills		
Incident Reason:	Equipment Failure		
Incident Summary:	Suncor Energy: 1 L engine oil to lake ontario		

Site: ***TERRATEC ENVIRONMENTAL LTD.***
AREA CREEK, SW OAKVILLE WPCP (EAST OF THIRD AND LAKESHORE) TANK TRUCK (CARGO) OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	224352	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	4/24/2002	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	OTHER CONTAINER LEAK	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	14403
Nature of Impact:	Water course or lake	***Site Lot:***	

Receiving Medium:	LAND / WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	4/24/2002	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:	HALTON REGION WORKS		
SAC Action Class:			
Incident Reason:	OTHER		
Incident Summary:	TERRATEC: UKN AMOUT OF BIOSOLIDS (SLUDGE) TO STORM C/B, CREEK.		

Site: ***UNKNOWN***
LAKE ONTARIO IN BURLINGTON HARBOUR BURLINGTON CITY ON

Database: ***SPL***

Ref No:	173639	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	10/10/1999	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	UNKNOWN	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	14101
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	CCG, HARBOUR COMMISSION
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	10/10/1999	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	UNKNOWN		
Incident Summary:	SOURCE UNKNOWN - LIGHT OIL SHEEN IN BURLINGTON HARBOUR.		

Site: ***MCASPHALT INDUSTRIES***
LAKE ONTARIO PETRO-CANADA DOCK BARGE OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	45528	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	1/9/1991	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	OTHER CONTAINER LEAK	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	14403
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	LAND / WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	CCG, EPS
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	1/9/1991	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			

Incident Reason: OVERSTRESS/OVERPRESSURE
Incident Summary: MCASPHALT: SMALL AMOUNT ASPHALT TO DOCK AND LAKE WHEN RELIEF VALVE OPENED

Site: ***Database:*** SPL
2463 Lakeshore Rd Oakville ON

Ref No:	4534-99WKJG	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	2013/07/24	***Client Type:***	
Year:		***Sector Type:***	Sewer (Private or Municipal)
Incident Cause:	Leak/Break	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:	44	***Site Name:***	force main<UNOFFICIAL>
Contaminant Name:	SEWAGE,RAW UNCHLORINATED	***Site Address:***	2463 Lakeshore Rd
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:	1 m^3	***Site Region:***	
Environment Impact:	Confirmed	***Site Municipality:***	Oakville
Nature of Impact:	Surface Water Pollution	***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:	No Field Response	***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	2013/07/24	***Site Map Datum:***	
Dt Document Closed:	2013/09/06		
Agency Involved:			
SAC Action Class:	Sewage Bypasses / Overflows		
Incident Reason:	Unknown / N/A		
Incident Summary:	2463 Lakeshore rd WW forcmain brk impct CB, ongoing		

Site: ***Database:*** SPL
Bronte Creek & Ontario Street Oakville ON

Ref No:	7206-AACW3W	***Discharger Report:***	
Site No:	NA	***Material Group:***	
Incident Dt:	2016/05/27	***Client Type:***	
Year:		***Sector Type:***	Unknown / N/A
Incident Cause:		***Source Type:***	
Incident Event:	Unknown / N/A	***Nearest Watercourse:***	
Contaminant Code:	13	***Site Name:***	Bronte Outer Harbour Marina <UNOFFICIAL>
Contaminant Name:	HYDROCARBON LIGHT	***Site Address:***	Bronte Creek & Ontario Street
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:	8 L	***Site Region:***	
Environment Impact:		***Site Municipality:***	Oakville
Nature of Impact:		***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:	Surface Water; Source Water Zone	***Northing:***	4805502
Health/Env Conseq:		***Easting:***	604914
MOE Response:	No	***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	2016/05/27	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:	Watercourse Spills		
Incident Reason:	Unknown / N/A		
Incident Summary:	Bronte Harbour Marina: Oil on water observation		

Site: ***Miller Waste Systems Inc.*** ***Database:*** SPL
near Lakeshore Dr E and Alexander Dr Oakville ON

Ref No:	1526-7R7JYM	***Discharger Report:***	

Site No:		***Material Group:***	
Incident Dt:		***Client Type:***	
Year:		***Sector Type:***	Motor Vehicle
Incident Cause:	Other Transport Accident	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	MVA<UNOFFICIAL>
Contaminant Name:	DIESEL FUEL	***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:	0 other - see incident description	***Site Region:***	
Environment Impact:	Confirmed	***Site Municipality:***	Oakville
Nature of Impact:	Soil Contamination	***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	4/17/2009	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:	Land Spills		
Incident Reason:	Other - Reason not otherwise defined		
Incident Summary:	Miller Waste Systems: diesel to grnd and ditch, cntd		

Site: ***HALTON, REGIONAL MUNICIPALITY***
LAKE ONTARIO. OAKVILLE WTP. OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	168393	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	6/1/1999	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	OTHER CAUSE (N.O.S.)	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	14403
Nature of Impact:		***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	6/1/1999	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	ERROR		
Incident Summary:	HALTON R.M.,OAKVILLE WTP-2 HRS OVERFLOW OF SLUDGE/FILTRATE TO S.S. & LAKE.		

Site: ***HALTON, REGIONAL MUNICIPALITY***
LAKE ONTARIO & SIXTEEN MILE CREEK SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS)
BURLINGTON CITY ON

Database: ***SPL***

Ref No:	120948	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	11/17/1995	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	WASTEWATER DISCHARGE TO WATERCOURSE	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	

Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	14101
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	11/17/1995	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	EQUIPMENT FAILURE		
Incident Summary:	R-M HALTON-RAW SEWAGE TO LAKE ONTARIO & 16-MILE CR: MAJOR PUMP FAILURE		

Site: ***UNKNOWN***
LAKE ONTARIO OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	103924	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	8/13/1994	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	WASTEWATER DISCHARGE TO WATERCOURSE	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	14403
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	FD, WORKS, REGION SPILLS
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	8/13/1994	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	UNKNOWN		
Incident Summary:	UNKNOWN SOURCE-OIL SHEEN TO OAKVILLE HARBOUR FROM STORM OUTFALL.		

Site: ***OAKVILLE HYDRO***
LAKE ONTARIO TRANSFORMER OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	109533	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	1/26/1995	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	COOLING SYSTEM LEAK	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	14403
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	

Health/Env Conseq:		***Easting:***	HALTON REGION
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	1/26/1995	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	UNKNOWN		
Incident Summary:	OAKVILLE HYDRO - 120 L OFMINERAL OIL TO STORM SEWER FROM TRANSFORMER.		

Site: ***The Regional Municipality of Halton***
108 Maplegrove Rd Oakville ON

Database: ***SPL***

Ref No:	6653-9R7Q5U	***Discharger Report:***	
Site No:	NA	***Material Group:***	
Incident Dt:	2014/11/24	***Client Type:***	
Year:		***Sector Type:***	Sewer (Private or Municipal)
Incident Cause:	Bypass	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	Lake Ontario
Contaminant Code:	44	***Site Name:***	Residential<UNOFFICIAL>
Contaminant Name:	SEWAGE,RAW UNCHLORINATED	***Site Address:***	108 Maplegrove Rd
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:	1 m^3	***Site Region:***	
Environment Impact:		***Site Municipality:***	Oakville
Nature of Impact:	Surface Water	***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:		***Northing:***	4813799
Health/Env Conseq:		***Easting:***	609689
MOE Response:	N	***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	2014/11/25	***Site Map Datum:***	
Dt Document Closed:	2014/12/12		
Agency Involved:			
SAC Action Class:	Watercourse Spills		
Incident Reason:	Operator/Human Error		
Incident Summary:	Region of Halton, cross connection of sanitary to storm, Lake Ontario		

Site: ***Union Gas Limited***
134 Maple Grove Ave. Oakville ON

Database: ***SPL***

Ref No:	4017-9CK4HU	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	2013/10/16	***Client Type:***	
Year:		***Sector Type:***	Pipeline/Components
Incident Cause:	Leak/Break	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:	35	***Site Name:***	Residential<UNOFFICIAL>
Contaminant Name:	NATURAL GAS (METHANE)	***Site Address:***	134 Maple Grove Ave.
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:	0 other - see incident description	***Site Region:***	
Environment Impact:	Confirmed	***Site Municipality:***	Oakville
Nature of Impact:	Air Pollution	***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:	Not MOE mandate	***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	2013/10/16	***Site Map Datum:***	
Dt Document Closed:	2013/11/01		
Agency Involved:			
SAC Action Class:	TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill		
Incident Reason:	Operator/Human Error		
Incident Summary:	TSSA FSB: 1 1/4" plastic service line strike to atm.		

Site: ***Cole Engineering Group Ltd.***
Lakeshore Road & Willow Ridge Crescent - 43.418620, -79.689945 Oakville ON

Database: ***SPL***

Ref No:	0804-AC8GWG	***Discharger Report:***	
Site No:	NA	***Material Group:***	
Incident Dt:	2016/07/26	***Client Type:***	
Year:		***Sector Type:***	Miscellaneous Industrial
Incident Cause:		***Source Type:***	
Incident Event:	Leak/Break	***Nearest Watercourse:***	Unknown Name
Contaminant Code:	41	***Site Name:***	14 Mile Creek<UNOFFICIAL>
Contaminant Name:	BENTONITE SLURRY	***Site Address:***	Lakeshore Road & Willow Ridge Crescent - 43.418620, -79.689945
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:	2 L	***Site Region:***	
Environment Impact:		***Site Municipality:***	Oakville
Nature of Impact:		***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:	Surface Water	***Northing:***	4808137
Health/Env Conseq:		***Easting:***	606053
MOE Response:	No	***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	2016/07/26	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:	Watercourse Spills		
Incident Reason:	Operator/Human Error		
Incident Summary:	Oakville: Bentonite Slurry to 14 Mile Creek, cntd.		

Site: ***To be determined<UNOFFICIAL>***
cb and Old Lakeshore Rd<UNOFFICIAL> Burlington ON

Database: ***SPL***

Ref No:	0357-6Z6QP2	***Discharger Report:***	
Site No:		***Material Group:***	Oil
Incident Dt:		***Client Type:***	
Year:		***Sector Type:***	Other Motor Vehicle
Incident Cause:	Unknown	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:	15	***Site Name:***	cb and Old Lakeshore Rd<UNOFFICIAL>
Contaminant Name:	OIL (PETROLEUM BASED, NOT SPECIFIED)	***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:	0 other - see incident description	***Site Region:***	
Environment Impact:	Confirmed	***Site Municipality:***	Burlington
Nature of Impact:	Surface Water Pollution	***Site Lot:***	
Receiving Medium:	Water	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:	No Field Response	***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	3/10/2007	***Site Map Datum:***	
Dt Document Closed:	4/4/2007		
Agency Involved:			
SAC Action Class:			
Incident Reason:	Unknown - Reason not determined		
Incident Summary:	ukn src: sheen flowing down road and into cb.		

Site: ***CONTRACTOR***
LAKE ONTARIO, FROM APPLEBY CREEK BEHIND LORD ELGIN SCHOOL (N.O.S.) BURLINGTON CITY ON

Database: ***SPL***

Ref No:	142554	***Discharger Report:***	
Site No:		***Material Group:***	

Incident Dt:	6/24/1997	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	OTHER CAUSE (N.O.S.)	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	14101
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	CITY OF BURLINGTON
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	6/24/1997	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	VANDALISM		
Incident Summary:	CONTRACTOR - DUMPING UNK MATERIAL TO CATCH BASIN WORKS ON SCENE.		

Site: ***HALTON, REGIONAL MUNICIPALITY***
TO CREEK & LAKE ONTARIO FROM PUMPING STATION #5, 374 NORTH SHORE BLVD. SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS) BURLINGTON CITY ON

Database: ***SPL***

Ref No:	118399	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	9/11/1995	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	WASTEWATER DISCHARGE TO WATERCOURSE	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	14101
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	9/12/1995	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	EQUIPMENT FAILURE		
Incident Summary:	HALTON REGION: BYPASS OF 1 M3 RAW, CHLORINATED SEWAGE, PUMP FAILURE.		

Site: ***MSO CONSTRUCTION***
PARK 200' WEST OF CAIRN CROFT AND SOUTH OF LAKESHORE TO MORRISON CREEK. TANK TRUCK (CARGO) OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	117388	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	8/17/1995	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	OTHER CAUSE (N.O.S.)	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	

Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	14403
Nature of Impact:	Soil contamination	***Site Lot:***	
Receiving Medium:	LAND / WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	WORKS,
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	8/18/1995	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	ERROR		
Incident Summary:	MSO CONSTRUCTION- CRS2 ASPHALT EMULSION TO C/B AND MORRISON CREEK.		

Site: ***Database:*** ***SPL***

b/t Randall St and Lakeshore Rd W Bridges Oakville ON

Ref No:	7020-86GB63	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:		***Client Type:***	
Year:		***Sector Type:***	Water Craft
Incident Cause:	Sinking - Watercraft	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	Busby Park Shore<UNOFFICIAL>
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	Confirmed	***Site Municipality:***	
Nature of Impact:	Surface Water Pollution	***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:	Priority Field Response (ERP Callout)	***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	6/16/2010	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:	Watercourse Spills		
Incident Reason:	Unknown - Reason not determined		
Incident Summary:	4 pleasurecraft on fire along the shores of 16mi creek		

Site: ***CONTRACTOR*** ***Database:*** ***SPL***

LAKE ONTARIO AT BRONTE HARBOUR (N.O.S.) OAKVILLE TOWN ON

Ref No:	113888	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	6/1/1995	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	UNKNOWN	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	14403
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	EPS, CCG

MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	6/1/1995	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	UNKNOWN		
Incident Summary:	SOUTHEAST MARINE - OIL TO LAKE ONTARIO AT BRONTEHARBOUR.		

Site: ***HALTON, REGIONAL MUNICIPALITY***
LAKE ONTARIO, FROM THE MID-HALTON PUMPING STATION ON NORTH SERVICE RD. SANITARY SEWER SYSTEM (INCLUDING PUMPING STATIONS) OAKVILLE TOWN ON

Database: ***SPL***

Ref No:	136515	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	1/16/1997	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	WASTEWATER DISCHARGE TO WATERCOURSE	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	14403
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	1/24/1997	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	ICE/FROST DAMAGE		
Incident Summary:	HALTON, REGIONAL MUNIC: 120 M3 BYPASS OF RAW, CHLORINATED SEWAGE.		

Site:
Western Lake Ontario Burlington ON

Database: ***SPL***

Ref No:	0451-AXGJ6M	***Discharger Report:***	
Site No:	NA	***Material Group:***	
Incident Dt:	2018/04/03	***Client Type:***	
Year:		***Sector Type:***	Unknown / N/A
Incident Cause:		***Source Type:***	Marine - Bulk Carrier/Tanker
Incident Event:	Leak/Break	***Nearest Watercourse:***	
Contaminant Code:	13	***Site Name:***	CCGS Private Robertson<UNOFFICIAL>
Contaminant Name:	FUEL OIL	***Site Address:***	Western Lake Ontario
Contaminant Limit 1:		***Site District Office:***	Halton-Peel
Contam Limit Freq 1:		***Site County/District:***	Regional Municipality of Halton
Contaminant UN No 1:	1202	***Site Postal Code:***	
Contaminant Qty:	0 L	***Site Region:***	Central
Environment Impact:		***Site Municipality:***	Burlington
Nature of Impact:		***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:	Surface Water	***Northing:***	
Health/Env Conseq:	2 - Minor Environment	***Easting:***	
MOE Response:	No	***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	2018/04/03	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:	Watercourse Spills		
Incident Reason:	Unknown / N/A		

Incident Summary: DUPLICATE OF 5677-AXGJ3S

Site: ***Database:*** ***SPL***

Outfall in Nelson Park just south of Longmoor Burlington ON

Ref No:	7222-7VER5R	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:		***Client Type:***	
Year:		***Sector Type:***	Other
Incident Cause:		***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	Outfall in Nelson Park just south of Longmoor<UNOFFICIAL>
Contaminant Name:	OIL (PETROLEUM BASED, NOT SPECIFIED)	***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	Confirmed	***Site Municipality:***	Burlington
Nature of Impact:	Surface Water Pollution	***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:	No Field Response	***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	8/30/2009	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:	Watercourse Spills		
Incident Reason:			
Incident Summary:	Nelson Park: Hydrocarbon sheen on Shore Acres Creek		

Site: ***UNKNOWN*** ***Database:*** ***SPL***

SHOREACRES CREEK BETWEEN NELSON ARENA AND NELSON HIGH SCHOOL. BURLINGTON CITY ON

Ref No:	151638	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	1/20/1998	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	WASTEWATER DISCHARGE TO WATERCOURSE	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	14101
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	WORKS
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	1/20/1998	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:			
Incident Reason:	UNKNOWN		
Incident Summary:	UNKNOWN SOURCE-OILY MATERIAL TO CREEK, WORKS SETUP BOOM, CONTAINED.		

Site: ***Database:*** ***SPL***

Lake Ontario (just south of Oakville) Oakville ON

Ref No:	1358-9XDVGW	***Discharger Report:***	
Site No:	NA	***Material Group:***	
Incident Dt:	6/11/2015	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	Unknown / N/A	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	Lake Ontario
Contaminant Code:	15	***Site Name:***	Lake Ontario (43"25'.12 north, 79"39'.18 west)<UNOFFICIAL>
Contaminant Name:	OIL (PETROLEUM BASED, NOT SPECIFIED)	***Site Address:***	Lake Ontario (just south of Oakville)
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:	5 L	***Site Region:***	
Environment Impact:		***Site Municipality:***	Oakville
Nature of Impact:	Surface Water	***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:		***Northing:***	4789966
Health/Env Conseq:		***Easting:***	630548
MOE Response:	N	***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	6/11/2015	***Site Map Datum:***	
Dt Document Closed:	6/24/2015		
Agency Involved:			
SAC Action Class:	Watercourse Spills		
Incident Reason:	Unknown / N/A		
Incident Summary:	Unknown: 5 L oil sheen in Lake Ontario		

Site: ***Union Gas Limited***
Corner of Lakeshore Rd and Great Lakes Blvd Oakville ON

Database: ***SPL***

Ref No:	7844-9SXQHV	***Discharger Report:***	
Site No:	NA	***Material Group:***	
Incident Dt:	1/20/2015	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	Leak/Break	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:	35	***Site Name:***	6-inch Gas Main<UNOFFICIAL>
Contaminant Name:	NATURAL GAS (METHANE)	***Site Address:***	Corner of Lakeshore Rd and Great Lakes Blvd
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:	0 other - see incident description	***Site Region:***	
Environment Impact:		***Site Municipality:***	Oakville
Nature of Impact:	Air	***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:	N	***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	1/20/2015	***Site Map Datum:***	
Dt Document Closed:			
Agency Involved:			
SAC Action Class:	Air Spills - Gases and Vapours		
Incident Reason:	Equipment Failure		
Incident Summary:	TSSA: leak in 6-inch gas main		

Site:
OAKVILLE ON

Database: ***WWIS***

Well ID:	7216634	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:	Monitoring	***Date Received:***	2/20/2014
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	0	***Abandonment Rec:***	
Water Type:		***Contractor:***	7295
Casing Material:		***Form Version:***	7
Audit No:	Z165896	***Owner:***	

Tag: A144025
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Street Name: 7477 LAKESHORE RD E
County:
Municipality:
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1004713317
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10-SEP-13
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 0
East83: 794329
Org CS: UTM83
North83: 4322191
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1005084874
Layer: 2
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 91
Other Materials: WATER-BEARING
Mat3:
Other Materials:
Formation Top Depth: 8
Formation End Depth: 10
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1005084875
Layer: 3
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 10
Formation End Depth: 20
Formation End Depth UOM: ft

Overburden and Bedrock

Materials Interval

Formation ID:	1005084873
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	77
Other Materials:	LOOSE
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	8
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005084882
Layer:	1
Plug From:	0
Plug To:	9
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1005084881
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1005084872
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005084878
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	10
Casing Diameter:	1.8
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1005084879
Layer:	1
Slot:	10
Screen Top Depth:	10
Screen End Depth:	20
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2

Water Details

Water ID: 1005084877
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1005084876
Diameter: 6
Depth From: 1
Depth To: 20
Hole Depth UOM: ft
Hole Diameter UOM: inch

Site:
BURLINGTON ON

Database:
WWIS

Well ID: 7240590
Construction Date:
Primary Water Use: Monitoring
Sec. Water Use:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z208585
Tag: A179744
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 4/27/2015
Selected Flag: Yes
Abandonment Rec:
Contractor: 7472
Form Version: 7
Owner:
Street Name: LOCUS & ELGIN ST
County:
Municipality:
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1005329365
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 30-MAR-15
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone:
East83:
Org CS: UTM83
North83:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1005596837
Layer: 1
Color: 6
General Color: BROWN
Mat1: 09

Most Common Material: MEDIUM SAND
Mat2: 06
Other Materials: SILT
Mat3: 77
Other Materials: LOOSE
Formation Top Depth: 0
Formation End Depth: 1.5
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1005596839
Layer: 3
Color: 2
General Color: GREY
Mat1: 17
Most Common Material: SHALE
Mat2:
Other Materials:
Mat3: 73
Other Materials: HARD
Formation Top Depth: 2.1
Formation End Depth: 4.6
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1005596838
Layer: 2
Color: 7
General Color: RED
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Other Materials: SILT
Mat3: 79
Other Materials: PACKED
Formation Top Depth: 1.5
Formation End Depth: 2.1
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005596848
Layer: 2
Plug From: 2.5
Plug To: 4.6
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005596846
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005596847
Layer: 1

Plug From: 0
Plug To: 2.5
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1005596845
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1005596836
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005596842
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 2.5
Casing Diameter: 5.2
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1005596843
Layer: 1
Slot: 10
Screen Top Depth: 2.5
Screen End Depth: 4.6
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.4

Water Details

Water ID: 1005596841
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1005596840
Diameter: 21
Depth From: 0
Depth To: 4.6
Hole Depth UOM: m
Hole Diameter UOM: cm

Site:
Burlington ON

Database:
WWIS

Well ID: 7194899
Construction Date:
Primary Water Use: Monitoring
Sec. Water Use:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z159672
Tag: A139222
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 1/7/2013
Selected Flag: Yes
Abandonment Rec:
Contractor: 7472
Form Version: 7
Owner:
Street Name: 5348 LAKESHORE ROAD
County:
Municipality:
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1004232010
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10-DEC-12
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone:
East83:
Org CS: UTM83
North83:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1004744502
Layer: 1
Color: 6
General Color: BROWN
Mat1: 34
Most Common Material: TILL
Mat2:
Other Materials:
Mat3: 77
Other Materials: LOOSE
Formation Top Depth: 0
Formation End Depth: 1.5
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004744503
Layer: 2
Color: 7
General Color: RED
Mat1: 17
Most Common Material: SHALE
Mat2:
Other Materials:

Mat3: 66
Other Materials: DENSE
Formation Top Depth: 1.5
Formation End Depth: 7.6
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004744511
Layer: 2
Plug From: 5.5
Plug To: 7.6
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004744510
Layer: 1
Plug From: 0
Plug To: 5.5
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004744509
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1004744501
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004744506
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 7.6
Casing Diameter: 1.9
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004744507
Layer: 1
Slot: 10
Screen Top Depth: 6.1
Screen End Depth: 7.6
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 2.3

Water Details

Water ID: 1004744505
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004744504
Diameter: 15
Depth From: 0
Depth To: 7.6
Hole Depth UOM: m
Hole Diameter UOM: cm

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ***Note:*** *Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.*

Abandoned Aggregate Inventory: Provincial AAGR

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

Government Publication Date: Sept 2002*

Aggregate Inventory: Provincial AGR

The Ontario Ministry of Natural Resources maintains a database of all active pits and quarries. The database provides information regarding the registered owner/operator, location name, operation type, approval type, and maximum annual tonnage.

Government Publication Date: Up to Sep 2018

Abandoned Mine Information System: Provincial AMIS

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

Government Publication Date: 1800-Nov 2016

Anderson's Waste Disposal Sites: Private ANDR

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1860s-Present

Automobile Wrecking & Supplies: Private AUWR

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

Government Publication Date: 1999-Jul 31, 2018

Borehole: Provincial BORE

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

Government Publication Date: 1875-Jul 2014

Certificates of Approval: Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

Government Publication Date: 1985-Oct 30, 2011*

Commercial Fuel Oil Tanks: Provincial CFOT

List of commercial underground fuel oil tanks made available by the Fuels Safety Program of the Technical Standards & Safety Authority (TSSA). Ontario Regulation 213/01 of the Technical Standards and Safety Act (2000) requires that all underground tanks be registered with the TSSA. Note: the Fuels Safety Division does not register waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of commercial fuel tanks in the province. The TSSA updates information in its system on an ongoing basis; this listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Chemical Register: Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

Government Publication Date: 1999-Jul 31, 2018

Compressed Natural Gas Stations: Private CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

Government Publication Date: Dec 2012 - Jul 2018

Inventory of Coal Gasification Plants and Coal Tar Sites: Provincial COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

Government Publication Date: Apr 1987 and Nov 1988*

Compliance and Convictions: Provincial CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

Government Publication Date: 1989-Sep 2018

Certificates of Property Use: Provincial CPU

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include all CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

Government Publication Date: 1994-Oct 31, 2018

Drill Hole Database: Provincial DRL

The Ontario Drill Hole Database contains information on more than 113,000 percussion, overburden, sonic and diamond drill holes from assessment files on record with the department of Mines and Minerals. Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted to the MNDM. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

Government Publication Date: 1886-Nov 30, 2017

Dry Cleaning Facilities: Federal DRYCLEANERS

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.

Government Publication Date: Jan 2004-Dec 2016

Environmental Activity and Sector Registry: Provincial EASR

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval), Please see our ECA database.

Government Publication Date: Oct 2011-Oct 31, 2018

Environmental Registry: Provincial EBR

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

Government Publication Date: 1994-Oct 31, 2018

Environmental Compliance Approval: Provincial ECA

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

Government Publication Date: Oct 2011-Oct 31, 2018

Environmental Effects Monitoring: Federal EEM

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

Government Publication Date: 1992-2007*

ERIS Historical Searches: Private EHS

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

Government Publication Date: 1999-Oct 31, 2018

Environmental Issues Inventory System: Federal EIIS

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

Government Publication Date: 1992-2001*

Emergency Management Historical Event: Provincial EMHE

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

Government Publication Date: Dec 31, 2016

List of TSSA Expired Facilities: Provincial EXP

List of facilities and tanks - for which there was once a registration - no longer registered with the Fuels Safety Program of the Technical Standards and Safety Authority (TSSA). Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc. Tanks which have been removed from the ground are included in the expired facilities inventory held by the TSSA. Notes: the Fuels Safety Division did not register private fuel underground/aboveground storage tanks prior to January of 1990, or furnace oil tanks prior to May 1, 2002; nor does the Division register waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of expired tanks/tank facilities in the province. The TSSA updates information in its system on an ongoing basis; this listing is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Federal Convictions: Federal FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

Government Publication Date: 1988-Jun 2007*

Contaminated Sites on Federal Land: Federal FCS

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government.

Government Publication Date: Jun 2000-Aug 2018

Fisheries & Oceans Fuel Tanks: Federal FOFT

Fisheries & Oceans Canada maintains an inventory of aboveground & underground fuel storage tanks located on Fisheries & Oceans property or controlled by DFO. Our inventory provides information on the site name, location, tank owner, tank operator, facility type, storage tank location, tank contents & capacity, and date of tank installation.

Government Publication Date: 1964-Sep 2017

Fuel Storage Tank: Provincial FST

List of registered private and retail fuel storage tanks made available by the Fuels Safety Program of the Technical Standards & Safety Authority (TSSA). Ontario Regulation 213/01 of the Technical Standards and Safety Act (2000) requires that all underground tanks be registered with the TSSA. Notes: the Fuels Safety Division did not register private fuel underground/aboveground storage tanks prior to January of 1990, or furnace oil tanks prior to May 1, 2002; nor does the Division register waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of fuel storage tanks/tank facilities in the province. The TSSA updates information in its system on an ongoing basis; this listing is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Fuel Storage Tank - Historic: Provincial FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

Government Publication Date: Pre-Jan 2010*

Ontario Regulation 347 Waste Generators Summary: Provincial GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

Government Publication Date: 1986-June 30, 2018

Greenhouse Gas Emissions from Large Facilities: Federal GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO2 eq).

Government Publication Date: 2013-Dec 2016

TSSA Historic Incidents: Provincial HINC

List of historic incidences of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen recorded by the TSSA in their previous incident tracking system. The TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of historical fuel spills and leaks in the province. This listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: 2006-June 2009*

Indian & Northern Affairs Fuel Tanks: Federal IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

Government Publication Date: 1950-Aug 2003*

TSSA Incidents: Provincial INC

List of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen reported to the Spills Action Centre (SAC) and made available by the Technical Standards and Safety Authority (TSSA). Under the Technical Standards & Safety Act (2000), the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors, and equipment or appliances that use fuels. Includes incidents from fuel-related hazards such as spills, fires, and explosions. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of fuel-related leaks, spills, and incidents in the province. The TSSA updates information in its system on an ongoing basis; this listing is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Landfill Inventory Management Ontario: Provincial LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the ministry compiles new and updated information. The inventory will include small and large landfills. Additionally, each year the ministry will request operators of the larger landfills complete a landfill data collection form that will be used to update LIMO and will include the following information from the previous operating year. This will include additional information such as estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills will include information such as site owner, site location and certificate of approval # and status.

Government Publication Date: Sep 30, 2017

Canadian Mine Locations: Private MINE

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

Government Publication Date: 1998-2009*

Environmental Penalty Annual Report: Provincial MISA PENALTY

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment and Climate Change. These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

Government Publication Date: Jan 1, 2011 - Dec 31, 2017

Mineral Occurrences: Provincial MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

Government Publication Date: 1846-Jan 2018

National Analysis of Trends in Emergencies System (NATES): Federal NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

Government Publication Date: 1974-1994*

Non-Compliance Reports: Provincial NCPL

The Ministry of the Environment provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act.

Government Publication Date: Dec 31, 2016

National Defense & Canadian Forces Fuel Tanks: Federal NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

Government Publication Date: Up to May 2001*

National Defense & Canadian Forces Spills: Federal NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

Government Publication Date: Mar 1999-Apr 2018

National Defence & Canadian Forces Waste Disposal Sites: Federal NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

Government Publication Date: 2001-Apr 2007*

National Energy Board Pipeline Incidents: Federal NEBI

Locations of pipeline incidents from 2008 to present, made available by the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

Government Publication Date: 2008-Jun 30, 2018

National Energy Board Wells: Federal NEBW

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release date.

Government Publication Date: 1920-Feb 2003*

National Environmental Emergencies System (NEES): Federal NEES

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December 2004.

Government Publication Date: 1974-2003*

National PCB Inventory: Federal NPCB

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

Government Publication Date: 1988-2008*

National Pollutant Release Inventory: Federal NPRI

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances.

Government Publication Date: 1993-May 2017

Oil and Gas Wells: Private OGW

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

Government Publication Date: 1988-August 31, 2018

Ontario Oil and Gas Wells: Provincial OOGW

In 1998, the MNR handed over to the Ontario Oil, Gas and Salt Resources Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database include well owner/operator, location, permit issue date, and well cap date, license No., status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provide for each well record.

Government Publication Date: 1800-May 2018

Inventory of PCB Storage Sites: Provincial OPCB

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

Government Publication Date: 1987-Oct 2004; 2012-Dec 2013

Orders: Provincial ORD

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include all Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

Government Publication Date: 1994-Oct 31, 2018

Canadian Pulp and Paper: Private PAP

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

Government Publication Date: 1999, 2002, 2004, 2005, 2009-2014

Parks Canada Fuel Storage Tanks: Federal PCFT

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

Government Publication Date: 1920-Jan 2005*

Pesticide Register: Provincial PES

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

Government Publication Date: 1988-Mar 2018

TSSA Pipeline Incidents: Provincial PINC

List of pipeline incidents (strikes, leaks, spills) made available by the Technical Standards and Safety Authority (TSSA). Under the Technical Standards & Safety Act (2000), the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors, and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of pipeline incidents in the province. The TSSA updates information in its system on an ongoing basis; this listing is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Private and Retail Fuel Storage Tanks: Provincial PRT

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

Government Publication Date: 1989-1996*

Permit to Take Water: Provincial PTTW

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include all PTTW's on the registry such as OWRA s. 34 - Permit to take water.

Government Publication Date: 1994-Oct 31, 2018

Ontario Regulation 347 Waste Receivers Summary: Provincial REC

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

Government Publication Date: 1986-2016

Record of Site Condition: Provincial RSC

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up.
RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09).

Government Publication Date: 1997-Sept 2001, Oct 2004-Sep 2018

Retail Fuel Storage Tanks: Private RST

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

Government Publication Date: 1999-Jul 31, 2018

Scott's Manufacturing Directory: Private SCT

Scott's Directories is a data bank containing information on over 200,000 manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, and main products are included in this database.

Government Publication Date: 1992-Mar 2011*

Ontario Spills: Provincial SPL

This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X.

Government Publication Date: 1988-Jul 2018

Wastewater Discharger Registration Database: Provincial SRDS

Information under this heading is combination of the following 2 programs. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment maintained a database of all direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation; Mining; Petroleum Refining; Organic Chemicals; Inorganic Chemicals; Pulp & Paper; Metal Casting; Iron & Steel; and Quarries. All sampling information is now collected and stored within the Sample Result Data Store (SRDS).

Government Publication Date: 1990-Dec 31, 2016

Anderson's Storage Tanks: Private TANK

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1915-1953*

Transport Canada Fuel Storage Tanks: Federal TCFT

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

Government Publication Date: 1970-Aug 2017

TSSA Variances for Abandonment of Underground Storage Tanks: Provincial VAR

List of variances granted for abandoned tanks. Under the Technical Standards and Safety Authority (TSSA) Liquid Fuels Handling Code and Fuel Oil Code, all underground storage tanks must be removed within two years of disuse. If removal of a tank is not feasible, an application may be sought for a variance from this code requirement.
Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of tank variances in the province. The TSSA updates information in its system on an ongoing basis; this listing is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Waste Disposal Sites - MOE CA Inventory: Provincial WDS

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

Government Publication Date: Oct 2011-Oct 31, 2018

Waste Disposal Sites - MOE 1991 Historical Approval Inventory: Provincial WDSH

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

Government Publication Date: Up to Oct 1990*

Water Well Information System: Provincial WWIS

This database describes locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table.

Government Publication Date: Dec 31, 2017

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.