Phase One Environmental Site Assessment

1393 Grahams Lane

Burlington, Ontario

March 1, 2024

2621458 Ontario Inc. C/O Altus Group
33 Yonge Street, Suite 500
Toronto, Ontario
M5E 1G4

File No: 02211083.001

ENGLOBE

2621458 Ontario Inc. C/O Altus Group
02211083.001

Prepared by:



Syed Ali, EIT
Project Manager - Environment



Muhammad Shahid, P.Geo., QP_{ESA} (ON)
Team Lead, Environment - GTA Ontario

TABLE OF CONTENTS

SECTION		PAGE
1.0	EXECUTIVE SUMMARY	1
2.0	INTRODUCTION	4
2.1	Phase One Property Information	4
2.2	Site Description	4
2.3	Buildings	4
2.4	Purpose of Investigation	4
3.0	SCOPE OF INVESTIGATION	6
3.1	Records Review	6
3.2	Interviews	7
3.3	Site Reconnaissance	7
3.4	Documentation and Evaluation of Information	8
4.0	RECORDS REVIEW	9
4.1	General	9
4.1.1	Phase One Study Area Determination	9
4.1.2	Fire Insurance Plans and Insurance Inspection Reports	9
4.1.3	Chain of Title	10
4.1.4	City Directory Search	10
4.1.5	Environmental Reports	11
4.2	Environmental Source Information	13
4.2.1	EcoLog ERIS	13
4.2.2	Other Source Information	24
4.3	Physical Setting Sources	25
4.3.1	Aerial Photographs	25
4.3.2	Topography Hydrology, Geology	27
4.3.3	Fill Materials	27
4.3.4	Water Bodies and Areas of Natural Significance	28
4.3.5	Well Records	29
4.4	Site Operating Records	29
5.0	INTERVIEWS	30
6.0	SITE RECONNAISSANCE	31
6.1	General Requirements	31
6.2	Specific Observations at Phase One Property	31
6.2.1	Building Description	31
6.2.2	Designated Substances and Other Special Attention Items	31
6.2.3	Below Ground Structures	32
6.2.4	Aboveground Storage Tanks	32
6.2.5	Underground Storage Tanks	32
6.2.6	Exterior Site Conditions	32
6.2.7	Enhanced Investigation Property	33
6.3	Investigation of Phase One Study Area	33
6.3.1	Potentially Contaminating Activity	34
7.0	REVIEW AND EVALUATION OF INFORMATION	35

7.1 Current and Past Uses 35
7.2 Potentially Contaminating Activities 35
7.3 Areas of Potential Environmental Concern 49
7.4 Phase One Conceptual Site Model 50
7.5 Uncertainty or Absence of Information 50

8.0 CONCLUSIONS 53
8.1 Phase Two ESA Required to Assess Soil and Groundwater Quality 53
8.2 Signatures 55

9.0 REFERENCES 57

10.0 LIMITATIONS AND USE OF THE REPORT 58

FIGURES

Figure 1 – Location Plan
Figure 2 – Site Plan
Figure 3 – PCA Locations
Figure 4 – Site and Surrounding Area
Figure 5 – APEC Locations

APPENDICES

Appendix A – Site photographs
Appendix B – Title Search Results
Appendix C – City Directory
Appendix D- EcoLog ERIS Report
Appendix E – Aerial Photographs and Historic Maps
Appendix F – Topographic Map and Geological Mapping
Appendix G – Water Well Record
Appendix H – Table of Current and Past Land Uses
Appendix I – APEC Table
Appendix J – Phase One Conceptual Site Model
Appendix K – Fire Insurance Plans

1.0 EXECUTIVE SUMMARY

Englobe Corporation (formerly Terraprobe Inc.) was retained by 2621458 Ontario Inc. C/O Altus Group to complete a Phase One Environmental Site Assessment (ESA) of the Property located at 1393 Grahams Lane (herein referred to as “Property” or “Site”) situated on the north side of Grahams Lane approximately 230m southwest of the intersection of Grahams Lane and Brant Street in the City of Burlington, Ontario.

The Property consists of an “L” shaped parcel of land currently consisting of a two-storey commercial warehouse building with associated at grade parking lots and driveways. The Property covers approximately 1.08 ha (2.67 acres) of land. The surrounding area is predominantly commercial and residential in land use. The Property is currently in commercial land use per Ontario Regulation 153/04 (O. Reg. 153/04). The location and extent of the Property is indicated in Figures 1 and 2. Adjacent property uses are presented in Figure 4.

It is understood that the Property is proposed to be redeveloped with three (3) residential buildings: Building A - 16 storeys, Building B - 9 storeys, and Building C - 20 storeys, resting on a two level underground parking garage.

The Phase One and Phase Two ESA are required by the client in support of the Site Plan Application for the proposed development and in support of securing an RSC for the Property due to the proposed change to a more sensitive land use. The Phase One ESA was completed to satisfy the intent of the requirements, methodology and practices for a Phase One ESA as described in O. Reg. 153/04.

Englobe Corporation (Englobe) completed the Phase One ESA in January 2024 to assess the environmental conditions of the Property. The Phase One ESA identified Potentially Contaminating Activities (PCAs) causing Areas of Potential Environmental Concern (APECs) at the Property. The Phase One ESA concluded that the quality of soil and groundwater should be assessed prior to the proposed development of the Property. Also, a Phase Two ESA would be required to investigate the APECs that have been identified on the Property.

Based on the records reviewed and site inspection, the following Potentially Contaminating Activities (PCAs) and Areas of Potential Environmental Concerns (APECs) were identified within the Phase One Property and Phase One Study Area (Study Area):

APEC No.	Location of APEC	Potentially Contaminating Activity	Location of PCA	Contaminants of Potential Concern	Media Potentially Impacted
APEC 1	Southern Portion of Phase One Property	#19 - Electronic and Computer Equipment Manufacturing	On-Site	Metals, As, Sb, Se, B-HWS, CN-, Hg, Cr(VI), pH, EC, PHCs, BTEX, VOCs, PAHs	Soil and Groundwater
APEC 2	Southern Portion of Phase One Property	#34 - Metal Fabrication	On-Site	Metals, As, Sb, Se, B-HWS, CN-, Hg, Cr(VI), pH	Soil and Groundwater
APEC 3	Exterior Western Wall of Commercial Building (Western Portion of Phase One Property)	#28 - Gasoline and Associated Products Storage in Fixed Tanks	On-Site	PHCs, BTEX, VOCs	Soil and Groundwater
APEC 4	Midway point along fence on Western Property Boundary (Western Portion of Phase One Property)	#28 - Gasoline and Associated Products Storage in Fixed Tanks	On-Site	PHCs, BTEX, VOCs	Soil and Groundwater
APEC 5	Southern Portion of Phase One Property	Others 1 - Ontario Regulation 347 - Waste Generator	On-Site	Metals, As, Sb, Se, B-HWS, CN-, Hg, Cr(VI), pH, EC, PHCs, BTEX, VOCs, PAHs	Soil and Groundwater
APEC 6A	Across Phase One Property	Others 2 - Salt Application for De-Icing Purposes	On-Site	SAR, EC, Na, Cl	Soil and Groundwater
APEC 6B	Across Phase One Property	#30 – Importation of Fill Material of Unknown Quality	On-Site	PAHs, PCBs, Metals, As, Sb, Se, B-HWS, CN-, Hg, Cr(VI), pH, EC, SAR	Soil
APEC 7	Southern Property Boundary	Others 1 - Ontario Regulation 347 - Waste Generator	Off-Site	Metals, As, Sb, Se, B-HWS, CN-, Hg, Cr(VI), pH, EC, SAR, PHCs, BTEX, VOCs, PAHs, PCBs	Soil and Groundwater
		#28 - Gasoline and Associated Products Storage in Fixed Tanks			
		#18 – Electricity Generation, Transformation and Power Stations			
		#55 – Transformer Manufacturing, Processing and Use			
		#57: Vehicles and Associated Parts Manufacturing			
		#34 – Metal Fabrication			

		#31 – Ink Manufacturing, Processing and Bulk Storage			
		#8 – Chemical Manufacturing, Processing, and Bulk Storage			
		#33 – Metal Treatment, Coating, Plating, & Finishing			
		#10 - Commercial Auto Body Shops			
		#19 – Electronic and Computer Equipment Manufacturing			
APEC 8	Northern Property Boundary	Others 1 - Ontario Regulation 347 - Waste Generator	Off-Site	Metals, As, Sb, Se, B-HWS, CN-, Hg, Cr(VI), pH, EC, PHCs, BTEX, VOCs, PAHs, PCBs	Soil and Groundwater
		#40 - Pesticides (including Herbicides, Fungicides and Anti-Fouling Agents) Manufacturing, Processing, Bulk Storage and Large-Scale Applications			
		#45 – Pulp, Paper, and Paperboard Manufacturing & Processing			
		#31 – Ink Manufacturing, Processing and Bulk Storage			
		#59 – Wood Treating and Preservative Facility and Bulk Storage of Treated and Preserved Wood Products			
		#54 – Textile Manufacturing and Processing			
		#34 – Metal Fabrication			
		#33 - Metal Treatment, Coating, Plating and Finishing			
		PCA #10 – Commercial Auto Body Shops			
		#43 - Plastics (including Fibreglass) Manufacturing and Processing			
APEC 9	Eastern Property Boundary	#10 - Commercial Auto Body Shops	Off-Site	Metals, As, Sb, Se, B-HWS, CN-, Hg, Cr(VI), pH, EC, PHCs, BTEX, VOCs, PAHs	Soil and Groundwater
		#34 - Metal Fabrication			
APEC 10	Western Property Boundary	#46 Rail Yards, Tracks and Spurs	Off-Site	Metals, As, Sb, Se, B-HWS, CN-, Hg, Cr(VI), pH, EC, PHCs, BTEX, VOCs, PAHs, PCBs	Soil and Groundwater
		Others 1 - Ontario Regulation 347 - Waste Generator			

A Phase Two Environmental Site Assessment will be required to investigate the APECs that have been identified on the Property arising from the current and historical PCAs found at the Property and within the Study Area, which may have resulted in adverse impacts on the environmental condition of the Property.

2.0 INTRODUCTION

Englobe Corporation (formerly Terraprobe Inc.) was retained by 2621458 Ontario Inc. to complete a Phase One Environmental Site Assessment (ESA) of the Property at 1393 Grahams Lane (herein referred to as "Property" or "Site") situated on the north side of Grahams Lane approximately 230m southwest of the intersection of Grahams Lane and Brant Street in the City of Burlington, Ontario..

The general location of the Property is presented in Figure 1.

2.1 Phase One Property Information

The Phase One Property information is provided below.

Municipal Address	1393 Grahams Lane, Burlington, ON.
Zoning	The Property is zoned as Mixed Use Corridor – Employment Oriented (MXE) under Part 5 of By-Law 2020-58
Property Owner Information	2621458 Ontario Inc. C/O Altus Group 33 Yonge Street, Suite 500 Toronto, ON. M5E 1G4

2.2 Site Description

The Property consists of an "L" shaped parcel of land currently consisting of a two-storey commercial warehouse building with associated at grade parking lots and driveways. The Property covers approximately 1.08 ha (2.67 acres) of land. The surrounding area is predominantly commercial and residential in land use. The Property is currently in commercial land use per Ontario Regulation 153/04 (O. Reg. 153/04). The location of and extent of the Property is indicated in Figures 1 and 2.

2.3 Buildings

The Site is currently occupied by a two-storey commercial warehouse building with associated at-grade parking lots and driveways.

2.4 Purpose of Investigation

It is understood that the Property is proposed to be redeveloped with three (3) residential buildings: Building A - 16 storeys, Building B - 9 storeys, and Building C - 20 storeys, resting on a two level underground parking garage.

The Phase One and Phase Two ESA are required by the client in support of the Site Plan Application for the proposed development and in support of securing an RSC for the Property due to the proposed change to a more sensitive land use. The Phase One ESA was completed to satisfy the intent of the requirements, methodology and practices for a Phase One ESA as described in O. Reg. 153/04.

3.0 SCOPE OF INVESTIGATION

The Phase One ESA consisted of:

- A review of historical background information for the site and surrounding areas available through background research
- A detailed site inspection of the subject property and surrounding properties to determine the current condition of the Property and surrounding area.

The information on the Property and Study Area is summarized in this report. Sampling and analysis of soil, ground water, or other materials (e.g., construction materials, air) were not carried out as part of the investigation.

3.1 Records Review

The records review provides information on historical and current activities. The objectives of the records review were as follows:

- To obtain and review records that relate to the current and past uses, site features and activities at the Property.
- To obtain and review records that relate to potentially contaminating activities, water bodies, and areas of natural significance in the Study Area (in addition to the Property).
- Based on the above, to provide an assessment of actual and potential contaminating activities and concerns with respect to the environmental condition of the Property.

The following sources of information were reviewed:

- Archival information for the site including aerial photographs, topographic maps, historical maps and drawings.
- Site-specific environmental reports and/or company records (e.g., Certificates of Approval, waste generator registration, approvals, and permits) provided to Englobe Corporation (formerly Terraprobe Inc.)
- Geological and hydrogeological information in published government maps and/or reports.
- Databases maintained by EcoLog ERIS containing environmentally related information from private, provincial, and federal sources.
- Fire insurance plans and insurance inspection reports (and related plans) on file with EcoLog ERIS.
- Published Ontario Ministry of the Environment Conservation and Parks (MECP) directories related to registered PCB storage sites and active and closed landfill sites.
- The Ontario Ministry of Natural Resources and Forestry (MNRF) Natural Heritage Information Centre database for information specific to natural areas, such as locations of environmentally sensitive areas.

- Published information regarding an Official Plan for the area.
- Sensitivity mapping by the local Conservation Authority.

3.2 Interviews

The objectives of the interview were:

- To obtain information to assist in determining if an area of potential environmental concern exists.
- To identify details of potentially contaminating activities or potential contaminant pathways in, on or under the Property.

Key personnel were interviewed and asked questions related to specific site activities, such as:

- The nature of the operations.
- Handling and storage of environmentally sensitive products and related wastes.
- Environmental approvals and registrations.
- Knowledge of previous reports related to the environmental condition of the Property.
- Issues related to non-compliance, orders, or charges related to environmental conditions on the Property.

3.3 Site Reconnaissance

A detailed inspection of the subject property and surrounding properties is carried out to determine the current condition of the Property and surrounding area. The objectives of the site reconnaissance were:

- To identify potential environmental concerns based on observations of current and past uses, and potentially contaminating activities at the Property and in the Study Area.
- To identify potential pathways for contamination at the Property and Study Area.

The site reconnaissance included a review of issues of potential environmental concern, including the following:

- Activities and practices, including site operations, processes and waste management currently carried out on the Property.
- Evidence of past waste disposal, landfill or fill placement on the Property.
- The presence of hazardous or toxic chemicals, materials or processes.
- The presence of existing or former aboveground or underground fuel storage tanks.
- Identification of heating and cooling systems.

- The presence of floor cracks, hydraulic hoists, elevators, sumps and drains, wells, pits and lagoons.
- Identification of water supply source to the Property.
- The presence of various designated substances and building materials, including friable and non-friable asbestos, PCB-containing materials and electrical equipment, lead-based paint, mould, and chlorofluorocarbons (CFCs) in air-conditioning and refrigeration equipment.
- Evidence of stained or odorous soils and stressed vegetation.

In addition, an inspection of adjacent properties within the Study Area (identified in Section 4.1.1) was completed to assess the potential for operations being carried out on those properties to impact on the environmental condition of the Property. The inspection of adjacent properties was limited to inspection from the Property boundaries and public areas (roads, sidewalks, etc.).

3.4 Documentation and Evaluation of Information

The information obtained from the records review, interviews and site reconnaissance was described, documented and evaluated as summarized below:

- Documentation of information, as noted in subsequent sections of the report.
- Description of potentially contaminating activities.
- Description of areas of potential environmental concern.
- Development of a Phase One Conceptual Site Model.
- Discussion of the need, if any, for further investigation.

4.0 RECORDS REVIEW

4.1 General

4.1.1 Phase One Study Area Determination

The Phase One Study Area (Study Area) consisted of properties located within a 250 m radius from the Property boundary.

Commercial and industrial land uses were present to the north, east and south of the Phase One Property. The Phase One Property is neighboured on the West by agricultural or other land uses in from a natural creek valley and wooded area around Beaver Creek, followed by more industrial and commercial land uses further to the west. The surface topography is slightly rolling to the west toward Beaver Creek. The Phase One Study Area is shown on Figure 3.

Based on the historical property use and development on the Property and surrounding area, it was determined that a 250 m study area around the Property was sufficient to identify issues of potential environmental concern that could potentially impact on the environmental condition of the Property.

4.1.2 Fire Insurance Plans and Insurance Inspection Reports

Fire Insurance Plans (FIPs) were searched for the Property. A 1971 FIP was available for the surround area but no records for the Property were present for review. PCAs in the Phase One Study Area were identified from review of the FIPs and are presented below. The 1971 FIP is attached in Appendix K.

Location of PCA	PCA	Justification
892 Brant Street 250m North of Property	#10 Commercial Auto Body Shops	FIP – A commercial auto service shop and associated tank are observed as being present at this location in the 1971 FIP
	#28 Gasoline and Associated Products Storage in Fixed Tanks	Based on the distance from the Phase One Property and its downgradient location this PCA is not considered to contribute to an on-Site APEC
850 Brant Street 121m Northeast of Property	#10 Commercial Auto Body Shops	FIP – A commercial auto body shop is observed as being present at this location in the 1971 FIP Based on the distance from the Phase One Property and its transgradient location this PCA is not considered to contribute to an on-Site APEC

Location of PCA	PCA	Justification
814 Brant Street 147m East of Property	#10 Commercial Auto Body Shops	FIP – A commercial auto service shop is observed as being present at this location in the 1971 FIP Based on the distance from the Phase One Property and its transgradient location this PCA is not considered to contribute to an on-Site APEC
1451 Grahams Lane 140m East of Property	#34 – Metal Fabrication	FIP – Machine shop is observed as being present at this location in the 1971 FIP Based on the distance from the Phase One Property and its transgradient location this PCA is not considered to contribute to an on-Site APEC
825 Legion Road Adjacent to East of Property	#34 – Metal Fabrication	FIP – Machine shop is observed as being present at this location in the 1971 FIP
1392 Grahams Lane 18m South of Property	#34 – Metal Fabrication #28 – Gasoline and Associated Products Storage in Fixed Tanks	FIP – Machine shop and 8 associated fuel oil tanks are observed as being present at this location in the 1971 FIP

4.1.3 Chain of Title

A chain of title requests was made to Domson's Title Search Inc., a freelance title search consultant. The following pertinent information was obtained:

- The Property was under Crown ownership until 1798.
- The Property changed from Crown owner to private ownership (Capt. Joseph Brant) in 1798.
- Since then, various individuals have owned the Property, including the current owner, 2621458 Ontario Inc.

4.1.4 City Directory Search

Available City Directories were obtained through EcoLog Environmental Risk Information Services Ltd. (ERIS) and were reviewed for the Property and adjacent properties. The following PCAs were identified on the Property and in the Phase One Study Area. The full search results can be found in Appendix C.

Location of PCA	PCA	APEC (YES/NO)	Details
On-Site PCAs			
1393 Grahams Lane On-Site	PCA 34 – Metal Fabrication PCA 19 – Electronic and Computer Equipment Manufacturing	Yes	City Directory listings for International Aluminum Canada in 2000 City Directory listings for Walker Magnetics National Limited and McGraw-Edison Limited Electric Coil Division, manufacturers of electrical components from in 1980-1995
Off-Site PCAs			
942 Brant Street 158m North of Property	PCA #8 – Chemical Manufacturing, Processing and Bulk Storage	No	City Directory Listings for Ashland Canada and Hercules Canada Inc. both of which operated as chemical manufacturers from 1960-2021 Due to the distance and downgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property.
1380 Grahams Lane 20m South of Property	PCA #28 – Gasoline and Associated Products Storage in Fixed Tanks	Yes	City Directory listings for Burlington Energy Systems Co. Ltd., Frew Energy, and John Ebos Fuels Ltd. all of which operated as gas stations from 2000-2021
1392 Grahams Lane 18m South of Property	PCA #10 – Commercial Auto Body Shops	Yes	City Directory Listings for Airds Automotive, Brant Auto Body, Burlington Automotive Centre and Hi-Tech Collision which operated as Automotive Repair Services from 1985-2021
1400 Grahams Lane 20m South of Property	PCA #10 – Commercial Auto Body Shops	Yes	City Directory listings for Wicks' Auto Collision, Smit Auto Body and Freedom Motors, Automotive Repair Services from 1975-2021

1416 Grahams Lane 36m Southeast of Property	PCA #31 – Ink Manufacturing, Processing and Bulk Storage PCA #34 – Metal Fabrication	Yes	City Directory listings for Sinclair-Smith Printing and Lithographing Co. Ltd. and Allied Arts Display Ltd. commercial printers from 1975-2005 City Directory Listings for Parkdale Machine & Tool Co. Ltd. a machine shop in 1970
1421 Grahams Lane Adjacent to East of Property	PCA #10 – Commercial Auto Body Shops	Yes	City Directory listings for Als Lawn Mower Small Engine and gas engine repair service and equipment supplier from 2012-2021
1425 Grahams Lane Adjacent to East of Property	PCA #10 – Commercial Auto Body Shops	Yes	City Directory listings for SWC Automotive, Metro Collision Repair Auto, and Maaco Auto Paint and Bodyworks a commercial auto garage from 1985-2021
1439 Grahams Lane 100m East of Property	PCA #34 – Metal Fabrication	Yes	City Directory Listings for Frank Tool & Die Co. Ltd. a machine shop in from 1960-1965
850 Legion Road Adjacent to North of Property	PCA #59 - Wood Treating and Preservative Facility and Bulk Storage of Treated and Preserved Wood Products PCA #33 - Metal Treatment, Coating, Plating and Finishing PCA #31 – Ink Manufacturing, Processing and Bulk Storage	Yes	City Directory listings for Artisan Design a Kitchen Cabinet and Household furniture manufacturer from 1990-2021 City Directory listings for Carl's Precision Grinding a Metal Coating and Engraving operation from 2012-2017 City Directory listings for Dynamic Plastic Solutions Inc. a Plastics Manufacturer from 2012-2017 City Directory listings for Fry Graphics a commercial lithographic printer from 2000-2017 City Directory listings for Teckmark Label System Inc. a coated and laminated paper manufacturer from 1995-2017

	PCA #45 - Pulp, Paper and Paperboard Manufacturing and Processing PCA #43 - Plastics (including Fibreglass) Manufacturing and Processing PCA #10 – Commercial Auto Body Shops		City Directory listings for ACA Performance Inc., an auto parts manufacturer in from 2000-2012 City Directory listings for Wheels of Dreams., a commercial auto garage from in 2012
932 Brant Street 250m North of Property	PCA #10 – Commercial Auto Body Shops	No	City Directory listings for Dollar Thrifty Automotive Group, a commercial auto garage in 2005 Due to the distance and downgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property.

4.1.5 Environmental Reports

No previous environmental reports were prepared for the Property. Additionally, no RSCs were identified as being filed in the Phase One Study Area.

4.2 Environmental Source Information

4.2.1 EcoLog ERIS

EcoLog Environmental Risk Information Services Ltd. (ERIS) is an organization that maintains and searches various government and private databases for property-related environmental information. A search of the EcoLog ERIS Ltd. databases was requested for the Property and Study Area. The ERIS Report is provided in Appendix D.

Based on the review of the EcoLog ERIS report, the following potentially contaminating activities (PCAs) were identified:

Location of PCA	PCA	APEC (YES/NO)	Details
On-Site PCAs			
1393 Grahams Lane	Others 1 – Ontario Regulation 347 – Waste Generator	Yes	Ecolog ERIS – The property was occupied by McGraw Edison and Walker Magnetics National Ltd. which were Electrical equipment manufacturers that were registered as a waste generators from 1986-1998 of: - Halogenated Solvents - Organic Acids - Petroleum Distillates - Waste Oils & Lubricants Scotts Manufacturing Directory Listings indicated that businesses operating at the Property included Walker Magnetics National Ltd., which operated in manufacturing Electrical Industrial Apparatuses not elsewhere classified Relays and Industrial Controls, and Special Industrial Machinery not elsewhere classified, and United States Aluminum of Canada Ltd. which operated in Metal Window and Door Manufacturing
	PCA #19 – Electronic and Computer Equipment Manufacturing		
	PCA #34 – Metal Fabrication		
Off-Site PCAs			
942 Brant Street 158m North of Property	PCA #8 – Chemical Manufacturing, Processing, and Bulk Storage	No	Ecolog ERIS - The Property was occupied by Hercules Canada Inc. Ashland, and Solenis Canada all of which were registered in the Chemical Register and Chemical Manufacturers and Distributors Registry. The property was occupied by Ashland Canada Corp., Solenis Canada ULC, and Hercules Canada Inc. which were registered as a waste generators from 1986-Present of:

	Others 1 – Ontario Regulation 347 – Waste Generator	- Organic Acids - Amines - Non-Halogenated Pesticides - Other Specified Organics - Waste Compressed Gases - Organic Laboratory Chemicals - Acid Waste

	Others 3 - Spills		- Aromatic Solvents - Paint/Pigment/Coating Residues - Aliphatic Solvents - Other Specified Inorganics - Inorganic Laboratory Chemicals - Petroleum Distillates - Emulsified Oils - Alkaline Wastes - Light Fuels - Polymeric Resins - Halogenated Pesticides - PCBs - Oil Skimmings and Sludges - Heavy Fuels - Phenolic Wastes Multiple National Environmental Emergencies System and Ontario Spills Record indicating spills of different chemical agents has occurred at the Property. Scotts Manufacturing Directory Listings indicated that businesses operating at the Property included Ashland Canada Corp, which operated in manufacturing of Miscellaneous Chemical Products. Due to the distance and downgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property.
1380 Grahams Lane 20m South of Property	PCA #28 – Gasoline and Associated Products Stroage in Fixed Tanks	Yes	Ecolog ERIS – The Property was identified in as having multiple Delisted Fuel Tanks and Private and Retail Fuel Storage Tanks related to gasoline and diesel fuels.

	Others 1 – Ontario Regulation 347 – Waste Generator		The property was occupied by Petro-Canada, Suncor Energy and John Ebos Fuels Limited which operated as Gas Stations and were registered as waste generators from 1988-Present of: - Light Fuels - Petroleum Distillates - Oil Skimmings & Sludges - Waste Oils & Lubricants
1448 Grahams Lane 145m East of Property	PCA #28 – Gasoline and Associated Products Stroage in Fixed Tanks	No	Ecolog ERIS – The Property was identified in as having multiple Delisted Fuel Tanks and Private and Retail Fuel Storage Tanks related to gasoline and diesel fuels. Additionally, the Property was identified on the Registry of Expired Fuels Safety Facilities Due to the distance and transgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property.
809 Brant Street 250m East of Property	PCA #28 – Gasoline and Associated Products Stroage in Fixed Tanks	No	Ecolog ERIS – The Property was identified in as having multiple Delisted Fuel Tanks and Private and Retail Fuel Storage Tanks related to gasoline and diesel fuels. Additionally, the Property was identified on the Registry of Expired Fuels Safety Facilities Due to the distance and transgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property.
1370 Grahams Lane	Others 1 – Ontario Regulation 347 – Waste Generator	Yes	Ecolog ERIS – The Property was occupied by the Burlington Hydro-Electric Commission which operated as an Electric Distribution

51m Southwest of Property	PCA #18 – Electricity Generation, Transformation and Power Stations PCA #55 – Transformer Manufacturing, Processing and Use		System Station and was registered as a waste generator from 1989-1998 of: - Alkaline Wastes - Oil Skimmings & Sludges
1416 Grahams Lane 36m South of Property	Others 1 – Ontario Regulation 347 – Waste Generator PCA #57: Vehicles and Associated Parts Manufacturing PCA #34 – Metal Fabrication	Yes	Ecolog ERIS - The property was occupied by Sinclair-Smith Printing & Lithographing, which was identified as a waste generator from 1986-1994 of unspecified wastes. Scotts Manufacturing Directory Listings indicated that businesses operating at the Property included Arctic Traveller (Canada) Ltd., which operated in manufacturing Heating Equipment and Commercial Refrigeration Equipment, and New Motor Vehicle Parts and Accessories,
850 Legion Road Adjacent to North of Property	Others 1 – Ontario Regulation 347 – Waste Generator	Yes	The property was occupied by Wentworth Electronics, Teckmark Label Systems, Artisan Design, B-Line Cresting, Golden Horseshoe Services, The Maples Animal Hospital, Historia Building Restoration Inc., SOAR Veterinary Profession Corporation, and Carl's Grinding Service which were registered as a waste generators from 1988-Present of: - Aromatic Solvents

	PCA #40 - Pesticides (including Herbicides, Fungicides and Anti-Fouling Agents) Manufacturing, Processing, Bulk Storage and Large-Scale Applications		- Acid Waste - Alkaline Wastes - Petroleum Distillates - Halogenated Solvents - Aromatic Solvents - Pathological Wastes - Paint/Pigment/Coating Residues - Organic Laboratory Chemicals - Pharmaceuticals - Waste Oils & Lubricants The Pesticide Register indicates that McConnell-Spadafora Inc. which operated at the property was registered as a pesticide vendor. Scotts Manufacturing Directory Listings indicated that businesses operating at the Property included Teckmark Label Systems Inc., KLB Interiors Inc., Artisan Design, Meridan Golf Inc., Hibon Inc., Woodcraft Rail Inc., B-Line Cresting, Fry Graphics Ltd., Burlington Letterpress, McConnell-Spadafora Inc., and Mulit-Line Products Inc. which operated in a wide variety of activities including; - Commercial Printing & Lithography - Manufacturing of Coated and Laminated Paper - Wood Cabinet, Countertop and Furniture Manufacturing - Industrial Machinery Manufacturing and Other Millwork - Curtin and Linen Mills - Textile Fabric Manufacturing and Finishing - Stationary Product Manufacturing
	PCA #45 – Pulp, Paper, and Paperboard Manufacturing & Processing		
	PCA #31 – Ink Manufacturing, Processing and Bulk Storage		
	PCA #59 – Wood Treating and Preservative Facility and Bulk Storage of Treated and Preserved Wood Products		
	PCA #54 – Textile Manufacturing and Processing		
	PCA #34 – Metal Fabrication		

1440 Grahams Lane 45m Southeast of Property	Others 1 – Ontario Regulation 347 – Waste Generator	Yes	Ecolog ERIS - The property was occupied by Dover Corporation (Canada) Limited, Thyssen Dover Elevator, Ontario Testing Labs, Ash Temple Ltd., Bodycote Galt Materials Testing Ltd., and Exova Burlington, which were registered as a waste generators from 1992-Present of: - Emulsified Oils - Photo processing Wastes - Polymeric Resins - Acid Waste - Inorganic Laboratory Chemicals - Organic Laboratory Chemicals - Organic Acids - Waste Compressed Gases - Oil Skimmings & Sludges
	PCA #8 – Chemical Manufacturing, Processing, and Bulk Storage		
	PCA #33 – Metal Treatment, Coating, Plating, & Finishing		
	PCA #34 – Metal Fabrication		
	PCA #31 – Ink Manufacturing, Processing and Bulk Storage		

	PCA #19 – Electronic and Computer Equipment Manufacturing		- Miscellaneous Wastes and Organic/Inorganic Chemicals Scotts Manufacturing Directory Listings indicated that businesses operating at the Property included Scherzinger Pump Technology, Thyssen Dover Elevators, Burlington Laminating & Binder, Peters Steel Rule Dies, Endress & Hauser Canada Ltd., Magnus Chemicals Ltd., and Pyramid Pumps. which operated in a wide variety of activities including; - Chemical (except Agricultural) and Allied Products Wholesaler-Distribution - Industrial Machinery, Equipment and Supplies Wholesaler-Distribution - Other Metal Working Machinery Manufacturing - Commercial Printing not elsewhere classified - Relays and Industrial Controls Manufacturing - Industrial Machinery and Equipment
1355 Stephenson Drive 68m West of Property	Others 1 – Ontario Regulation 347 – Waste Generator	Yes	Ecolog ERIS – The property was occupied by Hydro One Networks Inc. which was registered as a waste generator from 2019-Present of: - Other Specified Inorganic Sludges, Slurries or Solids
1439 Grahams Lane 100m East of Property	Others 1 – Ontario Regulation 347 – Waste Generator	No	Ecolog ERIS – The property was occupied by Burlington Hydro Inc. which was registered as a waste generator in 2004 of unspecified wastes. Due to the distance and transgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property.

831 Legion Road 100m East of Property	Others 1 – Ontario Regulation 347 – Waste Generator	No	Ecolog ERIS – The property was occupied by the Burlington Association for Community which was registered as a waste generator from 1990-1998 of: - Acid Waste Due to the distance and transgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property.
802 Hagar Avenue 100m South of Property	Others 1 – Ontario Regulation 347 – Waste Generator	Yes	Ecolog ERIS – The property was occupied by the Wellington Park Care Centre, Responsive Management Inc. and Suncor Energy Products, which were registered as waste generators from 2011-Present of: - Paint/Pigment/Coating Residues - Waste Oils & Lubricants - Light Fuels - Waste Oils & Sludges
1881 Fairview Street 200m North of Property	Others 1 – Ontario Regulation 347 – Waste Generator	No	Ecolog ERIS – The property was occupied by Michaels Stores Inc. which was registered as a waste generator from 2013-2018 of: - Paint/Pigment/Coating Residues - Alkaline Wastes - Inorganic Laboratory Chemicals - Aliphatic Solvents - Organic Laboratory Chemicals - Other Specified Inorganics - Waste Compressed Gases - Detergents/Soaps Due to the distance and downgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property.

760 Brant Street 210m Southeast of Property	Others 1 – Ontario Regulation 347 – Waste Generator	No	Ecolog ERIS - The property was occupied by 1086891 Ontario Inc, Burlington Ultrasound and Radiology, McAuthur Properties, Trillium College Inc, Wentworth Halton X-Ray and Ultrasound Inc., Oxford College of Arts, Business and Technology, and Dr. Ronald Yim Dentistry Professional Corp. which were registered as waste generators from 2010-Present of: - Pathological Wastes - Neutralized Waste - Inorganic Laboratory Chemicals - Photo processing Wastes - Miscellaneous Wastes and Inorganic Chemicals Due to the distance of this PCA this PCA is not likely to cause APEC on the Property.
834 Brant Street 70m Northeast of Property	PCA #40 - Pesticides (including Herbicides, Fungicides and Anti-Fouling Agents) Manufacturing, Processing, Bulk Storage and Large-Scale Applications	No	Ecolog ERIS - The Pesticide Register indicates that Pets & Garden Ltd. which operated at the property was registered as a retail pesticide vendor Class 03. Due to the distance and transgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property.

1-2004 Maplewood Drive 250m Northeast of Property	PCA #40 - Pesticides (including Herbicides, Fungicides and Anti-Fouling Agents) Manufacturing, Processing, Bulk Storage and Large-Scale Applications	No	Ecolog ERIS - The Pesticide Register indicates that Canada Pest Control. which operated at the property was registered as a pesticide operator Class 01 Type 02. Due to the distance and transgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property.
817 Brant Street 249m East of Property	PCA #34 – Metal Fabrication	No	Scotts Manufacturing Directory Listings indicated that businesses operating at the Property included Advanced Integrated Resources Inc., which operated in manufacturing Industrial and Commercial Fan and Blower and Air Purification Equipment Due to the distance and transgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property.
	PCA #19 - Electronic and Computer Equipment Manufacturing		

4.2.2 Other Source Information

Information obtained from the following other sources is summarized below:

- Freedom of Information (FOI) request to the Ontario Ministry of the Environment Conservation and Parks (MECP). The FOI request determines if information regarding orders, investigations or other information on file with respect to the Property.
- Technical Standards and Safety Authority (TSSA) was contacted in regard to records related to storage tanks for petroleum-related products with respect to the Property.
- The local Conservation Authority was contacted to determine if the Property was considered regulated under the Conservation Authorities Act and Ontario Regulations 42/06, 146/06 to 182/06 and 97/04.
- Municipal Zoning and Official Plan information was reviewed.

The information requests and responses are summarized below.

Information Request	Response
MECP FOI	A response from the MECP has not been received for the municipal addresses of 1393 Grahams Lane, Burlington, Ontario. The report will be updated, or an addendum will be issued if any issue of environmental concern is identified in the response from MECP.
TSSA	A response from TSSA indicated the former presence of 6 Tanks at 809 Brant Street and two tanks at 1448 Grahams Lane. No other tank records were available for the Phase One Property or within the Phase One Study Area.
Conservation Authority	A response form the governing Conservation Authority request has been received as of the date of this report. The property is not regulated by the Halton Conservation Authority (HCA).
Zoning	The City of Burlington interactive zoning map bylaw map was accessed on January 31, 2024. The Property is zoned as Mixed Use Corridor – Employment Oriented (MXE) under Part 5 of By-Law 2020-58

Two (2) Potentially Contaminating Activity was identified from the review of other source information.

Location of PCA	PCA	Justification
809 Brant Street 240m East of Property	PCA #28 – Gasoline and Associated Products Storage in Fixed Tanks	TSSA records indicate the former presence of multiple fuel tank at this property. Due to the distance and transgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property.
1448 Grahams Lane 145m East of Property	PCA #28 – Gasoline and Associated Products Storage in Fixed Tanks	TSSA records indicate the former presence of multiple fuel tank at this property. Due to the distance and downgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property.

4.3 Physical Setting Sources

4.3.1 Aerial Photographs

Aerial photographs, satellite imagery and historic maps were reviewed. Aerial photographs, satellite images and historic maps were selected based on available dates and scale in order to

provide as much information as reasonably practical regarding the development of the Property and Study Area from first developed land use until the present development of the Property. The state of development of the Property and Study Area is summarized in below.

Date	Source	Property	Study Area
1998	Aerial	Property is developed with a single commercial building with the same layout and dimensions of the building currently on Site. The area north of the on-Site building is a landscaped grass area and a parking lot in present on the other side of the landscaped area	*North* - Properties mostly consist of Commercial land uses. *South* - Properties mostly consist of Commercial land uses. *East* - Properties mostly consist of Commercial land uses. *West* - A CN Railway corridor is present immediately west of the Site followed by Residential homes.
2009	Satellite	No significant changes	*North* - No significant changes *South* - No significant changes *East* - No significant changes *West* - No significant changes
2024	Satellite	The Property appears to be in its current day configuration the landscaped area between the on-Site building and the Parking lot in the northern part of the Site has been paved	*North* - No significant changes *South* - No significant changes *East* - No significant changes *West* - No significant changes

A selection of aerial photographs and historic maps are presented in Appendix E.

Two (2) Potentially Contaminating Activities were identified from the aerial photographs.

Location of PCA	PCA	Justification
Adjacent to West of Phase One Property	#46 - Rail Yards, Tracks and Spurs	Aerials - A CN Railway Corridor runs from North to South Directly adjacent to the west of the Phase One Property. Therefore, the QP's assessment is that this PCA is likely to cause an APEC on the Property.
Phase One Property	Others 2 - Salt Application for De-Icing Purposes	Aerials indicate that the majority of the Site is covered by an asphalt parking lot, which has likely had salt applied to it in the winter months for De-Icing purposes. Therefore, the QP's assessment is that this PCA is likely to cause an APEC on-Site.

Location of PCA	PCA	Justification
Phase One Property	#30 – Importation of Fill Material of Unknown Quality	During development of the Property, it is likely that fill material of unknown quality may would been used.

4.3.2 Topography, Hydrology, Geology

A topographic map from the Ontario Ministry of Natural Resources and Forestry (MNRF) and the geological mapping produced by the Ontario Ministry of Northern Development and Mines - *Ontario Geological Survey* was reviewed. The information gleaned from the mapping is summarized below. The maps are provided in Appendix F.

Elevation	The OBM showed the elevation of the Property was approximately 95 m above sea level (m asl)
Topography	The Property is relatively flat-lying, gently rolling with a slight slope to the north toward Upper Hager Creek. Thus, surface water is directed towards the north.
Hydrogeology	The nearest surface water body to the Site appears to be Upper Hager Creek, 50 m north of the Property. The inferred direction of groundwater flow at the Phase One Property is to the North-Northwest.
Geology (overburden)	Based on published geology, the overburden material is generally coarse-textured glaciolacustrine deposits consisting of sand, gravel, minor silt and clay (9).
Geology (bedrock)	The bedrock on the site is of the Queenston formation, which is comprised of shale, minor limestone, sandstone, dolostone and siltstone.
Geology (depth to bedrock)	Based on published geological information in the area, the depth to bedrock is approximately 20 m within the vicinity of the Property. Bedrock was encountered in some wells in the well record for the area at depths ranging from 15-20 mbgs.

4.3.3 Fill Materials

Based upon the historic land use of the property, it is not probable that historic filling occurred across the property. However, fill material may have been placed during development of the Property.

4.3.4 Water Bodies and Areas of Natural Significance

Mapping from the Ontario Ministry of Natural Resources and Forestry (MNRF) was reviewed to determine if water bodies were present on the Property and within the Study Area. The Ontario Ministry of Natural Resources National Heritage Information Centre database for listings of Areas of Natural or Scientific Interest (ANSIs) was reviewed. The information is summarized below.

Water Bodies (Property)	• No water bodies were identified on the Property.
Water Bodies (Study Area)	• The nearest surface water body to the Site appears to be Upper Hager Creek, 50 m north of the Property. The inferred direction of groundwater flow at the Phase One Property is to the North-Northwest.
Wetland (Property)	Provincially Significant • No Provincially Significant wetlands were present on the Property Non- Provincially Significant • No Non- Provincially Significant wetlands were present on the Property Unevaluated • No Unevaluated wetlands were present on the Property
Wetland (Study Area)	Provincially Significant • No Provincially Significant wetlands were present in the Study Area. Non- Provincially Significant • No Non- Provincially Significant wetlands were present in the Study Area Unevaluated • No Unevaluated wetlands are present in the Study Area adjacent to the west of the Phase One Property.
ANSIs (Property)	Provincially Significant Life Science ANSI • No Life Science ANSIs were identified on the Property. Provincially Significant Earth Science ANSI • No Earth Science ANSIs were identified on the Property.

ANSIs (Study Area)	Provincially Significant Life Science ANSI • No Life Science ANSIs were identified in the Study Area. Provincially Significant Earth Science ANSI • No Earth Science ANSIs were identified on the Property.

4.3.5 Well Records

The Ontario Ministry of the Environment, Conservation and Parks (MECP) well records database was searched through EcoLog ERIS and through the Ministry of the Environment online Water Well Database for records located on the Property and in the Study Area (within 250 m). A copy of the Well Records is provided in Appendix G and is summarized below.

Water Wells (Property)	• No monitoring wells were identified on the Property during site inspection.
Water Wells (Study Area)	The following wells were located in the Study Area: • Twenty-three (23) – Observation-Monitoring and Test Holes • Sixteen (16) – Abandoned-Other
Stratigraphy	• 0 to 4 m – Fill, Silty Sand • 4 to 10 m – Red Sandy Silt Till • 10 to 16 m – Grey, Sandy Silt Till • 16m – Shale Bedrock
Depth to Water Table	Based on the water well records, the depth to the water table is approximately 7-11 m.
Depth to Bedrock	Based on published geotechnical information, the depth to bedrock is approximately 15-20 m in the vicinity of the Property.

4.4 Site Operating Records

No site operating records were provided for review.

5.0 INTERVIEWS

A response to the interview questionnaire was received and the information is summarized below:

Interviewed	Mike Szczepanski
Date	January 12th, 2024
Method of Interview	Email
Reason for Selection	Mike Szczepanski is the manager at Blue Sky Storage.
Assessment of the Information	A thorough assessment was completed.
Relevant Information	The following information was provided by Mike Szczepanski: • There should be no underground structures, tanks, or pits. • There are no wells located on the Property

6.0 SITE RECONNAISSANCE

6.1 General Requirements

Date of Investigation	January 17, 2024
Time of Investigation	11:00 am - 2:00 pm
Weather Conditions	Cloudy -2 °C
Duration of Investigation	3.0 hours
Was the Facility Operating?	Yes
Person(s) Conducting Investigation and Qualifications	Syed Ali EIT under the supervision of Muhammad Shahid, P. Geo., QP_{ESA}

6.2 Specific Observations at Phase One Property

The site reconnaissance included a walking tour of the Property, as well as compiling written and photographic records. Site features are illustrated on Figure 2.

6.2.1 Building Description

No buildings or structures were located on the Property.

6.2.2 Designated Substances and Other Special Attention Items

The inspection was carried out in accessible areas and included an assessment of the potential presence of the following materials:

- Designated substances (i.e., acrylonitrile, asbestos, arsenic, benzene, coke oven emissions, ethylene oxide, isocyanates, lead, mercury, silica, vinyl chloride).
- Polychlorinated biphenyls (PCBs).
- Ozone-depleting substances.
- Urea-formaldehyde foam insulation (UFFI).
- Special attention items (i.e., mould radioactive materials).

The presence of these materials based on the site reconnaissance is summarized below.

Asbestos	No materials containing asbestos were observed during the site inspection.
Lead	No suspected lead-based paint or plumbing components were observed during the inspection of the Property.
Mercury	No materials containing mercury were observed during the site inspection.
PCBs	No PCBs or related materials were found during the site inspection.
Ozone Depleting Substances (ODS)	No ozone-depleting substances were observed during the site inspection.
UFFI	No UFFI products were observed during the site inspection.
Mould	There is no evidence of mounding on the Property.
Radioactive Materials	No manmade sources of radiation were observed during the site inspection.
Herbicides and Pesticides	During the site inspection, no materials containing herbicides or pesticides were observed to be stored at the site.

6.2.3 Below Ground Structures

No below-ground structures were observed on the Property.

6.2.4 Aboveground Storage Tanks

Six (6) aboveground storage tanks were observed on the western portion of the Property.

6.2.5 Underground Storage Tanks

No underground storage tanks or evidence of historical underground storage tanks was observed during the site inspection.

6.2.6 Exterior Site Conditions

The Property appears to be flat, lying with the ground surface sloping gently to the west. The Property is occupied by a warehouse building, and the majority of the exterior is asphalt-covered.

Water Sources	The Property is supplied with municipal water.
Underground Utilities and Services	Underground utilities were identified on the Property at the time of inspection.

Current and Former Wells	No wells were located on the Property.
Sewage Works	The Property is serviced with municipal sewers.
Railways	No existing rail lines were located on the Property.
Stained and Odorous Soils	No stained or odorous soils were observed on the Property.
Stressed Vegetation	No stressed vegetation was noted on the Property.
Fill Materials	No fill material was observed on the Property.
Watercourses, Ditches or Standing Water	No watercourses, ditches or standing water were noted on the property during the investigation.
Air Emissions	No air emissions are resulting from the Property.
Roads, Parking Facilities, and Right-of-Ways	No roads, parking facilities, or right-of-ways.
Waste Handling	Waste handling was noted on the Property in small amounts.

6.2.7 Enhanced Investigation Property

An Enhanced Investigation Property is "(i) a property used, or has ever been used, in whole or part, for an industrial purpose, or (ii) a commercial property used as a garage, a bulk liquid dispensing facility, including a gasoline outlet or for the operation of dry-cleaning equipment" (O.Reg.511/09).

Based on the records review and Property visit, the Property was classified as an Enhanced Investigation Property.

6.2.8 Operations at the Property

The Property is currently occupied by a warehouse building for storage and landscaping equipment.

6.2.9 Hazardous Materials

No hazardous materials were noted on the Property during the site inspection. No hazardous wastes were reportedly generated at the Property.

6.2.10 Products Manufactured

No products are currently manufactured at the Property.

6.2.11 By-products and Wastes

No by-products or hazardous wastes are generated at the Property.

6.2.12 Raw Materials Handling and Storage Locations

No raw materials were stored at the Property.

6.2.13 Drums, Totes, and Bins

No totes were located on the Property.

6.2.14 Oil/Water Separators

No oil/water separators were noted on the Property.

6.2.15 Vehicle and Equipment Maintenance Areas

No vehicle or equipment maintenance was carried out on the Property.

6.2.16 Spills

No evidence of spills was noted on the Property during the site inspection.

6.2.17 Liquid Discharge Points

No evidence of liquid discharge points was noted on the Property during the site inspection.

6.2.18 Hydraulic Lift Equipment

No hydraulic lift equipment was present on the Property at the time of the site inspection.

6.3 Investigation of Phase One Study Area

At the time of the site inspection, the following land uses were noted on the properties immediately adjacent to the Property.

Direction	Land Uses
North	Commercial Use
East	Commercial and Industrial Use
South	Commercial and Industrial Use
West	Parkland

6.3.1 Potentially Contaminating Activity

The site inspection identified the following Potentially Contaminating Activities (PCAs) within the Phase One Property. The detailed locations of the PCAs are illustrated in Figure 4.

Location of PCA	PCA	Details
Phase One Property	#28 - Gasoline and Associated Products Storage in Fixed Tanks	Site Inspection - A group of three tanks was observed along the western wall of the building on Site
Phase One Property	#28 - Gasoline and Associated Products Storage in Fixed Tanks	Site Inspection - A group of three tanks was observed along the fence on the western boundary of the Site.

7.0 REVIEW AND EVALUATION OF INFORMATION

7.1 Current and Past Uses

Current and past uses of the Property were determined from historical aerial photographs, a chain of title documents and city directories. The full list of current and past uses of the Property is provided in Appendix H, in a form approved by the Ontario Ministry of the Environment and Climate Change under O. Reg. 153/04.

7.2 Potentially Contaminating Activities

The Phase One Environmental Site Assessment identified the following Potentially Contaminating Activities (PCAs) on the Phase One Property and the Phase One Study Area. The detailed locations of the PCAs are illustrated in Figure 4.

Location of PCA	PCA	APEC (YES/NO)	Details
On-Site PCAs			
1393 Grahams Lane	Others 1 – Ontario Regulation 347 – Waste Generator	Yes	Ecolog ERIS – The property was occupied by McGraw Edison and Walker Magnetics National Ltd. which were Electrical equipment manufacturers that were registered as waste generators from 1986-1998 of: - Halogenated Solvents - Organic Acids - Petroleum Distillates - Waste Oils & Lubricants Scotts Manufacturing Directory Listings indicated that businesses operating at the Property included Walker Magnetics National Ltd., which operated in manufacturing Electrical Industrial Apparatuses not elsewhere classified Relays and Industrial Controls, and Special Industrial Machinery not elsewhere classified, and United States Aluminum of Canada Ltd. which operated in Metal Window and Door Manufacturing City Directory listings for International Aluminum Canada in 2000 City Directory listings for Walker Magnetics National Limited and McGraw-Edison Limited Electric Coil Division, manufacturers of electrical components from in 1980-1995 The presence of paved parking lots and driveways on the Site indicate potential for the application of salt at the property during winter months for de-icing purposes. Site Reconnaissance – Two sets of 3 Tanks were observed on the Site. The first set of tanks was located along the western wall of the commercial building on the Site. The second was observed along the fence at midway point of the western property boundary.
	PCA #19 – Electronic and Computer Equipment Manufacturing		
	PCA #34 – Metal Fabrication		
	PCA #28 – Gasoline and Associated Products Storage in Fixed Tanks		
	PCA #28 – Gasoline and Associated Products Storage in Fixed Tanks		
	Others 2 – Salt Application for De-icing Purposes		

Off-Site PCAs			
942 Brant Street 158m North of Property	PCA #8 – Chemical Manufacturing, Processing, and Bulk Storage	No	Ecolog ERIS - The Property was occupied by Hercules Canada Inc. Ashland, and Solenis Canada all of which were registered in the Chemical Register and Chemical Manufacturers and Distributors Registry. The property was occupied by Ashland Canada Corp., Solenis Canada ULC, and Hercules Canada Inc. which were registered as waste generators from 1986-Present of: - Organic Acids - Amines - Non-Halogenated Pesticides - Other Specified Organics - Waste Compressed Gases - Organic Laboratory Chemicals - Acid Waste - Aromatic Solvents
	Others 1 – Ontario Regulation 347 – Waste Generator		

	Others 3 - Spills		- Paint/Pigment/Coating Residues - Aliphatic Solvents - Other Specified Inorganics - Inorganic Laboratory Chemicals - Petroleum Distillates - Emulsified Oils - Alkaline Wastes - Light Fuels - Polymeric Resins - Halogenated Pesticides - PCBs - Oil Skimmings and Sludges - Heavy Fuels - Phenolic Wastes Multiple National Environmental Emergencies System and Ontario Spills Record indicating spills of different chemical agents has occurred at the Property. Scotts Manufacturing Directory Listings indicated that businesses operating at the Property included Ashland Canada Corp, which operated in manufacturing of Miscellaneous Chemical Products. City Directory Listings for Ashland Canada and Hercules Canada Inc. both of which operated as chemical manufacturers from 1960-2021 Due to the distance and downgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property.
1380 Grahams Lane 20m South of Property	PCA #28 – Gasoline and Associated Products Stroage in Fixed Tanks	Yes	Ecolog ERIS – The Property was identified in as having multiple Delisted Fuel Tanks and Private and Retail Fuel Storage Tanks related to gasoline and diesel fuels.

	Others 1 – Ontario Regulation 347 – Waste Generator		The property was occupied by Petro-Canada, Suncor Energy and John Ebos Fuels Limited which operated as Gas Stations and were registered as a waste generators from 1988-Present of: - Light Fuels - Petroleum Distillates - Oil Skimmings & Sludges - Waste Oils & Lubricants City Directory listings for Burlington Energy Systems Co. Ltd., Frew Energy, and John Ebos Fuels Ltd. all of which operated as gas stations from 2000-2021
1448 Grahams Lane 145m East of Property	PCA #28 – Gasoline and Associated Products Stroage in Fixed Tanks	No	Ecolog ERIS – The Property was identified in as having multiple Delisted Fuel Tanks and Private and Retail Fuel Storage Tanks related to gasoline and diesel fuels. TSSA records indicate the former presence of multiple fuel tank at this property. Additionally, the Property was identified on the Registry of Expired Fuels Safety Facilities Due to the distance and transgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property.

809 Brant Street 250m East of Property	PCA #28 – Gasoline and Associated Products Stroage in Fixed Tanks	No	Ecolog ERIS – The Property was identified in as having multiple Delisted Fuel Tanks and Private and Retail Fuel Storage Tanks related to gasoline and diesel fuels. The Property was identified on the Registry of Expired Fuels Safety Facilities Additionally, TSSA records indicate the former presence of multiple fuel tank at this property. Due to the distance and transgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property.
1370 Grahams Lane 51m Southwest of Property	Others 1 – Ontario Regulation 347 – Waste Generator PCA #18 – Electricity Generation, Transformation and Power Stations PCA #55 – Transformer Manufacturing, Processing and Use	Yes	Ecolog ERIS – The Property was occupied by the Burlington Hydro-Electric Commission which operated as an Electric Distribution System Station and was registered as a waste generator from 1989-1998 of: - Alkaline Wastes - Oil Skimmings & Sludges
1416 Grahams Lane 36m South of Property	Others 1 – Ontario Regulation 347 – Waste Generator PCA #57: Vehicles and Associated Parts Manufacturing PCA #34 – Metal Fabrication	Yes	Ecolog ERIS - The property was occupied by Sinclair-Smith Printing & Lithographing, which was identified as a waste generator from 1986-1994 of unspecified wastes. Scotts Manufacturing Directory Listings indicated that businesses operating at the Property included Arctic Traveller (Canada) Ltd., which operated in manufacturing Heating Equipment and Commercial

	PCA #31 – Ink Manufacturing, Processing and Bulk Storage		Refrigeration Equipment, and New Motor Vehicle Parts and Accessories, City Directory listings for Sinclair-Smith Printing and Lithographing Co. Ltd. and Allied Arts Display Ltd. commercial printers from 1975-2005 City Directory Listings for Parkdale Machine & Tool Co. Ltd. a machine shop in 1970
850 Legion Road Adjacent to North of Property	Others 1 – Ontario Regulation 347 – Waste Generator	Yes	The property was occupied by Wentworth Electronics, Teckmark Label Systems, Artisan Design, B-Line Cresting, Golden Horseshoe Services, The Maples Animal Hospital, Historia Building Restoration Inc., SOAR Veterinary Profession Corporation, and Carl's Grinding Service which were registered as waste generators from 1988-Present of: - Aromatic Solvents - Acid Waste - Alkaline Wastes - Petroleum Distillates - Halogenated Solvents - Aromatic Solvents - Pathological Wastes - Paint/Pigment/Coating Residues - Organic Laboratory Chemicals - Pharmaceuticals - Waste Oils & Lubricants The Pesticide Register indicates that McConnell-Spadafora Inc. which operated at the property was registered as a pesticide vendor.
	PCA #40 - Pesticides (including Herbicides, Fungicides and Anti-Fouling Agents) Manufacturing, Processing, Bulk Storage and Large-Scale Applications		
	PCA #45 – Pulp, Paper, and Paperboard Manufacturing & Processing		
	PCA #31 – Ink Manufacturing, Processing and Bulk Storage		

	PCA #59 – Wood Treating and Preservative Facility and Bulk Storage of Treated and Preserved Wood Products		Scotts Manufacturing Directory Listings indicated that businesses operating at the Property included Teckmark Label Systems Inc., KLB Interiors Inc., Artisan Design, Meridan Golf Inc., Hibon Inc., Woodcraft Rail Inc., B-Line Cresting, Fry Graphics Ltd., Burlington Letterpress, McConnell-Spadafora Inc., and Mulit-Line Products Inc. which operated in a wide variety of activities including; - Commercial Printing & Lithography - Manufacturing of Coated and Laminated Paper - Wood Cabinet, Countertop and Furniture Manufacturing - Industrial Machinery Manufacturing and Other Millwork - Curtin and Linen Mills - Textile Fabric Manufacturing and Finishing - Stationary Product Manufacturing City Directory listings for Artisan Design a Kitchen Cabinet and Household furniture manufacturer from 1990-2021
	PCA #54 – Textile Manufacturing and Processing		
	PCA #34 – Metal Fabrication		
	PCA #33 - Metal Treatment, Coating, Plating and Finishing		
	PCA #43 - Plastics (including Fibreglass) Manufacturing and Processing		

	PCA #10 – Commercial Auto Body Shops		City Directory listings for Carl's Precision Grinding a Metal Coating and Engraving operation from 2012-2017 City Directory listings for Dynamic Plastic Solutions Inc. a Plastics Manufacturer from 2012-2017 City Directory listings for Fry Graphics a commercial lithographic printer from 2000-2017 City Directory listings for Teckmark Label System Inc. a coated and laminated paper manufacturer from 1995-2017 City Directory listings for ACA Performance Inc., an auto parts manufacturer in from 2000-2012 City Directory listings for Wheels of Dreams., a commercial auto garage from in 2012
1440 Grahams Lane 45m Southeast of Property	Others 1 – Ontario Regulation 347 – Waste Generator PCA #8 – Chemical Manufacturing, Processing, and Bulk Storage PCA #33 – Metal Treatment, Coating, Plating, & Finishing PCA #34 – Metal Fabrication PCA #31 – Ink Manufacturing, Processing and Bulk Storage PCA #19 – Electronic and Computer Equipment Manufacturing	Yes	Ecolog ERIS - The property was occupied by Dover Corporation (Canada) Limited, Thyssen Dover Elevator, Ontario Testing Labs, Ash Temple Ltd., Bodycote Galt Materials Testing Ltd., and Exova Burlington, which were registered as a waste generators from 1992-Present of: - Emulsified Oils - Photo processing Wastes - Polymeric Resins - Acid Waste - Inorganic Laboratory Chemicals - Organic Laboratory Chemicals - Organic Acids - Waste Compressed Gases - Oil Skimmings & Sludges - Miscellaneous Wastes and Organic/Inorganic Chemicals Scotts Manufacturing Directory Listings indicated that businesses operating at the

	PCA #10 – Commercial Auto Body Shops		Property included Scherzinger Pump Technology, Thyssen Dover Elevators, Burlington Laminating & Binder, Peters Steel Rule Dies, Endress & Hauser Canada Ltd., Magnus Chemicals Ltd., and Pyramid Pumps. which operated in a wide variety of activities including; - Chemical (except Agricultural) and Allied Products Wholesaler-Distribution - Industrial Machinery, Equipment and Supplies Wholesaler-Distribution - Other Metal Working Machinery Manufacturing - Commercial Printing not elsewhere classified - Relays and Industrial Controls Manufacturing - Industrial Machinery and Equipment City Directory listings for Wicks' Auto Collision, Smit Auto Body and Freedom Motors, Automotive Repair Services from 1975-2021
1355 Stephenson Drive 68m West of Property	Others 1 – Ontario Regulation 347 – Waste Generator	Yes	Ecolog ERIS – The property was occupied by Hydro One Networks Inc. which was registered as a waste generator from 2019-Present of: - Other Specified Inorganic Sludges, Slurries or Solids
1439 Grahams Lane	Others 1 – Ontario Regulation 347 – Waste Generator	No	Ecolog ERIS – The property was occupied by Burlington Hydro Inc. which was registered as a waste generator in 2004 of unspecified wastes

100m East of Property	PCA #34 – Metal Fabrication		Due to the distance and transgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property. City Directory Listings for Frank Tool & Die Co. Ltd. a machine shop from 1960-1965
831 Legion Road 100m East of Property	Others 1 – Ontario Regulation 347 – Waste Generator	No	Ecolog ERIS – The property was occupied by the Burlington Association for Community which was registered as a waste generator from 1990-1998 of: - Acid Waste Due to the distance and transgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property.
802 Hagar Avenue 100m South of Property	Others 1 – Ontario Regulation 347 – Waste Generator	Yes	Ecolog ERIS – The property was occupied by the Wellington Park Care Centre, Responsive Management Inc. and Suncor Energy Products, which were registered as waste generators from 2011-Present of: - Paint/Pigment/Coating Residues - Waste Oils & Lubricants - Light Fuels - Waste Oils & Sludges

1881 Fairview Street 200m North of Property	Others 1 – Ontario Regulation 347 – Waste Generator	No	Ecolog ERIS – The property was occupied by Michaels Stores Inc. which was registered as a waste generator from 2013-2018 of: - Paint/Pigment/Coating Residues - Alkaline Wastes - Inorganic Laboratory Chemicals - Aliphatic Solvents - Organic Laboratory Chemicals - Other Specified Inorganics - Waste Compressed Gases - Detergents/Soaps Due to the distance and downgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property.
760 Brant Street 210m Southeast of Property	Others 1 – Ontario Regulation 347 – Waste Generator	No	Ecolog ERIS - The property was occupied by 1086891 Ontario Inc, Burlington Ultrasound and Radiology, McAuthur Properties, Trillium College Inc, Wentworth Halton X-Ray and Ultrasound Inc., Oxford College of Arts, Business and Technology, and Dr. Ronald Yim Dentistry Professional Corp. which were registered as a waste generators from 2010-Present of: - Pathological Wastes - Neutralized Waste - Inorganic Laboratory Chemicals - Photo processing Wastes - Miscellaneous Wastes and Inorganic Chemicals Due to the distance of this PCA this PCA is not likely to cause APEC on the Property.

834 Brant Street 70m Northeast of Property	PCA #40 - Pesticides (including Herbicides, Fungicides and Anti-Fouling Agents) Manufacturing, Processing, Bulk Storage and Large-Scale Applications	No	Ecolog ERIS - The Pesticide Register indicates that Pets & Garden Ltd. which operated at the property was registered as a retail pesticide vendor Class 03. Due to the distance and transgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property.
1-2004 Maplewood Drive 250m Northeast of Property	PCA #40 - Pesticides (including Herbicides, Fungicides and Anti-Fouling Agents) Manufacturing, Processing, Bulk Storage and Large-Scale Applications	No	Ecolog ERIS - The Pesticide Register indicates that Canada Pest Control. which operated at the property was registered as a pesticide operator Class 01 Type 02. Due to the distance and transgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property.
817 Brant Street 249m East of Property	PCA #34 – Metal Fabrication PCA #19 - Electronic and Computer Equipment Manufacturing	No	Scotts Manufacturing Directory Listings indicated that businesses operating at the Property included Advanced Integrated Resources Inc., which operated in manufacturing Industrial and Commercial Fan and Blower and Air Purification Equipment Due to the distance and transgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property.
1380 Grahams Lane 20m South of Property	PCA #28 – Gasoline and Associated Products Storage in Fixed Tanks	Yes	City Directory listings for Burlington Energy Systems Co. Ltd., Frew Energy, and John Ebos Fuels Ltd. all of which operated as gas stations from 2000-2021
1392 Grahams Lane	PCA #10 – Commercial Auto Body Shops	Yes	City Directory Listings for Airds Automotive, Brant Auto Body, Burlington Automotive

18m South of Property	PCA #28 – Gasoline and Associated Products Storage in Fixed Tanks PCA #34 – Metal Fabrication		Centre and Hi-Tech Collision which operated as Automotive Repair Services from 1985-2021 FIP – Machine shop and 8 associated fuel oil tanks are observed as being present at this location in the 1971 FIP
1421 Grahams Lane Adjacent to East of Property	PCA #10 – Commercial Auto Body Shops	Yes	City Directory listings for Als Lawn Mower Small Engine and gas engine repair service and equipment supplier from 2012-2021
1425 Grahams Lane Adjacent to East of Property	PCA #10 – Commercial Auto Body Shops	Yes	City Directory listings for SWC Automotive, Metro Collision Repair Auto, and Maaco Auto Paint and Bodyworks a commercial auto garage from 1985-2021
932 Brant Street 250m North of Property	PCA #10 – Commercial Auto Body Shops	No	City Directory listings for Dollar Thrifty Automotive Group, a commercial auto garage in 2005 Due to the distance and downgradient nature of this PCA with respect to the inferred groundwater flow direction, this PCA is not likely to cause APEC on the Property.
892 Brant Street 250m North of Property	PCA #10 Commercial Auto Body Shops PCA #28 Gasoline and Associated Products Storage in Fixed Tanks	No	FIP – A commercial auto service shop and associated tank are observed as being present at this location in the 1971 FIP Based on the distance from the Phase One Property and its downgradient location this PCA is not considered to contribute to an on-Site APEC

850 Brant Street 121m Northeast of Property	PCA #10 Commercial Auto Body Shops	No	FIP – A commercial auto body is observed as being present at this location in the 1971 FIP Based on the distance from the Phase One Property and its transgradient location this PCA is not considered to contribute to an on-Site APEC
814 Brant Street 147m East of Property	PCA #10 Commercial Auto Body Shops	No	FIP – A commercial auto service shop is observed as being present at this location in the 1971 FIP Based on the distance from the Phase One Property and its transgradient location this PCA is not considered to contribute to an on-Site APEC
1451 Grahams Lane 140m East of Property	PCA #34 – Metal Fabrication	No	FIP – Machine shop is observed as being present at this location in the 1971 FIP Based on the distance from the Phase One Property and its transgradient location this PCA is not considered to contribute to an on-Site APEC
825 Legion Road Adjacent to East of Property	PCA #34 – Metal Fabrication	Yes	FIP – Machine shop is observed as being present at this location in the 1971 FIP
Adjacent to the West of the Phase One Property	PCA #46 – Rail Yards, Tracks, and Spurs	Yes	Aerials – A CN Railway Corridor runs from North to South Directly adjacent to the west of the Phase One Property. Therefore, the QP's assessment is that this PCA is likely to cause an APEC on the Property.

7.3 Areas of Potential Environmental Concern

The Potentially Contaminating Activities identified in Section 7.2 were evaluated for their potential to create an Area of Potential Environmental Concern (APEC) on the Phase One Property through consideration of:

- The type of PCA
- The potential magnitude of the PCA (e.g. small-scale waste generation versus significant commercial activity)

- The Potential Contaminants of Concern (PCoC) associated with the PCA
- The nature of those PCoCs in terms of their mobility in soil, ground water, and sediment as applicable
- The anticipated direction of ground water flow
- The anticipated hydraulic conductivity of saturated media
- The distance between the PCA and the Property

The analysis and rationale used to determine that a particular PCA does not create an APEC is provided in Section 7.2. The APECs identified are presented in a form approved by the Director in Appendix I.

The physical area of each APEC is illustrated on Figure 6. Please note that the area illustrated does not necessarily represent the complete potential area of impact but represents the most likely potential area of impact and thus represents the area that would first require intrusive investigation in a Phase Two ESA should a Phase Two ESA be conducted.

7.4 Phase One Conceptual Site Model

The Phase One Conceptual Site Model (CSM) is presented in Appendix J, which is illustrated and includes Figure 1 through Figure 6.

7.5 Uncertainty or Absence of Information

The following uncertainties or absence of information may have an impact on the Phase One Conceptual Site Model:

Component	Uncertainty of Absence of Information	Effect on Phase One CSM
Fire Insurance Plans	Fire Insurance Plans were available for review. As such, there exists no known void or absence of information for this component.	No effect upon the Phase One CSM
Chain of Title	Chain of Title was received at the time of this Report, information from the Chain of Title has been incorporated into the Phase One ESA.	No effect upon the Phase One CSM
Environmental Reports	Previous reports were not available to Englobe Corporation (formerly Terraprobe Inc.) to review as part of the investigation; No known environmental reports have previously been conducted for the Site.	No effect upon the Phase One CSM

Component	Uncertainty of Absence of Information	Effect on Phase One CSM
Environmental Source Information	Environmental Source Information was searched through a combination of Environmental Risk Information Services (ERIS) and Freedom of Information requests (FOI). As such, there exists no known void or absence of information for this component.	No effect upon the Phase One CSM
Aerial Photographs	Aerial Photographs were obtained from a combination of federal, provincial, municipal and private sources. The series of air photos selected represent the development of the Phase One Property and Phase One Study Area. As such, there exists no known void or absence of information for this component.	No effect upon the Phase One CSM
Topography, Hydrogeology and Geology	The Topography, Hydrogeology and Geology were evaluated through available resources from the Ministry of Natural Resources and Forestry as well as Water Well Records. As such, there exists no known void or absence of information for this component.	No effect upon the Phase One CSM
Water Bodies and Areas and Natural Significance	Water Bodies and Areas and Natural Significance were evaluated through available resources from the Ministry of Natural Resources and Forestry, local conservation authorities and the Ministry of the Environment. As such, there exists no known void or absence of information for this component.	No effect upon the Phase One CSM
Well Records	Well Records through the summary provided by Environmental Risk Information Services (ERIS) as well as the Ministry of the Environment Water Well Information System (WWIS). As such, there exists no known void or absence of information for this component.	No effect upon the Phase One CSM
Site Reconnaissance	Unrestricted access to the Phase One Property was provided during the Site Reconnaissance. As such, there exists no known void or absence of information for this component.	No effect upon the Phase One CSM

Component	Uncertainty of Absence of Information	Effect on Phase One CSM
Interviews	Interviews with persons knowledgeable regarding the current and historic environmental condition of the Phase One Property were conducted. As such, there exists no known void or absence of information for this component.	No effect upon the Phase One CSM

Based upon the information obtained, as noted above, it is the belief of the QP_{ESA} that there is no known significant uncertainty or absence of information and that the Phase One Conceptual Site Model is valid.

8.0 CONCLUSIONS

8.1 Phase Two ESA Required to Assess Soil and Groundwater Quality

Based upon the review and evaluation of information gathered from the Phase One ESA, there are Potentially Contaminating Activities (PCA) noted on the Phase One Property and study area, which resulted in ten (10) Areas of Potential Environmental Concern (APECs) generated from the PCAs.

The Phase One ESA identified the following APECs on the Property:

APEC No.	Location of APEC	Potentially Contaminating Activity	Location of PCA	Contaminants of Potential Concern	Media Potentially Impacted
APEC 1	Southern Portion of Phase One Property	#19 - Electronic and Computer Equipment Manufacturing	On-Site	Metals, As, Sb, Se, B-HWS, CN-, Hg, Cr(VI), pH, EC, PHCs, BTEX, VOCs, PAHs	Soil and Groundwater
APEC 2	Southern Portion of Phase One Property	#34 - Metal Fabrication	On-Site	Metals, As, Sb, Se, B-HWS, CN-, Hg, Cr(VI), pH	Soil and Groundwater
APEC 3	Exterior Western Wall of Commercial Building (Western Portion of Phase One Property)	#28 - Gasoline and Associated Products Storage in Fixed Tanks	On-Site	PHCs, BTEX, VOCs	Soil and Groundwater
APEC 4	Midway point along fence on Western Property Boundary (Western Portion of Phase One Property)	#28 - Gasoline and Associated Products Storage in Fixed Tanks	On-Site	PHCs, BTEX, VOCs	Soil and Groundwater
APEC 5	Southern Portion of Phase One Property	Others 1 - Ontario Regulation 347 - Waste Generator	On-Site	Metals, As, Sb, Se, B-HWS, CN-, Hg, Cr(VI), pH, EC, PHCs, BTEX, VOCs, PAHs	Soil and Groundwater
APEC 6A	Across Phase One Property	Others 2 - Salt Application for De-Icing Purposes	On-Site	SAR, EC, Na, Cl	Soil and Groundwater
APEC 6B	Across Phase One Property	#30 – Importation of Fill Material of Unknown Quality	On-Site	PAHs, PCBs, Metals, As, Sb, Se, B-HWS,	Soil

				CN-, Hg, Cr(VI), pH, EC, SAR	
APEC 7	Southern Property Boundary	Others 1 - Ontario Regulation 347 - Waste Generator #28 - Gasoline and Associated Products Storage in Fixed Tanks #18 – Electricity Generation, Transformation and Power Stations #55 – Transformer Manufacturing, Processing and Use #57: Vehicles and Associated Parts Manufacturing #34 – Metal Fabrication #31 – Ink Manufacturing, Processing and Bulk Storage #8 – Chemical Manufacturing, Processing, and Bulk Storage #33 – Metal Treatment, Coating, Plating, & Finishing #10 - Commercial Auto Body Shops #19 – Electronic and Computer Equipment Manufacturing	Off-Site	Metals, As, Sb, Se, B-HWS, CN-, Hg, Cr(VI), pH, EC, SAR, PHCs, BTEX, VOCs, PAHs, PCBs	Soil and Groundwater
APEC 8	Northern Property Boundary	Others 1 - Ontario Regulation 347 - Waste Generator #40 - Pesticides (including Herbicides, Fungicides and Anti-Fouling Agents) Manufacturing, Processing, Bulk Storage and Large-Scale Applications #45 – Pulp, Paper, and Paperboard Manufacturing & Processing #31 – Ink Manufacturing, Processing and Bulk Storage #59 – Wood Treating and Preservative Facility and Bulk Storage of Treated and Preserved Wood Products #54 – Textile Manufacturing and Processing #34 – Metal Fabrication #33 - Metal Treatment, Coating, Plating and Finishing PCA #10 – Commercial Auto Body Shops #43 - Plastics (including Fibreglass) Manufacturing and Processing	Off-Site	Metals, As, Sb, Se, B-HWS, CN-, Hg, Cr(VI), pH, EC, PHCs, BTEX, VOCs, PAHs, PCBs	Soil and Groundwater
APEC 9	Eastern Property Boundary	#10 - Commercial Auto Body Shops	Off-Site	Metals, As, Sb, Se, B-HWS, CN-, Hg,	Soil and Groundwater

		#34 - Metal Fabrication		Cr(VI), pH, EC, PHCs, BTEX, VOCs, PAHs	
APEC 10	Western Property Boundary	#46 Rail Yards, Tracks and Spurs	Off-Site	Metals, As, Sb, Se, B-HWS, CN-, Hg, Cr(VI), pH, EC, PHCs, BTEX, VOCs, PAHs, PCBs	Soil and Groundwater
		Others 1 - Ontario Regulation 347 - Waste Generator			

A Phase Two Environmental Site Assessment will be required to investigate the APECs that have been identified on the Property arising from the current and historical PCAs found at the Property and within the Study Area, which may have resulted in adverse impacts to the environmental condition of the Property.

8.2 Signatures

The Phase One Environmental Site Assessment has been completed under the direction and supervision of Muhammad Shahid, P.Geo., QP_{ESA}. The findings and conclusions presented in this report have been determined on the basis of the information that was obtained and reviewed and on an assessment of the existing conditions on the Phase One Property and properties within the Phase One Study Area.

We trust this report meets with your requirements. Should you have any questions regarding the information presented, please do not hesitate to contact our office.

Yours truly,

Syed Ali EIT.
Project Manager

Muhammad Shahid, P.Geo., QP_{ESA}

9.0 REFERENCES

1. Armstrong, D.K. and Dodge, J.E.P. *Paleozoic Geology Map of Southern Ontario*. Ontario Geological Survey, Miscellaneous Release--Data 219.
2. Chapman, L.J. and Putnam, D.F. 2007. *The Physiography of Southern Ontario*. Ontario Geological Survey, Miscellaneous Release--Data 228.
3. Gao, C., Shirota, J., Kelly, R. I., Brunton, F.R., van Haaften, S. 2006. Bedrock topography and overburden thickness mapping, southern Ontario; Ontario Geological Survey, Miscellaneous Release--Data 207.
4. Ontario Geological Survey 2010. *Surficial Geology of Southern Ontario.* Ontario Geological Survey, Miscellaneous Release--Data 128-REV. ISBN 978-1-4435-2483-7
5. Ontario Geological Survey 2006. *Bedrock Topography and Overburden Thickness Mapping, Southern Ontario.* Ontario Geological Survey, Miscellaneous Release–Data 207.

10.0 LIMITATIONS AND USE OF THE REPORT

This report was prepared for the exclusive use of **2621458 Ontario Inc.**. and is intended to provide an assessment of the environmental condition on the property identified as **1393 Grahams Lane, Burlington, Ontario.**

Any use which a third party makes of this report, or any reliance on or decisions to be made based on it, are the responsibility of such third parties. Englobe Corporation (formerly Terraprobe Inc.) accepts no responsibility for damages, if any, suffered by any third party as a result of decisions made or actions based on this report, including consequential financial effects on transactions or property values or requirements for follow-up actions and costs.

The assessment should not be considered a comprehensive audit that eliminates all risks of encountering environmental problems. The information presented in this report is based on information collected during the completion of the Phase One Environmental Site Assessment by Englobe Corporation (formerly Terraprobe Inc.) It is based on the conditions on the Phase One property at the time of the site inspection, supplemented by a review of historical information to assess the environmental conditions of the Phase One, as reported herein.

Sampling and analysis of soil, ground water or any other material was not carried out as part of this assessment. Consequently, the presence and/or extent of any adverse environmental impact cannot be verified. The potential for environmental liability and/or environmental impact is an opinion that has been arrived at within the scope of this assessment.


In assessing the environmental conditions/history of the Phase One, Englobe Corporation (formerly Terraprobe Inc.) has relied in good faith on information provided by others, as noted in this report, and has assumed that the information provided by those individuals is factual and accurate. Englobe Corporation (formerly Terraprobe Inc.) accepts no responsibility for any deficiency, misstatement or inaccuracy in this report resulting from the information provided by those individuals.

There is no warranty expressed or implied by this report regarding the environmental status of the Phase One. Professional judgement was exercised in gathering and analysing information collected by our staff, as well as that submitted by others. The conclusions presented are the product of professional care and competence and cannot be construed as an absolute guarantee.

In the event that during future work, new information regarding the environmental condition of the Phase One is encountered, or in the event that the outstanding responses from the regulatory agencies indicate outstanding issues on file with respect to the Phase One, Englobe Corporation (formerly Terraprobe Inc.) should be notified in order that we may re-evaluate the findings of this assessment and provide amendments, as required.

FIGURES







Note

1. This drawing shall be read in conjunction with the associated technical report.

A	5/3/2024	Final	X.X
Revision	Date	Issue	Approval


Client	ONTARIO INC.C/O Altus Group
Site	1393 Grahams Lane, Burlington, Ontario

Report Title	Phase One Environmental Site Assessment	Designed By: S.A	Date: March 2024
		Drawn By: AA	Project No.: 02211083.001
Drawing Title	Location Plan	Approved By: M.S	Figure No.: 1
		Scale: As Shown	

20 Carlson Court, Etobicoke, Ontario | M9W 7K6 | Tel: (905) 796-2650 | Website: www.englobecorp.com

Copyright © 2024 Englobe Corp.

Folder: Y:\Shared\CA\Terraprobe\Brampton\1-Project Files\2022-Englobe\02211083.001 - 1393 Grahams Lane, ENV\0100 - Phase One ESA\A. Dwgs, Logs\AutoCAD\02211083.001.dwg, Tuesday, March 05, 2024 @ 11:52 by Aws Alashaab
Drawing: 02211083.001.dwg
Y:\Shared\CA\Terraprobe\Brampton\1-Project Files\2022-Englobe\02211083.001 - 1393 Grahams Lane, ENV\0100 - Phase One ESA\A. Dwgs, Logs\AutoCAD\02211083.001.dwg, 1, _AutoCAD PDF (Smallest File).pc3



Source:
City of Burlington Interactive Maps

ENGLOBE

Legend

Site Boundary

Note

1. This drawing shall be read in conjunction with the associated technical report.
2. Drawing scale may be distorted. Measurements/locations taken from the drawing must be verified in the field.

1:1 000

0 10 20 30 40 50 m

0 5 cm

1:1

Scale accurate when printed at 100% using paper size ANSI Full Bleed B (11.0 x 17.0 Inches). Field verify all measurements.

Revision	Date	Issue	Approval
A	5/3/2024	Final	X.X

Client
ONTARIO INC.C/O Altus Group

Site
1393 Grahams Lane, Burlington, Ontario

Report Title
Phase One Environmental Site Assessment

Drawing Title
Site Plan


Designed By	Scale
S.A	As Shown
Drawn By	**Date**
A.A	March 2024
Approved By	**Project No.**
M.S	02211083.001

Figure No.
2

20 Carlson Court, Etobicoke, Ontario | M9W 7K6 | Tel: (905) 796-2650 | Website: www.englobecorp.com

Copyright © 2024 Englobe Corp.

Drawing: 02211083.001.dwg Folder: Y:\Shared\CA\Terraprobe\Brampton\1-Project Files\2022-Englobe\02211083.001 - 1393 Grahams Lane, ENV\0100 - Phase One ESA\A. Dwgs, Logs\AutoCAD\02211083.001.dwg. Tuesday, March 05, 2024 @ 11:52 by Aws Alashaab
Y:\Shared\CA\Terraprobe\Brampton\1-Project Files\2022-Englobe\02211083.001 - 1393 Grahams Lane, ENV\0100 - Phase One ESA\A. Dwgs, Logs\AutoCAD\02211083.001.dwg.
2, _AutoCAD PDF (Smallest File).pc3



Legend

- Site Boundary
- Study Area (250m Radius)

Potentially Contaminating Activity (PCA)	
PCA No.	Description
8	Chemical Manufacturing, Processing and Bulk Storage
10	Commercial Autobody Shops
18	Electricity Generation, Transformation and Power Stations
19	Electronic and Computer Equipment Manufacturing
28	Gasoline and Associated Products Storage in Fixed Tanks
31	Ink Manufacturing, Processing and Bulk Storage
33	Metal Treatment, Coating, Plating and Finishing
34	Metal Fabrication
40	Pesticides (including Herbicides, Fungicides and Anti-Fouling Agents) Manufacturing, Processing, Bulk Storage and Large-Scale Applications
43	Plastics (including Fibreglass) Manufacturing and Processing
45	Pulp, Paper and Paperboard Manufacturing and Processing
46	Rail Yards, Tracks and Spurs
54	Textile Manufacturing and Processing
55	Transformer Manufacturing, Processing and Use
57	Vehicles and Associated Parts Manufacturing
59	Wood Treating and Preservative Facility and Bulk Storage of Treated and Preserved Wood Products
Others1	Waste Generators
Others2	Use of Winter De-icing Salts
Others3	Spills

Note

1. This drawing shall be read in conjunction with the associated technical report.
2. Drawing scale may be distorted. Measurements/locations taken from the drawing must be verified in the field.

1:300

0 5 10 15 m

0 1:1 5 cm

Scale accurate when printed at 100% using paper size ANSI Full Bleed B (11.0 x 17.0 Inches). Field verify all measurements.

Revision	Date	Issue	Approval
A	5/3/2024	Final	X.X

Client
ONTARIO INC.C/O Altus Group

Site
1393 Grahams Lane, Burlington, Ontario

Report Title
Phase One Environmental Site Assessment

Drawing Title
PCA Locations


Designed By: S.A	Scale: As Shown
Drawn By: A.A	Date: March 2024
Approved By: M.S	Project No.: 02211083.001

Figure No. **3**

20 Carlson Court, Etobicoke, Ontario | M9W 7K6 | Tel: (905) 796-2650 | Website: www.englobecorp.com

Copyright © 2024 Englobe Corp.

Drawing: 02211083.001.dwg Folder: Y:\Shared\CA\Terraprobe\Brampton\1-Project Files\2022-Englobe\02211083.001 - 1393 Grahams Lane, ENV\0100 - Phase One ESA\A. Dwgs. Logs\AutoCAD\02211083.001.dwg, Tuesday, March 05, 2024 @ 11:52 by Aws Alashaab
Y:\Shared\CA\Terraprobe\Brampton\1-Project Files\2022-Englobe\02211083.001 - 1393 Grahams Lane, ENV\0100 - Phase One ESA\A. Dwgs. Logs\AutoCAD\02211083.001.dwg, 3_AutoCAD PDF (Smallest File).pc3



ENGLOBE

Legend

- Site Boundary
- Study Area (250m Radius)

Note

1. This drawing shall be read in conjunction with the associated technical report.
2. Drawing scale may be distorted. Measurements/locations taken from the drawing must be verified in the field.

1:300

0 5 10 15 m

0 1:1 5 cm

Scale accurate when printed at 100% using paper size ANSI Full Bleed B (11.0 x 17.0 Inches). Field verify all measurements.

Revision	Date	Issue	Approval
A	5/3/2024	Final	X.X

Client
ONTARIO INC.C/O Altus Group

Site
1393 Grahams Lane, Burlington, Ontario

Report Title
Phase One Environmental Site Assessment

Drawing Title
Site and Surrounding Area


Designed By	Scale
S.A	As Shown
Drawn By	**Date**
A.A	March 2024
Approved By	**Project No.**
M.S	02211083.001

Figure No.
4

20 Carlson Court, Etobicoke, Ontario | M9W 7K6 | Tel: (905) 796-2650 | Website: www.englobecorp.com

Copyright © 2024 Englobe Corp.

Drawing: 02211083.001.dwg Folder: Y:\Shared\CA\Terraprobe\Brampton\1-Project Files\2022-Englobe\02211083.001 - 1393 Grahams Lane, ENV\0100 - Phase One ESA\A. Dwgs. Logs\AutoCAD\02211083.001.dwg, Tuesday, March 05, 2024 @ 11:52 by Aws Alashaab
Y:\Shared\CA\Terraprobe\Brampton\1-Project Files\2022-Englobe\02211083.001 - 1393 Grahams Lane, ENV\0100 - Phase One ESA\A. Dwgs. Logs\AutoCAD\02211083.001.dwg, 4_AutoCAD PDF (Smallest File).pc3



Source:
City of Burlington Interactive Maps

Legend

- Site Boundary
- APEC 1
- APEC 2
- APEC 3
- APEC 4
- APEC 5
- APEC 6
- APEC 7
- APEC 8
- APEC 9
- APEC 10

Note

1. This drawing shall be read in conjunction with the associated technical report.
2. Drawing scale may be distorted. Measurements/locations taken from the drawing must be verified in the field.

1:1 000

0 10 20 30 40 50 m

0 1:1 5 cm

Scale accurate when printed at 100% using paper size ANSI Full Bleed B (11.0 x 17.0 Inches). Field verify all measurements

Revision	Date	Issue	Approval
A	5/3/2024	Final	X.X

Client
ONTARIO INC.C/O Altus Group

Site
1393 Grahams Lane, Burlington, Ontario

Report Title
Phase One Environmental Site Assessment

Drawing Title
APEC Locations

Designed By	Scale
S.A	As Shown
Drawn By	**Date**
A.A	March 2024
Approved By	**Project No.**
M.S	02211083.001

Figure No.
5

20 Carlson Court, Etobicoke, Ontario | M9W 7K6 | Tel: (905) 796-2650 | Website: www.englobecorp.com

Copyright © 2024 Englobe Corp.

Drawing: 02211083.001.dwg Folder: Y:\Shared\CA\Terraprobe\Brampton\1-Project Files\2022-Englobe\02211083.001 - 1393 Grahams Lane, ENV\0100 - Phase One ESA\A. Dwgs. Logs\AutoCAD\ Tuesday, March 05, 2024 @ 11:52 by Aws Alashaab
Y:\Shared\CA\Terraprobe\Brampton\1-Project Files\2022-Englobe\02211083.001 - 1393 Grahams Lane, ENV\0100 - Phase One ESA\A. Dwgs. Logs\AutoCAD\02211083.001.dwg, 5, AutoCAD PDF (Smallest File).pc3

Appendix A
Site Photographs



Photograph 1

Location: 1393 Grahams Lane

Viewing: Exterior

Description: View from northeast corner of property



Photograph 2

Location: 1393 Grahams Lane

Viewing: Exterior

Description: Fuel storage tanks




Photograph 3

Location: 1393 Grahams Lane

Viewing: Interior

Description: Storage area



Photograph 4

Location: 1393 Grahams Lane

Viewing: Interior

Description: Water heaters



Photograph 5

Location: 1393 Grahams Lane

Viewing: Interior

Description: Water supply



Photograph 6


Location: 1393 Grahams Lane

Viewing: Exterior

Description: View of building from Grahams Lane

Appendix B
Title Search Results





ServiceOntario

PRINTED ON 30 JAN, 2024 AT 10:07:43
FOR BERTUCCI

SCALE

0 10 20 30 40 50 60
meters

PROPERTY INDEX MAP

HALTON(No. 20)

LEGEND

FREEHOLD PROPERTY	
LEASEHOLD PROPERTY	
LIMITED INTEREST PROPERTY	
CONDOMINIUM PROPERTY	
RETIRED PIN (MAP UPDATE PENDING)	
PROPERTY NUMBER	*0449*
BLOCK NUMBER	**08050**
GEOGRAPHIC FABRIC	
EASEMENT	

THIS IS NOT A PLAN OF SURVEY

NOTES

REVIEW THE TITLE RECORDS FOR COMPLETE PROPERTY INFORMATION AS THIS MAP MAY NOT REFLECT RECENT REGISTRATIONS

THIS MAP WAS COMPILED FROM PLANS AND DOCUMENTS RECORDED IN THE LAND REGISTRATION SYSTEM AND HAS BEEN PREPARED FOR PROPERTY INDEXING PURPOSES ONLY

FOR DIMENSIONS OF PROPERTIES BOUNDARIES SEE RECORDED PLANS AND DOCUMENTS

ONLY MAJOR EASEMENTS ARE SHOWN

REFERENCE PLANS UNDERLYING MORE RECENT REFERENCE PLANS ARE NOT ILLUSTRATED

Ontario

© Queen's Printer for Ontario, 2024

CHAIN OF TITLE REPORT

Project #:	#02211083.001	**Searched at:**	Milton
Address:	1393 Graham's Lane, Burlington	**LRO #:**	20
Legal Description:	Part Lot 69 RCP 99 Part 1 20R3140 & Part 1 20R21599		
PIN #:	07090-0669 (LT)		

****Pertains to Part 1, 20R21599****

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
	Patent	14 02 1798	Crown	**Capt. Joseph BRANT**
83	Deed	18 12 1803	Capt. Joseph Brant	Robert WILSON
311	Deed	27 09 1808	Robert Wilson	Benjamin MALLONY
313	Deed	29 09 1808	Benjamin Mallony	John HEIGH
325	Deed	11 01 1809	John Heigh	Benjamin MALLONY
2350	Tax Deed	05 01 1815	Sheriff John Biskie (Benjamin Mallony defaulted in taxes)	Augustus BATES
318	Deed	09 07 1825	Augustus Bates	William REYNOLDS
319	Deed	11 07 1825	William Reynolds	Francis J. HAROLD
400	Deed	06 12 1828	Francis J. Harold	William REYNOLDS

Cont'd on Page 2

CHAIN OF TITLE REPORT

Project #: #02211083.001
Address: 1393 Graham's Lane, Burlington
Legal Description: Part Lot 69 RCP 99
Part 1 20R3140 & Part 1 20R21599

PIN #: 07090-0669 (LT)

Searched at: Milton
LRO #: 20

Pertains to Part 1, 20R21599

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
678	Deed	20 03 1835	William Reynolds	William TISDALE
576	Deed	20 06 1840	William Tisdale	William REYNOLDS
139	Deed	08 11 1843	William Reynolds	John HOGARTH
331	Deed	28 03 1855	John Hogarth	George HILL
2141	Deed	11 12 1877	George Hill - Estate	George N. HILL
2173	Deed	11 01 1878	George N. Hill	Thomas CASHMAN
258	Deed	04 03 1878	Thomas Cashman	Johnston ZIMMERMAN
2509	Deed	05 12 1904	Johnston Zimmerman - Estate	Joseph M. MARTIN
2510	Deed	05 12 1909	Joseph M. Martin	Joseph ANDERSON Henry ZEATS

Cont'd on Page 3

CHAIN OF TITLE REPORT

Project #: #02211083.001
Address: 1393 Graham's Lane, Burlington
Legal Description: Part Lot 69 RCP 99
Part 1 20R3140 & Part 1 20R21599

PIN #: 07090-0669 (LT)

Searched at: Milton
LRO #: 20

Pertains to Part 1, 20R21599

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
2919	Deed	02 03 1908	Henry Zeats	Joseph ANDERSON
4918	Deed	13 09 1918	Joseph Anderson	Robert MOSELEY THOMPSON
5534	Deed	30 10 1920	Robert Moseley Thompson	William MacDONALD
15970	Deed	06 11 1951	William MacDonald	William MacDONALD, Jr.
104137	Deed	21 10 1959	William MacDonald, Jr.	Trustees for Burlington Vinton Memorial Branch 60 of The Canadian Legion of The British Empire Service League
268871	Deed	23 04 1969	Trustees for Burlington Vinton Memorial Branch 60 of The Canadian Legion of The British Empire Service League	Vinton Memorial Branch 60 Royal Canadian Legion
HR484243	Name Change	13 06 2006	Vinton Memorial Branch 60 Royal Canadian Legion	Burlington (Ontario No. 60) Branch of The Royal Canadian Legion

Cont'd on Page 4

CHAIN OF TITLE REPORT

Project #:	#02211083.001	**Searched at:**	Milton
Address:	1393 Graham's Lane, Burlington	**LRO #:**	20
Legal Description:	Part Lot 69 RCP 99 Part 1 20R3140 & Part 1 20R21599		
PIN #:	07090-0669 (LT)		

Pertains to Part 1, 20R21599

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
HR1739003	Deed	27 10 2020	Burlington (Ontario No. 60) Branch of The Royal Canadian Legion	2584979 Ontario Inc.
HR1932640	Deed **(Present Owner)**	08 11 2022	2584979 Ontario Inc.	**1256384 B.C. Ltd.**

CHAIN OF TITLE REPORT

Project #:	#02211083.001	**Searched at:**	Milton
Address:	1393 Graham's Lane, Burlington	**LRO #:**	20
Legal Description:	Part Lot 69 RCP 99 Part 1 20R3140 & Part 1 20R21599		
PIN #:	07090-0669 (LT)		

Pertains to Part 1, 20R3140

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
	Patent	14 02 1798	Crown	**Capt. Joseph BRANT**
83	Deed	18 04 1803	Capt. Joseph Brant	Robert WILSON
311	Deed	27 09 1808	Robert Wilson	Benjamin MALLONY
313	Deed	29 09 1808	Benjamin Mallony	John HEIGH
325	Deed	11 01 1809	John Heigh	Benjamin MALLONY
2350	Tax Deed	05 01 1815	Sheriff John Biskie (Benjamin Mallony defaulted in taxes)	Augustus BATES
318	Deed	09 07 1825	Augustus Bates	William REYNOLDS
319	Deed	11 07 1825	William Reynolds	Francis J. HAROLD
400	Deed	06 12 1828	Francis J. Harold	William REYNOLDS

Cont'd on Page 2

CHAIN OF TITLE REPORT

Project #: #02211083.001 **Searched at:** Milton
Address: 1393 Graham's Lane, Burlington **LRO #:** 20
Legal Description: Part Lot 69 RCP 99 Part 1 20R3140 & Part 1 20R21599

PIN #: 07090-0669 (LT)

Pertains to Part 1, 20R3140

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
678	Deed	20 03 1835	William Reynolds	William TISDALE
576	Deed	20 06 1840	William Tisdale	William REYNOLDS
139	Deed	08 11 1843	William Reynolds	John HOGARTH
331	Deed	28 03 1855	John Hogarth	George HILL
2141	Deed	11 12 1877	George Hill - Estate	George N. HILL
2173	Deed	11 01 1878	George N. Hill	Thomas CASHMAN
258	Deed	04 03 1878	Thomas Cashman	Johnston ZIMMERMAN
2509	Deed	05 12 1904	Johnston Zimmerman - Estate	Joseph M. MARTIN
2510	Deed	05 12 1904	Joseph M. Martin	Joseph ANDERSON Henry ZEATS

Cont'd on Page 3

CHAIN OF TITLE REPORT

Project #: #02211083.001
Address: 1393 Graham's Lane, Burlington
Legal Description: Part Lot 69 RCP 99
Part 1 20R3140 & Part 1 20R21599

PIN #: 07090-0669 (LT)

Searched at: Milton
LRO #: 20

Pertains to Part 1, 20R3140

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
2919	Deed	02 03 1908	Henry Zeats	Joseph ANDERSON
3461	Deed	22 10 1911	Joseph Anderson	Elmer HALL
5048	Deed	14 05 1919	Elmer Hall	Kenneth ALLEN Clara Aline ALLEN
7110	Deed	30 01 1925	Kenneth Allen Clara Aline Allen	Row Bertie BUTLER Walter Francis BUTLER
7728	Deed	11 06 1927	Row Bertie Butler Walter Francis Butler	T. Gordon BROWN
7857	Deed	13 01 1928	T. Gordon Brown	Abraham K. HUNT
11797	Deed	05 12 1944	Abraham K. Hunt	Ignac SAWCZYSZYN Irene SAWCZYSZYN
47429	Deed	14 02 1956	Ignac Sawczyszyn Irene Sawczyszyn	John Nicoll BLAIR George Stanley BLAIR
95535	Deed	07 04 1959	John Nicoll Blair George Stanley Blair	Trustees for Burlington Vinton Memorial Branch 60 of The Canadian Legion of The British Empire Service League

Cont'd on Page 4

CHAIN OF TITLE REPORT

Project #: #02211083.001
Address: 1393 Graham's Lane, Burlington
Legal Description: Part Lot 69 RCP 99
Part 1 20R3140 & Part 1 20R21599

PIN #: 07090-0669 (LT)

Searched at: Milton
LRO #: 20

Pertains to Part 1, 20R3140

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
363182	Deed	01 06 1973	Trustees For Vinton Memorial Branch 60, Royal Canadian Legion	Francis Shaw (Canada) Limited
364943	Deed	21 06 1973	Francis Shaw (Canada) Limited	Matys Designs Limited
526057	Deed	12 08 1980	Matys Industries Limited (Fmly Matys Designs Limited)	Selenex Corporation Limited
HR194143	Deed	01 05 2003	Selenex Corporation Limited	Erbdocs Inc.
HR808075	Deed	17 12 2009	Erbdocs Inc.	Don Marie WALKER
HR1181547	Mortgage	15 05 2014	Don Marie Walker	The Bank of Nova Scotia Trust Company (Mortgagee)
HR1185762	Deed	02 06 2014	Don Marie Walker	1916310 Ontario Inc.
HR1514990	Deed (Power of Sale)	22 12 2017	The Bank of Nova Scotia Trust Company (1916310 Ontario Inc. defaulted in Mtg)	2584979 Ontario Inc.
HR1932640	Deed **(Present Owner)**	08 11 2022	2584979 Ontario Inc.	**1256384 B. C. Ltd.**

Appendix C
City Directory Search Results



ERIS

CITY DIRECTORY

Project Property:	*1393 Grahams Lane* *1393 Grahams Lane* *Burlington,ON L7S 1W4*
Project No:	*02211083.001*
Requested By:	*EnGlobe Corp.*
Order No:	*24011900269*
Date Completed:	*January 25, 2024*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

January 25, 2024
RE: CITY DIRECTORY RESEARCH
1393 Grahams Lane
Burlington,ON L7S 1W4

Thank you for contacting ERIS regarding our City Directory Search services. Our staff has conducted a reverse listing City Directory search to determine prior occupants of the subject site and adjacent properties. When searching a range of addresses, all civic addresses within that range found in the Directory are included.

Note: Reverse Listing Directories generally are focused on highly developed areas, while newly developed areas may be covered in the more recent years, older directories tend to cover only "central" parts of the city. To complete the search, we have either utilized the Toronto Reference Library, Library & Archives Canada and multiple digitized directories. While these do not claim to be a complete collection of all reverse listing city directories produced, ERIS has made every effort to provide accurate and complete information. ERIS shall not be held liable for missing, incomplete, or inaccurate information. If you believe there are additional addresses or streets that require searching, please contact us.

Search Criteria:
942 of Brant Street
1370-1425 of Grahams Lane
828-850 Even of Legion Road
1360-1375 of Stephenson Drive
Search Notes:
Data from 2012 to 2021 for Burlington, Ontario does not include residential information

Search Results Summary

Date	Source	Comment
2021	DIGITAL BUSINESS DIRECTORY	
2017	DIGITAL BUSINESS DIRECTORY	
2012	DIGITAL BUSINESS DIRECTORY	
2005	VERNONS	
2000	VERNONS	
1995	VERNONS	
1990	VERNONS	
1985	VERNONS	
1980	VERNONS	
1975	VERNONS	
1970	VERNONS	
1965	VERNONS	
1960	VERNONS	
1957	VERNONS	

2021 BRANT STREET

SOURCE: DIGITAL BUSINESS DIRECTORY

942 **ASHLAND CANADA**...*OIL FIELD CHEMICALS (WHLS)*

2021 GRAHAMS LANE

SOURCE: DIGITAL BUSINESS DIRECTORY

1380 **FREW ENERGY**...*DIESEL FUEL (WHLS)*
1392 **BURLINGTON AUTOMOTIVE CTR**...*AUTOMOBILE REPAIRING & SERVICE*
1392 **HI TECH COLLISION**...*AUTOMOBILE REPAIRING & SERVICE*
1400 **SMIT AUTO BODY**...*AUTOMOBILE REPAIRING & SERVICE*
1416 **ARCTIC TRAVELER LTD**...*REFRIGERATING EQUIP-COMMERCIAL (WHLS)*
1421 **AL'S LAWN MOWER SMALL ENGINE**...*LAWN & GARDEN EQUIP & SUPPLIES-RETAIL*
1423 **MCKENZIE ATHLETIC THERAPY SVC**...*MEDICAL & SURGICAL SVC ORGANIZATIONS*
1423 **TIDAL CROSSFIT BURLINGTON**...*HEALTH CLUBS STUDIOS & GYMNASIUMS*
1425 **SWC AUTOMOTIVE**...*AUTOMOBILE REPAIRING & SERVICE*

2021 LEGION ROAD

SOURCE: DIGITAL BUSINESS DIRECTORY

828 **715 MOHAWK AIR CADETS**...*NONCLASSIFIED ESTABLISHMENTS*
828 **BURLINGTON ARMY CADET CORPS**...*NONCLASSIFIED ESTABLISHMENTS*
850 **ARTISAN DESIGN**...*KITCHEN CABINETS & EQUIPMENT-HOUSEHOLD*
850 **BURLINGTON ENERGY SYSTEMS**...*FURNACES-REPAIRING & CLEANING*
850 **COVE CONTRACTING INC**...*HEATING CONTRACTORS*
850 **COVE MECHANICAL**...*HEATING CONTRACTORS*
850 **CUSTOM COUNTERTOPS MORE**...*HOME IMPROVEMENTS*
850 **MAPLES ANIMAL HOSPITAL**...*PET SUPPLIES & FOODS-RETAIL*
850 **MCCONNELL-SPADAFORA INC**...*JANITORS EQUIPMENT & SUPPLIES-MFRS*
850 **TELCOM RESEARCH**...*FEDERAL GOVERNMENT CONTRACTORS*
850 **ZEPHYR NORTH**...*WIND ENERGY SYSTEMS (WHLS)*

2021 STEPHENSON DRIVE

SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND

2017 BRANT STREET

SOURCE: DIGITAL BUSINESS DIRECTORY

942 **ASHLAND CANADA**...*OTHER CHEMICAL MERCHANT WHOLS*
942 **HERCULES CANADA INC**...*OTHER CHEMICAL MERCHANT WHOLS*

2017 GRAHAMS LANE

SOURCE: DIGITAL BUSINESS DIRECTORY

1380 **JOHN EBOS FUELS LTD**...*OTHER PETROLEUM MERCHANT WHOLS*
1380 **PETRO-CANADA**...*OTHER GASOLINE STATIONS*
1392 **AUTO SPLASH CAR WASH DTLNG**...*CAR WASHES*
1392 **BRANT AUTO BODY**...*AUTOMOTIVE BODY & INTERIOR REPAIR*
1392 **BURLINGTON AUTOMOTIVE CTR**...*GENERAL AUTOMOTIVE REPAIR*
1393 **TMCP BUILDING SYSTEMS INC**...*COMMERCIAL BUILDING CONSTRUCTION*
1400 **GOLDEN HORSESHOE APPRAISALS**...*ALL OTHER PROFESSIONAL & TECHNICAL SVCS*
1400 **MIKE'S BODY SHOP SUPPLIES**...*NEW MOTOR VEHICLE PARTS MERCHANT WHOLS*
1400 **SMIT AUTO BODY**...*AUTOMOTIVE BODY & INTERIOR REPAIR*
1416 **ARCTIC TRAVELER LTD**...*AC, REFRIGERATION, & FORCED AIR HEATING*
1421 **AL'S LAWN MOWER SMALL ENGINE**...*OUTDOOR POWER EQUIP STORES*
1421 **AL'S LAWNMOWER SM ENG REPAIR**...*OUTDOOR POWER EQUIP STORES*
1421 **AL'S SKATE SHARPENING**...*SPORTING GOODS STORES*
1423 **CROSS FIT ALTITUDE**...*FITNESS & RECREATIONAL SPORTS CENTERS*
1423 **NATIONAL SPECIALTY CAKES**...*STORE RETAILERS NOT SPECIFIED ELSEWHERE*
1423 **NSC CAKES**...*RETAIL BAKERIES*
1425 **MAACO AUTO PAINT & BODYWORKS**...*AUTOMOTIVE BODY & INTERIOR REPAIR*
1425 **METRO COLLISION REPAIR AUTO**...*AUTOMOTIVE BODY & INTERIOR REPAIR*
1425 **STREET WYZE CUSTOMS**...*AUTOMOTIVE BODY & INTERIOR REPAIR*
1425 **SWC AUTOMOTIVE**...*GENERAL AUTOMOTIVE REPAIR*

2017 LEGION ROAD

SOURCE: DIGITAL BUSINESS DIRECTORY

828 **BURLINGTON ARMY CADET CORPS**...*UNCLASSIFIED*
828 **POPPY TRUST FUND**...*BUSINESS ASSOCIATIONS*
828 **ROYAL CANADIAN LEGION**...*CIVIL & SOCIAL ORGANIZATIONS*
850 **ARTISAN DESIGN**...*FINISH CARPENTRY CONTRS*
850 **BURLINGTON ENERGY SYSTS CO LTD**...*PLUMBING & HVAC CONTRS*
850 **BURLINGTON LETTERPRESS**...*COMMERCIAL LITHOGRAPHIC PRINTING*
850 **CARL'S PRECISION GRINDING**...*METAL COATING & NONPRECIOUS ENGRAVING*
850 **COVE CONTRACTING INC**...*PLUMBING & HVAC CONTRS*
850 **COVE MECHANICAL INC**...*PLUMBING & HVAC CONTRS*
850 **DYNAMIC PLASTIC SOLUTIONS INC**...*ALL OTHER PLASTICS PROD MFG*
850 **FRESH LIFE FLOWERS**...*FLORISTS*
850 **FRY GRAPHICS**...*COMMERCIAL LITHOGRAPHIC PRINTING*
850 **GREENTARIO LANDSCAPING LTD**...*LANDSCAPE CONTRACTORS*
850 **HISTORIA BUILDING RESTORATION**...*ALL OTHER SPECIALTY TRADE CONTRS*
850 **KINA CONSTRUCTION**...*NEW SINGLE-FAMILY GENERAL CONTRS*
850 **KLB INTERIORS INC**...*HOME FURNISHING MERCHANT WHOLS*
850 **MAPLES ANIMAL HOSPITAL**...*VETERINARIANS*
850 **MCCONNELL-SPADAFORA INC**...*SERVICE ESTABLISHMENT EQUIP MERCHANT WHOLS*
850 **TECKMARK LABEL SYSTEMS INC**...*COATED & LAMINATED PAPER MFG*
850 **TELCOM RESEARCH**...*ELECTRICAL CONTRS*
850 **ZEPHYR NORTH**...*PLUMBING EQUIP MERCHANT WHOLS*

2017 STEPHENSON DRIVE

SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND

2012 BRANT STREET

SOURCE: DIGITAL BUSINESS DIRECTORY

942 **HERCULES CANADA INC**...*OTHER CHEMICAL MERCHANT WHOLS*

2012 GRAHAMS LANE

SOURCE: DIGITAL BUSINESS DIRECTORY

1380 **FARAGO STEW PRODUCTIONS**...*ADVERTISING AGENCIES*
1380 **JOHN EBOS FUELS**...*OTHER MISC CHEMICAL PROD MFG*
1380 **JOHN EBOS FUELS LTD**...*OTHER PETROLEUM MERCHANT WHOLS*
1392 **BRANT AUTO BODY**...*AUTOMOTIVE BODY & INTERIOR REPAIR*
1392 **BURLINGTON AUTOMOTIVE CTR**...*GENERAL AUTOMOTIVE REPAIR*
1393 **INTERNATIONAL ALUMINUMCANADA**...*OTHER BUILDING MATERIAL DEALERS*
1393 **TMCP BUILDING SYSTEMS INC**...*COMMERCIAL BUILDING CONSTRUCTION*
1400 **GOLDEN HORSESHOE APPRAISALS**...*ALL OTHER PROFESSIONAL & TECHNICAL SVCS*
1400 **MITCHELL AUTOMOTIVE ESTIMATING**...*GENERAL AUTOMOTIVE REPAIR*
1400 **SMIT AUTO BODY**...*AUTOMOTIVE BODY & INTERIOR REPAIR*
1416 **ARCTIC TRAVELER LTD**...*AC, REFRIGERATION, & FORCED AIR HEATING*
1421 **AL'S LAWN MOWER SMALL ENGINE**...*OUTDOOR POWER EQUIP STORES*
1423 **NATIONAL SPECIALTY CAKES**...*STORE RETAILERS NOT SPECIFIED ELSEWHERE*
1423 **NSC CAKES**...*RETAIL BAKERIES*
1423 **ZONE GOLF CTR**...*GOLF COURSES & COUNTRY CLUBS*
1425 **MAACO AUTO PAINT & BODYWORKS**...*AUTOMOTIVE BODY & INTERIOR REPAIR*

2012 LEGION ROAD

SOURCE: DIGITAL BUSINESS DIRECTORY

828 **BURLINGTON ARMY CADET CORPS**...*UNCLASSIFIED*
828 **ROYAL CANADIAN LEGION**...*CIVIL & SOCIAL ORGANIZATIONS*
850 **1V1 SOCCER**...*SPORTS TEAMS & CLUBS*
850 **ACA PERFORMANCE INC**...*ALL OTHER MOTOR VEHICLE PARTS MFG*
850 **ARTISAN DESIGN**...*FINISH CARPENTRY CONTRS*
850 **BUDDY'S HYDROPONICS**...*UNCLASSIFIED*
850 **BURLINGTON ENERGY SYSTS CO LTD**...*PLUMBING & HVAC CONTRS*
850 **BURLINGTON LETTERPRESS**...*COMMERCIAL LITHOGRAPHIC PRINTING*
850 **CARL'S PRECISION GRINDING**...*METAL COATING & NONPRECIOUS ENGRAVING*
850 **COMPUMARS**...*COMMERCIAL LITHOGRAPHIC PRINTING*
850 **COVE CONTRACTING INC**...*ALL OTHER SPECIALTY TRADE CONTRS*
850 **CRYSTAL CLEAN SVC**...*ALL OTHER SPECIALTY TRADE CONTRS*
850 **DYNAMIC PLASTIC SOLUTIONS INC**...*ALL OTHER PLASTICS PROD MFG*
850 **FRESH LIFE FLOWERS**...*FLORISTS*
850 **FRY GRAPHICS**...*COMMERCIAL LITHOGRAPHIC PRINTING*
850 **FURNITURE COVER UP**...*REUPHOLSTERY & FURNITURE REPAIR*
850 **GRAPHIC DISPLAY WORK**...*OFFICE SUPPLIES MERCHANT WHOLS*
850 **GREENTARIO LANDSCAPING LTD**...*LANDSCAPE CONTRACTORS*
850 **HISTORIA BUILDING RESTORATION**...*ALL OTHER SPECIALTY TRADE CONTRS*
850 **KLB INTERIORS INC**...*OTHER KNIT FABRIC & LACE MILLS*
850 **MAPLES ANIMAL HOSPITAL**...*VETERINARIANS*
850 **MC CONNELL-SPADAFORA INC**...*SERVICE ESTABLISHMENT EQUIP MERCHANT WHOLS*
850 **MULTI-LINE PRODUCTS**...*ALL OTHER DURABLE GOODS MERCHANT WHOLS*
850 **PREFERRED MOVING & STORAGE**...*GENERAL FREIGHT TRUCKING, LOCAL*
850 **PROCESS DRYING & FILTRATION**...*ALL OTHER SUPPORT SVCS*
850 **REACO INC**...*OTHER CONSTRUCTION MATERIAL MERCHANT WHOLS*
850 **TAYLOR MADE MACHINING**...*MACHINE SHOPS*
850 **TECKMARK LABEL SYSTEMS INC**...*COATED & LAMINATED PAPER MFG*
850 **WHEELS OF DREAMS**...*AUTOMOTIVE BODY & INTERIOR REPAIR*
850 **ZEPHRY NORTH**...*PLUMBING EQUIP MERCHANT WHOLS*

2012 STEPHENSON DRIVE

SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND

2005 BRANT STREET

SOURCE: VERNONS

■	932	Dollar Thrifty Automotive Group Can Inc	▲333-3334
X	942	Hercules Canada Inc	▲632-7861
(6)	944	Vacant	
(6)	950	Vacant	

2005 GRAHAMS LANE-A

SOURCE: VERNONS

-- CNR CROSSES
L7S 1W4

(2)	1393	TMCP Building Systems Inc	▲631-0035
(3)	1421	Halton Work Programme	▲631-5913
(2)	1423	National Specialty Cakes Inc	▲633-8871
X	1425	Maaco Auto Painting & Body Works	▲632-8861

-- LEGION RD BEGINS & ENDS
L7S 1W5

2005 GRAHAMS LANE-B

SOURCE: VERNONS

-- CNR CROSSES
L7S 1W3

X	1380	Ebos John Fuel Ltd	▲637-0033
X	1392	Burlington Automotive Centre	▲681-9286
X	1392	Brant Auto Body	▲637-8265
(1)	1392	Fairview Chrysler Dodge Ltd (Body Shop)	▲637-8265
X	1400	Smit Auto Body	▲333-0215
X	1416	Arctic Traveler (Canada) Ltd	▲637-3468
X	1416	Sinclair-Smith Printing & Lithographing Co Ltd	▲639-3917
X	1440	Ash Temple Ltd	▲632-5972
X	1440	Endress & Hauser	▲681-4350

2005 LEGION ROAD-A

SOURCE: VERNONS

LEGION RD East Side
n from Graham's Lane 1 west Brant St

L7S 1T6

(1)	850	Woodcraft Rail Inc	▲681-3116
(8)	831	Living Waters	▲333-3373

Legion Br 60)
850 Brant Park
Industrial Mall
1 Artisan Design ▲333-0079
5 KLB Interiors Inc ▲681-0711
6 Fry Graphics Ltd ▲631-9989
-- Rea-Co Inc ▲633-8994
7 Source Solutions ▲333-4054
-- Buddy's Hydroponics ▲681-0937
-- Preferred Packing & Moving Solutions ▲315-8968
-- Pixel Touch Inc ▲681-9009
-- Historia Building Restoration Inc ▲333-0101
-- Dynamic Plastic Solutions Inc ▲335-5555
-- Burlington Energy Systems Co Ltd ▲632-8079
-- Greentario Landscaping ▲634-9568
-- 360 Multimedia ▲333-4425
-- Zephyr North ▲335-9670
-- 1V1 Soccer ▲633-6812
11 Preston's Letterpress ▲637-1539
12-A Furniture Cover Up ▲333-4143

794 LEGION RD
(8) 15 Woodcraft Rail Inc (Shop) ▲681-3116
X 22 Maples Animal Hospital The ▲681-0300
X 23 Teckmark Label Systems Inc ▲681-7070

I FIGHLAND RD North Side

2005 STEPHENSON DRIVE

SOURCE: VERNONS

(2)	1359	Michtics P	633-8112
(2)	1361	Moynihan J	639-9705
	1363	No Return	
(2)	1365	Brittle J	633-8035
	1375	Apartments	
(3)	--	Lavergne W	333-5921
(3)	--	Gibbons T	333-1509

2000 BRANT STREET

SOURCE: VERNONS

		Lease Centre	
■	932	Al Paparoni Accounting & Tax	▲333-6770
X	942	Hercules Canada Inc	▲632-7861
(1)	944	Vacant	
(1)	950	Vacant	

-- CNR CROSSES
L7S 1W4

■	1393	International Aluminum Canada	▲333-3212
X	1421	Halton Work Program Burlington	▲631-5913
■	1421	Stride	▲637-5489
■	1423	Get A Grip-Div Of Stride	▲333-5375
X	1425	Maaco Auto Painting & Body Works	▲632-8861

-- LEGION RD BEGINS & ENDS
L7S 1W5

-- CNR CROSSES
L7S 1W3

X	1380	Burlington Energy Systems Co Ltd	▲632-8079
(1)	1380	Stew Fargo Productions	▲333-3262
X	1380	Ebos John Fuel Ltd	▲637-0033
(5)	1392	Burlington Automotive Centre	▲681-9286
X	1392	Brant Auto Body	▲637-8265
(6)	1400	Smit Auto Body	▲333-0215
X	1416	Arctic Traveler (Canada) Ltd	▲637-3468
X	1416	Sinclair-Smith Printing & Lithographing Co Ltd	▲639-3917

WARNING !! Ke

	■	1416	Advanced Temperature Control	▲637-3468
3	(5)	1440	Ash Temple Ltd	▲632-6610
2	(7)	1440	Endress & Hauser	▲681-9292

LEGION RD West Side

L7S 1T5

X		828	Royal Canadian Legion Branch 60	▲632-6060
(6)		828	Burlington Army Cadet Corps	▲681-3923
X		828	Ladies' Auxiliary (Royal Canadian Legion Br 60)	▲639-0571
		850	Brant Park Industrial Mall	
X		1	Artisan Design	▲333-0079
(6)		3	Hibon-Stokes (Sales Office)	▲681-7712
(1)		4	Burlington Studio Dance	▲634-1515
(3)		5	K L B Interiors Inc	▲681-0711
■		6	Fry Graphics Ltd	▲631-9989
(3)		7	B-Line Cresting	▲631-1226
■		8	Alternative Human Resources (AHR)	▲631-9920
■		9	Brimac Refrigeration Ltd	▲637-1010
■		11	Preston's Letterpress	▲637-1539
(1)		11	ASI International Inc	▲639-4222
X		12A	Furniture Cover Up	▲333-4143
(3)		15	Woodcraft Rail Inc	▲681-3116
■		17	Golden Horseshoe Services	▲634-5555
(2)		18	Pure Touch Services	▲333-1203
■		19	ACA Performance Inc	▲632-2209
■		20	U Trendline Home Improvements	▲633-9456
(5)		22	Maples Animal Hospital The	▲681-0300
X		23	Teckmark Label Systems Inc	▲681-7070


2000 STEPHENSON DRIVE

SOURCE: VERNONS

1360-1375 **NO LISTINGS WITHIN RADIUS**

1995 BRANT STREET

SOURCE: VERNONS



-- CNR CROSSES
L7S 1W4

(4) 1393 Walker Magnetics † 632-1171
National Limited
X 1421 Halton Work † 637-5489
Program
Burlington
(6) 1423 Gemini Ceramics † 333-5505
X 1425 Maaco Auto † 632-8861
Painting & Body
Works

-- LEGION RD BEGINS & ENDS
L7S 1W5

-- HAMMOND ENDS

-- CNR CROSSES
L7S 1W3

X 1380 Burlington † 632-8079
Energy Systems
Co Ltd
1380 Stew Fargo † 333-3262
Productions
X 1380 EBOS, JOHN † 637-0033
FUEL LTD
• 1392 Burlington † 681-9286
Automotive
Centre
(7) 1392 Brant Auto Body † 637-8265
(1) 1400 Smit Auto Body † 333-0215
X 1416 Arctic Traveler † 637-3468
(Canada) Ltd
X 1416 Sinclair-Smith † 639-3917
Printing &
Lithographing Co
Ltd
• 1440 Ash Temple Ltd † 632-6610
(2) 1440 Endress & Hauser † 681-9292

LEGION RD West Side

L7S 1T5

X 828 Royal Canadian Legion Branch 60 † 639-6060

(1) 828 Burlington Army Cadet Corps † 681-3923

850 Brant Park Industrial Mall

(6) 1 Artisan Design † 333-0079

(3) 2 Log'N Lawn † 632-8329

(1) 3 Hibon-Stokes (Sales Office) † 681-7712

4 Burlington Studio Dance † 634-1515

(5) 5 Burlington Tai Chi † 634-4990

(2) 7 Tsuruoka Karate School † 634-4891

(1) 9 McLeod D J Company † 639-1702

(6) 12A Furniture Cover Up † 333-4143

14 Meridian Golf (2000) Inc † 632-7335

(1) 18 Inadel Wholesale Inc † 681-3360

(1) 19 Merry Maids † 637-9844

(2) 20 Wercholoz Associates Ltd † 637-2122

(7) 21 Servicemaster Contract Services † 637-1411

• 22 Maples Animal Hospital The † 681-0300

(5) 23 Teckmark Label Systems Inc † 681-7070

1995 STEPHENSON DRIVE

SOURCE: VERNONS

1360-1375 **NO LISTINGS WITHIN RADIUS**

1990 BRANT STREET

SOURCE: VERNONS

•	932	Brant Windows Inc	333-9658
X	942	Hercules Canada Inc	632-7861
	944	No Return	
	950	Canadian National	

1990 GRAHAMS LANE-A

SOURCE: VERNONS

-- CNR CROSSES
L7S 1W4

1393 Vacant

(6) 1421 Halton Work Program Burlington † 637-5489

(1) 1423 Gemini Ceramics † 333-5505

(9) 1425 Maaco Auto Painting & Body Works † 632-8861

(1) 1439 Canadian Fire Restoration Services † 333-1236

-- LEGION RD BEGINS

1990 GRAHAMS LANE-B

SOURCE: VERNONS

-- CNR CROSSES
L7S 1W3

(1) 1380 E & J Tank Removal Services † 333-3571

(6) 1380 Burlington Energy Systems Co Ltd † 632-8079

(2) 1380 Fargo Stew Productions † 333-3262

X 1380 Ebos John Fuel Ltd † 637-0033

• 1392 Lou's Garage † 333-0345

(2) 1392 Brant Auto Body † 637-8265

• 1400 Freedom Motors † 333-4266

X 1416 Arctic Traveler (Canada) Ltd † 637-3468

1416 No Return

X 1416 Sinclair-Smith Printing & Lithographing Co Ltd † 639-3917

(3) 1416 Picture Perfect † 634-4557

• 1440 Tarbutt-Buttenham Construction Ltd † 681-8181

LEGION ROAD West Side

L7S 1T5

X 828 Royal Canadian Legion Branch 60 † 639-6060

850 Brant Park Industrial Mall

(1) 1 Artisan Design † 333-0079
(2) 2 Filtration Textiles † 336-0001

(5) 3 Gemini TV & Audio † 634-1720
4 Cintia's Studio Dance † 634-1515

• 5 Burlington Tai Chi † 634-4990

(1) 6 Tables Unlimited † 637-5962
• 7 Tsurvoka Karate School † 634-4891

• 8 Kirby Centre-Burlington † 333-1081

9 Vacant

• 10 Foundation Trading Inc † 333-0229

• 11 Stock-Well Supply † 333-3292

• 12 Montgomery Marketing † 333-5999

(1) 12A Furniture Cover Up † 333-4143

13 Vacant

14 Vacant

(1) 15 Allison-Britt Ltd † 637-6371

(1) 15 Brant Plumbing & Heating † 637-6371

• 16 Yuppie Gourmet Inc † 333-0799

• 17 Darcon Design & Construction † 681-6390

(1) 18 Professional Computing Services † 333-3193

(2) 19 Hitech Erectors Inc † 681-9000

(1) 20 A N C Courier † 333-3793
(2) 21 Servicemaster Contract Services † 637-1411

(3) 22 M M O S Inc † 333-6667
• 23 Teckmark Label Systems Inc † 681-7070

Street Continued

1990 STEPHENSON DRIVE

SOURCE: VERNONS

1360-1375 **NO LISTINGS WITHIN RADIUS**

1985 BRANT STREET

SOURCE: VERNONS

637-2532

932 Energy Update 637-2532

942 Hercules Canada Ltd

chem 632-7861

944 No Return

950 Canadian National

— *CNR CROSSES*
L7S 1W4

1393 McGraw-Edison Limited elect coil div 632-1171

1421 Halton Co-ordinated Work Program Burlington 637-5489

1423 Monroe Systems For Business 637-8288

1423 Kimball Systems 637-7404

1425 Maaco Auto Painting & Body Works 632-8861

— *LEGION RD BEGINS*
L7S 1W5

1451 Johnson Machine

— *CNR CROSSES*
L7S 1W3

1380 McGrath G 634-2483

1380 Burlington Energy Systems Co Ltd 632-8079

1380 Ebos John Fuel Ltd agt for Gulf Oil Ltd 637-0033

1392 Aird's Automotive 639-4130

1400 Wicks' Auto Collision 634-1873

1416 Arctic Traveler (Canada) Ltd 637-3468

1416 Sinclair-Smith Printing & Lithographing Co Ltd 639-3917

1448 Brant Car Wash Ltd 634-0155

1985 LEGION ROAD

SOURCE: VERNONS

LEGION ROAD West Side

L7S 1T5
828 Royal Canadian Legion
Branch 60 632-6060

****

1985 STEPHENSON DRIVE

SOURCE: VERNONS

1360-1375 **STREET NOT LISTED**

1980 BRANT STREET

SOURCE: VERNONS

Surgeons 639-3392

932 Vacant

942 Hercules Canada Ltd
chem 632-7861

944 Niagara Chemical Co
(div of Reichhold
Chemicals Ltd)

1980 GRAHAMS LANE-A

SOURCE: VERNONS

— *CNR CROSSES*
L7S 1W4

1393 McGraw-Edison Limited
elect coil div
632-1171

— *LEGION RD BEGINS*
L7S 1W5

1451 Johnsen Machine
Company Ltd
632-2171

1380 Total Insulation Services Limited 639-5651
1392 P K Towing 632-6718
1400 Wicks' Auto Collision 634-1873
1416 Artic Traveler (Canada) Ltd 637-3468
1416 Sinclair-Smith Printing & Lithographing Co Ltd 639-3917
1448 Brant Car Wash Ltd 634-0155

****

LEGION ROAD West Side

L7S 1T5

828 Royal Canadian Legion Branch 60 639-6060

****

1980 STEPHENSON DRIVE

SOURCE: VERNONS

1360-1375 **STREET NOT LISTED**

1975 BRANT STREET

SOURCE: VERNONS

932 Aldershot Asphalt Contrs, pvg 637-6073

942 Hercules Canada Ltd, chem 634-2327

944 FMC of Canada Ltd (see 1274 Plains Rd e)

1975 GRAHAMS LANE-A

SOURCE: VERNONS

+ CNR CROSSES

1393 Matys Inds Ltd 639-1953

+ LEGION RD BEGINS

1451 Johnsen Mach Co Ltd 632-2171

1975 GRAHAMS LANE-B

SOURCE: VERNONS

+ CNR CROSSES

1380 Biller-Vansickle Co Ltd, htg & coml refrig 634-4397

1392 Dom Power Prs Equip Ltd, mfrs 634-5547

1400 City Automotive 632-1499


1400 P K Towing 632-6718

1416 Allied Arts Display Ltd 639-0581

1448 Brant Car Wash 637-3633

1975 LEGION ROAD

SOURCE: VERNONS



LEGION ROAD, West Side

828 Royal Can Legion Br 60
639-6060

1975 STEPHENSON DRIVE

SOURCE: VERNONS

1360-1375 **STREET NOT LISTED**

1970 BRANT STREET

SOURCE: VERNONS

940 Vacant
942 Hercules Canada Ltd, chem
634-2386
944 Niag Brand Chem (s e)

1970 GRAHAMS LANE-A

SOURCE: VERNONS

1345^ Schermer, Olaf
1345 Voskamp, J A

+ CNR CROSSES

1393 Francis Shaw (Can) Ltd,
machy 637-8231

+ LEGION RD BEGINS

+ CNR CROSSES

1380 Biller-Vansickle Co, htg & coml refrig 634-4397

1392 Dom Power Press Equip Ltd, mfrs 634-5547

1400 Burl Recreation Dept (Mntnce & Recvg Depot) 632-4347

1416 Standard Cap & Seal (Can) Ltd, dairy spls 634-7791

1416 Parkdale Mach & Tl Co, Ltd mach shop 637-0958

1488 Brant Car Wash 637-3633

LEGION ROAD, West Side

828 Royal Canadian Legion Br 60 637-1025

1970 STEPHENSON DRIVE

SOURCE: VERNONS

1360-1375 **STREET NOT LISTED**

1965 BRANT STREET

SOURCE: VERNONS

940 Tinning's Gro, 634-2122
942 Hercules Pwdr Co (Can) Ltd, 634-2386
944 Niag Brand Chemicals, 634-2355

1965 GRAHAMS LANE-A

SOURCE: VERNONS

1345 Vacant

+ CNR CROSSES

1393 Shaw, Francis (Can) Ltd, engs, 634-2350

+ LEGION RD BEGINS

1439 Frank Tl & Die Co Ltd, 634-7417

1965 GRAHAMS LANE-B

SOURCE: VERNONS

+ CNR CROSSES

1380 Biller-Vansickle Co, 634-4397

1392 Dom Power Press Equip Ltd, 634-5547

r1392 Leskew Furn & Upholstering, 634-6313

1400 Calad Co Ltd, The, decals, 634-5501

1416 Standard Cap & Seal (Can) Ltd, dairy supplies, 634-7791

1448 Brant Car Wash, 637-3633

1965 LEGION ROAD

SOURCE: VERNONS

LEGION RD, west side

828 Royal Canadian Legion Branch 60,
637-1025

****

1965 STEPHENSON DRIVE

SOURCE: VERNONS

1360-1375 **STREET NOT LISTED**

1960 BRANT STREET

SOURCE: VERNONS

940 Timming, Lionel, NE 4-2122

940 Timning, L & Son,
NE 4-3198

942 Hercules Pwdr Co (Can) Ltd,
NE 4-2386

944 Niag Brand Chemicals,
NE 4-2355

1960 GRAHAMS LANE-A

SOURCE: VERNONS

NE 4-6424

✚CNR CROSSES

1393 Shaw, Francis (Can) Ltd,
mach, NE 4-2350

✚LEGION RD BEGINS

1439 Frank, Tl & Die Co,
Ltd, NE 4-7417

1296 Te Brake, Henry
✚CNR CROSSES
1392 Dom Power Press Equip Ltd,
NE 4-5547
r1392 Burl Uphol & Cabt Shop,
NE 4-6313
1400 Calad Co Ltd, The, decals,
NE 4-1210

1416 Stand Cap & Seal (Can) Ltd
dairy supplies, NE 4-7791

1960 LEGION ROAD

SOURCE: VERNONS

LEGION RD, north from
Graham's la, 1 w Brant
828 Canadian Legion Branch 60,
NE 7-1025

1960 STEPHENSON DRIVE

SOURCE: VERNONS

1360-1375 **STREET NOT LISTED**

1957 BRANT STREET

SOURCE: VERNONS

942 **ADDRESS NOT LISTED**

1957 GRAHAMS LANE

SOURCE: VERNONS

1370-1425 **NO LISTINGS WITHIN RADIUS**

1957 LEGION ROAD

SOURCE: VERNONS

828-850 **STREET NOT LISTED**

1957 STEPHENSON DRIVE

SOURCE: VERNONS

1360-1375 **STREET NOT LISTED**

Appendix D
Ecolog ERIS Report

DATABASE REPORT

Project Property:	*1393 Grahams Lane* *1393 Grahams Lane* *Burlington ON L7S 1W4*
Project No:	*02211083.001*
Report Type:	*RSC Report (Urban)*
Order No:	*24011900269*
Requested by:	*EnGlobe Corp.*
Date Completed:	*January 22, 2024*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....7
Executive Summary: Site Report Summary - Surrounding Properties.....9
Executive Summary: Summary By Data Source.....48
Map.....96
Aerial.....97
Topographic Map.....98
Detail Report.....99
Unplottable Summary.....444
Unplottable Report.....446
Appendix: Database Descriptions.....457
Definitions.....467

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Limited Partnership ("ERIS") using various sources of information, including information provided by Federal and Provincial government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Limited Partnership. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:	*1393 Grahams Lane* *1393 Grahams Lane Burlington ON L7S 1W4*
Project No:	*02211083.001*

Order Information:

Order No:	*24011900269*
Date Requested:	*January 19, 2024*
Requested by:	*EnGlobe Corp.*
Report Type:	*RSC Report (Urban)*

Historical/Products:

City Directory Search	*Smart CD Search*
ERIS Xplorer	*ERIS Xplorer*
Insurance Products	*Fire Insurance Maps/Inspection Reports/Site Plans*
Topographic Map	*RSC Maps*

Executive Summary: Report Summary

Database	Name	Searched	Project Property	Boundary to 0.30km	Total
AAGR	Abandoned Aggregate Inventory	Y	0	0	0
AGR	Aggregate Inventory	Y	0	0	0
AMIS	Abandoned Mine Information System	Y	0	0	0
ANDR	Anderson's Waste Disposal Sites	Y	0	0	0
AST	Aboveground Storage Tanks	Y	0	0	0
AUWR	Automobile Wrecking & Supplies	Y	0	0	0
BORE	Borehole	Y	0	13	13
CA	Certificates of Approval	Y	0	23	23
CDRY	Dry Cleaning Facilities	Y	0	0	0
CFOT	Commercial Fuel Oil Tanks	Y	0	0	0
CHEM	Chemical Manufacturers and Distributors	Y	0	1	1
CHM	Chemical Register	Y	0	3	3
CNG	Compressed Natural Gas Stations	Y	0	0	0
COAL	Inventory of Coal Gasification Plants and Coal Tar Sites	Y	0	0	0
CONV	Compliance and Convictions	Y	0	0	0
CPU	Certificates of Property Use	Y	0	1	1
DRL	Drill Hole Database	Y	0	0	0
DTNK	Delisted Fuel Tanks	Y	0	43	43
EASR	Environmental Activity and Sector Registry	Y	0	1	1
EBR	Environmental Registry	Y	0	7	7
ECA	Environmental Compliance Approval	Y	0	17	17
EEM	Environmental Effects Monitoring	Y	0	0	0
EHS	ERIS Historical Searches	Y	5	69	74
EIIS	Environmental Issues Inventory System	Y	0	0	0
EMHE	Emergency Management Historical Event	Y	0	0	0
EPAR	Environmental Penalty Annual Report	Y	0	0	0
EXP	List of Expired Fuels Safety Facilities	Y	0	15	15
FCON	Federal Convictions	Y	0	0	0
FCS	Contaminated Sites on Federal Land	Y	0	0	0
FOFT	Fisheries & Oceans Fuel Tanks	Y	0	0	0
FRST	Federal Identification Registry for Storage Tank Systems (FIRSTS)	Y	0	0	0
FST	Fuel Storage Tank	Y	0	0	0
FSTH	Fuel Storage Tank - Historic	Y	0	0	0
GEN	Ontario Regulation 347 Waste Generators Summary	Y	5	163	168
GHG	Greenhouse Gas Emissions from Large Facilities	Y	0	0	0
HINC	TSSA Historic Incidents	Y	0	0	0

Database	Name	Searched	Project Property	Boundary to 0.30km	Total
IAFT	Indian & Northern Affairs Fuel Tanks	Y	0	0	0
INC	Fuel Oil Spills and Leaks	Y	0	0	0
LIMO	Landfill Inventory Management Ontario	Y	0	0	0
MINE	Canadian Mine Locations	Y	0	0	0
MNR	Mineral Occurrences	Y	0	0	0
NATE	National Analysis of Trends in Emergencies System (NATES)	Y	0	1	1
NCPL	Non-Compliance Reports	Y	0	0	0
NDFT	National Defense & Canadian Forces Fuel Tanks	Y	0	0	0
NDSP	National Defense & Canadian Forces Spills	Y	0	0	0
NDWD	National Defence & Canadian Forces Waste Disposal Sites	Y	0	0	0
NEBI	National Energy Board Pipeline Incidents	Y	0	0	0
NEBP	National Energy Board Wells	Y	0	0	0
NEES	National Environmental Emergencies System (NEES)	Y	0	7	7
NPCB	National PCB Inventory	Y	0	0	0
NPR2	National Pollutant Release Inventory 1993-2020	Y	0	3	3
NPRI	National Pollutant Release Inventory - Historic	Y	0	0	0
OGWE	Oil and Gas Wells	Y	0	0	0
OOGW	Ontario Oil and Gas Wells	Y	0	0	0
OPCB	Inventory of PCB Storage Sites	Y	0	0	0
ORD	Orders	Y	0	0	0
PAP	Canadian Pulp and Paper	Y	0	0	0
PCFT	Parks Canada Fuel Storage Tanks	Y	0	0	0
PES	Pesticide Register	Y	0	6	6
PFCH	NPRI Reporters - PFAS Substances	Y	0	0	0
PFHA	Potential PFAS Handers from NPRI	Y	0	0	0
PINC	Pipeline Incidents	Y	0	0	0
PRT	Private and Retail Fuel Storage Tanks	Y	0	6	6
PTTW	Permit to Take Water	Y	0	0	0
REC	Ontario Regulation 347 Waste Receivers Summary	Y	0	0	0
RSC	Record of Site Condition	Y	0	1	1
RST	Retail Fuel Storage Tanks	Y	0	6	6
SCT	Scott's Manufacturing Directory	Y	3	33	36
SPL	Ontario Spills	Y	0	38	38
SRDS	Wastewater Discharger Registration Database	Y	0	0	0
TANK	Anderson's Storage Tanks	Y	0	0	0
TCFT	Transport Canada Fuel Storage Tanks	Y	0	0	0
VAR	Variances for Abandonment of Underground Storage Tanks	Y	0	0	0
WDS	Waste Disposal Sites - MOE CA Inventory	Y	0	0	0
WDSH	Waste Disposal Sites - MOE 1991 Historical Approval Inventory	Y	0	0	0
WWIS	Water Well Information System	Y	0	35	35

Database	Name	Searched	Project Property	Boundary to 0.30km	Total
Total:			13	492	505

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
1	SCT	WALKER MAGNETICS NATIONAL LTD.	1393 GRAHAMS LANE BURLINGTON ON L7S 1W4	ESE/0.0	0.00	99
1	SCT	UNITED STATES ALUMINUM OF CDA	1393 Grahams Lane Burlington ON L7S 1W4	ESE/0.0	0.00	99
1	SCT	United States Aluminum of Canada-Ontario Ltd.	1393 Grahams Lane Burlington ON L7S 1W4	ESE/0.0	0.00	99
1	GEN	MCGRAW EDISON	NAT. ELECT. COIL 1393 GRAHAM'S LANE BURLINGTON ON L7S 1W4	ESE/0.0	0.00	99
1	GEN	MCGRAW (SEE&USE ON1234100)	NAT. ELECT. COIL 1393 GRAHAM'S LANE BURLINGTON ON L7S 1W4	ESE/0.0	0.00	100
1	GEN	MCGRAW (SEE&USE ON1234100) 26-115	NAT. ELECT. COIL 1393 GRAHAM'S LANE BURLINGTON ON L7S 1W4	ESE/0.0	0.00	100
1	GEN	WALKER MAGNETICS NATIONAL LTD.	1393 GRAHAMS LANE BURLINGTON ON L7S 1W4	ESE/0.0	0.00	100
1	GEN	WALKER MAGNETICS NATIONAL LTD. 26-115	1393 GRAHAMS LANE BURLINGTON ON L7S 1W4	ESE/0.0	0.00	101

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
1	EHS		1393 Grahams Lane Burlington ON L7S 1W4	ESE/0.0	0.00	101
1	EHS		1393 Grahams Lane Burlington ON L7S 1W4	ESE/0.0	0.00	102
1	EHS		1393 Grahams Lane Burlington ON L7S 1W4	ESE/0.0	0.00	102
1	EHS		1393 Grahams Lane Burlington ON L7S 1W4	ESE/0.0	0.00	102
2	EHS		1393 Grahams Lane Burlington ON L7S 1W4	ESE/0.0	0.00	102

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
3	WWIS		1416 GRAHAM LN Burlington ON ***Well ID:*** 7314898	E/7.7	-0.52	103
4	WWIS		1380 GRAHAM'S LANE Burlington ON ***Well ID:*** 7179514	SE/23.7	0.00	106
5	WWIS		1380 GRAHAM'S LANE Burlington ON ***Well ID:*** 7179515	SSE/25.2	0.00	109
6	WWIS		ON ***Well ID:*** 7291911	SSE/30.5	0.00	113
7	BORE		ON	WNW/33.1	-0.49	114
8	EBR	Smit Autobody	1400 Graham's Lane Burlington Ontario L7S 1W3 Burlington ON	ESE/33.5	-0.68	115
8	CA	Smit Autobody	1400 Graham's Lane Burlington ON	ESE/33.5	-0.68	115
8	ECA	Smit Autobody	1400 Graham's Lane Burlington ON L7S 1W3	ESE/33.5	-0.68	116
9	SCT	National Specialty Cakes Inc.	1423 Grahams Lane Burlington ON L7S 1W4	ENE/34.8	-0.19	116
9	SCT	NSC Cakes Inc.	1423 Grahams Lane Burlington ON L7S 1W4	ENE/34.8	-0.19	116
10	PRT	JOHN EBOS FUELS LTD	1380 GRAHAMS LA BURLINGTON ON L7S 1W3	SE/40.0	0.00	116
10	PRT	PETRO CANADA PRODUCTS C/O BURLINGTON BULK PLANT J	1380 GRAHAMS LA BURLINGTON ON L7S1W3	SE/40.0	0.00	117

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
10	RST	EBOS JOHN FUELS LTD	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	SE/40.0	0.00	117
10	RST	EBOS JOHN FUELS A DIV OF PETRO PARTNERS LTD	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	SE/40.0	0.00	117
10	GEN	PETRO-CANADA PRODUCTS	1380 GRAHAM'S LANE BURLINGTON C/O 5140 YONGE STREET SUITE 200 NORTH YORK ON L7S 1W3	SE/40.0	0.00	117
10	GEN	PETRO-CANADA PRODUCTS	1380 GRAHAM'S LANE BURLINGTON ON L7S 1W3	SE/40.0	0.00	118
10	GEN	PETRO-CANADA PRODUCTS 30-464	1380 GRAHAM'S LANE BURLINGTON C/O 5140 YONGE STREET SUITE 200 NORTH YORK ON L7S 1W3	SE/40.0	0.00	118
10	GEN	JOHN EBOS FUELS LIMITED 22-460	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	SE/40.0	0.00	118
10	GEN	JOHN EBOS FUELS LIMITED	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	SE/40.0	0.00	119
10	GEN	JOHN EBOS FUELS, A DIVISION OF PETRO PARTNERS LTD.	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	119
10	GEN	Petro-Canada Retail Development Centres (Central)	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	SE/40.0	0.00	120
10	RST	JOHN EBOS FUELS	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	SE/40.0	0.00	120
10	SPL	John Ebos Fuels Limited	1380 Grahams Lane Burlington ON L7S 1W3	SE/40.0	0.00	121
10	GEN	Petro Canada	1380 Grahams Lane Burlington ON L7S 1W3	SE/40.0	0.00	121

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
10	DTNK	FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	122
10	DTNK	PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	122
10	DTNK	FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	123
10	DTNK	FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	124
10	DTNK	FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	124
10	DTNK	FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	125
10	DTNK	PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	125
10	DTNK	FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	126
10	DTNK	FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	127
10	DTNK	FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	127
10	DTNK	FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	128
10	DTNK	FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	128
10	DTNK	FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	129

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
10	DTNK	FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	130
10	DTNK	FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	130
10	DTNK	FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	131
10	DTNK	FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	131
10	DTNK	FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	132
10	DTNK	PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	133
10	DTNK	PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	133
10	DTNK	PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	134
10	DTNK	PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	134
10	DTNK	PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	135
10	DTNK	PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	136
10	DTNK	PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	136

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
10	DTNK	PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	137
10	DTNK	FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	138
10	GEN	Petro-Canada Retail Development Centres (Central)	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	SE/40.0	0.00	138
10	WWIS		1380 GRAHAM'S LANE Burlington ON ***Well ID:*** 7179516	SE/40.0	0.00	139
10	GEN	Petro-Canada Retail Development Centres (Central)	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	SE/40.0	0.00	142
10	GEN	Petro-Canada Retail Development Centres (Central)	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	SE/40.0	0.00	143
10	GEN	Suncor Energy	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	SE/40.0	0.00	143
10	RST	LIPPERT & WRIGHT FUELS	1380 GRAHAMS LANE BURLINGTON ON L7S1W3	SE/40.0	0.00	144
10	GEN	Suncor Energy	1380 GRAHAMS LANE BURLINGTON ON	SE/40.0	0.00	144
10	RST	FREW ENERGY	1380 GRAHAMS LANE BURLINGTON ON L7S1W3	SE/40.0	0.00	144
10	GEN	Suncor Energy	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	SE/40.0	0.00	145
10	GEN	Suncor Energy	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	SE/40.0	0.00	145
10	GEN	Suncor Energy	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	SE/40.0	0.00	146

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
10	GEN	Suncor Energy	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	SE/40.0	0.00	146
10	RST	FREW ENERGY	1380 GRAHAMS LANE BURLINGTON ON L7S1W3	SE/40.0	0.00	147
10	GEN	Suncor Energy	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	SE/40.0	0.00	147
10	GEN	Suncor Energy	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	SE/40.0	0.00	147
10	GEN	Suncor Energy Products Partnership	1380 Grahams Lane Burlington ON L7S 1W3	SE/40.0	0.00	148
10	GEN	Suncor Energy	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	SE/40.0	0.00	148
10	GEN	Suncor Energy Products Partnership	1380 Grahams Lane Burlington ON L7S 1W3	SE/40.0	0.00	149
11	WWIS		1380 GRAHAM'S LANE Burlington ON ***Well ID:*** 7179605	SE/41.4	0.00	149
12	EHS		1416 Grahams Lane Burlington ON L7S 1W3	E/60.6	-1.00	153
12	EHS		1416 Grahams Lane Burlington ON L7S 1W3	E/60.6	-1.00	153
12	EHS		1416 Grahams Lane Burlington ON L7S 1W3	E/60.6	-1.00	153
12	EHS		1416 Grahams Lane Burlington ON L7S 1W3	E/60.6	-1.00	153
13	EHS		828 Legion Road Burlington ON L7S 1T5	NNE/64.7	0.00	153

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
14	GEN	BURLINGTON HYDRO-ELEC. COMMISSION	1370 GRAHAMS LANE C/O 1340 BRANT ST. BURLINGTON ON L7R 3Z7	S/68.2	0.00	154
14	GEN	BURLINGTON HYDRO-ELEC. COMMISSION 05-334	1370 GRAHAMS LANE C/O 1340 BRANT ST. BURLINGTON ON L7R 3Z7	S/68.2	0.00	154
15	SCT	Arctic Traveler (Canada) Ltd.	1416 Grahams Lane Burlington ON L7S 1W3	E/71.3	-1.00	154
15	GEN	SINCLAIR-SMITH PRINTING &	LITHOGRAPHING CO. LTD., THE 1416 GRAHAMS LANE BURLINGTON ON L7S 1W3	E/71.3	-1.00	155
15	GEN	SINCLAIR-SMITH PRINTING & 35-086	LITHOGRAPHING CO. LTD., THE 1416 GRAHAMS LANE BURLINGTON ON L7S 1W3	E/71.3	-1.00	155
15	EHS		1416 Grahams Ln Burlington ON L7S 1W3	E/71.3	-1.00	155
16	WWIS		1380 GRAHAM'S LANE BURLINGTON ON ***Well ID:*** 2810308	SSE/74.5	-0.24	156
17	SPL	HERCULES CANADA INC.	850 LEGION RD/SOUTH OF FAIRVIEW AVE. BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7S 1T5	N/78.7	0.00	159
17	SCT	TECKMARK LABEL SYSTEMS INC.	850 LEGION RD UNIT 23 BURLINGTON ON L7S 1T5	N/78.7	0.00	160
17	SCT	K L B INTERIORS INC	850 LEGION RD UNIT 5 BURLINGTON ON L7S 1T5	N/78.7	0.00	160
17	SCT	Artisan Design	850 Legion Rd Unit 1-3 Burlington ON L7S 1T5	N/78.7	0.00	161
17	SCT	MERIDIAN GOLF (2000) INC.	850 LEGION RD UNIT 14 BURLINGTON ON L7S 1T5	N/78.7	0.00	161
17	SCT	HIBON INC.	850 LEGION RD UNIT 3 BURLINGTON ON L7S 1T5	N/78.7	0.00	161

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
17	SCT	WOODCRAFT RAIL INC.	850 Legion Rd Unit 15 Burlington ON L7S 1T5	N/78.7	0.00	161
17	SCT	KLB Interiors Inc.	850 Legion Rd Unit 5 Burlington ON L7S 1T5	N/78.7	0.00	162
17	SCT	Teckmark Label Systems Inc.	850 Legion Rd Unit 23 Burlington ON L7S 1T5	N/78.7	0.00	162
17	SCT	B-LINE CRESTING	850 Legion Rd Unit 7 Burlington ON L7S 1T5	N/78.7	0.00	162
17	GEN	WENTWORTH ELECTRONICS	850 LEGION ROAD, UNIT #7 BURLINGTON ON L7S 1T5	N/78.7	0.00	163
17	GEN	WENTWORTH OUT OF BUSINESS 41-236	850 LEGION ROAD, UNIT #7 BURLINGTON ON L7S 1T5	N/78.7	0.00	163
17	GEN	TECKMARK LABEL SYSTEMS INC.	850 - #23 LEGION ROAD BURLINGTON ON L7S 1T5	N/78.7	0.00	164
17	GEN	TECKMARK LABEL SYSTEMS INC. 37-552	850 - #23 LEGION ROAD BURLINGTON ON L7S 1T5	N/78.7	0.00	164
17	GEN	TECKMARK LABEL SYSTEMS INC.	850 - #23 LEGION ROAD BURLINGTON ON L7S 1T5	N/78.7	0.00	164
17	GEN	ARTISAN DESIGN	850 LEGION ROAD UNIT #1 BURLINGTON ON L7S 1T5	N/78.7	0.00	165
17	GEN	B-LINE CRESTING, DIVISION OF	850 LEGION ROAD, UNIT #7 BURLINGTON ON L7S 1T5	N/78.7	0.00	165
17	GEN	GOLDEN HORSESHOE SERVICES	850 LEGION ROAD, #17 BURLINGTON ON L7S 1T5	N/78.7	0.00	165
17	GEN	GOLDEN HORSESHOE SERVICES	850 LEGION ROAD, #17 BURLINGTON ON L7S 1T5	N/78.7	0.00	166

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
17	GEN	ARTISAN DESIGN	850 LEGION ROAD, UNIT 1 BURLINGTON ON L7S 1T5	N/78.7	0.00	166
17	GEN	B-LINE CRESTING	850 LEGION ROAD, UNIT 7 BURLINGTON ON L7S 1T5	N/78.7	0.00	167
17	GEN	GOLDEN HORSESHOE SERVICES	850 LEGION ROAD, UNIT 17 BURLINGTON ON L7S 1T5	N/78.7	0.00	167
17	SCT	Rea/Co Inc.	850 Legion Rd Unit 18 Burlington ON L7S 1T5	N/78.7	0.00	167
17	GEN	The Maples Animal Hospital	850 Legion Road Unit 21 Burlington ON L7S 1T5	N/78.7	0.00	168
17	GEN	TECKMARK LABEL SYSTEMS INC.	850 - #23 LEGION ROAD BURLINGTON ON L7S 1T5	N/78.7	0.00	168
17	SCT	Fry Graphics Ltd.	850 Legion Rd Unit 6 Burlington ON L7S 1T5	N/78.7	0.00	168
17	SCT	Burlington Letterpress	850 Legion Rd Unit 11 Burlington ON L7S 1T5	N/78.7	0.00	168
17	PES	MCCONNELL-SPADAFORA INC	850 LEGION RD, UNIT #4 BURLINGTON ON L7S 1T5	N/78.7	0.00	169
17	GEN	Techmark Label Systems Inc.	850 Legion Unit 23 Burlington ON L7S 1T5	N/78.7	0.00	169
17	SCT	McConnell-Spadafora Inc.	850 Legion Rd Unit 4 Burlington ON L7S 1T5	N/78.7	0.00	169
17	SCT	Multi-Line Products Inc.	850 Legion Rd Unit 9 Burlington ON L7S 1T5	N/78.7	0.00	170
17	GEN	The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON L7S 1T5	N/78.7	0.00	170

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
17	GEN	Historia Building Restoration Inc.	850 Legion Road Unit 19A Burlington ON	N/78.7	0.00	171
17	PES	MCCONNELL-SPADAFORA INC	850 LEGION RD, UNIT 4 BURLINGTON ON L7S 1T5	N/78.7	0.00	171
17	GEN	The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON L7S 1T5	N/78.7	0.00	171
17	GEN	Historia Building Restoration Inc.	850 Legion Road Unit 19A Burlington ON L7S 1T5	N/78.7	0.00	172
17	GEN	The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON L7S 1T5	N/78.7	0.00	172
17	PES	MCCONNELL-SPADAFORA INC	850 LEGION RD, UNIT 4 BURLINGTON ON L7S1T5	N/78.7	0.00	172
17	GEN	Historia Building Restoration Inc.	850 Legion Road Unit 19A Burlington ON L7S 1T5	N/78.7	0.00	173
17	GEN	The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON L7S 1T5	N/78.7	0.00	173
17	GEN	The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON	N/78.7	0.00	173
17	GEN	The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON L7S 1T5	N/78.7	0.00	174
17	GEN	The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON L7S 1T5	N/78.7	0.00	174
17	GEN	The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON L7S 1T5	N/78.7	0.00	175
17	GEN	The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON L7S 1T5	N/78.7	0.00	175

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
17	GEN	The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON L7S 1T5	N/78.7	0.00	176
17	GEN	SOAR Veterinary Professional Corporation	850 Legion Rd Unit 5 Burlington ON L7S 1T5	N/78.7	0.00	176
17	GEN	SOAR Veterinary Professional Corporation	850 Legion Rd Unit 5 Burlington ON L7S 1T5	N/78.7	0.00	176
17	GEN	The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON L7S 1T5	N/78.7	0.00	177
17	GEN	SOAR Veterinary Professional Corporation	850 Legion Rd Unit 5 Burlington ON L7S 1T5	N/78.7	0.00	177
17	GEN	The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON L7S 1T5	N/78.7	0.00	178
17	GEN	Carl's Grinding Service	850 Legion Road #8 Burlington ON L7S 1T5	N/78.7	0.00	178
18	BORE		ON	NE/86.2	0.00	178
19	WWIS		BURLINGTON ON ***Well ID:*** 2810214	S/87.4	-0.03	180
20	CA	ETRATECH DESIGNS INC.	1440 GRAHAMS LANE, UNIT #5 BURLINGTON CITY ON L7S 1W3	E/88.7	-2.00	182
20	SCT	THYSSEN DOVER ELEVATORS	1440 GRAHAMS LANE UNIT 3 BURLINGTON ON L7S 1W3	E/88.7	-2.00	182
20	SCT	BURLINGTON LAMINATING & BINDER	1440 GRAHAMS LANE UNIT 2 BURLINGTON ON L7S 1W3	E/88.7	-2.00	183
20	SCT	Peters Steel Rule Dies	1440 Grahams Lane Unit 6-7 Burlington ON L7S 1W3	E/88.7	-2.00	183

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
20	SCT	ENDRESS + HAUSER CANADA LTD	1440 GRAHAMS LANE UNIT 1 BURLINGTON ON L7S 1W3	E/88.7	-2.00	183
20	SCT	DOVER CORPORATION CANADA LTD	1440 GRAHAMS LANE UNIT 3 BURLINGTON ON L7S 1W3	E/88.7	-2.00	183
20	EBR	Ontario Testing Labs Inc.	1440 GRAHAM'S LANE, UNIT #9, BURLINGTON CITY CITY OF BURLINGTON ON	E/88.7	-2.00	184
20	SCT	Endress + Hauser Canada Ltd.	1440 Grahams Lane Unit 1 Burlington ON L7S 1W3	E/88.7	-2.00	184
20	SCT	Thyssen Krupp Elevator Limited	1440 Grahams Lane Unit 3 Burlington ON L7S 1W3	E/88.7	-2.00	184
20	GEN	DOVER CORPORATION (CANADA) LIMITED12-701	1440 GRAHAM'S LANE, UNIT #3 BURLINGTON ON L7S 1W3	E/88.7	-2.00	185
20	GEN	DOVER CORPORATION (CANADA) LIMITED	1440 GRAHAM'S LANE UNIT 3 BURLINGTON ON L7S 1W3	E/88.7	-2.00	185
20	GEN	THYSSEN DOVER ELEVATOR	1440 GRAHAM'S LANE UNIT 3 BURLINGTON ON L7S 1W3	E/88.7	-2.00	185
20	GEN	THYSSEN KRUPP ELEVATOR	1440 GRAHAM'S LANE UNIT 3 BURLINGTON ON L7S 1W3	E/88.7	-2.00	186
20	GEN	BCT BUSINESS (OUT OF BUSINESS) 05-745	1440 GRAHAM'S LANE, UNIT #8 BURLINGTON ON L7S 1W3	E/88.7	-2.00	186
20	GEN	ETRATECH MAN(OUT OF BUSINESS) 49-115	1440 GRAHAMS LANE UNIT 6 BURLINGTON ON L7S 1W3	E/88.7	-2.00	186
20	GEN	ASH TEMPLE LTD.	1440 GRAHAM'S LANE, SUITE 5 BURLINGTON ON L7S 1W3	E/88.7	-2.00	187

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
20	GEN	ONTARIO TESTING LABS	1440 GRAHAMS LANE BURLINGTON ON L7S 1W3	E/88.7	-2.00	187
20	GEN	ASH TEMPLE LTD.	1440 GRAHAM'S LANE SUITE 5 BURLINGTON ON L7S 1W3	E/88.7	-2.00	188
20	GEN	BODYCOTE GALT MATERIALS TESTING LTD.	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	E/88.7	-2.00	188
20	GEN	Bodycote Materials Testing Canada Inc.	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	E/88.7	-2.00	188
20	SCT	Magnus Chemicals Ltd.	1440 Grahams Lane Unit 5 Burlington ON L7S 1W3	E/88.7	-2.00	189
20	SCT	Pyramid Pumps	1440 Grahams Lane Unit 3 Burlington ON L7S 1W3	E/88.7	-2.00	189
20	SCT	Scherzinger Pump Technology Inc.	1440 Grahams Lane Unit 3 Burlington ON L7S 1W3	E/88.7	-2.00	190
20	SCT	Peters Steel Rule Dies Ltd.	1440 Grahams Lane Unit 6-7 Burlington ON L7S 1W3	E/88.7	-2.00	190
20	SCT	Scherzinger Pump Technology	1440 Grahams Lane Unit 3 Burlington ON L7S 1W3	E/88.7	-2.00	190
20	EHS		1440 Graham's Lane, Unit #9 Burlington ON L7S 1W3	E/88.7	-2.00	190
20	GEN	Bodycote Testing Group	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	E/88.7	-2.00	190
20	GEN	Exova	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	E/88.7	-2.00	191
20	GEN	Exova	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	E/88.7	-2.00	191

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
20	GEN	Exova	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	E/88.7	-2.00	192
20	GEN	Exova	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	E/88.7	-2.00	192
20	GEN	Exova	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON	E/88.7	-2.00	193
20	EHS		1440 Grahams Lane Unit 2 Burlington ON	E/88.7	-2.00	193
20	GEN	Exova	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	E/88.7	-2.00	194
20	GEN	Exova	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	E/88.7	-2.00	194
20	GEN	Exova	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	E/88.7	-2.00	195
20	GEN	Exova Burlington	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	E/88.7	-2.00	195
20	GEN	Exova Burlington	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	E/88.7	-2.00	196
20	GEN	Exova Burlington	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	E/88.7	-2.00	197
21	WWIS		1380 GRAHAM'S LANE BURLINGTON ON ***Well ID:*** 2810171	SSE/89.8	-0.83	198
22	EHS		850 Legion Road Burlington ON L7S 1T6	N/90.5	0.00	201
22	EHS		850 Legion Road Burlington ON L7S 1T6	N/90.5	0.00	201

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
22	EHS		850 Legion Road Burlington ON L7S 1T6	N/90.5	0.00	201
22	EHS		850 Legion Road Burlington ON L7S 1T6	N/90.5	0.00	202
23	GEN	Hydro One Networks Inc.	1355 Stephenson Dr. Burlington ON L7S 2M5	SW/91.0	0.00	202
24	WWIS		802 Hagar Ave Burlington ON ***Well ID:*** 7354371	SSE/95.5	-1.00	202
25	WWIS		802 Hager Ave Burlington ON ***Well ID:*** 7354375	SE/110.8	-1.00	204
26	WWIS		439 Graham's Lane Burlington ON ***Well ID:*** 7343297	ENE/112.6	-1.00	206
27	WWIS		850 Brant Street Burlington ON ***Well ID:*** 7330856	NNE/116.9	0.00	210
28	EHS		1439 Grahams Lane Burlington ON L7S 1W5	ENE/119.1	-1.00	213
29	GEN	Burlington Hydro Inc.	1439 Grahams Lane Burlington ON L7S 1W4	ENE/119.1	-1.00	213
29	EHS		1439 Grahams Lane Burlington ON L7S 1W5	ENE/119.1	-1.00	213
29	EHS		1439 Grahams Lane Burlington ON L7S 1W5	ENE/119.1	-1.00	214
29	EHS		1439 Grahams Lane Burlington ON L7S 1W5	ENE/119.1	-1.00	214
29	EHS		1439 Grahams Lane Burlington ON L7S 1W5	ENE/119.1	-1.00	214

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
29	EHS		1439 Grahams Lane Burlington ON L7S 1W5	ENE/119.1	-1.00	214
30	GEN	BURLINGTON ASS. FOR COMMUNITY	LIVING 831 LEGION ROAD BURLINGTON ON L7S 1T6	NE/119.4	-0.90	214
30	GEN	BURLINGTON ASS. FOR COMMUNITY 05-519	LIVING 831 LEGION ROAD BURLINGTON ON L7S 1T6	NE/119.4	-0.90	215
30	EHS		831 Legion Rd Burlington On Burlington ON L7S1T6	NE/119.4	-0.90	215
31	BORE		ON	WNW/123.9	5.44	215
32	EHS		802 Hager Avenue Burlington ON L7S	SE/128.0	-1.00	217
32	EHS		802 Hager Avenue Burlington ON L7S	SE/128.0	-1.00	217
32	EHS		802 Hager Avenue Burlington ON L7S	SE/128.0	-1.00	217
32	EHS		802 Hager Avenue Burlington ON L7S	SE/128.0	-1.00	217
33	BORE		ON	N/128.4	-1.14	218
34	WWIS		1439 Graham's Lane Burlington ON ***Well ID:*** 7343299	ENE/128.8	-1.00	219
35	EHS		802 Hager Avenue Burlington ON L7S 1X2	SE/128.9	-1.00	223
35	EHS		802 Hager Avenue Burlington ON L7S 1X2	SE/128.9	-1.00	223

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
35	GEN	Wellington Park Care Centre	802 Hagar Avenue Burlington ON L7S 1X2	SE/128.9	-1.00	223
35	GEN	Wellington Park Care Centre	802 Hagar Avenue Burlington ON L7S 1X2	SE/128.9	-1.00	223
35	CPU	Wellington Park Care Centre Facility Inc.	802 Hager Avenue CITY OF BURLINGTON ON	SE/128.9	-1.00	224
35	GEN	Wellington Park Care Centre	802 Hagar Avenue Burlington ON	SE/128.9	-1.00	224
35	EHS		802 Hager Ave Burlington ON L7S1X2	SE/128.9	-1.00	224
35	GEN	Responsive Management Inc	802 Hager Avenue Burlington ON L7S1X2	SE/128.9	-1.00	225
35	GEN	Wellington Park Care Centre	802 Hagar Avenue Burlington ON L7S 1X2	SE/128.9	-1.00	225
35	GEN	Wellington Park Care Centre	802 Hagar Avenue Burlington ON L7S 1X2	SE/128.9	-1.00	225
35	GEN	Suncor Energy Products	802 Hager Ave, Burlington ON L7S 1X2	SE/128.9	-1.00	226
35	EHS		802 Hager Avenue Burlington ON	SE/128.9	-1.00	226
35	GEN	Suncor Energy Products	802 Hager Ave, Burlington ON L7S 1X2	SE/128.9	-1.00	226
35	RSC	WELLINGTON PARK CARE CENTRE FACILITY INC.	802 HAGER AVENUE, BURLINGTON, ON L7S 1X2 Burlington ON	SE/128.9	-1.00	227
35	GEN	Suncor Energy Products	802 Hager Ave, Burlington ON L7S 1X2	SE/128.9	-1.00	228

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
35	GEN	Suncor Energy Products	802 Hager Ave, Burlington ON L7S 1X2	SE/128.9	-1.00	228
36	BORE		ON	NE/131.5	-0.97	229
37	WWIS		439 Graham's Lane Burlington ON ***Well ID:*** 7343298	ENE/131.6	-1.41	231
38	BORE		ON	NE/137.1	-1.00	234
39	EHS		Highway 403 (QEW) Burlington Burlington ON	N/144.8	-0.43	236
40	PRT	845275 ONTARIO INC	1448 GRAHAMS LA BURLINGTON ON L7S1W3	ENE/147.9	-2.00	236
40	DTNK	578122 ONTARIO INC	1448 GRAHAMS LA BURLINGTON ON	ENE/147.9	-2.00	236
40	DTNK	578122 ONTARIO INC	1448 GRAHAMS LA BURLINGTON ON	ENE/147.9	-2.00	237
40	DTNK	578122 ONTARIO INC	1448 GRAHAMS LA BURLINGTON ON	ENE/147.9	-2.00	238
40	DTNK	578122 ONTARIO INC	1448 GRAHAMS LA BURLINGTON ON	ENE/147.9	-2.00	238
40	EXP	578122 ONTARIO INC	1448 GRAHAMS LANE BURLINGTON ON	ENE/147.9	-2.00	239
40	EXP	578122 ONTARIO INC	1448 GRAHAMS LANE BURLINGTON ON	ENE/147.9	-2.00	239
40	EXP	578122 ONTARIO INC	1448 GRAHAMS LANE BURLINGTON ON	ENE/147.9	-2.00	239

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
41	WWIS		802 HAGER AVE BURLINGTON ON ***Well ID:*** 7042731	ESE/155.9	-1.55	240
42	WWIS		770 HAGGAR AV E Burlington ON ***Well ID:*** 7284939	SE/163.4	-1.00	243
43	WWIS		770 HAGGER AVE Burlington ON ***Well ID:*** 7284940	SE/163.6	-1.10	246
44	WWIS		850 BRANT ST Burlington ON ***Well ID:*** 7330855	NE/163.8	-0.42	249
45	WWIS		850 Brant Street Burlington ON ***Well ID:*** 7330854	NNE/164.8	0.00	252
46	WWIS		850 Brant St Burlington ON ***Well ID:*** 7330859	NNE/164.8	0.00	255
47	BORE		ON	WSW/167.5	-0.80	259
48	EHS		850 Brant Street Burlington ON L7R 2J5	NNE/172.5	0.00	260
48	GEN	Discovery Ford	850 Brant Street Burlington ON L7R 2J5	NNE/172.5	0.00	260
49	PES	PETS & GARDENS LTD	834 BRANT ST BURLINGTON ON L7R 2J5	NE/175.8	-1.00	261
49	PES	PETS & GARDENS LTD	834 BRANT ST BURLINGTON ON L7R2J5	NE/175.8	-1.00	261
50	WWIS		ON ***Well ID:*** 7387995	ENE/183.9	-2.34	261
51	SPL	HARMAC TRANSPORTATION	808 BRANT ST. TANK TRUCK (CARGO) BURLINGTON CITY ON	ENE/184.3	-2.00	262

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
52	EHS		780 Brant Street Burlington ON L7R 2J2	E/191.0	-3.00	263
53	EHS		796 Brant Street Burlington ON L7R 2J2	ENE/193.3	-2.00	263
53	EHS		796 Brant Street Burlington ON L7R 2J2	ENE/193.3	-2.00	263
53	EHS		796 Brant Street Burlington ON L7R 2J2	ENE/193.3	-2.00	264
53	EHS		796 Brant Street Burlington ON L7R 2J2	ENE/193.3	-2.00	264
54	WWIS		ON ***Well ID:*** 7369395	E/194.8	-3.00	264
55	WWIS		1380 GRAHAMS LANE BURLINGTON ON ***Well ID:*** 7047125	SSW/197.4	-1.00	265
56	EHS		QEW and 403 Burlington ON	SSW/198.0	-1.00	268
56	EHS		QEW and 403 Burlington ON	SSW/198.0	-1.00	268
56	EHS		QEW and 403 Burlington ON	SSW/198.0	-1.00	268
57	WWIS		850 Brant Street Burlington ON ***Well ID:*** 7330858	NNE/201.2	0.00	269
58	WWIS		ON ***Well ID:*** 7387994	ENE/208.8	-2.00	272
59	EHS		942 Brant Street Burlington ON L7R 2J7	WNW/220.3	2.92	273

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
59	EHS		942 Brant Street Burlington ON L7R 2J7	WNW/220.3	2.92	273
59	EHS		942 Brant Street Burlington ON L7R 2J7	WNW/220.3	2.92	273
59	EHS		942 Brant Street Burlington ON L7R 2J7	WNW/220.3	2.92	273
60	WWIS		ON ***Well ID:*** 7387993	ENE/220.9	-3.00	273
61	NPR2	BURLINGTON PLANT SITE	942 BRANT STREET BURLINGTON ON L7R2J7	WNW/222.3	4.67	274
61	NPR2	BURLINGTON PLANT	942 BRANT STREET BURLINGTON ON L7R3X8	WNW/222.3	4.67	282
61	NPR2	BURLINGTON PLANT	942 BRANT ST., 942 BRANT STREET BURLINGTON ON	WNW/222.3	4.67	287
62	WWIS		280 BRANT ST Burlington ON ***Well ID:*** 7331850	ENE/222.5	-3.00	310
63	EHS		Former CNR Land Burlington ON L7S	SSE/222.9	-2.00	313
64	CA	HERCULES CANADA INC.	942 BRANT STREET BURLINGTON CITY ON L7R 2J7	NW/223.3	5.00	313
64	CA	HERCULES CANADA INC.	942 BRANT STREET BURLINGTON CITY ON L7R 2J7	NW/223.3	5.00	313
64	CA	HERCULES CANADA INC.	942 BRANT STREET BURLINGTON CITY ON L7R 2J7	NW/223.3	5.00	314
64	CA	HERCULES CANADA INC.	942 BRANT STREET BURLINGTON CITY ON L7R 2J7	NW/223.3	5.00	314

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
64	SPL	HERCULES CANADA INC.	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	NW/223.3	5.00	314
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	NW/223.3	5.00	315
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	NW/223.3	5.00	316
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	NW/223.3	5.00	317
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	NW/223.3	5.00	318
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	NW/223.3	5.00	318
64	SPL	HERCULES CANADA	BOILER STACK BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON	NW/223.3	5.00	319
64	SPL	HERCULES CANADA	HOLDING TANK BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON	NW/223.3	5.00	320
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	NW/223.3	5.00	321
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	NW/223.3	5.00	322
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	NW/223.3	5.00	322
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	NW/223.3	5.00	323

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	NW/223.3	5.00	324
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	NW/223.3	5.00	325
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	NW/223.3	5.00	326
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	NW/223.3	5.00	327
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	NW/223.3	5.00	327
64	SPL	HERCULES CANADA INC.	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	NW/223.3	5.00	328
64	SPL	HERCULES CANADA INC.	BRANT ST/PLAINS RD INTERSECTION. BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON	NW/223.3	5.00	329
64	CHEM	HERCULES CANADA INC.	BURLINGTON ON	NW/223.3	5.00	330
64	CHM	HERCULES CANADA INC	942 BRANT ST BURLINGTON ON L7R 2J7	NW/223.3	5.00	330
64	SCT	Ashland Canada Corp.	942 Brant St Burlington ON L7R 2J7	NW/223.3	5.00	330
64	SPL	HERCULES CANADA INC.	942 BRANT ST BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	NW/223.3	5.00	330
64	CA	HERCULES CANADA INC.	BURLINGTON CITY ON	NW/223.3	5.00	331

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
64	CA		942 Brant Street Burlington ON L7R 2J7	NW/223.3	5.00	332
64	CA		942 Brant Street Burlington ON L7R 2J7	NW/223.3	5.00	332
64	CA		942 Brant Street Burlington ON L7R 2J7	NW/223.3	5.00	332
64	CA		942 Brant Street Burlington ON L7R 2J7	NW/223.3	5.00	333
64	CA		942 Brant Street Burlington ON L7R 2J7	NW/223.3	5.00	333
64	EBR	Hercules Canada Inc.	942 Brant Street Burlington Ontario L7R 3X8 Burlington ON	NW/223.3	5.00	333
64	EBR	Hercules Canada (2002) Inc.	942 Brant Street Burlington Ontario L7R 2J7 Burlington ON	NW/223.3	5.00	334
64	GEN	HERCULES CANADA INC.	942 BRANT ST. P.O. BOX 100 BURLINGTON ON L7R 2J7	NW/223.3	5.00	334
64	GEN	HERCULES CANADA INC.	942 BRANT ST. P.O.BOX 100 BURLINGTON ON L7R 2J7	NW/223.3	5.00	335
64	GEN	HERCULES CANADA INC.	942 BRANT STREET BURLINGTON ON L7R 3X8	NW/223.3	5.00	336
64	GEN	HERCULES CANADA INC. 20-010	942 BRANT ST. P.O.BOX 100 BURLINGTON ON L7R 2J7	NW/223.3	5.00	337
64	GEN	HERCULES CANADA	942 BRANT STREET BURLINGTON ON L7R 3X8	NW/223.3	5.00	337
64	GEN	HERCULES CANADA (2002) INC	942 BRANT STREET BURLINGTON ON L7R 3X8	NW/223.3	5.00	338

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
64	NEES	HERCULESCANADALTD	BURLINGTON ON	NW/223.3	5.00	340
64	NEES	HERCULES CANADA	BURLINGTON CITY ON	NW/223.3	5.00	340
64	NEES	HERCULES CANADA	BURLINGTON CITY ON	NW/223.3	5.00	340
64	NEES	HERCULES CANADA	BURLINGTON CITY ON	NW/223.3	5.00	340
64	NEES	HERCULES CANADA	BURLINGTON CITY ON	NW/223.3	5.00	341
64	NEES	HERCULES CANADA	BURLINGTON CITY ON	NW/223.3	5.00	341
64	NEES	HERCULES CANADA	BURLINGTON CITY ON	NW/223.3	5.00	341
64	NATE	HERCULESCANADALTD	BURLINGTON ON	NW/223.3	5.00	341
64	EHS		942 Brant Street Burlington ON L7R 2J7	NW/223.3	5.00	342
64	EBR	Hercules Canada (2002) Inc.	942 Brant Street Burlington Ontario L7R 2J7 Burlington ON	NW/223.3	5.00	342
64	EBR	Hercules Canada (2002) Inc.	942 Brant Street Burlington Ontario L7R 3X8 Burlington ON	NW/223.3	5.00	343
64	SPL	Hercules Canada Inc.	942 Brant Street Burlington ON L7R 2J7	NW/223.3	5.00	343

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
64	SPL	Hercules Canada Inc.	942 Brant Street Burlington ON L7R 2J7	NW/223.3	5.00	344
64	SPL	Hercules Canada Inc.	942 Brant Street Burlington ON L7R 2J7	NW/223.3	5.00	345
64	SPL	Hercules Canada Inc.	942 Brant Street Burlington ON L7R 2J7	NW/223.3	5.00	346
64	SPL	942 Brant Street	942 Brant Street Burlington ON	NW/223.3	5.00	346
64	SPL	Hercules Canada Inc.	942 Brant St. Burlington Burlington ON L7R 2J7	NW/223.3	5.00	347
64	SPL	Hercules Canada Inc.	942 Brant St Burlington; Burlington ON L7R 2J7	NW/223.3	5.00	348
64	CA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	NW/223.3	5.00	349
64	CA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	NW/223.3	5.00	349
64	CA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	NW/223.3	5.00	350
64	CA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	NW/223.3	5.00	350
64	CA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	NW/223.3	5.00	350
64	CA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	NW/223.3	5.00	350
64	CA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	NW/223.3	5.00	351

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
64	CA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	NW/223.3	5.00	351
64	EBR	Ashland Canada Corp.	942 Brant Street Burlington, Regional Municipality of Halton L7R 2J7 CITY OF BURLINGTON ON	NW/223.3	5.00	351
64	GEN	Ashland Canada Corp.	942 BRANT STREET BURLINGTON ON	NW/223.3	5.00	352
64	ECA	Ashland Canada Corp.	942 Brant St Ashland Burlington ON L7R 2J7	NW/223.3	5.00	353
64	GEN	Ashland Canada Corp.	942 BRANT STREET BURLINGTON ON	NW/223.3	5.00	353
64	GEN	Ashland Canada Corp.	942 BRANT STREET BURLINGTON ON	NW/223.3	5.00	355
64	GEN	Ashland Canada Corp.	942 BRANT STREET BURLINGTON ON L7R 3X8	NW/223.3	5.00	356
64	CHM	ASHLAND	942 BRANT ST BURLINGTON ON L7R2J7	NW/223.3	5.00	357
64	EHS		942 Brant Street Burlington ON	NW/223.3	5.00	358
64	EHS		942 Brant Burlington ON L7RSJ7	NW/223.3	5.00	358
64	GEN	Solenis Canada ULC	942 BRANT STREET BURLINGTON ON	NW/223.3	5.00	358
64	SPL	Solenis Canada ULC	942 Brant St Burlington ON L7R 2J7	NW/223.3	5.00	360
64	ECA	Hercules Canada (2002) Inc.	942 Brant St Burlington ON L7R 3X8	NW/223.3	5.00	361

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
64	ECA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON L7R 3X8	NW/223.3	5.00	361
64	ECA	Hercules Canada Inc.	942 Brant St Burlington ON L7R 3X8	NW/223.3	5.00	361
64	ECA	Hercules Canada	942 Brant St Burlington ON L7R 3X8	NW/223.3	5.00	361
64	ECA	Hercules Canada (2002) Inc.	942 Brant St Burlington ON L6H 5R7	NW/223.3	5.00	362
64	ECA	Hercules Canada Inc.	942 Brant St Burlington ON L7R 3X8	NW/223.3	5.00	362
64	ECA	Hercules Canada Inc.	942 Brant St Burlington ON L7R 3X8	NW/223.3	5.00	362
64	ECA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON L7R 3X8	NW/223.3	5.00	363
64	ECA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON L7R 3X8	NW/223.3	5.00	363
64	ECA	Hercules Canada (2002) Inc.	942 Brant St Burlington ON L6H 5R7	NW/223.3	5.00	363
64	ECA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON L7R 3X8	NW/223.3	5.00	364
64	ECA	Hercules Canada (2002) Inc.	942 Brant St Burlington ON L7R 3X8	NW/223.3	5.00	364
64	ECA	Hercules Canada Inc.	942 Brant St Burlington ON L7R 3X8	NW/223.3	5.00	364
64	ECA	Ashland Canada Corp.	942 Brant St Ashland Burlington ON L7R 3X8	NW/223.3	5.00	364

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
64	ECA	Hercules Canada (2002) Inc.	942 Brant St Burlington ON L6H 5R7	NW/223.3	5.00	365
64	GEN	Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 3X8	NW/223.3	5.00	365
64	GEN	Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 3X8	NW/223.3	5.00	367
64	GEN	Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 2J7	NW/223.3	5.00	368
64	GEN	Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 3X8	NW/223.3	5.00	370
64	GEN	Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 2J7	NW/223.3	5.00	372
64	GEN	Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 2J7	NW/223.3	5.00	374
64	GEN	Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 2J7	NW/223.3	5.00	375
65	EHS		1881 FAIRVIEW STREET BURLINGTON ON L7S 2K4	NNW/230.8	4.08	377
65	GEN	Michaels Stores, Inc.	1881 Fairview St Burlington ON	NNW/230.8	4.08	377
65	GEN	Michaels Stores, Inc.	1881 Fairview St Burlington ON L7S 2K4	NNW/230.8	4.08	378
65	GEN	Michaels Stores, Inc.	1881 Fairview St Burlington ON L7S 2K4	NNW/230.8	4.08	379
65	GEN	Michaels Stores, Inc.	1881 Fairview St Burlington ON L7S 2K4	NNW/230.8	4.08	379

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
65	GEN	Michaels Stores, Inc.	1881 Fairview St Burlington ON L7S 2K4	NNW/230.8	4.08	380
66	EHS		770 Hager Ave Burlington ON L7S1X1	SE/231.8	-2.00	381
67	WWIS		850 BRANT ST Burlington ON ***Well ID:*** 7330857	NNE/238.8	0.00	381
68	WWIS		ON ***Well ID:*** 7369392	E/244.0	-3.00	384
69	BORE		ON	ENE/246.9	-2.76	385
70	SPL	Union Gas Limited	753 Hagar Avenue Burlington ON	SE/247.4	-2.04	387
71	SCT	Advanced Integrated Resources	817 Brant St Burlington ON L7R 2J4	NE/248.3	-2.00	388
71	SCT	Advanced Integrated Resources Inc.	817 Brant St Burlington ON L7R 2J4	NE/248.3	-2.00	388
72	PES	CANADA PEST CONTROL	1-2004 MAPLEWOOD DR BURLINGTON ON L7R2C4	NE/248.5	-1.81	388
73	WWIS		ON ***Well ID:*** 7369396	E/248.7	-3.00	389
74	CHM	SOLENIS CANADA	942 BRANT ST BURLINGTON ON L7R2J7	WNW/248.8	5.19	389
75	PRT	CLARES SHELL & CAR WASH INC	809 BRANT ST BURLINGTON ON L7R 2J4	ENE/248.9	-2.37	390
75	PRT	LAMONTS SERVICES LTD	809 BRANT ST BURLINGTON ON L7R2J4	ENE/248.9	-2.37	390

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
75	SPL	SHELL CANADA PRODUCTS LTD.	809 BRANT STREET. SERVICE STATION BURLINGTON CITY ON L7R 2J4	ENE/248.9	-2.37	390
75	DTNK	SHELL CANADA PRODUCTS**	809 BRANT ST BURLINGTON ON L7R 2J4	ENE/248.9	-2.37	391
75	DTNK	LAMONTS SERVICES LTD	809 BRANT ST BURLINGTON ON L7R 2J4	ENE/248.9	-2.37	391
75	DTNK	SHELL CANADA PRODUCTS**	809 BRANT ST BURLINGTON ON	ENE/248.9	-2.37	392
75	DTNK	SHELL CANADA PRODUCTS**	809 BRANT ST BURLINGTON ON	ENE/248.9	-2.37	393
75	DTNK	SHELL CANADA PRODUCTS**	809 BRANT ST BURLINGTON ON	ENE/248.9	-2.37	393
75	DTNK	LAMONTS SERVICES LTD	809 BRANT ST BURLINGTON ON	ENE/248.9	-2.37	394
75	DTNK	SHELL CANADA PRODUCTS**	809 BRANT ST BURLINGTON ON	ENE/248.9	-2.37	394
75	SPL	Union Gas Limited	809 Brant St Burlington ON	ENE/248.9	-2.37	395
76	CA	ROYAL CANADIAN NAVAL ASSOCIATION	760 BRANT ST., SUITE #417 BURLINGTON CITY ON	E/249.7	-3.73	396
76	CA	ROYAL CANADIAN NAVAL ASSOCIATION	760 BRANT STREET, 2ND FLOOR BURLINGTON CITY ON	E/249.7	-3.73	396
76	CA	CENTRE FRANCOPHONE DE BURLINGTON INC.	760 BRANT STREET (#401) BURLINGTON CITY ON	E/249.7	-3.73	396
76	EHS		760 Brant Street Burlington ON L7R 4B8	E/249.7	-3.73	397

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
76	EASR	Cogeco Cable Canada LP	760 BRANT STREET BURLINGTON ON L7R 4B8	E/249.7	-3.73	397
76	GEN	1086891 Ontario Inc.	760 Brant Street Burlington ON L7R 4B8	E/249.7	-3.73	397
76	GEN	Burlington Ultrasound and Radiology	Suite 2 760 Brant Street Burlington ON L7R 4B7	E/249.7	-3.73	398
76	GEN	McArthur Properties	760 Brant St. Burlington ON L7R 4B8	E/249.7	-3.73	398
76	GEN	Burlington Ultrasound and Radiology	Suite 2 760 Brant Street Burlington ON L7R 4B7	E/249.7	-3.73	398
76	GEN	Burlington Ultrasound and Radiology	Suite 2 760 Brant Street Burlington ON L7R 4B7	E/249.7	-3.73	399
76	GEN	Trillium College Inc	760 Brant Street Unit #25 Burlington ON	E/249.7	-3.73	399
76	GEN	Trillium College Inc	760 Brant Street Unit #25 Burlington ON	E/249.7	-3.73	399
76	GEN	Burlington Ultrasound and Radiology	Suite 2 760 Brant Street Burlington ON	E/249.7	-3.73	400
76	GEN	Wentworth Halton X-Ray and Ultrasound Inc	Suite 2 760 Brant Street Burlington ON L7R 4B7	E/249.7	-3.73	400
76	GEN	Dr Ronald Yim Dentistry Professional Corp	6-760 Brant Street Burlington ON L7R 4B7	E/249.7	-3.73	400
76	GEN	Burlington Ultrasound and Radiology	Suite 2 760 Brant Street Burlington ON L7R 4B7	E/249.7	-3.73	401
76	GEN	Trillium College Inc	760 Brant Street Unit #25 Burlington ON L7R4B7	E/249.7	-3.73	401

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
76	GEN	Oxford College of Arts, Business and Technology	760 Brant Street Unit #25 Burlington ON L7R4B7	E/249.7	-3.73	402
76	GEN	Burlington Ultrasound and Radiology	Suite 2 760 Brant Street Burlington ON L7R 4B7	E/249.7	-3.73	402
76	GEN	Trillium College Inc	760 Brant Street Unit #25 Burlington ON L7R4B7	E/249.7	-3.73	402
76	GEN	Oxford College of Arts, Business and Technology	760 Brant Street Unit #25 Burlington ON L7R4B7	E/249.7	-3.73	403
76	GEN	Dr Ronald Yim Dentistry Professional Corp	6-760 Brant Street Burlington ON L7R 4B7	E/249.7	-3.73	403
76	GEN	Wentworth Halton X-Ray and Ultrasound Inc	Suite 2 760 Brant Street Burlington ON L7R 4B7	E/249.7	-3.73	404
76	GEN	Oxford College of Arts, Business and Technology	760 Brant Street Unit #25 Burlington ON L7R4B7	E/249.7	-3.73	404
76	GEN	Dr Ronald Yim Dentistry Professional Corp	6-760 Brant Street Burlington ON L7R 4B7	E/249.7	-3.73	405
76	GEN	Wentworth Halton X-Ray and Ultrasound Inc	760 Brant Street Suite 2 Burlington ON L7R 4B7	E/249.7	-3.73	405
76	GEN	Dr Ronald Yim Dentistry Professional Corp	6-760 Brant Street Burlington ON L7R 4B7	E/249.7	-3.73	405
76	GEN	Wentworth Halton X-Ray and Ultrasound Inc	760 Brant Street Suite 2 Burlington ON L7R 4B7	E/249.7	-3.73	406
76	GEN	Oxford College of Arts, Business and Technology	760 Brant Street Unit #25 Burlington ON L7R4B7	E/249.7	-3.73	406
76	GEN	Dr Ronald Yim Dentistry Professional Corp	6-760 Brant Street Burlington ON L7R 4B7	E/249.7	-3.73	407

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
76	GEN	Oxford College of Arts, Business and Technology	760 Brant Street Unit #25 Burlington ON L7R4B7	E/249.7	-3.73	407
76	GEN	Wentworth Halton X-Ray and Ultrasound Inc	760 Brant Street Suite 2 Burlington ON L7R 4B7	E/249.7	-3.73	408
77	BORE		ON	NE/255.9	-1.00	408
78	WWIS		ON ***Well ID:*** 7374925	ENE/261.2	-2.00	410
79	EXP	SHELL CANADA PRODUCTS	809 BRANT ST BURLINGTON ON	ENE/265.4	-2.67	411
79	EXP	SHELL CANADA PRODUCTS	809 BRANT ST BURLINGTON ON	ENE/265.4	-2.67	411
79	EXP	SHELL CANADA PRODUCTS	809 BRANT ST BURLINGTON ON	ENE/265.4	-2.67	411
79	EXP	SHELL CANADA PRODUCTS	809 BRANT ST BURLINGTON ON	ENE/265.4	-2.67	411
79	EXP	LAMONTS SERVICES LTD	809 BRANT ST BURLINGTON ON	ENE/265.4	-2.67	412
79	EXP	LAMONTS SERVICES LTD	809 BRANT ST BURLINGTON ON	ENE/265.4	-2.67	412
79	EXP	LAMONTS SERVICES LTD	809 BRANT ST BURLINGTON ON	ENE/265.4	-2.67	412
79	EXP	LAMONTS SERVICES LTD	809 BRANT ST BURLINGTON ON	ENE/265.4	-2.67	412
80	GEN	1297760 ont. Inc	849 Brant Burlington ON L7R 2J6	NNE/275.6	-1.00	413

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
80	EHS		849 Brant Street Burlington ON	NNE/275.6	-1.00	413
80	EHS		849 Brant St Burlington ON L7R2J6	NNE/275.6	-1.00	413
81	WWIS		849 BRANT ST Burlington ON ***Well ID:*** 7292316	NE/277.0	-1.00	413
82	SCT	American Optics Inc.	789 Brant St Burlington ON L7R 2J3	ENE/277.9	-3.47	417
83	EHS		789-795 Brant Street Burlington ON L7R 2J3	ENE/282.1	-3.00	417
83	EHS		789-795 Brant Street Burlington ON L7R 2J3	ENE/282.1	-3.00	417
83	EHS		789-795 Brant Street Burlington ON L7R 2J3	ENE/282.1	-3.00	417
83	EHS		789-795 Brant Street Burlington ON L7R 2J3	ENE/282.1	-3.00	417
84	EHS		789-795 Brant Street Burlington ON L7R 2J3	ENE/282.1	-3.00	418
84	EHS		789-795 Brant Street Burlington ON L7R 2J3	ENE/282.1	-3.00	418
84	EHS		789-795 Brant Street Burlington ON L7R 2J3	ENE/282.1	-3.00	418
84	EHS		789-795 Brant Street Burlington ON L7R 2J3	ENE/282.1	-3.00	418
85	EHS		1450 Ghent Ave Burlington ON L7S 1W8	E/282.2	-4.00	418

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
85	EHS		1450 Ghent Ave Burlington ON L7S 1W8	E/282.2	-4.00	419
85	EHS		1450 Ghent Ave Burlington ON L7S 1W8	E/282.2	-4.00	419
85	EHS		1450 Ghent Ave Burlington ON L7S 1W8	E/282.2	-4.00	419
86	BORE		ON	ENE/285.0	-3.00	419
87	WWIS		ON ***Well ID:*** 7369394	ENE/288.2	-3.64	421
88	WWIS		ON ***Well ID:*** 7376950	NNE/288.4	-0.53	422
89	PRT	ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE	892 BRANT ST BURLINGTON ON L7R 2J5	N/288.9	1.79	423
89	GEN	BRANT CYCLE AND SPORTS LIMITED	892 BRANT STREET BURLINGTON ON L7R 2J5	N/288.9	1.79	423
89	GEN	BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R 2J5	N/288.9	1.79	424
89	DTNK	ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE	892 BRANT ST BURLINGTON ON L7R 2J5	N/288.9	1.79	424
89	DTNK	ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE	892 BRANT ST BURLINGTON ON	N/288.9	1.79	425
89	DTNK	ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE	892 BRANT ST BURLINGTON ON	N/288.9	1.79	425

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
89	DTNK	ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE	892 BRANT ST BURLINGTON ON	N/288.9	1.79	426
89	DTNK	ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE	892 BRANT ST BURLINGTON ON	N/288.9	1.79	426
89	GEN	BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R 2J5	N/288.9	1.79	427
89	GEN	BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R 2J5	N/288.9	1.79	427
89	GEN	BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R 2J5	N/288.9	1.79	428
89	GEN	BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R 2J5	N/288.9	1.79	428
89	GEN	BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON	N/288.9	1.79	428
89	GEN	BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R-2J5	N/288.9	1.79	429
89	GEN	BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R-2J5	N/288.9	1.79	429
89	GEN	BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R-2J5	N/288.9	1.79	430
89	GEN	BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R-2J5	N/288.9	1.79	430
89	GEN	BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R-2J5	N/288.9	1.79	430
89	GEN	BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R-2J5	N/288.9	1.79	431

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
89	GEN	BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R-2J5	N/288.9	1.79	431
89	EXP	ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE	892 BRANT ST BURLINGTON ON	N/288.9	1.79	432
89	EXP	ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE	892 BRANT ST BURLINGTON ON	N/288.9	1.79	432
89	EXP	ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE	892 BRANT ST BURLINGTON ON	N/288.9	1.79	432
89	EXP	ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE	892 BRANT ST BURLINGTON ON	N/288.9	1.79	432
90	BORE		ON	SW/290.1	-1.00	433
91	BORE		ON	N/290.2	0.00	435
92	EHS		849 and 855 Brant Street Burlington ON L7R 2J6	NNE/294.7	-0.66	436
92	EHS		849 and 855 Brant Street Burlington ON L7R 2J6	NNE/294.7	-0.66	437
92	EHS		849 and 855 Brant Street Burlington ON L7R 2J6	NNE/294.7	-0.66	437
92	EHS		849 and 855 Brant Street Burlington ON L7R 2J6	NNE/294.7	-0.66	437
93	BORE		ON	NNE/294.8	0.00	437

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
94	EHS		730 Brant St Burlington ON L7R2H9	E/294.8	-4.00	439
95	EHS		855 Brant Street Burlington ON L7R 2J6	NNE/297.8	-0.21	439
95	EHS		855 Brant St Burlington ON	NNE/297.8	-0.21	439
96	SPL	ALCHEM	BRANT & FAIRVIEW RAMBO CREEK BURLINGTON PLANT 1055 TRUMAN STREET BURLINGTON CITY ON	NNE/299.5	0.00	439
96	SPL		Fairview and Brant Burlington ON	NNE/299.5	0.00	440
96	SPL		cb at Brant Street and Fairview Street Burlington ON	NNE/299.5	0.00	441
96	SPL		intersection of Fairview St. and Brant St. Burlington ON	NNE/299.5	0.00	442

Executive Summary: Summary By Data Source

BORE - Borehole

A search of the BORE database, dated 1875-Jul 2018 has found that there are 13 BORE site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	ON	33.1	7
	ON	86.2	18
	ON	123.9	31
	ON	128.4	33
	ON	131.5	36
	ON	137.1	38
	ON	167.5	47
	ON	246.9	69
	ON	255.9	77

Site	Address	Distance (m)	Map Key
	ON	285.0	86
	ON	290.1	90
	ON	290.2	91
	ON	294.8	93

CA - Certificates of Approval

A search of the CA database, dated 1985-Oct 30, 2011* has found that there are 23 CA site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Smit Autobody	1400 Graham's Lane Burlington ON	33.5	8
ETRATECH DESIGNS INC.	1440 GRAHAMS LANE, UNIT #5 BURLINGTON CITY ON L7S 1W3	88.7	20
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	223.3	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	223.3	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	223.3	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	223.3	64

Site	Address	Distance (m)	Map Key
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	223.3	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	223.3	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	223.3	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	223.3	64
	942 Brant Street Burlington ON L7R 2J7	223.3	64
	942 Brant Street Burlington ON L7R 2J7	223.3	64
	942 Brant Street Burlington ON L7R 2J7	223.3	64
	942 Brant Street Burlington ON L7R 2J7	223.3	64
HERCULES CANADA INC.	942 BRANT STREET BURLINGTON CITY ON L7R 2J7	223.3	64
HERCULES CANADA INC.	942 BRANT STREET BURLINGTON CITY ON L7R 2J7	223.3	64
HERCULES CANADA INC.	942 BRANT STREET BURLINGTON CITY ON L7R 2J7	223.3	64

Site	Address	Distance (m)	Map Key
HERCULES CANADA INC.	942 BRANT STREET BURLINGTON CITY ON L7R 2J7	223.3	64
HERCULES CANADA INC.	BURLINGTON CITY ON	223.3	64
	942 Brant Street Burlington ON L7R 2J7	223.3	64
ROYAL CANADIAN NAVAL ASSOCIATION	760 BRANT ST., SUITE #417 BURLINGTON CITY ON	249.7	76
ROYAL CANADIAN NAVAL ASSOCIATION	760 BRANT STREET, 2ND FLOOR BURLINGTON CITY ON	249.7	76
CENTRE FRANCOPHONE DE BURLINGTON INC.	760 BRANT STREET (#401) BURLINGTON CITY ON	249.7	76

CHEM - Chemical Manufacturers and Distributors

A search of the CHEM database, dated 1999-Jan 31, 2020 has found that there are 1 CHEM site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
HERCULES CANADA INC.	BURLINGTON ON	223.3	64

CHM - Chemical Register

A search of the CHM database, dated 1999-Oct 31, 2023 has found that there are 3 CHM site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
HERCULES CANADA INC	942 BRANT ST BURLINGTON ON L7R 2J7	223.3	64

Site	Address	Distance (m)	Map Key
ASHLAND	942 BRANT ST BURLINGTON ON L7R2J7	223.3	64
SOLENIS CANADA	942 BRANT ST BURLINGTON ON L7R2J7	248.8	74

CPU - Certificates of Property Use

A search of the CPU database, dated 1994 - Dec 31, 2023 has found that there are 1 CPU site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Wellington Park Care Centre Facility Inc.	802 Hager Avenue CITY OF BURLINGTON ON	128.9	35

DTNK - Delisted Fuel Tanks

A search of the DTNK database, dated Oct 2023 has found that there are 43 DTNK site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	40.0	10

Site	Address	Distance (m)	Map Key
FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	40.0	10

Site	Address	Distance (m)	Map Key
FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
FREW PETROLEUM CORPORATION	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD	1380 GRAHAMS LANE BURLINGTON ON	40.0	10

Site	Address	Distance (m)	Map Key
578122 ONTARIO INC	1448 GRAHAMS LA BURLINGTON ON	147.9	40
578122 ONTARIO INC	1448 GRAHAMS LA BURLINGTON ON	147.9	40
578122 ONTARIO INC	1448 GRAHAMS LA BURLINGTON ON	147.9	40
578122 ONTARIO INC	1448 GRAHAMS LA BURLINGTON ON	147.9	40
SHELL CANADA PRODUCTS**	809 BRANT ST BURLINGTON ON L7R 2J4	248.9	75
SHELL CANADA PRODUCTS**	809 BRANT ST BURLINGTON ON	248.9	75
SHELL CANADA PRODUCTS**	809 BRANT ST BURLINGTON ON	248.9	75
SHELL CANADA PRODUCTS**	809 BRANT ST BURLINGTON ON	248.9	75
LAMONTS SERVICES LTD	809 BRANT ST BURLINGTON ON	248.9	75
SHELL CANADA PRODUCTS**	809 BRANT ST BURLINGTON ON	248.9	75
LAMONTS SERVICES LTD	809 BRANT ST BURLINGTON ON L7R 2J4	248.9	75
ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE	892 BRANT ST BURLINGTON ON L7R 2J5	288.9	89

Site	Address	Distance (m)	Map Key
ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE	892 BRANT ST BURLINGTON ON	288.9	89
ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE	892 BRANT ST BURLINGTON ON	288.9	89
ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE	892 BRANT ST BURLINGTON ON	288.9	89
ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE	892 BRANT ST BURLINGTON ON	288.9	89

EASR - Environmental Activity and Sector Registry

A search of the EASR database, dated Oct 2011- Nov 30, 2023 has found that there are 1 EASR site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Cogeco Cable Canada LP	760 BRANT STREET BURLINGTON ON L7R 4B8	249.7	76

EBR - Environmental Registry

A search of the EBR database, dated 1994 - Dec 31, 2023 has found that there are 7 EBR site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Smit Autobody	1400 Graham's Lane Burlington Ontario L7S 1W3 Burlington ON	33.5	8
Ontario Testing Labs Inc.	1440 GRAHAM'S LANE, UNIT #9, BURLINGTON CITY CITY OF BURLINGTON ON	88.7	20
Hercules Canada (2002) Inc.	942 Brant Street Burlington Ontario L7R 2J7 Burlington ON	223.3	64

Site	Address	Distance (m)	Map Key
Hercules Canada (2002) Inc.	942 Brant Street Burlington Ontario L7R 3X8 Burlington ON	223.3	64
Ashland Canada Corp.	942 Brant Street Burlington, Regional Municipality of Halton L7R 2J7 CITY OF BURLINGTON ON	223.3	64
Hercules Canada Inc.	942 Brant Street Burlington Ontario L7R 3X8 Burlington ON	223.3	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington Ontario L7R 2J7 Burlington ON	223.3	64

ECA - Environmental Compliance Approval

A search of the ECA database, dated Oct 2011- Nov 30, 2023 has found that there are 17 ECA site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Smit Autobody	1400 Graham's Lane Burlington ON L7S 1W3	33.5	8
Hercules Canada (2002) Inc.	942 Brant St Burlington ON L7R 3X8	223.3	64
Ashland Canada Corp.	942 Brant St Ashland Burlington ON L7R 2J7	223.3	64
Hercules Canada Inc.	942 Brant St Burlington ON L7R 3X8	223.3	64
Hercules Canada	942 Brant St Burlington ON L7R 3X8	223.3	64

Site	Address	Distance (m)	Map Key
Hercules Canada (2002) Inc.	942 Brant St Burlington ON L6H 5R7	223.3	64
Hercules Canada Inc.	942 Brant St Burlington ON L7R 3X8	223.3	64
Hercules Canada Inc.	942 Brant St Burlington ON L7R 3X8	223.3	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON L7R 3X8	223.3	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON L7R 3X8	223.3	64
Hercules Canada (2002) Inc.	942 Brant St Burlington ON L6H 5R7	223.3	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON L7R 3X8	223.3	64
Hercules Canada (2002) Inc.	942 Brant St Burlington ON L7R 3X8	223.3	64
Hercules Canada Inc.	942 Brant St Burlington ON L7R 3X8	223.3	64
Ashland Canada Corp.	942 Brant St Ashland Burlington ON L7R 3X8	223.3	64
Hercules Canada (2002) Inc.	942 Brant St Burlington ON L6H 5R7	223.3	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON L7R 3X8	223.3	64

Site	Address	Distance (m)	Map Key

EHS - ERIS Historical Searches

A search of the EHS database, dated 1999-Dec 31, 2023 has found that there are 74 EHS site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	1393 Grahams Lane Burlington ON L7S 1W4	0.0	1
	1393 Grahams Lane Burlington ON L7S 1W4	0.0	1
	1393 Grahams Lane Burlington ON L7S 1W4	0.0	1
	1393 Grahams Lane Burlington ON L7S 1W4	0.0	1
	1393 Grahams Lane Burlington ON L7S 1W4	0.0	2
	1416 Grahams Lane Burlington ON L7S 1W3	60.6	12
	1416 Grahams Lane Burlington ON L7S 1W3	60.6	12
	1416 Grahams Lane Burlington ON L7S 1W3	60.6	12
	1416 Grahams Lane Burlington ON L7S 1W3	60.6	12

Site	Address	Distance (m)	Map Key
	828 Legion Road Burlington ON L7S 1T5	64.7	13
	1416 Grahams Ln Burlington ON L7S 1W3	71.3	15
	1440 Graham's Lane, Unit #9 Burlington ON L7S 1W3	88.7	20
	1440 Grahams Lane Unit 2 Burlington ON	88.7	20
	850 Legion Road Burlington ON L7S 1T6	90.5	22
	850 Legion Road Burlington ON L7S 1T6	90.5	22
	850 Legion Road Burlington ON L7S 1T6	90.5	22
	850 Legion Road Burlington ON L7S 1T6	90.5	22
	1439 Grahams Lane Burlington ON L7S 1W5	119.1	28
	1439 Grahams Lane Burlington ON L7S 1W5	119.1	29
	1439 Grahams Lane Burlington ON L7S 1W5	119.1	29
	1439 Grahams Lane Burlington ON L7S 1W5	119.1	29

Site	Address	Distance (m)	Map Key
	1439 Grahams Lane Burlington ON L7S 1W5	119.1	29
	1439 Grahams Lane Burlington ON L7S 1W5	119.1	29
	831 Legion Rd Burlington On Burlington ON L7S1T6	119.4	30
	802 Hager Avenue Burlington ON L7S	128.0	32
	802 Hager Avenue Burlington ON L7S	128.0	32
	802 Hager Avenue Burlington ON L7S	128.0	32
	802 Hager Avenue Burlington ON L7S	128.0	32
	802 Hager Avenue Burlington ON L7S 1X2	128.9	35
	802 Hager Avenue Burlington ON L7S 1X2	128.9	35
	802 Hager Ave Burlington ON L7S1X2	128.9	35
	802 Hager Avenue Burlington ON	128.9	35

Site	Address	Distance (m)	Map Key
	Highway 403 (QEW) Burlington Burlington ON	144.8	39
	850 Brant Street Burlington ON L7R 2J5	172.5	48
	780 Brant Street Burlington ON L7R 2J2	191.0	52
	796 Brant Street Burlington ON L7R 2J2	193.3	53
	796 Brant Street Burlington ON L7R 2J2	193.3	53
	796 Brant Street Burlington ON L7R 2J2	193.3	53
	796 Brant Street Burlington ON L7R 2J2	193.3	53
	QEW and 403 Burlington ON	198.0	56
	QEW and 403 Burlington ON	198.0	56
	QEW and 403 Burlington ON	198.0	56
	942 Brant Street Burlington ON L7R 2J7	220.3	59
	942 Brant Street Burlington ON L7R 2J7	220.3	59

Site	Address	Distance (m)	Map Key
	942 Brant Street Burlington ON L7R 2J7	220.3	59
	942 Brant Street Burlington ON L7R 2J7	220.3	59
	Former CNR Land Burlington ON L7S	222.9	63
	942 Brant Street Burlington ON L7R 2J7	223.3	64
	942 Brant Street Burlington ON	223.3	64
	942 Brant Burlington ON L7RSJ7	223.3	64
	1881 FAIRVIEW STREET BURLINGTON ON L7S 2K4	230.8	65
	770 Hager Ave Burlington ON L7S1X1	231.8	66
	760 Brant Street Burlington ON L7R 4B8	249.7	76
	849 Brant Street Burlington ON	275.6	80
	849 Brant St Burlington ON L7R2J6	275.6	80

Site	Address	Distance (m)	Map Key
	789-795 Brant Street Burlington ON L7R 2J3	282.1	83
	789-795 Brant Street Burlington ON L7R 2J3	282.1	83
	789-795 Brant Street Burlington ON L7R 2J3	282.1	83
	789-795 Brant Street Burlington ON L7R 2J3	282.1	83
	789-795 Brant Street Burlington ON L7R 2J3	282.1	84
	789-795 Brant Street Burlington ON L7R 2J3	282.1	84
	789-795 Brant Street Burlington ON L7R 2J3	282.1	84
	789-795 Brant Street Burlington ON L7R 2J3	282.1	84
	1450 Ghent Ave Burlington ON L7S 1W8	282.2	85
	1450 Ghent Ave Burlington ON L7S 1W8	282.2	85
	1450 Ghent Ave Burlington ON L7S 1W8	282.2	85
	1450 Ghent Ave Burlington ON L7S 1W8	282.2	85

Site	Address	Distance (m)	Map Key
	849 and 855 Brant Street Burlington ON L7R 2J6	294.7	92
	849 and 855 Brant Street Burlington ON L7R 2J6	294.7	92
	849 and 855 Brant Street Burlington ON L7R 2J6	294.7	92
	849 and 855 Brant Street Burlington ON L7R 2J6	294.7	92
	730 Brant St Burlington ON L7R2H9	294.8	94
	855 Brant Street Burlington ON L7R 2J6	297.8	95
	855 Brant St Burlington ON	297.8	95

EXP - List of Expired Fuels Safety Facilities

A search of the EXP database, dated Oct 2023 has found that there are 15 EXP site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
578122 ONTARIO INC	1448 GRAHAMS LANE BURLINGTON ON	147.9	40
578122 ONTARIO INC	1448 GRAHAMS LANE BURLINGTON ON	147.9	40

Site	Address	Distance (m)	Map Key
578122 ONTARIO INC	1448 GRAHAMS LANE BURLINGTON ON	147.9	40
SHELL CANADA PRODUCTS	809 BRANT ST BURLINGTON ON	265.4	79
SHELL CANADA PRODUCTS	809 BRANT ST BURLINGTON ON	265.4	79
SHELL CANADA PRODUCTS	809 BRANT ST BURLINGTON ON	265.4	79
SHELL CANADA PRODUCTS	809 BRANT ST BURLINGTON ON	265.4	79
LAMONTS SERVICES LTD	809 BRANT ST BURLINGTON ON	265.4	79
LAMONTS SERVICES LTD	809 BRANT ST BURLINGTON ON	265.4	79
LAMONTS SERVICES LTD	809 BRANT ST BURLINGTON ON	265.4	79
LAMONTS SERVICES LTD	809 BRANT ST BURLINGTON ON	265.4	79
ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE	892 BRANT ST BURLINGTON ON	288.9	89
ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE	892 BRANT ST BURLINGTON ON	288.9	89
ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE	892 BRANT ST BURLINGTON ON	288.9	89

Site	Address	Distance (m)	Map Key
ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE	892 BRANT ST BURLINGTON ON	288.9	89

GEN - Ontario Regulation 347 Waste Generators Summary

A search of the GEN database, dated 1986-Oct 31, 2022 has found that there are 168 GEN site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
MCGRAW EDISON	NAT. ELECT. COIL 1393 GRAHAM'S LANE BURLINGTON ON L7S 1W4	0.0	1
MCGRAW (SEE&USE ON1234100)	NAT. ELECT. COIL 1393 GRAHAM'S LANE BURLINGTON ON L7S 1W4	0.0	1
MCGRAW (SEE&USE ON1234100) 26-115	NAT. ELECT. COIL 1393 GRAHAM'S LANE BURLINGTON ON L7S 1W4	0.0	1
WALKER MAGNETICS NATIONAL LTD.	1393 GRAHAMS LANE BURLINGTON ON L7S 1W4	0.0	1
WALKER MAGNETICS NATIONAL LTD. 26-115	1393 GRAHAMS LANE BURLINGTON ON L7S 1W4	0.0	1
PETRO-CANADA PRODUCTS	1380 GRAHAM'S LANE BURLINGTON C/O 5140 YONGE STREET SUITE 200 NORTH YORK ON L7S 1W3	40.0	10
PETRO-CANADA PRODUCTS	1380 GRAHAM'S LANE BURLINGTON ON L7S 1W3	40.0	10
PETRO-CANADA PRODUCTS 30-464	1380 GRAHAM'S LANE BURLINGTON C/O 5140 YONGE STREET SUITE 200 NORTH YORK ON L7S 1W3	40.0	10

Site	Address	Distance (m)	Map Key
JOHN EBOS FUELS LIMITED 22-460	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	40.0	10
JOHN EBOS FUELS LIMITED	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	40.0	10
JOHN EBOS FUELS, A DIVISION OF PETRO PARTNERS LTD.	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
Petro-Canada Retail Development Centres (Central)	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	40.0	10
Petro Canada	1380 Grahams Lane Burlington ON L7S 1W3	40.0	10
Petro-Canada Retail Development Centres (Central)	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	40.0	10
Petro-Canada Retail Development Centres (Central)	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	40.0	10
Petro-Canada Retail Development Centres (Central)	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	40.0	10
Suncor Energy	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	40.0	10
Suncor Energy	1380 GRAHAMS LANE BURLINGTON ON	40.0	10
Suncor Energy	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	40.0	10
Suncor Energy	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	40.0	10

Site	Address	Distance (m)	Map Key
Suncor Energy	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	40.0	10
Suncor Energy	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	40.0	10
Suncor Energy	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	40.0	10
Suncor Energy	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	40.0	10
Suncor Energy Products Partnership	1380 Grahams Lane Burlington ON L7S 1W3	40.0	10
Suncor Energy	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	40.0	10
Suncor Energy Products Partnership	1380 Grahams Lane Burlington ON L7S 1W3	40.0	10
BURLINGTON HYDRO-ELEC. COMMISSION	1370 GRAHAMS LANE C/O 1340 BRANT ST. BURLINGTON ON L7R 3Z7	68.2	14
BURLINGTON HYDRO-ELEC. COMMISSION 05-334	1370 GRAHAMS LANE C/O 1340 BRANT ST. BURLINGTON ON L7R 3Z7	68.2	14
SINCLAIR-SMITH PRINTING &	LITHOGRAPHING CO. LTD., THE 1416 GRAHAMS LANE BURLINGTON ON L7S 1W3	71.3	15
SINCLAIR-SMITH PRINTING & 35-086	LITHOGRAPHING CO. LTD., THE 1416 GRAHAMS LANE BURLINGTON ON L7S 1W3	71.3	15

Site	Address	Distance (m)	Map Key
WENTWORTH ELECTRONICS	850 LEGION ROAD, UNIT #7 BURLINGTON ON L7S 1T5	78.7	17
WENTWORTH OUT OF BUSINESS 41-236	850 LEGION ROAD, UNIT #7 BURLINGTON ON L7S 1T5	78.7	17
TECKMARK LABEL SYSTEMS INC.	850 - #23 LEGION ROAD BURLINGTON ON L7S 1T5	78.7	17
TECKMARK LABEL SYSTEMS INC. 37-552	850 - #23 LEGION ROAD BURLINGTON ON L7S 1T5	78.7	17
TECKMARK LABEL SYSTEMS INC.	850 - #23 LEGION ROAD BURLINGTON ON L7S 1T5	78.7	17
ARTISAN DESIGN	850 LEGION ROAD UNIT #1 BURLINGTON ON L7S 1T5	78.7	17
B-LINE CRESTING, DIVISION OF	850 LEGION ROAD, UNIT #7 BURLINGTON ON L7S 1T5	78.7	17
GOLDEN HORSESHOE SERVICES	850 LEGION ROAD, #17 BURLINGTON ON L7S 1T5	78.7	17
GOLDEN HORSESHOE SERVICES	850 LEGION ROAD, #17 BURLINGTON ON L7S 1T5	78.7	17
ARTISAN DESIGN	850 LEGION ROAD, UNIT 1 BURLINGTON ON L7S 1T5	78.7	17
B-LINE CRESTING	850 LEGION ROAD, UNIT 7 BURLINGTON ON L7S 1T5	78.7	17
GOLDEN HORSESHOE SERVICES	850 LEGION ROAD, UNIT 17 BURLINGTON ON L7S 1T5	78.7	17

Site	Address	Distance (m)	Map Key
The Maples Animal Hospital	850 Legion Road Unit 21 Burlington ON L7S 1T5	78.7	17
TECKMARK LABEL SYSTEMS INC.	850 - #23 LEGION ROAD BURLINGTON ON L7S 1T5	78.7	17
Techmark Label Systems Inc.	850 Legion Unit 23 Burlington ON L7S 1T5	78.7	17
The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON L7S 1T5	78.7	17
Historia Building Restoration Inc.	850 Legion Road Unit 19A Burlington ON	78.7	17
The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON L7S 1T5	78.7	17
Historia Building Restoration Inc.	850 Legion Road Unit 19A Burlington ON L7S 1T5	78.7	17
The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON L7S 1T5	78.7	17
Historia Building Restoration Inc.	850 Legion Road Unit 19A Burlington ON L7S 1T5	78.7	17
The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON L7S 1T5	78.7	17
The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON	78.7	17

Site	Address	Distance (m)	Map Key
The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON L7S 1T5	78.7	17
The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON L7S 1T5	78.7	17
The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON L7S 1T5	78.7	17
The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON L7S 1T5	78.7	17
The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON L7S 1T5	78.7	17
SOAR Veterinary Professional Corporation	850 Legion Rd Unit 5 Burlington ON L7S 1T5	78.7	17
SOAR Veterinary Professional Corporation	850 Legion Rd Unit 5 Burlington ON L7S 1T5	78.7	17
The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON L7S 1T5	78.7	17
SOAR Veterinary Professional Corporation	850 Legion Rd Unit 5 Burlington ON L7S 1T5	78.7	17
The Maples Animal Hospital Professional Corporatio	850 Legion Road Unit 21 Burlington ON L7S 1T5	78.7	17
Carl's Grinding Service	850 Legion Road #8 Burlington ON L7S 1T5	78.7	17
DOVER CORPORATION (CANADA) LIMITED12-701	1440 GRAHAM'S LANE, UNIT #3 BURLINGTON ON L7S 1W3	88.7	20

Site	Address	Distance (m)	Map Key
DOVER CORPORATION (CANADA) LIMITED	1440 GRAHAM'S LANE UNIT 3 BURLINGTON ON L7S 1W3	88.7	20
THYSSEN DOVER ELEVATOR	1440 GRAHAM'S LANE UNIT 3 BURLINGTON ON L7S 1W3	88.7	20
THYSSEN KRUPP ELEVATOR	1440 GRAHAM'S LANE UNIT 3 BURLINGTON ON L7S 1W3	88.7	20
BCT BUSINESS (OUT OF BUSINESS) 05-745	1440 GRAHAM'S LANE, UNIT #8 BURLINGTON ON L7S 1W3	88.7	20
ETRATECH MAN(OUT OF BUSINESS) 49-115	1440 GRAHAMS LANE UNIT 6 BURLINGTON ON L7S 1W3	88.7	20
ASH TEMPLE LTD.	1440 GRAHAM'S LANE, SUITE 5 BURLINGTON ON L7S 1W3	88.7	20
ONTARIO TESTING LABS	1440 GRAHAMS LANE BURLINGTON ON L7S 1W3	88.7	20
ASH TEMPLE LTD.	1440 GRAHAM'S LANE SUITE 5 BURLINGTON ON L7S 1W3	88.7	20
BODYCOTE GALT MATERIALS TESTING LTD.	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	88.7	20
Bodycote Materials Testing Canada Inc.	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	88.7	20
Bodycote Testing Group	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	88.7	20

Site	Address	Distance (m)	Map Key
Exova	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	88.7	20
Exova	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	88.7	20
Exova	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	88.7	20
Exova	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	88.7	20
Exova	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	88.7	20
Exova	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	88.7	20
Exova Burlington	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	88.7	20
Exova Burlington	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	88.7	20
Exova Burlington	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	88.7	20
Exova	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	88.7	20
Exova	1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON	88.7	20
Hydro One Networks Inc.	1355 Stephenson Dr. Burlington ON L7S 2M5	91.0	23

Site	Address	Distance (m)	Map Key
Burlington Hydro Inc.	1439 Grahams Lane Burlington ON L7S 1W4	119.1	29
BURLINGTON ASS. FOR COMMUNITY	LIVING 831 LEGION ROAD BURLINGTON ON L7S 1T6	119.4	30
BURLINGTON ASS. FOR COMMUNITY 05-519	LIVING 831 LEGION ROAD BURLINGTON ON L7S 1T6	119.4	30
Wellington Park Care Centre	802 Hagar Avenue Burlington ON L7S 1X2	128.9	35
Wellington Park Care Centre	802 Hagar Avenue Burlington ON L7S 1X2	128.9	35
Wellington Park Care Centre	802 Hagar Avenue Burlington ON	128.9	35
Responsive Management Inc	802 Hager Avenue Burlington ON L7S1X2	128.9	35
Wellington Park Care Centre	802 Hagar Avenue Burlington ON L7S 1X2	128.9	35
Suncor Energy Products	802 Hager Ave, Burlington ON L7S 1X2	128.9	35
Suncor Energy Products	802 Hager Ave, Burlington ON L7S 1X2	128.9	35
Suncor Energy Products	802 Hager Ave, Burlington ON L7S 1X2	128.9	35

Site	Address	Distance (m)	Map Key
Wellington Park Care Centre	802 Hagar Avenue Burlington ON L7S 1X2	128.9	35
Suncor Energy Products	802 Hager Ave, Burlington ON L7S 1X2	128.9	35
Discovery Ford	850 Brant Street Burlington ON L7R 2J5	172.5	48
Ashland Canada Corp.	942 BRANT STREET BURLINGTON ON	223.3	64
Ashland Canada Corp.	942 BRANT STREET BURLINGTON ON	223.3	64
Ashland Canada Corp.	942 BRANT STREET BURLINGTON ON	223.3	64
Ashland Canada Corp.	942 BRANT STREET BURLINGTON ON L7R 3X8	223.3	64
Solenis Canada ULC	942 BRANT STREET BURLINGTON ON	223.3	64
Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 3X8	223.3	64
Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 3X8	223.3	64
Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 2J7	223.3	64
Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 3X8	223.3	64

Site	Address	Distance (m)	Map Key
Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 2J7	223.3	64
Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 2J7	223.3	64
Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 2J7	223.3	64
HERCULES CANADA INC.	942 BRANT ST. P.O. BOX 100 BURLINGTON ON L7R 2J7	223.3	64
HERCULES CANADA INC.	942 BRANT ST. P.O.BOX 100 BURLINGTON ON L7R 2J7	223.3	64
HERCULES CANADA INC.	942 BRANT STREET BURLINGTON ON L7R 3X8	223.3	64
HERCULES CANADA INC. 20-010	942 BRANT ST. P.O.BOX 100 BURLINGTON ON L7R 2J7	223.3	64
HERCULES CANADA	942 BRANT STREET BURLINGTON ON L7R 3X8	223.3	64
HERCULES CANADA (2002) INC	942 BRANT STREET BURLINGTON ON L7R 3X8	223.3	64
Michaels Stores, Inc.	1881 Fairview St Burlington ON	230.8	65
Michaels Stores, Inc.	1881 Fairview St Burlington ON L7S 2K4	230.8	65

Site	Address	Distance (m)	Map Key
Michaels Stores, Inc.	1881 Fairview St Burlington ON L7S 2K4	230.8	65
Michaels Stores, Inc.	1881 Fairview St Burlington ON L7S 2K4	230.8	65
Michaels Stores, Inc.	1881 Fairview St Burlington ON L7S 2K4	230.8	65
1086891 Ontario Inc.	760 Brant Street Burlington ON L7R 4B8	249.7	76
Burlington Ultrasound and Radiology	Suite 2 760 Brant Street Burlington ON L7R 4B7	249.7	76
McArthur Properties	760 Brant St. Burlington ON L7R 4B8	249.7	76
Burlington Ultrasound and Radiology	Suite 2 760 Brant Street Burlington ON L7R 4B7	249.7	76
Trillium College Inc	760 Brant Street Unit #25 Burlington ON	249.7	76
Trillium College Inc	760 Brant Street Unit #25 Burlington ON	249.7	76
Burlington Ultrasound and Radiology	Suite 2 760 Brant Street Burlington ON	249.7	76
Wentworth Halton X-Ray and Ultrasound Inc	Suite 2 760 Brant Street Burlington ON L7R 4B7	249.7	76
Dr Ronald Yim Dentistry Professional Corp	6-760 Brant Street Burlington ON L7R 4B7	249.7	76

Site	Address	Distance (m)	Map Key
Burlington Ultrasound and Radiology	Suite 2 760 Brant Street Burlington ON L7R 4B7	249.7	76
Trillium College Inc	760 Brant Street Unit #25 Burlington ON L7R4B7	249.7	76
Oxford College of Arts, Business and Technology	760 Brant Street Unit #25 Burlington ON L7R4B7	249.7	76
Burlington Ultrasound and Radiology	Suite 2 760 Brant Street Burlington ON L7R 4B7	249.7	76
Trillium College Inc	760 Brant Street Unit #25 Burlington ON L7R4B7	249.7	76
Oxford College of Arts, Business and Technology	760 Brant Street Unit #25 Burlington ON L7R4B7	249.7	76
Dr Ronald Yim Dentistry Professional Corp	6-760 Brant Street Burlington ON L7R 4B7	249.7	76
Wentworth Halton X-Ray and Ultrasound Inc	Suite 2 760 Brant Street Burlington ON L7R 4B7	249.7	76
Oxford College of Arts, Business and Technology	760 Brant Street Unit #25 Burlington ON L7R4B7	249.7	76
Dr Ronald Yim Dentistry Professional Corp	6-760 Brant Street Burlington ON L7R 4B7	249.7	76
Wentworth Halton X-Ray and Ultrasound Inc	760 Brant Street Suite 2 Burlington ON L7R 4B7	249.7	76

Site	Address	Distance (m)	Map Key
Dr Ronald Yim Dentistry Professional Corp	6-760 Brant Street Burlington ON L7R 4B7	249.7	76
Wentworth Halton X-Ray and Ultrasound Inc	760 Brant Street Suite 2 Burlington ON L7R 4B7	249.7	76
Oxford College of Arts, Business and Technology	760 Brant Street Unit #25 Burlington ON L7R4B7	249.7	76
Dr Ronald Yim Dentistry Professional Corp	6-760 Brant Street Burlington ON L7R 4B7	249.7	76
Oxford College of Arts, Business and Technology	760 Brant Street Unit #25 Burlington ON L7R4B7	249.7	76
Wentworth Halton X-Ray and Ultrasound Inc	760 Brant Street Suite 2 Burlington ON L7R 4B7	249.7	76
Burlington Ultrasound and Radiology	Suite 2 760 Brant Street Burlington ON L7R 4B7	249.7	76
1297760 ont. Inc	849 Brant Burlington ON L7R 2J6	275.6	80
BRANT CYCLE AND SPORTS LIMITED	892 BRANT STREET BURLINGTON ON L7R 2J5	288.9	89
BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R 2J5	288.9	89
BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R 2J5	288.9	89
BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R 2J5	288.9	89

Site	Address	Distance (m)	Map Key
BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R 2J5	288.9	89
BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R 2J5	288.9	89
BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON	288.9	89
BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R-2J5	288.9	89
BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R-2J5	288.9	89
BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R-2J5	288.9	89
BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R-2J5	288.9	89
BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R-2J5	288.9	89
BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R-2J5	288.9	89
BRANT CYCLE AND SPORTS LIMITED	892 BRANT ST. BURLINGTON ON L7R-2J5	288.9	89

NATE - National Analysis of Trends in Emergencies System (NATES)

A search of the NATE database, dated 1974-1994* has found that there are 1 NATE site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
HERCULESCANADALTD	BURLINGTON ON	223.3	64

NEES - National Environmental Emergencies System (NEES)

A search of the NEES database, dated 1974-2003* has found that there are 7 NEES site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
HERCULES CANADA	BURLINGTON CITY ON	223.3	64
HERCULES CANADA	BURLINGTON CITY ON	223.3	64
HERCULES CANADA	BURLINGTON CITY ON	223.3	64
HERCULES CANADA	BURLINGTON CITY ON	223.3	64
HERCULES CANADA	BURLINGTON CITY ON	223.3	64
HERCULES CANADA	BURLINGTON CITY ON	223.3	64
HERCULESCANADALTD	BURLINGTON ON	223.3	64

NPR2 - National Pollutant Release Inventory 1993-2020

A search of the NPR2 database, dated Sep 2020 has found that there are 3 NPR2 site(s) within approximately 0.30 kilometers of the

project property.

Site	Address	Distance (m)	Map Key
BURLINGTON PLANT	942 BRANT ST., 942 BRANT STREET BURLINGTON ON	222.3	61
BURLINGTON PLANT	942 BRANT STREET BURLINGTON ON L7R3X8	222.3	61
BURLINGTON PLANT SITE	942 BRANT STREET BURLINGTON ON L7R2J7	222.3	61

PES - Pesticide Register

A search of the PES database, dated Oct 2011- Nov 30, 2023 has found that there are 6 PES site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
MCCONNELL-SPADAFORA INC	850 LEGION RD, UNIT 4 BURLINGTON ON L7S 1T5	78.7	17
MCCONNELL-SPADAFORA INC	850 LEGION RD, UNIT 4 BURLINGTON ON L7S1T5	78.7	17
MCCONNELL-SPADAFORA INC	850 LEGION RD, UNIT #4 BURLINGTON ON L7S 1T5	78.7	17
PETS & GARDENS LTD	834 BRANT ST BURLINGTON ON L7R2J5	175.8	49
PETS & GARDENS LTD	834 BRANT ST BURLINGTON ON L7R 2J5	175.8	49
CANADA PEST CONTROL	1-2004 MAPLEWOOD DR BURLINGTON ON L7R2C4	248.5	72

PRT - Private and Retail Fuel Storage Tanks

A search of the PRT database, dated 1989-1996* has found that there are 6 PRT site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
PETRO CANADA PRODUCTS C/O BURLINGTON BULK PLANT J	1380 GRAHAMS LA BURLINGTON ON L7S1W3	40.0	10
JOHN EBOS FUELS LTD	1380 GRAHAMS LA BURLINGTON ON L7S 1W3	40.0	10
845275 ONTARIO INC	1448 GRAHAMS LA BURLINGTON ON L7S1W3	147.9	40
LAMONTS SERVICES LTD	809 BRANT ST BURLINGTON ON L7R2J4	248.9	75
CLARES SHELL & CAR WASH INC	809 BRANT ST BURLINGTON ON L7R 2J4	248.9	75
ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE	892 BRANT ST BURLINGTON ON L7R 2J5	288.9	89

RSC - Record of Site Condition

A search of the RSC database, dated 1997-Sept 2001, Oct 2004-Nov 2023 has found that there are 1 RSC site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
WELLINGTON PARK CARE CENTRE FACILITY INC.	802 HAGER AVENUE, BURLINGTON, ON L7S 1X2 Burlington ON	128.9	35

RST - Retail Fuel Storage Tanks

A search of the RST database, dated 1999-Oct 31, 2023 has found that there are 6 RST site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
EBOS JOHN FUELS A DIV OF PETRO PARTNERS LTD	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	40.0	10
FREW ENERGY	1380 GRAHAMS LANE BURLINGTON ON L7S1W3	40.0	10
LIPPERT & WRIGHT FUELS	1380 GRAHAMS LANE BURLINGTON ON L7S1W3	40.0	10
FREW ENERGY	1380 GRAHAMS LANE BURLINGTON ON L7S1W3	40.0	10
EBOS JOHN FUELS LTD	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	40.0	10
JOHN EBOS FUELS	1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	40.0	10

SCT - Scott's Manufacturing Directory

A search of the SCT database, dated 1992-Mar 2011* has found that there are 36 SCT site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
WALKER MAGNETICS NATIONAL LTD.	1393 GRAHAMS LANE BURLINGTON ON L7S 1W4	0.0	1
UNITED STATES ALUMINUM OF CDA	1393 Grahams Lane Burlington ON L7S 1W4	0.0	1
United States Aluminum of Canada-Ontario Ltd.	1393 Grahams Lane Burlington ON L7S 1W4	0.0	1
National Specialty Cakes Inc.	1423 Grahams Lane Burlington ON L7S 1W4	34.8	9

Site	Address	Distance (m)	Map Key
NSC Cakes Inc.	1423 Grahams Lane Burlington ON L7S 1W4	34.8	9
Arctic Traveler (Canada) Ltd.	1416 Grahams Lane Burlington ON L7S 1W3	71.3	15
TECKMARK LABEL SYSTEMS INC.	850 LEGION RD UNIT 23 BURLINGTON ON L7S 1T5	78.7	17
K L B INTERIORS INC	850 LEGION RD UNIT 5 BURLINGTON ON L7S 1T5	78.7	17
Artisan Design	850 Legion Rd Unit 1-3 Burlington ON L7S 1T5	78.7	17
MERIDIAN GOLF (2000) INC.	850 LEGION RD UNIT 14 BURLINGTON ON L7S 1T5	78.7	17
HIBON INC.	850 LEGION RD UNIT 3 BURLINGTON ON L7S 1T5	78.7	17
WOODCRAFT RAIL INC.	850 Legion Rd Unit 15 Burlington ON L7S 1T5	78.7	17
KLB Interiors Inc.	850 Legion Rd Unit 5 Burlington ON L7S 1T5	78.7	17
Teckmark Label Systems Inc.	850 Legion Rd Unit 23 Burlington ON L7S 1T5	78.7	17
B-LINE CRESTING	850 Legion Rd Unit 7 Burlington ON L7S 1T5	78.7	17

Site	Address	Distance (m)	Map Key
Rea/Co Inc.	850 Legion Rd Unit 18 Burlington ON L7S 1T5	78.7	17
Fry Graphics Ltd.	850 Legion Rd Unit 6 Burlington ON L7S 1T5	78.7	17
Burlington Letterpress	850 Legion Rd Unit 11 Burlington ON L7S 1T5	78.7	17
McConnell-Spadafora Inc.	850 Legion Rd Unit 4 Burlington ON L7S 1T5	78.7	17
Multi-Line Products Inc.	850 Legion Rd Unit 9 Burlington ON L7S 1T5	78.7	17
Scherzinger Pump Technology	1440 Grahams Lane Unit 3 Burlington ON L7S 1W3	88.7	20
THYSSEN DOVER ELEVATORS	1440 GRAHAMS LANE UNIT 3 BURLINGTON ON L7S 1W3	88.7	20
DOVER CORPORATION CANADA LTD	1440 GRAHAMS LANE UNIT 3 BURLINGTON ON L7S 1W3	88.7	20
BURLINGTON LAMINATING & BINDER	1440 GRAHAMS LANE UNIT 2 BURLINGTON ON L7S 1W3	88.7	20
Peters Steel Rule Dies	1440 Grahams Lane Unit 6-7 Burlington ON L7S 1W3	88.7	20
ENDRESS + HAUSER CANADA LTD	1440 GRAHAMS LANE UNIT 1 BURLINGTON ON L7S 1W3	88.7	20
Endress + Hauser Canada Ltd.	1440 Grahams Lane Unit 1 Burlington ON L7S 1W3	88.7	20

Site	Address	Distance (m)	Map Key
Thyssen Krupp Elevator Limited	1440 Grahams Lane Unit 3 Burlington ON L7S 1W3	88.7	20
Magnus Chemicals Ltd.	1440 Grahams Lane Unit 5 Burlington ON L7S 1W3	88.7	20
Pyramid Pumps	1440 Grahams Lane Unit 3 Burlington ON L7S 1W3	88.7	20
Scherzinger Pump Technology Inc.	1440 Grahams Lane Unit 3 Burlington ON L7S 1W3	88.7	20
Peters Steel Rule Dies Ltd.	1440 Grahams Lane Unit 6-7 Burlington ON L7S 1W3	88.7	20
Ashland Canada Corp.	942 Brant St Burlington ON L7R 2J7	223.3	64
Advanced Integrated Resources	817 Brant St Burlington ON L7R 2J4	248.3	71
Advanced Integrated Resources Inc.	817 Brant St Burlington ON L7R 2J4	248.3	71
American Optics Inc.	789 Brant St Burlington ON L7R 2J3	277.9	82

SPL - Ontario Spills

A search of the SPL database, dated 1988-Dec 2021; see description has found that there are 38 SPL site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
John Ebos Fuels Limited	1380 Grahams Lane Burlington ON L7S 1W3	40.0	10
HERCULES CANADA INC.	850 LEGION RD/SOUTH OF FAIRVIEW AVE. BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7S 1T5	78.7	17
HARMAC TRANSPORTATION	808 BRANT ST. TANK TRUCK (CARGO) BURLINGTON CITY ON	184.3	51
HERCULES CANADA INC.	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	223.3	64
HERCULES CANADA INC.	BRANT ST/PLAINS RD INTERSECTION. BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON	223.3	64
HERCULES CANADA INC.	942 BRANT ST BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	223.3	64
Hercules Canada Inc.	942 Brant Street Burlington ON L7R 2J7	223.3	64
Hercules Canada Inc.	942 Brant Street Burlington ON L7R 2J7	223.3	64
Hercules Canada Inc.	942 Brant Street Burlington ON L7R 2J7	223.3	64
Hercules Canada Inc.	942 Brant Street Burlington ON L7R 2J7	223.3	64
942 Brant Street	942 Brant Street Burlington ON	223.3	64
Hercules Canada Inc.	942 Brant St. Burlington Burlington ON L7R 2J7	223.3	64

Site	Address	Distance (m)	Map Key
Hercules Canada Inc.	942 Brant St Burlington; Burlington ON L7R 2J7	223.3	64
Solenis Canada ULC	942 Brant St Burlington ON L7R 2J7	223.3	64
HERCULES CANADA INC.	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	223.3	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	223.3	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	223.3	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	223.3	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	223.3	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	223.3	64
HERCULES CANADA	BOILER STACK BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON	223.3	64
HERCULES CANADA	HOLDING TANK BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON	223.3	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	223.3	64

Site	Address	Distance (m)	Map Key
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	223.3	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	223.3	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	223.3	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	223.3	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	223.3	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	223.3	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	223.3	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	223.3	64
Union Gas Limited	753 Hagar Avenue Burlington ON	247.4	70
SHELL CANADA PRODUCTS LTD.	809 BRANT STREET. SERVICE STATION BURLINGTON CITY ON L7R 2J4	248.9	75
Union Gas Limited	809 Brant St Burlington ON	248.9	75
ALCHEM	BRANT & FAIRVIEW RAMBO CREEK BURLINGTON PLANT 1055 TRUMAN STREET BURLINGTON CITY ON	299.5	96

Site	Address	Distance (m)	Map Key
	Fairview and Brant Burlington ON	299.5	96
	cb at Brant Street and Fairview Street Burlington ON	299.5	96
	intersection of Fairview St. and Brant St. Burlington ON	299.5	96

WWIS - Water Well Information System


A search of the WWIS database, dated Mar 31 2023 has found that there are 35 WWIS site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	1416 GRAHAM LN Burlington ON ***Well ID:*** 7314898	7.7	3
	1380 GRAHAM'S LANE Burlington ON ***Well ID:*** 7179514	23.7	4
	1380 GRAHAM'S LANE Burlington ON ***Well ID:*** 7179515	25.2	5
	ON ***Well ID:*** 7291911	30.5	6
	1380 GRAHAM'S LANE Burlington ON ***Well ID:*** 7179516	40.0	10
	1380 GRAHAM'S LANE Burlington ON ***Well ID:*** 7179605	41.4	11

Site	Address	Distance (m)	Map Key
	1380 GRAHAM'S LANE BURLINGTON ON ***Well ID:*** 2810308	74.5	16
	BURLINGTON ON ***Well ID:*** 2810214	87.4	19
	1380 GRAHAM'S LANE BURLINGTON ON ***Well ID:*** 2810171	89.8	21
	802 Hagar Ave Burlington ON ***Well ID:*** 7354371	95.5	24
	802 Hager Ave Burlington ON ***Well ID:*** 7354375	110.8	25
	439 Graham's Lane Burlington ON ***Well ID:*** 7343297	112.6	26
	850 Brant Street Burlington ON ***Well ID:*** 7330856	116.9	27
	1439 Graham's Lane Burlington ON ***Well ID:*** 7343299	128.8	34
	439 Graham's Lane Burlington ON ***Well ID:*** 7343298	131.6	37
	802 HAGER AVE BURLINGTON ON ***Well ID:*** 7042731	155.9	41
	770 HAGGAR AV E Burlington ON ***Well ID:*** 7284939	163.4	42
	770 HAGGER AVE Burlington ON	163.6	43

Site	Address	Distance (m)	Map Key
	Well ID: 7284940		
	850 BRANT ST Burlington ON ***Well ID:*** 7330855	163.8	44
	850 Brant Street Burlington ON ***Well ID:*** 7330854	164.8	45
	850 Brant St Burlington ON ***Well ID:*** 7330859	164.8	46
	ON ***Well ID:*** 7387995	183.9	50
	ON ***Well ID:*** 7369395	194.8	54
	1380 GRAHAMS LANE BURLINGTON ON ***Well ID:*** 7047125	197.4	55
	850 Brant Street Burlington ON ***Well ID:*** 7330858	201.2	57
	ON ***Well ID:*** 7387994	208.8	58
	ON ***Well ID:*** 7387993	220.9	60
	280 BRANT ST Burlington ON ***Well ID:*** 7331850	222.5	62
	850 BRANT ST Burlington ON ***Well ID:*** 7330857	238.8	67

Site	Address	Distance (m)	Map Key
	ON ***Well ID:*** 7369392	244.0	68
	ON ***Well ID:*** 7369396	248.7	73
	ON ***Well ID:*** 7374925	261.2	78
	849 BRANT ST Burlington ON ***Well ID:*** 7292316	277.0	81
	ON ***Well ID:*** 7369394	288.2	87
	ON ***Well ID:*** 7376950	288.4	88



Map: 0.3 Kilometer Radius

Order Number: 24011900269


Address: 1393 Grahams Lane, Burlington, ON

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership

79°49'30"W



43°19'30"N

43°19'30"N


Aerial **Year: 2021**

Order Number: 24011900269

Address: 1393 Grahams Lane, Burlington, ON

Source: ESRI World Imagery

© ERIS Information Limited Partnership



Topographic Map

Address: 1393 Grahams Lane, ON

Source: ESRI World Topographic Map

Order Number: 24011900269

© ERIS Information Limited Partnership

Detail Report

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	1 of 12	ESE/0.0	94.8 / 0.00	WALKER MAGNETICS NATIONAL LTD. 1393 GRAHAMS LANE BURLINGTON ON L7S 1W4	SCT

Established: 1978
Plant Size (ft²): 20000
Employment: 16

--Details--
Description: SPECIAL INDUSTRY MACHINERY, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3559

Description: RELAYS AND INDUSTRIAL CONTROLS
SIC/NAICS Code: 3625

Description: ELECTRICAL INDUSTRIAL APPARATUS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3629

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	2 of 12	ESE/0.0	94.8 / 0.00	UNITED STATES ALUMINUM OF CDA 1393 Grahams Lane Burlington ON L7S 1W4	SCT

Established: 1994
Plant Size (ft²): 22000
Employment: 15

--Details--
Description: Metal Window and Door Manufacturing
SIC/NAICS Code: 332321

Description: Other Ornamental and Architectural Metal Products Manufacturing
SIC/NAICS Code: 332329

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	3 of 12	ESE/0.0	94.8 / 0.00	United States Aluminum of Canada-Ontario Ltd. 1393 Grahams Lane Burlington ON L7S 1W4	SCT

Established: 1994
Plant Size (ft²): 22000
Employment: 25

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	4 of 12	ESE/0.0	94.8 / 0.00	MCGRAW EDISON NAT. ELECT. COIL 1393 GRAHAM'S LANE BURLINGTON ON L7S 1W4	GEN

Generator No: ON0120201
SIC Code: 3379
SIC Description: OTHER ELECT. EQUIP.
Approval Years: 86,87,88

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	5 of 12	ESE/0.0	94.8 / 0.00	MCGRAW (SEE&USE ON1234100) NAT. ELECT. COIL 1393 GRAHAM'S LANE BURLINGTON ON L7S 1W4	GEN

Generator No: ON0120201
SIC Code: 3379
SIC Description: OTHER ELECT. EQUIP.
Approval Years: 89,90,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	6 of 12	ESE/0.0	94.8 / 0.00	MCGRAW (SEE&USE ON1234100) 26-115 NAT. ELECT. COIL 1393 GRAHAM'S LANE BURLINGTON ON L7S 1W4	GEN

Generator No: ON0120201
SIC Code: 3379
SIC Description: OTHER ELECT. EQUIP.
Approval Years: 92,93,94,95,96,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	7 of 12	ESE/0.0	94.8 / 0.00	WALKER MAGNETICS NATIONAL LTD. 1393 GRAHAMS LANE	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				BURLINGTON ON L7S 1W4	

Generator No: ON1234100
SIC Code: 3379
SIC Description: OTHER ELECT. EQUIP.
Approval Years: 89
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

1	***8 of 12***	***ESE/0.0***	***94.8 / 0.00***	***WALKER MAGNETICS NATIONAL LTD. 26-115*** ***1393 GRAHAMS LANE*** ***BURLINGTON ON L7S 1W4***	***GEN***

Generator No: ON1234100
SIC Code: 3379
SIC Description: OTHER ELECT. EQUIP.
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

1	***9 of 12***	***ESE/0.0***	***94.8 / 0.00***	***1393 Grahams Lane*** ***Burlington ON L7S 1W4***	***EHS***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Order No: 22083004077
Status: C
Report Type: Standard Report
Report Date: 02-SEP-22
Date Received: 30-AUG-22
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8129962
Y: 43.3324406

1	10 of 12	ESE/0.0	94.8 / 0.00	1393 Grahams Lane Burlington ON L7S 1W4	EHS

Order No: 22083004077
Status: C
Report Type: Standard Report
Report Date: 02-SEP-22
Date Received: 30-AUG-22
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8129962
Y: 43.3324406

1	11 of 12	ESE/0.0	94.8 / 0.00	1393 Grahams Lane Burlington ON L7S 1W4	EHS

Order No: 22083004077
Status: C
Report Type: Standard Report
Report Date: 02-SEP-22
Date Received: 30-AUG-22
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8129962
Y: 43.3324406

1	12 of 12	ESE/0.0	94.8 / 0.00	1393 Grahams Lane Burlington ON L7S 1W4	EHS

Order No: 22083004077
Status: C
Report Type: Standard Report
Report Date: 02-SEP-22
Date Received: 30-AUG-22
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8129962
Y: 43.3324406

2	1 of 1	ESE/0.0	94.8 / 0.00	1393 Grahams Lane Burlington ON L7S 1W4	EHS

Order No: 20190618226
Status: C
Report Type: Standard Report
Report Date: 25-JUN-19
Date Received: 18-JUN-19
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.812927
Y: 43.332409

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
3	1 of 1	E/7.7	94.3 / -0.52	1416 GRAHAM LN Burlington ON	WWIS

Well ID: 7314898
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z261607
Tag: A193556
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 07/19/2018
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7484
Form Version: 7
Owner:
County: HALTON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 07/04/2018
Year Completed: 2018
Depth (m): 4.572
Latitude: 43.3327389169928
Longitude: -79.8121626826306
Path:

Bore Hole Information

Bore Hole ID: 1007188815
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 07/04/2018
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 596295.00
North83: 4798451.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1007265296
Layer: 3
Color: 6
General Color: BROWN

Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Mat2 Desc:	SILT
Mat3:	
Mat3 Desc:	
Formation Top Depth:	13.0
Formation End Depth:	15.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1007265294
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	01
Mat3 Desc:	FILL
Formation Top Depth:	0.0
Formation End Depth:	3.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1007265295
Layer:	2
Color:	8
General Color:	BLACK
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Mat2 Desc:	SILT
Mat3:	01
Mat3 Desc:	FILL
Formation Top Depth:	3.0
Formation End Depth:	13.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1007265304
Layer:	2
Plug From:	9.0
Plug To:	15.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1007265303
Layer:	1
Plug From:	0.0
Plug To:	9.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1007265302
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	AUGER

Pipe Information

Pipe ID:	1007265293
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007265299
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	10.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1007265300
Layer:	1
Slot:	.01
Screen Top Depth:	10.0
Screen End Depth:	15.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.5

Water Details

Water ID:	1007265298
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1007265297
Diameter:	6.0
Depth From:	0.0
Depth To:	15.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1007188815	***Tag No:***	A193556
Depth M:	4.572	***Contractor:***	7484

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Year Completed:	2018	**Latitude:**	43.3327389169928
Well Completed Dt:	07/04/2018	**Longitude:**	-79.8121626826306
Audit No:	Z261607	**Y:**	43.33273891476214
Path:	731\7314898.pdf	**X:**	-79.81216253441498

4 **1 of 1** **SE/23.7** **94.8 / 0.00** **1380 GRAHAM'S LANE**
Burlington ON **WWIS**

Well ID:	7179514	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	04/17/2012
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z142478	**Contractor:**	7241
Tag:	A097677	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7179514.pdf

Additional Detail(s) (Map)

Well Completed Date:	01/19/2012
Year Completed:	2012
Depth (m):	5.1
Latitude:	43.3320170033901
Longitude:	-79.812879857498
Path:	717\7179514.pdf

Bore Hole Information

Bore Hole ID:	1003711328	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596238.00
Code OB Desc:		**North83:**	4798370.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	01/19/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004248558
Layer:	1
Color:	8
General Color:	BLACK
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	85
Mat3 Desc:	SOFT
Formation Top Depth:	0.0
Formation End Depth:	0.10000000149011612
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004248560
Layer:	3
Color:	7
General Color:	RED
Mat1:	06
Most Common Material:	SILT
Mat2:	08
Mat2 Desc:	FINE SAND
Mat3:	85
Mat3 Desc:	SOFT
Formation Top Depth:	1.0
Formation End Depth:	3.0
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004248561
Layer:	4
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	
Mat2 Desc:	
Mat3:	73
Mat3 Desc:	HARD
Formation Top Depth:	3.0
Formation End Depth:	5.099999904632568
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004248559
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	85
Mat3 Desc:	SOFT
Formation Top Depth:	0.10000000149011612
Formation End Depth:	1.0

Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004248569
Layer: 1
Plug From: 0.0
Plug To: 0.3100000023841858
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004248570
Layer: 2
Plug From: 0.3100000023841858
Plug To: 1.7999999523162842
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004248571
Layer: 3
Plug From: 1.7999999523162842
Plug To: 5.099999904632568
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004248568
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1004248557
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004248564
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 2.0999999046325684
Casing Diameter: 5.199999809265137
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004248565
Layer: 1

Slot:	10
Screen Top Depth:	2.0999999046325684
Screen End Depth:	5.099999904632568
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.159999847412109

Water Details

Water ID:	1004248563
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004248562
Diameter:	20.0
Depth From:	0.0
Depth To:	5.099999904632568
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	1003711328	**Tag No:**	A097677
Depth M:	5.1	**Contractor:**	7241
Year Completed:	2012	**Latitude:**	43.3320170033901
Well Completed Dt:	01/19/2012	**Longitude:**	-79.812879857498
Audit No:	Z142478	**Y:**	43.33201700032168
Path:	717\7179514.pdf	**X:**	-79.81287970785101

5 | ***1 of 1*** | ***SSE/25.2*** | ***94.8 / 0.00*** | ***1380 GRAHAM'S LANE Burlington ON*** | ***WWIS***

Well ID:	7179515	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	04/17/2012
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z142479	**Contractor:**	7241
Tag:	A097676	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7179515.pdf

Additional Detail(s) (Map)

Well Completed Date: 01/19/2012
Year Completed: 2012
Depth (m): 5.1
Latitude: 43.3319457504325
Longitude: -79.8129552563012
Path: 717\7179515.pdf

Bore Hole Information

Bore Hole ID: 1003711331
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 01/19/2012
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 596232.00
North83: 4798362.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1004248576
Layer: 4
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2: 34
Mat2 Desc: TILL
Mat3: 73
Mat3 Desc: HARD
Formation Top Depth: 3.0
Formation End Depth: 5.099999904632568
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004248573
Layer: 1
Color: 8
General Color: BLACK
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3: 85
Mat3 Desc: SOFT
Formation Top Depth: 0.0
Formation End Depth: 0.10000000149011612
Formation End Depth UOM: m

Overburden and Bedrock

Materials Interval

Formation ID:	1004248574
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	85
Mat3 Desc:	SOFT
Formation Top Depth:	0.10000000149011612
Formation End Depth:	1.0
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004248575
Layer:	3
Color:	7
General Color:	RED
Mat1:	08
Most Common Material:	FINE SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	85
Mat3 Desc:	SOFT
Formation Top Depth:	1.0
Formation End Depth:	3.0
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004248586
Layer:	3
Plug From:	1.7999999523162842
Plug To:	5.099999904632568
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004248584
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004248585
Layer:	2
Plug From:	0.3100000023841858
Plug To:	1.7999999523162842
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID: 1004248583
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1004248572
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004248579
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 2.0999999046325684
Casing Diameter: 5.199999809265137
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004248580
Layer: 1
Slot: 10
Screen Top Depth: 2.0999999046325684
Screen End Depth: 5.099999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.099999904632568

Water Details

Water ID: 1004248578
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004248577
Diameter: 20.0
Depth From: 0.0
Depth To: 5.099999904632568
Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Bore Hole ID: 1003711331
Depth M: 5.1
Year Completed: 2012
Well Completed Dt: 01/19/2012
Tag No: A097676
Contractor: 7241
Latitude: 43.3319457504325
Longitude: -79.8129552563012

Audit No:	Z142479	**Y:**	43.33194574757449
Path:	717\7179515.pdf	**X:**	-79.8129551070284

6 **1 of 1** **SSE/30.5** **94.8 / 0.00** **ON** **WWIS**

Well ID:	7291911	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	08/02/2017
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	C31093	**Contractor:**	6607
Tag:	A224440	**Form Version:**	8
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	06/12/2017
Year Completed:	2017
Depth (m):	
Latitude:	43.3318117350078
Longitude:	-79.8130565475863
Path:	

Bore Hole Information

Bore Hole ID:	1006696174	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596224.00
Code OB Desc:		**North83:**	4798347.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	06/12/2017	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1006696174	**Tag No:**	A224440
Depth M:		**Contractor:**	6607
Year Completed:	2017	**Latitude:**	43.3318117350078

Well Completed Dt:	06/12/2017	**Longitude:**	-79.8130565475863
Audit No:	C31093	**Y:**	43.331811732458185
Path:		**X:**	-79.8130563992428

7 **1 of 1** **WNW/33.1** **94.4 / -0.49** **ON** **BORE**

Borehole ID:	623977	**Inclin FLG:**	No
OGF ID:	215524429	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	MAY-1968	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.332959
Total Depth m:	12.2	**Longitude DD:**	-79.814631
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	596095
Drill Method:	Power auger	**Northing:**	4798473
Orig Ground Elev m:	95.6	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	94		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218431699	**Mat Consistency:**	Hard
Top Depth:	.5	**Material Moisture:**	
Bottom Depth:	9.1	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:	Gravel	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,CLAY, GRAVEL. BROWN,GLACIAL,VERY HARD, AGE GLACIAL.		

Geology Stratum ID:	218431698	**Mat Consistency:**	Compact
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.5	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Gravel	**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SILT,SAND,GRAVEL. BROWN,COMPACT.		

Geology Stratum ID:	218431700	**Mat Consistency:**	
Top Depth:	9.1	**Material Moisture:**	
Bottom Depth:	12.2	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. WEATHERED, AGE UNDIFFERENTIATED. 017012034000000200001510000005501502 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	H	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: HAM.txt RecordID: 029770 NTS_Sheet: 30M05C
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		

Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

8 ***1 of 3*** ***ESE/33.5*** ***94.2 / -0.68*** ***Smit Autobody***
1400 Graham's Lane Burlington Ontario L7S 1W3
Burlington
ON ***EBR***

EBR Registry No:	IA02E1287	***Decision Posted:***	
Ministry Ref No:	5390-5EHSWP	***Exception Posted:***	
Notice Type:	Instrument Decision	***Section:***	
Notice Stage:		***Act 1:***	
Notice Date:	August 01, 2003	***Act 2:***	
Proposal Date:	October 21, 2002	***Site Location Map:***	
Year:	2002		

Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Smit Autobody
Site Address:
Location Other:
Proponent Name:
Proponent Address: 1400 Graham's Lane, Burlington Ontario, L7S 1W3
Comment Period:
URL:

Site Location Details:

1400 Graham's Lane Burlington Ontario L7S 1W3 Burlington

---

8 ***2 of 3*** ***ESE/33.5*** ***94.2 / -0.68*** ***Smit Autobody***
1400 Graham's Lane
Burlington ON ***CA***

Certificate #: 2361-5PFQ9L
Application Year: 2003
Issue Date: 7/29/2003
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Project Description:
Contaminants:
Emission Control:

---

8 | ***3 of 3*** | ***ESE/33.5*** | ***94.2 / -0.68*** | ***Smit Autobody*** | ***ECA***
1400 Graham's Lane
Burlington ON L7S 1W3

Approval No:	2361-5PFQ9L	***MOE District:***	Halton-Peel
Approval Date:	2003-07-29	***City:***	
Status:	Approved	***Longitude:***	-79.81074
Record Type:	ECA	***Latitude:***	43.3336
Link Source:	IDS	***Geometry X:***	
SWP Area Name:	Halton	***Geometry Y:***	

Approval Type: ECA-AIR
Project Type: AIR
Business Name: Smit Autobody
Address: 1400 Graham's Lane
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/5390-5EHSWP-14.pdf
PDF Site Location:

---

9 | ***1 of 2*** | ***ENE/34.8*** | ***94.7 / -0.19*** | ***National Specialty Cakes Inc.*** | ***SCT***
1423 Grahams Lane
Burlington ON L7S 1W4

Established: 1996
Plant Size (ft²):
Employment: 6

--Details--
Description: Commercial Bakeries and Frozen Bakery Product Manufacturing
SIC/NAICS Code: 311814

Description: Cookie and Cracker Manufacturing
SIC/NAICS Code: 311821

---

9 | ***2 of 2*** | ***ENE/34.8*** | ***94.7 / -0.19*** | ***NSC Cakes Inc.*** | ***SCT***
1423 Grahams Lane
Burlington ON L7S 1W4

Established: 1996
Plant Size (ft²):
Employment: 6

--Details--
Description: Retail Bakeries
SIC/NAICS Code: 311811

Description: Commercial Bakeries and Frozen Bakery Product Manufacturing
SIC/NAICS Code: 311814

Description: Cookie and Cracker Manufacturing
SIC/NAICS Code: 311821

---

10 | ***1 of 59*** | ***SE/40.0*** | ***94.8 / 0.00*** | ***JOHN EBOS FUELS LTD*** | ***PRT***
1380 GRAHAMS LA

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				BURLINGTON ON L7S 1W3	

Location ID: 2417
Type: private
Expiry Date:
Capacity (L): 36330.00
Licence #: 0001048745

10	2 of 59	SE/40.0	94.8 / 0.00	PETRO CANADA PRODUCTS C/O BURLINGTON BULK PLANT J 1380 GRAHAMS LA BURLINGTON ON L7S1W3	PRT

Location ID: 2417
Type: retail
Expiry Date: 1996-03-31
Capacity (L): 0
Licence #: 0015515438

10	3 of 59	SE/40.0	94.8 / 0.00	EBOS JOHN FUELS LTD 1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	RST

Headcode: 924800
Headcode Desc: Oils-Fuel
Phone: 9055288449
List Name:
Description:

10	4 of 59	SE/40.0	94.8 / 0.00	EBOS JOHN FUELS A DIV OF PETRO PARTNERS LTD 1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	RST

Headcode: 924800
Headcode Desc: Oils-Fuel
Phone: 9056370033
List Name:
Description:

10	5 of 59	SE/40.0	94.8 / 0.00	PETRO-CANADA PRODUCTS 1380 GRAHAM'S LANE BURLINGTON C/O 5140 YONGE STREET SUITE 200 NORTH YORK ON L7S 1W3	GEN

Generator No: ON1014924
SIC Code: 5111
SIC Description: PETROLEUM PROD., WH.
Approval Years: 88,89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

10 | ***6 of 59*** | ***SE/40.0*** | ***94.8 / 0.00*** | ***PETRO-CANADA PRODUCTS***
1380 GRAHAM'S LANE
BURLINGTON ON L7S 1W3 | ***GEN***

Generator No: ON1014924
SIC Code: 5111
SIC Description: PETROLEUM PROD., WH.
Approval Years: 92,93,97,98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

10 | ***7 of 59*** | ***SE/40.0*** | ***94.8 / 0.00*** | ***PETRO-CANADA PRODUCTS 30-464***
1380 GRAHAM'S LANE BURLINGTON C/O 5140
YONGE STREET SUITE 200
NORTH YORK ON L7S 1W3 | ***GEN***

Generator No: ON1014924
SIC Code: 5111
SIC Description: PETROLEUM PROD., WH.
Approval Years: 94,95,96
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

10 | ***8 of 59*** | ***SE/40.0*** | ***94.8 / 0.00*** | ***JOHN EBOS FUELS LIMITED 22-460***
1380 GRAHAMS LANE
BURLINGTON ON L7S 1W3 | ***GEN***

Generator No: ON1446200
SIC Code: 3611
SIC Description: REFINED PETRO. PROD.
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

10	*9 of 59*	*SE/40.0*	*94.8 / 0.00*	***JOHN EBOS FUELS LIMITED*** ***1380 GRAHAMS LANE*** ***BURLINGTON ON L7S 1W3***	***GEN***

Generator No: ON1446200
SIC Code: 3611
SIC Description: REFINED PETRO. PROD.
Approval Years: 99,00,01,02
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

10	*10 of 59*	*SE/40.0*	*94.8 / 0.00*	***JOHN EBOS FUELS, A DIVISION OF PETRO PARTNERS LTD.*** ***1380 GRAHAMS LANE*** ***BURLINGTON ON***	***GEN***

Generator No: ON1446200
SIC Code: 419120
SIC Description: Petroleum Product Agents & Brokers
Approval Years: 03,04
PO Box No:
Country:
Status:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

10	11 of 59	SE/40.0	94.8 / 0.00	***Petro-Canada Retail Development Centres (Central)*** ***1380 GRAHAMS LANE*** ***BURLINGTON ON L7S 1W3***	***GEN***

Generator No: ON1446200
SIC Code: 419120
SIC Description: Petroleum Product Agents and Brokers
Approval Years: 05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

10	12 of 59	SE/40.0	94.8 / 0.00	***JOHN EBOS FUELS*** ***1380 GRAHAMS LANE*** ***BURLINGTON ON L7S 1W3***	***RST***

Headcode: 00924800
Headcode Desc: OILS-FUEL
Phone:
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	13 of 59	SE/40.0	94.8 / 0.00	John Ebos Fuels Limited 1380 Grahams Lane Burlington ON L7S 1W3	SPL

Ref No: 5663-7D6J79
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/28/2008
Dt Document Closed: 4/14/2008
Site No:
Facility Name:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: John Ebos Fuels Limited
Site Address:
Site Region:
Site Municipality: Burlington
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: NA
Easting: NA
Incident Cause:
Incident Event:
Environment Impact: Confirmed
Nature of Impact:
Contaminant Qty: 200 L
System Facility Address:
Client Name: John Ebos Fuels Limited
Client Type:
Call Report Locatn Geodata:
Contaminant Code: 15
Contaminant Name: LUBRICATING OIL/GREASE
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Receiving Environment:
Incident Reason:
Incident Summary: John Ebos Fuels: spill lub oil to grnd, clng
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Other Storage Facility
SAC Action Class: Land Spills
Source Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	14 of 59	SE/40.0	94.8 / 0.00	Petro Canada 1380 Grahams Lane Burlington ON L7S 1W3	GEN

Generator No: ON2645903
SIC Code: 447110
SIC Description: Gasoline Stations with Convenience Stores
Approval Years: 07,08
PO Box No:
Country:
Status:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

10	15 of 59	SE/40.0	94.8 / 0.00	FREW PETROLEUM CORPORATION 1380 GRAHAMS LANE BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 10491707
Status: EXPIRED
Instance ID: 24885
Instance Type: FS Highway Tank - Gas/Diesel
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

10	16 of 59	SE/40.0	94.8 / 0.00	PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD 1380 GRAHAMS LANE BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 10492860

Expired Date:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	24836	**Facility Location:**	
Instance Type:	FS Highway Tank - Gas/Diesel	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS HIGHWAY TANK - GASOLINE/DIESEL		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

10	17 of 59	SE/40.0	94.8 / 0.00	**FREW PETROLEUM CORPORATION** **1380 GRAHAMS LANE** **BURLINGTON ON**	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10491720	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	25395	**Facility Location:**	
Instance Type:	FS Highway Tank - Gas/Diesel	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS HIGHWAY TANK - GASOLINE/DIESEL		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Original Source:		EXP			
Record Date:		Up to Mar 2012			

10	18 of 59	SE/40.0	94.8 / 0.00	FREW PETROLEUM CORPORATION 1380 GRAHAMS LANE BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10456754	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	17667	**Facility Location:**	
Instance Type:	FS Highway Tank - Gas/Diesel	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS HIGHWAY TANK - GASOLINE/DIESEL		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

10	19 of 59	SE/40.0	94.8 / 0.00	FREW PETROLEUM CORPORATION 1380 GRAHAMS LANE BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10458087	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	17806	**Facility Location:**	
Instance Type:	FS Highway Tank - Gas/Diesel	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Original Source: EXP
Record Date: Up to Mar 2012

10	***20 of 59***	***SE/40.0***	***94.8 / 0.00***	***FREW PETROLEUM CORPORATION*** ***1380 GRAHAMS LANE*** ***BURLINGTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10458683 ***Expired Date:***
Status: EXPIRED ***Max Hazard Rank:***
Instance ID: 17931 ***Facility Location:***
Instance Type: FS Highway Tank - Gas/Diesel ***Facility Type:***
Instance Creation Dt: ***Fuel Type 2:***
Instance Install Dt: ***Fuel Type 3:***
Item Description: ***Panam Related:***
Manufacturer: ***Panam Venue Nm:***
Model: ***External Identifier:***
Serial No: ***Item:***
ULC Standard: ***Piping Steel:***
Quantity: ***Piping Galvanized:***
Unit of Measure: ***Tank Single Wall St:***
Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Original Source: EXP
Record Date: Up to Mar 2012

10	***21 of 59***	***SE/40.0***	***94.8 / 0.00***	***PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD*** ***1380 GRAHAMS LANE*** ***BURLINGTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance No:	10451239	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	18156	**Facility Location:**	
Instance Type:	FS Highway Tank - Gas/Diesel	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS HIGHWAY TANK - GASOLINE/DIESEL		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

10	22 of 59	SE/40.0	94.8 / 0.00	**FREW PETROLEUM CORPORATION** **1380 GRAHAMS LANE** **BURLINGTON ON**	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10454836	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	17896	**Facility Location:**	
Instance Type:	FS Highway Tank - Gas/Diesel	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Description:		FS HIGHWAY TANK - GASOLINE/DIESEL			
Original Source:		EXP			
Record Date:		Up to Mar 2012			

10	23 of 59	SE/40.0	94.8 / 0.00	FREW PETROLEUM CORPORATION 1380 GRAHAMS LANE BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10456746	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	18375	**Facility Location:**	
Instance Type:	FS Highway Tank - Gas/Diesel	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS HIGHWAY TANK - GASOLINE/DIESEL		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

10	24 of 59	SE/40.0	94.8 / 0.00	FREW PETROLEUM CORPORATION 1380 GRAHAMS LANE BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10456764	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	18729	**Facility Location:**	
Instance Type:	FS Highway Tank - Gas/Diesel	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Piping Underground:
Tank Underground:
Source:
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Original Source: EXP
Record Date: Up to Mar 2012

10	25 of 59	SE/40.0	94.8 / 0.00	FREW PETROLEUM CORPORATION 1380 GRAHAMS LANE BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 10458678
Status: EXPIRED
Instance ID: 18711
Instance Type: FS Highway Tank - Gas/Diesel
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Original Source: EXP
Record Date: Up to Mar 2012

10	26 of 59	SE/40.0	94.8 / 0.00	FREW PETROLEUM CORPORATION 1380 GRAHAMS LANE BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance No:	10456725	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	18737	**Facility Location:**	
Instance Type:	FS Highway Tank - Gas/Diesel	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS HIGHWAY TANK - GASOLINE/DIESEL		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

10	27 of 59	SE/40.0	94.8 / 0.00	**FREW PETROLEUM CORPORATION** **1380 GRAHAMS LANE** **BURLINGTON ON**	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10457143	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	18927	**Facility Location:**	
Instance Type:	FS Highway Tank - Gas/Diesel	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Description:		FS HIGHWAY TANK - GASOLINE/DIESEL			
Original Source:		EXP			
Record Date:		Up to Mar 2012			
10	28 of 59	SE/40.0	94.8 / 0.00	FREW PETROLEUM CORPORATION 1380 GRAHAMS LANE BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10454833	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	19081	**Facility Location:**	
Instance Type:	FS Highway Tank - Gas/Diesel	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS HIGHWAY TANK - GASOLINE/DIESEL		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	29 of 59	SE/40.0	94.8 / 0.00	FREW PETROLEUM CORPORATION 1380 GRAHAMS LANE BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10456728	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	19280	**Facility Location:**	
Instance Type:	FS Highway Tank - Gas/Diesel	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Original Source: EXP
Record Date: Up to Mar 2012

10	*30 of 59*	*SE/40.0*	*94.8 / 0.00*	***FREW PETROLEUM CORPORATION*** ***1380 GRAHAMS LANE*** ***BURLINGTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10456744 ***Expired Date:***
Status: EXPIRED ***Max Hazard Rank:***
Instance ID: 19396 ***Facility Location:***
Instance Type: FS Highway Tank - Gas/Diesel ***Facility Type:***
Instance Creation Dt: ***Fuel Type 2:***
Instance Install Dt: ***Fuel Type 3:***
Item Description: ***Panam Related:***
Manufacturer: ***Panam Venue Nm:***
Model: ***External Identifier:***
Serial No: ***Item:***
ULC Standard: ***Piping Steel:***
Quantity: ***Piping Galvanized:***
Unit of Measure: ***Tank Single Wall St:***
Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Original Source: EXP
Record Date: Up to Mar 2012

10	*31 of 59*	*SE/40.0*	*94.8 / 0.00*	***FREW PETROLEUM CORPORATION*** ***1380 GRAHAMS LANE*** ***BURLINGTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance No:	10456756	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	19699	**Facility Location:**	
Instance Type:	FS Highway Tank - Gas/Diesel	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS HIGHWAY TANK - GASOLINE/DIESEL		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

10	32 of 59	SE/40.0	94.8 / 0.00	**FREW PETROLEUM CORPORATION** **1380 GRAHAMS LANE** **BURLINGTON ON**	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10458083	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	19711	**Facility Location:**	
Instance Type:	FS Highway Tank - Gas/Diesel	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Description:		FS HIGHWAY TANK - GASOLINE/DIESEL			
Original Source:		EXP			
Record Date:		Up to Mar 2012			
10	33 of 59	SE/40.0	94.8 / 0.00	PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD 1380 GRAHAMS LANE BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10461494	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	20247	**Facility Location:**	
Instance Type:	FS Highway Tank - Gas/Diesel	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS HIGHWAY TANK - GASOLINE/DIESEL		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	34 of 59	SE/40.0	94.8 / 0.00	PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD 1380 GRAHAMS LANE BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10472914	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	20485	**Facility Location:**	
Instance Type:	FS Highway Tank - Gas/Diesel	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Quantity: ***Piping Galvanized:***
Unit of Measure: ***Tank Single Wall St:***
Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Original Source: EXP
Record Date: Up to Mar 2012

10	***35 of 59***	***SE/40.0***	***94.8 / 0.00***	***PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD 1380 GRAHAMS LANE BURLINGTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10476512 ***Expired Date:***
Status: EXPIRED ***Max Hazard Rank:***
Instance ID: 21128 ***Facility Location:***
Instance Type: FS Highway Tank - Gas/Diesel ***Facility Type:***
Instance Creation Dt: ***Fuel Type 2:***
Instance Install Dt: ***Fuel Type 3:***
Item Description: ***Panam Related:***
Manufacturer: ***Panam Venue Nm:***
Model: ***External Identifier:***
Serial No: ***Item:***
ULC Standard: ***Piping Steel:***
Quantity: ***Piping Galvanized:***
Unit of Measure: ***Tank Single Wall St:***
Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Original Source: EXP
Record Date: Up to Mar 2012

10	***36 of 59***	***SE/40.0***	***94.8 / 0.00***	***PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD 1380 GRAHAMS LANE BURLINGTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	10471110	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	21254	***Facility Location:***	
Instance Type:	FS Highway Tank - Gas/Diesel	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS HIGHWAY TANK - GASOLINE/DIESEL		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	37 of 59	SE/40.0	94.8 / 0.00	***PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD*** ***1380 GRAHAMS LANE*** ***BURLINGTON ON***	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10470911	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	21843	***Facility Location:***	
Instance Type:	FS Highway Tank - Gas/Diesel	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			

TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Original Source: EXP
Record Date: Up to Mar 2012

---

10 | ***38 of 59*** | ***SE/40.0*** | ***94.8 / 0.00*** | ***PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD 1380 GRAHAMS LANE BURLINGTON ON*** | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10471101
Status: EXPIRED
Instance ID: 22181
Instance Type: FS Highway Tank - Gas/Diesel
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

10 | ***39 of 59*** | ***SE/40.0*** | ***94.8 / 0.00*** | ***PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD 1380 GRAHAMS LANE BURLINGTON ON*** | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10478764
Status: EXPIRED
Instance ID: 23149
Instance Type: FS Highway Tank - Gas/Diesel
Instance Creation Dt:

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance Install Dt: ***Fuel Type 3:***
Item Description: ***Panam Related:***
Manufacturer: ***Panam Venue Nm:***
Model: ***External Identifier:***
Serial No: ***Item:***
ULC Standard: ***Piping Steel:***
Quantity: ***Piping Galvanized:***
Unit of Measure: ***Tank Single Wall St:***
Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Original Source: EXP
Record Date: Up to Mar 2012

10	40 of 59	SE/40.0	94.8 / 0.00	***PETRO CANADA RETAIL DEVELOPMENT CENTRES (CENTRAL) LTD*** ***1380 GRAHAMS LANE*** ***BURLINGTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10479950 ***Expired Date:***
Status: EXPIRED ***Max Hazard Rank:***
Instance ID: 23340 ***Facility Location:***
Instance Type: FS Highway Tank - Gas/Diesel ***Facility Type:***
Instance Creation Dt: ***Fuel Type 2:***
Instance Install Dt: ***Fuel Type 3:***
Item Description: ***Panam Related:***
Manufacturer: ***Panam Venue Nm:***
Model: ***External Identifier:***
Serial No: ***Item:***
ULC Standard: ***Piping Steel:***
Quantity: ***Piping Galvanized:***
Unit of Measure: ***Tank Single Wall St:***
Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Original Source: EXP
Record Date: Up to Mar 2012

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	41 of 59	SE/40.0	94.8 / 0.00	FREW PETROLEUM CORPORATION 1380 GRAHAMS LANE BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10491711	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	23656	**Facility Location:**	
Instance Type:	FS Highway Tank - Gas/Diesel	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS HIGHWAY TANK - GASOLINE/DIESEL		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	42 of 59	SE/40.0	94.8 / 0.00	Petro-Canada Retail Development Centres (Central) 1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	GEN

Generator No:	ON1446200
SIC Code:	419120
SIC Description:	Petroleum Product Agents and Brokers
Approval Years:	2009
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES
Waste Class:	221

Waste Class Name: LIGHT FUELS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

10 | **43 of 59** | **SE/40.0** | **94.8 / 0.00** | **1380 GRAHAM'S LANE Burlington ON** | **WWIS**

Well ID:	7179516	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	04/17/2012
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z142477	**Contractor:**	7241
Tag:	A097678	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7179516.pdf

Additional Detail(s) (Map)

Well Completed Date: 01/19/2010
Year Completed: 2010
Depth (m): 5.1
Latitude: 43.3318720651591
Longitude: -79.8127963350498
Path: 717\7179516.pdf

Bore Hole Information

Bore Hole ID:	1003711334	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596245.00
Code OB Desc:		**North83:**	4798354.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	01/19/2010	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004248746
Layer:	3
Color:	7
General Color:	RED
Mat1:	08
Most Common Material:	FINE SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	85
Mat3 Desc:	SOFT
Formation Top Depth:	1.0
Formation End Depth:	3.0
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004248747
Layer:	4
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	34
Mat2 Desc:	TILL
Mat3:	73
Mat3 Desc:	HARD
Formation Top Depth:	3.0
Formation End Depth:	5.099999904632568
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004248744
Layer:	1
Color:	1
General Color:	WHITE
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	73
Mat3 Desc:	HARD
Formation Top Depth:	0.0
Formation End Depth:	0.30000001192092896
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004248745
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	77

Mat3 Desc: LOOSE
Formation Top Depth: 0.30000001192092896
Formation End Depth: 1.0
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004248757
Layer: 3
Plug From: 1.7999999523162842
Plug To: 5.099999904632568
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004248755
Layer: 1
Plug From: 0.0
Plug To: 0.3100000023841858
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004248756
Layer: 2
Plug From: 0.3100000023841858
Plug To: 1.7999999523162842
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004248754
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1004248743
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004248750
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 2.0999999046325684
Casing Diameter: 3.450000047683716
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004248751
Layer: 1
Slot: 10
Screen Top Depth: 2.0999999046325684
Screen End Depth: 5.099999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.050000190734863

Water Details

Water ID: 1004248749
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004248748
Diameter: 10.899999618530273
Depth From: 0.0
Depth To: 5.099999904632568
Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Bore Hole ID: 1003711334
Depth M: 5.1
Year Completed: 2010
Well Completed Dt: 01/19/2010
Audit No: Z142477
Path: 717\7179516.pdf
Tag No: A097678
Contractor: 7241
Latitude: 43.3318720651591
Longitude: -79.8127963350498
Y: 43.331872062679764
X: -79.81279618612835

---

10 | ***44 of 59*** | ***SE/40.0*** | ***94.8 / 0.00*** | ***Petro-Canada Retail Development Centres (Central)*** ***1380 GRAHAMS LANE*** ***BURLINGTON ON L7S 1W3*** | ***GEN***

Generator No: ON1446200
SIC Code: 419120
SIC Description: Petroleum Product Agents and Brokers
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 251

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

10 | ***45 of 59*** | ***SE/40.0*** | ***94.8 / 0.00*** | ***Petro-Canada Retail Development Centres (Central)***
1380 GRAHAMS LANE
BURLINGTON ON L7S 1W3 | ***GEN***

Generator No: ON1446200
SIC Code: 419120
SIC Description: Petroleum Product Agents and Brokers
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

10 | ***46 of 59*** | ***SE/40.0*** | ***94.8 / 0.00*** | ***Suncor Energy***
1380 GRAHAMS LANE
BURLINGTON ON L7S 1W3 | ***GEN***

Generator No: ON1446200
SIC Code: 419120
SIC Description: Petroleum Product Agents and Brokers
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 221

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class Name:		LIGHT FUELS			
Waste Class:		213			
Waste Class Name:		PETROLEUM DISTILLATES			
Waste Class:		251			
Waste Class Name:		OIL SKIMMINGS & SLUDGES			
10	47 of 59	SE/40.0	94.8 / 0.00	LIPPERT & WRIGHT FUELS 1380 GRAHAMS LANE BURLINGTON ON L7S1W3	RST
Headcode:		00426100			
Headcode Desc:		DIESEL FUEL			
Phone:		9056370033			
List Name:					
Description:					
10	48 of 59	SE/40.0	94.8 / 0.00	Suncor Energy 1380 GRAHAMS LANE BURLINGTON ON	GEN
Generator No:		ON1446200			
SIC Code:		419120			
SIC Description:		PETROLEUM PRODUCT AGENTS AND BROKERS, WHOLESALE TRADE AGENTS AND BROKERS			
Approval Years:		2013			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
Waste Class:		251			
Waste Class Name:		OIL SKIMMINGS & SLUDGES			
Waste Class:		213			
Waste Class Name:		PETROLEUM DISTILLATES			
Waste Class:		221			
Waste Class Name:		LIGHT FUELS			
10	49 of 59	SE/40.0	94.8 / 0.00	FREW ENERGY 1380 GRAHAMS LANE BURLINGTON ON L7S1W3	RST
Headcode:		00924800			
Headcode Desc:		OILS FUEL			
Phone:		4164610991			
List Name:		INFO-DIRECT(TM) BUSINESS FILE			
Description:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	50 of 59	SE/40.0	94.8 / 0.00	Suncor Energy 1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	GEN

Generator No: ON1446200
SIC Code: 419120
SIC Description: PETROLEUM PRODUCT AGENTS AND BROKERS, WHOLESALE TRADE AGENTS AND BROKERS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Craig Bujarsky
Choice of Contact: CO_ADMIN
Phone No Admin: 905-469-3794 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	51 of 59	SE/40.0	94.8 / 0.00	Suncor Energy 1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	GEN

Generator No: ON1446200
SIC Code: 419120
SIC Description: PETROLEUM PRODUCT AGENTS AND BROKERS, WHOLESALE TRADE AGENTS AND BROKERS
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Craig Bujarsky
Choice of Contact: CO_ADMIN
Phone No Admin: 905-469-3794 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	52 of 59	SE/40.0	94.8 / 0.00	Suncor Energy 1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	GEN

Generator No: ON1446200
SIC Code: 419120
SIC Description: PETROLEUM PRODUCT AGENTS AND BROKERS, WHOLESALE TRADE AGENTS AND BROKERS
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Craig Bujarsky
Choice of Contact: CO_ADMIN
Phone No Admin: 905-469-3794 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	53 of 59	SE/40.0	94.8 / 0.00	Suncor Energy 1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	GEN

Generator No: ON1446200
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	54 of 59	SE/40.0	94.8 / 0.00	FREW ENERGY 1380 GRAHAMS LANE BURLINGTON ON L7S1W3	RST

Headcode: 00426100
Headcode Desc: DIESEL FUEL
Phone: 4164610991
List Name: INFO-DIRECT(TM) BUSINESS FILE
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	55 of 59	SE/40.0	94.8 / 0.00	Suncor Energy 1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	GEN

Generator No: ON1446200
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 221 L
Waste Class Name: Light fuels

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	56 of 59	SE/40.0	94.8 / 0.00	Suncor Energy 1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	GEN

Generator No: ON1446200
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	57 of 59	SE/40.0	94.8 / 0.00	Suncor Energy Products Partnership 1380 Grahams Lane Burlington ON L7S 1W3	GEN

Generator No: ON9995619
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	58 of 59	SE/40.0	94.8 / 0.00	Suncor Energy 1380 GRAHAMS LANE BURLINGTON ON L7S 1W3	GEN

Generator No: ON1446200
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 221 L
Waste Class Name: LIGHT FUELS

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 213 I
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221 I
Waste Class Name: LIGHT FUELS

---

10 | **59 of 59** | **SE/40.0** | **94.8 / 0.00** | **Suncor Energy Products Partnership**
1380 Grahams Lane
Burlington ON L7S 1W3 | **GEN**

Generator No: ON9995619
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221 L
Waste Class Name: LIGHT FUELS

---

11 | **1 of 1** | **SE/41.4** | **94.8 / 0.00** | **1380 GRAHAM'S LANE**
Burlington ON | **WWIS**

Well ID: 7179605
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z142480
Tag: A097679
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 04/17/2012
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: HALTON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7179605.pdf

Additional Detail(s) (Map)

Well Completed Date: 01/19/2012
Year Completed: 2012
Depth (m): 5.5
Latitude: 43.3318806837032

Longitude: -79.8127591617892
Path: 717\7179605.pdf

Bore Hole Information

Bore Hole ID: 1003711669
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 01/19/2012
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 596248.00
North83: 4798355.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1004251486
Layer: 3
Color: 7
General Color: RED
Mat1: 08
Most Common Material: FINE SAND
Mat2: 06
Mat2 Desc: SILT
Mat3: 85
Mat3 Desc: SOFT
Formation Top Depth: 1.0
Formation End Depth: 3.0
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004251485
Layer: 2
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Mat2 Desc: GRAVEL
Mat3: 77
Mat3 Desc: LOOSE
Formation Top Depth: 0.30000001192092896
Formation End Depth: 1.0
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004251487
Layer: 4
Color: 2

General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2: 34
Mat2 Desc: TILL
Mat3: 73
Mat3 Desc: HARD
Formation Top Depth: 3.0
Formation End Depth: 5.5
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004251484
Layer: 1
Color: 1
General Color: WHITE
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3: 73
Mat3 Desc: HARD
Formation Top Depth: 0.0
Formation End Depth: 0.30000001192092896
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004251496
Layer: 2
Plug From: 0.3100000023841858
Plug To: 3.200000047683716
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004251495
Layer: 1
Plug From: 0.0
Plug To: 0.3100000023841858
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004251497
Layer: 3
Plug From: 3.200000047683716
Plug To: 5.5
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004251494
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID:	1004251483
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004251490
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	2.5
Casing Diameter:	5.199999809265137
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004251491
Layer:	1
Slot:	10
Screen Top Depth:	2.5
Screen End Depth:	5.5
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.099999904632568

Water Details

Water ID:	1004251489
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004251488
Diameter:	20.0
Depth From:	0.0
Depth To:	5.5
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	1003711669	***Tag No:***	A097679
Depth M:	5.5	***Contractor:***	7241
Year Completed:	2012	***Latitude:***	43.3318806837032
Well Completed Dt:	01/19/2012	***Longitude:***	-79.8127591617892
Audit No:	Z142480	***Y:***	43.331880681371295
Path:	717\7179605.pdf	***X:***	-79.81275901295457

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	1 of 4	E/60.6	93.8 / -1.00	1416 Grahams Lane Burlington ON L7S 1W3	EHS

Order No:	21120600288	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	RSC Report (Urban)	**Client Prov/State:**	OH
Report Date:	09-DEC-21	**Search Radius (km):**	.3
Date Received:	06-DEC-21	**X:**	-79.81175934
Previous Site Name:		**Y:**	43.33233013
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Aerial Photos		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	2 of 4	E/60.6	93.8 / -1.00	1416 Grahams Lane Burlington ON L7S 1W3	EHS

Order No:	21120600288	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	RSC Report (Urban)	**Client Prov/State:**	OH
Report Date:	09-DEC-21	**Search Radius (km):**	.3
Date Received:	06-DEC-21	**X:**	-79.81175934
Previous Site Name:		**Y:**	43.33233013
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Aerial Photos		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	3 of 4	E/60.6	93.8 / -1.00	1416 Grahams Lane Burlington ON L7S 1W3	EHS

Order No:	21120600288	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	RSC Report (Urban)	**Client Prov/State:**	OH
Report Date:	09-DEC-21	**Search Radius (km):**	.3
Date Received:	06-DEC-21	**X:**	-79.81175934
Previous Site Name:		**Y:**	43.33233013
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Aerial Photos		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	4 of 4	E/60.6	93.8 / -1.00	1416 Grahams Lane Burlington ON L7S 1W3	EHS

Order No:	21120600288	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	RSC Report (Urban)	**Client Prov/State:**	OH
Report Date:	09-DEC-21	**Search Radius (km):**	.3
Date Received:	06-DEC-21	**X:**	-79.81175934
Previous Site Name:		**Y:**	43.33233013
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Aerial Photos		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	1 of 1	NNE/64.7	94.8 / 0.00	828 Legion Road Burlington ON L7S 1T5	EHS

Order No:	20060427025	**Nearest Intersection:**	Graham's Lane
Status:	C	**Municipality:**	Burlington
Report Type:	Complete Report	**Client Prov/State:**	ON
Report Date:	5/8/2006	**Search Radius (km):**	0.25
Date Received:	4/27/2006	**X:**	-79.812716
Previous Site Name:		**Y:**	43.333924
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	1 of 2	S/68.2	94.8 / 0.00	BURLINGTON HYDRO-ELEC. COMMISSION 1370 GRAHAMS LANE C/O 1340 BRANT ST. BURLINGTON ON L7R 3Z7	GEN

Generator No: ON0676610
SIC Code: 4911
SIC Description: ELECT. POWER SYS.
Approval Years: 89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	2 of 2	S/68.2	94.8 / 0.00	BURLINGTON HYDRO-ELEC. COMMISSION 05-334 1370 GRAHAMS LANE C/O 1340 BRANT ST. BURLINGTON ON L7R 3Z7	GEN

Generator No: ON0676610
SIC Code: 4911
SIC Description: ELECT. POWER SYS.
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	1 of 4	E/71.3	93.8 / -1.00	Arctic Traveler (Canada) Ltd. 1416 Grahams Lane Burlington ON L7S 1W3	SCT

Established: 01-JUN-60
Plant Size (ft²):
Employment:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--

Description: Heating Equipment and Commercial Refrigeration Equipment Manufacturing
SIC/NAICS Code: 333416

Description: Other New Motor Vehicle Parts and Accessories Wholesaler-Distributors
SIC/NAICS Code: 415290

Description: Plumbing, Heating and Air-Conditioning Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 416120

Description: Heating Equipment and Commercial Refrigeration Equipment Manufacturing
SIC/NAICS Code: 333416

Description: Office and Store Machinery and Equipment Wholesaler-Distributors
SIC/NAICS Code: 417910

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	2 of 4	E/71.3	93.8 / -1.00	SINCLAIR-SMITH PRINTING & LITHOGRAPHING CO. LTD., THE 1416 GRAHAMS LANE BURLINGTON ON L7S 1W3	GEN

Generator No: ON0463700
SIC Code: 0007
SIC Description: LETTER ACKNOWLEDG.
Approval Years: 86,87,88,89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	3 of 4	E/71.3	93.8 / -1.00	SINCLAIR-SMITH PRINTING & 35-086 LITHOGRAPHING CO. LTD., THE 1416 GRAHAMS LANE BURLINGTON ON L7S 1W3	GEN

Generator No: ON0463700
SIC Code: 0007
SIC Description: LETTER ACKNOWLEDG.
Approval Years: 92,93,94
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	4 of 4	E/71.3	93.8 / -1.00	1416 Grahams Ln Burlington ON L7S 1W3	EHS

Order No: 20190904236
Status: C
Report Type: RSC Report (Urban)
Report Date: 11-SEP-19
Date Received: 04-SEP-19
Previous Site Name:
Lot/Building Size:
Nearest Intersection:
Municipality:
Client Prov/State: IL
Search Radius (km): .3
X: -79.811754
Y: 43.332332

Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Aerial Photos

---

16 | ***1 of 1*** | ***SSE/74.5*** | ***94.6 / -0.24*** | ***1380 GRAHAM'S LANE BURLINGTON ON*** | ***WWIS***

Well ID:	2810308	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	08/03/2005
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z27865	***Contractor:***	1129
Tag:	A026658	***Form Version:***	3
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	HALTON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	

Municipality: BURLINGTON CITY
Site Info: OAKVILLE SUBDIVISION

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/281\2810308.pdf

Additional Detail(s) (Map)

Well Completed Date: 05/16/2005
Year Completed: 2005
Depth (m): 4.6
Latitude: 43.3314045684986
Longitude: -79.812867117473
Path: 281\2810308.pdf

Bore Hole Information

Bore Hole ID:	11319263	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	596240.00
Code OB Desc:		***North83:***	4798302.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	05/16/2005	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID: 933007488
Layer: 2

Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	05
Mat3 Desc:	CLAY
Formation Top Depth:	0.20999999344348907
Formation End Depth:	3.4100000858306885
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	933007487
Layer:	1
Color:	
General Color:	
Mat1:	02
Most Common Material:	TOPSOIL
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.20999999344348907
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	933007489
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	05
Most Common Material:	CLAY
Mat2:	34
Mat2 Desc:	TILL
Mat3:	28
Mat3 Desc:	SAND
Formation Top Depth:	3.4100000858306885
Formation End Depth:	4.599999904632568
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933273895
Layer:	3
Plug From:	0.5699999928474426
Plug To:	4.599999904632568
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933273897
Layer:	1
Plug From:	0.0
Plug To:	0.3499999940395355

Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933273896
Layer: 2
Plug From: 0.3499999940395355
Plug To: 0.5699999928474426
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 962810308
Method Construction Code: B
Method Construction: Other Method
Other Method Construction:

Pipe Information

Pipe ID: 11334118
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930860250
Layer: 2
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 0.9700000286102295
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Casing

Casing ID: 930860249
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From: 0.0
Depth To: 0.30000001192092896
Casing Diameter: 20.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933413912
Layer: 1
Slot: 10
Screen Top Depth: 0.9700000286102295
Screen End Depth: 4.599999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.099999904632568

Water Details

Water ID:	934062788
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	2.5
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	11537841
Diameter:	20.0
Depth From:	0.0
Depth To:	4.599999904632568
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	11319263	***Tag No:***	A026658
Depth M:	4.6	***Contractor:***	1129
Year Completed:	2005	***Latitude:***	43.3314045684986
Well Completed Dt:	05/16/2005	***Longitude:***	-79.812867117473
Audit No:	Z27865	***Y:***	43.33140456567731
Path:	281\2810308.pdf	***X:***	-79.81286696800129

---

17 | ***1 of 52*** | ***N/78.7*** | ***94.8 / 0.00*** | ***HERCULES CANADA INC.***
850 LEGION RD/SOUTH OF FAIRVIEW AVE.
BURLINGTON PLANT 942 BRANT STREET
BURLINGTON CITY ON L7S 1T5 | ***SPL***

Ref No:	110772	***Municipality No:***	14101
Year:		***Nature of Damage:***	
Incident Dt:	3/6/1995	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	3/7/1995	***Health/Env Conseq:***	
Dt Document Closed:		***Agency Involved:***	HALTON REG.
Site No:			
Facility Name:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BURLINGTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:	UNKNOWN		
Incident Event:			
Environment Impact:	POSSIBLE		
Nature of Impact:	Water course or lake		
Contaminant Qty:			
System Facility Address:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Client Name:
Client Type:
Call Report Locatn Geodata:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: WATER
Receiving Environment:
Incident Reason: UNKNOWN
Incident Summary: HERCULES CANADA- UNKNOWN QUANT. OF EMULSIFIER TO DITCH, MOEE INVESTIGATING
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:

17	*2 of 52*	*N/78.7*	*94.8 / 0.00*	***TECKMARK LABEL SYSTEMS INC.*** ***850 LEGION RD UNIT 23*** ***BURLINGTON ON L7S 1T5***	***SCT***

Established: 1989
Plant Size (ft²): 4400
Employment: 8

--Details--
Description: COATED AND LAMINATED PAPER, NOT ELSEWHERE CLASSIFED
SIC/NAICS Code: 2672

Description: COMMERCIAL PRINTING, LITHOGRAPHIC
SIC/NAICS Code: 2752

Description: COMMERCIAL PRINTING, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 2759

Description: PACKAGING MACHINERY
SIC/NAICS Code: 3565

Description: OFFICE MACHINES, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3579

17	*3 of 52*	*N/78.7*	*94.8 / 0.00*	***K L B INTERIORS INC*** ***850 LEGION RD UNIT 5*** ***BURLINGTON ON L7S 1T5***	***SCT***

Established: 1970
Plant Size (ft²): 1500
Employment: 6

--Details--
Description: CURTAINS AND DRAPERIES
SIC/NAICS Code: 2391

Description: HOUSEFURNISHINGS, EXCEPT CURTAINS AND DRAPERIES
SIC/NAICS Code: 2392

Description: PLEATING, DECORATIVE AND NOVELTY STITCHING, AND TUCKING FOR THE TRADE
SIC/NAICS Code: 2395

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Description:		DRAPERY HARDWARE AND WINDOW BLINDS AND SHADES			
SIC/NAICS Code:		2591			
17	4 of 52	N/78.7	94.8 / 0.00	**Artisan Design** **850 Legion Rd Unit 1-3** **Burlington ON L7S 1T5**	SCT
Established:		1989			
Plant Size (ft²):		3900			
Employment:		5			
--Details--					
Description:		Wood Kitchen Cabinet and Counter Top Manufacturing			
SIC/NAICS Code:		337110			
Description:		Other Wood Household Furniture Manufacturing			
SIC/NAICS Code:		337123			
Description:		Showcase, Partition, Shelving and Locker Manufacturing			
SIC/NAICS Code:		337215			
17	5 of 52	N/78.7	94.8 / 0.00	**MERIDIAN GOLF (2000) INC.** **850 LEGION RD UNIT 14** **BURLINGTON ON L7S 1T5**	SCT
Established:		1992			
Plant Size (ft²):		0			
Employment:		5			
--Details--					
Description:		SPORTING AND ATHLETIC GOODS, NOT ELSEWHERE CLASSIFIED			
SIC/NAICS Code:		3949			
Description:		SPORTING AND RECREATIONAL GOODS AND SUPPLIES			
SIC/NAICS Code:		5091			
Description:		MEN'S AND BOYS' CLOTHING AND FURNISHINGS			
SIC/NAICS Code:		5136			
Description:		WOMEN'S, CHILDREN'S, AND INFANTS' CLOTHING AND ACCESSORIES			
SIC/NAICS Code:		5137			
17	6 of 52	N/78.7	94.8 / 0.00	**HIBON INC.** **850 LEGION RD UNIT 3** **BURLINGTON ON L7S 1T5**	SCT
Established:		1981			
Plant Size (ft²):		2000			
Employment:		3			
--Details--					
Description:		INDUSTRIAL MACHINERY AND EQUIPMENT			
SIC/NAICS Code:		5084			
17	7 of 52	N/78.7	94.8 / 0.00	**WOODCRAFT RAIL INC.** **850 Legion Rd Unit 15**	SCT

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Burlington ON L7S 1T5	

Established: 1985
Plant Size (ft²): 0
Employment: 1

--Details--
Description: Other Millwork
SIC/NAICS Code: 321919

17	8 of 52	N/78.7	94.8 / 0.00	**KLB Interiors Inc.** **850 Legion Rd Unit 5** **Burlington ON L7S 1T5**	SCT

Established: 01-AUG-70
Plant Size (ft²): 1500
Employment:

--Details--
Description: Blind and Shade Manufacturing
SIC/NAICS Code: 337920

Description: Curtain and Linen Mills
SIC/NAICS Code: 314120

17	9 of 52	N/78.7	94.8 / 0.00	**Teckmark Label Systems Inc.** **850 Legion Rd Unit 23** **Burlington ON L7S 1T5**	SCT

Established: 01-JUL-99
Plant Size (ft²):
Employment:

--Details--
Description: Textile and Fabric Finishing
SIC/NAICS Code: 313310

Description: Paper Bag and Coated and Treated Paper Manufacturing
SIC/NAICS Code: 322220

Description: Stationery Product Manufacturing
SIC/NAICS Code: 322230

Description: Other Printing
SIC/NAICS Code: 323119

17	10 of 52	N/78.7	94.8 / 0.00	**B-LINE CRESTING** **850 Legion Rd Unit 7** **Burlington ON L7S 1T5**	SCT

Established: 0000
Plant Size (ft²): 0
Employment: 0

--Details--
Description: All Other Textile Product Mills

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
SIC/NAICS Code:		314990			

17	11 of 52	N/78.7	94.8 / 0.00	**WENTWORTH ELECTRONICS** **850 LEGION ROAD, UNIT #7** **BURLINGTON ON L7S 1T5**	GEN

Generator No: ON0988200
SIC Code: 3361
SIC Description: ELECT. COMP. & PERI.
Approval Years: 88,89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

17	12 of 52	N/78.7	94.8 / 0.00	**WENTWORTH OUT OF BUSINESS 41-236** **850 LEGION ROAD, UNIT #7** **BURLINGTON ON L7S 1T5**	GEN

Generator No: ON0988200
SIC Code: 3361
SIC Description: ELECT. COMP. & PERI.
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 122

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

17	13 of 52	N/78.7	94.8 / 0.00	**TECKMARK LABEL SYSTEMS INC.** **850 - #23 LEGION ROAD** **BURLINGTON ON L7S 1T5**	GEN

Generator No: ON1207100
SIC Code: 2819
SIC Description: OTHER COMM. PRINTING
Approval Years: 89,99,00,01,03
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

17	14 of 52	N/78.7	94.8 / 0.00	**TECKMARK LABEL SYSTEMS INC. 37-552** **850 - #23 LEGION ROAD** **BURLINGTON ON L7S 1T5**	GEN

Generator No: ON1207100
SIC Code: 2819
SIC Description: OTHER COMM. PRINTING
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

17	15 of 52	N/78.7	94.8 / 0.00	**TECKMARK LABEL SYSTEMS INC.** **850 - #23 LEGION ROAD** **BURLINGTON ON L7S 1T5**	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Generator No:		ON1207100			
SIC Code:					
SIC Description:					
Approval Years:		02			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					

17	16 of 52	N/78.7	94.8 / 0.00	**ARTISAN DESIGN** **850 LEGION ROAD UNIT #1** **BURLINGTON ON L7S 1T5**	GEN

Generator No:	ON1884000
SIC Code:	2819
SIC Description:	OTHER COMM. PRINTING
Approval Years:	94,95,96,97,98
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	211
Waste Class Name:	AROMATIC SOLVENTS

17	17 of 52	N/78.7	94.8 / 0.00	**B-LINE CRESTING, DIVISION OF** **850 LEGION ROAD, UNIT #7** **BURLINGTON ON L7S 1T5**	GEN

Generator No:	ON2208500
SIC Code:	2434
SIC Description:	MEN'S & BOY'S SHIRT
Approval Years:	97,98
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

17	18 of 52	N/78.7	94.8 / 0.00	**GOLDEN HORSESHOE SERVICES** **850 LEGION ROAD, #17** **BURLINGTON ON L7S 1T5**	GEN

Generator No:	ON2247400

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Code: 9731
SIC Description: FUNERAL HOMES
Approval Years: 97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

17	19 of 52	N/78.7	94.8 / 0.00	**GOLDEN HORSESHOE SERVICES** **850 LEGION ROAD, #17** **BURLINGTON ON L7S 1T5**	GEN

Generator No: ONF059200
SIC Code: 9731
SIC Description: FUNERAL HOMES
Approval Years: 97,98,99
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

17	20 of 52	N/78.7	94.8 / 0.00	**ARTISAN DESIGN** **850 LEGION ROAD, UNIT 1** **BURLINGTON ON L7S 1T5**	GEN

Generator No: ON1884000
SIC Code: 2819
SIC Description: OTHER COMM. PRINTING
Approval Years: 99,00,01,02,03,04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	21 of 52	N/78.7	94.8 / 0.00	B-LINE CRESTING 850 LEGION ROAD, UNIT 7 BURLINGTON ON L7S 1T5	GEN

Generator No: ON2208500
SIC Code: 2434
SIC Description: MEN'S & BOY'S SHIRT
Approval Years: 99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	22 of 52	N/78.7	94.8 / 0.00	GOLDEN HORSESHOE SERVICES 850 LEGION ROAD, UNIT 17 BURLINGTON ON L7S 1T5	GEN

Generator No: ONF059200
SIC Code: 9731
SIC Description: FUNERAL HOMES
Approval Years: 00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	23 of 52	N/78.7	94.8 / 0.00	Rea/Co Inc. 850 Legion Rd Unit 18 Burlington ON L7S 1T5	SCT

Established: 1995
Plant Size (ft²): 2000
Employment: 8

--Details--
Description: Other Concrete Product Manufacturing
SIC/NAICS Code: 327390

Description: Other Plate Work and Fabricated Structural Product Manufacturing
SIC/NAICS Code: 332319

Description: Machine Shops
SIC/NAICS Code: 332710

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Description:		Metal Valve Manufacturing			
SIC/NAICS Code:		332910			

17	24 of 52	N/78.7	94.8 / 0.00	**The Maples Animal Hospital** **850 Legion Road Unit 21** **Burlington ON L7S 1T5**	GEN

Generator No:	ON3879047
SIC Code:	
SIC Description:	
Approval Years:	03,04
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

17	25 of 52	N/78.7	94.8 / 0.00	**TECKMARK LABEL SYSTEMS INC.** **850 - #23 LEGION ROAD** **BURLINGTON ON L7S 1T5**	GEN

Generator No:	ON1207100
SIC Code:	
SIC Description:	
Approval Years:	04
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

17	26 of 52	N/78.7	94.8 / 0.00	**Fry Graphics Ltd.** **850 Legion Rd Unit 6** **Burlington ON L7S 1T5**	SCT

Established:	7/1/1999
Plant Size (ft²):	
Employment:	

--Details--

Description:	Other Printing
SIC/NAICS Code:	323119
Description:	Digital Printing
SIC/NAICS Code:	323115

17	27 of 52	N/78.7	94.8 / 0.00	**Burlington Letterpress** **850 Legion Rd Unit 11** **Burlington ON L7S 1T5**	SCT

Established:	01-JUL-99
Plant Size (ft²):	2700
Employment:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--

Description: Other Printing
SIC/NAICS Code: 323119

Description: Other Printing
SIC/NAICS Code: 323119

Description: Quick Printing
SIC/NAICS Code: 323114

Description: Digital Printing
SIC/NAICS Code: 323115

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	28 of 52	N/78.7	94.8 / 0.00	***MCCONNELL-SPADAFORA INC*** ***850 LEGION RD, UNIT #4*** ***BURLINGTON ON L7S 1T5***	PES

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Limited Vendor
Licence Type Code: 23
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	29 of 52	N/78.7	94.8 / 0.00	***Techmark Label Systems Inc.*** ***850 Legion Unit 23*** ***Burlington ON L7S 1T5***	GEN

Generator No: ON4216156
SIC Code: 323119
SIC Description: Other Printing
Approval Years: 07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	30 of 52	N/78.7	94.8 / 0.00	***McConnell-Spadafora Inc.*** ***850 Legion Rd Unit 4***	SCT

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Burlington ON L7S 1T5	

Established: 01-SEP-83
Plant Size (ft²): 2500
Employment:

--Details--
Description: Wholesale Trade Agents and Brokers
SIC/NAICS Code: 419120

Description: Wholesale Trade Agents and Brokers
SIC/NAICS Code: 419120

17	31 of 52	N/78.7	94.8 / 0.00	**Multi-Line Products Inc.** **850 Legion Rd Unit 9** **Burlington ON L7S 1T5**	SCT

Established: 01-SEP-95
Plant Size (ft²):
Employment:

--Details--
Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Description: Hardware Wholesaler-Distributors
SIC/NAICS Code: 416330

Description: General-Line Building Supplies Wholesaler-Distributors
SIC/NAICS Code: 416310

17	32 of 52	N/78.7	94.8 / 0.00	**The Maples Animal Hospital Professional Corporatio** **850 Legion Road Unit 21** **Burlington ON L7S 1T5**	GEN

Generator No: ON3879047
SIC Code: 541940
SIC Description: Veterinary Services
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	33 of 52	N/78.7	94.8 / 0.00	Historia Building Restoration Inc. 850 Legion Road Unit 19A Burlington ON	GEN

Generator No: ON8321327
SIC Code: 238990
SIC Description: ALL OTHER SPECIALTY TRADE CONTRACTORS
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	34 of 52	N/78.7	94.8 / 0.00	MCCONNELL-SPADAFORA INC 850 LEGION RD, UNIT 4 BURLINGTON ON L7S 1T5	PES

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	35 of 52	N/78.7	94.8 / 0.00	The Maples Animal Hospital Professional Corporatio 850 Legion Road Unit 21 Burlington ON L7S 1T5	GEN

Generator No: ON3879047
SIC Code: 541940
SIC Description: Veterinary Services
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

17	36 of 52	N/78.7	94.8 / 0.00	**Historia Building Restoration Inc.** **850 Legion Road Unit 19A** **Burlington ON L7S 1T5**	GEN

Generator No: ON8321327
SIC Code: 238990
SIC Description:
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

17	37 of 52	N/78.7	94.8 / 0.00	**The Maples Animal Hospital Professional Corporatio** **850 Legion Road Unit 21** **Burlington ON L7S 1T5**	GEN

Generator No: ON3879047
SIC Code: 541940
SIC Description: Veterinary Services
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

17	38 of 52	N/78.7	94.8 / 0.00	**MCCONNELL-SPADAFORA INC** **850 LEGION RD, UNIT 4** **BURLINGTON ON L7S1T5**	PES

Detail Licence No:
Licence No: 13826
Status:
Approval Date:
Operator Box:
Operator Class:
Operator No:
Operator Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	905
Licence Type:	Limited Vendor	**Oper Phone No:**	6819563
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

17	39 of 52	N/78.7	94.8 / 0.00	**Historia Building Restoration Inc.** **850 Legion Road Unit 19A** **Burlington ON L7S 1T5**	GEN

Generator No:	ON8321327
SIC Code:	238990
SIC Description:	All Other Specialty Trade Contractors
Approval Years:	2012
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

17	40 of 52	N/78.7	94.8 / 0.00	**The Maples Animal Hospital Professional Corporatio** **850 Legion Road Unit 21** **Burlington ON L7S 1T5**	GEN

Generator No:	ON3879047
SIC Code:	541940
SIC Description:	Veterinary Services
Approval Years:	2012
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	261
Waste Class Name:	PHARMACEUTICALS
Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

17	41 of 52	N/78.7	94.8 / 0.00	**The Maples Animal Hospital Professional Corporatio** **850 Legion Road Unit 21**	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Burlington ON	

Generator No: ON3879047
SIC Code: 541940
SIC Description: VETERINARY SERVICES
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	42 of 52	N/78.7	94.8 / 0.00	**The Maples Animal Hospital Professional Corporatio** **850 Legion Road Unit 21** **Burlington ON L7S 1T5**	GEN

Generator No: ON3879047
SIC Code: 541940
SIC Description: VETERINARY SERVICES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	43 of 52	N/78.7	94.8 / 0.00	**The Maples Animal Hospital Professional Corporatio** **850 Legion Road Unit 21** **Burlington ON L7S 1T5**	GEN

Generator No: ON3879047
SIC Code: 541940
SIC Description: VETERINARY SERVICES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

17	44 of 52	N/78.7	94.8 / 0.00	The Maples Animal Hospital Professional Corporatio 850 Legion Road Unit 21 Burlington ON L7S 1T5	GEN

Generator No: ON3879047
SIC Code: 541940
SIC Description: VETERINARY SERVICES
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

17	45 of 52	N/78.7	94.8 / 0.00	The Maples Animal Hospital Professional Corporatio 850 Legion Road Unit 21 Burlington ON L7S 1T5	GEN

Generator No: ON3879047
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
17	46 of 52	N/78.7	94.8 / 0.00	**The Maples Animal Hospital Professional Corporatio** **850 Legion Road Unit 21** **Burlington ON L7S 1T5**	GEN
Generator No:		ON3879047			
SIC Code:					
SIC Description:					
Approval Years:		As of Jul 2020			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		261 A			
Waste Class Name:		Pharmaceuticals			
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
17	47 of 52	N/78.7	94.8 / 0.00	**SOAR Veterinary Professional Corporation** **850 Legion Rd Unit 5** **Burlington ON L7S 1T5**	GEN
Generator No:		ON4732024			
SIC Code:					
SIC Description:					
Approval Years:		As of Jul 2020			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
Waste Class:		261 A			
Waste Class Name:		Pharmaceuticals			
17	48 of 52	N/78.7	94.8 / 0.00	**SOAR Veterinary Professional Corporation** **850 Legion Rd Unit 5** **Burlington ON L7S 1T5**	GEN
Generator No:		ON4732024			
SIC Code:					
SIC Description:					
Approval Years:		As of Nov 2021			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	49 of 52	N/78.7	94.8 / 0.00	***The Maples Animal Hospital Professional Corporatio*** ***850 Legion Road Unit 21*** ***Burlington ON L7S 1T5***	GEN

Generator No: ON3879047
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	50 of 52	N/78.7	94.8 / 0.00	***SOAR Veterinary Professional Corporation*** ***850 Legion Rd Unit 5*** ***Burlington ON L7S 1T5***	GEN

Generator No: ON4732024
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		261 A			
Waste Class Name:		PHARMACEUTICALS			
Waste Class:		312 P			
Waste Class Name:		PATHOLOGICAL WASTES			
17	51 of 52	N/78.7	94.8 / 0.00	**The Maples Animal Hospital Professional Corporatio** **850 Legion Road Unit 21** **Burlington ON L7S 1T5**	GEN
Generator No:		ON3879047			
SIC Code:					
SIC Description:					
Approval Years:		As of Oct 2022			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		261 A			
Waste Class Name:		PHARMACEUTICALS			
Waste Class:		312 P			
Waste Class Name:		PATHOLOGICAL WASTES			
17	52 of 52	N/78.7	94.8 / 0.00	**Carl's Grinding Service** **850 Legion Road #8** **Burlington ON L7S 1T5**	GEN
Generator No:		ON3991822			
SIC Code:					
SIC Description:					
Approval Years:		As of Oct 2022			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		212 L			
Waste Class Name:		ALIPHATIC SOLVENTS			
Waste Class:		252 L			
Waste Class Name:		WASTE OILS & LUBRICANTS			
Waste Class:		251 L			
Waste Class Name:		OIL SKIMMINGS & SLUDGES			
18	1 of 1	NE/86.2	94.8 / 0.00	**ON**	BORE

Borehole ID:	623591	**Inclin FLG:**	No
OGF ID:	215524043	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	FEB-1959	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.333837
Total Depth m:	3	**Longitude DD:**	-79.812394
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	596275
Drill Method:	Diamond Drill	**Northing:**	4798573
Orig Ground Elev m:	84.1	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	93.7		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218430152	**Mat Consistency:**	Hard
Top Depth:	1.4	**Material Moisture:**	
Bottom Depth:	3	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. RED,HARD,AGE ORDOVICIAN. L. SA **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218430151	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	1.4	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Shale	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SHALE,CLAY. RED,AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: HAM.txt RecordID: 025910 NTS_Sheet: 30M05C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator

Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

19 | **1 of 1** | **S/87.4** | **94.8 / -0.03** | **BURLINGTON ON** | **WWIS**

Well ID: 2810214
Construction Date:
Use 1st: Not Used
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z25954
Tag: A025466
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 04/26/2005
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7075
Form Version: 3
Owner:
County: HALTON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/281\2810214.pdf

Additional Detail(s) (Map)

Well Completed Date: 03/21/2005
Year Completed: 2005
Depth (m): 4.5
Latitude: 43.3311740840424
Longitude: -79.8132169865897
Path: 281\2810214.pdf

Bore Hole Information

Bore Hole ID: 11319169
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 03/21/2005
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 596212.00
North83: 4798276.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 933007281

Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	06
Mat3 Desc:	SILT
Formation Top Depth:	0.0
Formation End Depth:	4.0
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	933007282
Layer:	2
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Mat2 Desc:	CLAY
Mat3:	11
Mat3 Desc:	GRAVEL
Formation Top Depth:	4.0
Formation End Depth:	4.5
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933268028
Layer:	1
Plug From:	0.0
Plug To:	0.699999988079071
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	962810214
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	11334024
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930860165
Layer:	1
Material:	
Open Hole or Material:	
Depth From:	0.699999988079071
Depth To:	0.0

Casing Diameter:
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933412453
Layer: 1
Slot: 010
Screen Top Depth: 0.699999988079071
Screen End Depth: 4.5
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter:

Water Details

Water ID: 934059578
Layer: 1
Kind Code:
Kind:
Water Found Depth: 2.0
Water Found Depth UOM: m

Links

Bore Hole ID: 11319169
Depth M: 4.5
Year Completed: 2005
Well Completed Dt: 03/21/2005
Audit No: Z25954
Path: 281\2810214.pdf
Tag No: A025466
Contractor: 7075
Latitude: 43.3311740840424
Longitude: -79.8132169865897
Y: 43.331174081703935
X: -79.81321683835745

---

20 ***1 of 39*** ***E/88.7*** ***92.8 / -2.00*** ***ETRATECH DESIGNS INC.***
1440 GRAHAMS LANE, UNIT #5
BURLINGTON CITY ON L7S 1W3 ***CA***

Certificate #: 8-3185-91-
Application Year: 91
Issue Date: 8/7/1991
Approval Type: Industrial air
Status: Underwent 1st revision in 1992
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: VENTILATION OF NEW WAVE SOLDER MACHINE
Contaminants: Tin, Lead, Isopropyl Alcohol, Other Contaminant
Emission Control: Mist Eliminator,

---

20 ***2 of 39*** ***E/88.7*** ***92.8 / -2.00*** ***THYSSEN DOVER ELEVATORS***
1440 GRAHAMS LANE UNIT 3
BURLINGTON ON L7S 1W3 ***SCT***

Established: 1900
Plant Size (ft²): 0
Employment: 15

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
--Details--					
Description:		Industrial Machinery, Equipment and Supplies Wholesaler-Distributors			
SIC/NAICS Code:		417230			
20	3 of 39	E/88.7	92.8 / -2.00	BURLINGTON LAMINATING & BINDER 1440 GRAHAMS LANE UNIT 2 BURLINGTON ON L7S 1W3	SCT
Established:		1976			
Plant Size (ft²):		3000			
Employment:		4			
--Details--					
Description:		COMMERCIAL PRINTING, NOT ELSEWHERE CLASSIFIED			
SIC/NAICS Code:		2759			
Description:		BOOKBINDING AND RELATED WORK			
SIC/NAICS Code:		2789			
20	4 of 39	E/88.7	92.8 / -2.00	Peters Steel Rule Dies 1440 Grahams Lane Unit 6-7 Burlington ON L7S 1W3	SCT
Established:		01-JAN-70			
Plant Size (ft²):		4500			
Employment:					
--Details--					
Description:		Other Metalworking Machinery Manufacturing			
SIC/NAICS Code:		333519			
Description:		Other Metalworking Machinery Manufacturing			
SIC/NAICS Code:		333519			
20	5 of 39	E/88.7	92.8 / -2.00	ENDRESS + HAUSER CANADA LTD 1440 GRAHAMS LANE UNIT 1 BURLINGTON ON L7S 1W3	SCT
Established:		1990			
Plant Size (ft²):		0			
Employment:		17			
--Details--					
Description:		RELAYS AND INDUSTRIAL CONTROLS			
SIC/NAICS Code:		3625			
20	6 of 39	E/88.7	92.8 / -2.00	DOVER CORPORATION CANADA LTD 1440 GRAHAMS LANE UNIT 3 BURLINGTON ON L7S 1W3	SCT
Established:		1900			
Plant Size (ft²):		0			
Employment:		15			
--Details--					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: INDUSTRIAL MACHINERY AND EQUIPMENT
SIC/NAICS Code: 5084

---

20 | **7 of 39** | **E/88.7** | **92.8 / -2.00** | **Ontario Testing Labs Inc.**
1440 GRAHAM'S LANE, UNIT #9, BURLINGTON
CITY CITY OF BURLINGTON
ON | **EBR**

EBR Registry No: IA7E0420
Ministry Ref No: 8349693 19970317
Notice Type: Instrument Decision
Notice Stage:
Notice Date: May 05, 1997
Proposal Date: March 25, 1997
Year: 1997
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Ontario Testing Labs Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 1440 Graham's Lane, Unit #9, Burlington Ontario, L7L 1W3
Comment Period:
URL:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

1440 GRAHAM'S LANE, UNIT #9, BURLINGTON CITY CITY OF BURLINGTON

---

20 | **8 of 39** | **E/88.7** | **92.8 / -2.00** | **Endress + Hauser Canada Ltd.**
1440 Grahams Lane Unit 1
Burlington ON L7S 1W3 | **SCT**

Established: 1990
Plant Size (ft²):
Employment: 30

--Details--
Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

---

20 | **9 of 39** | **E/88.7** | **92.8 / -2.00** | **Thyssen Krupp Elevator Limited**
1440 Grahams Lane Unit 3
Burlington ON L7S 1W3 | **SCT**

Established: 1900
Plant Size (ft²):
Employment: 15

--Details--
Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	10 of 39	E/88.7	92.8 / -2.00	DOVER CORPORATION (CANADA) LIMITED12-701 1440 GRAHAM'S LANE, UNIT #3 BURLINGTON ON L7S 1W3	GEN

Generator No: ON0407707
SIC Code: 5799
SIC Description: OTHER MACHINERY, WH.
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	11 of 39	E/88.7	92.8 / -2.00	DOVER CORPORATION (CANADA) LIMITED 1440 GRAHAM'S LANE UNIT 3 BURLINGTON ON L7S 1W3	GEN

Generator No: ON0407707
SIC Code: 5799
SIC Description: OTHER MACHINERY, WH.
Approval Years: 99
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	12 of 39	E/88.7	92.8 / -2.00	THYSSEN DOVER ELEVATOR 1440 GRAHAM'S LANE UNIT 3 BURLINGTON ON L7S 1W3	GEN

Generator No: ON0407707
SIC Code: 5799
SIC Description: OTHER MACHINERY, WH.
Approval Years: 00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

---

20 | ***13 of 39*** | ***E/88.7*** | ***92.8 / -2.00*** | ***THYSSEN KRUPP ELEVATOR***
1440 GRAHAM'S LANE UNIT 3
BURLINGTON ON L7S 1W3 | ***GEN***

Generator No: ON0407707
SIC Code:
SIC Description:
Approval Years: 02,03,04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

---

20 | ***14 of 39*** | ***E/88.7*** | ***92.8 / -2.00*** | ***BCT BUSINESS (OUT OF BUSINESS) 05-745***
1440 GRAHAM'S LANE, UNIT #8
BURLINGTON ON L7S 1W3 | ***GEN***

Generator No: ON1503002
SIC Code: 2821
SIC Description: PLATEMAKING, ETC.
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

20 | ***15 of 39*** | ***E/88.7*** | ***92.8 / -2.00*** | ***ETRATECH MAN(OUT OF BUSINESS) 49-115***
1440 GRAHAMS LANE UNIT 6
BURLINGTON ON L7S 1W3 | ***GEN***

Generator No: ON1622300
SIC Code: 3352
SIC Description: ELECT. PARTS & COMP.
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

---

20 | ***16 of 39*** | ***E/88.7*** | ***92.8 / -2.00*** | ***ASH TEMPLE LTD.***
1440 GRAHAM'S LANE, SUITE 5
BURLINGTON ON L7S 1W3 | ***GEN***

Generator No: ON1695401
SIC Code: 8682
SIC Description: RADIOLOGICAL LAB.
Approval Years: 95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

20 | ***17 of 39*** | ***E/88.7*** | ***92.8 / -2.00*** | ***ONTARIO TESTING LABS***
1440 GRAHAMS LANE
BURLINGTON ON L7S 1W3 | ***GEN***

Generator No: ON2290700
SIC Code: 3799
SIC Description: OTHER CHEM. PROD.
Approval Years: 97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	18 of 39	E/88.7	92.8 / -2.00	ASH TEMPLE LTD. 1440 GRAHAM'S LANE SUITE 5 BURLINGTON ON L7S 1W3	GEN

Generator No: ON1695401
SIC Code: 8682
SIC Description: RADIOLOGICAL LAB.
Approval Years: 99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	19 of 39	E/88.7	92.8 / -2.00	BODYCOTE GALT MATERIALS TESTING LTD. 1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	GEN

Generator No: ON2290700
SIC Code: 3799
SIC Description: OTHER CHEM. PROD.
Approval Years: 99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	20 of 39	E/88.7	92.8 / -2.00	Bodycote Materials Testing Canada Inc. 1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	GEN

Generator No: ON2290700
SIC Code:
SIC Description:
Approval Years: 02,03,04,05,06

PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

20	***21 of 39***	***E/88.7***	***92.8 / -2.00***	***Magnus Chemicals Ltd.*** ***1440 Grahams Lane Unit 5*** ***Burlington ON L7S 1W3***	***SCT***

Established: 1946
Plant Size (ft²): 2100
Employment: 6

--Details--
Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Description: Service Establishment Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417920

Description: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
SIC/NAICS Code: 418410

20	***22 of 39***	***E/88.7***	***92.8 / -2.00***	***Pyramid Pumps*** ***1440 Grahams Lane Unit 3*** ***Burlington ON L7S 1W3***	***SCT***

Established: 01-SEP-97
Plant Size (ft²): 2500
Employment:

--Details--
Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	23 of 39	E/88.7	92.8 / -2.00	Scherzinger Pump Technology Inc. 1440 Grahams Lane Unit 3 Burlington ON L7S 1W3	SCT

Established: 2002
Plant Size (ft²): 2500
Employment: 1

--Details--
Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	24 of 39	E/88.7	92.8 / -2.00	Peters Steel Rule Dies Ltd. 1440 Grahams Lane Unit 6-7 Burlington ON L7S 1W3	SCT

Established: 1970
Plant Size (ft²): 4500
Employment: 8

--Details--
Description: Other Metalworking Machinery Manufacturing
SIC/NAICS Code: 333519

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	25 of 39	E/88.7	92.8 / -2.00	Scherzinger Pump Technology 1440 Grahams Lane Unit 3 Burlington ON L7S 1W3	SCT

Established: 01-JUL-02
Plant Size (ft²): 2500
Employment:

--Details--
Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	26 of 39	E/88.7	92.8 / -2.00	1440 Graham's Lane, Unit #9 Burlington ON L7S 1W3	EHS

Order No: 20070131005
Status: C
Report Type: CAN - Complete Report
Report Date: 2/5/2007
Date Received: 1/31/2007
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps And /or Site Plans

Nearest Intersection:
Municipality: Halton
Client Prov/State:
Search Radius (km): 0.25
X: -79.811216
Y: 43.332822

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	27 of 39	E/88.7	92.8 / -2.00	Bodycote Testing Group 1440 GRAHAMS LANE, UNIT 9 BURLINGTON ON L7S 1W3	GEN

Generator No: ON2290700

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Code: 541380
SIC Description: Testing Laboratories
Approval Years: 07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

20	28 of 39	E/88.7	92.8 / -2.00	**Exova** **1440 GRAHAMS LANE, UNIT 9** **BURLINGTON ON L7S 1W3**	GEN

Generator No: ON2290700
SIC Code: 541380
SIC Description: Testing Laboratories
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

20	29 of 39	E/88.7	92.8 / -2.00	**Exova** **1440 GRAHAMS LANE, UNIT 9** **BURLINGTON ON L7S 1W3**	GEN

Generator No: ON2290700
SIC Code: 541380

SIC Description: Testing Laboratories
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	30 of 39	E/88.7	92.8 / -2.00	**Exova** **1440 GRAHAMS LANE, UNIT 9** **BURLINGTON ON L7S 1W3**	GEN

Generator No: ON2290700
SIC Code: 541380
SIC Description: Testing Laboratories
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	31 of 39	E/88.7	92.8 / -2.00	**Exova** **1440 GRAHAMS LANE, UNIT 9** **BURLINGTON ON L7S 1W3**	GEN

Generator No: ON2290700
SIC Code: 541380
SIC Description: Testing Laboratories

Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

---

20 | ***32 of 39*** | ***E/88.7*** | ***92.8 / -2.00*** | ***Exova***
1440 GRAHAMS LANE, UNIT 9
BURLINGTON ON | ***GEN***

Generator No: ON2290700
SIC Code: 541380
SIC Description: TESTING LABORATORIES
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

---

20 | ***33 of 39*** | ***E/88.7*** | ***92.8 / -2.00*** | ***1440 Grahams Lane Unit 2*** | ***EHS***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Burlington ON

Order No:	20160830039	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Site Report	***Client Prov/State:***	ON
Report Date:	31-AUG-16	***Search Radius (km):***	.001
Date Received:	30-AUG-16	***X:***	-79.811089
Previous Site Name:		***Y:***	43.332818
Lot/Building Size:			
Additional Info Ordered:			

20	***34 of 39***	***E/88.7***	***92.8 / -2.00***	***Exova*** ***1440 GRAHAMS LANE, UNIT 9*** ***BURLINGTON ON L7S 1W3***	***GEN***

Generator No:	ON2290700
SIC Code:	541380
SIC Description:	TESTING LABORATORIES
Approval Years:	2016
PO Box No:	
Country:	Canada
Status:	
Co Admin:	Kathleen J Gibson
Choice of Contact:	CO_OFFICIAL
Phone No Admin:	905-631-7785 Ext.15112
Contaminated Facility:	No
MHSW Facility:	No

Detail(s)

Waste Class:	113
Waste Class Name:	ACID WASTE - OTHER METALS
Waste Class:	263
Waste Class Name:	ORGANIC LABORATORY CHEMICALS
Waste Class:	331
Waste Class Name:	WASTE COMPRESSED GASES
Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS
Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES
Waste Class:	253
Waste Class Name:	EMULSIFIED OILS

20	***35 of 39***	***E/88.7***	***92.8 / -2.00***	***Exova*** ***1440 GRAHAMS LANE, UNIT 9*** ***BURLINGTON ON L7S 1W3***	***GEN***

Generator No:	ON2290700
SIC Code:	541380
SIC Description:	TESTING LABORATORIES
Approval Years:	2015
PO Box No:	
Country:	Canada
Status:	
Co Admin:	Kathleen J Gibson
Choice of Contact:	CO_OFFICIAL
Phone No Admin:	905-631-7785 Ext.15112

Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

20 | ***36 of 39*** | ***E/88.7*** | ***92.8 / -2.00*** | ***Exova***
1440 GRAHAMS LANE, UNIT 9
BURLINGTON ON L7S 1W3 | ***GEN***

Generator No: ON2290700
SIC Code: 541380
SIC Description: TESTING LABORATORIES
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Kathleen J Gibson
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-631-7785 Ext.15112
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

20 | ***37 of 39*** | ***E/88.7*** | ***92.8 / -2.00*** | ***Exova Burlington***
1440 GRAHAMS LANE, UNIT 9 | ***GEN***

BURLINGTON ON L7S 1W3

Generator No: ON2290700
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 113 B
Waste Class Name: Acid solutions - containing other metals and non-metals

Waste Class: 113 C
Waste Class Name: Acid solutions - containing other metals and non-metals

Waste Class: 148 A
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 B
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 R
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 253 L
Waste Class Name: Emulsified oils

Waste Class: 253 T
Waste Class Name: Emulsified oils

Waste Class: 263 B
Waste Class Name: Misc. waste organic chemicals

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

20	***38 of 39***	***E/88.7***	***92.8 / -2.00***	***Exova Burlington*** ***1440 GRAHAMS LANE, UNIT 9*** ***BURLINGTON ON L7S 1W3***	***GEN***

Generator No: ON2290700
SIC Code:
SIC Description:

Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 253 T
Waste Class Name: Emulsified oils

Waste Class: 113 C
Waste Class Name: Acid solutions - containing other metals and non-metals

Waste Class: 263 B
Waste Class Name: Misc. waste organic chemicals

Waste Class: 148 R
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 253 L
Waste Class Name: Emulsified oils

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 113 B
Waste Class Name: Acid solutions - containing other metals and non-metals

Waste Class: 148 A
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 B
Waste Class Name: Misc. wastes and inorganic chemicals

20	39 of 39	E/88.7	92.8 / -2.00	***Exova Burlington*** ***1440 GRAHAMS LANE, UNIT 9*** ***BURLINGTON ON L7S 1W3***	***GEN***

Generator No: ON2290700
SIC Code:
SIC Description:
Approval Years: As of Jan 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:

Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148 A
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 263 B
Waste Class Name: Misc. waste organic chemicals

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 113 C
Waste Class Name: Acid solutions - containing other metals and non-metals

Waste Class: 148 R
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 113 B
Waste Class Name: Acid solutions - containing other metals and non-metals

Waste Class: 253 T
Waste Class Name: Emulsified oils

Waste Class: 148 B
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 253 L
Waste Class Name: Emulsified oils

---

21 | ***1 of 1*** | ***SSE/89.8*** | ***94.0 / -0.83*** | ***1380 GRAHAM'S LANE BURLINGTON ON*** | ***WWIS***

Well ID:	2810171	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	03/10/2005
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z22705	***Contractor:***	7075
Tag:	A025452	***Form Version:***	3
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	HALTON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	

Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/281\2810171.pdf

Additional Detail(s) (Map)

Well Completed Date:	02/09/2005
Year Completed:	2005
Depth (m):	4.5
Latitude:	43.3313130058869
Longitude:	-79.8127208810228
Path:	281\2810171.pdf

Bore Hole Information

Bore Hole ID:	11319126	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	596252.00
Code OB Desc:		***North83:***	4798292.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	02/09/2005	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	933007147
Layer:	2
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	
Mat3 Desc:	
Formation Top Depth:	3.5
Formation End Depth:	4.5
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	933007146
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	01
Most Common Material:	FILL
Mat2:	

Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 3.5
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933265927
Layer: 1
Plug From: 0.10000000149011612
Plug To: 1.2000000476837158
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 962810171
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 11333981
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930860119
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.5
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933411937
Layer: 1
Slot:
Screen Top Depth: 1.5
Screen End Depth: 4.5
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 5.5

Water Details

Water ID: 934058346
Layer: 1
Kind Code: 1
Kind: FRESH

Water Found Depth: 3.5
Water Found Depth UOM: m

Hole Diameter

Hole ID: 11537685
Diameter: 20.0
Depth From: 0.0
Depth To: 4.5
Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Bore Hole ID: 11319126
Depth M: 4.5
Year Completed: 2005
Well Completed Dt: 02/09/2005
Audit No: Z22705
Path: 281\2810171.pdf
Tag No: A025452
Contractor: 7075
Latitude: 43.3313130058869
Longitude: -79.8127208810228
Y: 43.33131300352595
X: -79.81272073220887

---

22 ***1 of 4*** ***N/90.5*** ***94.8 / 0.00*** ***850 Legion Road Burlington ON L7S 1T6*** ***EHS***

Order No: 20200622126
Status: C
Report Type: Standard Report
Report Date: 25-JUN-20
Date Received: 22-JUN-20
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8131001
Y: 43.3339038

---

22 ***2 of 4*** ***N/90.5*** ***94.8 / 0.00*** ***850 Legion Road Burlington ON L7S 1T6*** ***EHS***

Order No: 20200622126
Status: C
Report Type: Standard Report
Report Date: 25-JUN-20
Date Received: 22-JUN-20
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8131001
Y: 43.3339038

---

22 ***3 of 4*** ***N/90.5*** ***94.8 / 0.00*** ***850 Legion Road Burlington ON L7S 1T6*** ***EHS***

Order No: 20200622126
Status: C
Report Type: Standard Report
Report Date: 25-JUN-20
Date Received: 22-JUN-20
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8131001
Y: 43.3339038

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
22	4 of 4	N/90.5	94.8 / 0.00	850 Legion Road Burlington ON L7S 1T6	EHS

Order No: 20200622126
Status: C
Report Type: Standard Report
Report Date: 25-JUN-20
Date Received: 22-JUN-20
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8131001
Y: 43.3339038

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
23	1 of 1	SW/91.0	94.8 / 0.00	Hydro One Networks Inc. 1355 Stephenson Dr. Burlington ON L7S 2M5	GEN

Generator No: ON4223579
SIC Code:
SIC Description:
Approval Years: As of Oct 2019
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146 L
Waste Class Name: Other specified inorganic sludges, slurries or solids

---

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	1 of 1	SSE/95.5	93.8 / -1.00	802 Hagar Ave Burlington ON	WWIS

Well ID: 7354371
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z330614
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 02/19/2020
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7241
Form Version: 7
Owner:
County: HALTON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 01/31/2020
Year Completed: 2020
Depth (m):
Latitude: 43.3313917247382
Longitude: -79.8124973170305
Path:

Bore Hole Information

Bore Hole ID: 1008181265
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 01/31/2020
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 596270.00
North83: 4798301.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1008353281
Layer: 2
Plug From: 6.0
Plug To: 1.600000023841858
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008353280
Layer: 1
Plug From: 0.0
Plug To: 6.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008353282
Layer: 3
Plug From: 1.600000023841858
Plug To: 20.0
Plug Depth UOM: ft

Pipe Information

Pipe ID: 1008352696
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1008353751
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	
Casing Diameter:	2.0
Casing Diameter UOM:	Inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1008353847
Layer:	1
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	5
Screen Depth UOM:	
Screen Diameter UOM:	inch
Screen Diameter:	2.25

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008353987
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Links

Bore Hole ID:	1008181265	**Tag No:**	
Depth M:		**Contractor:**	7241
Year Completed:	2020	**Latitude:**	43.3313917247382
Well Completed Dt:	01/31/2020	**Longitude:**	-79.8124973170305
Audit No:	Z330614	**Y:**	43.33139172246443
Path:		**X:**	-79.81249716854815

25 | ***1 of 1*** | ***SE/110.8*** | ***93.8 / -1.00*** | ***802 Hager Ave Burlington ON*** | ***WWIS***

Well ID:	7354375	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	02/19/2020
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes

Audit No:	Z330613	**Contractor:**	7241
Tag:		**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	01/31/2020
Year Completed:	2020
Depth (m):	
Latitude:	43.3313889071493
Longitude:	-79.8122260014817
Path:	

Bore Hole Information

Bore Hole ID:	1008181277	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596292.00
Code OB Desc:		**North83:**	4798301.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	01/31/2020	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1008353292
Layer:	1
Plug From:	0.0
Plug To:	6.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008353294
Layer:	3
Plug From:	1.600000023841858
Plug To:	20.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008353293
Layer:	2
Plug From:	6.0
Plug To:	1.600000023841858
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1008352700
Casing No:	0
Comment:	
Alt Name:	

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008353991
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1008353550
Diameter:	6.0
Depth From:	0.0
Depth To:	10.0
Hole Depth UOM:	ft
Hole Diameter UOM:	Inch

Links

Bore Hole ID:	1008181277	***Tag No:***	
Depth M:		***Contractor:***	7241
Year Completed:	2020	***Latitude:***	43.3313889071493
Well Completed Dt:	01/31/2020	***Longitude:***	-79.8122260014817
Audit No:	Z330613	***Y:***	43.33138890485493
Path:		***X:***	-79.81222585226581

26	1 of 1	ENE/112.6	93.8 / -1.00	439 Graham's Lane Burlington ON	WWIS

Well ID:	7343297	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Monitoring and Test Hole	***Date Received:***	09/06/2019

Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z316536	**Contractor:**	7241
Tag:	A257273	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	08/13/2019
Year Completed:	2019
Depth (m):	7.3152
Latitude:	43.3336145112607
Longitude:	-79.8115041704658
Path:	

Bore Hole Information

Bore Hole ID:	1007661408	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596347.00
Code OB Desc:		**North83:**	4798549.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	08/13/2019	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1007858483
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	
Mat3 Desc:	
Formation Top Depth:	3.0
Formation End Depth:	17.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1007858484
Layer:	3
Color:	7
General Color:	RED
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Mat2 Desc:	SAND
Mat3:	
Mat3 Desc:	
Formation Top Depth:	17.0
Formation End Depth:	24.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1007858482
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	01
Mat3 Desc:	FILL
Formation Top Depth:	0.0
Formation End Depth:	3.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1007859791
Layer:	3
Plug From:	13.0
Plug To:	24.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1007859789
Layer:	1
Plug From:	0.0
Plug To:	0.05000000074505806
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1007859790
Layer:	2
Plug From:	0.5
Plug To:	13.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1007861506
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	

Pipe Information

Pipe ID:	1007857244
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007862150
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	14.0
Casing Diameter:	2.0
Casing Diameter UOM:	Inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1007862668
Layer:	1
Slot:	10
Screen Top Depth:	14.0
Screen End Depth:	24.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.25

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1007863409
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1007860945

Diameter:	6.0
Depth From:	0.0
Depth To:	24.0
Hole Depth UOM:	ft
Hole Diameter UOM:	Inch

Links

Bore Hole ID:	1007661408	**Tag No:**	A257273
Depth M:	7.3152	**Contractor:**	7241
Year Completed:	2019	**Latitude:**	43.3336145112607
Well Completed Dt:	08/13/2019	**Longitude:**	-79.8115041704658
Audit No:	Z316536	**Y:**	43.333614508826436
Path:		**X:**	-79.81150402093496

27 ***1 of 1*** ***NNE/116.9*** ***94.8 / 0.00*** ***850 Brant Street Burlington ON*** ***WWIS***

Well ID:	7330856	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	04/01/2019
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z287723	**Contractor:**	7609
Tag:	A242663	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	02/15/2019
Year Completed:	2019
Depth (m):	4.75
Latitude:	43.334156683876
Longitude:	-79.8125544559342
Path:	

Bore Hole Information

Bore Hole ID:	1007413109	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596261.00
Code OB Desc:		**North83:**	4798608.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	02/15/2019	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1007835432
Layer: 1
Color:
General Color:
Mat1: 01
Most Common Material: FILL
Mat2: 28
Mat2 Desc: SAND
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 1.2200000286102295
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007835434
Layer: 3
Color: 2
General Color: GREY
Mat1: 34
Most Common Material: TILL
Mat2: 06
Mat2 Desc: SILT
Mat3:
Mat3 Desc:
Formation Top Depth: 3.049999952316284
Formation End Depth: 4.75
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007835433
Layer: 2
Color: 7
General Color: RED
Mat1: 34
Most Common Material: TILL
Mat2: 06
Mat2 Desc: SILT
Mat3:
Mat3 Desc:
Formation Top Depth: 1.2200000286102295
Formation End Depth: 3.049999952316284
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007836410

Layer: 1
Plug From: 0.0
Plug To: 1.2200000286102295
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1007837889
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1007834303
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007838315
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.5199999809265137
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1007838599
Layer: 1
Slot: 10
Screen Top Depth: 1.5199999809265137
Screen End Depth: 4.75
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.0

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1007839321
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:

Flowing:

Hole Diameter

Hole ID:	1007837204
Diameter:	10.199999809265137
Depth From:	0.0
Depth To:	4.75
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	1007413109	***Tag No:***	A242663
Depth M:	4.75	***Contractor:***	7609
Year Completed:	2019	***Latitude:***	43.334156683876
Well Completed Dt:	02/15/2019	***Longitude:***	-79.8125544559342
Audit No:	Z287723	***Y:***	43.33415668188841
Path:	733\7330856.pdf	***X:***	-79.81255430742837

---

28 ***1 of 1*** ***ENE/119.1*** ***93.8 / -1.00*** ***1439 Grahams Lane Burlington ON L7S 1W5*** ***EHS***

Order No:	20190710002	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Standard Report	***Client Prov/State:***	ON
Report Date:	15-JUL-19	***Search Radius (km):***	.25
Date Received:	10-JUL-19	***X:***	-79.811534
Previous Site Name:		***Y:***	43.333718
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

---

29 ***1 of 6*** ***ENE/119.1*** ***93.8 / -1.00*** ***Burlington Hydro Inc. 1439 Grahams Lane Burlington ON L7S 1W4*** ***GEN***

Generator No:	ON7616426
SIC Code:	221122
SIC Description:	Electric Power Distribution
Approval Years:	04
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

---

29 ***2 of 6*** ***ENE/119.1*** ***93.8 / -1.00*** ***1439 Grahams Lane Burlington ON L7S 1W5*** ***EHS***

Order No:	20110722006	***Nearest Intersection:***	Legion Road and Grahams Lane
Status:	C	***Municipality:***	Burlington
Report Type:	Standard Select Report	***Client Prov/State:***	ON
Report Date:	8/2/2011	***Search Radius (km):***	0.25
Date Received:	7/22/2011 10:23:35 AM	***X:***	-79.811457
Previous Site Name:		***Y:***	43.333574
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
29	3 of 6	ENE/119.1	93.8 / -1.00	1439 Grahams Lane Burlington ON L7S 1W5	EHS

Order No:	22060100011	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	06-JUN-22	**Search Radius (km):**	.25
Date Received:	01-JUN-22	**X:**	-79.8115344
Previous Site Name:		**Y:**	43.3337184
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
29	4 of 6	ENE/119.1	93.8 / -1.00	1439 Grahams Lane Burlington ON L7S 1W5	EHS

Order No:	22060100011	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	06-JUN-22	**Search Radius (km):**	.25
Date Received:	01-JUN-22	**X:**	-79.8115344
Previous Site Name:		**Y:**	43.3337184
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
29	5 of 6	ENE/119.1	93.8 / -1.00	1439 Grahams Lane Burlington ON L7S 1W5	EHS

Order No:	22060100011	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	06-JUN-22	**Search Radius (km):**	.25
Date Received:	01-JUN-22	**X:**	-79.8115344
Previous Site Name:		**Y:**	43.3337184
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
29	6 of 6	ENE/119.1	93.8 / -1.00	1439 Grahams Lane Burlington ON L7S 1W5	EHS

Order No:	22060100011	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	06-JUN-22	**Search Radius (km):**	.25
Date Received:	01-JUN-22	**X:**	-79.8115344
Previous Site Name:		**Y:**	43.3337184
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
30	1 of 3	NE/119.4	93.9 / -0.90	BURLINGTON ASS. FOR COMMUNITY LIVING 831 LEGION ROAD BURLINGTON ON L7S 1T6	GEN

Generator No:	ON1368800
SIC Code:	8624
SIC Description:	MENTAL. DISABLED H.
Approval Years:	90
PO Box No:	

Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

---

30 | ***2 of 3*** | ***NE/119.4*** | ***93.9 / -0.90*** | ***BURLINGTON ASS. FOR COMMUNITY 05-519 LIVING 831 LEGION ROAD BURLINGTON ON L7S 1T6*** | ***GEN***

Generator No: ON1368800
SIC Code: 8624
SIC Description: MENTAL. DISABLED H.
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

---

30 | ***3 of 3*** | ***NE/119.4*** | ***93.9 / -0.90*** | ***831 Legion Rd Burlington On Burlington ON L7S1T6*** | ***EHS***

Order No:	20140226016	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Site Report	***Client Prov/State:***	ON
Report Date:	27-FEB-14	***Search Radius (km):***	.001
Date Received:	26-FEB-14	***X:***	-79.812027
Previous Site Name:		***Y:***	43.333919
Lot/Building Size:			
Additional Info Ordered:			

---

31 | ***1 of 1*** | ***WNW/123.9*** | ***100.3 / 5.44*** | ***ON*** | ***BORE***

Borehole ID:	622676	***Inclin FLG:***	No
OGF ID:	215523130	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	FEB-1967	***Municipality:***	
Static Water Level:		***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.333597
Total Depth m:	8.1	***Longitude DD:***	-79.815359
Depth Ref:	Ground Surface	***UTM Zone:***	17

Depth Elev:		***Easting:***	596035
Drill Method:	Power auger	***Northing:***	4798543
Orig Ground Elev m:	97.5	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	99.7		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218426649	***Mat Consistency:***	Hard
Top Depth:	2.7	***Material Moisture:***	
Bottom Depth:	3	***Material Texture:***	
Material Color:	Green	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:	Gravel	***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	SILT,CLAY,GRAVEL. GREEN,HARD,UNIFORM, AGE GLACIAL.		

Geology Stratum ID:	218426651	***Mat Consistency:***	Hard
Top Depth:	5.2	***Material Moisture:***	
Bottom Depth:	8.1	***Material Texture:***	Medium
Material Color:	Green	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:	Sand	***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	SILT,CLAY,SAND MEDIUM. GREEN,HARD,UNIFORM, AGE GLACIAL. 008 010 012 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218426648	***Mat Consistency:***	Loose
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	2.7	***Material Texture:***	Fine to Medium
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Sand	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Gravel	***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	SAND-FINE TO MEDIUM,SILT,GRAVEL. BROWN,LOOSE,GRANULAR, AGE GLACIAL.		

Geology Stratum ID:	218426650	***Mat Consistency:***	Dense
Top Depth:	3	***Material Moisture:***	
Bottom Depth:	5.2	***Material Texture:***	
Material Color:	Green	***Non Geo Mat Type:***	
Material 1:	Sand	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Clay	***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	SAND,SILT,CLAY. GREEN,VERY DENSE,GRANULAR, AGE GLACIAL.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	M	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: HAM.txt RecordID: 016760 NTS_Sheet: 30M05C
Confiden 1: Reliable information but incomplete.

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada
Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

32 | **1 of 4** | **SE/128.0** | **93.8 / -1.00** | **802 Hager Avenue Burlington ON L7S** | **EHS**

Order No: 20200206139
Status: C
Report Type: Custom Report
Report Date: 11-FEB-20
Date Received: 06-FEB-20
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.81198215
Y: 43.33134391

---

32 | **2 of 4** | **SE/128.0** | **93.8 / -1.00** | **802 Hager Avenue Burlington ON L7S** | **EHS**

Order No: 20200206139
Status: C
Report Type: Custom Report
Report Date: 11-FEB-20
Date Received: 06-FEB-20
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.81198215
Y: 43.33134391

---

32 | **3 of 4** | **SE/128.0** | **93.8 / -1.00** | **802 Hager Avenue Burlington ON L7S** | **EHS**

Order No: 20200206139
Status: C
Report Type: Custom Report
Report Date: 11-FEB-20
Date Received: 06-FEB-20
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.81198215
Y: 43.33134391

---

32 | **4 of 4** | **SE/128.0** | **93.8 / -1.00** | **802 Hager Avenue Burlington ON L7S** | **EHS**

Order No: 20200206139
Status: C
Report Type: Custom Report
Report Date: 11-FEB-20
Date Received: 06-FEB-20
Previous Site Name:
Lot/Building Size:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.81198215
Y: 43.33134391

Additional Info Ordered:

33 | ***1 of 1*** | ***N/128.4*** | ***93.7 / -1.14*** | ***ON*** | ***BORE***

Borehole ID:	623976	***Inclin FLG:***	No
OGF ID:	215524428	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	MAY-1968	***Municipality:***	
Static Water Level:		***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.3343
Total Depth m:	5.8	***Longitude DD:***	-79.813618
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	596175
Drill Method:	Power auger	***Northing:***	4798623
Orig Ground Elev m:	95.8	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	93.4		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218431695	***Mat Consistency:***	Loose
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	.5	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Soil	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	SOIL. LOOSE,AGE POST-GLACIAL.		

Geology Stratum ID:	218431696	***Mat Consistency:***	Compact
Top Depth:	.5	***Material Moisture:***	
Bottom Depth:	1.7	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Sand	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	lacustrine
Gsc Material Description:			
Stratum Description:	SAND,SILT. BROWN,LACUSTRINE,COMPACT, AGE GLACIAL.		

Geology Stratum ID:	218431697	***Mat Consistency:***	Hard
Top Depth:	1.7	***Material Moisture:***	
Bottom Depth:	5.8	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Clay	***Geologic Period:***	
Material 4:	Gravel	***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,CLAY, GRAVEL. BROWN,GLACIAL,VERY HARD, AGE GLACIAL. 027 0160100240000000 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	M	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: HAM.txt RecordID: 029760 NTS_Sheet: 30M05C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

34 ***1 of 1*** ***ENE/128.8*** ***93.8 / -1.00*** ***1439 Graham's Lane Burlington ON*** ***WWIS***

Well ID:	7343299	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Monitoring and Test Hole	***Date Received:***	09/06/2019
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z316535	***Contractor:***	7241
Tag:	A257272	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	HALTON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	08/13/2019
Year Completed:	2019
Depth (m):	4.8768
Latitude:	43.3337211327781
Longitude:	-79.8113664005347
Path:	

Bore Hole Information

Bore Hole ID:	1007661414	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	596358.00
Code OB Desc:		***North83:***	4798561.00

Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	08/13/2019	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1007858491
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	
Mat3 Desc:	
Formation Top Depth:	2.0
Formation End Depth:	16.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1007858490
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	01
Mat3 Desc:	FILL
Formation Top Depth:	0.5
Formation End Depth:	2.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1007858492
Layer:	4
Color:	
General Color:	
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	16.0
Formation End Depth:	
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1007858489
Layer:	1
Color:	2
General Color:	GREY
Mat1:	27
Most Common Material:	OTHER
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.5
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1007859797
Layer:	3
Plug From:	5.0
Plug To:	16.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1007859798
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1007859795
Layer:	1
Plug From:	0.0
Plug To:	0.5
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1007859796
Layer:	2
Plug From:	0.5
Plug To:	5.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1007861516
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	

Pipe Information

Pipe ID:	1007857246
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007862152
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	6.0
Casing Diameter:	2.0
Casing Diameter UOM:	Inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1007862670
Layer:	1
Slot:	10
Screen Top Depth:	6.0
Screen End Depth:	16.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.25

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1007863411
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1007860947
Diameter:	6.0
Depth From:	0.0
Depth To:	16.0
Hole Depth UOM:	ft
Hole Diameter UOM:	Inch

Links

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Bore Hole ID:	1007661414	**Tag No:**	A257272
Depth M:	4.8768	**Contractor:**	7241
Year Completed:	2019	**Latitude:**	43.3337211327781
Well Completed Dt:	08/13/2019	**Longitude:**	-79.8113664005347
Audit No:	Z316535	**Y:**	43.33372113047621
Path:		**X:**	-79.81136625264239

---

35 | **1 of 16** | **SE/128.9** | **93.8 / -1.00** | **802 Hager Avenue, Burlington ON L7S 1X2** | **EHS**

Order No:	20070615032	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	CAN - Complete Report	**Client Prov/State:**	
Report Date:	6/26/2007	**Search Radius (km):**	0.25
Date Received:	6/15/2007	**X:**	-79.811834
Previous Site Name:		**Y:**	43.331489
Lot/Building Size:			
Additional Info Ordered:			

---

35 | **2 of 16** | **SE/128.9** | **93.8 / -1.00** | **802 Hager Avenue, Burlington ON L7S 1X2** | **EHS**

Order No:	20090406002	**Nearest Intersection:**	Hager Avenue and Ghent Avenue
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	4/15/2009	**Search Radius (km):**	0.25
Date Received:	4/6/2009	**X:**	-79.811695
Previous Site Name:		**Y:**	43.331351
Lot/Building Size:			
Additional Info Ordered:			

---

35 | **3 of 16** | **SE/128.9** | **93.8 / -1.00** | **Wellington Park Care Centre, 802 Hagar Avenue, Burlington ON L7S 1X2** | **GEN**

Generator No:	ON6214142
SIC Code:	623310
SIC Description:	
Approval Years:	2011
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

---

35 | **4 of 16** | **SE/128.9** | **93.8 / -1.00** | **Wellington Park Care Centre, 802 Hagar Avenue, Burlington ON L7S 1X2** | **GEN**

Generator No:	ON6214142
SIC Code:	623310
SIC Description:	Community Care Facilities for the Elderly
Approval Years:	2012
PO Box No:	
Country:	
Status:	
Co Admin:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

---

35 **5 of 16** **SE/128.9** **93.8 / -1.00** **Wellington Park Care Centre Facility Inc.**
802 Hager Avenue CITY OF BURLINGTON
ON **CPU**

EBR Registry No: 012-2474
Ministry Ref No: 5555-9GPKV8
Notice Type: Instrument Decision
Notice Stage:
Notice Date: November 13, 2014
Proposal Date: September 02, 2014
Year: 2014
Instrument Type: (EPA s. 168.6) - Certificate of Property Use
Off Instrument Name:
Posted By:
Company Name: Wellington Park Care Centre Facility Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 50 Samor Road , Suite 205, Toronto Ontario, Canada M6A 1J6
Comment Period:
URL:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

802 Hager Avenue CITY OF BURLINGTON

---

35 **6 of 16** **SE/128.9** **93.8 / -1.00** **Wellington Park Care Centre**
802 Hagar Avenue
Burlington ON **GEN**

Generator No: ON6214142
SIC Code: 623310
SIC Description:
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

35 **7 of 16** **SE/128.9** **93.8 / -1.00** **802 Hager Ave**
Burlington ON L7S1X2 **EHS**

Order No: 20150601128
Status: C
Report Type: Custom Report
Report Date: 05-JUN-15
Date Received: 01-JUN-15

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.81201

Previous Site Name: ***Y:*** 43.331357
Lot/Building Size:
Additional Info Ordered:

---

35 ***8 of 16*** ***SE/128.9*** ***93.8 / -1.00*** ***Responsive Management Inc*** ***GEN***
802 Hager Avenue
Burlington ON L7S1X2

Generator No:	ON5280829
SIC Code:	623310
SIC Description:	623310
Approval Years:	2015
PO Box No:	
Country:	Canada
Status:	
Co Admin:	Scott McIntyre
Choice of Contact:	CO_ADMIN
Phone No Admin:	905-682-2427 Ext.
Contaminated Facility:	No
MHSW Facility:	No

Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

---

35 ***9 of 16*** ***SE/128.9*** ***93.8 / -1.00*** ***Wellington Park Care Centre*** ***GEN***
802 Hagar Avenue
Burlington ON L7S 1X2

Generator No:	ON6214142
SIC Code:	623310
SIC Description:	623310
Approval Years:	2015
PO Box No:	
Country:	Canada
Status:	
Co Admin:	Juan Sosa
Choice of Contact:	CO_OFFICIAL
Phone No Admin:	905-637-9481 Ext.229
Contaminated Facility:	No
MHSW Facility:	No

Detail(s)

Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES

---

35 ***10 of 16*** ***SE/128.9*** ***93.8 / -1.00*** ***Wellington Park Care Centre*** ***GEN***
802 Hagar Avenue
Burlington ON L7S 1X2

Generator No:	ON6214142
SIC Code:	623310
SIC Description:	623310
Approval Years:	2014
PO Box No:	
Country:	Canada
Status:	
Co Admin:	Juan Sosa
Choice of Contact:	CO_OFFICIAL

Phone No Admin: 905-637-9481 Ext.229
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

35 | **11 of 16** | **SE/128.9** | **93.8 / -1.00** | **Suncor Energy Products**
802 Hager Ave,
Burlington ON L7S 1X2 | **GEN**

Generator No: ON9071437
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

---

35 | **12 of 16** | **SE/128.9** | **93.8 / -1.00** | **802 Hager Avenue**
Burlington ON | **EHS**

Order No: 20171017125
Status: C
Report Type: Custom Report
Report Date: 24-OCT-17
Date Received: 17-OCT-17
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.811995
Y: 43.331387

---

35 | **13 of 16** | **SE/128.9** | **93.8 / -1.00** | **Suncor Energy Products**
802 Hager Ave,
Burlington ON L7S 1X2 | **GEN**

Generator No: ON9071437
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:

MHSW Facility:

Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

---

35 | ***14 of 16*** | ***SE/128.9*** | ***93.8 / -1.00*** | ***WELLINGTON PARK CARE CENTRE FACILITY INC.***
802 HAGER AVENUE, BURLINGTON, ON L7S 1X2
Burlington ON | ***RSC***

RSC ID: 227208
RA No: RA 1179-11
RSC Type: Phase 1 and 2 RSC with RA
Curr Property Use: Residential
Ministry District: Halton-Peel District Office
Filing Date: 2020/10/13
Date Ack:
Date Returned:
Restoration Type:
Soil Type:
Criteria:
CPU Issued Sect 1686:
Cert Date:
Cert Prop Use No:
Intended Prop Use: Residential
Qual Person Name: GRACE FERGUSON
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N):
Accuracy Estimate:
Telephone:
Fax:
Email:
Asmt Roll No: 2402-05-0502-08400-0000
Prop ID No (PIN): 07090-0437 (LT)
Property Municipal Address: 802 HAGER AVENUE, BURLINGTON, ON L7S 1X2
Mailing Address:
Latitude & Latitude:
UTM Coordinates:
Consultant:
Legal Desc:
Measurement Method:
Applicable Standards:
RSC PDF: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=134107&fileName=BROWNFIELDS-E.pdf

Document(s) Detail

Document Heading: Supporting Documents
Document Name: Survey.pdf
Document Type: A Current plan of Survey
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=136766&fileName=Survey.pdf

Document Heading: Supporting Documents
Document Name: revised_ph_two_csm_122121029_20200408.pdf
Document Type: Phase 2 Conceptual Site Model
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=134103&fileName=revised_ph_two_csm_122121029_20200408.pdf

Document Heading: Supporting Documents
Document Name: transfer_802_hager_and_nominee_agreement.pdf
Document Type: Copy of any deed(s), transfer(s) or other document(s)
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=134106&fileName=transfer_802_hager_and_nominee_agreement.pdf

Document Heading: Supporting Documents
Document Name: APEC_Table_with_disclaimer_rsc_122121029.pdf

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Document Type: Area(s) of Potential Environmental Concern
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=134113&fileName=APEC_Table_with_disclaimer_rsc_122121029.pdf

Document Heading: Supporting Documents
Document Name: Current_Past_Use_rsc_122121029.pdf
Document Type: Table of Current and Past Property Use
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=134104&fileName=Current_Past_Use_rsc_122121029.pdf

Document Heading: Supporting Documents
Document Name: CertofStatus.pdf
Document Type: Certificate of Status
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=136765&fileName=CertofStatus.pdf

Document Heading: Orders and Notices
Document Name: 802 Hager Avenue Burlington CPU 5555-9GPKV8 FINAL.pdf
Document Type: CPU
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=136763&fileName=802+Hager+Avenue+Burlington+CPU+5555-9GPKV8+FINAL.pdf

Document Heading: Supporting Documents
Document Name: PSS_RA1179-11_Oct31-14.xls
Document Type: Property Specific Standards
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=134111&fileName=PSS_RA1179-11_Oct31-14.xls

Document Heading: Supporting Documents
Document Name: Hager Letter - May 2020.pdf
Document Type: Lawyer's letter consisting of a legal description of the property
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=134105&fileName=Hager+Letter+-+May+2020.pdf

---

35	***15 of 16***	***SE/128.9***	***93.8 / -1.00***	***Suncor Energy Products*** ***802 Hager Ave,*** ***Burlington ON L7S 1X2***	***GEN***

Generator No: ON9071437
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 221 L
Waste Class Name: Light fuels

35	***16 of 16***	***SE/128.9***	***93.8 / -1.00***	***Suncor Energy Products*** ***802 Hager Ave,*** ***Burlington ON L7S 1X2***	***GEN***

Generator No: ON9071437

SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221 L
Waste Class Name: LIGHT FUELS

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

36 | ***1 of 1*** | ***NE/131.5*** | ***93.9 / -0.97*** | ***ON*** | ***BORE***

Borehole ID: 621933
OGF ID: 215522387
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: DEC-1966
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 6.6
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Power auger
Orig Ground Elev m: 91.4
Elev Reliabil Note:
DEM Ground Elev m: 93.8
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.334102
Longitude DD: -79.811895
UTM Zone: 17
Easting: 596315
Northing: 4798603
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218423333
Top Depth: .2
Bottom Depth: .7
Material Color: Brown
Material 1: Fill
Material 2: Sand
Material 3: Silt
Material 4:
Gsc Material Description:
Stratum Description: FILL,SAND-MEDIUM, SILT. BROWN,MAN-MADE,LOOSE,GRANULAR,AGE POST-GLACIAL.

Mat Consistency: Loose
Material Moisture:
Material Texture: Medium
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: fill

Geology Stratum ID: 218423336
Top Depth: 1.8
Bottom Depth: 4.8
Material Color: Brown
Material 1: Till
Material 2: Silt

Mat Consistency: Hard
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:

Material 3:	Clay	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,CLAY. BROWN,GLACIAL,HARD,UNIFORM, AGE GLACIAL.		

Geology Stratum ID:	218423338	**Mat Consistency:**	Dense
Top Depth:	5.8	**Material Moisture:**	
Bottom Depth:	6.6	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Shale	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SAND,SILT,SHALEBROWN,GLACIAL,DENSE,LAYERED, AGE GLACIAL. 022 015 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218423334	**Mat Consistency:**	Loose
Top Depth:	.7	**Material Moisture:**	
Bottom Depth:	1.2	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Soil	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SOIL,SAND,SILT. LOOSE,GRANULAR, AGE POST-GLACIAL.		

Geology Stratum ID:	218423335	**Mat Consistency:**	Compact
Top Depth:	1.2	**Material Moisture:**	
Bottom Depth:	1.8	**Material Texture:**	Medium
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Organic	**Geologic Period:**	
Material 4:		**Depositional Gen:**	organic
Gsc Material Description:			
Stratum Description:	SAND-MEDIUM,SILT, ORGANIC. BROWN,COMPACT,GRANULAR, AGE GLACIAL.		

Geology Stratum ID:	218423332	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.2	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Stones	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,STONES. MAN-MADE,BROKEN, AGE POST-GLACIAL.		

Geology Stratum ID:	218423337	**Mat Consistency:**	Soft
Top Depth:	4.8	**Material Moisture:**	
Bottom Depth:	5.8	**Material Texture:**	
Material Color:	Green	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT. GREEN,GLACIAL,VERY SOFT, UNIFORM,AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: HAM.txt RecordID: 009330 NTS_Sheet: 30M05C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

37 | ***1 of 1*** | ***ENE/131.6*** | ***93.4 / -1.41*** | ***439 Graham's Lane Burlington ON*** | ***WWIS***

Well ID:	7343298	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	09/06/2019
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z316537	**Contractor:**	7241
Tag:	A257274	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	08/13/2019
Year Completed:	2019
Depth (m):	5.1816
Latitude:	43.3335926603222
Longitude:	-79.8111345326441
Path:	

Bore Hole Information

Bore Hole ID:	1007661411	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596377.00
Code OB Desc:		**North83:**	4798547.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	08/13/2019	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Loc Method Desc:	on Water Well Record
Elevrc Desc:	
Location Source Date:	
Improvement Location Source:	
Improvement Location Method:	
Source Revision Comment:	
Supplier Comment:	

Overburden and Bedrock Materials Interval

Formation ID:	1007858486
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	01
Mat3 Desc:	FILL
Formation Top Depth:	0.5
Formation End Depth:	2.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1007858487
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	2.0
Formation End Depth:	11.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1007858485
Layer:	1
Color:	8
General Color:	BLACK
Mat1:	27
Most Common Material:	OTHER
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.5
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1007858488
Layer:	4
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	
Mat3 Desc:	
Formation Top Depth:	11.0
Formation End Depth:	17.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1007859792
Layer:	1
Plug From:	0.0
Plug To:	0.5
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1007859793
Layer:	2
Plug From:	0.5
Plug To:	6.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1007859794
Layer:	3
Plug From:	6.0
Plug To:	17.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1007861509
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	

Pipe Information

Pipe ID:	1007857245
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007862151
Layer:	1
Material:	5

Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	7.0
Casing Diameter:	2.0
Casing Diameter UOM:	Inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1007862669
Layer:	1
Slot:	10
Screen Top Depth:	7.0
Screen End Depth:	17.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.25

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1007863410
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1007860946
Diameter:	6.0
Depth From:	0.0
Depth To:	17.0
Hole Depth UOM:	ft
Hole Diameter UOM:	Inch

Links

Bore Hole ID:	1007661411	**Tag No:**	A257274
Depth M:	5.1816	**Contractor:**	7241
Year Completed:	2019	**Latitude:**	43.3335926603222
Well Completed Dt:	08/13/2019	**Longitude:**	-79.8111345326441
Audit No:	Z316537	**Y:**	43.333592657547385
Path:		**X:**	-79.81113438407763

38 ***1 of 1*** ***NE/137.1*** ***93.8 / -1.00*** ***ON*** ***BORE***

Borehole ID:	621934	**Inclin FLG:**	No
OGF ID:	215522388	**SP Status:**	Initial Entry

Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	DEC-1966	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.3341
Total Depth m:	6.6	**Longitude DD:**	-79.811772
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	596325
Drill Method:	Power auger	**Northing:**	4798603
Orig Ground Elev m:	91.4	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	93.7		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218423343	**Mat Consistency:**	Dense
Top Depth:	5.5	**Material Moisture:**	
Bottom Depth:	6.6	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Shale	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SHALE. BROWN,GLACIAL,DENSE,LAYERED, AGE GLACIAL. 024 007 020 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218423340	**Mat Consistency:**	Loose
Top Depth:	.6	**Material Moisture:**	
Bottom Depth:	1.3	**Material Texture:**	Medium
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND-MEDIUM,SILT. BROWN,LOOSE,GRANULAR, AGE GLACIAL.		

Geology Stratum ID:	218423342	**Mat Consistency:**	Hard
Top Depth:	4.3	**Material Moisture:**	
Bottom Depth:	5.5	**Material Texture:**	
Material Color:	Green	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND. GREEN,GLACIAL,HARD,LAYERED, AGE GLACIAL.		

Geology Stratum ID:	218423341	**Mat Consistency:**	Soft
Top Depth:	1.3	**Material Moisture:**	
Bottom Depth:	4.3	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,CLAY. BROWN,GLACIAL,VERY SOFT, UNIFORM,AGE GLACIAL.		

Geology Stratum ID: 218423339
Top Depth: 0
Bottom Depth: .6
Material Color:
Material 1: Soil
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SOIL. AGE POST-GLACIAL.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: M
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: HAM.txt RecordID: 009340 NTS_Sheet: 30M05C
Confiden 1: Reliable information but incomplete.

Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

39 | **1 of 1** | **N/144.8** | **94.4 / -0.43** | **Highway 403 (QEW) Burlington**
Burlington ON | **EHS**

Order No: 20080609001
Status: C
Report Type: Custom Report
Report Date: 6/12/2008
Date Received: 6/9/2008
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.15
X: -79.813425
Y: 43.334428

---

40 | **1 of 8** | **ENE/147.9** | **92.8 / -2.00** | **845275 ONTARIO INC**
1448 GRAHAMS LA
BURLINGTON ON L7S1W3 | **PRT**

Location ID: 2418
Type: retail
Expiry Date: 1994-09-30
Capacity (L): 13000
Licence #: 0055404001

---

40 | **2 of 8** | **ENE/147.9** | **92.8 / -2.00** | **578122 ONTARIO INC**
1448 GRAHAMS LA
BURLINGTON ON | **DTNK**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Delisted Expired Fuel Safety Facilities

Instance No:	9812252	***Expired Date:***	5/25/1995
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:		***Facility Location:***	
Instance Type:	FS Facility	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:			
Original Source:	EXP		
Record Date:	Up to May 2013		

40	***3 of 8***	***ENE/147.9***	***92.8 / -2.00***	***578122 ONTARIO INC 1448 GRAHAMS LA BURLINGTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	10629591	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	29725	***Facility Location:***	
Instance Type:	FS Piping	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	4 of 8	ENE/147.9	92.8 / -2.00	578122 ONTARIO INC 1448 GRAHAMS LA BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 10629506
Status: EXPIRED
Instance ID: 31234
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	5 of 8	ENE/147.9	92.8 / -2.00	578122 ONTARIO INC 1448 GRAHAMS LA BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 10629544
Status: EXPIRED
Instance ID: 31862
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:

ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

40 ***6 of 8*** ***ENE/147.9*** ***92.8 / -2.00*** ***578122 ONTARIO INC***
1448 GRAHAMS LANE
BURLINGTON ON ***EXP***

Inventory No: 10629479
Inventory Status: EXPIRED
Installation Year: 1988
Capacity: 5000
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

40 ***7 of 8*** ***ENE/147.9*** ***92.8 / -2.00*** ***578122 ONTARIO INC***
1448 GRAHAMS LANE
BURLINGTON ON ***EXP***

Inventory No: 10629526
Inventory Status: EXPIRED
Installation Year: 1988
Capacity: 5000
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

40 ***8 of 8*** ***ENE/147.9*** ***92.8 / -2.00*** ***578122 ONTARIO INC***
1448 GRAHAMS LANE
BURLINGTON ON ***EXP***

Inventory No: 10629568
Inventory Status: EXPIRED
Installation Year: 1988
Capacity: 3000
Capacity Unit:
Tank Type:
Manufacturer:

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline

---

41 | **1 of 1** | **ESE/155.9** | **93.3 / -1.55** | **802 HAGER AVE BURLINGTON ON** | **WWIS**

Well ID:	7042731	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Not Used	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	04/17/2007
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z64348	**Contractor:**	7147
Tag:	A048929	**Form Version:**	3
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: MILTON TOWN (NELSON)
Site Info: BRANT'S BLOCK, 0

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/704\7042731.pdf

Additional Detail(s) (Map)

Well Completed Date: 04/03/2007
Year Completed: 2007
Depth (m): 4
Latitude: 43.3314160764955
Longitude: -79.8113743551574
Path: 704\7042731.pdf

Bore Hole Information

Bore Hole ID:	11765225	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596361.00
Code OB Desc:		**North83:**	4798305.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	04/03/2007	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	933097929
Layer:	1
Color:	8
General Color:	BLACK
Mat1:	02
Most Common Material:	TOPSOIL
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.20000000298023224
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	933097930
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Mat2 Desc:	SAND
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.20000000298023224
Formation End Depth:	4.0
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933317287
Layer:	3
Plug From:	0.699999988079071
Plug To:	4.0
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933317288
Layer:	4
Plug From:	
Plug To:	4.0
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933317286
Layer:	2
Plug From:	0.20000000298023224
Plug To:	0.699999988079071
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933317285

Layer: 1
Plug From: 0.0
Plug To: 0.20000000298023224
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 967042731
Method Construction Code: B
Method Construction: Other Method
Other Method Construction:

Pipe Information

Pipe ID: 11772915
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930898156
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 0.8999999761581421
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933423996
Layer: 1
Slot:
Screen Top Depth: 0.8999999761581421
Screen End Depth: 4.0
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.300000190734863

Hole Diameter

Hole ID: 11851505
Diameter: 10.0
Depth From: 0.0
Depth To: 4.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Bore Hole ID: 11765225
Depth M: 4
Year Completed: 2007
Well Completed Dt: 04/03/2007
Audit No: Z64348
Path: 704\7042731.pdf
Tag No: A048929
Contractor: 7147
Latitude: 43.3314160764955
Longitude: -79.8113743551574
Y: 43.3314160738405
X: -79.81137420652506

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	1 of 1	SE/163.4	93.8 / -1.00	770 HAGGAR AV E Burlington ON	WWIS

Well ID: 7284939
Construction Date:
Use 1st: Test Hole
Use 2nd: Monitoring
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z253594
Tag: A217316
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 04/10/2017
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: HALTON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 03/07/2017
Year Completed: 2017
Depth (m): 4.572
Latitude: 43.3309623248088
Longitude: -79.8119012723746
Path:

Bore Hole Information

Bore Hole ID: 1006379479
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 03/07/2017
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 596319.00
North83: 4798254.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1006649153
Layer: 3
Color: 7
General Color: RED

Mat1: 17
Most Common Material: SHALE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 13.0
Formation End Depth: 15.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006649151
Layer: 1
Color: 8
General Color: BLACK
Mat1:
Most Common Material:
Mat2: 60
Mat2 Desc: CEMENTED
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006649152
Layer: 2
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 28
Mat2 Desc: SAND
Mat3:
Mat3 Desc:
Formation Top Depth: 0.5
Formation End Depth: 13.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006649163
Layer: 3
Plug From: 0.5
Plug To: 0.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006649161
Layer: 1
Plug From: 15.0
Plug To: 4.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006649162
Layer:	2
Plug From:	4.0
Plug To:	0.5
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1006649160
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	DIRECT PUSH

Pipe Information

Pipe ID:	1006649150
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006649156
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	5.0
Depth To:	0.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1006649157
Layer:	1
Slot:	10
Screen Top Depth:	15.0
Screen End Depth:	5.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.25

Water Details

Water ID:	1006649155
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1006649154
Diameter:	6.0

Depth From:	15.0
Depth To:	0.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1006379479	**Tag No:**	A217316
Depth M:	4.572	**Contractor:**	7241
Year Completed:	2017	**Latitude:**	43.3309623248088
Well Completed Dt:	03/07/2017	**Longitude:**	-79.8119012723746
Audit No:	Z253594	**Y:**	43.33096232230119
Path:	728\7284939.pdf	**X:**	-79.81190112310901

43 | ***1 of 1*** | ***SE/163.6*** | ***93.8 / -1.10*** | ***770 HAGGER AVE Burlington ON*** | ***WWIS***

Well ID:	7284940	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Test Hole	**Data Entry Status:**	
Use 2nd:	Monitoring	**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	04/10/2017
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z253701	**Contractor:**	7241
Tag:	A217268	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	BB
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	03/07/2017
Year Completed:	2017
Depth (m):	4.572
Latitude:	43.3308735796637
Longitude:	-79.8120263516455
Path:	

Bore Hole Information

Bore Hole ID:	1006379482	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596309.00
Code OB Desc:		**North83:**	4798244.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	03/07/2017	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			

Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1006649199
Layer: 2
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 28
Mat2 Desc: SAND
Mat3:
Mat3 Desc:
Formation Top Depth: 0.5
Formation End Depth: 13.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006649200
Layer: 3
Color: 7
General Color: RED
Mat1: 17
Most Common Material: SHALE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 13.0
Formation End Depth: 15.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006649198
Layer: 1
Color: 8
General Color: BLACK
Mat1:
Most Common Material:
Mat2: 60
Mat2 Desc: CEMENTED
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.5
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006649208
Layer: 1

Plug From: 15.0
Plug To: 4.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006649210
Layer: 3
Plug From: 0.5
Plug To: 0.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006649209
Layer: 2
Plug From: 4.0
Plug To: 0.5
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1006649207
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction: DIRECT PUSH

Pipe Information

Pipe ID: 1006649197
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006649203
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 5.0
Depth To: 0.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1006649204
Layer: 1
Slot: 10
Screen Top Depth: 15.0
Screen End Depth: 5.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.25

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Water Details

Water ID:	1006649202
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1006649201
Diameter:	6.0
Depth From:	15.0
Depth To:	0.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1006379482	***Tag No:***	A217268
Depth M:	4.572	***Contractor:***	7241
Year Completed:	2017	***Latitude:***	43.3308735796637
Well Completed Dt:	03/07/2017	***Longitude:***	-79.8120263516455
Audit No:	Z253701	***Y:***	43.33087357777009
Path:	728\7284940.pdf	***X:***	-79.81202620359893

---

44 ***1 of 1*** ***NE/163.8*** ***94.4 / -0.42*** ***850 BRANT ST Burlington ON*** ***WWIS***

Well ID:	7330855	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	04/01/2019
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z287722	***Contractor:***	7609
Tag:	A242662	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	HALTON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	02/14/2019
Year Completed:	2019
Depth (m):	4.75
Latitude:	43.334475142479
Longitude:	-79.8120054817548
Path:	

Bore Hole Information

Bore Hole ID:	1007413064	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	596305.00
Code OB Desc:		***North83:***	4798644.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	02/14/2019	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1007835429
Layer:	1
Color:	
General Color:	
Mat1:	01
Most Common Material:	FILL
Mat2:	28
Mat2 Desc:	SAND
Mat3:	01
Mat3 Desc:	FILL
Formation Top Depth:	0.0
Formation End Depth:	1.2200000286102295
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1007835431
Layer:	3
Color:	2
General Color:	GREY
Mat1:	34
Most Common Material:	TILL
Mat2:	06
Mat2 Desc:	SILT
Mat3:	84
Mat3 Desc:	SILTY
Formation Top Depth:	3.049999952316284
Formation End Depth:	4.75
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1007835430
Layer:	2
Color:	7
General Color:	RED
Mat1:	34
Most Common Material:	TILL

Mat2: 06
Mat2 Desc: SILT
Mat3: 84
Mat3 Desc: SILTY
Formation Top Depth: 1.2200000286102295
Formation End Depth: 3.049999952316284
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007836409
Layer: 1
Plug From: 0.0
Plug To: 1.2200000286102295
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1007837888
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1007834302
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007838052
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.5199999809265137
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1007838598
Layer: 1
Slot: 10
Screen Top Depth: 1.5199999809265137
Screen End Depth: 4.75
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.0

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1007839320
Pump Set At:

Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1007837203
Diameter: 10.199999809265137
Depth From: 0.0
Depth To: 4.75
Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Bore Hole ID: 1007413064
Depth M: 4.75
Year Completed: 2019
Well Completed Dt: 02/14/2019
Audit No: Z287722
Path: 733\7330855.pdf
Tag No: A242662
Contractor: 7609
Latitude: 43.334475142479
Longitude: -79.8120054817548
Y: 43.334475139914495
X: -79.81200533362978

---

45 | ***1 of 1*** | ***NNE/164.8*** | ***94.8 / 0.00*** | ***850 Brant Street Burlington ON*** | ***WWIS***

Well ID: 7330854
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z287721
Tag: A242658
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 04/01/2019
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7609
Form Version: 7
Owner:
County: HALTON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 02/14/2019

Year Completed: 2019
Depth (m): 3.96
Latitude: 43.3345786546579
Longitude: -79.8124352119992
Path:

Bore Hole Information

Bore Hole ID: 1007413061
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 02/14/2019
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 596270.00
North83: 4798655.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1007835426
Layer: 1
Color:
General Color:
Mat1: 01
Most Common Material: FILL
Mat2: 28
Mat2 Desc: SAND
Mat3: 81
Mat3 Desc: SANDY
Formation Top Depth: 0.0
Formation End Depth: 1.2200000286102295
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007835427
Layer: 2
Color: 7
General Color: RED
Mat1: 34
Most Common Material: TILL
Mat2: 06
Mat2 Desc: SILT
Mat3: 84
Mat3 Desc: SILTY
Formation Top Depth: 1.2200000286102295
Formation End Depth: 3.049999952316284
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID:	1007835428
Layer:	3
Color:	2
General Color:	GREY
Mat1:	34
Most Common Material:	TILL
Mat2:	06
Mat2 Desc:	SILT
Mat3:	84
Mat3 Desc:	SILTY
Formation Top Depth:	3.049999952316284
Formation End Depth:	3.9600000381469727
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007836408
Layer:	1
Plug From:	0.0
Plug To:	0.6100000143051147
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1007837887
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1007834301
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007838053
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	0.9100000262260437
Casing Diameter:	5.0
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1007838600
Layer:	1
Slot:	10
Screen Top Depth:	0.9100000262260437
Screen End Depth:	3.9600000381469727
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.0

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1007839347
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1007837202
Diameter:	10.199999809265137
Depth From:	0.0
Depth To:	3.9600000381469727
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	1007413061	***Tag No:***	A242658
Depth M:	3.96	***Contractor:***	7609
Year Completed:	2019	***Latitude:***	43.3345786546579
Well Completed Dt:	02/14/2019	***Longitude:***	-79.8124352119992
Audit No:	Z287721	***Y:***	43.33457865252249
Path:	733\7330854.pdf	***X:***	-79.81243506326183

---

46 | ***1 of 1*** | ***NNE/164.8*** | ***94.8 / 0.00*** | ***850 Brant St Burlington ON*** | ***WWIS***

Well ID:	7330859	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	04/01/2019
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z287726	***Contractor:***	7609
Tag:	A242657	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	HALTON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 02/14/2019
Year Completed: 2019
Depth (m): 6.1
Latitude: 43.3345403386563
Longitude: -79.812213916884
Path:

Bore Hole Information

Bore Hole ID: 1007413222
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 02/14/2019
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 596288.00
North83: 4798651.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1007835444
Layer: 4
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2:
Mat2 Desc:
Mat3: 66
Mat3 Desc: DENSE
Formation Top Depth: 4.75
Formation End Depth: 6.099999904632568
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007835441
Layer: 1
Color:
General Color:
Mat1: 01
Most Common Material: FILL
Mat2: 28
Mat2 Desc: SAND
Mat3: 81
Mat3 Desc: SANDY
Formation Top Depth: 0.0
Formation End Depth: 1.2200000286102295

Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007835442
Layer: 2
Color: 7
General Color: RED
Mat1: 34
Most Common Material: TILL
Mat2: 06
Mat2 Desc: SILT
Mat3: 84
Mat3 Desc: SILTY
Formation Top Depth: 1.2200000286102295
Formation End Depth: 3.049999952316284
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007835443
Layer: 3
Color: 2
General Color: GREY
Mat1: 34
Most Common Material: TILL
Mat2: 06
Mat2 Desc: SILT
Mat3: 84
Mat3 Desc: SILTY
Formation Top Depth: 3.049999952316284
Formation End Depth: 4.75
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007836413
Layer: 1
Plug From:
Plug To:
Plug Depth UOM:

Annular Space/Abandonment Sealing Record

Plug ID: 1007836414
Layer: 1
Plug From: 0.0
Plug To:
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1007837897
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID:	1007834306
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007838061
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	3.049999952316284
Casing Diameter:	5.0
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1007838607
Layer:	1
Slot:	10
Screen Top Depth:	3.049999952316284
Screen End Depth:	6.099999904632568
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.0

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1007839328
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1007837207
Diameter:	10.199999809265137
Depth From:	0.0
Depth To:	6.099999904632568
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	1007413222	**Tag No:**	A242657
Depth M:	6.1	**Contractor:**	7609
Year Completed:	2019	**Latitude:**	43.3345403386563
Well Completed Dt:	02/14/2019	**Longitude:**	-79.812213916884
Audit No:	Z287726	**Y:**	43.33454033663172
Path:	733\7330859.pdf	**X:**	-79.81221376785672

47 **1 of 1** **WSW/167.5** **94.0 / -0.80** **ON** **BORE**

Borehole ID:	623978	**Inclin FLG:**	No
OGF ID:	215524430	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	MAY-1968	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.331619
Total Depth m:	5.6	**Longitude DD:**	-79.815644
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	596015
Drill Method:	Power auger	**Northing:**	4798323
Orig Ground Elev m:	94.3	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	94.2		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218431704	**Mat Consistency:**	Hard
Top Depth:	2.1	**Material Moisture:**	
Bottom Depth:	5.6	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:	Gravel	**Depositional Gen:**	glacial
Gsc Material Description:			

Stratum Description: TILL,SILT,CLAY, GRAVEL. BROWN,GLACIAL,VERY HARD, AGE GLACIAL. 00000008000100200005502300070086 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID:	218431701	**Mat Consistency:**	Loose
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Soil	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			

Stratum Description: SOIL. LOOSE,AGE POST-GLACIAL.

Geology Stratum ID:	218431702	**Mat Consistency:**	Compact
Top Depth:	.3	**Material Moisture:**	
Bottom Depth:	1.7	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	

Material 3: **Geologic Period:**
Material 4: **Depositional Gen:** lacustrine
Gsc Material Description:
Stratum Description: SAND(81),SILT(13). BROWN,LACUSTRINE,COMPACT, AGE GLACIAL.

Geology Stratum ID: 218431703 **Mat Consistency:** Compact
Top Depth: 1.7 **Material Moisture:**
Bottom Depth: 2.1 **Material Texture:**
Material Color: Brown **Non Geo Mat Type:**
Material 1: Sand **Geologic Formation:**
Material 2: **Geologic Group:**
Material 3: **Geologic Period:**
Material 4: **Depositional Gen:** lacustrine
Gsc Material Description:
Stratum Description: SAND. BROWN,LACUSTRINE,COMPACT, AGE GLACIAL.

Source

Source Type: Data Survey **Source Appl:** Spatial/Tabular
Source Orig: Geological Survey of Canada **Source Iden:** 1
Source Date: 1956-1972 **Scale or Res:** Varies
Confidence: M **Horizontal:** NAD27
Observatio: **Verticalda:** Mean Average Sea Level
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: HAM.txt RecordID: 029780 NTS_Sheet: 30M05C
Confiden 1: Reliable information but incomplete.

Source List

Source Identifier: 1 **Horizontal Datum:** NAD27
Source Type: Data Survey **Vertical Datum:** Mean Average Sea Level
Source Date: 1956-1972 **Projection Name:** Universal Transverse Mercator
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

48 ***1 of 2*** ***NNE/172.5*** ***94.8 / 0.00*** ***850 Brant Street Burlington ON L7R 2J5*** ***EHS***

Order No: 20180928134 **Nearest Intersection:**
Status: C **Municipality:**
Report Type: Site Report **Client Prov/State:** ON
Report Date: 01-OCT-18 **Search Radius (km):** .001
Date Received: 28-SEP-18 **X:** -79.812252
Previous Site Name: **Y:** 43.334727
Lot/Building Size:
Additional Info Ordered:

---

48 ***2 of 2*** ***NNE/172.5*** ***94.8 / 0.00*** ***Discovery Ford 850 Brant Street Burlington ON L7R 2J5*** ***GEN***

Generator No: ON3487038
SIC Code:
SIC Description:
Approval Years: As of Oct 2019
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

---

49 **1 of 2** **NE/175.8** **93.8 / -1.00** **PES**

PETS & GARDENS LTD
834 BRANT ST
BURLINGTON ON L7R 2J5

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

49 **2 of 2** **NE/175.8** **93.8 / -1.00** **PES**

PETS & GARDENS LTD
834 BRANT ST
BURLINGTON ON L7R2J5

Detail Licence No:
Licence No: 06709
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Retail Vendor Class 03
Licence Type Code: 21
Licence Class: 03
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 416
Oper Phone No: 6344155
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

50 **1 of 1** **ENE/183.9** **92.5 / -2.34** **ON** **WWIS**

Well ID: 7387995
Construction Date:
Use 1st:
Use 2nd:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:

Final Well Status:		**Date Received:**	03/31/2021
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z361255	**Contractor:**	7241
Tag:	A333003	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	BB
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008670292	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596458.00
Code OB Desc:		**North83:**	4798519.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	04/23/2021	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008670292	**Tag No:**	A333003
Depth M:		**Contractor:**	7241
Year Completed:	2021	**Latitude:**	43.3333301976551
Well Completed Dt:	04/23/2021	**Longitude:**	-79.8101404847104
Audit No:	Z361255	**Y:**	43.333330195410326
Path:		**X:**	-79.81014033657023

---

51 | ***1 of 1*** | ***ENE/184.3*** | ***92.8 / -2.00*** | ***HARMAC TRANSPORTATION***
808 BRANT ST. TANK TRUCK (CARGO)
BURLINGTON CITY ON | ***SPL***

Ref No:	79999	**Municipality No:**	14101
Year:		**Nature of Damage:**	
Incident Dt:	12/17/1992	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	12/17/1992	**Health/Env Conseq:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
Facility Name:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site Address:	
Site Region:	
Site Municipality:	BURLINGTON CITY
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE
Incident Event:	
Environment Impact:	NOT ANTICIPATED
Nature of Impact:	Other
Contaminant Qty:	
System Facility Address:	
Client Name:	
Client Type:	
Call Report Locatn Geodata:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	LAND
Receiving Environment:	
Incident Reason:	ERROR
Incident Summary:	HARMAC TRANSPORT - 30 L GASOLINE LEAK TO PAVEMENTDURING DELIVERY
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Source Type:	

52	1 of 1	E/191.0	91.8 / -3.00	**780 Brant Street** **Burlington ON L7R 2J2**	EHS

Order No:	20180730201	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	07-AUG-18	**Search Radius (km):**	.25
Date Received:	30-JUL-18	**X:**	-79.809916
Previous Site Name:		**Y:**	43.332923
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Title Searches; City Directory; Aerial Photos		

53	1 of 4	ENE/193.3	92.8 / -2.00	**796 Brant Street** **Burlington ON L7R 2J2**	EHS

Order No:	21032500063	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	30-MAR-21	**Search Radius (km):**	.25
Date Received:	25-MAR-21	**X:**	-79.8101944
Previous Site Name:		**Y:**	43.3336083
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos		

53	2 of 4	ENE/193.3	92.8 / -2.00	**796 Brant Street** **Burlington ON L7R 2J2**	EHS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Order No:	21032500063	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	30-MAR-21	**Search Radius (km):**	.25
Date Received:	25-MAR-21	**X:**	-79.8101944
Previous Site Name:		**Y:**	43.3336083
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos		

---

53 *3 of 4* *ENE/193.3* *92.8 / -2.00* ***796 Brant Street Burlington ON L7R 2J2*** ***EHS***

Order No:	21032500063	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	30-MAR-21	**Search Radius (km):**	.25
Date Received:	25-MAR-21	**X:**	-79.8101944
Previous Site Name:		**Y:**	43.3336083
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos		

---

53 *4 of 4* *ENE/193.3* *92.8 / -2.00* ***796 Brant Street Burlington ON L7R 2J2*** ***EHS***

Order No:	21032500063	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	30-MAR-21	**Search Radius (km):**	.25
Date Received:	25-MAR-21	**X:**	-79.8101944
Previous Site Name:		**Y:**	43.3336083
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos		

---

54 *1 of 1* *E/194.8* *91.8 / -3.00* ***ON*** ***WWIS***

Well ID:	7369395	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	10/05/2020
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z341752	**Contractor:**	7644
Tag:	A297611	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

Bore Hole Information

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Bore Hole ID:	1008484031	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596481.00
Code OB Desc:		**North83:**	4798471.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	09/04/2020	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008484031	**Tag No:**	A297611
Depth M:		**Contractor:**	7644
Year Completed:	2020	**Latitude:**	43.3328951203564
Well Completed Dt:	09/04/2020	**Longitude:**	-79.8098652673884
Audit No:	Z341752	**Y:**	43.33289511771997
Path:	736\7369395.pdf	**X:**	-79.80986511804535

---

55 | ***1 of 1*** | ***SSW/197.4*** | ***93.8 / -1.00*** | ***1380 GRAHAMS LANE BURLINGTON ON*** | ***WWIS***

Well ID:	7047125	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	07/26/2007
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z70585	**Contractor:**	6607
Tag:	A053612	**Form Version:**	3
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	06/04/2007
Year Completed:	2007
Depth (m):	3.6
Latitude:	43.3302938243615
Longitude:	-79.8142949209827
Path:	

Bore Hole Information

Bore Hole ID:	23047125	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596126.00
Code OB Desc:		**North83:**	4798177.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	06/04/2007	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	30347125
Layer:	3
Color:	7
General Color:	RED
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	91
Mat3 Desc:	WATER-BEARING
Formation Top Depth:	3.0
Formation End Depth:	3.5999999046325684
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	30147125
Layer:	1
Color:	2
General Color:	GREY
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	1.5
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	30247125
Layer:	2
Color:	7
General Color:	RED
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT

Mat3:
Mat3 Desc:
Formation Top Depth: 1.5
Formation End Depth: 3.0
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 44002080
Layer: 1
Plug From: 0.0
Plug To: 0.15000000596046448
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 44002081
Layer: 2
Plug From: 0.15000000596046448
Plug To: 1.2000000476837158
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 25947125
Method Construction Code: 9
Method Construction: Driving
Other Method Construction:

Pipe Information

Pipe ID: 29047125
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 42147125
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.5
Casing Diameter: 3.200000047683716
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 43147125
Layer: 1
Slot: 20
Screen Top Depth: 1.5
Screen End Depth: 3.5999999046325684
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm

Screen Diameter: 4.199999809265137

Water Details

Water ID: 41147125
Layer: 1
Kind Code:
Kind:
Water Found Depth: 3.0
Water Found Depth UOM: m

Hole Diameter

Hole ID: 46001291
Diameter: 6.400000095367432
Depth From: 0.0
Depth To: 3.5999999046325684
Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Bore Hole ID: 23047125
Depth M: 3.6
Year Completed: 2007
Well Completed Dt: 06/04/2007
Audit No: Z70585
Path:
Tag No: A053612
Contractor: 6607
Latitude: 43.3302938243615
Longitude: -79.8142949209827
Y: 43.330293821521344
X: -79.81429477241608

---

56 ***1 of 3*** ***SSW/198.0*** ***93.8 / -1.00*** ***QEW and 403 Burlington ON*** ***EHS***

Order No: 23041700076
Status: C
Report Type: Custom Report
Report Date: 20-APR-23
Date Received: 17-APR-23
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: City Directory; Aerial Photos
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.81430592
Y: 43.33029136

---

56 ***2 of 3*** ***SSW/198.0*** ***93.8 / -1.00*** ***QEW and 403 Burlington ON*** ***EHS***

Order No: 23041700076
Status: C
Report Type: Custom Report
Report Date: 20-APR-23
Date Received: 17-APR-23
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: City Directory; Aerial Photos
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.81430592
Y: 43.33029136

---

56 ***3 of 3*** ***SSW/198.0*** ***93.8 / -1.00*** ***QEW and 403 Burlington ON*** ***EHS***

Order No: 23041700076
Status: C
Report Type: Custom Report
Nearest Intersection:
Municipality:
Client Prov/State: ON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Report Date:	20-APR-23	**Search Radius (km):**	.25
Date Received:	17-APR-23	**X:**	-79.81430592
Previous Site Name:		**Y:**	43.33029136
Lot/Building Size:			
Additional Info Ordered:	City Directory; Aerial Photos		

57 **1 of 1** **NNE/201.2** **94.8 / 0.00** **850 Brant Street Burlington ON** **WWIS**

Well ID:	7330858	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	04/01/2019
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z287725	**Contractor:**	7609
Tag:	A242669	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	02/15/2019
Year Completed:	2019
Depth (m):	4.75
Latitude:	43.3349221630954
Longitude:	-79.8125642103948
Path:	

Bore Hole Information

Bore Hole ID:	1007413156	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596259.00
Code OB Desc:		**North83:**	4798693.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	02/15/2019	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock

Materials Interval

Formation ID:	1007835439
Layer:	2
Color:	7
General Color:	RED
Mat1:	34
Most Common Material:	TILL
Mat2:	06
Mat2 Desc:	SILT
Mat3:	
Mat3 Desc:	
Formation Top Depth:	1.2200000286102295
Formation End Depth:	3.049999952316284
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1007835440
Layer:	3
Color:	2
General Color:	GREY
Mat1:	34
Most Common Material:	TILL
Mat2:	06
Mat2 Desc:	SILT
Mat3:	
Mat3 Desc:	
Formation Top Depth:	3.049999952316284
Formation End Depth:	4.75
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1007835438
Layer:	1
Color:	
General Color:	
Mat1:	01
Most Common Material:	FILL
Mat2:	28
Mat2 Desc:	SAND
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	1.2200000286102295
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007836412
Layer:	1
Plug From:	0.0
Plug To:	1.2200000286102295
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID: 1007837891
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1007834305
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007838055
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.5199999809265137
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1007838602
Layer: 1
Slot: 10
Screen Top Depth: 1.5199999809265137
Screen End Depth: 4.75
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.0

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1007839323
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1007837206
Diameter: 10.199999809265137
Depth From: 0.0
Depth To: 4.75

Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Bore Hole ID: 1007413156
Depth M: 4.75
Year Completed: 2019
Well Completed Dt: 02/15/2019
Audit No: Z287725
Path: 733\7330858.pdf
Tag No: A242669
Contractor: 7609
Latitude: 43.3349221630954
Longitude: -79.8125642103948
Y: 43.33492216078826
X: -79.81256406126568

---

58 | **1 of 1** | **ENE/208.8** | **92.8 / -2.00** | **ON** | **WWIS**

Well ID: 7387994
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z361256
Tag: A333002
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:
Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 03/31/2021
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: HALTON
Lot:
Concession:
Concession Name: BB
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1008670289
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 04/23/2021
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation:
Elevrc:
Zone: 17
East83: 596452.00
North83: 4798579.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Links

Bore Hole ID: 1008670289
Depth M:
Year Completed: 2021
Well Completed Dt: 04/23/2021
Audit No: Z361256
Tag No: A333002
Contractor: 7241
Latitude: 43.3338711246417
Longitude: -79.8102039356503
Y: 43.3338711223079

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Path: **X:** -79.81020378720626

---

59 *1 of 4* **WNW/220.3** **97.8 / 2.92**

942 Brant Street
Burlington ON L7R 2J7

EHS

Order No: 21052700187
Status: C
Report Type: RSC Report - Quote
Report Date: 01-JUN-21
Date Received: 27-MAY-21
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Topographic Maps; City Directory; Aerial Photos

Nearest Intersection:
Municipality:
Client Prov/State: OH
Search Radius (km): .3
X: -79.81683293
Y: 43.3334874

---

59 *2 of 4* **WNW/220.3** **97.8 / 2.92**

942 Brant Street
Burlington ON L7R 2J7

EHS

Order No: 21052700187
Status: C
Report Type: RSC Report - Quote
Report Date: 01-JUN-21
Date Received: 27-MAY-21
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Topographic Maps; City Directory; Aerial Photos

Nearest Intersection:
Municipality:
Client Prov/State: OH
Search Radius (km): .3
X: -79.81683293
Y: 43.3334874

---

59 *3 of 4* **WNW/220.3** **97.8 / 2.92**

942 Brant Street
Burlington ON L7R 2J7

EHS

Order No: 21052700187
Status: C
Report Type: RSC Report - Quote
Report Date: 01-JUN-21
Date Received: 27-MAY-21
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Topographic Maps; City Directory; Aerial Photos

Nearest Intersection:
Municipality:
Client Prov/State: OH
Search Radius (km): .3
X: -79.81683293
Y: 43.3334874

---

59 *4 of 4* **WNW/220.3** **97.8 / 2.92**

942 Brant Street
Burlington ON L7R 2J7

EHS

Order No: 21052700187
Status: C
Report Type: RSC Report - Quote
Report Date: 01-JUN-21
Date Received: 27-MAY-21
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Topographic Maps; City Directory; Aerial Photos

Nearest Intersection:
Municipality:
Client Prov/State: OH
Search Radius (km): .3
X: -79.81683293
Y: 43.3334874

---

60 *1 of 1* **ENE/220.9** **91.8 / -3.00**

ON

WWIS

Well ID: 7387993
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 03/31/2021

Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z361257	**Contractor:**	7241
Tag:	A333001	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	BB
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008670286	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596482.00
Code OB Desc:		**North83:**	4798555.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	04/23/2021	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008670286	**Tag No:**	A333001
Depth M:		**Contractor:**	7241
Year Completed:	2021	**Latitude:**	43.3336512119123
Well Completed Dt:	04/23/2021	**Longitude:**	-79.8098381651174
Audit No:	Z361257	**Y:**	43.33365120933729
Path:		**X:**	-79.80983801581569

---

61 ***1 of 3*** ***WNW/222.3*** ***99.5 / 4.67*** ***BURLINGTON PLANT SITE***
942 BRANT STREET
BURLINGTON ON L7R2J7 ***NPR2***

NPRI ID:	3643	**Latitude:**	43.334043
Facility ID:	224310	**Longitude:**	-79.816436

Note: Substances included on NPRI reports for this NPRI ID are summarized below in the NPRI ID Substances Summary section. Substances listed in the Substances Summary are included on the basis of NPRI ID only. For entities (NPRI ID) with mobile plants and/or more than one facility location, substances listed above may or may not have been reported for specific facilities/mobile locations. The list of substances additionally includes those which have been included on the NPRI report with an unknown quantity or a quantity of 0.

For specific details about substance quantities, years, release/transfer/disposal methods, the reader is referred the facility report:

https://pollution-waste.canada.ca/national-release-inventory/?fromYear=1993&toYear=2022&name=3643

NPRI ID Substances Summary

CAS No:	NA - 01	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Antimony (and its compounds)		
Name French:	Antimoine (et ses composés)		
Sort English:	Antimony (and its compounds)		
Sort French:	Antimoine (et ses composés)		

CAS No:	111-42-2	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Diethanolamine (and its salts)		
Name French:	Diéthanolamine (et ses sels)		
Sort English:	Diethanolamine (and its salts)		
Sort French:	Diéthanolamine (et ses sels)		

CAS No:	11104-93-1	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Nitrogen oxides (expressed as nitrogen dioxide)		
Name French:	Oxydes d'azote (exprimés en dioxyde d'azote)		
Sort English:	Nitrogen oxides (expressed as nitrogen dioxide)		
Sort French:	Oxydes d'azote (exprimés en dioxyde d'azote)		

CAS No:	NA - M08	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Total particulate matter		
Name French:	Matière particulaire totale		
Sort English:	PM - Total Particulate Matter		
Sort French:	PM - Particules totales		

CAS No:	107-21-1	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Ethylene glycol		
Name French:	Éthylène glycol		
Sort English:	Ethylene glycol		
Sort French:	Éthylèneglycol		

CAS No:	NA - 16	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Ammonia (total)		
Name French:	Ammoniac (total)		
Sort English:	Ammonia (total)		
Sort French:	Ammoniac (total)		

CAS No:	7664-93-9	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Sulphuric acid		
Name French:	Acide sulfurique		
Sort English:	Sulphuric acid		
Sort French:	Acide sulfurique		

CAS No:	71-36-3	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	n-Butyl alcohol		
Name French:	Butan-1-ol		
Sort English:	Butyl alcohol:n-		
Sort French:	Butan-1-ol		

CAS No:	630-08-0	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE

Is DF?:	FALSE		
Name English:	Carbon monoxide		
Name French:	Monoxyde de carbone		
Sort English:	Carbon monoxide		
Sort French:	Oxyde de carbone (monoxyde de carbone)		

CAS No:	95-63-6	**Is PAH?:**	FALSE
Is VOC?:	TRUE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	1,2,4-Trimethylbenzene		
Name French:	1,2,4-Triméthylbenzène		
Sort English:	Trimethylbenzene:1,2,4-		
Sort French:	Triméthylbenzène:1,2,4-		

CAS No:	NA - 20	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Nonylphenol and its ethoxylates		
Name French:	Nonylphénol et ses dérivés éthoxylés		
Sort English:	Nonylphenol and its ethoxylates		
Sort French:	Nonylphénol et ses dérivés éthoxylés		

CAS No:	NA - M10	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	PM2.5 - Particulate Matter <= 2.5 Micrometers		
Name French:	PM2,5 - Matière particulaire <= 2,5 micromètres		
Sort English:	PM2.5 - Particulate Matter <= 2.5 Micrometers		
Sort French:	PM2,5 - Matière particulaire <= 2,5 micromètres		

CAS No:	7632-00-0	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Sodium nitrite		
Name French:	Nitrite de sodium		
Sort English:	Sodium nitrite		
Sort French:	Nitrite de sodium		

CAS No:	NA - 14	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Zinc (and its compounds)		
Name French:	Zinc (et ses composés)		
Sort English:	Zinc (and its compounds)		
Sort French:	Zinc (et ses composés)		

CAS No:	7647-01-0	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Hydrochloric acid		
Name French:	Acide chlorhydrique		
Sort English:	Hydrochloric acid		
Sort French:	Acide chlorhydrique		

CAS No:	64742-94-5	**Is PAH?:**	FALSE
Is VOC?:	TRUE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Heavy aromatic solvent naphtha		
Name French:	Solvent naphtha aromatique lourd		
Sort English:	Heavy aromatic solvent naphtha		
Sort French:	Solvent naphtha aromatique lourd		

CAS No:	NA - M09	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	PM10 - Particulate Matter <= 10 Micrometers		

Name French: PM10 - Matière particulaire <= 10 micromètres
Sort English: PM10 - Particulate Matter <= 10 Micrometers
Sort French: PM10 - Matière particulaire <= 10 micromètres

CAS No: 91-20-3 **Is PAH?:** FALSE
Is VOC?: FALSE **NPRI:** TRUE
Is DF?: FALSE
Name English: Naphthalene
Name French: Naphtalène
Sort English: Naphthalene
Sort French: Naphtalène

CAS No: 8042-47-5 **Is PAH?:** FALSE
Is VOC?: TRUE **NPRI:** TRUE
Is DF?: FALSE
Name English: White mineral oil
Name French: Huile minérale blanche
Sort English: White mineral oil
Sort French: Huile minérale blanche

CAS No: 7446-09-5 **Is PAH?:** FALSE
Is VOC?: FALSE **NPRI:** TRUE
Is DF?: FALSE
Name English: Sulphur dioxide
Name French: Dioxyde de soufre
Sort English: Sulphur dioxide
Sort French: Dioxyde de soufre

Geographic Location

DLS Description: **Datum:** 1983.0
NTS Description: A-006-F/030-M-5 **Forward Sort Area:** L7S
Latitude: 43.334043 **SOMA:** TRUE
Longitude: -79.816436 **ON PEMA:** TRUE
Census Subdiv ID: 3524002 **QC PEMA:** FALSE
Ecozone ID: 8 **Quebec Windsor Corr:** TRUE
Water Survey ID: 2 **Province Code:** ON

NPRI ID Facility ID

NPRI ID: 3643
Facility ID: 224310

Facility

Facility ID: 224310 **IDM ID:** 0
Portable: FALSE **AB Approval ID:** 0
NAICS Primary: 325999 **GHGRP ID:** 0
NAICS Secondary: 0 **ON GHGRP ID:** 0
NAICS Tertiary: 0
Facility Name: Burlington Plant Site
Website:

Address

Address1: 942 Brant Street
Address2:
City: BURLINGTON
Postal Zip: L7R2J7
Prov:

Primary NAICS Details

NAICS Code:	325999	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All Other Miscellaneous Chemical Product Manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	***Start Date:***	1993
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All Other Miscellaneous Chemical Product Manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	***Start Date:***	1993
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All Other Miscellaneous Chemical Product Manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	***Start Date:***	1993
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All other miscellaneous chemical product manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing chemical products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de produits chimiques.

NAICS Code:	325999	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All other miscellaneous chemical product manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing chemical products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de produits chimiques.

NPRI Report

Report ID:	4845	***Repor Type ID:***	1
Report Year:	1994	***New Reporter:***	FALSE
NPRI ID:	3643	***No of Employees:***	56
Company ID:	102059	***Is Compressor:***	FALSE
Facility ID:	224310	***Is NPRI Part 4:***	FALSE
SWR Report ID:	19940000003643	***Is Battery:***	FALSE

Company

Company Name:	Hercules Canada Inc.
Trade Name En:	
Trade Name Fr:	
DUNS No:	0
Website:	

NPRI Report

Report ID:	6428	***Repor Type ID:***	1
Report Year:	1993	***New Reporter:***	FALSE
NPRI ID:	3643	***No of Employees:***	0
Company ID:	102059	***Is Compressor:***	FALSE
Facility ID:	224310	***Is NPRI Part 4:***	FALSE
SWR Report ID:	19930000003643	***Is Battery:***	FALSE

Company

Company Name:	Hercules Canada Inc.
Trade Name En:	
Trade Name Fr:	
DUNS No:	0
Website:	

NPRI Report

Report ID:	1938	***Repor Type ID:***	1
Report Year:	1995	***New Reporter:***	FALSE
NPRI ID:	3643	***No of Employees:***	56
Company ID:	102059	***Is Compressor:***	FALSE
Facility ID:	224310	***Is NPRI Part 4:***	FALSE
SWR Report ID:	19950000003643	***Is Battery:***	FALSE

Company

Company Name:	Hercules Canada Inc.
Trade Name En:	
Trade Name Fr:	
DUNS No:	0
Website:	

NPRI Report

Report ID:	1101	***Repor Type ID:***	1
Report Year:	1996	***New Reporter:***	FALSE
NPRI ID:	3643	***No of Employees:***	56
Company ID:	102059	***Is Compressor:***	FALSE
Facility ID:	224310	***Is NPRI Part 4:***	FALSE
SWR Report ID:	19960000003643	***Is Battery:***	FALSE

Company

Company Name:	Hercules Canada Inc.
Trade Name En:	
Trade Name Fr:	
DUNS No:	0
Website:	

NPRI ID Facility ID

NPRI ID:	3643
Facility ID:	279570

NPRI Report

Report ID:	88600	***Repor Type ID:***	1
Report Year:	2017	***New Reporter:***	FALSE
NPRI ID:	3643	***No of Employees:***	28
Company ID:	111131	***Is Compressor:***	FALSE
Facility ID:	279570	***Is NPRI Part 4:***	FALSE
SWR Report ID:	103947	***Is Battery:***	FALSE

Company

Company Name:	Solenis Canada ULC
Trade Name En:	
Trade Name Fr:	
DUNS No:	0
Website:	solenis.com

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9056327861
First Name:	Arturo	***Extension:***	2116
Last Name:	Pena	***Fax:***	
Email:	apenamedina@solenis.com		
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	EHS Engineer		
Language:	E		
Company Name:			

NPRI Report

Report ID:	88604	***Repor Type ID:***	1
Report Year:	2018	***New Reporter:***	FALSE
NPRI ID:	3643	***No of Employees:***	29
Company ID:	111131	***Is Compressor:***	FALSE
Facility ID:	279570	***Is NPRI Part 4:***	FALSE
SWR Report ID:	148871	***Is Battery:***	FALSE

Company

Company Name: Solenis Canada ULC
Trade Name En:
Trade Name Fr:
DUNS No: 0
Website: solenis.com

NPRI Report Contact

Contact Type: NPRI
First Name: Arturo
Last Name: Pena
Email: mpongetti@solenis.com
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: EHS Engineer
Language: E
Company Name:
Phone: 9056327861
Extension: 2116
Fax:

NPRI Report

Report ID: 57282
Report Year: 2011
NPRI ID: 3643
Company ID: 111400
Facility ID: 279570
SWR Report ID: 10794
Repor Type ID: 1
New Reporter: FALSE
No of Employees: 28
Is Compressor: FALSE
Is NPRI Part 4: TRUE
Is Battery: FALSE

Company

Company Name: Ashland Canada Corp.
Trade Name En:
Trade Name Fr:
DUNS No: 201226151
Website: www.ashland.com

NPRI Report

Report ID: 88599
Report Year: 2016
NPRI ID: 3643
Company ID: 111131
Facility ID: 279570
SWR Report ID: 88843
Repor Type ID: 1
New Reporter: FALSE
No of Employees: 29
Is Compressor: FALSE
Is NPRI Part 4: FALSE
Is Battery: FALSE

Company

Company Name: Solenis Canada ULC
Trade Name En:
Trade Name Fr:
DUNS No: 0
Website: solenis.com

NPRI Report Contact

Contact Type: NPRI
First Name: Arturo
Last Name: Pena
Email: apenamedina@solenis.com
Phone: 9056327861
Extension: 2116
Fax:

Description En:	Public Contact
Description Fr:	Responsable des renseignements au public
Position:	EHS Engineer
Language:	E
Company Name:	

61 **2 of 3** **WNW/222.3** **99.5 / 4.67** **BURLINGTON PLANT**
942 BRANT STREET
BURLINGTON ON L7R3X8 **NPR2**

NPRI ID:	3643	**Latitude:**	43.334043
Facility ID:	378857	**Longitude:**	-79.816436

Note: Substances included on NPRI reports for this NPRI ID are summarized below in the NPRI ID Substances Summary section. Substances listed in the Substances Summary are included on the basis of NPRI ID only. For entities (NPRI ID) with mobile plants and/or more than one facility location, substances listed above may or may not have been reported for specific facilities/mobile locations. The list of substances additionally includes those which have been included on the NPRI report with an unknown quantity or a quantity of 0.

For specific details about substance quantities, years, release/transfer/disposal methods, the reader is referred the facility report:

https://pollution-waste.canada.ca/national-release-inventory/?fromYear=1993&toYear=2022&name=3643

NPRI ID Substances Summary

CAS No:	11104-93-1	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Nitrogen oxides (expressed as nitrogen dioxide)		
Name French:	Oxydes d'azote (exprimés en dioxyde d'azote)		
Sort English:	Nitrogen oxides (expressed as nitrogen dioxide)		
Sort French:	Oxydes d'azote (exprimés en dioxyde d'azote)		

CAS No:	91-20-3	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Naphthalene		
Name French:	Naphtalène		
Sort English:	Naphthalene		
Sort French:	Naphtalène		

CAS No:	NA - 20	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Nonylphenol and its ethoxylates		
Name French:	Nonylphénol et ses dérivés éthoxylés		
Sort English:	Nonylphenol and its ethoxylates		
Sort French:	Nonylphénol et ses dérivés éthoxylés		

CAS No:	64742-94-5	**Is PAH?:**	FALSE
Is VOC?:	TRUE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Heavy aromatic solvent naphtha		
Name French:	Solvent naphtha aromatique lourd		
Sort English:	Heavy aromatic solvent naphtha		
Sort French:	Solvent naphtha aromatique lourd		

CAS No:	111-42-2	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Diethanolamine (and its salts)		
Name French:	Diéthanolamine (et ses sels)		
Sort English:	Diethanolamine (and its salts)		
Sort French:	Diéthanolamine (et ses sels)		

CAS No:	NA - 14	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Zinc (and its compounds)		
Name French:	Zinc (et ses composés)		
Sort English:	Zinc (and its compounds)		
Sort French:	Zinc (et ses composés)		

CAS No:	8042-47-5	***Is PAH?:***	FALSE
Is VOC?:	TRUE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	White mineral oil		
Name French:	Huile minérale blanche		
Sort English:	White mineral oil		
Sort French:	Huile minérale blanche		

CAS No:	NA - M08	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Total particulate matter		
Name French:	Matière particulaire totale		
Sort English:	PM - Total Particulate Matter		
Sort French:	PM - Particules totales		

CAS No:	107-21-1	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Ethylene glycol		
Name French:	Éthylène glycol		
Sort English:	Ethylene glycol		
Sort French:	Éthylèneglycol		

CAS No:	7446-09-5	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Sulphur dioxide		
Name French:	Dioxyde de soufre		
Sort English:	Sulphur dioxide		
Sort French:	Dioxyde de soufre		

CAS No:	NA - M10	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	PM2.5 - Particulate Matter <= 2.5 Micrometers		
Name French:	PM2,5 - Matière particulaire <= 2,5 micromètres		
Sort English:	PM2.5 - Particulate Matter <= 2.5 Micrometers		
Sort French:	PM2,5 - Matière particulaire <= 2,5 micromètres		

CAS No:	7632-00-0	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Sodium nitrite		
Name French:	Nitrite de sodium		
Sort English:	Sodium nitrite		
Sort French:	Nitrite de sodium		

CAS No:	7664-93-9	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Sulphuric acid		
Name French:	Acide sulfurique		
Sort English:	Sulphuric acid		
Sort French:	Acide sulfurique		

CAS No:	NA - 16	***Is PAH?:***	FALSE

Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Ammonia (total)		
Name French:	Ammoniac (total)		
Sort English:	Ammonia (total)		
Sort French:	Ammoniac (total)		

CAS No:	NA - M09	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	PM10 - Particulate Matter <= 10 Micrometers		
Name French:	PM10 - Matière particulaire <= 10 micromètres		
Sort English:	PM10 - Particulate Matter <= 10 Micrometers		
Sort French:	PM10 - Matière particulaire <= 10 micromètres		

CAS No:	95-63-6	***Is PAH?:***	FALSE
Is VOC?:	TRUE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	1,2,4-Trimethylbenzene		
Name French:	1,2,4-Triméthylbenzène		
Sort English:	Trimethylbenzene:1,2,4-		
Sort French:	Triméthylbenzène:1,2,4-		

CAS No:	NA - 01	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Antimony (and its compounds)		
Name French:	Antimoine (et ses composés)		
Sort English:	Antimony (and its compounds)		
Sort French:	Antimoine (et ses composés)		

CAS No:	71-36-3	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	n-Butyl alcohol		
Name French:	Butan-1-ol		
Sort English:	Butyl alcohol:n-		
Sort French:	Butan-1-ol		

CAS No:	630-08-0	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Carbon monoxide		
Name French:	Monoxyde de carbone		
Sort English:	Carbon monoxide		
Sort French:	Oxyde de carbone (monoxyde de carbone)		

CAS No:	7647-01-0	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Hydrochloric acid		
Name French:	Acide chlorhydrique		
Sort English:	Hydrochloric acid		
Sort French:	Acide chlorhydrique		

Geographic Location

DLS Description:		***Datum:***	1983.0
NTS Description:	A-006-F/030-M-5	***Forward Sort Area:***	L7S
Latitude:	43.334043	***SOMA:***	TRUE
Longitude:	-79.816436	***ON PEMA:***	TRUE
Census Subdiv ID:	3524002	***QC PEMA:***	FALSE
Ecozone ID:	8	***Quebec Windsor Corr:***	TRUE
Water Survey ID:	2	***Province Code:***	ON

NPRI ID Facility ID

NPRI ID: 3643
Facility ID: 378857

Facility

Facility ID:	378857	***IDM ID:***	0
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	325999	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		

Facility Name:
Website: www.herc.com

Address

Address1: 942 Brant Street
Address2: P. O. Box 100
City: BURLINGTON
Postal Zip: L7R3X8
Prov:

Address Geographic

Latitude:	43.3365	***Datum:***	1983
Longitude:	-79.8131	***Land Survey:***	
UTM Easting:	0.000000	***Topograph:***	
UTM Northing:	0.000000	***Additional Info:***	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	325999	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001

Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: All Other Miscellaneous Chemical Product Manufacturing
NAICS Title Fr: Fabrication de tous les autres produits chimiques divers

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	***Start Date:***	1993
Record Year:	2002	***End Date:***	2006

Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: All Other Miscellaneous Chemical Product Manufacturing
NAICS Title Fr: Fabrication de tous les autres produits chimiques divers

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	***Start Date:***	1993
Record Year:	2007	***End Date:***	2011

Key Indus Sector En: Chemicals

Key Indus Sector Fr: Produits chimiques
NAICS Title En: All Other Miscellaneous Chemical Product Manufacturing
NAICS Title Fr: Fabrication de tous les autres produits chimiques divers

NAICS Description En:

NAICS Description Fr:

NAICS Code: 325999 ***Start Date:*** 1993
Record Year: 2012 ***End Date:*** 2016
Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: All other miscellaneous chemical product manufacturing
NAICS Title Fr: Fabrication de tous les autres produits chimiques divers

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing chemical products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de produits chimiques.

NAICS Code: 325999 ***Start Date:*** 2017
Record Year: 2017 ***End Date:*** 2021
Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: All other miscellaneous chemical product manufacturing
NAICS Title Fr: Fabrication de tous les autres produits chimiques divers

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing chemical products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de produits chimiques.

NPRI Report

Report ID: 271259 ***Repor Type ID:*** 1
Report Year: 2003 ***New Reporter:*** FALSE
NPRI ID: 3643 ***No of Employees:*** 45
Company ID: 139546 ***Is Compressor:*** FALSE
Facility ID: 378857 ***Is NPRI Part 4:*** FALSE
SWR Report ID: 20030000003643 ***Is Battery:*** FALSE

Company

Company Name: HERCULES CANADA (2002) INC
Trade Name En:
Trade Name Fr:
DUNS No: 201226151
Website: www.herc.com

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9056327861
First Name:	Gerry	***Extension:***	115
Last Name:	Willard	***Fax:***	9053333718
Email:	gwillard@herc.com		
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Plant Manager		
Language:			
Company Name:			

61	***3 of 3***	***WNW/222.3***	***99.5 / 4.67***	***BURLINGTON PLANT*** ***942 BRANT ST., 942 BRANT STREET*** ***BURLINGTON ON***	***NPR2***

NPRI ID:	3643	***Latitude:***	43.334043
Facility ID:	368482, 369696, 422980, 356072, 251023, 244732, 244855, 244812	***Longitude:***	-79.816436

Note: Substances included on NPRI reports for this NPRI ID are summarized below in the NPRI ID Substances Summary section. Substances listed in the Substances Summary are included on the basis of NPRI ID only. For entities (NPRI ID) with mobile plants and/or more than one facility location, substances listed above may or may not have been reported for specific facilities/mobile locations. The list of substances additionally includes those which have been included on the NPRI report with an unknown quantity or a quantity of 0.

For specific details about substance quantities, years, release/transfer/disposal methods, the reader is referred the facility report:

https://pollution-waste.canada.ca/national-release-inventory/?fromYear=1993&toYear=2022&name=3643

NPRI ID Substances Summary

CAS No:	107-21-1	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Ethylene glycol		
Name French:	Éthylène glycol		
Sort English:	Ethylene glycol		
Sort French:	Éthylèneglycol		

CAS No:	95-63-6	***Is PAH?:***	FALSE
Is VOC?:	TRUE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	1,2,4-Trimethylbenzene		
Name French:	1,2,4-Triméthylbenzène		
Sort English:	Trimethylbenzene:1,2,4-		
Sort French:	Triméthylbenzène:1,2,4-		

CAS No:	64742-94-5	***Is PAH?:***	FALSE
Is VOC?:	TRUE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Heavy aromatic solvent naphtha		
Name French:	Solvent naphtha aromatique lourd		
Sort English:	Heavy aromatic solvent naphtha		
Sort French:	Solvent naphtha aromatique lourd		

CAS No:	NA - M09	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	PM10 - Particulate Matter <= 10 Micrometers		
Name French:	PM10 - Matière particulaire <= 10 micromètres		
Sort English:	PM10 - Particulate Matter <= 10 Micrometers		
Sort French:	PM10 - Matière particulaire <= 10 micromètres		

CAS No:	NA - 14	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Zinc (and its compounds)		
Name French:	Zinc (et ses composés)		
Sort English:	Zinc (and its compounds)		
Sort French:	Zinc (et ses composés)		

CAS No:	11104-93-1	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Nitrogen oxides (expressed as nitrogen dioxide)		
Name French:	Oxydes d'azote (exprimés en dioxyde d'azote)		
Sort English:	Nitrogen oxides (expressed as nitrogen dioxide)		
Sort French:	Oxydes d'azote (exprimés en dioxyde d'azote)		

CAS No:	7446-09-5	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Sulphur dioxide		
Name French:	Dioxyde de soufre		
Sort English:	Sulphur dioxide		
Sort French:	Dioxyde de soufre		

CAS No:	630-08-0	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Carbon monoxide		
Name French:	Monoxyde de carbone		
Sort English:	Carbon monoxide		
Sort French:	Oxyde de carbone (monoxyde de carbone)		

CAS No:	8042-47-5	***Is PAH?:***	FALSE
Is VOC?:	TRUE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	White mineral oil		
Name French:	Huile minérale blanche		
Sort English:	White mineral oil		
Sort French:	Huile minérale blanche		

CAS No:	NA - 01	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Antimony (and its compounds)		
Name French:	Antimoine (et ses composés)		
Sort English:	Antimony (and its compounds)		
Sort French:	Antimoine (et ses composés)		

CAS No:	7647-01-0	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Hydrochloric acid		
Name French:	Acide chlorhydrique		
Sort English:	Hydrochloric acid		
Sort French:	Acide chlorhydrique		

CAS No:	NA - 16	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Ammonia (total)		
Name French:	Ammoniac (total)		
Sort English:	Ammonia (total)		
Sort French:	Ammoniac (total)		

CAS No:	NA - M08	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE

Is DF?:	FALSE		
Name English:	Total particulate matter		
Name French:	Matière particulaire totale		
Sort English:	PM - Total Particulate Matter		
Sort French:	PM - Particules totales		

CAS No:	91-20-3	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Naphthalene		
Name French:	Naphtalène		
Sort English:	Naphthalene		
Sort French:	Naphtalène		

CAS No:	NA - M10	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	PM2.5 - Particulate Matter <= 2.5 Micrometers		
Name French:	PM2,5 - Matière particulaire <= 2,5 micromètres		
Sort English:	PM2.5 - Particulate Matter <= 2.5 Micrometers		
Sort French:	PM2,5 - Matière particulaire <= 2,5 micromètres		

CAS No:	7632-00-0	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Sodium nitrite		
Name French:	Nitrite de sodium		
Sort English:	Sodium nitrite		
Sort French:	Nitrite de sodium		

CAS No:	7664-93-9	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Sulphuric acid		
Name French:	Acide sulfurique		
Sort English:	Sulphuric acid		
Sort French:	Acide sulfurique		

CAS No:	111-42-2	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Diethanolamine (and its salts)		
Name French:	Diéthanolamine (et ses sels)		
Sort English:	Diethanolamine (and its salts)		
Sort French:	Diéthanolamine (et ses sels)		

CAS No:	71-36-3	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	n-Butyl alcohol		
Name French:	Butan-1-ol		
Sort English:	Butyl alcohol:n-		
Sort French:	Butan-1-ol		

CAS No:	NA - 20	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Nonylphenol and its ethoxylates		
Name French:	Nonylphénol et ses dérivés éthoxylés		
Sort English:	Nonylphenol and its ethoxylates		
Sort French:	Nonylphénol et ses dérivés éthoxylés		

Geographic Location

DLS Description:		**Datum:**	1983.0

NTS Description:	A-006-F/030-M-5	**Forward Sort Area:**	L7S
Latitude:	43.334043	**SOMA:**	TRUE
Longitude:	-79.816436	**ON PEMA:**	TRUE
Census Subdiv ID:	3524002	**QC PEMA:**	FALSE
Ecozone ID:	8	**Quebec Windsor Corr:**	TRUE
Water Survey ID:	2	**Province Code:**	ON

NPRI ID Facility ID

NPRI ID:	3643
Facility ID:	356072

Facility

Facility ID:	356072	**IDM ID:**	0
Portable:	FALSE	**AB Approval ID:**	0
NAICS Primary:	325999	**GHGRP ID:**	0
NAICS Secondary:	0	**ON GHGRP ID:**	0
NAICS Tertiary:	0		
Facility Name:	BURLINGTON PLANT		
Website:			

Address

Address1:	942 Brant Street
Address2:	
City:	BURLINGTON
Postal Zip:	L7R3X8
Prov:	

Address Geographic

Latitude:	43.3365	**Datum:**	1983
Longitude:	-79.8131	**Land Survey:**	
UTM Easting:	0.000000	**Topograph:**	
UTM Northing:	0.000000	**Additional Info:**	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	325999	**Start Date:**	1993
Record Year:	1997	**End Date:**	2001
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All Other Miscellaneous Chemical Product Manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	**Start Date:**	1993
Record Year:	2002	**End Date:**	2006
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All Other Miscellaneous Chemical Product Manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	***Start Date:***	1993
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All Other Miscellaneous Chemical Product Manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	***Start Date:***	1993
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All other miscellaneous chemical product manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing chemical products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de produits chimiques.

NAICS Code:	325999	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All other miscellaneous chemical product manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing chemical products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de produits chimiques.

NPRI Report

Report ID:	133861	***Repor Type ID:***	1
Report Year:	2009	***New Reporter:***	FALSE
NPRI ID:	3643	***No of Employees:***	38
Company ID:	129777	***Is Compressor:***	FALSE
Facility ID:	356072	***Is NPRI Part 4:***	FALSE
SWR Report ID:	20090000003643	***Is Battery:***	FALSE

Company

Company Name: ASHLAND CANADA CORPORATION
Trade Name En:
Trade Name Fr:
DUNS No: 201226151
Website:

NPRI Report Contact

Contact Type: NPRI
First Name: Tricia
Last Name: Rennie
Email: trennie@ashland.com
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: Environmental, Safety and Health Leader
Language:
Company Name:
Phone: 9056327861
Extension: 116
Fax: 9053333718

NPRI Report

Report ID: 153519
Report Year: 2006
NPRI ID: 3643
Company ID: 130984
Facility ID: 356072
SWR Report ID: 20060000003643
Repor Type ID: 1
New Reporter: FALSE
No of Employees: 37
Is Compressor: FALSE
Is NPRI Part 4: FALSE
Is Battery: FALSE

Company

Company Name: HERCULES CANADA
Trade Name En:
Trade Name Fr:
DUNS No: 201226151
Website:

NPRI Report Contact

Contact Type: NPRI
First Name: Tricia
Last Name: Rennie
Email: trennie@herc.com
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: Environmental, Safety and Health Leader
Language:
Company Name:
Phone: 9056327861
Extension: 116
Fax: 9053333718

NPRI Report

Report ID: 154623
Report Year: 2007
NPRI ID: 3643
Company ID: 130984
Facility ID: 356072
SWR Report ID: 20070000003643
Repor Type ID: 1
New Reporter: FALSE
No of Employees: 37
Is Compressor: FALSE
Is NPRI Part 4: FALSE
Is Battery: FALSE

Company

Company Name: HERCULES CANADA
Trade Name En:
Trade Name Fr:

DUNS No: 201226151
Website:

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9056327861
First Name:	Tricia	***Extension:***	116
Last Name:	Rennie	***Fax:***	9053333718
Email:	trennie@herc.com		
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Environmental, Safety and Health Leader		
Language:			
Company Name:			

NPRI Report

Report ID:	139833	***Repor Type ID:***	1
Report Year:	2008	***New Reporter:***	FALSE
NPRI ID:	3643	***No of Employees:***	36
Company ID:	130984	***Is Compressor:***	FALSE
Facility ID:	356072	***Is NPRI Part 4:***	FALSE
SWR Report ID:	20080000003643	***Is Battery:***	FALSE

Company

Company Name: HERCULES CANADA
Trade Name En:
Trade Name Fr:
DUNS No: 201226151
Website:

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9056327861
First Name:	Tricia	***Extension:***	116
Last Name:	Rennie	***Fax:***	9053333718
Email:	trennie@herc.com		
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Environmental, Safety and Health Leader		
Language:			
Company Name:			

NPRI ID Facility ID

NPRI ID: 3643
Facility ID: 244855

Facility

Facility ID:	244855	***IDM ID:***	9051
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	325999	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:	BURLINGTON PLANT		
Website:			

Address

Address1: 942 Brant Street
Address2:
City: BURLINGTON
Postal Zip: L7R3X8
Prov:

Address Geographic

Latitude:	43.3365	***Datum:***	1983
Longitude:	-79.8131	***Land Survey:***	
UTM Easting:	0.000000	***Topograph:***	
UTM Northing:	0.000000	***Additional Info:***	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	325999	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All Other Miscellaneous Chemical Product Manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	***Start Date:***	1993
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All Other Miscellaneous Chemical Product Manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	***Start Date:***	1993
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All Other Miscellaneous Chemical Product Manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	***Start Date:***	1993
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All other miscellaneous chemical product manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing chemical products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de produits chimiques.

NAICS Code:	325999	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All other miscellaneous chemical product manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing chemical products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de produits chimiques.

NPRI Report

Report ID:	33123	***Repor Type ID:***	3
Report Year:	2014	***New Reporter:***	FALSE
NPRI ID:	3643	***No of Employees:***	0
Company ID:	112750	***Is Compressor:***	FALSE
Facility ID:	244855	***Is NPRI Part 4:***	FALSE
SWR Report ID:	80028	***Is Battery:***	FALSE

Company

Company Name:	Ashland Canada Corp.
Trade Name En:	
Trade Name Fr:	
DUNS No:	0
Website:	

NPRI Report Comment

Description En:	Reason the facility does not meet the criteria for NPRI
Description Fr:	La raison pour laquelle cette installation ne rencontre pas les critères de déclaration de l'INRP
Comment:	Site was sold to Solenis in 2014
Note:	Many NPRI Report Comments are truncated in the NPRI data.

NPRI ID Facility ID

NPRI ID:	3643
Facility ID:	244812

Facility

Facility ID:	244812	***IDM ID:***	9051
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	325999	***GHGRP ID:***	0

NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:	BURLINGTON PLANT		
Website:	www.ashland.com		

Address

Address1:	942 Brant Street
Address2:	
City:	BURLINGTON
Postal Zip:	L7R3X8
Prov:	

Address Geographic

Latitude:	43.3365	***Datum:***	1983
Longitude:	-79.8131	***Land Survey:***	
UTM Easting:	0.000000	***Topograph:***	
UTM Northing:	0.000000	***Additional Info:***	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	325999	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All Other Miscellaneous Chemical Product Manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	***Start Date:***	1993
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All Other Miscellaneous Chemical Product Manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	***Start Date:***	1993
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All Other Miscellaneous Chemical Product Manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	***Start Date:***	1993

Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All other miscellaneous chemical product manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing chemical products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de produits chimiques.

NAICS Code:	325999	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All other miscellaneous chemical product manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing chemical products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de produits chimiques.

NPRI Report

Report ID:	47973	***Repor Type ID:***	1
Report Year:	2012	***New Reporter:***	FALSE
NPRI ID:	3643	***No of Employees:***	25
Company ID:	111400	***Is Compressor:***	FALSE
Facility ID:	244812	***Is NPRI Part 4:***	TRUE
SWR Report ID:	41027	***Is Battery:***	FALSE

Company

Company Name:	Ashland Canada Corp.
Trade Name En:	
Trade Name Fr:	
DUNS No:	201226151
Website:	www.ashland.com

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	6147904641
First Name:	Kara	***Extension:***	
Last Name:	Long	***Fax:***	
Email:	klong@ashland.com		
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Corporate Environmental Engineer		
Language:	E		
Company Name:			

NPRI Report

Report ID:	106342	***Repor Type ID:***	1
Report Year:	2010	***New Reporter:***	TRUE
NPRI ID:	3643	***No of Employees:***	38
Company ID:	111400	***Is Compressor:***	FALSE
Facility ID:	244812	***Is NPRI Part 4:***	FALSE
SWR Report ID:	20100000003643	***Is Battery:***	FALSE

Company

Company Name:	Ashland Canada Corp.
Trade Name En:	
Trade Name Fr:	
DUNS No:	201226151
Website:	www.ashland.com

NPRI Report

Report ID:	38898	***Repor Type ID:***	1
Report Year:	2013	***New Reporter:***	FALSE
NPRI ID:	3643	***No of Employees:***	24
Company ID:	110926	***Is Compressor:***	FALSE
Facility ID:	244812	***Is NPRI Part 4:***	TRUE
SWR Report ID:	42437	***Is Battery:***	FALSE

Company

Company Name:	Ashland Canada Corp.
Trade Name En:	
Trade Name Fr:	
DUNS No:	201226151
Website:	www.ashland.com

NPRI ID Facility ID

NPRI ID:	3643
Facility ID:	251023

Facility

Facility ID:	251023	***IDM ID:***	9051
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	325999	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:	BURLINGTON PLANT		
Website:	www.ashland.com		

Address

Address1:	942 Brant Street
Address2:	
City:	BURLINGTON
Postal Zip:	L7R3X8
Prov:	

Address Geographic

Latitude:	49.76453	**Datum:**	1983
Longitude:	-89.28594	**Land Survey:**	
UTM Easting:	0.000000	**Topograph:**	
UTM Northing:	0.000000	**Additional Info:**	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	325999	**Start Date:**	1993
Record Year:	1997	**End Date:**	2001
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All Other Miscellaneous Chemical Product Manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	**Start Date:**	1993
Record Year:	2002	**End Date:**	2006
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All Other Miscellaneous Chemical Product Manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	**Start Date:**	1993
Record Year:	2007	**End Date:**	2011
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All Other Miscellaneous Chemical Product Manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	**Start Date:**	1993
Record Year:	2012	**End Date:**	2016
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All other miscellaneous chemical product manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing chemical products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de produits chimiques.

NAICS Code:	325999	**Start Date:**	2017
Record Year:	2017	**End Date:**	2021
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All other miscellaneous chemical product manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing chemical products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de produits chimiques.

NPRI Report

Report ID:	33414	**Repor Type ID:**	4
Report Year:	2014	**New Reporter:**	FALSE
NPRI ID:	3643	**No of Employees:**	0
Company ID:	110925	**Is Compressor:**	FALSE
Facility ID:	251023	**Is NPRI Part 4:**	FALSE
SWR Report ID:	48154	**Is Battery:**	FALSE

Company

Company Name:	Ashland Canada Corp.
Trade Name En:	
Trade Name Fr:	
DUNS No:	201226151
Website:	www.ashland.com

NPRI Report

Report ID:	67129	**Repor Type ID:**	1
Report Year:	2019	**New Reporter:**	FALSE
NPRI ID:	3643	**No of Employees:**	28
Company ID:	111131	**Is Compressor:**	FALSE
Facility ID:	251023	**Is NPRI Part 4:**	FALSE
SWR Report ID:	160750	**Is Battery:**	FALSE

Company

Company Name:	Solenis Canada ULC
Trade Name En:	
Trade Name Fr:	
DUNS No:	0
Website:	solenis.com

NPRI Report Comment

Description En:	NPRI - Report Submission
Description Fr:	INRP - Soumission de rapport
Comment:	Voluntary reporting for Ethylene Glycol (CAS RN 107-21-1) as it did not meet reporting criteria for 2019.
Note:	Many NPRI Report Comments are truncated in the NPRI data.

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9056327861
First Name:	Arturo	**Extension:**	2116
Last Name:	Pena	**Fax:**	
Email:	mpongetti@solenis.com		
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	EHS Specialist Senior		
Language:	E		
Company Name:			

NPRI ID Facility ID

NPRI ID:	3643
Facility ID:	368482

Facility

Facility ID:	368482	**IDM ID:**	0
Portable:	FALSE	**AB Approval ID:**	0
NAICS Primary:	325999	**GHGRP ID:**	0
NAICS Secondary:	0	**ON GHGRP ID:**	0
NAICS Tertiary:	0		
Facility Name:	BURLINGTON PLANT		
Website:	www.herc.com		

Address

Address1:	942 Brant St.
Address2:	
City:	BURLINGTON
Postal Zip:	L7R3X8
Prov:	

Primary NAICS Details

NAICS Code:	325999	**Start Date:**	1993
Record Year:	1997	**End Date:**	2001
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All Other Miscellaneous Chemical Product Manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	**Start Date:**	1993
Record Year:	2002	**End Date:**	2006
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All Other Miscellaneous Chemical Product Manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	**Start Date:**	1993
Record Year:	2007	**End Date:**	2011
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All Other Miscellaneous Chemical Product Manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	**Start Date:**	1993
Record Year:	2012	**End Date:**	2016
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All other miscellaneous chemical product manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing chemical products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de produits chimiques.

NAICS Code:	325999	**Start Date:**	2017
Record Year:	2017	**End Date:**	2021
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All other miscellaneous chemical product manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing chemical products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de produits chimiques.

NPRI Report

Report ID:	277389	**Repor Type ID:**	1
Report Year:	2002	**New Reporter:**	FALSE
NPRI ID:	3643	**No of Employees:**	45
Company ID:	145017	**Is Compressor:**	FALSE
Facility ID:	368482	**Is NPRI Part 4:**	FALSE
SWR Report ID:	20020000003643	**Is Battery:**	FALSE

Company

Company Name:	HERCULES CANADA (2002) INC
Trade Name En:	
Trade Name Fr:	
DUNS No:	201226151

Website:	www.herc.com		

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9056327861
First Name:	Gerry	**Extension:**	115
Last Name:	Willard	**Fax:**	9053333718
Email:	gwillard@herc.com		
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Plant Manager		
Language:			
Company Name:			

NPRI ID Facility ID

NPRI ID:	3643
Facility ID:	244732

Facility

Facility ID:	244732	**IDM ID:**	9051
Portable:	FALSE	**AB Approval ID:**	0
NAICS Primary:	325999	**GHGRP ID:**	0
NAICS Secondary:	0	**ON GHGRP ID:**	0
NAICS Tertiary:	0		
Facility Name:	BURLINGTON PLANT		
Website:	solenis.com		

Address

Address1:	942 Brant Street
Address2:	
City:	BURLINGTON
Postal Zip:	L7R3X8
Prov:	

Address Geographic

Latitude:	43.3365	**Datum:**	1983
Longitude:	-79.8131	**Land Survey:**	
UTM Easting:	0.000000	**Topograph:**	
UTM Northing:	0.000000	**Additional Info:**	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	325999	**Start Date:**	1993
Record Year:	1997	**End Date:**	2001
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All Other Miscellaneous Chemical Product Manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	**Start Date:**	1993

Record Year: 2002 ***End Date:*** 2006
Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: All Other Miscellaneous Chemical Product Manufacturing
NAICS Title Fr: Fabrication de tous les autres produits chimiques divers

NAICS Description En:

NAICS Description Fr:

NAICS Code: 325999 ***Start Date:*** 1993
Record Year: 2007 ***End Date:*** 2011
Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: All Other Miscellaneous Chemical Product Manufacturing
NAICS Title Fr: Fabrication de tous les autres produits chimiques divers

NAICS Description En:

NAICS Description Fr:

NAICS Code: 325999 ***Start Date:*** 1993
Record Year: 2012 ***End Date:*** 2016
Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: All other miscellaneous chemical product manufacturing
NAICS Title Fr: Fabrication de tous les autres produits chimiques divers

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing chemical products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de produits chimiques.

NAICS Code: 325999 ***Start Date:*** 2017
Record Year: 2017 ***End Date:*** 2021
Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: All other miscellaneous chemical product manufacturing
NAICS Title Fr: Fabrication de tous les autres produits chimiques divers

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing chemical products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de produits chimiques.

NPRI Report

Report ID: 19284 ***Repor Type ID:*** 1
Report Year: 2015 ***New Reporter:*** FALSE

NPRI ID:	3643	**No of Employees:**	25
Company ID:	111131	**Is Compressor:**	FALSE
Facility ID:	244732	**Is NPRI Part 4:**	FALSE
SWR Report ID:	74885	**Is Battery:**	FALSE

Company

Company Name:	Solenis Canada ULC
Trade Name En:	
Trade Name Fr:	
DUNS No:	0
Website:	solenis.com

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9056327861
First Name:	Arturo	**Extension:**	2116
Last Name:	Pena	**Fax:**	
Email:	mpongetti@solenis.com		
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	EHS Engineer		
Language:	E		
Company Name:			

NPRI ID Facility ID

NPRI ID:	3643
Facility ID:	422980

Facility

Facility ID:	422980	**IDM ID:**	9051
Portable:	FALSE	**AB Approval ID:**	
NAICS Primary:	325999	**GHGRP ID:**	
NAICS Secondary:	0	**ON GHGRP ID:**	
NAICS Tertiary:	0		
Facility Name:	BURLINGTON PLANT		
Website:	Solenis.com		

Address

Address1:	942 Brant Street
Address2:	
City:	BURLINGTON
Postal Zip:	L7R 3X8
Prov:	

Address Geographic

Latitude:	43.33404	**Datum:**	
Longitude:	-79.81644	**Land Survey:**	
UTM Easting:	595916.000000	**Topograph:**	
UTM Northing:	4798504.000000	**Additional Info:**	
UTM Zone:	17		

Primary NAICS Details

NAICS Code:	325999	**Start Date:**	1993
Record Year:	1997	**End Date:**	2001

Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: All Other Miscellaneous Chemical Product Manufacturing
NAICS Title Fr: Fabrication de tous les autres produits chimiques divers

NAICS Description En:

NAICS Description Fr:

NAICS Code: 325999 ***Start Date:*** 1993
Record Year: 2002 ***End Date:*** 2006
Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: All Other Miscellaneous Chemical Product Manufacturing
NAICS Title Fr: Fabrication de tous les autres produits chimiques divers

NAICS Description En:

NAICS Description Fr:

NAICS Code: 325999 ***Start Date:*** 1993
Record Year: 2007 ***End Date:*** 2011
Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: All Other Miscellaneous Chemical Product Manufacturing
NAICS Title Fr: Fabrication de tous les autres produits chimiques divers

NAICS Description En:

NAICS Description Fr:

NAICS Code: 325999 ***Start Date:*** 1993
Record Year: 2012 ***End Date:*** 2016
Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: All other miscellaneous chemical product manufacturing
NAICS Title Fr: Fabrication de tous les autres produits chimiques divers

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing chemical products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de produits chimiques.

NAICS Code: 325999 ***Start Date:*** 2017
Record Year: 2017 ***End Date:*** 2021
Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: All other miscellaneous chemical product manufacturing
NAICS Title Fr: Fabrication de tous les autres produits chimiques divers

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing chemical products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de produits chimiques.

NPRI Report

Report ID:	316035	***Repor Type ID:***	1
Report Year:	2020	***New Reporter:***	FALSE
NPRI ID:	3643	***No of Employees:***	27
Company ID:	173064	***Is Compressor:***	FALSE
Facility ID:	422980	***Is NPRI Part 4:***	FALSE
SWR Report ID:	166232	***Is Battery:***	FALSE

Company

Company Name:	Solenis Canada ULC
Trade Name En:	
Trade Name Fr:	
DUNS No:	0
Website:	

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	2897142716
First Name:	Arturo	***Extension:***	
Last Name:	Pena	***Fax:***	
Email:	apenamedina@solenis.com		
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Senior EHS Specialist		
Language:	E		
Company Name:			

NPRI ID Facility ID

NPRI ID:	3643
Facility ID:	369696

Facility

Facility ID:	369696	***IDM ID:***	0
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	325999	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:	BURLINGTON PLANT		
Website:			

Address

Address1:	942 Brant Street
Address2:	P. O. Box 100
City:	BURLINGTON
Postal Zip:	L7R3X8
Prov:	

Address Geographic

Latitude:	43.3365	**Datum:**	1983
Longitude:	-79.8131	**Land Survey:**	
UTM Easting:	0.000000	**Topograph:**	
UTM Northing:	0.000000	**Additional Info:**	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	325999	**Start Date:**	1993
Record Year:	1997	**End Date:**	2001
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All Other Miscellaneous Chemical Product Manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	**Start Date:**	1993
Record Year:	2002	**End Date:**	2006
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All Other Miscellaneous Chemical Product Manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	**Start Date:**	1993
Record Year:	2007	**End Date:**	2011
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All Other Miscellaneous Chemical Product Manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

NAICS Description Fr:

NAICS Code:	325999	**Start Date:**	1993
Record Year:	2012	**End Date:**	2016
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All other miscellaneous chemical product manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing chemical products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de produits chimiques.

NAICS Code:	325999	**Start Date:**	2017
Record Year:	2017	**End Date:**	2021
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	All other miscellaneous chemical product manufacturing		
NAICS Title Fr:	Fabrication de tous les autres produits chimiques divers		

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing chemical products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de produits chimiques.

NPRI Report

Report ID:	255634	**Repor Type ID:**	1
Report Year:	2005	**New Reporter:**	FALSE
NPRI ID:	3643	**No of Employees:**	39
Company ID:	130984	**Is Compressor:**	FALSE
Facility ID:	369696	**Is NPRI Part 4:**	FALSE
SWR Report ID:	20050000003643	**Is Battery:**	FALSE

Company

Company Name:	HERCULES CANADA
Trade Name En:	
Trade Name Fr:	
DUNS No:	201226151
Website:	

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9056327861
First Name:	Tricia	**Extension:**	116
Last Name:	Rennie	**Fax:**	9053333718
Email:	trennie@herc.com		
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Environmental, Safety and Health Leader		
Language:			
Company Name:			

NPRI Report

Report ID:	264024	**Repor Type ID:**	1
Report Year:	2004	**New Reporter:**	FALSE
NPRI ID:	3643	**No of Employees:**	38
Company ID:	130984	**Is Compressor:**	FALSE
Facility ID:	369696	**Is NPRI Part 4:**	FALSE
SWR Report ID:	20040000003643	**Is Battery:**	FALSE

Company

Company Name:	HERCULES CANADA
Trade Name En:	
Trade Name Fr:	

DUNS No: 201226151
Website:

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9056327861
First Name:	Michele	**Extension:**	122
Last Name:	Pongetti	**Fax:**	9053333718
Email:	mpongetti@herc.com		
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Health, Safety, Environment		
Language:			
Company Name:			

---

62 | **1 of 1** | **ENE/222.5** | **91.8 / -3.00** | **280 BRANT ST Burlington ON** | **WWIS**

Well ID:	7331850	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	04/23/2019
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z297195	**Contractor:**	7295
Tag:	A237091	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/733\7331850.pdf

Additional Detail(s) (Map)

Well Completed Date:	08/23/2018
Year Completed:	2018
Depth (m):	6.096
Latitude:	43.3334516140485
Longitude:	-79.8096940381957
Path:	733\7331850.pdf

Bore Hole Information

Bore Hole ID:	1007434499	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596494.00
Code OB Desc:		**North83:**	4798533.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	08/23/2018	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1007889620
Layer: 1
Color: 6
General Color: BROWN
Mat1: 01
Most Common Material: FILL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 3.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1007889622
Layer: 3
Color: 7
General Color: RED
Mat1: 17
Most Common Material: SHALE
Mat2:
Mat2 Desc:
Mat3: 91
Mat3 Desc: WATER-BEARING
Formation Top Depth: 10.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1007889621
Layer: 2
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 3.0
Formation End Depth: 10.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1007890695

Layer: 1
Plug From: 0.0
Plug To: 9.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1007892572
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1007888306
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007892798
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 10.0
Casing Diameter: 1.7999999523162842
Casing Diameter UOM: Inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1007893155
Layer: 1
Slot: 10
Screen Top Depth: 10.0
Screen End Depth: 20.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.0

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1007893793
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:

Flowing:

Hole Diameter

Hole ID:	1007891848
Diameter:	8.0
Depth From:	0.0
Depth To:	20.0
Hole Depth UOM:	ft
Hole Diameter UOM:	Inch

Links

Bore Hole ID:	1007434499	***Tag No:***	A237091
Depth M:	6.096	***Contractor:***	7295
Year Completed:	2018	***Latitude:***	43.3334516140485
Well Completed Dt:	08/23/2018	***Longitude:***	-79.8096940381957
Audit No:	Z297195	***Y:***	43.333451611388476
Path:	733\7331850.pdf	***X:***	-79.80969388927636

63 ***1 of 1*** ***SSE/222.9*** ***92.8 / -2.00*** ***Former CNR Land Burlington ON L7S*** ***EHS***

Order No:	20190103051	***Nearest Intersection:***	
Status:	C	***Municipality:***	Burlington
Report Type:	Custom Report	***Client Prov/State:***	ON
Report Date:	10-JAN-19	***Search Radius (km):***	.25
Date Received:	03-JAN-19	***X:***	-79.811863
Previous Site Name:	CNR railway land	***Y:***	43.330287
Lot/Building Size:	0.95 hectares		
Additional Info Ordered:			

64 ***1 of 100*** ***NW/223.3*** ***99.8 / 5.00*** ***HERCULES CANADA INC. 942 BRANT STREET BURLINGTON CITY ON L7R 2J7*** ***CA***

Certificate #:	8-3202-95-
Application Year:	95
Issue Date:	7/17/1995
Approval Type:	Industrial air
Status:	
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	SCRUBBER FOR (8) PROC. TANKS
Contaminants:	Sound, Nitrogen Oxides, Sulphur Dioxide
Emission Control:	Muffler

64 ***2 of 100*** ***NW/223.3*** ***99.8 / 5.00*** ***HERCULES CANADA INC. 942 BRANT STREET BURLINGTON CITY ON L7R 2J7*** ***CA***

Certificate #:	8-3039-89-
Application Year:	89
Issue Date:	7/28/1989
Approval Type:	Industrial air
Status:	Approved
Application Type:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Client Name:					
Client Address:					
Client City:					
Client Postal Code:					
Project Description:		MELTER FOR ALKYL KETENE DIMER			
Contaminants:					
Emission Control:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	3 of 100	NW/223.3	99.8 / 5.00	HERCULES CANADA INC. 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	CA

Certificate #:	8-3108-89-
Application Year:	89
Issue Date:	11/17/1989
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	UPGRADING OF HERCON MIXING TANK VENTILAT
Contaminants:	
Emission Control:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	4 of 100	NW/223.3	99.8 / 5.00	HERCULES CANADA INC. 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	CA

Certificate #:	8-3149-89-
Application Year:	89
Issue Date:	5/6/1992
Approval Type:	Industrial air
Status:	Cancelled
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	TEMP. BOILER FUEL SUBSTITUTION
Contaminants:	
Emission Control:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	5 of 100	NW/223.3	99.8 / 5.00	HERCULES CANADA INC. BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SPL

Ref No:	95990	**Municipality No:**	14101
Year:		**Nature of Damage:**	
Incident Dt:	2/2/1994	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2/2/1994	**Health/Env Conseq:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
Facility Name:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			

Nearest Watercourse:	
Site Name:	
Site Address:	
Site Region:	
Site Municipality:	BURLINGTON CITY
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	ABOVE-GROUND TANK LEAK
Incident Event:	
Environment Impact:	NOT ANTICIPATED
Nature of Impact:	
Contaminant Qty:	
System Facility Address:	
Client Name:	
Client Type:	
Call Report Locatn Geodata:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	LAND
Receiving Environment:	
Incident Reason:	OTHER
Incident Summary:	HERCULES - 60000 LBS OF HEAVY VEGETABLE OIL TO GROUND AND LAGOON
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Source Type:	

---

64 | **6 of 100** | **NW/223.3** | **99.8 / 5.00** | **HERCULES CANADA BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7** | **SPL**

Ref No:	2945	**Municipality No:**	14101
Year:		**Nature of Damage:**	
Incident Dt:	4/28/1988	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	4/28/1988	**Health/Env Conseq:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
Facility Name:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BURLINGTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:	PROCESS UPSET		

Incident Event:
Environment Impact:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Call Report Locatn Geodata:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: AIR
Receiving Environment:
Incident Reason: OTHER
Incident Summary: HERCULES CANADA - 10 SEC SMOKE EMISSION
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:

---

64 | ***7 of 100*** | ***NW/223.3*** | ***99.8 / 5.00*** | ***HERCULES CANADA BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7*** | ***SPL***

Ref No: 7355
Year:
Incident Dt: 7/31/1988
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/31/1988
Dt Document Closed:
Site No:
Facility Name:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BURLINGTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: PROCESS UPSET
Incident Event:
Environment Impact:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Call Report Locatn Geodata:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:

Municipality No: 14101
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved:

Contaminant UN No 1:
Receiving Medium: AIR
Receiving Environment:
Incident Reason: EQUIPMENT FAILURE
Incident Summary: HERCULES - 5 SEC. SMOKE TO ATM.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:

---

64 | ***8 of 100*** | ***NW/223.3*** | ***99.8 / 5.00*** | ***HERCULES CANADA BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7*** | ***SPL***

Ref No: 9219
Year:
Incident Dt: 1/10/1988
Dt MOE Arvl on Scn:
MOE Reported Dt: 1/10/1988
Dt Document Closed:
Site No:
Facility Name:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BURLINGTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: PROCESS UPSET
Incident Event:
Environment Impact:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Call Report Locatn Geodata:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: AIR
Receiving Environment:
Incident Reason: EQUIPMENT FAILURE
Incident Summary: HERCULES CANADA - SMOKE FOR 30 MIN. FROM LEAKY TUBE IN VAPOURIZER.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:

Municipality No: 14101
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	9 of 100	NW/223.3	99.8 / 5.00	HERCULES CANADA BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SPL

Ref No:	15926	**Municipality No:**	14101
Year:		**Nature of Damage:**	
Incident Dt:	3/16/1989	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	3/16/1989	**Health/Env Conseq:**	
Dt Document Closed:		**Agency Involved:**	

Site No:
Facility Name:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BURLINGTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: UNKNOWN
Incident Event:
Environment Impact:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Call Report Locatn Geodata:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND / WATER
Receiving Environment:
Incident Reason: ERROR
Incident Summary: HERCULES CANADA-18000 L LUBE OIL TO GROUND AND SEWER.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	10 of 100	NW/223.3	99.8 / 5.00	HERCULES CANADA BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SPL

Ref No:	18212	**Municipality No:**	14101
Year:		**Nature of Damage:**	
Incident Dt:	5/8/1989	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	5/8/1989	**Health/Env Conseq:**	
Dt Document Closed:		**Agency Involved:**	

Site No:
Facility Name:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BURLINGTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: OTHER CAUSE (N.O.S.)
Incident Event:
Environment Impact:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Call Report Locatn Geodata:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Receiving Environment:
Incident Reason: ERROR
Incident Summary: HERCULES - 100 KG FORMALDEHYDE (37%) TO DYKED AREA.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:

---

64 | ***11 of 100*** | ***NW/223.3*** | ***99.8 / 5.00*** | ***HERCULES CANADA***
BOILER STACK BURLINGTON PLANT 942
BRANT STREET
BURLINGTON CITY ON | ***SPL***

Ref No: 18455
Year:
Incident Dt: 5/13/1989
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/13/1989
Dt Document Closed:
Site No:
Facility Name:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BURLINGTON CITY

Municipality No: 14101
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved:

Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: PROCESS UPSET
Incident Event:
Environment Impact:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Call Report Locatn Geodata:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: AIR
Receiving Environment:
Incident Reason: COMBUSTION PROBLEMS
Incident Summary: HERCULES-INTERMITTENT SMOKE FOR UNKNOWN DURATION.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:

64	12 of 100	NW/223.3	99.8 / 5.00	HERCULES CANADA HOLDING TANK BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON	SPL

Ref No: 19561
Year:
Incident Dt: 10/4/1988
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/4/1988
Dt Document Closed:
Site No:
Facility Name:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BURLINGTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: VALVE/FITTING LEAK OR FAILURE
Incident Event:
Environment Impact: NOT ANTICIPATED
Nature of Impact:
Contaminant Qty:
Municipality No: 14101
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved: HALTON REGION

System Facility Address:
Client Name:
Client Type:
Call Report Locatn Geodata:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: WATER
Receiving Environment:
Incident Reason: ERROR
Incident Summary: BACKENTRY - HERCULES 4000 KGS AMILE RESIN TO LAGOON
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:

---

64 | ***13 of 100*** | ***NW/223.3*** | ***99.8 / 5.00*** | ***HERCULES CANADA BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7*** | ***SPL***

Ref No: 20428
Year:
Incident Dt: 6/15/1989
Dt MOE Arvl on Scn:
MOE Reported Dt: 6/15/1989
Dt Document Closed:
Site No:
Facility Name:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BURLINGTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: ABOVE-GROUND TANK LEAK
Incident Event:
Environment Impact:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Call Report Locatn Geodata:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Receiving Environment:
Incident Reason: ERROR
Municipality No: 14101
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved:

Incident Summary: HERCULES - 500 KG MAX. PITCH DISTILLATE TO DYKED AREA.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:

---

64 **14 of 100** **NW/223.3** **99.8 / 5.00** **HERCULES CANADA**
BURLINGTON PLANT 942 BRANT STREET
BURLINGTON CITY ON L7R 2J7 **SPL**

Ref No: 20441
Year:
Incident Dt: 3/16/1989
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/16/1989
Dt Document Closed:
Site No:
Facility Name:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BURLINGTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: VALVE/FITTING LEAK OR FAILURE
Incident Event:
Environment Impact: NOT ANTICIPATED
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Call Report Locatn Geodata:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Receiving Environment:
Incident Reason: NEGLIGENCE (APPARENT)
Incident Summary: BACKENTRY - HERCULES CAN.15 000L LUBRICATING OIL FROM OPEN VALVES
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:

Municipality No: 14101
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved: REG MUNICIPALITY OF HALTON

---

64 **15 of 100** **NW/223.3** **99.8 / 5.00** **HERCULES CANADA**
BURLINGTON PLANT 942 BRANT STREET **SPL**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

BURLINGTON CITY ON L7R 2J7

Ref No:	25002	***Municipality No:***	14101
Year:		***Nature of Damage:***	
Incident Dt:	9/9/1989	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	9/9/1989	***Health/Env Conseq:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
Facility Name:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BURLINGTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:	PROCESS UPSET		
Incident Event:			
Environment Impact:			
Nature of Impact:			
Contaminant Qty:			
System Facility Address:			
Client Name:			
Client Type:			
Call Report Locatn Geodata:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	AIR		
Receiving Environment:			
Incident Reason:	EQUIPMENT FAILURE		
Incident Summary:	HERCULES -1 HOUR OF WASTEGAS EMISSIONS		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Source Type:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	16 of 100	NW/223.3	99.8 / 5.00	***HERCULES CANADA BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7***	SPL

Ref No:	28860	***Municipality No:***	14101
Year:		***Nature of Damage:***	
Incident Dt:	12/14/1989	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	12/14/1989	***Health/Env Conseq:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
Facility Name:			
MOE Response:			

Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BURLINGTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: PROCESS UPSET
Incident Event:
Environment Impact:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Call Report Locatn Geodata:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: AIR
Receiving Environment:
Incident Reason: EQUIPMENT FAILURE
Incident Summary: HERCULES-TALL OIL GAS TO AIR
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:

64	17 of 100	NW/223.3	99.8 / 5.00	HERCULES CANADA BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SPL

Ref No: 29596
Year:
Incident Dt: 1/7/1990
Dt MOE Arvl on Scn:
MOE Reported Dt: 1/7/1990
Dt Document Closed:
Site No:
Facility Name:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BURLINGTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Municipality No: 14101
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved:

Northing:
Easting:
Incident Cause: PROCESS UPSET
Incident Event:
Environment Impact: NOT ANTICIPATED
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Call Report Locatn Geodata:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: AIR
Receiving Environment:
Incident Reason: COMBUSTION PROBLEMS
Incident Summary: HERCULES - INTERMITTENT SMOKE EMISSIONS 4 HRS.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:

---

64 | ***18 of 100*** | ***NW/223.3*** | ***99.8 / 5.00*** | ***HERCULES CANADA BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7*** | ***SPL***

Ref No: 31941
Year:
Incident Dt: 3/12/1990
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/12/1990
Dt Document Closed:
Site No:
Facility Name:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BURLINGTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: OTHER CAUSE (N.O.S.)
Incident Event:
Environment Impact: NOT ANTICIPATED
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Call Report Locatn Geodata:
Contaminant Code:

Municipality No: 14101
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved:

Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: AIR
Receiving Environment:
Incident Reason: INTENTIONAL/PLANNED
Incident Summary: HERCULES - WASTE GASES TOAIR FOR ONE HOUR
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:

---

64 | ***19 of 100*** | ***NW/223.3*** | ***99.8 / 5.00*** | ***HERCULES CANADA BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7*** | ***SPL***

Ref No: 37185
Year:
Incident Dt: 7/3/1990
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/3/1990
Dt Document Closed:
Site No:
Facility Name:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BURLINGTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: START-UPS/SHUTDOWNS/INTERRUPTIONS
Incident Event:
Environment Impact: POSSIBLE
Nature of Impact: Vegetation
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Call Report Locatn Geodata:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: AIR
Receiving Environment:
Incident Reason: INTENTIONAL/PLANNED
Incident Summary: HERCULES CANADA- ONGOING INTERMITTENT SMOKE.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:

Municipality No: 14101
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SAC Action Class:
Source Type:

---

64 **20 of 100** **NW/223.3** **99.8 / 5.00** **HERCULES CANADA**
BURLINGTON PLANT 942 BRANT STREET
BURLINGTON CITY ON L7R 2J7 **SPL**

Ref No: 41587
Year:
Incident Dt: 10/2/1990
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/2/1990
Dt Document Closed:
Site No:
Facility Name:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BURLINGTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: PROCESS UPSET
Incident Event:
Environment Impact: POSSIBLE
Nature of Impact: Soil contamination
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Call Report Locatn Geodata:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND / AIR
Receiving Environment:
Incident Reason: OVERSTRESS/OVERPRESSURE
Incident Summary: HERCULES CANADA -THERMO OIL RELEASED TO AIR AND GROUND FROM RELIEF VALVE.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:

Municipality No: 14101
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved:

---

64 **21 of 100** **NW/223.3** **99.8 / 5.00** **HERCULES CANADA**
BURLINGTON PLANT 942 BRANT STREET
BURLINGTON CITY ON L7R 2J7 **SPL**

Ref No: 42467
Year:
Incident Dt: 10/22/1990

Municipality No: 14101
Nature of Damage:
Discharger Report:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	10/22/1990	**Health/Env Conseq:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
Facility Name:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BURLINGTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:	PROCESS UPSET		
Incident Event:			
Environment Impact:	POSSIBLE		
Nature of Impact:	Vegetation		
Contaminant Qty:			
System Facility Address:			
Client Name:			
Client Type:			
Call Report Locatn Geodata:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	AIR		
Receiving Environment:			
Incident Reason:	ERROR		
Incident Summary:	HERCULES-INTERMITTENT SMOKE TO ATMOSPHERE.		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Source Type:			

64	22 of 100	NW/223.3	99.8 / 5.00	**HERCULES CANADA INC.** **BURLINGTON PLANT 942 BRANT STREET** **BURLINGTON CITY ON L7R 2J7**	SPL

Ref No:	47814	**Municipality No:**	14101
Year:		**Nature of Damage:**	
Incident Dt:	3/19/1991	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	3/19/1991	**Health/Env Conseq:**	
Dt Document Closed:		**Agency Involved:**	HALTO REG SPILLS,SEWAGE PLANT
Site No:			
Facility Name:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			

Site Region:
Site Municipality: BURLINGTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: CONTAINER OVERFLOW
Incident Event:
Environment Impact: POSSIBLE
Nature of Impact: Water course or lake
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Call Report Locatn Geodata:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND / WATER
Receiving Environment:
Incident Reason: ERROR
Incident Summary: HERCULES-540 LITRES KYMENE 557 H TO GRND AND SANITARY SEWER.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:

---

64 | ***23 of 100*** | ***NW/223.3*** | ***99.8 / 5.00*** | ***HERCULES CANADA INC.***
BRANT ST/PLAINS RD INTERSECTION.
BURLINGTON PLANT 942 BRANT STREET
BURLINGTON CITY ON | ***SPL***

Ref No: 85983
Year:
Incident Dt: 5/23/1993
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/23/1993
Dt Document Closed:
Site No:
Facility Name:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BURLINGTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: PIPE/HOSE LEAK
Incident Event:
Environment Impact: CONFIRMED

Municipality No: 14101
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Nature of Impact: Air Pollution
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Call Report Locatn Geodata:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: AIR
Receiving Environment:
Incident Reason: MATERIAL FAILURE
Incident Summary: HERCULES CANADA INC-MER- CAPTAN TO AIR FROM LEAK- ING VAPOR COLLECTION TANK
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:

64	***24 of 100***	***NW/223.3***	***99.8 / 5.00***	***HERCULES CANADA INC.*** ***BURLINGTON ON***	***CHEM***

Headcode:
Headcode Desc:
Phone:
List Name:
Description:
Head Office Province: ON
Head Office Postal: L4Z1S1
Mailing Address: 4 ROBERT SPECK PARKWAY
Mailing Address 2:
Mailing City: MISSISSAUGA

64	***25 of 100***	***NW/223.3***	***99.8 / 5.00***	***HERCULES CANADA INC*** ***942 BRANT ST*** ***BURLINGTON ON L7R 2J7***	***CHM***

Headcode: 00273600
Headcode Desc: CHEMICALS
Phone:
List Name:
Description:

64	***26 of 100***	***NW/223.3***	***99.8 / 5.00***	***Ashland Canada Corp.*** ***942 Brant St*** ***Burlington ON L7R 2J7***	***SCT***

Established: 01-JUL-13
Plant Size (ft²):
Employment:

--Details--
Description: All Other Miscellaneous Chemical Product Manufacturing
SIC/NAICS Code: 325999

64	***27 of 100***	***NW/223.3***	***99.8 / 5.00***	***HERCULES CANADA INC.*** ***942 BRANT ST BURLINGTON PLANT 942 BRANT STREET*** ***BURLINGTON CITY ON L7R 2J7***	***SPL***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Ref No:	196324	**Municipality No:**	14101
Year:		**Nature of Damage:**	
Incident Dt:	3/12/2001	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	3/12/2001	**Health/Env Conseq:**	
Dt Document Closed:		**Agency Involved:**	

Site No:
Facility Name:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BURLINGTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: PIPE/HOSE LEAK
Incident Event:
Environment Impact: Possible
Nature of Impact: Multi Media Pollution
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Call Report Locatn Geodata:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Air
Receiving Environment:
Incident Reason: MATERIAL FAILURE
Incident Summary: HERCULES:SPILL OF DOW THERM TO AIR. FD, MOE. PLANT EVACUATED
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:

64	28 of 100	NW/223.3	99.8 / 5.00	**HERCULES CANADA INC.** **BURLINGTON CITY ON**	CA

Certificate #: 8-3069-85-000
Application Year: 85
Issue Date: 8/14/85
Approval Type: Industrial air
Status: Application Cancelled
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminants:
Emission Control:

---

64 | ***29 of 100*** | ***NW/223.3*** | ***99.8 / 5.00*** | ***942 Brant Street Burlington ON L7R 2J7*** | ***CA***

Certificate #:	2119-4ZENQD
Application Year:	02
Issue Date:	3/13/02
Approval Type:	Industrial air
Status:	Revoked and/or Replaced
Application Type:	New Certificate of Approval
Client Name:	Hercules Canada Inc.
Client Address:	942 Brant Street
Client City:	Burlington
Client Postal Code:	L7R 3X8
Project Description:	This application is for approval to modify existing No. 1 silica dryer. Modifications will allow the dryer to operate as a natural gas combustion unit. The burner is currently fired wit No. 2 fuel oil. The only significant emissions from the dryer are by-products of combustion of natural gas. The silica dryer will operate for a maximum of 16 hours per day.
Contaminants:	
Emission Control:	

---

64 | ***30 of 100*** | ***NW/223.3*** | ***99.8 / 5.00*** | ***942 Brant Street Burlington ON L7R 2J7*** | ***CA***

Certificate #:	6293-587JMD
Application Year:	02
Issue Date:	3/13/02
Approval Type:	Industrial air
Status:	Amended
Application Type:	Amended CofA
Client Name:	Hercules Canada Inc.
Client Address:	942 Brant Street
Client City:	Burlington
Client Postal Code:	L7R 3X8
Project Description:	This application is for the addition of new tank #150 (source 12) venting to atmosphere via a stack located on the roof of building No. 9301.
Contaminants:	
Emission Control:	

---

64 | ***31 of 100*** | ***NW/223.3*** | ***99.8 / 5.00*** | ***942 Brant Street Burlington ON L7R 2J7*** | ***CA***

Certificate #:	1976-579RVZ
Application Year:	02
Issue Date:	3/13/02
Approval Type:	Industrial air
Status:	Revoked and/or Replaced
Application Type:	Amended CofA
Client Name:	Hercules Canada Inc.
Client Address:	942 Brant Street
Client City:	Burlington
Client Postal Code:	L7R 3X8
Project Description:	This application is for a change in use of an existing storage tank (T082). This tank will be used for the storage of Ultra-Phase (a cationic dispersed size agent) used in the pulp and paper industry.
Contaminants:	
Emission Control:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	32 of 100	NW/223.3	99.8 / 5.00	942 Brant Street Burlington ON L7R 2J7	CA

Certificate #: 8-300-064-77-776
Application Year: 00
Issue Date: 12/8/00
Approval Type: Industrial air
Status: Approved
Application Type: Notice
Client Name: Hercules Canada
Client Address: 942 Brant Street
Client City: Burlington
Client Postal Code: L7R 3X8
Project Description: Company name change to read: BetzDearborn Canada Inc. & Hercules Canada Inc. o/a Hercules Canada
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	33 of 100	NW/223.3	99.8 / 5.00	942 Brant Street Burlington ON L7R 2J7	CA

Certificate #: 8-3062-83-006
Application Year: 00
Issue Date: 11/6/00
Approval Type: Industrial air
Status: Approved
Application Type: Notice
Client Name: Hercules Canada Inc.
Client Address: 942 Brant Street
Client City: Burlington
Client Postal Code: L7R 3X8
Project Description: The name of the company has changed FROM: Hercules Canada Inc. TO: Hercules Canada Inc. operating as Hercules Canada
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	34 of 100	NW/223.3	99.8 / 5.00	Hercules Canada Inc. 942 Brant Street Burlington Ontario L7R 3X8 Burlington ON	EBR

EBR Registry No: IA01E1664
Ministry Ref No: 7783-54YLF5
Notice Type: Instrument Decision
Notice Stage:
Notice Date: December 06, 2006
Proposal Date: November 30, 2001
Year: 2001
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Hercules Canada Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 942 Brant Street, Burlington Ontario, L7R 3X8
Comment Period:
URL:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

942 Brant Street Burlington Ontario L7R 3X8 Burlington

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	35 of 100	NW/223.3	99.8 / 5.00	Hercules Canada (2002) Inc. 942 Brant Street Burlington Ontario L7R 2J7 Burlington ON	EBR

EBR Registry No: IA02E1353
Ministry Ref No: 3329-5FENN3
Notice Type: Instrument Decision
Notice Stage:
Notice Date: May 29, 2003
Proposal Date: November 01, 2002
Year: 2002
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Hercules Canada (2002) Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 942 Brant Street, P.O. Box 100, Burlington Ontario, L7R 3X8
Comment Period:
URL:

Site Location Details:

942 Brant Street Burlington Ontario L7R 2J7 Burlington

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	36 of 100	NW/223.3	99.8 / 5.00	HERCULES CANADA INC. 942 BRANT ST. P.O. BOX 100 BURLINGTON ON L7R 2J7	GEN

Generator No: ON0096300
SIC Code: 3712
SIC Description: IND. ORGANIC CHEM.
Approval Years: 86,87,88
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 232

Waste Class Name: POLYMERIC RESINS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

---

64 | **37 of 100** | **NW/223.3** | **99.8 / 5.00** | **HERCULES CANADA INC.**
942 BRANT ST. P.O.BOX 100
BURLINGTON ON L7R 2J7 | **GEN**

Generator No: ON0096300
SIC Code: 3712
SIC Description: IND. ORGANIC CHEM.
Approval Years: 89
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 267

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Name: ORGANIC ACIDS

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	38 of 100	NW/223.3	99.8 / 5.00	HERCULES CANADA INC. 942 BRANT STREET BURLINGTON ON L7R 3X8	GEN

Generator No: ON0096300
SIC Code: 3712
SIC Description: IND. ORGANIC CHEM.
Approval Years: 92,93,97,98,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	39 of 100	NW/223.3	99.8 / 5.00	HERCULES CANADA INC. 20-010 942 BRANT ST. P.O.BOX 100 BURLINGTON ON L7R 2J7	GEN

Generator No: ON0096300
SIC Code: 3712
SIC Description: IND. ORGANIC CHEM.
Approval Years: 94,95,96
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	40 of 100	NW/223.3	99.8 / 5.00	HERCULES CANADA 942 BRANT STREET BURLINGTON ON L7R 3X8	GEN

Generator No: ON0096300
SIC Code: 3712

SIC Description: IND. ORGANIC CHEM.
Approval Years: 99,00
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

64	41 of 100	NW/223.3	99.8 / 5.00	**HERCULES CANADA (2002) INC** **942 BRANT STREET** **BURLINGTON ON L7R 3X8**	GEN

Generator No: ON0096300
SIC Code:
SIC Description:
Approval Years: 02,03,04,05,06,07,08
PO Box No:
Country:
Status:
Co Admin:

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 243
Waste Class Name: PCB'S

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 232

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Name: POLYMERIC RESINS

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

---

64 | **42 of 100** | **NW/223.3** | **99.8 / 5.00** | **HERCULESCANADALTD** | **NEES**

BURLINGTON ON

Incident Date: 6/16/76
Contaminant: other oil
Amount:
Units:
Quantity:
Cause: Discharge
Source: Unknown
Reason: Intent
Sector: Service Industry

---

64 | **43 of 100** | **NW/223.3** | **99.8 / 5.00** | **HERCULES CANADA** | **NEES**

BURLINGTON CITY ON

Incident Date: 1/10/88
Contaminant: SMOKE
Amount: 0
Units: Process Upset
Quantity:
Cause: Equipment Failure
Source: Other Industrial Plant
Reason:
Sector: Chemical

---

64 | **44 of 100** | **NW/223.3** | **99.8 / 5.00** | **HERCULES CANADA** | **NEES**

BURLINGTON CITY ON

Incident Date: 4/28/88
Contaminant: SMOKE
Amount: 0
Units: Process Upset
Quantity:
Cause: Other
Source: Other Industrial Plant
Reason:
Sector: Chemical

---

64 | **45 of 100** | **NW/223.3** | **99.8 / 5.00** | **HERCULES CANADA** | **NEES**

BURLINGTON CITY ON

Incident Date: 7/31/88
Contaminant: SMOKE
Amount: 0
Units: Process Upset
Quantity:
Cause: Equipment Failure

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Source:		Other Industrial Plant			
Reason:					
Sector:		Chemical			

64	46 of 100	NW/223.3	99.8 / 5.00	HERCULES CANADA BURLINGTON CITY ON	NEES

Incident Date:	10/4/88
Contaminant:	RESIN, NATURAL
Amount:	3.6
Units:	Tonnes (Metric)
Quantity:	
Cause:	Valve, Fitting Leak
Source:	Other Industrial Plant
Reason:	Error
Sector:	Chemical

64	47 of 100	NW/223.3	99.8 / 5.00	HERCULES CANADA BURLINGTON CITY ON	NEES

Incident Date:	3/16/89
Contaminant:	LUBRICATING OIL
Amount:	0
Units:	Unknown
Quantity:	
Cause:	Error
Source:	Other Industrial Plant
Reason:	
Sector:	Chemical

64	48 of 100	NW/223.3	99.8 / 5.00	HERCULES CANADA BURLINGTON CITY ON	NEES

Incident Date:	3/16/89
Contaminant:	LUBRICATING OIL
Amount:	0
Units:	Valve, Fitting Leak
Quantity:	
Cause:	Negligence
Source:	Other Industrial Plant
Reason:	
Sector:	Chemical

64	49 of 100	NW/223.3	99.8 / 5.00	HERCULESCANADALTD BURLINGTON ON	NATE

File No.:	MOE76361
Reported By:	Province
Material Reaction:	
Spill Date:	760616
Lead Agency:	
Basin:	St. Lawrence River Drainage
Air:	
DOE on Scene:	
Land:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Fresh Water:	
Ground Water:	
Salt Water:	
Other Environment:	
Waterbody:	RAMBO CREEK
Cause:	Discharge
Reason:	Intent
Source:	Unknown
Sector:	Service Industry
Ship No.:	
Ship Name:	
Clean Up By:	none
Disposal Method:	none
Recovery %:	0.00
Act Invoked:	Unknown
Enforcement Resp:	
Fish Kill:	N
Oiled Birds:	N
Other Kill:	N
Vegetation Damage:	N
Property Damage:	N
Drinking Water:	N
Income Loss:	N
Other Consequences:	N
No. of Injuries:	
No. of Evacuations:	
Fine:	
No. of Dead:	
Cleanup Cost:	
Material:	other oil
Amount (ton):	
Volume (L):	
Concentration:	
Phase:	
Additional Info:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	50 of 100	NW/223.3	99.8 / 5.00	942 Brant Street Burlington ON L7R 2J7	EHS

Order No:	20071010017	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	CAN - Complete Report	**Client Prov/State:**	
Report Date:	10/19/2007	**Search Radius (km):**	0.3
Date Received:	10/10/2007	**X:**	-79.816071
Previous Site Name:		**Y:**	43.334607
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	51 of 100	NW/223.3	99.8 / 5.00	Hercules Canada (2002) Inc. 942 Brant Street Burlington Ontario L7R 2J7 Burlington ON	EBR

EBR Registry No:	IA03E1744	**Decision Posted:**	
Ministry Ref No:	5698-5RPQPK	**Exception Posted:**	
Notice Type:	Instrument Decision	**Section:**	
Notice Stage:		**Act 1:**	
Notice Date:	January 30, 2004	**Act 2:**	
Proposal Date:	November 27, 2003	**Site Location Map:**	
Year:	2003		
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)		
Off Instrument Name:			

Posted By:
Company Name: Hercules Canada (2002) Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 942 Brant Street, P.O. Box 100, Burlington Ontario, L7R 3X8
Comment Period:
URL:

Site Location Details:

942 Brant Street Burlington Ontario L7R 2J7 Burlington

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	52 of 100	NW/223.3	99.8 / 5.00	**Hercules Canada (2002) Inc.** **942 Brant Street Burlington Ontario L7R 3X8** **Burlington** **ON**	EBR

EBR Registry No: IA05E0512
Ministry Ref No: 6667-6BCSP7
Notice Type: Instrument Decision
Notice Stage:
Notice Date: March 24, 2006
Proposal Date: November 10, 2005
Year: 2005
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Hercules Canada (2002) Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 942 Brant Street, P.O. Box 100, Burlington Ontario, L7R 3X8
Comment Period:
URL:

Site Location Details:

942 Brant Street Burlington Ontario L7R 3X8 Burlington

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	53 of 100	NW/223.3	99.8 / 5.00	**Hercules Canada Inc.** **942 Brant Street** **Burlington ON L7R 2J7**	SPL

Ref No: 5161-5MEDHH
Year:
Incident Dt: 5/10/2003
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/10/2003
Dt Document Closed:
Site No:
Facility Name:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: HERCULES CANADA INC.
Site Address:
Site Region: Central
Municipality No:
Nature of Damage:
Discharger Report:
Material Group: Chemical
Health/Env Conseq:
Agency Involved:

Site Municipality:	Burlington
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	NA
Easting:	NA
Incident Cause:	Unknown
Incident Event:	
Environment Impact:	Possible
Nature of Impact:	Air Pollution
Contaminant Qty:	
System Facility Address:	
Client Name:	Hercules Canada Inc.
Client Type:	
Call Report Locatn Geodata:	
Contaminant Code:	27
Contaminant Name:	DOWTHERM
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Air
Receiving Environment:	
Incident Reason:	Unknown - Reason not determined
Incident Summary:	Hecules Canada - Unkn vol DowTherm-ATM
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Other Plant
SAC Action Class:	Spill to Air
Source Type:	

---

64 | ***54 of 100*** | ***NW/223.3*** | ***99.8 / 5.00*** | ***Hercules Canada Inc.***
942 Brant Street
Burlington ON L7R 2J7 | ***SPL***

Ref No:	0301-65WUGJ	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	10/19/2004	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	Chemical
MOE Reported Dt:	10/19/2004	***Health/Env Conseq:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
Facility Name:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	HERCULES CANADA INC.		
Site Address:			
Site Region:	Central		
Site Municipality:	Burlington		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:	NA		
Easting:	NA		
Incident Cause:	Valve / Fitting Leak Or Failure		
Incident Event:			
Environment Impact:	Not Anticipated		
Nature of Impact:			
Contaminant Qty:	454.545454545455 Kg		

System Facility Address:
Client Name: Hercules Canada Inc.
Client Type:
Call Report Locatn Geodata:
Contaminant Code: 27
Contaminant Name: SURFACTANT (N.O.S.)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Receiving Environment:
Incident Reason: Error- Operator error
Incident Summary: Hercules Can. - Oil Based Surfactant Spill
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Other Plant
SAC Action Class: Spill to Land
Source Type:

---

64 | ***55 of 100*** | ***NW/223.3*** | ***99.8 / 5.00*** | ***Hercules Canada Inc.***
942 Brant Street
Burlington ON L7R 2J7 | ***SPL***

Ref No: 1738-63X64V
Year:
Incident Dt: 8/16/2004
Dt MOE Arvl on Scn:
MOE Reported Dt: 8/16/2004
Dt Document Closed:
Site No:
Facility Name:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: HERCULES CANADA INC.
Site Address:
Site Region: Central
Site Municipality: Burlington
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: NA
Easting: NA
Incident Cause: Container Leak (Fuel Tank Barrels)
Incident Event:
Environment Impact:
Nature of Impact:
Contaminant Qty: 450 L
System Facility Address:
Client Name: Hercules Canada Inc.
Client Type:
Call Report Locatn Geodata:
Contaminant Code: 24
Contaminant Name: SOLVENT (N.O.S.)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Water
Receiving Environment:
Incident Reason: Error- Operator error

Municipality No:
Nature of Damage:
Discharger Report:
Material Group: Chemical
Health/Env Conseq:
Agency Involved:

Incident Summary: Hercules - 450 L of solvent to dyke.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:

---

64 | ***56 of 100*** | ***NW/223.3*** | ***99.8 / 5.00*** | ***Hercules Canada Inc.***
942 Brant Street
Burlington ON L7R 2J7 | ***SPL***

Ref No: 3030-62QJAU
Year:
Incident Dt: 7/9/2004
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/9/2004
Dt Document Closed:
Site No:
Facility Name:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: HERCULES CANADA INC.
Site Address:
Site Region: Central
Site Municipality: Burlington
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: NA
Easting: NA
Incident Cause: Overflow (Tanks Lagoons)
Incident Event:
Environment Impact: Possible
Nature of Impact: Soil Contamination
Contaminant Qty: 910 L
System Facility Address:
Client Name: Hercules Canada Inc.
Client Type:
Call Report Locatn Geodata:
Contaminant Code:
Contaminant Name: Embreak 2W570
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Receiving Environment:
Incident Reason: Unknown - Reason not determined
Incident Summary: Hercules Canada-200 gal spill of Embreak2W570
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Other
SAC Action Class: Spill to Land
Source Type:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group: Chemical
Health/Env Conseq:
Agency Involved:

---

64 | ***57 of 100*** | ***NW/223.3*** | ***99.8 / 5.00*** | ***942 Brant Street***
942 Brant Street | ***SPL***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Burlington ON	

Ref No: 0206-6M9VBZ
Year:
Incident Dt: 2/22/2006
Dt MOE Arvl on Scn:
MOE Reported Dt: 2/22/2006
Dt Document Closed:
Site No:
Facility Name:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: 942 Brant Street
Site Address: 942 Brant Street
Site Region:
Site Municipality: Burlington
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting: NA
Incident Cause:
Incident Event:
Environment Impact: Possible
Nature of Impact:
Contaminant Qty: Not specified m3
System Facility Address:
Client Name:
Client Type:
Call Report Locatn Geodata:
Contaminant Code: 31
Contaminant Name: SMOKE
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Receiving Environment:
Incident Reason: Unknown - Reason not determined
Incident Summary: Hercules Canada: orange/brown cloud to atm, unknown
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type: Other Plant

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	58 of 100	NW/223.3	99.8 / 5.00	**Hercules Canada Inc.** **942 Brant St. Burlington** **Burlington ON L7R 2J7**	SPL

Ref No: 7808-7FXN2Y
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 6/25/2008
Dt Document Closed: 6/27/2008
Site No:
Facility Name:
MOE Response: No Field Response

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: Hercules Canada Inc<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality: Burlington
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause:
Incident Event:
Environment Impact: Possible
Nature of Impact: Soil Contamination
Contaminant Qty: 80 kg
System Facility Address:
Client Name: Hercules Canada Inc.
Client Type:
Call Report Locatn Geodata:
Contaminant Code: 22
Contaminant Name: SODIUM HYDROXIDE (SOL'N) (CAUSTIC SODA)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Receiving Environment:
Incident Reason:
Incident Summary: Hercules Can, leaking trailer Sodium Hydroxide sol'n
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Tank Truck
SAC Action Class: Land Spills
Source Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	59 of 100	NW/223.3	99.8 / 5.00	Hercules Canada Inc. 942 Brant St Burlington; Burlington ON L7R 2J7	SPL

Ref No: 5462-7HGS6Y
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 8/13/2008
Dt Document Closed: 8/25/2008
Site No:
Facility Name:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel; Halton-Peel
Nearest Watercourse:
Site Name: Brant Street from Dundas Street to Fairview Street<UNOFFICIAL>; 942 Brant Street
Site Address:
Site Region:
Site Municipality: Burlington; Burlington
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved:

Northing:	NA
Easting:	NA
Incident Cause:	Other Discharges
Incident Event:	
Environment Impact:	Confirmed
Nature of Impact:	Other Impact(s); Soil Contamination
Contaminant Qty:	205 L
System Facility Address:	
Client Name:	Hercules Canada Inc.
Client Type:	
Call Report Locatn Geodata:	
Contaminant Code:	13
Contaminant Name:	HYDROCARBON LIGHT
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Receiving Environment:	
Incident Reason:	
Incident Summary:	Jump Logistics: drum of slippery oil to ground, road, plant
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Other Motor Vehicle
SAC Action Class:	Land Spills
Source Type:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	60 of 100	NW/223.3	99.8 / 5.00	**Hercules Canada (2002) Inc.** **942 Brant Street** **Burlington ON**	CA

Certificate #:	5682-5K6Q99
Application Year:	2003
Issue Date:	3/20/2003
Approval Type:	Industrial Sewage Works
Status:	Revoked and/or Replaced
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	61 of 100	NW/223.3	99.8 / 5.00	**Hercules Canada (2002) Inc.** **942 Brant Street** **Burlington ON**	CA

Certificate #:	6136-5VFMR3
Application Year:	2004
Issue Date:	1/28/2004
Approval Type:	Air
Status:	Revoked and/or Replaced
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	62 of 100	NW/223.3	99.8 / 5.00	Hercules Canada (2002) Inc. 942 Brant Street Burlington ON	CA

Certificate #: 6293-587JMD
Application Year: 2002
Issue Date: 11/8/2002
Approval Type: Air
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	63 of 100	NW/223.3	99.8 / 5.00	Hercules Canada (2002) Inc. 942 Brant Street Burlington ON	CA

Certificate #: 7123-6H3JVY
Application Year: 2006
Issue Date: 3/3/2006
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	64 of 100	NW/223.3	99.8 / 5.00	Hercules Canada (2002) Inc. 942 Brant Street Burlington ON	CA

Certificate #: 8-300-064-77-776
Application Year: 2002
Issue Date: 11/8/2002
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	65 of 100	NW/223.3	99.8 / 5.00	Hercules Canada (2002) Inc. 942 Brant Street Burlington ON	CA

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Certificate #: 8-3062-83-006
Application Year: 2002
Issue Date: 11/8/2002
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

64 | ***66 of 100*** | ***NW/223.3*** | ***99.8 / 5.00*** | ***Hercules Canada (2002) Inc.***
942 Brant Street
Burlington ON | ***CA***

Certificate #: 8413-5JRKW4
Application Year: 2003
Issue Date: 12/4/2003
Approval Type: Air
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

64 | ***67 of 100*** | ***NW/223.3*** | ***99.8 / 5.00*** | ***Hercules Canada (2002) Inc.***
942 Brant Street
Burlington ON | ***CA***

Certificate #: 8413-5JRKW4
Application Year: 2003
Issue Date: 5/23/2003
Approval Type: Air
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

64 | ***68 of 100*** | ***NW/223.3*** | ***99.8 / 5.00*** | ***Ashland Canada Corp.***
942 Brant Street Burlington, Regional Municipality of Halton L7R 2J7 CITY OF BURLINGTON
ON | ***EBR***

EBR Registry No: 011-3757
Ministry Ref No: 4643-8H2J58
Notice Type: Instrument Decision
Notice Stage:
Decision Posted:
Exception Posted:
Section:
Act 1:

Notice Date: September 13, 2012
Proposal Date: June 06, 2011
Year: 2011
Act 2:
Site Location Map:
Instrument Type: (EPA Part II.1-air) - Environmental Compliance Approval (project type: air)
Off Instrument Name:
Posted By:
Company Name: Ashland Canada Corp.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 942 Brant Street, Post Office Box Delivery 100, Burlington Ontario, Canada L7R 3X8
Comment Period:
URL:

Site Location Details:

942 Brant Street Burlington, Regional Municipality of Halton L7R 2J7 CITY OF BURLINGTON

---

64 | ***69 of 100*** | ***NW/223.3*** | ***99.8 / 5.00*** | ***Ashland Canada Corp.***
942 BRANT STREET
BURLINGTON ON | ***GEN***

Generator No: ON0096300
SIC Code: 325999
SIC Description: All Other Miscellaneous Chemical Product Manufacturing
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 211

Waste Class Name: AROMATIC SOLVENTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

64 | ***70 of 100*** | ***NW/223.3*** | ***99.8 / 5.00*** | ***Ashland Canada Corp.***
942 Brant St Ashland
Burlington ON L7R 2J7 | ***ECA***

Approval No: 3448-8PJRH9
Approval Date: 9/7/2012
Status: Approved
Record Type:
Link Source:
SWP Area Name:
Approval Type:
Project Type: Air/Noise
Business Name:
Address:
Full Address:
Full PDF Link:
PDF Site Location:

MOE District:
City: Burlington
Longitude:
Latitude:
Geometry X:
Geometry Y:

---

64 | ***71 of 100*** | ***NW/223.3*** | ***99.8 / 5.00*** | ***Ashland Canada Corp.***
942 BRANT STREET
BURLINGTON ON | ***GEN***

Generator No: ON0096300
SIC Code: 325999
SIC Description: All Other Miscellaneous Chemical Product Manufacturing
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	72 of 100	NW/223.3	99.8 / 5.00	Ashland Canada Corp. 942 BRANT STREET BURLINGTON ON	GEN

Generator No: ON0096300
SIC Code: 325999
SIC Description: All Other Miscellaneous Chemical Product Manufacturing
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 268
Waste Class Name: AMINES

64	***73 of 100***	***NW/223.3***	***99.8 / 5.00***	***Ashland Canada Corp.*** ***942 BRANT STREET*** ***BURLINGTON ON L7R 3X8***	***GEN***

Generator No: ON0096300
SIC Code: 325999
SIC Description: All Other Miscellaneous Chemical Product Manufacturing
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	74 of 100	NW/223.3	99.8 / 5.00	ASHLAND 942 BRANT ST BURLINGTON ON L7R2J7	CHM

Headcode: 00273600
Headcode Desc: CHEMICALS
Phone: 9056327861

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
List Name:					
Description:					

64	75 of 100	NW/223.3	99.8 / 5.00	942 Brant Street Burlington ON	EHS

Order No:	20130910026	Nearest Intersection:	
Status:	C	Municipality:	
Report Type:	Custom Report	Client Prov/State:	ON
Report Date:	19-SEP-13	Search Radius (km):	.25
Date Received:	10-SEP-13	X:	-79.816515
Previous Site Name:		Y:	43.333775
Lot/Building Size:			
Additional Info Ordered:			

64	76 of 100	NW/223.3	99.8 / 5.00	942 Brant Burlington ON L7RSJ7	EHS

Order No:	20140408002	Nearest Intersection:	
Status:	C	Municipality:	
Report Type:	Site Report	Client Prov/State:	NY
Report Date:	09-APR-14	Search Radius (km):	.001
Date Received:	08-APR-14	X:	-79.816262
Previous Site Name:		Y:	43.334487
Lot/Building Size:			
Additional Info Ordered:			

64	77 of 100	NW/223.3	99.8 / 5.00	Solenis Canada ULC 942 BRANT STREET BURLINGTON ON	GEN

Generator No:	ON0096300
SIC Code:	325999
SIC Description:	ALL OTHER MISCELLANEOUS CHEMICAL PRODUCT MANUFACTURING
Approval Years:	2013
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	268
Waste Class Name:	AMINES
Waste Class:	122
Waste Class Name:	ALKALINE WASTES - OTHER METALS
Waste Class:	331
Waste Class Name:	WASTE COMPRESSED GASES
Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES
Waste Class:	270
Waste Class Name:	OTHER SPECIFIED ORGANICS

Waste Class: 135
Waste Class Name: REACTIVE ANION WASTES

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 123
Waste Class Name: ALKALINE PHOSPHATES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 114
Waste Class Name: OTHER INORGANIC ACID WASTES

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 266
Waste Class Name: PHENOLIC WASTES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

64 | **78 of 100** | **NW/223.3** | **99.8 / 5.00** | **Solenis Canada ULC**
942 Brant St
Burlington ON L7R 2J7 | **SPL**

Ref No: 4083-ACNTLM
Year:
Incident Dt: 2016/08/09
Dt MOE Arvl on Scn:
MOE Reported Dt: 2016/08/09
Dt Document Closed:
Site No: 7401-9Z9HDK
Facility Name:
MOE Response: No
Site County/District:
Site Geo Ref Meth: 1-10 metres eg. Good Quality GPS
Site District Office:
Nearest Watercourse:
Site Name: Solenis Canada ULC
Site Address: 942 Brant St
Site Region:
Site Municipality: Burlington
Site Lot:
Site Conc:
Site Geo Ref Accu: GPS
Site Map Datum: NAD83
Northing: 4798181
Easting: 596379
Incident Cause:
Incident Event: Operator/Human error
Environment Impact:
Nature of Impact:
Contaminant Qty: 4000 kg
System Facility Address:
Client Name: Solenis Canada ULC
Client Type:
Call Report Locatn Geodata:
Contaminant Code: 15
Contaminant Name: PARAFFINIC OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Receiving Environment: Land
Incident Reason: Operator/Human Error
Incident Summary: Solenis: 4000 kg of Parrafinic oil to concrete/soil: contd & clng
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Industrial
SAC Action Class: Land Spills
Source Type:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	79 of 100	NW/223.3	99.8 / 5.00	Hercules Canada (2002) Inc. 942 Brant St Burlington ON L7R 3X8	ECA

Approval No:	5682-5K6Q99	**MOE District:**	Halton-Peel
Approval Date:	2003-03-20	**City:**	
Status:	Revoked and/or Replaced	**Longitude:**	-79.81651
Record Type:	ECA	**Latitude:**	43.337975
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Halton	**Geometry Y:**	
Approval Type:	ECA-INDUSTRIAL SEWAGE WORKS		
Project Type:	INDUSTRIAL SEWAGE WORKS		
Business Name:	Hercules Canada (2002) Inc.		
Address:	942 Brant St		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/4932-5DNM6X-14.pdf		
PDF Site Location:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	80 of 100	NW/223.3	99.8 / 5.00	Hercules Canada (2002) Inc. 942 Brant Street Burlington ON L7R 3X8	ECA

Approval No:	8413-5JRKW4	**MOE District:**	Halton-Peel
Approval Date:	2003-11-27	**City:**	
Status:	Revoked and/or Replaced	**Longitude:**	-79.81117
Record Type:	ECA	**Latitude:**	43.33029
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Halton	**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	Hercules Canada (2002) Inc.		
Address:	942 Brant Street		
Full Address:			
Full PDF Link:			
PDF Site Location:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	81 of 100	NW/223.3	99.8 / 5.00	Hercules Canada Inc. 942 Brant St Burlington ON L7R 3X8	ECA

Approval No:	2119-4ZENQD	**MOE District:**	Halton-Peel
Approval Date:	2002-03-13	**City:**	
Status:	Revoked and/or Replaced	**Longitude:**	-79.81651
Record Type:	ECA	**Latitude:**	43.337975
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Halton	**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	Hercules Canada Inc.		
Address:	942 Brant St		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/6413-4YZPUV-14.pdf		
PDF Site Location:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	82 of 100	NW/223.3	99.8 / 5.00	Hercules Canada 942 Brant St Burlington ON L7R 3X8	ECA

Approval No:	8-300-064-77-776	**MOE District:**	Halton-Peel
Approval Date:	2000-12-08	**City:**	
Status:	Approved	**Longitude:**	-79.81651

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Hercules Canada
Address: 942 Brant St
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7070-4QQMRA-14.pdf
PDF Site Location:
Latitude: 43.337975
Geometry X:
Geometry Y:

---

64 | **83 of 100** | **NW/223.3** | **99.8 / 5.00**

Hercules Canada (2002) Inc.
942 Brant St
Burlington ON L6H 5R7

ECA

Approval No: 6293-587JMD
Approval Date: 2002-11-08
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Hercules Canada (2002) Inc.
Address: 942 Brant St
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/8663-5C3JFG-14.pdf
PDF Site Location:
MOE District: Halton-Peel
City:
Longitude: -79.81651
Latitude: 43.337975
Geometry X:
Geometry Y:

---

64 | **84 of 100** | **NW/223.3** | **99.8 / 5.00**

Hercules Canada Inc.
942 Brant St
Burlington ON L7R 3X8

ECA

Approval No: 6293-587JMD
Approval Date: 2002-03-13
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Hercules Canada Inc.
Address: 942 Brant St
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3849-586TRU-14.pdf
PDF Site Location:
MOE District: Halton-Peel
City:
Longitude: -79.81651
Latitude: 43.337975
Geometry X:
Geometry Y:

---

64 | **85 of 100** | **NW/223.3** | **99.8 / 5.00**

Hercules Canada Inc.
942 Brant St
Burlington ON L7R 3X8

ECA

Approval No: 1976-579RVZ
Approval Date: 2002-03-13
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Hercules Canada Inc.
MOE District: Halton-Peel
City:
Longitude: -79.81651
Latitude: 43.337975
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Address: 942 Brant St
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2444-574K7S-14.pdf
PDF Site Location:

---

64 | **86 of 100** | **NW/223.3** | **99.8 / 5.00** | **Hercules Canada (2002) Inc.**
942 Brant Street
Burlington ON L7R 3X8 | **ECA**

Approval No: 7123-6H3JVY
Approval Date: 2006-03-03
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
MOE District: Halton-Peel
City:
Longitude: -79.81117
Latitude: 43.33029
Geometry X:
Geometry Y:
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Hercules Canada (2002) Inc.
Address: 942 Brant Street
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/6667-6BCSP7-14.pdf
PDF Site Location:

---

64 | **87 of 100** | **NW/223.3** | **99.8 / 5.00** | **Hercules Canada (2002) Inc.**
942 Brant Street
Burlington ON L7R 3X8 | **ECA**

Approval No: 6136-5VFMR3
Approval Date: 2004-01-28
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
MOE District: Halton-Peel
City:
Longitude: -79.80659
Latitude: 43.331657
Geometry X:
Geometry Y:
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Hercules Canada (2002) Inc.
Address: 942 Brant Street
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/5698-5RPQPK-14.pdf
PDF Site Location:

---

64 | **88 of 100** | **NW/223.3** | **99.8 / 5.00** | **Hercules Canada (2002) Inc.**
942 Brant St
Burlington ON L6H 5R7 | **ECA**

Approval No: 8-300-064-77-776
Approval Date: 2002-11-08
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
MOE District: Halton-Peel
City:
Longitude: -79.81651
Latitude: 43.337975
Geometry X:
Geometry Y:
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Hercules Canada (2002) Inc.
Address: 942 Brant St
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7484-5C3LC8-14.pdf
PDF Site Location:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	89 of 100	NW/223.3	99.8 / 5.00	Hercules Canada (2002) Inc. 942 Brant Street Burlington ON L7R 3X8	ECA

Approval No:	8413-5JRKW4	**MOE District:**	Halton-Peel
Approval Date:	2003-12-04	**City:**	
Status:	Revoked and/or Replaced	**Longitude:**	-79.81117
Record Type:	ECA	**Latitude:**	43.33029
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Halton	**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	Hercules Canada (2002) Inc.		
Address:	942 Brant Street		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/6535-5TUTRG-14.pdf		
PDF Site Location:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	90 of 100	NW/223.3	99.8 / 5.00	Hercules Canada (2002) Inc. 942 Brant St Burlington ON L7R 3X8	ECA

Approval No:	8413-5JRKW4	**MOE District:**	Halton-Peel
Approval Date:	2003-05-23	**City:**	
Status:	Revoked and/or Replaced	**Longitude:**	-79.81651
Record Type:	ECA	**Latitude:**	43.337975
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Halton	**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	Hercules Canada (2002) Inc.		
Address:	942 Brant St		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/3329-5FENN3-14.pdf		
PDF Site Location:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	91 of 100	NW/223.3	99.8 / 5.00	Hercules Canada Inc. 942 Brant St Burlington ON L7R 3X8	ECA

Approval No:	8-3062-83-006	**MOE District:**	Halton-Peel
Approval Date:	2000-11-06	**City:**	
Status:	Approved	**Longitude:**	-79.81651
Record Type:	ECA	**Latitude:**	43.337975
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Halton	**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	Hercules Canada Inc.		
Address:	942 Brant St		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/3058-4QAHW5-14.pdf		
PDF Site Location:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	92 of 100	NW/223.3	99.8 / 5.00	Ashland Canada Corp. 942 Brant St Ashland Burlington ON L7R 3X8	ECA

Approval No:	3448-8PJRH9	**MOE District:**	Halton-Peel
Approval Date:	2012-09-07	**City:**	
Status:	Approved	**Longitude:**	-79.81117

Record Type:	ECA	**Latitude:**	43.33029
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Halton	**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	Ashland Canada Corp.		
Address:	942 Brant St Ashland		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/4643-8H2J58-14.pdf		
PDF Site Location:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	93 of 100	NW/223.3	99.8 / 5.00	**Hercules Canada (2002) Inc.** **942 Brant St** **Burlington ON L6H 5R7**	ECA

Approval No:	8-3062-83-006	**MOE District:**	Halton-Peel
Approval Date:	2002-11-08	**City:**	
Status:	Approved	**Longitude:**	-79.81651
Record Type:	ECA	**Latitude:**	43.337975
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Halton	**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	Hercules Canada (2002) Inc.		
Address:	942 Brant St		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/7745-5C3JXK-14.pdf		
PDF Site Location:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	94 of 100	NW/223.3	99.8 / 5.00	**Solenis Canada ULC** **942 BRANT STREET** **BURLINGTON ON L7R 3X8**	GEN

Generator No:	ON0096300
SIC Code:	325999
SIC Description:	ALL OTHER MISCELLANEOUS CHEMICAL PRODUCT MANUFACTURING
Approval Years:	2016
PO Box No:	
Country:	Canada
Status:	
Co Admin:	James Faulstich
Choice of Contact:	CO_OFFICIAL
Phone No Admin:	8046298299 Ext.
Contaminated Facility:	No
MHSW Facility:	No

Detail(s)

Waste Class:	113
Waste Class Name:	ACID WASTE - OTHER METALS
Waste Class:	265
Waste Class Name:	GRAPHIC ART WASTES
Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS
Waste Class:	263
Waste Class Name:	ORGANIC LABORATORY CHEMICALS
Waste Class:	135

Waste Class Name: REACTIVE ANION WASTES

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 123
Waste Class Name: ALKALINE PHOSPHATES

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 114
Waste Class Name: OTHER INORGANIC ACID WASTES

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 266
Waste Class Name: PHENOLIC WASTES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 331

Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

64 | ***95 of 100*** | ***NW/223.3*** | ***99.8 / 5.00*** | ***Solenis Canada ULC***
942 BRANT STREET
BURLINGTON ON L7R 3X8 | ***GEN***

Generator No: ON0096300
SIC Code: 325999
SIC Description: ALL OTHER MISCELLANEOUS CHEMICAL PRODUCT MANUFACTURING
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: James Faulstich
Choice of Contact: CO_OFFICIAL
Phone No Admin: 8046298299 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 114
Waste Class Name: OTHER INORGANIC ACID WASTES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 221

Waste Class Name:	LIGHT FUELS
Waste Class:	123
Waste Class Name:	ALKALINE PHOSPHATES
Waste Class:	241
Waste Class Name:	HALOGENATED SOLVENTS
Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS
Waste Class:	266
Waste Class Name:	PHENOLIC WASTES
Waste Class:	270
Waste Class Name:	OTHER SPECIFIED ORGANICS
Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES
Waste Class:	122
Waste Class Name:	ALKALINE WASTES - OTHER METALS
Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS
Waste Class:	265
Waste Class Name:	GRAPHIC ART WASTES
Waste Class:	112
Waste Class Name:	ACID WASTE - HEAVY METALS
Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS
Waste Class:	146
Waste Class Name:	OTHER SPECIFIED INORGANICS
Waste Class:	262
Waste Class Name:	DETERGENTS/SOAPS
Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES
Waste Class:	113
Waste Class Name:	ACID WASTE - OTHER METALS
Waste Class:	253
Waste Class Name:	EMULSIFIED OILS
Waste Class:	242
Waste Class Name:	HALOGENATED PESTICIDES
Waste Class:	211
Waste Class Name:	AROMATIC SOLVENTS
Waste Class:	135
Waste Class Name:	REACTIVE ANION WASTES
Waste Class:	267
Waste Class Name:	ORGANIC ACIDS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	96 of 100	NW/223.3	99.8 / 5.00	***Solenis Canada ULC*** ***942 BRANT STREET*** ***BURLINGTON ON L7R 2J7***	***GEN***

Generator No: ON0096300
SIC Code: 325999
SIC Description: ALL OTHER MISCELLANEOUS CHEMICAL PRODUCT MANUFACTURING
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Kara Long
Choice of Contact: CO_OFFICIAL
Phone No Admin: 614-790-4641 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 114
Waste Class Name: OTHER INORGANIC ACID WASTES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 266
Waste Class Name: PHENOLIC WASTES

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 112

Waste Class Name:	ACID WASTE - HEAVY METALS
Waste Class:	232
Waste Class Name:	POLYMERIC RESINS
Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES
Waste Class:	123
Waste Class Name:	ALKALINE PHOSPHATES
Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS
Waste Class:	135
Waste Class Name:	REACTIVE ANION WASTES
Waste Class:	241
Waste Class Name:	HALOGENATED SOLVENTS
Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES
Waste Class:	269
Waste Class Name:	NON-HALOGENATED PESTICIDES
Waste Class:	222
Waste Class Name:	HEAVY FUELS
Waste Class:	243
Waste Class Name:	PCBS
Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS
Waste Class:	265
Waste Class Name:	GRAPHIC ART WASTES
Waste Class:	268
Waste Class Name:	AMINES
Waste Class:	270
Waste Class Name:	OTHER SPECIFIED ORGANICS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	97 of 100	NW/223.3	99.8 / 5.00	***Solenis Canada ULC*** ***942 BRANT STREET*** ***BURLINGTON ON L7R 3X8***	GEN

Generator No:	ON0096300
SIC Code:	
SIC Description:	
Approval Years:	As of Dec 2018
PO Box No:	100
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	112 C

Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 112 L
Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 122 L
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 L
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 T
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 213 L
Waste Class Name: Petroleum distillates

Waste Class: 213 T
Waste Class Name: Petroleum distillates

Waste Class: 233 L
Waste Class Name: Other polymeric wastes

Waste Class: 241 L
Waste Class Name: Halogenated solvents and residues

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 262 C
Waste Class Name: Detergents and soaps

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Class: 263 C
Waste Class Name: Misc. waste organic chemicals

Waste Class: 263 I

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Name: Misc. waste organic chemicals

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 263 T
Waste Class Name: Misc. waste organic chemicals

Waste Class: 265 L
Waste Class Name: Graphic arts wastes

Waste Class: 267 C
Waste Class Name: Organic acids

Waste Class: 267 L
Waste Class Name: Organic acids

Waste Class: 268 C
Waste Class Name: Amines

Waste Class: 268 I
Waste Class Name: Amines

Waste Class: 268 L
Waste Class Name: Amines

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

64	98 of 100	NW/223.3	99.8 / 5.00	**Solenis Canada ULC** **942 BRANT STREET** **BURLINGTON ON L7R 2J7**	GEN

Generator No: ON0096300
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241 L
Waste Class Name: Halogenated solvents and residues

Waste Class: 213 L
Waste Class Name: Petroleum distillates

Waste Class: 262 C
Waste Class Name: Detergents and soaps

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 268 I

Waste Class Name: Amines

Waste Class: 122 L
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 263 T
Waste Class Name: Misc. waste organic chemicals

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 268 C
Waste Class Name: Amines

Waste Class: 233 L
Waste Class Name: Other polymeric wastes

Waste Class: 148 L
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 267 C
Waste Class Name: Organic acids

Waste Class: 268 L
Waste Class Name: Amines

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 112 L
Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 267 L
Waste Class Name: Organic acids

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 213 T
Waste Class Name: Petroleum distillates

Waste Class: 263 C
Waste Class Name: Misc. waste organic chemicals

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 265 L
Waste Class Name: Graphic arts wastes

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Class: 251 L

Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 T
Waste Class Name: Misc. wastes and inorganic chemicals

---

64 | ***99 of 100*** | ***NW/223.3*** | ***99.8 / 5.00*** | ***Solenis Canada ULC***
942 BRANT STREET
BURLINGTON ON L7R 2J7 | ***GEN***

Generator No: ON0096300
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 112 L
Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 263 T
Waste Class Name: Misc. waste organic chemicals

Waste Class: 213 T
Waste Class Name: Petroleum distillates

Waste Class: 241 L
Waste Class Name: Halogenated solvents and residues

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 122 L
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 148 C

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Name:	Misc. wastes and inorganic chemicals
Waste Class:	148 L
Waste Class Name:	Misc. wastes and inorganic chemicals
Waste Class:	263 C
Waste Class Name:	Misc. waste organic chemicals
Waste Class:	148 T
Waste Class Name:	Misc. wastes and inorganic chemicals
Waste Class:	263 I
Waste Class Name:	Misc. waste organic chemicals
Waste Class:	213 I
Waste Class Name:	Petroleum distillates
Waste Class:	268 C
Waste Class Name:	Amines
Waste Class:	267 L
Waste Class Name:	Organic acids
Waste Class:	112 C
Waste Class Name:	Acid solutions - containing heavy metals
Waste Class:	122 C
Waste Class Name:	Alkaline slutions - containing other metals and non-metals (not cyanide)
Waste Class:	213 L
Waste Class Name:	Petroleum distillates
Waste Class:	233 L
Waste Class Name:	Other polymeric wastes
Waste Class:	268 I
Waste Class Name:	Amines
Waste Class:	262 L
Waste Class Name:	Detergents and soaps
Waste Class:	145 L
Waste Class Name:	Wastes from the use of pigments, coatings and paints
Waste Class:	262 C
Waste Class Name:	Detergents and soaps
Waste Class:	251 L
Waste Class Name:	Waste oils/sludges (petroleum based)
Waste Class:	268 L
Waste Class Name:	Amines
Waste Class:	267 C
Waste Class Name:	Organic acids
Waste Class:	252 L
Waste Class Name:	Waste crankcase oils and lubricants
Waste Class:	212 L
Waste Class Name:	Aliphatic solvents and residues

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	*100 of 100*	*NW/223.3*	*99.8 / 5.00*	***Solenis Canada ULC*** ***942 BRANT STREET*** ***BURLINGTON ON L7R 2J7***	*GEN*

Generator No: ON0096300
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 233 L
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 122 C
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 268 C
Waste Class Name: AMINES

Waste Class: 213 T
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 148 C
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 268 L
Waste Class Name: AMINES

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 263 C
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 112 L
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 148 L
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 268 I
Waste Class Name: AMINES

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 263 I
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 112 C

Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 145 L
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 267 L
Waste Class Name: ORGANIC ACIDS

Waste Class: 262 L
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 263 T
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 148 T
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 213 L
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 241 L
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 263 L
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 212 I
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 267 C
Waste Class Name: ORGANIC ACIDS

Waste Class: 213 I
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 148 I
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 262 C
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 122 L
Waste Class Name: ALKALINE WASTES - OTHER METALS

---

65 | ***1 of 6*** | ***NNW/230.8*** | ***98.9 / 4.08*** | ***1881 FAIRVIEW STREET BURLINGTON ON L7S 2K4*** | ***EHS***

Order No: 20090714002
Status: C
Report Type: Standard Select Report
Report Date: 7/22/2009
Date Received: 7/14/2009
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Aerial Photos

Nearest Intersection: FAIRVIEW STREET & BRANT STREET
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.814462
Y: 43.335094

---

65 | ***2 of 6*** | ***NNW/230.8*** | ***98.9 / 4.08*** | ***Michaels Stores, Inc. 1881 Fairview St Burlington ON*** | ***GEN***

Generator No: ON9856459
SIC Code: 451130
SIC Description: SEWING, NEEDLEWORK AND PIECE GOODS STORES

Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

---

65 | ***3 of 6*** | ***NNW/230.8*** | ***98.9 / 4.08*** | ***Michaels Stores, Inc.***
1881 Fairview St
Burlington ON L7S 2K4 | ***GEN***

Generator No: ON9856459
SIC Code: 451130
SIC Description: SEWING, NEEDLEWORK AND PIECE GOODS STORES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: James Williams
Choice of Contact: CO_OFFICIAL
Phone No Admin: (647)288-3298 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

---

65 | ***4 of 6*** | ***NNW/230.8*** | ***98.9 / 4.08*** | ***Michaels Stores, Inc.***
1881 Fairview St
Burlington ON L7S 2K4 | ***GEN***

Generator No: ON9856459
SIC Code: 451130
SIC Description: SEWING, NEEDLEWORK AND PIECE GOODS STORES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: James Williams
Choice of Contact: CO_OFFICIAL
Phone No Admin: (647)288-3298 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

---

65 | ***5 of 6*** | ***NNW/230.8*** | ***98.9 / 4.08*** | ***Michaels Stores, Inc.***
1881 Fairview St
Burlington ON L7S 2K4 | ***GEN***

Generator No: ON9856459
SIC Code: 451130
SIC Description: SEWING, NEEDLEWORK AND PIECE GOODS STORES

Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: James Williams
Choice of Contact: CO_OFFICIAL
Phone No Admin: (647)288-3298 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

65 | ***6 of 6*** | ***NNW/230.8*** | ***98.9 / 4.08*** | ***Michaels Stores, Inc.***
1881 Fairview St
Burlington ON L7S 2K4 | ***GEN***

Generator No: ON9856459
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 148 A
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 L
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Class: 263 A
Waste Class Name: Misc. waste organic chemicals

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 331 L
Waste Class Name: Waste compressed gases including cylinders

---

66 | **1 of 1** | **SE/231.8** | **92.8 / -2.00** | **770 Hager Ave Burlington ON L7S1X1** | **EHS**

Order No: 20170214159
Status: C
Report Type: Standard Report
Report Date: 20-FEB-17
Date Received: 14-FEB-17
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.81147
Y: 43.330413

---

67 | **1 of 1** | **NNE/238.8** | **94.8 / 0.00** | **850 BRANT ST Burlington ON** | **WWIS**

Well ID: 7330857
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z287724
Tag: A242664
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 04/01/2019
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7609
Form Version: 7
Owner:
County: HALTON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 02/15/2019
Year Completed: 2019
Depth (m): 4.75
Latitude: 43.3352649030869
Longitude: -79.8126192103432
Path:

Bore Hole Information

Bore Hole ID: 1007413112
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 02/15/2019
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 596254.00
North83: 4798731.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1007835437
Layer: 3
Color: 2
General Color: GREY
Mat1: 34
Most Common Material: TILL
Mat2: 06
Mat2 Desc: SILT
Mat3: 84
Mat3 Desc: SILTY
Formation Top Depth: 3.049999952316284
Formation End Depth: 4.75
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007835435
Layer: 1
Color:
General Color:
Mat1: 01
Most Common Material: FILL
Mat2: 28
Mat2 Desc: SAND
Mat3: 81
Mat3 Desc: SANDY
Formation Top Depth: 0.0

Formation End Depth: 1.2200000286102295
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007835436
Layer: 2
Color: 7
General Color: RED
Mat1: 34
Most Common Material: TILL
Mat2: 06
Mat2 Desc: SILT
Mat3: 84
Mat3 Desc: SILTY
Formation Top Depth: 1.2200000286102295
Formation End Depth: 3.049999952316284
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007836411
Layer: 1
Plug From: 0.0
Plug To: 1.2200000286102295
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1007837890
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1007834304
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007838054
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.5199999809265137
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1007838601
Layer: 1
Slot: 10

Screen Top Depth:	1.5199999809265137
Screen End Depth:	4.75
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.0

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1007839322
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1007837205
Diameter:	10.199999809265137
Depth From:	0.0
Depth To:	4.75
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	1007413112	**Tag No:**	A242664
Depth M:	4.75	**Contractor:**	7609
Year Completed:	2019	**Latitude:**	43.3352649030869
Well Completed Dt:	02/15/2019	**Longitude:**	-79.8126192103432
Audit No:	Z287724	**Y:**	43.33526490068123
Path:	733\7330857.pdf	**X:**	-79.81261906146982

---

68 ***1 of 1*** ***E/244.0*** ***91.8 / -3.00*** ***ON*** ***WWIS***

Well ID:	7369392	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	10/05/2020
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z341750	**Contractor:**	7644
Tag:	A297604	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	

Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008484022	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596527.00
Code OB Desc:		**North83:**	4798496.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	09/04/2020	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008484022	**Tag No:**	A297604
Depth M:		**Contractor:**	7644
Year Completed:	2020	**Latitude:**	43.3331142804957
Well Completed Dt:	09/04/2020	**Longitude:**	-79.8092935601753
Audit No:	Z341750	**Y:**	43.33311427738601
Path:	736\7369392.pdf	**X:**	-79.80929341149609

---

69 | ***1 of 1*** | ***ENE/246.9*** | ***92.1 / -2.76*** | ***ON*** | ***BORE***

Borehole ID:	621029	**Inclin FLG:**	No
OGF ID:	215521483	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	APR-1967	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.334262
Total Depth m:	-999	**Longitude DD:**	-79.810042
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	596465
Drill Method:	Power auger	**Northing:**	4798623
Orig Ground Elev m:	92.3	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	92.3		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218419502	**Mat Consistency:**	Stiff

Top Depth:	1.4	**Material Moisture:**	
Bottom Depth:	2.3	**Material Texture:**	
Material Color:	Green	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Gravel	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND,GRAVEL. GREEN,STIFF,AGE GLACIAL.		

Geology Stratum ID:	218419506	**Mat Consistency:**	
Top Depth:	4.6	**Material Moisture:**	
Bottom Depth:		**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Refusal	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	REFUSAL OF ENTRY. 0001500800047013000750600009806000147300000042 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218419501	**Mat Consistency:**	Firm
Top Depth:	.5	**Material Moisture:**	
Bottom Depth:	1.4	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND,CLAY. BROWN,FIRM,AGE GLACIAL.		

Geology Stratum ID:	218419500	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.5	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Soil	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SOIL. AGE POST-GLACIAL.		

Geology Stratum ID:	218419503	**Mat Consistency:**	Dense
Top Depth:	2.3	**Material Moisture:**	
Bottom Depth:	3	**Material Texture:**	
Material Color:	Green	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND. GREEN,VERY DENSE,AGE GLACIAL.		

Geology Stratum ID:	218419504	**Mat Consistency:**	Dense
Top Depth:	3	**Material Moisture:**	
Bottom Depth:	4.5	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Gravel	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,GRAVEL,SAND. RED,VERY DENSE,AGE GLACIAL.		

Geology Stratum ID:	218419505	**Mat Consistency:**	Dense
Top Depth:	4.5	**Material Moisture:**	
Bottom Depth:	4.6	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. RED,WEATHERED,VERY DENSE, AGE UNDIFFERENTIATED.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: HAM.txt RecordID: 000280 NTS_Sheet: 30N05C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

70 | ***1 of 1*** | ***SE/247.4*** | ***92.8 / -2.04*** | ***Union Gas Limited 753 Hagar Avenue Burlington ON*** | ***SPL***

Ref No:	4745-9ZM35M	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	8/21/2015	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	8/21/2015	**Health/Env Conseq:**	
Dt Document Closed:	8/26/2015	**Agency Involved:**	
Site No:	NA		
Facility Name:			
MOE Response:	No		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Residence<UNOFFICIAL>		
Site Address:	753 Hagar Avenue		
Site Region:			
Site Municipality:	Burlington		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:			
Incident Event:			
Environment Impact:			
Nature of Impact:			
Contaminant Qty:	0 other - see incident description		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

System Facility Address:
Client Name: Union Gas Limited
Client Type:
Call Report Locatn Geodata:
Contaminant Code: 35
Contaminant Name: NATURAL GAS (METHANE)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Receiving Environment:
Incident Reason: Operator/Human Error
Incident Summary: TSSA FSB: meter damaged by vehicle; made safe
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Unknown / N/A
SAC Action Class: TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Source Type:

71	1 of 2	NE/248.3	92.8 / -2.00	**Advanced Integrated Resources** **817 Brant St** **Burlington ON L7R 2J4**	SCT

Established: 1985
Plant Size (ft²):
Employment: 5

--Details--
Description: Industrial and Commercial Fan and Blower and Air Purification Equipment Manufacturing
SIC/NAICS Code: 333413

71	2 of 2	NE/248.3	92.8 / -2.00	**Advanced Integrated Resources Inc.** **817 Brant St** **Burlington ON L7R 2J4**	SCT

Established: 1985
Plant Size (ft²):
Employment: 5

72	1 of 1	NE/248.5	93.0 / -1.81	**CANADA PEST CONTROL** **1-2004 MAPLEWOOD DR** **BURLINGTON ON L7R2C4**	PES

Detail Licence No:
Licence No: 09032
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Operator
Licence Type Code: 02
Licence Class: 01
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 905
Oper Phone No: 2208048
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

Trade Name:
PDF URL:

---

73 **1 of 1** **E/248.7** **91.8 / -3.00** **ON** **WWIS**

Well ID:	7369396	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	10/05/2020
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z341751	**Contractor:**	7644
Tag:	A297612	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008484034	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596532.00
Code OB Desc:		**North83:**	4798495.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	09/04/2020	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008484034	**Tag No:**	A297612
Depth M:		**Contractor:**	7644
Year Completed:	2020	**Latitude:**	43.3331046358275
Well Completed Dt:	09/04/2020	**Longitude:**	-79.8092320717925
Audit No:	Z341751	**Y:**	43.33310463365975
Path:	736\7369396.pdf	**X:**	-79.80923192363186

---

74 **1 of 1** **WNW/248.8** **100.0 / 5.19** **SOLENIS CANADA**
942 BRANT ST
BURLINGTON ON L7R2J7 **CHM**

Headcode:	00273600
Headcode Desc:	CHEMICALS
Phone:	9056321958

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
List Name:		INFO-DIRECT(TM) BUSINESS FILE			
Description:					

75	1 of 11	ENE/248.9	92.5 / -2.37	**CLARES SHELL & CAR WASH INC** **809 BRANT ST** **BURLINGTON ON L7R 2J4**	PRT

Location ID:	2393
Type:	retail
Expiry Date:	1992-09-30
Capacity (L):	90800
Licence #:	0026548001

75	2 of 11	ENE/248.9	92.5 / -2.37	**LAMONTS SERVICES LTD** **809 BRANT ST** **BURLINGTON ON L7R2J4**	PRT

Location ID:	2393
Type:	retail
Expiry Date:	1996-01-31
Capacity (L):	80000
Licence #:	0076380690

75	3 of 11	ENE/248.9	92.5 / -2.37	**SHELL CANADA PRODUCTS LTD.** **809 BRANT STREET. SERVICE STATION** **BURLINGTON CITY ON L7R 2J4**	SPL

Ref No:	180647	**Municipality No:**	14101
Year:		**Nature of Damage:**	
Incident Dt:	5/11/2000	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	5/11/2000	**Health/Env Conseq:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
Facility Name:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BURLINGTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:	UNKNOWN		
Incident Event:			
Environment Impact:	CONFIRMED		
Nature of Impact:	Soil contamination		
Contaminant Qty:			
System Facility Address:			
Client Name:			
Client Type:			
Call Report Locatn Geodata:			
Contaminant Code:			

Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Receiving Environment:
Incident Reason: UNKNOWN
Incident Summary: SHELL CANADA-CONTAMINATEDSOIL FOUND AT CLOSED STATION.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	4 of 11	ENE/248.9	92.5 / -2.37	SHELL CANADA PRODUCTS** 809 BRANT ST BURLINGTON ON L7R 2J4	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 9584130
Status: EXPIRED
Instance ID:
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description:
Original Source: EXP
Record Date: Up to May 2013

Expired Date: 4/28/1992
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	5 of 11	ENE/248.9	92.5 / -2.37	LAMONTS SERVICES LTD 809 BRANT ST BURLINGTON ON L7R 2J4	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 9984970

Expired Date: 1/7/1993

Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:		**Facility Location:**	
Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:			
Original Source:	EXP		
Record Date:	Up to May 2013		

75	***6 of 11***	***ENE/248.9***	***92.5 / -2.37***	***SHELL CANADA PRODUCTS***** ***809 BRANT ST*** ***BURLINGTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	10626895	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	30129	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		

Original Source:	EXP
Record Date:	Up to Mar 2012

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	7 of 11	ENE/248.9	92.5 / -2.37	SHELL CANADA PRODUCTS** 809 BRANT ST BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10626844	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	31038	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	8 of 11	ENE/248.9	92.5 / -2.37	SHELL CANADA PRODUCTS** 809 BRANT ST BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10626798	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	31347	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

75	*9 of 11*	*ENE/248.9*	*92.5 / -2.37*	***LAMONTS SERVICES LTD*** ***809 BRANT ST*** ***BURLINGTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 11162261 ***Expired Date:***
Status: EXPIRED ***Max Hazard Rank:***
Instance ID: 71476 ***Facility Location:***
Instance Type: FS Piping ***Facility Type:***
Instance Creation Dt: ***Fuel Type 2:***
Instance Install Dt: ***Fuel Type 3:***
Item Description: ***Panam Related:***
Manufacturer: ***Panam Venue Nm:***
Model: ***External Identifier:***
Serial No: ***Item:***
ULC Standard: ***Piping Steel:***
Quantity: ***Piping Galvanized:***
Unit of Measure: ***Tank Single Wall St:***
Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

75	*10 of 11*	*ENE/248.9*	*92.5 / -2.37*	***SHELL CANADA PRODUCTS***** ***809 BRANT ST*** ***BURLINGTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10626751 ***Expired Date:***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	31664	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

75	11 of 11	ENE/248.9	92.5 / -2.37	**Union Gas Limited** **809 Brant St** **Burlington ON**	SPL

Ref No:	1100-A4FR7L	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	11/20/2015	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	11/20/2015	**Health/Env Conseq:**	
Dt Document Closed:	11/27/2015	**Agency Involved:**	
Site No:	NA		
Facility Name:			
MOE Response:	No		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Commercial Building<UNOFFICIAL>		
Site Address:	809 Brant St		
Site Region:			
Site Municipality:	Burlington		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:			
Incident Event:			
Environment Impact:			
Nature of Impact:			
Contaminant Qty:	0 other - see incident description		
System Facility Address:			
Client Name:	Union Gas Limited		
Client Type:			
Call Report Locatn Geodata:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminant Code: 35
Contaminant Name: NATURAL GAS (METHANE)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Receiving Environment:
Incident Reason: Operator/Human Error
Incident Summary: TSSA: gas meter damage, made safe
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Industrial
SAC Action Class: TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Source Type:

76	1 of 32	E/249.7	91.1 / -3.73	ROYAL CANADIAN NAVAL ASSOCIATION 760 BRANT ST., SUITE #417 BURLINGTON CITY ON	CA

Certificate #: 8-3222-95-
Application Year: 95
Issue Date: 5/23/1995
Approval Type: Industrial air
Status: Cancelled
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: EXHAUST SYS. FOR VETERAN'S SERVICE CLUB
Contaminants:
Emission Control:

76	2 of 32	E/249.7	91.1 / -3.73	ROYAL CANADIAN NAVAL ASSOCIATION 760 BRANT STREET, 2ND FLOOR BURLINGTON CITY ON	CA

Certificate #: 8-3379-95-
Application Year: 95
Issue Date: 8/2/1995
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: COMMERCIAL KITCHEN EXHAUST HOOD
Contaminants:
Emission Control: No Controls

76	3 of 32	E/249.7	91.1 / -3.73	CENTRE FRANCOPHONE DE BURLINGTON INC. 760 BRANT STREET (#401) BURLINGTON CITY ON	CA

Certificate #: 8-3073-96-
Application Year: 96
Issue Date: 2/21/1996
Approval Type: Industrial air

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: COMMERCIAL KITCHEN EXHAUST HOOD
Contaminants: Odour/Fumes
Emission Control: No Controls

---

76 | ***4 of 32*** | ***E/249.7*** | ***91.1 / -3.73*** | ***760 Brant Street Burlington ON L7R 4B8*** | ***EHS***

Order No: 20101026031
Status: C
Report Type: Custom Report
Report Date: 11/2/2010
Date Received: 10/26/2010 1:57:46 PM
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.808721
Y: 43.332296

---

76 | ***5 of 32*** | ***E/249.7*** | ***91.1 / -3.73*** | ***Cogeco Cable Canada LP 760 BRANT STREET BURLINGTON ON L7R 4B8*** | ***EASR***

Approval No: R-002-9844707899
Status: REGISTERED
Date: 2012-03-28
Record Type: EASR
Link Source: MOFA
Project Type: Standby Power System
Full Address:
Approval Type: EASR-Standby Power System
SWP Area Name: Halton
PDF URL:
PDF Site Location:
MOE District: Halton-Peel
Municipality: BURLINGTON
Latitude: 43.332207
Longitude: -79.80887
Geometry X:
Geometry Y:

---

76 | ***6 of 32*** | ***E/249.7*** | ***91.1 / -3.73*** | ***1086891 Ontario Inc. 760 Brant Street Burlington ON L7R 4B8*** | ***GEN***

Generator No: ON8316469
SIC Code: 111111
SIC Description:
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
76	7 of 32	E/249.7	91.1 / -3.73	Burlington Ultrasound and Radiology Suite 2 760 Brant Street Burlington ON L7R 4B7	GEN

Generator No: ON5490518
SIC Code: 621510
SIC Description: Medical and Diagnostic Laboratories
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
76	8 of 32	E/249.7	91.1 / -3.73	McArthur Properties 760 Brant St. Burlington ON L7R 4B8	GEN

Generator No: ON3263313
SIC Code: 551113
SIC Description:
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
76	9 of 32	E/249.7	91.1 / -3.73	Burlington Ultrasound and Radiology Suite 2 760 Brant Street Burlington ON L7R 4B7	GEN

Generator No: ON5490518
SIC Code: 621510
SIC Description: Medical and Diagnostic Laboratories
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
76	10 of 32	E/249.7	91.1 / -3.73	Burlington Ultrasound and Radiology Suite 2 760 Brant Street Burlington ON L7R 4B7	GEN

Generator No: ON5490518
SIC Code: 621510
SIC Description: Medical and Diagnostic Laboratories
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
76	11 of 32	E/249.7	91.1 / -3.73	Trillium College Inc 760 Brant Street Unit #25 Burlington ON	GEN

Generator No: ON5427602
SIC Code: 611510, 611690
SIC Description: Technical and Trade Schools, All Other Schools and Instruction
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
76	12 of 32	E/249.7	91.1 / -3.73	Trillium College Inc 760 Brant Street Unit #25 Burlington ON	GEN

Generator No: ON5427602
SIC Code: 611510, 611690
SIC Description: TECHNICAL AND TRADE SCHOOLS, ALL OTHER SCHOOLS AND INSTRUCTION
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 131
Waste Class Name: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

76 | **13 of 32** | **E/249.7** | **91.1 / -3.73** | **Burlington Ultrasound and Radiology**
Suite 2 760 Brant Street
Burlington ON | **GEN**

Generator No: ON5490518
SIC Code: 621510
SIC Description: MEDICAL AND DIAGNOSTIC LABORATORIES
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

76 | **14 of 32** | **E/249.7** | **91.1 / -3.73** | **Wentworth Halton X-Ray and Ultrasound Inc**
Suite 2 760 Brant Street
Burlington ON L7R 4B7 | **GEN**

Generator No: ON5490518
SIC Code: 621510
SIC Description: MEDICAL AND DIAGNOSTIC LABORATORIES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Donna Duffy
Choice of Contact: CO_ADMIN
Phone No Admin: 905-637-7606 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

76 | **15 of 32** | **E/249.7** | **91.1 / -3.73** | **Dr Ronald Yim Dentistry Professional Corp**
6-760 Brant Street
Burlington ON L7R 4B7 | **GEN**

Generator No: ON5645674
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2016
PO Box No:
Country: Canada
Status:

Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

76 | **16 of 32** | **E/249.7** | **91.1 / -3.73** | **Burlington Ultrasound and Radiology**
Suite 2 760 Brant Street
Burlington ON L7R 4B7 | **GEN**

Generator No: ON5490518
SIC Code: 621510
SIC Description: MEDICAL AND DIAGNOSTIC LABORATORIES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Donna Duffy
Choice of Contact: CO_ADMIN
Phone No Admin: 905-637-7606 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

76 | **17 of 32** | **E/249.7** | **91.1 / -3.73** | **Trillium College Inc**
760 Brant Street Unit #25
Burlington ON L7R4B7 | **GEN**

Generator No: ON5427602
SIC Code: 611510, 611690
SIC Description: TECHNICAL AND TRADE SCHOOLS, ALL OTHER SCHOOLS AND INSTRUCTION
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Greg Zbikowski
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-448-4130 Ext.354
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 131
Waste Class Name: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 264

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class Name:		PHOTOPROCESSING WASTES			

76	18 of 32	E/249.7	91.1 / -3.73	**Oxford College of Arts, Business and Technology** **760 Brant Street Unit #25** **Burlington ON L7R4B7**	GEN

Generator No: ON5427602
SIC Code: 611510, 611690
SIC Description: TECHNICAL AND TRADE SCHOOLS, ALL OTHER SCHOOLS AND INSTRUCTION
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Nakia Meyers
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-632-3200 Ext.322
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 131
Waste Class Name: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

76	19 of 32	E/249.7	91.1 / -3.73	**Burlington Ultrasound and Radiology** **Suite 2 760 Brant Street** **Burlington ON L7R 4B7**	GEN

Generator No: ON5490518
SIC Code: 621510
SIC Description: MEDICAL AND DIAGNOSTIC LABORATORIES
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Donna Duffy
Choice of Contact: CO_ADMIN
Phone No Admin: 905-637-7606 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

76	20 of 32	E/249.7	91.1 / -3.73	**Trillium College Inc** **760 Brant Street Unit #25** **Burlington ON L7R4B7**	GEN

Generator No: ON5427602
SIC Code: 611510, 611690

SIC Description:	TECHNICAL AND TRADE SCHOOLS, ALL OTHER SCHOOLS AND INSTRUCTION
Approval Years:	2014
PO Box No:	
Country:	Canada
Status:	
Co Admin:	Greg Zbikowski
Choice of Contact:	CO_OFFICIAL
Phone No Admin:	905-448-4130 Ext.354
Contaminated Facility:	No
MHSW Facility:	No

Detail(s)

Waste Class:	131
Waste Class Name:	NEUTRALIZED WASTES - HEAVY METALS
Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES
Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS
Waste Class:	264
Waste Class Name:	PHOTOPROCESSING WASTES

---

76 | ***21 of 32*** | ***E/249.7*** | ***91.1 / -3.73*** | ***Oxford College of Arts, Business and Technology***
760 Brant Street Unit #25
Burlington ON L7R4B7 | ***GEN***

Generator No:	ON5427602
SIC Code:	
SIC Description:	
Approval Years:	As of Dec 2018
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	131 H
Waste Class Name:	Neutralized solutions - containing heavy metals
Waste Class:	148 B
Waste Class Name:	Misc. wastes and inorganic chemicals
Waste Class:	264 L
Waste Class Name:	Photoprocessing wastes
Waste Class:	264 T
Waste Class Name:	Photoprocessing wastes
Waste Class:	312 P
Waste Class Name:	Pathological wastes

---

76 | ***22 of 32*** | ***E/249.7*** | ***91.1 / -3.73*** | ***Dr Ronald Yim Dentistry Professional Corp***
6-760 Brant Street | ***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Burlington ON L7R 4B7	

Generator No: ON5645674
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

76	23 of 32	E/249.7	91.1 / -3.73	**Wentworth Halton X-Ray and Ultrasound Inc** **Suite 2 760 Brant Street** **Burlington ON L7R 4B7**	GEN

Generator No: ON5490518
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

76	24 of 32	E/249.7	91.1 / -3.73	**Oxford College of Arts, Business and Technology** **760 Brant Street Unit #25** **Burlington ON L7R4B7**	GEN

Generator No: ON5427602
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Class: 131 H
Waste Class Name: Neutralized solutions - containing heavy metals

Waste Class: 264 T
Waste Class Name: Photoprocessing wastes

Waste Class: 148 B
Waste Class Name: Misc. wastes and inorganic chemicals

76	25 of 32	E/249.7	91.1 / -3.73	**Dr Ronald Yim Dentistry Professional Corp** **6-760 Brant Street** **Burlington ON L7R 4B7**	GEN

Generator No: ON5645674
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

76	26 of 32	E/249.7	91.1 / -3.73	**Wentworth Halton X-Ray and Ultrasound Inc** **760 Brant Street Suite 2** **Burlington ON L7R 4B7**	GEN

Generator No: ON5490518
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

76	27 of 32	E/249.7	91.1 / -3.73	**Dr Ronald Yim Dentistry Professional Corp** **6-760 Brant Street**	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Burlington ON L7R 4B7	

Generator No: ON5645674
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

76	28 of 32	E/249.7	91.1 / -3.73	**Wentworth Halton X-Ray and Ultrasound Inc** **760 Brant Street Suite 2** **Burlington ON L7R 4B7**	GEN

Generator No: ON5490518
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

76	29 of 32	E/249.7	91.1 / -3.73	**Oxford College of Arts, Business and Technology** **760 Brant Street Unit #25** **Burlington ON L7R4B7**	GEN

Generator No: ON5427602
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Class: 131 H
Waste Class Name: Neutralized solutions - containing heavy metals

Waste Class: 148 B
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

Waste Class: 264 T
Waste Class Name: Photoprocessing wastes

76	30 of 32	E/249.7	91.1 / -3.73	**Dr Ronald Yim Dentistry Professional Corp** **6-760 Brant Street** **Burlington ON L7R 4B7**	GEN

Generator No: ON5645674
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

76	31 of 32	E/249.7	91.1 / -3.73	**Oxford College of Arts, Business and Technology** **760 Brant Street Unit #25** **Burlington ON L7R4B7**	GEN

Generator No: ON5427602
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148 B
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 264 T
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 131 H
Waste Class Name: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 264 L
Waste Class Name: PHOTOPROCESSING WASTES

---

76 | **32 of 32** | **E/249.7** | **91.1 / -3.73** | **Wentworth Halton X-Ray and Ultrasound Inc**
760 Brant Street Suite 2
Burlington ON L7R 4B7 | **GEN**

Generator No: ON5490518
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

---

77 | **1 of 1** | **NE/255.9** | **93.8 / -1.00** | **ON** | **BORE**

Borehole ID: 621030
OGF ID: 215521484
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: APR-1967
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: -999
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Power auger
Orig Ground Elev m: 94
Elev Reliabil Note:
DEM Ground Elev m: 94
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.335177
Longitude DD: -79.811381
UTM Zone: 17
Easting: 596355
Northing: 4798723
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218419509
Top Depth: 1.2
Bottom Depth: 4.3
Material Color: Brown
Material 1: Silt

Mat Consistency: Dense
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:

Material 2:	Sand	**Geologic Group:**	
Material 3:	Gravel	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND,GRAVEL. BROWN,VERY DENSE,AGE GLACIAL.		

Geology Stratum ID:	218419511	**Mat Consistency:**	Dense
Top Depth:	5.8	**Material Moisture:**	
Bottom Depth:	8.9	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Gravel	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND,SILT,GRAVEL. RED,VERY DENSE,AGE GLACIAL.		

Geology Stratum ID:	218419510	**Mat Consistency:**	Dense
Top Depth:	4.3	**Material Moisture:**	
Bottom Depth:	5.8	**Material Texture:**	
Material Color:	Green	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,CLAY. GREEN,VERY DENSE,AGE GLACIAL.		

Geology Stratum ID:	218419512	**Mat Consistency:**	
Top Depth:	8.9	**Material Moisture:**	
Bottom Depth:		**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Refusal	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	REFUSAL OF ENTRY. 000100090004004900140079001900980017O **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218419507	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Soil	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SOIL. AGE POST-GLACIAL.		

Geology Stratum ID:	218419508	**Mat Consistency:**	Loose
Top Depth:	.3	**Material Moisture:**	
Bottom Depth:	1.2	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Gravel	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND,SILT,GRAVEL. BROWN,LOOSE,AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular

Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: HAM.txt RecordID: 000290 NTS_Sheet: 30N05C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

78 ***1 of 1*** ***ENE/261.2*** ***92.8 / -2.00*** ***ON*** ***WWIS***

Well ID:	7374925	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	12/11/2020
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z338623	**Contractor:**	7464
Tag:	A309623	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008531648	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596448.00
Code OB Desc:		**North83:**	4798658.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	11/13/2020	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Bore Hole ID:	1008531648	**Tag No:**	A309623
Depth M:		**Contractor:**	7464
Year Completed:	2020	**Latitude:**	43.3345828446705
Well Completed Dt:	11/13/2020	**Longitude:**	-79.8102393816156
Audit No:	Z338623	**Y:**	43.33458284265655
Path:	737\7374925.pdf	**X:**	-79.81023923285721

---

79 | **1 of 8** | **ENE/265.4** | **92.2 / -2.67** | **SHELL CANADA PRODUCTS**
809 BRANT ST
BURLINGTON ON | **EXP**

Inventory No:	10626869	**Tank Material:**	Steel
Inventory Status:	EXPIRED	**Corrosion Protect:**	Internally Lined
Installation Year:	1987	**Overfill Protection:**	
Capacity:	22700	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	UNDERGROUND TANK		
Previous Fuel Type:	Gasoline		

---

79 | **2 of 8** | **ENE/265.4** | **92.2 / -2.67** | **SHELL CANADA PRODUCTS**
809 BRANT ST
BURLINGTON ON | **EXP**

Inventory No:	10626727	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	EXPIRED	**Corrosion Protect:**	Fiberglass
Installation Year:	1987	**Overfill Protection:**	
Capacity:	22730	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	UNDERGROUND TANK		
Previous Fuel Type:	Gasoline		

---

79 | **3 of 8** | **ENE/265.4** | **92.2 / -2.67** | **SHELL CANADA PRODUCTS**
809 BRANT ST
BURLINGTON ON | **EXP**

Inventory No:	10626776	**Tank Material:**	Steel
Inventory Status:	EXPIRED	**Corrosion Protect:**	Internally Lined
Installation Year:	1987	**Overfill Protection:**	
Capacity:	22700	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	UNDERGROUND TANK		
Previous Fuel Type:	Gasoline		

---

79 | **4 of 8** | **ENE/265.4** | **92.2 / -2.67** | **SHELL CANADA PRODUCTS**
809 BRANT ST
BURLINGTON ON | **EXP**

Inventory No:	10626820	**Tank Material:**	Steel
Inventory Status:	EXPIRED	**Corrosion Protect:**	Internally Lined
Installation Year:	1987	**Overfill Protection:**	
Capacity:	22700	**Inventory Context:**	FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline
Inventory Item: FS LIQUID FUEL TANK

---

79 *5 of 8* *ENE/265.4* *92.2 / -2.67*

LAMONTS SERVICES LTD
809 BRANT ST
BURLINGTON ON

EXP

Inventory No: 10626913
Inventory Status: EXPIRED
Installation Year: 1987
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description:
Previous Fuel Type: Gasoline
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

79 *6 of 8* *ENE/265.4* *92.2 / -2.67*

LAMONTS SERVICES LTD
809 BRANT ST
BURLINGTON ON

EXP

Inventory No: 11162197
Inventory Status: EXPIRED
Installation Year: 1987
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description:
Previous Fuel Type: Gasoline
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

79 *7 of 8* *ENE/265.4* *92.2 / -2.67*

LAMONTS SERVICES LTD
809 BRANT ST
BURLINGTON ON

EXP

Inventory No: 11162241
Inventory Status: EXPIRED
Installation Year: 1987
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description:
Previous Fuel Type: Gasoline
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

79 *8 of 8* *ENE/265.4* *92.2 / -2.67*

LAMONTS SERVICES LTD
809 BRANT ST
BURLINGTON ON

EXP

Inventory No: 11162219
Inventory Status: EXPIRED
Installation Year: 1987
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Capacity:	22700	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:			
Previous Fuel Type:	Gasoline		

---

80 *1 of 3* *NNE/275.6* *93.8 / -1.00* ***1297760 ont. Inc*** ***849 Brant*** ***Burlington ON L7R 2J6*** ***GEN***

Generator No:	ON4101955
SIC Code:	
SIC Description:	
Approval Years:	05
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	221
Waste Class Name:	LIGHT FUELS

---

80 *2 of 3* *NNE/275.6* *93.8 / -1.00* ***849 Brant Street*** ***Burlington ON*** ***EHS***

Order No:	20110512001	**Nearest Intersection:**	Fairview St & Maplewood Dr
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	5/18/2011	**Search Radius (km):**	0.25
Date Received:	5/12/2011 6:40:31 AM	**X:**	-79.811546
Previous Site Name:		**Y:**	43.335402
Lot/Building Size:			
Additional Info Ordered:			

---

80 *3 of 3* *NNE/275.6* *93.8 / -1.00* ***849 Brant St*** ***Burlington ON L7R2J6*** ***EHS***

Order No:	20161121011	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	24-NOV-16	**Search Radius (km):**	.25
Date Received:	21-NOV-16	**X:**	-79.811293
Previous Site Name:		**Y:**	43.335418
Lot/Building Size:			
Additional Info Ordered:			

---

81 *1 of 1* *NE/277.0* *93.8 / -1.00* ***849 BRANT ST*** ***Burlington ON*** ***WWIS***

Well ID:	7292316	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	

Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	08/11/2017
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z259635	***Contractor:***	7472
Tag:	A227431	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	HALTON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	BB
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	06/21/2017
Year Completed:	2017
Depth (m):	5.4864
Latitude:	43.3353592251793
Longitude:	-79.8112974391261
Path:	

Bore Hole Information

Bore Hole ID:	1006709738	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	596361.00
Code OB Desc:		***North83:***	4798743.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	06/21/2017	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1006846596
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Mat2 Desc:	CLAY
Mat3:	34
Mat3 Desc:	TILL
Formation Top Depth:	6.0

Formation End Depth:	18.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006846595
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	01
Mat3 Desc:	FILL
Formation Top Depth:	1.0
Formation End Depth:	6.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006846594
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	02
Most Common Material:	TOPSOIL
Mat2:	
Mat2 Desc:	
Mat3:	77
Mat3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	1.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006846604
Layer:	2
Plug From:	12.0
Plug To:	18.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006846603
Layer:	1
Plug From:	0.0
Plug To:	12.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1006846602
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1006846593
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006846599
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	13.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1006846600
Layer:	1
Slot:	10
Screen Top Depth:	13.0
Screen End Depth:	18.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.5

Water Details

Water ID:	1006846598
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1006846597
Diameter:	6.0
Depth From:	0.0
Depth To:	18.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1006709738	***Tag No:***	A227431
Depth M:	5.4864	***Contractor:***	7472
Year Completed:	2017	***Latitude:***	43.3353592251793
Well Completed Dt:	06/21/2017	***Longitude:***	-79.8112974391261
Audit No:	Z259635	***Y:***	43.33535922260118
Path:	729\7292316.pdf	***X:***	-79.8112972897549

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
82	1 of 1	ENE/277.9	91.4 / -3.47	American Optics Inc. 789 Brant St Burlington ON L7R 2J3	SCT

Established: 2001
Plant Size (ft²):
Employment: 5

--Details--
Description: Glass Product Manufacturing from Purchased Glass
SIC/NAICS Code: 327215

Description: Measuring, Medical and Controlling Devices Manufacturing
SIC/NAICS Code: 334512

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
83	1 of 4	ENE/282.1	91.8 / -3.00	789-795 Brant Street Burlington ON L7R 2J3	EHS

Order No: 22120800663
Status: C
Report Type: RSC Report (Urban)
Report Date: 13-DEC-22
Date Received: 08-DEC-22
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .3
X: -79.8093025
Y: 43.33407756

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
83	2 of 4	ENE/282.1	91.8 / -3.00	789-795 Brant Street Burlington ON L7R 2J3	EHS

Order No: 22120800663
Status: C
Report Type: RSC Report (Urban)
Report Date: 13-DEC-22
Date Received: 08-DEC-22
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .3
X: -79.8093025
Y: 43.33407756

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
83	3 of 4	ENE/282.1	91.8 / -3.00	789-795 Brant Street Burlington ON L7R 2J3	EHS

Order No: 22120800663
Status: C
Report Type: RSC Report (Urban)
Report Date: 13-DEC-22
Date Received: 08-DEC-22
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .3
X: -79.8093025
Y: 43.33407756

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
83	4 of 4	ENE/282.1	91.8 / -3.00	789-795 Brant Street Burlington ON L7R 2J3	EHS

Order No: 22120800663
Status: C
Report Type: RSC Report (Urban)
Report Date: 13-DEC-22
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .3

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Date Received:	08-DEC-22	**X:**	-79.8093025
Previous Site Name:		**Y:**	43.33407756
Lot/Building Size:			
Additional Info Ordered:			

---

84 **1 of 4** **ENE/282.1** **91.8 / -3.00** **789-795 Brant Street Burlington ON L7R 2J3** **EHS**

Order No:	21041500518	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	RSC Report (Urban)	**Client Prov/State:**	ON
Report Date:	20-APR-21	**Search Radius (km):**	.3
Date Received:	15-APR-21	**X:**	-79.80930188
Previous Site Name:		**Y:**	43.33407731
Lot/Building Size:			
Additional Info Ordered:			

---

84 **2 of 4** **ENE/282.1** **91.8 / -3.00** **789-795 Brant Street Burlington ON L7R 2J3** **EHS**

Order No:	21041500518	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	RSC Report (Urban)	**Client Prov/State:**	ON
Report Date:	20-APR-21	**Search Radius (km):**	.3
Date Received:	15-APR-21	**X:**	-79.80930188
Previous Site Name:		**Y:**	43.33407731
Lot/Building Size:			
Additional Info Ordered:			

---

84 **3 of 4** **ENE/282.1** **91.8 / -3.00** **789-795 Brant Street Burlington ON L7R 2J3** **EHS**

Order No:	21041500518	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	RSC Report (Urban)	**Client Prov/State:**	ON
Report Date:	20-APR-21	**Search Radius (km):**	.3
Date Received:	15-APR-21	**X:**	-79.80930188
Previous Site Name:		**Y:**	43.33407731
Lot/Building Size:			
Additional Info Ordered:			

---

84 **4 of 4** **ENE/282.1** **91.8 / -3.00** **789-795 Brant Street Burlington ON L7R 2J3** **EHS**

Order No:	21041500518	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	RSC Report (Urban)	**Client Prov/State:**	ON
Report Date:	20-APR-21	**Search Radius (km):**	.3
Date Received:	15-APR-21	**X:**	-79.80930188
Previous Site Name:		**Y:**	43.33407731
Lot/Building Size:			
Additional Info Ordered:			

---

85 **1 of 4** **E/282.2** **90.8 / -4.00** **1450 Ghent Ave Burlington ON L7S 1W8** **EHS**

Order No:	22062000034	**Nearest Intersection:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:	C	**Municipality:**		
Report Type:	Standard Report	**Client Prov/State:**	ON	
Report Date:	23-JUN-22	**Search Radius (km):**	.25	
Date Received:	20-JUN-22	**X:**	-79.8088194	
Previous Site Name:		**Y:**	43.3323412	
Lot/Building Size:				
Additional Info Ordered:				

---

85 | ***2 of 4*** | ***E/282.2*** | ***90.8 / -4.00*** | ***1450 Ghent Ave Burlington ON L7S 1W8*** | ***EHS***

Order No:	22062000034	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	23-JUN-22	**Search Radius (km):**	.25
Date Received:	20-JUN-22	**X:**	-79.8088194
Previous Site Name:		**Y:**	43.3323412
Lot/Building Size:			
Additional Info Ordered:			

---

85 | ***3 of 4*** | ***E/282.2*** | ***90.8 / -4.00*** | ***1450 Ghent Ave Burlington ON L7S 1W8*** | ***EHS***

Order No:	22062000034	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	23-JUN-22	**Search Radius (km):**	.25
Date Received:	20-JUN-22	**X:**	-79.8088194
Previous Site Name:		**Y:**	43.3323412
Lot/Building Size:			
Additional Info Ordered:			

---

85 | ***4 of 4*** | ***E/282.2*** | ***90.8 / -4.00*** | ***1450 Ghent Ave Burlington ON L7S 1W8*** | ***EHS***

Order No:	22062000034	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	23-JUN-22	**Search Radius (km):**	.25
Date Received:	20-JUN-22	**X:**	-79.8088194
Previous Site Name:		**Y:**	43.3323412
Lot/Building Size:			
Additional Info Ordered:			

---

86 | ***1 of 1*** | ***ENE/285.0*** | ***91.8 / -3.00*** | ***ON*** | ***BORE***

Borehole ID:	621733	**Inclin FLG:**	No
OGF ID:	215522187	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JUN-1964	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.334256
Total Depth m:	-999	**Longitude DD:**	-79.809425
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	596515

Drill Method:	Power auger	***Northing:***	4798623
Orig Ground Elev m:	92.4	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	91.6		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218422178	***Mat Consistency:***	Soft
Top Depth:	1.2	***Material Moisture:***	
Bottom Depth:	2.3	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Sand	***Geologic Period:***	
Material 4:	Clay	***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND,CLAY.BROWN,GLACIAL,VERY SOFT, UNIFORM,AGE GLACIAL.		

Geology Stratum ID:	218422176	***Mat Consistency:***	
Top Depth:	.1	***Material Moisture:***	
Bottom Depth:	.6	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Fill	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	fill
Gsc Material Description:			
Stratum Description:	FILL,SAND. MAN-MADE,AGE POST-GLACIAL.		

Geology Stratum ID:	218422177	***Mat Consistency:***	Loose
Top Depth:	.6	***Material Moisture:***	
Bottom Depth:	1.2	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Fill	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:	Silt	***Geologic Period:***	
Material 4:		***Depositional Gen:***	fill
Gsc Material Description:			
Stratum Description:	FILL,SAND,SILT. BROWN,MAN-MADE,LOOSE,RUBBLY, AGE POST-GLACIAL.		

Geology Stratum ID:	218422179	***Mat Consistency:***	Soft
Top Depth:	2.3	***Material Moisture:***	
Bottom Depth:	3.2	***Material Texture:***	
Material Color:	Green	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:	Sand	***Geologic Period:***	
Material 4:		***Depositional Gen:***	lacustrine
Gsc Material Description:			
Stratum Description:	SILT,CLAY,SAND. GREEN,LACUSTRINE,VERY SOFT, LAYERED,AGE GLACIAL.		

Geology Stratum ID:	218422180	***Mat Consistency:***	Dense
Top Depth:	3.2	***Material Moisture:***	
Bottom Depth:	4	***Material Texture:***	
Material Color:	Red	***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Sand	***Geologic Period:***	
Material 4:	Shale	***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND,SHALERED,GLACIAL,VERY DENSE, UNIFORM,AGE GLACIAL.		

Geology Stratum ID:	218422181	**Mat Consistency:**	Dense
Top Depth:	4	**Material Moisture:**	
Bottom Depth:	4.5	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. RED,VERY DENSE,WEATHERED, AGE ORDOVICIAN.		

Geology Stratum ID:	218422182	**Mat Consistency:**	
Top Depth:	4.5	**Material Moisture:**	
Bottom Depth:		**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Refusal	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	REFUSAL OF ENTRY. 000200090004001800075026001051170013005300055 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218422175	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.1	**Material Texture:**	
Material Color:	Black	**Non Geo Mat Type:**	
Material 1:	Soil	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SOIL. BLACK,MAN-MADE, AGE POST-GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: HAM.txt RecordID: 007330 NTS_Sheet: 30M05C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

87 ***1 of 1*** ***ENE/288.2*** ***91.2 / -3.64*** ***ON*** ***WWIS***

Well ID:	7369394	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	10/05/2020

Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z341749	**Contractor:**	7644
Tag:	A296263	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008484028	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596539.00
Code OB Desc:		**North83:**	4798591.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	09/04/2020	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008484028	**Tag No:**	A296263
Depth M:		**Contractor:**	7644
Year Completed:	2020	**Latitude:**	43.3339679879529
Well Completed Dt:	09/04/2020	**Longitude:**	-79.8091288522168
Audit No:	Z341749	**Y:**	43.33396798553153
Path:	736\7369394.pdf	**X:**	-79.80912870356966

88 ***1 of 1*** ***NNE/288.4*** ***94.3 / -0.53*** ***ON*** ***WWIS***

Well ID:	7376950	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	12/30/2020
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z295975	**Contractor:**	7484
Tag:	A255195	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	

Static Water Level: ***Zone:***
Clear/Cloudy: ***UTM Reliability:***
Municipality: BURLINGTON CITY
Site Info:

Bore Hole Information

Bore Hole ID:	1008570919	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	596314.00
Code OB Desc:		***North83:***	4798772.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	11/23/2020	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008570919	***Tag No:***	A255195
Depth M:		***Contractor:***	7484
Year Completed:	2020	***Latitude:***	43.3356263249453
Well Completed Dt:	11/23/2020	***Longitude:***	-79.8118720147307
Audit No:	Z295975	***Y:***	43.3356263228308
Path:		***X:***	-79.81187186637806

---

89 ***1 of 24*** ***N/288.9*** ***96.6 / 1.79*** ***PRT***

ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE
892 BRANT ST
BURLINGTON ON L7R 2J5

Location ID: 2394
Type: retail
Expiry Date: 1993-10-30
Capacity (L): 27959
Licence #: 0053678001

---

89 ***2 of 24*** ***N/288.9*** ***96.6 / 1.79*** ***GEN***

BRANT CYCLE AND SPORTS LIMITED
892 BRANT STREET
BURLINGTON ON L7R 2J5

Generator No: ON0615902
SIC Code: 6581
SIC Description: TOY/HOBBY STORES
Approval Years: 96,97,98,99,00,01,02,03,04,05,06
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
89	3 of 24	N/288.9	96.6 / 1.79	BRANT CYCLE AND SPORTS LIMITED 892 BRANT ST. BURLINGTON ON L7R 2J5	GEN

Generator No: ON0615902
SIC Code: 811490
SIC Description: Other Personal and Household Goods Repair and Maintenance
Approval Years: 07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
89	4 of 24	N/288.9	96.6 / 1.79	ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE 892 BRANT ST BURLINGTON ON L7R 2J5	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 9767445
Status: EXPIRED
Instance ID:
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description:

Expired Date: 2/4/1993
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Original Source:		EXP			
Record Date:		Up to May 2013			

89	5 of 24	N/288.9	96.6 / 1.79	ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE 892 BRANT ST BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10627063	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	30806	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

89	6 of 24	N/288.9	96.6 / 1.79	ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE 892 BRANT ST BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10627111	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	31167	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

89	*7 of 24*	*N/288.9*	*96.6 / 1.79*	*ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE* *892 BRANT ST* *BURLINGTON ON*	*DTNK*

Delisted Expired Fuel Safety Facilities

Instance No: 10627089
Status: EXPIRED
Instance ID: 31042
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012
Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

89	*8 of 24*	*N/288.9*	*96.6 / 1.79*	*ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE* *892 BRANT ST* *BURLINGTON ON*	*DTNK*

Delisted Expired Fuel Safety Facilities

Instance No:	10627045	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	31369	***Facility Location:***	
Instance Type:	FS Piping	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

89	***9 of 24***	***N/288.9***	***96.6 / 1.79***	***BRANT CYCLE AND SPORTS LIMITED*** ***892 BRANT ST.*** ***BURLINGTON ON L7R 2J5***	***GEN***

Generator No:	ON0615902
SIC Code:	811490
SIC Description:	Other Personal and Household Goods Repair and Maintenance
Approval Years:	2009
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

89	***10 of 24***	***N/288.9***	***96.6 / 1.79***	***BRANT CYCLE AND SPORTS LIMITED*** ***892 BRANT ST.*** ***BURLINGTON ON L7R 2J5***	***GEN***

Generator No:	ON0615902
SIC Code:	811490
SIC Description:	Other Personal and Household Goods Repair and Maintenance
Approval Years:	2010

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

89 | ***11 of 24*** | ***N/288.9*** | ***96.6 / 1.79*** | ***BRANT CYCLE AND SPORTS LIMITED***
892 BRANT ST.
BURLINGTON ON L7R 2J5 | ***GEN***

Generator No: ON0615902
SIC Code: 811490
SIC Description: Other Personal and Household Goods Repair and Maintenance
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

89 | ***12 of 24*** | ***N/288.9*** | ***96.6 / 1.79*** | ***BRANT CYCLE AND SPORTS LIMITED***
892 BRANT ST.
BURLINGTON ON L7R 2J5 | ***GEN***

Generator No: ON0615902
SIC Code: 811490
SIC Description: Other Personal and Household Goods Repair and Maintenance
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

89 | ***13 of 24*** | ***N/288.9*** | ***96.6 / 1.79*** | ***BRANT CYCLE AND SPORTS LIMITED***
892 BRANT ST.
BURLINGTON ON | ***GEN***

Generator No: ON0615902
SIC Code: 811490
SIC Description: OTHER PERSONAL AND HOUSEHOLD GOODS REPAIR AND MAINTENANCE
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

89 | ***14 of 24*** | ***N/288.9*** | ***96.6 / 1.79*** | ***BRANT CYCLE AND SPORTS LIMITED***
892 BRANT ST.
BURLINGTON ON L7R-2J5 | ***GEN***

Generator No: ON0615902
SIC Code: 811490
SIC Description: OTHER PERSONAL AND HOUSEHOLD GOODS REPAIR AND MAINTENANCE
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

89 | ***15 of 24*** | ***N/288.9*** | ***96.6 / 1.79*** | ***BRANT CYCLE AND SPORTS LIMITED***
892 BRANT ST.
BURLINGTON ON L7R-2J5 | ***GEN***

Generator No: ON0615902
SIC Code: 811490
SIC Description: OTHER PERSONAL AND HOUSEHOLD GOODS REPAIR AND MAINTENANCE
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
89	16 of 24	N/288.9	96.6 / 1.79	BRANT CYCLE AND SPORTS LIMITED 892 BRANT ST. BURLINGTON ON L7R-2J5	GEN

Generator No: ON0615902
SIC Code: 811490
SIC Description: OTHER PERSONAL AND HOUSEHOLD GOODS REPAIR AND MAINTENANCE
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
89	17 of 24	N/288.9	96.6 / 1.79	BRANT CYCLE AND SPORTS LIMITED 892 BRANT ST. BURLINGTON ON L7R-2J5	GEN

Generator No: ON0615902
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 213 L
Waste Class Name: Petroleum distillates

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
89	18 of 24	N/288.9	96.6 / 1.79	BRANT CYCLE AND SPORTS LIMITED 892 BRANT ST. BURLINGTON ON L7R-2J5	GEN

Generator No: ON0615902
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213 L
Waste Class Name: Petroleum distillates

Waste Class: 213 I
Waste Class Name: Petroleum distillates

89	19 of 24	N/288.9	96.6 / 1.79	**BRANT CYCLE AND SPORTS LIMITED** **892 BRANT ST.** **BURLINGTON ON L7R-2J5**	GEN

Generator No: ON0615902
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 213 L
Waste Class Name: Petroleum distillates

89	20 of 24	N/288.9	96.6 / 1.79	**BRANT CYCLE AND SPORTS LIMITED** **892 BRANT ST.** **BURLINGTON ON L7R-2J5**	GEN

Generator No: ON0615902
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213 I
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 213 L
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
89	21 of 24	N/288.9	96.6 / 1.79	ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE 892 BRANT ST BURLINGTON ON	EXP

Inventory No: 10627026
Inventory Status: EXPIRED
Installation Year: 1984
Capacity: 45400
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: LICENCED UNDERGROUND TANKS
Previous Fuel Type: Gasoline

Tank Material: Steel
Corrosion Protect: Sacrificial anode
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
89	22 of 24	N/288.9	96.6 / 1.79	ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE 892 BRANT ST BURLINGTON ON	EXP

Inventory No: 10627005
Inventory Status: EXPIRED
Installation Year: 1984
Capacity: 36300
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: LICENCED UNDERGROUND TANKS
Previous Fuel Type: Gasoline

Tank Material: Steel
Corrosion Protect: Sacrificial anode
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
89	23 of 24	N/288.9	96.6 / 1.79	ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE 892 BRANT ST BURLINGTON ON	EXP

Inventory No: 10626949
Inventory Status: EXPIRED
Installation Year: 1984
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: LICENCED UNDERGROUND TANKS
Previous Fuel Type: Gasoline

Tank Material: Steel
Corrosion Protect: Sacrificial anode
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
89	24 of 24	N/288.9	96.6 / 1.79	ELIZABETH BALOG ELIZABETHS SELF SERVICE CENTRE 892 BRANT ST BURLINGTON ON	EXP

Inventory No: 10626979
Inventory Status: EXPIRED
Installation Year: 1984
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:

Tank Material: Steel
Corrosion Protect: Sacrificial anode
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Description: LICENCED UNDERGROUND TANKS
Previous Fuel Type: Gasoline

---

90 **1 of 1** **SW/290.1** **93.8 / -1.00** **ON** **BORE**

Borehole ID:	621739	**Inclin FLG:**	No
OGF ID:	215522193	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	MAY-1964	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.330183
Total Depth m:	5.8	**Longitude DD:**	-79.816042
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	595985
Drill Method:	Power auger	**Northing:**	4798163
Orig Ground Elev m:	91.9	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	93.3		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218422209	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Soil	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SOIL,SAND,SILT. AGE POST-GLACIAL.		

Geology Stratum ID:	218422215	**Mat Consistency:**	Dense
Top Depth:	4.6	**Material Moisture:**	
Bottom Depth:	5.2	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Shale	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SAND,SILT,SHALERED,GLACIAL,VERY DENSE,RUBBLY,AGE GLACIAL.		

Geology Stratum ID:	218422214	**Mat Consistency:**	Dense
Top Depth:	3.7	**Material Moisture:**	
Bottom Depth:	4.6	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Shale	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SAND,SILT,SHALERED,GLACIAL,VERY DENSE, UNIFORM,AGE GLACIAL.		

Geology Stratum ID:	218422213	**Mat Consistency:**	Dense

Top Depth:	2.1	**Material Moisture:**	
Bottom Depth:	3.7	**Material Texture:**	
Material Color:	Green	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SAND,SILT. GREEN,GLACIAL,VERY DENSE, LAYERED,AGE GLACIAL.		

Geology Stratum ID:	218422211	**Mat Consistency:**	Soft
Top Depth:	.9	**Material Moisture:**	
Bottom Depth:	1.2	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	CLAY,SILT. BROWN,LACUSTRINE,VERY SOFT, BEDDED,AGE GLACIAL.		

Geology Stratum ID:	218422212	**Mat Consistency:**	Dense
Top Depth:	1.2	**Material Moisture:**	
Bottom Depth:	2.1	**Material Texture:**	
Material Color:	Green	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:	Silt	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SAND,CLAY,SILT.GREEN,GLACIAL,DENSE,LAYERED, AGE GLACIAL.		

Geology Stratum ID:	218422216	**Mat Consistency:**	
Top Depth:	5.2	**Material Moisture:**	
Bottom Depth:	5.8	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. RED,WEATHERED,AGE ORDOVICIAN. 000100020003000200040033000700660012005500150058000 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218422210	**Mat Consistency:**	Loose
Top Depth:	.3	**Material Moisture:**	
Bottom Depth:	.9	**Material Texture:**	Fine to Medium
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	SAND-FINE TO MEDIUM,SILT. BROWN,LACUSTRINE,LOOSE, GRANULAR,AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: HAM.txt RecordID: 007390 NTS_Sheet: 30M05C		

Confiden 1: Reliable information but incomplete.

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada
Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

91 ***1 of 1*** ***N/290.2*** ***94.8 / 0.00*** ***ON*** ***BORE***

Borehole ID: 624326
OGF ID: 215524778
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: OCT-1968
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 4.7
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Power auger
Orig Ground Elev m: 96
Elev Reliabil Note:
DEM Ground Elev m: 95.2
Concession:
Location D:
Survey D:
Comments:
Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.335731
Longitude DD: -79.812727
UTM Zone: 17
Easting: 596245
Northing: 4798783
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218433307
Top Depth: 1.6
Bottom Depth: 4.7
Material Color: Green
Material 1: Till
Material 2: Silt
Material 3: Clay
Material 4: Sand
Gsc Material Description:
Stratum Description: TILL,SILT,CLAY,SAND.GREEN,GLACIAL,HARD, AGE GLACIAL. 0004201300052044930 **Note: Many records provided by the department have a truncated [Stratum Description] field.
Mat Consistency: Hard
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Geology Stratum ID: 218433304
Top Depth: 0
Bottom Depth: .5
Material Color: Brown
Material 1: Soil
Material 2: Sand
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SOIL,SAND. BROWN,AGE POST-GLACIAL.
Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218433303
Top Depth: 0
Bottom Depth: 0
Mat Consistency:
Material Moisture:
Material Texture:

Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL. MAN-MADE,GRANULAR, AGE POST-GLACIAL.		

Geology Stratum ID:	218433305	**Mat Consistency:**	
Top Depth:	.5	**Material Moisture:**	
Bottom Depth:	1.3	**Material Texture:**	Medium
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND-MEDIUM. BROWN,AGE GLACIAL.		

Geology Stratum ID:	218433306	**Mat Consistency:**	
Top Depth:	1.3	**Material Moisture:**	
Bottom Depth:	1.6	**Material Texture:**	Fine to Medium
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Gravel	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND-FINE TO MEDIUM,GRAVEL. BROWN,AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: HAM.txt RecordID: 033270 NTS_Sheet: 30M05C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

92 | ***1 of 4*** | ***NNE/294.7*** | ***94.2 / -0.66*** | ***849 and 855 Brant Street Burlington ON L7R 2J6*** | ***EHS***

Order No:	20311600071	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	19-NOV-20	**Search Radius (km):**	.2
Date Received:	16-NOV-20	**X:**	-79.8116966
Previous Site Name:		**Y:**	43.3356475
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
92	2 of 4	NNE/294.7	94.2 / -0.66	849 and 855 Brant Street Burlington ON L7R 2J6	EHS

Order No:	20311600071	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	19-NOV-20	**Search Radius (km):**	.2
Date Received:	16-NOV-20	**X:**	-79.8116966
Previous Site Name:		**Y:**	43.3356475
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
92	3 of 4	NNE/294.7	94.2 / -0.66	849 and 855 Brant Street Burlington ON L7R 2J6	EHS

Order No:	20311600071	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	19-NOV-20	**Search Radius (km):**	.2
Date Received:	16-NOV-20	**X:**	-79.8116966
Previous Site Name:		**Y:**	43.3356475
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
92	4 of 4	NNE/294.7	94.2 / -0.66	849 and 855 Brant Street Burlington ON L7R 2J6	EHS

Order No:	20311600071	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	19-NOV-20	**Search Radius (km):**	.2
Date Received:	16-NOV-20	**X:**	-79.8116966
Previous Site Name:		**Y:**	43.3356475
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
93	1 of 1	NNE/294.8	94.8 / 0.00	ON	BORE

Borehole ID:	621079	**Inclin FLG:**	No
OGF ID:	215521533	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	FEB-1969	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.335725
Total Depth m:	5	**Longitude DD:**	-79.81211
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	596295
Drill Method:	Power auger	**Northing:**	4798783
Orig Ground Elev m:	94.8	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	95		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218419703	***Mat Consistency:***	Stiff
Top Depth:	1.5	***Material Moisture:***	
Bottom Depth:	3	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Sand	***Geologic Period:***	
Material 4:	Clay	***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND,CLAY.BROWN,GLACIAL,STIFF, AGE GLACIAL.		

Geology Stratum ID:	218419701	***Mat Consistency:***	
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	.3	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Soil	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	SOIL. AGE POST-GLACIAL.		

Geology Stratum ID:	218419705	***Mat Consistency:***	Dense
Top Depth:	3.8	***Material Moisture:***	
Bottom Depth:	5	***Material Texture:***	
Material Color:	Green	***Non Geo Mat Type:***	
Material 1:	Gravel	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	GRAVEL,SAND. GREEN,GLACIAL,VERY DENSE, AGE GLACIAL. 00048012001000210012505 5 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218419702	***Mat Consistency:***	
Top Depth:	.3	***Material Moisture:***	
Bottom Depth:	1.5	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:	Gravel	***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND,GRAVEL. BROWN,AGE GLACIAL.		

Geology Stratum ID:	218419704	***Mat Consistency:***	Soft
Top Depth:	3	***Material Moisture:***	
Bottom Depth:	3.8	***Material Texture:***	
Material Color:	Green	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	SILT,CLAY. GREEN,GLACIAL,VERY SOFT, AGE GLACIAL.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	M	***Horizontal:***	NAD27

Observatio: **Verticalda:** Mean Average Sea Level
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: HAM.txt RecordID: 000780 NTS_Sheet: 30M05C
Confiden 1: Reliable information but incomplete.

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada
Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

94 | **1 of 1** | **E/294.8** | **90.8 / -4.00** | **730 Brant St**
Burlington ON L7R2H9 | **EHS**

Order No: 20150512005
Status: C
Report Type: Custom Report
Report Date: 15-MAY-15
Date Received: 12-MAY-15
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.808645
Y: 43.332435

---

95 | **1 of 2** | **NNE/297.8** | **94.6 / -0.21** | **855 Brant Street**
Burlington ON L7R 2J6 | **EHS**

Order No: 20060620022
Status: C
Report Type: Complete Report
Report Date: 6/26/2006
Date Received: 6/20/2006
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.81229
Y: 43.335853

---

95 | **2 of 2** | **NNE/297.8** | **94.6 / -0.21** | **855 Brant St**
Burlington ON | **EHS**

Order No: 20170406211
Status: C
Report Type: Standard Report
Report Date: 13-APR-17
Date Received: 06-APR-17
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.811869
Y: 43.335864

---

96 | **1 of 4** | **NNE/299.5** | **94.8 / 0.00** | **ALCHEM**
BRANT & FAIRVIEW RAMBO CREEK
BURLINGTON PLANT 1055 TRUMAN STREET
BURLINGTON CITY ON | **SPL**

Ref No: 979
Year:
Incident Dt: 1/20/1988
Dt MOE Arvl on Scn:
Municipality No: 14101
Nature of Damage:
Discharger Report:
Material Group:

MOE Reported Dt:	1/20/1988	**Health/Env Conseq:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
Facility Name:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BURLINGTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:	ABOVE-GROUND TANK LEAK		
Incident Event:			
Environment Impact:			
Nature of Impact:			
Contaminant Qty:			
System Facility Address:			
Client Name:			
Client Type:			
Call Report Locatn Geodata:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	WATER		
Receiving Environment:			
Incident Reason:	UNKNOWN		
Incident Summary:	ALCHEM- 900 L OF FUEL OILTO CREEK FROM LEAKY TANK.		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Source Type:			

96 | ***2 of 4*** | ***NNE/299.5*** | ***94.8 / 0.00*** | ***Fairview and Brant Burlington ON*** | ***SPL***

Ref No:	7026-7SQ3PU	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:		**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	6/4/2009	**Health/Env Conseq:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
Facility Name:			
MOE Response:	No Field Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Walmart<UNOFFICIAL>		
Site Address:			
Site Region:			
Site Municipality:	Burlington		

Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Pipe Or Hose Leak
Incident Event:
Environment Impact:
Nature of Impact: Other Impact(s); Soil Contamination
Contaminant Qty: 378 L
System Facility Address:
Client Name:
Client Type:
Call Report Locatn Geodata:
Contaminant Code:
Contaminant Name: GLYCOL/WATER SOLUTION
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Receiving Environment:
Incident Reason: Spill
Incident Summary: Walmart: 378L glycol to grnd. cont'd
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Other
SAC Action Class: Land Spills
Source Type:

---

96 | ***3 of 4*** | ***NNE/299.5*** | ***94.8 / 0.00*** | ***cb at Brant Street and Fairview Street Burlington ON*** | ***SPL***

Ref No: 5626-84A2VJ
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 4/6/2010
Dt Document Closed: 5/26/2010
Site No:
Facility Name:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: cb at Brant Street and Fairview Street<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality:
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Other Discharges
Incident Event:
Environment Impact: Confirmed
Nature of Impact: Surface Water Pollution
Contaminant Qty: 0 other - see incident description
System Facility Address:
Client Name:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved:

Client Type:
Call Report Locatn Geodata:
Contaminant Code: 12
Contaminant Name: GASOLINE
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Receiving Environment:
Incident Reason: Fire/Explosion - Resulting from fires/explosions (Not occurrences which cause a fire or explosion)
Incident Summary: car fire, gasoline to catch basin, Works responding
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Motor Vehicle
SAC Action Class: Watercourse Spills
Source Type:

---

96 | ***4 of 4*** | ***NNE/299.5*** | ***94.8 / 0.00*** | ***intersection of Fairview St. and Brant St. Burlington ON*** | ***SPL***

Ref No: 5123-AAALK5
Year:
Incident Dt: 2016/05/25
Dt MOE Arvl on Scn:
MOE Reported Dt: 2016/05/25
Dt Document Closed:
Site No: NA
Facility Name:
MOE Response: No
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Hager Rambo channel<UNOFFICIAL>
Site Address: intersection of Fairview St. and Brant St.
Site Region:
Site Municipality: Burlington
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum: NAD83
Northing: 4798802
Easting: 596258
Incident Cause:
Incident Event: Unknown / N/A
Environment Impact:
Nature of Impact:
Contaminant Qty: 0 other - see incident description
System Facility Address:
Client Name:
Client Type:
Call Report Locatn Geodata:
Contaminant Code: 13
Contaminant Name: HYDROCARBON LIGHT
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Receiving Environment: Surface Water
Incident Reason: Unknown / N/A
Incident Summary: gas to flood diverging channel
Activity Preceding Spill:
Property 2nd Watershed:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved:

Property Tertiary Watershed:
Sector Type: Unknown / N/A
SAC Action Class: Watercourse Spills
Source Type:

Unplottable Summary

Total: 27 Unplottable sites

DB	Company Name/Site Name	Address	City	Postal
CA	REG. MUN. OF HALTON	FAIRVIEW ST.	BURLINGTON ON	
CA	CITY	FAIRVIEW ST.	BURLINGTON ON	
CA	CITY	MAPLEWOOD DR. E.	BURLINGTON ON	
CA		Prospect Street	Burlington ON	
CA		Prospect Street	Burlington ON	
CA	Suncor Energy Products Inc.		Burlington ON	
CA	R.M. OF HALTON	GHENT AVE.	BURLINGTON CITY ON	
CA	R.M. OF HALTON SHELDON COURT	FAIRVIEW ST.	BURLINGTON CITY ON	
CA	BURLINGTON CITY	GHENT AVE.	BURLINGTON CITY ON	
CA	R.M. OF HALTON	GHENT AVE.	BURLINGTON CITY ON	
CA	CMH EQUITIES INC.	FAIRVIEW ST.	BURLINGTON CITY ON	
CA	R.M. OF HALTON SHELDON COURT EXTENSION	FAIRVIEW ST.	BURLINGTON CITY ON	
CA	R.M. OF HALTON	BRANT ST/QUE INTERCHANGE	BURLINGTON CITY ON	
CA	KEENMAR LIMITED - PT. LOT 5/RP# 125	PROSPECT ST./GHENT AVE.	BURLINGTON CITY ON	
CA	CMH EQUITIES INC.	FAIRVIEW ST.	BURLINGTON CITY ON	
ECA	The Regional Municipality of Halton	Brant Street	Burlington ON	L6M 3L1
ECA	The Regional Municipality of Halton	Prospect Street	Burlington ON	L6M 3L1

ECA	The Regional Municipality of Halton	Maplewood Dr	Burlington ON	L6M 3L1
ECA	The Regional Municipality of Halton	Prospect Street	Burlington ON	L6M 3L1
NCPL	Hercules Canada Inc.		Halton-Peel ON	
NCPL	Hercules Canada Inc.		Halton-Peel ON	
PAP	Magnus Chemicals Limited		Burlington ON	
SPL	Petro Canada<UNOFFICIAL>	CN RAILYARD - ALDERSHOT<UNOFFICIAL>	Burlington ON	
SPL	Longo's<UNOFFICIAL>	Fairview St.	Burlington ON	
SPL	UNKNOWN	LAKE ONTARIO - OUTFALL AT END OF BRANT ST.	BURLINGTON CITY ON	
SPL	Suncor Energy Inc.		Burlington ON	
SPL	SANEXEN ENVIRONMENTAL SERVICES	TYANDAGA SUBSTATION BRANT STREET PCB DESTRUCTION UNIT	BURLINGTON CITY ON	

Unplottable Report

Site: ***REG. MUN. OF HALTON***
FAIRVIEW ST. BURLINGTON ON

Database: ***CA***

Certificate #:	7-0151-85-006
Application Year:	85
Issue Date:	3/25/85
Approval Type:	Municipal water
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Site: ***CITY***
FAIRVIEW ST. BURLINGTON ON

Database: ***CA***

Certificate #:	3-0154-85-006
Application Year:	85
Issue Date:	3/21/85
Approval Type:	Municipal sewage
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Site: ***CITY***
MAPLEWOOD DR. E. BURLINGTON ON

Database: ***CA***

Certificate #:	3-0211-85-006
Application Year:	85
Issue Date:	3/26/85
Approval Type:	Municipal sewage
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Site:
Prospect Street Burlington ON

Database: ***CA***

Certificate #:	2314-5B7HYU

Application Year: 02
Issue Date: 6/17/02
Approval Type: Municipal & Private sewage
Status: Approved
Application Type: Amended CofA
Client Name: The Regional Municipality of Halton
Client Address: 1151 Bronte Road
Client City: Oakville
Client Postal Code: L6M 3L1
Project Description: Amended for change of site location.
Contaminants:
Emission Control:

Site:
Prospect Street Burlington ON

Database: ***CA***

Certificate #: 8832-5AYKPL
Application Year: 02
Issue Date: 6/17/02
Approval Type: Municipal & Private sewage
Status: Revoked and/or Replaced
Application Type: New Certificate of Approval
Client Name: The Regional Municipality of Halton
Client Address: 1151 Bronte Road
Client City: Oakville
Client Postal Code: L6M 3L1
Project Description: Approval is sought for the construction of sanitary sewers on Prospect Street
Contaminants:
Emission Control:

Site: ***Suncor Energy Products Inc.***
Burlington ON

Database: ***CA***

Certificate #: 0845-6FHK5G
Application Year: 2007
Issue Date: 12/11/2007
Approval Type: Industrial Sewage Works
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON***
GHENT AVE. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0366-86-
Application Year: 86
Issue Date: 4/25/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON SHELDON COURT***
FAIRVIEW ST. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0330-89-
Application Year: 89
Issue Date: 3/10/1989
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BURLINGTON CITY***
GHENT AVE. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0389-86-
Application Year: 86
Issue Date: 4/18/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON***
GHENT AVE. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-0257-86-
Application Year: 86
Issue Date: 4/25/1986
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***CMH EQUITIES INC.***
FAIRVIEW ST. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-1101-87-
Application Year: 87
Issue Date: 7/23/1987
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:

Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON SHELDON COURT EXTENSION***
FAIRVIEW ST. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-0291-89-
Application Year: 89
Issue Date: 3/10/1989
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON***
BRANT ST/QUE INTERCHANGE BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-1413-88-
Application Year: 88
Issue Date: 9/7/1988
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***KEENMAR LIMITED - PT. LOT 5/RP# 125***
PROSPECT ST./GHENT AVE. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0090-92-
Application Year: 92
Issue Date: 2/4/1992
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***CMH EQUITIES INC.***
FAIRVIEW ST. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-1326-87-
Application Year: 87

Issue Date: 8/4/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Regional Municipality of Halton***
Brant Street Burlington ON L6M 3L1

Database: ***ECA***

Approval No: 2285-6S8P4V
Approval Date: 2006-08-02
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-Municipal Drinking Water Systems
Project Type: Municipal Drinking Water Systems
Business Name: The Regional Municipality of Halton
Address: Brant Street
Full Address:
Full PDF Link:
PDF Site Location:

MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***The Regional Municipality of Halton***
Prospect Street Burlington ON L6M 3L1

Database: ***ECA***

Approval No: 2314-5B7HYU
Approval Date: 2002-06-17
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: The Regional Municipality of Halton
Address: Prospect Street
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/9650-5B4HPF-14.pdf
PDF Site Location:

MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***The Regional Municipality of Halton***
Maplewood Dr Burlington ON L6M 3L1

Database: ***ECA***

Approval No: 4822-6A6QJ8
Approval Date: 2005-03-08
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-Municipal Drinking Water Systems
Project Type: Municipal Drinking Water Systems
Business Name: The Regional Municipality of Halton
Address: Maplewood Dr
Full Address:
Full PDF Link:
PDF Site Location:

MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***The Regional Municipality of Halton***
Prospect Street Burlington ON L6M 3L1

Database: ***ECA***

Approval No:	8832-5AYKPL	***MOE District:***	
Approval Date:	2002-06-17	***City:***	
Status:	Revoked and/or Replaced	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	

Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: The Regional Municipality of Halton
Address: Prospect Street
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2438-5ATPAL-14.pdf
PDF Site Location:

Site: ***Hercules Canada Inc.***
Halton-Peel ON

Database: ***NCPL***

Year: 2001
Site Name:
Facility Owner:
Discharge Type: Air
Sector: Air Discharges
District Area: Halton-Peel
Type of Concern: Reg. 346
Contaminant: Dimethyl Sulphide
Status Report:

Details

Incident Date:
Exceedance Start Date:
Exceedance End Date:
Limit/Unit/Freq:
Quantity Min/Max:
Facility Action: implementing improvements - action plan submitted
Ministry Action: Provincial Officer's Order issued

Site: ***Hercules Canada Inc.***
Halton-Peel ON

Database: ***NCPL***

Year: 2001
Site Name:
Facility Owner:
Discharge Type: Air
Sector: Air Discharges
District Area: Halton-Peel
Type of Concern: Reg. 346
Contaminant: carbon disulphide
Status Report:

Details

Incident Date:
Exceedance Start Date:
Exceedance End Date:
Limit/Unit/Freq:
Quantity Min/Max:
Facility Action: implementing improvements - action plan submitted
Ministry Action: Provincial Officer's Order issued

Site: ***Magnus Chemicals Limited***
Burlington ON

Database: ***PAP***

Company ID:	2454317253	***Year:***	2009
Status:	Inactive	***Description:***	
Type:		***Website:***	
Operation:			
Status Desc:			
Effluent Pollution Control:			
Company Name:			
Division:			
Company Mailing Address:			
Mailing Address:			
Mill Mailing Address:			
Mill Notes:			
History:			
Company History:			

Site: ***Petro Canada<UNOFFICIAL>***
CN RAILYARD - ALDERSHOT<UNOFFICIAL> Burlington ON

Database: ***SPL***

Ref No:	8564-65HVEG	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	10/7/2004	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	Chemical
MOE Reported Dt:	10/6/2004	***Health/Env Conseq:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
Facility Name:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	CN RAILYARD - ALDERSHOT<UNOFFICIAL>		
Site Address:			
Site Region:	Central		
Site Municipality:	Burlington		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:	Tank (Above Ground) Leak		
Incident Event:			
Environment Impact:	Possible		
Nature of Impact:	Other Impact(s)		
Contaminant Qty:	227.5 L		
System Facility Address:			
Client Name:	Petro Canada<UNOFFICIAL>		
Client Type:			
Call Report Locatn Geodata:			
Contaminant Code:	21		
Contaminant Name:	SPENT SULFURIC ACID		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	Land		
Receiving Environment:			
Incident Reason:	Equipment Failure		
Incident Summary:	CN- <50 gal spent sulf acid to grv,clng.		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:	Spill to Land		

Source Type:

Site: ***Longo's<UNOFFICIAL>*** ***Database:*** ***SPL***
Fairview St. Burlington ON

Ref No:	1481-6UK77E	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	10/10/2006	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	10/14/2006	***Health/Env Conseq:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
Facility Name:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	Longo's<UNOFFICIAL>		
Site Address:	Fairview St.		
Site Region:			
Site Municipality:	Burlington		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:			
Incident Event:			
Environment Impact:	Possible		
Nature of Impact:			
Contaminant Qty:	181.6 kg		
System Facility Address:			
Client Name:			
Client Type:			
Call Report Locatn Geodata:			
Contaminant Code:	38		
Contaminant Name:	FREON (CFC)		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:			
Receiving Environment:			
Incident Reason:	Other - Reason not otherwise defined		
Incident Summary:	Longo's Burlington 181.6 kg of Freon to atm		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Source Type:	Other		

Site: ***UNKNOWN*** ***Database:*** ***SPL***
LAKE ONTARIO - OUTFALL AT END OF BRANT ST. BURLINGTON CITY ON

Ref No:	31611	***Municipality No:***	14101
Year:		***Nature of Damage:***	
Incident Dt:	3/4/1990	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	3/4/1990	***Health/Env Conseq:***	
Dt Document Closed:		***Agency Involved:***	WORKS
Site No:			
Facility Name:			
MOE Response:			
Site County/District:			

Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BURLINGTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: UNKNOWN
Incident Event:
Environment Impact: POSSIBLE
Nature of Impact: Water course or lake
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Call Report Locatn Geodata:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: WATER
Receiving Environment:
Incident Reason: UNKNOWN
Incident Summary: EST. 2 L DIESEL FUEL DUMPED TO STORM SEWER & LAKE ONTARIO.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:

Site: ***Suncor Energy Inc.***
Burlington ON

Database: ***SPL***

Ref No: 1818-8GCHYZ
Year:
Incident Dt: 4/28/2011
Dt MOE Arvl on Scn:
MOE Reported Dt: 4/28/2011
Dt Document Closed: 5/19/2011
Site No:
Facility Name:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Corner of Appleby and Dundas<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality: Burlington
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Other Transport Accident
Incident Event:
Environment Impact: Confirmed

Nature of Impact:	Soil Contamination
Contaminant Qty:	7000 L
System Facility Address:	
Client Name:	Suncor Energy Inc.
Client Type:	
Call Report Locatn Geodata:	
Contaminant Code:	12
Contaminant Name:	GASOLINE
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Receiving Environment:	
Incident Reason:	Spill
Incident Summary:	SIMULATION: Suncor spill of 7000 L of gasoline to road/land
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Tank Truck
SAC Action Class:	Land Spills
Source Type:	

Site: ***SANEXEN ENVIRONMENTAL SERVICES***
TYANDAGA SUBSTATION BRANT STREET PCB DESTRUCTION UNIT BURLINGTON CITY ON

Database: ***SPL***

Ref No:	30633	***Municipality No:***	14101
Year:		***Nature of Damage:***	
Incident Dt:	2/6/1990	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	2/6/1990	***Health/Env Conseq:***	
Dt Document Closed:		***Agency Involved:***	M.O.E.

Site No:	
Facility Name:	
MOE Response:	
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	
Nearest Watercourse:	
Site Name:	
Site Address:	
Site Region:	
Site Municipality:	BURLINGTON CITY
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	PROCESS UPSET
Incident Event:	
Environment Impact:	
Nature of Impact:	
Contaminant Qty:	
System Facility Address:	
Client Name:	
Client Type:	
Call Report Locatn Geodata:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	AIR
Receiving Environment:	
Incident Reason:	COMBUSTION PROBLEMS
Incident Summary:	SANEXEN M.D.U. HEATER MALFUNCTION-HEAVY BLACK SMOKE. *MEDIA*
Activity Preceding Spill:	

Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ***Note:*** *Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.*

Abandoned Aggregate Inventory: Provincial AAGR

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

Government Publication Date: Sept 2002*

Aggregate Inventory: Provincial AGR

The Ontario Ministry of Northern Development, Mines, Natural Resources and Forestry (ONDMNRF) maintains this database of pits and quarries. The database provides information regarding the registered owner/operator, location name, operation type, approval type, and maximum annual tonnage.

Government Publication Date: Up to Oct 2022

Abandoned Mine Information System: Provincial AMIS

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

Government Publication Date: 1800-Mar 2022

Anderson's Waste Disposal Sites: Private ANDR

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1860s-Present

Aboveground Storage Tanks: Provincial AST

Historical listing of aboveground storage tanks made available by the Department of Natural Resources and Forestry. Includes tanks used to hold water or petroleum. This dataset has been retired as of September 25, 2014 and will no longer be updated.

Government Publication Date: May 31, 2014

Automobile Wrecking & Supplies: Private AUWR

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

Government Publication Date: 1999-Oct 31, 2023

Borehole: Provincial BORE

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

Government Publication Date: 1875-Jul 2018

Certificates of Approval: Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

Government Publication Date: 1985-Oct 30, 2011*

Dry Cleaning Facilities: Federal CDRY

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.

Government Publication Date: Jan 2004-Dec 2022

Commercial Fuel Oil Tanks: Provincial CFOT

Locations of commercial underground fuel oil tanks. This is not a comprehensive or complete inventory of commercial fuel tanks in the province; this listing is a copy of records of registered commercial underground fuel oil tanks obtained under Access to Public Information.
Note that the following types of tanks do not require registration: waste oil tanks in apartments, office buildings, residences, etc.; aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Chemical Manufacturers and Distributors: Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

Government Publication Date: 1999-Jan 31, 2020

Chemical Register: Private CHM

This database includes a listing of locations of facilities within the Province or Territory that either manufacture and/or distributes chemicals.

Government Publication Date: 1999-Oct 31, 2023

Compressed Natural Gas Stations: Private CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

Government Publication Date: Dec 2012 -Nov 2023

Inventory of Coal Gasification Plants and Coal Tar Sites: Provincial COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

Government Publication Date: Apr 1987 and Nov 1988*

Compliance and Convictions: Provincial CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

Government Publication Date: 1989-Nov 2023

Certificates of Property Use: Provincial CPU

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

Government Publication Date: 1994 - Dec 31, 2023

Drill Hole Database: Provincial DRL

The Ontario Drill Hole Database contains information on more than 113,000 percussion, overburden, sonic and diamond drill holes from assessment files on record with the department of Mines and Minerals. Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted to the MNDM. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

Government Publication Date: 1886 - Aug 2023

Delisted Fuel Tanks: Provincial DTNK

List of fuel storage tank sites that were once found in - and have since been removed from - the list of fuel storage tanks made available by the regulatory agency under Access to Public Information.

Government Publication Date: Oct 2023

Environmental Activity and Sector Registry: Provincial EASR

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval), Please see our ECA database.

Government Publication Date: Oct 2011- Nov 30, 2023

Environmental Registry: Provincial EBR

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

Government Publication Date: 1994 - Dec 31, 2023

Environmental Compliance Approval: Provincial ECA

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

Government Publication Date: Oct 2011- Nov 30, 2023

Environmental Effects Monitoring: Federal EEM

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

Government Publication Date: 1992-2007*

ERIS Historical Searches: Private EHS

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

Government Publication Date: 1999-Dec 31, 2023

Environmental Issues Inventory System: Federal EIIS

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

Government Publication Date: 1992-2001*

Emergency Management Historical Event: Provincial EMHE

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

Government Publication Date: Apr 30, 2022

Environmental Penalty Annual Report: Provincial EPAR

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment and Climate Change. These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

Government Publication Date: Jan 1, 2011 - Dec 31, 2022

List of Expired Fuels Safety Facilities: Provincial EXP

List of facilities and tanks for which there was once a fuel registration. This is not a comprehensive or complete inventory of expired tanks/tank facilities in the province; this listing is a copy of previously registered tanks and facilities obtained under Access to Public Information. Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc; includes tanks which have been removed from the ground.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Federal Convictions: Federal FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

Government Publication Date: 1988-Jun 2007*

Contaminated Sites on Federal Land: Federal FCS

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government. Includes fire training sites and sites at which Per- and Polyfluoroalkyl Substances (PFAS) are a concern.

Government Publication Date: Jun 2000-Oct 2023

Fisheries & Oceans Fuel Tanks: Federal FOFT

Fisheries & Oceans Canada maintains an inventory of aboveground & underground fuel storage tanks located on Fisheries & Oceans property or controlled by DFO. Our inventory provides information on the site name, location, tank owner, tank operator, facility type, storage tank location, tank contents & capacity, and date of tank installation.

Government Publication Date: 1964-Sep 2019

Federal Identification Registry for Storage Tank Systems (FIRSTS): Federal FRST

A list of federally regulated Storage tanks from the Federal Identification Registry for Storage Tank Systems (FIRSTS). FIRSTS is Environment and Climate Change Canada's database of storage tank systems subject to the Storage Tank for Petroleum Products and Allied Petroleum Products Regulations. The main objective of the Regulations is to prevent soil and groundwater contamination from storage tank systems located on federal and aboriginal lands. Storage tank systems that do not have a valid identification number displayed in a readily visible location on or near the storage tank system may be refused product delivery.

Government Publication Date: Oct 31, 2021

Fuel Storage Tank: Provincial FST

List of registered private and retail fuel storage tanks. This is not a comprehensive or complete inventory of private and retail fuel storage tanks in the province; this listing is a copy of registered private and retail fuel storage tanks, obtained under Access to Public Information.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Fuel Storage Tank - Historic: Provincial FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

Government Publication Date: Pre-Jan 2010*

Ontario Regulation 347 Waste Generators Summary: Provincial GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

Government Publication Date: 1986-Oct 31, 2022

Greenhouse Gas Emissions from Large Facilities: Federal GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO2 eq).

Government Publication Date: 2013-Dec 2020

TSSA Historic Incidents: Provincial HINC

List of historic incidences of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen recorded by the TSSA in their previous incident tracking system. The TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of historical fuel spills and leaks in the province. This listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: 2006-June 2009*

Indian & Northern Affairs Fuel Tanks: Federal IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

Government Publication Date: 1950-Aug 2003*

Fuel Oil Spills and Leaks: Provincial INC

Listing of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen reported to the Spills Action Centre (SAC). This is not a comprehensive or complete inventory of fuel-related leaks, spills, and incidents in the province; this listing in a copy of incidents reported to the SAC, obtained under Access to Public Information. Includes incidents from fuel-related hazards such as spills, fires, and explosions. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Landfill Inventory Management Ontario: Provincial LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the Ministry of the Environment, Conservation and Parks compiles new and updated information. Includes small and large landfills currently operating as well as those which are closed and historic. Operators of larger landfills provide landfill information for the previous operating year to the ministry for LIMO including: estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills include information such as site owner, site location and certificate of approval # and status.

Government Publication Date: Mar 21, 2022

Canadian Mine Locations: Private MINE

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

Government Publication Date: 1998-2009*

Mineral Occurrences: Provincial MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

Government Publication Date: 1846-Feb 2023

National Analysis of Trends in Emergencies System (NATES): Federal NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

Government Publication Date: 1974-1994*

Non-Compliance Reports: Provincial NCPL

The Ministry of the Environment provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act.

Government Publication Date: Dec 31, 2021

National Defense & Canadian Forces Fuel Tanks: Federal NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

Government Publication Date: Up to May 2001*

National Defense & Canadian Forces Spills: Federal NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

Government Publication Date: Mar 1999-Oct 2022

National Defence & Canadian Forces Waste Disposal Sites: Federal NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

Government Publication Date: 2001-Apr 2007*

National Energy Board Pipeline Incidents: Federal NEBI

Locations of pipeline incidents from 2008 to present, made available by the Canada Energy Regulator (CER) - previously the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

Government Publication Date: 2008-Jun 30, 2021

National Energy Board Wells: Federal NEBP

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release date.

Government Publication Date: 1920-Feb 2003*

National Environmental Emergencies System (NEES): Federal NEES

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December 2004.

Government Publication Date: 1974-2003*

National PCB Inventory: Federal NPCB

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

Government Publication Date: 1988-2008*

National Pollutant Release Inventory 1993-2020: Federal NPR2

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of pollutant releases (to air, water and land), disposals, and transfers for recycling. The inventory, managed by Environment and Climate Change Canada, tracks over 300 substances. Under the authority of the Canadian Environmental Protection Act (CEPA), owners or operators of facilities that meet published reporting requirements are required to report to the NPRI.

Government Publication Date: Sep 2020

National Pollutant Release Inventory - Historic: Federal NPRI

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances. This data holds historic records; current records are found in NPR2.

Government Publication Date: 1993-May 2017

Oil and Gas Wells: Private OGWE

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

Government Publication Date: 1988-Nov 30, 2023

Ontario Oil and Gas Wells: Provincial OOGW

In 1998, the MNR handed over to the Ontario Oil, Gas and Salt Resources Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database include well owner/operator, location, permit issue date, and well cap date, license No., status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provide for each well record.

Government Publication Date: 1800-Aug 2023

Inventory of PCB Storage Sites: Provincial OPCB

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

Government Publication Date: 1987-Oct 2004; 2012-Dec 2013

Orders: Provincial ORD

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

Government Publication Date: 1994 - Dec 31, 2023

Canadian Pulp and Paper: Private PAP

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

Government Publication Date: 1999, 2002, 2004, 2005, 2009-2014

Parks Canada Fuel Storage Tanks: Federal PCFT

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

Government Publication Date: 1920-Jan 2005*

Pesticide Register: Provincial PES

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

Government Publication Date: Oct 2011- Nov 30, 2023

NPRI Reporters - PFAS Substances: Federal PFCH

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of releases, disposals, and transfers, tracking over 320 pollutants. Per - and polyfluoroalkyl substances (PFAS) are a group of over 4,700 human-made substances for which adverse environmental and health effects have been observed. This listing of PFAS substance reporters includes those NPRI facilities that reported substances that are found in either: a) the Comprehensive Global Database of PFASs compiled by the Organisation for Economic Co-operation and Development (OECD), b) the US Environmental Protection Agency (US EPA) Master List of PFAS Substances, c) the US EPA list of PFAS chemicals without explicit structures, or d) the US EPA list of PFAS structures (encompassing the largest set of structures having sufficient levels of fluorination to potentially impart PFAS-type properties).

Government Publication Date: Sep 2020

Potential PFAS Handers from NPRI: Federal PFHA

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of releases, disposals, and transfers, tracking over 320 pollutants. Per - and polyfluoroalkyl substances (PFAS) are a group of over 4,700 human-made substances for which adverse environmental and health effects have been observed. This list of potential PFAS handlers includes those NPRI facilities that reported business activity (NAICS code) included in the US Environmental Protection Agency (US EPA) list of Potential PFAS-Handling Industry Sectors, further described as operating in industry sectors where literature reviews indicate that PFAS may be handled and/or released. Inclusion of a facility in this listing does not indicate that PFAS are being manufactured, processed, used, or released by the facility - these are facilities that potentially handle PFAS based on their industrial profile.

Government Publication Date: Sep 2020

Pipeline Incidents: Provincial PINC

List of pipeline incidents (strikes, leaks, spills). This is not a comprehensive or complete inventory of pipeline incidents in the province; this listing in an historical copy of records previously obtained under Access to Public Information. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2021

Private and Retail Fuel Storage Tanks: Provincial PRT

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

Government Publication Date: 1989-1996*

Permit to Take Water: Provincial PTTW

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include PTTW's on the registry such as OWRA s. 34 - Permit to take water.

Government Publication Date: 1994 - Dec 31, 2023

Ontario Regulation 347 Waste Receivers Summary: Provincial REC

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

Government Publication Date: 1986-1990, 1992-2021

Record of Site Condition: Provincial RSC

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up.
RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09).

Government Publication Date: 1997-Sept 2001, Oct 2004-Nov 2023

Retail Fuel Storage Tanks: Private RST

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

Government Publication Date: 1999-Oct 31, 2023

Scott's Manufacturing Directory: Private SCT

Scott's Directories is a data bank containing information on over 200,000 manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, and main products are included in this database.

Government Publication Date: 1992-Mar 2011*

Ontario Spills: Provincial SPL

List of spills and incidents made available by the Ministry of the Environment, Conservation and Parks. This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X. The Ministry of the Environment, Conservation and Parks cites the coronavirus pandemic as an explanation for delays in releasing data pursuant to requests. This database includes spill incidents that occurred in February, March, May, June-November 2022, and January 2023 in addition to those listed in the Government Publication Date.

Government Publication Date: 1988-Dec 2021; see description

Wastewater Discharger Registration Database: Provincial SRDS

Facilities that report either municipal treated wastewater effluent or industrial wastewater discharges under the Effluent Monitoring and Effluent Limits (EMEL) and Municipal/Industrial Strategy for Abatement Regulations. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment keeps record of direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation, Mining, Petroleum Refining, Organic Chemicals, Inorganic Chemicals, Pulp & Paper, Metal Casting, Iron & Steel, and Quarries.

Government Publication Date: 1990-Dec 31, 2020

Anderson's Storage Tanks: Private TANK

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1915-1953*

Transport Canada Fuel Storage Tanks: Federal TCFT

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

Government Publication Date: 1970 - Apr 2023

Variances for Abandonment of Underground Storage Tanks: Provincial VAR

Listing of variances granted for storage tank abandonment. This is not a comprehensive or complete inventory of tank abandonment variances in the province; this listing is a copy of tank abandonment variance records previously obtained under Access to Public Information. In Ontario, registered underground storage tanks must be removed within two years of disuse; if removal of a tank is not feasible, an application may be sought for a variance from this code requirement.
Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Waste Disposal Sites - MOE CA Inventory: Provincial WDS

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

Government Publication Date: Oct 2011-Nov 30, 2023

Waste Disposal Sites - MOE 1991 Historical Approval Inventory: Provincial WDSH

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

Government Publication Date: Up to Oct 1990*

Water Well Information System: Provincial WWIS

This database describes locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table.

Government Publication Date: Mar 31 2023

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.


Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.


The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

Appendix E
Aerial Photographs And Historic Maps


Plains Rd E
Canadian National
Brant St
Fairview St
Maplewood Dr
Prospect St
Brantview Plaza
Robinson St
Legion Rd
Grahams Lane
Ghent Ave
Stephenson Dr
Hyde Rd
Olga Dr
Hager Ave
Brentwood Dr
Hammond St
Miriam Cres
Maple Mews Plaza


Image © 2024 Maxar Technologies
893 ft


759 ft
Google

Appendix F
Topographic Map And Geological Mapping


Ontario

Ministry of Natural Resources and Forestry

Make-a-Map: Natural Heritage Areas

Enter map title

Map created:1/24/2024



Legend

- Assessment Parcel
- Greenbelt Area Boundary
- Greenbelt Hamlets
- ORM Boundary
- NEP Boundary
- NEP Parks and Open Space System
- ANSI
- Earth Science Provincially Significant/sciences de la terre d'importance provinciale
- Earth Science Regionally Significant/sciences de la terre d'importance régionale
- Life Science Provincially Significant/sciences de la vie d'importance provinciale
- Life Science Regionally Significant/sciences de la vie d'importance régionale
- Evaluated Wetland
- Provincially Significant/considérée d'importance provinciale
- Non-Provincially Significant/non considérée d'importance provinciale
- Unevaluated Wetland
- Woodland
- Conservation Reserve
- Provincial Park
- ORM Land Use Designation
- Countryside Area/zone de campagne
- Natural Core Area/zone centrale naturelle
- Natural Linkage Area/lien naturel
- Palgrave Estates Residential Community/communauté résidentielle de Palgrave Estates
- Rural Settlement/zone de peuplement rurale
- Settlement Area/zone de peuplement
- NEP Land Use Designation
- Escarpment Natural Area/zone naturelle de l'escarpement
- Escarpment Protection Area/zone protégée l'escarpement
- Escarpment Recreation Area/zone récréative de l'escarpement
- Escarpment Rural Area/zone rurale de l'escarpement
- Mineral Resource Extraction Area/zone d'extraction de resources minérales
- Urban Area/zone urbaine
- Natural Heritage System
- Greenbelt Specialty Crop Area
- Greenbelt Land Use Designation
- Protected Countryside/campagne protégé
- Urban River Valley/vallée fluviale urbaine

0.7 0 0.33 0.7 Kilometres

Absence of a feature in the map does not mean they do not exist in this area.



This map should not be relied on as a precise indicator of routes or locations, nor as a guide to navigation. The Ontario Ministry of Natural Resources and Forestry(OMNRF) shall not be liable in any way for the use of, or reliance upon, this map or any information on this map.

© Copyright for Ontario Parcel data is held by King's Printer for Ontario and its licensors and may not be reproduced without permission. THIS IS NOT A PLAN OF SURVEY.

Imagery Copyright Notices: DRAPE © Aéro-Photo (1961) Inc., 2008 - 2009
GTA 2005 / SWOOP 2006 / Simcoe-Muskoka-Dufferin © FirstBase Solutions, 2005 / 2006 / 2008
© King's Printer for Ontario, 2024

Toporama



January 24, 2024

1:10,000

0 0.075 0.15 0.3 mi


0 0.125 0.25 0.5 km

Natural Resources Canada Ressources naturelles Canada

© His Majesty the King in Right of Canada, as represented by the Minister of Natural Resources, 2024.
© Sa Majesté le Roi du chef du Canada, représentée par le ministre de Ressources naturelles Canada, 2024.

Canada


Ontario
Ontario Geological Survey
Queenston
Unit Name: Queenston
Group:
Formation: Queenston
Lithology: shale
Description: shale, siltstone, minor limestone and sandstone
Image © 2024 TerraMetrics
Image NOAA
3.50 mi
Google Earth


Ontario
Ontario Geological Survey
59d
55a
Shale, limestone, dolostone, siltstone
Queenston Formation
Image NOAA
Image Landsat / Copernicus
14.30 mi
Google Earth


Ontario
Ontario Geological Survey
Bedrock, post-Precambrian
undifferentiated carbonate and clastic sedimentary rock, exposed at surface or covered by a discontinuous, thin layer of drift
Paleozoic
Directions: To here - From here
Image © 2024 TerraMetrics
Image NOAA
3.65 mi
Google Earth


Ontario
Ontario Geological Survey
9 Coarse-textured glaciolacustrine deposits
sand, gravel, minor silt and clay
Image © 2024 TerraMetrics
Image NOAA
2.82 mi
Google Earth


Ontario
Ontario Geological Survey
Drift Thickness (m)
High : 262
Low : 0
Image © 2024 TerraMetrics
Image NOAA
3.71 mi
Google Earth


Ontario
Ontario Geological Survey
11 Sand Plains
Sand Plains
Image © 2024 TerraMetrics
Image NOAA
7114 ft
Google Earth


Ontario
Ontario Geological Survey
41 Iroquois Plain
Iroquois Plain
Image NOAA
Image Landsat / Copernicus
12.49 mi
Google Earth

Appendix G
Water Well Records



Water Well Records

Wednesday, January 31, 2024

5:09:26 PM

TOWNSHIP CON LOT	UTM	DATE CNTR	CASING DIA	WATER	PUMP TEST	WELL USE	SCREEN	WELL	FORMATION
BURLINGTON CITY	17 596245 4798354 W	2010/01 7241	1.36			MT	0007 10	7179516 (Z142477) A097678	WHIT HARD 0001 BRWN SAND GRVL LOOS 0003 RED FSND SILT SOFT 0010 GREY SILT TILL HARD 0017
BURLINGTON CITY	17 596261 4798608 W	2019/02 7609	1.97		///:	MO	0005 11	7330856 (Z287723) A242663	FILL SAND 0004 RED TILL SILT 0010 GREY TILL SILT 0016
BURLINGTON CITY	17 596270 4798655 W	2019/02 7609	1.97		///:	MO	0003 10	7330854 (Z287721) A242658	FILL SAND SNDY 0004 RED TILL SILT SLTY 0010 GREY TILL SILT SLTY 0013
BURLINGTON CITY	17 596126 4798177 W	2007/06 6607	1.25	0010			0005 7	7047125 (Z70585) A053612	GREY 0005 RED SAND SILT 0010 RED SAND SILT WBRG 0012
BURLINGTON CITY	17 596224 4798347 W	2017/06 6607						7291911 (C31093) A224440 P	
BURLINGTON CITY	17 596289 4798790 W	2017/05 7241	2			TH MO	0010 10	7290058 (Z260781) A221842	BLCK LOAM 0001 BRWN FILL 0005 BRWN SAND SILT 0013 RED SAND SILT 0020
BURLINGTON CITY	17 596254 4798731 W	2019/02 7609	1.97		///:	MO	0005 11	7330857 (Z287724) A242664	FILL SAND SNDY 0004 RED TILL SILT SLTY 0010 GREY TILL SILT SLTY 0016
BURLINGTON CITY	17 596248 4798355 W	2012/01 7241	2.04			MT	0008 10	7179605 (Z142480) A097679	WHIT HARD 0001 BRWN SAND GRVL LOOS 0003 RED FSND SILT SOFT 0010 GREY SILT TILL HARD 0018
BURLINGTON CITY	17 596305 4798644 W	2019/02 7609	1.97		///:	MO	0005 11	7330855 (Z287722) A242662	FILL SAND FILL 0004 RED TILL SILT SLTY 0010 GREY TILL SILT SLTY 0016
BURLINGTON CITY	17 596232 4798362 W	2012/01 7241	2.04			MT	0007 10	7179515 (Z142479) A097676	BLCK SOFT 0000 BRWN SAND GRVL SOFT 0003 RED FSND SILT SOFT 0010 GREY SILT TILL HARD 0017
BURLINGTON CITY	17 596238 4798370 W	2012/01 7241	2.04			MT	0007 10	7179514 (Z142478) A097677	BLCK SOFT 0000 BRWN SAND GRVL SOFT 0003 RED SILT FSND SOFT 0010 GREY SILT HARD 0017
BURLINGTON CITY	17 596186 4798748 W	2008/01 6607	2.00			MO		7128794 (M00705) A	
BURLINGTON CITY	17 596240 4798302 W	2005/05 1129	7.86 1.97	FR 0008			0003 12	2810308 (Z27865) A026658	LOAM 0001 BRWN SAND SILT CLAY 0011 BRWN CLAY TILL SAND 0015

TOWNSHIP CON LOT	UTM	DATE CNTR	CASING DIA	WATER	PUMP TEST	WELL USE	SCREEN	WELL	FORMATION
BURLINGTON CITY	17 596212 4798276 W	2005/03 7075		0007		NU	0002 12	2810214 (Z25954) A025466	BRWN SAND GRVL SILT 0013 GREY SILT CLAY GRVL 0015
BURLINGTON CITY	17 596252 4798292 W	2005/02 7075	1.97	FR 0011			0005 10	2810171 (Z22705) A025452	BRWN FILL 0011 GREY CLAY GRVL 0015
BURLINGTON CITY	17 596319 4798254 W	2017/03 7241	2			TH MO	0015 10	7284939 (Z253594) A217316	BLCK CMTD 0000 BRWN SILT SAND 0013 RED SHLE 0015
BURLINGTON CITY	17 596270 4798301 W	2020/01 7241	2		///:	MO		7354371 (Z330614) A	
BURLINGTON CITY	17 596314 4798772 W	2020/11 7484						7376950 (Z295975) A255195 P	
BURLINGTON CITY	17 596448 4798658 W	2020/11 7464						7374925 (Z338623) A309623 P	
BURLINGTON CITY	17 596532 4798495 W	2020/09 7644						7369396 (Z341751) A297612 P	
BURLINGTON CITY	17 596481 4798471 W	2020/09 7644						7369395 (Z341752) A297611 P	
BURLINGTON CITY	17 596539 4798591 W	2020/09 7644						7369394 (Z341749) A296263 P	
BURLINGTON CITY	17 596527 4798496 W	2020/09 7644						7369392 (Z341750) A297604 P	
BURLINGTON CITY	17 596295 4798451 W	2018/07 7484	2			MO	0010 5	7314898 (Z261607) A193556	BRWN SAND GRVL FILL 0003 BLCK CLAY SILT FILL 0013 BRWN CLAY SILT 0015
BURLINGTON CITY	17 596292 4798301 W	2020/01 7241			///:			7354375 (Z330613) A	
BURLINGTON CITY	17 596259 4798693 W	2019/02 7609	1.97		///:	MO	0005 11	7330858 (Z287725) A242669	FILL SAND 0004 RED TILL SILT 0010 GREY TILL SILT 0016
BURLINGTON CITY	17 596358 4798561 W	2019/08 7241	2		///:	MT	0006 10	7343299 (Z316535) A257272	GREY ---- 0000 BRWN SAND GRVL FILL 0002 BRWN SAND SILT 0016
BURLINGTON CITY	17 596377 4798547 W	2019/08 7241	2		///:	MT	0007 10	7343298 (Z316537) A257274	BLCK ---- 0000 BRWN SAND GRVL FILL 0002 BRWN SAND 0011 BRWN SAND SILT 0017

TOWNSHIP CON LOT	UTM	DATE CNTR	CASING DIA	WATER	PUMP TEST	WELL USE	SCREEN	WELL	FORMATION
BURLINGTON CITY	17 596347 4798549 W	2019/08 7241	2		///:	MT	0014 10	7343297 (Z316536) A257273	BRWN SAND GRVL FILL 0003 BRWN SAND SILT 0017 RED SILT SAND 0024
BURLINGTON CITY	17 596494 4798533 W	2018/08 7295	1.79		///:	MO	0010 10	7331850 (Z297195) A237091	BRWN FILL 0003 BRWN CLAY 0010 RED SHLE WBRG 0020
BURLINGTON CITY	17 596288 4798651 W	2019/02 7609	1.97		///:	MO	0010 10	7330859 (Z287726) A242657	FILL SAND SNDY 0004 RED TILL SILT SLTY 0010 GREY TILL SILT SLTY 0016 GREY CLAY DNSE 0020
BURLINGTON CITY BB	17 596336 4798785 W	2017/06 7472	2			MO	0015 5	7292314 (Z259637) A227433	BRWN SILT GRVL FILL 0006 BRWN SILT CLAY TILL 0018 GREY SAND SILT TILL 0020
BURLINGTON CITY BB	17 596336 4798786 W	2017/06 7472	2			MO	0025 5	7292315 (Z259636) A227432	BRWN SILT GRVL FILL 0006 BRWN SILT CLAY TILL 0018 GREY SAND SILT TILL 0030
BURLINGTON CITY BB	17 596361 4798743 W	2017/06 7472	2			MO	0013 5	7292316 (Z259635) A227431	BRWN LOAM LOOS 0001 BRWN SILT GRVL FILL 0006 BRWN SILT CLAY TILL 0018
BURLINGTON CITY BB	17 596352 4798776 W	2017/06 7472	2			MO	0013 5	7292317 (Z259634) A227430	BRWN SILT GRVL FILL 0006 BRWN SILT CLAY TILL 0018
BURLINGTON CITY BB	17 596458 4798519 W	2021/04 7241						7387995 (Z361255) A333003 P	
BURLINGTON CITY BB	17 596482 4798555 W	2021/04 7241						7387993 (Z361257) A333001 P	
BURLINGTON CITY BB	17 596452 4798579 W	2021/04 7241						7387994 (Z361256) A333002 P	
BURLINGTON CITY BB	17 596309 4798244 W	2017/03 7241	2			TH MO	0015 10	7284940 (Z253701) A217268	BLCK CMTD 0000 BRWN SILT SAND 0013 RED SHLE 0015
MILTON TOWN (NELSON)	17 596361 4798305 W	2007/04 7147	1.97			NU	0003 10	7042731 (Z64348) A048929	BLCK LOAM 0001 BRWN SILT SAND 0013

Notes:
UTM: UTM in Zone, Easting, Northing and Datum is NAD83; L: UTM estimated from Centroid of Lot; W: UTM not from Lot Centroid
DATE CNTR: Date Work Completedand Well Contractor Licence Number
CASING DIA: Casing diameter in inches
WATER: Unit of Depth in Fee. See Table 4 for Meaning of Code

PUMP TEST: Static Water Level in Feet / Water Level After Pumping in Feet / Pump Test Rate in GPM / Pump Test Duration in Hour : Minutes
WELL USE: See Table 3 for Meaning of Code
SCREEN: Screen Depth and Length in feet
WELL: WEL (AUDIT #) Well Tag . A: Abandonment; P: Partial Data Entry Only
FORMATION: See Table 1 and 2 for Meaning of Code

1. Core Material and Descriptive terms

Code	Description	Code	Description	Code	Description	Code	Description	Code	Description
BLDR	BOULDERS	FCRD	FRACTURED	IRFM	IRON FORMATION	PORS	POROUS	SOFT	SOFT
BSLT	BASALT	FGRD	FINE-GRAINED	LIMY	LIMY	PRDG	PREVIOUSLY DUG	SPST	SOAPSTONE
CGRD	COARSE-GRAINED	FGVL	FINE GRAVEL	LMSN	LIMESTONE	PRDR	PREV. DRILLED	STKY	STICKY
CGVL	COARSE GRAVEL	FILL	FILL	LOAM	TOPSOIL	QRTZ	QUARTZITE	STNS	STONES
CHRT	CHERT	FLDS	FELDSPAR	LOOS	LOOSE	QSND	QUICKSAND	STNY	STONEY
CLAY	CLAY	FLNT	FLINT	LTCL	LIGHT-COLOURED	QTZ	QUARTZ	THIK	THICK
CLN	CLEAN	FOSS	FOSILIFEROUS	LYRD	LAYERED	ROCK	ROCK	THIN	THIN
CLYY	CLAYEY	FSND	FINE SAND	MARL	MARL	SAND	SAND	TILL	TILL
CMTD	CEMENTED	GNIS	GNEISS	MGRD	MEDIUM-GRAINED	SHLE	SHALE	UNKN	UNKNOWN TYPE
CONG	CONGLOMERATE	GRNT	GRANITE	MGVL	MEDIUM GRAVEL	SHLY	SHALY	VERY	VERY
CRYS	CRYSTALLINE	GRSN	GREENSTONE	MRBL	MARBLE	SHRP	SHARP	WBRG	WATER-BEARING
CSND	COARSE SAND	GRVL	GRAVEL	MSND	MEDIUM SAND	SHST	SCHIST	WDFR	WOOD FRAGMENTS
DKCL	DARK-COLOURED	GRWK	GREYWACKE	MUCK	MUCK	SILT	SILT	WTHD	WEATHERED
DLMT	DOLOMITE	GVLY	GRAVELLY	OBDN	OVERBURDEN	SLTE	SLATE		
DNSE	DENSE	GYPS	GYPSUM	PCKD	PACKED	SLTY	SILTY		
DRTY	DIRTY	HARD	HARD	PEAT	PEAT	SNDS	SANDSTONE		
DRY	DRY	HPAN	HARDPAN	PGVL	PEA GRAVEL	SNDY	SANDYOAPSTONE		

2. Core Color

Code	Description
WHIT	WHITE
GREY	GREY
BLUE	BLUE
GREN	GREEN
YLLW	YELLOW
BRWN	BROWN
RED	RED
BLCK	BLACK
BLGY	BLUE-GREY

3. Well Use

Code	Description	Code	Description
DO	Domestic	OT	Other
ST	Livestock	TH	Test Hole
IR	Irrigation	DE	Dewatering
IN	Industrial	MO	Monitoring
CO	Commercial	MT	Monitoring TestHole
MN	Municipal		
PS	Public		
AC	Cooling And A/C		
NU	Not Used		

4. Water Detail

Code	Description	Code	Description
FR	Fresh	GS	Gas
SA	Salty	IR	Iron
SU	Sulphur		
MN	Mineral		
UK	Unknown		

Appendix H
Table of Current And Past Land Uses



1393 Grahams Laane, Burlington, Ontario
TABLE OF CURRENT AND PAST USES OF THE PHASE ONE PROPERTY
(Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04)

Project No: 02211083.001
Address: 1393 Grahams Lane Burlington
Pin:07090-0669(LT) Pretaining to Part 1, 20R21599

Year	Name of Owner	Description of Property Use	Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, Etc.
2022-Present	1256384 B.C. Ltd.	Parking Lot	Commercial Use	2024 Aerial Photograph Property is developed as a Parking lot
2020-2022	2584979 Ontario Inc.			No Other Observations
1959-2020	Trustees for Burlington Vinton Memorial Branch 60 of the Royal Canadian Legion			1979 FIP, 1989 & 2009 Aerial Photographs, Property is developed as a parking lot
1951-1959	William MacDonald Jr.	Undeveloped Agricultural Land	Agricultural or Other Use	No Other Observations
1920-1951	William MacDonald			
1918-1920	Robert Moseley Thompson			
1904-1918	Joseph Anderson, Henry Zeats			
1904-1909	Joseph M. Martin			
1878-1904	Johnston Zimmerman			
1878-1878	Thomas Cashman			
1877-1878	George N. Hill			
1855-1877	George Hill			
1843-1855	John Hogarth			
1840-1843	William Reynolds			
1835-1840	William Tisdale			
1828-1835	William Reynolds			
1825-1828	Francis J. Harold			
1825-1825	William Reynolds			
1815-1825	Augustus Bates			
1809-1815	Benjamin Mallony			
1808-1809	John Heigh			
1808-1808	Benjamin Mallony			
1803-1808	Robert Wilson			
1798-1803	Capt. Joseph Brant			
Prior to 1798	Crown			

Notes:
1 - for each owner, specify one of the following types of property use (as defined in O.Reg. 153/04) that applies:
Agriculture or other use
Commercial use
Community use
Industrial use
Institutional use

Parkland use
Residential use
2 - when submitting a record of site condition for filing, a copy of this table must be attached
**Cette publication hautement spécialisée n'est disponible qu'en anglais en vertu du règlement 671/92, qui en exempte l'application de la Loi sur les services en français. Pour obtenir de l'aide en francais, veuillez communiquer avec le ministère de l'Environnement au 1-800-461-6290
SI: Satellit Image
FIP: Fire Insurance Plan
CD: City Directories
AP: Air Photo

TABLE OF CURRENT AND PAST USES OF THE PHASE ONE PROPERTY
(Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04)

Project No: 02211083.001
Address: 1393 Grahams Lane Burlington
Pin:07090-0669(LT) Pretaining to Part 1, 20R3140

Year	Name of Owner	Description of Property Use	Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, Etc.
2022-Present	1256384 B.C. Ltd.	Commercial Building	Commercial Use	2024 Aerial Photo - Property is developed with a commercial building and assoicated driveways and parking lots
2017-2022	2584979 Ontario Limited			No Other Observations
2014-2017	1916310 Ontario Limited			
2009-2014	Don Marie Walker			2009 Aerial Photo Property is developed with a commercial building
2003-2009	Erbdocs Inc.			
1980-2003	Selenex Corporation Limited			1989 Aerial Photograph - Property is developed with a commercial building
1973-1980	Matys Industries Limited (fmly Matys Designs Limited)			1979 FIP - Property is developed with a commercial building
1973-1973	Francis Shaw (Canada) Limited	Undeveloped Land	Commercial Use	No Other Observations
1959-1973	Trustees for Burlington Vinton Memorial Branch 60 of the Royal Canadian Legion	Part of Royal Canadian Legion Branch 60 Hall Lands	Commercial Use	No Other Observations
1956-1959	John Nicoll Blair & George Stanley Blair			
1944-1956	Ignac Sawczyszyn, & Irene Sawczysnzyn			
1928-1944	Abraham K. Hunt			
1927-1928	T. Gordon Brown			
1925-1927	Row Bertie Butler & Walter Francis Butler			
1919-1925	Kenneth Allen & Clara Aline Allen			
1911-1919	Elmer Hall			
1904-1911	Joseph Anderson, Henry Zeats			
1904-1904	Joseph M. Martin			

TABLE OF CURRENT AND PAST USES OF THE PHASE ONE PROPERTY
(Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04)

Project No: 02211083.001
Address: 1393 Grahams Lane Burlington
Pin:07090-0669(LT) Pretaining to Part 1, 20R3140

Year	Name of Owner	Description of Property Use	Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, Etc.
1878-1904	Johnston Zimmerman	Undeveloped Land	Agricultural or Other Use	No Other Observations
1878-1878	Thomas Cashman			
1877-1878	George N. Hill			
1855-1877	George Hill			
1843-1855	John Hogarth			
1840-1843	William Reynolds			
1835-1840	William Tisdale			
1828-1835	William Reynolds			
1825-1828	Francis J. Harold			
1825-1825	William Reynolds			
1815-1825	Augustus Bates			
1809-1815	Benjamin Mallony			
1808-1809	John Heigh			
1808-1808	Benjamin Mallony			
1803-1808	Robert Wilson			
1798-1803	Capt. Joseph Brant			
Prior to 1798	Crown			

Notes:
1 - for each owner, specify one of the following types of property use (as defined in O.Reg. 153/04) that applies:
Agriculture or other use
Commercial use
Community use
Industrial use
Institutional use
Parkland use
Residential use
2 - when submitting a record of site condition for filing, a copy of this table must be attached
**Cette publication hautement spécialisée n'est disponible qu'en anglais en vertu du règlement 671/92, qui en exempte l'application de la Loi sur les services en français. Pour obtenir de l'aide en francais, veuillez communiquer avec le ministère de l'Environnement au 1-800-461-6290
SI: Satellit Image
FIP: Fire Insurance Plan
CD: City Directories
AP: Air Photo

Appendix I
APEC Table



TABLE OF AREAS OF POTENTIAL ENVIRONMENTAL CONCERN
(Refer to clause 16(2)(a), Schedule D, O. Reg. 153/04)

Area of Potential Environmental Concern	Location of Area of Potential Environmental Concern on Phase One Property	Potentially Contaminating Activity	Location of PCA (on-site or off-site)	Contaminants of Potential Concern	Media Potentially Impacted (Ground water, soil and/or sediment)
APEC 1	Southern Portion of Phase One Property	#19 - Electronic and Computer Equipment Manufacturing	On-Site	Metals, As, Sb, Se, B-HWS, CN-, Hg, Cr(VI), pH, EC, PHCs, BTEX, VOCs, PAHs	Soil and Groundwater
APEC 2	Southern Portion of Phase One Property	#34 - Metal Fabrication	On-Site	Metals, As, Sb, Se, B-HWS, CN-, Hg, Cr(VI), pH	Soil and Groundwater
APEC 3	Exterior Western Wall of Commercial Building	#28 - Gasoline and Associated Products Storage in Fixed Tanks	On-Site	PHCs, BTEX, VOCs	Soil and Groundwater
APEC 4	Midway point along fence on Western Property	#28 - Gasoline and Associated Products Storage in Fixed Tanks	On-Site	PHCs, BTEX, VOCs	Soil and Groundwater
APEC 5	Southern Portion of Phase One Property	Others 1 - Ontario Regulation 347 - Waste Generator	On-Site	Metals, As, Sb, Se, B-HWS, CN-, Hg, Cr(VI), pH, EC, PHCs, BTEX, VOCs, PAHs	Soil and Groundwater
APEC 6	Across Phase One Property	Others 2 - Salt Application for De-Icing Purposes	On-Site	SAR, EC, Na, Cl	Soil and Groundwater
APEC 7	Southern Property Boundary	Others 1 - Ontario Regulation 347 - Waste Generator	Off-Site	Metals, As, Sb, Se, B-HWS, CN-, Hg, Cr(VI), pH, EC, SAR, PHCs, BTEX, VOCs, PAHs, PCBs	Soil and Groundwater
		#28 - Gasoline and Associated Products Storage in Fixed Tanks			
		#18 – Electricity Generation, Transformation and Power Stations			
		#55 – Transformer Manufacturing, Processing and Use			
		#57: Vehicles and Associated Parts Manufacturing			
		#34 – Metal Fabrication			
		#31 – Ink Manufacturing, Processing and Bulk Storage			
		#8 – Chemical Manufacturing, Processing, and Bulk Storage			
		#33 – Metal Treatment, Coating, Plating, & Finishing			
		#10 - Commercial Auto Body Shops			
		#19 – Electronic and Computer Equipment Manufacturing			
		Others 1 - Ontario Regulation 347 - Waste Generator			
		#40 - Pesticides (including Herbicides, Fungicides and Anti-Fouling Agents) Manufacturing, Processing, Bulk Storage and Large-Scale Applications			
		#45 – Pulp, Paper, and Paperboard Manufacturing & Processing			

TABLE OF AREAS OF POTENTIAL ENVIRONMENTAL CONCERN
(Refer to clause 16(2)(a), Schedule D, O. Reg. 153/04)

Area of Potential Environmental Concern	Location of Area of Potential Environmental Concern on Phase One Property	Potentially Contaminating Activity	Location of PCA (on-site or off-site)	Contaminants of Potential Concern	Media Potentially Impacted (Ground water, soil and/or sediment)
APEC 8	Northern Property Boundary	#31 – Ink Manufacturing, Processing and Bulk Storage	Off-Site	Metals, As, Sb, Se, B-HWS, CN-, Hg, Cr(VI), pH, EC, PHCs, BTEX, VOCs, PAHs, PCBs	Soil and Groundwater
		#59 – Wood Treating and Preservative Facility and Bulk Storage of Treated and Preserved Wood Products			
		#54 – Textile Manufacturing and Processing			
		#34 – Metal Fabrication			
		#33 - Metal Treatment, Coating, Plating and Finishing			
		PCA #10 – Commercial Auto Body Shops			
		#43 - Plastics (including Fibreglass) Manufacturing and Processing			
APEC 9	Eastern Property Boundary	#10 - Commercial Auto Body Shops	Off-Site	Metals, As, Sb, Se, B-HWS, CN-, Hg, Cr(VI), pH, EC, PHCs, BTEX, VOCs, PAHs	Soil and Groundwater
		#34 - Metal Fabrication			
APEC 10	Western Property Boundary	#46 Rail Yards, Tracks and Spurs	Off-Site	Metals, As, Sb, Se, B-HWS, CN-, Hg, Cr(VI), pH, EC, PHCs, BTEX, VOCs, PAHs, PCBs	Soil and Groundwater
		Others 1 - Ontario Regulation 347 - Waste Generator			

Notes:
1 - Area of Potential Environmental Concern means the area on, in or under a phase one property where one or more contaminants are potentially present, as determined through the phase one environmental site assessment, including through,
(a) identification of past or present uses on, in or under the phase one property, and
(b) identification of potentially contaminating activity.

2 - Potentially Contaminating Activity means a use or activity set out in Column A of Table 2 of Schedule D that is occurring or has occurred in a phase one study area

3 - when completing this column, identify all contaminants of potential concern using the Method Groups as identified in the Protocol for in the Assessment of Properties under Part XV.1 of the Environmental Protection Act, March 9, 2004, amended as of July 1, 2011, as specified below:
ABNs, PCBs, Metals, Electrical Conductivity, SAR, CPs, PAHs, As, Sb, Se, Cr (VI),
1,4-Dioxane, THMs, Na, Hg, Dioxins/Furans, PCDDs/PCDFs VOCs, B-HWS, Methyl Mercury,
Ocs, BTEX, Cl-, high pH, PHCs, Ca, Mg, CN-, low pH

4 - when submitting a record of site condition for filing, a copy of this table must be attached

Appendix J
Phase One Conceptual Site Model



1393 GRAHAMS LANE
BURLINGTON, ONTARIO
PHASE ONE CONCEPTUAL SITE MODEL

Phase One CSM		Information Pertaining to Property
Figures of the Phase One Study Area are provided that:		
i.	Show any existing buildings and structures,	The Property is developed for commercial land use with a two-storey commercial warehouse building with associated at grade parking lots and driveways on the Property.
ii.	Identify and locate water bodies located in whole or in part on the Phase One Study Area	There are no surface water bodies or features located on the Property. The Property is relatively flat-lying, gently rolling with a slight slope to the north toward Upper Hager Creek. Thus, surface water is directed towards the north.
iii.	Identify and locate any Area of Natural Significance located in whole or in part on the Phase One Study Area	Englobe reviewed the Ontario Ministry of Natural Resources NHIC database for natural area listings. No provincially significant wetland is present in the Study Area.
iv.	Locate any drinking water wells at the Phase One Property	No drinking water well was identified at the Property. No domestic wells were found in the MECP Water Well Information System (WWIS) within the Study Area.
v.	Show roads, including names, within the Phase One Study Area	The Property is bounded by Grahams Lane to the south, commercial land use to the east and north, and residential land use to the west. Other roads and properties within the Study Area are presented in Figure 4.
vi.	Show use of properties adjacent to the Phase One Property	The land uses of the adjacent properties are shown in Figure 4. The neighboring properties to the Phase One Property are primarily in residential land use or commercial land use.
vii.	Identify and locate area where any potentially contaminating activity has occurred, and show tanks in such areas	Potentially Contaminating Activities (PCAs) located on the Property and within the Study Area are presented in Figure 3.
viii.	Identify and locate any areas of potential environmental concern	Ten (10) Areas of Potential Environmental Concern (APECs) were identified on the Property. The locations of the APECs are presented in Figure 6 and the description of the APECs and Contaminants of Potential Concern (COPCs) are described in the Table of Areas of Potential Concern.
The following is a description and assessment of:		
i.	Any areas where potentially contaminating activity on or potentially affecting the Phase One Property has occurred.	See above list of APECs
ii.	Any contaminants of potential concern,	Contaminants of Potential Concern (COPCs) identified on the Property that have potential to be present in soil and groundwater: • Metals, As, Sb, Se, B-HWS, CN-, Hg, Cr(VI) • pH, EC

		• PHCs • BTEX • VOCs • PAHs • PCBs
iii.	The potential for underground utilities, if any present, to affect contaminant distribution and transport	There are underground utilities located on the Property, as such, the potential for contaminant distribution is present.
iv.	Available regional or site specific geological and hydrogeological information,	Topography • The elevation of the Property is approximately 95m above mean sea level (masl). Hydrogeology • There are no surface water bodies or features located on the Property. The Property is relatively flat-lying, gently rolling with a slight slope to the north toward Upper Hager Creek. Thus, surface water is directed towards the north. Geology (overburden) • Comprised of predominantly sand and gravel with minor silt and clay. Geology (bedrock) • The bedrock on the Property is of the Queenston formation, which is comprised of shale, minor limestone, sandstone, dolostone and siltstone. Geology (depth to bedrock) • Based on the published information, the depth of bedrock in the vicinity is approximately 20 m below ground surface.
v.	How any uncertainty or absence of information obtained in each of the components of the Phase One ESA could affect the validity of the model.	No uncertainty was encountered while conducting the Phase One ESA that could affect the validity of the model.

Appendix K
Fire Insurance Plans



opta
INFORMATION INTELLIGENCE

enviroscan







175 Commerce Valley Drive W
Markham, Ontario L3T 7Z3

T: 1 877 244 9437
W: optaintel.ca

Nate

Site Address:

1393 Grahams Lane, Burlington, ON

Project No:

24011900269

Opta Order ID:

139263

Requested by:

Eleanor Goolab
ERIS

Date Completed:

1/31/2024 7:17:27 PM

Project Name: 1393 Grahams Lane


Project #: 24011900269
P.O. #: 02211083.001

ENVIROSCAN Report

Search Area: 1393 Grahams Lane, Burlington, ON

Requested by:
Eleanor Goolab
Date Completed: 01/31/2024 19:17:27

enviroscan
OPTA INFORMATION INTELLIGENCE



This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

Opta Historical Environmental Services Enviroscan™ Terms and Conditions

Report

The documents (hereinafter referred to as the "Documents") to be released as part of the report (hereinafter referred to as the "Report") to be delivered to the purchaser as set out above are documents in Opta's records relating to the described property (hereinafter referred to as the "Property"). Opta makes no representations or warranties respecting the Documents whatsoever, including, without limitation, with respect to the completeness, accuracy or usefulness of the Documents, and does not represent or warrant that these are the only plans and reports prepared in association with the Property or in Opta's possession at the time of Report delivery to the purchaser. The Documents are current as of the date(s) indicated on them. Interpretation of the Documents, if any, is by inference based upon the information which is apparent and obvious on the face of the Documents only. Opta does not represent, warrant or guarantee that interpretations other than those referred to do not exist from other sources. The Report will be prepared for use by the purchaser of the services as shown above hereof only.

Disclaimer

Opta disclaims responsibility for any losses or damages of any kind whatsoever, whether consequential or other, however caused, incurred or suffered, arising directly or indirectly as a result of the services (which services include, but are not limited to, the preparation of the Report provided hereunder), including but not limited to, any losses or damages arising directly or indirectly from any breach of contract, fundamental or otherwise, from reliance on Opta Reports or from any tortious acts or omissions of Opta's agents, employees or representatives.

Entire Agreement

The parties hereto acknowledge and agree to be bound by the terms and conditions hereof. The request form constitutes the entire agreement between the parties pertaining to the subject matter hereof and supersedes all prior and contemporaneous agreements, negotiations and discussions, whether oral or written, and there are no representations or warranties, or other agreements between the parties in connection with the subject matter hereof except as specifically set forth herein. No supplement, modification, waiver, or termination of the request shall be binding, unless confirmed in writing by the parties hereto.

Governing Document

In the event of any conflicts or inconsistencies between the provisions hereof and the Reports, the rights and obligations of the parties shall be deemed to be governed by the request form, which shall be the paramount document.

Law

This agreement shall be governed by and construed in accordance with the laws of the Province of Ontario and the laws of Canada applicable therein.

ENVIROSCAN Report

Report Index

OPTA INFORMATION INTELLIGENCE

Page	Report Title
6	(1971) Volume: Burlington Firemap: 44
8	(1971) Volume: Burlington Firemap: 49
10	(1971) Volume: Burlington Firemap: 49

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

N
W E
S

Project Name: 1393 Grahams Lane

Project #: 24011900269
P.O. #: 02211083.001


ENVIROSCAN Report

1971 Volume: Burlington Firemap: 44
Burlington Plan: 296 (1971)
Sheet: 44 (1971)

Requested by:
Eleanor Goolab
Date Completed: 01/31/2024 19:17:27

enviroscan
OPTA INFORMATION INTELLIGENCE

FIP Locator Map
The detailed FIP is on the following page




This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

ENVIROSCAN Report

1971 Volume: Burlington Firemap: 44
Burlington Plan: 296 (1971)
Sheet: 44 (1971)

Requested by:
Eleanor Goolab
Date Completed: 01/31/2024 19:17:27

OPTA INFORMATION INTELLIGENCE



Project Name: 1393 Grahams Lane

Project #: 24011900269
P.O. #: 02211083.001

ENVIROSCAN Report


1971 Volume: Burlington Firemap: 49
Burlington Plan: 296 (1971)
Sheet: 49 (1971)

Requested by:
Eleanor Goolab
Date Completed: 01/31/2024 19:17:27

enviroscan
OPTA INFORMATION INTELLIGENCE

FIP Locator Map

The detailed FIP is on the following page




This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

ENVIROSCAN Report

1971 Volume: Burlington Firemap: 49
Burlington Plan: 296 (1971)
Sheet: 49 (1971)

Requested by:
Eleanor Goolab
Date Completed: 01/31/2024 19:17:27

OPTA INFORMATION INTELLIGENCE



Project Name: 1393 Grahams Lane

Project #: 24011900269
P.O. #: 02211083.001

ENVIROSCAN Report


1971 Volume: Burlington Firemap: 49
Burlington Plan: 296 (1971)
Sheet: 49 (1971)

Requested by:
Eleanor Goolab
Date Completed: 01/31/2024 19:17:27

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

FIP Locator Map
The detailed FIP is on the following page



ENVIROSCAN Report

1971 Volume: Burlington Firemap: 49
Burlington Plan: 296 (1971)
Sheet: 49 (1971)

Requested by:
Eleanor Goolab
Date Completed: 01/31/2024 19:17:27

OPTA INFORMATION INTELLIGENCE

