Phase One Environmental Site Assessment

1376 and 1382 Plains Road East, Burlington, ON

Client:
273119 Ontario Inc., Manor Care Homes Inc., F.K Deals on Wheels Inc.,
2731115 Ontario Inc.
2235 Sheppard Ave E., Suite 1700
North York, ON M2J 5B5

Attention: Mr. Nolan Moss

Type of Document:
Final

Project Name:
Phase One Environmental Site Assessment

Project Number:
GTR-222029872-A0

EXP Services Inc.
1595 Clark Boulevard
Brampton, ON, L6T 4V1
t: 905.793.9800
f: 905.793.0641

Date Submitted:
2023-07-25

Table of Contents

1 Executive Summary 4
2 Introduction 8
2.1 Site Information 8
3 Scope of Investigation 10
4 Record Review 11
4.1 General 11
4.1.1 Phase One Study Area Determination 11
4.1.2 First Developed Use Determination 11
4.1.3 Fire Insurance Plans 11
4.1.4 Chain of Title 13
4.1.5 Environmental Reports 14
4.2 Environmental Source Information 14
4.2.1 Federal and Provincial Database Search 14
4.2.2 Municipal Records 16
4.2.3 Ontario Ministry of the Environment Records 18
4.2.4 Technical Standards and Safety Authority 18
4.2.5 Record of Site Condition 18
4.3 Physical Setting Sources 19
4.3.1 Aerial Photographs 19
4.3.2 Topography, Hydrology and Geology 22
4.3.3 Fill Materials 22
4.3.4 Areas of Natural Significance 22
4.3.5 Well Records 22
4.4 Site Operating Records 23
5. Interviews 24
6. Site Reconnaissance 25
6.1 General Requirements 25

6.2 Specific Observations at Phase One ESA Property 25
6.2.1 Site Description and Buildings 25
6.2.2 Heating and Cooling Systems 25
6.2.3 Site Utilities and Services 25
6.2.4 Sewage and Wastewater Disposal 26
6.2.5 Potable Water Sources 26
6.2.6 Abandoned and Existing Wells 26
6.2.7 Site Production and Manufacturing 26
6.2.8 Drains, Pits and Sumps 26
6.2.9 Storage Tanks 26
6.2.10 Water Wells 26
6.2.11 Site Housekeeping 27
6.2.12 Chemical Storage and Handling and Floor Condition 27
6.2.13 Areas of Stained Soil, Pavement or Stressed Vegetation 27
6.2.14 Fill and Debris 27
6.2.15 Air Emissions 27
6.2.16 Polychlorinated Biphenyls (PCBs) 27
6.3 Enhanced Investigation Property Observations 27
6.4 Adjacent and Surrounding Properties 28
6.5 Written Description of Investigation 28
7. Review and Evaluation of Information 29
7.1 Current and Past Uses 29
7.2 Potentially Contaminating Activities (PCAs) 29
7.3 Areas of Potential Environmental Concern (APECs) 29
8. Conclusions 30
8.1 Whether Phase Two ESA Required Before RSC Submitted 30
8.2 RSC Based on Phase One ESA Alone 32
9 Closure 33
10 References 34

Appendices

Figures

Tables

Appendix A – Liability

Appendix B – Survey Plan

Appendix C – Qualifications

Appendix D – Chain of Title

Appendix E – ERIS Report and Insurance Products

Appendix F – Municipal Records

Appendix G – Regulatory Requests

Appendix H – Aerials

Appendix I – Site Photographs

Appendix J – Phase One Conceptual Site Model

1 Executive Summary

EXP Services Inc. (EXP) was retained by 273119 Ontario Inc., Manor Care Homes In., F.K Deals on Wheels Inc., 2731115 Ontario Inc. (the "Client") to complete a Phase One Environmental Site Assessment (ESA) of a parcel of land that encompasses two (2) adjacent properties with the municipal address 1376 and 1382 Plains Road East, in Burlington, Ontario, as well as the laneways adjacent to these properties. These lands are collectively herein after referred to as the "Site".

For the purposes of this report the alignment of Plains Road East is assumed to be in an east-west direction, with the Site being located on the southside of Plains Road East. The Site is an irregularly shaped parcel of land that measures approximately 0.33 hectares (083 acres).

Based on the records review, the Site was developed prior to 1924 with the two (2) buildings that were identified as residential dwellings in the reviewed fire insurance plans (FIP). The buildings had the municipal addresses 41 and 43 Plains Road East. Circa the early 1970s, the Site buildings were assigned the currently municipal addresses 1376 and 1382 Plains Road East. The building extension on the Site building at 1376 Plains Road East was developed prior to 1971 based on the reviewed FIP. The on-Site areas surrounding the Site buildings have been paved and developed as laneways and parking lots for the Site buildings. Landscaped areas with grass cover were observed adjacent to the northern and southwestern Site boundaries.

According to the records review, since development, the Site buildings have been developed for residential and commercial use.

It is EXP's understanding that the Client is redeveloping the Site with one (1) multi-storey residential building with one (1) level of underground parking This redevelopment of the Site will require a Record of Site Condition (RSC) to be filed. As such, the objective of the investigation is to support the filing of a Record of Site Condition (RSC) in accordance with Ontario Regulation 153/04, as amended (O.Reg.153/04).

A Phase One ESA is a systematic qualitative process to assess the environmental condition of a Site based on its historical and current uses. This Phase One ESA was conducted in accordance with the Phase One ESA standard as defined by O.Reg.153/04, and in accordance with generally accepted professional practices. Subject to this standard of care, EXP makes no express or implied warranties regarding its services and no third-party beneficiaries are intended. Limitation of liability, scope of report and third-party reliance are outlined in Appendix A.

It is noted that general environmental management and housekeeping practices were reviewed as part of this assessment insofar as they could impact the environmental condition of the property. However, a detailed review of regulatory compliance issues was beyond the scope of our investigation. This Phase One ESA does not constitute an audit of environmental management practices, indicate geotechnical conditions, or identify geologic hazards.

Based on the Phase One ESA findings, the following information is provided in Table 1-1 in support of the Phase One Qualified Person's (QP's) conclusion:

Table 1-1: Areas of Potential Environmental Concern

Area of Potential Environmental Concern (APEC)	Location of APEC on Phase One Property	Potentially Contaminating Activity (PCA)[1]	Location of PCA (on-Site or off-Site)	Contaminants of Potential Concern	Media Potentially Impacted (Groundwater, soil and/or sediment)
APEC 1A: Application of De-icing salt on the on-Site paved areas (PCA 1A)	Asphalt paved driveways and walking areas at the Site	PCA" Other"- Application of De-icing salt	On-Site	EC and SAR	Soil
APEC 1B: Former storage of heating oil at 1376 Plains Road East (PCA 1B)	Southern portion of the building (prior to the extension)	PCA#28-Gasoline and Associated Products Storage in Fixed Tanks	On-Site	PHCS, PAH and BTEX	Soil and Ground Water
APEC 1C: Former storage of heating oil at 1382 Plains Road East (PCA 1C)	Southern portion of the building, where the furnace room is located	PCA#28-Gasoline and Associated Products Storage in Fixed Tanks	On-Site	PHCs, PAH and BTEX	Soil and Ground Water
APEC 2: Auto Service to the west of the Site (PCA 2 and 3A-C)	Western Site boundary	PCA#27-Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles #52-Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems	Off-Site 1364 Plains Road East (20 m west) 1358 Plains Road East (former 1364 Plains Road East) 1368 Plains Road East (West adjacent)	PHCs, PAH, VOCs and Metals	Groundwater

Area of Potential Environmental Concern (APEC)	Location of APEC on Phase One Property	Potentially Contaminating Activity (PCA)[1]	Location of PCA (on-Site or off-Site)	Contaminants of Potential Concern	Media Potentially Impacted (Groundwater, soil and/or sediment)
APEC 3: Current presence of auto service to the east adjacent to Site (PCA 4A) Former presence of printing facility east adjacent to Site (PCA 4B)	Eastern Site boundary	#52-Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems PCA#31- Ink Manufacturing, Processing and Bulk Storage	Off-Site- east adjacent 1400 Plains Road East (PCA4C) Off-Site 1390 Plains Road East (PCA4B)	PHCs, PAH, VOCs and Metals	Groundwater
APEC 4: Former presence of a fruit canning company southeast adjacent to Site (PCA5A-C)	Southeastern Site boundary	PCA#2-Adhesives and Resins Manufacturing, Processing and Bulk Storage	Off-Site – southeast adjacent	VOCs, PHCs, Metals	Groundwater
		PCA#4- Antifreeze and De-icing Manufacturing and Bulk Storage			
		PCA#34-Metal Fabrication			
APEC 5: Historical auto repair at 1401 Plains Road East (PCA 7)	Northeastern boundary of the Site	#52-Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems	Off-Site – 25 m north	PHCs, PAH, VOCs and Metals	Groundwater
APEC 6: Presence of a rail line in close proximity to Site (PCA 6)	Southwestern boundary of the Site	PCA#46-Rail Yards, Tracks and Spurs	Off-Site- 5 m south	Metals, PAHs and PHCs	Groundwater

(1) Potentially contaminating activity means a use or activity set out in Column A of Table 2 of Schedule D (O.Reg.153/04, as amended) that is occurring or has occurred in a phase one Study area.

Based on the findings of the Phase One ESA and conclusions, a Phase Two ESA is required to assess the soil and groundwater conditions at the Site prior to submitting an RSC.

This executive summary is a brief synopsis of the report and should not be read in lieu of reading the report in its entirety.

2 Introduction

EXP Services Inc. (EXP) was retained by 273119 Ontario Inc., Manor Care Homes In., F.K Deals on Wheels Inc., 2731115 Ontario Inc. (the "Client") to complete a Phase One Environmental Site Assessment (ESA) of the two (2) adjacent properties with the municipal address 1376 and 1382 Plains Road East, in Burlington, Ontario, as well as the laneways adjacent to these properties. These lands are collectively herein after referred to as the "Site".

For the purposes of this report the alignment of Plains Road East is assumed to be in an east-west direction, with the Site being located on the southside of Plains Road East.

It is EXP's understanding that the Client is redeveloping the Site with one (1) multi-storey residential building with one (1) level of underground parking. This redevelopment of the Site will require a Record of Site Condition (RSC) to be filed. As such, the objective of the investigation is to support the filing of a Record of Site Condition (RSC) in accordance with Ontario Regulation 153/04, as amended (O.Reg.153/04).

A Phase One ESA is a systematic qualitative process to assess the environmental condition of a Site based on its historical and current uses. This Phase One ESA was conducted in accordance with the Phase One ESA standard as defined by O.Reg.153/04, and in accordance with generally accepted professional practices. Subject to this standard of care, EXP makes no express or implied warranties regarding its services and no third-party beneficiaries are intended. Limitation of liability, scope of report and third-party reliance are outlined in Appendix A.

It should be noted that the objective of this review was to identify any environmental concerns associated with the Site.

2.1 Site Information

Details of the Site are as follows:

Municipal Address	1376 and 1382 Plains Road East, Burlington, ON
Current Land Use	Commercial Use
Proposed Land Use	Residential Use
Legal Description	1376 Plains Rd E - Pt Lts 18 & 19, Pl 88, As In 403089 Except Part 1, 20R11699; Burlington 1382 Plains Rd E - Lt 17 & Pt Lt 18, Pl 88 As In 704027 Pt 1, 20R18576. City Of Burlington Laneway to the east of 1382 Plains Rd E – Pt Lane, Pl 88, Lying Wly Of 20r4064; Pt Lt 16, Pl 88, Part 3 & 4, 20r4701; Burlington Laneway to the west of 1376 Plains Rd E- Alleyway, Pl 88; Burlington Southwest portion (railway land)- Part Lot 16, 69, 75, 77, 78 Rcp Pl 99 Part Brant St (closed By 322844) Rcp Pl99 As In Nr1126, Ns113, Bh417, Bh418, Bh421, Bh1099, Bh1231, Bh1232, Pm38, 149819, 294934, 307249, Pt 1, 2, 8, 9 Br55 Lying Btw Plains Road And Brant Street , T/w H837379, H810868, H856856 Burlington Together With An Easement Over Pts 1 To 4 20r19491, Pt 1 20r19492, Pt 1 20r19493, Pts 1 To 4 20r19494, Pts 1 & 2 20r19499, Pt 1 20r19500, Pts 1 To 4 20r19501, Pts 1 & 2 20r19502, Pts 1 & 2 20r19503, Pts 1 To 9 20r19507, Pts 1 To 3 20r19508, Pts 1 & 2 20r19509 & Pts 1 To 4 20r19510 As In Hr1094626

Property Identification Number (PIN)	1376 Plains Rd E- 070870044(LT) 1382 Plains Rd E-070870405(LT) Laneway to the east of 1382 Plains Rd E – 070870046 Laneway to the west of 1376 Plains Rd E- 070870043 Southwest portion (railway land) - 070870393
Approximate Universal Transverse Mercator (UTM) coordinates	NAD83 17T 595755.86 m E 4798800.48 m N
Accuracy Estimate of UTM	10-15 m
Measurement Method	Global Positioning System (GPS)
Site Area	0.33hectares (0.83 acres)
Property Owners, Owner Contact and Address	273119 Ontario Inc., Manor Care Homes In., F.K Deals on Wheels Inc., 2731115 Ontario Inc. 2235 Sheppard Ave E., Suite 1700 North York, ON M2J 5B5 Mr. Nolan Moss
Any Other Person Who Engaged the QPESA	NA

3 Scope of Investigation

The scope of work for the Phase One ESA consisted of the following activities:

- Reviewing the historical occupancy of the Site through the use of available archived and relevant municipal and business directories, fire insurance plans (FIPs), topographical maps, and aerial photographs;
- Contacting municipal and provincial agencies to determine the existence of records of environmental regulatory non-compliance, if any, and reviewing such records where available;
- Obtaining an Environmental Risk Information Services Ltd. (ERIS) report for the Site and surrounding properties within a 250 metre radius of the Site;
- Reviewing available geological maps, well records and utility maps for the vicinity of the Site;
- Obtaining and reviewing a chain of title and assessment rolls for the Site;
- Reviewing available reports previously completed at the Site;
- Conducting interviews with designated Site representative(s) as a resource for current and historical Site information, as well as to provide EXP staff with unrestricted access to all areas of the Site and Site buildings (as required by O.Reg. 153/04, as amended);
- Conducting a Site reconnaissance in order to identify any land use practices that may have impacted the environmental condition of the Site;
- Conducting a reconnaissance of the surrounding properties from the Site and publicly accessible areas in order to identify any land use practices that may have impacted the environmental condition of the Site; and,
- Preparing a report to document the findings.

The following sections summarize the information gathered by EXP during the Phase One ESA and identifies Potentially Contaminating Activities (PCAs) on the Phase One property and in the Phase One study area, and Areas of Potential Environmental Concern (APECs) associated with the Site. APECs and PCAs are defined in the O. Reg 153/04, as amended.

In completing the scope of work, EXP did not conduct any intrusive investigations, including sampling, analyses or monitoring.

EXP has confirmed neither the completeness nor the accuracy of any of the records that were obtained or any of the statements made by others.

EXP personnel who conducted assessment work for this project included Ms. Ramila Senanayake, Mr. Nolan McGahey, B.Sc., and Mr. Syed Hussaini, M.Eng., P.Eng., QP_{ESA}. An outline of their qualifications is provided in Appendix C.

4 Record Review

4.1 General

4.1.1 Phase One Study Area Determination

The Phase One Study Area consists of properties within a distance of approximately 250 m from the Site boundaries. The Phase One Study Area consists of residential, commercial, and institutional property uses. The Phase One Study Area is bound by residential properties to the north, commercial and industrial properties to the east and south, and residential and industrial properties to the west. The CNR lines transect the central portion of the Phase One Study Area in a roughly east-west direction.

The Phase One Study Area and a Surrounding Land Use Plan are shown on Figure 2.

4.1.2 First Developed Use Determination

Based on the information available at this time, the Site was inferred to be developed prior to 1924s for residential use.

4.1.3 Fire Insurance Plans

A search of completed by EXP and ERIS identified fire insurance plans (FIPs) dated 1932 and 1971 that provide coverage of the Site and the Phase One Study Area. EXP also identified a FIP dated 1924 from the McMaster University website. The review of the FIPs identified the following environmentally significant information.

Year	Observation
1924 Properties on Plains Road had different municipal addresses to present day, and the portion of Plains Road west of Brant Street was shown as Plains Road West.	**Site** • The Site was developed with two (2) residential buildings, identified as “D”- dwellings • The Site had the municipal addresses 41 and 45 Plains Road West. The properties were each developed with 1 ½ storey buildings. • No other buildings structures were observed at the Site. **Phase One Study Area** • Majority of the lands south adjacent to Plains Road (west) were developed for residential use. Commercial and industrial development was observed adjacent to Brant Street. Based on the observations in the FIP, the following were identified to be associated with a PCA: • The property southeast adjacent to the Site was occupied by Ontario Canning Co. The building had a Machine Room there the food products were likely filled in the cans and labeled in preparation for distribution. For this purpose, the property likely bulk stored adhesives. This is associated with PCA#2-Adhesives and Resins Manufacturing, Processing and Bulk Storage. There was also a foundry in the southwestern corner of this building. This is associated with PCA#34-Metal Fabrication. • The CNR lines were observed 5 m south of the Site. This is associated with PCA#46-Rail Yards, Tracks and Spurs. • The property at 1274 Plains Road East, approximately 65 m south/southwest of the Site was occupied by Niagara Brand Spray Co. mfrs Germicide Chemicals. This is associated with PCA#8-Chemical Manufacturing, Processing and Bulk Storage.

Year	Observation
	• The property approximately 65 m east of the Site was occupied by the Biggs Fruit Co Ltd., and a machines shop was located at this property. This is associated with PCA#34-Metal Fabrication. • A building was observed approximately 150 m south of the Site that was occupied by Vera Chemical Co of Canada Ltd. This is associated with PCA#8-Chemical Manufacturing, Processing and Bulk Storage.
1932	**Site** • Conditions at the Site were similar to that observed in the 1924 FIP. **Phase One Study Area** • The property southeast adjacent to the Site was occupied by Tip-Top Canning Co. The building has a machine room in the eastern portion of the building. This is associated with PCA#34-Metal Fabrication. • The property 95 m south/southwest of the Site was occupied by Niagara Brand Spray Co. mfrs Germicide Chemicals. The building had an “arsenic room”, “mixing and warehouse”, tanks. This is associated with PCA#8-Chemical Manufacturing, Processing and Bulk Storage. The building • The building that was observed 160 m south of the Site in the 1924 FIP, was now occupied by Paper Makers, Chemical Corp Limited. This is associated with PCA#8-Chemical Manufacturing, Processing and Bulk Storage and PCA#45- Pulp, Paper and Paperboard Manufacturing and Processing.
1971	**Site** • The Site has been reassigned the municipal addresses 1376 and 1382 Plains Road East. • A southern extension has been developed on the building at 1376 Plains Road East. The two (2) building that occupy the Site are similar to that observed at the time of the Site visit. • The building at 1376 Plains Road East was identified as a “used car lot”, and 1382 had the southeastern portion of the building identified as “auto”. **Phase One Study Area** • Properties on Plains Road East have reassigned municipal addresses that are similar to that which are currently Industrial and commercial development has expended on Plains Road East • The property at 1390 Plains Road East, east adjacent to the Site, was identified as “Blue Printing” on the 1st floor. This is associated with PCA#31- Ink Manufacturing, Processing and Bulk Storage. • The property southeast adjacent to the Site was occupied by the industrial building of Tip Top Canners Ltd. in addition to the operation noted in the previous FIPs, this FIP shows that the southern building was a storehouse that used anti-freeze. There were tanks storing antifreeze were observed east adjacent to the building. This is associated with PCA#4- Antifreeze and De-icing Manufacturing and Bulk Storage • The property at 1355 Plains Road East, approximately 65 m northwest, was occupied by a machine shop. This is associated with PCA#34-Metal Fabrication.

Year	Observation
	• The property at 1358 Plains Road East, approximately 20 m west of the Site, was occupied by Motorcycle sales and service. This is associated with PCA#52- Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems. • Niagara Chemicals was observed in the southern portion of the Phase One Study Area. Approximately 95 m south/southwest of the Site. The operations have expanded since the 1932 FIP. Several more building were observed where operations including – herbicide manufacturing and emulsion manufacturing took place. There were also above ground tanks on this property which were likely used to store the manufactured chemicals, and the chemical ingredients. This is associated with PCA#8- Chemical Manufacturing, Processing and Bulk Storage and PCA#40- Pesticides (including Herbicides, Fungicides and Anti-Fouling Agents) Manufacturing, Processing, Bulk Storage and Large-Scale Applications. A UST was also observed on this property which is associated with PCA#28-Gasoline and Associated Products Storage in Fixed Tanks. • The property approximately 150 m south of the Site was occupied by Hercules Canada Ltd. The property had industrial operations that included resin melting and storage. This is associated with PCA#2- Adhesives and Resins Manufacturing, Processing and Bulk Storage. • The property 1439 Plains Road East was developed with an auto service building that has a UST. This is associated with PCA#28- Gasoline and Associated Products Storage in Fixed Tanks, and PCA#52- Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems.

In addition to these FIPs, an insurance report titled *"Fire Inspection and Rate Calculation Form Report – 1981 1382 Plains Road East Burlington ON L7R 3P8*.

- Based on the insurance report, the Site building was used as a sales office. It appears that in addition to the sales, they also washed and cleaned the cars on-Site. This is not inferred to be associated with a PCA.
- Based on the information in this insurance report it appears that no auto service work took place at the Site.
- According to the report, the Site building was heated using an oil-fired furnace. No further information was provided in the report regarding the type of tank used to store the heating oil.

A copy of the insurance products provided by ERIS are included in Appendix E.

4.1.4 Chain of Title

The search for the historic chain of titles that comprise of the Site were requested to be completed by Dominic Bertucci, an independent title searcher on March 7, 2023. The completed chain of titles will be provided in Appendix D. It is noted that the search for the PIN 070870393 did not identify any results. According to the feedback received this PIN is currently "inactive".

Based on the search, the Site was Crown land until 1798. The names of the current owners of the Site and purchase date are provided in the table below.

PIN	Owner	Date of Purchase
07087-0044	Manor Care Homes Inc (50%); 2731119 Ontario Inc. (50%)	December 11, 2019
07087-0405	F. K Deals on Wheels Inc. (50%); 2731115 Ontario Inc. (50%)	December 11, 2019
07087-0438	Manor Care Homes Inc., 2731119 Ontario Inc., F. K Deals on Wheels Inc; 2731115 Ontario Inc.	February 3, 2023
07087-0440	Manor Care Homes Inc., 2731119 Ontario Inc., F. K Deals on Wheels Inc; 2731115 Ontario Inc.	February 3, 2023
070870-0393	Unknown as PIN is currently Inactive	

Based on the names of previous owners of the Site, only one (1) former owner, the Burlington Manufacturing Company was noted as a potential source of concern; however, based on the observations from FIPs, there is no evidence that any portion of the Site was historically used for industrial operations. The earliest image available for the Site (the 1924 FIP- see Section 4.1.3) did not show any evidence of manufacturing operations/warehousing taking place on the Site. Based on the information available at this time, it is inferred that this former owner did not carry out any industrial activities on-Site, and as such is not associated with a PCA.

A list of previous owners of the Site has been summarized in Table II.

4.1.5 Environmental Reports

At the time of this Phase One ESA, no previously completed environmental reports were available for review.

4.2 Environmental Source Information

4.2.1 Federal and Provincial Database Search

A search of provincial, federal and private environmental databases for records pertaining to the Site and properties within the Phase One Study Area was completed by Environmental Risk Information Services (ERIS) on February 15, 2023. EXP has confirmed neither the completeness nor the accuracy of the records that were provided. The ERIS Report is provided in Appendix E.

A summary of the significant findings is provided below. It is noted that only records that are associated with a PCA/have information that pose an issue of environmental concern (e.g., large spills or generation of halogenated solvent wastes) were summarized in the table below:

Address	Description	Database	Associated PCA(s)
Site			
No records were identified for the Site that would be associated with a PCA			

Address	Description	Database	Associated PCA(s)
Surrounding Properties			
1364 Plains Rd E (10 m west)	The property was registered for having a retail tank. The tank expired in 1994, and has a capacity of 2000 L.	*PRT*	PCA#28-Gasoline and Associated Products Storage in Fixed Tanks
	Burlington Taxi Ltd., a tenant of the property was registered as a garage (gen. repair) and listed for the generation of waste oils and lubricants from 1989-2001.	*GEN*	PCA#27-Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles
Plains Rd E and Helena St (45 m northwest)	A spill was recorded in 2001 when 20 L of furnace oil was released to the ground due to equipment failure. Environmental impact was not an anticipated impact from this spill.	*SPL*	No, due to the information in the record.
1282 Plains Rd (120 m west)	A spill was recorded in 1998 when an unknown quantity of hydraulic oil was released to gravel from a motor vehicle. According to the record, soil contamination was a possible outcome of the spill.	*SPL*	No, due to the information in the record
1446 Plains Rd E (175 m east)	The property was registered for having expired retail tanks in 1995.	*PRT*	PCA#28-Gasoline and Associated Products Storage in Fixed Tanks
	The property was registered as service stations - gasoline, oil and natural gas.	*RST*	
	The property, registered as gasoline station was registered for having three (3) double wall USTs and one (1) single wall UST for gasoline storage. Based on information in the databases, the tanks were installed in 1984, 1994.	*FSTH* *DTNK* *FST*	
	The property was registered for the generation of waste oils and sludges and light fuels from 2021-2022.	*GEN*	
1274 Plains Road East (65 m southwest)	Sun Chemical Ltd. was registered for a fire at the plant in 1996. Soil contamination was a possible outcome of this fire.	*SPL*	PCA#8- Chemical Manufacturing, Processing and Bulk Storage
942 Brant Street (150 m south)	Several spills were recorded at this property. Among the spills the following were noted to be significant spills with potential environmental concerns: • A spill was recorded in 1989 when 18,000 L, and 15,000 L of lube oil was release to the ground. • 450 L of solvent was released to a dyke in 2004.	*SPL*	PCA "Other" – Spill with potential environmental impacts
	The property was registered on the database for "other chemical product manufacturing" and "all other miscellaneous chemical product manufacturing".	*CHM* *NPRI* *SCT*	PCA#8- Chemical Manufacturing, Processing and Bulk Storage

Address	Description	Database	Associated PCA(s)
		NEES	
	The property was registered for the generation of wastes including halogenated solvents from 2013-2022.	*GEN*	PCA"Other"- Generation of Halogenated Solvents
932 Brant Street (230 m southeast)	A leak of transformer oil was recorded in 2012. 4.5 L of mineral was released to a paved area. Environmental impact was not "anticipated".	*SPL*	PCA#55-Transformer Manufacturing, Processing and Use
920 Brant Street (210 m southeast)	Unit 13 was registered for operations including metal valve manufacturing.	*SCT*	PCA#34-Metal Fabrication
	Unit 23 was registered for power, distribution and speciality transformers manufacturing.	*SCT*	PCA#55-Transformer Manufacturing, Processing and Use
	Unit 18-19, registered for quick printing, was registered for the generation of wastes including petroleum distillates in 2005, photoprocessing wastes from 2005-2016.	*GEN*	PCA#31- Ink Manufacturing, Processing and Bulk Storage
	Unit 16 was registered for electronic and precision equipment repair and maintenance and for the generation of acid wastes in 2005.	*GEN*	PCA#19- Electronic and Computer Equipment Manufacturing
	A transformer oil spill was recorded in 2016 when 2 L of non-PCB oil was released to the ground.	*SPL*	PCA#55-Transformer Manufacturing, Processing and Use

Databases:

GEN – Ontario Regulation 347 Waste Generators Summary
FST-Fuel Storage Tank
FSTH-Fuel Storage Tank – Historic
PRT-Private and Retail Fuel Storage Tanks
RST-Retail Fuel Storage Tanks
NEES- National Environmental Emergencies System (NEES)
SCT – Scott's Manufacturing Directory
SPL – Ontario Spills
DTNK-Delisted Fuel Tanks
CHM- Chemical Register
NPRI- National Pollutant Release Inventory

4.2.2 Municipal Records

4.2.2.1 Municipal Directories

The available Vernon's City Directories dated 1957, 1961, 1971, 1976, 1981, 1986, 1990, 1996, 2001 and 2006, and digital directories dated 2012, 2017 and 2021 were reviewed by ERIS to identify the occupancy history of the Site and properties within the Phase One Study Area. A copy of the results from the ERIS search are included in Appendix F.

The following table summarizes the occupants at the Site and the Phase One Study Area that are associated with a PCA.

Address	Occupants	Years Occupied	PCA
Site			
No tenants were identified at the Site that would be associated with a PCA. Based on observations from the FIPs, ERIS, aerials and Site visit, the Site was historically occupied by auto sellers, however, no repair/service took place on-Site.			
Surrounding Properties			
920 Brant Street (210 m southeast)	Kwik Kopy Design Print Centre	2006, 2012, 2017	PCA#31- Ink Manufacturing, Processing and Bulk Storage
932 Brant Street (230 m southeast)	Dan's Welding and Fabricating	1957, 1961, 1966, 1971	PCA#34-Metal Fabrication
942 Brant Street (150 m south)	Hercules Powder Co (Can) Ltd.	1957 -2017	PCA#8- Chemical Manufacturing, Processing and Bulk Storage
	Ashland Canada	2017, 2021	
944 Brant Street (150 m south)	Niagara Chemical Co	1957, 1961, 1966, 1971, 1981	PCA#8- Chemical Manufacturing, Processing and Bulk Storage
1043 Glendora Avenue (200 m northwest)	B and M Marine Salvage	2006, 2012	PCA#49- Salvage Yard, including automobile wrecking
1274 Plains Road East (65 m southwest)	Chemical and Printing Companies	1966-2021	PCA#8- Chemical Manufacturing, Processing and Bulk Storage
1371-1411 Plains Road East (20 m north)	Holland J Motors Collision Service	1966	PCA#52- Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems
1400 Plain Road East (East adjacent)	Smart Choice Auto Repairs	2001, 2012, 2021	PCA#52- Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems
1401 Plains Road East (20 m north)	Holland Chevrolet Geo Oldmobile Ltd	1976-2001	PCA#52- Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems
1435 Plains Road East (140 m northeast)	Vickie's Esso Service Station	1990	PCA28-Gasoline and Associated Products Storage in Fixed Tanks
	Greenwood L H Service Station	1957, 1961	
1446 Plains Road East (175 m east)	Service Station	1961-2021	PCA28-Gasoline and Associated Products Storage in Fixed Tanks

4.2.3 Ontario Ministry of the Environment Records

4.2.3.1 Ministry of the Environment, Conservation and Parks (MECP)

The MECP was contacted through the Freedom of Information and Protection of Privacy Act (FOI) for copies of any records they had pertaining to the Site on February 22, 2023.

A written response from the MECP was received on March 8, 2023. According to the response, a search of the ministry's Halton Peel District Office, Environmental Assessment and Permissions Division (EAPD), Environmental Monitoring and Reporting Branch (EMRB), Environmental Investigations and Enforcement Branch (EIEB) and Safe Drinking Water Branch, there are no records or the Site.

A copy of the response is provided in Appendix G.

4.2.3.2 Ministry of the Environment and Climate Change Databases

The ERIS report summarized in the Federal and Provincial Database Search section of the report included a summary of MECP databases (see section 4.2.1). The databases include the following: Environmental Bill of Rights (EBR), Brownfields Environmental Site Registry, Hazardous Waste Information Network (HWIN) and Waste Disposal Sites.

4.2.4 Technical Standards and Safety Authority

A request was made to the TSSA by email on February 27, 2023, for information regarding fuel storage at the Site and adjacent properties.

A written response for the TSSA was received on February 27, 2023. According to a search of their database, there are no records of fuel storage tanks at the Site.

One (1) property that is in close proximity to the Site was registered on the database. The property, 1364 Plains Road East, located 10 m west of the Site was registered for operating a propane refilling center and for having propane tanks. Due to the nature of these chemicals (i.e., gas) this property was not identified to be associated with a PCA.

A copy of the e-mail correspondence with the TSSA is provided in Appendix G.

4.2.5 Record of Site Condition

A Record of Site Condition (RSC) summarizes the environmental conditions of a property as determined by a qualified person (QP) by conducting a Phase I ESA, and where necessary, a Phase II ESA, confirmatory sampling and risk assessment. Upon completion of the necessary environmental Site assessments, an RSC for an assessed property can be filed with the MECP and added to the Environmental Brownfields Site Registry database. This online, publicly available database can be searched to identify properties which may have potential environmental concerns.

Based on a search of the Environmental Brownfields Site Registry database and ERIS Report, the Site was not listed with an RSC.

RSC were filled for the following properties in the Phase One Study Area;

- An RSC was filed for 1343 Plains Rd E. The RSC ID is 230135, and the filing date was December 15, 2021. The RSC was filed when the property use changed from commercial to residential use.

- An RSC was filed for 1401 Plains Rd E. The RSC ID is 45717, and the filing date was October 23, 2008. The RSC was filed when the property use changed from commercial to residential use. Another RSC filed for this property on July 30, 2009 and the RSC ID was 58115.
- An RSC was filed 1325 Plains Road East. The RSC ID is 214226, and the filing date was July 24, 2014. The RSC was filed when the property use changed from commercial to residential use.
- An RSC was filed for 930 Brant Street. The RSC ID is 21301 and the filing date is June 18, 2007. The property use did not change from commercial use following the filing of the RSC.

4.3 Physical Setting Sources

4.3.1 Aerial Photographs

Aerial photograph dated 1934, 1954, 1961, 1973, 1986, 1998, 2004, 2014 and 2021 were obtained in order to review the development and land use history of the Site as well as determine major developments at and in the immediate vicinity of the Site.

The development and land use history of the Site and adjacent properties as depicted on the reviewed aerial photography is summarized in the table below. Copies of the aerial photographs are included in Appendix H.

Aerial Photography Year	Observations
1934	**Site:** • The Site has been developed. Based on the observations from the FIP, the buildings on-Site are inferred to be residential in use. **Phase One Study Area:** • Brant Street and Plains Road East have been developed. • Lands adjacent to Brant Street was observed to be vacant and undeveloped. • Lands adjacent to Plaints Road East have been developed with buildings that are inferred to be predominantly residential in use. • An orchard was observed on the north side of Plains Road East, approximately 90 m northwest of the Site. • The CNR line was observed transecting the central portion of the Phase One Study Area in a northwest-southeast direction. The CNR line travels 10 m south of the Site.
1954	Due to the low resolution of the aerial photograph details were difficult to observe. **Site:** • Details of the Site could not be observed. **Phase One Study Area:** • Additional roads have been developed within the Phase One Study Area. Expansion in residential development was observed adjacent to these roadways. • The orchard observed in the 1934 aerial photograph was not observed in this aerial photograph.

Aerial Photography Year	Observations
1961	**Site:** • Conditions at the Site were similar to that observed in the 1934 aerial photograph. **Phase One Study Area:** • Plains Road East has been widened. • The southwestern portion of the Phase One Study Area 1274 Plains Road East /942 Brant Street have been developed with buildings that are inferred to be industrial use. • The lands 20 m north of the Site (1401 Plains Road East) have been cleared of the buildings observed in the previous aerial photographs; disturbed ground cover was observed on these lands that appear to be under development. • The land southeast adjacent to the Site have been developed with buildings that are similar to that observed in the 1924 FIP (see Section 4.1.3). • Lands east adjacent to the Site have been redeveloped with a rectangular shaped building.
1973	**Site:** • A southern extension has been developed on 1376 Plains Road East. • Dense tree cover was observed on the eastern portion of the Site that was obstructing the view of that portion of the Site. • No other significant changes were observed at the Site between the 1961 and 1973 aerial photographs. **Phase One Study Area:** • 1401 Plains Road East has been developed with a building that is inferred to be commercial in use. • The property at the southwest corner of plains Road E and brant Street (1446 Plains Rd E) have been developed with a building that is similar in shape to the service station that currently occupied this property. Cylindrical above ground tanks were observed on this property approximately 180 m south of the Site. • Additional buildings have been developed on the industrial property in the southern portion of the Phase One Study Area. • The property southeast adjacent to the Site has been redeveloped with an irregular shaped building.
1986	**Site:** • There was a lot of small structures, inferred to be vehicles on-Site. • No other significant observations were observed at the Site between the 1973 and 1986 aerial photographs. **Phase One Study Area:**

Aerial Photography Year	Observations
	• Further expansion in the development of commercial properties was observed adjacent to Plains Road East. • The residential dwellings south adjacent to Plains Road East have been demolished, and in place, the land has been redeveloped with a rectangular shaped building that is similar in shape to that which occupies 1400 Plains Road East. • The area to the east of the building at 1400 Plains Road East has been paved and developed as a parking lot similar to that which currently occupies this property. • No other significant changes were observed between the 1973 and 1986 aerial photographs.
1998	**Site:** • Conditions at the Site were similar to that observed in the 1986 aerial photograph. **Phase One Study Area:** • The building at the northwest corner of Plains Road East and Brant Street has been demolished. • No other significant changes were observed between the 1986 and 1998 aerial photographs.
2004	• Conditions at the Site and the Phase One Study Area were similar to that observed in the 1998 aerial photograph.
2014	**Site:** • Conditions at the Site were similar to that observed in the 2004 aerial photograph. **Phase One Study Area:** • The northwest corner of Plains Road East and Brant Street have been developed with a building that is similar in shape and size to the building that currently occupies this property. • The commercial building at 1400 Plains Road East has been demolished, the property has been redeveloped with a residential subdivision. • No other significant changes were observed between the 2004 and 2021 aerial photographs.
2021	• Conditions at the Site and the Phase One Study Area were similar to that observed in the 2014 aerial photograph and that observed at the time of the Site visit.

Based on the reviewed aerial photographs, no PCAs were identified for the Site. The reviewed aerial photographs show that the Site was developed for residential use prior to 1934.

Based on information from the aerial photographs, the following PCAs were identified for the Phase I Study Area;

- An orchard was observed approximately 90 m northwest of the Site in the 1934 aerial photograph. This is associated with PCA#40- Pesticides (including Herbicides, Fungicides and Anti-Fouling Agents) Manufacturing, Processing, Bulk Storage and Large-Scale Applications

- Based on the aerial photographs, the CNR line has occupied the study area from prior to 1934. This is associated with PCA#46- Rail Yards, Tracks and Spurs.

The PCAs associated with the industrial property in the southern portion of the Phase One Study Area are listed in Section 4.1.3 and 4.1.5.

4.3.2 Topography, Hydrology and Geology

The following physiographic, geological and soil maps were reviewed:

- "Toporama"; Natural Resources Canada. Map 030M11. Scale 1:15,000. 2008.
- Quaternary Geology of Ontario - geology_ll.shp [computer file], Ontario: Ontario Geological Survey, 2000.
- Bedrock Geology of Ontario - geology_ll.shp [computer file], Ontario: Ontario Geological Survey, 2000.

Based on the review of the above maps, the following information was obtained:

- The Site and surrounding areas slope to the south. Lake Ontario is located 2.35 km south of the Site. Based on the information available at this time, the direction of groundwater flow in the area of the Site is inferred to be to the south.
- The Site and surrounding areas are dominated by Paleozoic bedrock.
- The bedrock in the general area of the Site is part of a group belonging to the Queenston Formation, consisting of shale, limestone, dolostone and siltstone.

4.3.3 Fill Materials

Fill material is typically brought to a property as a base for buildings and pavement areas. Fill can also be used to re-grade a property, and to backfill excavations.

Based on the information from the records review, there is no evidence to suggest that fill materials are present at the Site.

4.3.4 Areas of Natural Significance

Based on the review of available resources from the Ministry of Natural Resources and Forestry website February 22, 2023, no areas of natural significance were identified at the Site or within 30 m of the Site.

4.3.5 Well Records

4.3.5.1 Water Wells

A search of the water well database was conducted by ERIS of the surrounding Phase One Study Area and Ontario Well Records Database to identify water wells within the Phase One Study Area.

The ERIS database report had a record of a monitoring well that had been installed on-Site. The monitoring well had been installed at 1382 Plains Road East in 2006. The well had been completed to a depth of 3.0 m. According to the record the general stratigraphy on that portion of the Site was described as silt, sand and clay underlain by brown clay and silt. Groundwater was encountered at 1.0 m bgs.

There were thirty-seven (37) records of wells installed within the Phase One Study Area. The review of these records did not identify any additional information of environmental significance for the Site.

4.3.5.2 Oil, Gas, and Salt Wells

A search of the Oil, Gas & Salt Resources Library (2014) was completed by ERIS. According to the findings of ERIS's search, no oil, gas or salt wells are located on-Site or within the Phase One Study Area.

4.4 Site Operating Records

In general, a request is usually made to the property representative for copies of any operating records pertaining to the environmental conditions at the Site. Records would include: regulatory permits; Material Safety Data Sheets (MSDS) for all chemicals that were handled on-Site; underground utility drawings; inventories of chemicals, chemical usage, and chemical storage areas; inventory of aboveground storage tanks (ASTs) and underground storage tanks (USTs); environmental monitoring data; correspondence pertaining to an order or request by the MECP or TSSA; waste management records; process, production, and maintenance documents; records of spills and records of discharges of chemicals; emergency response and contingency plans, including spill prevention and contingency plans; environmental audit reports; and Site plans of the facility showing areas of production and manufacturing

There were no records of environmental significance available for review at the time of this Phase One ESA.

5. Interviews

Interviews were conducted by EXP staff with the individuals identified to be the most knowledgeable with respect to both the current and historical Site uses. The interviews were conducted during the Site reconnaissance in order to obtain information to assist in identifying details of potentially contaminating activities, potential contaminant pathways in, on, or below the Site, and areas of potential environmental concern.

During the completion of this Phase One ESA, the following individual was interviewed:

Mr. Frank Sabra completed a questionnaire regarding the Site on February 10, 2023. Mr. Sabra is the owner of the Site. Information collected from the Mr. Sabra (herein after referred to as “Site representative”) was used in the completion of Section 6.0.

6. Site Reconnaissance

6.1 General Requirements

The Phase One Site reconnaissance was conducted on February 15, 2023, between 10:00 am and 12:00 pm by Mr. Nolan McGahey under the supervision of Mr. Syed Hussaini, QP_{ESA}, a Qualified Person as defined by O.Reg. 153/04, as amended. On the day of the Site reconnaissance, the weather was cloudy and raining and approximately 10°C.

The Site and the adjoining properties were observed from the Site and/or publicly accessible areas. Photographs documenting the Site visit are included in Appendix I.

6.2 Specific Observations at Phase One ESA Property

6.2.1 Site Description and Buildings

The Site is an irregular shaped parcel of land that measures approximately 0.33 hectares (0.83 acres).

The central portion of the Site is occupied by two (2) properties with the municipal addresses 1376 and 1382 Plains Road East. Each property is developed with a building. The building on 1382 Plains Road is similar in shape to the building observed in the 1924 FIP. The northern portion of the building at 1376 Plains Road East is also similar to building observed in the FIP.; however, a southern extension has been developed on to this building. The Site representative was unaware of the date of the extension but based on the aerial photographs, this extension was developed prior to 1973 (see Section 4.3.1).

The areas surrounding these Site buildings have been asphalt paved or landscaped with grass cover. During the winter months, de-icing salt would have been applied to the paved areas to remove the snow/ice build up. This is associated PCA" Other"-Application of De-icing salt.

The eastern, western and southern boundaries of the Site are occupied by laneways.

No other buildings or structures were observed at the time of the Site.

6.2.2 Heating and Cooling Systems

The Site building at 1376 Plains Road East was heated using a natural gas fired furnace and an air conditioning unit.

The Site building at 1382 Plains Road East was heated and cooled using a natural gas fired HVAC unit.

Both Site buildings have chimneys (no longer in use) adjacent to the original south wall of the Site buildings. Based on the age of the Site buildings it is likely that the buildings were heated using a combination of chimney and heating oil. Based on information from the insurance report (see Section 4.1.3), 1382 Plains Road East was historically heated using an oil-fired furnace. The storage of heating oil is associated with PCA#28-Gasoline and Associated Products Storage in Fixed Tanks.

6.2.3 Site Utilities and Services

The Site utilities and services were identified at the Site based on information provided in environmental records, relevant utility infrastructure observed during the Site reconnaissance. The Site utilities are summarized in the table below and noted on Figure 3, where available. It is noted that the precise underground location of the utilities cannot be determined without professional locate services.

Utility	Source	Location	Site Entry
Natural Gas	Enbridge Gas	Underground	The natural gas meter was observed at 1376 and 1382 Plains Road East on the west and south walls of the Site buildings respectively.
Sanitary Sewer	City of Burlington	Underground	Unknown
Storm Sewer	City of Burlington	Underground	Storm sewers observed in the asphalt portion of the Site
Water	City of Burlington	Underground	Unknown
Electricity	Burlington Hydro	Underground	Unknown
Telecommunications	Bell	Underground	Unknown

6.2.4 Sewage and Wastewater Disposal

The Site and surrounding area are served by municipal sanitary and storm sewer systems.

6.2.5 Potable Water Sources

The Site was connected to the municipal water source at the time of the Site visit.

6.2.6 Abandoned and Existing Wells

At the time of the Site visit, one (1) monitoring well was observed at 1382 Plains Road East. Based on information from the ERIS report (see Section 4.3.5) this well was likely that monitoring well described in that report.

No other wells were observed at the time of the Site visit.

6.2.7 Site Production and Manufacturing

There are no on-Site production or manufacturing activities.

6.2.8 Drains, Pits and Sumps

All floor drains within Site buildings are connected directly to the municipal sewer system.

No other drains, pits, or sumps were observed on the Site at the time of the Site visit.

6.2.9 Storage Tanks

The presence/absence and condition (if present) of underground storage tanks (USTs) and aboveground storage tanks (ASTs) at the Site were assessed during the Site visit.

No evidence of the presence of USTs (i.e., fill and vent pipes) or ASTs were identified at the time of the Site visit.

6.2.10 Water Wells

No potable water wells were observed at the time of the Site visit.

6.2.11 Site Housekeeping

The Site was well maintained, with no evidence of misplaced/excessive waste or spills being observed at the time of the Site visit.

6.2.12 Chemical Storage and Handling and Floor Condition

Based on the observations made at the time of the Site visit, and information provided by the Site representative, the Site does not store any hazardous chemicals apart from household cleaners. The storage of household cleaners is not associated with a PCA.

6.2.13 Areas of Stained Soil, Pavement or Stressed Vegetation

No evidence of significant staining was observed during the Site visit.

No stressed vegetation was noted at the time of the Site visit.

6.2.14 Fill and Debris

Fill material is typically brought to a property as a base for buildings and pavement areas. Fill can also be used to re-grade a property and to backfill excavations.

At the time of the Site visit no evidence of fill materials was observed.

6.2.15 Air Emissions

Air emissions in Ontario are regulated under the Environmental Protection Act (EPA) and its Regulations (O. Reg. 419/05, O. Reg. 245/11, O.Reg 1/17). Owners and operators of activities that may discharge a contaminant into the natural environment must seek permissions from the Ministry of Environment, Conservation and Parks (MECP) to carry out these activities. As of October 31, 2011, amendments to the EPA resulted in a two-path environmental approval process, the Environmental Compliance Approval (ECA) and Environmental Activity and Sector Registry (EASR). The EASR allows businesses to register certain activities with the ministry, rather than apply for approvals. The EASR is for common systems and processes, initially for heating systems, standby power systems and automotive refinishing, to which preset rules of operation can be applied. Effective January 3, 2017 additional activities were allowed through the EASR process based on the facility's North American Industry Classification System (NAICS) code but required full assessment for compliance of emissions under O.Reg. 419/05. Unless explicitly exempted, most industrial processes or modification to industrial processes and equipment require an ECA, formerly a Certificate of Approval (Air and Noise).

Based on the Site visit, there was no evidence of operations would require MECP approval for air emissions.

6.2.16 Polychlorinated Biphenyls (PCBs)

No evidence of pad-mounted oil type transformers was observed at the time of the Site visit.

Fluorescent light fixtures were observed within the Site. Based on this information it is likely that PCBs are present only within the older light ballasts.

6.3 Enhanced Investigation Property Observations

An Enhanced Investigation Property is "(i) a property used, or has ever been used, in whole or part, for an industrial purpose, or (ii) a commercial property used as a garage, a bulk liquid dispensing facility, including a gasoline outlet or for the operation of dry-cleaning equipment" (O.Reg. 153/04).

Based on the information reviewed on the historical and current use, the Site is not classified as an Enhanced Investigation Property.

6.4 Adjacent and Surrounding Properties

A visual reconnaissance of the adjacent properties, and properties within the Phase One Study Area was conducted from publicly accessible areas to identify the occupants; and document any PCAs that may be contributing to an APEC at the Site.

Based on the visual reconnaissance of adjacent and surrounding properties within the Phase One Study Area, the following properties within the Phase One Study Area were identified as having operations that contribute towards a PCA as defined in Table 2 of Schedule D;

Address	Occupant	PCA
1368 Plains Road East (West adjacent)	Tire shop It is noted that at the time of the Site visit, two vent pipes were observed at this property, however, there are no records of fuel storage, or fill pipes noted. As such, it was not flagged for PCA#28.	PCA#52-Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems
1400 Plains Road East (East adjacent)	Several tenants with auto repair shops	#52-Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems
No municipal address (5 m south)	CNR Line	PCA#46- Rail Yards, Tracks and Spurs

6.5 Written Description of Investigation

A reconnaissance of the Site was conducted by EXP to examine the exterior of the Site. Access was provided to the entirety of the Phase One Property. The exterior portions of the Site were examined for evidence of utilities and related infrastructure; water wells; Site drainage and related infrastructure; stained areas; stressed vegetation; and, evidence of fill material.

The reconnaissance of the Site included an examination of all properties within the Phase One Study Area from public access ways to document and characterize PCAs, water bodies and areas of natural significance.

7. Review and Evaluation of Information

7.1 Current and Past Uses

Based on the records review, the Site was developed prior to 1924 with the two (2) buildings that were identified as residential dwellings in the reviewed fire insurance plans (FIP). The buildings had the municipal addresses 41 and 43 Plains Road East. Circa the early 1970s, the Site buildings were assigned the currently municipal addresses 1376 and 1382 Plains Road East. The building extension on the Site building at 1376 Plains Road East was developed prior to 1971 based on the reviewed FIP. The on-Site areas surrounding the Site buildings have been paved and developed as laneways and parking lots for the Site buildings.

According to the records review, since development, the Site buildings have been developed for residential and commercial use.

The current and past ownership of the Site is summarized in Table II.

7.2 Potentially Contaminating Activities (PCAs)

A list of all the PCAs identified at the Site and within the Phase One Study Area are listed in the CSM Appendix J and shown on Figure 2.

7.3 Areas of Potential Environmental Concern (APECs)

Based on information from the reviewed maps, groundwater in the Phase One Study Area is inferred to flow in a southerly direction. Based on this, properties north of the Site are inferred to be up-gradient to the south, and properties south of the Site are inferred to be down-gradient. Furthermore, any PCAs located significantly distant from the Site (>100 m) were considered to be too distant to be contributing to an APEC on the Site.

The following PCAs were considered to contribute to an APEC:

- PCAs identified at the Site; and
- PCAs located on immediately adjacent properties (off-Site) or situated up-gradient to the Site with respect to the anticipated groundwater flow direction.

The APECs identified at the Site are summarized in the CSM in Appendix J and on Figure 4.

8. Conclusions

8.1 Whether Phase Two ESA Required Before RSC Submitted

Based on the results and findings of the Phase One ESA, a Phase Two ESA is required before a RSC may be submitted to investigate the following APECs identified at the Site:

Area of Potential Environmental Concern (APEC)	Location of APEC on Phase One Property	Potentially Contaminating Activity (PCA)[1]	Location of PCA (on-Site or off-Site)	Contaminants of Potential Concern	Media Potentially Impacted (Groundwater, soil and/or sediment)
APEC 1A: Application of De-icing salt on the on-Site paved areas (PCA 1A)	Asphalt paved driveways and walking areas at the Site	PCA" Other"- Application of De-icing salt	On-Site	EC and SAR	Soil
APEC 1B: Former storage of heating oil at 1376 Plains Road East (PCA 1B)	Southern portion of the building (prior to the extension)	PCA#28-Gasoline and Associated Products Storage in Fixed Tanks	On-Site	PHCS, PAH and BTEX	Soil and Ground Water
APEC 1C: Former storage of heating oil at 1382 Plains Road East (PCA 1C)	Southern portion of the building, where the furnace room is located	PCA#28-Gasoline and Associated Products Storage in Fixed Tanks	On-Site	PHCs, PAH and BTEX	Soil and Ground Water
APEC 2: Auto Service to the west of the Site (PCA 2 and 3A-C)	Western Site boundary	PCA#27-Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles #52-Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to	Off-Site 1364 Plains Road East (20 m west) 1358 Plains Road East (former 1364 Plains Road East)	PHCs, PAH, VOCs and Metals	Groundwater

Area of Potential Environmental Concern (APEC)	Location of APEC on Phase One Property	Potentially Contaminating Activity (PCA)[1]	Location of PCA (on-Site or off-Site)	Contaminants of Potential Concern	Media Potentially Impacted (Groundwater, soil and/or sediment)
		maintain transportation systems	1368 Plains Road East (West adjacent)		
APEC 3: Current presence of auto service to the east adjacent to Site (PCA 4A) Former presence of printing facility east adjacent to Site (PCA 4B)	Eastern Site boundary	#52-Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems PCA#31- Ink Manufacturing, Processing and Bulk Storage	Off-Site- east adjacent 1400 Plains Road East (PCA4C) Off-Site 1390 Plains Road East (PCA4B)	PHCs, PAH, VOCs and Metals	Groundwater
APEC 4: Former presence of a fruit canning company southeast adjacent to Site (PCA5A-C)	Southeastern Site boundary	PCA#2-Adhesives and Resins Manufacturing, Processing and Bulk Storage PCA#4- Antifreeze and De-icing Manufacturing and Bulk Storage PCA#34-Metal Fabrication	Off-Site – southeast adjacent	VOCs, PHCs, Metals	Groundwater
APEC 5: Historical auto repair at 1401 Plains Road East (PCA 7)	Northeastern boundary of the Site	#52-Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems	Off-Site – 25 m north	PHCs, PAH, VOCs and Metals	Groundwater

Area of Potential Environmental Concern (APEC)	Location of APEC on Phase One Property	Potentially Contaminating Activity (PCA)[1]	Location of PCA (on-Site or off-Site)	Contaminants of Potential Concern	Media Potentially Impacted (Groundwater, soil and/or sediment)
APEC 6: Presence of a rail line in close proximity to Site (PCA 6)	Southwestern boundary of the Site	PCA#46-Rail Yards, Tracks and Spurs	Off-Site- 5 m south	Metals, PAHs and PHCs	Groundwater

(1) Potentially contaminating activity means a use or activity set out in Column A of Table 2 of Schedule D (O.Reg.153/04, as amended) that is occurring or has occurred in a phase one Study area.

8.2 RSC Based on Phase One ESA Alone

As such, an RSC cannot be filed based on the Phase One ESA alone.

A Phase Two ESA is required to investigate the APECs identified in this Phase One ESA, prior to filing a RSC, if required.

9 Closure

We trust this report is satisfactory for your purposes. Should you have any questions, please do not hesitate to contact this office.

Yours truly,


EXP Services Inc.



Ramila Senanayake, M.E.S
Environmental Scientist
Environmental Services



Nolan McGahey, B.Sc.
Environmental Technologist
Environmental Services




Syed Hussaini, M.Eng., P.Eng., QP_{ESA}
Senior Project Engineer/Project Manager
Environmental Services

10 References

- Canadian Standards Association. November 2001. Z768-0 Phase I Environmental Site Assessment.
- Occupational Health and Safety Act - Ministry of Labour (MOL)
- York County Atlas: Miles & Co., 1878
- “Toporama"; Natural Resources Canada. Map 030M14. Scale 1:6,000. 2008.
- Quaternary Geology of Ontario - geology_ll.shp [computer file], Ontario: Ontario Geological Survey, 2000.
- Bedrock Geology of Ontario - geology_ll.shp [computer file], Ontario: Ontario Geological Survey, 2000.
- Inventory of Coal Gasification Plant Waste Sites in Ontario. Ontario Ministry of the Environment, April 1987.
- Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario. Ontario Ministry of the Environment, November 1988.
- Waste Disposal Site Inventory. Waste Management Branch Ontario Ministry of the Environment, June 1991.
- Ontario Inventory of PCB Storage Sites. Ontario Ministry of the Environment, 1993- 2003-2004.
- Catalogue of Canadian Fire Insurance Plans 1875 – 1975
- Ontario Ministry of the Environment, Brownfields Registry website (www.ene.gov.on.ca/environet/BESR/index.htm)
- Ontario Ministry of the Environment, Environmental Registry website (www.ene.gov.on.ca/envision/env_reg/ebr/english/index.htm)
- Ontario Ministry of Natural Resources, Natural Heritage website (www.mnr.gov.on.ca/MNR/nhic/areas.cfm)
- Oil, Gas & Salt Resources Library website (www.ogsrlibrary.com)
- Technical Standards and Safety Authority, Environmental Management Protocol for Fuel Handling Sites in Ontario, May 2007.
- Database Report, Phase One ESA 1376 and 1382 Plains Road East, Burlington, ON. Environmental Risk Information Services Ltd. (ERIS Ltd.) Order Number 23021000646 dated February 15, 2023.

Figures



EXP Services Inc.
t: +1.905.793.9800 | f: +1.905.793.0641
1595 Clark Boulevard
Brampton, ON L6T 4V1
Canada
www.exp.com

•BUILDINGS • EARTH & ENVIRONMENT • ENERGY •
• INDUSTRIAL • INFRASTRUCTURE • SUSTAINABILITY •


N

0 100 200 300 400 500 m

TITLE AND LOCATION:

SITE LOCATION PLAN
Phase One Environmental Site Assessment
1376 and 1382 Plains Road East
Burlington, Ontario

PROJECT No.: GTR-22029872-A0	DWN: HY
SCALE: AS NOTED	CHKD: SH
DATE: JULY 2023	FIG. No.: 1



EXP Services Inc.
t: +1.905.793.9800 | f: +1.905.793.0641
1595 Clark Boulevard
Brampton, ON L6T 4V1
Canada
www.exp.com

•BUILDINGS • EARTH & ENVIRONMENT • ENERGY •
• INDUSTRIAL • INFRASTRUCTURE • SUSTAINABILITY •

TITLE AND LOCATION:

PHASE ONE STUDY AREA, SURROUNDING LAND USE AND POTENTIALLY CONTAMINATING ACTIVITIES

Phase One Environmental Site Assessment
1376 and 1382 Plains Road East
Burlington, Ontario

PROJECT No.: GTR-22029872-A0	DWN: HY
SCALE: AS NOTED	CHKD: SH
DATE: JULY 2023	FIG. No.: 2



EXP Services Inc.
t: +1.905.793.9800 | f: +1.905.793.0641
1595 Clark Boulevard
Brampton, ON L6T 4V1
Canada
www.exp.com

•BUILDINGS • EARTH & ENVIRONMENT • ENERGY •
• INDUSTRIAL • INFRASTRUCTURE • SUSTAINABILITY •

N

0 4 8 12 16 20 m

TITLE AND LOCATION:

SITE PLAN
Phase One Environmental Site Assessment
1376 and 1382 Plains Road East
Burlington, Ontario

PROJECT No.: GTR-22029872-A0	DWN: HY
SCALE: AS NOTED	CHKD: SH
DATE: JULY 2023	FIG. No.: 3



EXP Services Inc.
t: +1.905.793.9800 | f: +1.905.793.0641
1595 Clark Boulevard
Brampton, ON L6T 4V1
Canada
www.exp.com

•BUILDINGS • EARTH & ENVIRONMENT • ENERGY •
• INDUSTRIAL • INFRASTRUCTURE • SUSTAINABILITY •

N

0 4 8 12 16 20 m

TITLE AND LOCATION:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN
Phase One Environmental Site Assessment
1376 and 1382 Plains Road East
Burlington, Ontario

PROJECT No.: GTR-22029872-A0	DWN: HY
SCALE: AS NOTED	CHKD: SH
DATE: JULY 2023	FIG. No.: 4

Tables

TABLE I

SITE ENVIRONMENTAL SETTING DATA

1376 and 1382 Plains Road East, Burlington, ON

NATIVE SOIL AND BEDROCK

Type:	Paleozoic bedrock
Hydraulic Conductivity:	Unknown
Percent Sand:	Unknown
Depth to Bedrock:	Unknown
Bedrock Type:	Georgian Bay Formation, Blue Mountain Formation, Billings Formation, Collingwood Member, and Eastview Member, primarily consisting of

GROUND WATER

Depth to Water Table:	Unknown
Estimated or Measured:	N/A
Direction of Flow:	South
Estimated or Measured:	Estimated (based on topomaps)

POTABLE WATER AND SEWERS

Potable Water Source:	Halton Region
Municipal Water Source:	Halton Region
Distance to Nearest Municipal Water Well:	Unknown
Distance to Nearest Private Water Well:	Unknown
Sanitary Sewage System:	Halton Region
Storm Water System:	Halton Region

SURFACE WATER

Name of Nearest Water Body:	Lake Ontario
Distance/Direction from Site:	2.35 km
Elevation Drop from Site:	Unknown
Direct Drainage from Site:	Infiltration

TABLE II

TABLE OF CURRENT AND PAST USES OF THE PHASE ONE PROPERTY

(Refer to clause 16(2)(b), Schedule D, O.Reg. 153/04)
1376 and 1382 Plains Road East, Burlington, ON

Year	Name of Owner	Description of Property Use	Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, Etc.
1376 Plains Road East, Burlington, ON				
1798	Crown			
1798-1810	Joseph Brant			
1810-1818	Ralph Morden			
1818-1845	Joshua Frecueau			
1845-1858	Joseph Frecueau			
1858-1879	James Filman			
1879-1889	Joseph Sommens			
1889-1892	The Burlington Manufacturing Company			
1892-1897	William Yong			
1897-1901	Martha and Alonzo Tufford			
1901-1904	Eliza Ann Hanes			
1904-1942	Ann Jane Baker	Residential Use	Residential Use	Based on the reviewed FIPs, the Site was developed with a residential dwelling prior to 1924.
1942-1965	James Baker			
1965-1974	EdwardJ and Katherine Robers			
1974-1999	Shirley Alexandra Mayeski			
1999-2017	Hardsoft Systems Inc.	Commercial building	Commercial Use	Based on the observations made at the time of the Site visit, the building is occupied by commercial tenants
2017-2019	Manor Care Homes Inc.			
2019-present	Manor Care Homes Inc (50%); 2731119 Ontario Inc. (50%)			

Notes:

1 - for each owner, specify one of the following types of property use (as defined in O.Reg. 153/04) that applies:

Agriculture or other use
Commercial use
Community use
Industrial use
Institutional use
Parkland use
Residential use

2 - when submitting a record of site condition for filing, a copy of this table must be attached

Cette publication hautement spécialisée n'est disponible qu'en anglais en vertu du règlement 671/92, qui en exempte l'application de la Loi sur les services en français. Pour obtenir de

TABLE II

TABLE OF CURRENT AND PAST USES OF THE PHASE ONE PROPERTY

(Refer to clause 16(2)(b), Schedule D, O.Reg. 153/04)
1376 and 1382 Plains Road East, Burlington, ON

Year	Name of Owner	Description of Property Use	Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, Etc.
1382 Plains Road East, Burlington, ON				
1798	Crown	Vacant land	Agricultural or other use	None
1798-1810	Joseph Brant			
1810-1818	Ralph Morden			
1818-1845	Joshua Frecueau			
1845-1858	Joseph Frecueau			
1858-1879	James Filman			
1879-1889	Joseph Sommens			
1889-1903	The Burlington Manufacturing Company			
1903-1905	Charles G Davis			
1905-1906	Henry Potter			
1906-1951	Robert Gray	Residential dwelling	Residential Use	Based on the reviewed FIPs, the Site was developed with a residential dwelling prior to 1924.
1951-1952	Amy Lucinda Gray			
1952-1965	Josepf and Helen Koziello			
1965-1969	William John Frederick and Bradley Laurence Clack			
1969-1971	Kam Fran Kung			
1971-1988	Brian Calvin and Lennard Mayeski			
1988-2004	Jamal Razek			
2004-2008	Ahmad El-Dorra and Razek Jamal	Commercial building	Commercial Use	Based on the observations made at the time of the Site visit, the building is occupied by commercial tenants
2008-2019	F.K Deals on Wheels Inc.			
2019-Present	F. K Deals on Wheels Inc. (50%); 2731115 Ontario Inc. (50%)			

Notes:

1 - for each owner, specify one of the following types of property use (as defined in O.Reg. 153/04) that applies:

Agriculture or other use
Commercial use
Community use
Industrial use
Institutional use
Parkland use
Residential use

2 - when submitting a record of site condition for filing, a copy of this table must be attached

Cette publication hautement spécialisée n'est disponible qu'en anglais en vertu du règlement 671/92, qui en exempte l'application de la Loi sur les services en français. Pour obtenir de

TABLE II

TABLE OF CURRENT AND PAST USES OF THE PHASE ONE PROPERTY

(Refer to clause 16(2)(b), Schedule D, O.Reg. 153/04)
Lane plan 88, Burlington, ON

Year	Name of Owner	Description of Property Use	Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, Etc.
07087-0440 (LT)				
1798	Crown	Vacant land	Agricultural or Other Use	None
1798-1810	Joseph Brant			
1810-1818	Ralph Morden			
1818-1845	Joshua Frecueau			
1845-1858	Joseph Frecueau			
1858-1879	James Filman			
1879-1889	Joseph Sommens			
1889-1889	The Burlington Manufacturing Company			
1889-2023	The Minicipal Corporation of the Town of Burlington	Laneway	Community use	Based on the reviewed aerial photogrphs, this portion of the Site was developed as a paved roadway.
2023-Present	Manor Care Homes Inc., 2731119 Ontario Inc., F. K Deals on Wheels Inc.; 2731115 Ontario Inc.			At the time of the Site visit, this was a paved roadway.

Notes:

1 - for each owner, specify one of the following types of property use (as defined in O.Reg. 153/04) that applies:

Agriculture or other use
Commercial use
Community use
Industrial use
Institutional use
Parkland use
Residential use

2 - when submitting a record of site condition for filing, a copy of this table must be attached

Cette publication hautement spécialisée n'est disponible qu'en anglais en vertu du règlement 671/92, qui en exempte l'application de la Loi sur les services en français. Pour obtenir de

TABLE II

TABLE OF CURRENT AND PAST USES OF THE PHASE ONE PROPERTY

(Refer to clause 16(2)(b), Schedule D, O.Reg. 153/04)

Alley Plan 88, Burlington, ON

Year	Name of Owner	Description of Property Use	Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, Etc.
07087-0438 (LT)				
1798	Crown	Vacant land	Agricultural or Other Use	None
1798-1810	Joseph Brant			
1810-1818	Ralph Morden			
1818-1845	Joshua Frecueau			
1845-1858	Joseph Frecueau			
1858-1879	James Filman			
1879-1889	Joseph Sommens			
1889-1941	The Burlington Manufacturing Company			Based on the reviewed 1924 FIP, this was observed to be vacant land with no buildings or structures.
1941-2023	The Minicipal Corporation of the Town of Burlington	Laneway	Community use	Based on the reviewed aerial photogrphs, this portion of the Site was developed as a paved roadway.
2023-Present	Manor Care Homes Inc., 2731119 Ontario Inc., F. K Deals on Wheels Inc; 2731115 Ontario Inc.			At the time of the Site visit, this was a paved roadway.

Notes:

1 - for each owner, specify one of the following types of property use (as defined in O.Reg. 153/04) that applies:

Agriculture or other use
Commercial use
Community use
Industrial use
Institutional use
Parkland use
Residential use

2 - when submitting a record of site condition for filing, a copy of this table must be attached

Cette publication hautement spécialisée n'est disponible qu'en anglais en vertu du règlement 671/92, qui en exempte l'application de la Loi sur les services en français. Pour obtenir de

Appendix A – Liability

LIMITATIONS AND USE OF REPORT

BASIS OF REPORT

The Report is based on site conditions known or inferred by the investigation undertaken as of the date of the Report. Should changes occur which potentially impact the condition of the site the recommendations of EXP may require re-evaluation. Where special concerns exist, or the Client has special considerations or requirements, these should be disclosed to EXP to allow for additional or special investigations to be undertaken not otherwise within the scope of investigation conducted for the purpose of the Report.

Where applicable, recommended field services are the minimum necessary to ascertain that construction is being carried out in general conformity with building code guidelines, generally accepted practices and EXP's recommendations. Any reduction in the level of services recommended will result in EXP providing qualified opinions regarding the adequacy of the work. EXP can assist design professionals or contractors retained by the Client to review applicable plans, drawings, and specifications as they relate to the Report or to conduct field reviews during construction.

RELIANCE ON INFORMATION PROVIDED

The evaluation and conclusions contained in the Report are based on conditions in evidence at the time of site inspections and information provided to EXP by the Client and others. The Report has been prepared for the specific site, development, building, design or building assessment objectives and purpose as communicated by the Client. EXP has relied in good faith upon such representations, information and instructions and accepts no responsibility for any deficiency, misstatement or inaccuracy contained in the Report as a result of any misstatements, omissions, misrepresentation or fraudulent acts of persons providing information. Unless specifically stated otherwise, the applicability and reliability of the findings, recommendations, suggestions or opinions expressed in the Report are only valid to the extent that there has been no material alteration to or variation from any of the information provided to EXP.

STANDARD OF CARE

This report ("Report") has been prepared in a manner consistent with the degree of care and skill exercised by engineering consultants currently practicing under similar circumstances and locale. No other warranty, expressed or implied, is made. Unless specifically stated otherwise, the Report does not contain environmental consulting advice.

COMPLETE REPORT

All documents, records, data and files, whether electronic or otherwise, generated as part of this assignment form part of the Report. This material includes, but is not limited to, the terms of reference given to EXP by the Client, communications between EXP and the Client, other reports, proposals or documents prepared by EXP for the Client in connection with the site described in the Report. In order to properly understand the suggestions, recommendations and opinions expressed in the Report, reference must be made to the Report in its entirety. EXP is not responsible for use by any party of portions of the Report.


USE OF REPORT

The information and opinions expressed in the Report, or any document forming part of the Report, are for the sole benefit of the Client. No other party may use or rely upon the Report in whole or in part without the written consent of EXP. Any use of the Report, or any portion of the Report, by a third party are the sole responsibility of such third party. EXP is not responsible for damages suffered by any third party resulting from unauthorised use of the Report.

REPORT FORMAT

Where EXP has submitted both electronic file and a hard copy of the Report, or any document forming part of the Report, only the signed and sealed hard copy shall be the original documents for record and working purposes. In the event of a dispute or discrepancy, the hard copy shall govern. Electronic files transmitted by EXP utilize specific software and hardware systems. EXP makes no representation about the compatibility of these files with the Client's current or future software and hardware systems. Regardless of format, the documents described herein are EXP's instruments of professional service and shall not be altered without the written consent of EXP.

Appendix B – Survey Plan



SCHEDULE			
PART	LOT	PLAN	PART OF PIN
1	PART OF ALLEYWAY	REGISTERED PLAN 88	07087-0043
2	PART OF LANE		07087-0046

PLAN OF SURVEY OF
PART OF

ALLEYWAY & LANE REGISTERED PLAN 88

IN THE

CITY OF BURLINGTON

REGIONAL MUNICIPALITY OF HALTON

SCALE 1 : 200

0 5 10 20 metres

THE INTENDED PLOT SIZE OF THIS PLAN IS 915mm IN WIDTH BY 610mm IN HEIGHT WHEN PLOTTED AT A SCALE OF 1:200

MacKAY, MacKAY & PETERS LIMITED - ONTARIO LAND SURVEYORS - 2022

METRIC *DISTANCES AND COORDINATES SHOWN HEREON ARE IN METRES AND CAN BE CONVERTED TO FEET BY DIVIDING BY 0.3048*

INTEGRATION DATA		
OBSERVED REFERENCE POINTS (ORP's): UTM ZONE 17, NAD83 (CSRS) (2010.0) COORDINATES ARE TO AN URBAN ACCURACY PER SECTION 14(2) OF O.REG. 216/10		
POINT ID	NORTHING	EASTING
A	4798782.45	595720.89
B	4798811.61	595792.52
CAUTION: COORDINATES CANNOT, IN THEMSELVES, BE USED TO RE-ESTABLISH CORNERS OR BOUNDARIES SHOWN ON THIS PLAN		

BEARING REFERENCE

BEARINGS ARE UTM GRID, DERIVED FROM OBSERVED REFERENCE POINTS A AND B, BY REAL TIME NETWORK (RTN) OBSERVATIONS, UTM ZONE 17, NAD83 (CSRS) (2010.0)

DISTANCES ON THIS PLAN ARE GROUND AND CAN BE CONVERTED TO GRID BY MULTIPLYING BY THE COMBINED SCALE FACTOR OF 0.99955482

A ROTATION OF 01°05'20" HAS BEEN APPLIED TO BEARINGS ON P1, P2, P3, P4, P5 & P6

LEGEND

- ■ DENOTES A SURVEY MONUMENT FOUND
- □ DENOTES A SURVEY MONUMENT PLANTED
- SIB DENOTES STANDARD IRON BAR
- SSIB DENOTES SHORT STANDAR IRON BAR
- IB DENOTES IRON BAR
- CP DENOTES CONCRETE PIN
- (OU) DENOTES ORIGIN UNKNOWN
- PIN DENOTES PROPERTY IDENTIFICATION NUMBER
- P1 DENOTES PLAN BY MACKAY, MACKAY & PETERS LIMITED DATED JANUARY 28, 2000 (00H-005)
- P2 DENOTES PLAN 20R-18576
- P3 DENOTES PLAN 20R-4701
- P4 DENOTES PLAN 20R-11699
- P5 DENOTES PLAN BY YATES & YATES LIMITED DATED AUGUST 16, 1985 (85Y-429)
- P6 DENOTES PLAN 20R-13096
- P7 DENOTES PLAN 20R-21086
- C1 DENOTES CALCULATED FROM P3 AND P5

SURVEYOR'S CERTIFICATE

I CERTIFY THAT:

1. THIS SURVEY AND PLAN ARE CORRECT AND IN ACCORDANCE WITH THE SURVEYS ACT, THE SURVEYORS ACT, THE LAND TITLES ACT AND THE REGULATIONS MADE UNDER THEM.
2. THE SURVEY WAS COMPLETED ON THE DAY OF

DATE

ROY C. MAYO
ONTARIO LAND SURVEYOR
FOR MACKAY, MACKAY AND PETERS LIMITED

THIS PLAN OF SURVEY RELATES TO AOLS PLAN SUBMISSION FORM NUMBER

E:\(20) Halton\Registered Plans\RP0088\LANEWAY\21-467\21-467-R.dwg

MacKay, MacKay & Peters Limited
LAND SURVEYORS & MAPPERS
SINCE 1906

3380 South Service Road
Unit 101
Burlington, ON
L7N 3J5
(905) 639-1375

halton@mmplimited.com
mmplimited.com

DRAWN BY:	K.J.D.
PARTY CHIEF:	
CHECKED BY:	
PROJECT No.:	21-467-R

Appendix C – Qualifications

Qualifications of Assessors

The records review was completed by Ms. Ramila Senanayake, M.E.S., who has over six (6) years of experience conducting Phase I environmental site assessments in accordance with applicable CSA Standards and O.Reg. 153/04. Ramila completed a Bachelor of Environmental Science Degree from University of Toronto at Mississauga, Master of Environmental Studies at York University and post graduate program in Environmental Control at Sheridan College.

The Site visit was conducted by Mr. Nolan McGahey, B.Sc., who has been trained to conduct Phase I and II Environmental Site Assessments (in accordance with the applicable CSA Standards and O.Reg. 153/04) and Assessment of Past Uses (in accordance with O.Reg. 406/19). Mr. McGahey completed a Bachelor of Environmental Resource Science at Trent University and obtained an diploma in the Environmental Technologist program at Sir Sandford Fleming Colleg

This report was reviewed by Mr. Syed Hussaini. Syed is a licensed professional engineer in Ontario, is a Qualified Person (QP) under O. Reg. 153/04 (as amended) and has over 25 years of experience conducting and managing Phase I and II ESAs for residential, commercial and industrial properties across Ontario. Syed has a Master of Engineering degree from the University of Maryland (1996). Syed has worked on a variety of environmental site assessment, remediation, and brownfield redevelopment projects during his career.

EXP Services Inc. is a full-service consulting and engineering firm and provides a full range of environmental services through the Environmental Services Group. EXP's Environmental Services Group has developed a strong working relationship with clients in both the private and public sectors and has developed a positive relationship with the Ontario Ministry of the Environment. Personnel in the numerous branch offices form part of a large network of full-time dedicated environmental professionals in the EXP organization.

Appendix D – Chain of Title

CHAIN OF TITLE REPORT

Project #: GTR-22029872-A0
Address: 1376 Plains Road E., Burlington
Legal Description: Part lots 18 & 19, Plan 88 as in 403089 ex. Pt 1, 20R11699

PIN #: 07087-0044(LT)

Searched at: Milton
LRO #: 20

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
	Patent	14 02 1798	Crown	**Capt. Joseph BRANT**
405	Deed	21 03 1810	Joseph Brant	Ralph MORDEN
274	Deed	30 05 1818	Ralph Morden	Joshua FRECUEAU
155	Deed	10 07 1845	Joshua Frecueau	Joseph FRECUEAU
853	Deed	10 03 1858	Joseph Frecueau	James FILMAN
341	Deed	04 06 1879	James Filman	Joseph SOMMENS
1162	Deed	02 11 1889	Joseph Sommens	The Burlington Manufacturing Company
1389	Deed	22 06 1892	The Burlington Manufacturing Co.	William YOUNG
1783	Deed	15 05 1897	William Young	Martha TUFFORD & Alonzo TUFFORD

Cont'd on page 2

CHAIN OF TITLE REPORT

Project #: GTR-22029872-A0
Address: 1376 Plains Road E., Burlington
Legal Description: Part lots 18 & 19, Plan 88 as in 403089 ex. Pt 1, 20R11699

Searched at: Milton
LRO #: 20

PIN #: 07087-0044(LT)

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
2062	Deed	14 02 1901	Martha & Alonzo Tufford	Eliza Ann HANES
2849	Deed	25 03 1904	Eliza Ann Hanes	Ann Jane BAKER
10854	Deed	16 04 1942	Ann Jane Baker - estate	James BAKER
185028	Deed	18 06 1965	James Baker	Edward J. ROBERTS & Katherine ROBERTS
403089	Deed	29 11 1974	Edward J. Roberts & Katherine Roberts	Shirley Alexandra MAYESKI
H813833	Deed	30 09 1999	Shirley Alexandra Mayeski	Hardsoft Systems Inc.
HR1501333	Deed	01 11 2017	Hardsoft Systems Inc.	Manor Care Homes Inc.
HR1671659	Deed **(Present Owners)**	11 12 2019	Manor Care Homes Inc.	**Manor Care Homes Inc. 50%** **2731119 Ontario Inc. 50%**

CHAIN OF TITLE REPORT

Project #: GTR-22029872-A0
Address: 1382 Plains Road E., Burlington
Legal Description: lot 17, Part lot 18, Plan 88 as in 704027 ex. Pt 1, 20R18576

Searched at: Milton
LRO #: 20

PIN #: 07087-0405(LT)

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
	Patent	14 02 1798	Crown	**Capt. Joseph BRANT**
405	Deed	21 03 1810	Joseph Brant	Ralph MORDEN
274	Deed	30 05 1818	Ralph Morden	Joshua FRECUEAU
155	Deed	10 07 1845	Joshua Frecueau	Joseph FRECUEAU
853	Deed	10 03 1858	Joseph Frecueau	James FILMAN
341	Deed	04 06 1879	James Filman	Joseph SOMMENS
1162	Deed	02 11 1889	Joseph Sommens	The Burlington Manufacturing Company
2235	Deed	29 02 1903	The Burlington Manufacturing Co.	Charles G. DAVIS
2554	Deed	05 04 1905	Charles G. Davis	Henry POTTER

Cont'd on page 2

CHAIN OF TITLE REPORT

Project #: GTR-22029872-A0
Address: 1382 Plains Road E., Burlington
Legal Description: lot 17, Part lot 18, Plan 88 as in 704027 ex. Pt 1, 20R18576

Searched at: Milton
LRO #: 20

PIN #: 07087-0405(LT)

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
2684	Deed	02 04 1906	Henry Potter	Robert GRAY
15563	Deed	03 04 1951	Robert Gray - estate	Amy Lucinda GRAY
16156	Deed	07 03 1952	Amy Lucinda Gray	Josef KOZIELLO & Helen KOZIELLO
182704	Deed	30 04 1965	Josef & Helen Koziello	William John Frederick CLACK Bradley Laurence CLACK
283459	Deed	31 10 1969	William John Frederick Clack Bradley Laurence Clack	Kam Fran KUNG
284279	Deed	12 06 1971	Kam Fran Kung	Brian CALVIN & Lennard MAYESKI
418175	Deed	21 08 1975	Brian Calvin	Lennard Mayeski
704027	Deed	14 10 1988	Lennard Mayeski	Jamal RAZEK
HR289830	Deed	31 05 2004	Jamal Razek	Ahmad EL-DORRA Razek JAMAL

Cont'd on page 3

CHAIN OF TITLE REPORT

Project #: GTR-22029872-A0
Address: 1382 Plains Road E., Burlington
Legal Description: lot 17, Part lot 18, Plan 88 as in 704027 ex. Pt 1, 20R18576

Searched at: Milton
LRO #: 20

PIN #: 07087-0405(LT)

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
HR648493	Deed	14 03 2008	Ahmad El-Dorra Razek Jamal	F.K. Deals On Wheels Inc.
HR1671662	Deed **(Present Owners)**	11 12 2019	F.K. Deals On Wheels Inc.	**F.K. Deals On Wheels Inc. 50% int.** **2731115 Ontario Inc. 50% int.**

* CERTIFIED IN ACCORDANCE WITH THE LAND TITLES ACT * SUBJECT TO RESERVATIONS IN CROWN GRANT *

PROPERTY DESCRIPTION: PT LTS 18 & 19, PL 88 , AS IN 403089 EXCEPT PART 1, 20R11699 ; BURLINGTON

PROPERTY REMARKS:

ESTATE/QUALIFIER:
FEE SIMPLE
LT CONVERSION QUALIFIED

RECENTLY:
FIRST CONVERSION FROM BOOK

PIN CREATION DATE:
1998/01/26

OWNERS' NAMES	CAPACITY	SHARE
MANOR CARE HOMES INC.	TCOM	50%
2731119 ONTARIO INC.	TCOM	50%

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
EFFECTIVE 2000/07/29 THE NOTATION OF THE "BLOCK IMPLEMENTATION DATE" OF 1998/01/26 ON THIS PIN						
WAS REPLACED WITH THE "PIN CREATION DATE" OF 1998/01/26						
*** PRINTOUT INCLUDES ALL DOCUMENT TYPES AND DELETED INSTRUMENTS SINCE 1998/01/23 ***						
***SUBJECT, ON FIRST REGISTRATION UNDER THE LAND TITLES ACT, TO:*						
*** SUBSECTION 44(1) OF THE LAND TITLES ACT, EXCEPT PARAGRAPH 11, PARAGRAPH 14, PROVINCIAL SUCCESSION DUTIES **						
*** AND ESCHEATS OR FORFEITURE TO THE CROWN.*						
*** THE RIGHTS OF ANY PERSON WHO WOULD, BUT FOR THE LAND TITLES ACT, BE ENTITLED TO THE LAND OR ANY PART OF*						
*** IT THROUGH LENGTH OF ADVERSE POSSESSION, PRESCRIPTION, MISDESCRIPTION OR BOUNDARIES SETTLED BY*						
*** CONVENTION.*						
*** ANY LEASE TO WHICH THE SUBSECTION 70(2) OF THE REGISTRY ACT APPLIES.*						
***DATE OF CONVERSION TO LAND TITLES: 1998/01/26 ***						
119980	1961/01/25	BYLAW				C
344020	1972/08/23	AGREEMENT			THE CORPORATION OF THE TOWN OF BURLINGTON	C
403089	1974/11/29	TRANSFER		*** COMPLETELY DELETED ***	MAYESKI, SHIRLEY ALEXANDRA	
636472	1986/02/27	NOTICE OF LEASE		*** COMPLETELY DELETED ***	VAN HERWYNEN, JAN P. VAN HERWYNEN, DENISE VAN HERWYNEN FLORIST COMPANY LIMITED COB KING'S FLORIST	
636473	1986/02/27	NOTICE OF LEASE		*** COMPLETELY DELETED ***		

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
					VAN HERWYNEN, JAN P. VAN HERWYNEN, DENISE VAN HERWYNEN FLORIST COMPANY LIMITED COB KING'S FLORIST	
842250	1995/08/30	AGREEMENT			THE CORPORATION OF THE CITY OF BURLINGTON	C
H813254	1999/09/29	APL (GENERAL)		*** COMPLETELY DELETED *** MAYESKI, SHIRLEY ALEXANDRA		
	REMARKS: DELETE 636473					
H813255	1999/09/29	APL (GENERAL)		*** COMPLETELY DELETED *** MAYESKI, SHIRLEY ALEXANDRA		
	REMARKS: DELETE 636472					
H813833	1999/09/30	TRANSFER		*** COMPLETELY DELETED *** MAYESKI, SHIRLEY ALEXANDRA	HARDSOFT SYSTEMS LTD.	
H813834	1999/09/30	CHARGE		*** COMPLETELY DELETED *** HARDSOFT SYSTEMS LTD.	MAYESKI, SHIRLEY ALEXANDRA MAYESKI, LENNARD JOHN	
HR326474	2004/10/07	LIEN		*** COMPLETELY DELETED *** HER MAJESTY THE QUEEN IN RIGHT OF ONTARIO AS REPRESENTED BY THE MINISTER OF FINANCE		
HR611245	2007/10/12	CHARGE		*** COMPLETELY DELETED *** HARDSOFT SYSTEMS LTD.	ROYAL BANK OF CANADA	
HR611379	2007/10/12	DISCH OF CHARGE		*** COMPLETELY DELETED *** MAYESKI, SHIRLEY ALEXANDRA MAYESKI, LENNARD JOHN		
	REMARKS: RE: H813834					
HR619382	2007/11/13	DISCHARGE INTEREST		*** COMPLETELY DELETED ***	HER MAJESTY THE QUEEN IN RIGHT OF ONTARIO AS REPRESENTED BY THE MINISTER OF REVENUE	
	REMARKS: RE: HR326474					
HR1501333	2017/11/01	TRANSFER	$1,000,000	HARDSOFT SYSTEMS LTD.	MANOR CARE HOMES INC.	C
	REMARKS: PLANNING ACT STATEMENTS.					

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

* CERTIFIED IN ACCORDANCE WITH THE LAND TITLES ACT * SUBJECT TO RESERVATIONS IN CROWN GRANT *

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
HR1501334	2017/11/01	CHARGE		*** COMPLETELY DELETED *** MANOR CARE HOMES INC.	HARDSOFT SYSTEMS LTD.	
HR1586338	2018/11/16	DISCH OF CHARGE		*** COMPLETELY DELETED *** ROYAL BANK OF CANADA		
	REMARKS: HR611245.					
HR1671659	2019/12/11	TRANSFER	$575,553	MANOR CARE HOMES INC.	2731119 ONTARIO INC.	C
	REMARKS: PLANNING ACT STATEMENTS.					
HR1706502	2020/06/12	DISCH OF CHARGE		*** COMPLETELY DELETED *** HARDSOFT SYSTEMS LTD.		
	REMARKS: HR1501334.					
HR1706832	2020/06/15	CHARGE	$1,680,000	MANOR CARE HOMES INC. 2731119 ONTARIO INC. 2731115 ONTARIO INC. F.K DEALS ON WHEELS INC.	LAURENTIAN BANK OF CANADA	C
HR1706833	2020/06/15	NO ASSGN RENT GEN		MANOR CARE HOMES INC. 2731119 ONTARIO INC. 2731115 ONTARIO INC. F.K DEALS ON WHEELS INC.	LAURENTIAN BANK OF CANADA	C
	REMARKS: HR1706832					

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

* CERTIFIED IN ACCORDANCE WITH THE LAND TITLES ACT * SUBJECT TO RESERVATIONS IN CROWN GRANT *

PROPERTY DESCRIPTION: LT 17 & PT LT 18, PL 88 AS IN 704027 S&E PT 1, 20R18576.; CITY OF BURLINGTON

PROPERTY REMARKS:

ESTATE/QUALIFIER:
FEE SIMPLE
LT CONVERSION QUALIFIED

RECENTLY:
DIVISION FROM 07087-0045

PIN CREATION DATE:
2010/08/25

OWNERS' NAMES	CAPACITY	SHARE
2731115 ONTARIO INC.	TCOM	50% INT
F.K DEALS ON WHEELS INC.	TCOM	50% INT

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
** PRINTOUT INCLUDES ALL DOCUMENT TYPES AND DELETED INSTRUMENTS SINCE 2010/08/25 **						
**SUBJECT, ON FIRST REGISTRATION UNDER THE LAND TITLES ACT, TO:						
** SUBSECTION 44(1) OF THE LAND TITLES ACT, EXCEPT PARAGRAPH 11, PARAGRAPH 14, PROVINCIAL SUCCESSION DUTIES *						
** AND ESCHEATS OR FORFEITURE TO THE CROWN.						
** THE RIGHTS OF ANY PERSON WHO WOULD, BUT FOR THE LAND TITLES ACT, BE ENTITLED TO THE LAND OR ANY PART OF						
** IT THROUGH LENGTH OF ADVERSE POSSESSION, PRESCRIPTION, MISDESCRIPTION OR BOUNDARIES SETTLED BY						
** CONVENTION.						
** ANY LEASE TO WHICH THE SUBSECTION 70(2) OF THE REGISTRY ACT APPLIES.						
**DATE OF CONVERSION TO LAND TITLES: 1998/01/26 **						
119980	1961/01/25	BYLAW				C
HR648493	2008/03/14	TRANSFER	$505,000	EL-DORRA, AHMAD JAMAL, RAZEK	F.K DEALS ON WHEELS INC.	C
REMARKS: PLANNING ACT STATEMENTS THIS DOCUMENT WAS RE-INSTATED ON 2020/02/11 AT 10:43 BY OUELLETTE, MARY BETH.						
HR648494	2008/03/14	CHARGE		*** DELETED AGAINST THIS PROPERTY *** F.K DEALS ON WHEELS INC.	PALANDRA, MATTEO PALANDRA, VALERIA	
HR648495	2008/03/14	NO ASSGN RENT GEN		*** DELETED AGAINST THIS PROPERTY *** F.K DEALS ON WHEELS INC.	PALANDRA, MATTEO PALANDRA, VALERIA	
REMARKS: HR648494-RENTS						
HR835016	2010/04/22	NOTICE		*** DELETED AGAINST THIS PROPERTY *** F. K DEALS ON WHEELS INC.	PALANDRA, MATTEO PALANDRA, VALERIA	

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
	REMARKS: HR648494					
HR865526	2010/08/03	NOTICE	$1	THE CORPORATION OF THE CITY OF BURLINGTON		C
HR1671643	2019/12/11	DISCH OF CHARGE		*** COMPLETELY DELETED *** PALANDRA, MATTEO PALANDRA, VALERIA		
	REMARKS: HR648494.					
HR1671662	2019/12/11	TRANSFER	$441,181	F.K DEALS ON WHEELS INC.	2731115 ONTARIO INC.	C
	REMARKS: PLANNING ACT STATEMENTS.					
HR1683554	2020/02/11	LR'S ORDER		LAND REGISTRAR, HALTON LAND REGISTRY OFFICE		C
	REMARKS: AMEND OWNERSHIP FIELD, RE-INSTATE DOCUMENT					
HR1706832	2020/06/15	CHARGE	$1,680,000	MANOR CARE HOMES INC. 2731119 ONTARIO INC. 2731115 ONTARIO INC. F.K DEALS ON WHEELS INC.	LAURENTIAN BANK OF CANADA	C
HR1706833	2020/06/15	NO ASSGN RENT GEN		MANOR CARE HOMES INC. 2731119 ONTARIO INC. 2731115 ONTARIO INC. F.K DEALS ON WHEELS INC.	LAURENTIAN BANK OF CANADA	C
	REMARKS: HR1706832					

PARCEL REGISTER (ABBREVIATED) FOR PROPERTY IDENTIFIER

LAND REGISTRY OFFICE #20

07087-0438 (LT)

PREPARED FOR bertucci

ON 2023/03/07 AT 11:22:26

* CERTIFIED IN ACCORDANCE WITH THE LAND TITLES ACT * SUBJECT TO RESERVATIONS IN CROWN GRANT *

PROPERTY DESCRIPTION: PT ALLEYWAY, PL 88 ; DESIGNATED AS PART 1, PLAN 20R22199; BURLINGTON; SUBJECT TO AN EASEMENT AS IN HR1947526

PROPERTY REMARKS:

ESTATE/QUALIFIER:
FEE SIMPLE
LT CONVERSION QUALIFIED

RECENTLY:
DIVISION FROM 07087-0043

PIN CREATION DATE:
2023/03/06

OWNERS' NAMES	CAPACITY	SHARE
MANOR CARE HOMES INC.	TCOM	
2731119 ONTARIO INC.	TCOM	
F. K DEALS ON WHEELS INC.	TCOM	
2731115 ONTARIO INC.	TCOM	

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
*** PRINTOUT INCLUDES ALL DOCUMENT TYPES AND DELETED INSTRUMENTS SINCE 2023/03/06 ****						
***SUBJECT, ON FIRST REGISTRATION UNDER THE LAND TITLES ACT, TO:*						
** SUBSECTION 44(1) OF THE LAND TITLES ACT, EXCEPT PARAGRAPH 11, PARAGRAPH 14, PROVINCIAL SUCCESSION DUTIES *						
** AND ESCHEATS OR FORFEITURE TO THE CROWN.						
** THE RIGHTS OF ANY PERSON WHO WOULD, BUT FOR THE LAND TITLES ACT, BE ENTITLED TO THE LAND OR ANY PART OF						
** IT THROUGH LENGTH OF ADVERSE POSSESSION, PRESCRIPTION, MISDESCRIPTION OR BOUNDARIES SETTLED BY						
** CONVENTION.						
** ANY LEASE TO WHICH THE SUBSECTION 70(2) OF THE REGISTRY ACT APPLIES.						
DATE OF CONVERSION TO LAND TITLES: 1998/01/26 *						
BH9160	1934/10/16	COURT ORDER				C
20R22199	2022/07/25	PLAN REFERENCE				C
		REMARKS: HR1909400.				
HR1943124	2023/01/11	BYLAW		THE CORPORATION OF THE CITY OF BURLINGTON		C
HR1947525	2023/02/03	TRANSFER	$80,000	THE CORPORATION OF THE CITY OF BURLINGTON	MANOR CARE HOMES INC. 2731119 ONTARIO INC. F. K DEALS ON WHEELS INC. 2731115 ONTARIO INC.	C
HR1947526	2023/02/03	TRANSFER EASEMENT	$1	MANOR CARE HOMES INC. 2731119 ONTARIO INC. F. K DEALS ON WHEELS INC. 2731115 ONTARIO INC.	THE CORPORATION OF THE CITY OF BURLINGTON	C

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

* CERTIFIED IN ACCORDANCE WITH THE LAND TITLES ACT * SUBJECT TO RESERVATIONS IN CROWN GRANT *

PROPERTY DESCRIPTION: PT LANE, PL 88 , DESIGNATED AS PART 2 PLAN 20R22199; BURLINGTON; SUBJECT TO AN EASEMENT AS IN HR1947526

PROPERTY REMARKS:

ESTATE/QUALIFIER:	RECENTLY:	PIN CREATION DATE:
FEE SIMPLE LT CONVERSION QUALIFIED	DIVISION FROM 07087-0046	2023/03/06

OWNERS' NAMES	CAPACITY	SHARE
MANOR CARE HOMES INC.	TCOM	
2731119 ONTARIO INC.	TCOM	
F. K DEALS ON WHEELS INC.	TCOM	
2731115 ONTARIO INC.	TCOM	

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
** PRINTOUT INCLUDES ALL DOCUMENT TYPES AND DELETED INSTRUMENTS SINCE 2023/03/06 **						
**SUBJECT, ON FIRST REGISTRATION UNDER THE LAND TITLES ACT, TO:						
** SUBSECTION 44(1) OF THE LAND TITLES ACT, EXCEPT PARAGRAPH 11, PARAGRAPH 14, PROVINCIAL SUCCESSION DUTIES *						
** AND ESCHEATS OR FORFEITURE TO THE CROWN.						
** THE RIGHTS OF ANY PERSON WHO WOULD, BUT FOR THE LAND TITLES ACT, BE ENTITLED TO THE LAND OR ANY PART OF						
** IT THROUGH LENGTH OF ADVERSE POSSESSION, PRESCRIPTION, MISDESCRIPTION OR BOUNDARIES SETTLED BY						
** CONVENTION.						
** ANY LEASE TO WHICH THE SUBSECTION 70(2) OF THE REGISTRY ACT APPLIES.						
**DATE OF CONVERSION TO LAND TITLES: 1998/01/26 **						
PL88	1889/10/22	PLAN SUBDIVISION				C
119980	1961/01/25	BYLAW				C
523132	1980/06/17	AGREEMENT			THE CORPORATION OF THE CITY OF BURLINGTON	C
523133	1980/06/17	AGREEMENT			THE CORPORATION OF THE CITY OF BURLINGTON	C
523328	1980/06/20	AGREEMENT			THE CORPORATION OF THE CITY OF BURLINGTON	C
540018	1981/05/21	BYLAW				C
20R22199	2022/07/25	PLAN REFERENCE				C
REMARKS: HR1909400.						
HR1943124	2023/01/11	BYLAW		THE CORPORATION OF THE CITY OF BURLINGTON		C

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

* CERTIFIED IN ACCORDANCE WITH THE LAND TITLES ACT * SUBJECT TO RESERVATIONS IN CROWN GRANT *

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
HR1947525	2023/02/03	TRANSFER	$80,000	THE CORPORATION OF THE CITY OF BURLINGTON	MANOR CARE HOMES INC. 2731119 ONTARIO INC. F. K DEALS ON WHEELS INC. 2731115 ONTARIO INC.	C
HR1947526	2023/02/03	TRANSFER EASEMENT	$1	MANOR CARE HOMES INC. 2731119 ONTARIO INC. F. K DEALS ON WHEELS INC. 2731115 ONTARIO INC.	THE CORPORATION OF THE CITY OF BURLINGTON	C

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

CHAIN OF TITLE REPORT

Project #: GTR-22029872-A0 **Searched at:** Milton
Address: Alleyway Plan 88 **LRO #:** 20
Legal Description:

PIN #: 07087-0438(LT)

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
	Patent	14 02 1798	Crown	**Capt. Joseph BRANT**
405	Deed	21 03 1810	Joseph Brant	Ralph MORDEN
274	Deed	30 05 1818	Ralph Morden	Joshua FRECUEAU
155	Deed	10 07 1845	Joshua Frecueau	Joseph FRECUEAU
853	Deed	10 03 1858	Joseph Frecueau	James FILMAN
341	Deed	04 06 1879	James Filman	Joseph SOMMENS
1162	Deed	02 11 1889	Joseph Sommens	The Burlington Manufacturing Company
BH10365	Deed	06 01 1941	The Burlington Manufacturing Co.	The Municipal Corporation of The Town of Burlington
HR1947525	Deed **(Present Owners)**	03 02 2023	The Corporation of The City of Burlington	**Manor Care Homes Inc., 2731119 Ontario Inc., F.K. Deals On Wheels Inc & 2731115 Ontario Inc.**
HR1947526	Easement	03 02 2023	Manor Care Homes Inc et al	The Corporation of The City of Burlington


CHAIN OF TITLE REPORT

Project #: GTR-22029872-A0
Address: Lane Plan 88
Legal Description: as Part 2, 20R22199

Searched at: Milton
LRO #: 20

PIN #: 07087-0440(LT)

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
	Patent	14 02 1798	Crown	**Capt. Joseph BRANT**
405	Deed	21 03 1810	Joseph Brant	Ralph MORDEN
274	Deed	30 05 1818	Ralph Morden	Joshua FRECUEAU
155	Deed	10 07 1845	Joshua Frecueau	Joseph FRECUEAU
853	Deed	10 03 1858	Joseph Frecueau	James FILMAN
341	Deed	04 06 1879	James Filman	Joseph SOMMENS
1162	Deed	02 11 1889	Joseph Sommens	The Burlington Manufacturing Company
88	Plan	02 11 1889	The Burlington Manufacturing Co.	The Municipal Corporation of The Town of Burlington
HR1947525	Deed **(Present Owners)**	03 02 2023	The Corporation of The City of Burlington	**Manor Care Homes Inc., 2731119 Ontario Inc., F.K. Deals On Wheels Inc & 2731115 Ontario Inc.**
HR1947526	Easement	03 02 2023	Manor Care Homes Inc et al	The Corporation of The City of Burlington



ServiceOntario

PRINTED ON 07 MAR, 2023 AT 11:20:06
FOR BERTUCCI

SCALE

0 30 60 90
meters

PROPERTY INDEX MAP

HALTON(No. 20)

LEGEND

FREEHOLD PROPERTY	
LEASEHOLD PROPERTY	
LIMITED INTEREST PROPERTY	
CONDOMINIUM PROPERTY	
RETIRED PIN (MAP UPDATE PENDING)	
PROPERTY NUMBER	*0449*
BLOCK NUMBER	**08050**
GEOGRAPHIC FABRIC	
EASEMENT	

THIS IS NOT A PLAN OF SURVEY

NOTES

REVIEW THE TITLE RECORDS FOR COMPLETE PROPERTY INFORMATION AS THIS MAP MAY NOT REFLECT RECENT REGISTRATIONS

THIS MAP WAS COMPILED FROM PLANS AND DOCUMENTS RECORDED IN THE LAND REGISTRATION SYSTEM AND HAS BEEN PREPARED FOR PROPERTY INDEXING PURPOSES ONLY


FOR DIMENSIONS OF PROPERTIES BOUNDARIES SEE RECORDED PLANS AND DOCUMENTS

ONLY MAJOR EASEMENTS ARE SHOWN

REFERENCE PLANS UNDERLYING MORE RECENT REFERENCE PLANS ARE NOT ILLUSTRATED

Ontario

© Queen's Printer for Ontario, 2023



ServiceOntario

PRINTED ON 07 MAR, 2023 AT 11:18:23
FOR BERTUCCI

SCALE

0 30 60 90 meters

PROPERTY INDEX MAP

HALTON(No. 20)

LEGEND

FREEHOLD PROPERTY	
LEASEHOLD PROPERTY	
LIMITED INTEREST PROPERTY	
CONDOMINIUM PROPERTY	
RETIRED PIN (MAP UPDATE PENDING)	
PROPERTY NUMBER	*0449*
BLOCK NUMBER	08050
GEOGRAPHIC FABRIC	
EASEMENT	

THIS IS NOT A PLAN OF SURVEY

NOTES

REVIEW THE TITLE RECORDS FOR COMPLETE PROPERTY INFORMATION AS THIS MAP MAY NOT REFLECT RECENT REGISTRATIONS

THIS MAP WAS COMPILED FROM PLANS AND DOCUMENTS RECORDED IN THE LAND REGISTRATION SYSTEM AND HAS BEEN PREPARED FOR PROPERTY INDEXING PURPOSES ONLY


FOR DIMENSIONS OF PROPERTIES BOUNDARIES SEE RECORDED PLANS AND DOCUMENTS

ONLY MAJOR EASEMENTS ARE SHOWN

REFERENCE PLANS UNDERLYING MORE RECENT REFERENCE PLANS ARE NOT ILLUSTRATED

Ontario

© Queen's Printer for Ontario, 2023



ServiceOntario

PRINTED ON 07 MAR, 2023 AT 11:23:53
FOR BERTUCCI

SCALE

0 30 60 90
meters

PROPERTY INDEX MAP

HALTON(No. 20)

LEGEND

FREEHOLD PROPERTY	
LEASEHOLD PROPERTY	
LIMITED INTEREST PROPERTY	
CONDOMINIUM PROPERTY	
RETIRED PIN (MAP UPDATE PENDING)	
PROPERTY NUMBER	*0449*
BLOCK NUMBER	**08050**
GEOGRAPHIC FABRIC	
EASEMENT	

THIS IS NOT A PLAN OF SURVEY

NOTES

REVIEW THE TITLE RECORDS FOR COMPLETE PROPERTY INFORMATION AS THIS MAP MAY NOT REFLECT RECENT REGISTRATIONS

THIS MAP WAS COMPILED FROM PLANS AND DOCUMENTS RECORDED IN THE LAND REGISTRATION SYSTEM AND HAS BEEN PREPARED FOR PROPERTY INDEXING PURPOSES ONLY


FOR DIMENSIONS OF PROPERTIES BOUNDARIES SEE RECORDED PLANS AND DOCUMENTS

ONLY MAJOR EASEMENTS ARE SHOWN

REFERENCE PLANS UNDERLYING MORE RECENT REFERENCE PLANS ARE NOT ILLUSTRATED

Ontario

© Queen's Printer for Ontario, 2023



ServiceOntario

PRINTED ON 07 MAR, 2023 AT 11:23:12
FOR BERTUCCI

SCALE

0 30 meters

PROPERTY INDEX MAP

HALTON(No. 20)

LEGEND

FREEHOLD PROPERTY	
LEASEHOLD PROPERTY	
LIMITED INTEREST PROPERTY	
CONDOMINIUM PROPERTY	
RETIRED PIN (MAP UPDATE PENDING)	
PROPERTY NUMBER	*0449*
BLOCK NUMBER	**08050**
GEOGRAPHIC FABRIC	
EASEMENT	

THIS IS NOT A PLAN OF SURVEY

NOTES

REVIEW THE TITLE RECORDS FOR COMPLETE PROPERTY INFORMATION AS THIS MAP MAY NOT REFLECT RECENT REGISTRATIONS

THIS MAP WAS COMPILED FROM PLANS AND DOCUMENTS RECORDED IN THE LAND REGISTRATION SYSTEM AND HAS BEEN PREPARED FOR PROPERTY INDEXING PURPOSES ONLY

FOR DIMENSIONS OF PROPERTIES BOUNDARIES SEE RECORDED PLANS AND DOCUMENTS

ONLY MAJOR EASEMENTS ARE SHOWN

REFERENCE PLANS UNDERLYING MORE RECENT REFERENCE PLANS ARE NOT ILLUSTRATED

Ontario

© Queen's Printer for Ontario, 2023

Appendix E – ERIS Report and Insurance Products

DATABASE REPORT

Project Property:	*Phase one ESA -1376 and 1382 Plain Road East,Burlington, ON* *Phase one ESA -1376 and 1382 Plain Road East,* *Burlington ON L7R 3P8*
Project No:	*GTR-22029872-A0*
Report Type:	*RSC Report (Urban)*
Order No:	*23021000646*
Requested by:	*exp Services Inc.*
Date Completed:	*February 15, 2023*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....6
Executive Summary: Site Report Summary - Surrounding Properties.....7
Executive Summary: Summary By Data Source.....34
Map.....67
Aerial.....68
Topographic Map.....69
Detail Report.....70
Unplottable Summary.....334
Unplottable Report.....336
Appendix: Database Descriptions.....347
Definitions.....356

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Limited Partnership ("ERIS") using various sources of information, including information provided by Federal and Provincial government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Limited Partnership. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:	*Phase one ESA -1376 and 1382 Plain Road East,Burlington, ON* *Phase one ESA -1376 and 1382 Plain Road East, Burlington ON L7R 3P8*
Project No:	*GTR-22029872-A0*

Order Information:

Order No:	*23021000646*
Date Requested:	*February 10, 2023*
Requested by:	*exp Services Inc.*
Report Type:	*RSC Report (Urban)*

Historical/Products:

City Directory Search	*CD - QUOTE Custom City Directory Search*
ERIS Xplorer	*ERIS Xplorer*
Topographic Map	*RSC Maps*

Executive Summary: Report Summary

Database	Name	Searched	Project Property	Boundary to 0.30km	Total
AAGR	Abandoned Aggregate Inventory	Y	0	0	0
AGR	Aggregate Inventory	Y	0	0	0
AMIS	Abandoned Mine Information System	Y	0	0	0
ANDR	Anderson's Waste Disposal Sites	Y	0	0	0
AST	Aboveground Storage Tanks	Y	0	0	0
AUWR	Automobile Wrecking & Supplies	Y	0	0	0
BORE	Borehole	Y	0	18	18
CA	Certificates of Approval	Y	0	25	25
CDRY	Dry Cleaning Facilities	Y	0	0	0
CFOT	Commercial Fuel Oil Tanks	Y	0	0	0
CHEM	Chemical Manufacturers and Distributors	Y	0	1	1
CHM	Chemical Register	Y	0	3	3
CNG	Compressed Natural Gas Stations	Y	0	0	0
COAL	Inventory of Coal Gasification Plants and Coal Tar Sites	Y	0	0	0
CONV	Compliance and Convictions	Y	0	0	0
CPU	Certificates of Property Use	Y	0	0	0
DRL	Drill Hole Database	Y	0	0	0
DTNK	Delisted Fuel Tanks	Y	0	14	14
EASR	Environmental Activity and Sector Registry	Y	0	0	0
EBR	Environmental Registry	Y	0	5	5
ECA	Environmental Compliance Approval	Y	0	18	18
EEM	Environmental Effects Monitoring	Y	0	0	0
EHS	ERIS Historical Searches	Y	2	34	36
EIIS	Environmental Issues Inventory System	Y	0	0	0
EMHE	Emergency Management Historical Event	Y	0	0	0
EPAR	Environmental Penalty Annual Report	Y	0	0	0
EXP	List of Expired Fuels Safety Facilities	Y	0	0	0
FCON	Federal Convictions	Y	0	0	0
FCS	Contaminated Sites on Federal Land	Y	0	0	0
FOFT	Fisheries & Oceans Fuel Tanks	Y	0	0	0
FRST	Federal Identification Registry for Storage Tank Systems (FIRSTS)	Y	0	0	0
FST	Fuel Storage Tank	Y	0	7	7
FSTH	Fuel Storage Tank - Historic	Y	0	1	1
GEN	Ontario Regulation 347 Waste Generators Summary	Y	0	68	68
GHG	Greenhouse Gas Emissions from Large Facilities	Y	0	0	0
HINC	TSSA Historic Incidents	Y	0	0	0

Database	Name	Searched	Project Property	Boundary to 0.30km	Total
IAFT	Indian & Northern Affairs Fuel Tanks	Y	0	0	0
INC	Fuel Oil Spills and Leaks	Y	0	0	0
LIMO	Landfill Inventory Management Ontario	Y	0	0	0
MINE	Canadian Mine Locations	Y	0	0	0
MNR	Mineral Occurrences	Y	0	0	0
NATE	National Analysis of Trends in Emergencies System (NATES)	Y	0	1	1
NCPL	Non-Compliance Reports	Y	0	0	0
NDFT	National Defense & Canadian Forces Fuel Tanks	Y	0	0	0
NDSP	National Defense & Canadian Forces Spills	Y	0	0	0
NDWD	National Defence & Canadian Forces Waste Disposal Sites	Y	0	0	0
NEBI	National Energy Board Pipeline Incidents	Y	0	0	0
NEBP	National Energy Board Wells	Y	0	0	0
NEES	National Environmental Emergencies System (NEES)	Y	0	7	7
NPCB	National PCB Inventory	Y	0	0	0
NPRI	National Pollutant Release Inventory	Y	0	20	20
OGWE	Oil and Gas Wells	Y	0	0	0
OOGW	Ontario Oil and Gas Wells	Y	0	0	0
OPCB	Inventory of PCB Storage Sites	Y	0	0	0
ORD	Orders	Y	0	0	0
PAP	Canadian Pulp and Paper	Y	0	0	0
PCFT	Parks Canada Fuel Storage Tanks	Y	0	0	0
PES	Pesticide Register	Y	0	3	3
PINC	Pipeline Incidents	Y	0	2	2
PRT	Private and Retail Fuel Storage Tanks	Y	0	3	3
PTTW	Permit to Take Water	Y	0	0	0
REC	Ontario Regulation 347 Waste Receivers Summary	Y	0	0	0
RSC	Record of Site Condition	Y	0	5	5
RST	Retail Fuel Storage Tanks	Y	0	8	8
SCT	Scott's Manufacturing Directory	Y	0	12	12
SPL	Ontario Spills	Y	0	42	42
SRDS	Wastewater Discharger Registration Database	Y	0	0	0
TANK	Anderson's Storage Tanks	Y	0	0	0
TCFT	Transport Canada Fuel Storage Tanks	Y	0	0	0
VAR	Variances for Abandonment of Underground Storage Tanks	Y	0	0	0
WDS	Waste Disposal Sites - MOE CA Inventory	Y	0	0	0
WDSH	Waste Disposal Sites - MOE 1991 Historical Approval Inventory	Y	0	0	0
WWIS	Water Well Information System	Y	1	37	38
	Total:		3	334	337

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
1	WWIS		1382 PLAINS RD EAST BURLIGNTON ON ***Well ID:*** 2810666	WNW/0.0	0.00	70
2	EHS		1376-1382 Plains Road East Burlington ON L7R 3P8	W/0.0	0.00	72
2	EHS		1376-1382 Plains Road East Burlington ON L7R 3P8	W/0.0	0.00	73

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
3	WWIS		ON **Well ID:** 7276104	SW/17.5	0.00	73
4	EHS		1368 Plains Road East Burlington ON L7R 3P8	WSW/25.1	0.00	74
5	PRT	BURLINGTON TAXI LTD	1364 PLAINS RD E BURLINGTON ON L7R3P8	SW/36.3	0.00	74
5	RST	GASLINK TRANSPORT INC	MAIN 1364 PLAINS RD E BURLINGTON ON L7R 3P8	SW/36.3	0.00	74
5	GEN	BURLINGTON TAXI LTD.	1364 PLAINS RD. EAST BURLINGTON ON L7R 3P8	SW/36.3	0.00	74
5	GEN	BURLINGTON TAXI LTD. 06-368	1364 PLAINS ROAD EAST BURLINGTON ON L7R 3P8	SW/36.3	0.00	75
5	GEN	BURLINGTON TAXI LTD. 06-368	1364 PLAINS RD. EAST BURLINGTON ON L7R 3P8	SW/36.3	0.00	75
5	GEN	BURLINGTON TAXI LIMITED	1364 PLAINS ROAD EAST BURLINGTON ON L7R 3P8	SW/36.3	0.00	76
5	GEN	BURLING(OUT OF BUSINESS)	1364 PLAINS ROAD EAST BURLINGTON ON L7R 3P8	SW/36.3	0.00	76
5	RST	GAS LINK SERVICES INC	MAIN 1364 PLAINS RD E BURLINGTON ON L7R 3P8	SW/36.3	0.00	76
5	DTNK	BURLINGTON TAXI LTD	1364 PLAINS RD E BURLINGTON ON	SW/36.3	0.00	77
5	DTNK	BURLINGTON TAXI LTD	1364 PLAINS RD E BURLINGTON ON	SW/36.3	0.00	77

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
5	DTNK	BURLINGTON TAXI LTD	1364 PLAINS RD E BURLINGTON ON	SW/36.3	0.00	78
5	RST	GASLINK SERVICES INC	1364 PLAINS RD E BURLINGTON ON L7R3P8	SW/36.3	0.00	78
5	EHS		1364 Plains Rd E Burlington ON L7R3P8	SW/36.3	0.00	79
5	SPL	Union Gas Limited	1364 Plains Road East Burlington ON	SW/36.3	0.00	79
5	RST	GAS LINK	1364 PLAINS RD E BURLINGTON ON L7R3P8	SW/36.3	0.00	79
5	PINC	PIPELINE HIT - 1 ¼"	1364 PLAINS ROAD EAST,, BURLINGTON,ON,L7R 3P8,CA ON	SW/36.3	0.00	79
6	WWIS		ON ***Well ID:*** 2800006	W/47.4	0.00	80
7	CA	R.M. OF HALTON - LEIGHLAND RD.	HELENA ST./PLAINS RD. E. BURLINGTON CITY ON	WSW/67.3	0.00	83
7	CA	R.M. OF HALTON - LEIGHLAND RD.	PLAINS RD.E./HELENA ST/GLENDOR BURLINGTON CITY ON	WSW/67.3	0.00	83
7	SPL	TANK TRUCK	PLAINS RD/HELENA ST. TANK TRUCK (CARGO) NOT PETROLEUM BURLINGTON CITY ON	WSW/67.3	0.00	83
8	BORE		ON	NNW/71.2	0.00	84
9	WWIS		1355 Plains Road East Burlington ON ***Well ID:*** 7384176	W/78.1	0.00	85

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
10	WWIS		1355 Plains Road East Burlington ON ***Well ID:*** 7380256	W/78.7	0.00	88
10	WWIS		1355 Plains Road East Burlington ON ***Well ID:*** 7382222	W/78.7	0.00	91
11	WWIS		1355 Plains Road East Burlington ON ***Well ID:*** 7380255	W/83.0	0.00	93
11	WWIS		1355 Plains Road East Burlington ON ***Well ID:*** 7382221	W/83.0	0.00	96
12	WWIS		1355 Plains Road East Burlington ON ***Well ID:*** 7384177	WSW/84.0	0.00	99
13	EHS		1355 Plains Rd E Burlington ON L7R3P7	W/86.5	0.00	101
14	WWIS		ON ***Well ID:*** 7385804	WSW/87.4	0.00	101
15	WWIS		1335 Plains Road East Burlington ON ***Well ID:*** 7338455	W/87.9	0.00	102
16	GEN	DVLP Property Group	1335- 1355 Plains Road East Burlington ON L7R3P7	W/88.8	0.00	105
17	WWIS		1335 Plains Road East Burlington ON ***Well ID:*** 7338507	W/92.9	0.00	105
18	WWIS		1355 Plains Road East Burlington ON ***Well ID:*** 7380254	W/93.0	0.00	108
18	WWIS		1355 Plains Road East Burlington ON ***Well ID:*** 7382220	W/93.0	0.00	111
19	WWIS		1335 Plains Road East Burlington ON ***Well ID:*** 7338464	WSW/93.7	0.00	113

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
20	WWIS		1355 Plains Road East Burlington ON ***Well ID:*** 7384175	W/93.9	0.00	116
21	WWIS		1355 Plains Road East Burlington ON ***Well ID:*** 7384174	W/95.3	0.00	118
22	WWIS		1335 Plains Road East Burlington ON ***Well ID:*** 7338506	W/97.3	0.00	120
23	WWIS		1390-1400 PLAINS RD. BIRLINGTON ON ***Well ID:*** 2810541	ENE/98.6	0.00	123
24	WWIS		1335 Plains Road East Burlington ON ***Well ID:*** 7338505	W/101.2	0.00	126
25	WWIS		1335 Plains Road East Burlington ON ***Well ID:*** 7338508	W/101.4	0.00	128
26	WWIS		1355 Plains Road East Burlington ON ***Well ID:*** 7380232	W/103.3	0.00	131
27	BORE		ON	NW/105.8	0.00	134
28	WWIS		1335 Plains Road East Burlington ON ***Well ID:*** 7338498	W/106.9	0.00	135
29	RSC	DVLP PROPERTY GROUP INC.	1343 PLAINS ROAD EAST, BURLINGTON, ON L7R 3P7 Burlington ON	WSW/107.1	0.00	138
30	EHS		1401 Plains Road East Burlington ON L7R 3P9	NW/109.5	0.00	139
30	RSC	Mississauga Motors Limited	1401 PLAINS RD E, BURLINGTON, ON, L7R 3P9 BURLINGTON ON L7R 3P9	NW/109.5	0.00	139
30	RSC	Mississauga Motors Limited	1401 PLAINS RD E, BURLINGTON, ON, L7R 3P9 BURLINGTON ON L7R 3P9	NW/109.5	0.00	140

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
30	GEN	Holland Chev Olds	1401 Plains Road East Burlington ON L7R 3P9	NW/109.5	0.00	140
31	BORE		ON	NNW/112.4	0.00	141
32	WWIS		1335 Plains Road East Burlington ON ***Well ID:*** 7338509	WSW/113.7	0.00	142
33	WWIS		ON ***Well ID:*** 7301199	NE/114.8	0.00	145
34	EHS		1400 Plains Rd E Burlington ON L7R3P8	NE/115.0	0.00	146
35	CA	TARBOOSH RESTAURANT	1400 PLANS ROAD EAST BURLINGTON CITY ON	NE/115.1	0.00	146
35	EHS		1390-1400 Plains Rd E Burlington ON L7R 3P8	NE/115.1	0.00	146
35	SCT	CES Graphic Supplies Inc.	1400 Plains Rd E Burlington ON L7R 3P8	NE/115.1	0.00	146
35	GEN	Stone Gate Properties Inc.	1400 Plains Road East Burlington ON L7R 3P8	NE/115.1	0.00	147
35	EHS		1400 Plains Road East Burlington ON L7R 3P8	NE/115.1	0.00	147
35	GEN	Stone Gate Properties Inc.	1400 Plains Road East Burlington ON L7R 3P8	NE/115.1	0.00	147
35	GEN	Stone Gate Properties Inc.	1400 Plains Road East Burlington ON L7R 3P8	NE/115.1	0.00	148
35	GEN	Stone Gate Properties Inc.	1400 Plains Road East Burlington ON	NE/115.1	0.00	148

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
35	GEN	Stone Gate Properties Inc.	1400 Plains Road Burlington ON L7R 3P8	NE/115.1	0.00	148
35	GEN	Stone Gate Properties Inc.	1400 Plains Road East Burlington ON L7R 3P8	NE/115.1	0.00	149
35	WWIS		1400 Plains Road East Burlington ON ***Well ID:*** 7385081	NE/115.1	0.00	149
35	WWIS		1400 Plains Road East Burlington ON ***Well ID:*** 7385082	NE/115.1	0.00	153
36	EHS		1335, 1343, 1349 and 1355 Plains Road East, Burlington Burlington ON L7R 3P7	WSW/117.3	0.00	157
36	EHS		1335, 1343, 1349 and 1355 Plains Road East, Burlington Burlington ON L7R 3P7	WSW/117.3	0.00	157
37	EHS		1335-1349 Plains Rd E, Burlington Burlington ON	WSW/122.4	0.00	157
38	WWIS		1335 Plains Road East Burlington ON ***Well ID:*** 7360647	WSW/124.1	0.00	157
39	WWIS		2201 PLAINS RD E BURLINGTON ON ***Well ID:*** 2810057	SW/124.4	0.00	161
40	WWIS		ON ***Well ID:*** 7164921	NE/129.3	0.00	164
41	WWIS		1335 Plains Road East Burlington ON ***Well ID:*** 7338463	WSW/134.1	-0.37	167
42	SPL	HAMILTON, CORP. OF THE CITY OF	1282 PLAINS RD. MOTOR VEHICLE (OPERATING FLUID) BURLINGTON CITY ON	SW/135.6	0.00	169

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
43	WWIS		1335 Plains Road East Burlington ON ***Well ID:*** 7338511	WSW/137.2	-0.38	170
44	BORE		ON	NE/140.0	0.00	172
45	WWIS		1335 Plains Road East Burlington ON ***Well ID:*** 7338514	WSW/146.0	-1.00	174
46	GEN	DVLP Property Group Inc.	1335 Plains Road East Burlington ON L7R 3P7	WSW/147.6	-0.70	176
47	EHS		Lakeshore West - Beach Layover Burlington ON L7S 1W6	E/152.0	1.11	177
47	EHS		Lakeshore West - Beach Layover Burlington ON L7S 1W6	E/152.0	1.11	177
48	BORE		ON	ENE/155.9	0.00	177
49	WWIS		1325 PLAINS RD. E BURLINGTON ON ***Well ID:*** 7251866	WSW/173.2	0.00	178
50	SPL	UNKNOWN	1417 PLAINS RD E BURLINGTON CITY ON L7R 3P9	N/173.2	0.00	180
51	EHS		PIN# 45393 Burlington ON	E/181.9	0.00	181
52	RSC	HABITAT FOR HUMANITY HALTON	1325 PLAINS ROAD EAST, BURLINGTON, ON L7R 3P7 Burlington ON	WSW/184.4	-0.65	181
52	EHS		1325 Plains Rd E Burlington ON	WSW/184.4	-0.65	182
53	WWIS		ON ***Well ID:*** 7204013	NE/187.2	0.00	182

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
54	BORE		ON	ENE/191.3	0.00	183
55	SCT	WYATT ART POTTERY	1390 LEIGHLAND RD BURLINGTON ON L7R 3S8	NW/193.0	0.00	185
56	GEN	Canadian Tire Corporation, limited	1435 Plains Road East Burlington ON L7R 3P9	NNE/197.2	0.00	185
56	GEN	Canadian Tire Corporation, limited	1435 Plains Road East Burlington ON L7R 3P9	NNE/197.2	0.00	186
56	GEN	Tawse Realco Inc.	1435 Plains Road East Burlington ON L7R 3P9	NNE/197.2	0.00	186
56	GEN	Canadian Tire Corporation, limited	1435 Plains Road East Burlington ON L7R 3P9	NNE/197.2	0.00	187
56	GEN	Tawse Realco Inc.	1435 Plains Road East Burlington ON L7R 3P9	NNE/197.2	0.00	187
56	GEN	Tawse Realco Inc.	1435 Plains Road East Burlington ON L7R 3P9	NNE/197.2	0.00	187
56	GEN	Canadian Tire Corporation, limited	1435 Plains Road East Burlington ON L7R 3P9	NNE/197.2	0.00	188
56	GEN	Canadian Tire Corporation, limited	1435 Plains Road East Burlington ON L7R 3P9	NNE/197.2	0.00	188
56	GEN	Tawse Realco Inc.	1435 Plains Road East Burlington ON L7R 3P9	NNE/197.2	0.00	189
57	BORE		ON	WSW/202.8	-0.68	189
58	PRT	SOUTH WESTERN ONTARIO PROPANE DIV 998131 ONTARIO L	1446 PLAINS RD E BURLINGTON ON L7R3P8	NE/203.1	0.00	191

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
58	PRT	JULIE M DURHAM	1446 PLAINS RD E BURLINGTON ON L7R3P8	NE/203.1	0.00	191
58	RST	DAN'S SUNOCO	1446 PLAINS RD E BURLINGTON ON L7R 3P8	NE/203.1	0.00	191
58	RST	SUNOCO	1446 PLAINS RD E BURLINGTON ON L7R3P8	NE/203.1	0.00	191
58	FSTH	SUNCOR ENERGY PRODUCTS INC**	1446 PLAINS RD E AT BRANT ST BURLINGTON ON L7R 3P8	NE/203.1	0.00	191
58	RST	MAIMAR ASSOCIATES INC	1446 PLAINS RD E BURLINGTON ON L7R 3P8	NE/203.1	0.00	192
58	DTNK	1463963 ONTARIO INC O/A SUNOCO GAS STN #5834	1446 PLAINS RD E AT BRANT ST BURLINGTON ON L7P 3P8	NE/203.1	0.00	192
58	DTNK	SUNCOR ENERGY PRODUCTS INC	1446 PLAINS RD E AT BRANT ST BURLINGTON ON	NE/203.1	0.00	193
58	DTNK	1333916 ONTARIO INC	1446 PLAINS RD E AT BRANT ST BURLINGTON ON	NE/203.1	0.00	193
58	DTNK	1333916 ONTARIO INC	1446 PLAINS RD E AT BRANT ST BURLINGTON ON	NE/203.1	0.00	194
58	DTNK	MAIMAR ASSOCIATES INC	1446 PLAINS RD E AT BRANT ST BURLINGTON ON	NE/203.1	0.00	194
58	DTNK	MAIMAR ASSOCIATES INC	1446 PLAINS RD E AT BRANT ST BURLINGTON ON	NE/203.1	0.00	195
58	DTNK	MAIMAR ASSOCIATES INC	1446 PLAINS RD E AT BRANT ST BURLINGTON ON	NE/203.1	0.00	196
58	DTNK	1333916 ONTARIO INC	1446 PLAINS RD E AT BRANT ST BURLINGTON ON	NE/203.1	0.00	196

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
58	RST	MAIMAR ASSOCIATES INC	1446 PLAINS RD E BURLINGTON ON L7R3P8	NE/203.1	0.00	197
58	DTNK	1333916 ONTARIO INC	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA ON	NE/203.1	0.00	197
58	DTNK	1463963 ONTARIO INC O/A SUNOCO GAS STN #5834	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA ON	NE/203.1	0.00	198
58	DTNK	1463963 ONTARIO INC O/A SUNOCO GAS STN #5834	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA ON	NE/203.1	0.00	198
58	GEN	Suncor Energy Products Inc.	1446 Plains Road Burlington ON L7R 1H9	NE/203.1	0.00	199
58	EHS		1446 Plains Road E Burlington ON L7R 3P8	NE/203.1	0.00	199
58	EHS		1446 Plains Road E Burlington ON L7R 3P8	NE/203.1	0.00	200
59	SPL	SUN CHEMICAL LTD.	LUGGER BOX BURLINGTON CITY ON	SW/207.2	0.00	200
60	WWIS		Glendor Ave Burlington ON ***Well ID:*** 7355019	WSW/211.3	-1.00	200
61	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA ON	NE/213.2	0.00	203
61	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA ON	NE/213.2	0.00	204
61	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA ON	NE/213.2	0.00	204
61	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA ON	NE/213.2	0.00	205

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
61	FST	1463963 ONTARIO INC O/A SUNOCO GAS STN #5834	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA ON	NE/213.2	0.00	205
61	FST	1463963 ONTARIO INC O/A SUNOCO GAS STN #5834	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA ON	NE/213.2	0.00	206
61	FST	1333916 ONTARIO INC	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA ON	NE/213.2	0.00	206
61	GEN	Suncor Energy Products Inc.	1446 Plains Road East Burlington ON L7R 3P8	NE/213.2	0.00	207
62	BORE		ON	S/217.4	-1.99	207
63	WWIS		ON ***Well ID:*** 7265586	E/222.6	0.01	208
64	CA	HERCULES CANADA INC.	942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SE/225.7	0.19	209
64	CA	HERCULES CANADA INC.	942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SE/225.7	0.19	210
64	CA	HERCULES CANADA INC.	942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SE/225.7	0.19	210
64	CA	HERCULES CANADA INC.	942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SE/225.7	0.19	210
64	SPL	HERCULES CANADA INC.	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SE/225.7	0.19	211
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SE/225.7	0.19	211

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SE/225.7	0.19	212
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SE/225.7	0.19	212
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SE/225.7	0.19	213
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SE/225.7	0.19	213
64	SPL	HERCULES CANADA	BOILER STACK BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON	SE/225.7	0.19	214
64	SPL	HERCULES CANADA	HOLDING TANK BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON	SE/225.7	0.19	214
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SE/225.7	0.19	215
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SE/225.7	0.19	215
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SE/225.7	0.19	216
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SE/225.7	0.19	216
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SE/225.7	0.19	217
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SE/225.7	0.19	217

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SE/225.7	0.19	217
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SE/225.7	0.19	218
64	SPL	HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SE/225.7	0.19	218
64	SPL	HERCULES CANADA INC.	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SE/225.7	0.19	219
64	SPL	HERCULES CANADA INC.	BRANT ST/PLAINS RD INTERSECTION. BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON	SE/225.7	0.19	219
64	CHEM	HERCULES CANADA INC.	BURLINGTON ON	SE/225.7	0.19	220
64	CHM	HERCULES CANADA INC	942 BRANT ST BURLINGTON ON L7R 2J7	SE/225.7	0.19	220
64	SCT	Ashland Canada Corp.	942 Brant St Burlington ON L7R 2J7	SE/225.7	0.19	220
64	NPRI	HERCULES CANADA INC.	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	SE/225.7	0.19	221
64	NPRI	HERCULES CANADA INC.	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	SE/225.7	0.19	221
64	NPRI	HERCULES CANADA INC.	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	SE/225.7	0.19	222
64	NPRI	HERCULES CANADA INC.	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	SE/225.7	0.19	223
64	SPL	HERCULES CANADA INC.	942 BRANT ST BURLINGTON PLANT 942 BRANT STREET	SE/225.7	0.19	223

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			BURLINGTON CITY ON L7R 2J7			
64	CA	HERCULES CANADA INC.	BURLINGTON CITY ON	SE/225.7	0.19	224
64	CA		942 Brant Street Burlington ON L7R 2J7	SE/225.7	0.19	224
64	CA		942 Brant Street Burlington ON L7R 2J7	SE/225.7	0.19	224
64	CA		942 Brant Street Burlington ON L7R 2J7	SE/225.7	0.19	225
64	CA		942 Brant Street Burlington ON L7R 2J7	SE/225.7	0.19	225
64	CA		942 Brant Street Burlington ON L7R 2J7	SE/225.7	0.19	225
64	EBR	Hercules Canada Inc.	942 Brant Street Burlington Ontario L7R 3X8 Burlington ON	SE/225.7	0.19	226
64	EBR	Hercules Canada (2002) Inc.	942 Brant Street Burlington Ontario L7R 2J7 Burlington ON	SE/225.7	0.19	226
64	GEN	HERCULES CANADA INC.	942 BRANT ST. P.O. BOX 100 BURLINGTON ON L7R 2J7	SE/225.7	0.19	226
64	GEN	HERCULES CANADA INC.	942 BRANT ST. P.O.BOX 100 BURLINGTON ON L7R 2J7	SE/225.7	0.19	227
64	GEN	HERCULES CANADA INC.	942 BRANT STREET BURLINGTON ON L7R 3X8	SE/225.7	0.19	228
64	GEN	HERCULES CANADA INC. 20-010	942 BRANT ST. P.O.BOX 100 BURLINGTON ON L7R 2J7	SE/225.7	0.19	229

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
64	GEN	HERCULES CANADA	942 BRANT STREET BURLINGTON ON L7R 3X8	SE/225.7	0.19	230
64	GEN	HERCULES CANADA (2002) INC	942 BRANT STREET BURLINGTON ON L7R 3X8	SE/225.7	0.19	231
64	NPRI	HERCULES CANADA (2002) INC	942 BRANT ST. NOT AVAILABLE BURLINGTON ON L7R 3X8	SE/225.7	0.19	232
64	NEES	HERCULESCANADALTD	BURLINGTON ON	SE/225.7	0.19	234
64	NEES	HERCULES CANADA	BURLINGTON CITY ON	SE/225.7	0.19	234
64	NEES	HERCULES CANADA	BURLINGTON CITY ON	SE/225.7	0.19	234
64	NEES	HERCULES CANADA	BURLINGTON CITY ON	SE/225.7	0.19	234
64	NEES	HERCULES CANADA	BURLINGTON CITY ON	SE/225.7	0.19	235
64	NEES	HERCULES CANADA	BURLINGTON CITY ON	SE/225.7	0.19	235
64	NEES	HERCULES CANADA	BURLINGTON CITY ON	SE/225.7	0.19	235
64	NATE	HERCULESCANADALTD	BURLINGTON ON	SE/225.7	0.19	235
64	NPRI	HERCULES CANADA (2002) INC	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	SE/225.7	0.19	236
64	NPRI	HERCULES CANADA	942 BRANT STREET P. O. BOX 100 BURLINGTON ON L7R3X8	SE/225.7	0.19	238

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
64	NPRI	HERCULES CANADA	942 BRANT STREET P. O. BOX 100 BURLINGTON ON L7R3X8	SE/225.7	0.19	241
64	EHS		942 Brant Street Burlington ON L7R 2J7	SE/225.7	0.19	243
64	NPRI	HERCULES CANADA	942 BRANT STREET P. O. BOX 100 BURLINGTON ON L7R3X8	SE/225.7	0.19	243
64	EBR	Hercules Canada (2002) Inc.	942 Brant Street Burlington Ontario L7R 2J7 Burlington ON	SE/225.7	0.19	245
64	EBR	Hercules Canada (2002) Inc.	942 Brant Street Burlington Ontario L7R 3X8 Burlington ON	SE/225.7	0.19	245
64	SPL	Hercules Canada Inc.	942 Brant Street Burlington ON L7R 2J7	SE/225.7	0.19	246
64	SPL	Hercules Canada Inc.	942 Brant Street Burlington ON L7R 2J7	SE/225.7	0.19	246
64	SPL	Hercules Canada Inc.	942 Brant Street Burlington ON L7R 2J7	SE/225.7	0.19	247
64	SPL	Hercules Canada Inc.	942 Brant Street Burlington ON L7R 2J7	SE/225.7	0.19	247
64	SPL		942 Brant Street 942 BRANT STREET Burlington ON L7R 2J7	SE/225.7	0.19	248
64	NPRI	HERCULES CANADA	942 BRANT STREET P. O. BOX 100 BURLINGTON ON L7R3X8	SE/225.7	0.19	248
64	SPL	Hercules Canada Inc.	942 Brant St. Burlington Burlington ON L7R 2J7	SE/225.7	0.19	249

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
64	SPL	Hercules Canada Inc.	942 Brant St Burlington; Burlington ON L7R 2J7	SE/225.7	0.19	250
64	NPRI	HERCULES CANADA	942 BRANT STREET P. O. BOX 100 BURLINGTON ON L7R3X8	SE/225.7	0.19	250
64	CA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	SE/225.7	0.19	252
64	CA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	SE/225.7	0.19	252
64	CA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	SE/225.7	0.19	252
64	CA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	SE/225.7	0.19	253
64	CA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	SE/225.7	0.19	253
64	CA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	SE/225.7	0.19	253
64	CA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	SE/225.7	0.19	254
64	CA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	SE/225.7	0.19	254
64	NPRI	ASHLAND CANADA CORPORATION	942 BRANT STREET P. O. BOX 100 BURLINGTON ON L7R3X8	SE/225.7	0.19	254
64	EBR	Ashland Canada Corp.	942 Brant Street Burlington, Regional Municipality of Halton L7R 2J7 CITY OF BURLINGTON ON	SE/225.7	0.19	255
64	NPRI	ASHLAND CANADA CORP.	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	SE/225.7	0.19	256

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
64	GEN	Ashland Canada Corp.	942 BRANT STREET BURLINGTON ON	SE/225.7	0.19	257
64	ECA	Ashland Canada Corp.	942 Brant St Ashland Burlington ON L7R 2J7	SE/225.7	0.19	258
64	NPRI	ASHLAND CANADA CORP.	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	SE/225.7	0.19	259
64	GEN	Ashland Canada Corp.	942 BRANT STREET BURLINGTON ON	SE/225.7	0.19	260
64	GEN	Ashland Canada Corp.	942 BRANT STREET BURLINGTON ON	SE/225.7	0.19	261
64	GEN	Ashland Canada Corp.	942 BRANT STREET BURLINGTON ON L7R 3X8	SE/225.7	0.19	263
64	NPRI	ASHLAND CANADA CORP.	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	SE/225.7	0.19	264
64	CHM	ASHLAND	942 BRANT ST BURLINGTON ON L7R2J7	SE/225.7	0.19	265
64	EHS		942 Brant Burlington ON L7RSJ7	SE/225.7	0.19	266
64	GEN	Solenis Canada ULC	942 BRANT STREET BURLINGTON ON	SE/225.7	0.19	266
64	NPRI	ASHLAND CANADA CORP.	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	SE/225.7	0.19	267
64	NPRI	ASHLAND CANADA CORP.	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	SE/225.7	0.19	269
64	NPRI	SOLENIS CANADA ULC	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	SE/225.7	0.19	270

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
64	CHM	SOLENIS CANADA	942 BRANT ST BURLINGTON ON L7R2J7	SE/225.7	0.19	271
64	SPL	Solenis Canada ULC	942 Brant St Burlington ON L7R 2J7	SE/225.7	0.19	271
64	ECA	Hercules Canada (2002) Inc.	942 Brant St Burlington ON L7R 3X8	SE/225.7	0.19	271
64	ECA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON L7R 3X8	SE/225.7	0.19	272
64	ECA	Hercules Canada Inc.	942 Brant St Burlington ON L7R 3X8	SE/225.7	0.19	272
64	ECA	Hercules Canada	942 Brant St Burlington ON L7R 3X8	SE/225.7	0.19	272
64	ECA	Hercules Canada (2002) Inc.	942 Brant St Burlington ON L6H 5R7	SE/225.7	0.19	273
64	ECA	Hercules Canada Inc.	942 Brant St Burlington ON L7R 3X8	SE/225.7	0.19	273
64	ECA	Hercules Canada Inc.	942 Brant St Burlington ON L7R 3X8	SE/225.7	0.19	273
64	ECA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON L7R 3X8	SE/225.7	0.19	273
64	ECA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON L7R 3X8	SE/225.7	0.19	274
64	ECA	Hercules Canada (2002) Inc.	942 Brant St Burlington ON L6H 5R7	SE/225.7	0.19	274
64	ECA	Hercules Canada (2002) Inc.	942 Brant Street Burlington ON L7R 3X8	SE/225.7	0.19	274

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
64	ECA	Hercules Canada (2002) Inc.	942 Brant St Burlington ON L7R 3X8	SE/225.7	0.19	275
64	ECA	Hercules Canada Inc.	942 Brant St Burlington ON L7R 3X8	SE/225.7	0.19	275
64	ECA	Ashland Canada Corp.	942 Brant St Ashland Burlington ON L7R 3X8	SE/225.7	0.19	275
64	ECA	Hercules Canada (2002) Inc.	942 Brant St Burlington ON L6H 5R7	SE/225.7	0.19	276
64	GEN	Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 3X8	SE/225.7	0.19	276
64	GEN	Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 3X8	SE/225.7	0.19	278
64	GEN	Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 2J7	SE/225.7	0.19	279
64	GEN	Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 3X8	SE/225.7	0.19	281
64	NPRI	Solenis Canada ULC	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	SE/225.7	0.19	283
64	NPRI	ASHLAND CANADA CORP.	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	SE/225.7	0.19	284
64	GEN	Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 2J7	SE/225.7	0.19	285
64	GEN	Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 2J7	SE/225.7	0.19	287
64	GEN	Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 2J7	SE/225.7	0.19	289

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
65	EHS		930 Brant Street Burlington ON	E/230.4	-0.99	290
66	CA	Premiere Village Ltd.	1393, 1397, 1403, 1413 & 1423, 1417 Leighland Rd Burlington ON	NNW/233.9	0.35	291
67	BORE		ON	ENE/234.3	0.00	291
68	WWIS		1446 PLAINS RD E Burlington ON ***Well ID:*** 7203959	NE/237.8	0.00	293
69	SPL	Burlington Hydro Inc.	932 Brant Street Burlington ON	ENE/243.4	-0.43	296
70	ECA	Premiere Village Ltd.	1393 Leighland Rd & 1397 1403 1413 1423 & 1417 Leighland Road Burlington ON L9T 5A6	NW/245.2	0.00	296
70	ECA	Premiere Village Ltd.	1393 Leighland Rd & 1397 1403 1413 1423 & 1417 Leighland Road Burlington ON L9T 5A6	NW/245.2	0.00	297
71	BORE		ON	W/245.3	-1.00	297
72	BORE		ON	WNW/250.0	-1.00	298
73	EHS		1428-1430 Leighland Road Burlington ON L7R 3S8	N/250.9	1.00	300
74	CA	BRANT VILLAGE CENTRE INC.-PT.PARCEL A&B	PLAINS RD./BRANT ST./LEIGHLAND BURLINGTON CITY ON	NNE/254.7	0.00	300
74	CA	R.M. OF HALTON	PLAINS RD.E./BRANT ST. BURLINGTON CITY ON	NNE/254.7	0.00	300

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
74	CA	R.M. OF HALTON	PLAINS RD.E./BRANT ST. BURLINGTON CITY ON	NNE/254.7	0.00	300
74	SPL	UNKNOWN	RAMBO CREEK, ACROSS COURT HOUSE AT PLAINS RD EAST/BRANT ST. BURLINGTON CITY ON	NNE/254.7	0.00	301
74	SPL	TRANSPORT TRUCK	BRANT STREET AND PLAINS ROAD TRANSPORT TRUCK (CARGO) BURLINGTON CITY ON	NNE/254.7	0.00	301
74	SPL	UNKNOWN	BRANT & PLAINS ROAD, SW CORNER P. LOT, NEAR CAR RENTAL PLACE (NRG PARKING LOT) BURLINGTON CITY ON	NNE/254.7	0.00	302
74	SPL	Dufferin Concrete<UNOFFICIAL>	NE corner of Brant St. and Plains Rd. Burlington ON	NNE/254.7	0.00	302
74	SPL	Rothsay	Brant St and Plains Rd Burlington ON	NNE/254.7	0.00	303
75	EHS		932 Brant Street Burlington ON L7R 2J7	ENE/258.1	-0.93	303
76	BORE		ON	NE/264.8	0.00	303
77	EHS		920 Brant St Burlington ON L7R	E/266.9	-1.12	305
77	EHS		920 Brant St Burlington ON L7R	E/266.9	-1.12	305
78	BORE		ON	ENE/269.1	-0.54	306
79	BORE		ON	W/270.2	-1.00	308
80	EHS		1030 Brant St Burlington ON L7R 0B2	N/273.0	1.00	309

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
80	EHS		1030 Brant St Burlington ON L7R 0B2	N/273.0	1.00	309
80	EHS		1030 Brant St Burlington ON L7R 0B2	N/273.0	1.00	309
81	EHS		942 Brant Street Burlington ON	SE/273.0	-1.62	310
82	GEN	Mountain Equipment Co-Op	1030 Brant Avenue Burlington ON L7R 0B2	N/274.3	1.00	310
82	GEN	Mountain Equipment Co-Op	1030 Brant Avenue Burlington ON L7R 0B2	N/274.3	1.00	310
82	GEN	Mountain Equipment Co-Op	1030 Brant Avenue Burlington ON L7R 0B2	N/274.3	1.00	311
82	GEN	Mountain Equipment Co-Op	1030 Brant Street Burlington ON	N/274.3	1.00	311
82	GEN	Mountain Equipment Co-Op	1030 Brant Street Burlington ON	N/274.3	1.00	311
82	GEN	Mountain Equipment Co-Op	1030 Brant Street Burlington ON L7R 0B2	N/274.3	1.00	312
82	GEN	Mountain Equipment Co-Op	1030 Brant Street Burlington ON L7R 0B2	N/274.3	1.00	312
82	GEN	Mountain Equipment Co-Op	1030 Brant Street Burlington ON L7R 0B2	N/274.3	1.00	312
82	GEN	Mountain Equipment Co-Op	1030 Brant Street Burlington ON L7R 0B2	N/274.3	1.00	313
82	GEN	Mountain Equipment Co-Op	1030 Brant Street Burlington ON L7R 0B2	N/274.3	1.00	313

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
82	PES	MOUNTAIN EQUIPMENT CO-OPERATIVE	1030 BRANT ST BURLINGTON ON L7R 0B2	N/274.3	1.00	313
82	PES	MEC MOUNTAIN EQUIPMENT COMPANY LTD.	1030 Brant ST Burlington ON L7R 0B2	N/274.3	1.00	314
82	EHS		1030 brant street Burlington ON L7R 0B2	N/274.3	1.00	314
82	EHS		1030 brant street Burlington ON L7R 0B2	N/274.3	1.00	314
83	SPL	CANADIAN PACIFIC RAILWAYS	BRANT ST. BY OLD TRAIN STATION AT CP YARD TRAIN BURLINGTON CITY ON	E/274.8	-1.02	315
84	BORE		ON	ENE/276.2	-0.67	315
85	BORE		ON	NE/277.3	0.00	316
86	SPL	PRIVATE OWNER	1312 CORIC AVE. MOTOR VEHICLE (OPERATING FLUID) BURLINGTON CITY ON L7R 3S3	WSW/277.7	-1.00	318
87	PINC		1425 LEIGHLAND ROAD, BURLINGTON ON	NNW/278.4	1.00	318
88	RSC	2064973 Ontario Inc.	930 Brant Street, Burlington, Ontario , L7R 2J7 , Canada, ON L7R 2J7	E/280.3	-0.97	319
88	GEN	New Alliance Ltd	930 Brant Street Burlington ON L7R 2J7	E/280.3	-0.97	319
88	GEN	New Alliance Ltd	930 Brant Street Burlington ON L7R 2J7	E/280.3	-0.97	319

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
88	GEN	New Alliance Ltd	930 Brant Street Burlington ON L7R 2J7	E/280.3	-0.97	320
88	GEN	New Alliance Ltd	930 Brant Street Burlington ON	E/280.3	-0.97	320
88	GEN	New Alliance Ltd	930 Brant Street Burlington ON L7R 2L7	E/280.3	-0.97	321
88	GEN	New Alliance Ltd	930 Brant Street Burlington ON L7R 2L7	E/280.3	-0.97	321
89	EHS		942 Brant Street Burlington ON L7R 2J7	SE/282.3	-2.08	321
89	EHS		942 Brant Street Burlington ON L7R 2J7	SE/282.3	-2.08	322
90	EHS		1425, 1427, 1429, and 1431 Leighland Road Burlington ON	NNW/285.2	1.00	322
91	BORE		ON	NNE/285.7	0.00	322
92	SCT	EDWARDS CANADA	920 BRANT ST UNIT 16 BURLINGTON ON L7R 4J1	E/299.0	-2.05	323
92	PES	PEST PREVENTION SYSTEMS	920 BRANT STREET, UNIT 13 BURLINGTON ON L3T 1L3	E/299.0	-2.05	324
92	SCT	EDWARDS	920 BRANT ST UNIT 16 BURLINGTON ON L7R 4J1	E/299.0	-2.05	324
92	SCT	Carbo-Tech Environmental Group	920 Brant St Unit 13 Burlington ON L7R 4J1	E/299.0	-2.05	325
92	SCT	RACOL CONTROLS	920 BRANT ST UNIT 23 BURLINGTON ON L7R 4J1	E/299.0	-2.05	325

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
92	SCT	Orthogait Inc.	920 Brant St Unit 1 Burlington ON L7R 4J1	E/299.0	-2.05	325
92	SCT	Carbo-Tech Environmental Group Inc.	920 Brant St Unit 13 Burlington ON L7R 4J1	E/299.0	-2.05	325
92	SCT	Kwik Kopy Printing	920 Brant St Unit 18 Burlington ON L7R 4J1	E/299.0	-2.05	326
92	SCT	Edwards - Part of GE Security	920 Brant St Unit 16 Burlington ON L7R 4J1	E/299.0	-2.05	326
92	GEN	1617136 Ontario Ltd.	920 Brant Street, Unit 18-19 Burlington ON L7R 4J1	E/299.0	-2.05	326
92	GEN	Edwards A Part of GE Security Canada	920 Brant Street Unit #16 Burlington ON L7R 4J1	E/299.0	-2.05	327
92	SCT	Kwik Kopy Design & Print	920 Brant St Unit 18 Burlington ON L7R 4J1	E/299.0	-2.05	327
92	GEN	1617136 Ontario Ltd.	920 Brant Street Units 18 - 19 Burlington ON	E/299.0	-2.05	327
92	GEN	2304866 Ontario Ltd.	920 Brant Street Units 18 - 19 Burlington ON L7R 4J1	E/299.0	-2.05	328
92	GEN	2304866 Ontario Ltd.	920 Brant Street Units 18 - 19 Burlington ON L7R 4J1	E/299.0	-2.05	328
92	GEN	2304866 Ontario Ltd.	920 Brant Street Units 18 - 19 Burlington ON	E/299.0	-2.05	329
92	SPL	Burlington Hydro Inc.	920 Grays Lane Burlington ON	E/299.0	-2.05	329
92	GEN	2304866 Ontario Ltd.	920 Brant Street Units 18 - 19 Burlington ON L7R 4J1	E/299.0	-2.05	329

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
92	GEN	2304866 Ontario Ltd.	920 Brant Street Units 18 - 19 Burlington ON L7R 4J1	E/299.0	-2.05	330
92	GEN	2304866 Ontario Ltd.	920 Brant Street Units 18 - 19 Burlington ON L7R 4J1	E/299.0	-2.05	330
92	EHS		920 Brant Street Burlington ON L7R 4J1	E/299.0	-2.05	331
92	EHS		920 Brant Street Burlington ON L7R 4J1	E/299.0	-2.05	331
93	BORE		ON	ENE/299.7	0.00	331

Executive Summary: Summary By Data Source

BORE - Borehole

A search of the BORE database, dated 1875-Jul 2018 has found that there are 18 BORE site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	ON	71.2	8
	ON	105.8	27
	ON	112.4	31
	ON	140.0	44
	ON	155.9	48
	ON	191.3	54
	ON	202.8	57
	ON	217.4	62
	ON	234.3	67

Site	Address	Distance (m)	Map Key
	ON	245.3	71
	ON	250.0	72
	ON	264.8	76
	ON	269.1	78
	ON	270.2	79
	ON	276.2	84
	ON	277.3	85
	ON	285.7	91
	ON	299.7	93

CA - Certificates of Approval

A search of the CA database, dated 1985-Oct 30, 2011* has found that there are 25 CA site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
R.M. OF HALTON - LEIGHLAND RD.	HELENA ST./PLAINS RD. E. BURLINGTON CITY ON	67.3	7

Site	Address	Distance (m)	Map Key
R.M. OF HALTON - LEIGHLAND RD.	PLAINS RD.E./HELENA ST/GLENDOR BURLINGTON CITY ON	67.3	7
TARBOOSH RESTAURANT	1400 PLANS ROAD EAST BURLINGTON CITY ON	115.1	35
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	225.7	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	225.7	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	225.7	64
HERCULES CANADA INC.	942 BRANT STREET BURLINGTON CITY ON L7R 2J7	225.7	64
HERCULES CANADA INC.	942 BRANT STREET BURLINGTON CITY ON L7R 2J7	225.7	64
HERCULES CANADA INC.	942 BRANT STREET BURLINGTON CITY ON L7R 2J7	225.7	64
HERCULES CANADA INC.	942 BRANT STREET BURLINGTON CITY ON L7R 2J7	225.7	64
HERCULES CANADA INC.	BURLINGTON CITY ON	225.7	64
	942 Brant Street Burlington ON L7R 2J7	225.7	64

Site	Address	Distance (m)	Map Key
	942 Brant Street Burlington ON L7R 2J7	225.7	64
	942 Brant Street Burlington ON L7R 2J7	225.7	64
	942 Brant Street Burlington ON L7R 2J7	225.7	64
	942 Brant Street Burlington ON L7R 2J7	225.7	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	225.7	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	225.7	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	225.7	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	225.7	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON	225.7	64
Premiere Village Ltd.	1393, 1397, 1403, 1413 & 1423, 1417 Leighland Rd Burlington ON	233.9	66
BRANT VILLAGE CENTRE INC.-PT. PARCEL A&B	PLAINS RD./BRANT ST./LEIGHLAND BURLINGTON CITY ON	254.7	74
R.M. OF HALTON	PLAINS RD.E./BRANT ST. BURLINGTON CITY ON	254.7	74

Site	Address	Distance (m)	Map Key
R.M. OF HALTON	PLAINS RD.E./BRANT ST. BURLINGTON CITY ON	254.7	74

CHEM - Chemical Manufacturers and Distributors

A search of the CHEM database, dated 1999-Jan 31, 2020 has found that there are 1 CHEM site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
HERCULES CANADA INC.	BURLINGTON ON	225.7	64

CHM - Chemical Register

A search of the CHM database, dated 1999-May 31, 2022 has found that there are 3 CHM site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
ASHLAND	942 BRANT ST BURLINGTON ON L7R2J7	225.7	64
HERCULES CANADA INC	942 BRANT ST BURLINGTON ON L7R 2J7	225.7	64
SOLENIS CANADA	942 BRANT ST BURLINGTON ON L7R2J7	225.7	64

DTNK - Delisted Fuel Tanks

A search of the DTNK database, dated Feb 28, 2022 has found that there are 14 DTNK site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
BURLINGTON TAXI LTD	1364 PLAINS RD E BURLINGTON ON	36.3	5

Site	Address	Distance (m)	Map Key
BURLINGTON TAXI LTD	1364 PLAINS RD E BURLINGTON ON	36.3	5
BURLINGTON TAXI LTD	1364 PLAINS RD E BURLINGTON ON	36.3	5
1463963 ONTARIO INC O/A SUNOCO GAS STN #5834	1446 PLAINS RD E AT BRANT ST BURLINGTON ON L7P 3P8	203.1	58
SUNCOR ENERGY PRODUCTS INC	1446 PLAINS RD E AT BRANT ST BURLINGTON ON	203.1	58
1333916 ONTARIO INC	1446 PLAINS RD E AT BRANT ST BURLINGTON ON	203.1	58
1463963 ONTARIO INC O/A SUNOCO GAS STN #5834	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA ON	203.1	58
MAIMAR ASSOCIATES INC	1446 PLAINS RD E AT BRANT ST BURLINGTON ON	203.1	58
MAIMAR ASSOCIATES INC	1446 PLAINS RD E AT BRANT ST BURLINGTON ON	203.1	58
MAIMAR ASSOCIATES INC	1446 PLAINS RD E AT BRANT ST BURLINGTON ON	203.1	58
1333916 ONTARIO INC	1446 PLAINS RD E AT BRANT ST BURLINGTON ON	203.1	58
1333916 ONTARIO INC	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA ON	203.1	58

Site	Address	Distance (m)	Map Key
1463963 ONTARIO INC O/A SUNOCO GAS STN #5834	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA ON	203.1	58
1333916 ONTARIO INC	1446 PLAINS RD E AT BRANT ST BURLINGTON ON	203.1	58

EBR - Environmental Registry

A search of the EBR database, dated 1994 - Dec 31, 2022 has found that there are 5 EBR site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Ashland Canada Corp.	942 Brant Street Burlington, Regional Municipality of Halton L7R 2J7 CITY OF BURLINGTON ON	225.7	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington Ontario L7R 3X8 Burlington ON	225.7	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington Ontario L7R 2J7 Burlington ON	225.7	64
Hercules Canada Inc.	942 Brant Street Burlington Ontario L7R 3X8 Burlington ON	225.7	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington Ontario L7R 2J7 Burlington ON	225.7	64

ECA - Environmental Compliance Approval

A search of the ECA database, dated Oct 2011- Dec 31, 2022 has found that there are 18 ECA site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON L7R 3X8	225.7	64

Site	Address	Distance (m)	Map Key
Hercules Canada (2002) Inc.	942 Brant St Burlington ON L6H 5R7	225.7	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON L7R 3X8	225.7	64
Hercules Canada Inc.	942 Brant St Burlington ON L7R 3X8	225.7	64
Hercules Canada Inc.	942 Brant St Burlington ON L7R 3X8	225.7	64
Hercules Canada (2002) Inc.	942 Brant St Burlington ON L6H 5R7	225.7	64
Hercules Canada	942 Brant St Burlington ON L7R 3X8	225.7	64
Hercules Canada Inc.	942 Brant St Burlington ON L7R 3X8	225.7	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON L7R 3X8	225.7	64
Hercules Canada (2002) Inc.	942 Brant St Burlington ON L7R 3X8	225.7	64
Hercules Canada (2002) Inc.	942 Brant St Burlington ON L6H 5R7	225.7	64
Ashland Canada Corp.	942 Brant St Ashland Burlington ON L7R 2J7	225.7	64
Hercules Canada (2002) Inc.	942 Brant St Burlington ON L7R 3X8	225.7	64

Site	Address	Distance (m)	Map Key
Hercules Canada Inc.	942 Brant St Burlington ON L7R 3X8	225.7	64
Ashland Canada Corp.	942 Brant St Ashland Burlington ON L7R 3X8	225.7	64
Hercules Canada (2002) Inc.	942 Brant Street Burlington ON L7R 3X8	225.7	64
Premiere Village Ltd.	1393 Leighland Rd & 1397 1403 1413 1423 & 1417 Leighland Road Burlington ON L9T 5A6	245.2	70
Premiere Village Ltd.	1393 Leighland Rd & 1397 1403 1413 1423 & 1417 Leighland Road Burlington ON L9T 5A6	245.2	70

EHS - ERIS Historical Searches

A search of the EHS database, dated 1999-Jul 31, 2022 has found that there are 36 EHS site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	1376-1382 Plains Road East Burlington ON L7R 3P8	0.0	2
	1376-1382 Plains Road East Burlington ON L7R 3P8	0.0	2
	1368 Plains Road East Burlington ON L7R 3P8	25.1	4
	1364 Plains Rd E Burlington ON L7R3P8	36.3	5

Site	Address	Distance (m)	Map Key
	1355 Plains Rd E Burlington ON L7R3P7	86.5	13
	1401 Plains Road East Burlington ON L7R 3P9	109.5	30
	1400 Plains Rd E Burlington ON L7R3P8	115.0	34
	1400 Plains Road East Burlington ON L7R 3P8	115.1	35
	1390-1400 Plains Rd E Burlington ON L7R 3P8	115.1	35
	1335, 1343, 1349 and 1355 Plains Road East, Burlington Burlington ON L7R 3P7	117.3	36
	1335, 1343, 1349 and 1355 Plains Road East, Burlington Burlington ON L7R 3P7	117.3	36
	1335-1349 Plains Rd E, Burlington Burlington ON	122.4	37
	Lakeshore West - Beach Layover Burlington ON L7S 1W6	152.0	47
	Lakeshore West - Beach Layover Burlington ON L7S 1W6	152.0	47
	PIN# 45393 Burlington ON	181.9	51
	1325 Plains Rd E Burlington ON	184.4	52

Site	Address	Distance (m)	Map Key
	1446 Plains Road E Burlington ON L7R 3P8	203.1	58
	1446 Plains Road E Burlington ON L7R 3P8	203.1	58
	942 Brant Street Burlington ON L7R 2J7	225.7	64
	942 Brant Burlington ON L7RSJ7	225.7	64
	930 Brant Street Burlington ON	230.4	65
	1428-1430 Leighland Road Burlington ON L7R 3S8	250.9	73
	932 Brant Street Burlington ON L7R 2J7	258.1	75
	920 Brant St Burlington ON L7R	266.9	77
	920 Brant St Burlington ON L7R	266.9	77
	1030 Brant St Burlington ON L7R 0B2	273.0	80
	1030 Brant St Burlington ON L7R 0B2	273.0	80

Site	Address	Distance (m)	Map Key
	1030 Brant St Burlington ON L7R 0B2	273.0	80
	942 Brant Street Burlington ON	273.0	81
	1030 brant street Burlington ON L7R 0B2	274.3	82
	1030 brant street Burlington ON L7R 0B2	274.3	82
	942 Brant Street Burlington ON L7R 2J7	282.3	89
	942 Brant Street Burlington ON L7R 2J7	282.3	89
	1425, 1427, 1429, and 1431 Leighland Road Burlington ON	285.2	90
	920 Brant Street Burlington ON L7R 4J1	299.0	92
	920 Brant Street Burlington ON L7R 4J1	299.0	92

FST - Fuel Storage Tank

A search of the FST database, dated Feb 28, 2022 has found that there are 7 FST site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
SUNCOR ENERGY PRODUCTS PARTNERSHIP	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA ON	213.2	61

Site	Address	Distance (m)	Map Key
SUNCOR ENERGY PRODUCTS PARTNERSHIP	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA ON	213.2	61
SUNCOR ENERGY PRODUCTS PARTNERSHIP	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA ON	213.2	61
1333916 ONTARIO INC	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA ON	213.2	61
SUNCOR ENERGY PRODUCTS PARTNERSHIP	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA ON	213.2	61
1463963 ONTARIO INC O/A SUNOCO GAS STN #5834	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA ON	213.2	61
1463963 ONTARIO INC O/A SUNOCO GAS STN #5834	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA ON	213.2	61

FSTH - Fuel Storage Tank - Historic

A search of the FSTH database, dated Pre-Jan 2010* has found that there are 1 FSTH site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
SUNCOR ENERGY PRODUCTS INC**	1446 PLAINS RD E AT BRANT ST BURLINGTON ON L7R 3P8	203.1	58

GEN - Ontario Regulation 347 Waste Generators Summary

A search of the GEN database, dated 1986-Oct 31, 2022 has found that there are 68 GEN site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
BURLINGTON TAXI LTD.	1364 PLAINS RD. EAST BURLINGTON ON L7R 3P8	36.3	5

Site	Address	Distance (m)	Map Key
BURLINGTON TAXI LTD. 06-368	1364 PLAINS ROAD EAST BURLINGTON ON L7R 3P8	36.3	5
BURLINGTON TAXI LTD. 06-368	1364 PLAINS RD. EAST BURLINGTON ON L7R 3P8	36.3	5
BURLINGTON TAXI LIMITED	1364 PLAINS ROAD EAST BURLINGTON ON L7R 3P8	36.3	5
BURLING(OUT OF BUSINESS)	1364 PLAINS ROAD EAST BURLINGTON ON L7R 3P8	36.3	5
DVLP Property Group	1335- 1355 Plains Road East Burlington ON L7R3P7	88.8	16
Holland Chev Olds	1401 Plains Road East Burlington ON L7R 3P9	109.5	30
Stone Gate Properties Inc.	1400 Plains Road East Burlington ON L7R 3P8	115.1	35
Stone Gate Properties Inc.	1400 Plains Road East Burlington ON L7R 3P8	115.1	35
Stone Gate Properties Inc.	1400 Plains Road East Burlington ON L7R 3P8	115.1	35
Stone Gate Properties Inc.	1400 Plains Road East Burlington ON	115.1	35
Stone Gate Properties Inc.	1400 Plains Road Burlington ON L7R 3P8	115.1	35

Site	Address	Distance (m)	Map Key
Stone Gate Properties Inc.	1400 Plains Road East Burlington ON L7R 3P8	115.1	35
DVLP Property Group Inc.	1335 Plains Road East Burlington ON L7R 3P7	147.6	46
Canadian Tire Corporation, limited	1435 Plains Road East Burlington ON L7R 3P9	197.2	56
Canadian Tire Corporation, limited	1435 Plains Road East Burlington ON L7R 3P9	197.2	56
Tawse Realco Inc.	1435 Plains Road East Burlington ON L7R 3P9	197.2	56
Canadian Tire Corporation, limited	1435 Plains Road East Burlington ON L7R 3P9	197.2	56
Tawse Realco Inc.	1435 Plains Road East Burlington ON L7R 3P9	197.2	56
Tawse Realco Inc.	1435 Plains Road East Burlington ON L7R 3P9	197.2	56
Canadian Tire Corporation, limited	1435 Plains Road East Burlington ON L7R 3P9	197.2	56
Canadian Tire Corporation, limited	1435 Plains Road East Burlington ON L7R 3P9	197.2	56
Tawse Realco Inc.	1435 Plains Road East Burlington ON L7R 3P9	197.2	56
Suncor Energy Products Inc.	1446 Plains Road Burlington ON L7R 1H9	203.1	58

Site	Address	Distance (m)	Map Key
Suncor Energy Products Inc.	1446 Plains Road East Burlington ON L7R 3P8	213.2	61
Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 3X8	225.7	64
Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 3X8	225.7	64
Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 2J7	225.7	64
Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 3X8	225.7	64
Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 2J7	225.7	64
Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 2J7	225.7	64
Solenis Canada ULC	942 BRANT STREET BURLINGTON ON L7R 2J7	225.7	64
HERCULES CANADA INC.	942 BRANT ST. P.O. BOX 100 BURLINGTON ON L7R 2J7	225.7	64
HERCULES CANADA INC.	942 BRANT ST. P.O.BOX 100 BURLINGTON ON L7R 2J7	225.7	64
HERCULES CANADA INC.	942 BRANT STREET BURLINGTON ON L7R 3X8	225.7	64

Site	Address	Distance (m)	Map Key
HERCULES CANADA INC. 20-010	942 BRANT ST. P.O.BOX 100 BURLINGTON ON L7R 2J7	225.7	64
HERCULES CANADA	942 BRANT STREET BURLINGTON ON L7R 3X8	225.7	64
HERCULES CANADA (2002) INC	942 BRANT STREET BURLINGTON ON L7R 3X8	225.7	64
Ashland Canada Corp.	942 BRANT STREET BURLINGTON ON	225.7	64
Ashland Canada Corp.	942 BRANT STREET BURLINGTON ON	225.7	64
Ashland Canada Corp.	942 BRANT STREET BURLINGTON ON	225.7	64
Ashland Canada Corp.	942 BRANT STREET BURLINGTON ON L7R 3X8	225.7	64
Solenis Canada ULC	942 BRANT STREET BURLINGTON ON	225.7	64
Mountain Equipment Co-Op	1030 Brant Avenue Burlington ON L7R 0B2	274.3	82
Mountain Equipment Co-Op	1030 Brant Avenue Burlington ON L7R 0B2	274.3	82
Mountain Equipment Co-Op	1030 Brant Avenue Burlington ON L7R 0B2	274.3	82
Mountain Equipment Co-Op	1030 Brant Street Burlington ON	274.3	82

Site	Address	Distance (m)	Map Key
Mountain Equipment Co-Op	1030 Brant Street Burlington ON	274.3	82
Mountain Equipment Co-Op	1030 Brant Street Burlington ON L7R 0B2	274.3	82
Mountain Equipment Co-Op	1030 Brant Street Burlington ON L7R 0B2	274.3	82
Mountain Equipment Co-Op	1030 Brant Street Burlington ON L7R 0B2	274.3	82
Mountain Equipment Co-Op	1030 Brant Street Burlington ON L7R 0B2	274.3	82
Mountain Equipment Co-Op	1030 Brant Street Burlington ON L7R 0B2	274.3	82
New Alliance Ltd	930 Brant Street Burlington ON L7R 2L7	280.3	88
New Alliance Ltd	930 Brant Street Burlington ON L7R 2J7	280.3	88
New Alliance Ltd	930 Brant Street Burlington ON L7R 2J7	280.3	88
New Alliance Ltd	930 Brant Street Burlington ON L7R 2J7	280.3	88
New Alliance Ltd	930 Brant Street Burlington ON	280.3	88

Site	Address	Distance (m)	Map Key
New Alliance Ltd	930 Brant Street Burlington ON L7R 2L7	280.3	88
1617136 Ontario Ltd.	920 Brant Street, Unit 18-19 Burlington ON L7R 4J1	299.0	92
Edwards A Part of GE Security Canada	920 Brant Street Unit #16 Burlington ON L7R 4J1	299.0	92
1617136 Ontario Ltd.	920 Brant Street Units 18 - 19 Burlington ON	299.0	92
2304866 Ontario Ltd.	920 Brant Street Units 18 - 19 Burlington ON L7R 4J1	299.0	92
2304866 Ontario Ltd.	920 Brant Street Units 18 - 19 Burlington ON L7R 4J1	299.0	92
2304866 Ontario Ltd.	920 Brant Street Units 18 - 19 Burlington ON	299.0	92
2304866 Ontario Ltd.	920 Brant Street Units 18 - 19 Burlington ON L7R 4J1	299.0	92
2304866 Ontario Ltd.	920 Brant Street Units 18 - 19 Burlington ON L7R 4J1	299.0	92
2304866 Ontario Ltd.	920 Brant Street Units 18 - 19 Burlington ON L7R 4J1	299.0	92

NATE - National Analysis of Trends in Emergencies System (NATES)

A search of the NATE database, dated 1974-1994* has found that there are 1 NATE site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
HERCULESCANADALTD	BURLINGTON ON	225.7	64

NEES - National Environmental Emergencies System (NEES)

A search of the NEES database, dated 1974-2003* has found that there are 7 NEES site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
HERCULES CANADA	BURLINGTON CITY ON	225.7	64
HERCULES CANADA	BURLINGTON CITY ON	225.7	64
HERCULES CANADA	BURLINGTON CITY ON	225.7	64
HERCULESCANADALTD	BURLINGTON ON	225.7	64
HERCULES CANADA	BURLINGTON CITY ON	225.7	64
HERCULES CANADA	BURLINGTON CITY ON	225.7	64
HERCULES CANADA	BURLINGTON CITY ON	225.7	64

NPRI - National Pollutant Release Inventory

A search of the NPRI database, dated 1993-May 2017 has found that there are 20 NPRI site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
HERCULES CANADA	942 BRANT STREET P. O. BOX 100 BURLINGTON ON L7R3X8	225.7	64
HERCULES CANADA	942 BRANT STREET P. O. BOX 100 BURLINGTON ON L7R3X8	225.7	64
HERCULES CANADA	942 BRANT STREET P. O. BOX 100 BURLINGTON ON L7R3X8	225.7	64
HERCULES CANADA	942 BRANT STREET P. O. BOX 100 BURLINGTON ON L7R3X8	225.7	64
HERCULES CANADA	942 BRANT STREET P. O. BOX 100 BURLINGTON ON L7R3X8	225.7	64
ASHLAND CANADA CORPORATION	942 BRANT STREET P. O. BOX 100 BURLINGTON ON L7R3X8	225.7	64
ASHLAND CANADA CORP.	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	225.7	64
ASHLAND CANADA CORP.	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	225.7	64
ASHLAND CANADA CORP.	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	225.7	64
ASHLAND CANADA CORP.	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	225.7	64
ASHLAND CANADA CORP.	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	225.7	64
HERCULES CANADA (2002) INC	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	225.7	64

Site	Address	Distance (m)	Map Key
HERCULES CANADA (2002) INC	942 BRANT ST. NOT AVAILABLE BURLINGTON ON L7R 3X8	225.7	64
HERCULES CANADA INC.	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	225.7	64
HERCULES CANADA INC.	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	225.7	64
HERCULES CANADA INC.	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	225.7	64
HERCULES CANADA INC.	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	225.7	64
SOLENIS CANADA ULC	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	225.7	64
Solenis Canada ULC	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	225.7	64
ASHLAND CANADA CORP.	942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	225.7	64

PES - Pesticide Register

A search of the PES database, dated Oct 2011- Dec 31, 2022 has found that there are 3 PES site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
MEC MOUNTAIN EQUIPMENT COMPANY LTD.	1030 Brant ST Burlington ON L7R 0B2	274.3	82

Site	Address	Distance (m)	Map Key
MOUNTAIN EQUIPMENT CO-OPERATIVE	1030 BRANT ST BURLINGTON ON L7R 0B2	274.3	82
PEST PREVENTION SYSTEMS	920 BRANT STREET, UNIT 13 BURLINGTON ON L3T 1L3	299.0	92

PINC - Pipeline Incidents

A search of the PINC database, dated Feb 28, 2021 has found that there are 2 PINC site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
PIPELINE HIT - 1 ¼"	1364 PLAINS ROAD EAST,,BURLINGTON, ON,L7R 3P8,CA ON	36.3	5
	1425 LEIGHLAND ROAD, BURLINGTON ON	278.4	87

PRT - Private and Retail Fuel Storage Tanks

A search of the PRT database, dated 1989-1996* has found that there are 3 PRT site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
BURLINGTON TAXI LTD	1364 PLAINS RD E BURLINGTON ON L7R3P8	36.3	5
JULIE M DURHAM	1446 PLAINS RD E BURLINGTON ON L7R3P8	203.1	58
SOUTH WESTERN ONTARIO PROPANE DIV 998131 ONTARIO L	1446 PLAINS RD E BURLINGTON ON L7R3P8	203.1	58

RSC - Record of Site Condition

A search of the RSC database, dated 1997-Sept 2001, Oct 2004-Dec 2022 has found that there are 5 RSC site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
DVLP PROPERTY GROUP INC.	1343 PLAINS ROAD EAST, BURLINGTON, ON L7R 3P7 Burlington ON	107.1	29
Mississauga Motors Limited	1401 PLAINS RD E, BURLINGTON, ON, L7R 3P9 BURLINGTON ON L7R 3P9	109.5	30
Mississauga Motors Limited	1401 PLAINS RD E, BURLINGTON, ON, L7R 3P9 BURLINGTON ON L7R 3P9	109.5	30
HABITAT FOR HUMANITY HALTON	1325 PLAINS ROAD EAST, BURLINGTON, ON L7R 3P7 Burlington ON	184.4	52
2064973 Ontario Inc.	930 Brant Street, Burlington, Ontario , L7R 2J7 , Canada, ON L7R 2J7	280.3	88

RST - Retail Fuel Storage Tanks

A search of the RST database, dated 1999-May 31, 2022 has found that there are 8 RST site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
GAS LINK	1364 PLAINS RD E BURLINGTON ON L7R3P8	36.3	5
GASLINK SERVICES INC	1364 PLAINS RD E BURLINGTON ON L7R3P8	36.3	5
GAS LINK SERVICES INC	MAIN 1364 PLAINS RD E BURLINGTON ON L7R 3P8	36.3	5
GASLINK TRANSPORT INC	MAIN 1364 PLAINS RD E BURLINGTON ON L7R 3P8	36.3	5

Site	Address	Distance (m)	Map Key
SUNOCO	1446 PLAINS RD E BURLINGTON ON L7R3P8	203.1	58
MAIMAR ASSOCIATES INC	1446 PLAINS RD E BURLINGTON ON L7R 3P8	203.1	58
MAIMAR ASSOCIATES INC	1446 PLAINS RD E BURLINGTON ON L7R3P8	203.1	58
DAN'S SUNOCO	1446 PLAINS RD E BURLINGTON ON L7R 3P8	203.1	58

SCT - Scott's Manufacturing Directory

A search of the SCT database, dated 1992-Mar 2011* has found that there are 12 SCT site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
CES Graphic Supplies Inc.	1400 Plains Rd E Burlington ON L7R 3P8	115.1	35
WYATT ART POTTERY	1390 LEIGHLAND RD BURLINGTON ON L7R 3S8	193.0	55
Ashland Canada Corp.	942 Brant St Burlington ON L7R 2J7	225.7	64
Carbo-Tech Environmental Group	920 Brant St Unit 13 Burlington ON L7R 4J1	299.0	92
EDWARDS	920 BRANT ST UNIT 16 BURLINGTON ON L7R 4J1	299.0	92
EDWARDS CANADA	920 BRANT ST UNIT 16 BURLINGTON ON L7R 4J1	299.0	92

Site	Address	Distance (m)	Map Key
Kwik Kopy Design & Print	920 Brant St Unit 18 Burlington ON L7R 4J1	299.0	92
RACOL CONTROLS	920 BRANT ST UNIT 23 BURLINGTON ON L7R 4J1	299.0	92
Kwik Kopy Printing	920 Brant St Unit 18 Burlington ON L7R 4J1	299.0	92
Carbo-Tech Environmental Group Inc.	920 Brant St Unit 13 Burlington ON L7R 4J1	299.0	92
Orthogait Inc.	920 Brant St Unit 1 Burlington ON L7R 4J1	299.0	92
Edwards - Part of GE Security	920 Brant St Unit 16 Burlington ON L7R 4J1	299.0	92

SPL - Ontario Spills

A search of the SPL database, dated 1988-Sep 2020; Dec 2020-Mar 2021 has found that there are 42 SPL site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Union Gas Limited	1364 Plains Road East Burlington ON	36.3	5
TANK TRUCK	PLAINS RD/HELENA ST. TANK TRUCK (CARGO) NOT PETROLEUM BURLINGTON CITY ON	67.3	7
HAMILTON, CORP. OF THE CITY OF	1282 PLAINS RD. MOTOR VEHICLE (OPERATING FLUID) BURLINGTON CITY ON	135.6	42

Site	Address	Distance (m)	Map Key
UNKNOWN	1417 PLAINS RD E BURLINGTON CITY ON L7R 3P9	173.2	50
SUN CHEMICAL LTD.	LUGGER BOX BURLINGTON CITY ON	207.2	59
HERCULES CANADA INC.	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	225.7	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	225.7	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	225.7	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	225.7	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	225.7	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	225.7	64
HERCULES CANADA	BOILER STACK BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON	225.7	64
HERCULES CANADA	HOLDING TANK BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON	225.7	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	225.7	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	225.7	64

Site	Address	Distance (m)	Map Key
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	225.7	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	225.7	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	225.7	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	225.7	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	225.7	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	225.7	64
HERCULES CANADA	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	225.7	64
HERCULES CANADA INC.	BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	225.7	64
HERCULES CANADA INC.	BRANT ST/PLAINS RD INTERSECTION. BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON	225.7	64
HERCULES CANADA INC.	942 BRANT ST BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	225.7	64
Hercules Canada Inc.	942 Brant Street Burlington ON L7R 2J7	225.7	64

Site	Address	Distance (m)	Map Key
Hercules Canada Inc.	942 Brant Street Burlington ON L7R 2J7	225.7	64
Hercules Canada Inc.	942 Brant Street Burlington ON L7R 2J7	225.7	64
Hercules Canada Inc.	942 Brant Street Burlington ON L7R 2J7	225.7	64
	942 Brant Street 942 BRANT STREET Burlington ON L7R 2J7	225.7	64
Hercules Canada Inc.	942 Brant St. Burlington Burlington ON L7R 2J7	225.7	64
Hercules Canada Inc.	942 Brant St Burlington; Burlington ON L7R 2J7	225.7	64
Solenis Canada ULC	942 Brant St Burlington ON L7R 2J7	225.7	64
Burlington Hydro Inc.	932 Brant Street Burlington ON	243.4	69
Rothsay	Brant St and Plains Rd Burlington ON	254.7	74
Dufferin Concrete<UNOFFICIAL>	NE corner of Brant St. and Plains Rd. Burlington ON	254.7	74
UNKNOWN	BRANT & PLAINS ROAD, SW CORNER P. LOT, NEAR CAR RENTAL PLACE (NRG PARKING LOT) BURLINGTON CITY ON	254.7	74
TRANSPORT TRUCK	BRANT STREET AND PLAINS ROAD TRANSPORT TRUCK (CARGO) BURLINGTON CITY ON	254.7	74

Site	Address	Distance (m)	Map Key
UNKNOWN	RAMBO CREEK, ACROSS COURT HOUSE AT PLAINS RD EAST/BRANT ST. BURLINGTON CITY ON	254.7	74
CANADIAN PACIFIC RAILWAYS	BRANT ST. BY OLD TRAIN STATION AT CP YARD TRAIN BURLINGTON CITY ON	274.8	83
PRIVATE OWNER	1312 CORIC AVE. MOTOR VEHICLE (OPERATING FLUID) BURLINGTON CITY ON L7R 3S3	277.7	86
Burlington Hydro Inc.	920 Grays Lane Burlington ON	299.0	92

WWIS - Water Well Information System


A search of the WWIS database, dated Jun 30 2022 has found that there are 38 WWIS site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	1382 PLAINS RD EAST BURLIGNTON ON ***Well ID:*** 2810666	0.0	1
	ON ***Well ID:*** 7276104	17.5	3
	ON ***Well ID:*** 2800006	47.4	6
	1355 Plains Road East Burlington ON ***Well ID:*** 7384176	78.1	9
	1355 Plains Road East Burlington ON ***Well ID:*** 7380256	78.7	10

Site	Address	Distance (m)	Map Key
	1355 Plains Road East Burlington ON ***Well ID:*** 7382222	78.7	10
	1355 Plains Road East Burlington ON ***Well ID:*** 7380255	83.0	11
	1355 Plains Road East Burlington ON ***Well ID:*** 7382221	83.0	11
	1355 Plains Road East Burlington ON ***Well ID:*** 7384177	84.0	12
	ON ***Well ID:*** 7385804	87.4	14
	1335 Plains Road East Burlington ON ***Well ID:*** 7338455	87.9	15
	1335 Plains Road East Burlington ON ***Well ID:*** 7338507	92.9	17
	1355 Plains Road East Burlington ON ***Well ID:*** 7380254	93.0	18
	1355 Plains Road East Burlington ON ***Well ID:*** 7382220	93.0	18
	1335 Plains Road East Burlington ON ***Well ID:*** 7338464	93.7	19
	1355 Plains Road East Burlington ON ***Well ID:*** 7384175	93.9	20
	1355 Plains Road East Burlington ON	95.3	21

Site	Address	Distance (m)	Map Key
	Well ID: 7384174		
	1335 Plains Road East Burlington ON ***Well ID:*** 7338506	97.3	22
	1390-1400 PLAINS RD. BIRLINGTON ON ***Well ID:*** 2810541	98.6	23
	1335 Plains Road East Burlington ON ***Well ID:*** 7338505	101.2	24
	1335 Plains Road East Burlington ON ***Well ID:*** 7338508	101.4	25
	1355 Plains Road East Burlington ON ***Well ID:*** 7380232	103.3	26
	1335 Plains Road East Burlington ON ***Well ID:*** 7338498	106.9	28
	1335 Plains Road East Burlington ON ***Well ID:*** 7338509	113.7	32
	ON ***Well ID:*** 7301199	114.8	33
	1400 Plains Road East Burlington ON ***Well ID:*** 7385081	115.1	35
	1400 Plains Road East Burlington ON ***Well ID:*** 7385082	115.1	35
	1335 Plains Road East Burlington ON ***Well ID:*** 7360647	124.1	38

Site	Address	Distance (m)	Map Key
	2201 PLAINS RD E BURLINGTON ON ***Well ID:*** 2810057	124.4	39
	ON ***Well ID:*** 7164921	129.3	40
	1335 Plains Road East Burlington ON ***Well ID:*** 7338463	134.1	41
	1335 Plains Road East Burlington ON ***Well ID:*** 7338511	137.2	43
	1335 Plains Road East Burlington ON ***Well ID:*** 7338514	146.0	45
	1325 PLAINS RD. E BURLINGTON ON ***Well ID:*** 7251866	173.2	49
	ON ***Well ID:*** 7204013	187.2	53
	Glendor Ave Burlington ON ***Well ID:*** 7355019	211.3	60
	ON ***Well ID:*** 7265586	222.6	63
	1446 PLAINS RD E Burlington ON ***Well ID:*** 7203959	237.8	68



Map: 0.3 Kilometer Radius

Order Number: 23021000646


Address: Phase one ESA -1376 and 1382 Plain Road East, Burlington, ON

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership

79°49'30"W



Aerial


Year: 2021

Order Number: 23021000646

Address: Phase one ESA -1376 and 1382 Plain Road East, Burlington, ON

Source: ESRI World Imagery

© ERIS Information Limited Partnership



Topographic Map

Order Number: 23021000646

Address: Phase one ESA -1376 and 1382 Plain Road East, ON

Source: ESRI World Topographic Map

© ERIS Information Limited Partnership

Detail Report

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	1 of 1	WNW/0.0	99.8 / 0.00	1382 PLAINS RD EAST BURLIGNTON ON	WWIS

Well ID: 2810666
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z56620
Tag: A051083
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 18-Dec-2006 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 6607
Form Version: 3
Owner:
County: HALTON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2006/10/27
Year Completed: 2006
Depth (m): 3
Latitude: 43.3359504555976
Longitude: -79.8188231674491
Path:

Bore Hole Information

Bore Hole ID: 11692871
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 27-Oct-2006 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 595750.00
North83: 4798800.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID:	933073954
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	81
Mat2 Desc:	SANDY
Mat3:	05
Mat3 Desc:	CLAY
Formation Top Depth:	0.0
Formation End Depth:	1.0
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	933073955
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Mat2 Desc:	SILT
Mat3:	
Mat3 Desc:	
Formation Top Depth:	1.0
Formation End Depth:	3.0
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933303536
Layer:	1
Plug From:	0.0
Plug To:	0.8999999761581421
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	962810666
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	11697737
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930888215

Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	1.0
Casing Diameter:	5.099999904632568
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	933420786
Layer:	1
Slot:	10
Screen Top Depth:	1.0
Screen End Depth:	3.0
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.400000095367432

Water Details

Water ID:	934071753
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	1.0
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	11756641
Diameter:	21.0
Depth From:	0.0
Depth To:	3.0
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	11692871	**Tag No:**	A051083
Depth M:	3	**Contractor:**	6607
Year Completed:	2006	**Path:**	
Well Completed Dt:	2006/10/27	**Latitude:**	43.3359504555976
Audit No:	Z56620	**Longitude:**	-79.8188231674491

---

2 | ***1 of 2*** | ***W/0.0*** | ***99.8 / 0.00*** | ***1376-1382 Plains Road East Burlington ON L7R 3P8*** | ***EHS***

Order No:	20200312047	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	QC
Report Date:	17-MAR-20	**Search Radius (km):**	.25
Date Received:	12-MAR-20	**X:**	-79.818928
Previous Site Name:		**Y:**	43.3359039
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Title Searches; City Directory; Aerial Photos		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
2	2 of 2	W/0.0	99.8 / 0.00	1376-1382 Plains Road East Burlington ON L7R 3P8	EHS

Order No:	20200312047	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	QC
Report Date:	17-MAR-20	**Search Radius (km):**	.25
Date Received:	12-MAR-20	**X:**	-79.818928
Previous Site Name:		**Y:**	43.3359039
Lot/Building Size:			

Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Title Searches; City Directory; Aerial Photos

---

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
3	1 of 1	SW/17.5	99.8 / 0.00	ON	WWIS

Well ID:	7276104	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	29-Nov-2016 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	C33131	**Contractor:**	7215
Tag:	A202987	**Form Version:**	8
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	2016/04/25
Year Completed:	2016
Depth (m):	
Latitude:	43.3354931040383
Longitude:	-79.8190047350911
Path:	

Bore Hole Information

Bore Hole ID:	1006298681	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595736.00
Code OB Desc:		**North83:**	4798749.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	25-Apr-2016 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Links

Bore Hole ID:	1006298681	***Tag No:***	A202987
Depth M:		***Contractor:***	7215
Year Completed:	2016	***Path:***	
Well Completed Dt:	2016/04/25	***Latitude:***	43.3354931040383
Audit No:	C33131	***Longitude:***	-79.8190047350911

---

4 | ***1 of 1*** | ***WSW/25.1*** | ***99.8 / 0.00*** | ***1368 Plains Road East Burlington ON L7R 3P8*** | ***EHS***

Order No:	20120511024	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Custom Report	***Client Prov/State:***	ON
Report Date:	5/18/2012 1:03:32 PM	***Search Radius (km):***	0.25
Date Received:	5/11/2012 1:02:35 PM	***X:***	-79.819405
Previous Site Name:		***Y:***	43.335642
Lot/Building Size:			
Additional Info Ordered:			

---

5 | ***1 of 16*** | ***SW/36.3*** | ***99.8 / 0.00*** | ***BURLINGTON TAXI LTD 1364 PLAINS RD E BURLINGTON ON L7R3P8*** | ***PRT***

Location ID:	2479
Type:	retail
Expiry Date:	1994-09-30
Capacity (L):	2000
Licence #:	0034341001

---

5 | ***2 of 16*** | ***SW/36.3*** | ***99.8 / 0.00*** | ***GASLINK TRANSPORT INC MAIN 1364 PLAINS RD E BURLINGTON ON L7R 3P8*** | ***RST***

Headcode:	01070540
Headcode Desc:	PROPANE GAS-TANKS & REFILLING
Phone:	
List Name:	
Description:	

---

5 | ***3 of 16*** | ***SW/36.3*** | ***99.8 / 0.00*** | ***BURLINGTON TAXI LTD. 1364 PLAINS RD. EAST BURLINGTON ON L7R 3P8*** | ***GEN***

Generator No:	ON1166700
SIC Code:	6351
SIC Description:	GARAGES(GEN. REPAIR)
Approval Years:	89
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	4 of 16	SW/36.3	99.8 / 0.00	BURLINGTON TAXI LTD. 06-368 1364 PLAINS ROAD EAST BURLINGTON ON L7R 3P8	GEN

Generator No: ON1166700
SIC Code: 6351
SIC Description: GARAGES(GEN. REPAIR)
Approval Years: 92,93,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	5 of 16	SW/36.3	99.8 / 0.00	BURLINGTON TAXI LTD. 06-368 1364 PLAINS RD. EAST BURLINGTON ON L7R 3P8	GEN

Generator No: ON1166700
SIC Code: 6351
SIC Description: GARAGES(GEN. REPAIR)
Approval Years: 94,95
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	6 of 16	SW/36.3	99.8 / 0.00	BURLINGTON TAXI LIMITED 1364 PLAINS ROAD EAST BURLINGTON ON L7R 3P8	GEN

Generator No: ON1166700
SIC Code: 6351
SIC Description: GARAGES(GEN. REPAIR)
Approval Years: 99,00
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	7 of 16	SW/36.3	99.8 / 0.00	BURLING(OUT OF BUSINESS) 1364 PLAINS ROAD EAST BURLINGTON ON L7R 3P8	GEN

Generator No: ON1166700
SIC Code: 6351
SIC Description: GARAGES(GEN. REPAIR)
Approval Years: 01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	8 of 16	SW/36.3	99.8 / 0.00	GAS LINK SERVICES INC MAIN 1364 PLAINS RD E BURLINGTON ON L7R 3P8	RST

Headcode: 01070540
Headcode Desc: PROPANE GAS-TANKS & REFILLING
Phone:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
List Name: Description:					
5	9 of 16	SW/36.3	99.8 / 0.00	BURLINGTON TAXI LTD 1364 PLAINS RD E BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	9653914	Expired Date:	
Status:	EXPIRED	Max Hazard Rank:	
Instance ID:	387991	Facility Location:	
Instance Type:	FS Facility	Facility Type:	
Instance Creation Dt:		Fuel Type 2:	
Instance Install Dt:		Fuel Type 3:	
Item Description:		Panam Related:	
Manufacturer:		Panam Venue Nm:	
Model:		External Identifier:	
Serial No:		Item:	
ULC Standard:		Piping Steel:	
Quantity:		Piping Galvanized:	
Unit of Measure:		Tank Single Wall St:	
Overfill Prot Type:		Piping Underground:	
Creation Date:		Tank Underground:	
Next Periodic Str DT:		Source:	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Propane Refill Cntr - Motor Fill		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	10 of 16	SW/36.3	99.8 / 0.00	BURLINGTON TAXI LTD 1364 PLAINS RD E BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	11564004	Expired Date:	
Status:	EXPIRED	Max Hazard Rank:	
Instance ID:	90815	Facility Location:	
Instance Type:	FS Propane Tank	Facility Type:	
Instance Creation Dt:		Fuel Type 2:	
Instance Install Dt:		Fuel Type 3:	
Item Description:		Panam Related:	
Manufacturer:		Panam Venue Nm:	
Model:		External Identifier:	
Serial No:		Item:	
ULC Standard:		Piping Steel:	
Quantity:		Piping Galvanized:	
Unit of Measure:		Tank Single Wall St:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Tank
Original Source: EXP
Record Date: Up to Mar 2012

5	11 of 16	SW/36.3	99.8 / 0.00	**BURLINGTON TAXI LTD** **1364 PLAINS RD E** **BURLINGTON ON**	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 10634236 ***Expired Date:***
Status: EXPIRED ***Max Hazard Rank:***
Instance ID: 31095 ***Facility Location:***
Instance Type: FS Propane Tank ***Facility Type:***
Instance Creation Dt: ***Fuel Type 2:***
Instance Install Dt: ***Fuel Type 3:***
Item Description: ***Panam Related:***
Manufacturer: ***Panam Venue Nm:***
Model: ***External Identifier:***
Serial No: ***Item:***
ULC Standard: ***Piping Steel:***
Quantity: ***Piping Galvanized:***
Unit of Measure: ***Tank Single Wall St:***
Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Tank
Original Source: EXP
Record Date: Up to Mar 2012

5	12 of 16	SW/36.3	99.8 / 0.00	**GASLINK SERVICES INC** **1364 PLAINS RD E** **BURLINGTON ON L7R3P8**	RST

Headcode: 01070510
Headcode Desc: PROPANE GAS SALES & SERVICE
Phone: 9056814550
List Name: INFO-DIRECT(TM) BUSINESS FILE

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Description:					

---

5 **13 of 16** **SW/36.3** **99.8 / 0.00** **1364 Plains Rd E**
Burlington ON L7R3P8 **EHS**

Order No:	20160217116	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	24-FEB-16	**Search Radius (km):**	.25
Date Received:	17-FEB-16	**X:**	-79.819407
Previous Site Name:		**Y:**	43.33535
Lot/Building Size:			
Additional Info Ordered:			

---

5 **14 of 16** **SW/36.3** **99.8 / 0.00** **Union Gas Limited**
1364 Plains Road East
Burlington ON **SPL**

Ref No:	1488-AD3R9W	**Discharger Report:**	
Site No:	NA	**Material Group:**	
Incident Dt:	8/22/2016	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:		**Sector Type:**	Miscellaneous Communal
Incident Event:	Leak/Break	**Agency Involved:**	
Contaminant Code:	35	**Nearest Watercourse:**	
Contaminant Name:	NATURAL GAS (METHANE)	**Site Address:**	1364 Plains Road East
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:		**Site Municipality:**	Burlington
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:	Air	**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	8/22/2016	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Incident Reason:	Operator/Human Error	**Source Type:**	
Site Name:	Residence<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	TSSA: FSB 1.25" ST line strike.		
Contaminant Qty:	0 other - see incident description		

---

5 **15 of 16** **SW/36.3** **99.8 / 0.00** **GAS LINK**
1364 PLAINS RD E
BURLINGTON ON L7R3P8 **RST**

Headcode:	01070510
Headcode Desc:	PROPANE GAS SALES & SERVICE
Phone:	9056814550
List Name:	INFO-DIRECT(TM) BUSINESS FILE
Description:	

---

5 **16 of 16** **SW/36.3** **99.8 / 0.00** **PIPELINE HIT - 1 ¼"**
1364 PLAINS ROAD EAST,,BURLINGTON,ON,
L7R 3P8,CA
ON **PINC**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Incident Id:		**Pipe Material:**	
Incident No:	1927842	**Fuel Category:**	
Incident Reported Dt:	8/23/2016	**Health Impact:**	
Type:	FS-Pipeline Incident	**Environment Impact:**	
Status Code:		**Property Damage:**	
Tank Status:	Non Mandated	**Service Interrupt:**	
Task No:		**Enforce Policy:**	
Spills Action Centre:		**Public Relation:**	
Fuel Type:		**Pipeline System:**	
Fuel Occurrence Tp:		**PSIG:**	
Date of Occurrence:		**Attribute Category:**	
Occurrence Start Dt:		**Regulator Location:**	
Depth:		**Method Details:**	

Customer Acct Name: PIPELINE HIT - 1 ¼"
Incident Address: 1364 PLAINS ROAD EAST,,BURLINGTON,ON,L7R 3P8,CA
Operation Type:
Pipeline Type:
Regulator Type:
Summary:
Reported By:
Affiliation:
Occurrence Desc:
Damage Reason:
Notes:

---

6 | ***1 of 1*** | ***W/47.4*** | ***99.8 / 0.00*** | ***ON*** | ***WWIS***

Well ID:	2800006	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Domestic	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	15-Dec-1952 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	2309
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	BB
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: BURLINGTON CITY
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/280\2800006.pdf

Additional Detail(s) (Map)

Well Completed Date: 1952/11/20
Year Completed: 1952
Depth (m): 27.432
Latitude: 43.3359951890132
Longitude: -79.8196673132119
Path: 280\2800006.pdf

Bore Hole Information

Bore Hole ID:	10146563	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595681.50
Code OB Desc:		**North83:**	4798804.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	5
Date Completed:	20-Nov-1952 00:00:00	**UTMRC Desc:**	margin of error : 100 m - 300 m
Remarks:		**Location Method:**	p5

Loc Method Desc: Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	931420872
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	11
Most Common Material:	GRAVEL
Mat2:	09
Mat2 Desc:	MEDIUM SAND
Mat3:	
Mat3 Desc:	
Formation Top Depth:	30.0
Formation End Depth:	64.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931420873
Layer:	3
Color:	
General Color:	
Mat1:	15
Most Common Material:	LIMESTONE
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	64.0
Formation End Depth:	90.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931420871
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	05
Most Common Material:	CLAY
Mat2:	12
Mat2 Desc:	STONES

Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 30.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 962800006
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10695133
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930249341
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 64.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930249342
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 90.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 992800006
Pump Set At:
Static Level: 55.0
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate: 2.0
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 2
Water State After Test: CLOUDY
Pumping Test Method: 1
Pumping Duration HR: 0

Pumping Duration MIN: 30
Flowing: No

Water Details

Water ID: 933601190
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 90.0
Water Found Depth UOM: ft

Links

Bore Hole ID: 10146563
Depth M: 27.432
Year Completed: 1952
Well Completed Dt: 1952/11/20
Audit No:
Tag No:
Contractor: 2309
Path: 280\2800006.pdf
Latitude: 43.3359951890132
Longitude: -79.8196673132119

7	1 of 3	WSW/67.3	99.8 / 0.00	R.M. OF HALTON - LEIGHLAND RD. HELENA ST./PLAINS RD. E. BURLINGTON CITY ON	CA

Certificate #: 3-1056-92-
Application Year: 92
Issue Date: 8/25/1992
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

7	2 of 3	WSW/67.3	99.8 / 0.00	R.M. OF HALTON - LEIGHLAND RD. PLAINS RD.E./HELENA ST/GLENDOR BURLINGTON CITY ON	CA

Certificate #: 7-0843-92-
Application Year: 92
Issue Date: 8/25/1992
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

7	3 of 3	WSW/67.3	99.8 / 0.00	TANK TRUCK PLAINS RD/HELENA ST. TANK TRUCK (CARGO) NOT PETROLEUM BURLINGTON CITY ON	SPL

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Ref No:	193907	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	1/26/2001	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Not Anticipated	**Site Municipality:**	14101
Nature of Impact:		**Site Lot:**	
Receiving Medium:	Land	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	1/26/2001	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	EQUIPMENT FAILURE	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	THERMSHELL TANK TRUCK- 20L FURNACE OIL TO RD WHEN VALVE GOT STUCK, CLEANED.		
Contaminant Qty:			

8	*1 of 1*	*NNW/71.2*	*99.8 / 0.00*	*ON*	*BORE*

Borehole ID:	621546	**Inclin FLG:**	No
OGF ID:	215522000	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	MAR-1965	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.336877
Total Depth m:	4.5	**Longitude DD:**	-79.818996
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	595735
Drill Method:	Power auger	**Northing:**	4798903
Orig Ground Elev m:	100	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	100		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218421428	**Mat Consistency:**	
Top Depth:	.6	**Material Moisture:**	
Bottom Depth:	.8	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND. BROWN,AGE GLACIAL.		

Geology Stratum ID:	218421427	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.6	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Soil	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SOIL. AGE POST-GLACIAL.		

Geology Stratum ID:	218421429	**Mat Consistency:**	Hard
Top Depth:	.8	**Material Moisture:**	
Bottom Depth:	4.5	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Stones	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SAND,SILT, STONES. BROWN,GLACIAL,HARD, AGE GLACIAL. 00025050SAND.BRO **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: HAM.txt RecordID: 005450 NTS_Sheet: 30M05C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

9 | **1 of 1** | **W/78.1** | **99.8 / 0.00** | **1355 Plains Road East Burlington ON** | **WWIS**

Well ID:	7384176	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	29-Mar-2021 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	UM6TVOKQ	**Contractor:**	7732
Tag:	_NO_TAG	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	BB
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	

Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BURLINGTON CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008598781	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	595645.00
Code OB Desc:		***North83:***	4798775.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	11-Mar-2021 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1008598875
Layer:	1
Color:	
General Color:	
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008598975
Layer:	1
Plug From:	0.0
Plug To:	4.099999904632568
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008598940
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	m

Pipe Information

Pipe ID:	1008598813

Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008598900
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.0
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1008598914
Layer: 1
Slot:
Screen Top Depth: 1.0
Screen End Depth: 4.099999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008598814
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1008598850
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 1.600000023841858
Water Found Depth UOM: m

Links

Bore Hole ID: 1008598781
Depth M:
Year Completed: 2021
Tag No: _NO_TAG
Contractor: 7732
Path: 738\7384176.pdf

Well Completed Dt:	2021/03/11	**Latitude:**	43.3357387576343
Audit No:	UM6TVOKQ	**Longitude:**	-79.8201225410501

10 | **1 of 2** | **W/78.7** | **99.8 / 0.00** | **1355 Plains Road East Burlington ON** | **WWIS**

Well ID:	7380256	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	09-Feb-2021 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	I4PIAOIJ	**Contractor:**	7732
Tag:	A296641	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	BB
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008568597	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595646.00
Code OB Desc:		**North83:**	4798764.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	28-Jan-2021 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1008568693
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.20000000298023224
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1008568694
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Mat2 Desc:	CLAY
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.20000000298023224
Formation End Depth:	4.0
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008568780
Layer:	3
Plug From:	0.6000000238418579
Plug To:	4.0
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008568779
Layer:	2
Plug From:	0.30000001192092896
Plug To:	0.6000000238418579
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008568758
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008568778
Layer:	1
Plug From:	0.0
Plug To:	0.30000001192092896
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1008568649
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1008568631
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1008568705
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	0.8999999761581421
Casing Diameter:	3.200000047683716
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1008568712
Layer:	1
Slot:	10
Screen Top Depth:	0.8999999761581421
Screen End Depth:	4.0
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008568632
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1008568678
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	1.7999999523162842
Water Found Depth UOM:	m

Hole Diameter

Hole ID: 1008568725
Diameter: 5.0
Depth From: 0.0
Depth To: 4.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Bore Hole ID: 1008568597
Depth M: 4
Year Completed: 2021
Well Completed Dt: 2021/01/28
Audit No: I4PIAOIJ
Tag No: A296641
Contractor: 7732
Path: 738\7380256.pdf
Latitude: 43.3356396012658
Longitude: -79.8201121251873

---

10 **2 of 2** **W/78.7** **99.8 / 0.00** **1355 Plains Road East Burlington ON** **WWIS**

Well ID: 7382222
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: KI7GVUAD
Tag: A296641
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 10-Mar-2021 00:00:00
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7732
Form Version: 9
Owner:
County: HALTON
Lot:
Concession:
Concession Name: BB
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1008583697
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 18-Feb-2021 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation:
Elevrc:
Zone: 17
East83: 595646.00
North83: 4798764.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1008583802
Layer: 1
Color:
General Color:
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008583894
Layer: 1
Plug From: 0.0
Plug To: 4.0
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008583879
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Pipe Information

Pipe ID: 1008583738
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008583837
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 0.8999999761581421
Casing Diameter: 3.200000047683716
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1008583853
Layer: 1
Slot:
Screen Top Depth: 0.8999999761581421
Screen End Depth: 4.0
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008583739
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1008583786
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	1.7999999523162842
Water Found Depth UOM:	m

Links

Bore Hole ID:	1008583697	***Tag No:***	A296641
Depth M:		***Contractor:***	7732
Year Completed:	2021	***Path:***	738\7382222.pdf
Well Completed Dt:	2021/02/18	***Latitude:***	43.3356396012658
Audit No:	KI7GVUAD	***Longitude:***	-79.8201121251873

---

11 | ***1 of 2*** | ***W/83.0*** | ***99.8 / 0.00*** | ***1355 Plains Road East Burlington ON*** | ***WWIS***

Well ID:	7380255	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	09-Feb-2021 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	SOS7YBCY	***Contractor:***	7732
Tag:	A296640	***Form Version:***	9
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	HALTON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	BB
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BURLINGTON CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008568594	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	595640.00
Code OB Desc:		***North83:***	4798776.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	28-Jan-2021 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1008568692
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Mat2 Desc:	CLAY
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.20000000298023224
Formation End Depth:	4.0
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1008568691
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.20000000298023224
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008568777
Layer:	3
Plug From:	0.6000000238418579
Plug To:	4.0
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008568776
Layer:	2
Plug From:	0.30000001192092896
Plug To:	0.6000000238418579
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008568757
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008568775
Layer:	1
Plug From:	0.0
Plug To:	0.30000001192092896
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1008568648
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1008568629
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1008568704
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	0.8999999761581421
Casing Diameter:	3.200000047683716
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1008568711
Layer:	1
Slot:	10
Screen Top Depth:	0.8999999761581421
Screen End Depth:	4.0

Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008568630
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1008568677
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	1.7999999523162842
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1008568724
Diameter:	5.0
Depth From:	0.0
Depth To:	4.0
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	1008568594	**Tag No:**	A296640
Depth M:	4	**Contractor:**	7732
Year Completed:	2021	**Path:**	738\7380255.pdf
Well Completed Dt:	2021/01/28	**Latitude:**	43.3357483964932
Audit No:	SOS7YBCY	**Longitude:**	-79.8201840339338

11 ***2 of 2*** ***W/83.0*** ***99.8 / 0.00*** ***1355 Plains Road East Burlington ON*** ***WWIS***

Well ID:	7382221	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	10-Mar-2021 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	VY8A5G3L	**Contractor:**	7732

Tag:	A296640	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	BB
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008583694	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595640.00
Code OB Desc:		**North83:**	4798776.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	18-Feb-2021 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1008583801
Layer:	1
Color:	
General Color:	
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008583878
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008583893

Layer: 1
Plug From: 0.0
Plug To: 4.0
Plug Depth UOM: m

Pipe Information

Pipe ID: 1008583736
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008583836
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 0.8999999761581421
Casing Diameter: 3.200000047683716
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1008583852
Layer: 1
Slot:
Screen Top Depth: 0.8999999761581421
Screen End Depth: 4.0
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008583737
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1008583785
Layer: 1
Kind Code: 8
Kind: Untested

Water Found Depth: 1.7999999523162842
Water Found Depth UOM: m

Links

Bore Hole ID: 1008583694
Depth M:
Year Completed: 2021
Well Completed Dt: 2021/02/18
Audit No: VY8A5G3L
Tag No: A296640
Contractor: 7732
Path: 738\7382221.pdf
Latitude: 43.3357483964932
Longitude: -79.8201840339338

---

12 | **1 of 1** | **WSW/84.0** | **99.8 / 0.00** | **1355 Plains Road East Burlington ON** | **WWIS**

Well ID: 7384177
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: M68POPWD
Tag: _NO_TAG
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 29-Mar-2021 00:00:00
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7732
Form Version: 9
Owner:
County: HALTON
Lot:
Concession:
Concession Name: BB
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1008598784
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 11-Mar-2021 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation:
Elevrc:
Zone: 17
East83: 595642.00
North83: 4798758.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1008598876
Layer: 1
Color:
General Color:
Mat1:

Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008598941
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008598976
Layer: 1
Plug From: 0.0
Plug To: 3.200000047683716
Plug Depth UOM: m

Pipe Information

Pipe ID: 1008598815
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008598901
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 0.10000000149011612
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1008598915
Layer: 1
Slot:
Screen Top Depth: 0.10000000149011612
Screen End Depth: 3.200000047683716
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:

Pump Test ID:	1008598816
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1008598851
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	0.8999999761581421
Water Found Depth UOM:	m

Links

Bore Hole ID:	1008598784	**Tag No:**	_NO_TAG
Depth M:		**Contractor:**	7732
Year Completed:	2021	**Path:**	738\7384177.pdf
Well Completed Dt:	2021/03/11	**Latitude:**	43.3355860943543
Audit No:	M68POPWD	**Longitude:**	-79.8201625047685

---

13 | ***1 of 1*** | ***W/86.5*** | ***99.8 / 0.00*** | ***1355 Plains Rd E Burlington ON L7R3P7*** | ***EHS***

Order No:	20170914115	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	RSC Report (Urban)	**Client Prov/State:**	ON
Report Date:	21-SEP-17	**Search Radius (km):**	.3
Date Received:	14-SEP-17	**X:**	-79.820225
Previous Site Name:		**Y:**	43.335725
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Topographic Maps		

---

14 | ***1 of 1*** | ***WSW/87.4*** | ***99.8 / 0.00*** | ***ON*** | ***WWIS***

Well ID:	7385804	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	26-Apr-2021 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	C36202	**Contractor:**	7282
Tag:	A268202	**Form Version:**	8
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	

Well Depth: **Concession Name:**
Overburden/Bedrock: **Easting NAD83:**
Pump Rate: **Northing NAD83:**
Static Water Level: **Zone:**
Clear/Cloudy: **UTM Reliability:**
Municipality: BURLINGTON CITY
Site Info:

Bore Hole Information

Bore Hole ID:	1008632508	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595638.00
Code OB Desc:		**North83:**	4798760.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	14-Nov-2019 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008632508	**Tag No:**	A268202
Depth M:		**Contractor:**	7282
Year Completed:	2019	**Path:**	
Well Completed Dt:	2019/11/14	**Latitude:**	43.3356046086032
Audit No:	C36202	**Longitude:**	-79.8202114897847

---

15 | ***1 of 1*** | ***W/87.9*** | ***99.8 / 0.00*** | ***1335 Plains Road East Burlington ON*** | ***WWIS***

Well ID:	7338455	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Not Used	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	12-Jun-2019 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	E2ORS62Z	**Contractor:**	7147
Tag:	A201427	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	BB
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/733\7338455.pdf

Additional Detail(s) (Map)

Well Completed Date: 2019/05/17
Year Completed: 2019
Depth (m):
Latitude: 43.3356227411341
Longitude: -79.8202234745813
Path: 733\7338455.pdf

Bore Hole Information

Bore Hole ID: 1007557338
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 17-May-2019 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 595637.00
North83: 4798762.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1007558124
Layer: 1
Color:
General Color:
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007558852
Layer: 1
Plug From: 0.0
Plug To: 4.599999904632568
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007558624
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Pipe Information

Pipe ID:	1007557738
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007558298
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	3.0999999046325684
Casing Diameter:	5.0
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1007558447
Layer:	1
Slot:	
Screen Top Depth:	3.0999999046325684
Screen End Depth:	4.599999904632568
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1007557739
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1007557982
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	0.8999999761581421
Water Found Depth UOM:	m

Links

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Bore Hole ID:	1007557338	**Tag No:**	A201427
Depth M:		**Contractor:**	7147
Year Completed:	2019	**Path:**	733\7338455.pdf
Well Completed Dt:	2019/05/17	**Latitude:**	43.3356227411341
Audit No:	E2ORS62Z	**Longitude:**	-79.8202234745813

16 **1 of 1** **W/88.8** **99.8 / 0.00** **DVLP Property Group** **GEN**
1335- 1355 Plains Road East
Burlington ON L7R3P7

Generator No:	ON8378518
SIC Code:	
SIC Description:	
Approval Years:	As of Nov 2021
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	146 L
Waste Class Name:	Other specified inorganic sludges, slurries or solids

17 **1 of 1** **W/92.9** **99.8 / 0.00** **1335 Plains Road East** **WWIS**
Burlington ON

Well ID:	7338507	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Not Used	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	12-Jun-2019 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	RRCYW8ZU	**Contractor:**	7147
Tag:	_NO_TAG	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	BB
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/733\7338507.pdf

Additional Detail(s) (Map)

Well Completed Date:	2019/05/17
Year Completed:	2019
Depth (m):	
Latitude:	43.3356685177574
Longitude:	-79.8202966035943
Path:	733\7338507.pdf

Bore Hole Information

Bore Hole ID:	1007557494	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	595631.00
Code OB Desc:		***North83:***	4798767.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	17-May-2019 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1007558185
Layer:	1
Color:	
General Color:	
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007558676
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007558937
Layer:	1
Plug From:	0.0
Plug To:	4.599999904632568
Plug Depth UOM:	m

Pipe Information

Pipe ID:	1007557842
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007558350
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	1.5
Casing Diameter:	5.0
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1007558497
Layer:	1
Slot:	
Screen Top Depth:	1.5
Screen End Depth:	4.599999904632568
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1007557843
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1007558011
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	0.8999999761581421
Water Found Depth UOM:	m

Links

Bore Hole ID:	1007557494	***Tag No:***	_NO_TAG
Depth M:		***Contractor:***	7147
Year Completed:	2019	***Path:***	733\7338507.pdf
Well Completed Dt:	2019/05/17	***Latitude:***	43.3356685177574
Audit No:	RRCYW8ZU	***Longitude:***	-79.8202966035943

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
18	1 of 2	W/93.0	99.8 / 0.00	1355 Plains Road East Burlington ON	WWIS

Well ID: 7380254
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: 6RMHNDVA
Tag: A296639
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 09-Feb-2021 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7732
Form Version: 9
Owner:
County: HALTON
Lot:
Concession:
Concession Name: BB
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1008568591
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 28-Jan-2021 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 595630.00
North83: 4798775.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1008568689
Layer: 1
Color: 6
General Color: BROWN
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.20000000298023224
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID:	1008568690
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Mat2 Desc:	CLAY
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.20000000298023224
Formation End Depth:	4.0
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008568756
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008568774
Layer:	3
Plug From:	0.6000000238418579
Plug To:	4.0
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008568772
Layer:	1
Plug From:	0.0
Plug To:	0.30000001192092896
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008568773
Layer:	2
Plug From:	0.30000001192092896
Plug To:	0.6000000238418579
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1008568647
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1008568627

Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008568703
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 0.8999999761581421
Casing Diameter: 3.200000047683716
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1008568710
Layer: 1
Slot: 10
Screen Top Depth: 0.8999999761581421
Screen End Depth: 4.0
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008568628
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1008568676
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 1.7999999523162842
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1008568723
Diameter: 5.0
Depth From: 0.0

Depth To:	4.0
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	1008568591	**Tag No:**	A296639
Depth M:	4	**Contractor:**	7732
Year Completed:	2021	**Path:**	738\7380254.pdf
Well Completed Dt:	2021/01/28	**Latitude:**	43.3357406661682
Audit No:	6RMHNDVA	**Longitude:**	-79.8203075426513

---

18 | ***2 of 2*** | ***W/93.0*** | ***99.8 / 0.00*** | ***1355 Plains Road East Burlington ON*** | ***WWIS***

Well ID:	7382220	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	10-Mar-2021 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	O2CT59PQ	**Contractor:**	7732
Tag:	A296639	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	BB
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008583691	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595630.00
Code OB Desc:		**North83:**	4798775.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	18-Feb-2021 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1008583800
Layer:	1
Color:	
General Color:	

Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008583892
Layer: 1
Plug From: 0.0
Plug To: 4.0
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008583877
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Pipe Information

Pipe ID: 1008583734
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008583835
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 0.8999999761581421
Casing Diameter: 3.200000047683716
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1008583851
Layer: 1
Slot:
Screen Top Depth: 0.8999999761581421
Screen End Depth: 4.0
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008583735
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1008583784
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 1.7999999523162842
Water Found Depth UOM: m

Links

Bore Hole ID: 1008583691
Depth M:
Year Completed: 2021
Well Completed Dt: 2021/02/18
Audit No: O2CT59PQ
Tag No: A296639
Contractor: 7732
Path: 738\7382220.pdf
Latitude: 43.3357406661682
Longitude: -79.8203075426513

---

19 ***1 of 1*** ***WSW/93.7*** ***99.8 / 0.00*** ***1335 Plains Road East Burlington ON*** ***WWIS***

Well ID: 7338464
Construction Date:
Use 1st: Not Used
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: T6399Y3L
Tag: A253441
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 12-Jun-2019 00:00:00
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7147
Form Version: 9
Owner:
County: HALTON
Lot:
Concession:
Concession Name: BB
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/733\7338464.pdf

Additional Detail(s) (Map)

Well Completed Date: 2019/05/17
Year Completed: 2019
Depth (m):
Latitude: 43.3355240937017
Longitude: -79.8202623921558
Path: 733\7338464.pdf

Bore Hole Information

Bore Hole ID: 1007557365
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 17-May-2019 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 595634.00
North83: 4798751.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1007558133
Layer: 1
Color:
General Color:
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007558633
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007558866
Layer: 1
Plug From: 0.0
Plug To: 3.0999999046325684
Plug Depth UOM: m

Pipe Information

Pipe ID: 1007557756
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007558307
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 0.6000000238418579
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1007558454
Layer: 1
Slot:
Screen Top Depth: 0.6000000238418579
Screen End Depth: 3.0999999046325684
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1007557757
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1007557986
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 0.8999999761581421
Water Found Depth UOM: m

Links

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Bore Hole ID:	1007557365	**Tag No:**	A253441
Depth M:		**Contractor:**	7147
Year Completed:	2019	**Path:**	733\7338464.pdf
Well Completed Dt:	2019/05/17	**Latitude:**	43.3355240937017
Audit No:	T6399Y3L	**Longitude:**	-79.8202623921558

20 **1 of 1** **W/93.9** **99.8 / 0.00** **1355 Plains Road East Burlington ON** **WWIS**

Well ID:	7384175	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	29-Mar-2021 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	MYND744N	**Contractor:**	7732
Tag:	_NO_TAG	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	BB
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008598778	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595629.00
Code OB Desc:		**North83:**	4798783.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	11-Mar-2021 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1008598874
Layer:	1
Color:	
General Color:	
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0

Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008598974
Layer: 1
Plug From: 0.0
Plug To: 4.199999809265137
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008598939
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Pipe Information

Pipe ID: 1008598811
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008598899
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.100000023841858
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1008598913
Layer: 1
Slot:
Screen Top Depth: 1.100000023841858
Screen End Depth: 4.199999809265137
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008598812
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:

Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1008598849
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 1.399999976158142
Water Found Depth UOM: m

Links

Bore Hole ID: 1008598778
Depth M:
Year Completed: 2021
Well Completed Dt: 2021/03/11
Audit No: MYND744N
Tag No: _NO_TAG
Contractor: 7732
Path: 738\7384175.pdf
Latitude: 43.3358128145774
Longitude: -79.8203184817324

---

21 | ***1 of 1*** | ***W/95.3*** | ***99.8 / 0.00*** | ***1355 Plains Road East Burlington ON*** | ***WWIS***

Well ID: 7384174
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: BJE9TO5P
Tag: _NO_TAG
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 29-Mar-2021 00:00:00
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7732
Form Version: 9
Owner:
County: HALTON
Lot:
Concession:
Concession Name: BB
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1008598775
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 11-Mar-2021 00:00:00
Elevation:
Elevrc:
Zone: 17
East83: 595628.00
North83: 4798790.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m

Remarks: ***Location Method:*** wwr
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1008598873
Layer: 1
Color:
General Color:
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008598973
Layer: 1
Plug From: 0.0
Plug To: 4.099999904632568
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008598938
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Pipe Information

Pipe ID: 1008598809
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008598898
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.0
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID:	1008598912
Layer:	1
Slot:	
Screen Top Depth:	1.0
Screen End Depth:	4.099999904632568
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008598810
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1008598848
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	0.8999999761581421
Water Found Depth UOM:	m

Links

Bore Hole ID:	1008598775	***Tag No:***	_NO_TAG
Depth M:		***Contractor:***	7732
Year Completed:	2021	***Path:***	738\7384174.pdf
Well Completed Dt:	2021/03/11	***Latitude:***	43.335875960337
Audit No:	BJE9TO5P	***Longitude:***	-79.8203295951317

22 ***1 of 1*** ***W/97.3*** ***99.8 / 0.00*** ***1335 Plains Road East Burlington ON*** ***WWIS***

Well ID:	7338506	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Not Used	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Abandoned-Other	***Date Received:***	12-Jun-2019 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	Yes
Audit No:	827Q25U9	***Contractor:***	7147
Tag:	_NO_TAG	***Form Version:***	9

Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	BB
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/733\7338506.pdf

Additional Detail(s) (Map)

Well Completed Date:	2019/05/17
Year Completed:	2019
Depth (m):	
Latitude:	43.3357051644671
Longitude:	-79.8203575735707
Path:	733\7338506.pdf

Bore Hole Information

Bore Hole ID:	1007557491	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595626.00
Code OB Desc:		**North83:**	4798771.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	17-May-2019 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1007558184
Layer:	1
Color:	
General Color:	
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID: 1007558936
Layer: 1
Plug From: 0.0
Plug To: 4.599999904632568
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007558675
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Pipe Information

Pipe ID: 1007557840
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007558349
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.5
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1007558496
Layer: 1
Slot:
Screen Top Depth: 1.5
Screen End Depth: 4.599999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1007557841
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:

Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1007558010
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 0.8999999761581421
Water Found Depth UOM: m

Links

Bore Hole ID: 1007557491
Depth M:
Year Completed: 2019
Well Completed Dt: 2019/05/17
Audit No: 827Q25U9
Tag No: _NO_TAG
Contractor: 7147
Path: 733\7338506.pdf
Latitude: 43.3357051644671
Longitude: -79.8203575735707

---

23 | ***1 of 1*** | ***ENE/98.6*** | ***99.8 / 0.00*** | ***1390-1400 PLAINS RD. BIRLINGTON ON*** | ***WWIS***

Well ID: 2810541
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z43694
Tag: A041344
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 12-May-2006 00:00:00
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7241
Form Version: 3
Owner:
County: HALTON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/281\2810541.pdf

Additional Detail(s) (Map)

Well Completed Date: 2006/04/25
Year Completed: 2006
Depth (m): 3.66
Latitude: 43.3365738239922
Longitude: -79.8172801766726
Path: 281\2810541.pdf

Bore Hole Information

Bore Hole ID: 11552451
DP2BR:
Spatial Status:
Code OB:
Elevation:
Elevrc:
Zone: 17
East83: 595874.10

Code OB Desc:		***North83:***	4798871.00
Open Hole:		***Org CS:***	G83a
Cluster Kind:		***UTMRC:***	3
Date Completed:	25-Apr-2006 00:00:00	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	933060498
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	34
Mat2 Desc:	TILL
Mat3:	
Mat3 Desc:	
Formation Top Depth:	2.440000057220459
Formation End Depth:	3.6600000858306885
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	933060496
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	11
Most Common Material:	GRAVEL
Mat2:	01
Mat2 Desc:	FILL
Mat3:	77
Mat3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	1.2200000286102295
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	933060497
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	
Mat3 Desc:	
Formation Top Depth:	1.2200000286102295
Formation End Depth:	2.440000057220459
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID: 933297310
Layer: 3
Plug From: 0.9100000262260437
Plug To: 3.6600000858306885
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933297309
Layer: 2
Plug From: 0.30000001192092896
Plug To: 0.9100000262260437
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933297308
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 962810541
Method Construction Code: B
Method Construction: Other Method
Other Method Construction:

Pipe Information

Pipe ID: 11562058
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930882546
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.2200000286102295
Casing Diameter: 5.079999923706055
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933419481
Layer: 1
Slot: 010

Screen Top Depth:	1.2200000286102295
Screen End Depth:	3.6600000858306885
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	5.329999923706055

Hole Diameter

Hole ID:	11683574
Diameter:	10.0
Depth From:	0.0
Depth To:	3.6600000858306885
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	11552451	**Tag No:**	A041344
Depth M:	3.66	**Contractor:**	7241
Year Completed:	2006	**Path:**	281\2810541.pdf
Well Completed Dt:	2006/04/25	**Latitude:**	43.3365738239922
Audit No:	Z43694	**Longitude:**	-79.8172801766726

---

24 ***1 of 1*** ***W/101.2*** ***99.8 / 0.00*** ***1335 Plains Road East Burlington ON*** ***WWIS***

Well ID:	7338505	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Not Used	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	12-Jun-2019 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	JKQ9ANPE	**Contractor:**	7147
Tag:	_NO_TAG	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	BB
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/733\7338505.pdf

Additional Detail(s) (Map)

Well Completed Date:	2019/05/17
Year Completed:	2019
Depth (m):	
Latitude:	43.3357236786339
Longitude:	-79.820406558743
Path:	733\7338505.pdf

Bore Hole Information

Bore Hole ID:	1007557488	**Elevation:**	

DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595622.00
Code OB Desc:		**North83:**	4798773.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	17-May-2019 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1007558183
Layer:	1
Color:	
General Color:	
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007558935
Layer:	1
Plug From:	0.0
Plug To:	4.599999904632568
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007558674
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	m

Pipe Information

Pipe ID:	1007557838
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007558348
Layer:	1

Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	1.5
Casing Diameter:	5.0
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1007558495
Layer:	1
Slot:	
Screen Top Depth:	1.5
Screen End Depth:	4.599999904632568
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1007557839
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1007558009
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	0.800000011920929
Water Found Depth UOM:	m

Links

Bore Hole ID:	1007557488	**Tag No:**	_NO_TAG
Depth M:		**Contractor:**	7147
Year Completed:	2019	**Path:**	733\7338505.pdf
Well Completed Dt:	2019/05/17	**Latitude:**	43.3357236786339
Audit No:	JKQ9ANPE	**Longitude:**	-79.820406558743

25 ***1 of 1*** ***W/101.4*** ***99.8 / 0.00*** ***1335 Plains Road East Burlington ON*** ***WWIS***

Well ID:	7338508	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	

Use 1st:	Not Used	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	12-Jun-2019 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	9BJBSOQD	**Contractor:**	7147
Tag:	_NO_TAG	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	BB
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: BURLINGTON CITY
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/733\7338508.pdf

Additional Detail(s) (Map)

Well Completed Date: 2019/05/17
Year Completed: 2019
Depth (m):
Latitude: 43.3356335249341
Longitude: -79.8203959681368
Path: 733\7338508.pdf

Bore Hole Information

Bore Hole ID:	1007557497	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595623.00
Code OB Desc:		**North83:**	4798763.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	17-May-2019 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1007558186
Layer: 1
Color:
General Color:
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0

Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007558938
Layer: 1
Plug From: 0.0
Plug To: 4.599999904632568
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007558677
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Pipe Information

Pipe ID: 1007557844
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007558351
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.5
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1007558498
Layer: 1
Slot:
Screen Top Depth: 1.5
Screen End Depth: 4.599999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1007557845
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:

Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1007558012
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 0.8999999761581421
Water Found Depth UOM: m

Links

Bore Hole ID: 1007557497
Depth M:
Year Completed: 2019
Well Completed Dt: 2019/05/17
Audit No: 9BJBSOQD
Tag No: _NO_TAG
Contractor: 7147
Path: 733\7338508.pdf
Latitude: 43.3356335249341
Longitude: -79.8203959681368

---

26 ***1 of 1*** ***W/103.3*** ***99.8 / 0.00*** ***1355 Plains Road East Burlington ON*** ***WWIS***

Well ID: 7380232
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: KTJLR5LE
Tag: A296681
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 09-Feb-2021 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7732
Form Version: 9
Owner:
County: HALTON
Lot:
Concession:
Concession Name: BB
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1008568338
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 28-Jan-2021 00:00:00
Elevation:
Elevrc:
Zone: 17
East83: 595620.00
North83: 4798771.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m

Remarks: ***Location Method:*** wwr
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1008568429
Layer: 1
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 05
Mat2 Desc: CLAY
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 8.5
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008568493
Layer: 2
Plug From: 0.30000001192092896
Plug To: 5.099999904632568
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008568476
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008568494
Layer: 3
Plug From: 5.099999904632568
Plug To: 8.5
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008568492
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID:	1008568408
Method Construction Code:	E
Method Construction:	Auger
Other Method Construction:	

Pipe Information

Pipe ID:	1008568381
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1008568444
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	5.400000095367432
Casing Diameter:	5.0
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1008568459
Layer:	1
Slot:	10
Screen Top Depth:	5.400000095367432
Screen End Depth:	8.5
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008568382
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1008568413
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	2.4000000953674316
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1008568473
Diameter:	11.399999618530273
Depth From:	0.0
Depth To:	8.5
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	1008568338	**Tag No:**	A296681
Depth M:	8.5	**Contractor:**	7732
Year Completed:	2021	**Path:**	738\7380232.pdf
Well Completed Dt:	2021/01/28	**Latitude:**	43.335705927764
Audit No:	KTJLR5LE	**Longitude:**	-79.8204315741745

---

27 **1 of 1** **NW/105.8** **99.8 / 0.00** **ON** **BORE**

Borehole ID:	621548	**Inclin FLG:**	No
OGF ID:	215522002	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	MAR-1965	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.336884
Total Depth m:	-999	**Longitude DD:**	-79.819736
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	595675
Drill Method:	Power auger	**Northing:**	4798903
Orig Ground Elev m:	100	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	99.9		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218421433	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.2	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Soil	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SOIL. AGE POST-GLACIAL.		

Geology Stratum ID:	218421436	**Mat Consistency:**	

Top Depth:	4.4	**Material Moisture:**	
Bottom Depth:		**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SAND. 0000801400030060 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218421435	**Mat Consistency:**	Hard
Top Depth:	.9	**Material Moisture:**	
Bottom Depth:	4.4	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:	Gravel	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SAND,CLAY, GRAVEL. BROWN,GLACIAL,HARD, AGE GLACIAL.		

Geology Stratum ID:	218421434	**Mat Consistency:**	
Top Depth:	.2	**Material Moisture:**	
Bottom Depth:	.9	**Material Texture:**	Fine to Medium
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND-FINE TO MEDIUM,SILT. BROWN,AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: HAM.txt RecordID: 005470 NTS_Sheet: 30M05C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

28 **1 of 1** **W/106.9** **99.8 / 0.00** **1335 Plains Road East Burlington ON** **WWIS**

Well ID:	7338498	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Not Used	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	12-Jun-2019 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes

Audit No:	QIDVWAJ6	**Contractor:**	7147
Tag:	_NO_TAG	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	BB
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/733\7338498.pdf

Additional Detail(s) (Map)

Well Completed Date:	2019/05/17
Year Completed:	2019
Depth (m):	
Latitude:	43.3357604524937
Longitude:	-79.8204798622867
Path:	733\7338498.pdf

Bore Hole Information

Bore Hole ID:	1007557467	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595616.00
Code OB Desc:		**North83:**	4798777.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	17-May-2019 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1007558176
Layer:	1
Color:	
General Color:	
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	
Formation End Depth UOM:	m

Annular Space/Abandonment

Sealing Record

Plug ID:	1007558928
Layer:	1
Plug From:	0.0
Plug To:	4.599999904632568
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007558667
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	m

Pipe Information

Pipe ID:	1007557824
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007558341
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	1.5
Casing Diameter:	5.0
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1007558488
Layer:	1
Slot:	
Screen Top Depth:	1.5
Screen End Depth:	4.599999904632568
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1007557825
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	

Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1007558002
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 0.800000011920929
Water Found Depth UOM: m

Links

Bore Hole ID: 1007557467
Depth M:
Year Completed: 2019
Well Completed Dt: 2019/05/17
Audit No: QIDVWAJ6
Tag No: _NO_TAG
Contractor: 7147
Path: 733\7338498.pdf
Latitude: 43.3357604524937
Longitude: -79.8204798622867

---

29 ***1 of 1*** ***WSW/107.1*** ***99.8 / 0.00*** ***DVLP PROPERTY GROUP INC.***
1343 PLAINS ROAD EAST, BURLINGTON, ON
L7R 3P7
Burlington ON ***RSC***

RSC ID: 230135
RA No:
RSC Type: Phase 1 and 2 RSC
Curr Property Use: Commercial
Ministry District: Halton-Peel District Office
Filing Date: 2021/12/15
Date Ack:
Date Returned:
Restoration Type:
Soil Type:
Criteria:
CPU Issued Sect 1686:
Cert Date:
Cert Prop Use No:
Intended Prop Use: Residential
Qual Person Name: RIYAZ PUNJANI
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N):
Accuracy Estimate:
Telephone:
Fax:
Email:

Asmt Roll No: 2402-020-207-09600-0000,
2402-020-207-09900-0000,
2402-020-207-09700-0000,
2402-020-207-09800-0000,
2402-020-207-10000-0000

Prop ID No (PIN): 07081-0502 (LT),
07081-0500 (LT),
07081-0501 (LT)

Property Municipal Address: 1349 PLAINS ROAD EAST, BURLINGTON, ON L7R 3P8, 1339 PLAINS ROAD EAST, BURLINGTON, ON L7R 3P7, 1335 PLAINS ROAD EAST, BURLINGTON, ON L7R 3P7, 1343 PLAINS ROAD EAST, BURLINGTON, ON L7R 3P7, 1355 PLAINS ROAD EAST, BURLINGTON, ON L7R 3P7

Mailing Address:
Latitude & Latitude:
UTM Coordinates:
Consultant:
Legal Desc:
Measurement Method:
Applicable Standards:
RSC PDF: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=154624&fileName=BROWNFIELDS-E.pdf

Document(s) Detail

Document Heading: Supporting Documents
Document Name: 3 - Lawyers Letter-Aug 25-20.pdf
Document Type: Lawyer's letter consisting of a legal description of the property
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=154617&fileName=3+-+Lawyers+Letter-Aug+25-20.pdf

Document Heading: Supporting Documents
Document Name: 4 - Land Registry and Transfer.pdf
Document Type: Copy of any deed(s), transfer(s) or other document(s)
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=154618&fileName=4+-+Land+Registry+and+Transfer.pdf

Document Heading: Supporting Documents
Document Name: 1 - Certificates of Status.pdf
Document Type: Certificate of Status
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=154625&fileName=1+-+Certificates+of+Status.pdf

Document Heading: Supporting Documents
Document Name: 7 - Table of Current-Past Uses-Plains Rd E.pdf
Document Type: Table of Current and Past Property Use
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=154615&fileName=7+-+Table+of+Current-Past+Uses-Plains+Rd+E.pdf

Document Heading: Supporting Documents
Document Name: Authorization.pdf
Document Type: Proof of the owner's authorization
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=157736&fileName=Authorization.pdf

Document Heading: Supporting Documents
Document Name: 6 - Table of APECs-Plains Rd E.pdf
Document Type: Area(s) of Potential Environmental Concern
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=154619&fileName=6+-+Table+of+APECs-Plains+Rd+E.pdf

Document Heading: Supporting Documents
Document Name: 5 - Plan of Survey.pdf
Document Type: A Current plan of Survey
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=154626&fileName=5+-+Plan+of+Survey.pdf

Document Heading: Supporting Documents
Document Name: PhaseTwo.pdf
Document Type: Phase 2 Conceptual Site Model
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=157735&fileName=PhaseTwo.pdf

---

30 | ***1 of 4*** | ***NW/109.5*** | ***99.8 / 0.00*** | ***1401 Plains Road East Burlington ON L7R 3P9*** | ***EHS***

Order No: 20070126016
Status: C
Report Type: CAN - Basic Report
Report Date: 2/6/2007
Date Received: 1/26/2007
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State:
Search Radius (km): 0.25
X: -79.818573
Y: 43.337138

---

30 | ***2 of 4*** | ***NW/109.5*** | ***99.8 / 0.00*** | ***Mississauga Motors Limited 1401 PLAINS RD E, BURLINGTON, ON, L7R 3P9*** | ***RSC***

BURLINGTON ON L7R 3P9

RSC ID:	45717	***Cert Date:***	27-May-08
RA No:		***Cert Prop Use No:***	No CPU
RSC Type:		***Intended Prop Use:***	Residential
Curr Property Use:	Commercial	***Qual Person Name:***	David W. Holland
Ministry District:	BURLINGTON	***Stratified (Y/N):***	
Filing Date:	23-Oct-08	***Audit (Y/N):***	
Date Ack:		***Entire Leg Prop. (Y/N):***	Yes
Date Returned:		***Accuracy Estimate:***	6 to 10 meters
Restoration Type:		***Telephone:***	905-2782886
Soil Type:		***Fax:***	905-2782885
Criteria:		***Email:***	hollandholdings@bellnet.ca
CPU Issued Sect 1686:	No		

Asmt Roll No: 2.40202E+14
Prop ID No (PIN): 07081-0247 (LT)
Property Municipal Address: 1401 PLAINS RD E, BURLINGTON, ON, L7R 3P9
Mailing Address: Suite 1, 360 REVUS RD, MISSISSAUGA, ON, L5G 4S4
Latitude & Latitude: 43.33705230N 79.81914720W (converted from UTM)
UTM Coordinates: NAD83 17-595722-4798922
Consultant:
Legal Desc: Part Lot 15, RCP Plan 99, as in 175832, 177986 & 180366 except Parts 2, 3 & 4, Plan 1309; Burlington
Measurement Method: Global Positioning System
Applicable Standards: Stratified Site Conditions Standard, with Nonpotable Ground Water, Medium/Fine Textured Soil, for Residential/Parkland/Institutional property use
RSC PDF:

---

30 ***3 of 4*** ***NW/109.5*** ***99.8 / 0.00*** ***Mississauga Motors Limited*** ***RSC***
1401 PLAINS RD E, BURLINGTON, ON, L7R 3P9
BURLINGTON ON L7R 3P9

RSC ID:	58115	***Cert Date:***	15-Jul-09
RA No:		***Cert Prop Use No:***	No CPU
RSC Type:		***Intended Prop Use:***	Residential
Curr Property Use:	Commercial	***Qual Person Name:***	David W. Holland
Ministry District:	BURLINGTON	***Stratified (Y/N):***	
Filing Date:	30-Jul-09	***Audit (Y/N):***	
Date Ack:		***Entire Leg Prop. (Y/N):***	Yes
Date Returned:		***Accuracy Estimate:***	6 to 10 meters
Restoration Type:		***Telephone:***	905-2782886
Soil Type:		***Fax:***	905-2782885
Criteria:		***Email:***	hollandholdings@bellnet.ca
CPU Issued Sect 1686:	No		

Asmt Roll No: 2.40202E+18
Prop ID No (PIN): 07081-0247 (LT)
Property Municipal Address: 1401 PLAINS RD E, BURLINGTON, ON, L7R 3P9
Mailing Address: Suite 1, 360 REVUS RD, MISSISSAUGA, ON, L5G 4S4
Latitude & Latitude: 43.33705230N 79.81914720W (converted from UTM)
UTM Coordinates: NAD83 17-595722-4798922
Consultant:
Legal Desc: Part Lot 15, RCP Plan 99, as in 175832, 177986 & 180366 except Parts 2, 3 & 4, Plan 1309; Burlington
Measurement Method: Global Positioning System
Applicable Standards: Stratified Site Conditions Standard, with Nonpotable Ground Water, Medium/Fine Textured Soil, for Residential/Parkland/Institutional property use
RSC PDF:

---

30 ***4 of 4*** ***NW/109.5*** ***99.8 / 0.00*** ***Holland Chev Olds*** ***GEN***
1401 Plains Road East
Burlington ON L7R 3P9

Generator No: ON2740338
SIC Code: 531310

SIC Description:	Real Estate Property Managers
Approval Years:	07,08
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	221
Waste Class Name:	LIGHT FUELS

---

31 **1 of 1** **NNW/112.4** **99.8 / 0.00** **ON** **BORE**

Borehole ID:	621547	**Inclin FLG:**	No
OGF ID:	215522001	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	MAR-1965	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.337238
Total Depth m:	4.5	**Longitude DD:**	-79.819113
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	595725
Drill Method:	Power auger	**Northing:**	4798943
Orig Ground Elev m:	100	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	100		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218421432	**Mat Consistency:**	Hard
Top Depth:	1.2	**Material Moisture:**	
Bottom Depth:	4.5	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Gravel	**Geologic Period:**	
Material 4:	Clay	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SAND,GRAVEL, CLAY. BROWN,GLACIAL,HARD, AGE GLACIAL. 0000700900040052 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218421431	**Mat Consistency:**	Loose
Top Depth:	.2	**Material Moisture:**	
Bottom Depth:	1.2	**Material Texture:**	Fine to Medium
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			

Stratum Description: SAND-FINE TO MEDIUM,SILT. BROWN,LOOSE,AGE GLACIAL.

Geology Stratum ID: 218421430
Top Depth: 0
Bottom Depth: .2
Material Color:
Material 1: Soil
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SOIL. AGE POST-GLACIAL.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: M
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: HAM.txt RecordID: 005460 NTS_Sheet: 30M05C
Confiden 1: Reliable information but incomplete.

Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

32 | **1 of 1** | **WSW/113.7** | **99.8 / 0.00** | **1335 Plains Road East Burlington ON** | **WWIS**

Well ID: 7338509
Construction Date:
Use 1st: Not Used
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: BFWDU8SR
Tag: _NO_TAG
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 12-Jun-2019 00:00:00
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7147
Form Version: 9
Owner:
County: HALTON
Lot:
Concession:
Concession Name: BB
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/733\7338509.pdf

Additional Detail(s) (Map)

Well Completed Date: 2019/05/17

Year Completed: 2019
Depth (m):
Latitude: 43.3352731645512
Longitude: -79.820378272689
Path: 733\7338509.pdf

Bore Hole Information

Bore Hole ID: 1007557500
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 17-May-2019 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 595625.00
North83: 4798723.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1007558187
Layer: 1
Color:
General Color:
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007558939
Layer: 1
Plug From: 0.0
Plug To: 4.599999904632568
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007558678
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Pipe Information

Pipe ID: 1007557846
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007558352
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.5
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1007558499
Layer: 1
Slot:
Screen Top Depth: 1.5
Screen End Depth: 4.599999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1007557847
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1007558013
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 1.7999999523162842
Water Found Depth UOM: m

Links

Bore Hole ID: 1007557500 ***Tag No:*** _NO_TAG
Depth M: ***Contractor:*** 7147

Year Completed:	2019	**Path:**	733\7338509.pdf
Well Completed Dt:	2019/05/17	**Latitude:**	43.3352731645512
Audit No:	BFWDU8SR	**Longitude:**	-79.820378272689

33 **1 of 1** **NE/114.8** **99.8 / 0.00** **ON** **WWIS**

Well ID:	7301199	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	11-Dec-2017 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	C39673	**Contractor:**	7215
Tag:	A238168	**Form Version:**	8
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	2017/11/21
Year Completed:	2017
Depth (m):	
Latitude:	43.3368356785179
Longitude:	-79.817350344183
Path:	

Bore Hole Information

Bore Hole ID:	1006870681	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595868.00
Code OB Desc:		**North83:**	4798900.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	21-Nov-2017 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	cnrev
Loc Method Desc:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1006870681	**Tag No:**	A238168
Depth M:		**Contractor:**	7215

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Year Completed:	2017	**Path:**	
Well Completed Dt:	2017/11/21	**Latitude:**	43.3368356785179
Audit No:	C39673	**Longitude:**	-79.817350344183

34 **1 of 1** **NE/115.0** **99.8 / 0.00** **1400 Plains Rd E**
Burlington ON L7R3P8 **EHS**

Order No:	20171006001	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Select Report	**Client Prov/State:**	ON
Report Date:	12-OCT-17	**Search Radius (km):**	.25
Date Received:	06-OCT-17	**X:**	-79.81779
Previous Site Name:		**Y:**	43.337047
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

35 **1 of 12** **NE/115.1** **99.8 / 0.00** **TARBOOSH RESTAURANT**
1400 PLANS ROAD EAST
BURLINGTON CITY ON **CA**

Certificate #:	8-3558-96-
Application Year:	96
Issue Date:	12/24/1996
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	COMMERCIAL KITCHEN EXHAUST HOOD
Contaminants:	Suspended Particulate Matter, Odour/Fumes
Emission Control:	Centri. And/Or Cycl. Scr., No Controls,

35 **2 of 12** **NE/115.1** **99.8 / 0.00** **1390-1400 Plains Rd E**
Burlington ON L7R 3P8 **EHS**

Order No:	20060317001	**Nearest Intersection:**	Plains Rd E. & Brant St
Status:	C	**Municipality:**	
Report Type:	Complete Report	**Client Prov/State:**	ON
Report Date:	3/27/2006	**Search Radius (km):**	0.25
Date Received:	3/17/2006	**X:**	-79.818394
Previous Site Name:		**Y:**	43.336677
Lot/Building Size:			
Additional Info Ordered:			

35 **3 of 12** **NE/115.1** **99.8 / 0.00** **CES Graphic Supplies Inc.**
1400 Plains Rd E
Burlington ON L7R 3P8 **SCT**

Established:	7/1/1996
Plant Size (ft²):	3000
Employment:	

--Details--

Description:	Office and Store Machinery and Equipment Wholesaler-Distributors
SIC/NAICS Code:	417910
Description:	Commercial Screen Printing

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC/NAICS Code: 323113

---

35 ***4 of 12*** ***NE/115.1*** ***99.8 / 0.00*** ***Stone Gate Properties Inc.*** ***GEN***
1400 Plains Road East
Burlington ON L7R 3P8

Generator No: ON6982753
SIC Code: 531310
SIC Description: Real Estate Property Managers
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 150
Waste Class Name: INERT INORGANIC WASTES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

35 ***5 of 12*** ***NE/115.1*** ***99.8 / 0.00*** ***1400 Plains Road East*** ***EHS***
Burlington ON L7R 3P8

Order No: 20120130039
Status: C
Report Type: Custom Report
Report Date: 2/8/2012
Date Received: 1/30/2012 7:13:44 PM
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: City Directory

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.818278
Y: 43.336806

---

35 ***6 of 12*** ***NE/115.1*** ***99.8 / 0.00*** ***Stone Gate Properties Inc.*** ***GEN***
1400 Plains Road East
Burlington ON L7R 3P8

Generator No: ON6982753
SIC Code: 531310
SIC Description: Real Estate Property Managers
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 150
Waste Class Name: INERT INORGANIC WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

35 **7 of 12** **NE/115.1** **99.8 / 0.00** **Stone Gate Properties Inc.**
1400 Plains Road East
Burlington ON L7R 3P8
GEN

Generator No: ON6982753
SIC Code: 531310
SIC Description: Real Estate Property Managers
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 150
Waste Class Name: INERT INORGANIC WASTES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

35 **8 of 12** **NE/115.1** **99.8 / 0.00** **Stone Gate Properties Inc.**
1400 Plains Road East
Burlington ON
GEN

Generator No: ON6982753
SIC Code: 531310
SIC Description: REAL ESTATE PROPERTY MANAGERS
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 150
Waste Class Name: INERT INORGANIC WASTES

---

35 **9 of 12** **NE/115.1** **99.8 / 0.00** **Stone Gate Properties Inc.**
1400 Plains Road
Burlington ON L7R 3P8
GEN

Generator No: ON8669967
SIC Code: 531310
SIC Description: REAL ESTATE PROPERTY MANAGERS
Approval Years: 2016

PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

35 ***10 of 12*** ***NE/115.1*** ***99.8 / 0.00*** ***Stone Gate Properties Inc.***
1400 Plains Road East
Burlington ON L7R 3P8 ***GEN***

Generator No: ON6982753
SIC Code: 531310
SIC Description: REAL ESTATE PROPERTY MANAGERS
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 150
Waste Class Name: INERT INORGANIC WASTES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

35 ***11 of 12*** ***NE/115.1*** ***99.8 / 0.00*** ***1400 Plains Road East***
Burlington ON ***WWIS***

Well ID: 7385081
Construction Date:
Use 1st: Test Hole
Use 2nd:
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: H727WQDX
Tag: A316893
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 09-Apr-2021 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7320
Form Version: 9
Owner:
County: HALTON
Lot:
Concession:
Concession Name: BB
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	1008607307	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	595878.00
Code OB Desc:		***North83:***	4798956.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	05-Apr-2021 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1008607401
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Mat2 Desc:	SAND
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.9100000262260437
Formation End Depth:	1.5199999809265137
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1008607402
Layer:	3
Color:	7
General Color:	RED
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Mat2 Desc:	CLAY
Mat3:	34
Mat3 Desc:	TILL
Formation Top Depth:	1.5199999809265137
Formation End Depth:	3.9600000381469727
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1008607400
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND

Mat2: 11
Mat2 Desc: GRAVEL
Mat3: 01
Mat3 Desc: FILL
Formation Top Depth: 0.0
Formation End Depth: 0.9100000262260437
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008607490
Layer: 1
Plug From: 0.0
Plug To: 0.15000000596046448
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008607463
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008607492
Layer: 3
Plug From: 0.7599999904632568
Plug To: 3.9600000381469727
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008607491
Layer: 2
Plug From: 0.15000000596046448
Plug To: 0.7599999904632568
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1008607356
Method Construction Code: E
Method Construction: Auger
Other Method Construction:

Pipe Information

Pipe ID: 1008607339
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008607423
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 0.9100000262260437
Casing Diameter: 5.099999904632568
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1008607430
Layer: 1
Slot: 010
Screen Top Depth: 0.9100000262260437
Screen End Depth: 3.9600000381469727
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.099999904632568

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008607340
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1008607448
Diameter: 16.0
Depth From: 0.30000001192092896
Depth To: 3.9600000381469727
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1008607447
Diameter: 21.0
Depth From: 0.0
Depth To: 0.30000001192092896
Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Bore Hole ID:	1008607307	**Tag No:**	A316893
Depth M:	3.96	**Contractor:**	7320
Year Completed:	2021	**Path:**	738\7385081.pdf
Well Completed Dt:	2021/04/05	**Latitude:**	43.3373385505913
Audit No:	H727WQDX	**Longitude:**	-79.8172172211097

35 | **12 of 12** | **NE/115.1** | **99.8 / 0.00** | **1400 Plains Road East Burlington ON** | **WWIS**

Well ID:	7385082	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Test Hole	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	09-Apr-2021 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	OSW3QRMD	**Contractor:**	7320
Tag:	A316892	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	BB
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008607310	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595928.00
Code OB Desc:		**North83:**	4798989.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	05-Apr-2021 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1008607406
Layer:	4
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Mat2 Desc:	SAND
Mat3:	
Mat3 Desc:	

Formation Top Depth: 1.8300000429153442
Formation End Depth: 2.440000057220459
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1008607403
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Mat2 Desc: GRAVEL
Mat3: 01
Mat3 Desc: FILL
Formation Top Depth: 0.0
Formation End Depth: 0.9100000262260437
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1008607407
Layer: 5
Color: 7
General Color: RED
Mat1: 06
Most Common Material: SILT
Mat2: 05
Mat2 Desc: CLAY
Mat3: 34
Mat3 Desc: TILL
Formation Top Depth: 2.440000057220459
Formation End Depth: 3.9600000381469727
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1008607405
Layer: 3
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 1.2200000286102295
Formation End Depth: 1.8300000429153442
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1008607404
Layer: 2
Color: 6
General Color: BROWN

Mat1: 28
Most Common Material: SAND
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.9100000262260437
Formation End Depth: 1.2200000286102295
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008607464
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008607493
Layer: 1
Plug From: 0.0
Plug To: 0.15000000596046448
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008607494
Layer: 2
Plug From: 0.15000000596046448
Plug To: 0.7599999904632568
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008607495
Layer: 3
Plug From: 0.7599999904632568
Plug To: 3.9600000381469727
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1008607357
Method Construction Code: E
Method Construction: Auger
Other Method Construction:

Pipe Information

Pipe ID: 1008607341
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1008607424
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	0.9100000262260437
Casing Diameter:	5.099999904632568
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1008607431
Layer:	1
Slot:	010
Screen Top Depth:	0.9100000262260437
Screen End Depth:	3.9600000381469727
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.099999904632568

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008607342
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1008607449
Diameter:	21.0
Depth From:	0.0
Depth To:	3.9600000381469727
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	1008607310	***Tag No:***	A316892
Depth M:	3.96	***Contractor:***	7320
Year Completed:	2021	***Path:***	738\7385082.pdf
Well Completed Dt:	2021/04/05	***Latitude:***	43.337629257697
Audit No:	OSW3QRMD	***Longitude:***	-79.8165947634746

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
36	1 of 2	WSW/117.3	99.8 / 0.00	1335, 1343, 1349 and 1355 Plains Road East, Burlington Burlington ON L7R 3P7	EHS

Order No:	20200609137	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	12-JUN-20	**Search Radius (km):**	.25
Date Received:	09-JUN-20	**X:**	-79.82053484
Previous Site Name:		**Y:**	43.3354495
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
36	2 of 2	WSW/117.3	99.8 / 0.00	1335, 1343, 1349 and 1355 Plains Road East, Burlington Burlington ON L7R 3P7	EHS

Order No:	20200609137	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	12-JUN-20	**Search Radius (km):**	.25
Date Received:	09-JUN-20	**X:**	-79.82053484
Previous Site Name:		**Y:**	43.3354495
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
37	1 of 1	WSW/122.4	99.8 / 0.00	1335-1349 Plains Rd E, Burlington Burlington ON	EHS

Order No:	20160808091	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	RSC Report (Urban)	**Client Prov/State:**	ON
Report Date:	15-AUG-16	**Search Radius (km):**	.3
Date Received:	08-AUG-16	**X:**	-79.820807
Previous Site Name:		**Y:**	43.335598
Lot/Building Size:			
Additional Info Ordered:	Aerial Photos		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	1 of 1	WSW/124.1	99.8 / 0.00	1335 Plains Road East Burlington ON	WWIS

Well ID:	7360647	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	10-Jun-2020 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	SV5N5NXW	**Contractor:**	7147
Tag:	A289548	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2020/05/14
Year Completed: 2020
Depth (m): 4.6
Latitude: 43.3354738941059
Longitude: -79.8206334395732
Path:

Bore Hole Information

Bore Hole ID: 1008307492
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 14-May-2020 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 595604.00
North83: 4798745.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1008308182
Layer: 3
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2: 05
Mat2 Desc: CLAY
Mat3:
Mat3 Desc:
Formation Top Depth: 2.700000047683716
Formation End Depth: 4.599999904632568
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1008308180
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 06
Mat2 Desc: SILT
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0

Formation End Depth: 1.5
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1008308181
Layer: 2
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 05
Mat2 Desc: CLAY
Mat3:
Mat3 Desc:
Formation Top Depth: 1.5
Formation End Depth: 2.700000047683716
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008308810
Layer: 3
Plug From: 1.2000000476837158
Plug To: 4.599999904632568
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008308676
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008308808
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008308809
Layer: 2
Plug From: 0.30000001192092896
Plug To: 1.2000000476837158
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1008307922
Method Construction Code: E

Method Construction: Auger
Other Method Construction:

Pipe Information

Pipe ID: 1008307756
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008308394
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.5
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1008308484
Layer: 1
Slot: 10
Screen Top Depth: 1.5
Screen End Depth: 4.599999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008307757
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1008308098
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 3.0999999046325684
Water Found Depth UOM: m

Hole Diameter

Hole ID:	1008308565
Diameter:	11.399999618530273
Depth From:	0.0
Depth To:	4.599999904632568
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	1008307492	***Tag No:***	A289548
Depth M:	4.6	***Contractor:***	7147
Year Completed:	2020	***Path:***	736\7360647.pdf
Well Completed Dt:	2020/05/14	***Latitude:***	43.3354738941059
Audit No:	SV5N5NXW	***Longitude:***	-79.8206334395732

39 ***1 of 1*** ***SW/124.4*** ***99.8 / 0.00*** ***2201 PLAINS RD E BURLINGTON ON*** ***WWIS***

Well ID:	2810057	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	
Use 2nd:		***Data Src:***	1
Final Well Status:	Observation Wells	***Date Received:***	23-Sep-2004 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z11844	***Contractor:***	6607
Tag:	A007529	***Form Version:***	3
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	HALTON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	BB
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	2004/04/29
Year Completed:	2004
Depth (m):	6
Latitude:	43.3348828698348
Longitude:	-79.8200774351137
Path:	

Bore Hole Information

Bore Hole ID:	11174674	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	595650.00
Code OB Desc:		***North83:***	4798680.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	3

Date Completed: 29-Apr-2004 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 932974909
Layer: 1
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 05
Mat2 Desc: CLAY
Mat3: 01
Mat3 Desc: FILL
Formation Top Depth: 0.0
Formation End Depth: 1.5
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 932974910
Layer: 2
Color: 7
General Color: RED
Mat1: 17
Most Common Material: SHALE
Mat2: 15
Mat2 Desc: LIMESTONE
Mat3: 73
Mat3 Desc: HARD
Formation Top Depth: 1.5
Formation End Depth: 6.0
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933255917
Layer: 1
Plug From: 0.0
Plug To: 2.700000047683716
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933255918
Layer: 2
Plug From: 2.700000047683716
Plug To: 6.0
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 962810057
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 11183193
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930845980
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933409574
Layer: 1
Slot: 10
Screen Top Depth: 3.0
Screen End Depth: 6.0
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.110000133514404

Water Details

Water ID: 934052443
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 3.0
Water Found Depth UOM: m

Hole Diameter

Hole ID: 11308274
Diameter: 15.0
Depth From: 0.0
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Bore Hole ID: 11174674 ***Tag No:*** A007529
Depth M: 6 ***Contractor:*** 6607

Year Completed:	2004	**Path:**	
Well Completed Dt:	2004/04/29	**Latitude:**	43.3348828698348
Audit No:	Z11844	**Longitude:**	-79.8200774351137

40 **1 of 1** **NE/129.3** **99.8 / 0.00** **ON** **WWIS**

Well ID:	7164921	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	06-Jul-2011 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z120157	**Contractor:**	7295
Tag:	A113792	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/716\7164921.pdf

Additional Detail(s) (Map)

Well Completed Date:	2011/01/31
Year Completed:	2011
Depth (m):	4.572
Latitude:	43.3371912447255
Longitude:	-79.8177752095179
Path:	716\7164921.pdf

Bore Hole Information

Bore Hole ID:	1003529350	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595833.00
Code OB Desc:		**North83:**	4798939.00
Open Hole:		**Org CS:**	dms83
Cluster Kind:		**UTMRC:**	6
Date Completed:	31-Jan-2011 00:00:00	**UTMRC Desc:**	margin of error : 300 m - 1 km
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID: 1003835582

Layer: 3
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3: 66
Mat3 Desc: DENSE
Formation Top Depth: 6.0
Formation End Depth: 9.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1003835583
Layer: 4
Color: 7
General Color: RED
Mat1: 17
Most Common Material: SHALE
Mat2:
Mat2 Desc:
Mat3: 73
Mat3 Desc: HARD
Formation Top Depth: 9.0
Formation End Depth: 15.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1003835581
Layer: 2
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2:
Mat2 Desc:
Mat3: 80
Mat3 Desc: POROUS
Formation Top Depth: 2.0
Formation End Depth: 6.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1003835580
Layer: 1
Color: 6
General Color: BROWN
Mat1: 11
Most Common Material: GRAVEL
Mat2: 28
Mat2 Desc: SAND
Mat3: 79
Mat3 Desc: PACKED
Formation Top Depth: 0.0
Formation End Depth: 2.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003835591
Layer:	1
Plug From:	0.5
Plug To:	
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1003835589
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	

Pipe Information

Pipe ID:	1003835579
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1003835586
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	5.0
Casing Diameter:	1.7999999523162842
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1003835587
Layer:	1
Slot:	10
Screen Top Depth:	5.0
Screen End Depth:	15.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.0

Water Details

Water ID:	1003835585
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1003835584
Diameter:	6.0
Depth From:	0.0
Depth To:	15.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1003529350	**Tag No:**	A113792
Depth M:	4.572	**Contractor:**	7295
Year Completed:	2011	**Path:**	716\7164921.pdf
Well Completed Dt:	2011/01/31	**Latitude:**	43.3371912447255
Audit No:	Z120157	**Longitude:**	-79.8177752095179

41 ***1 of 1*** ***WSW/134.1*** ***99.5 / -0.37*** ***1335 Plains Road East Burlington ON*** ***WWIS***

Well ID:	7338463	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Not Used	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	12-Jun-2019 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	PPSWIO3A	**Contractor:**	7147
Tag:	A249412	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	BB
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/733\7338463.pdf

Additional Detail(s) (Map)

Well Completed Date:	2019/05/17
Year Completed:	2019
Depth (m):	
Latitude:	43.335357622773
Longitude:	-79.8207097049615
Path:	733\7338463.pdf

Bore Hole Information

Bore Hole ID:	1007557362	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595598.00
Code OB Desc:		**North83:**	4798732.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	17-May-2019 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1007558132
Layer: 1
Color:
General Color:
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007558632
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007558865
Layer: 1
Plug From: 0.0
Plug To: 3.0999999046325684
Plug Depth UOM: m

Pipe Information

Pipe ID: 1007557754
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007558306
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.5
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID:	1007558453
Layer:	1
Slot:	
Screen Top Depth:	1.5
Screen End Depth:	3.0999999046325684
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1007557755
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1007557985
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	0.8999999761581421
Water Found Depth UOM:	m

Links

Bore Hole ID:	1007557362	***Tag No:***	A249412
Depth M:		***Contractor:***	7147
Year Completed:	2019	***Path:***	733\7338463.pdf
Well Completed Dt:	2019/05/17	***Latitude:***	43.335357622773
Audit No:	PPSWIO3A	***Longitude:***	-79.8207097049615

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	1 of 1	SW/135.6	99.8 / 0.00	HAMILTON, CORP. OF THE CITY OF 1282 PLAINS RD. MOTOR VEHICLE (OPERATING FLUID) BURLINGTON CITY ON	SPL

Ref No:	153050	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	3/6/1998	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	UNKNOWN	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	

Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	POSSIBLE	**Site Municipality:**	14101
Nature of Impact:	Soil contamination	**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	3/6/1998	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	UNKNOWN	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	CITY OF HAMILTON - UNK QUAN HYDRAULIC OIL TO GRAVEL.		
Contaminant Qty:			

43 **1 of 1** **WSW/137.2** **99.5 / -0.38** **1335 Plains Road East Burlington ON** **WWIS**

Well ID:	7338511	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Not Used	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	12-Jun-2019 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	ZNJ3F94V	**Contractor:**	7147
Tag:	_NO_TAG	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	BB
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/733\7338511.pdf

Additional Detail(s) (Map)

Well Completed Date:	2019/05/17
Year Completed:	2019
Depth (m):	
Latitude:	43.3351949391517
Longitude:	-79.8206511745135
Path:	733\7338511.pdf

Bore Hole Information

Bore Hole ID:	1007557506	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595603.00
Code OB Desc:		**North83:**	4798714.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4

Date Completed: 17-May-2019 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1007558189
Layer: 1
Color:
General Color:
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007558680
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007558941
Layer: 1
Plug From: 0.0
Plug To: 4.599999904632568
Plug Depth UOM: m

Pipe Information

Pipe ID: 1007557850
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007558354
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.5
Casing Diameter: 5.0
Casing Diameter UOM: cm

Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1007558501
Layer: 1
Slot:
Screen Top Depth: 1.5
Screen End Depth: 4.599999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1007557851
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1007558015
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 1.2000000476837158
Water Found Depth UOM: m

Links

Bore Hole ID: 1007557506
Depth M:
Year Completed: 2019
Well Completed Dt: 2019/05/17
Audit No: ZNJ3F94V
Tag No: _NO_TAG
Contractor: 7147
Path: 733\7338511.pdf
Latitude: 43.3351949391517
Longitude: -79.8206511745135

---

44 ***1 of 1*** ***NE/140.0*** ***99.8 / 0.00*** ***ON*** ***BORE***

Borehole ID: 623361
OGF ID: 215523813
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: APR-1967
Static Water Level:
Primary Water Use: Not Used
Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:

Sec. Water Use:		***Latitude DD:***	43.33713
Total Depth m:	4.9	***Longitude DD:***	-79.817388
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	595865
Drill Method:	Diamond Drill	***Northing:***	4798933
Orig Ground Elev m:	100	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	100		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218429215	***Mat Consistency:***	Soft
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	1.7	***Material Texture:***	
Material Color:	Black	***Non Geo Mat Type:***	
Material 1:	Fill	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:	Sand	***Geologic Period:***	
Material 4:	Slag	***Depositional Gen:***	fill
Gsc Material Description:			
Stratum Description:	FILL,CLAY,SAND,SLAG.BLACK,MAN-MADE,SOFT, AGE POST-GLACIAL.		

Geology Stratum ID:	218429217	***Mat Consistency:***	Hard
Top Depth:	2.4	***Material Moisture:***	
Bottom Depth:	4.9	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:	Silt	***Geologic Period:***	
Material 4:	Stones	***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY,SILT, STONES. BROWN,GLACIAL,HARD, AGE GLACIAL. 00000008000550360008018000015 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218429216	***Mat Consistency:***	Hard
Top Depth:	1.7	***Material Moisture:***	
Bottom Depth:	2.4	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Fill	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:	Silt	***Geologic Period:***	
Material 4:	Stones	***Depositional Gen:***	fill
Gsc Material Description:			
Stratum Description:	FILL,CLAY,SILT, STONES. BROWN,MAN-MADE,HARD, AGE POST-GLACIAL.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	M	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: HAM.txt RecordID: 023610 NTS_Sheet: 30M05C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

45 **1 of 1** **WSW/146.0** **98.8 / -1.00** **1335 Plains Road East Burlington ON** **WWIS**

Well ID:	7338514	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Not Used	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	12-Jun-2019 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	JJQ2W8AH	**Contractor:**	7147
Tag:	_NO_TAG	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	BB
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/733\7338514.pdf

Additional Detail(s) (Map)

Well Completed Date:	2019/05/17
Year Completed:	2019
Depth (m):	
Latitude:	43.3352958759673
Longitude:	-79.8208342581286
Path:	733\7338514.pdf

Bore Hole Information

Bore Hole ID:	1007557515	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595588.00
Code OB Desc:		**North83:**	4798725.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	17-May-2019 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID: 1007558192
Layer: 1
Color:
General Color:
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007558683
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007558944
Layer: 1
Plug From: 0.0
Plug To: 4.599999904632568
Plug Depth UOM: m

Pipe Information

Pipe ID: 1007557856
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007558357
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.5
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1007558504
Layer: 1
Slot:
Screen Top Depth: 1.5
Screen End Depth: 4.599999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm

Screen Diameter: 6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1007557857
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1007558018
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 1.2000000476837158
Water Found Depth UOM: m

Links

Bore Hole ID: 1007557515
Depth M:
Year Completed: 2019
Well Completed Dt: 2019/05/17
Audit No: JJQ2W8AH
Tag No: _NO_TAG
Contractor: 7147
Path: 733\7338514.pdf
Latitude: 43.3352958759673
Longitude: -79.8208342581286

---

46 ***1 of 1*** ***WSW/147.6*** ***99.1 / -0.70***

DVLP Property Group Inc.
1335 Plains Road East
Burlington ON L7R 3P7

GEN

Generator No: ON5434980
SIC Code:
SIC Description:
Approval Years: As of Oct 2019
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
47	1 of 2	E/152.0	101.0 / 1.11	Lakeshore West - Beach Layover Burlington ON L7S 1W6	EHS

Order No:	20191025022	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	30-OCT-19	**Search Radius (km):**	.25
Date Received:	25-OCT-19	**X:**	-79.816381
Previous Site Name:		**Y:**	43.335902
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
47	2 of 2	E/152.0	101.0 / 1.11	Lakeshore West - Beach Layover Burlington ON L7S 1W6	EHS

Order No:	20191025022	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	30-OCT-19	**Search Radius (km):**	.25
Date Received:	25-OCT-19	**X:**	-79.816381
Previous Site Name:		**Y:**	43.335902
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
48	1 of 1	ENE/155.9	99.8 / 0.00	ON	BORE

Borehole ID:	623362	**Inclin FLG:**	No
OGF ID:	215523814	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	APR-1967	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.337035
Total Depth m:	2.3	**Longitude DD:**	-79.816896
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	595905
Drill Method:	Diamond Drill	**Northing:**	4798923
Orig Ground Elev m:	100	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	99.9		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218429218	**Mat Consistency:**	Soft
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	1.1	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,CLAY,SAND. BROWN,MAN-MADE,SOFT, AGE POST-GLACIAL.		

Geology Stratum ID:	218429219	**Mat Consistency:**	Hard

Top Depth:	1.1	**Material Moisture:**	
Bottom Depth:	2.3	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Stones	**Depositional Gen:**	glacial

Gsc Material Description:

Stratum Description: TILL,CLAY,SILT, STONES. BROWN,GLACIAL,HARD, AGE GLACIAL. 0003507400023 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: HAM.txt RecordID: 023620 NTS_Sheet: 30M05C
Confiden 1: Reliable information but incomplete.

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		

Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

49 | ***1 of 1*** | ***WSW/173.2*** | ***99.8 / 0.00*** | ***1325 PLAINS RD. E BURLINGTON ON*** | ***WWIS***

Well ID:	7251866	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	10-Nov-2015 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	Z204810	**Contractor:**	7295
Tag:		**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: BURLINGTON CITY
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/725\7251866.pdf

Additional Detail(s) (Map)

Well Completed Date: 2015/05/26
Year Completed: 2015
Depth (m):

Latitude:	43.3348096056551
Longitude:	-79.8208313324173
Path:	725\7251866.pdf

Bore Hole Information

Bore Hole ID:	1005793606	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595589.00
Code OB Desc:		**North83:**	4798671.00
Open Hole:		**Org CS:**	dms83
Cluster Kind:		**UTMRC:**	4
Date Completed:	26-May-2015 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1005825187
Layer:	1
Plug From:	0.0
Plug To:	28.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005825186
Layer:	1
Plug From:	0.0
Plug To:	28.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1005825185
Method Construction Code:	
Method Construction:	
Other Method Construction:	

Pipe Information

Pipe ID:	1005825178
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005825182
Layer:	1
Material:	5

Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	
Casing Diameter:	1.7999999523162842
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1005825183
Layer:	1
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.0

Water Details

Water ID:	1005825181
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1005825180
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1005793606	**Tag No:**	
Depth M:		**Contractor:**	7295
Year Completed:	2015	**Path:**	725\7251866.pdf
Well Completed Dt:	2015/05/26	**Latitude:**	43.3348096056551
Audit No:	Z204810	**Longitude:**	-79.8208313324173

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	1 of 1	N/173.2	99.8 / 0.00	UNKNOWN 1417 PLAINS RD E BURLINGTON CITY ON L7R 3P9	SPL

Ref No:	211031	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	9/6/2001	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	UNKNOWN	**Sector Type:**	
Incident Event:		**Agency Involved:**	HEALTH UNIT
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Possible	**Site Municipality:**	14101
Nature of Impact:	Multi Media Pollution	**Site Lot:**	

Receiving Medium:	Land, Air	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	9/8/2001	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	UNKNOWN	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	UKN SOURCE OF BLACK SOOT - FALLOUT OVER NEIGHBOUR-HOOD. H/U TAKEN SAMPLES		
Contaminant Qty:			

51	1 of 1	E/181.9	99.8 / 0.00	**PIN# 45393** **Burlington ON**	EHS

Order No:	19990426003	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	5/3/99	**Search Radius (km):**	0.35
Date Received:	4/26/99	**X:**	-79.816046
Previous Site Name:		**Y:**	43.336353
Lot/Building Size:			
Additional Info Ordered:			

52	1 of 2	WSW/184.4	99.2 / -0.65	**HABITAT FOR HUMANITY HALTON** **1325 PLAINS ROAD EAST, BURLINGTON, ON L7R 3P7** **Burlington ON**	RSC

RSC ID:	214226	**Cert Date:**	
RA No:		**Cert Prop Use No:**	
RSC Type:	Phase 1 RSC	**Intended Prop Use:**	Residential
Curr Property Use:	Commercial	**Qual Person Name:**	JOHN MONKMAN
Ministry District:	Halton-Peel District Office	**Stratified (Y/N):**	
Filing Date:	2014/07/24	**Audit (Y/N):**	
Date Ack:		**Entire Leg Prop. (Y/N):**	
Date Returned:		**Accuracy Estimate:**	
Restoration Type:		**Telephone:**	
Soil Type:		**Fax:**	
Criteria:		**Email:**	
CPU Issued Sect 1686:			

Asmt Roll No:	2402020207094000000
Prop ID No (PIN):	07081-0234 (LT)
Property Municipal Address:	1325 PLAINS ROAD EAST, BURLINGTON, ON L7R 3P7
Mailing Address:	
Latitude & Latitude:	
UTM Coordinates:	
Consultant:	
Legal Desc:	
Measurement Method:	
Applicable Standards:	
RSC PDF:	https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=37541&fileName=BROWNFIELDS-E.pdf

Document(s) Detail

Document Heading:	Supporting Documents
Document Name:	CertofStatus.pdf
Document Type:	Certificate of Status

Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=37542&fileName=CertofStatus.pdf

Document Heading: Supporting Documents
Document Name: LawyersLetter.pdf
Document Type: Lawyer's letter consisting of a legal description of the property
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=37547&fileName=LawyersLetter.pdf

Document Heading: Supporting Documents
Document Name: PlanofSurvey.pdf
Document Type: A Current plan of Survey
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=37543&fileName=PlanofSurvey.pdf

Document Heading: Supporting Documents
Document Name: PhaseOneCSM.pdf
Document Type: Phase 1 Conceptual Site Model
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=37549&fileName=PhaseOneCSM.pdf

Document Heading: Supporting Documents
Document Name: TableofCandPUses.pdf
Document Type: Table of Current and Past Property Use
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=37544&fileName=TableofCandPUses.pdf

Document Heading: Supporting Documents
Document Name: TransferDeed.pdf
Document Type: Copy of any deed(s), transfer(s) or other document(s)
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=37548&fileName=TransferDeed.pdf

---

52 **2 of 2** **WSW/184.4** **99.2 / -0.65** **1325 Plains Rd E Burlington ON** **EHS**

Order No:	20131219006	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	RSC Report (Rural)	**Client Prov/State:**	ON
Report Date:	02-JAN-14	**Search Radius (km):**	.3
Date Received:	19-DEC-13	**X:**	-79.821025
Previous Site Name:		**Y:**	43.334762
Lot/Building Size:	Approximately 0.075 hectares		
Additional Info Ordered:			

---

53 **1 of 1** **NE/187.2** **99.8 / 0.00** **ON** **WWIS**

Well ID:	7204013	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	28-Jun-2013 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	C22800	**Contractor:**	7215
Tag:	A144975	**Form Version:**	8
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	

Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2013/06/13
Year Completed: 2013
Depth (m):
Latitude: 43.3375178378938
Longitude: -79.8171397231199
Path:

Bore Hole Information

Bore Hole ID: 1004383798
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 13-Jun-2013 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 595884.00
North83: 4798976.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Links

Bore Hole ID: 1004383798
Depth M:
Year Completed: 2013
Well Completed Dt: 2013/06/13
Audit No: C22800

Tag No: A144975
Contractor: 7215
Path:
Latitude: 43.3375178378938
Longitude: -79.8171397231199

---

54 ***1 of 1*** ***ENE/191.3*** ***99.8 / 0.00*** ***ON*** ***BORE***

Borehole ID: 622142
OGF ID: 215522596
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: SEP-1965
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 11.5
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Diamond Drill
Orig Ground Elev m: 99.8
Elev Reliabil Note:
DEM Ground Elev m: 99.5

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.337211
Longitude DD: -79.816522
UTM Zone: 17
Easting: 595935
Northing: 4798943
Location Accuracy:
Accuracy: Not Applicable

Concession:
Location D:
Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID: 218424577
Top Depth: 0
Bottom Depth: .5
Material Color:
Material 1: Soil
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SOIL. MAN-MADE,AGE POST-GLACIAL.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218424580
Top Depth: 6.7
Bottom Depth: 7.3
Material Color: Brown
Material 1: Sand
Material 2: Silt
Material 3: Gravel
Material 4:
Gsc Material Description:
Stratum Description: SAND(32),SILT(34), GRAVEL(17). BROWN,HARD,AGE GLACIAL.

Mat Consistency: Hard
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Geology Stratum ID: 218424579
Top Depth: 2.1
Bottom Depth: 6.7
Material Color: Brown
Material 1: Till
Material 2: Sand
Material 3: Clay
Material 4: Gravel
Gsc Material Description:
Stratum Description: TILL,SAND,CLAY, GRAVEL. BROWN,GLACIAL,HARD, AGE GLACIAL.

Mat Consistency: Hard
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Geology Stratum ID: 218424578
Top Depth: .5
Bottom Depth: 2.1
Material Color: Brown
Material 1: Fill
Material 2: Sand
Material 3: Clay
Material 4:
Gsc Material Description:
Stratum Description: FILL,SAND,CLAY. BROWN,MAN-MADE,LOOSE, AGE POST-GLACIAL.

Mat Consistency: Loose
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: fill

Geology Stratum ID: 218424581
Top Depth: 7.3
Bottom Depth: 11.5
Material Color: Red
Material 1: Bedrock
Material 2: Shale
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: BEDROCK,SHALE. RED,VERY HARD, AGE UNDIFFERENTIATED.
00000016000150120007012500238999000 54 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency: Hard
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	H	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: HAM.txt RecordID: 011420 NTS_Sheet: 30M05C
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		

Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

55 | ***1 of 1*** | ***NW/193.0*** | ***99.8 / 0.00*** | ***WYATT ART POTTERY***
1390 LEIGHLAND RD
BURLINGTON ON L7R 3S8 | ***SCT***

Established: 1948
Plant Size (ft²): 4000
Employment: 2

--Details--
Description: POTTERY PRODUCTS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3269

Description: HOMEFURNISHINGS
SIC/NAICS Code: 5023

Description: NONDURABLE GOODS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 5199

Description: Pottery, Ceramics and Plumbing Fixture Manufacturing
SIC/NAICS Code: 327110

---

56 | ***1 of 9*** | ***NNE/197.2*** | ***99.8 / 0.00*** | ***Canadian Tire Corporation, limited***
1435 Plains Road East
Burlington ON L7R 3P9 | ***GEN***

Generator No: ON3881175
SIC Code: 415290
SIC Description: OTHER NEW MOTOR VEHICLE PARTS AND ACCESSORIES WHOLESALER-DISTRIBUTORS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Ryan lawson
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905 Ext.637-4
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 263

Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

---

56 **2 of 9** **NNE/197.2** **99.8 / 0.00** **Canadian Tire Corporation, limited**
1435 Plains Road East
Burlington ON L7R 3P9
GEN

Generator No: ON3881175
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 232 I
Waste Class Name: Polymeric resins

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

---

56 **3 of 9** **NNE/197.2** **99.8 / 0.00** **Tawse Realco Inc.**
1435 Plains Road East
Burlington ON L7R 3P9
GEN

Generator No: ON3400970
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	4 of 9	NNE/197.2	99.8 / 0.00	Canadian Tire Corporation, limited 1435 Plains Road East Burlington ON L7R 3P9	GEN

Generator No: ON3881175
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 232 I
Waste Class Name: Polymeric resins

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	5 of 9	NNE/197.2	99.8 / 0.00	Tawse Realco Inc. 1435 Plains Road East Burlington ON L7R 3P9	GEN

Generator No: ON3400970
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	6 of 9	NNE/197.2	99.8 / 0.00	Tawse Realco Inc. 1435 Plains Road East Burlington ON L7R 3P9	GEN

Generator No: ON3400970
SIC Code:
SIC Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

---

56 ***7 of 9*** ***NNE/197.2*** ***99.8 / 0.00*** ***Canadian Tire Corporation, limited***
1435 Plains Road East
Burlington ON L7R 3P9 ***GEN***

Generator No: ON3881175
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 232 I
Waste Class Name: Polymeric resins

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

---

56 ***8 of 9*** ***NNE/197.2*** ***99.8 / 0.00*** ***Canadian Tire Corporation, limited***
1435 Plains Road East
Burlington ON L7R 3P9 ***GEN***

Generator No: ON3881175
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 267 C
Waste Class Name: ORGANIC ACIDS

Waste Class: 232 I
Waste Class Name: POLYMERIC RESINS

Waste Class: 263 I
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 122 C
Waste Class Name: ALKALINE WASTES - OTHER METALS

---

56 ***9 of 9*** ***NNE/197.2*** ***99.8 / 0.00*** ***Tawse Realco Inc.***
1435 Plains Road East
Burlington ON L7R 3P9 ***GEN***

Generator No: ON3400970
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

57 ***1 of 1*** ***WSW/202.8*** ***99.2 / -0.68*** ***ON*** ***BORE***

Borehole ID:	621051	***Inclin FLG:***	No
OGF ID:	215521505	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	SEP-1965	***Municipality:***	
Static Water Level:		***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.334556
Total Depth m:	6.2	***Longitude DD:***	-79.821015
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	595575
Drill Method:	Power auger	***Northing:***	4798643
Orig Ground Elev m:	98.5	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable

DEM Ground Elev m: 99.3
Concession:
Location D:
Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID: 218419589
Top Depth: 0
Bottom Depth: .2
Material Color:
Material 1: Soil
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SOIL. AGE POST-GLACIAL.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218419590
Top Depth: .2
Bottom Depth: .9
Material Color: Brown
Material 1: Sand
Material 2: Silt
Material 3: Clay
Material 4:
Gsc Material Description:
Stratum Description: SAND,SILT,CLAY. BROWN,LOOSE,AGE GLACIAL.

Mat Consistency: Loose
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Geology Stratum ID: 218419591
Top Depth: .9
Bottom Depth: 6.2
Material Color: Brown
Material 1: Till
Material 2: Clay
Material 3: Silt
Material 4: Sand
Gsc Material Description:
Stratum Description: TILL,CLAY,SILT,SAND.BROWN,GLACIAL,HARD, AGE GLACIAL. 012 0000500700030072T,GRA **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency: Hard
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: M
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: HAM.txt RecordID: 000500 NTS_Sheet: 30M05C
Confiden 1: Reliable information but incomplete.

Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	1 of 21	NE/203.1	99.8 / 0.00	SOUTH WESTERN ONTARIO PROPANE DIV 998131 ONTARIO L 1446 PLAINS RD E BURLINGTON ON L7R3P8	PRT

Location ID: 2482
Type: retail
Expiry Date: 1995-07-31
Capacity (L): 0
Licence #: 0076397660

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	2 of 21	NE/203.1	99.8 / 0.00	JULIE M DURHAM 1446 PLAINS RD E BURLINGTON ON L7R3P8	PRT

Location ID: 2482
Type: retail
Expiry Date: 1995-08-31
Capacity (L): 95466
Licence #: 0055302001

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	3 of 21	NE/203.1	99.8 / 0.00	DAN'S SUNOCO 1446 PLAINS RD E BURLINGTON ON L7R 3P8	RST

Headcode: 01186800
Headcode Desc: SERVICE STATIONS-GASOLINE, OIL & NATURAL GAS
Phone: 9056376853
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	4 of 21	NE/203.1	99.8 / 0.00	SUNOCO 1446 PLAINS RD E BURLINGTON ON L7R3P8	RST

Headcode: 1186800
Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 9056316616
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	5 of 21	NE/203.1	99.8 / 0.00	SUNCOR ENERGY PRODUCTS INC** 1446 PLAINS RD E AT BRANT ST BURLINGTON ON L7R 3P8	FSTH

License Issue Date: 1/10/2007
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1984
Corrosion Protection:
Capacity: 36368
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status:	Active
Year of Installation:	1994
Corrosion Protection:	
Capacity:	22730
Tank Fuel Type:	Liquid Fuel Double Wall UST - Gasoline
Status:	Active
Year of Installation:	1994
Corrosion Protection:	
Capacity:	22730
Tank Fuel Type:	Liquid Fuel Double Wall UST - Gasoline
Status:	Active
Year of Installation:	2006
Corrosion Protection:	
Capacity:	50000
Tank Fuel Type:	Liquid Fuel Double Wall UST - Gasoline

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	6 of 21	NE/203.1	99.8 / 0.00	MAIMAR ASSOCIATES INC 1446 PLAINS RD E BURLINGTON ON L7R 3P8	RST

Headcode:	01186800
Headcode Desc:	SERVICE STATIONS-GASOLINE, OIL & NATURAL GAS
Phone:	
List Name:	
Description:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	7 of 21	NE/203.1	99.8 / 0.00	1463963 ONTARIO INC O/A SUNOCO GAS STN #5834 1446 PLAINS RD E AT BRANT ST BURLINGTON ON L7P 3P8	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	9810128	**Expired Date:**	12/7/2009 15:57
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:		**Facility Location:**	
Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

TSSA Program Area:
TSSA Program Area 2:
Description:
Original Source: EXP
Record Date: Up to May 2013

---

58 | ***8 of 21*** | ***NE/203.1*** | ***99.8 / 0.00*** | ***SUNCOR ENERGY PRODUCTS INC***
1446 PLAINS RD E AT BRANT ST
BURLINGTON ON | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10003410
Status: EXPIRED
Instance ID: 10072
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Cylr Handling Facility
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

58 | ***9 of 21*** | ***NE/203.1*** | ***99.8 / 0.00*** | ***1333916 ONTARIO INC***
1446 PLAINS RD E AT BRANT ST
BURLINGTON ON | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 11301595
Status: EXPIRED
Instance ID: 76511
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Quantity: ***Piping Galvanized:***
Unit of Measure: ***Tank Single Wall St:***
Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

58	*10 of 21*	*NE/203.1*	*99.8 / 0.00*	***1333916 ONTARIO INC*** ***1446 PLAINS RD E AT BRANT ST*** ***BURLINGTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 11301574
Status: EXPIRED
Instance ID: 77004
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

58	*11 of 21*	*NE/203.1*	*99.8 / 0.00*	***MAIMAR ASSOCIATES INC*** ***1446 PLAINS RD E AT BRANT ST*** ***BURLINGTON ON***	***DTNK***

Delisted Expired Fuel Safety

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Facilities

Instance No:	10634424	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	29950	***Facility Location:***	
Instance Type:	FS Piping	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

58	***12 of 21***	***NE/203.1***	***99.8 / 0.00***	***MAIMAR ASSOCIATES INC*** ***1446 PLAINS RD E AT BRANT ST*** ***BURLINGTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	10634468	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	31481	***Facility Location:***	
Instance Type:	FS Piping	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

---

58 | ***13 of 21*** | ***NE/203.1*** | ***99.8 / 0.00*** | ***MAIMAR ASSOCIATES INC***
1446 PLAINS RD E AT BRANT ST
BURLINGTON ON | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10634378
Status: EXPIRED
Instance ID: 32063
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

58 | ***14 of 21*** | ***NE/203.1*** | ***99.8 / 0.00*** | ***1333916 ONTARIO INC***
1446 PLAINS RD E AT BRANT ST
BURLINGTON ON | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 11427629
Status: EXPIRED
Instance ID: 84134
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

58	15 of 21	NE/203.1	99.8 / 0.00	**MAIMAR ASSOCIATES INC** **1446 PLAINS RD E** **BURLINGTON ON L7R3P8**	RST

Headcode:	01186800
Headcode Desc:	SERVICE STATIONS GASOLINE OIL & NATURAL GAS
Phone:	9056316616
List Name:	INFO-DIRECT(TM) BUSINESS FILE
Description:	

58	16 of 21	NE/203.1	99.8 / 0.00	**1333916 ONTARIO INC** **1446 PLAINS RD E AT BRANT ST BURLINGTON** **L7P 3P8 ON CA** **ON**	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	11427620	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	NULL
Instance ID:		**Facility Location:**	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA
Instance Type:		**Facility Type:**	FS LIQUID FUEL TANK
Instance Creation Dt:	11/17/1994	**Fuel Type 2:**	NULL
Instance Install Dt:	11/17/1994	**Fuel Type 3:**	NULL
Item Description:	FS Liquid Fuel Tank	**Panam Related:**	NULL
Manufacturer:	NULL	**Panam Venue Nm:**	NULL
Model:	NULL	**External Identifier:**	NULL
Serial No:	NULL	**Item:**	
ULC Standard:	NULL	**Piping Steel:**	
Quantity:	1	**Piping Galvanized:**	
Unit of Measure:	EA	**Tank Single Wall St:**	
Overfill Prot Type:	NULL	**Piping Underground:**	
Creation Date:	7/5/2009 1:25:17 AM	**Tank Underground:**	
Next Periodic Str DT:	NULL	**Source:**	FS Liquid Fuel Tank
TSSA Base Sched Cycle 2:	NULL		
TSSAMax Hazard Rank 1:	NULL		
TSSA Risk Based Periodic Yn:	NULL		
TSSA Volume of Directives:	NULL		
TSSA Periodic Exempt:	NULL		
TSSA Statutory Interval:	NULL		
TSSA Recd Insp Interva:	NULL		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

TSSA Recd Tolerance:	NULL
TSSA Program Area:	NULL
TSSA Program Area 2:	NULL
Description:	DUP RECORD
Original Source:	EXP
Record Date:	31-JUL-2020

---

58 | **17 of 21** | **NE/203.1** | **99.8 / 0.00** | **1463963 ONTARIO INC O/A SUNOCO GAS STN #5834**
1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA
ON | **DTNK**

Delisted Expired Fuel Safety Facilities

Instance No:	10634343	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	NULL
Instance ID:		**Facility Location:**	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA
Instance Type:		**Facility Type:**	FS LIQUID FUEL TANK
Instance Creation Dt:	5/5/1992	**Fuel Type 2:**	NULL
Instance Install Dt:	5/5/1992	**Fuel Type 3:**	NULL
Item Description:	FS Liquid Fuel Tank	**Panam Related:**	NULL
Manufacturer:	NULL	**Panam Venue Nm:**	NULL
Model:	NULL	**External Identifier:**	NULL
Serial No:	NULL	**Item:**	
ULC Standard:	NULL	**Piping Steel:**	
Quantity:	1	**Piping Galvanized:**	
Unit of Measure:	EA	**Tank Single Wall St:**	
Overfill Prot Type:	NULL	**Piping Underground:**	
Creation Date:	7/5/2009 1:20:03 AM	**Tank Underground:**	
Next Periodic Str DT:	NULL	**Source:**	FS Liquid Fuel Tank

TSSA Base Sched Cycle 2:	NULL
TSSAMax Hazard Rank 1:	NULL
TSSA Risk Based Periodic Yn:	NULL
TSSA Volume of Directives:	NULL
TSSA Periodic Exempt:	NULL
TSSA Statutory Interval:	NULL
TSSA Recd Insp Interva:	NULL
TSSA Recd Tolerance:	NULL
TSSA Program Area:	NULL
TSSA Program Area 2:	NULL
Description:	DUPLICATE RECORD
Original Source:	EXP
Record Date:	31-JUL-2020

---

58 | **18 of 21** | **NE/203.1** | **99.8 / 0.00** | **1463963 ONTARIO INC O/A SUNOCO GAS STN #5834**
1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA
ON | **DTNK**

Delisted Expired Fuel Safety Facilities

Instance No:	10634399	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	NULL
Instance ID:		**Facility Location:**	1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA
Instance Type:		**Facility Type:**	FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance Creation Dt:	10/2/1989	**Fuel Type 2:**	NULL
Instance Install Dt:	10/2/1989	**Fuel Type 3:**	NULL
Item Description:	FS Liquid Fuel Tank	**Panam Related:**	NULL
Manufacturer:	NULL	**Panam Venue Nm:**	NULL
Model:	NULL	**External Identifier:**	NULL
Serial No:	NULL	**Item:**	
ULC Standard:	NULL	**Piping Steel:**	
Quantity:	1	**Piping Galvanized:**	
Unit of Measure:	EA	**Tank Single Wall St:**	
Overfill Prot Type:	NULL	**Piping Underground:**	
Creation Date:	7/5/2009 1:20:04 AM	**Tank Underground:**	
Next Periodic Str DT:	NULL	**Source:**	FS Liquid Fuel Tank

TSSA Base Sched Cycle 2:	NULL
TSSAMax Hazard Rank 1:	NULL
TSSA Risk Based Periodic Yn:	NULL
TSSA Volume of Directives:	NULL
TSSA Periodic Exempt:	NULL
TSSA Statutory Interval:	NULL
TSSA Recd Insp Interva:	NULL
TSSA Recd Tolerance:	NULL
TSSA Program Area:	NULL
TSSA Program Area 2:	NULL
Description:	DUPLICATE RECORD
Original Source:	EXP
Record Date:	31-JUL-2020

---

58 | ***19 of 21*** | ***NE/203.1*** | ***99.8 / 0.00*** | ***Suncor Energy Products Inc.*** | ***GEN***
1446 Plains Road
Burlington ON L7R 1H9

Generator No:	ON8853903
SIC Code:	
SIC Description:	
Approval Years:	As of Nov 2021
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	221 L
Waste Class Name:	Light fuels
Waste Class:	251 L
Waste Class Name:	Waste oils/sludges (petroleum based)

---

58 | ***20 of 21*** | ***NE/203.1*** | ***99.8 / 0.00*** | ***1446 Plains Road E*** | ***EHS***
Burlington ON L7R 3P8

Order No:	22030900651	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	14-MAR-22	**Search Radius (km):**	.25
Date Received:	09-MAR-22	**X:**	-79.8173193
Previous Site Name:		**Y:**	43.3377668
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	21 of 21	NE/203.1	99.8 / 0.00	1446 Plains Road E Burlington ON L7R 3P8	EHS

Order No:	22030900651	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	14-MAR-22	**Search Radius (km):**	.25
Date Received:	09-MAR-22	**X:**	-79.8173193
Previous Site Name:		**Y:**	43.3377668
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
59	1 of 1	SW/207.2	99.8 / 0.00	SUN CHEMICAL LTD. LUGGER BOX BURLINGTON CITY ON	SPL

Ref No:	125106	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	4/17/1996	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	OTHER CAUSE (N.O.S.)	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	POSSIBLE	**Site Municipality:**	14101
Nature of Impact:	Soil contamination	**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	HALTON REGIONAL POLICE
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	4/17/1996	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	FIRE/EXPLOSION	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	SUN CHEMICAL - FIRE AT PLANT, OIL RUNOFF WATER TO GROUND, CONTAINED.		
Contaminant Qty:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
60	1 of 1	WSW/211.3	98.8 / -1.00	Glendor Ave Burlington ON	WWIS

Well ID:	7355019	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	06-Mar-2020 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z317754	**Contractor:**	7247
Tag:	A286458	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	

Static Water Level: ***Zone:***
Clear/Cloudy: ***UTM Reliability:***
Municipality: BURLINGTON CITY
Site Info:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2020/01/14
Year Completed: 2020
Depth (m): 6.096
Latitude: 43.3348518458529
Longitude: -79.8214349654912
Path:

Bore Hole Information

Bore Hole ID: 1008204469 ***Elevation:***
DP2BR: ***Elevrc:***
Spatial Status: ***Zone:*** 17
Code OB: ***East83:*** 595540.00
Code OB Desc: ***North83:*** 4798675.00
Open Hole: ***Org CS:*** UTM83
Cluster Kind: ***UTMRC:*** 4
Date Completed: 14-Jan-2020 00:00:00 ***UTMRC Desc:*** margin of error : 30 m - 100 m
Remarks: ***Location Method:*** wwr
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1008361084
Layer: 1
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3: 02
Mat3 Desc: TOPSOIL
Formation Top Depth: 0.0
Formation End Depth: 5.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1008361085
Layer: 2
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2: 05

Mat2 Desc:	CLAY
Mat3:	34
Mat3 Desc:	TILL
Formation Top Depth:	5.0
Formation End Depth:	20.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008361776
Layer:	1
Plug From:	0.0
Plug To:	8.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1008362627
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	

Pipe Information

Pipe ID:	1008360353
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1008362909
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	10.0
Casing Diameter:	2.0
Casing Diameter UOM:	Inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1008363203
Layer:	1
Slot:	10
Screen Top Depth:	10.0
Screen End Depth:	20.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.125

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008363647
Pump Set At:	
Static Level:	

Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1008362339
Diameter: 6.0
Depth From: 0.0
Depth To: 20.0
Hole Depth UOM: ft
Hole Diameter UOM: Inch

Links

Bore Hole ID: 1008204469
Depth M: 6.096
Year Completed: 2020
Well Completed Dt: 2020/01/14
Audit No: Z317754
Tag No: A286458
Contractor: 7247
Path: 735\7355019.pdf
Latitude: 43.3348518458529
Longitude: -79.8214349654912

---

61 | ***1 of 8*** | ***NE/213.2*** | ***99.8 / 0.00*** | ***SUNCOR ENERGY PRODUCTS PARTNERSHIP***
1446 PLAINS RD E AT BRANT ST BURLINGTON
L7P 3P8 ON CA
ON | ***FST***

Instance No: 46077488
Status:
Cont Name:
Instance Type: FS Liquid Fuel Tank
Item:
Item Description: FS Liquid Fuel Tank
Tank Type: Double Wall UST
Install Date: 11/16/2006
Install Year: 2006
Years in Service:
Model: NULL
Description:
Capacity: 50000
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protect:
Manufacturer:
Serial No:
Ulc Standard:
Quantity:
Unit of Measure:
Fuel Type: Gasoline
Fuel Type2: NULL
Fuel Type3: NULL
Piping Steel:
Piping Galvanized:
Tanks Single Wall St:
Piping Underground:
No Underground:
Panam Related:
Panam Venue:
Facility Type: FS Liquid Fuel Tank
Parent Facility Type: FS Gasoline Station - Self Serve
Facility Location:
Device Installed Location: 1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA

Liquid Fuel Tank Details

Overfill Protection:
Owner Account Name: SUNCOR ENERGY PRODUCTS PARTNERSHIP
Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
61	2 of 8	NE/213.2	99.8 / 0.00	SUNCOR ENERGY PRODUCTS PARTNERSHIP 1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA ON	FST

Instance No: 11301568
Status:
Cont Name:
Instance Type: FS Liquid Fuel Tank
Item:
Item Description: FS Liquid Fuel Tank
Tank Type: Single Wall UST
Install Date: 11/17/1994
Install Year: 1984
Years in Service:
Model: NULL
Description:
Capacity: 22730
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protect:
Facility Type: FS Liquid Fuel Tank
Parent Facility Type: FS Gasoline Station - Self Serve
Facility Location:
Device Installed Location: 1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA

Manufacturer:
Serial No:
Ulc Standard:
Quantity:
Unit of Measure:
Fuel Type: Gasoline
Fuel Type2: NULL
Fuel Type3: NULL
Piping Steel:
Piping Galvanized:
Tanks Single Wall St:
Piping Underground:
No Underground:
Panam Related:
Panam Venue:

Liquid Fuel Tank Details

Overfill Protection:
Owner Account Name: SUNCOR ENERGY PRODUCTS PARTNERSHIP
Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
61	3 of 8	NE/213.2	99.8 / 0.00	SUNCOR ENERGY PRODUCTS PARTNERSHIP 1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA ON	FST

Instance No: 10634446
Status:
Cont Name:
Instance Type: FS Liquid Fuel Tank
Item:
Item Description: FS Liquid Fuel Tank
Tank Type: Single Wall UST
Install Date: 10/2/1989
Install Year: 1984
Years in Service:
Model: NULL
Description:
Capacity: 36368
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protect:
Facility Type: FS Liquid Fuel Tank
Parent Facility Type: FS Gasoline Station - Self Serve
Facility Location:
Device Installed Location: 1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA

Manufacturer:
Serial No:
Ulc Standard:
Quantity:
Unit of Measure:
Fuel Type: Gasoline
Fuel Type2: NULL
Fuel Type3: NULL
Piping Steel:
Piping Galvanized:
Tanks Single Wall St:
Piping Underground:
No Underground:
Panam Related:
Panam Venue:

Liquid Fuel Tank Details

Overfill Protection:
Owner Account Name: SUNCOR ENERGY PRODUCTS PARTNERSHIP

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Item: FS LIQUID FUEL TANK

---

61 | **4 of 8** | **NE/213.2** | **99.8 / 0.00** | **SUNCOR ENERGY PRODUCTS PARTNERSHIP**
1446 PLAINS RD E AT BRANT ST BURLINGTON
L7P 3P8 ON CA
ON | **FST**

Instance No: 11301585
Status:
Cont Name:
Instance Type: FS Liquid Fuel Tank
Item:
Item Description: FS Liquid Fuel Tank
Tank Type: Single Wall UST
Install Date: 11/17/1994
Install Year: 1984
Years in Service:
Model: NULL
Description:
Capacity: 22730
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protect:
Facility Type: FS Liquid Fuel Tank
Parent Facility Type: FS Gasoline Station - Self Serve
Facility Location:
Device Installed Location: 1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA

Manufacturer:
Serial No:
Ulc Standard:
Quantity:
Unit of Measure:
Fuel Type: Gasoline
Fuel Type2: NULL
Fuel Type3: NULL
Piping Steel:
Piping Galvanized:
Tanks Single Wall St:
Piping Underground:
No Underground:
Panam Related:
Panam Venue:

Liquid Fuel Tank Details

Overfill Protection:
Owner Account Name: SUNCOR ENERGY PRODUCTS PARTNERSHIP
Item: FS LIQUID FUEL TANK

---

61 | **5 of 8** | **NE/213.2** | **99.8 / 0.00** | **1463963 ONTARIO INC O/A SUNOCO GAS STN #5834**
1446 PLAINS RD E AT BRANT ST BURLINGTON
L7P 3P8 ON CA
ON | **FST**

Instance No: 10634399
Status:
Cont Name:
Instance Type:
Item:
Item Description: FS Liquid Fuel Tank
Tank Type: Liquid Fuel Single Wall UST
Install Date: 10/2/1989
Install Year: 1984
Years in Service:
Model: NULL
Description:
Capacity: 36368
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protect:
Facility Type: FS Liquid Fuel Tank
Parent Facility Type:
Facility Location:
Device Installed Location: 1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA

Manufacturer:
Serial No:
Ulc Standard:
Quantity:
Unit of Measure:
Fuel Type: Gasoline
Fuel Type2: NULL
Fuel Type3: NULL
Piping Steel:
Piping Galvanized:
Tanks Single Wall St:
Piping Underground:
No Underground:
Panam Related:
Panam Venue:

Liquid Fuel Tank Details

Overfill Protection:
Owner Account Name: 1463963 ONTARIO INC O/A SUNOCO GAS STN #5834
Item: FS LIQUID FUEL TANK

---

61 | **6 of 8** | **NE/213.2** | **99.8 / 0.00** | **1463963 ONTARIO INC O/A SUNOCO GAS STN #5834**
1446 PLAINS RD E AT BRANT ST BURLINGTON
L7P 3P8 ON CA
ON | **FST**

Instance No: 10634343
Status:
Cont Name:
Instance Type:
Item:
Item Description: FS Liquid Fuel Tank
Tank Type: Liquid Fuel Single Wall UST
Install Date: 5/5/1992
Install Year: 1984
Years in Service:
Model: NULL
Description:
Capacity: 22730
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protect:
Facility Type: FS Liquid Fuel Tank
Parent Facility Type:
Facility Location:
Device Installed Location: 1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA

Manufacturer:
Serial No:
Ulc Standard:
Quantity:
Unit of Measure:
Fuel Type: Gasoline
Fuel Type2: NULL
Fuel Type3: NULL
Piping Steel:
Piping Galvanized:
Tanks Single Wall St:
Piping Underground:
No Underground:
Panam Related:
Panam Venue:

Liquid Fuel Tank Details

Overfill Protection:
Owner Account Name: 1463963 ONTARIO INC O/A SUNOCO GAS STN #5834
Item: FS LIQUID FUEL TANK

---

61 | **7 of 8** | **NE/213.2** | **99.8 / 0.00** | **1333916 ONTARIO INC**
1446 PLAINS RD E AT BRANT ST BURLINGTON
L7P 3P8 ON CA
ON | **FST**

Instance No: 11427620
Status:
Cont Name:
Instance Type:
Item:
Item Description: FS Liquid Fuel Tank
Tank Type: Liquid Fuel Double Wall UST
Install Date: 11/17/1994
Install Year: 1994
Years in Service:
Model: NULL
Description:
Capacity: 22730
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protect:
Facility Type: FS Liquid Fuel Tank
Parent Facility Type:
Facility Location:
Device Installed Location: 1446 PLAINS RD E AT BRANT ST BURLINGTON L7P 3P8 ON CA

Manufacturer:
Serial No:
Ulc Standard:
Quantity:
Unit of Measure:
Fuel Type: Gasoline
Fuel Type2: NULL
Fuel Type3: NULL
Piping Steel:
Piping Galvanized:
Tanks Single Wall St:
Piping Underground:
No Underground:
Panam Related:
Panam Venue:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Liquid Fuel Tank Details

Overfill Protection:
Owner Account Name: 1333916 ONTARIO INC
Item: FS LIQUID FUEL TANK

---

61 | ***8 of 8*** | ***NE/213.2*** | ***99.8 / 0.00*** | ***Suncor Energy Products Inc.***
1446 Plains Road East
Burlington ON L7R 3P8 | ***GEN***

Generator No: ON8853903
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221 L
Waste Class Name: LIGHT FUELS

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

62 | ***1 of 1*** | ***S/217.4*** | ***97.9 / -1.99*** | ***ON*** | ***BORE***

Borehole ID: 622675
OGF ID: 215523129
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: FEB-1967
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 11.1
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Power auger
Orig Ground Elev m: 99.1
Elev Reliabil Note:
DEM Ground Elev m: 97.8
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.333631
Longitude DD: -79.818566
UTM Zone: 17
Easting: 595775
Northing: 4798543
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218426646
Top Depth: 2.7
Bottom Depth: 9.4
Material Color: Green
Material 1: Silt
Material 2: Sand

Mat Consistency: Dense
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:

Material 3:	Clay	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND,CLAY. GREEN,VERY DENSE,GRANULAR, AGE GLACIAL.		

Geology Stratum ID:	218426644	**Mat Consistency:**	Dense
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	1.5	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND. BROWN,VERY DENSE,GRANULAR, AGE GLACIAL.		

Geology Stratum ID:	218426645	**Mat Consistency:**	Dense
Top Depth:	1.5	**Material Moisture:**	
Bottom Depth:	2.7	**Material Texture:**	
Material Color:	Green	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND,CLAY. GREEN,VERY DENSE,GRANULAR, AGE GLACIAL.		

Geology Stratum ID:	218426647	**Mat Consistency:**	Hard
Top Depth:	9.4	**Material Moisture:**	
Bottom Depth:	11.1	**Material Texture:**	
Material Color:	Green	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,CLAY. GREEN,VERY HARD,LAYERED, AGE GLACIAL. 014 021 011 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: HAM.txt RecordID: 016750 NTS_Sheet: 30M05C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

63	*1 of 1*	*E/222.6*	*99.9 / 0.01*	*ON*	*WWIS*

Well ID:	7265586	**Flowing (Y/N):**	

Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	24-Jun-2016 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	C31808	***Contractor:***	7464
Tag:	A197916	***Form Version:***	8
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	HALTON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	2016/03/10
Year Completed:	2016
Depth (m):	
Latitude:	43.3359251432429
Longitude:	-79.8155052901711
Path:	

Bore Hole Information

Bore Hole ID:	1006075945	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	596019.00
Code OB Desc:		***North83:***	4798801.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	10-Mar-2016 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1006075945	***Tag No:***	A197916
Depth M:		***Contractor:***	7464
Year Completed:	2016	***Path:***	
Well Completed Dt:	2016/03/10	***Latitude:***	43.3359251432429
Audit No:	C31808	***Longitude:***	-79.8155052901711

64	***1 of 120***	***SE/225.7***	***100.0 / 0.19***	***HERCULES CANADA INC.*** ***942 BRANT STREET*** ***BURLINGTON CITY ON L7R 2J7***	***CA***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Certificate #: 8-3202-95-
Application Year: 95
Issue Date: 7/17/1995
Approval Type: Industrial air
Status:
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: SCRUBBER FOR (8) PROC. TANKS
Contaminants: Sound, Nitrogen Oxides, Sulphur Dioxide
Emission Control: Muffler

64	*2 of 120*	*SE/225.7*	*100.0 / 0.19*	***HERCULES CANADA INC.*** ***942 BRANT STREET*** ***BURLINGTON CITY ON L7R 2J7***	*CA*

Certificate #: 8-3039-89-
Application Year: 89
Issue Date: 7/28/1989
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: MELTER FOR ALKYL KETENE DIMER
Contaminants:
Emission Control:

64	*3 of 120*	*SE/225.7*	*100.0 / 0.19*	***HERCULES CANADA INC.*** ***942 BRANT STREET*** ***BURLINGTON CITY ON L7R 2J7***	*CA*

Certificate #: 8-3108-89-
Application Year: 89
Issue Date: 11/17/1989
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: UPGRADING OF HERCON MIXING TANK VENTILAT
Contaminants:
Emission Control:

64	*4 of 120*	*SE/225.7*	*100.0 / 0.19*	***HERCULES CANADA INC.*** ***942 BRANT STREET*** ***BURLINGTON CITY ON L7R 2J7***	*CA*

Certificate #: 8-3149-89-
Application Year: 89
Issue Date: 5/6/1992
Approval Type: Industrial air
Status: Cancelled
Application Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: TEMP. BOILER FUEL SUBSTITUTION
Contaminants:
Emission Control:

---

64 | **5 of 120** | **SE/225.7** | **100.0 / 0.19** | **HERCULES CANADA INC.**
BURLINGTON PLANT 942 BRANT STREET
BURLINGTON CITY ON L7R 2J7 | **SPL**

Ref No:	95990	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	2/2/1994	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	ABOVE-GROUND TANK LEAK	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	NOT ANTICIPATED	**Site Municipality:**	14101
Nature of Impact:		**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2/2/1994	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	OTHER	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			

Incident Summary: HERCULES - 60000 LBS OF HEAVY VEGETABLE OIL TO GROUND AND LAGOON
Contaminant Qty:

---

64 | **6 of 120** | **SE/225.7** | **100.0 / 0.19** | **HERCULES CANADA**
BURLINGTON PLANT 942 BRANT STREET
BURLINGTON CITY ON L7R 2J7 | **SPL**

Ref No:	2945	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	4/28/1988	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	PROCESS UPSET	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:		**Site Municipality:**	14101
Nature of Impact:		**Site Lot:**	
Receiving Medium:	AIR	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	4/28/1988	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	OTHER	**Source Type:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: HERCULES CANADA - 10 SEC SMOKE EMISSION
Contaminant Qty:

---

64 **7 of 120** **SE/225.7** **100.0 / 0.19**

HERCULES CANADA
BURLINGTON PLANT 942 BRANT STREET
BURLINGTON CITY ON L7R 2J7

SPL

Ref No: 7355
Site No:
Incident Dt: 7/31/1988
Year:
Incident Cause: PROCESS UPSET
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact:
Nature of Impact:
Receiving Medium: AIR
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/31/1988
Dt Document Closed:
Incident Reason: EQUIPMENT FAILURE
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: HERCULES - 5 SEC. SMOKE TO ATM.
Contaminant Qty:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 14101
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

---

64 **8 of 120** **SE/225.7** **100.0 / 0.19**

HERCULES CANADA
BURLINGTON PLANT 942 BRANT STREET
BURLINGTON CITY ON L7R 2J7

SPL

Ref No: 9219
Site No:
Incident Dt: 1/10/1988
Year:
Incident Cause: PROCESS UPSET
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact:
Nature of Impact:
Receiving Medium: AIR
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 1/10/1988
Dt Document Closed:
Incident Reason: EQUIPMENT FAILURE
Site Name:
Site County/District:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 14101
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site Geo Ref Meth:
Incident Summary: HERCULES CANADA - SMOKE FOR 30 MIN. FROM LEAKY TUBE IN VAPOURIZER.
Contaminant Qty:

---

64 | 9 of 120 | SE/225.7 | 100.0 / 0.19 | HERCULES CANADA BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7 | SPL

Ref No: 15926
Site No:
Incident Dt: 3/16/1989
Year:
Incident Cause: UNKNOWN
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact:
Nature of Impact:
Receiving Medium: LAND / WATER
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/16/1989
Dt Document Closed:
Incident Reason: ERROR
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: HERCULES CANADA-18000 L LUBE OIL TO GROUND AND SEWER.
Contaminant Qty:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 14101
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

---

64 | 10 of 120 | SE/225.7 | 100.0 / 0.19 | HERCULES CANADA BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7 | SPL

Ref No: 18212
Site No:
Incident Dt: 5/8/1989
Year:
Incident Cause: OTHER CAUSE (N.O.S.)
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact:
Nature of Impact:
Receiving Medium: LAND
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/8/1989
Dt Document Closed:
Incident Reason: ERROR
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: HERCULES - 100 KG FORMALDEHYDE (37%) TO DYKED AREA.

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 14101
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

Contaminant Qty:

---

64 | **11 of 120** | **SE/225.7** | **100.0 / 0.19** | **HERCULES CANADA**
BOILER STACK BURLINGTON PLANT 942
BRANT STREET
BURLINGTON CITY ON | **SPL**

Ref No:	18455	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	5/13/1989	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	PROCESS UPSET	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:		**Site Municipality:**	14101
Nature of Impact:		**Site Lot:**	
Receiving Medium:	AIR	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	5/13/1989	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	COMBUSTION PROBLEMS	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			

Incident Summary: HERCULES-INTERMITTENT SMOKE FOR UNKNOWN DURATION.
Contaminant Qty:

---

64 | **12 of 120** | **SE/225.7** | **100.0 / 0.19** | **HERCULES CANADA**
HOLDING TANK BURLINGTON PLANT 942
BRANT STREET
BURLINGTON CITY ON | **SPL**

Ref No:	19561	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	10/4/1988	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	NOT ANTICIPATED	**Site Municipality:**	14101
Nature of Impact:		**Site Lot:**	
Receiving Medium:	WATER	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	HALTON REGION
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	10/4/1988	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	ERROR	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			

Incident Summary: BACKENTRY - HERCULES 4000 KGS AMILE RESIN TO LAGOON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminant Qty:

---

64 | 13 of 120 | SE/225.7 | 100.0 / 0.19 | HERCULES CANADA BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7 | SPL

Ref No:	20428	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	6/15/1989	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	ABOVE-GROUND TANK LEAK	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:		Site Municipality:	14101
Nature of Impact:		Site Lot:	
Receiving Medium:	LAND	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	6/15/1989	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	ERROR	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			

Incident Summary: HERCULES - 500 KG MAX. PITCH DISTILLATE TO DYKED AREA.

Contaminant Qty:

---

64 | 14 of 120 | SE/225.7 | 100.0 / 0.19 | HERCULES CANADA BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7 | SPL

Ref No:	20441	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	3/16/1989	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:	NOT ANTICIPATED	Site Municipality:	14101
Nature of Impact:		Site Lot:	
Receiving Medium:	LAND	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	REG MUNICIPALITY OF HALTON
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	3/16/1989	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	NEGLIGENCE (APPARENT)	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			

Incident Summary: BACKENTRY - HERCULES CAN.15 000L LUBRICATING OIL FROM OPEN VALVES

Contaminant Qty:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	15 of 120	SE/225.7	100.0 / 0.19	HERCULES CANADA BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SPL

Ref No:	25002	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	9/9/1989	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	PROCESS UPSET	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:		**Site Municipality:**	14101
Nature of Impact:		**Site Lot:**	
Receiving Medium:	AIR	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	9/9/1989	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	EQUIPMENT FAILURE	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	HERCULES -1 HOUR OF WASTEGAS EMISSIONS		
Contaminant Qty:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	16 of 120	SE/225.7	100.0 / 0.19	HERCULES CANADA BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SPL

Ref No:	28860	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	12/14/1989	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	PROCESS UPSET	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:		**Site Municipality:**	14101
Nature of Impact:		**Site Lot:**	
Receiving Medium:	AIR	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	12/14/1989	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	EQUIPMENT FAILURE	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	HERCULES-TALL OIL GAS TO AIR		
Contaminant Qty:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	17 of 120	SE/225.7	100.0 / 0.19	HERCULES CANADA BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SPL

Ref No:	29596	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	1/7/1990	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	PROCESS UPSET	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:	NOT ANTICIPATED	Site Municipality:	14101
Nature of Impact:		Site Lot:	
Receiving Medium:	AIR	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	1/7/1990	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	COMBUSTION PROBLEMS	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	HERCULES - INTERMITTENT SMOKE EMISSIONS 4 HRS.		
Contaminant Qty:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	18 of 120	SE/225.7	100.0 / 0.19	HERCULES CANADA BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SPL

Ref No:	31941	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	3/12/1990	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	OTHER CAUSE (N.O.S.)	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:	NOT ANTICIPATED	Site Municipality:	14101
Nature of Impact:		Site Lot:	
Receiving Medium:	AIR	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	3/12/1990	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	INTENTIONAL/PLANNED	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	HERCULES - WASTE GASES TOAIR FOR ONE HOUR		
Contaminant Qty:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	19 of 120	SE/225.7	100.0 / 0.19	HERCULES CANADA BURLINGTON PLANT 942 BRANT STREET	SPL

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				BURLINGTON CITY ON L7R 2J7	

Ref No:	37185	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	7/3/1990	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	START-UPS/SHUTDOWNS/INTERRUPTIONS	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	POSSIBLE	**Site Municipality:**	14101
Nature of Impact:	Vegetation	**Site Lot:**	
Receiving Medium:	AIR	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	7/3/1990	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	INTENTIONAL/PLANNED	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	HERCULES CANADA- ONGOING INTERMITTENT SMOKE.		
Contaminant Qty:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	20 of 120	SE/225.7	100.0 / 0.19	HERCULES CANADA BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SPL

Ref No:	41587	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	10/2/1990	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	PROCESS UPSET	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	POSSIBLE	**Site Municipality:**	14101
Nature of Impact:	Soil contamination	**Site Lot:**	
Receiving Medium:	LAND / AIR	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	10/2/1990	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	OVERSTRESS/OVERPRESSURE	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	HERCULES CANADA -THERMO OIL RELEASED TO AIR AND GROUND FROM RELIEF VALVE.		
Contaminant Qty:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	21 of 120	SE/225.7	100.0 / 0.19	HERCULES CANADA BURLINGTON PLANT 942 BRANT STREET	SPL

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				BURLINGTON CITY ON L7R 2J7	

Ref No:	42467	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	10/22/1990	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	PROCESS UPSET	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:	POSSIBLE	Site Municipality:	14101
Nature of Impact:	Vegetation	Site Lot:	
Receiving Medium:	AIR	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	10/22/1990	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	ERROR	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	HERCULES-INTERMITTENT SMOKE TO ATMOSPHERE.		
Contaminant Qty:			

64	22 of 120	SE/225.7	100.0 / 0.19	HERCULES CANADA INC. BURLINGTON PLANT 942 BRANT STREET BURLINGTON CITY ON L7R 2J7	SPL

Ref No:	47814	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	3/19/1991	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	CONTAINER OVERFLOW	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:	POSSIBLE	Site Municipality:	14101
Nature of Impact:	Water course or lake	Site Lot:	
Receiving Medium:	LAND / WATER	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	HALTO REG SPILLS,SEWAGE PLANT
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	3/19/1991	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	ERROR	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	HERCULES-540 LITRES KYMENE 557 H TO GRND AND SANITARY SEWER.		
Contaminant Qty:			

64	23 of 120	SE/225.7	100.0 / 0.19	HERCULES CANADA INC. BRANT ST/PLAINS RD INTERSECTION. BURLINGTON PLANT 942 BRANT STREET	SPL

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

BURLINGTON CITY ON

Ref No:	85983	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	5/23/1993	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	PIPE/HOSE LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	14101
Nature of Impact:	Air Pollution	***Site Lot:***	
Receiving Medium:	AIR	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	5/23/1993	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	MATERIAL FAILURE	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			

Incident Summary: HERCULES CANADA INC-MER- CAPTAN TO AIR FROM LEAK- ING VAPOR COLLECTION TANK
Contaminant Qty:

---

64 ***24 of 120*** ***SE/225.7*** ***100.0 / 0.19*** ***HERCULES CANADA INC.*** ***CHEM***

BURLINGTON ON

Headcode:		***Head Office Province:***	ON
Headcode Desc:		***Head Office Postal:***	L4Z1S1
Phone:		***Mailing Address:***	4 ROBERT SPECK PARKWAY
List Name:		***Mailing Address 2:***	
Description:		***Mailing City:***	MISSISSAUGA

---

64 ***25 of 120*** ***SE/225.7*** ***100.0 / 0.19*** ***HERCULES CANADA INC*** ***CHM***
942 BRANT ST
BURLINGTON ON L7R 2J7

Headcode:	00273600
Headcode Desc:	CHEMICALS
Phone:	
List Name:	
Description:	

---

64 ***26 of 120*** ***SE/225.7*** ***100.0 / 0.19*** ***Ashland Canada Corp.*** ***SCT***
942 Brant St
Burlington ON L7R 2J7

Established:	01-JUL-13
Plant Size (ft²):	
Employment:	

--Details--

Description:	All Other Miscellaneous Chemical Product Manufacturing
SIC/NAICS Code:	325999

64 | **27 of 120** | **SE/225.7** | **100.0 / 0.19** | **HERCULES CANADA INC.**
942 BRANT STREET NOT AVAILABLE
BURLINGTON ON L7R3X8 | **NPRI**

NPRI ID:	3643	**Org ID:**	13633
Other ID:		**Submit Date:**	
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	9809	**Contact ID:**	
Report ID:		**Cont Type:**	
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	1993	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2014	**Contact Fax:**	
Fac ID:	115074	**Contact Ph.:**	
Fac Name:	NOT AVAILABLE	**Cont Area Code:**	
Fac Address1:	942 BRANT STREET	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	L7R3X8	**Cont Fax Area Cde:**	
Facility Lat:	43.3365	**Contact Fax:**	
Facility Long:	-79.8131	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.334043
Facility DLS:		**Longitude:**	-79.816436
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:		**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3259		
NAICS 4 Description:	Other chemical product manufacturing		
NAICS Code (6 digit):	325999		
NAICS 6 Description:	All other miscellaneous chemical product manufacturing		

64 | **28 of 120** | **SE/225.7** | **100.0 / 0.19** | **HERCULES CANADA INC.**
942 BRANT STREET NOT AVAILABLE
BURLINGTON ON L7R3X8 | **NPRI**

NPRI ID:	3643	**Org ID:**	13633
Other ID:	FALSE	**Submit Date:**	
No Other ID:	0	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	9810	**Contact ID:**	
Report ID:		**Cont Type:**	
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	1994	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2014	**Contact Fax:**	
Fac ID:	115074	**Contact Ph.:**	
Fac Name:	NOT AVAILABLE	**Cont Area Code:**	
Fac Address1:	942 BRANT STREET	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	L7R3X8	**Cont Fax Area Cde:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Facility Lat:	43.3365	**Contact Fax:**	
Facility Long:	-79.8131	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.334043
Facility DLS:		**Longitude:**	-79.816436
Datum:	1983	**UTM Zone:**	17
Facility Cmnts:	FALSE	**UTM Northing:**	4798641
URL:		**UTM Easting:**	596200
No of Empl.:	56	**Waste Streams:**	FALSE
Parent Co.:	TRUE	**No Streams:**	0
No Parent Co.:	1	**Waste Off Sites:**	FALSE
Pollut Prev Cmnts:		**No Off Sites:**	1
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3259		
NAICS 4 Description:	Other chemical product manufacturing		
NAICS Code (6 digit):	325999		
NAICS 6 Description:	All other miscellaneous chemical product manufacturing		

64	29 of 120	SE/225.7	100.0 / 0.19	**HERCULES CANADA INC.** **942 BRANT STREET NOT AVAILABLE** **BURLINGTON ON L7R3X8**	NPRI

NPRI ID:	3643	**Org ID:**	13633
Other ID:	Y	**Submit Date:**	9/26/2001
No Other ID:	1	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	9811	**Contact ID:**	
Report ID:		**Cont Type:**	
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	1995	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2014	**Contact Fax:**	
Fac ID:	115074	**Contact Ph.:**	
Fac Name:	NOT AVAILABLE	**Cont Area Code:**	
Fac Address1:	942 BRANT STREET	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	L7R3X8	**Cont Fax Area Cde:**	
Facility Lat:	43.3365	**Contact Fax:**	
Facility Long:	-79.8131	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.334043
Facility DLS:		**Longitude:**	-79.816436
Datum:	1983	**UTM Zone:**	17
Facility Cmnts:	FALSE	**UTM Northing:**	4798641
URL:		**UTM Easting:**	596200
No of Empl.:	56	**Waste Streams:**	FALSE
Parent Co.:	Y	**No Streams:**	0
No Parent Co.:	1	**Waste Off Sites:**	TRUE
Pollut Prev Cmnts:	FALSE	**No Off Sites:**	1
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3259		
NAICS 4 Description:	Other chemical product manufacturing		
NAICS Code (6 digit):	325999		

NAICS 6 Description: All other miscellaneous chemical product manufacturing

---

64 | **30 of 120** | **SE/225.7** | **100.0 / 0.19** | **HERCULES CANADA INC.**
942 BRANT STREET NOT AVAILABLE
BURLINGTON ON L7R3X8 | **NPRI**

NPRI ID:	3643	**Org ID:**	13633
Other ID:	Y	**Submit Date:**	6/27/1997
No Other ID:	1	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	9812	**Contact ID:**	87813
Report ID:		**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	GERRY
Report Year:	1996	**Cont Last Name:**	WILLARD
Not-Current Rpt?:	No	**Contact Position:**	PLANT MANAGER
Yr of Last Filed Rpt:	2014	**Contact Fax:**	9053333718
Fac ID:	46151	**Contact Ph.:**	9056327861
Fac Name:	BURLINGTON PLANT SITE	**Cont Area Code:**	905
Fac Address1:	942 BRANT STREET	**Contact Tel.:**	56327861
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	115
Fac Postal Zip:	L7R3X8	**Cont Fax Area Cde:**	905
Facility Lat:	43.334043	**Contact Fax:**	53333718
Facility Long:	-79.816436	**Contact Email:**	NOT AVAILABLE
DLS (Last Filed Rpt):		**Latitude:**	43.334043
Facility DLS:		**Longitude:**	-79.816436
Datum:	1983	**UTM Zone:**	17
Facility Cmnts:	FALSE	**UTM Northing:**	4798641
URL:		**UTM Easting:**	596200
No of Empl.:	56	**Waste Streams:**	FALSE
Parent Co.:	Y	**No Streams:**	0
No Parent Co.:	1	**Waste Off Sites:**	TRUE
Pollut Prev Cmnts:	FALSE	**No Off Sites:**	1
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3259		
NAICS 4 Description:	Other chemical product manufacturing		
NAICS Code (6 digit):	325999		
NAICS 6 Description:	All other miscellaneous chemical product manufacturing		

---

64 | **31 of 120** | **SE/225.7** | **100.0 / 0.19** | **HERCULES CANADA INC.**
942 BRANT ST BURLINGTON PLANT 942 BRANT STREET
BURLINGTON CITY ON L7R 2J7 | **SPL**

Ref No:	196324	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	3/12/2001	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	PIPE/HOSE LEAK	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Possible	**Site Municipality:**	14101
Nature of Impact:	Multi Media Pollution	**Site Lot:**	
Receiving Medium:	Air	**Site Conc:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/12/2001
Dt Document Closed:
Incident Reason: MATERIAL FAILURE
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: HERCULES:SPILL OF DOW THERM TO AIR. FD, MOE. PLANT EVACUATED
Contaminant Qty:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

---

64 | **32 of 120** | **SE/225.7** | **100.0 / 0.19** | **HERCULES CANADA INC.** | **CA**

BURLINGTON CITY ON

Certificate #: 8-3069-85-000
Application Year: 85
Issue Date: 8/14/85
Approval Type: Industrial air
Status: Application Cancelled
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

64 | **33 of 120** | **SE/225.7** | **100.0 / 0.19** | **942 Brant Street Burlington ON L7R 2J7** | **CA**

Certificate #: 2119-4ZENQD
Application Year: 02
Issue Date: 3/13/02
Approval Type: Industrial air
Status: Revoked and/or Replaced
Application Type: New Certificate of Approval
Client Name: Hercules Canada Inc.
Client Address: 942 Brant Street
Client City: Burlington
Client Postal Code: L7R 3X8
Project Description: This application is for approval to modify existing No. 1 silica dryer. Modifications will allow the dryer to operate as a natural gas combustion unit. The burner is currently fired wit No. 2 fuel oil. The only significant emissions from the dryer are by-products of combustion of natural gas. The silica dryer will operate for a maximum of 16 hours per day.
Contaminants:
Emission Control:

---

64 | **34 of 120** | **SE/225.7** | **100.0 / 0.19** | **942 Brant Street Burlington ON L7R 2J7** | **CA**

Certificate #: 6293-587JMD
Application Year: 02
Issue Date: 3/13/02
Approval Type: Industrial air
Status: Amended
Application Type: Amended CofA
Client Name: Hercules Canada Inc.
Client Address: 942 Brant Street

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Client City: Burlington
Client Postal Code: L7R 3X8
Project Description: This application is for the addition of new tank #150 (source 12) venting to atmosphere via a stack located on the roof of building No. 9301.
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	35 of 120	SE/225.7	100.0 / 0.19	942 Brant Street Burlington ON L7R 2J7	CA

Certificate #: 1976-579RVZ
Application Year: 02
Issue Date: 3/13/02
Approval Type: Industrial air
Status: Revoked and/or Replaced
Application Type: Amended CofA
Client Name: Hercules Canada Inc.
Client Address: 942 Brant Street
Client City: Burlington
Client Postal Code: L7R 3X8
Project Description: This application is for a change in use of an existing storage tank (T082). This tank will be used for the storage of Ultra-Phase (a cationic dispersed size agent) used in the pulp and paper industry.
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	36 of 120	SE/225.7	100.0 / 0.19	942 Brant Street Burlington ON L7R 2J7	CA

Certificate #: 8-300-064-77-776
Application Year: 00
Issue Date: 12/8/00
Approval Type: Industrial air
Status: Approved
Application Type: Notice
Client Name: Hercules Canada
Client Address: 942 Brant Street
Client City: Burlington
Client Postal Code: L7R 3X8
Project Description: Company name change to read: BetzDearborn Canada Inc. & Hercules Canada Inc. o/a Hercules Canada
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	37 of 120	SE/225.7	100.0 / 0.19	942 Brant Street Burlington ON L7R 2J7	CA

Certificate #: 8-3062-83-006
Application Year: 00
Issue Date: 11/6/00
Approval Type: Industrial air
Status: Approved
Application Type: Notice
Client Name: Hercules Canada Inc.
Client Address: 942 Brant Street
Client City: Burlington
Client Postal Code: L7R 3X8
Project Description: The name of the company has changed FROM: Hercules Canada Inc. TO: Hercules Canada Inc. operating as Hercules Canada
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	38 of 120	SE/225.7	100.0 / 0.19	**Hercules Canada Inc.** **942 Brant Street Burlington Ontario L7R 3X8** **Burlington** **ON**	EBR

EBR Registry No: IA01E1664
Ministry Ref No: 7783-54YLF5
Notice Type: Instrument Decision
Notice Stage:
Notice Date: December 06, 2006
Proposal Date: November 30, 2001
Year: 2001
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Hercules Canada Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 942 Brant Street, Burlington Ontario, L7R 3X8
Comment Period:
URL:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

942 Brant Street Burlington Ontario L7R 3X8 Burlington

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	39 of 120	SE/225.7	100.0 / 0.19	**Hercules Canada (2002) Inc.** **942 Brant Street Burlington Ontario L7R 2J7** **Burlington** **ON**	EBR

EBR Registry No: IA02E1353
Ministry Ref No: 3329-5FENN3
Notice Type: Instrument Decision
Notice Stage:
Notice Date: May 29, 2003
Proposal Date: November 01, 2002
Year: 2002
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Hercules Canada (2002) Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 942 Brant Street, P.O. Box 100, Burlington Ontario, L7R 3X8
Comment Period:
URL:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

942 Brant Street Burlington Ontario L7R 2J7 Burlington

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	40 of 120	SE/225.7	100.0 / 0.19	**HERCULES CANADA INC.** **942 BRANT ST. P.O. BOX 100** **BURLINGTON ON L7R 2J7**	GEN

Generator No: ON0096300

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Code:	3712
SIC Description:	IND. ORGANIC CHEM.
Approval Years:	86,87,88
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	113
Waste Class Name:	ACID WASTE - OTHER METALS
Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS
Waste Class:	211
Waste Class Name:	AROMATIC SOLVENTS
Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS
Waste Class:	232
Waste Class Name:	POLYMERIC RESINS
Waste Class:	233
Waste Class Name:	OTHER POLYMERIC WASTES
Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES
Waste Class:	263
Waste Class Name:	ORGANIC LABORATORY CHEMICALS
Waste Class:	267
Waste Class Name:	ORGANIC ACIDS
Waste Class:	270
Waste Class Name:	OTHER SPECIFIED ORGANICS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	41 of 120	SE/225.7	100.0 / 0.19	HERCULES CANADA INC. 942 BRANT ST. P.O.BOX 100 BURLINGTON ON L7R 2J7	GEN

Generator No:	ON0096300
SIC Code:	3712
SIC Description:	IND. ORGANIC CHEM.
Approval Years:	89
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	42 of 120	SE/225.7	100.0 / 0.19	HERCULES CANADA INC. 942 BRANT STREET BURLINGTON ON L7R 3X8	GEN

Generator No: ON0096300
SIC Code: 3712
SIC Description: IND. ORGANIC CHEM.
Approval Years: 92,93,97,98,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	43 of 120	SE/225.7	100.0 / 0.19	HERCULES CANADA INC. 20-010 942 BRANT ST. P.O.BOX 100 BURLINGTON ON L7R 2J7	GEN

Generator No: ON0096300
SIC Code: 3712
SIC Description: IND. ORGANIC CHEM.
Approval Years: 94,95,96
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

---

64 | **44 of 120** | **SE/225.7** | **100.0 / 0.19** | **HERCULES CANADA**
942 BRANT STREET
BURLINGTON ON L7R 3X8 | **GEN**

Generator No: ON0096300
SIC Code: 3712
SIC Description: IND. ORGANIC CHEM.
Approval Years: 99,00
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

---

64 | **45 of 120** | **SE/225.7** | **100.0 / 0.19** | **HERCULES CANADA (2002) INC**
942 BRANT STREET
BURLINGTON ON L7R 3X8 | **GEN**

Generator No: ON0096300
SIC Code:
SIC Description:
Approval Years: 02,03,04,05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 243
Waste Class Name: PCB'S

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class:	242
Waste Class Name:	HALOGENATED PESTICIDES
Waste Class:	253
Waste Class Name:	EMULSIFIED OILS
Waste Class:	269
Waste Class Name:	NON-HALOGENATED PESTICIDES
Waste Class:	267
Waste Class Name:	ORGANIC ACIDS
Waste Class:	268
Waste Class Name:	AMINES
Waste Class:	270
Waste Class Name:	OTHER SPECIFIED ORGANICS
Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS
Waste Class:	211
Waste Class Name:	AROMATIC SOLVENTS
Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES
Waste Class:	232
Waste Class Name:	POLYMERIC RESINS
Waste Class:	113
Waste Class Name:	ACID WASTE - OTHER METALS
Waste Class:	122
Waste Class Name:	ALKALINE WASTES - OTHER METALS

64 | ***46 of 120*** | ***SE/225.7*** | ***100.0 / 0.19*** | ***HERCULES CANADA (2002) INC***
942 BRANT ST. NOT AVAILABLE
BURLINGTON ON L7R 3X8 | ***NPRI***

NPRI ID:	3643	**Org ID:**	51249
Other ID:	*	**Submit Date:**	5/30/2003
No Other ID:	0	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	76451	**Contact ID:**	152619
Report ID:	160927	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	GERRY
Report Year:	2002	**Cont Last Name:**	WILLARD
Not-Current Rpt?:	No	**Contact Position:**	PLANT MANAGER
Yr of Last Filed Rpt:	2014	**Contact Fax:**	9053333718
Fac ID:	115076	**Contact Ph.:**	9056327861
Fac Name:	BURLINGTON PLANT	**Cont Area Code:**	905
Fac Address1:	942 BRANT ST.	**Contact Tel.:**	56327861
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	115
Fac Postal Zip:	L7R 3X8	**Cont Fax Area Cde:**	905
Facility Lat:		**Contact Fax:**	53333718
Facility Long:		**Contact Email:**	GWILLARD@HERC.COM
DLS (Last Filed Rpt):		**Latitude:**	43.334043
Facility DLS:		**Longitude:**	-79.816436
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:	www.herc.com	**UTM Easting:**	
No of Empl.:	45	**Waste Streams:**	False
Parent Co.:	Y	**No Streams:**	0
No Parent Co.:	1	**Waste Off Sites:**	False

Pollut Prev Cmnts:	False	***No Off Sites:***	0
Stacks:	False	***Shutdown:***	False
No of Stacks:		***No of Shutdown:***	0
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3259		
NAICS 4 Description:	Other chemical product manufacturing		
NAICS Code (6 digit):	325999		
NAICS 6 Description:	All other miscellaneous chemical product manufacturing		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	1.934
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Sulphur dioxide
Chem (fr):	Dioxyde de soufre
Quantity:	31.23
Unit:	tonnes
Basis of Estimate Cd:	E E2
Basis of Estimate Desc:	E- Emission Factor - In use from 1994 to 2002 ; E2- Published Emission Factors - In use from 2003 and onward

Category Type ID:	6
Category Type Desc:	Road dust
Category Type Desc (fr):	Poussières de routes
Grouping:	Total Air
Trans Code:	
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	.016
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Nitrogen oxides (expressed as NO2)
Chem (fr):	Oxydes d'azote (exprimés en NO2)
Quantity:	27.8
Unit:	tonnes
Basis of Estimate Cd:	E E2
Basis of Estimate Desc:	E- Emission Factor - In use from 1994 to 2002 ; E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 13

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr): PM2,5 - Matière particulaire <= 2,5 microns
Quantity: .583
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

64	47 of 120	SE/225.7	100.0 / 0.19	HERCULESCANADALTD BURLINGTON ON	NEES

Incident Date: 6/16/76
Contaminant: other oil
Amount:
Units:
Quantity:
Cause: Discharge
Source: Unknown
Reason: Intent
Sector: Service Industry

64	48 of 120	SE/225.7	100.0 / 0.19	HERCULES CANADA BURLINGTON CITY ON	NEES

Incident Date: 1/10/88
Contaminant: SMOKE
Amount: 0
Units: Process Upset
Quantity:
Cause: Equipment Failure
Source: Other Industrial Plant
Reason:
Sector: Chemical

64	49 of 120	SE/225.7	100.0 / 0.19	HERCULES CANADA BURLINGTON CITY ON	NEES

Incident Date: 4/28/88
Contaminant: SMOKE
Amount: 0
Units: Process Upset
Quantity:
Cause: Other
Source: Other Industrial Plant
Reason:
Sector: Chemical

64	50 of 120	SE/225.7	100.0 / 0.19	HERCULES CANADA BURLINGTON CITY ON	NEES

Incident Date: 7/31/88
Contaminant: SMOKE
Amount: 0

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Units:	Process Upset
Quantity:	
Cause:	Equipment Failure
Source:	Other Industrial Plant
Reason:	
Sector:	Chemical

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	51 of 120	SE/225.7	100.0 / 0.19	HERCULES CANADA BURLINGTON CITY ON	NEES

Incident Date:	10/4/88
Contaminant:	RESIN, NATURAL
Amount:	3.6
Units:	Tonnes (Metric)
Quantity:	
Cause:	Valve, Fitting Leak
Source:	Other Industrial Plant
Reason:	Error
Sector:	Chemical

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	52 of 120	SE/225.7	100.0 / 0.19	HERCULES CANADA BURLINGTON CITY ON	NEES

Incident Date:	3/16/89
Contaminant:	LUBRICATING OIL
Amount:	0
Units:	Unknown
Quantity:	
Cause:	Error
Source:	Other Industrial Plant
Reason:	
Sector:	Chemical

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	53 of 120	SE/225.7	100.0 / 0.19	HERCULES CANADA BURLINGTON CITY ON	NEES

Incident Date:	3/16/89
Contaminant:	LUBRICATING OIL
Amount:	0
Units:	Valve, Fitting Leak
Quantity:	
Cause:	Negligence
Source:	Other Industrial Plant
Reason:	
Sector:	Chemical

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	54 of 120	SE/225.7	100.0 / 0.19	HERCULESCANADALTD BURLINGTON ON	NATE

File No.:	MOE76361
Reported By:	Province
Material Reaction:	
Spill Date:	760616
Lead Agency:	
Basin:	St. Lawrence River Drainage

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Air:	
DOE on Scene:	
Land:	
Fresh Water:	
Ground Water:	
Salt Water:	
Other Environment:	
Waterbody:	RAMBO CREEK
Cause:	Discharge
Reason:	Intent
Source:	Unknown
Sector:	Service Industry
Ship No.:	
Ship Name:	
Clean Up By:	none
Disposal Method:	none
Recovery %:	0.00
Act Invoked:	Unknown
Enforcement Resp:	
Fish Kill:	N
Oiled Birds:	N
Other Kill:	N
Vegetation Damage:	N
Property Damage:	N
Drinking Water:	N
Income Loss:	N
Other Consequences:	N
No. of Injuries:	
No. of Evacuations:	
Fine:	
No. of Dead:	
Cleanup Cost:	
Material:	other oil
Amount (ton):	
Volume (L):	
Concentration:	
Phase:	
Additional Info:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	55 of 120	SE/225.7	100.0 / 0.19	HERCULES CANADA (2002) INC 942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	NPRI

NPRI ID:	3643	**Org ID:**	51249
Other ID:	*	**Submit Date:**	11/16/2004
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	73048	**Contact ID:**	152619
Report ID:	152493	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	GERRY
Report Year:	2003	**Cont Last Name:**	WILLARD
Not-Current Rpt?:	No	**Contact Position:**	PLANT MANAGER
Yr of Last Filed Rpt:	2014	**Contact Fax:**	9053333718
Fac ID:	115074	**Contact Ph.:**	9056327861
Fac Name:	NOT AVAILABLE	**Cont Area Code:**	905
Fac Address1:	942 BRANT STREET	**Contact Tel.:**	56327861
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	115
Fac Postal Zip:	L7R3X8	**Cont Fax Area Cde:**	905
Facility Lat:	43.3365	**Contact Fax:**	53333718
Facility Long:	-79.8131	**Contact Email:**	GWILLARD@HERC.COM
DLS (Last Filed Rpt):		**Latitude:**	43.334043
Facility DLS:		**Longitude:**	-79.816436
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	

URL:	www.herc.com	***UTM Easting:***	
No of Empl.:	45	***Waste Streams:***	True¿
Parent Co.:	Y	***No Streams:***	
No Parent Co.:	1	***Waste Off Sites:***	Fals
Pollut Prev Cmnts:	Fals	***No Off Sites:***	1
Stacks:	True	***Shutdown:***	True
No of Stacks:		***No of Shutdown:***	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 32
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3259
NAICS 4 Description: Other chemical product manufacturing
NAICS Code (6 digit): 325999
NAICS 6 Description: All other miscellaneous chemical product manufacturing

Substance Release Report

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: PM10 - Particulate Matter <= 10 Microns
Chem (fr): PM10 - Matière particulaire <= 10 microns
Quantity: 2.246
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Nitrogen oxides (expressed as NO2)
Chem (fr): Oxydes d'azote (exprimés en NO2)
Quantity: 30.8
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Sulphur dioxide
Chem (fr): Dioxyde de soufre
Quantity: 37.5
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 6
Category Type Desc: Road dust
Category Type Desc (fr): Poussières de routes
Grouping: Total Air
Trans Code:
Chem: PM10 - Particulate Matter <= 10 Microns
Chem (fr): PM10 - Matière particulaire <= 10 microns
Quantity: .013
Unit: tonnes

Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates
Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	.678
Unit:	tonnes
Basis of Estimate Cd:	
Basis of Estimate Desc:	

---

64 | ***56 of 120*** | ***SE/225.7*** | ***100.0 / 0.19*** | ***HERCULES CANADA***
942 BRANT STREET P. O. BOX 100
BURLINGTON ON L7R3X8 | ***NPRI***

NPRI ID:	3643	**Org ID:**	51247
Other ID:	N	**Submit Date:**	6/30/2005
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	31081	**Contact ID:**	189462
Report ID:	90958	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	MICHELE
Report Year:	2004	**Cont Last Name:**	PONGETTI
Not-Current Rpt?:	No	**Contact Position:**	HEALTH, SAFETY, ENVIRONMENT
Yr of Last Filed Rpt:	2014	**Contact Fax:**	9053333718
Fac ID:	115085	**Contact Ph.:**	9056327861
Fac Name:	BURLINGTON PLANT	**Cont Area Code:**	905
Fac Address1:	942 BRANT STREET	**Contact Tel.:**	56327861
Fac Address2:	P. O. BOX 100	**Contact Ext.:**	122
Fac Postal Zip:	L7R3X8	**Cont Fax Area Cde:**	905
Facility Lat:	43.3365	**Contact Fax:**	53333718
Facility Long:	-79.8131	**Contact Email:**	MPONGETTI@HERC.COM
DLS (Last Filed Rpt):		**Latitude:**	43.334043
Facility DLS:		**Longitude:**	-79.816436
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	True	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	38	**Waste Streams:**	False
Parent Co.:	Y	**No Streams:**	
No Parent Co.:	1	**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	True	**No Off Sites:**	1
Stacks:	No	**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3259		
NAICS 4 Description:	Other chemical product manufacturing		
NAICS Code (6 digit):	325999		
NAICS 6 Description:	All other miscellaneous chemical product manufacturing		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air

Trans Code: ASta
Chem: PM10 - Particulate Matter <= 10 Microns
Chem (fr): PM10 - Matière particulaire <= 10 microns
Quantity: 1.73
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr): PM2,5 - Matière particulaire <= 2,5 microns
Quantity: 1.167
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Methane
Chem (fr): Méthane
Quantity: .066
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Nitrous oxide
Chem (fr): Protoxyde d'azote (Oxyde nitreux)
Quantity: .063
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Volatile Organic Compounds (VOCs)
Chem (fr): Composés organiques volatils (COV)
Quantity: 1.036
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Heavy aromatic solvent naphtha
Chem (fr): Solvant naphta aromatique lourd
Quantity: .019
Unit: tonnes
Basis of Estimate Cd: O

Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: PM - Total Particulate Matter
Chem (fr): PM - Particules totales
Quantity: 1.98
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Carbon monoxide
Chem (fr): Monoxyde de carbone
Quantity: 2.571
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Carbon dioxide
Chem (fr): Dioxyde de carbone
Quantity: 3545.142
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Naphthalene
Chem (fr): Naphtalène
Quantity: .004
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Sulphur dioxide
Chem (fr): Dioxyde de soufre
Quantity: .483
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t

Trans Code:	
Chem:	MSG#2 - Hydrotreated light distillate
Chem (fr):	EMG#2 - Distillat léger hydrotraité
Quantity:	.035
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Nitrogen oxides (expressed as NO2)
Chem (fr):	Oxydes d'azote (exprimés en NO2)
Quantity:	2.932
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

64	57 of 120	SE/225.7	100.0 / 0.19	**HERCULES CANADA** **942 BRANT STREET P. O. BOX 100** **BURLINGTON ON L7R3X8**	NPRI

NPRI ID:	3643	**Org ID:**	51247
Other ID:	N	**Submit Date:**	6/1/2006
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	40367	**Contact ID:**	223936
Report ID:	100566	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	TRICIA
Report Year:	2005	**Cont Last Name:**	RENNIE
Not-Current Rpt?:	No	**Contact Position:**	ENVIRONMENTAL, SAFETY AND HEALTH LEADER
Yr of Last Filed Rpt:	2014	**Contact Fax:**	9053333718
Fac ID:	115085	**Contact Ph.:**	9056327861
Fac Name:	BURLINGTON PLANT	**Cont Area Code:**	905
Fac Address1:	942 BRANT STREET	**Contact Tel.:**	56327861
Fac Address2:	P. O. BOX 100	**Contact Ext.:**	116
Fac Postal Zip:	L7R3X8	**Cont Fax Area Cde:**	905
Facility Lat:	43.3365	**Contact Fax:**	53333718
Facility Long:	-79.8131	**Contact Email:**	TRENNIE@HERC.COM
DLS (Last Filed Rpt):		**Latitude:**	43.334043
Facility DLS:		**Longitude:**	-79.816436
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	39	**Waste Streams:**	False
Parent Co.:	Y	**No Streams:**	
No Parent Co.:	1	**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	False	**No Off Sites:**	1.00
Stacks:	False	**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3259		
NAICS 4 Description:	Other chemical product manufacturing		
NAICS Code (6 digit):	325999		
NAICS 6 Description:	All other miscellaneous chemical product manufacturing		

Substance Release Report

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Sulphur dioxide
Chem (fr): Dioxyde de soufre
Quantity: .093
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Nitrogen oxides (expressed as NO2)
Chem (fr): Oxydes d'azote (exprimés en NO2)
Quantity: 5.571
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: PM10 - Particulate Matter <= 10 Microns
Chem (fr): PM10 - Matière particulaire <= 10 microns
Quantity: 2.562
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Carbon monoxide
Chem (fr): Monoxyde de carbone
Quantity: 4.305
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: MSG#2 - Hydrotreated light distillate
Chem (fr): EMG#2 - Distillat léger hydrotraité
Quantity: .034
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air

Trans Code:	ASta
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	1.717
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM - Total Particulate Matter
Chem (fr):	PM - Particules totales
Quantity:	2.938
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

64 | ***58 of 120*** | ***SE/225.7*** | ***100.0 / 0.19*** | ***942 Brant Street Burlington ON L7R 2J7*** | ***EHS***

Order No:	20071010017	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	CAN - Complete Report	**Client Prov/State:**	
Report Date:	10/19/2007	**Search Radius (km):**	0.3
Date Received:	10/10/2007	**X:**	-79.816071
Previous Site Name:		**Y:**	43.334607
Lot/Building Size:			
Additional Info Ordered:			

64 | ***59 of 120*** | ***SE/225.7*** | ***100.0 / 0.19*** | ***HERCULES CANADA 942 BRANT STREET P. O. BOX 100 BURLINGTON ON L7R3X8*** | ***NPRI***

NPRI ID:	3643	**Org ID:**	51247
Other ID:	N	**Submit Date:**	5/31/2007
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	49130	**Contact ID:**	223936
Report ID:	110184	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	TRICIA
Report Year:	2006	**Cont Last Name:**	RENNIE
Not-Current Rpt?:	No	**Contact Position:**	ENVIRONMENTAL, SAFETY AND HEALTH LEADER
Yr of Last Filed Rpt:	2014	**Contact Fax:**	9053333718
Fac ID:	115085	**Contact Ph.:**	9056327861
Fac Name:	BURLINGTON PLANT	**Cont Area Code:**	905
Fac Address1:	942 BRANT STREET	**Contact Tel.:**	56327861
Fac Address2:	P. O. BOX 100	**Contact Ext.:**	116
Fac Postal Zip:	L7R3X8	**Cont Fax Area Cde:**	905
Facility Lat:	43.3365	**Contact Fax:**	53333718
Facility Long:	-79.8131	**Contact Email:**	TRENNIE@HERC.COM
DLS (Last Filed Rpt):		**Latitude:**	43.334043
Facility DLS:		**Longitude:**	-79.816436
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	37	**Waste Streams:**	True¿
Parent Co.:	Y	**No Streams:**	
No Parent Co.:	1	**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	False	**No Off Sites:**	1.00

Stacks: True
Shutdown:
No of Stacks:
No of Shutdown:
Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 32
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3259
NAICS 4 Description: Other chemical product manufacturing
NAICS Code (6 digit): 325999
NAICS 6 Description: All other miscellaneous chemical product manufacturing

Substance Release Report

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: PM10 - Particulate Matter <= 10 Microns
Chem (fr): PM10 - Matière particulaire <= 10 microns
Quantity: 2.334
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: n-Butyl alcohol
Chem (fr): Butan-1-ol
Quantity: 0
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Naphthalene
Chem (fr): Naphtalène
Quantity: 0
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Sodium nitrite
Chem (fr): Nitrite de sodium
Quantity: 0
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 1
Category Type Desc: Stack / Point

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr): PM2,5 - Matière particulaire <= 2,5 microns
Quantity: 1.489
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

---

64 | ***60 of 120*** | ***SE/225.7*** | ***100.0 / 0.19*** | ***Hercules Canada (2002) Inc.***
942 Brant Street Burlington Ontario L7R 2J7
Burlington
ON | ***EBR***

EBR Registry No: IA03E1744
Ministry Ref No: 5698-5RPQPK
Notice Type: Instrument Decision
Notice Stage:
Notice Date: January 30, 2004
Proposal Date: November 27, 2003
Year: 2003
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Hercules Canada (2002) Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 942 Brant Street, P.O. Box 100, Burlington Ontario, L7R 3X8
Comment Period:
URL:

Site Location Details:

942 Brant Street Burlington Ontario L7R 2J7 Burlington

---

64 | ***61 of 120*** | ***SE/225.7*** | ***100.0 / 0.19*** | ***Hercules Canada (2002) Inc.***
942 Brant Street Burlington Ontario L7R 3X8
Burlington
ON | ***EBR***

EBR Registry No: IA05E0512
Ministry Ref No: 6667-6BCSP7
Notice Type: Instrument Decision
Notice Stage:
Notice Date: March 24, 2006
Proposal Date: November 10, 2005
Year: 2005
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Hercules Canada (2002) Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 942 Brant Street, P.O. Box 100, Burlington Ontario, L7R 3X8
Comment Period:
URL:

Site Location Details:

942 Brant Street Burlington Ontario L7R 3X8 Burlington

---

64 | **62 of 120** | **SE/225.7** | **100.0 / 0.19** | **Hercules Canada Inc.**
942 Brant Street
Burlington ON L7R 2J7 | **SPL**

Ref No:	5161-5MEDHH	***Discharger Report:***	
Site No:		***Material Group:***	Chemical
Incident Dt:	5/10/2003	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	Unknown	***Sector Type:***	Other Plant
Incident Event:		***Agency Involved:***	
Contaminant Code:	27	***Nearest Watercourse:***	
Contaminant Name:	DOWTHERM	***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	Halton-Peel
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	Central
Environment Impact:	Possible	***Site Municipality:***	Burlington
Nature of Impact:	Air Pollution	***Site Lot:***	
Receiving Medium:	Air	***Site Conc:***	
Receiving Env:		***Northing:***	NA
MOE Response:		***Easting:***	NA
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	5/10/2003	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	Spill to Air
Incident Reason:	Unknown - Reason not determined	***Source Type:***	
Site Name:	HERCULES CANADA INC.		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Hecules Canada - Unkn vol DowTherm-ATM		
Contaminant Qty:			

---

64 | **63 of 120** | **SE/225.7** | **100.0 / 0.19** | **Hercules Canada Inc.**
942 Brant Street
Burlington ON L7R 2J7 | **SPL**

Ref No:	0301-65WUGJ	***Discharger Report:***	
Site No:		***Material Group:***	Chemical
Incident Dt:	10/19/2004	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	Valve / Fitting Leak Or Failure	***Sector Type:***	Other Plant
Incident Event:		***Agency Involved:***	
Contaminant Code:	27	***Nearest Watercourse:***	
Contaminant Name:	SURFACTANT (N.O.S.)	***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	Halton-Peel
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	Central
Environment Impact:	Not Anticipated	***Site Municipality:***	Burlington
Nature of Impact:		***Site Lot:***	
Receiving Medium:	Land	***Site Conc:***	
Receiving Env:		***Northing:***	NA
MOE Response:		***Easting:***	NA
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	10/19/2004	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	Spill to Land
Incident Reason:	Error- Operator error	***Source Type:***	
Site Name:	HERCULES CANADA INC.		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Hercules Can. - Oil Based Surfactant Spill		
Contaminant Qty:	454.545454545455 Kg		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

64 | **64 of 120** | **SE/225.7** | **100.0 / 0.19** | **Hercules Canada Inc.**
942 Brant Street
Burlington ON L7R 2J7 | **SPL**

Ref No:	1738-63X64V	**Discharger Report:**	
Site No:		**Material Group:**	Chemical
Incident Dt:	8/16/2004	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Container Leak (Fuel Tank Barrels)	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:	24	**Nearest Watercourse:**	
Contaminant Name:	SOLVENT (N.O.S.)	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	Halton-Peel
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	Central
Environment Impact:		**Site Municipality:**	Burlington
Nature of Impact:		**Site Lot:**	
Receiving Medium:	Water	**Site Conc:**	
Receiving Env:		**Northing:**	NA
MOE Response:		**Easting:**	NA
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	8/16/2004	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	Error- Operator error	**Source Type:**	
Site Name:	HERCULES CANADA INC.		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Hercules - 450 L of solvent to dyke.		
Contaminant Qty:	450 L		

64 | **65 of 120** | **SE/225.7** | **100.0 / 0.19** | **Hercules Canada Inc.**
942 Brant Street
Burlington ON L7R 2J7 | **SPL**

Ref No:	3030-62QJAU	**Discharger Report:**	
Site No:		**Material Group:**	Chemical
Incident Dt:	7/9/2004	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Overflow (Tanks Lagoons)	**Sector Type:**	Other
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:	Embreak 2W570	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	Halton-Peel
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	Central
Environment Impact:	Possible	**Site Municipality:**	Burlington
Nature of Impact:	Soil Contamination	**Site Lot:**	
Receiving Medium:	Land	**Site Conc:**	
Receiving Env:		**Northing:**	NA
MOE Response:		**Easting:**	NA
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	7/9/2004	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Spill to Land
Incident Reason:	Unknown - Reason not determined	**Source Type:**	
Site Name:	HERCULES CANADA INC.		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Hercules Canada-200 gal spill of Embreak2W570		
Contaminant Qty:	910 L		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	66 of 120	SE/225.7	100.0 / 0.19	942 Brant Street 942 BRANT STREET Burlington ON L7R 2J7	SPL

Ref No:	0206-6M9VBZ	**Discharger Report:**	
Site No:		**Material Group:**	Gases/Particulates
Incident Dt:	2/22/2006	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Discharge or Emission to Air	**Sector Type:**	Other Plant
Incident Event:		**Agency Involved:**	
Contaminant Code:	31	**Nearest Watercourse:**	
Contaminant Name:	SMOKE	**Site Address:**	942 BRANT STREET
Contaminant Limit 1:		**Site District Office:**	Halton-Peel
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Possible	**Site Municipality:**	Burlington
Nature of Impact:	Air Pollution	**Site Lot:**	
Receiving Medium:	Air	**Site Conc:**	
Receiving Env:		**Northing:**	NA
MOE Response:		**Easting:**	NA
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2/22/2006	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	Unknown - Reason not determined	**Source Type:**	
Site Name:	942 BRANT STREET		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Hercules Canada: orange/brown cloud to atm, unknown		
Contaminant Qty:	Not specified m3		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	67 of 120	SE/225.7	100.0 / 0.19	HERCULES CANADA 942 BRANT STREET P. O. BOX 100 BURLINGTON ON L7R3X8	NPRI

NPRI ID:	3643	**Org ID:**	51247
Other ID:	N	**Submit Date:**	6/2/2008
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	60150	**Contact ID:**	223936
Report ID:	120652	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	TRICIA
Report Year:	2007	**Cont Last Name:**	RENNIE
Not-Current Rpt?:	No	**Contact Position:**	ENVIRONMENTAL, SAFETY AND HEALTH LEADER
Yr of Last Filed Rpt:	2014	**Contact Fax:**	9053333718
Fac ID:	115085	**Contact Ph.:**	9056327861
Fac Name:	BURLINGTON PLANT	**Cont Area Code:**	905
Fac Address1:	942 BRANT STREET	**Contact Tel.:**	56327861
Fac Address2:	P. O. BOX 100	**Contact Ext.:**	116
Fac Postal Zip:	L7R3X8	**Cont Fax Area Cde:**	905
Facility Lat:	43.3365	**Contact Fax:**	53333718
Facility Long:	-79.8131	**Contact Email:**	TRENNIE@HERC.COM
DLS (Last Filed Rpt):		**Latitude:**	43.334043
Facility DLS:		**Longitude:**	-79.816436
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	37	**Waste Streams:**	True¿
Parent Co.:	Y	**No Streams:**	
No Parent Co.:	1.00	**Waste Off Sites:**	True
Pollut Prev Cmnts:	False	**No Off Sites:**	1.00
Stacks:	True	**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			

Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 32
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3259
NAICS 4 Description: Other chemical product manufacturing
NAICS Code (6 digit): 325999
NAICS 6 Description: All other miscellaneous chemical product manufacturing

Substance Release Report

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Naphthalene
Chem (fr): Naphtalène
Quantity: 0
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: MSG#1 - Solvent naphtha medium aliphatic
Chem (fr): EMG#1 - Solvant naphta aliphatique moyen
Quantity: 0
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr): PM2,5 - Matière particulaire <= 2,5 microns
Quantity: 1.334
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: PM10 - Particulate Matter <= 10 Microns
Chem (fr): PM10 - Matière particulaire <= 10 microns
Quantity: 2.178
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

64	***68 of 120***	***SE/225.7***	***100.0 / 0.19***	***Hercules Canada Inc.*** ***942 Brant St. Burlington*** ***Burlington ON L7R 2J7***	***SPL***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Ref No:	7808-7FXN2Y	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:		**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:		**Sector Type:**	Tank Truck
Incident Event:		**Agency Involved:**	
Contaminant Code:	22	**Nearest Watercourse:**	
Contaminant Name:	SODIUM HYDROXIDE (SOL'N) (CAUSTIC SODA)	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	Halton-Peel
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Possible	**Site Municipality:**	Burlington
Nature of Impact:	Soil Contamination	**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:	No Field Response	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	6/25/2008	**Site Map Datum:**	
Dt Document Closed:	6/27/2008	**SAC Action Class:**	Land Spills
Incident Reason:		**Source Type:**	

Site Name: Hercules Canada Inc<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: Hercules Can, leaking trailer Sodium Hydroxide sol'n
Contaminant Qty: 80 kg

64	69 of 120	SE/225.7	100.0 / 0.19	**Hercules Canada Inc.** **942 Brant St** **Burlington; Burlington ON L7R 2J7**	SPL

Ref No:	5462-7HGS6Y	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:		**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Other Discharges	**Sector Type:**	Other Motor Vehicle
Incident Event:		**Agency Involved:**	
Contaminant Code:	13	**Nearest Watercourse:**	
Contaminant Name:	HYDROCARBON LIGHT	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	Halton-Peel; Halton-Peel
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Confirmed	**Site Municipality:**	Burlington; Burlington
Nature of Impact:	Other Impact(s); Soil Contamination	**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	NA
MOE Response:	No Field Response	**Easting:**	NA
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	8/13/2008	**Site Map Datum:**	
Dt Document Closed:	8/25/2008	**SAC Action Class:**	Land Spills
Incident Reason:		**Source Type:**	

Site Name: Brant Street from Dundas Street to Fairview Street<UNOFFICIAL>; 942 Brant Street
Site County/District:
Site Geo Ref Meth:
Incident Summary: Jump Logistics: drum of slippery oil to ground, road, plant
Contaminant Qty: 205 L

64	70 of 120	SE/225.7	100.0 / 0.19	**HERCULES CANADA** **942 BRANT STREET P. O. BOX 100** **BURLINGTON ON L7R3X8**	NPRI

NPRI ID:	3643	**Org ID:**	51247

Other ID:	N	***Submit Date:***	5/28/2009
No Other ID:		***Last Modified:***	5/29/2015 3:28:24 PM
Track ID:	65201	***Contact ID:***	223936
Report ID:	122975	***Cont Type:***	MED
Report Type:	NPRI	***Contact Title:***	
Rpt Type ID:	1	***Cont First Name:***	TRICIA
Report Year:	2008	***Cont Last Name:***	RENNIE
Not-Current Rpt?:	No	***Contact Position:***	ENVIRONMENTAL, SAFETY AND HEALTH LEADER
Yr of Last Filed Rpt:	2014	***Contact Fax:***	9053333718
Fac ID:	115085	***Contact Ph.:***	9056327861
Fac Name:	BURLINGTON PLANT	***Cont Area Code:***	905
Fac Address1:	942 BRANT STREET	***Contact Tel.:***	56327861
Fac Address2:	P. O. BOX 100	***Contact Ext.:***	116
Fac Postal Zip:	L7R3X8	***Cont Fax Area Cde:***	905
Facility Lat:	43.3365	***Contact Fax:***	53333718
Facility Long:	-79.8131	***Contact Email:***	TRENNIE@HERC.COM
DLS (Last Filed Rpt):		***Latitude:***	43.334043
Facility DLS:		***Longitude:***	-79.816436
Datum:	1983	***UTM Zone:***	
Facility Cmnts:	No	***UTM Northing:***	
URL:		***UTM Easting:***	
No of Empl.:	36	***Waste Streams:***	No
Parent Co.:	Y	***No Streams:***	
No Parent Co.:	1	***Waste Off Sites:***	Yes
Pollut Prev Cmnts:	No	***No Off Sites:***	1
Stacks:	No	***Shutdown:***	No
No of Stacks:		***No of Shutdown:***	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3259		
NAICS 4 Description:	Other chemical product manufacturing		
NAICS Code (6 digit):	325999		
NAICS 6 Description:	All other miscellaneous chemical product manufacturing		

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Naphthalene
Chem (fr):	Naphtalène
Quantity:	0
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	1.33
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	2.175
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	71 of 120	SE/225.7	100.0 / 0.19	**Hercules Canada (2002) Inc.** **942 Brant Street** **Burlington ON**	CA

Certificate #:	5682-5K6Q99
Application Year:	2003
Issue Date:	3/20/2003
Approval Type:	Industrial Sewage Works
Status:	Revoked and/or Replaced
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	72 of 120	SE/225.7	100.0 / 0.19	**Hercules Canada (2002) Inc.** **942 Brant Street** **Burlington ON**	CA

Certificate #:	6136-5VFMR3
Application Year:	2004
Issue Date:	1/28/2004
Approval Type:	Air
Status:	Revoked and/or Replaced
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	73 of 120	SE/225.7	100.0 / 0.19	**Hercules Canada (2002) Inc.** **942 Brant Street** **Burlington ON**	CA

Certificate #:	6293-587JMD
Application Year:	2002
Issue Date:	11/8/2002
Approval Type:	Air
Status:	Revoked and/or Replaced
Application Type:	
Client Name:	
Client Address:	
Client City:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Client Postal Code:					
Project Description:					
Contaminants:					
Emission Control:					

64	74 of 120	SE/225.7	100.0 / 0.19	**Hercules Canada (2002) Inc.** **942 Brant Street** **Burlington ON**	CA

Certificate #:	7123-6H3JVY
Application Year:	2006
Issue Date:	3/3/2006
Approval Type:	Air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

64	75 of 120	SE/225.7	100.0 / 0.19	**Hercules Canada (2002) Inc.** **942 Brant Street** **Burlington ON**	CA

Certificate #:	8-300-064-77-776
Application Year:	2002
Issue Date:	11/8/2002
Approval Type:	Air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

64	76 of 120	SE/225.7	100.0 / 0.19	**Hercules Canada (2002) Inc.** **942 Brant Street** **Burlington ON**	CA

Certificate #:	8-3062-83-006
Application Year:	2002
Issue Date:	11/8/2002
Approval Type:	Air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	77 of 120	SE/225.7	100.0 / 0.19	Hercules Canada (2002) Inc. 942 Brant Street Burlington ON	CA

Certificate #: 8413-5JRKW4
Application Year: 2003
Issue Date: 12/4/2003
Approval Type: Air
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	78 of 120	SE/225.7	100.0 / 0.19	Hercules Canada (2002) Inc. 942 Brant Street Burlington ON	CA

Certificate #: 8413-5JRKW4
Application Year: 2003
Issue Date: 5/23/2003
Approval Type: Air
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	79 of 120	SE/225.7	100.0 / 0.19	ASHLAND CANADA CORPORATION 942 BRANT STREET P. O. BOX 100 BURLINGTON ON L7R3X8	NPRI

NPRI ID: 3643
Other ID: N
No Other ID:
Track ID: 81917
Report ID: 135682
Report Type: NPRI
Rpt Type ID: 1
Report Year: 2009
Not-Current Rpt?: No
Yr of Last Filed Rpt: 2014
Fac ID: 115085
Fac Name: BURLINGTON PLANT
Fac Address1: 942 BRANT STREET
Fac Address2: P. O. BOX 100
Fac Postal Zip: L7R3X8
Facility Lat: 43.3365
Facility Long: -79.8131
DLS (Last Filed Rpt):
Facility DLS:
Datum: 1983
Facility Cmnts: No

Org ID: 37699
Submit Date: 6/28/2010
Last Modified: 5/29/2015 3:28:24 PM
Contact ID: 223934
Cont Type: MED
Contact Title:
Cont First Name: TRICIA
Cont Last Name: RENNIE
Contact Position: ENVIRONMENTAL, SAFETY AND HEALTH LEADER
Contact Fax: 9053333718
Contact Ph.: 9056327861
Cont Area Code: 905
Contact Tel.: 56327861
Contact Ext.: 116
Cont Fax Area Cde: 905
Contact Fax: 53333718
Contact Email: TRENNIE@ASHLAND.COM
Latitude: 43.334043
Longitude: -79.816436
UTM Zone:
UTM Northing:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

URL:		**UTM Easting:**	
No of Empl.:	38	**Waste Streams:**	No
Parent Co.:	Y	**No Streams:**	
No Parent Co.:	1	**Waste Off Sites:**	Yes
Pollut Prev Cmnts:	No	**No Off Sites:**	1
Stacks:	No	**Shutdown:**	No
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 32
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3259
NAICS 4 Description: Other chemical product manufacturing
NAICS Code (6 digit): 325999
NAICS 6 Description: All other miscellaneous chemical product manufacturing

Substance Release Report

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Naphthalene
Chem (fr): Naphtalène
Quantity: 0
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr): PM2,5 - Matière particulaire <= 2,5 microns
Quantity: 1.327
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: PM10 - Particulate Matter <= 10 Microns
Chem (fr): PM10 - Matière particulaire <= 10 microns
Quantity: 2.173
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

64	80 of 120	SE/225.7	100.0 / 0.19	***Ashland Canada Corp.*** ***942 Brant Street Burlington, Regional Municipality of Halton L7R 2J7 CITY OF BURLINGTON*** ***ON***	EBR

EBR Registry No:	011-3757	**Decision Posted:**	
Ministry Ref No:	4643-8H2J58	**Exception Posted:**	

Notice Type:	Instrument Decision	**Section:**	
Notice Stage:		**Act 1:**	
Notice Date:	September 13, 2012	**Act 2:**	
Proposal Date:	June 06, 2011	**Site Location Map:**	
Year:	2011		
Instrument Type:	(EPA Part II.1-air) - Environmental Compliance Approval (project type: air)		
Off Instrument Name:			
Posted By:			
Company Name:	Ashland Canada Corp.		
Site Address:			
Location Other:			
Proponent Name:			
Proponent Address:	942 Brant Street, Post Office Box Delivery 100, Burlington Ontario, Canada L7R 3X8		
Comment Period:			
URL:			

Site Location Details:

942 Brant Street Burlington, Regional Municipality of Halton L7R 2J7 CITY OF BURLINGTON

---

64 | **81 of 120** | **SE/225.7** | **100.0 / 0.19** | **ASHLAND CANADA CORP.**
942 BRANT STREET NOT AVAILABLE
BURLINGTON ON L7R3X8 | **NPRI**

NPRI ID:	3643	**Org ID:**	37696
Other ID:	Y	**Submit Date:**	6/17/2011
No Other ID:	2	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	91091	**Contact ID:**	
Report ID:	145150	**Cont Type:**	
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	2010	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2014	**Contact Fax:**	
Fac ID:	223559	**Contact Ph.:**	
Fac Name:	BURLINGTON PLANT	**Cont Area Code:**	
Fac Address1:	942 BRANT STREET	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	L7R3X8	**Cont Fax Area Cde:**	
Facility Lat:	43.3365	**Contact Fax:**	
Facility Long:	-79.8131	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.334043
Facility DLS:		**Longitude:**	-79.816436
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	No	**UTM Northing:**	
URL:	www.ashland.com	**UTM Easting:**	
No of Empl.:	38	**Waste Streams:**	No
Parent Co.:	Y	**No Streams:**	
No Parent Co.:	1	**Waste Off Sites:**	Yes
Pollut Prev Cmnts:	No	**No Off Sites:**	1
Stacks:	No	**Shutdown:**	No
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3259		
NAICS 4 Description:	Other chemical product manufacturing		
NAICS Code (6 digit):	325999		
NAICS 6 Description:	All other miscellaneous chemical product manufacturing		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Substance Release Report

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Naphthalene
Chem (fr): Naphtalène
Quantity: 0
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr): PM2,5 - Matière particulaire <= 2,5 microns
Quantity: 1.325
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: PM10 - Particulate Matter <= 10 Microns
Chem (fr): PM10 - Matière particulaire <= 10 microns
Quantity: 2.17
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	82 of 120	SE/225.7	100.0 / 0.19	Ashland Canada Corp. 942 BRANT STREET BURLINGTON ON	GEN

Generator No: ON0096300
SIC Code: 325999
SIC Description: All Other Miscellaneous Chemical Product Manufacturing
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

64	***83 of 120***	***SE/225.7***	***100.0 / 0.19***	***Ashland Canada Corp.*** ***942 Brant St Ashland*** ***Burlington ON L7R 2J7***	***ECA***

Approval No: 3448-8PJRH9 ***MOE District:***

Approval Date:	9/7/2012	**City:**	Burlington
Status:	Approved	**Longitude:**	
Record Type:		**Latitude:**	
Link Source:		**Geometry X:**	
SWP Area Name:		**Geometry Y:**	
Approval Type:			
Project Type:	Air/Noise		
Business Name:			
Address:			
Full Address:			
Full PDF Link:			
PDF Site Location:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	84 of 120	SE/225.7	100.0 / 0.19	ASHLAND CANADA CORP. 942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	NPRI

NPRI ID:	3643	**Org ID:**	37696
Other ID:		**Submit Date:**	3/8/2013
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	78529	**Contact ID:**	
Report ID:	10794	**Cont Type:**	
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	2011	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2014	**Contact Fax:**	
Fac ID:	223559	**Contact Ph.:**	
Fac Name:	BURLINGTON PLANT	**Cont Area Code:**	
Fac Address1:	942 BRANT STREET	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	L7R3X8	**Cont Fax Area Cde:**	
Facility Lat:	43.3365	**Contact Fax:**	
Facility Long:	-79.8131	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.334043
Facility DLS:		**Longitude:**	-79.816436
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:	www.ashland.com	**UTM Easting:**	
No of Empl.:	28	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3259		
NAICS 4 Description:	Other chemical product manufacturing		
NAICS Code (6 digit):	325999		
NAICS 6 Description:	All other miscellaneous chemical product manufacturing		

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	

Chem:	Naphthalene
Chem (fr):	Naphtalène
Quantity:	.0001
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	1.322
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	2.167
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	85 of 120	SE/225.7	100.0 / 0.19	**Ashland Canada Corp.** **942 BRANT STREET** **BURLINGTON ON**	GEN

Generator No:	ON0096300
SIC Code:	325999
SIC Description:	All Other Miscellaneous Chemical Product Manufacturing
Approval Years:	2010
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	268
Waste Class Name:	AMINES
Waste Class:	233
Waste Class Name:	OTHER POLYMERIC WASTES
Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS
Waste Class:	122
Waste Class Name:	ALKALINE WASTES - OTHER METALS

Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS
Waste Class:	221
Waste Class Name:	LIGHT FUELS
Waste Class:	263
Waste Class Name:	ORGANIC LABORATORY CHEMICALS
Waste Class:	232
Waste Class Name:	POLYMERIC RESINS
Waste Class:	113
Waste Class Name:	ACID WASTE - OTHER METALS
Waste Class:	269
Waste Class Name:	NON-HALOGENATED PESTICIDES
Waste Class:	146
Waste Class Name:	OTHER SPECIFIED INORGANICS
Waste Class:	270
Waste Class Name:	OTHER SPECIFIED ORGANICS
Waste Class:	242
Waste Class Name:	HALOGENATED PESTICIDES
Waste Class:	112
Waste Class Name:	ACID WASTE - HEAVY METALS
Waste Class:	253
Waste Class Name:	EMULSIFIED OILS
Waste Class:	211
Waste Class Name:	AROMATIC SOLVENTS
Waste Class:	243
Waste Class Name:	PCBS
Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES
Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES
Waste Class:	267
Waste Class Name:	ORGANIC ACIDS
Waste Class:	331
Waste Class Name:	WASTE COMPRESSED GASES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	86 of 120	SE/225.7	100.0 / 0.19	**Ashland Canada Corp.** **942 BRANT STREET** **BURLINGTON ON**	GEN

Generator No:	ON0096300
SIC Code:	325999
SIC Description:	All Other Miscellaneous Chemical Product Manufacturing
Approval Years:	2011
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	

Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 268
Waste Class Name: AMINES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	87 of 120	SE/225.7	100.0 / 0.19	Ashland Canada Corp. 942 BRANT STREET BURLINGTON ON L7R 3X8	GEN

Generator No: ON0096300
SIC Code: 325999
SIC Description: All Other Miscellaneous Chemical Product Manufacturing
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class:	211
Waste Class Name:	AROMATIC SOLVENTS
Waste Class:	263
Waste Class Name:	ORGANIC LABORATORY CHEMICALS
Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES
Waste Class:	331
Waste Class Name:	WASTE COMPRESSED GASES
Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS
Waste Class:	253
Waste Class Name:	EMULSIFIED OILS
Waste Class:	233
Waste Class Name:	OTHER POLYMERIC WASTES
Waste Class:	268
Waste Class Name:	AMINES
Waste Class:	221
Waste Class Name:	LIGHT FUELS

64 | ***88 of 120*** | ***SE/225.7*** | ***100.0 / 0.19*** | ***ASHLAND CANADA CORP.***
942 BRANT STREET NOT AVAILABLE
BURLINGTON ON L7R3X8 | ***NPRI***

NPRI ID:	3643	***Org ID:***	37696
Other ID:		***Submit Date:***	6/2/2014
No Other ID:		***Last Modified:***	5/29/2015 3:28:24 PM
Track ID:	122933	***Contact ID:***	232651
Report ID:	41027	***Cont Type:***	MED
Report Type:	NPRI	***Contact Title:***	
Rpt Type ID:	1	***Cont First Name:***	
Report Year:	2012	***Cont Last Name:***	
Not-Current Rpt?:	No	***Contact Position:***	
Yr of Last Filed Rpt:	2014	***Contact Fax:***	
Fac ID:	223559	***Contact Ph.:***	
Fac Name:	BURLINGTON PLANT	***Cont Area Code:***	
Fac Address1:	942 BRANT STREET	***Contact Tel.:***	
Fac Address2:	NOT AVAILABLE	***Contact Ext.:***	
Fac Postal Zip:	L7R3X8	***Cont Fax Area Cde:***	
Facility Lat:	43.3365	***Contact Fax:***	
Facility Long:	-79.8131	***Contact Email:***	
DLS (Last Filed Rpt):		***Latitude:***	43.334043
Facility DLS:		***Longitude:***	-79.816436
Datum:	1983	***UTM Zone:***	
Facility Cmnts:		***UTM Northing:***	
URL:	www.ashland.com	***UTM Easting:***	
No of Empl.:	25	***Waste Streams:***	
Parent Co.:		***No Streams:***	
No Parent Co.:		***Waste Off Sites:***	
Pollut Prev Cmnts:		***No Off Sites:***	
Stacks:		***Shutdown:***	
No of Stacks:		***No of Shutdown:***	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		

NAICS 2 Description:	Manufacturing
NAICS Code (4 digit):	3259
NAICS 4 Description:	Other chemical product manufacturing
NAICS Code (6 digit):	325999
NAICS 6 Description:	All other miscellaneous chemical product manufacturing

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Hydrochloric acid
Chem (fr):	Acide chlorhydrique
Quantity:	.062
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	1.294
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	2
Category Type Desc:	Storage / Handling
Category Type Desc (fr):	Rejets de stockage ou manutention
Grouping:	Total Air
Trans Code:	VOCg
Chem:	Sodium nitrite
Chem (fr):	Nitrite de sodium
Quantity:	.044
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	2.127
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

---

64 | ***89 of 120*** | ***SE/225.7*** | ***100.0 / 0.19*** | ***ASHLAND***
942 BRANT ST
BURLINGTON ON L7R2J7 | ***CHM***

Headcode:	00273600
Headcode Desc:	CHEMICALS
Phone:	9056327861
List Name:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Description:					

64 **90 of 120** **SE/225.7** **100.0 / 0.19** **942 Brant**
Burlington ON L7RSJ7 **EHS**

Order No:	20140408002	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Site Report	**Client Prov/State:**	NY
Report Date:	09-APR-14	**Search Radius (km):**	.001
Date Received:	08-APR-14	**X:**	-79.816262
Previous Site Name:		**Y:**	43.334487
Lot/Building Size:			
Additional Info Ordered:			

64 **91 of 120** **SE/225.7** **100.0 / 0.19** **Solenis Canada ULC**
942 BRANT STREET
BURLINGTON ON **GEN**

Generator No:	ON0096300
SIC Code:	325999
SIC Description:	ALL OTHER MISCELLANEOUS CHEMICAL PRODUCT MANUFACTURING
Approval Years:	2013
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	268
Waste Class Name:	AMINES
Waste Class:	122
Waste Class Name:	ALKALINE WASTES - OTHER METALS
Waste Class:	331
Waste Class Name:	WASTE COMPRESSED GASES
Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES
Waste Class:	270
Waste Class Name:	OTHER SPECIFIED ORGANICS
Waste Class:	135
Waste Class Name:	REACTIVE ANION WASTES
Waste Class:	262
Waste Class Name:	DETERGENTS/SOAPS
Waste Class:	112
Waste Class Name:	ACID WASTE - HEAVY METALS
Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS
Waste Class:	241

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Name:	HALOGENATED SOLVENTS
Waste Class:	232
Waste Class Name:	POLYMERIC RESINS
Waste Class:	211
Waste Class Name:	AROMATIC SOLVENTS
Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS
Waste Class:	243
Waste Class Name:	PCBS
Waste Class:	222
Waste Class Name:	HEAVY FUELS
Waste Class:	233
Waste Class Name:	OTHER POLYMERIC WASTES
Waste Class:	146
Waste Class Name:	OTHER SPECIFIED INORGANICS
Waste Class:	267
Waste Class Name:	ORGANIC ACIDS
Waste Class:	113
Waste Class Name:	ACID WASTE - OTHER METALS
Waste Class:	123
Waste Class Name:	ALKALINE PHOSPHATES
Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES
Waste Class:	263
Waste Class Name:	ORGANIC LABORATORY CHEMICALS
Waste Class:	114
Waste Class Name:	OTHER INORGANIC ACID WASTES
Waste Class:	269
Waste Class Name:	NON-HALOGENATED PESTICIDES
Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS
Waste Class:	242
Waste Class Name:	HALOGENATED PESTICIDES
Waste Class:	253
Waste Class Name:	EMULSIFIED OILS
Waste Class:	266
Waste Class Name:	PHENOLIC WASTES
Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	221
Waste Class Name:	LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	*92 of 120*	*SE/225.7*	*100.0 / 0.19*	***ASHLAND CANADA CORP.*** ***942 BRANT STREET NOT AVAILABLE*** ***BURLINGTON ON L7R3X8***	***NPRI***

NPRI ID:	3643	**Org ID:**	37696
Other ID:		**Submit Date:**	12/29/2014
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	124768	**Contact ID:**	
Report ID:	42437	**Cont Type:**	
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	2013	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2014	**Contact Fax:**	
Fac ID:	223559	**Contact Ph.:**	
Fac Name:	BURLINGTON PLANT	**Cont Area Code:**	
Fac Address1:	942 BRANT STREET	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	L7R3X8	**Cont Fax Area Cde:**	
Facility Lat:	43.3365	**Contact Fax:**	
Facility Long:	-79.8131	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.334043
Facility DLS:		**Longitude:**	-79.816436
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:	www.ashland.com	**UTM Easting:**	
No of Empl.:	24	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3259		
NAICS 4 Description:	Other chemical product manufacturing		
NAICS Code (6 digit):	325999		
NAICS 6 Description:	All other miscellaneous chemical product manufacturing		

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Ethylene glycol
Chem (fr):	Éthylèneglycol
Quantity:	.0001
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	1.325
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Sodium nitrite
Chem (fr):	Nitrite de sodium
Quantity:	.051
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	2.17
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	93 of 120	SE/225.7	100.0 / 0.19	ASHLAND CANADA CORP. 942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	NPRI

NPRI ID:	3643	**Org ID:**	37696
Other ID:		**Submit Date:**	4/24/2015
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	125911	**Contact ID:**	
Report ID:	48154	**Cont Type:**	
Report Type:	Sale/Purchase/Closure	**Contact Title:**	
Rpt Type ID:	3	**Cont First Name:**	
Report Year:	2014	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2014	**Contact Fax:**	
Fac ID:	223559	**Contact Ph.:**	
Fac Name:	BURLINGTON PLANT	**Cont Area Code:**	
Fac Address1:	942 BRANT STREET	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	L7R3X8	**Cont Fax Area Cde:**	
Facility Lat:	43.3365	**Contact Fax:**	
Facility Long:	-79.8131	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.334043
Facility DLS:		**Longitude:**	-79.816436
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:	www.ashland.com	**UTM Easting:**	
No of Empl.:		**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3259		
NAICS 4 Description:	Other chemical product manufacturing		

NAICS Code (6 digit): 325999
NAICS 6 Description: All other miscellaneous chemical product manufacturing

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	94 of 120	SE/225.7	100.0 / 0.19	SOLENIS CANADA ULC 942 BRANT STREET NOT AVAILABLE BURLINGTON ON L7R3X8	NPRI

NPRI ID:	3643	**Org ID:**	103465
Other ID:		**Submit Date:**	6/1/2015
No Other ID:		**Last Modified:**	6/10/2015 10:59:04 AM
Track ID:	130562	**Contact ID:**	230267
Report ID:	56569	**Cont Type:**	MEM
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	2014	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2014	**Contact Fax:**	
Fac ID:	223559	**Contact Ph.:**	
Fac Name:	BURLINGTON PLANT	**Cont Area Code:**	
Fac Address1:	942 BRANT STREET	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	L7R3X8	**Cont Fax Area Cde:**	
Facility Lat:	43.3365	**Contact Fax:**	
Facility Long:	-79.8131	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.334043
Facility DLS:		**Longitude:**	-79.816436
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:	solenis.com	**UTM Easting:**	
No of Empl.:	25	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 32
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3259
NAICS 4 Description: Other chemical product manufacturing
NAICS Code (6 digit): 325999
NAICS 6 Description: All other miscellaneous chemical product manufacturing

Substance Release Report

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Ethylene glycol
Chem (fr): Éthylèneglycol
Quantity: .0001
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Trans Code:
Chem: Sodium nitrite
Chem (fr): Nitrite de sodium
Quantity: .045
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

---

64 | 95 of 120 | SE/225.7 | 100.0 / 0.19 | SOLENIS CANADA
942 BRANT ST
BURLINGTON ON L7R2J7 | CHM

Headcode: 00273600
Headcode Desc: CHEMICALS
Phone: 9056321958
List Name: INFO-DIRECT(TM) BUSINESS FILE
Description:

---

64 | 96 of 120 | SE/225.7 | 100.0 / 0.19 | Solenis Canada ULC
942 Brant St
Burlington ON L7R 2J7 | SPL

Ref No: 4083-ACNTLM
Site No: 7401-9Z9HDK
Incident Dt: 2016/08/09
Year:
Incident Cause:
Incident Event: Operator/Human error
Contaminant Code: 15
Contaminant Name: PARAFFINIC OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact:
Nature of Impact:
Receiving Medium:
Receiving Env: Land
MOE Response: No
Dt MOE Arvl on Scn:
MOE Reported Dt: 2016/08/09
Dt Document Closed:
Incident Reason: Operator/Human Error
Site Name: Solenis Canada ULC
Site County/District:
Site Geo Ref Meth: 1-10 metres eg. Good Quality GPS
Incident Summary: Solenis: 4000 kg of Parrafinic oil to concrete/soil: contd & clng
Contaminant Qty: 4000 kg

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type: Miscellaneous Industrial
Agency Involved:
Nearest Watercourse:
Site Address: 942 Brant St
Site District Office:
Site Postal Code: L7R 2J7
Site Region:
Site Municipality: Burlington
Site Lot:
Site Conc:
Northing: 4798181
Easting: 596379
Site Geo Ref Accu: GPS
Site Map Datum: NAD83
SAC Action Class: Land Spills
Source Type:

---

64 | 97 of 120 | SE/225.7 | 100.0 / 0.19 | Hercules Canada (2002) Inc.
942 Brant St
Burlington ON L7R 3X8 | ECA

Approval No: 5682-5K6Q99
Approval Date: 2003-03-20
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
Approval Type: ECA-INDUSTRIAL SEWAGE WORKS
Project Type: INDUSTRIAL SEWAGE WORKS
Business Name: Hercules Canada (2002) Inc.

MOE District: Halton-Peel
City:
Longitude: -79.81651
Latitude: 43.337975
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Address: 942 Brant St
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/4932-5DNM6X-14.pdf
PDF Site Location:

---

64 **98 of 120** **SE/225.7** **100.0 / 0.19** **Hercules Canada (2002) Inc.** **ECA**
942 Brant Street
Burlington ON L7R 3X8

Approval No: 8413-5JRKW4
Approval Date: 2003-11-27
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Hercules Canada (2002) Inc.
Address: 942 Brant Street
Full Address:
Full PDF Link:
PDF Site Location:

MOE District: Halton-Peel
City:
Longitude: -79.81117
Latitude: 43.33029
Geometry X:
Geometry Y:

---

64 **99 of 120** **SE/225.7** **100.0 / 0.19** **Hercules Canada Inc.** **ECA**
942 Brant St
Burlington ON L7R 3X8

Approval No: 2119-4ZENQD
Approval Date: 2002-03-13
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Hercules Canada Inc.
Address: 942 Brant St
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/6413-4YZPUV-14.pdf
PDF Site Location:

MOE District: Halton-Peel
City:
Longitude: -79.81651
Latitude: 43.337975
Geometry X:
Geometry Y:

---

64 **100 of 120** **SE/225.7** **100.0 / 0.19** **Hercules Canada** **ECA**
942 Brant St
Burlington ON L7R 3X8

Approval No: 8-300-064-77-776
Approval Date: 2000-12-08
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Hercules Canada
Address: 942 Brant St
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7070-4QQMRA-14.pdf
PDF Site Location:

MOE District: Halton-Peel
City:
Longitude: -79.81651
Latitude: 43.337975
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	101 of 120	SE/225.7	100.0 / 0.19	Hercules Canada (2002) Inc. 942 Brant St Burlington ON L6H 5R7	ECA

Approval No: 6293-587JMD
Approval Date: 2002-11-08
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Hercules Canada (2002) Inc.
Address: 942 Brant St
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/8663-5C3JFG-14.pdf
PDF Site Location:
MOE District: Halton-Peel
City:
Longitude: -79.81651
Latitude: 43.337975
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	102 of 120	SE/225.7	100.0 / 0.19	Hercules Canada Inc. 942 Brant St Burlington ON L7R 3X8	ECA

Approval No: 6293-587JMD
Approval Date: 2002-03-13
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Hercules Canada Inc.
Address: 942 Brant St
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3849-586TRU-14.pdf
PDF Site Location:
MOE District: Halton-Peel
City:
Longitude: -79.81651
Latitude: 43.337975
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	103 of 120	SE/225.7	100.0 / 0.19	Hercules Canada Inc. 942 Brant St Burlington ON L7R 3X8	ECA

Approval No: 1976-579RVZ
Approval Date: 2002-03-13
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Hercules Canada Inc.
Address: 942 Brant St
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2444-574K7S-14.pdf
PDF Site Location:
MOE District: Halton-Peel
City:
Longitude: -79.81651
Latitude: 43.337975
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	104 of 120	SE/225.7	100.0 / 0.19	Hercules Canada (2002) Inc. 942 Brant Street Burlington ON L7R 3X8	ECA

Approval No: 7123-6H3JVY
Approval Date: 2006-03-03
Status: Revoked and/or Replaced
MOE District: Halton-Peel
City:
Longitude: -79.81117

Record Type:	ECA	**Latitude:**	43.33029
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Halton	**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	Hercules Canada (2002) Inc.		
Address:	942 Brant Street		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/6667-6BCSP7-14.pdf		
PDF Site Location:			

---

64 | ***105 of 120*** | ***SE/225.7*** | ***100.0 / 0.19*** | ***Hercules Canada (2002) Inc.***
942 Brant Street
Burlington ON L7R 3X8 | ***ECA***

Approval No:	6136-5VFMR3	**MOE District:**	Halton-Peel
Approval Date:	2004-01-28	**City:**	
Status:	Revoked and/or Replaced	**Longitude:**	-79.80659
Record Type:	ECA	**Latitude:**	43.331657
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Halton	**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	Hercules Canada (2002) Inc.		
Address:	942 Brant Street		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/5698-5RPQPK-14.pdf		
PDF Site Location:			

---

64 | ***106 of 120*** | ***SE/225.7*** | ***100.0 / 0.19*** | ***Hercules Canada (2002) Inc.***
942 Brant St
Burlington ON L6H 5R7 | ***ECA***

Approval No:	8-300-064-77-776	**MOE District:**	Halton-Peel
Approval Date:	2002-11-08	**City:**	
Status:	Approved	**Longitude:**	-79.81651
Record Type:	ECA	**Latitude:**	43.337975
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Halton	**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	Hercules Canada (2002) Inc.		
Address:	942 Brant St		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/7484-5C3LC8-14.pdf		
PDF Site Location:			

---

64 | ***107 of 120*** | ***SE/225.7*** | ***100.0 / 0.19*** | ***Hercules Canada (2002) Inc.***
942 Brant Street
Burlington ON L7R 3X8 | ***ECA***

Approval No:	8413-5JRKW4	**MOE District:**	Halton-Peel
Approval Date:	2003-12-04	**City:**	
Status:	Revoked and/or Replaced	**Longitude:**	-79.81117
Record Type:	ECA	**Latitude:**	43.33029
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Halton	**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	Hercules Canada (2002) Inc.		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Address: 942 Brant Street
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/6535-5TUTRG-14.pdf
PDF Site Location:

---

64 | ***108 of 120*** | ***SE/225.7*** | ***100.0 / 0.19*** | ***Hercules Canada (2002) Inc.***
942 Brant St
Burlington ON L7R 3X8 | ***ECA***

Approval No: 8413-5JRKW4
Approval Date: 2003-05-23
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Hercules Canada (2002) Inc.
Address: 942 Brant St
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3329-5FENN3-14.pdf
PDF Site Location:
MOE District: Halton-Peel
City:
Longitude: -79.81651
Latitude: 43.337975
Geometry X:
Geometry Y:

---

64 | ***109 of 120*** | ***SE/225.7*** | ***100.0 / 0.19*** | ***Hercules Canada Inc.***
942 Brant St
Burlington ON L7R 3X8 | ***ECA***

Approval No: 8-3062-83-006
Approval Date: 2000-11-06
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Hercules Canada Inc.
Address: 942 Brant St
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3058-4QAHW5-14.pdf
PDF Site Location:
MOE District: Halton-Peel
City:
Longitude: -79.81651
Latitude: 43.337975
Geometry X:
Geometry Y:

---

64 | ***110 of 120*** | ***SE/225.7*** | ***100.0 / 0.19*** | ***Ashland Canada Corp.***
942 Brant St Ashland
Burlington ON L7R 3X8 | ***ECA***

Approval No: 3448-8PJRH9
Approval Date: 2012-09-07
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Ashland Canada Corp.
Address: 942 Brant St Ashland
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/4643-8H2J58-14.pdf
PDF Site Location:
MOE District: Halton-Peel
City:
Longitude: -79.81117
Latitude: 43.33029
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	111 of 120	SE/225.7	100.0 / 0.19	Hercules Canada (2002) Inc. 942 Brant St Burlington ON L6H 5R7	ECA

Approval No: 8-3062-83-006
Approval Date: 2002-11-08
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
MOE District: Halton-Peel
City:
Longitude: -79.81651
Latitude: 43.337975
Geometry X:
Geometry Y:
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Hercules Canada (2002) Inc.
Address: 942 Brant St
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7745-5C3JXK-14.pdf
PDF Site Location:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	112 of 120	SE/225.7	100.0 / 0.19	Solenis Canada ULC 942 BRANT STREET BURLINGTON ON L7R 3X8	GEN

Generator No: ON0096300
SIC Code: 325999
SIC Description: ALL OTHER MISCELLANEOUS CHEMICAL PRODUCT MANUFACTURING
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: James Faulstich
Choice of Contact: CO_OFFICIAL
Phone No Admin: 8046298299 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 135
Waste Class Name: REACTIVE ANION WASTES

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 123
Waste Class Name: ALKALINE PHOSPHATES

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 114
Waste Class Name: OTHER INORGANIC ACID WASTES

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 266
Waste Class Name: PHENOLIC WASTES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	113 of 120	SE/225.7	100.0 / 0.19	Solenis Canada ULC 942 BRANT STREET BURLINGTON ON L7R 3X8	GEN

Generator No: ON0096300
SIC Code: 325999
SIC Description: ALL OTHER MISCELLANEOUS CHEMICAL PRODUCT MANUFACTURING
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: James Faulstich
Choice of Contact: CO_OFFICIAL
Phone No Admin: 8046298299 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 114
Waste Class Name: OTHER INORGANIC ACID WASTES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 123
Waste Class Name: ALKALINE PHOSPHATES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 266
Waste Class Name: PHENOLIC WASTES

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 135
Waste Class Name: REACTIVE ANION WASTES

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

---

64 | ***114 of 120*** | ***SE/225.7*** | ***100.0 / 0.19*** | ***Solenis Canada ULC***
942 BRANT STREET
BURLINGTON ON L7R 2J7 | ***GEN***

Generator No: ON0096300
SIC Code: 325999
SIC Description: ALL OTHER MISCELLANEOUS CHEMICAL PRODUCT MANUFACTURING
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Kara Long
Choice of Contact: CO_OFFICIAL
Phone No Admin: 614-790-4641 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 114
Waste Class Name: OTHER INORGANIC ACID WASTES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 266
Waste Class Name: PHENOLIC WASTES

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 123
Waste Class Name: ALKALINE PHOSPHATES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 135
Waste Class Name: REACTIVE ANION WASTES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

---

64 | ***115 of 120*** | ***SE/225.7*** | ***100.0 / 0.19*** | ***Solenis Canada ULC***
942 BRANT STREET
BURLINGTON ON L7R 3X8 | ***GEN***

Generator No: ON0096300
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No: 100
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 112 L
Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 122 L
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 L
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 T
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 213 L
Waste Class Name: Petroleum distillates

Waste Class: 213 T
Waste Class Name: Petroleum distillates

Waste Class: 233 L
Waste Class Name: Other polymeric wastes

Waste Class: 241 L
Waste Class Name: Halogenated solvents and residues

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 262 C
Waste Class Name: Detergents and soaps

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Class: 263 C
Waste Class Name: Misc. waste organic chemicals

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 263 T
Waste Class Name: Misc. waste organic chemicals

Waste Class: 265 L
Waste Class Name: Graphic arts wastes

Waste Class: 267 C
Waste Class Name: Organic acids

Waste Class: 267 L
Waste Class Name: Organic acids

Waste Class: 268 C
Waste Class Name: Amines

Waste Class: 268 I
Waste Class Name: Amines

Waste Class: 268 L
Waste Class Name: Amines

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

---

64 | **116 of 120** | **SE/225.7** | **100.0 / 0.19** | **Solenis Canada ULC**
942 BRANT STREET NOT AVAILABLE
BURLINGTON ON L7R3X8 | **NPRI**

NPRI ID:	3643	**Org ID:**	107759
Other ID:		**Submit Date:**	5/30/2016
No Other ID:		**Last Modified:**	11/18/2016 8:28:05 AM
Track ID:	140187	**Contact ID:**	236893
Report ID:	74885	**Cont Type:**	MEM
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	Arturo
Report Year:	2015	**Cont Last Name:**	Pena
Not-Current Rpt?:	No	**Contact Position:**	EHS Engineer
Yr of Last Filed Rpt:	2014	**Contact Fax:**	
Fac ID:	223559	**Contact Ph.:**	9056327861
Fac Name:	BURLINGTON PLANT	**Cont Area Code:**	905
Fac Address1:	942 BRANT STREET	**Contact Tel.:**	56327861
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	2116
Fac Postal Zip:	L7R3X8	**Cont Fax Area Cde:**	
Facility Lat:	43.3365	**Contact Fax:**	
Facility Long:	-79.8131	**Contact Email:**	mpongetti@solenis.com
DLS (Last Filed Rpt):		**Latitude:**	43.334043
Facility DLS:		**Longitude:**	-79.816436
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	25	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3259		
NAICS 4 Description:	Other chemical product manufacturing		
NAICS Code (6 digit):	325999		
NAICS 6 Description:	All other miscellaneous chemical product manufacturing		

Substance Release Report

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias

Grouping:	Total All Media<1t
Trans Code:	
Chem:	
Chem (fr):	
Quantity:	.0001
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

64 | **117 of 120** | **SE/225.7** | **100.0 / 0.19** | **ASHLAND CANADA CORP.**
942 BRANT STREET NOT AVAILABLE
BURLINGTON ON L7R3X8 | **NPRI**

NPRI ID:	3643	**Org ID:**	37696
Other ID:		**Submit Date:**	6/2/2014
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	120288	**Contact ID:**	
Report ID:	40641	**Cont Type:**	
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	2013	**Cont Last Name:**	
Not-Current Rpt?:	Yes	**Contact Position:**	
Yr of Last Filed Rpt:	2014	**Contact Fax:**	
Fac ID:	223559	**Contact Ph.:**	
Fac Name:	BURLINGTON PLANT	**Cont Area Code:**	
Fac Address1:	942 BRANT STREET	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	L7R3X8	**Cont Fax Area Cde:**	
Facility Lat:	43.3365	**Contact Fax:**	
Facility Long:	-79.8131	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.334043
Facility DLS:		**Longitude:**	-79.816436
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	24	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3259		
NAICS 4 Description:	Other chemical product manufacturing		
NAICS Code (6 digit):	325999		
NAICS 6 Description:	All other miscellaneous chemical product manufacturing		

Substance Release Report

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	1.325
Unit:	tonnes
Basis of Estimate Cd:	O

Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 3
Category Type Desc: Fugitive
Category Type Desc (fr): Émissions fugitives
Grouping: Total Air
Trans Code: VOCs
Chem: PM10 - Particulate Matter <= 10 Microns
Chem (fr): PM10 - Matière particulaire <= 10 microns
Quantity: 2.17
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Sodium nitrite
Chem (fr): Nitrite de sodium
Quantity: .051
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Ethylene glycol
Chem (fr): Éthylèneglycol
Quantity: .0001
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

64	118 of 120	SE/225.7	100.0 / 0.19	**Solenis Canada ULC** **942 BRANT STREET** **BURLINGTON ON L7R 2J7**	GEN

Generator No: ON0096300
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241 L
Waste Class Name: Halogenated solvents and residues

Waste Class: 213 L
Waste Class Name: Petroleum distillates

Waste Class: 262 C

Waste Class Name: Detergents and soaps

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 268 I
Waste Class Name: Amines

Waste Class: 122 L
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 263 T
Waste Class Name: Misc. waste organic chemicals

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 268 C
Waste Class Name: Amines

Waste Class: 233 L
Waste Class Name: Other polymeric wastes

Waste Class: 148 L
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 267 C
Waste Class Name: Organic acids

Waste Class: 268 L
Waste Class Name: Amines

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 112 L
Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 267 L
Waste Class Name: Organic acids

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 213 T
Waste Class Name: Petroleum distillates

Waste Class: 263 C
Waste Class Name: Misc. waste organic chemicals

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 265 L

Waste Class Name: Graphic arts wastes

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 T
Waste Class Name: Misc. wastes and inorganic chemicals

---

64 | ***119 of 120*** | ***SE/225.7*** | ***100.0 / 0.19*** | ***Solenis Canada ULC***
942 BRANT STREET
BURLINGTON ON L7R 2J7 | ***GEN***

Generator No: ON0096300
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 112 L
Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 263 T
Waste Class Name: Misc. waste organic chemicals

Waste Class: 213 T
Waste Class Name: Petroleum distillates

Waste Class: 241 L
Waste Class Name: Halogenated solvents and residues

Waste Class: 145 I

Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 122 L
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 L
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 263 C
Waste Class Name: Misc. waste organic chemicals

Waste Class: 148 T
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 268 C
Waste Class Name: Amines

Waste Class: 267 L
Waste Class Name: Organic acids

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 213 L
Waste Class Name: Petroleum distillates

Waste Class: 233 L
Waste Class Name: Other polymeric wastes

Waste Class: 268 I
Waste Class Name: Amines

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 262 C
Waste Class Name: Detergents and soaps

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 268 L
Waste Class Name: Amines

Waste Class: 267 C
Waste Class Name: Organic acids

Waste Class: 252 L

Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	120 of 120	SE/225.7	100.0 / 0.19	Solenis Canada ULC 942 BRANT STREET BURLINGTON ON L7R 2J7	GEN

Generator No: ON0096300
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 233 L
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 122 C
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 268 C
Waste Class Name: AMINES

Waste Class: 213 T
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 148 C
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 268 L
Waste Class Name: AMINES

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 263 C
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 112 L
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 148 L
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 268 I
Waste Class Name: AMINES

Waste Class: 331 I

Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 263 I
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 112 C
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 145 L
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 267 L
Waste Class Name: ORGANIC ACIDS

Waste Class: 262 L
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 263 T
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 148 T
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 213 L
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 241 L
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 263 L
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 212 I
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 267 C
Waste Class Name: ORGANIC ACIDS

Waste Class: 213 I
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 148 I
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 262 C
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 122 L
Waste Class Name: ALKALINE WASTES - OTHER METALS

---

65 | **1 of 1** | **E/230.4** | **98.9 / -0.99** | **930 Brant Street Burlington ON** | **EHS**

Order No: 20160310051
Status: C
Report Type: Standard Report
Report Date: 16-MAR-16
Date Received: 10-MAR-16
Previous Site Name:
Lot/Building Size: 0.4 acre
Additional Info Ordered:

Nearest Intersection:
Municipality: Burlington
Client Prov/State: ON
Search Radius (km): .25
X: -79.815435
Y: 43.336336

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
66	1 of 1	NNW/233.9	100.2 / 0.35	Premiere Village Ltd. 1393, 1397, 1403, 1413 & 1423, 1417 Leighland Rd Burlington ON	CA

Certificate #: 2284-5JJT63
Application Year: 2003
Issue Date: 2/10/2003
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
67	1 of 1	ENE/234.3	99.8 / 0.00	ON	BORE

Borehole ID: 621069
OGF ID: 215521523
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: JAN-1969
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 13
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Power auger
Orig Ground Elev m: 99.9
Elev Reliabil Note:
DEM Ground Elev m: 99.5
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.337386
Longitude DD: -79.816026
UTM Zone: 17
Easting: 595975
Northing: 4798963
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218419646
Top Depth: 1.7
Bottom Depth: 6.8
Material Color: Brown
Material 1: Till
Material 2: Silt
Material 3: Sand
Material 4: Clay
Gsc Material Description:
Stratum Description: TILL,SILT,SAND,CLAY.BROWN,GLACIAL,HARD, AGE GLACIAL.

Mat Consistency: Hard
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Geology Stratum ID: 218419644
Top Depth: 0
Bottom Depth: .3
Material Color:
Material 1: Fill

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:

Material 2:	Sand	**Geologic Group:**	
Material 3:	Gravel	**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,SAND,GRAVEL. MAN-MADE,AGE POST-GLACIAL.		

Geology Stratum ID:	218419645	**Mat Consistency:**	Compact
Top Depth:	.3	**Material Moisture:**	
Bottom Depth:	1.7	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,SAND. BROWN,MAN-MADE,COMPACT, AGE POST-GLACIAL.		

Geology Stratum ID:	218419647	**Mat Consistency:**	Hard
Top Depth:	6.8	**Material Moisture:**	
Bottom Depth:	7.2	**Material Texture:**	
Material Color:	Green	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,CLAY,SAND. GREEN,GLACIAL,HARD,LAYERED, AGE GLACIAL.		

Geology Stratum ID:	218419648	**Mat Consistency:**	Hard
Top Depth:	7.2	**Material Moisture:**	
Bottom Depth:	8.4	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Shale	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND,SHALE. BROWN,GLACIAL,HARD, AGE GLACIAL.		

Geology Stratum ID:	218419649	**Mat Consistency:**	Hard
Top Depth:	8.4	**Material Moisture:**	
Bottom Depth:	13	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. RED,HARD,AGE UNDIFFERENTIATED. 013010024 006 009 0001001500 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: HAM.txt RecordID: 000680 NTS_Sheet: 30M05C		
Confiden 1:	Reliable information but incomplete.		

Source List

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

68 | **1 of 1** | **NE/237.8** | **99.8 / 0.00** | **1446 PLAINS RD E Burlington ON** | **WWIS**

Well ID:	7203959	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Test Hole	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	28-Jun-2013 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z163870	**Contractor:**	7215
Tag:	A144929	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/720\7203959.pdf

Additional Detail(s) (Map)

Well Completed Date:	2013/06/14
Year Completed:	2013
Depth (m):	4.572
Latitude:	43.3378831181261
Longitude:	-79.8167625414737
Path:	720\7203959.pdf

Bore Hole Information

Bore Hole ID:	1004381696	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595914.00
Code OB Desc:		**North83:**	4799017.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	14-Jun-2013 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock

Materials Interval

Formation ID:	1004977582
Layer:	2
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	34
Mat2 Desc:	TILL
Mat3:	
Mat3 Desc:	
Formation Top Depth:	2.0
Formation End Depth:	15.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1004977581
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	2.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004977592
Layer:	3
Plug From:	1.0
Plug To:	0.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004977593
Layer:	4
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004977590
Layer:	1
Plug From:	15.0
Plug To:	4.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004977591
Layer: 2
Plug From: 4.0
Plug To: 1.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1004977589
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1004977580
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004977586
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 5.0
Depth To: 0.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004977587
Layer: 1
Slot: 10
Screen Top Depth: 15.0
Screen End Depth: 5.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.0

Water Details

Water ID: 1004977585
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1004977584
Diameter: 4.5
Depth From: 1.0
Depth To: 15.0

Hole Depth UOM: ft
Hole Diameter UOM: inch

Hole Diameter

Hole ID: 1004977583
Diameter: 8.0
Depth From: 0.0
Depth To: 1.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID: 1004381696
Depth M: 4.572
Year Completed: 2013
Well Completed Dt: 2013/06/14
Audit No: Z163870
Tag No: A144929
Contractor: 7215
Path: 720\7203959.pdf
Latitude: 43.3378831181261
Longitude: -79.8167625414737

---

69 | **1 of 1** | **ENE/243.4** | **99.4 / -0.43** | **Burlington Hydro Inc.**
932 Brant Street
Burlington ON | **SPL**

Ref No: 2515-8XXLP3
Site No:
Incident Dt: 08-SEP-12
Year:
Incident Cause: Leak/Break
Incident Event:
Contaminant Code: 15
Contaminant Name: TRANSFORMER OIL (N.O.S.)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Not Anticipated
Nature of Impact: Other Impact(s); Soil Contamination
Receiving Medium:
Receiving Env:
MOE Response: No Field Response
Dt MOE Arvl on Scn:
MOE Reported Dt: 08-SEP-12
Dt Document Closed: 24-DEC-12
Incident Reason: Weather Conditions
Site Name: Private Parking Lot<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: Burlington Hydro: 4.5L mineral oil to paved area, clng
Contaminant Qty: 4.5 L
Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type: Transformer
Agency Involved:
Nearest Watercourse:
Site Address: 932 Brant Street
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: Burlington
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Land Spills
Source Type:

---

70 | **1 of 2** | **NW/245.2** | **99.8 / 0.00** | **Premiere Village Ltd.**
1393 Leighland Rd & 1397 1403 1413 1423 &
1417 Leighland Road
Burlington ON L9T 5A6 | **ECA**

Approval No: 2284-5JJT63
Approval Date: 2003-02-10
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
MOE District: Halton-Peel
City:
Longitude: -79.82093
Latitude: 43.33785
Geometry X:
Geometry Y:

Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Premiere Village Ltd.
Address: 1393 Leighland Rd & 1397 1403 1413 1423 & 1417 Leighland Road
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2766-5JJLKH-14.pdf
PDF Site Location:

---

70 | **2 of 2** | **NW/245.2** | **99.8 / 0.00** | **Premiere Village Ltd.**
1393 Leighland Rd & 1397 1403 1413 1423 & 1417 Leighland Road
Burlington ON L9T 5A6 | **ECA**

Approval No: 9550-5JJT9T
Approval Date: 2003-02-10
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
MOE District: Halton-Peel
City:
Longitude: -79.82092999999999
Latitude: 43.337849999999996
Geometry X:
Geometry Y:
Approval Type: ECA-Municipal and Private Water Works
Project Type: Municipal and Private Water Works
Business Name: Premiere Village Ltd.
Address: 1393 Leighland Rd & 1397 1403 1413 1423 & 1417 Leighland Road
Full Address:
Full PDF Link:
PDF Site Location:

---

71 | **1 of 1** | **W/245.3** | **98.8 / -1.00** | **ON** | **BORE**

Borehole ID: 621052
OGF ID: 215521506
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: SEP-1965
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 5.9
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Power auger
Orig Ground Elev m: 98.6
Elev Reliabil Note:
DEM Ground Elev m: 98.6
Concession:
Location D:
Survey D:
Comments:
Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.335288
Longitude DD: -79.822111
UTM Zone: 17
Easting: 595485
Northing: 4798723
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218419593
Top Depth: .2
Bottom Depth: 1.4
Material Color: Brown
Material 1: Fill
Material 2: Silt
Material 3: Clay
Material 4: Sand
Gsc Material Description:
Mat Consistency: Soft
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: fill

Stratum Description: FILL,SILT,CLAY,SAND.BROWN,MAN-MADE,VERY SOFT, AGE POST-GLACIAL.

Geology Stratum ID:	218419595	**Mat Consistency:**	Hard
Top Depth:	5.6	**Material Moisture:**	
Bottom Depth:	5.9	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:	Gravel	**Depositional Gen:**	glacial

Gsc Material Description:
Stratum Description: TILL,SILT,SAND, GRAVEL. BROWN,GLACIAL,HARD, AGE GLACIAL. 010 000050180004507100185100 0
**Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID:	218419592	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.2	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Soil	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	

Gsc Material Description:
Stratum Description: SOIL. MAN-MADE,AGE POST-GLACIAL.

Geology Stratum ID:	218419594	**Mat Consistency:**	Hard
Top Depth:	1.4	**Material Moisture:**	
Bottom Depth:	5.6	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	glacial

Gsc Material Description:
Stratum Description: TILL,CLAY,SILT,SAND.BROWN,GLACIAL,HARD, AGE GLACIAL.

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: HAM.txt RecordID: 000510 NTS_Sheet: 30M05C
Confiden 1: Reliable information but incomplete.

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		

Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

72 **1 of 1** **WNW/250.0** **98.8 / -1.00** **ON** **BORE**

Borehole ID:	621054	**Inclin FLG:**	No
OGF ID:	215521508	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No

Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	SEP-1965	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.336727
Total Depth m:	5.7	**Longitude DD:**	-79.82196
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	595495
Drill Method:	Power auger	**Northing:**	4798883
Orig Ground Elev m:	99.2	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	99.3		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218419600	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Soil	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SOIL. AGE POST-GLACIAL.		

Geology Stratum ID:	218419602	**Mat Consistency:**	Hard
Top Depth:	4.6	**Material Moisture:**	
Bottom Depth:	5.7	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:	Gravel	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND, GRAVEL. BROWN,GLACIAL,HARD, AGE GLACIAL. 000100980015010000043,SAND, G **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218419601	**Mat Consistency:**	Hard
Top Depth:	.3	**Material Moisture:**	
Bottom Depth:	4.6	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY,SILT,SAND.BROWN,GLACIAL,HARD, AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: HAM.txt RecordID: 000530 NTS_Sheet: 30M05C		
Confiden 1:	Reliable information but incomplete.		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

73	***1 of 1***	***N/250.9***	***100.8 / 1.00***	***1428-1430 Leighland Road Burlington ON L7R 3S8***	***EHS***

Order No:	20071018004	***Nearest Intersection:***	Brant
Status:	C	***Municipality:***	
Report Type:	CAN - Basic Report	***Client Prov/State:***	
Report Date:	10/26/2007	***Search Radius (km):***	0.25
Date Received:	10/18/2007	***X:***	-79.819084
Previous Site Name:		***Y:***	43.338333
Lot/Building Size:			
Additional Info Ordered:			

74	***1 of 8***	***NNE/254.7***	***99.8 / 0.00***	***BRANT VILLAGE CENTRE INC.-PT.PARCEL A&B PLAINS RD./BRANT ST./LEIGHLAND BURLINGTON CITY ON***	***CA***

Certificate #:	7-1267-91-
Application Year:	91
Issue Date:	10/21/1991
Approval Type:	Municipal water
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

74	***2 of 8***	***NNE/254.7***	***99.8 / 0.00***	***R.M. OF HALTON PLAINS RD.E./BRANT ST. BURLINGTON CITY ON***	***CA***

Certificate #:	7-0993-93-
Application Year:	93
Issue Date:	11/9/1993
Approval Type:	Municipal water
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

74	***3 of 8***	***NNE/254.7***	***99.8 / 0.00***	***R.M. OF HALTON PLAINS RD.E./BRANT ST.***	***CA***

BURLINGTON CITY ON

Certificate #: 3-1289-95-
Application Year: 95
Issue Date: 9/19/1995
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

74 ***4 of 8*** ***NNE/254.7*** ***99.8 / 0.00*** ***SPL***

UNKNOWN
RAMBO CREEK, ACROSS COURT HOUSE AT PLAINS RD EAST/BRANT ST.
BURLINGTON CITY ON

Ref No: 103600
Site No:
Incident Dt: 8/4/1994
Year:
Incident Cause: UNKNOWN
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: NOT ANTICIPATED
Nature of Impact:
Receiving Medium: WATER
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 8/4/1994
Dt Document Closed:
Incident Reason: UNKNOWN
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: UNKN'N QUANT. OF FUEL TO RAMBO CREEK,SOURCE UNKN'NBOOMED,FD,WORKS & REG.MUN
Contaminant Qty:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 14101
Site Lot:
Site Conc:
Northing:
Easting: FD, WORKS, HALTON REG.
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

---

74 ***5 of 8*** ***NNE/254.7*** ***99.8 / 0.00*** ***SPL***

TRANSPORT TRUCK
BRANT STREET AND PLAINS ROAD
TRANSPORT TRUCK (CARGO)
BURLINGTON CITY ON

Ref No: 141840
Site No:
Incident Dt: 6/10/1997
Year:
Incident Cause: CONTAINER OVERFLOW
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminant UN No 1:		**Site Region:**	
Environment Impact:	NOT ANTICIPATED	**Site Municipality:**	14101
Nature of Impact:		**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	WORKS, MOEE
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	6/10/1997	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	ERROR	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	SUN CHEMICAL - SPILL OF INK FROM CARGO QUANTITY UNKNOWN		
Contaminant Qty:			

74	6 of 8	NNE/254.7	99.8 / 0.00	**UNKNOWN** **BRANT & PLAINS ROAD, SW CORNER P. LOT, NEAR CAR RENTAL PLACE (NRG PARKING LOT)** **BURLINGTON CITY ON**	SPL

Ref No:	207813	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	8/4/2001	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	UNKNOWN	**Sector Type:**	
Incident Event:		**Agency Involved:**	WORKS, REGIONAL SPILL RESPONSE
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Possible	**Site Municipality:**	14101
Nature of Impact:	Multi Media Pollution	**Site Lot:**	
Receiving Medium:	Land, Water	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	8/4/2001	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	UNKNOWN	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	UNKNOWN: OIL IN STORM SEWER - ILLEGAL DUMPING. WORKS CONTACTED.		
Contaminant Qty:			

74	7 of 8	NNE/254.7	99.8 / 0.00	**Dufferin Concrete<UNOFFICIAL>** **NE corner of Brant St. and Plains Rd.** **Burlington ON**	SPL

Ref No:	1672-8AZPQH	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:		**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Unknown	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:	27	**Nearest Watercourse:**	
Contaminant Name:	CONCRETE	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Not Anticipated	**Site Municipality:**	
Nature of Impact:	Surface Water Pollution	**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	11/8/2010	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Watercourse Spills
Incident Reason:	Error- Operator error	**Source Type:**	
Site Name:	Commercial Lot<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Dufferin Concrete: concrete spill to cb		
Contaminant Qty:	0 other - see incident description		

---

74 | ***8 of 8*** | ***NNE/254.7*** | ***99.8 / 0.00*** | ***Rothsay, Brant St and Plains Rd, Burlington ON*** | ***SPL***

Ref No:	8543-8TBF4Z	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	13-APR-12	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Other Transport Accident	**Sector Type:**	Transport Truck
Incident Event:		**Agency Involved:**	
Contaminant Code:	46	**Nearest Watercourse:**	
Contaminant Name:	COOKING GREASE	**Site Address:**	Brant St and Plains Rd
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Possible	**Site Municipality:**	Burlington
Nature of Impact:	Other Impact(s)	**Site Lot:**	
Receiving Medium:	Sewage - Municipal/Private and Commercial	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:	No Field Response	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	13-APR-12	**Site Map Datum:**	
Dt Document Closed:	25-JUL-12	**SAC Action Class:**	Land Spills
Incident Reason:	Error- Operator error	**Source Type:**	
Site Name:	Used cooking oil spill<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Rothsay: max 170L used cooking oil to rd, cleaning		
Contaminant Qty:			

---

75 | ***1 of 1*** | ***ENE/258.1*** | ***98.9 / -0.93*** | ***932 Brant Street, Burlington ON L7R 2J7*** | ***EHS***

Order No:	22061500504	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Express Report	**Client Prov/State:**	ON
Report Date:	15-JUN-22	**Search Radius (km):**	.25
Date Received:	15-JUN-22	**X:**	-79.8151942
Previous Site Name:		**Y:**	43.3366956
Lot/Building Size:			
Additional Info Ordered:			

---

76 | ***1 of 1*** | ***NE/264.8*** | ***99.8 / 0.00*** | ***ON*** | ***BORE***

Borehole ID:	621064	**Inclin FLG:**	No
OGF ID:	215521518	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JAN-1969	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.337929
Total Depth m:	10.4	**Longitude DD:**	-79.816262
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	595955
Drill Method:	Power auger	**Northing:**	4799023
Orig Ground Elev m:	100	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	100		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218419627	**Mat Consistency:**	Hard
Top Depth:	2.7	**Material Moisture:**	
Bottom Depth:	7.3	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:	Clay	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND,CLAY.RED,GLACIAL,HARD,AGE GLACIAL.		

Geology Stratum ID:	218419628	**Mat Consistency:**	Hard
Top Depth:	7.3	**Material Moisture:**	
Bottom Depth:	8.9	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND. RED,HARD,AGE GLACIAL.		

Geology Stratum ID:	218419629	**Mat Consistency:**	
Top Depth:	8.9	**Material Moisture:**	
Bottom Depth:	10.4	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. RED,LAYERED, AGE UNDIFFERENTIATED. 020 018 010 00010 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218419625	**Mat Consistency:**	Loose
Top Depth:	.3	**Material Moisture:**	
Bottom Depth:	1.7	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	

Material 4: **Depositional Gen:** fill
Gsc Material Description:
Stratum Description: FILL,SAND. MAN-MADE,LOOSE, AGE POST-GLACIAL.

Geology Stratum ID: 218419626
Top Depth: 1.7
Bottom Depth: 2.7
Material Color: Brown
Material 1: Till
Material 2: Silt
Material 3: Clay
Material 4: Sand
Gsc Material Description:
Stratum Description: TILL,SILT,CLAY,SAND.BROWN,GLACIAL,VERY SOFT, AGE GLACIAL.

Mat Consistency: Soft
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Geology Stratum ID: 218419624
Top Depth: 0
Bottom Depth: .3
Material Color:
Material 1: Soil
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SOIL. MAN-MADE,AGE POST-GLACIAL.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: M
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: HAM.txt RecordID: 000630 NTS_Sheet: 30M05C
Confiden 1: Reliable information but incomplete.

Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

77	1 of 2	E/266.9	98.7 / -1.12	920 Brant St Burlington ON L7R	EHS

Order No: 20321600024
Status: C
Report Type: RSC Report - Quote
Report Date: 21-DEC-20
Date Received: 16-DEC-20
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .3
X: -79.81495575
Y: 43.33609172

77	2 of 2	E/266.9	98.7 / -1.12	920 Brant St Burlington ON L7R	EHS

Order No: 20321600024

Nearest Intersection:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:	C	**Municipality:**	
Report Type:	RSC Report - Quote	**Client Prov/State:**	ON
Report Date:	21-DEC-20	**Search Radius (km):**	.3
Date Received:	16-DEC-20	**X:**	-79.81495575
Previous Site Name:		**Y:**	43.33609172
Lot/Building Size:			
Additional Info Ordered:			

78 **1 of 1** **ENE/269.1** **99.3 / -0.54** **ON** **BORE**

Borehole ID:	621071	**Inclin FLG:**	No
OGF ID:	215521525	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JAN-1969	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.337745
Total Depth m:	12.7	**Longitude DD:**	-79.815895
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	595985
Drill Method:	Power auger	**Northing:**	4799003
Orig Ground Elev m:	99.8	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	101		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218419657	**Mat Consistency:**	Loose
Top Depth:	.3	**Material Moisture:**	
Bottom Depth:	1.8	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,SAND. MAN-MADE,LOOSE, AGE POST-GLACIAL.		

Geology Stratum ID:	218419658	**Mat Consistency:**	Soft
Top Depth:	1.8	**Material Moisture:**	
Bottom Depth:	2.1	**Material Texture:**	
Material Color:	Green	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,CLAY. GREEN,GLACIAL,VERY SOFT, AGE GLACIAL.		

Geology Stratum ID:	218419662	**Mat Consistency:**	
Top Depth:	8.2	**Material Moisture:**	
Bottom Depth:	12.7	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	

Material 4: ***Depositional Gen:***
Gsc Material Description:
Stratum Description: BEDROCK,SHALE. RED,LAYERED, AGE UNDIFFERENTIATED. 018 007 010 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID: 218419661 ***Mat Consistency:*** Hard
Top Depth: 7.9 ***Material Moisture:***
Bottom Depth: 8.2 ***Material Texture:***
Material Color: Red ***Non Geo Mat Type:***
Material 1: Silt ***Geologic Formation:***
Material 2: Sand ***Geologic Group:***
Material 3: Shale ***Geologic Period:***
Material 4: ***Depositional Gen:*** glacial
Gsc Material Description:
Stratum Description: SILT,SAND,SHALE. RED,GLACIAL,HARD,AGE GLACIAL.

Geology Stratum ID: 218419656 ***Mat Consistency:***
Top Depth: 0 ***Material Moisture:***
Bottom Depth: .3 ***Material Texture:***
Material Color: ***Non Geo Mat Type:***
Material 1: Soil ***Geologic Formation:***
Material 2: ***Geologic Group:***
Material 3: ***Geologic Period:***
Material 4: ***Depositional Gen:***
Gsc Material Description:
Stratum Description: SOIL. MAN-MADE,AGE POST-GLACIAL.

Geology Stratum ID: 218419660 ***Mat Consistency:*** Hard
Top Depth: 7 ***Material Moisture:***
Bottom Depth: 7.9 ***Material Texture:***
Material Color: Red ***Non Geo Mat Type:***
Material 1: Silt ***Geologic Formation:***
Material 2: Sand ***Geologic Group:***
Material 3: Gravel ***Geologic Period:***
Material 4: ***Depositional Gen:*** glacial
Gsc Material Description:
Stratum Description: SILT,SAND,GRAVEL. RED,GLACIAL,HARD,AGE GLACIAL.

Geology Stratum ID: 218419659 ***Mat Consistency:*** Hard
Top Depth: 2.1 ***Material Moisture:***
Bottom Depth: 7 ***Material Texture:***
Material Color: Red ***Non Geo Mat Type:***
Material 1: Till ***Geologic Formation:***
Material 2: Silt ***Geologic Group:***
Material 3: Sand ***Geologic Period:***
Material 4: Clay ***Depositional Gen:*** glacial
Gsc Material Description:
Stratum Description: TILL,SILT,SAND,CLAY.RED,GLACIAL,HARD,AGE GLACIAL.

Source

Source Type: Data Survey ***Source Appl:*** Spatial/Tabular
Source Orig: Geological Survey of Canada ***Source Iden:*** 1
Source Date: 1956-1972 ***Scale or Res:*** Varies
Confidence: M ***Horizontal:*** NAD27
Observatio: ***Verticalda:*** Mean Average Sea Level
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: HAM.txt RecordID: 000700 NTS_Sheet: 30M05C
Confiden 1: Reliable information but incomplete.

Source List

Source Identifier: 1 ***Horizontal Datum:*** NAD27
Source Type: Data Survey ***Vertical Datum:*** Mean Average Sea Level

Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

79 **1 of 1** **W/270.2** **98.8 / -1.00** **ON** **BORE**

Borehole ID:	621053	**Inclin FLG:**	No
OGF ID:	215521507	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	SEP-1965	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.336102
Total Depth m:	5.9	**Longitude DD:**	-79.822465
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	595455
Drill Method:	Power auger	**Northing:**	4798813
Orig Ground Elev m:	99.6	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	99.2		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218419599	**Mat Consistency:**	Hard
Top Depth:	5.3	**Material Moisture:**	
Bottom Depth:	5.9	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:	Gravel	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND, GRAVEL. BROWN,GLACIAL,HARD, AGE GLACIAL. 010 0001001400030071001751000 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218419597	**Mat Consistency:**	Stiff
Top Depth:	.3	**Material Moisture:**	
Bottom Depth:	.9	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,SILT,CLAY,SAND.BROWN,MAN-MADE,STIFF, AGE POST-GLACIAL.		

Geology Stratum ID:	218419598	**Mat Consistency:**	Hard
Top Depth:	.9	**Material Moisture:**	
Bottom Depth:	5.3	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY,SILT,SAND.BROWN,GLACIAL,HARD, AGE GLACIAL.		

Geology Stratum ID:	218419596	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Asphalt	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	ASPHALT. MAN-MADE,AGE POST-GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: HAM.txt RecordID: 000520 NTS_Sheet: 30M05C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

80 | ***1 of 3*** | ***N/273.0*** | ***100.8 / 1.00*** | ***1030 Brant St Burlington ON L7R 0B2*** | ***EHS***

Order No:	20282400317	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	31-AUG-20	**Search Radius (km):**	.25
Date Received:	24-AUG-20	**X:**	-79.818682
Previous Site Name:		**Y:**	43.3387194
Lot/Building Size:			
Additional Info Ordered:			

---

80 | ***2 of 3*** | ***N/273.0*** | ***100.8 / 1.00*** | ***1030 Brant St Burlington ON L7R 0B2*** | ***EHS***

Order No:	20282400317	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	31-AUG-20	**Search Radius (km):**	.25
Date Received:	24-AUG-20	**X:**	-79.818682
Previous Site Name:		**Y:**	43.3387194
Lot/Building Size:			
Additional Info Ordered:			

---

80 | ***3 of 3*** | ***N/273.0*** | ***100.8 / 1.00*** | ***1030 Brant St Burlington ON L7R 0B2*** | ***EHS***

Order No:	20282400317	**Nearest Intersection:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	31-AUG-20	**Search Radius (km):**	.25
Date Received:	24-AUG-20	**X:**	-79.818682
Previous Site Name:		**Y:**	43.3387194
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
81	1 of 1	SE/273.0	98.2 / -1.62	942 Brant Street Burlington ON	EHS

Order No:	20130910026	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	19-SEP-13	**Search Radius (km):**	.25
Date Received:	10-SEP-13	**X:**	-79.816515
Previous Site Name:		**Y:**	43.333775
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
82	1 of 14	N/274.3	100.8 / 1.00	Mountain Equipment Co-Op 1030 Brant Avenue Burlington ON L7R 0B2	GEN

Generator No:	ON8701656
SIC Code:	451110
SIC Description:	Sporting Goods Stores
Approval Years:	2009
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
82	2 of 14	N/274.3	100.8 / 1.00	Mountain Equipment Co-Op 1030 Brant Avenue Burlington ON L7R 0B2	GEN

Generator No:	ON8701656
SIC Code:	451110
SIC Description:	Sporting Goods Stores
Approval Years:	2010
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

82 **3 of 14** **N/274.3** **100.8 / 1.00** **Mountain Equipment Co-Op**
1030 Brant Avenue
Burlington ON L7R 0B2
GEN

Generator No: ON8701656
SIC Code: 451110
SIC Description: Sporting Goods Stores
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

82 **4 of 14** **N/274.3** **100.8 / 1.00** **Mountain Equipment Co-Op**
1030 Brant Street
Burlington ON
GEN

Generator No: ON8701656
SIC Code: 451110
SIC Description: Sporting Goods Stores
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

82 **5 of 14** **N/274.3** **100.8 / 1.00** **Mountain Equipment Co-Op**
1030 Brant Street
Burlington ON
GEN

Generator No: ON8701656
SIC Code: 451110
SIC Description: SPORTING GOODS STORES
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
82	6 of 14	N/274.3	100.8 / 1.00	Mountain Equipment Co-Op 1030 Brant Street Burlington ON L7R 0B2	GEN

Generator No: ON8701656
SIC Code: 451110
SIC Description: SPORTING GOODS STORES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
82	7 of 14	N/274.3	100.8 / 1.00	Mountain Equipment Co-Op 1030 Brant Street Burlington ON L7R 0B2	GEN

Generator No: ON8701656
SIC Code: 451110
SIC Description: SPORTING GOODS STORES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
82	8 of 14	N/274.3	100.8 / 1.00	Mountain Equipment Co-Op 1030 Brant Street Burlington ON L7R 0B2	GEN

Generator No: ON8701656
SIC Code: 451110
SIC Description: SPORTING GOODS STORES
Approval Years: 2014
PO Box No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Country: Canada
Status:
Co Admin: Patricia Bigattini
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-333-8559 Ext.246
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

82	9 of 14	N/274.3	100.8 / 1.00	***Mountain Equipment Co-Op*** ***1030 Brant Street*** ***Burlington ON L7R 0B2***	GEN

Generator No: ON8701656
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

82	10 of 14	N/274.3	100.8 / 1.00	***Mountain Equipment Co-Op*** ***1030 Brant Street*** ***Burlington ON L7R 0B2***	GEN

Generator No: ON8701656
SIC Code:
SIC Description:
Approval Years: As of Oct 2019
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

82	11 of 14	N/274.3	100.8 / 1.00	***MOUNTAIN EQUIPMENT CO-OPERATIVE*** ***1030 BRANT ST*** ***BURLINGTON ON L7R 0B2***	PES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail Licence No:		**Operator Box:**	
Licence No:	L-232-4030696132	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	2018-10-16	**Operator Type:**	
Report Source:	PEST-Limited Vendor	**Oper Area Code:**	
Licence Type:	Limited Vendor	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.33833333	**Operator Region:**	
Longitude:	-79.81861111	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Halton
Trade Name:			
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2098067		

---

82 | **12 of 14** | **N/274.3** | **100.8 / 1.00** | **MEC MOUNTAIN EQUIPMENT COMPANY LTD.**
1030 Brant ST
Burlington ON L7R 0B2 | **PES**

Detail Licence No:		**Operator Box:**	
Licence No:	L-232-2104513319	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	2020-11-17	**Operator Type:**	
Report Source:	PEST-Limited Vendor	**Oper Area Code:**	
Licence Type:	Limited Vendor	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.33833333	**Operator Region:**	
Longitude:	-79.81861111	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Halton
Trade Name:			
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2304648		

---

82 | **13 of 14** | **N/274.3** | **100.8 / 1.00** | **1030 brant street**
Burlington ON L7R 0B2 | **EHS**

Order No:	22010500436	**Nearest Intersection:**	
Status:	C	**Municipality:**	Burlington
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	10-JAN-22	**Search Radius (km):**	.25
Date Received:	05-JAN-22	**X:**	-79.8185559
Previous Site Name:		**Y:**	43.3387272
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Title Searches; City Directory; Aerial Photos		

---

82 | **14 of 14** | **N/274.3** | **100.8 / 1.00** | **1030 brant street**
Burlington ON L7R 0B2 | **EHS**

Order No:	22010500436	**Nearest Intersection:**	
Status:	C	**Municipality:**	Burlington
Report Type:	Standard Report	**Client Prov/State:**	ON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Report Date:	10-JAN-22	**Search Radius (km):**	.25
Date Received:	05-JAN-22	**X:**	-79.8185559
Previous Site Name:		**Y:**	43.3387272
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Title Searches; City Directory; Aerial Photos		

---

83 | **1 of 1** | **E/274.8** | **98.8 / -1.02** | **CANADIAN PACIFIC RAILWAYS**
BRANT ST. BY OLD TRAIN STATION AT CP YARD TRAIN
BURLINGTON CITY ON | **SPL**

Ref No:	30403	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	1/30/1990	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	OTHER CAUSE (N.O.S.)	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	NOT ANTICIPATED	**Site Municipality:**	14101
Nature of Impact:		**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	1/30/1990	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	EQUIPMENT FAILURE	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	CPR - 10 L DIESEL FUEL TO TRACKS.		
Contaminant Qty:			

---

84 | **1 of 1** | **ENE/276.2** | **99.2 / -0.67** | **ON** | **BORE**

Borehole ID:	622141	**Inclin FLG:**	No
OGF ID:	215522595	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	MAR-1962	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.337744
Total Depth m:	11.2	**Longitude DD:**	-79.815772
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	595995
Drill Method:	Diamond Drill	**Northing:**	4799003
Orig Ground Elev m:	97.4	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	100		
Concession:			
Location D:			
Survey D:			
Comments:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Borehole Geology Stratum

Geology Stratum ID:	218424576	***Mat Consistency:***	
Top Depth:	8.1	***Material Moisture:***	
Bottom Depth:	11.2	***Material Texture:***	
Material Color:	Red	***Non Geo Mat Type:***	
Material 1:	Bedrock	***Geologic Formation:***	
Material 2:	Shale	***Geologic Group:***	
Material 3:	Clay	***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE,CLAY. RED,LAYERED, AGE UNDIFFERENTIATED. GRAVEL, **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218424575	***Mat Consistency:***	
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	8.1	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Unknown	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	UNSPECIFIED. AGE UNDIFFERENTIATED.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	M	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: HAM.txt RecordID: 011410 NTS_Sheet: 30M05C		
Confiden 1:	Logs are approximately correct. Lack of information. Doubtful terminology.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

85	***1 of 1***	***NE/277.3***	***99.8 / 0.00***	***ON***	***BORE***

Borehole ID:	621065	***Inclin FLG:***	No
OGF ID:	215521519	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	JAN-1969	***Municipality:***	
Static Water Level:		***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.338294
Total Depth m:	4.9	***Longitude DD:***	-79.816748
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	595915
Drill Method:	Power auger	***Northing:***	4799063
Orig Ground Elev m:	100	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable

DEM Ground Elev m: 100
Concession:
Location D:
Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID: 218419631
Top Depth: .1
Bottom Depth: .2
Material Color:
Material 1: Soil
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SOIL. MAN-MADE,AGE POST-GLACIAL.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218419632
Top Depth: .2
Bottom Depth: 2.4
Material Color: Brown
Material 1: Fill
Material 2: Sand
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: FILL,SAND. BROWN,MAN-MADE,LOOSE, AGE POST-GLACIAL.

Mat Consistency: Loose
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: fill

Geology Stratum ID: 218419633
Top Depth: 2.4
Bottom Depth: 4.9
Material Color: Green
Material 1: Till
Material 2: Silt
Material 3: Sand
Material 4: Clay
Gsc Material Description:
Stratum Description: TILL,SILT,SAND,CLAY.GREEN,GLACIAL,AGE GLACIAL. 008 0000700300080043D,HA **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Geology Stratum ID: 218419630
Top Depth: 0
Bottom Depth: .1
Material Color:
Material 1: Asphalt
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: ASPHALT. MAN-MADE,AGE POST-GLACIAL.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: M
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: HAM.txt RecordID: 000640 NTS_Sheet: 30M05C
Confiden 1: Reliable information but incomplete.

Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

86 | ***1 of 1*** | ***WSW/277.7*** | ***98.8 / -1.00*** | ***PRIVATE OWNER 1312 CORIC AVE. MOTOR VEHICLE (OPERATING FLUID) BURLINGTON CITY ON L7R 3S3*** | ***SPL***

Ref No:	119224	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	10/1/1995	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	OTHER CAUSE (N.O.S.)	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	14101
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	HALTON REG, WORKS.
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	10/2/1995	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	INTENTIONAL/PLANNED	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	PRIVATE OWNER-USED MOTOR OIL DUMPED INTO CATCH BA-SIN, CLEANED BY WORKS.		
Contaminant Qty:			

87 | ***1 of 1*** | ***NNW/278.4*** | ***100.8 / 1.00*** | ***1425 LEIGHLAND ROAD, BURLINGTON ON*** | ***PINC***

Incident Id:	2678496	***Pipe Material:***	Plastic
Incident No:	522102	***Fuel Category:***	Natural Gas
Incident Reported Dt:		***Health Impact:***	No
Type:	FS-Pipeline Incident	***Environment Impact:***	Unknown
Status Code:	Pipeline Damage Reason Est	***Property Damage:***	Yes
Tank Status:	RC Established	***Service Interrupt:***	Unknown
Task No:	3208271	***Enforce Policy:***	Yes
Spills Action Centre:	N/A	***Public Relation:***	No
Fuel Type:	Natural Gas	***Pipeline System:***	
Fuel Occurrence Tp:	Pipeline Strike	***PSIG:***	
Date of Occurrence:	10/23/2010 0:00	***Attribute Category:***	FS-Perform P-line Inc Invest
Occurrence Start Dt:	2011/01/25	***Regulator Location:***	
Depth:		***Method Details:***	E-mail
Customer Acct Name:			
Incident Address:			
Operation Type:	Construction Site (pipeline strike)		
Pipeline Type:	Main Distribution Pipeline		
Regulator Type:			
Summary:	1425 LEIGHLAND ROAD, BURLINGTON - 1 1/4" PIPELINE HIT		

Reported By: LORI DEVAY - UNION GAS HALTON
Affiliation: Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.)
Occurrence Desc:
Damage Reason: Facility was not located or marked
Notes:

---

88 | **1 of 7** | **E/280.3** | **98.9 / -0.97** | **2064973 Ontario Inc.**
930 Brant Street, Burlington, Ontario , L7R 2J7 , Canada,
ON L7R 2J7 | **RSC**

RSC ID: 21301
RA No:
RSC Type:
Curr Property Use: Commercial
Ministry District: BURLINGTON
Filing Date: 18-Jun-07
Date Ack:
Date Returned:
Restoration Type:
Soil Type:
Criteria:
CPU Issued Sect 1686: No
Cert Date: 26-Jan-07
Cert Prop Use No: No CPU
Intended Prop Use: Commercial
Qual Person Name: Mr. David Balardo
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N): Yes
Accuracy Estimate: 2 to 5 meters
Telephone: 905-5787784
Fax: 905-5787786
Email:
Asmt Roll No: 2402050-50203600
Prop ID No (PIN): 07087-0051 [LT]
Property Municipal Address: 930 Brant Street, Burlington, Ontario , L7R 2J7 , Canada,
Mailing Address: 18 Cedargrove Court, Ancaster, Ontario , L9G 4W5
Latitude & Latitude: 43.33583330N 79.81583330W
UTM Coordinates: NAD83 17-595993-4798790 (converted from Latitude & Longitude)
Consultant:
Legal Desc: Lt 76, rcp pl99, except pt2, 20R5391 & 301872; pt lt 75, rcp pl99; pt lt 77, rcp pl99, as in 623554 s/t 623554; s/t bh9167 burlington "amended mar 29' 99 j. menard.
Measurement Method: Digitized from a map
Applicable Standards: Full Depth Site Conditions Standard, with Nonpotable Ground Water, Medium/Fine Textured Soil, for Industrial/Commercial/Community property use
RSC PDF:

---

88 | **2 of 7** | **E/280.3** | **98.9 / -0.97** | **New Alliance Ltd**
930 Brant Street
Burlington ON L7R 2J7 | **GEN**

Generator No: ON5753751
SIC Code: 237990
SIC Description: Other Heavy and Civil Engineering Construction
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

88 | **3 of 7** | **E/280.3** | **98.9 / -0.97** | **New Alliance Ltd**
930 Brant Street | **GEN**

Burlington ON L7R 2J7

Generator No: ON5753751
SIC Code: 237990
SIC Description: Other Heavy and Civil Engineering Construction
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

88 ***4 of 7*** ***E/280.3*** ***98.9 / -0.97*** ***New Alliance Ltd*** ***GEN***
930 Brant Street
Burlington ON L7R 2J7

Generator No: ON5753751
SIC Code: 237990
SIC Description: Other Heavy and Civil Engineering Construction
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

88 ***5 of 7*** ***E/280.3*** ***98.9 / -0.97*** ***New Alliance Ltd*** ***GEN***
930 Brant Street
Burlington ON

Generator No: ON5753751
SIC Code: 237990
SIC Description: OTHER HEAVY AND CIVIL ENGINEERING CONSTRUCTION
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

88 | **6 of 7** | **E/280.3** | **98.9 / -0.97** | **New Alliance Ltd**
930 Brant Street
Burlington ON L7R 2L7 | **GEN**

Generator No: ON5753751
SIC Code: 237990
SIC Description: OTHER HEAVY AND CIVIL ENGINEERING CONSTRUCTION
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

88 | **7 of 7** | **E/280.3** | **98.9 / -0.97** | **New Alliance Ltd**
930 Brant Street
Burlington ON L7R 2L7 | **GEN**

Generator No: ON5753751
SIC Code: 237990
SIC Description: OTHER HEAVY AND CIVIL ENGINEERING CONSTRUCTION
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

89 | **1 of 2** | **SE/282.3** | **97.8 / -2.08** | **942 Brant Street**
Burlington ON L7R 2J7 | **EHS**

Order No: 21052700187
Status: C
Report Type: RSC Report - Quote
Nearest Intersection:
Municipality:
Client Prov/State: OH

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Report Date:	01-JUN-21	**Search Radius (km):**	.3
Date Received:	27-MAY-21	**X:**	-79.81683293
Previous Site Name:		**Y:**	43.3334874
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Topographic Maps; City Directory; Aerial Photos		

---

89 | **2 of 2** | **SE/282.3** | **97.8 / -2.08** | **942 Brant Street, Burlington ON L7R 2J7** | **EHS**

Order No:	21052700187	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	RSC Report - Quote	**Client Prov/State:**	OH
Report Date:	01-JUN-21	**Search Radius (km):**	.3
Date Received:	27-MAY-21	**X:**	-79.81683293
Previous Site Name:		**Y:**	43.3334874
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Topographic Maps; City Directory; Aerial Photos		

---

90 | **1 of 1** | **NNW/285.2** | **100.8 / 1.00** | **1425, 1427, 1429, and 1431 Leighland Road, Burlington ON** | **EHS**

Order No:	20090219005	**Nearest Intersection:**	Brant Street + Leighland Road
Status:	C	**Municipality:**	City of Burlington, Region of Halton
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	2/27/2009	**Search Radius (km):**	0.25
Date Received:	2/19/2009	**X:**	-79.819798
Previous Site Name:		**Y:**	43.338804
Lot/Building Size:	4 Adjoining Residential Properties		
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Aerials Photos		

---

91 | **1 of 1** | **NNE/285.7** | **99.8 / 0.00** | **ON** | **BORE**

Borehole ID:	621066	**Inclin FLG:**	No
OGF ID:	215521520	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JAN-1969	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.338662
Total Depth m:	4.3	**Longitude DD:**	-79.817481
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	595855
Drill Method:	Power auger	**Northing:**	4799103
Orig Ground Elev m:	100	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	100		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218419634	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.1	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	

Material 1:	Asphalt	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	ASPHALT. MAN-MADE,AGE POST-GLACIAL.		

Geology Stratum ID:	218419636	**Mat Consistency:**	
Top Depth:	.2	**Material Moisture:**	
Bottom Depth:	1.4	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,SAND. BROWN,MAN-MADE, AGE POST-GLACIAL.		

Geology Stratum ID:	218419635	**Mat Consistency:**	
Top Depth:	.1	**Material Moisture:**	
Bottom Depth:	.2	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Gravel	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,GRAVEL. MAN-MADE,AGE POST-GLACIAL.		

Geology Stratum ID:	218419637	**Mat Consistency:**	Hard
Top Depth:	1.4	**Material Moisture:**	
Bottom Depth:	4.3	**Material Texture:**	
Material Color:	Green	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:	Clay	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND,CLAY.GREEN,GLACIAL,HARD, AGE GLACIAL. 008 00047052D,HA **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: HAM.txt RecordID: 000650 NTS_Sheet: 30M05C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
92	1 of 22	E/299.0	97.8 / -2.05	EDWARDS CANADA 920 BRANT ST UNIT 16	SCT

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				BURLINGTON ON L7R 4J1	

Established: 1914
Plant Size (ft²): 2500
Employment: 19

--Details--
Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Description: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
SIC/NAICS Code: 418410

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
92	2 of 22	E/299.0	97.8 / -2.05	PEST PREVENTION SYSTEMS 920 BRANT STREET, UNIT 13 BURLINGTON ON L3T 1L3	PES

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Operator
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
92	3 of 22	E/299.0	97.8 / -2.05	EDWARDS 920 BRANT ST UNIT 16 BURLINGTON ON L7R 4J1	SCT

Established: 0000
Plant Size (ft²): 0
Employment: 19

--Details--
Description: INDUSTRIAL MACHINERY AND EQUIPMENT
SIC/NAICS Code: 5084

Description: DURABLE GOODS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 5099

Description: ELECTRICAL APPARATUS AND EQUIPMENT, WIRING SUPPLIES, AND CONSTRUCTION MATERIALS
SIC/NAICS Code: 5063

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
92	4 of 22	E/299.0	97.8 / -2.05	Carbo-Tech Environmental Group 920 Brant St Unit 13 Burlington ON L7R 4J1	SCT

Established: 1991
Plant Size (ft²):
Employment: 6

--Details--
Description: Metal Valve Manufacturing
SIC/NAICS Code: 332910

Description: Industrial and Commercial Fan and Blower and Air Purification Equipment Manufacturing
SIC/NAICS Code: 333413

Description: All Other General-Purpose Machinery Manufacturing
SIC/NAICS Code: 333990

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
92	5 of 22	E/299.0	97.8 / -2.05	RACOL CONTROLS 920 BRANT ST UNIT 23 BURLINGTON ON L7R 4J1	SCT

Established: 1990
Plant Size (ft²): 0
Employment: 5

--Details--
Description: POWER, DISTRIBUTION, AND SPECIALTY TRANSFORMERS
SIC/NAICS Code: 3612

Description: Power, Distribution and Specialty Transformers Manufacturing
SIC/NAICS Code: 335311

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
92	6 of 22	E/299.0	97.8 / -2.05	Orthogait Inc. 920 Brant St Unit 1 Burlington ON L7R 4J1	SCT

Established: 01-AUG-98
Plant Size (ft²): 1000
Employment:

--Details--
Description: Medical Equipment and Supplies Manufacturing
SIC/NAICS Code: 339110

Description: Medical Equipment and Supplies Manufacturing
SIC/NAICS Code: 339110

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
92	7 of 22	E/299.0	97.8 / -2.05	Carbo-Tech Environmental Group Inc. 920 Brant St Unit 13 Burlington ON L7R 4J1	SCT

Established: 1991
Plant Size (ft²):
Employment: 6

--Details--

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: Plumbing, Heating and Air-Conditioning Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 416120

Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Description: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
SIC/NAICS Code: 418410

---

92 | 8 of 22 | E/299.0 | 97.8 / -2.05 | **Kwik Kopy Printing**
920 Brant St Unit 18
Burlington ON L7R 4J1 | SCT

Established: 1979
Plant Size (ft²): 3600
Employment: 4

--Details--
Description: Other Printing
SIC/NAICS Code: 323119

---

92 | 9 of 22 | E/299.0 | 97.8 / -2.05 | **Edwards - Part of GE Security**
920 Brant St Unit 16
Burlington ON L7R 4J1 | SCT

Established: 1929
Plant Size (ft²): 2500
Employment: 19

--Details--
Description: Home Entertainment Equipment Wholesaler-Distributors
SIC/NAICS Code: 414210

Description: Household Appliance Wholesaler-Distributors
SIC/NAICS Code: 414220

Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

Description: Electronic Components, Navigational and Communications Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417320

Description: All Other Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417990

Description: Security Systems Services (except Locksmiths)
SIC/NAICS Code: 561621

---

92 | 10 of 22 | E/299.0 | 97.8 / -2.05 | **1617136 Ontario Ltd.**
920 Brant Street, Unit 18-19
Burlington ON L7R 4J1 | GEN

Generator No: ON1724053
SIC Code: 323114
SIC Description: Quick Printing
Approval Years: 05
PO Box No:
Country:
Status:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

92	***11 of 22***	***E/299.0***	***97.8 / -2.05***	***Edwards A Part of GE Security Canada*** ***920 Brant Street Unit #16*** ***Burlington ON L7R 4J1***	***GEN***

Generator No: ON8324281
SIC Code: 811210
SIC Description: Electronic and Precision Equipment Repair and Maintenance
Approval Years: 05
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

92	***12 of 22***	***E/299.0***	***97.8 / -2.05***	***Kwik Kopy Design & Print*** ***920 Brant St Unit 18*** ***Burlington ON L7R 4J1***	***SCT***

Established: 01-JUL-79
Plant Size (ft²): 2400
Employment:

--Details--
Description: Other Printing
SIC/NAICS Code: 323119

92	***13 of 22***	***E/299.0***	***97.8 / -2.05***	***1617136 Ontario Ltd.*** ***920 Brant Street Units 18 - 19*** ***Burlington ON***	***GEN***

Generator No: ON7956584
SIC Code: 323114
SIC Description: Quick Printing
Approval Years: 2009
PO Box No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
92	14 of 22	E/299.0	97.8 / -2.05	2304866 Ontario Ltd. 920 Brant Street Units 18 - 19 Burlington ON L7R 4J1	GEN

Generator No: ON7956584
SIC Code: 323114
SIC Description:
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
92	15 of 22	E/299.0	97.8 / -2.05	2304866 Ontario Ltd. 920 Brant Street Units 18 - 19 Burlington ON L7R 4J1	GEN

Generator No: ON7956584
SIC Code: 323114
SIC Description: Quick Printing
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

92 **16 of 22** **E/299.0** **97.8 / -2.05** **2304866 Ontario Ltd.** **GEN**
920 Brant Street Units 18 - 19
Burlington ON

Generator No: ON7956584
SIC Code: 323114
SIC Description: QUICK PRINTING
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

92 **17 of 22** **E/299.0** **97.8 / -2.05** **Burlington Hydro Inc.** **SPL**
920 Grays Lane
Burlington ON

Ref No: 8100-ABKTSS
Site No: NA
Incident Dt: 2016/07/05
Year:
Incident Cause:
Incident Event: Leak/Break
Contaminant Code: 26
Contaminant Name: TRANSFORMER OIL (GT 50 PPM PCB)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact:
Nature of Impact:
Receiving Medium:
Receiving Env: Land
MOE Response: No
Dt MOE Arvl on Scn:
MOE Reported Dt: 2016/07/05
Dt Document Closed:
Incident Reason: Material Failure - Poor Design/Substandard Material
Site Name: Transformer spill<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: Burlington Hydro _ 2L of transformer oil (non PCBs) to grnd - Burlington
Contaminant Qty: 2 L

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type: Electric Power Generation
Agency Involved:
Nearest Watercourse:
Site Address: 920 Grays Lane
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: Burlington
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Land Spills
Source Type:

---

92 **18 of 22** **E/299.0** **97.8 / -2.05** **2304866 Ontario Ltd.** **GEN**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				920 Brant Street Units 18 - 19 **Burlington ON L7R 4J1**	

Generator No: ON7956584
SIC Code: 323114
SIC Description: QUICK PRINTING
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Ralph Paone
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-332-4225 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
92	19 of 22	E/299.0	97.8 / -2.05	**2304866 Ontario Ltd.** **920 Brant Street Units 18 - 19** **Burlington ON L7R 4J1**	GEN

Generator No: ON7956584
SIC Code: 323114
SIC Description: QUICK PRINTING
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Ralph Paone
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-332-4225 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
92	20 of 22	E/299.0	97.8 / -2.05	**2304866 Ontario Ltd.** **920 Brant Street Units 18 - 19** **Burlington ON L7R 4J1**	GEN

Generator No: ON7956584
SIC Code: 323114
SIC Description: QUICK PRINTING
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Ralph Paone
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-332-4225 Ext.

Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

---

92 | **21 of 22** | **E/299.0** | **97.8 / -2.05** | **920 Brant Street Burlington ON L7R 4J1** | **EHS**

Order No: 20200622122
Status: C
Report Type: Standard Report
Report Date: 25-JUN-20
Date Received: 22-JUN-20
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8146054
Y: 43.3364653

---

92 | **22 of 22** | **E/299.0** | **97.8 / -2.05** | **920 Brant Street Burlington ON L7R 4J1** | **EHS**

Order No: 20200622122
Status: C
Report Type: Standard Report
Report Date: 25-JUN-20
Date Received: 22-JUN-20
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8146054
Y: 43.3364653

---

93 | **1 of 1** | **ENE/299.7** | **99.8 / 0.00** | **ON** | **BORE**

Borehole ID: 621070
OGF ID: 215521524
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: JAN-1969
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 13.7
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Power auger
Orig Ground Elev m: 99.7
Elev Reliabil Note:
DEM Ground Elev m: 98.5
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.337376
Longitude DD: -79.815039
UTM Zone: 17
Easting: 596055
Northing: 4798963
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID:	218419654	**Mat Consistency:**	Hard
Top Depth:	6.2	**Material Moisture:**	
Bottom Depth:	8.3	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Shale	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND,SHALE. BROWN,GLACIAL,HARD, AGE GLACIAL.		

Geology Stratum ID:	218419652	**Mat Consistency:**	Hard
Top Depth:	2.1	**Material Moisture:**	
Bottom Depth:	5.8	**Material Texture:**	
Material Color:	Green	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:	Clay	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND,CLAY.GREEN,GLACIAL,HARD, AGE GLACIAL.		

Geology Stratum ID:	218419651	**Mat Consistency:**	Loose
Top Depth:	1.2	**Material Moisture:**	
Bottom Depth:	2.1	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,SAND. BROWN,MAN-MADE,LOOSE, AGE POST-GLACIAL.		

Geology Stratum ID:	218419650	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	1.2	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Gravel	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,GRAVEL,SAND. MAN-MADE,AGE POST-GLACIAL.		

Geology Stratum ID:	218419653	**Mat Consistency:**	Hard
Top Depth:	5.8	**Material Moisture:**	
Bottom Depth:	6.2	**Material Texture:**	
Material Color:	Green	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,CLAY,SAND. GREEN,GLACIAL,HARD, AGE GLACIAL.		

Geology Stratum ID:	218419655	**Mat Consistency:**	Hard
Top Depth:	8.3	**Material Moisture:**	
Bottom Depth:	13.7	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. RED,HARD,LAYERED, AGE UNDIFFERENTIATED.		

00040008000700500019005400205087000 42 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	M	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: HAM.txt RecordID: 000690 NTS_Sheet: 30M05C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

Unplottable Summary

Total: 32 Unplottable sites

DB	Company Name/Site Name	Address	City	Postal
CA	FORTINO'S SUPERMARKET LTD.	PLAINS ROAD EAST	BURLINGTON CITY ON	
CA	JUMBO VIDEO	BRANT ST., BURLINGTON P.C.MALL	BURLINGTON CITY ON	
CA		Leighland Road and Coric Avenue	Burlington ON	
CA		Leighland Road and Coric Avenue	Burlington ON	
CA		Leighland Road and Coric Avenue (Lot 15)	Burlington ON	
CA	Suncor Energy Products Inc.		Burlington ON	
CA	WHITE BIRCH LANDS LIMITED	TREELAND STREET	BURLINGTON CITY ON	
CA	SAMPURAN ENTERPRISES LTD.	PLAINS RD. EAST KINGS LANDING	BURLINGTON CITY ON	
CA	WHITE BIRCH LANDS LIMITED	TREELAND STREET	BURLINGTON CITY ON	
CA	R.M. OF HALTON	GLENDOR AVE.	BURLINGTON CITY ON	
CA	SAMPURAN ENTERPRISES LTD.	PLAINS RD. EAST KINGS LANDING	BURLINGTON CITY ON	
CA	UNITED LAND CORPORATION LTD.-PT. LOT 15	GLENDOR AVE.	BURLINGTON CITY ON	
CA	FALCO PROPERTY - PT. LOT 4, CONC. 2 SDS	GLENDOR AVENUE, NELSON TWP.	BURLINGTON CITY ON	
CA	IMPERIAL CITY CORP.	PLAINS RD. E.	BURLINGTON CITY ON	
CA	R.M. OF HALTON	BRANT ST/QUE INTERCHANGE	BURLINGTON CITY ON	
CA	BURLINGTON CITY	PLAINS RD. EAST	BURLINGTON CITY ON	
CA	WHITE BIRCH LANDS LIMITED	TREELAND ST. HALLEY HEIGHTS SB	BURLINGTON CITY ON	

CA	UNITED LAND CORPORATION LTD.-BRANT'S BLK	PT. LOT 15 R.P.#99/GLENDOR AVE	BURLINGTON CITY ON	
CA	R.M. OF HALTON	GLENDOR AVE.	BURLINGTON CITY ON	
CONV	SUN CHEMICAL CORPORATION LIMIT		ON	
ECA	Corporation of the City of Burlington	Leighland Road and Coric Ave	Burlington ON	L7R 3Z6
ECA	The Regional Municipality of Halton	Brant Street	Burlington ON	L6M 3L1
NCPL	Hercules Canada Inc.		Halton-Peel ON	
NCPL	Hercules Canada Inc.		Halton-Peel ON	
SPL	Dufferin Concrete	To the south of 640 Mullen Way	Burlington ON	
SPL		Plains Road, near QEW Niagara & Plains Rd	Burlington ON	
SPL	Sanimax ABP Inc.	Brant St., N of HWY 5	Burlington ON	
SPL	SANEXEN ENVIRONMENTAL SERVICES	TYANDAGA SUBSTATION BRANT STREET PCB DESTRUCTION UNIT	BURLINGTON CITY ON	
SPL		Brant St North of the QEW	Burlington ON	
SPL	TRANSPORT TRUCK	PLAINS ROAD NEAR 403/401. MOTOR VEHICLE (OPERATING FLUID)	BURLINGTON CITY ON	
SPL	UNKNOWN	LAKE ONTARIO - OUTFALL AT END OF BRANT ST.	BURLINGTON CITY ON	
SPL	CONSTRUCTION SITE	DEVELOPMENT SITE AT THE N.W. CORNER OF PLAINS RD. & JOB'S LANE,OPPOSITE FRANCIS (N.O.S.)	BURLINGTON CITY ON	

Unplottable Report

Site: ***FORTINO'S SUPERMARKET LTD.***
PLAINS ROAD EAST BURLINGTON CITY ON

Database: ***CA***

Certificate #:	8-3222-96-
Application Year:	96
Issue Date:	5/7/1996
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	COMMERCIAL KITCHEN EXHAUST HOOD
Contaminants:	Odour/Fumes
Emission Control:	No Controls

Site: ***JUMBO VIDEO***
BRANT ST., BURLINGTON P.C.MALL BURLINGTON CITY ON

Database: ***CA***

Certificate #:	8-3278-97-
Application Year:	97
Issue Date:	7/24/1997
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	COMMERCIAL KITCHEN EXHAUST SYSTEM
Contaminants:	Odour/Fumes
Emission Control:	Panel Filter

Site:
Leighland Road and Coric Avenue Burlington ON

Database: ***CA***

Certificate #:	1374-4Y6PLE
Application Year:	01
Issue Date:	7/6/01
Approval Type:	Municipal & Private sewage
Status:	Approved
Application Type:	New Certificate of Approval
Client Name:	Corporation of the Regional Municipality of Halton
Client Address:	1151 Bronte Road
Client City:	Oakville
Client Postal Code:	L6M 3L1
Project Description:	Construction of sanitary sewers on Coric Avenue and Leighland Road
Contaminants:	
Emission Control:	

Site:
Leighland Road and Coric Avenue Burlington ON

Database: ***CA***

Certificate #:	5264-4Y6PTT

Application Year: 01
Issue Date: 7/6/01
Approval Type: Municipal & Private water
Status: Approved
Application Type: New Certificate of Approval
Client Name: Corporation of the Regional Municipality of Halton
Client Address: 1151 Bronte Road
Client City: Oakville
Client Postal Code: L6M 3L1
Project Description: Construction of watermains on Leighland Road and Coric Avenue
Contaminants:
Emission Control:

Site: ***Database:*** ***CA***
Leighland Road and Coric Avenue (Lot 15) Burlington ON

Certificate #: 9978-4Z5LCS
Application Year: 01
Issue Date: 7/31/01
Approval Type: Municipal & Private sewage
Status: Approved
Application Type: New Certificate of Approval
Client Name: Corporation of the City of Burlington
Client Address: P.O. Box 5013, 426 Brant Street
Client City: Burlington
Client Postal Code: L7R 3Z6
Project Description: This application is for the construction of storm sewers and appurtenances on Leighland Road and Coric Avenue, from Glendor Avenue to West End.
Contaminants:
Emission Control:

Site: ***Suncor Energy Products Inc.*** ***Database:*** ***CA***
Burlington ON

Certificate #: 0845-6FHK5G
Application Year: 2007
Issue Date: 12/11/2007
Approval Type: Industrial Sewage Works
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***WHITE BIRCH LANDS LIMITED*** ***Database:*** ***CA***
TREELAND STREET BURLINGTON CITY ON

Certificate #: 3-0417-88-
Application Year: 88
Issue Date: 4/13/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***SAMPURAN ENTERPRISES LTD.***
PLAINS RD. EAST KINGS LANDING BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-2066-87-
Application Year: 87
Issue Date: 11/20/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***WHITE BIRCH LANDS LIMITED***
TREELAND STREET BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-0365-88-
Application Year: 88
Issue Date: 4/13/1988
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON***
GLENDOR AVE. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-1541-87-
Application Year: 87
Issue Date: 10/16/1987
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***SAMPURAN ENTERPRISES LTD.***
PLAINS RD. EAST KINGS LANDING BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-1744-87-
Application Year: 87
Issue Date: 11/20/1987
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:

Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***UNITED LAND CORPORATION LTD.-PT. LOT 15***
GLENDOR AVE. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-0369-91-
Application Year: 91
Issue Date: 4/19/1991
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***FALCO PROPERTY - PT. LOT 4, CONC. 2 SDS***
GLENDOR AVENUE, NELSON TWP. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-0368-91-
Application Year: 91
Issue Date: 4/19/1991
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***IMPERIAL CITY CORP.***
PLAINS RD. E. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-1379-89-
Application Year: 89
Issue Date: 8/14/1989
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON***
BRANT ST/QUE INTERCHANGE BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-1413-88-

Application Year: 88
Issue Date: 9/7/1988
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BURLINGTON CITY***
PLAINS RD. EAST BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-1430-92-
Application Year: 92
Issue Date: 11/2/1992
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***WHITE BIRCH LANDS LIMITED***
TREELAND ST. HALLEY HEIGHTS SB BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-0336-88-
Application Year: 88
Issue Date: 3/18/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***UNITED LAND CORPORATION LTD.-BRANT'S BLK***
PT. LOT 15 R.P.#99/GLENDOR AVE BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-1910-91-
Application Year: 91
Issue Date: 1/30/1992
Approval Type: Municipal sewage
Status: Approved in 1992
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF HALTON***
GLENDOR AVE. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-1857-87-
Application Year: 87
Issue Date: 10/16/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***SUN CHEMICAL CORPORATION LIMIT***
ON

Database: ***CONV***

File No:
Crown Brief No: 98-0000-9003
Court Location:
Publication City:
Publication Title:
Act:
Act(s):
First Matter:
Second Matter:
Investigation 1:
Investigation 2:
Penalty Imposed:
Description: THIS IS THE CENTRAL BRIEF FOR ALL P.O.A. TICKETS
Background:
URL:

Location:
Region: CENTRAL REGION
Ministry District:

Additional Details

Publication Date:
Count: 1
Act: EPA
Regulation: 347
Section: 18(5)
Act/Regulation/Section: EPA-347-18(5)
Date of Offence:
Date of Conviction:
Date Charged: 12/7/01
Charge Disposition: SUSPENDED SENTENCE
Fine: $305.00
Synopsis:

Site: ***Corporation of the City of Burlington***
Leighland Road and Coric Ave Burlington ON L7R 3Z6

Database: ***ECA***

Approval No: 9978-4Z5LCS
Approval Date: 2001-07-31
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Corporation of the City of Burlington
Address: Leighland Road and Coric Ave

MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/0785-4Z2HAN-14.pdf
PDF Site Location:

Site: ***The Regional Municipality of Halton***
Brant Street Burlington ON L6M 3L1

Database: ***ECA***

Approval No: 2285-6S8P4V
Approval Date: 2006-08-02
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-Municipal Drinking Water Systems
Project Type: Municipal Drinking Water Systems
Business Name: The Regional Municipality of Halton
Address: Brant Street
Full Address:
Full PDF Link:
PDF Site Location:

MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***Hercules Canada Inc.***
Halton-Peel ON

Database: ***NCPL***

Year: 2001
Site Name:
Facility Owner:
Discharge Type: Air
Sector: Air Discharges
District Area: Halton-Peel
Type of Concern: Reg. 346
Contaminant: Dimethyl Sulphide
Status Report:

Details

Incident Date:
Exceedance Start Date:
Exceedance End Date:
Limit/Unit/Freq:
Quantity Min/Max:
Facility Action: implementing improvements - action plan submitted
Ministry Action: Provincial Officer's Order issued

Site: ***Hercules Canada Inc.***
Halton-Peel ON

Database: ***NCPL***

Year: 2001
Site Name:
Facility Owner:
Discharge Type: Air
Sector: Air Discharges
District Area: Halton-Peel
Type of Concern: Reg. 346
Contaminant: carbon disulphide
Status Report:

Details

Incident Date:
Exceedance Start Date:
Exceedance End Date:
Limit/Unit/Freq:

Quantity Min/Max:
Facility Action: implementing improvements - action plan submitted
Ministry Action: Provincial Officer's Order issued

Site: ***Dufferin Concrete***
To the south of 640 Mullen Way Burlington ON

Database: ***SPL***

Ref No: 4151-87TKQB
Site No:
Incident Dt:
Year:
Incident Cause: Pipe Or Hose Leak
Incident Event:
Contaminant Code: 15
Contaminant Name: HYDRAULIC OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Possible
Nature of Impact: Other Impact(s); Surface Water Pollution
Receiving Medium:
Receiving Env:
MOE Response: No Field Response
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/29/2010
Dt Document Closed:
Incident Reason: Spill
Site Name: Hydraulic Oil Spill<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: Dufferin Concrete: 2 Gal Hydraulic Oil to Grnd
Contaminant Qty: 2 gal-Imp

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality:
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Land Spills
Source Type:

Site:
Plains Road, near QEW Niagara & Plains Rd Burlington ON

Database: ***SPL***

Ref No: 6643-7RQNSZ
Site No:
Incident Dt:
Year:
Incident Cause: Pipe Or Hose Leak
Incident Event:
Contaminant Code:
Contaminant Name: REFRIGERANT GAS, N.O.S.
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Confirmed
Nature of Impact: Air Pollution; Other Impact(s)
Receiving Medium:
Receiving Env:
MOE Response: No Field Response
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/4/2009
Dt Document Closed:
Incident Reason: Equipment Failure
Site Name: Fortino's <UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: Fortino's: 681kg of R507 released to atm
Contaminant Qty: 681 kg

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type: Other
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: Burlington
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Air Spills - Gases and Vapours
Source Type:

Site: ***Sanimax ABP Inc.***
Brant St., N of HWY 5 Burlington ON

Database: ***SPL***

Ref No:	3117-AC3LZM	***Discharger Report:***	
Site No:	NA	***Material Group:***	
Incident Dt:	2016/07/21	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:		***Sector Type:***	Miscellaneous Industrial
Incident Event:	Leak/Break	***Agency Involved:***	
Contaminant Code:	42	***Nearest Watercourse:***	
Contaminant Name:	WASTE SLURRY	***Site Address:***	Brant St., N of HWY 5
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:		***Site Municipality:***	Burlington
Nature of Impact:		***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:	Land	***Northing:***	4801849
MOE Response:	No	***Easting:***	592708
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	2016/07/21	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	Highway Spills (usually highway accidents)
Incident Reason:	Weather Conditions	***Source Type:***	
Site Name:	Roadway<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Burlington: 10kg Chicken Byproduct to Road.		
Contaminant Qty:	10 kg		

Site: ***SANEXEN ENVIRONMENTAL SERVICES***
TYANDAGA SUBSTATION BRANT STREET PCB DESTRUCTION UNIT BURLINGTON CITY ON

Database: ***SPL***

Ref No:	30633	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	2/6/1990	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	PROCESS UPSET	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:		***Site Municipality:***	14101
Nature of Impact:		***Site Lot:***	
Receiving Medium:	AIR	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	M.O.E.
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	2/6/1990	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	COMBUSTION PROBLEMS	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	SANEXEN M.D.U. HEATER MALFUNCTION-HEAVY BLACK SMOKE. *MEDIA*		
Contaminant Qty:			

Site:
Brant St North of the QEW Burlington ON

Database: ***SPL***

Ref No:	7003-7U4226	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:		***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	Other Discharges	***Sector Type:***	Sewer
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:	SEWAGE,RAW UNCHLORINATED	***Site Address:***	

Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	Not Anticipated	***Site Municipality:***	Burlington
Nature of Impact:	Surface Water Pollution	***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:	No Field Response	***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	7/18/2009	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	Watercourse Spills
Incident Reason:	Spill	***Source Type:***	
Site Name:	Milestones<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Milestones: Sanitary surcharge; 15L raw sewage to CB.		
Contaminant Qty:	15 L		

Site: ***TRANSPORT TRUCK***
PLAINS ROAD NEAR 403/401. MOTOR VEHICLE (OPERATING FLUID) BURLINGTON CITY ON

Database: ***SPL***

Ref No:	80602	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	1/5/1993	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	TRUCK/TRAILER OVERTURN	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	14101
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	1/5/1993	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	ERROR	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	FREDERICK TRANSPORT-UNKN QTY DIESEL FUEL TO ROAD DUE TO TRUCK OVERTURN.		
Contaminant Qty:			

Site: ***UNKNOWN***
LAKE ONTARIO - OUTFALL AT END OF BRANT ST. BURLINGTON CITY ON

Database: ***SPL***

Ref No:	31611	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	3/4/1990	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	UNKNOWN	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	14101
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	WORKS

Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	3/4/1990	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	UNKNOWN	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	EST. 2 L DIESEL FUEL DUMPED TO STORM SEWER & LAKE ONTARIO.		
Contaminant Qty:			

Site: ***CONSTRUCTION SITE***
DEVELOPMENT SITE AT THE N.W. CORNER OF PLAINS RD. & JOB'S LANE,OPPOSITE FRANCIS (N.O.S.)
BURLINGTON CITY ON

Database: ***SPL***

Ref No:	41775	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	10/5/1990	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	OTHER CONTAINER LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	14101
Nature of Impact:	Soil contamination	***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	HALTON REGION, BURLINGTON F.D.
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	10/5/1990	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	EQUIPMENT FAILURE	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	CARDEEN CONSTRUCTION - 20 L OF DIESEL FUEL TO GROUND FROM GENERATOR.		
Contaminant Qty:			

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ***Note:*** *Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.*

Abandoned Aggregate Inventory: Provincial AAGR

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

Government Publication Date: Sept 2002*

Aggregate Inventory: Provincial AGR

The Ontario Ministry of Northern Development, Mines, Natural Resources and Forestry (ONDMNRF) maintains this database of pits and quarries. The database provides information regarding the registered owner/operator, location name, operation type, approval type, and maximum annual tonnage.

Government Publication Date: Up to Oct 2022

Abandoned Mine Information System: Provincial AMIS

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

Government Publication Date: 1800-Mar 2022

Anderson's Waste Disposal Sites: Private ANDR

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1860s-Present

Aboveground Storage Tanks: Provincial AST

Historical listing of aboveground storage tanks made available by the Department of Natural Resources and Forestry. Includes tanks used to hold water or petroleum. This dataset has been retired as of September 25, 2014 and will no longer be updated.

Government Publication Date: May 31, 2014

Automobile Wrecking & Supplies: Private AUWR

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

Government Publication Date: 1999-May 31, 2022

Borehole: Provincial BORE

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

Government Publication Date: 1875-Jul 2018

Certificates of Approval: Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

Government Publication Date: 1985-Oct 30, 2011*

Dry Cleaning Facilities: Federal CDRY

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.

Government Publication Date: Jan 2004-Dec 2020

Commercial Fuel Oil Tanks: Provincial CFOT

Locations of commercial underground fuel oil tanks. This is not a comprehensive or complete inventory of commercial fuel tanks in the province; this listing is a copy of records of registered commercial underground fuel oil tanks obtained under Access to Public Information.
Note that the following types of tanks do not require registration: waste oil tanks in apartments, office buildings, residences, etc.; aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Chemical Manufacturers and Distributors: Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

Government Publication Date: 1999-Jan 31, 2020

Chemical Register: Private CHM

This database includes a listing of locations of facilities within the Province or Territory that either manufacture and/or distributes chemicals.

Government Publication Date: 1999-May 31, 2022

Compressed Natural Gas Stations: Private CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

Government Publication Date: Dec 2012 -Sep 2022

Inventory of Coal Gasification Plants and Coal Tar Sites: Provincial COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

Government Publication Date: Apr 1987 and Nov 1988*

Compliance and Convictions: Provincial CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

Government Publication Date: 1989-Nov 2022

Certificates of Property Use: Provincial CPU

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

Government Publication Date: 1994 - Dec 31, 2022

Drill Hole Database: Provincial DRL

The Ontario Drill Hole Database contains information on more than 113,000 percussion, overburden, sonic and diamond drill holes from assessment files on record with the department of Mines and Minerals. Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted to the MNDM. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

Government Publication Date: 1886 - Oct 2022

Delisted Fuel Tanks: Provincial DTNK

List of fuel storage tank sites that were once found in - and have since been removed from - the list of fuel storage tanks made available by the regulatory agency under Access to Public Information.

Government Publication Date: Feb 28, 2022

Environmental Activity and Sector Registry: Provincial EASR

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval), Please see our ECA database.

Government Publication Date: Oct 2011- Dec 31, 2022

Environmental Registry: Provincial EBR

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

Government Publication Date: 1994 - Dec 31, 2022

Environmental Compliance Approval: Provincial ECA

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

Government Publication Date: Oct 2011- Dec 31, 2022

Environmental Effects Monitoring: Federal EEM

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

Government Publication Date: 1992-2007*

ERIS Historical Searches: Private EHS

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

Government Publication Date: 1999-Jul 31, 2022

Environmental Issues Inventory System: Federal EIIS

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

Government Publication Date: 1992-2001*

Emergency Management Historical Event: Provincial EMHE

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

Government Publication Date: Apr 30, 2022

Environmental Penalty Annual Report: Provincial EPAR

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment and Climate Change. These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

Government Publication Date: Jan 1, 2011 - Dec 31, 2021

List of Expired Fuels Safety Facilities: Provincial EXP

List of facilities and tanks for which there was once a fuel registration. This is not a comprehensive or complete inventory of expired tanks/tank facilities in the province; this listing is a copy of previously registered tanks and facilities obtained under Access to Public Information. Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc; includes tanks which have been removed from the ground.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Federal Convictions: Federal FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

Government Publication Date: 1988-Jun 2007*

Contaminated Sites on Federal Land: Federal FCS

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government. Includes fire training sites and sites at which Per- and Polyfluoroalkyl Substances (PFAS) are a concern.

Government Publication Date: Jun 2000-Dec 2022

Fisheries & Oceans Fuel Tanks: Federal FOFT

Fisheries & Oceans Canada maintains an inventory of aboveground & underground fuel storage tanks located on Fisheries & Oceans property or controlled by DFO. Our inventory provides information on the site name, location, tank owner, tank operator, facility type, storage tank location, tank contents & capacity, and date of tank installation.

Government Publication Date: 1964-Sep 2019

Federal Identification Registry for Storage Tank Systems (FIRSTS): Federal FRST

A list of federally regulated Storage tanks from the Federal Identification Registry for Storage Tank Systems (FIRSTS). FIRSTS is Environment and Climate Change Canada's database of storage tank systems subject to the Storage Tank for Petroleum Products and Allied Petroleum Products Regulations. The main objective of the Regulations is to prevent soil and groundwater contamination from storage tank systems located on federal and aboriginal lands. Storage tank systems that do not have a valid identification number displayed in a readily visible location on or near the storage tank system may be refused product delivery.

Government Publication Date: May 31, 2018

Fuel Storage Tank: Provincial FST

List of registered private and retail fuel storage tanks. This is not a comprehensive or complete inventory of private and retail fuel storage tanks in the province; this listing is a copy of registered private and retail fuel storage tanks, obtained under Access to Public Information.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Fuel Storage Tank - Historic: Provincial FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

Government Publication Date: Pre-Jan 2010*

Ontario Regulation 347 Waste Generators Summary: Provincial GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

Government Publication Date: 1986-Oct 31, 2022

Greenhouse Gas Emissions from Large Facilities: Federal GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO2 eq).

Government Publication Date: 2013-Dec 2019

TSSA Historic Incidents: Provincial HINC

List of historic incidences of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen recorded by the TSSA in their previous incident tracking system. The TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of historical fuel spills and leaks in the province. This listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: 2006-June 2009*

Indian & Northern Affairs Fuel Tanks: Federal IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

Government Publication Date: 1950-Aug 2003*

Fuel Oil Spills and Leaks: Provincial INC

Listing of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen reported to the Spills Action Centre (SAC). This is not a comprehensive or complete inventory of fuel-related leaks, spills, and incidents in the province; this listing in a copy of incidents reported to the SAC, obtained under Access to Public Information. Includes incidents from fuel-related hazards such as spills, fires, and explosions. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Landfill Inventory Management Ontario: Provincial LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the Ministry of the Environment, Conservation and Parks compiles new and updated information. Includes small and large landfills currently operating as well as those which are closed and historic. Operators of larger landfills provide landfill information for the previous operating year to the ministry for LIMO including: estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills include information such as site owner, site location and certificate of approval # and status.

Government Publication Date: Mar 21, 2022

Canadian Mine Locations: Private MINE

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

Government Publication Date: 1998-2009*

Mineral Occurrences: Provincial MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

Government Publication Date: 1846-Feb 2022

National Analysis of Trends in Emergencies System (NATES): Federal NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

Government Publication Date: 1974-1994*

Non-Compliance Reports: Provincial NCPL

The Ministry of the Environment provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act.

Government Publication Date: Dec 31, 2021

National Defense & Canadian Forces Fuel Tanks: Federal NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

Government Publication Date: Up to May 2001*

National Defense & Canadian Forces Spills: Federal NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

Government Publication Date: Mar 1999-Apr 2018

National Defence & Canadian Forces Waste Disposal Sites: Federal NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

Government Publication Date: 2001-Apr 2007*

National Energy Board Pipeline Incidents: Federal NEBI

Locations of pipeline incidents from 2008 to present, made available by the Canada Energy Regulator (CER) - previously the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

Government Publication Date: 2008-Jun 30, 2021

National Energy Board Wells: Federal NEBP

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release date.

Government Publication Date: 1920-Feb 2003*

National Environmental Emergencies System (NEES): Federal NEES

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December 2004.

Government Publication Date: 1974-2003*

National PCB Inventory: Federal NPCB

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

Government Publication Date: 1988-2008*

National Pollutant Release Inventory: Federal NPRI

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances.

Government Publication Date: 1993-May 2017

Oil and Gas Wells: Private OGWE

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

Government Publication Date: 1988-Nov 30, 2022

Ontario Oil and Gas Wells: Provincial OOGW

In 1998, the MNR handed over to the Ontario Oil, Gas and Salt Resources Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database include well owner/operator, location, permit issue date, and well cap date, license No., status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provide for each well record.

Government Publication Date: 1800-Aug 2021

Inventory of PCB Storage Sites: Provincial OPCB

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

Government Publication Date: 1987-Oct 2004; 2012-Dec 2013

Orders: Provincial ORD

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

Government Publication Date: 1994 - Dec 31, 2022

Canadian Pulp and Paper: Private PAP

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

Government Publication Date: 1999, 2002, 2004, 2005, 2009-2014

Parks Canada Fuel Storage Tanks: Federal PCFT

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

Government Publication Date: 1920-Jan 2005*

Pesticide Register: Provincial PES

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

Government Publication Date: Oct 2011- Dec 31, 2022

Pipeline Incidents: Provincial PINC

List of pipeline incidents (strikes, leaks, spills). This is not a comprehensive or complete inventory of pipeline incidents in the province; this listing in an historical copy of records previously obtained under Access to Public Information. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2021

Private and Retail Fuel Storage Tanks: Provincial PRT

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

Government Publication Date: 1989-1996*

Permit to Take Water: Provincial PTTW

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include PTTW's on the registry such as OWRA s. 34 - Permit to take water.

Government Publication Date: 1994 - Dec 31, 2022

Ontario Regulation 347 Waste Receivers Summary: Provincial REC

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

Government Publication Date: 1986-1990, 1992-2019

Record of Site Condition: Provincial RSC

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up.
RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09).

Government Publication Date: 1997-Sept 2001, Oct 2004-Dec 2022

Retail Fuel Storage Tanks: Private RST

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

Government Publication Date: 1999-May 31, 2022

Scott's Manufacturing Directory: Private SCT

Scott's Directories is a data bank containing information on over 200,000 manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, and main products are included in this database.

Government Publication Date: 1992-Mar 2011*

Ontario Spills: Provincial SPL

List of spills and incidents made available the Ministry of the Environment, Conservation and Parks. This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X. The Ministry of the Environment, Conservation and Parks cites the coronavirus pandemic as an explanation for delays in releasing data pursuant to requests.

Government Publication Date: 1988-Sep 2020; Dec 2020-Mar 2021

Wastewater Discharger Registration Database: Provincial SRDS

Facilities that report either municipal treated wastewater effluent or industrial wastewater discharges under the Effluent Monitoring and Effluent Limits (EMEL) and Municipal/Industrial Strategy for Abatement Regulations. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment keeps record of direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation, Mining, Petroleum Refining, Organic Chemicals, Inorganic Chemicals, Pulp & Paper, Metal Casting, Iron & Steel, and Quarries.

Government Publication Date: 1990-Dec 31, 2020

Anderson's Storage Tanks: Private TANK

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1915-1953*

Transport Canada Fuel Storage Tanks: Federal TCFT

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

Government Publication Date: 1970 - Apr 2020

Variances for Abandonment of Underground Storage Tanks: Provincial VAR

Listing of variances granted for storage tank abandonment. This is not a comprehensive or complete inventory of tank abandonment variances in the province; this listing is a copy of tank abandonment variance records previously obtained under Access to Public Information. In Ontario, registered underground storage tanks must be removed within two years of disuse; if removal of a tank is not feasible, an application may be sought for a variance from this code requirement.
Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Waste Disposal Sites - MOE CA Inventory: Provincial WDS

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

Government Publication Date: Oct 2011- Dec 31, 2022

Waste Disposal Sites - MOE 1991 Historical Approval Inventory: Provincial WDSH

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

Government Publication Date: Up to Oct 1990*

Water Well Information System: Provincial WWIS

This database describes locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table.

Government Publication Date: Jun 30 2022

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

Appendix F – Municipal Records

ERIS City Directory Search

as of 03/21/2023

Project Property: Phase one ESA -1376 and 1382 Plain Road East,Burlington, ON - Phase one ESA -1376 and 1382 Plain Road East,, Burlington, ON L7R 3P8 CA

Product Description: CD - QUOTE Custom City Directory Search

Notes to Client:

ERIS Order No: 23021000646

ADDRESS	YEAR	LISTING	COMMENTS	SOURCE	CITY	COUNTY	STATE
1315-1340 BONNIE COURT	2021	NO LISTING FOUND		DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	NO LISTING FOUND		DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	NO LISTING FOUND		DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2001	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1996	STREET NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1990	STREET NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1986	STREET NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1981	STREET NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1976	STREET NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1971	STREET NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1966	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1961	STREET NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1957	STREET NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
920 BRANT STREET	2021	KKP	E-COMMERCE	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	SIGNS PLUS DIGITAL GRAPHICS	FLAG POLES (WHLS); TI	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	TERRAPEX ENVIRONMENTAL LTD	ENVIRONMENTAL &an	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	SHEILA NAILS AESTHETICS	BEAUTY SALONS; MAN	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	CLIMATECARE COOPERATIVE	PUMPS-REPAIRING	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	SABATINO HAIR DESIGN	BEAUTY SALONS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	GARDEN GALLERY INC	GARDEN CENTERS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	ELIZABETH MANTINI	NONCLASSIFIED ESTAB	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	SONAGGI COMPUTER	COMMERCIAL PRINTIN	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	MEYERS DON AGT	REAL ESTATE BUYERS &	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	ORTHOGAIT INC	FEDERAL GOVERNMEN	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	CION COULTER	ENGINEERS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	AIR TOOL SVC	TOOLS-PNEUMATIC (W	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	KCY AT LAW	ASSOCIATIONS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	KKP	COMMERCIAL LITHOGI	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	OAKWAY CABINETS DESIGN STUDIO	CABINETS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	KWIK-KOPY DESIGN & PRINT CTR	OTHER BUSINESS SVC (	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	COULTER BUILDING CONSULTANTS	ENGINEERING SVCS; EI	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	CENTENNIAL BUSINESS MACHINES	FURNITURE MERCHAN	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	SIGNS PLUS DIGITAL GRAPHICS	DISPLAY ADVERTISING;	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	SERVICE MASTER CONTRACT SVC	JANITORIAL SVCS; CARI	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	KWIK KOPY DESIGN PRINT CTR	OTHER BUSINESS SVC (	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	TERRAPEX ENVIRONMENTAL LTD	RESEARCH & DEVI	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	RIGHT AT HOME REALTY INC	REAL ESTATE	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	EDGECOMBE ABRASIVES LTD	INDUSTRIAL SUPPLIES I	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	SABATINO HAIR DESIGN	BEAUTY SALONS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	CARBO-TECH GROUP INC	PLUMBING & HVA	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	CLIMATE CARE CO-OP	COMMERCIAL MACHIN	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	APEX COURIERS INC	GENERAL FREIGHT TRU	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	PPC MICROSMITH	FINANCIAL SERVICES	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	360 ENERGY INC	HUMAN RESOURCE CO	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	ORTHOGAIT INC	ALL OTHER HEALTH &a	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	WOTIFCOM INC	HOTELS & MOTEL	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	AIR TOOL SVC	WHOLESALEINDUSTRIA	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	HAAS ANGELA	OFFICES OF REAL ESTA	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	KCY AT LAW	OFFICES OF LAWYERS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	EDWARDS	ALL OTHER DURABLE G	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	CARBO-TECH ENVIRONMENTAL GROUP	PLUMBING & HVA	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	KWIK-KOPY DESIGN & PRINT CTR	OTHER BUSINESS SVC (	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	COULTER BUILDING CONSULTANTS	ENGINEERING SVCS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	CENTENNIAL BUSINESS MACHINES	OTHER ELECTRONIC PA	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	SIGNS PLUS DIGITAL GRAPHICS	ALL OTHER MISC TEXTI	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	ATLAS ROBINSON CLIMATE CARE	PLUMBING & HVA	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	TERRAPEX ENVIRONMENTAL LTD	RESEARCH & DEVI	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	SERVICEMASTER CONTRACT SVC	JANITORIAL SVCS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	ATLAS ROBINSON CLIMATECARE	PLUMBING & HVA	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	GERRY B ENTERPRISES INC	SPORTING GOODS STO	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	EDGECOMBE ABRASIVES LTD	INDUSTRIAL SUPPLIES I	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	CANADIAN NIAGARA ENERGY	HUMAN RESOURCE CO	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	CLIMATE CARE CO-OP	COMMERCIAL MACHIN	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	CHAPEL OF THE AIR	RELIGIOUS ORGANIZAT	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	APEX COURIERS INC	COURIERS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	ORTHOGAIT INC	ALL OTHER HEALTH &a	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	WOTIFCOM INC	HOTELS & MOTEL	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	G E SECURITY	ALL OTHER DURABLE G	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	AIR TOOL SVC	WHOLESALE-INDUSTRI	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2006	WOTIFCOM INC		VERNONS	BURLINGTON	HALTON	ON
920-1030 Even BRANT STREET	2006	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
920 BRANT STREET	2006	SERVICE MASTER CONTRACT SERVICES		VERNONS	BURLINGTON	HALTON	ON
	2006	EDWARDS A UNIT OF SPX CANADA INC		VERNONS	BURLINGTON	HALTON	ON
	2006	KWIK KOPY DESIGN & PRINT CENTER		VERNONS	BURLINGTON	HALTON	ON
	2006	CARBO-TECH ENVIRONMENTAL GROUP		VERNONS	BURLINGTON	HALTON	ON
	2006	COULTER BUILDING CONSULTANTS		VERNONS	BURLINGTON	HALTON	ON
	2006	CENTENNIAL BUSINESS MACHINES		VERNONS	BURLINGTON	HALTON	ON
	2006	MDD DESIGN & CONSULTING INC		VERNONS	BURLINGTON	HALTON	ON
	2006	ATLAS ROBINSON CLIMATECARE		VERNONS	BURLINGTON	HALTON	ON
	2006	PEERLESS CONNECTIONS INC		VERNONS	BURLINGTON	HALTON	ON
	2006	CANADIAN CONDO INSTITUTE		VERNONS	BURLINGTON	HALTON	ON
	2006	EDGECOMBE ABRASIVES LTD		VERNONS	BURLINGTON	HALTON	ON
	2006	CANADIAN NIAGARA ENERGY		VERNONS	BURLINGTON	HALTON	ON
	2006	FENGATE PROPERTY MGMT		VERNONS	BURLINGTON	HALTON	ON
	2006	CLIMATE CARE CO-OP		VERNONS	BURLINGTON	HALTON	ON
	2006	CHAPEL OF THE AIR		VERNONS	BURLINGTON	HALTON	ON
	2006	AIR TOOL SERVICE		VERNONS	BURLINGTON	HALTON	ON
	2006	ORTHOGAIT INC		VERNONS	BURLINGTON	HALTON	ON
	2001	ORTHOGAIT INC		VERNONS	BURLINGTON	HALTON	ON
920-1030 Even BRANT STREET	2001	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
920 BRANT STREET	2001	SERVICE MASTER CONTRACT SERVICES		VERNONS	BURLINGTON	HALTON	ON

ERIS City Directory Search

as of 03/21/2023

Project Property: Phase one ESA -1376 and 1382 Plain Road East,Burlington, ON - Phase one ESA -1376 and 1382 Plain Road East,, Burlington, ON L7R 3P8 CA

Product Description: CD - QUOTE Custom City Directory Search

Notes to Client:

ERIS Order No: 23021000646

ADDRESS	YEAR	LISTING	COMMENTS	SOURCE	CITY	COUNTY	STATE
	2001	CARBO TECH ENVIRONMENTAL GROUP		VERNONS	BURLINGTON	HALTON	ON
	2001	SIGNS PLUS BUSINESS GRAPHICS		VERNONS	BURLINGTON	HALTON	ON
	2001	EDWARDS A UNIT OF SIGNAL LTD		VERNONS	BURLINGTON	HALTON	ON
	2001	CENTENNIAL BUSINESS MACHINES		VERNONS	BURLINGTON	HALTON	ON
	2001	EDGECOMBE ABRASIVES LTD		VERNONS	BURLINGTON	HALTON	ON
	2001	MH&W INTERNATIONAL LTD		VERNONS	BURLINGTON	HALTON	ON
	2001	RFM ELECTRO SALES LTD		VERNONS	BURLINGTON	HALTON	ON
	2001	BRANT TRAVEL SERVICE		VERNONS	BURLINGTON	HALTON	ON
	2001	ON TOUR PRODUCTIONS		VERNONS	BURLINGTON	HALTON	ON
	2001	M7 MEDIA SOLUTIONS		VERNONS	BURLINGTON	HALTON	ON
	2001	CHAPEL OF THE AIR		VERNONS	BURLINGTON	HALTON	ON
	2001	PRO-FIT LABS INC		VERNONS	BURLINGTON	HALTON	ON
	2001	AIR TOOL SERVICE		VERNONS	BURLINGTON	HALTON	ON
	2001	MONEX INTL INC		VERNONS	BURLINGTON	HALTON	ON
	1996	RACOL CONTROLS		VERNONS	BURLINGTON	HALTON	ON
920-1030 Even BRANT STREET	1996	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
920 BRANT STREET	1996	OFF THE WALL SCREENPRINTING & APPAREL		VERNONS	BURLINGTON	HALTON	ON
	1996	CULLIS REALTY & APPRAISAL LTD		VERNONS	BURLINGTON	HALTON	ON
	1996	CENTENNIAL BUSINESS MACHINES		VERNONS	BURLINGTON	HALTON	ON
	1996	CHETTLE AL REAL ESTATE LTD		VERNONS	BURLINGTON	HALTON	ON
	1996	TELECOM COMPUTER PRODUCTS		VERNONS	BURLINGTON	HALTON	ON
	1996	BRANT TRAVEL SERVICE		VERNONS	BURLINGTON	HALTON	ON
	1996	PURE TOUCH SERVICES		VERNONS	BURLINGTON	HALTON	ON
	1996	ON TOUR PRODUCTIONS		VERNONS	BURLINGTON	HALTON	ON
	1996	COMMUNITY APPLIANCE		VERNONS	BURLINGTON	HALTON	ON
	1996	BURLINGTON JOURNAL		VERNONS	BURLINGTON	HALTON	ON
	1996	ASPECTS OF DANCE		VERNONS	BURLINGTON	HALTON	ON
	1990	ULTRA CARE		VERNONS	BURLINGTON	HALTON	ON
920-1030 Even BRANT STREET	1990	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
920 BRANT STREET	1990	AIR TOOL SERVICE		VERNONS	BURLINGTON	HALTON	ON
	1990	EDWARDS OF CANADA		VERNONS	BURLINGTON	HALTON	ON
	1990	BRANT TICKET AGENCY		VERNONS	BURLINGTON	HALTON	ON
	1990	PURE TOUCH SERVICES		VERNONS	BURLINGTON	HALTON	ON
	1990	MATRIX MARBLE & TILE LTD		VERNONS	BURLINGTON	HALTON	ON
	1990	PEST CONTROL SYSTEMS INC		VERNONS	BURLINGTON	HALTON	ON
	1990	HELP-U-SELL BURLINGTON INC		VERNONS	BURLINGTON	HALTON	ON
	1990	STEVENSON ENVIRONMENTAL LTD		VERNONS	BURLINGTON	HALTON	ON
	1990	CENTENNIAL BUSINESS MACHINES		VERNONS	BURLINGTON	HALTON	ON
	1990	CULLIS REALTY & APPRAISAL LTD		VERNONS	BURLINGTON	HALTON	ON
	1990	ROADWAY COMMUNICATIONS BURLINGTON		VERNONS	BURLINGTON	HALTON	ON
920-1030 Even BRANT STREET	1986	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1981	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1976	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1971	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1966	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1961	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1957	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
922 BRANT STREET	1996	BURLINGTON IMPORTS		VERNONS	BURLINGTON	HALTON	ON
926 BRANT STREET	1966	SUNSHINE WINDOW CLEANING CO		VERNONS	BURLINGTON	HALTON	ON
	1961	SUNSHINE WINDOW CLEANING CO		VERNONS	BURLINGTON	HALTON	ON
	1957	SUNSHINE WINDOW CLEANING CO		VERNONS	BURLINGTON	HALTON	ON
930 BRANT STREET	2012	SUN SHELTERS INDUSTRY INC	SIGN MFG	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	1996	BURLINGTON TREE SURGEONS CO LTD		VERNONS	BURLINGTON	HALTON	ON
	1990	BURLINGTON TREE SURGEONS CO LTD		VERNONS	BURLINGTON	HALTON	ON
	1986	BURLINGTON TREE SURGEONS		VERNONS	BURLINGTON	HALTON	ON
	1981	BURLINGTON TREE SURGEONS		VERNONS	BURLINGTON	HALTON	ON
	1966	ELEQUIPMENT LTD		VERNONS	BURLINGTON	HALTON	ON
	1961	GAUDAUR MOTORS		VERNONS	BURLINGTON	HALTON	ON
	1957	GAUDAUR MOTORS		VERNONS	BURLINGTON	HALTON	ON
932 BRANT STREET	2021	SELECT SPRINKLERS	SPRINKLERS-GARDEN &	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	FOSTER AUTO GROUP	USED CAR DEALERS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	SELECT CHRISTMAS LGHTS INSTLTN	NURSERY, GARDEN, &c	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	MAINWAY ELECTRIC LTD	ELECTRICAL CONTRS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	SELECT SPRINKLERS	SPRINKLERS-GARDEN &	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	FOSTER AUTO GROUP	USED CAR DEALERS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	JOHN WEEMHOFF ELECTRIC LTD	ELECTRICAL CONTRS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	DOLLAR THRIFTY CAR RENTALS	PASSENGER CARS REN	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	MAINWAY ELECTRIC LTD	ELECTRICAL CONTRS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	THRIFTY CAR RENTAL	PASSENGER CARS REN	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2006	MAX AIR		VERNONS	BURLINGTON	HALTON	ON
	2006	DOLLAR THRIFTY AUTOMOTIVE GROUP CAN INC		VERNONS	BURLINGTON	HALTON	ON
	2006	WEEMHOFF JOHN ELECTRIC LTD		VERNONS	BURLINGTON	HALTON	ON
	2006	BURLINGTON IMPORTS		VERNONS	BURLINGTON	HALTON	ON
	2006	FOSTER AUTO GROUP		VERNONS	BURLINGTON	HALTON	ON
	2006	MAINWAY ELECTRIC		VERNONS	BURLINGTON	HALTON	ON
	2006	FOSTER JOHN AUTO		VERNONS	BURLINGTON	HALTON	ON
	2001	BURLINGTON IMPORTS		VERNONS	BURLINGTON	HALTON	ON
	2001	BURLINGTON AUTO & LEASE CENTRE		VERNONS	BURLINGTON	HALTON	ON
	2001	AL PAPARONI ACCOUNTING & TAX		VERNONS	BURLINGTON	HALTON	ON
	2001	WEEMHOFF JOHN ELECTRIC LTD		VERNONS	BURLINGTON	HALTON	ON
	2001	MAINWAY ELECTRIC LTD		VERNONS	BURLINGTON	HALTON	ON
	1996	MAINWAY ELECTRIC LTD		VERNONS	BURLINGTON	HALTON	ON
	1990	BRANT WINDOWS INC		VERNONS	BURLINGTON	HALTON	ON
	1990	WEEMHOFF ELECTRIC LTD		VERNONS	BURLINGTON	HALTON	ON
	1990	JR AUTO WHOLESALE		VERNONS	BURLINGTON	HALTON	ON
	1986	ENERGY UPDATE		VERNONS	BURLINGTON	HALTON	ON
	1981	WIEMHOFF ELECTRIC		VERNONS	BURLINGTON	HALTON	ON
	1976	ALDERSHOT ASPHALT CONTRACTORS		VERNONS	BURLINGTON	HALTON	ON
	1971	DAN'S WELDING & FABRICATING LTD		VERNONS	BURLINGTON	HALTON	ON
	1966	DAN'S WELDING & FABRICATING		VERNONS	BURLINGTON	HALTON	ON
	1961	DAN'S WELDING & FABRICATING		VERNONS	BURLINGTON	HALTON	ON

ERIS City Directory Search

as of 03/21/2023

Project Property: Phase one ESA -1376 and 1382 Plain Road East,Burlington, ON - Phase one ESA -1376 and 1382 Plain Road East,, Burlington, ON L7R 3P8 CA

Product Description: CD - QUOTE Custom City Directory Search

Notes to Client:

ERIS Order No: 23021000646

ADDRESS	YEAR	LISTING	COMMENTS	SOURCE	CITY	COUNTY	STATE
	1957	DAN'S WELDING & FABRICATING		VERNONS	BURLINGTON	HALTON	ON
934 BRANT STREET	1966	GREIG'S HAIRSTYLING		VERNONS	BURLINGTON	HALTON	ON
	1966	CHRISTIAN SERVICE BRIGADE		VERNONS	BURLINGTON	HALTON	ON
	1961	MACGREGOR BEAUTY SHOP		VERNONS	BURLINGTON	HALTON	ON
	1957	MACGREGOR BEAUTY SHOP		VERNONS	BURLINGTON	HALTON	ON
938 BRANT STREET	1966	OSSIE'S BARBER SHOP		VERNONS	BURLINGTON	HALTON	ON
	1961	OSSIE'S BARBER SHOPS		VERNONS	BURLINGTON	HALTON	ON
	1957	OSSIE'S BARBER SHOPS		VERNONS	BURLINGTON	HALTON	ON
940 BRANT STREET	1966	TINNING'S GROCERY		VERNONS	BURLINGTON	HALTON	ON
	1961	TINNING L & SON LTD		VERNONS	BURLINGTON	HALTON	ON
	1957	TINNING L & SON LTD		VERNONS	BURLINGTON	HALTON	ON
942 BRANT STREET	2021	ASHLAND CANADA	BOILERS-REPAIRING &c	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	ASHLAND CANADA	OTHER CHEMICAL MFR	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	HERCULES CANADA INC	OTHER CHEMICAL MFR	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	HERCULES CANADA INC	OTHER CHEMICAL MFR	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2006	HERCULES CANADA INC		VERNONS	BURLINGTON	HALTON	ON
	2001	HERCULES CANADA INC		VERNONS	BURLINGTON	HALTON	ON
	1996	HERCULES CANADA INC		VERNONS	BURLINGTON	HALTON	ON
	1990	HERCULES CANADA INC		VERNONS	BURLINGTON	HALTON	ON
	1986	HERCULES CANADA INC		VERNONS	BURLINGTON	HALTON	ON
	1981	HERCULES CANADA INC		VERNONS	BURLINGTON	HALTON	ON
	1976	HERCULES CANADA LTD		VERNONS	BURLINGTON	HALTON	ON
	1971	HERCULES CANADA LTD		VERNONS	BURLINGTON	HALTON	ON
	1966	HERCULES POWDER CO (CAN) LTD		VERNONS	BURLINGTON	HALTON	ON
	1961	HERCULES POWDER CO (CAN) LTD		VERNONS	BURLINGTON	HALTON	ON
	1957	HERCULES POWDER CO (CAN) LTD		VERNONS	BURLINGTON	HALTON	ON
944 BRANT STREET	1981	NIAGAR CHEMICAL CO		VERNONS	BURLINGTON	HALTON	ON
	1976	F M C OF CANADA LTD		VERNONS	BURLINGTON	HALTON	ON
	1971	NIAG CHEM		VERNONS	BURLINGTON	HALTON	ON
	1966	NIAGARA BRAND CHEMICALS		VERNONS	BURLINGTON	HALTON	ON
	1961	NIAG BRAND CHEMICALS		VERNONS	BURLINGTON	HALTON	ON
	1957	NIAG BRAND CHEMICALS		VERNONS	BURLINGTON	HALTON	ON
948 BRANT STREET	1966	C N R		VERNONS	BURLINGTON	HALTON	ON
	1961	C N R STATION		VERNONS	BURLINGTON	HALTON	ON
	1957	C N R STATION		VERNONS	BURLINGTON	HALTON	ON
950 BRANT STREET	1990	CANADIAN NATIONAL RAILWAYS STATION		VERNONS	BURLINGTON	HALTON	ON
	1986	CANADIAN NATIONAL RAILWAYS STATION		VERNONS	BURLINGTON	HALTON	ON
	1981	CANADIAN NATIONAL RAILWAYS STATION		VERNONS	BURLINGTON	HALTON	ON
	1976	CANADIAN NATIONAL RAILWAYS STATION		VERNONS	BURLINGTON	HALTON	ON
	1971	CANADIAN NATIONAL RAILWAYS STATION		VERNONS	BURLINGTON	HALTON	ON
	1966	C N EXPRESS		VERNONS	BURLINGTON	HALTON	ON
	1961	C N EXPRESS		VERNONS	BURLINGTON	HALTON	ON
	1957	C N EXPRESS		VERNONS	BURLINGTON	HALTON	ON
972 BRANT STREET	1961	VERMEULEN & SONS		VERNONS	BURLINGTON	HALTON	ON
	1957	VERMEULEN & SONS		VERNONS	BURLINGTON	HALTON	ON
978 BRANT STREET	1966	FREEMAN BUS TERMINAL		VERNONS	BURLINGTON	HALTON	ON
	1966	BRANT VARIETY & SNACK BAR		VERNONS	BURLINGTON	HALTON	ON
	1966	BRANT VARIETY & MARINE		VERNONS	BURLINGTON	HALTON	ON
	1961	BRANT VARIETY - SNACK BAR & BUS TERMINAL		VERNONS	BURLINGTON	HALTON	ON
	1957	BRANT VARIETY - SNACK BAR & BUS TERMINAL		VERNONS	BURLINGTON	HALTON	ON
982 BRANT STREET	1966	JOHNSEN'S TOOL & MACH SHOP		VERNONS	BURLINGTON	HALTON	ON
	1961	GUELPH LINE HAULAGE		VERNONS	BURLINGTON	HALTON	ON
	1957	GUELPH LINE HAULAGE		VERNONS	BURLINGTON	HALTON	ON
1020 BRANT STREET	2006	HOLLAND CHEVROLET GEO		VERNONS	BURLINGTON	HALTON	ON
	2001	HOLLAND CHEVROLET GEO		VERNONS	BURLINGTON	HALTON	ON
1030 BRANT STREET	2021	MOUNTAIN EQUIPMENT CO-OP	SPORTING GOODS-RET.	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	MOUNTAIN EQUIPMENT CO-OP	SPORTING GOODS STO	DIGITAL BUSINESS DIRE	BURLINGTON		ON
1881 FAIRVIEW STREET	2021	STAPLES	COPYING & DUPL	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	STAPLES PRINT MARKETING SVC	COMMERCIAL PRINTIN	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	BEDDINGTON'S BED BATH	FURNITURE-DEALERS-F	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	MANDARIN RESTAURANT	FOODS-CARRY OUT	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	STAPLES	OFFICE SUPPLIES &am	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	MICHAELS-THE ARTS & CRAFTS STR	HOBBY, TOY, & G	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	FRED'S FACTORY OUTLET STORES	FURNITURE STORES	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	MICHAEL'S ARTS CRAFTS	HOBBY, TOY, & G	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	BEDDINGTON'S BED BATH	FURNITURE STORES	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	DECORATING DEPOT	INTERIOR DESIGN SVCS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	MICHAELS-THE ARTS & CRAFTS STR	HOBBY, TOY, & G	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	FRED'S FACTORY OUTLET STORES	FURNITURE STORES	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	STAPLES BUSINESS DEPOT	OFFICE SUPPLIES &am	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2006	BRANTVIEW PLACE		VERNONS	BURLINGTON	HALTON	ON
	2006	FRED'S FACTORY OUTLET STORES		VERNONS	BURLINGTON	HALTON	ON
	2006	MICHAEL'S ARTS & CRAFTS		VERNONS	BURLINGTON	HALTON	ON
	2006	STAPLES BUSINESS DEPOT		VERNONS	BURLINGTON	HALTON	ON
	2006	DECORATING DEPOT		VERNONS	BURLINGTON	HALTON	ON
	2001	BUSINESS DEPOT		VERNONS	BURLINGTON	HALTON	ON
	2001	MICHAEL'S ARTS & CRAFTS		VERNONS	BURLINGTON	HALTON	ON
	2001	DECORATING DEPOT		VERNONS	BURLINGTON	HALTON	ON
	2001	BRANTVIEW PLACE		VERNONS	BURLINGTON	HALTON	ON
	1996	MICHAEL'S		VERNONS	BURLINGTON	HALTON	ON
	1996	PRESTIGE SOUNDS LTD		VERNONS	BURLINGTON	HALTON	ON
	1996	BRANTVIEW PLACE		VERNONS	BURLINGTON	HALTON	ON
	1996	BUSINESS DEPOT		VERNONS	BURLINGTON	HALTON	ON
	1996	BASE CELLULAR		VERNONS	BURLINGTON	HALTON	ON
	1990	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1986	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1981	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1976	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1971	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1966	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1961	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON

ERIS City Directory Search

as of 03/21/2023

Project Property: Phase one ESA -1376 and 1382 Plain Road East,Burlington, ON - Phase one ESA -1376 and 1382 Plain Road East,, Burlington, ON L7R 3P8 CA

Product Description: CD - QUOTE Custom City Directory Search

Notes to Client:

ERIS Order No: 23021000646

ADDRESS	YEAR	LISTING	COMMENTS	SOURCE	CITY	COUNTY	STATE
	1957	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
1025-1060 GLENDOR AVENUE	2006	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	2001	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1996	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1990	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1986	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1981	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1976	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1971	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1966	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1961	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1957	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
1026 GLENDOR AVENUE	2021	NELSON CO-OP HOMES	COOPERATIVES	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	DIVINE BOOKKEEPING TAX SVC	ACCOUNTING & B	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	TAILOR MAID CLEANING	MAID & BUTLER S	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	SERPHIM MEDIA	ALL OTHER PUBLISHER.	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	DIVINE BOOKKEEPING TAX SVC	OTHER ACCOUNTING S	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	TAILOR MAID CLEANING	JANITORIAL SVCS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	NELSON CO-OP HOMES	OTHER SIMILAR ORGAI	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	URBAN SOUND INC	UNCLASSIFIED	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	COMPWIN	COMPUTER & OFI	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	DIVINE BOOKKEEPING & TAX SVC	OTHER ACCOUNTING S	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	NELSON CO-OPERATIVE HOMES	OTHER SIMILAR ORGAI	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2006	NELSON CO-OP HOMES INC		VERNONS	BURLINGTON	HALTON	ON
	2001	NELSON CO-OP HOMES INC		VERNONS	BURLINGTON	HALTON	ON
	1996	NELSON CO-OP HOMES INC		VERNONS	BURLINGTON	HALTON	ON
	1996	BLADE BROTHERS LANDSCAPING		VERNONS	BURLINGTON	HALTON	ON
1043 GLENDOR AVENUE	2012	B & M MARINE SALVAGE	BOAT DEALERS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2006	B & M MARINE SALVAGE		VERNONS	BURLINGTON	HALTON	ON
1015-1055 HELENA STREET	2021	NO LISTING FOUND		DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	NO LISTING FOUND		DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2006	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	2001	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1996	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1990	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1986	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1981	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1976	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1971	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1966	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1961	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1957	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
1053 HELENA STREET	2012	ENGARDE	OTHER CONSTRUCTION	DIGITAL BUSINESS DIRE	BURLINGTON		ON
1330-1430 LEIGHLAND ROAD	2006	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	2001	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1996	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1990	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1986	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1981	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1976	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1971	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1966	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1961	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1957	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
1354 LEIGHLAND ROAD	1986	DAILY SIGNS		VERNONS	BURLINGTON	HALTON	ON
1358 LEIGHLAND ROAD	2017	ADVER-SIGNS D BARNHAM	UNCLASSIFIED	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	ADVER-SIGNS D BARNHAM	UNCLASSIFIED	DIGITAL BUSINESS DIRE	BURLINGTON		ON
1372 LEIGHLAND ROAD	1990	STEVE'S GENERAL CONTRACTING		VERNONS	BURLINGTON	HALTON	ON
1375 LEIGHLAND ROAD	2021	A R CONSTRUCTION	GENERAL CONTRACTO	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	A R CONSTRUCTION	COMMERCIAL BUILDIN	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	A R CONSTRUCTION	NEW SINGLE-FAMILY G	DIGITAL BUSINESS DIRE	BURLINGTON		ON
1390 LEIGHLAND ROAD	2012	ANGUS ARTS & POTTERY	ALL OTHER HOME FUR	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2006	ANGUS ARTS & POTTERY		VERNONS	BURLINGTON	HALTON	ON
	2001	WYATT ART POTTERY		VERNONS	BURLINGTON	HALTON	ON
	1996	WYATT ART POTTERY		VERNONS	BURLINGTON	HALTON	ON
	1990	WYATT ART POTTERY		VERNONS	BURLINGTON	HALTON	ON
	1986	WYATT ART POTTERY		VERNONS	BURLINGTON	HALTON	ON
	1981	WYATT ART POTTERY		VERNONS	BURLINGTON	HALTON	ON
	1976	WYATT ART POTTERY		VERNONS	BURLINGTON	HALTON	ON
	1971	WYATT ART POTTERY		VERNONS	BURLINGTON	HALTON	ON
	1966	WYATT ART POTTERY		VERNONS	BURLINGTON	HALTON	ON
	1961	WYATT ART POTTERY		VERNONS	BURLINGTON	HALTON	ON
	1957	WYATT ART POTTERY		VERNONS	BURLINGTON	HALTON	ON
1429 LEIGHLAND ROAD	2006	CARMODY CUSTOM FURNITURE		VERNONS	BURLINGTON	HALTON	ON
1376 PLAIN ROAD EAST	2001	HARDSOFT SYSTEMS		VERNONS	BURLINGTON	HALTON	ON
	2001	BURLINGTON COMPUTER TRAINING		VERNONS	BURLINGTON	HALTON	ON
	2001	BURLINGTON NETWORK SERVICES		VERNONS	BURLINGTON	HALTON	ON
	1996	QUEEN'S FLORIST		VERNONS	BURLINGTON	HALTON	ON
	1990	KING'S FLORIST		VERNONS	BURLINGTON	HALTON	ON
	1986	KING'S FLORIST		VERNONS	BURLINGTON	HALTON	ON
	1981	KING'S FLORIST		VERNONS	BURLINGTON	HALTON	ON
	1976	KING'S FLORIST		VERNONS	BURLINGTON	HALTON	ON
	1966	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1961	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1957	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
1382 PLAIN ROAD EAST	2001	DEALS ON WHEELS		VERNONS	BURLINGTON	HALTON	ON
	1996	DEALS ON WHEELS		VERNONS	BURLINGTON	HALTON	ON
	1996	BURLINGTON AUTOMOTIVE PLUS		VERNONS	BURLINGTON	HALTON	ON
	1990	DEALS ON WHEELS		VERNONS	BURLINGTON	HALTON	ON
	1986	TRIEX		VERNONS	BURLINGTON	HALTON	ON
	1981	PLAINS ROAD MOTORS		VERNONS	BURLINGTON	HALTON	ON

ERIS City Directory Search

as of 03/21/2023

Project Property: Phase one ESA -1376 and 1382 Plain Road East,Burlington, ON - Phase one ESA -1376 and 1382 Plain Road East,, Burlington, ON L7R 3P8 CA

Product Description: CD - QUOTE Custom City Directory Search

Notes to Client:

ERIS Order No: 23021000646

ADDRESS	YEAR	LISTING	COMMENTS	SOURCE	CITY	COUNTY	STATE
	1976	PLAINS ROAD MOTORS		VERNONS	BURLINGTON	HALTON	ON
	1966	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1961	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1957	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
1446 PLAIN ROAD EAST	1990	PLAIN'S ROAD SUNOCO		VERNONS	BURLINGTON	HALTON	ON
1239 PLAINS ROAD EAST	1986	BURLINGTON AUTO SALES		VERNONS	BURLINGTON	HALTON	ON
1240 PLAINS ROAD EAST	1986	AUTO VILLAGE LTD		VERNONS	BURLINGTON	HALTON	ON
	1986	ULTRA-MATIC SCREW MACHINE PRODUCTS INC		VERNONS	BURLINGTON	HALTON	ON
	1961	BRANT SUPPLY CO		VERNONS	BURLINGTON	HALTON	ON
	1961	JAMES EQUIPMENT		VERNONS	BURLINGTON	HALTON	ON
	1961	FULLER J C MFG CO		VERNONS	BURLINGTON	HALTON	ON
	1961	BRANTFORD ENG & MFG CO		VERNONS	BURLINGTON	HALTON	ON
1247 PLAINS ROAD EAST	1986	FLOWERLAND FLORISTS		VERNONS	BURLINGTON	HALTON	ON
1254 PLAINS ROAD EAST	1986	PARTRANS		VERNONS	BURLINGTON	HALTON	ON
	1986	BEDEIR'S CUSTOM UPHOLSTERY CO LTD		VERNONS	BURLINGTON	HALTON	ON
	1986	BURLINGTON TUNE UP SERVICES LTD		VERNONS	BURLINGTON	HALTON	ON
	1986	MOTION CONTROL DEVICES LTD		VERNONS	BURLINGTON	HALTON	ON
	1986	CHRISTIAN SERVICE BRIGADE		VERNONS	BURLINGTON	HALTON	ON
	1986	BERNIE'S AUTO BODY LTD		VERNONS	BURLINGTON	HALTON	ON
	1986	EURO-DRIVE CLUTCHES INC		VERNONS	BURLINGTON	HALTON	ON
	1986	WELLIGE INDUSTRIES LTD		VERNONS	BURLINGTON	HALTON	ON
	1986	WARDS SKATE SUPPLY LTD		VERNONS	BURLINGTON	HALTON	ON
	1986	M & B DRAFTING SERVICE		VERNONS	BURLINGTON	HALTON	ON
	1986	DESI'S ALUMINUM LTD		VERNONS	BURLINGTON	HALTON	ON
	1986	PRECISE CONTROLS LTD		VERNONS	BURLINGTON	HALTON	ON
	1986	CAMP KAKEKA FOR BOYS		VERNONS	BURLINGTON	HALTON	ON
	1986	CDN PINE CLASSICS		VERNONS	BURLINGTON	HALTON	ON
	1986	BTU AUTO PARTS		VERNONS	BURLINGTON	HALTON	ON
	1961	A & M MFG CO		VERNONS	BURLINGTON	HALTON	ON
	1961	VISCOUNT SUPPLY CO		VERNONS	BURLINGTON	HALTON	ON
1270-1450 PLAINS ROAD EAST	2001	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1996	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1990	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1986	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1981	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1976	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1966	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1961	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1957	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
1274 PLAINS ROAD EAST	2021	SUN CHEMICAL	PRINTERS (MFRS)	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	SUN PRINTING	COMMERCIAL LITHOGI	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	SUN CHEMICAL LTD	PRINTING INK MFG	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	SUN PRINTING	COMMERCIAL LITHOGI	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	SUN CHEMICAL LTD	PRINTING INK MFG	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2001	SUN CHEMICAL (GENERAL PRINTING INC)		VERNONS	BURLINGTON	HALTON	ON
	1996	GENERAL PRINTING INC (DIV OF SUN CHEMICAL CORP)		VERNONS	BURLINGTON	HALTON	ON
	1990	GENERAL PRINTING INC (DIV OF SUN CHEMICAL CORP)		VERNONS	BURLINGTON	HALTON	ON
	1986	CPI		VERNONS	BURLINGTON	HALTON	ON
	1986	MAY & BAKER CANADA LTD		VERNONS	BURLINGTON	HALTON	ON
	1981	NIAGARA CHEMICAL (DIVISION OF REICHHOLD LTD)		VERNONS	BURLINGTON	HALTON	ON
	1976	F M C OF CANADA LTD		VERNONS	BURLINGTON	HALTON	ON
	1966	NIAGARA BRAND CHEMICALS		VERNONS	BURLINGTON	HALTON	ON
1309 PLAINS ROAD EAST	2001	WHITE PRINT & REPRODUCTION		VERNONS	BURLINGTON	HALTON	ON
	1996	WHITE PRINT & REPRODUCTION		VERNONS	BURLINGTON	HALTON	ON
	1990	PLAINSMEN HALL		VERNONS	BURLINGTON	HALTON	ON
	1990	WHITE PRINT & REPRODUCTION		VERNONS	BURLINGTON	HALTON	ON
1325 PLAINS ROAD EAST	2017	LINDA COLLINS SCHOOL OF BALLET	FINE ART SCHOOLS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	LINDA COLLINS SCHOOL OF BALLET	ELEMENTARY & S	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2001	LINDA COLLINS SCHOOL OF DANCE		VERNONS	BURLINGTON	HALTON	ON
	1996	LINDA COLLINS SCHOOL OF DANCE		VERNONS	BURLINGTON	HALTON	ON
	1990	LINDA COLLINS SCHOOL OF DANCE		VERNONS	BURLINGTON	HALTON	ON
	1986	PLAINSMEN HALL		VERNONS	BURLINGTON	HALTON	ON
	1986	PLAINSMEN SPORT & SOCIAL CLUB		VERNONS	BURLINGTON	HALTON	ON
	1981	BAY CENTRE HALL		VERNONS	BURLINGTON	HALTON	ON
	1981	RESSEL DAY NURSERY SCHOOL		VERNONS	BURLINGTON	HALTON	ON
	1981	BAY CENTER REC CLUB		VERNONS	BURLINGTON	HALTON	ON
	1976	BAY CENTRE HALL		VERNONS	BURLINGTON	HALTON	ON
	1976	THE RESSEL DAY NURSERY SCHOOL		VERNONS	BURLINGTON	HALTON	ON
	1976	BAY CENTRE RECREATION CLUB		VERNONS	BURLINGTON	HALTON	ON
	1966	BAY CENTRE COMMUNITY CLUB		VERNONS	BURLINGTON	HALTON	ON
	1966	RESSEL DAY NURSERY SCHOOL		VERNONS	BURLINGTON	HALTON	ON
	1961	GLENDOR HALL		VERNONS	BURLINGTON	HALTON	ON
	1961	BAY CENTRE COMMUNITY CLUB		VERNONS	BURLINGTON	HALTON	ON
	1957	GLENDOR HALL		VERNONS	BURLINGTON	HALTON	ON
	1957	BAY CENTRE COMMUNITY CLUB		VERNONS	BURLINGTON	HALTON	ON
1335 PLAINS ROAD EAST	2021	RESSEL DAY NURSERY SCHOOL	CHILD CARE SERVICE	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	RESSEL DAY NURSERY SCHOOL	CHILD DAY CARE SVCS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	RESSEL DAY NURSERY SCHOOL	CHILD DAY CARE SVCS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2001	RESSEL DAY NURSERY SCHOOL		VERNONS	BURLINGTON	HALTON	ON
	1996	43- RESSEL DAY NURSERY SCHOOL		VERNONS	BURLINGTON	HALTON	ON
	1990	43-RESSEL DAY NURSERY SCHOOL		VERNONS	BURLINGTON	HALTON	ON
	1986	43-RESSEL DAY NURSERY SCHOOL		VERNONS	BURLINGTON	HALTON	ON
	1981	43-RESSEL DAY NURSERY SCHOOL		VERNONS	BURLINGTON	HALTON	ON
	1976	39-THE RESSEL DAY NURSERY SCHOOL		VERNONS	BURLINGTON	HALTON	ON
1349 PLAINS ROAD EAST	2012	PROFESSIONAL DESIGN GROUP	OTHER COMMERCIAL I	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	BURLINGTON COMMUNITY FNDTN	SOCIAL SCIENCE &	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2001	PROFESSIONAL DESIGN GROUP		VERNONS	BURLINGTON	HALTON	ON
	2001	BURLINGTON COMMUNITY FOUNDATION		VERNONS	BURLINGTON	HALTON	ON
	1996	COMPTREE SYSTEMS SERVICES		VERNONS	BURLINGTON	HALTON	ON
	1996	PROFESSIONAL DESIGN GROUP		VERNONS	BURLINGTON	HALTON	ON
	1986	DUBAY ORGANS LTD		VERNONS	BURLINGTON	HALTON	ON

ERIS City Directory Search

as of 03/21/2023

Project Property: Phase one ESA -1376 and 1382 Plain Road East,Burlington, ON - Phase one ESA -1376 and 1382 Plain Road East,, Burlington, ON L7R 3P8 CA

Product Description: CD - QUOTE Custom City Directory Search

Notes to Client:

ERIS Order No: 23021000646

ADDRESS	YEAR	LISTING	COMMENTS	SOURCE	CITY	COUNTY	STATE
	1981	DUBAY ORGANS LTD		VERNONS	BURLINGTON	HALTON	ON
	1976	DUBAY ORGANS LTD		VERNONS	BURLINGTON	HALTON	ON
	1966	OWENS WOOD PRODUCTS		VERNONS	BURLINGTON	HALTON	ON
	1961	OWENS WOOD PRODUCTS		VERNONS	BURLINGTON	HALTON	ON
	1957	OWENS WOOD PRODUCTS		VERNONS	BURLINGTON	HALTON	ON
1355 PLAINS ROAD EAST	2021	BESTNAFEMEVER	NONCLASSIFIED ESTAB	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	JQ REFRIGERATIONS	HEATING EQUIPMENT	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2001	COMCARE LTD		VERNONS	BURLINGTON	HALTON	ON
	1996	COMCARE LTD		VERNONS	BURLINGTON	HALTON	ON
	1990	WGM PRODUCTSLTD		VERNONS	BURLINGTON	HALTON	ON
	1986	WGM PRODUCTS LTD		VERNONS	BURLINGTON	HALTON	ON
	1981	WGM PRODUCTS LTD		VERNONS	BURLINGTON	HALTON	ON
	1976	W G M PROD LTD		VERNONS	BURLINGTON	HALTON	ON
	1966	WILLIAMS GRINDING & MACHINE PRODUCTS		VERNONS	BURLINGTON	HALTON	ON
	1957	WIENS SCREW PRODUCTS		VERNONS	BURLINGTON	HALTON	ON
1358 PLAINS ROAD EAST	1981	RUNIA SP COMPANY		VERNONS	BURLINGTON	HALTON	ON
	1981	CAMPERS WORLD SPLS		VERNONS	BURLINGTON	HALTON	ON
	1976	CAMPERS WORLD		VERNONS	BURLINGTON	HALTON	ON
	1976	RUNIA SIMON P CO		VERNONS	BURLINGTON	HALTON	ON
	1966	RUNIA SIMON P MFG CO		VERNONS	BURLINGTON	HALTON	ON
1364 PLAINS ROAD EAST	2021	SANI SONS	NONCLASSIFIED ESTAB	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	GAS LINK SVC INC	PROPANE (LP) GAS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	WELDPRO GASES	OTHER CHEMICAL MEF	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	U-HAUL NEIGHBORHOOD DEALER	TRUCK RENTING &	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	GAS LINK SVC INC	WHOLESALEINDUSTRIA	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	GASLINK SERVICES INC	WHOLESALE-INDUSTRI	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	AUTO SPLASH CAR WASH & DTLNG	CAR WASHES	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	DIRECT TO HOME GROCERS	SUPERMARKETS &amp	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2001	DIAL-A-RIDE		VERNONS	BURLINGTON	HALTON	ON
	2001	BURLINGTON TAXI INC		VERNONS	BURLINGTON	HALTON	ON
	2001	A & A DELUXE TAXI		VERNONS	BURLINGTON	HALTON	ON
	1996	BURLINGTON TAXI INC		VERNONS	BURLINGTON	HALTON	ON
	1990	PARKLANE TAXI		VERNONS	BURLINGTON	HALTON	ON
	1990	BURLINGTON TAXI PROPANE CENTRE		VERNONS	BURLINGTON	HALTON	ON
	1990	BURLINGTON TAXI LTD		VERNONS	BURLINGTON	HALTON	ON
	1986	PARKLANE TAXI		VERNONS	BURLINGTON	HALTON	ON
	1986	BURLINGTON TAXI LTD		VERNONS	BURLINGTON	HALTON	ON
	1981	PARKLANE TAXI		VERNONS	BURLINGTON	HALTON	ON
	1981	BURLINGTON TAXI LTD		VERNONS	BURLINGTON	HALTON	ON
	1976	PARKLANE TAXI		VERNONS	BURLINGTON	HALTON	ON
	1976	BURLINGTON TAXI LTD		VERNONS	BURLINGTON	HALTON	ON
1368 PLAINS ROAD EAST	2021	CITY TIRES BURLINGTON	TIRE-DEALERS-RETAIL	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	CATALINA SPAS-POOLS BURLINGTON	STORE RETAILERS NOT	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2001	ONTARIO SPA DISTRIBUTORS		VERNONS	BURLINGTON	HALTON	ON
	1996	FIREPLACE CENTRE		VERNONS	BURLINGTON	HALTON	ON
	1996	THE SPRINKLER CENTRE		VERNONS	BURLINGTON	HALTON	ON
	1990	FIREPLACE CENTRE		VERNONS	BURLINGTON	HALTON	ON
	1986	DISCOUNT FIREPLACE CENTRE		VERNONS	BURLINGTON	HALTON	ON
	1981	BURLINGTON CYCLE LTD		VERNONS	BURLINGTON	HALTON	ON
	1976	BURLINGTON CYCLE LTD		VERNONS	BURLINGTON	HALTON	ON
1369 PLAINS ROAD EAST	2021	L A CANDY BAR LTD	CANDY & CONFEC	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	HALTON SATELLITE	DATA PROCESSING &a	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2001	FANTASY CONVENIENCE		VERNONS	BURLINGTON	HALTON	ON
	1996	FANTASY CONVENIENCE		VERNONS	BURLINGTON	HALTON	ON
	1990	HILL'S VARIETY		VERNONS	BURLINGTON	HALTON	ON
	1976	NATIONAL PERFORMANCE CENTRE		VERNONS	BURLINGTON	HALTON	ON
	1961	GLENDORE BUTCHER & GROCER		VERNONS	BURLINGTON	HALTON	ON
1371 PLAINS ROAD EAST	2021	CORAL REEF SHOP	AQUACULTURE	DIGITAL BUSINESS DIRE	BURLINGTON		ON
1371-1411 PLAINS ROAD EAST	1966	HOLLAND J MOTORS		VERNONS	BURLINGTON	HALTON	ON
	1966	HOLLAND J MOTORS COLLISION SERVICE		VERNONS	BURLINGTON	HALTON	ON
1376 PLAINS ROAD EAST	2021	BNS	REAL ESTATE LOANS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	BURLINGTON COMPUTER TRAINING	FEDERAL GOVERNMEN	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	MIDNIGHT PROTECTION SVC	WILDLIFE SERVICES	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	HARD SOFT SYSTEMS LTD	COMPUTER SERVICES	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	HARDSOFT SYSTEMS	DATA PROCESSING &a	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	BURLINGTON COMPUTER TRAINING	COMPUTER TRAINING;	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	MIDNIGHT PROTECTION SVC	SECURITY GUARDS &a	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	BURLINGTON NETWORK SVC	DATA PROCESSING &a	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	HARD SOFT SYSTEMS LTD	CUSTOM COMPUTER P	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	WAVE II NETWORKS	DATA PROCESSING &a	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	HARDSOFT SYSTEMS	OTHER COMPUTER REL	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	WAVE II NETWORKS	DATA PROCESSING &a	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	HARD SOFT SYSTEMS LTD	CUSTOM COMPUTER P	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	BURLINGTON NETWORK SVC	DATA PROCESSING &a	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	MIDNIGHT PROTECTION SVC	SECURITY GUARDS &a	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	BURLINGTON COMPUTER TRAINING	COMPUTER TRAINING	DIGITAL BUSINESS DIRE	BURLINGTON		ON
1382 PLAINS ROAD EAST	2021	GEM AUTOS	AUTOMOBILE DEALERS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	GEM AUTOS	AUTOMOBILE DEALERS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	MARQUIES AUTO EXCHANGE	USED CAR DEALERS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	NATIONAL DEPOT INC	USED CAR DEALERS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	MCNEILL AUTO SALES	USED CAR DEALERS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	DEALS ON WHEELS	USED CAR DEALERS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	NATIONAL DEPOT INC	USED CAR DEALERS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
1390 PLAINS ROAD EAST	2012	POWERLINK EQUIPMENT	OUTDOOR POWER EQU	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	1996	SPEEDY AUTO GLASS		VERNONS	BURLINGTON	HALTON	ON
	1990	BINGO WORLD LTD		VERNONS	BURLINGTON	HALTON	ON
	1976	ALDERSHOT STRUCTURAL STEEL LTD		VERNONS	BURLINGTON	HALTON	ON
	1976	BURLINGTON WHITEPRINT & REPRODUCTIONS		VERNONS	BURLINGTON	HALTON	ON
1397 PLAINS ROAD EAST	1957	GREENHIL EXCAVATING CO		VERNONS	BURLINGTON	HALTON	ON
1398 PLAINS ROAD EAST	1976	WALDON POOL SERVICES		VERNONS	BURLINGTON	HALTON	ON
	1976	BURLINGTON TUNE UP SERVICES LTD		VERNONS	BURLINGTON	HALTON	ON

ERIS City Directory Search

as of 03/21/2023

Project Property: Phase one ESA -1376 and 1382 Plain Road East,Burlington, ON - Phase one ESA -1376 and 1382 Plain Road East,, Burlington, ON L7R 3P8 CA

Product Description: CD - QUOTE Custom City Directory Search

Notes to Client:

ERIS Order No: 23021000646

ADDRESS	YEAR	LISTING	COMMENTS	SOURCE	CITY	COUNTY	STATE
	1976	ROBERTSON DEWEY ATHLETIC CLUB		VERNONS	BURLINGTON	HALTON	ON
	1976	BURLINGTON SOUND CENTRE		VERNONS	BURLINGTON	HALTON	ON
	1966	TIP-TOP CANNERS		VERNONS	BURLINGTON	HALTON	ON
	1966	BRADFORD-PENN OIL LTD		VERNONS	BURLINGTON	HALTON	ON
	1961	TIP-TOP CANNERS		VERNONS	BURLINGTON	HALTON	ON
1400 PLAINS ROAD EAST	2021	VSP FITNESS	PERSONAL TRAINERS-F	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	SMART CHOICE AUTO REPAIRS	AUTOMOBILE REPAIRII	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	MEDITERRANEAN COOKERY	FOODS-CARRY OUT	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	BUDGET TRUCK RENTAL	TRUCK-DEALERS-USED	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	BUDGET RENT A CAR	AUTOMOBILE RENTIN(	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	FORMAC BILLIARDS	BILLIARD PARLORS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	AVIS RENT A CAR	AUTOMOBILE RENTIN(	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	ELEGANT NAILS	MANICURING	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	BAT CAVE	UNCLASSIFIED	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	GEORGE AUTO SALES DETAILING	SPORTING GOODS STO	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	SMART CHOICE AUTO REPAIRS	GENERAL AUTOMOTIV	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	GREYHOUND COURIER EXPRESS	COURIERS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	CARTER CAR TRUCK RENTALS	PASSENGER CARS REN	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	EURO-TECH WINDOWS HALTON	OTHER BUILDING MAT	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	AVIS CAR & TRUCK RENTAL	PASSENGER CARS REN	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	WU SHU TAE KWON DO CTR	SPORTS & RECRE/	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	MEDITERRANEAN COOKERY	FULLSERVICE RESTAUR	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	FORMAC BILLIARDS	SPORTS & RECRE/	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	AVIS RENT A CAR	PASSENGER CARS REN	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	NRG NIGHT CLUB	DRINKING PLACES, ALC	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	ROYAL TANDOOR	FULLSERVICE RESTAUR	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	ELEGANT NAILS	BEAUTY SALONS; MAN	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	NABIL MARKET	ALL OTHER GENERAL M	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	SOUND IMAGE	AUTOMOTIVE PARTS &	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	BAT CAVE	UNCLASSIFIED	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	EMOTION PICTURES STUDIOS INC	UNCLASSIFIED	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	SMART CHOICE AUTO REPAIRS	GENERAL AUTOMOTIV	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	EURO-TECH WINDOWS HALTON	OTHER BUILDING MAT	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	AVIS CAR & TRUCK RENTAL	PASSENGER CARS REN	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	WU SHU TAE KWON DO CTR	SPORTS & RECRE/	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	NEW LIFE THRIFT STORE	USED MERCHANDISE S	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	CES GRAPHIC SUPPLIES	COMMERCIAL SCREEN	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	TARBOOSH RESTAURANT	FULL-SERVICE RESTAUI	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	FORMAC BILLIARDS	SPORTS & RECRE/	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	SUNSHINE NAILS	UNCLASSIFIED	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	NRG NIGHT CLUB	DRINKING PLACES, ALC	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	NABIL MARKET	ALL OTHER GENERAL M	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	SOUND IMAGE	AUTOMOTIVE PARTS &	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	GUITAR SHOP	MUSICAL INSTRUMEN1	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2001	THE BAT CAVE		VERNONS	BURLINGTON	HALTON	ON
	2001	MASTER KIM'S TAE KWON DO CENTRE		VERNONS	BURLINGTON	HALTON	ON
	2001	SMART CHOICE AUTO REPAIRS		VERNONS	BURLINGTON	HALTON	ON
	2001	AVIS CAR & TRUCK RENTAL		VERNONS	BURLINGTON	HALTON	ON
	2001	NRG KINGDOM NIGHTCLUB		VERNONS	BURLINGTON	HALTON	ON
	2001	TARBOOSH RESTAURANT		VERNONS	BURLINGTON	HALTON	ON
	2001	1277759 ONTARIO INC		VERNONS	BURLINGTON	HALTON	ON
	2001	FORMAC BILLIARDS		VERNONS	BURLINGTON	HALTON	ON
	2001	FAMILY MARKET		VERNONS	BURLINGTON	HALTON	ON
	1996	NRG NIGHTCLUB		VERNONS	BURLINGTON	HALTON	ON
	1996	MASTER KIM'S TAE KWON DO		VERNONS	BURLINGTON	HALTON	ON
	1996	FINELINE AUTO ACCESSORIES		VERNONS	BURLINGTON	HALTON	ON
	1996	AVIS CAR & TRUCK RENTAL		VERNONS	BURLINGTON	HALTON	ON
	1996	FORMAC BILLIARDS		VERNONS	BURLINGTON	HALTON	ON
	1996	BINGO WORLD LTD		VERNONS	BURLINGTON	HALTON	ON
	1990	STARS DANCE CLUB		VERNONS	BURLINGTON	HALTON	ON
	1990	BURLINGTON PERFORMANCE CENTRE		VERNONS	BURLINGTON	HALTON	ON
	1990	GRAND SLAM BATTING CAGE INC		VERNONS	BURLINGTON	HALTON	ON
	1990	CARLINE MUFFLER CENTRE LTD		VERNONS	BURLINGTON	HALTON	ON
	1990	PZ PAINTING & DECORATING		VERNONS	BURLINGTON	HALTON	ON
	1990	BURLINGTON AUTO ELECTRIC		VERNONS	BURLINGTON	HALTON	ON
	1990	SPEEDY AUTO GLASS LTD		VERNONS	BURLINGTON	HALTON	ON
	1990	CANADIAN STYLE DONUTS		VERNONS	BURLINGTON	HALTON	ON
	1990	RUST CHECK CENTRES		VERNONS	BURLINGTON	HALTON	ON
	1990	PAINTERS PLACE LTD		VERNONS	BURLINGTON	HALTON	ON
	1990	FOSTER AUTO GROUP		VERNONS	BURLINGTON	HALTON	ON
	1990	FOR MAC BILLIARDS		VERNONS	BURLINGTON	HALTON	ON
	1986	THE RADMAN		VERNONS	BURLINGTON	HALTON	ON
	1986	COLLINS LINDA SCHOOL OF BALLET		VERNONS	BURLINGTON	HALTON	ON
	1986	CARLINE MUFFLER CENTRE LTD		VERNONS	BURLINGTON	HALTON	ON
	1986	BURLINGTON AUTO ELECTRIC		VERNONS	BURLINGTON	HALTON	ON
	1986	SPEEDY AUTO GLASS LTD		VERNONS	BURLINGTON	HALTON	ON
	1986	PAINTERS PLACE LTD		VERNONS	BURLINGTON	HALTON	ON
	1986	DONUT FOUNDRY LTD		VERNONS	BURLINGTON	HALTON	ON
	1986	BRONTE AUTO PARTS		VERNONS	BURLINGTON	HALTON	ON
	1986	BINGO WORLD LTD		VERNONS	BURLINGTON	HALTON	ON
	1986	PIZZA DELIGHT		VERNONS	BURLINGTON	HALTON	ON
	1981	THE RADMAN		VERNONS	BURLINGTON	HALTON	ON
	1981	SPEEDY AUTO GLASS LTD		VERNONS	BURLINGTON	HALTON	ON
	1981	THRUWAY MUFFLER CENTER		VERNONS	BURLINGTON	HALTON	ON
	1981	BURLINGTON MARTIAL ARTS		VERNONS	BURLINGTON	HALTON	ON
	1981	HOLIDAY RENT-A-CAR SYSTEM		VERNONS	BURLINGTON	HALTON	ON
1401 PLAINS ROAD EAST	2021	FRAME SITE	ART GALLERIES &	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	WESTSIDE CHIROPRACTIC GROUP	MASSAGE THERAPISTS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	DR LAURA THOMSON ASSOC	PSYCHOLOGISTS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	ADVANCED MIND CLINIC	DENTISTS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	NAIL EXPERTS SPA	MANICURING	DIGITAL BUSINESS DIRE	BURLINGTON		ON

ERIS City Directory Search

as of 03/21/2023

Project Property: Phase one ESA -1376 and 1382 Plain Road East,Burlington, ON - Phase one ESA -1376 and 1382 Plain Road East,, Burlington, ON L7R 3P8 CA

Product Description: CD - QUOTE Custom City Directory Search

Notes to Client:

ERIS Order No: 23021000646

ADDRESS	YEAR	LISTING	COMMENTS	SOURCE	CITY	COUNTY	STATE
	2021	LAILA HAIR DESIGN	BEAUTY SALONS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	GRAHAM JAMES DDS	DENTISTS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	KANCHERLA Y DR	PHYSICIANS & SU	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	FOCUS INSIGHTS	HUMAN RESOURCE CO	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	FRAME SITE	STORE RETAILERS NOT	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	ADVANCED MIND CLINIC	CLINICS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	LAILA HAIR DESIGN	BEAUTY SALONS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	J H ARCHITECTURE	ARCHITECTS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	CARTER CAR & TRUCK RENTALS	PASSENGER CARS REN	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	JOHN HOLLAND CHEVROLET LTD	NEW CAR DEALERS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2001	CARTER CAR & TRUCK RENTALS		VERNONS	BURLINGTON	HALTON	ON
	2001	HOLLAND CHEVROLET GEO OLDSMOBILE LTD		VERNONS	BURLINGTON	HALTON	ON
	1996	HOLLAND CHEVROLET GEO OLDSMOBILE LTD		VERNONS	BURLINGTON	HALTON	ON
	1990	HOLLAND CHEVROLET GEO OLDSMOBILE LTD		VERNONS	BURLINGTON	HALTON	ON
	1986	HOLLAND CHEVROLET GEO OLDSMOBILE LTD		VERNONS	BURLINGTON	HALTON	ON
	1981	HOLLAND CHEVROLET OLDSMOBILE LTD		VERNONS	BURLINGTON	HALTON	ON
	1976	HOLLAND CHEVROLET OLDSMOBILE INC		VERNONS	BURLINGTON	HALTON	ON
1435 PLAINS ROAD EAST	2021	DR KHETANI	PHYSICIANS & SU	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	BURLINGTON DENTAL CTR	DENTISTS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	FLEETWYZE INC	NONCLASSIFIED ESTAB	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	HEARING LIFE	HEARING AIDS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	PARTSOURCE	AUTOMOBILE REPAIRII	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	PARTSOURCE	AUTOMOTIVE PARTS &	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	EAST COAST CHEQUE CASHING	FINANCIAL TRANSACTI	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	BURLINGTON DENTAL CENTRE	OFFICES OF DENTISTS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	BACHLY BUILDERS LTD	RESIDENTIAL REMODEI	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	MAC RAE JOHN D MD	OFFICES OF PHYSICIAN	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	LISTENUP CANADA	ALL OTHER HEALTH &a	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	PART SOURCE	AUTOMOTIVE PARTS &	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	EAST COAST CHEQUE CASHING	FINANCIAL TRANSACTI	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	BURLINGTON DENTAL CENTRE	OFFICES OF DENTISTS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	BACHLY BUILDERS LTD	RESIDENTIAL REMODEI	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	MAC RAE, JOHN D MD	OFFICES OF PHYSICIAN	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	LISTENUP CANADA	ALL OTHER HEALTH &a	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	CITIFINANCIAL	REAL ESTATE CREDIT	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	BATCHRA, N MD	OFFICES OF PHYSICIAN	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	1990	VICKIE'S ESSO SERVICE STATION		VERNONS	BURLINGTON	HALTON	ON
	1986	SERVACAR LTD		VERNONS	BURLINGTON	HALTON	ON
	1981	IMPERIAL GAS BAR		VERNONS	BURLINGTON	HALTON	ON
	1981	VOYAGEUR RESTAURANT		VERNONS	BURLINGTON	HALTON	ON
	1976	IMPERIAL GAS BAR		VERNONS	BURLINGTON	HALTON	ON
	1976	VOYAGEUR RESTAURANT		VERNONS	BURLINGTON	HALTON	ON
	1966	TILDEN RENT-A-CAR		VERNONS	BURLINGTON	HALTON	ON
	1966	GREENWOOD MOTORING SERVICE		VERNONS	BURLINGTON	HALTON	ON
	1961	GREENWOOD L H SERVICE STATION		VERNONS	BURLINGTON	HALTON	ON
	1957	GREENWOOD L H SERVICE STATION		VERNONS	BURLINGTON	HALTON	ON
1439 PLAINS ROAD EAST	1986	SARACEN'S HEAD		VERNONS	BURLINGTON	HALTON	ON
	1966	THE CLANS COFFEE SHOP LTD		VERNONS	BURLINGTON	HALTON	ON
	1961	THE CLANS COFFEE SHOP LTD		VERNONS	BURLINGTON	HALTON	ON
	1957	THE CLANS LTD		VERNONS	BURLINGTON	HALTON	ON
1446 PLAINS ROAD EAST	2021	DANS SUNOCO	AUTOMOBILE REPAIRII	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2021	PETRO-CANADA	ALTERNATIVE FUELS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	DAN'S SUNOCO	ALTERNATIVE FUELS	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2017	PETRO-CANADA	OTHER GASOLINE STA1	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	SUNOCO	OTHER GASOLINE STA1	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2012	DAN'S SUNOCO	GENERAL AUTOMOTIV	DIGITAL BUSINESS DIRE	BURLINGTON		ON
	2001	SUNOCO		VERNONS	BURLINGTON	HALTON	ON
	1996	SUNOCO		VERNONS	BURLINGTON	HALTON	ON
	1986	MCEWAN AUTOMOTIVE		VERNONS	BURLINGTON	HALTON	ON
	1986	PLAINS ROAD SUNOCO		VERNONS	BURLINGTON	HALTON	ON
	1981	PLAINS & BRANT SUNOCO		VERNONS	BURLINGTON	HALTON	ON
	1976	SUNOCO SERVICE STATION		VERNONS	BURLINGTON	HALTON	ON
	1966	SUNOCO SERVICE STN		VERNONS	BURLINGTON	HALTON	ON
	1961	SUNOCO		VERNONS	BURLINGTON	HALTON	ON
	1961	SUNOCO SERVICE STATION		VERNONS	BURLINGTON	HALTON	ON

Appendix G – Regulatory Requests

Ministry of the Environment, Conservation and Parks

Access and Privacy Office

12th Floor
40 St. Clair Avenue West
Toronto ON M4V 1M2
Tel: (416) 314-4075

Ministère de l'Environnement, de la Protection de la nature et des Parcs

Bureau de l'accès à l'information et de la protection de la vie privée

12e étage
40, avenue St. Clair ouest
Toronto ON M4V 1M2
Tél. : (416) 314-4075

March 8, 2023

Ramila Senanayake
EXP Services Inc.
1595 Clark Boulevard
Brampton, Ontario L6T 4V1
ramila.senanayake@exp.com

Dear Ramila Senanayake:

RE: **MECP FOI A-2023-01259, Your Reference GTR-22029872-A0 – Decision Letter**

This letter is in response to your request made pursuant to the Freedom of Information and Protection of Privacy Act (the Act) relating to 1376 and 1382 Plains Road East, Burlington.

After a thorough search through the files of the ministry's Halton Peel District Office, Environmental Assessment and Permissions Division (EAPD), Environmental Monitoring and Reporting Branch (EMRB), Environmental Investigations and Enforcement Branch (EIEB), and Safe Drinking Water Branch (SDW) no records were located responsive to your request. **This file is now closed.**

You may request a review of my decision within 30 days from the date of this letter by contacting the Information and Privacy Commissioner/Ontario at http://www.ipc.on.ca. Please note there may be a fee associated with submitting the appeal.

If you have any questions, please contact Tolani Abraham at Tolani.Abraham2@ontario.ca.

Yours truly,

ORIGINAL SIGNED BY

Ryan Gunn
Manager (A), Access and Privacy Office

Ministry of the Environment, Conservation and Parks

Access and Privacy Office

12th Floor
40 St. Clair Avenue West
Toronto ON M4V 1M2
Tel: (416) 314-4075

Ministère de l'Environnement, de la Protection de la nature et des Parcs

Bureau de l'accès à l'information et de la protection de la vie privée

12e étage
40, avenue St. Clair ouest
Toronto ON M4V 1M2
Tél. : (416) 314-4075

Ontario

March 1, 2023

Ramila Senanayake
EXP Services Inc.
1595 Clark Boulevard
Brampton, Ontario L6T 4V1
ramila.senanayake@exp.com

Dear Ramila Senanayake:

RE: **MECP FOI A-2023-01259 / Your Reference GTR-22029872-A0 – Acknowledgement Letter**

The Ministry is in receipt of your request made pursuant to the Freedom of Information and Protection of Privacy Act and has received your payment in the amount of $5.00 (non-refundable application fee).

The search will be conducted on the following: 1376 and 1382 Plains Road East, Burlington. If there is any discrepancy, please contact us immediately.

Please note the file number that has been assigned to your request. This number should be referred to in all future communications with our office.

Also, the Ministry's Freedom of Information and Protection of Privacy Office (MECP Access and Privacy Office) is currently providing requesters with decisions/records via email. This allows requesters to obtain decisions containing records in a more timely and efficient way.

You may expect a reply or additional communication as your request is processed. For your information, the Ministry charges for search and preparation time.

Due to the COVID-19 outbreak, requesters may experience some delays with FOI requests at this time.

If you have any questions, please contact Nasreen Salar at 647-330-4599 or Nasreen.Salar@ontario.ca.

Yours truly,
MECP Access and Privacy Office

Luizza Sitarski

From: Public Information Services <publicinformationservices@tssa.org>
Sent: Monday, February 27, 2023 11:47 AM
To: Ramila Senanayake
Subject: RE: Request for Tank Search - Plains Rd E, Burlington, ON

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Hello,

RECORD FOUND IN CURRENT DATABASE

Thank you for your request for confirmation of public information. TSSA has performed a preliminary search of TSSA's current database.

- We confirm that there are records in our database of any **fuel storage tanks** at the subject address(es).

Inventory Number	Address	City	Province	Postal Code	Status	Asset Type / Inventory Item
10331281-2	1364 PLAINS RD E	BURLINGTON	ON	L7R 3P8	Active	FS PROPANE REFILL CNTR - MOTOR FILL
10634236	1364 PLAINS RD E	BURLINGTON	ON	L7R 3P8	EXPIRED	FS PROPANE TANK
11564004	1364 PLAINS RD E	BURLINGTON	ON	L7R 3P8	EXPIRED	FS PROPANE TANK
11638638	1364 PLAINS RD E	BURLINGTON	ON	L7R 3P8	Active	FS PROPANE TANK
9653914	1364 PLAINS RD E	BURLINGTON	ON	L7R 3P8	EXPIRED	FS PROPANE REFILL CNTR - MOTOR FILL

This is not a confirmation that there are no records in the archives. For a further search in our archives, please submit an application for release of public information (PI Form) through TSSA's new Service Prepayment Portal. The associated fee must be paid via credit card (Visa or MasterCard) through a secure site. Please follow the steps below to access the new application(s) and Service Prepayment Portal:

1. Click Release of Public Information - TSSA - TSSA and click "need a copy of a document";

2. Select the appropriate application, download it and complete it in full; and
3. Proceed to page 3 of the application and click the link TSSA Service Prepayment Portal under payment options (the link will take you the secure site to pay for the release via credit card).

Accessing the Service Prepayment Portal:

1. Select new or existing customer (*if you are an existing customer, you will need your account # & postal code to access your account);
2. Select the program area: AD (Amusement Devices), BPV (Boilers and Pressure Vessels), ED (Elevating Devices), FS (Fuels Services), OE (Operating Engineers) or SKI (Ski Lifts) and click continue;
3. Enter the application form number (obtained from bottom left corner of application form) and click continue;
   a. When selecting the application form number from the drop-down menu, please make sure you select the application that begins with "PI" (i.e. PI-FS, PI-BPV etc.);
4. Complete the primary contact information section;
5. Complete the fees section;
6. Upload your completed application; and
7. Upload supporting documents (if required) and click continue.

Once all steps have been successfully completed, you will receive your receipt via email.
Questions? Please contact TSSA's Public Information Release team at publicinformationservices@tssa.org.
Although TSSA believes the information provided pursuant to your request is accurate, please note that TSSA does not warrant this information in any way whatsoever.

Kind regards,

Kimberly Gage | Public Information Agent
Legal
345 Carlingview Drive
Toronto, Ontario M9W 6N9
Tel: +1 416-734-3348 | Fax: +1 416-734-3568 | E-Mail: kgage@tssa.org
www.tssa.org

From: Ramila Senanayake <Ramila.Senanayake@exp.com>
Sent: Monday, February 27, 2023 9:37 AM
To: Public Information Services <publicinformationservices@tssa.org>
Subject: Request for Tank Search - Plains Rd E, Burlington, ON

[CAUTION]: This email originated outside the organisation.
Please do not click links or open attachments unless you recognise the source of this email and know the content is safe.

Hi,

Please provide environmental information for the following properties in Burlington, Ontario

1. 1376 Plains Road East
2. 1382 Plains Road East
3. 1364 Plains Road East
4. 1400 Plains Road East
5. 1401 Plains Road East
6. 1365 Plains Road East
7. 1349 Plains Road East
8. 1371 Plains Road East
9. 1369 Plains Road East
10. 1368 Plains Road East

As part of our historical review for a Phase One ESA, we request that the Technical Standards and Safety Authority (TSSA), Safety Fuel Division, review its database to identify us any records of aboveground/underground storage tanks, spills, incidents, complaints, notices, tanks removals and/or remediation etc. with the TSSA for the above-mentioned properties.

Thank you,
Ramila

Ramila Senanayake
EXP | Environmental Scientist
t : +1.905.793.9800 | m : +1.416.903.2501 | e : Ramila.Senanayake@exp.com
1595 Clark Boulevard
Brampton, ON L6T 4V1
CANADA
exp.com | legal disclaimer
keep it green, read from the screen
This electronic message and any attached documents are intended only for the named recipients. This communication from the Technical Standards and Safety Authority may contain information that is privileged, confidential or otherwise protected from disclosure and it must not be disclosed, copied, forwarded or distributed without authorization. If you have received this message in error, please notify the sender immediately and delete the original message.

Appendix H – Aerials



EXP Services Inc.
t: +1.905.793.9800 | f: +1.905.793.0641
1595 Clark Boulevard
Brampton, ON L6T 4V1
Canada
www.exp.com

•BUILDINGS • EARTH & ENVIRONMENT • ENERGY •
• INDUSTRIAL • INFRASTRUCTURE • SUSTAINABILITY •

N

0 30 60 90 120 150 m

TITLE AND LOCATION:

1934 AERIAL PHOTOGRAPH
Phase One Environmental Site Assessment
1376 and 1382 Plains Road East
Burlington, Ontario

PROJECT No.: GTR-22029872-A0	DWN: HY
SCALE: AS NOTED	CHKD: SH
DATE: JULY 2023	FIG. No.: H1



EXP Services Inc.
t: +1.905.793.9800 | f: +1.905.793.0641
1595 Clark Boulevard
Brampton, ON L6T 4V1
Canada
www.exp.com

•BUILDINGS • EARTH & ENVIRONMENT • ENERGY •
• INDUSTRIAL • INFRASTRUCTURE • SUSTAINABILITY •

N

0 30 60 90 120 150 m

TITLE AND LOCATION:

1954 AERIAL PHOTOGRAPH
Phase One Environmental Site Assessment
1376 and 1382 Plains Road East
Burlington, Ontario

PROJECT No.:	DWN:
GTR-22029872-A0	HY
SCALE:	CHKD:
AS NOTED	SH
DATE:	FIG. No.:
JULY 2023	H2



EXP Services Inc.
t: +1.905.793.9800 | f: +1.905.793.0641
1595 Clark Boulevard
Brampton, ON L6T 4V1
Canada
www.exp.com

•BUILDINGS • EARTH & ENVIRONMENT • ENERGY •
• INDUSTRIAL • INFRASTRUCTURE • SUSTAINABILITY •

N

0 30 60 90 120 150 m

TITLE AND LOCATION:

1961 AERIAL PHOTOGRAPH
Phase One Environmental Site Assessment
1376 and 1382 Plains Road East
Burlington, Ontario

PROJECT No.: GTR-22029872-A0	DWN: HY
SCALE: AS NOTED	CHKD: SH
DATE: JULY 2023	FIG. No.: H3



EXP Services Inc.
t: +1.905.793.9800 | f: +1.905.793.0641
1595 Clark Boulevard
Brampton, ON L6T 4V1
Canada
www.exp.com

•BUILDINGS • EARTH & ENVIRONMENT • ENERGY •
• INDUSTRIAL • INFRASTRUCTURE • SUSTAINABILITY •

N

0 30 60 90 120 150 m

TITLE AND LOCATION:

1973 AERIAL PHOTOGRAPH
Phase One Environmental Site Assessment
1376 and 1382 Plains Road East
Burlington, Ontario

PROJECT No.: GTR-22029872-A0	DWN: HY
SCALE: AS NOTED	CHKD: SH
DATE: JULY 2023	FIG. No.: H4



EXP Services Inc.
t: +1.905.793.9800 | f: +1.905.793.0641
1595 Clark Boulevard
Brampton, ON L6T 4V1
Canada
www.exp.com

•BUILDINGS • EARTH & ENVIRONMENT • ENERGY •
• INDUSTRIAL • INFRASTRUCTURE • SUSTAINABILITY •

N

0 30 60 90 120 150 m

TITLE AND LOCATION:

1986 AERIAL PHOTOGRAPH
Phase One Environmental Site Assessment
1376 and 1382 Plains Road East
Burlington, Ontario

PROJECT No.: GTR-22029872-A0	DWN: HY
SCALE: AS NOTED	CHKD: SH
DATE: JULY 2023	FIG. No.: H5



EXP Services Inc.
t: +1.905.793.9800 | f: +1.905.793.0641
1595 Clark Boulevard
Brampton, ON L6T 4V1
Canada
www.exp.com

•BUILDINGS • EARTH & ENVIRONMENT • ENERGY •
• INDUSTRIAL • INFRASTRUCTURE • SUSTAINABILITY •

N

0 30 60 90 120 150 m

TITLE AND LOCATION:

1998 AERIAL PHOTOGRAPH
Phase One Environmental Site Assessment
1376 and 1382 Plains Road East
Burlington, Ontario

PROJECT No.:	DWN:
GTR-22029872-A0	HY
SCALE:	CHKD:
AS NOTED	SH
DATE:	FIG. No.:
JULY 2023	H6



EXP Services Inc.
t: +1.905.793.9800 | f: +1.905.793.0641
1595 Clark Boulevard
Brampton, ON L6T 4V1
Canada
www.exp.com

•BUILDINGS • EARTH & ENVIRONMENT • ENERGY •
• INDUSTRIAL • INFRASTRUCTURE • SUSTAINABILITY •

N

0 30 60 90 120 150 m

TITLE AND LOCATION:

2004 AERIAL PHOTOGRAPH
Phase One Environmental Site Assessment
1376 and 1382 Plains Road East
Burlington, Ontario

PROJECT No.: GTR-22029872-A0	DWN: HY
SCALE: AS NOTED	CHKD: SH
DATE: JULY 2023	FIG. No.: H7



EXP Services Inc.
t: +1.905.793.9800 | f: +1.905.793.0641
1595 Clark Boulevard
Brampton, ON L6T 4V1
Canada
www.exp.com

•BUILDINGS • EARTH & ENVIRONMENT • ENERGY •
• INDUSTRIAL • INFRASTRUCTURE • SUSTAINABILITY •

N

0 30 60 90 120 150 m

TITLE AND LOCATION:

2014 AERIAL PHOTOGRAPH
Phase One Environmental Site Assessment
1376 and 1382 Plains Road East
Burlington, Ontario

PROJECT No.: GTR-22029872-A0	DWN: HY
SCALE: AS NOTED	CHKD: SH
DATE: JULY 2023	FIG. No.: H8



EXP Services Inc.
t: +1.905.793.9800 | f: +1.905.793.0641
1595 Clark Boulevard
Brampton, ON L6T 4V1
Canada
www.exp.com

•BUILDINGS • EARTH & ENVIRONMENT • ENERGY •
• INDUSTRIAL • INFRASTRUCTURE • SUSTAINABILITY •

N

0 30 60 90 120 150 m

TITLE AND LOCATION:

2021 AERIAL PHOTOGRAPH
Phase One Environmental Site Assessment
1376 and 1382 Plains Road East
Burlington, Ontario

PROJECT No.: GTR-22029872-A0	DWN: HY
SCALE: AS NOTED	CHKD: SH
DATE: JULY 2023	FIG. No.: H9

Appendix I – Site Photographs



Photo 1: View of 1382 Plains Road East, Photograph taken facing southwest.



Photo 2: View of the east wall of 1376 Plains Road East. Photograph taken facing southwest.



Photo 3: View of paved area between 1376 and 1382 Plains Road East. Photograph taken facing north.



Photo 4: View of the rail line south of the Site . Photograph taken facing south.



Photo 5: View of the parking area in the southern portion of the Site. Photograph taken facing northwest.



Photo 6: View of the west wall of 1376 Plains Road East. Photograph taken facing east.

exp. EXP Services Inc. 1595 Clark Boulevard Brampton, Ontario L6T 4V1 T: 905-793-9800 F: 905-793-0641	**SITE PHOTOGRAPHS** PROJ. NO: GTR-22029872-A0	PHASE ONE ESA 1376 and 1382 PLAINS RD E BURLINGTON, ON	SCALE: NTS DRAWN: RS CHECKED: SH	FIGURE A1 MAR 2022



Photo 7: View of the interior of 1376 Plains Road East



Photo 8: View of the interior of 1376 Plains Road East.



Photo 9: View of basement of 1376 Plains Road East.



Photo 10: View of the natural-gas fired furnace at 1376 Plains Road East.



Photo 11: View of the natural-gas fired furnace at 1382 Plains Road East.



Photo 12: View of the basement of 1382 Plains Road East.

EXP Services Inc.
1595 Clark Boulevard
Brampton, Ontario
L6T 4V1
T: 905-793-9800
F: 905-793-0641

SITE PHOTOGRAPHS

PROJ. NO: GTR-22029872-A0

PHASE ONE ESA
1376 and 1382 PLAINS RD E
BURLINGTON, ON

SCALE:	NTS	FIGURE A2
DRAWN:	RS	
CHECKED:	SH	MAR 2022

Appendix J – Phase One Conceptual Site Model

Phase One ESA Conceptual Site Model-
1376 and 1382 Plains Road East, Burlington, ON

This section presents the Phase One Conceptual Site Model (P1CSM), as it relates to the Site designated as 1376 and 1382 Plains Road East, Burlington, Ontario, providing a narrative and graphical description integrating information related to the areas of potential environmental concern/potential contaminating activities and the presence and distribution of potential contaminants of concern. The P1CSM was completed in accordance with Ontario Regulation 153/04, as amended (O.Reg.153/04), as defined by the Ontario Ministry Environment, Conservation and Parks (MECP). There is no uncertainty or absence of information noted in the Phase One Environmental Site Assessment.

1.1 Introduction

For the purposes of this report the alignment of Plains Road East is assumed to be in an east-west direction, with the Site being located on the southside of Plains Road East.

Details of the Site are as follows:

Table 1

Municipal Address	1376 and 1382 Plains Road East, Burlington, ON
Current Land Use	Commercial Use
Proposed Land Use	Residential Use
Legal Description	1376 Plains Rd E - Pt Lts 18 & 19, Pl 88, As In 403089 Except Part 1, 20R11699; Burlington 1382 Plains Rd E - Lt 17 & Pt Lt 18, Pl 88 As In 704027 ex. Pt 1, 20R18576. City Of Burlington Laneway to the east of 1382 Plains Rd E – Pt Lane, Pl 88, Lying Wly Of 20r4064 ; Pt Lt 16, Pl 88 , Part 3 & 4 , 20r4701 ; Burlington Laneway to the west of 1376 Plains Rd E- Alleyway, Pl 88; Burlington Southwest portion (railway land)- Part Lot 16, 69, 75, 77, 78 Rcp Pl 99 Part Brant St (closed By 322844) Rcp Pl99 As In Nr1126, Ns113, Bh417, Bh418, Bh421, Bh1099, Bh1231, Bh1232, Pm38, 149819, 294934, 307249, Pt 1, 2, 8, 9 Br55 Lying Btw Plains Road And Brant Strret , T/w H837379, H810868, H856856 Burlington Together With An Easement Over Pts 1 To 4 20r19491, Pt 1 20r19492, Pt 1 20r19493, Pts 1 To 4 20r19494, Pts 1 & 2 20r19499, Pt 1 20r19500, Pts 1 To 4 20r19501, Pts 1 & 2 20r19502, Pts 1 & 2 20r19503, Pts 1 To 9 20r19507, Pts 1 To 3 20r19508, Pts 1 & 2 20r19509 & Pts 1 To 4 20r19510 As In Hr1094626
Property Identification Number (PIN)	1376 Plains Rd E- 070870044 (LT) 1382 Plains Rd E-070870405 (LT) Laneway to the east of 1382 Plains Rd E – 070870046

	Laneway to the west of 1376 Plains Rd E- 070870043 Southwest portion (railway land) -070870393
Approximate Universal Transverse Mercator (UTM) coordinates	NAD83 17T 595755.86 m E 4798800.48 m N
Accuracy Estimate of UTM	10-15 m
Measurement Method	Global Positioning System (GPS)
Site Area	0.33 hectares (0.82 acres)
Property Owners, Owner Contact and Address	273119 Ontario Inc., Major Care Homes In., F.K Deals on Wheels Inc., 2731115 Ontario Inc. 2235 Sheppard Ave E., Suite 1700 North York, ON M2J 5B5 Mr. Nolan Moss
Any Other Person Who Engaged the QPESA	NA

1.2 Background

Based on the information available at this time, the Site was inferred to be developed circa early 1920s for residential use.

At the time of the Site visit, the Site was occupied by commercial tenants.

1.3 Geological and Hydrogeological Conditions

According to the Geology of Ontario Map, the surficial geology in the area of the Site is classified as Paleozoic bedrock. The bedrock in the general area of the Site is part of a group belonging to the Queenston Formation, consisting of shale, limestone, dolostone and siltstone.

Site and surrounding areas slope to the south. Lake Ontario is located 2.35 km south of the Site. Based on the information available at this time, the direction of groundwater flow in the area of the Site is inferred to be to the south.

Based on the review of available resources from the Ministry of Natural Resources and Forestry website February 22, 2023, no areas of natural significance were identified at the Site or within 30 m of the Site.

1.4 Previous Investigations

No previous environmental reports were available to review at the time of this Phase One ESA.

1.5 Underground Utilities

The Site utilities and services were identified at the Site based on information provided in environmental records, relevant utility infrastructure observed during the Site reconnaissance. The Site utilities are summarized in the table below and noted on Figure 3, where available. It is noted that the precise underground location of the utilities cannot be determined without professional locate services.

Utility	Source	Location	Site Entry
Natural Gas	Enbridge Gas	Underground	The natural gas meter was observed at 1376 and 1382 Plains Road East on the west and south walls of the Site buildings respectively.
Sanitary Sewer	City of Burlington	Underground	Unknown
Storm Sewer	City of Burlington	Underground	Storm sewers observed in the asphalt portion of the Site
Water	City of Burlington	Underground	Unknown
Electricity	Burlington Hydro	Underground	Unknown
Telecommunications	Bell	Underground	Unknown

1.6 Potentially Contaminating Activities and Areas of Potential Environmental Concern:

Refer to Table 2 and Figure 2 for the list of potentially contaminating activities (PCAs) that have occurred within the Phase One Study Area, which includes the Site and properties within 250 m radius of the Site boundaries.

Table 2: Potentially Contaminating Activities

PCA Identifier	Address	Location of Activity (in relation to Site)[1]	Potentially Contaminating Activity (PCA)[2]	Approximate timeline that PCA occurred	Contributes to APEC (Yes or No)?
Site					
1A	1376 and 1382 Plains Road East	Asphalt paved driveways and walking areas at the Site	PCA" Other"-Application of De-icing salt	Since development (prior to 1924) the Site has had paved areas. For de-icing purposes, road salt would have been applied during the winter months.	Yes, due to the PCA occurring on the Site.
1B	1382 Plains Road East	Southern portion of the building, where the furnace room is located	PCA#28-Gasoline and Associated Products Storage in Fixed Tanks	Based on the reviewed 1981 insurance reports, this building was historically heated using heating oil. According to the report, the Site building was heated using one (1) oil fired forced air furnace. No further information was provided in the report regarding the type of containment using used for the oil; however, it is known that the oil would have been stored in a fixed tank.	Yes, due to the PCA occurring on the Site.
1C	1376 Plains Road East	Southern portion of the building, where the furnace room is located	PCA#28-Gasoline and Associated Products Storage in Fixed Tanks	Based on the information from the insurance report, 1382 Plains Road East was historically heated using oil. Since 1376 Plains Road East was developed at the same time 1382 Plains Road East was developed, this building is also inferred to have historically been heated using heating oil that was stored in a fixed tank.	Yes, due to the PCA occurring on the Site.
Surrounding Properties					

PCA Identifier	Address	Location of Activity (in relation to Site)[1]	Potentially Contaminating Activity (PCA)[2]	Approximate timeline that PCA occurred	Contributes to APEC (Yes or No)?
2	1368 Plains Road East	West adjacent	#52-Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems	At the time of the Site visit, a tire change/repair shop was observed at this property.	Yes, due to the nature of the operations (i.e., auto service) and the proximity to the Site.
3A	1364 Plains Rd E	20 m west	PCA#28-Gasoline and Associated Products Storage in Fixed Tanks	Based on the reviewed ERIS report, the property was registered for having a retail tank. The tank expired in 1994, and has a capacity of 2000 L.	Yes, due to the nature of the operations (i.e., auto service) and the proximity to the Site.
3B			PCA#27-Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	In the ERIS report, Burlington Taxi Ltd., a tenant of the property was registered as a garage (gen. repair) and listed for the generation of waste oils and lubricants from 1989-2001.	
3C			#52-Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems	Based on the reviewed 1971 FIP, 1358 Plains Road East (current 1364 Plains Road East) was occupied by Motorcycle sales and service.	
4A	1400 Plains Road East	East adjacent	#52-Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems	At the time of the Site visit, this building was occupied by several tenants who are engaged in auto service. Based on the reviewed city directories, the property was occupied by an auto repair shop from 2001-2021.	Yes, due to the nature of the operations (i.e., auto service) and the proximity to the Site.

PCA Identifier	Address	Location of Activity (in relation to Site)[1]	Potentially Contaminating Activity (PCA)[2]	Approximate timeline that PCA occurred	Contributes to APEC (Yes or No)?
4B	1390 Plains Road East (former 1400 Plains Road East)	East adjacent	PCA#31- Ink Manufacturing, Processing and Bulk Storage	Based on the reviewed 1971 FIP, this property was occupied by "Blue Printing".	Yes, due to the nature of the operations and the proximity to the Site.
5A	Historical municipal address unknown - currently the southern portion of 1400 Plains Road East	Southeast adjacent	PCA#2-Adhesives and Resins Manufacturing, Processing and Bulk Storage	Based on the reviewed 1924 FIP, this land was occupied by the Ontario Canning Co. The building had a Machine Room there the food products were likely filled in the cans and labeled in preparation for distribution. For this purpose, the property likely stored bulk stored adhesives.	Yes, due to the proximity to the Site and the nature of the operations.
5B			PCA#34-Metal Fabrication	Based on the reviewed 1924 and 1932 FIPs, there was a foundry in the southwestern corner of this building.	
5C			PCA#4- Antifreeze and De-icing Manufacturing and Bulk Storage	Based on the reviewed 1971 FIP, the property has a building that was used to store anti-freeze. There were also tanks storing anti-freeze exterior adjacent to the building.	
6	No municipal address	5 m south	PCA#46- Rail Yards, Tracks and Spurs	Based on the reviewed aerial photographs, the CNR lines have been located approximately 15 m south of the Site since prior to 1934.	Yes, due to the proximity to the Site.

PCA Identifier	Address	Location of Activity (in relation to Site)[1]	Potentially Contaminating Activity (PCA)[2]	Approximate timeline that PCA occurred	Contributes to APEC (Yes or No)?
7	1371-1411 Plains Road East (current 1401 Plains Rd E)	20 m north	#52-Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems	According to the reviewed city directories, the property was occupied by auto repair shops from 2001-2021.	Yes, due to the proximity to the Site and the inferred up-gradient location relative to the direction of groundwater flow.
8A	1274 Plains Road East	65 south/ Southwest	PCA#8- Chemical Manufacturing, Processing and Bulk Storage	Based on the reviewed FIPs and city directories, this property was historically occupied by chemicals manufacturing companies from prior to 1924 to circa 2021. Based on the reviewed ERIS report Sun Chemical Ltd. was registered for a fire at the plant in 1996. Soil contamination was a possible outcome of this fire.	No, based on the separation distance from the Site and the inferred down-gradient location relative to the direction of groundwater flow.
8B			PCA#31- Ink Manufacturing, Processing and Bulk Storage	According to the reviewed city directories, the property was occupied by printing companies from 1966-2021.	
9A	942 Brant Street	150 m south	PCA "Other" – Spill with potential environmental impacts	Based on the reviewed ERIS report, several spills were recorded at this property. Among the spills the following were noted to be significant spills with potential environmental concerns: • A spill was recorded in 1989 when 18,000 L, and 15,000 L of lube oil was release to the ground. • 450 L of solvent was released to a dyke in 2004.	No, based on the separation distance from the Site.

PCA Identifier	Address	Location of Activity (in relation to Site)[1]	Potentially Contaminating Activity (PCA)[2]	Approximate timeline that PCA occurred	Contributes to APEC (Yes or No)?
9B			PCA#8- Chemical Manufacturing, Processing and Bulk Storage	Based on the reviewed 1924, 1932 FIP and city directories, this property has been occupied by chemical manufacturing companies from prior to 1924. Based on the reviewed ERIS report, the property was registered on the database for “other chemical product manufacturing” and “all other miscellaneous chemical product manufacturing”.	
9C			PCA#45- Pulp, Paper and Paperboard Manufacturing and Processing	The 1932 FIP showed this building to be occupied by Paper Makers, Chemical Corp Limited.	
9D			PCA#40- Pesticides (including Herbicides, Fungicides and Anti-Fouling Agents) Manufacturing, Processing, Bulk Storage and Large-Scale Applications	Based on the reviewed 1932 FIP, this property had buildings where herbicide manufacturing took place.	
9E			PCA”Other”- Generation of Halogenated Solvents	Based on the reviewed ERIS report, the property was registered for the generation of wastes including halogenated solvents from 2013-2022.	
9F			PCA#28-Gasoline and Associated Products Storage in Fixed Tanks	Based on the reviewed 1932 FIP, a UST was located on this property.	

PCA Identifier	Address	Location of Activity (in relation to Site)[1]	Potentially Contaminating Activity (PCA)[2]	Approximate timeline that PCA occurred	Contributes to APEC (Yes or No)?
9G			PCA#2- Adhesives and Resins Manufacturing, Processing and Bulk Storage	Based on the reviewed 1971 FIP, this property had industrial operations that included resin melting and storage.	
10A	932 Brant Street	230 m southeast	PCA#55-Transformer Manufacturing, Processing and Use	Based on the reviewed ERIS report a leak of transformer oil was recorded in 2012. 4.5 L of mineral was released to a paved area. Environmental impact was not “anticipated”.	No, based on the separation distance from the Site.
10B			PCA#34-Metal Fabrication	According to the reviewed city directories, the property was occupied by Dan’s Welding and Fabricating from 1957-1971.	
11A	920 Brant Street	210 m southeast	PCA#34-Metal Fabrication	Based on the reviewed ERIS report, Unit 13 was registered for operations including metal valve manufacturing.	No, based on the separation distance from the Site.
11B			PCA#55-Transformer Manufacturing, Processing and Use	Based on the reviewed ERIS report, Unit 23 was registered for power, distribution and speciality transformers manufacturing.	
11C			PCA#31- Ink Manufacturing, Processing and Bulk Storage	According to the reviewed city directories, the property was occupied by a print centre from 2006-2017. Based on the reviewed ERIS report, Unit 18-19, registered for quick printing, was registered for	

PCA Identifier	Address	Location of Activity (in relation to Site)[1]	Potentially Contaminating Activity (PCA)[2]	Approximate timeline that PCA occurred	Contributes to APEC (Yes or No)?
				the generation of wastes including petroleum distillates in 2005, photoprocessing wastes from 2005- 2016.	
11D			PCA#19- Electronic and Computer Equipment Manufacturing	Based on the reviewed ERIS report, Unit 16 was registered for electronic and precision equipment repair and maintenance and for the generation of acid wastes in 2005.	
11E			PCA#55-Transformer Manufacturing, Processing and Use	Based on the reviewed ERIS report, a transformer oil spill was recorded in 2016 when 2 L of non-PCB oil was released to the ground.	
12	No municipal address	90 m northwest	PCA#40- Pesticides (including Herbicides, Fungicides and Anti-Fouling Agents) Manufacturing, Processing, Bulk Storage and Large-Scale Applications	Based on the reviewed aerial photographs, an orchard was observed approximately 90 m northwest of the Site in the 1934 aerial photograph.	No, based on the separation distance from the Site and the lower mobility of the contaminants of concern.
13	Historical municipal address unknown currently the southern portion of 1400 Plains Road East	65 m east	PCA#34	Based on the reviewed 1924 FIP, the property was occupied by the Biggs Fruit Co Ltd., and a machines shop was located at this property.	No, based on the separation distance from the Site and the inferred trans-gradient location relative to the direction of groundwater flow.
14	1435 Plains Road East	140 m northeast	PCA#28-Gasoline and Associated Products Storage in Fixed Tanks	Based on the reviewed city directories the property was occupied by service stations from 1957-1990.	No, based on the separation distance from the Site.

PCA Identifier	Address	Location of Activity (in relation to Site)[1]	Potentially Contaminating Activity (PCA)[2]	Approximate timeline that PCA occurred	Contributes to APEC (Yes or No)?
15	1446 Plains Rd E	175 m east	PCA#28-Gasoline and Associated Products Storage in Fixed Tanks	Based on the reviewed ERIS report, the property, registered as gasoline station was registered for having three (3) double wall USTs and one (1) single wall UST for gasoline storage. Based on information in the databases, the tanks were installed in 1984, 1994. Based on the reviewed city directories, the property was occupied by a service station from 1961-2021.	No, based on the separation distance from the Site.
16	1355 Plains Road East	65 m northwest	PCA#34-Metal Fabrication	Based on the reviewed 1971 FIP, this property was occupied by a machine shop.	No, based on the separation distance from the Site, and the inferred trans-gradient location relative to the direction of groundwater flow.
17	944 Brant Street	150 m south	PCA#8- Chemical Manufacturing, Processing and Bulk Storage	According to the reviewed city directories, the property was occupied by Niagara chemical company from 1957-1981. The 1924 FIP showed the property to be occupied by Vera Chemical Co. of Company Ltd.	No, based on the separation distance from the Site.
18	1043 Glendora Avenue	200 m northwest	PCA#49- Salvage Yard, including automobile wrecking	According to the reviewed city directories, the property was occupied by B and M Marine Salvage from 2006-2012.	No, based on the separation distance from the Site.

(1) Distances are approximate. Precise distances are not possible due to the age of some listings and the aggregation and/or loss of addresses.

(2) Potentially contaminating activity means a use or activity set out in Column A of Table 2 of Schedule D (O.Reg 153/04, as amended) that is occurring or has occurred in a Phase One Study area.

1.7 Areas of Potential Environmental Concern

Based on the evaluation of the PCAs located within the Phase One Study Area, the following areas of potential environmental concern (APECs) were identified, as presented in Figure 4.

Table 3: Areas of Potential Environmental Concern

Area of Potential Environmental Concern (APEC)	Location of APEC on Phase One Property	Potentially Contaminating Activity (PCA)[1]	Location of PCA (on-Site or off-Site)	Contaminants of Potential Concern	Media Potentially Impacted (Groundwater, soil and/or sediment)
APEC 1A: Application of De-icing salt on the on-Site paved areas (PCA 1A)	Asphalt paved driveways and walking areas at the Site	PCA" Other"-Application of De-icing salt	On-Site	EC and SAR	Soil
APEC 1B: Former storage of heating oil at 1376 Plains Road East (PCA 1B)	Southern portion of the building (prior to the extension)	PCA#28-Gasoline and Associated Products Storage in Fixed Tanks	On-Site	PHCS, PAH and BTEX	Soil and Ground Water
APEC 1C: Former storage of heating oil at 1382 Plains Road East (PCA1C)	Southern portion of the building, where the furnace room is located	PCA#28-Gasoline and Associated Products Storage in Fixed Tanks	On-Site	PHCs, PAH and BTEX	Soil and Ground Water
APEC 2: Auto Service to the west of the Site (PCA 2 and 3A-C)	Western Site boundary	PCA#27-Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles #52-Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems	Off-Site 1364 Plains Road East (20 m west) 1358 Plains Road East (former 1364	PHCs, PAH, VOCs and Metals	Groundwater

Area of Potential Environmental Concern (APEC)	Location of APEC on Phase One Property	Potentially Contaminating Activity (PCA)[1]	Location of PCA (on-Site or off-Site)	Contaminants of Potential Concern	Media Potentially Impacted (Groundwater, soil and/or sediment)
			Plains Road East) 1368 Plains Road East (West adjacent)		
APEC 3: Current presence of auto service to the east adjacent to Site (PCA 4A) Former presence of printing facility east adjacent to Site (PCA 4B)	Eastern Site boundary	#52-Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems PCA#31- Ink Manufacturing, Processing and Bulk Storage	Off-Site- east adjacent 1400 Plains Road East (PCA 4A) 1390 Plains Road East (PCA 4B)	PHCs, PAH, VOCs and Metals	Groundwater
APEC 4: Former presence of a fruit canning company southeast adjacent to Site (PCA5A-C)	Southeastern Site boundary	PCA#2-Adhesives and Resins Manufacturing, Processing and Bulk Storage PCA#4- Antifreeze and De-icing Manufacturing and Bulk Storage PCA#34-Metal Fabrication	Off-Site – southeast adjacent	VOCs, PHCs, Metals	Groundwater

Area of Potential Environmental Concern (APEC)	Location of APEC on Phase One Property	Potentially Contaminating Activity (PCA)[1]	Location of PCA (on-Site or off-Site)	Contaminants of Potential Concern	Media Potentially Impacted (Groundwater, soil and/or sediment)
APEC 5: Historical auto repair at 1401 Plains Road East (PCA 7)	Northeastern boundary of the Site	#52-Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems	Off-Site – 25 m north	PHCs, PAH, VOCs and Metals	Groundwater
APEC 6: Presence of a rail line in close proximity to Site (PCA 6)	Southwestern boundary of the Site	PCA#46-Rail Yards, Tracks and Spurs	Off-Site- 5 m south	Metals, PAHs and PHCs	Groundwater

(1) Potentially contaminating activity means a use or activity set out in Column A of Table 2 of Schedule D (O.Reg.153/04, as amended) that is occurring or has occurred in a phase one Study area.

Based on the findings of the Phase One ESA and conclusions, a Phase Two ESA is required to assess the soil and groundwater conditions at the Site.