Phase One Environmental Site Assessment

1160 Blair Road,
Burlington, Ontario

Client
Archangel Raphael and Saint Marina Coptic Orthodox Church
P.O. Box 25008 RPO Harrison
Burlington, ON L7M 0V8

Attn: Father Anthony Wadie

Project Number
HAM-00801245-G0

Prepared By
EXP Services Inc.
80 Bancroft Street
Hamilton, ON L8E 2W5

Date
February 20, 2019

Executive Summary

EXP Services Inc. (EXP) was retained by Archangel Raphael and Saint Marina Coptic Orthodox Church (client) to complete a Phase One Environmental Site Assessment (ESA) of the property located at 1160 Blair Road, in Burlington, Ontario (hereinafter referred to as the 'Site').

The objective of the investigation was to support the filing of a Record of Site Condition (RSC) in accordance with Ontario Regulation 153/04, as amended (O.Reg.153/04).

The Site is located on the southwest side of Blair Road at Landmark Road in Burlington, Ontario. The Site measures approximately 1.7 hectares (4.1 acres) in area. The Site is currently occupied by a two-storey industrial/commercial building with approximately 7,205 m² (77,555 ft²) of floor area. The Site building is currently occupied by various commercial tenants. A review of aerial photographs indicates that the Site building had been constructed between 1959 and 1978. According to the Site representative, the building was constructed in the 1970s.

A Phase One ESA is a systematic qualitative process to assess the environmental condition of a Site based on its historical and current uses. This Phase One ESA was conducted in accordance with the Phase One ESA standard as defined by O.Reg.153/04, and in accordance with generally accepted professional practices. Subject to this standard of care, EXP makes no express or implied warranties regarding its services and no third party beneficiaries are intended. Limitation of liability, scope of report and third party reliance are outlined in Appendix A.

Please note that general environmental management and housekeeping practices were reviewed as part of this assessment insofar as they could impact the environmental condition of the property. However, a detailed review of regulatory compliance issues was beyond the scope of our investigation. This Phase One ESA does not constitute an audit of environmental management practices, indicate geotechnical conditions or identify geologic hazards.

Based on the Phase One ESA findings, the following information is provided in Table 1-1 in support of the Phase One Qualified Person's (QP's) conclusion:

Table 1-1: Areas of Potential Environmental Concern

Area of Potential Environmental Concern (APEC)[1]	Location of APEC on Phase One Property	Potentially Contaminating Activity (PCA)[2]	Location of PCA (on-Site or off-Site)	Contaminants of Potential Concern	Media Potentially Impacted (Groundwater, soil and/or sediment)
APEC 1A	Entire Site	40 – Pesticides (including Herbicides, Fungicides, and Anti Fouling Agents) manufacturing, processing, bulk storage and large-scale applications	On-Site (1160 Blair Road)	Organochlorine Pesticides, Metals, As, Sb, Se	Soil
APEC 1B	Southeast Industrial Unit	34 – Metal Fabrication		Metals, VOCs and PHCs	Soil and Groundwater
APEC 1C	Northwest Industrial Unit	52 – Storage, maintenance, fuelling and repair of equipment, vehicles and materials used to maintain transportation systems		VOCs and PHCs	Soil and Groundwater

Area of Potential Environmental Concern (APEC)[1]	Location of APEC on Phase One Property	Potentially Contaminating Activity (PCA)[2]	Location of PCA (on-Site or off-Site)	Contaminants of Potential Concern	Media Potentially Impacted (Groundwater, soil and/or sediment)
APEC 2	Southeast adjacent to property line	28 – Gasoline and Associate Products in Fixed Tanks, 34 – Metal Fabrication	Off-Site (1150 Blair Road)	VOCs and PHCs, Metals	Soil and Groundwater
APEC 3	Southern corner of property	28- Gasoline and Associate Products Storage in Fixed Tank Not listed – Generator of hazardous wastes	Off-Site (1171 Blair Road)	PHCs, VOCs, BTEX, Metals	Groundwater
APEC 4	Northeast adjacent to property boundary	Not listed – Generator of hazardous wastes	Off-Site (1157 Blair Road)	PHCs, VOCs, BTEX, Metals	Groundwater
APEC 5	Northern corner of property	Not listed – Generator of hazardous wastes 34 – Metal Fabrication 27- Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Off-Site (3388 Mainway)	PHCs, VOCs, BTEX, Metals	Groundwater
APEC 6	Northern corner of property	Not listed – Generator of hazardous wastes	Off-Site (3390 Mainway)	PHCs, VOCs, BTEX, Metals	Groundwater

(1) Area of Potential Environmental Concern means the area on, in or under a phase one study area where one or more contaminants are potentially present, as determined through the PI ESA, including through (a) identification of post or present uses on, in or under the phase one property, and (b) identification of potentially contaminating activities.
(2) Potentially contaminating activity means a use or activity set out in Column A of Table 2 of Schedule D (O.Reg.153/04, as amended) that is occurring or has occurred in a phase one Study area.

Based on the findings of the Phase One ESA and conclusions, a Phase Two ESA is required to assess the soil and groundwater conditions at the Site prior to submitting a RSC.

This executive summary is a brief synopsis of the report and should not be read in lieu of reading the report in its entirety.

Table of Contents

Executive Summary ..... **i**

1. Introduction **1**

1.1 Phase One Property Information 1

2. Scope of Investigation **3**

3. Records Review **4**

3.1 General 4
3.1.1 Phase One Study Area Determination 4
3.1.2 First Developed Use Determination 4
3.1.3 Fire Insurance Plans 4
3.1.4 Chain of Title 4
3.1.5 Environmental Reports 4

3.2 Environmental Source Information 5
3.2.1 Federal and Provincial Database Search 5
3.2.2 Municipal Records 22
3.2.3 Ontario Ministry of the Environment Records 24
3.2.4 Technical Standards and Safety Authority 25

3.3 Physical Setting Sources 25
3.3.1 Aerial Photographs 25
3.3.2 Topography, Hydrology and Geology 26
3.3.3 Fill Materials 27
3.3.4 Water Bodies and Areas of Natural Significance 27
3.3.5 Well Records 27

3.4 Site Operating Records 27

4. Interviews **29**

5. Site Reconnaissance **30**

5.1 General Requirements 30

5.2 Specific Observations at Phase One ESA Property 30
5.2.1 Site Description and Buildings 30
5.2.2 Heating and Cooling Systems 30
5.2.3 Site Utilities and Services 30
5.2.4 Sewage and Wastewater Disposal 31
5.2.5 Potable Water Sources 31
5.2.6 Abandoned and Existing Wells 31

5.2.7 Site Production and Manufacturing 31
5.2.8 Drains, Pits and Sumps 31
5.2.9 Storage Tanks 31
5.2.10 Water Wells 31
5.2.11 Site Housekeeping 31
5.2.12 Chemical Storage and Handling and Floor Condition 31
5.2.13 Soil, Pavement or Stressed Vegetation 32
5.2.14 Fill and Debris 32
5.2.15 Air Emissions 32
5.2.16 Polychlorinated Biphenyls (PCBs) 32
5.2.17 Regulated Building Materials 33
5.3 Enhanced Investigation Property Observations 33
5.4 Adjacent and Surrounding Properties 33
5.5 Written Description of Investigation 37

6. Review and Evaluation of Information 39
6.1 Current and Past Uses 39
6.2 Potentially Contaminating Activities (PCAs) 39
6.3 Areas of Potential Environmental Concern (APECs) 39

7. Conclusions 40

8. Closure 41

9. References 42

List of Figures

Figure 1 – Site Location Plan
Figure 2 – Phase One ESA Study Area and Surrounding Land Use Plan
Figure 3 – Potentially Contaminating Activities (PCAs)
Figure 4 – Areas of Potential Environmental Concern (APECs)

List of Appendices

Appendix A – Limitation of Liability, Scope of Report, and Third Party Reliance
Appendix B – Survey Plan
Appendix C – Qualification of Assessors
Appendix D – Chain of Title Search
Appendix E – Ecolog ERIS Report
Appendix F – Municipal Records
Appendix G – Other Government Records
Appendix H – Aerial Photographs
Appendix I – Site Photographs
Appendix J – Phase One CSM

1. Introduction

EXP Services Inc. (EXP) was retained by Archangel Raphael and Saint Marina Coptic Orthodox Church (client) to complete a Phase One Environmental Site Assessment (ESA) of the property located at 1160 Blair Road, in Burlington, Ontario (hereinafter referred to as the 'Site').

The objective of the investigation was to support the filing of a Record of Site Condition (RSC) in accordance with Ontario Regulation 153/04, as amended (O.Reg.153/04).

A Phase One ESA is a systematic qualitative process to assess the environmental condition of a Site based on its historical and current uses. This Phase One ESA was conducted in accordance with the Phase One ESA standard as defined by O.Reg.153/04, and in accordance with generally accepted professional practices. Subject to this standard of care, EXP makes no express or implied warranties regarding its services and no third party beneficiaries are intended. Limitation of liability, scope of report and third party reliance are outlined in Appendix A.

The objective of this review was to identify any environmental concerns associated with the Site.

1.1 Phase One Property Information

The Site is located on the southwest side of Blair Road at Landmark Road in Burlington, Ontario (Figures 1 and 2). The Site measures approximately 1.7 hectares (4.1 acres) in area. The Site is currently occupied by a two-storey industrial/commercial building with approximately 7,205 m² (77,555 ft²) of floor area. The Site building is currently occupied by various commercial tenants including: Creative Edge Dance Studio, RDC (Responsible Distribution Canada) (office), Ciscon Landscaping (showroom, office and yard), Body by PT (exercise gym), Canadian Dance Company, Burlington Movers (storage and office), Eurostar Renos, Absolute Custom Steel Fabrications (workshop), Insatax (office), Nuway Software (office) and the Archangel Raphael and Saint Marina Coptic Orthodox Church.

At the time of the Site visit, three (3) of the units were vacant, two (2) of which were located on the second floor.

A review of aerial photographs indicates that the Site building had been constructed between 1959 and 1978. According to the Site representative, the building was constructed in the 1970s.

Details of the Site are as follows:

Civic Address	1160 Blair Road, Burlington, ON
Current Land Use	Commercial
Proposed Land Use	Community (Church)
Legal Description	Part of Lot 12, Concession 2, South of Dundas Street, “Nelson”, designated as Parts 9, 10 and 11, Reference Plan 20R-11755, Burlington
Property Identification Number (PIN)	07163-0083(LT)
Assessment Roll Number (ARN)	2402-090-903-41100-000
Universal Transverse Mercator (UTM) coordinates	NAD83 17, 597267E 4802107N
Site Area	1.67212 hectares
Property Owners	Archangel Raphael and Saint Marina Coptic Orthodox Church

2. Scope of Investigation

The scope of work for the Phase One ESA consisted of the following activities:

- Reviewing the historical occupancy of the Site through the use of available archived and relevant municipal and business directories, fire insurance plans (FIPs), topographical maps, and aerial photographs;
- Contacting municipal and provincial agencies to determine the existence of records of environmental regulatory non-compliance, if any, and reviewing such records where available;
- Obtaining an EcoLog Environmental Risk Information Services Ltd. (ERIS) report for the Site and surrounding properties within 250 metres of the Site;
- Reviewing available geological maps, well records and utility maps for the vicinity of the Site;
- Obtaining and reviewing a chain of title and assessment rolls for the Site;
- Reviewing available reports previously completed at the Site;
- Conducting interviews with designated Site representative(s) as a resource for current and historical Site information, as well as to provide EXP staff with unrestricted access to all areas of the Site and Site buildings (as required by O.Reg. 153/04, as amended);
- Conducting a Site reconnaissance in order to identify any land use practices that may have impacted the environmental condition of the Site;
- Conducting a reconnaissance of the surrounding properties from the Site and publicly accessible areas in order to identify any land use practices that may have impacted the environmental condition of the Site; and,
- Preparing a report to document the findings.

The following sections summarize the information gathered by EXP during the Phase One ESA and identify Potentially Contaminating Activities (PCAs) on the Phase One property and in the Phase One study area, and Areas of Potential Environmental Concern (APECs) associated with the Site. APECs and PCAs are defined in O.Reg. 153/04, as amended.

In completing the scope of work, EXP did not conduct any intrusive investigations, including sampling, analyses or monitoring.

EXP has confirmed neither the completeness nor the accuracy of any of the records that were obtained or any of the statements made by others.

EXP personnel who conducted assessment work for this project included: Ms. Kelsey Proks, B.Sc., Ms. Patricia McMullan, B.Eng, EIT, Mr. Erik Enders, P.Geo. (QP) and Mr. David Mably, P. Eng. (QP). An outline of their qualifications is provided in Appendix C.

3. Records Review

3.1 General

3.1.1 Phase One Study Area Determination

The Site is located on the southwest side of Blair Road at Landmark Road, at 1160 Blair Road in Burlington, Ontario (Figure 1). The Phase One ESA study area consists of properties within a distance of 250 metres (m) from the Site boundaries (Figure 2). The surrounding properties within the Phase One ESA study area predominantly consist of commercial/industrial properties. The Phase One ESA study area and a Surrounding Land Use Plan are shown on Figure 2.

3.1.2 First Developed Use Determination

Based on a review of historical aerial photographs, chain of title information, historical maps, and other records, the Site building was constructed in the early 1970s. Prior to Site development, the Site was used for agricultural purposes, including an orchard. A more detailed discussion of the Site history, based on the available documentation, is provided below.

3.1.3 Fire Insurance Plans

A search of Canadian Underwriter's Association FIPs of the general area was completed at McMaster Library. Based on the search, no FIPs were available for review for the Site or surrounding properties.

3.1.4 Chain of Title

A chain of title for the property located at 1160 Blair Road, was completed by Mr. Dominic Bertucci, an independent title searcher. The Site is currently owned by the client.

A copy of the Chain of Title is provided in Appendix D and a list of previous owners are provided in the table of current and past uses.

Based on a review of the previous owners of the Site, no additional PCAs were identified.

3.1.5 Environmental Reports

A report titled "*Update Phase I Environmental Site Assessment, 1160 Blair Road, Burlington Ontario*" was prepared by Trow Consulting Engineers Ltd. (now EXP) in January 1999.

The report reviewed indicated the following pertinent information:

- "The Site has been occupied by a commercial building since 1973 and the Site and surrounding area have historically been agricultural use since the early 1900s;
- Based on the date of building construction, asbestos containing materials (ACM) may be present in various types of building materials; and
- Lead based paint may be present on original painted surfaces."

3.2 Environmental Source Information

3.2.1 Federal and Provincial Database Search

A search of provincial, federal and private environmental databases for records pertaining to the Site and properties within the Phase One study area was conducted by EcoLog Environmental Risk Information Services (ERIS) in May 2018. EXP has confirmed neither the completeness nor the accuracy of the records that were provided. A copy of the EcoLog ERIS report is provided in Appendix E. A summary of the significant findings is provided below.

Location & Proximity to Site	Summary	Database	Associated PCA
Site			
Site (1160 Blair Road)	**Loomis Courier Service** was listed as having an expired propane refill centre. A spill incident associated with this occupant included 8 litres (L) of carbon tetrachloride leaked from a freight container. Given the small quantity of liquid spilled to a paved surface and the volatility of carbon tetrachloride, it is expected that the spill quickly evaporated and no residual contamination reached the underlying soil or groundwater. **Royal Lepage State Realty Brokerage** was listed as a waste generator for other specified inorganics in 2008. **S.E Sales and Service Ltd.** was listed as a waste generator of petroleum distillates, waste oils & lubricants and other polymeric wastes in 2005. **Jenimar Colour Separations Inc.** was listed as a waste generator of photoprocessing wastes from 1986 to 1998. Based on the characteristics of wastes generated on the Site and/or inferred small quantities of wastes handled by the above waste generators, the handling of hazardous wastes does not pose an environmental concern. **All-Tig Ltd**., is listed in Scott's Directory, with the following operations: "Fabricated Metal Products". The Site is listed for a water well record pertaining to monitoring well instrumented in 2012. The well is located on the grass easement in front of the Site.	*EXP, FSTH, PRT, SPL, GEN, SCT, WWIS*	N/A
Site and Surrounding Properties			
Site and ERIS study area	Based on the Ecolog ERIS report, the Site and surrounding properties are not listed in the Inventory of Coal Gasification Plants and Coal Tar Sites.	*COAL*	N/A

Location & Proximity to Site	Summary	Database	Associated PCA
Site and ERIS study area	Based on the Ecolog ERIS report, the Site and surrounding properties are not listed as Waste Disposal Sites.	*WDS*	N/A
Surrounding Properties			
1150 Blair Road (Southeast adjacent)	**Gotfryd Contracting Ltd.** was listed as having an expired private liquid fuel outlet (Self-Serve) expiring in 1989. A single walled diesel underground storage tank was present. A review of city directories (Appendix F) indicated that Gotfryd Contracting Ltd was a tenant at 1150 Blair Road in 1990. Given the absence of any other records of fuel storage on Site, it is considered that the TSSA listed the expired fuel tank at 1160 Blair Road instead of the correct address of 1150 Blair Road. **Simon Crane Rental Ltd.** was listed as a waste generator of waste oils & lubricants, aliphatic solvent and petroleum distillates from 1995 to 2015 and light fuels from 2010 to 2015. **A.W. Chesterton** was listed in Scott's Directory, with the following operations, "industrial machinery and equipment" and also registered as a waste generator of various wastes including emulsified oils, polymeric resins, inorganic & organic laboratory chemicals, halogenated solvents and petroleum distillates from 1994 to 2001. **Kenwar Tool & Die Ltd.** is listed in Scott's Directory, with the following operations: "Special dies and tool and industrial molds". **JR Tool and Die** is listed in Scott's Directory, with the following operations: "Machine tools, metal cutting types; special dies and tools, die sets, jigs and fixtures and industrial molds; industrial and commercial machinery and equipment". **SOS Cylinders Inc.** is listed in Scott's Directory, with the following operations: "All other general-purpose machinery manufacturing**"**. An observation well record is listed for this property dated March 2007.	*GEN, SCT, WWIS*	28- Gasoline and Associate Products Storage in Fixed Tank (PCA-2A) 34 – Metal Fabrication (PCA-2B) Not listed – Generator of hazardous wastes (PCA-2C)

Location & Proximity to Site	Summary	Database	Associated PCA
1157 Blair Road (30 m north)	**Fagersta Secoroc Ltd.** was registered as a waste generator of emulsified oils and halogenated solvents from 1986 to 1998. **Screenplay Designs Inc.** was registered as a waste generator of waste oils & lubricants for 2007 and 2008 and graphic art wastes in 2008. **Wardco Window & Door Manufacturing** was registered as a waste generator of paint/pigment/coating residues from 2013 to 2017. **XCG Consultants Ltd.** was registered as a waste generator of oil skimmings & sludges from 2003 to 2006. **Atlas Copco Canada** was registered as a waste generator of oil skimmings & sludges for 2002/2003/2007 and halogenated solvents, other specified inorganics, oil skimming & sludges from 2008 to 2017. A spill incident associated with this occupant included 2 L of potassium permanganate to the ground. Environmental impact was not anticipated. An observation well records are listed for this property dated April 2007 and February 2009.	*GEN, SPL, WWIS*	Not listed – Generator of hazardous wastes (PCA-3)
3300 Mainway (Southwest adjacent)	**Verns Metal Stamping Inc**., is listed in Scott's Directory, with the following operations: "Metal stampings; fabricated metal products". **Jones Tool & Machine Co. Ltd.** is listed in Scott's Directory, with the following description of operations: "Special dies and tools, die sets, jogs and fixtures and industrial molds; industrial and commercial machinery and equipment". **Swissline Industries Ltd**. was listed as waste generator of petroleum distillates from 1992 to 1998.	*GEN, SCT*	34 – Metal Fabrication (PCA-4A) Not listed – Generator of hazardous wastes (PCA-4B)
1140 Blair Road (45 m southeast)	**Jones Neon Displays Ltd**., was listed as a waste generator for paint/pigment/coating residues from 1997 to 2017. And is listed in Scott's Directory, with the following description of operations: "Sign manufacturing". A spill incident associated with this address included a 10 L spill of PCB oil to soil in 2001 due to a rotten hydro pole breaking. Environmental impact was deemed possible.	*GEN, SPL*	Not listed – Spill incident (PCA-5)

Location & Proximity to Site	Summary	Database	Associated PCA
3388 Mainway (30 m north)	**Thomas Wire Die Limited** was listed as a waste generator of aromatic solvents and emulsified oils from 1986 to 1998. **Canfanco Inc.** was listed as a waste generator of alkaline wastes-heavy metals, paint/pigment/coating residues, aromatic solvent, waste oils & lubricant and organic laboratory chemicals from 2002 to 2004 and is listed in Scott's Directory, with the following operations: "Stamping and all other machinery manufacturing". **Canadian Fanner Co. Ltd**. is listed in Scott's Directory, with the following operations: "Metal stamping; industrial and commercial machinery and equipment".	*GEN, SCT*	Not listed – Generator of hazardous wastes (PCA-6A) 34 – Metal Fabrication (PCA-6B)
3390 Mainway (30 m north)	**Chem Systems Inc.** was listed as a waste generator of petroleum distillates from 2002 to 2003. **Hayward Gordon Ltd.** was listed as a waste generator of petroleum distillates, paint/pigment/coating residues, inorganic/organic laboratory chemicals, waste compressed gases, polymeric resin, waste oils and lubricants from 2004 to 2006. Listed in Scott's Directory, with the following operations: "Material handling equipment manufacturing, all other general-purpose machinery".	*GEN*	Not listed – Generator of hazardous wastes (PCA-7)
3400 Landmark Road (30 m east)	**Airmax Compressor Services Ltd. (Units 9 & 10)** was registered as a waste generator of alkaline wastes, heavy metals, waste oils & lubricants, acid wastes, petroleum distillates from 2007 to 2016. **L&A Diecrafts Ltd. (Units 5-10)** was registered as a waste generator of waste oils & lubricants in 2005 and is listed in Scott's Directory, with the following operations: "Die-cut paper and paperboard and cardboard; signs and advertising specialties; sign manufacturing". **Febau Canada (Units 3,4,5 and 6)** was registered as a waste generator of inert inorganic wastes in 2007. **Ascona Management & Consulting Inc.** was registered as a waste generator of paint/pigment/coating residues in 2009. **Canadian Country Candles** was listed in Scott's Directory with the following operations: "Pressed and blown glasses and glassware; pottery products; fabricated metal products; silverware, plated ware and stainless steelware; glass manufacturing".	*GEN, SCT*	Not listed – Generator of hazardous wastes (PCA-8)

Location & Proximity to Site	Summary	Database	Associated PCA
1171 Pioneer Road Southwest adjacent	**Automotive Manager Bell Canada** was listed as having an expired private fuel outlet (Self-Serve) and piping. Expire year is 1990. The capacity of the tank was 25,000 L. **Bell Canada** was listed as a waste generator of various wastes including acid-waste- heavy metals, alkaline wastes, heavy metals, oil skimmings and sludges, aliphatic solvent, petroleum distillates, waste compressed gases, waste oils and lubricants, paint/pigments/coating residues, neutralized wastes- heavy metals, pathological wastes, organic/inorganic laboratory chemicals from 1988 to 2017.	*EXP, PRT, GEN*	28- Gasoline and Associate Products Storage in Fixed Tank (PCA-9A) Not listed – Generator of hazardous wastes (PCA-9B)
1153 Pioneer Road South adjacent	**Canadian Hazmat & Decon Services Inc.** was approved for an ECA for a Waste Management System. **BCG Precision Grinding and Honing Inc.** was listed as a waste generator of waste oils and lubricants from 2013 to 2017. **Mill Pack Industrial Maintenance Inc.** was listed as a waste generator of waste oils and lubricants from 2012 to 2017. **Burlington Centreless Grinding** was listed as a waste generator of waste oils and lubricants from 2001 to 2012 and listed in Scott's Directory, with the following operations: "Industrial and commercial machinery and equipment; coating, engraving, heat treating and allied activities". **K.C Graphics** was listed as a waste generator of petroleum distillates from 1989 to 2001 and was listed in Scott's Directory, as a textile and fabric finishing manufacturing business. **931344 Ontario Inc.** was listed as a waste generator of petroleum distillates and paint/pigment/coating residues from 2002 to 2004. **Canadian Induction Processing Inc.** was listed as a waste generator of oil skimming and sludges and emulsified oils from 1986 to 2001 and listed in Scott's Directory, with the following operations: "Coating, engraving, heat treating and allied activates". **Machinery Repair Technologies** was listed as a waste generator of petroleum distillates and waste oils and lubricants from 1997 to 2003. **Brant Custom Grinding Limited** was listed in Scott's Directory, with the following operations: "Coating, engraving, heat treatment and allied activities; machine shops; other plate work and fabricated structural product manufacturing".	*ECA, GEN, SCT*	33 – Metal Treatment, Coating, Plating and Finishing (PCA-10A) 34 – Metal Fabrication (PCA-10B) 54 – Textile Manufacturing and Processing (PCA-10C) Not listed – Generator of hazardous wastes (PCA-10D)

Location & Proximity to Site	Summary	Database	Associated PCA
3312 Mainway Northwest adjacent	**Weigh-Matic Systems Inc.** was listed in Scott's Directory, with the following operations: "Cutting Tools & Machinists' Precision Measuring Devices; packaging machinery". **Carlisle Technology Inc.** was listed in Scott's Directory, with the following operations: "Computer and peripheral equipment, semiconductor and other electronic component manufacturing". **Integrity Worldwide Inc.** was listed in Scott's Directory, with the following operations: "Ornamental and architectural metal product manufacturing".	*SCT*	34 – Metal Fabrication (PCA-11A) 19 – Electronic and Computer Equipment Manufacturing (PCA-11B)
3330 – 3344 Mainway West adjacent	**Loomis Courier Service** (3330 Mainway) was listed as a waste generator of paint/pigment/coating residues, inorganic/organic laboratory chemicals, halogenated pesticides and non-halogenated pesticides from 1996 to 1999. **Hamilton Digital Designs Ltd.** was listed in Scott's Directory, with the following operations: "Radio and television broadcasting and wireless communication equipment manufacturing; measuring, medical and controlling devices manufacturing; sign manufacturing". **1187188 Ontario Ltd.** (3344 Mainway) was listed as a waste generator of pathological wastes from 2010 to 2014.	*GEN, SCT*	Not listed – Generator of hazardous wastes (PCA-12A) 19 – Electronic and Computer Equipment Manufacturing (PCA-12B)
3317 – 3339 Mainway 120 m northwest	**Antel Optronics Inc.** was listed as a waste generator from 1986 to 1994, however no additional details were provided. **Modular Controls Limited** was listed as a waste generator of petroleum distillates, waste oils and lubricants and emulsified oils from 1986 to 1998. **Gates Air Systems Ltd.** was listed as a waste generator of waste oils and lubricants from 1993 to 1998. **Organizers Plus Modular Controls Limited** was listed in Scott's Directory, with the following operations: "Wood kitchen cabinet and counter top manufacturing and other millwork". **Halton Sheet Metal Ltd.** was listed in Scott's Directory, with the following operations: "Industrial and commercial fan and blower and air purification equipment manufacturing and coating, engraving, heat treating and allied activities". **Metal Equipment Services Ltd.** was listed as a waste generator of aromatic solvents from 1997 to 2001 and listed under Scott's Directory with the following operation: "Wood office and store fixtures, partitions, shelving and lockers manufacturing".	*GEN, SCT, SPL*	Not listed – Generator of hazardous wastes (PCA-13A) 33 – Metal Treatment, Coating, Plating and Finishing (PCA-13B) 34 – Metal Fabrication (PCA-13C) 47 – Rubber Manufacturing and Processing (PCA-13D) 43 – Plastics (including Fibreglass) Manufacturing and Processing (PCA-13E) Not listed – Spill incident (PCA-13F)

Location & Proximity to Site	Summary	Database	Associated PCA
3317 – 3339 Mainway 120 m northwest	**JC CNC** was listed as a waste generator of oil skimming and sludges from 1997 to 2001. The business was listed as a waste and listed under Scott's Directory with the following operations: "Machine Shop, mining and oil and gas field machinery manufacturing and railroad rolling stock manufacturing". **Accurate Concrete Cutting** was listed as a waste generator of waste crankcase oils and lubricants from 2016 to 2017. **Allen Industrial Rubber Prod** was listed in Scott's Directory, with the following description of operations: "Gaskets, packing and sealing devices; fabricated rubber products; resin and synthetic rubber manufacturing; other rubber product manufacturing and other miscellaneous manufacturing". **Alkano Grinding and Stamping Company** was listed as a waste generator of waste oils and lubricants from 2012 to 2017. **Quality Cylinder Service** was listed as a waste generator of waste oils and lubricants from 1986 to 1989. **Quality Hydraulic Service** was listed as a waste generator of petroleum distillates and waste oils and lubricants from 1990 to 1998. **Welcan Machine Shop** was listed as a waste generator of waste oils and lubricants and emulsified oils from 1996 to 2001. This business was listed in Scott's Directory, with the following description of operations: "Industrial and commercial machinery and equipment and steel foundries, not elsewhere classified". **Airon HVAC Service Ltd** was listed as a waste generator of aliphatic solvents and waste oils and lubricants for 2006.	*GEN, SCT, SPL*	Not listed – Generator of hazardous wastes (PCA-13A) 33 – Metal Treatment, Coating, Plating and Finishing (PCA-13B) 34 – Metal Fabrication (PCA-13C) 47 – Rubber Manufacturing and Processing (PCA-13D) 43 – Plastics (including Fibreglass) Manufacturing and Processing (PCA-13E) Not listed – Spill incident (PCA-13F)

Location & Proximity to Site	Summary	Database	Associated PCA
3317 – 3339 Mainway 120 m northwest	**Eagle-Quip Inc.** was listed as a waste generator of petroleum distillates and waste oils and lubricants from 1986 to 1988. **Fairway Industrial** was listed as a waste generator of petroleum distillates and waste oils and lubricants from 1989 to 2001. **Halton Metal Outlet Ltd.** was listed in Scott's Directory with the following description of operations: "Coating, engraving, heat treating and allied activities; iron and steel mills and ferro-alloy manufacturing". **Travis Industrial Maintenance** was listed as a waste generator of petroleum distillates and waste oils and lubricants from 1995 to 2004. **D.F Electronics Inc.** was listed in Scott's Directory, with the following description of operation: "Special industry machinery, not elsewhere classified". **OnDrive Inc.** was listed in Scott's Directory, with the following description of operations: "Measuring, medical, controlling devices manufacturing; industrial machinery, equipment and supplies wholesaler-distributors". **Firecraft Kilns Sales and Service** was listed in Scott's Directory, with the following description of operation: "All other industrial machinery manufacturing". **Helec Insulation Ltd.** was listed in Scott's Directory, with the following description of operations: "Plastic products, not elsewhere classified and mineral wool". **Feed Rite Automatic Inc.** was listed in Scott's Directory with the following description operations: "Material handling equipment manufacturing; other plate work and fabricated structural product manufacturing; cutlery and hand tool manufacturing; all other general-purpose machinery manufacturing; rubber and plastic hose and belting manufacturing". A spill incident associated with this property (3255 Mainway) included 27 L of Citrotech to asphalt. Environmental impact was not anticipated.	*GEN, SCT, SPL*	Not listed – Generator of hazardous wastes (PCA-13A) 33 – Metal Treatment, Coating, Plating and Finishing (PCA-13B) 34 – Metal Fabrication (PCA-13C) 47 – Rubber Manufacturing and Processing (PCA-13D) 43 – Plastics (including Fibreglass) Manufacturing and Processing (PCA-13E) Not listed – Spill incident (PCA-13F)

Location & Proximity to Site	Summary	Database	Associated PCA
3415 Landmark Road (95 m northeast)	**Euroline Custom Cabinets** was listed as a waste generator of paint/pigment/coating residues from 1995 to 2001 and in Scott's Directory, with the following operations: "Wood household furniture, window and door manufacturing and millwork". **Cor-Mag Inc.** was listed as a waste generator of waste oils and lubricants from 1992 to 1998. **IndustAutoCo Inc.** was listed as a waste generator of PCBs from 2014 to 2015.	*GEN*	Not listed – Generator of hazardous wastes (PCA-14A)
1101 Blair Road (90 m east)	**Shell Canada Products** was listed as a waste generator of waste oils/sludges (petroleum based), waste crankcase oils and lubricants as of December 2017. Waste oils and lubricants, alkaline wastes-other metals and oil skimming and sludges from 2011 to 2016. **Quaker State Inc.** was listed as a waste generator of oil skimmings and sludges, waste oils and lubricants and aromatic solvents from 1986 to 2001. **Pennzoil Quaker State Canada Company** was listed as a waste generator of oil skimmings and sludges, waste oils and lubricants and aromatic solvents from 2002 to 2010; emulsified oils from 2002 to 2008. This business was also in Scott's Directory as a wholesale distributor of new motor vehicle parts and accessories, chemical and allied product and petroleum products and a wholesale distributor of motor vehicle seating and interior trim and petroleum and coal products manufacturing. A spill incident in 2002 associated with this property included oil sheen on the lot and catchbasin due to watermain failure. The spill was contained, although environmental impact was deemed possible.	*GEN, SCT, SPL*	Not listed – Generator of hazardous wastes (PCA-15A) Not listed – Spill incident (PCA-15B)
1121 Pioneer (125 m south)	**Hunter Drums Limited** was registered in the Ontario PCB Storage Database. And was listed as a waste generator of acid wastes-heavy metals, paint/pigment/coating residues, aromatic solvents, aliphatic solvents, petroleum distillates and waste oil and lubricants from 1986 to 1989. Listed in Scott's Directory with the following operations: "Metal shipping barrels, drums, kegs and pails; all other plastic product manufacturing; other metal container manufacturing and coating, engraving, heat treating and allied activities".	*OPCB, NPCB, GEN, SCT*	Not listed – PCB Storage Site (PCA-16A) Not listed – Generator of hazardous wastes (PCA-16B) 33 – Metal Treatment, Coating, Plating and Finishing (PCA-16C) 43 – Plastic (including Fibreglass) Manufacturing and Processing (PCA-16D)

Location & Proximity to Site	Summary	Database	Associated PCA
1121 Pioneer (125 m south)	**Mauser Canada Ltd.** was listed as a waste generator of alkaline waste- other/heavy metals, oil skimmings and sludges, aliphatic solvents, detergents/soaps, aromatic solvents, waste oils and lubricants, inorganic laboratory chemicals and paint/pigment/coating residues from 2005 to 2017. Listed in Scott's Directory with the following operations: "All other plastic product manufacturing and other metal container manufacturing". **Russel-Stanley** was listed as a waste generator of paint/pigment/coating residues, aromatic solvents, waste oils and lubricants from 1997 to 2004 and acid wastes-heavy metals, alkaline wastes-other metals, aliphatic solvents, PCBs, oil skimmings and sludges and petroleum distillates from 1997 to 2001.	*OPCB, NPCB, GEN, SCT*	Not listed – PCB Storage Site (PCA-16A) Not listed – Generator of hazardous wastes (PCA-16B) 33 – Metal Treatment, Coating, Plating and Finishing (PCA-16C) 43 – Plastic (including Fibreglass) Manufacturing and Processing (PCA-16D)
3410 Mainway (100 m north)	**Reiger Printing Ink Co Ltd**. was registered in the Ontario PCB Storage Database, any PCBs stored on the property were removed as of 1996. The company was also listed as a waste generator of paint/pigment/coating residues from 1986 to 2008 and petroleum distillates, polymeric resins, PCB's, waste oils and lubricants, inorganic pigment wastes, graphic art wastes from 1992 to 2008. This business was in Scott's Directory with the following operations: "Printing Ink Manufacturing and other printing". **2210263 Ontario Inc** was registered as a RSC property (2010) and listed as a waste generator of waste oils and lubricants from 2009 to 2010. The intended property use was community. No soil was remediated within 3 m of the property boundary. **Activityplex Burlington Corp**. was listed as a waste generator of inert organic waste as of December 2017. **MIP Group Inc**. was listed as a waste generator of inert organic waste in 2016.	*OPCB, NPCB, GEN, RSC, REC*	Not listed – PCB Storage Site (PCA-17A) 31 – Ink Manufacturing, Processing and Bulk Storage (PCA-17B) Not listed – Generator of hazardous wastes (PCA-17C)
3264 Mainway (105 m west)	**FibreCast Inc**. was listed as a waste generator of waste oils and lubricants and PCBs in 2016 and waste crankcase oils and lubricants in 2017. The business was also listed under Scott's Directory, with the following operations: "Engineering services; clay building material and refractory manufacturing; other specialty line building supplies wholesaler-distributors; all other textile product mills; urethane and other foam products (except Polystyrene)	*GEN, SCT*	Not listed – Generator of hazardous wastes (PCA-18A) 26 – Foam and Expanded Foam Manufacturing and Processing (PCA-18B) 57 – Vehicle and Associated Parts Manufacturing (PCA-18C)

Location & Proximity to Site	Summary	Database	Associated PCA
3264 Mainway (105 m west)	manufacturing; polystyrene foam product manufacturing; all other non-metallic mineral product manufacturing; plumbing, heating and air conditioning equipment and supplies wholesaler distributors". **AISCO Systems Limited** was listed as a waste generator of paint/pigment/coating residues in 1990 and paint/pigment/coating residues, inorganic laboratory chemicals, petroleum distillated, polymeric resins, oil skimming and sludges and alkaline wastes-other metals from 1992 to 2001. The business was also listed as a waste generator from 1986 to 1989, however no additional details were provided. The business was listed under Scott's Directory, with the following operations: "Industrial and commercial machinery and equipment, service/special industry machinery and industrial truck, tractors, trailers and stackers".	*GEN, SCT*	Not listed – Generator of hazardous wastes (PCA-18A) 26 – Foam and Expanded Foam Manufacturing and Processing (PCA-18B) 57 – Vehicle and Associated Parts Manufacturing (PCA-18C)
1149 Pioneer Road (50 m south)	**Rehau Industries Inc.** was listed as a waste generator of aliphatic solvent, petroleum distillates, polymeric resins and waste oils and lubricants from 1986 to 2001 and listed under Scott's Directory with the following operations: "Lumber, plywood and millwork wholesaler-distributor; plumbing, heating and air conditioning equipment and supplies wholesaler-distributor; chemical (except agricultural) and allied product wholesaler-distributor; metal service centre; other new motor vehicle parts and accessories wholesaler-distributors; general-line building supplies wholesaler-distributors". A spill incident in 1991 associated with this property included 1000 L of plasticizer spilled to the ditch due to equipment failure relating to a valve/fitting leak. The receiving medium was land and environmental impact was deemed possible.	*GEN, SCT, SPL*	Not listed – Generator of hazardous wastes (PCA-19A) Not listed – Spill incident (PCA-19B)

Location & Proximity to Site	Summary	Database	Associated PCA
1100 Blair Road (115 m southeast)	**Quadra Chemicals Ltd.** was listed under the Chemical Registry which provides a listing of facilities that manufacture or distribute chemicals and listed under the Canadian Pulp and Paper Directory. This business was also listed as a waste generator of inorganic/organic laboratory chemicals from 1992 to 2012; paint/pigment/coating residues, alkaline wastes- other metals, PCBs and other specified inorganics from 1999 to 2012 and polymeric resins in 2012. Organic acids, paint/pigment/coating residues, aliphatic solvent, organic/inorganic laboratory chemicals, heavy fuels, detergents/soaps, PCBs, waste oils and lubricants, oil skimmings and sludges, aromatic solvents, amines, petroleum distillates, polymeric resins, other specified inorganics, graphic art wastes and alkaline wastes- other metals were listed for 2013 to 2017. **Acco Canadian Material Handling** was listed as a waste generator of paint/pigment/coating residues from 1986 to 1997 and alkaline wastes-other metals and waste oils and lubricants from 1990 to 1998. A spill incident in 1993 associated with this property included 15 kilograms of sodium dichromate dihydrate to the driveway due to weld/seam failure. The receiving medium was land and environmental impact was not anticipated.	*CHEM, PAP, GEN, SPL*	8 – Chemical Manufacturing, Processing and Bulk Storage (PCA-20A) Not listed – Generator of hazardous wastes (PCA-20B) Not listed – Spill incident (PCA-20C)
3285 - 3295 Mainway (115 m west	**Brown Falcon Machine & Tool** (3295 Mainway) was listed as a waste generator of petroleum distillates from 1992 to 1998. **Tymatic Controls (Div. of Tyrrell Air Controls Ltd.)** (3295 Mainway) was listed under Scott's Directory with the following operations: "Measuring, medical and controlling devices manufacturing; switchgear and switchboard and relay and industrial control apparatus manufacturing; electrical wiring and construction supplies wholesaler-distributors and industrial machinery, equipment and supplies wholesaler-distributors". **Erodall Ltd.** (3295 Mainway) was listed under Scott's Directory with the following operation: "Machine shops".	*GEN, SCT*	31 – Ink Manufacturing, Processing and Bulk Storage (PCA-21A) 34 – Metal Fabrication (PCA-21B) Not listed – Generator of hazardous wastes (PCA-21C)

Location & Proximity to Site	Summary	Database	Associated PCA
3285 - 3295 Mainway (115 m west)	**Rainbow Ceramics** (3295 Mainway) was listed under Scott's Directory with the following operations: "Pottery, ceramics and plumbing fixture manufacturing". **Printing House Ltd.** (3285 Mainway) was listed as a waste generator of oil skimmings and sludges, paint/pigment/coating residues, graphic art wastes and photoprocessing wastes from 1999. to 2017. Photoprocessing wastes was listed from 1994 to 1998. This business was also listed under Scott's Directory with the following operations: "Digital printing, quick printing and other printing". **Cooper Fluid Power Inc.** (3285 Mainway) was listed as a waste generator of aliphatic solvents, petroleum distillates, oil skimming and sludges and waste oils and lubricants from 1996 to 2001. **Cotswold Precision Company Ltd.** (3285 Mainway) was listed as a waste generator of waste oils and lubricants and emulsified oils from 1994 to 2001. This business was listed under Scott's Directory with the following operations: "Fabricated metal products; overhead travelling cranes, hoist and monorail systems; industrial and commercial machinery and equipment; machine shops; all other miscellaneous fabricated product manufacturing; material handling equipment manufacturing". **Precision Metalworks Inc.** (3285 Mainway) was listed as a waste generator of oil skimming and sludges and waste oils and lubricants from 2007 to 2009. **Sympro CNC Machining and Manufacturing** (3285 Mainway) was listed as a waste generator from 2003 to 2004, however no additional details were provided. **Precision Print** (3285 Mainway) was listed as a waste generator of paint/pigment/coating residues in 2010. This business was listed under Scott's Directory with the following operations: "Digital printing, quick printing and other printing". **Versa-Hoe Equipment Corp.** This business was listed under Scott's Directory with the following operation: "Special industry machinery, not elsewhere classified".	*GEN, SCT*	31 – Ink Manufacturing, Processing and Bulk Storage (PCA-21A) 34 – Metal Fabrication (PCA-21B) Not listed – Generator of hazardous wastes (PCA-21C)

Location & Proximity to Site	Summary	Database	Associated PCA
3424 Landmark Road (115 m northeast)	**Humpty Dumpty Foods Ltd.** was listed under TSSA Expired Facilities as having a private (self-serve) fuel outlet, expiring in 1993.	*EXP, PRT, SCT*	28- Gasoline and Associate Products Storage in Fixed Tank (PCA-22)
3385 Mainway (130 m northwest)	**Toromont Industries Ltd.** was listed as a waste generator of light fuels, waste crankcase and lubricants and petroleum distillates as of December 2017. **Kingsbury Machine Toll (CDA) Ltd.** was listed as a waste generator of paint/pigment/coating residues, aromatic solvents, petroleum distillates, oil skimming and sludges, waste oils and lubricants and emulsified oils from 1986 to 2004. The business was listed under Scott's Directory with the following operations: "Measuring, medical and controlling devices manufacturing, switchgear and switchboard and relay and industrial control apparatus manufacturing, other metalworking machinery manufacturing and all other general-purpose machinery manufacturing".	*GEN, SCT*	Not listed – Generator of hazardous wastes (PCA-23A) 34 – Metal Fabrication (PCA-23B)
3435 Landmark Road (160 m northeast)	**Laker Energy Products Ltd**. was listed as a waste generator of emulsified oils, inorganic laboratory chemical, other specified inorganics and acid waste- other metals from 2012 to 2016. **Gennum** was listed as a waste generator of aromatic solvent, aliphatic solvents, halogenated solvents, waste oils and lubricants, organic laboratory chemicals, acid waste-heavy metals, alkaline wastes-heavy metals and other specified inorganics from 1988 to 2004. **Linerar Technology Inc.** was listed as a waste generator of aromatic solvents, halogenated solvent, waste oils and lubricants from 1986 to 1987.	*GEN*	Not listed – Generator of hazardous wastes (PCA-24)
3365 Mainway (130 m northwest)	**Ecosynthetix Inc.** was listed as a waste generator for inorganic/organic laboratory chemicals, paint/pigment/coating residues, other polymeric wastes, waste oils and lubricants, waste compressed gases from 2012 to 2017.	*GEN, SCT*	Not listed – Generator of hazardous wastes (PCA-25)

Location & Proximity to Site	Summary	Database	Associated PCA
3426 Mainway (175 m north)	**Bosch Rexroth Canada Corp** was listed as a waste generator for acid waste-heavy metals, organic laboratory chemicals, alkaline wastes-heavy metals and aromatic solvents from 2010 to 2017 and for waste oils and lubricants and petroleum distillates, oil skimming and sludges and amines from 2001 to 2017. This business was also listed under the Canadian Pulp and Paper Directory and listed under Scott's Directory with the following operations: "Material handling Equipment Manufacturing; industrial machinery, equipment and supplies wholesaler-distributions; switchgear and switchboard and relay and industrial control apparatus manufacturing; computer, computer peripheral and pre-packing software wholesaler-distributors; measures, medical and controlling devices manufacturing; other engine and power transmission equipment manufacturing, metal valve manufacturing, motor and generator manufacturing; all other general-purpose machinery manufacturing." **Kernic Equipment** was listed as a waste generator of aromatic solvents and waste oils and lubricants from 1992 to 1998. **Basic Technologies** was listed as a waste generator of petroleum distillates and emulsified soils from 1997 to 2000.	*GEN, PAP, SCT*	Not listed – Generator of hazardous wastes (PCA-26A)
3291 Mainway (215 m west)	**Nixon Integrated Machining Design Ltd.** was listed as a waste generator of emulsified oils, waste oils and lubricants and petroleum distillates from 1996 to 2017 and was listed under Scott's Directory as a machine shop. **Brown Flacon Machine and Tool** was listed as a waste generator of petroleum distillates from 1993 to 2001 and was listed in Scott's Directory with the following operations: "Special dies and told, die sets, jigs and fixtures and industrial moulds; industrial and commercial machinery and equipment, not elsewhere classified". **McKellar Machine Products Ltd.** was listed in Scott's Directory with the following operations: "Screw machine products".	*GEN, SCT*	Not listed – Generator of hazardous wastes (PCA-27A) 34 – Metal Fabrication (PCA-27B)

Location & Proximity to Site	Summary	Database	Associated PCA
3450 Landmark Road (215 m northeast)	**Bramkal Contractors Inc.** was listed as a waste generator of paint/pigment/coating residues, reactive anion wastes, aromatic solvents, organic laboratory chemicals and emulsified oils in 2016 and as a waste generator of waste oils and lubricants and petroleum distillates from 2006 to 2008. **Burlington Cutting and Finishing Inc.** was listed as a waste generator of emulsified oils from 2007 to 2009 and was listed in Scott's Directory with the following operation: "Stamping". **A-1 Asphalt Maintenance Ltd.** was listed as a waste generator of paint/pigment/coating residues, petroleum distillates, heavy fuels and waste oils and lubricants from 2002 to 2005. **Tach West Technologies Ltd.** was listed in Scott's Directory with the following operations: "Semiconductor and other electronic component manufacturing; measuring, medical and controlling devices manufacturing; professional machinery, equipment and supplies wholesaler-distributors and other new motor vehicle parts and accessories wholesaler-distributors".	*GEN, SCT*	Not listed – Generator of hazardous wastes (PCA-28A) 19 – Electronic and Computer Equipment Manufacturing (PCA-28B)
3455 Landmark Road (215 m northeast)	**Comstock Canada Ltd.** was listed as a waste generator of petroleum distillates, inorganic/organic laboratory chemicals, waste oils and lubricants, alkaline wastes- other metals from 1999 to 2014 and acid wastes, paint/pigment/coating residues, halogenated solvents from 1995 to 2008. This business was also listed under the Canadian Pulp and Paper Directory as the head office.	*GEN, PAP*	Not listed – Generator of hazardous wastes (PCA-29)
3419 Mainway (235 m north)	A spill incident in 2000 associated with this property included 568 L of diesel fuel to the parking lot and drain/storm sewer due to a valve/fitting leak or failure to moving equipment. The receiving medium was land/water and environmental impact was deemed possible.	*SPL*	Not listed – Spill incident (PCA-30)

Location & Proximity to Site	Summary	Database	Associated PCA
3267 Mainway (150 m west)	**Revstone Industries Burlington Inc**. was listed as a waste generator of petroleum distillates, aliphatic solvents, acid-wastes-heavy metals, emulsified oils, waste oils and lubricants, oil skimmings and sludges, alkaline wastes-other metals from 2009 to 2012. **National Rigging and Transportation Ltd**. was listed as a waste generator in 2012, however no additional details were provided. **Burlington Technologies** was listed as a waste generator for waste oils and lubricants, emulsified oils, other specified inorganics, aliphatic solvent, petroleum distillates and oil skimmings and sludges from 1992 to 2008. **Burlington Die Casting** was listed as a waste generator of waste oils and lubricants and emulsified oils from 1986 to 1990 and was listed in Scott's Directory with the following operations: "Non-ferrous foundries (except die-casting); industrial mould manufacturing; other metalworking machinery manufacturing; automobile and light duty motor vehicle manufacturing; heavy-duty truck manufacturing". A spill incident in 2004 associated with this property included an unknown quantity of cutting oil (petroleum based, not specified) to a creek. The receiving medium was water and environmental impact was not noted in the report. A spill incident in 2005 associated with this property included approximately 20 L of hydraulic oil to an on-Site catch basin. The receiving medium was water and environmental impact was deemed possible.	*GEN, SCT, SPL*	Not listed – Generator of hazardous wastes (PCA-31A) 57 – Vehicle and Associated Part Manufacturing (PCA-31B) Not listed – Spill incident (PCA-31C)

Location & Proximity to Site	Summary	Database	Associated PCA
1232 Dillon Road (220 m northwest)	**JC CNC Works Inc.** was listed as a waste generator of emulsified oils and waste oils/sludges (petroleum based) from 2011 to 2017 and was listed in Scott's Directory with the following description operations: "Railroad rolling stock manufacturing; mining and oil and gas field machinery manufacturing; coating, engraving, heat treating and allied activities; other plate work and fabricated structural product manufacturing". **X-Pert Metal Finishing Ltd.** was listed as a waste generator of acid waste-heavy metals, alkaline wastes- heavy metals and oil skimming and sludges from 1986 to 1998. **Hahn and Sons Ltd.** was listed as a waste generator of waste oil and lubricants from 2013 to 2017. X-Pert Metals reported a spill incident in 1991 associated with a flood on site that leaked an unknown quantity of chemicals into a sewer. The receiving medium was watercourse or lake and environmental impact was deemed possible.	*GEN, SCT, SPL*	Not listed – Generator of hazardous wastes (PCA-33A) 33 – Metal Treatment, Coating, Plating and Processing (PCA- 33B) 34 – Metal Fabrication (PCA-33C) Not listed – Spill incident (PCA-33D)

3.2.2 Municipal Records

3.2.2.1 Municipal Directories

EXP retained LGI Copy Services Canada to review the available City of Burlington Directories between 1957 and 2011 in five and ten-year increments in order to identify the occupancy history of the Site and adjacent properties for PCAs. A copy of the city directories is located in Appendix F.

A review of the city directories for the Site and surrounding properties indicated the following pertinent details:

- The Site has been occupied by various commercial/light industrial establishments since approximately 1975.
- From reviewed city directories, former tenants have included: Town & Country Booking Service Ltd., Deer John Ltd., Columbian Chemicals Canada Ltd., White Motor Credit Corp. of Canada, Mayfair Travel Services, Chef Cafeteria, Fife Controls Canada Ltd., Hunter JD Packaging, Gibbs Wire & Steel Company Ltd., Eaman Riggs Insulation Ltd. (all circa 1984), Town & Country Booking Service Ltd., Loomis Courier Service, Adam Irrigation Systems, CSR Business Systems Inc., Robinson, Wurth Paul Ltd., Robinson Ogilvy Inc., Jenmar Color Separations Inc., and Wurth Paul Ltd. (all circa 1991), Town & Country Bookkeeping Service Ltd., Loomis Courier Service Ltd., (all circa 1994) and All Tig Ltd., Gowan's Repair & Service, Roofing Depot, Best Cut, Inter Mill Technologies, Creek Mill Meadows Inc., and Linton Roundhouse Warehousing (all circa 1997).
- Of these tenants, from our review of previous environmental reports, Best Cut and Gowan's Repair & Service and Best Cut were identified as having historical operations which may pose a PCA on-

- Site (PCA-1B Metal Fabrication and PCA 1C-52 – Storage, maintenance, fueling and repair of equipment, vehicles and materials used to maintain transportation systems).

Based on the city directory review of the surrounding properties, the following pertinent information was noted:

- The surrounding properties consist of commercial/light industrial establishments since approximately 1970.

Direction	Address	Occupant	Year	Associated PCA
North	1157 Blair Road (approx. 30 m)	Fagersta Secoroc Ltd.	1975 – 2000	Not listed – Generator of hazardous wastes (PCA-3)
	Landmark Road (approx. 100 m)	Cor-Mag Inc.	1980 – 1990	Not listed – Generator of hazardous wastes (PCA-14A)
	3388 Mainway (approx. 30 m north)	Ontario Auto Collision/Aro Motors Car Star	2005	Not listed – Generator of hazardous wastes (PCA-6A) 34 – Metal Fabrication (PCA-6B) 27- Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles (PCA-6C)
		Canfanco Inc.	2000	
		Canadian Fanner Co Ltd.	1975 – 1995	
		Thomas Wire Die Ltd.	1990 – 1995	
	3390 Mainway (approx. 30 m north)	Chem Systems Inc.	2000	Not listed – Generator of hazardous wastes (PCA-7)

The remaining properties within the Phase One study area were not associated with any PCAs or previously listed in Section 3.2.1.

3.2.2.1. *City of Burlington - Municipal Records*

On May 22, 2018, the City of Burlington Official Plan website was searched for information regarding zoning for the Site. The Site and surrounding properties are zoned at 'General Employment'.

3.2.2.2. *City of Burlington – FOI request*

On May 22, 2018, a request for information was submitted to the City of Burlington Freedom of Information (FOI), Protection of Privacy Office for information in their files regarding the Site that pertain to any Environmental Concerns, Orders and Spills.

A response was received on June 8, 2018 and indicated that no records were located. However, the City of Burlington specified that the Halton region may have custody of the certain records and a request for information was transferred to Halton Region on June 5, 2018.

3.2.2.3. *Region of Halton – FOI request*

On May 22, 2018, a request for information was submitted to the Region of Halton Freedom of Information, Protection of Privacy Office for information in their files regarding the Site that pertain to any Environmental Concerns, Orders and Spills.

A response from the Region of Halton, dated July 3, 2018, indicated that the Site is located within an Intake Protection Zone (Source Water Protection Plan). The response also indicated that the building type is Light Industrial/Office Multiple Unit Plaza and that the inventory of retail fuel storage tank databased shows one (1) steel diesel tank installed in 1989. Refer to section 3.2.4 for a discussion on the registered fuel tank.

No other relevant information (i.e. not already documented above) was provided in the Region. A copy of the request and response is included in Appendix F.

3.2.3 Ontario Ministry of the Environment Records

3.2.3.1 Ministry of the Environment and Climate Change (MOECC)

On July 12, 2017, a request for information was submitted to the Ontario Ministry of the Environment and Climate Change (MOECC) Freedom of Information, Protection of Privacy Office for information in their files regarding the Site that pertain to any Environmental Concerns, Orders and Spills.

In a written response dated July 26, 2017 from the MOECC. The response indicated two (2) incident reports and several HWIN generators.

The first incident report was dated March 3, 2013 and included illegal dumping of wastes in a runoff ditch located at the southwest boundary of the Site. Materials dumped included furniture, oil filters, paint cans, debris and some electronics. The garbage was reportedly cleaned up prior to October 2013 and a berm was put in place to prevent illegal dumping.

The second incident report was dated June 21, 2013, occurring at Absolute Custom Steel Fabricating (Unit #2) which included a person spray painting a metal structure half way into the bay door. Debbie Quattrin a Senior Property Manager with Prime Real Estate Group Inc. indicated that the company was not permitted to spray paint. The field personnel for the MOECC did not observe any spray painting upon return to the Site and no follow up was recommended.

Three (3) HWIN generators were also present in the MOECC response which included Royal Lepage State Realty Brokerage, S.E Sales and Service Ltd. and Jenmar Colour Separation Inc. (Refer to Section 3.2.1).

Based on the above information, the potential for the above incidents described in the FOI response to pose an environmental liability towards the Site is considered to be low.

A copy of the request and records are included in Appendix G.

3.2.3.2 Ministry of the Environment Databases

The Ecolog ERIS report summarized in the Federal and Provincial Database Search section of the report included a summary of MOECC databases (see Section 3.2.1). The databases include the following:

MOECC Environmental Bill of Rights (EBR), Brownfields Environmental Site Registry, Hazardous Waste Information Network (HWIN) and Waste Disposal Sites.

3.2.4 Technical Standards and Safety Authority

A request was made to the TSSA by email on July 12, 2017 for information regarding fuel storage The Technical Standards and Safety Authority (TSSA) is the Provincial regulatory agency responsible for overseeing the storage of fuels in Ontario. As such, the TSSA maintains a database (approximately 1987 to present) of all registered fuel storage tanks in Ontario.

A response provided by the TSSA indicated that records existed for the Site, including two expired liquid fuel tanks and one expired private fuel outlet. As such, a detailed report regarding the tanks listed above was ordered from the TSSA and received on August 22, 2017.

The detailed report listed the following pertinent information:

- two (2) expired diesel fuel storage tanks with capacity of 45,460 L, installed in 1989, for Gotfryd Contracting (no address); and
- a private fuel outlet which expired in 1992, also for Gotfryd Contracting at 1160 Blair Road.

A review of the city directories (see Appendix F) indicates that Gotfryd Contracting was a tenant at 1150 Blair Road in 1990. Given the absence of any other records of fuel storage on Site, it is considered likely that the TSSA report mistakenly listed the expired fuel tanks at 1160 Blair Road instead of the correct address of 1150 Blair Road. This aspect is associated with PCA 28- Gasoline and Associated Products Storage in Fixed Tanks (PCA-2A).

In addition to the tanks listed on Site, the property located southwest adjacent to the Site at 1171 Pioneer Road was listed with two (2) expired liquid fuel tanks and one (1) expired private fuel outlet. This aspect is associated with PCA 28- Gasoline and Associated Products Storage in Fixed Tanks (PCA-9A).

A copy of the TSSA request, Site records and detailed report are provided in Appendix G.

3.3 Physical Setting Sources

3.3.1 Aerial Photographs

Aerial photographs were obtained in order to review the development and land use history of the Site, as well as to the land in the immediate vicinity of the Site. The aerial photographs dated 1959, 1978, 2002, and 2015 were obtained for review.

The development and land use history of the Site and adjacent properties as depicted on the reviewed aerial photography is summarized in Table 3.3.1. Copies of the aerial photographs are included in Appendix H.

Table 3.3.1: Aerial Photograph Observations

Aerial Photograph	Details
1959	• The Site consists of agricultural land comprised of an orchard, with no building structures. • The surrounding properties appear to be agricultural land, vacant fields and forested areas. A farm building appears to the southeast.
1978	• The Site is developed with a building similar to that observed during the Site visit. • The surrounding areas are predominantly developed with large light industrial/commercial buildings and residential dwellings are observed to the north. • Remnants of the orchard observed in the 1959 aerial photograph are observed to the north and south of the Site.
2002	• The Site and surrounding areas appear similar in configuration to that observed on the 1978 aerial photograph. • The property south-adjacent to the Site has been developed. • A small portion of the orchard observed in the 1959 is observed north of the Site (3365 Mainway).
2015	• The Site and surrounding areas appear similar in configuration to that observed on the 2002 aerial photograph and the Site and adjacent properties contain structures similar in configuration to the structures observed at the time of the Site visit. • The property at 3365 Mainway has been developed with a warehouse-type building.

Based on the review of the aerial photography, the following PCAs were identified:

- A review of the earlier aerial photographs indicated that the Site consisted of agricultural land comprised of an orchard since at least 1959. This aspect is associated with PCA 40-Pesticides (including Herbicides, Fungicides and Anti-Fouling Agents) Manufacturing, Processing, Bulk Storage and Large-Scale Applications (PCA 1).

3.3.2 Topography, Hydrology and Geology

The following physiographic, geological and soil maps were reviewed on July 12, 2017:

- "Toporama"; Natural Resources Canada. Scale 1:17,500. 2008.
- Quaternary Geology of Ontario - geology_ll.shp [computer file], Ontario: Ontario Geological Survey, 2000.
- Bedrock Geology of Ontario - geology_ll.shp [computer file], Ontario: Ontario Geological Survey, 2000.
- Physiography of Southern Ontario - geology_ll.shp [computer file], Ontario: Ontario Geological Survey, 2007.

Based on the review of the above maps, the following information was obtained:

- The Site is generally flat and is approximately 125 m above sea level.

- Lake Ontario is situated approximately 3.8 kilometres (km) southeast of the Site.
- Based on the information provided on the topographic map, regional groundwater is anticipated to be in a southerly or southeasterly towards Lake Ontario.
- The Site is located in the physiographic region described as Till Plains (Drumlinized).
- The Site and surrounding areas are dominated by Halton Till deposits of the Late Wisconsinan. Deposits predominately consist of clay and silt till.
- The bedrock in the general area forms part of a group belonging to the Queenston formation, consisting of shale, limestone, dolostone and siltstone.

3.3.3 Fill Materials

Fill material is typically brought to a property as a base for buildings and pavement areas. Fill can also be used to re-grade a property and to backfill excavations, such as locations of former USTs.

Based on a review of historical records, a significant volume of fill material is not expected.

3.3.4 Water Bodies and Areas of Natural Significance

Based on the review of available resources from the Ministry of Natural Resources and Forestry and MOECC, no areas of natural significance were identified within the Phase One ESA study area.

3.3.5 Well Records

3.3.5.1 *Water Wells*

A search of the water well database was completed on July 4, 2018.

A total of 59 records were located within the Phase One ESA study area. No well records were identified on the Site. The well records on the surrounding properties indicated that the wells were test holes, monitoring/observation wells and or unknown use. No potable water wells were identified within the Phase One ESA study area.

3.3.5.2 *Oil, Gas, and Salt Wells*

A search of the Oil, Gas & Salt Resources Library (2014) website was completed to identify oil, gas and salt wells within the vicinity of the Site on May 23, 2018. The search of the website indicated there was no oil, gas or salt wells at the Site or within the Phase One ESA study area.

3.4 Site Operating Records

In general, a request is usually made to the property representative for copies of any operating records pertaining to the environmental conditions at the Site. Records would include: regulatory permits; Material Safety Data Sheets (MSDS) for all chemicals that were handled on-Site; underground utility drawings; inventories of chemicals, chemical usage, and chemical storage areas; inventory of aboveground storage tanks (ASTs) and underground storage tanks (USTs); environmental monitoring data; correspondence pertaining to an order or request by the MOE or TSSA; waste management records; process, production,

and maintenance documents; records of spills and records of discharges of chemicals; emergency response and contingency plans, including spill prevention and contingency plans; environmental audit reports; and site plans of the facility showing areas of production and manufacturing

No records were reviewed at the time of the Site visit.

4. Interviews

Interviews were conducted by EXP staff with the individuals identified to be the most knowledgeable with respect to both the current and historical Site uses. The interviews were conducted during the Site reconnaissance in order to obtain information to assist in identifying details of potentially contaminating activities, potential contaminant pathways in, on, or below the Site, and areas of potential environmental concern. Any information provided during the interviews is presented alongside information from the Site reconnaissance in Section 5.

During the completion of this Phase One ESA, the following individuals were interviewed:

1. Mr. Dennis Allison, manager of the property for four (4) years, was interviewed during the Site visit on July 18, 2017.

2. Several representatives of the Site tenants.

5. Site Reconnaissance

5.1 General Requirements

The Phase One ESA Site reconnaissance was conducted on July 18, 2017 by Ms. Kelsey Proks under the supervision of Mr. Erik Enders, a QP as defined by O.Reg. 153/04, as amended.

The Site and the adjoining properties were observed from the Site and/or publicly accessible areas. Photographs documenting the Site visit are included in Appendix I.

5.2 Specific Observations at Phase One ESA Property

5.2.1 Site Description and Buildings

The Site is located on the southwest side of Blair Road at Landmark Road in Burlington, Ontario. The Site measures approximately 1.7 hectares (4.1 acres) in area. The Site is currently occupied by a two-storey industrial/commercial building with approximately 7,205 m² (77,555 ft²) of floor area. The Site building is currently occupied by various commercial tenants.

At the time of the Site visit, three (3) of the units were vacant, two (2) of which were located on the second floor.

Several shipping containers were located along the back perimeter of the property. These containers are used for storage by Burlington Movers. Asphalt parking is located around the Site building.

According to the Site representative the building was constructed in the 1970s.

The main characteristics of the Site building are included in the following table:

Building Surface	Building Material Description
Floor Surfaces	• Carpet, tiles, laminated flooring, hardwood, poured concrete
Ceilings	• Suspended ceiling tile, metal decking, texture coat
Interior Walls	• Drywall, concrete block
Exterior Walls	• Stucco, concrete block

5.2.2 Heating and Cooling Systems

The building is heated and cooled by roof-top natural gas fired HVAC units and cooled by one (1) central air conditioning (AC) unit which was connected to the office space of Burlington Movers. Several natural gas fired radiant heaters were observed throughout the back units on the first floor. Several tenants indicated that these heaters are no longer used and that their heat is supplied by the HVAC units.

5.2.3 Site Utilities and Services

Potable water is provided to the Site building through the municipal water distribution system and sanitary wastewater is discharged to the municipal sewer system. Electrical service to the Site building is supplied by local hydro. Lighting in the building is supplied by fluorescent, incandescent, compact fluorescent and LED lighting fixtures. Electrical services to Site building by local hydro via pole mounted transformers off-site near the northwestern side of the Site.

The natural gas line enters the Site near the northeast corner from Blair Road.

Given that underground utilities are located on the Site, there is the potential for the distribution and transport of contaminants via the underground utilities.

5.2.4 Sewage and Wastewater Disposal

The Site and surrounding area is served by municipal sanitary and storm sewer systems.

5.2.5 Potable Water Sources

The Site is provided with a municipal water source (Lake Ontario).

5.2.6 Abandoned and Existing Wells

A monitoring well was observed on the grass area along Blair Road. The Ontario Well Record indicated the well is within the easement along Blair Road owned by the City of Burlington. The well was installed in 2011 however the purpose of the well is unknown.

5.2.7 Site Production and Manufacturing

No production or manufacturing occurs on the Site.

5.2.8 Drains, Pits and Sumps

Floor drains observed in the Site buildings were reportedly connected to the municipal sanitary sewer system. No pits or sumps were observed at the time of the Site visit.

5.2.9 Storage Tanks

Evidence of the presence/absence of Underground Storage Tanks (USTs) and Above Ground Storage Tanks (ASTs) at the Site was assessed during the Site visit.

No storage tanks and containers were observed at the Site at the time of the Site visit.

5.2.10 Water Wells

No potable water wells were observed at the Site during the Site visit.

5.2.11 Site Housekeeping

In general, the Site structure and visible infrastructure appeared to be in good condition.

5.2.12 Chemical Storage and Handling and Floor Condition

At the time of the Site visit, the following chemicals were noted:

- general household cleaning products were observed throughout the units;
- small quantities of pool chemicals were noted at Ciscon Landscaping;
- a 1000 L tote of organomodified siloxane emulsion outside of Absolute Custom Steel Fabrications. According to the tenant, this tote was present prior to renting the space; and

- several tanks of compressed gas were observed at Absolute Custom Steel Fabrications. Unused tanks were stored in a locked containment area located outside along the southeast side of the Site building.

No other significant chemical inventory, storage or evidence of chemical handling was observed or reported at the time of the Site visit.

5.2.13 Soil, Pavement or Stressed Vegetation

Exterior portions of the Site are asphalt paved. No stressed vegetation was observed on the Site at the time of the Site visit.

5.2.14 Fill and Debris

A small berm of vegetated soil covered was noted along the southwest boundary of the Site during the Site visit. According to the Site representative, this area is occupied by Ciscon Landscaping and is used as a storage space for various landscaping materials.

Based on observations made at the time of the Site reconnaissance and a review of historical records including previous reports, it is unlikely that significant fill material is located beneath the Phase One Property.

5.2.15 Air Emissions

Air emissions in Ontario are regulated under the Environmental Protection Act (EPA) and its Regulations (O.Reg. 419/05, O.Reg. 245/11). Owners and operators of activities that may discharge a contaminant into the natural environment must seek approval from the Ministry of the Environment (ministry) to carry out these activities. As of October 31, 2011 amendments to the EPA resulted in a two path environmental approval process, the Environmental Compliance Approval (ECA) and Environmental Activity and Sector Registry (EASR). The EASR allows businesses to register certain activities with the ministry, rather than apply for approvals. The EASR is for common systems and processes, currently for heating systems, standby power systems and automotive refinishing, to which preset rules of operation can be applied. Unless explicitly exempted, most industrial processes or modification to industrial processes and equipment require an ECA, formerly a Certificate of Approval (Air and Noise). Retroactive approval should be sought for equipment installed and unchanged between 1972 and June 29th, 1988 when the requirement for a Certificate of Approval was added to the EPA. The EPA provides a list of specific equipment and conditions, which are exempt from approval requirements (i.e. fuel burning equipment for comfort heating in a building using natural gas or number 2 fuel oil at a rate of less than 1.5 million British Thermal Units per hour [BTU/hour]).

Based on the Site visit, no operations were observed on-Site that would require MOECC approval for air emissions.

5.2.16 Polychlorinated Biphenyls (PCBs)

The manufacture of PCBs in North America was prohibited under the Toxic Substances Control Act (1977). Their use as a constituent of new products manufactured in or imported into Canada was prohibited by regulations in 1977 and 1980. As such, sites developed or significantly renovated after 1980 are unlikely to have PCBs-containing equipment on the Site. Potential equipment, which could contain PCBs include fluorescent mercury and sodium vapour light ballasts, oil filled capacitors and transformers. Recent scientific research has indicated the potential presence of PCBs in window caulking

material. A review of the Site was conducted to evaluate the potential presence of PCBs-containing equipment in use or stored at the Site.

Any electrical equipment containing PCBs must be disposed in accordance with Ontario Regulation 362 when it is removed from service. Ongoing operation of equipment containing PCBs is permissible.

Fluorescent light fixtures were observed throughout the Site building. Based on the age of the Site building (1970s), there is the potential for PCBs to be present on-Site in the original light ballasts and window caulking.

Pole mounted transformers were observed off-site near the northwestern side of the Site. The transformer appeared to be in good condition with no evidence of leaking or staining.

5.2.17 Regulated Building Materials

Based on the age of the Site building, it is considered possible that the buildings contain regulated building material(s) (e.g. lead, mercury, asbestos, etc). However, sampling of potential regulated building materials was beyond the scope of work. A Designated Substances Survey is recommended prior to any renovation activities.

5.3 Enhanced Investigation Property Observations

An Enhanced Investigation Property is "(i) a property used, or has ever been used, in whole or part, for an industrial purpose, or (ii) a commercial property used as a garage, a bulk liquid dispensing facility, including a gasoline outlet or for the operation of dry cleaning equipment" (O.Reg. 153/04).

Based on the records review and Site reconnaissance, the Site was classified as an Enhanced Investigation Property.

5.4 Adjacent and Surrounding Properties

A visual reconnaissance of the adjacent properties and properties within the Phase One ESA study area was conducted from publicly accessible areas to identify the occupants; and document any PCAs that may be contributing to an APEC at the Site.

The surrounding properties consisted primarily of commercial and industrial buildings.

The commercial tenants of the adjacent properties are listed in the following table. The remaining properties were noted to be residential.

Direction	Address	Occupants	Associated PCA
North	1157 Blair Road	Wardco (Window and Door Manufacturer)	Not listed – Generator of hazardous wastes (PCA-3)
	1176 Blair Road	Natural Click Co.	N/A
		Burlington Eagles Hockey Club	N/A
	1180 Blair Road	Catholic Teachers and Halton Elementary Association	N/A
	1190 Blair Road	OTLA	N/A
	3330 – 3342 Mainway	Paintball Nation	N/A

Direction	Address	Occupants	Associated PCA
		Nuera Industrial	No, based on current operations
		Burlington City Rep Hockey Club	N/A
		Moveware Ltd.	N/A
		Smart Thought Technologies	N/A
		Trillium Medical Billing Agency	N/A
		Ontario Trial Lawyers Assoc.	N/A
		Keep it Lite with Nicki	N/A
		Medset Specialists Ltd.	N/A
		Mid USE Motorcycle Parts Canada	N/A
		O.E.C.T.A Halton Elementary Unit	N/A
		Quality Underwriting Services	N/A
	3388 Mainway	Carstar Collision & Glass Service	27- Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles (PCA-6C)
	3390 Mainway	Rock this way (school of rock)	N/A
	3410 Mainway	Vacant	N/A
	3426 Mainway	Rexroth Bosch Group	Not listed – Generator of hazardous wastes (PCA-26)
	3460 Mainway		
	3419 Mainway	HTM Sensors	N/A
	1221 Dillion Road	HTM Sensors	N/A
		Sandtron Automation	No, based on current operations
	1233 Dillion Road	Burlington Fitness & Racquet Club	N/A
Northeast	3415 Landmark Road	TCR Machining Ltd.	34 – Metal Fabrication (PCA-14B)
	3424 Landmark Road	Waterworks Kitchen & Bath Boutique	N/A
	3435 Landmark Road	Air Separation Technologies Inc.	No, based on current operations
	3450 Landmark Road	Jarvis Insulation	No, based on current operations
		Bramkal Contractors Inc.	
	3455 Landmark Road	Eiffage ICCI	N/A
East	3400 Landmark Road	Kaidex Transportation Services Inc.	N/A
		Jimmy Tee (Embroidery/Screen Printing)	N/A
		Matheson Valves	N/A
		Airmax Compressor Services	Not listed – Generator of hazardous wastes (PCA-8)
	1101 Blair Road	QMBNV	N/A

Direction	Address	Occupants	Associated PCA
Southeast	1150 Blair Road	JR Tool and Die	34 – Metal Fabrication (PCA-2B)
		Canadian Blower	N/A
		Horton Automatics of Ontario	N/A
	1140 Blair Road	Jones Neon Displays Ltd.	N/A
		CR Container Resale Inc.	N/A
	1100 Blair Road	Quadra Chemicals Ltd.	8 – Chemical Manufacturing, Processing and Bulk Storage (PCA-20A) Not listed – Generator of hazardous wastes (PCA-20B)
	1121 Pioneer Road	Mauser Canada Ltd.	Not listed – Generator of hazardous wastes (PCA-16B) 43 – Plastic (including Fibreglass) Manufacturing and Processing (PCA-16D)
South	1153 Pioneer Road	Scholars in Collars	N/A
		Skinlicious Soaps Ltd.	N/A
		Singlepoint MFG. Inc.	34 – Metal Fabrication (PCA-10B)
		Mill Pack Industrial Maintenance	Not listed – Generator of hazardous wastes (PCA-10D)
		Free-Light	N/A
		Burlington Centreless Grinding	33 – Metal Treatment, Coating, Plating and Finishing (PCA-10A) 34 – Metal Fabrication (PCA-10B) Not listed – Generator of hazardous wastes (PCA-10D)
		BCG Precision Grinding & Honing Inc.	Not listed – Generator of hazardous wastes (PCA-10D)
		Brant Custom Grinding	33 – Metal Treatment, Coating, Plating and Finishing (PCA-10A) 34 – Metal Fabrication (PCA-10B)
		J.H Secord Enterprises	N/A
		Pioneer Road Holdings Inc.	N/A
		Complete Spa & Pool	N/A
		Special Effects M.C. Co.	N/A
		Action Radiator	N/A
		J.D. Restorations	N/A

Direction	Address	Occupants	Associated PCA
		Scanwest Design Ltd.	N/A
		Canadian Hazmat & Decon Service Inc.	N/A
		P.S.T Machining	34 – Metal Fabrication (PCA-10B)
		Tonic Appliances	N/A
		M.I.R Fabric Products Ltd.	54 – Textile Manufacturing and Processing (PCA-10C)
		Global Products & PKG Solutions	N/A
		TPREX Inc.	34 – Metal Fabrication (PCA-10B)
	1149 Pioneer Road	Willis/ Rehau	Not listed – Generator of hazardous wastes (PCA-19A)
	1122 Pioneer Road	Emterra Environmental	N/A
Southwest	1171 Pioneer Road	Bell Canada	28- Gasoline and Associate Products Storage in Fixed Tank (PCA-9A) Not listed – Generator of hazardous wastes (PCA-9B)
	3230 Mainway	Pioneer Family Pools Distribution Centre	N/A
	3264 Mainway	Fibrecast Inc.	Not listed – Generator of hazardous wastes (PCA-18A) 26 – Foam and Expanded Foam Manufacturing and Processing (PCA-18B)
West	3300 Mainway	Nuera Industrial	No, based on current operations
	3280 Mainway	Fix Auto Collision	27- Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles (PCA-33)
	3285/3291/3295 Mainway	The Printing House	Not listed – Generator of hazardous wastes (PCA-21C)
		Carlson Gracie Burlington	N/A
		McKellar Machine Products	34 – Metal Fabrication (PCA-21B)
		PowerPlay Hockey Training Centre	N/A
		Montvest Realty Limited	N/A
		Burlington Dance Company	N/A
		Pet Happy Grooming	N/A
	3267 Mainway	Vacant	N/A
Northwest	3310 Mainway	Integrity Worldwide Inc.	N/A
	3312 Mainway	Carlisle Technology	19 – Electronic and Computer Equipment Manufacturing (PCA-

Direction	Address	Occupants	Associated PCA
			11B)
	3317-3339 Mainway	Helec Insulation Inc.	43 – Plastics (including Fibreglass) Manufacturing and Processing (PCA-13E)
		West Windows & Doors	N/A
		Taurus Ind. Sales Inc.	N/A
		Allen Ind. Rubber	47 - Rubber Manufacturing and Processing (PCA-13D)
		R-Metrics Ltd.	N/A
		EGH-Evergreen Holdings	N/A
		Higgins Pro Team	N/A
		Simply Ballroom	N/A
		The Messengers Intl.	N/A
		DD Mechanical	34 – Metal Fabrication (PCA-13C)
		A.Joseph Mechanical	N/A
		Ettridges The Studio	N/A
		Alkano Ltd.	Not listed – Generator of hazardous wastes (PCA-13A)
		Halton Metal Outlet	N/A
		KD Sign Systems	N/A
		Custom Swag	N/A
	3365 Mainway	Exosynthetix	Not listed – Generator of hazardous wastes (PCA-25)
	3385 Mainway	Broadcast Services International	N/A
	1232 Dillon Road	JC CNC Works Inc.	Not listed – Generator of hazardous wastes (PCA-32A) 33 – Metal Treatment, Coating, Plating and Processing (PCA-32B) 34 – Metal Fabrication (PCA-32C)
		HAHN & Sons Ltd.	Not listed – Generator of hazardous wastes (PCA-32A)

No evidence of poor housekeeping was observed on the surrounding properties at the time of the Site reconnaissance.

5.5 Written Description of Investigation

A reconnaissance of the Site was conducted by EXP to examine the exterior and interior of on-Site buildings and structures, and to examine the exterior portions of the Site. Access was provided to the interiors of the Site building. Mechanical equipment (including heating and cooling systems) was

documented and characterized, as was any evidence of USTs and ASTs. The exterior portions of the Site were examined for evidence of utilities and related infrastructure; water wells; Site drainage and related infrastructure; stained areas; stressed vegetation; and evidence of fill material.

The Site reconnaissance included an examination of all properties within the Phase One study area from public access ways to document and characterize PCAs, water bodies and areas of natural significance.

6. Review and Evaluation of Information

6.1 Current and Past Uses

A review of the historical records indicated that the Site was first developed for agricultural purposes, including an orchard until at least 1959. The Site was converted into industrial/commercial since at least 1975, with the construction of a building similar to that observed during the Site visit.

6.2 Potentially Contaminating Activities (PCAs)

A list of all PCAs identified at the Site and within the Phase One ESA study area is included in Table 2 in the Phase One Conceptual Site Model (Appendix J) and shown on Figure 3.

6.3 Areas of Potential Environmental Concern (APECs)

Based on the inferred groundwater flow direction to the south/southeast, the properties within the Phase One Study Area north of the Site are considered to be hydraulically up-gradient of the Site; and, the properties to the east and west of the Site are considered to be hydraulically trans-gradient to the Site. PCAs to the south were considered to be down-gradient to the Site. Furthermore, or significantly distant from the Site (i.e. greater than 100 m) were considered to be too distant to be contributing to an APEC on the Site. Not withstanding industrial operations; PCAs which contributed to an APEC were mainly based on the following attributes: proximity to the Site, nature of waste streams and groundwater flow direction.

The APECs identified at the Site are summarized in Table 3 in the Phase One Conceptual Site Model (Appendix J) and shown on Figure 4.

7. Conclusions

Based on the results and findings of the Phase One ESA, a Phase Two ESA is required to investigate the APECs identified on the Phase One Property before a RSC can be submitted.

8. Closure

We trust this report is satisfactory for your purposes. Should you have any questions, please do not hesitate to contact this office.

Yours truly,

EXP Services Inc.



Patricia McMullan, B.Eng, EIT
Environmental Scientist
Environmental Services




David Mably, P.Eng QP$_{ESA}$
Senior Project Manager
Environmental Services

9. References

1. Canadian Standards Association. November 2001. Z768-0 *Phase I Environmental Site Assessment*.
2. *Occupational Health and Safety Act* - Ministry of Labour (MOL)
3. Physiography of Southern Ontario; Ontario Geological Survey, Scale 1:600,000. 1984.
4. Quaternary Geology of Ontario - geology_ll.shp [computer file],Ontario: Ontario Geological Survey, 2000.
5. Bedrock Geology of Ontario - geology_ll.shp [computer file],Ontario: Ontario Geological Survey, 2000.
6. Ontario Ministry of Natural Resources (2010) Ontario Base Mapping (OBM) (Scale 1:22,000).
7. "Toporama; Map 30M03, Natural Resources Canada. Scale 1:15,000. 2008
8. Inventory of Coal Gasification Plant Waste Sites in Ontario. Ontario Ministry of the Environment, April 1987.
9. Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario. Ontario Ministry of the Environment, November 1988.
10. Waste Disposal Site Inventory. Waste Management Branch Ontario Ministry of the Environment, June 1991.
11. Ontario Inventory of PCB Storage Sites. Ontario Ministry of the Environment, 1993- 2003-2004.
12. Catalogue of Canadian Fire Insurance Plans 1875 – 1975
13. Ontario Ministry of the Environment, Brownfields Registry website (www.ene.gov.on.ca/environet/BESR/index.htm)
14. Ontario Ministry of Natural Resources, Natural Heritage website (www.mnr.gov.on.ca/MNR/nhic/areas.cfm)
15. Oil, Gas & Salt Resources Library website (www.ogsrlibrary.com)
16. Technical Standards and Safety Authority, *Environmental Management Protocol for Fuel Handling Sites in Ontario,* May 2007.
17. Ecolog ERIS RSC Report (Urban) *1160 Blair Road, Burlington, Ontario*. May 24, 2018.
18. "Update *Phase I Environmental Site Assessment, 1160 Blair Road, Burlington, Ontario*" Trow Consulting Engineers Ltd. (now EXP), January 18, 1999.

Figures



EXP Services Inc.
t: +1.905.573.4000 | f: +1.905.573.9693
80 Bancroft Street
Hamilton, ON L8E 2W5
Canada
www.exp.com

• BUILDINGS • EARTH & ENVIRONMENT • ENERGY •
• INDUSTRIAL • INFRASTRUCTURE • SUSTAINABILITY •

Approximate Site Boundary

0 150 300 450 600 750 m

TITLE AND LOCATION:

SITE LOCATION PLAN
Phase One Environmental Site Assessment
1160 Blair Road
Burlington, Ontario

PROJECT No.: HAM-00801245-G0	DWN: AC
SCALE: AS NOTED	CHKD: DM
DATE: FEBRUARY 2019	FIG. No.: 1



EXP Services Inc.
t: +1.905.573.4000 | f: +1.905.573.9693
80 Bancroft Street
Hamilton, ON L8E 2W5
Canada
www.exp.com

•BUILDINGS • EARTH & ENVIRONMENT • ENERGY •
•INDUSTRIAL • INFRASTRUCTURE • SUSTAINABILITY •


Data Source: Burlington Official Plan - Schedule B. City of Burlington, 2017.

0 50 100 150 200 250 m

TITLE AND LOCATION:

PHASE ONE STUDY AREA AND SURROUNDING LAND USE MAP
Phase One Environmental Site Assessment
1160 Blair Road
Burlington, Ontario

PROJECT No.: HAM-00801245-G0	DWN: AC
SCALE: AS NOTED	CHKD: DM
DATE: FEBRUARY 2019	FIG. No.: 2



Legend

**Extent of the PCA is approximate as exact location is unknown

PCA**

- PCA does not contribute to APEC
- PCA contributing to APEC
- Approximate Site Boundary
- Phase One Study Area

EXP Services Inc.

t: +1.905.573.4000 | f: +1.905.573.9693
80 Bancroft Street
Hamilton, ON L8E 2W5
Canada
www.exp.com


•BUILDINGS • EARTH & ENVIRONMENT • ENERGY •
•INDUSTRIAL • INFRASTRUCTURE • SUSTAINABILITY•

0 50 100 150 200 250 m

TITLE AND LOCATION:

POTENTIALLY CONTAMINATING ACTIVITIES
Phase One Environmental Site Assessment
1160 Blair Road
Burlington, Ontario

PROJECT No.: HAM-00801245-G0	DWN: AC
SCALE: AS NOTED	CHKD: DM
DATE: FEBRUARY 2019	FIG. No.: 3



EXP Services Inc.
t: +1.905.573.4000 | f: +1.905.573.9693
80 Bancroft Street
Hamilton, ON L8E 2W5
Canada
www.exp.com

•BUILDINGS • EARTH & ENVIRONMENT • ENERGY •
• INDUSTRIAL • INFRASTRUCTURE • SUSTAINABILITY •

0 10 20 30 40 50 m

TITLE AND LOCATION:

AREAS OF POTENTIAL ENVIRONMENTAL CONCERN
Phase One Environmental Site Assessment
1160 Blair Road
Burlington, Ontario

PROJECT No.: HAM-00801245-G0	DWN: AC
SCALE: AS NOTED	CHKD: DM
DATE: FEBRUARY 2019	FIG. No.: 4

Tables

"Table of areas of potential environmental concern"
(Refer to clause 16(2)(a), Schedule D, O. Reg. 153/04)

Area of Potential Environmental Concern (APEC)[1]	Location of APEC on Phase One Property	Potentially Contaminating Activity (PCA)[2]	Location of PCA (on-Site or off-Site)	Contaminants of Potential Concern	Media Potentially Impacted (Groundwater, soil and/or sediment)
APEC 1A	Entire Site	40 – Pesticides (including Herbicides, Fungicides and Anti Fouling Agents), manufacturing, processing, bulk storage and large-scale applications 34 – Metal Fabrication 52 – Storage, maintenance, fuelling and repair of equipment, vehicles and materials used to maintain transportation systems	On-Site (1160 Blair Road)	Organochlorine Pesticides, Metals, As, Sb, Se	Soil
APEC 1B	Southeast Industrial Unit			Metals, VOCs and PHCs	Soil and Groundwater
APEC 1C	Northwest Industrial Unit			VOCs and PHCs	Soil and Groundwater
APEC 2	Southeast adjacent to property line	28 – Gasoline and Associate Products in Fixed Tanks, 34 – Metal Fabrication	Off-Site (1150 Blair Road)	VOCs and PHCs, Metals	Soil and Groundwater
APEC 3	Southern corner of property	28- Gasoline and Associate Products Storage in Fixed Tank Not listed – Generator of hazardous wastes	Off-Site (1171 Blair Road)	PHCs, VOCs, BTEX, Metals	Groundwater
APEC 4	Northeast adjacent to property boundary	Not listed – Generator of hazardous wastes	Off-Site (1157 Blair Road)	PHCs, VOCs, BTEX, Metals	Groundwater
APEC 5	Northern corner of property	Not listed – Generator of hazardous wastes 34 – Metal Fabrication 27- Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Off-Site (3388 Mainway)	PHCs, VOCs, BTEX, Metals	Groundwater
APEC 6	Northern corner of property	Not listed – Generator of hazardous wastes	Off-Site (3390 Mainway)	PHCs, VOCs, BTEX, Metals	Groundwater

Notes:

1 - Areas of potential environmental concern means the area on, in or under a phase one property where one or more contaminants are potentially present, as determined through the phase one environmental site assessment, including through,

(a) identification of past or present uses on, in or under the phase one property, and

(b) identification of potentially contaminating activity.

2 - Potentially contaminating activity means a use or activity set out in Column A of Table 2 of Schedule D that is occurring or has occurred in a phase one study area

3 - When completing this column, identify all contaminants of potential concern using the Method Groups as identified in the "Protocol for in the Assessment of Properties under Part XV.1 of the Environmental Protection Act, March 9, 2004, amended as of July 1, 2011, as specified below:

List of Method Groups:

ABNs	PCBs	Metals	Electrical Conductivity
CPs	PAHs	As, Sb, Se	Cr (VI)
1,4-Dioxane	THMs	Na	Hg
Dioxins/Furans, PCDDs/PCDFs	VOCs	B-HWS	Methyl Mercury
OCs	BTEX	Cl-	Low or high pH,
PHCs	Ca, Mg	CN-	SAR

4 - When submitting a record of site condition for filing, a copy of this table must be attached

Cette publication hautement spécialisée n'est disponible qu'en anglais en vertu du règlement 671/92, qui en exempte l'application de la Loi sur les services en français. Pour obtenir de l'aide en francais, veuillez communiquer avec le ministère de l'Environnement et de l'Action en matière de changement climatique au 1-800-461-6290

"Table of current and past uses of the Phase One property"
(Refer to Clause 16(2)(b), Schedule D, O.Reg. 153/04)

Year	Name of owner	Description of property use	Property use	Other observations from aerial photographs, fire insurance plans, etc.
Prior to 1846	Crown	Vacant Land	Agricultural or Other Use	A review of historical aerial photographs indicate that the Site was used for agricultural property use, including an orchard, since at least 1959.
1846 - 1872	George Dales	Agricultural	Agricultural or Other Use	
1872 - 1884	Benjamin Hugh Kean	Agricultural	Agricultural or Other Use	
1884 - 1889	Ralph Thomson	Agricultural	Agricultural or Other Use	
1889 - 1891	Sydney Colburn & Albert Colburn	Agricultural	Agricultural or Other Use	
1891 - 1892	Thomas Blaumhard	Agricultural	Agricultural or Other Use	
1892 - 1897	John Robert Blaumhard	Agricultural	Agricultural or Other Use	
1897 - 1948	Thomas Mount	Agricultural	Agricultural or Other Use	
1948 - 1955	Murray Webster Fisher	Agricultural	Agricultural or Other Use	
1955 - 1969	William Murray Fisher & Edward Reynold Hoover	Agricultural	Agricultural or Other Use	
1969 - 1971	The Corporation of The Town of Burlington	Multi-tenant Industrial property use	Industrial use	Based on information obtained during the Site visit and available municipal records, the Site building was being constructed for multi-tenant property use. The Site is not listed in the city directories in 1970.

Year	Name of owner	Description of property use	Property use	Other observations from aerial photographs, fire insurance plans, etc.
1971	Reimer Construction Limited	Multi-tenant Industrial property use	Industrial use	Based on the 1978 aerial photograph and available municipal records, the Site was developed with a multi-tenant building similar to that observed during the Site visit. Narrative describing the activities of potential industrial operations is provided in the CSM.
1971 - 1989	Sun Life Assurance Company of Canada			
1989 - 1995	808212 Ontario Limited & 816456 Ontario Limited			
1995 - 1999	Creek Meadows Inc.			
1999 - 2005	Kara Holding Inc.			
2005 - 2008	Irwin Mintz			
2008 to 2018	2118218 Ontario Inc.	Commercial Use	Commercial Use	At the time of the Site visit, the Site was occupied by a multi-tenant building with the same configuration as previous aerial photographs.
2018 to present	Archangel Raphael & St. Marina Coptic Orthodox Church	Commercial Use	Commercial Use	Same as above, the Site was occupied by a multi-tenant building.

Notes:

1 - for each owner, specify one of the following types of property use (as defined in O.Reg. 153/04) that applies:

Agriculture or other use
Commercial use
Community use
Industrial use
Institutional use
Parkland use
Residential use

2 - when submitting a record of site condition for filing, a copy of this table must be attached

Cette publication hautement spécialisée n'est disponible qu'en anglais en vertu du règlement 671/92, qui en exempte l'application de la Loi sur les services en français. Pour obtenir de l'aide en francais, veuillez communiquer avec le ministère de l'Environnement et de l'Action en matière de changement climatique au 1-800-461-6290

Appendix A: Limitation of Liability, Scope of Report, and Third Party Reliance

LIMITATIONS AND USE OF REPORT

BASIS OF REPORT

The Report is based on site conditions known or inferred by the investigation undertaken as of the date of the Report. Should changes occur which potentially impact the condition of the site the recommendations of exp may require re-evaluation. Where special concerns exist, or the Client has special considerations or requirements, these should be disclosed to exp to allow for additional or special investigations to be undertaken not otherwise within the scope of investigation conducted for the purpose of the Report.

Where applicable, recommended field services are the minimum necessary to ascertain that construction is being carried out in general conformity with building code guidelines, generally accepted practices and exp's recommendations. Any reduction in the level of services recommended will result in exp providing qualified opinions regarding the adequacy of the work. exp can assist design professionals or contractors retained by the Client to review applicable plans, drawings, and specifications as they relate to the Report or to conduct field reviews during construction.

RELIANCE ON INFORMATION PROVIDED

The evaluation and conclusions contained in the Report are based on conditions in evidence at the time of site inspections and information provided to exp by the Client and others. The Report has been prepared for the specific site, development, building, design or building assessment objectives and purpose as communicated by the Client. exp has relied in good faith upon such representations, information and instructions and accepts no responsibility for any deficiency, misstatement or inaccuracy contained in the Report as a result of any misstatements, omissions, misrepresentation or fraudulent acts of persons providing information. Unless specifically stated otherwise, the applicability and reliability of the findings, recommendations, suggestions or opinions expressed in the Report are only valid to the extent that there has been no material alteration to or variation from any of the information provided to exp.

STANDARD OF CARE

This report ("Report") has been prepared in a manner consistent with the degree of care and skill exercised by engineering consultants currently practicing under similar circumstances and locale. No other warranty, expressed or implied, is made. Unless specifically stated otherwise, the Report does not contain environmental consulting advice.

COMPLETE REPORT

All documents, records, data and files, whether electronic or otherwise, generated as part of this assignment form part of the Report. This material includes, but is not limited to, the terms of reference given to exp by the Client, communications between exp and the Client, other reports, proposals or documents prepared by exp for the Client in connection with the site described in the Report. In order to properly understand the suggestions, recommendations and opinions expressed in the Report, reference must be made to the Report in its entirety. exp is not responsible for use by any party of portions of the Report.


USE OF REPORT

The information and opinions expressed in the Report, or any document forming part of the Report, are for the sole benefit of the Client. No other party may use or rely upon the Report in whole or in part without the written consent of exp. Any use of the Report, or any portion of the Report, by a third party are the sole responsibility of such third party. exp is not responsible for damages suffered by any third party resulting from unauthorised use of the Report.

REPORT FORMAT

Where exp has submitted both electronic file and a hard copy of the Report, or any document forming part of the Report, only the signed and sealed hard copy shall be the original documents for record and working purposes. In the event of a dispute or discrepancy, the hard copy shall govern. Electronic files transmitted by exp utilize specific software and hardware systems. exp makes no representation about the compatibility of these files with the Client's current or future software and hardware systems. Regardless of format, the documents described herein are exp's instruments of professional service and shall not be altered without the written consent of exp.

Appendix B: Survey Plan


I REQUIRE THIS PLAN TO BE DEPOSITED UNDER THE REGISTRY ACT.
DATE – JUNE 5, 1995
M. J. TERRY
ONTARIO LAND SURVEYOR
PLAN 20R-11755
RECORDED AND DEPOSITED
DATE – 06 JUNE, 1995
LAND REGISTRAR FOR THE REGISTRY DIVISION OF HALTON 20
MAINWAY
(BY REGISTERED PLAN 1055)
MAINWAY
OPENED BY BY-LAW 4176 INST. 329269
PART 6, 20R-311 INST. 264743
DETAIL "A"
PART 16, 20R-311
PART 15, 20R-311
PART OF LOT 12 CONCESSION 2
INST. 711466
PART 14, 20R-311
PART 1
PART 2
PART 3
PART 4
PART 5
PART 6
PART 7
PART 8
PART 9
PART 10
PART 11, 20R-559
SUBJECT TO A 10' WIDE EASEMENT AS IN INST. 382238
PART 12 PLAN 20R-559
INST. 711466
SOUTH OF DUNDAS STREET
BRICK & CONC. BLOCK BUILDING
No. 1160
PART 1, 20R-7147
PART 2, 20R-7147
10' WIDE EASEMENT AS IN INST. 306753
INST. 824075
PART OF LOT 12
BLAIR ROAD
OPENED BY BY-LAW 4176 INST. 329269
PART 12, 20R-311 INST. 264743
REGISTERED PLAN 1055
LOT 16
INST. 694136
INST. 260689
INST. 646563
INST. 628132
INST. 764082
10' WIDE EASEMENT AS IN INST. 306168
SUBJECT TO A 10' WIDE EASEMENT AS IN INST. 386369
10' WIDE EASEMENT AS IN INST. 329274
DETAIL "B"
SCHEDULE
PART | LOT | CONCESSION | INSTRUMENT | AREA
1 | 12 | S. D.S. | 711466 | 1.672 ac
2 | | | 711466, EASEMENT AS IN 286565 AND 306168 AND 382238 | 9452 sq.ft.
3 | | | 711466 | 0 sq.ft.
4 | | | | 301 sq.ft.
5 | | | 711466, EASEMENT AS IN 286565 | 1074 sq.ft.
6 | | | 711466 | 2.434 ac
7 | | | 711466, EASEMENTS AS IN 306168, 329274 AND 382238 | 6722 sq.ft.
8 | | | 711466 | 8420 sq.ft.
9 | | | | 3.656 ac
10 | | | 711466, EASEMENT AS IN 382238, 286565 AND 306168 | 141 sq.ft.
11 | | | 711466, EASEMENT AS IN 382238 | 11367 sq.ft.
PLAN OF SURVEY OF
PART OF LOT 12
CONCESSION 2 S.D.S.
TOWNSHIP OF NELSON
CITY OF BURLINGTON
REGIONAL MUNICIPALITY OF HALTON
SCALE – 1" = 40'
YATES & YATES LIMITED
ONTARIO LAND SURVEYORS
1995
LEGEND
B – DENOTES SURVEY MONUMENT FOUND
D – DENOTES SURVEY MONUMENT SET
SIB – DENOTES STANDARD IRON BAR
IB – DENOTES IRON BAR
ICB – DENOTES CUT IRON BAR
CC – DENOTES CUT CROSS
CM – DENOTES CONCRETE MONUMENT
P1 – DENOTES PLAN 20R-311
P2 – DENOTES PLAN 20R-559
H17 – DENOTES JOHN VAN WESTRAND, O.L.S.
HP – DENOTES HYDRO POLE
BURL. – DENOTES CITY OF BURLINGTON
MEAS – DENOTES MEASURED
BEARING REFERENCE
BEARINGS SHOWN HEREON ARE ASTRONOMIC AND ARE REFERRED TO THE SOUTHWEST LIMIT OF BLAIR ROAD HAVING A BEARING OF N43°02'30"W AS SHOWN ON PLAN 20R-311.
SURVEYOR'S CERTIFICATE
I CERTIFY THAT :
1. This survey and plan are correct and in accordance with The Surveys Act and The Registry Act and the regulations made thereunder.
2. The survey was completed on the 5th day of MAY, 1995
DATE – JUNE 5, 1995
M. J. TERRY
ONTARIO LAND SURVEYOR
DETAIL "B"
YATES & YATES LIMITED
ONTARIO LAND SURVEYORS
Patents of Sewell & Sewell
817 BRANT STREET
BURLINGTON, ONT. L7R 2J4
(905) 634-1370
CAUTION – THIS PLAN IS NOT A PLAN OF SUBDIVISION WITHIN THE MEANING OF THE PLANNING ACT.
Phase One ESA,
Phase Two ESA, and RSC Property Boundary

30

Appendix C: Qualification of Assessors

QUALIFICATIONS OF ASSESSORS

The Site visit and records review for this assessment were conducted by Ms. Kelsey Proks, B.Sc., who has been trained to conduct Phase I ESAs in accordance with CSA Standards and O. Reg 153/04. She has conducted numerous Phase I ESAs for commercial/industrial/residential clients and is routinely engaged in this field. Ms. Proks have a Bachelor of Science degree in Earth Sciences and Geography from Brock University a Post Graduate Certificate in Environmental Management and Assessment at Niagara College.

The records review was conducted by Ms. Patricia McMullan, B. Eng., E.I.T, who has been trained to conduct Phase I and II environmental site assessments (in accordance with the applicable CSA Standards and O.Reg. 153/04). Ms. McMullan has conducted numerous Phase I ESAs for commercial/ industrial/ residential clients and is routinely engaged in this field Ms. McMullan completed a Bachelor of Engineering Degree from the University of Guelph.

The report was reviewed by Mr. Erik Enders, P.Geo. who is an Environmental Geoscientist at EXP with over eleven years environmental consulting experience in Canada. Mr. Enders graduated s*umma cum laude* from McMaster University with an Honours Bachelor of Science in Environmental Science with a specialization in Geographic Information Systems (GIS). Mr. Enders has managed and conducted numerous Phase One and Phase Two Environmental Site Assessments as well as numerous other due diligence projects and is a “Qualified Person” registered with the Ontario Ministry of the Environment, Conservation and Parks.

The report was also reviewed by Mr. David Mably, a Senior Project Manager in the Environmental Division. Mr. Mably has over 20 years of experience and is located in EXP’s Brampton Office, and has been with EXP since 2018. David obtained his Bachelor’s of Applied Science and Engineering degree in Geotechnical Engineering from the University of Toronto, Ontario. He is an experienced environmental professional, having worked on a variety of Phase I and II environmental site assessment (in accordance with the applicable CSA Standards and O.Reg. 153/04) and risk assessment projects in the past, as well as on numerous hazardous materials and mould assessment and abatement projects. As part of his responsibilities, David’s role is to ensure the consistency and quality of the environmental reports report prior to its submission to the client and the regulatory bodies. David is a registered Qualified Person (QP) with the Ontario Ministry of the Environment for the purpose of conducting Environmental Site Assessments (QPESA) projects.

EXP Services Inc. is a full-service consulting and engineering firm and provides a full range of environmental services through the Environmental Services Group. EXP's Environmental Services Group has developed a strong working relationship with clients in both the private and public sectors and has developed a positive relationship with the Ontario Ministry of the Environment, Conservation and Parks. Personnel in the numerous branch offices form part of a large network of full-time dedicated environmental professionals in the EXP organization.

Appendix D: Chain of Title Search

PROPERTY DESCRIPTION: PT LT 12 , CON 2 S.D.S."NELSON", PART 9, 10 & 11 , 20R11755 ; S/T 286594E,306168E,362226E BURLINGTON "ADDED OCT 5, 98 J. MENARD"

PROPERTY REMARKS:

ESTATE/QUALIFIER:
FEE SIMPLE
LT CONVERSION QUALIFIED

RECENTLY:
FIRST CONVERSION FROM BOOK

PIN CREATION DATE:
1996/02/19

OWNERS' NAMES
ARCHANGEL RAPHAEL & ST. MARINA COPTIC ORTHODOX CHURCH

CAPACITY SHARE

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
EFFECTIVE 2000/07/29 THE NOTATION OF THE "BLOCK IMPLEMENTATION DATE" OF 1996/02/19 ON THIS PIN						
WAS REPLACED WITH THE "PIN CREATION DATE" OF 1996/02/19						
*** PRINTOUT INCLUDES ALL DOCUMENT TYPES AND DELETED INSTRUMENTS SINCE 1996/02/16 ***						
***SUBJECT, ON FIRST REGISTRATION UNDER THE LAND TITLES ACT, TO:*						
*** SUBSECTION 44(1) OF THE LAND TITLES ACT, EXCEPT PARAGRAPH 11, PARAGRAPH 14, PROVINCIAL SUCCESSION DUTIES **						
*** AND ESCHEATS OR FORFEITURE TO THE CROWN.*						
*** THE RIGHTS OF ANY PERSON WHO WOULD, BUT FOR THE LAND TITLES ACT, BE ENTITLED TO THE LAND OR ANY PART OF*						
*** IT THROUGH LENGTH OF ADVERSE POSSESSION, PRESCRIPTION, MISDESCRIPTION OR BOUNDARIES SETTLED BY*						
*** CONVENTION.*						
*** ANY LEASE TO WHICH THE SUBSECTION 70(2) OF THE REGISTRY ACT APPLIES.*						
***DATE OF CONVERSION TO LAND TITLES: 1996/02/19 ***						
119980	1961/01/25	BYLAW				C
281246	1969/09/25	AGREEMENT		**** DELETED AGAINST THIS PROPERTY ****		
	REMARKS: SKETCH ATTACHED					
E286594	1969/12/29	TRANSFER EASEMENT			THE CORPORATION OF THE TOWN OF BURLINGTON	C
	REMARKS: SKETCH ATTACHED					
Z286594	1969/12/29	REST COV APL ANNEX		**** DELETED AGAINST THIS PROPERTY ****		
286596	1969/12/29	AGREEMENT		**** DELETED AGAINST THIS PROPERTY ****	THE CORPORATION OF THE TOWN OF BURLINGTON	
	REMARKS: SKETCH ATTACHED					

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
E306168	1971/01/11	TRANSFER EASEMENT			THE CORPORATION OF THE TOWN OF BURLINGTON	C
	REMARKS: SKETCH ATTACHED					
Z306168	1971/01/11	REST COV APL ANNEX		*** DELETED AGAINST THIS PROPERTY ***		
20R311	1971/12/16	PLAN REFERENCE				C
20R559	1973/04/12	PLAN REFERENCE				C
E362226	1973/05/23	TRANSFER EASEMENT			THE CORPORATION OF THE TOWN OF BURLINGTON	C
Z362226	1973/05/23	REST COV APL ANNEX		*** DELETED AGAINST THIS PROPERTY ***		
439074	1976/08/25	LEASE		*** DELETED AGAINST THIS PROPERTY ***	BURROUGHS BUSINESS MACHINES LTD.	
450334	1977/02/25	NOTICE OF LEASE		*** DELETED AGAINST THIS PROPERTY ***	ALEXANIAN AND SONS LIMITED	
518195	1980/02/19	NOTICE OF LEASE		*** DELETED AGAINST THIS PROPERTY ***	DOUWE EGBERTS LIMITED	
603709	1984/07/20	NOTICE OF LEASE		*** DELETED AGAINST THIS PROPERTY ***	G.W. ROBINSON COMPANY LIMITED	
711468	1989/01/31	ASSIGNMENT GENERAL		*** DELETED AGAINST THIS PROPERTY ***		
758408	1991/02/08	NOTICE		*** DELETED AGAINST THIS PROPERTY ***		
20R11755	1995/06/06	PLAN REFERENCE				C
840664	1995/07/24	TRANS POWER SALE		*** COMPLETELY DELETED ***	CREEK MILL MEADOWS INC.	
840666	1995/07/24	CHARGE		*** COMPLETELY DELETED ***	SUN LIFE ASSURANCE COMPANY OF CANADA	
840667	1995/07/24	ASSIGNMENT GENERAL		*** COMPLETELY DELETED ***		

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
REMARKS: 840666						
840668	1995/07/24	NO SEC INTEREST		*** COMPLETELY DELETED ***		
H625989	1996/03/12	CHARGE		*** COMPLETELY DELETED *** CREEK MILL MEADOWS INC.	 HOEGL, JOHANNES	
H649614	1996/10/21	DISCH OF CHARGE		*** COMPLETELY DELETED *** HOEGL, JOHANNES		
REMARKS: RE: H625989						
H657754	1996/12/18	CHARGE		*** COMPLETELY DELETED *** CREEK MILL MEADOWS INC.	 HOEGL, JOHANNES	
H665448	1997/02/26	CHARGE		*** COMPLETELY DELETED *** CREEK MILL MEADOWS INC.	 HOEGL, JOHANNES	
H707547	1997/10/30	CHARGE		*** COMPLETELY DELETED *** CREEK MILL MEADOWS INC.	 CHHABRA, RITA	
H709337	1997/11/07	DISCH OF CHARGE		*** COMPLETELY DELETED *** HOEGL, JOHANNES		
REMARKS: RE: H665448						
H717363	1997/12/31	DISCH OF CHARGE		*** COMPLETELY DELETED *** HOEGL, JOHANNES		
REMARKS: RE: H657754						
H717364	1997/12/31	DISCH OF CHARGE		*** COMPLETELY DELETED *** CHHABRA, RITA		
REMARKS: RE: H707547						
H717532	1998/01/05	CHARGE		*** COMPLETELY DELETED *** CREEK MILL MEADOWS INC.	 CHHABRA, RITA	
H719137	1998/01/16	APL (GENERAL)		*** COMPLETELY DELETED *** CREEK MILL MEADOWS INC.		
REMARKS: 281246						
H719138	1998/01/16	APL (GENERAL)		*** COMPLETELY DELETED *** CREEK MILL MEADOWS INC.		

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
	REMARKS: 758408					
H719139	1998/01/16	APL (GENERAL)		*** COMPLETELY DELETED ***		
				CREEK MILL MEADOWS INC.		
	REMARKS: 450334					
H719140	1998/01/16	APL (GENERAL)		*** COMPLETELY DELETED ***		
				CREEK MILL MEADOWS INC.		
	REMARKS: 439074					
H719141	1998/01/16	APL (GENERAL)		*** COMPLETELY DELETED ***		
				CREEK MILL MEADOWS INC.		
	REMARKS: 518195					
H719142	1998/01/16	APL (GENERAL)		*** COMPLETELY DELETED ***		
				CREEK MILL MEADOWS INC.		
	REMARKS: 603709					
H719990	1998/01/23	DIS NOTICE SEC INT		*** COMPLETELY DELETED ***		
				SUN LIFE ASSURANCE COMPANY OF CANADA		
	REMARKS: SECURITY INTEREST, 840668					
H719991	1998/01/23	DISCH OF CHARGE		*** COMPLETELY DELETED ***		
				SUN LIFE ASSURANCE COMPANY OF CANADA		
	REMARKS: RE: 840666					
H740859	1998/06/19	TRANSFER OF CHARGE		*** COMPLETELY DELETED ***		
				CHHABRA, RITA	E. LIPTAY ENTERPRISES LTD.	
	REMARKS: H717532					
H759936	1998/10/13	CHARGE		*** COMPLETELY DELETED ***		
				CREEK MILL MEADOWS INC.	MUSLU, SELAMI	
H776637	1999/02/18	POWER OF ATTORNEY		*** COMPLETELY DELETED ***		
				MUSLU, SELAMI	KARA, AHMET GOKHAN	
H776731	1999/02/19	CHARGE		*** COMPLETELY DELETED ***		
				CREEK MILL MEADOWS INC.	E. LIPTAY ENTERPRISES LTD.	
H776732	1999/02/19	POSTPONEMENT		*** COMPLETELY DELETED ***		
				MUSLU, SELAMI	E. LIPTAY ENTERPRISES LTD.	
	REMARKS: H759936 TO H776731					

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
H776733	1999/02/19	DISCH OF CHARGE		*** COMPLETELY DELETED *** E. LIPTAY ENTERPRISES LTD.		
	REMARKS: RE: H717532					
H793872	1999/06/15	CHARGE		*** COMPLETELY DELETED *** CREEK MILL MEADOWS INC.	E. LIPTAY ENTERPRISES LTD.	
H793873	1999/06/15	DISCH OF CHARGE		*** COMPLETELY DELETED *** E. LIPTAY ENTERPRISES LTD.		
	REMARKS: RE: H776731					
H793874	1999/06/15	POSTPONEMENT		*** COMPLETELY DELETED *** MUSLU, SELAMI	E. LIPTAY ENTERPRISES LTD.	
	REMARKS: H759936 TO H793872					
H798862	1999/07/08	DISCH OF CHARGE		*** COMPLETELY DELETED *** E. LIPTAY ENTERPRISES LTD.		
	REMARKS: RE: H793872					
H798863	1999/07/08	CHARGE		*** COMPLETELY DELETED *** CREEK MILL MEADOWS INC.	E. LIPTAY ENTERPRISES LTD.	
H798864	1999/07/08	POSTPONEMENT		*** COMPLETELY DELETED *** MUSLU, SALAMI	E. LIPTAY ENTERPRISES LTD.	
	REMARKS: H759936 TO H798863					
H804363	1999/08/09	CHARGE		*** COMPLETELY DELETED *** CREEK MILL MEADOWS INC.	E. LIPTAY ENTERPRISES LTD.	
H804364	1999/08/09	POSTPONEMENT		*** COMPLETELY DELETED *** MUSLU, SELAMI	E. LIPTAY ENTERPRISES LTD.	
	REMARKS: H759936 TO H804363					
H804676	1999/08/11	DISCH OF CHARGE		*** COMPLETELY DELETED *** E. LIPTAY ENTERPRISES LTD.		
	REMARKS: RE: H798863					
H807390	1999/08/26	CHARGE		*** COMPLETELY DELETED *** CREEK MILL MEADOWS INC.	KARA, YUNUS	
H809241	1999/09/02	DISCH OF CHARGE		*** COMPLETELY DELETED *** MUSLU, SELAMI		
	REMARKS: RE: H759936					

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
H815373	1999/10/08	CHARGE		*** COMPLETELY DELETED *** CREEK MILL MEADOWS INC.	E. LIPTAY ENTERPRISES LTD.	
H815374	1999/10/08	POSTPONEMENT		*** COMPLETELY DELETED *** KARA, YUNUS	E. LIPTAY ENTERPRISES LTD.	
	REMARKS: H807390 TO H815373					
H815375	1999/10/08	DISCH OF CHARGE		*** COMPLETELY DELETED *** E. LIPTAY ENTERPRISES LTD.		
	REMARKS: RE: H804363					
H815376	1999/10/08	TRANSFER		*** COMPLETELY DELETED *** CREEK MILL MEADOWS INC.	KARA HOLDING INC.	
H831639	2000/01/24	CHARGE		*** COMPLETELY DELETED *** KARA HOLDING INC.	E. LIPTAY ENTERPRISES LTD.	
H831640	2000/01/24	POSTPONEMENT		*** COMPLETELY DELETED *** KARA, YUNUS	E. LIPTAY ENTERPRISES LTD.	
	REMARKS: H807390 TO H831639					
H838945	2000/03/17	CHARGE		*** COMPLETELY DELETED *** KARA HOLDING INC.	E. LIPTAY ENTERPRISES LTD.	
H838946	2000/03/17	POSTPONEMENT		*** COMPLETELY DELETED *** KARA, YUNUS	E. LIPTAY ENTERPRISES LTD.	
	REMARKS: H807390 TO H838945					
H844637	2000/04/26	CHARGE		*** COMPLETELY DELETED *** KARA HOLDING INC.	E. LIPTAY ENTERPRISES LTD.	
H844638	2000/04/26	POSTPONEMENT		*** COMPLETELY DELETED *** KARA, YUNUS	E. LIPTAY ENTERPRISES LTD.	
	REMARKS: H807390 TO H844637					
H853051	2000/06/16	CHARGE		*** COMPLETELY DELETED *** KARA HOLDING INC.	E. LIPTAY ENTERPRISES LTD.	
H853052	2000/06/16	POSTPONEMENT		*** COMPLETELY DELETED *** KARA, YUNUS	E. LIPTAY ENTERPRISES LTD	
	REMARKS: H807390 TO H853051					

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
H854839	2000/06/27	CHARGE		*** COMPLETELY DELETED *** KARA HOLDING INC.	E. LIPTAY ENTERPRISES LTD.	
H854840	2000/06/27	NOTICE		*** COMPLETELY DELETED *** KARA HOLDINGS INC.	E. LIPTAY ENTERPRISES LTD.	
	REMARKS: H815373 - RENTS					
H854841	2000/06/27	POSTPONEMENT		*** COMPLETELY DELETED *** KARA, YUNUS	E. LIPTAY ENTERPRISES LTD.	
	REMARKS: H807390 TO H854839					
HR34769	2001/01/31	CHARGE		*** COMPLETELY DELETED *** KARA HOLDING INC.	E. LIPTAY ENTERPRISES LTD.	
HR34770	2001/01/31	POSTPONEMENT		*** COMPLETELY DELETED *** KARA, YUNUS	E. LIPTAY ENTERPRISES LTD.	
	REMARKS: H807390 TO HR34769					
HR42981	2001/03/30	CHARGE		*** COMPLETELY DELETED *** KARA HOLDING INC.	E. LIPTAY ENTERPRISES LTD.	
HR42982	2001/03/30	POSTPONEMENT		*** COMPLETELY DELETED *** YUNUS, KARA	E. LIPTAY ENTERPRISES LTD.	
	REMARKS: H807390 TO HR42981					
HR54580	2001/06/14	CHARGE		*** COMPLETELY DELETED *** KARA HOLDING INC.	E. LIPTAY ENTERPRISES LTD.	
HR54582	2001/06/14	POSTPONEMENT		*** COMPLETELY DELETED *** KARA, YUNUS	E. LIPTAY ENTERPRISES LTD.	
	REMARKS: H807390 TO HR54580					
HR92220	2001/12/21	CHARGE		*** COMPLETELY DELETED *** KARA HOLDING INC.	CIBC MORTGAGES INC.	
HR92223	2001/12/21	NO ASSGN RENT GEN		*** COMPLETELY DELETED *** KARA HOLDING INC.	CIBC MORTGAGES INC.	
	REMARKS: HR92220 - RENTS					
HR92245	2001/12/21	NOTICE OF LEASE		*** COMPLETELY DELETED *** KARA HOLDING INC.	1407846 ONTARIO INC.	
HR92246	2001/12/21	NOTICE OF LEASE		*** COMPLETELY DELETED ***		

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
				KARA HOLDING INC.	1407846 ONTARIO INC.	
HR92247	2001/12/21	NOTICE OF LEASE		*** COMPLETELY DELETED ***		
				KARA HOLDING INC.	1407846 ONTARIO INC.	
HR92248	2001/12/21	NOTICE OF LEASE		*** COMPLETELY DELETED ***		
				KARA HOLDING INC.	1407846 ONTARIO INC.	
HR92249	2001/12/21	NOTICE OF LEASE		*** COMPLETELY DELETED ***		
				KARA HOLDING INC.	AUBURN INDUSTRIAL SERVICES LTD.	
HR92250	2001/12/21	NOTICE OF LEASE		*** COMPLETELY DELETED ***		
				KARA HOLDING INC.	CSI CUTTING SYSTEMS INC.	
HR92251	2001/12/21	NOTICE OF LEASE		*** COMPLETELY DELETED ***		
				KARA HOLDING INC.	1389819 ONTARIO LTD.	
HR92252	2001/12/21	NOTICE OF LEASE		*** COMPLETELY DELETED ***		
				KARA HOLDING INC.	1389819 ONTARIO LTD.	
HR92253	2001/12/21	NOTICE OF LEASE		KARA HOLDING INC.	BURLINGTON MOVERS INC.	C
HR92325	2001/12/21	NO ASSG LESSOR INT		*** COMPLETELY DELETED ***		
				KARA HOLDING INC.	CIBC MORTGAGES INC.	
	REMARKS: LEASE HR92245 CHARGE HR92220					
HR92326	2001/12/21	NO ASSG LESSOR INT		*** COMPLETELY DELETED ***		
				KARA HOLDING INC.	CIBC MORTGAGES INC.	
	REMARKS: LEASE HR92246 CHARGE HR92220					
HR92327	2001/12/21	NO ASSG LESSOR INT		*** COMPLETELY DELETED ***		
				KARA HOLDING INC.	CIBC MORTGAGES INC.	
	REMARKS: LEASE HR92247 CHARGE HR92220					
HR92328	2001/12/21	NO ASSG LESSOR INT		*** COMPLETELY DELETED ***		
				KARA HOLDING INC.	CIBC MORTGAGES INC.	
	REMARKS: LEASE HR92248 CHARGE HR92220					
HR92329	2001/12/21	NO ASSG LESSOR INT		*** COMPLETELY DELETED ***		
				KARA HOLDING INC.	CIBC MORTGAGES INC.	
	REMARKS: LEASE HR92249 CHARGE HR92220					
HR92330	2001/12/21	NO ASSG LESSOR INT		*** COMPLETELY DELETED ***		

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
				KARA HOLDING INC.	CIBC MORTGAGES INC.	
	REMARKS: LEASE HR92250 CHARGE HR92220					
HR92331	2001/12/21	NO ASSG LESSOR INT		*** COMPLETELY DELETED ***		
				KARA HOLDING INC.	CIBC MORTGAGES INC.	
	REMARKS: LEASE HR92251 CHARGE HR92220					
HR92332	2001/12/21	NO ASSG LESSOR INT		*** COMPLETELY DELETED ***		
				KARA HOLDING INC.	CIBC MORTGAGES INC.	
	REMARKS: LEASE HR92252 CHARGE HR92220					
HR92333	2001/12/21	NO ASSG LESSOR INT		*** COMPLETELY DELETED ***		
				KARA HOLDING INC.	CIBC MORTGAGES INC.	
	REMARKS: LEASE HR92253 CHARGE HR92220					
HR92334	2001/12/21	POSTPONEMENT		*** COMPLETELY DELETED ***		
				KARA, YUNUS	CIBC MORTGAGES INC.	
	REMARKS: H807390 TO HR92220					
HR92347	2001/12/21	CHARGE		*** COMPLETELY DELETED ***		
				KARA HOLDING INC.	E. LIPTAY ENTERPRISES LTD.	
HR92355	2001/12/21	POSTPONEMENT		*** COMPLETELY DELETED ***		
				KARA, YUNUS	E. LIPTAY ENTERPRISES LTD.	
	REMARKS: H807390 TO HR92347					
HR92356	2001/12/21	DISCH OF CHARGE		*** COMPLETELY DELETED ***		
				E. LIPTAY ENTERPRISES LTD.		
	REMARKS: RE: H815373					
HR92357	2001/12/21	DISCH OF CHARGE		*** COMPLETELY DELETED ***		
				E. LIPTAY ENTERPRISES LTD.		
	REMARKS: RE: H831639					
HR92358	2001/12/21	DISCH OF CHARGE		*** COMPLETELY DELETED ***		
				E. LIPTAY ENTERPRISES LTD.		
	REMARKS: RE: H838945					
HR92359	2001/12/21	DISCH OF CHARGE		*** COMPLETELY DELETED ***		
				E. LIPTAY ENTERPRISES LTD.		
	REMARKS: RE: H844637					
HR92360	2001/12/21	DISCH OF CHARGE		*** COMPLETELY DELETED ***		

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
				E. LIPTAY ENTERPRISES LTD.		
	REMARKS: RE: H853051					
HR92361	2001/12/21	DISCH OF CHARGE		*** COMPLETELY DELETED *** E. LIPTAY ENTERPRISES LTD.		
	REMARKS: RE: H854839					
HR92362	2001/12/21	DISCH OF CHARGE		*** COMPLETELY DELETED *** E. LIPTAY ENTERPRISES LTD.		
	REMARKS: RE: HR34769					
HR92363	2001/12/21	DISCH OF CHARGE		*** COMPLETELY DELETED *** E. LIPTAY ENTERPRISES LTD.		
	REMARKS: RE: HR42981					
HR92364	2001/12/21	DISCH OF CHARGE		*** COMPLETELY DELETED *** E. LIPTAY ENTERPRISES LTD.		
	REMARKS: RE: HR54580					
HR177057	2003/02/06	LIEN		*** COMPLETELY DELETED *** HER MAJESTY THE QUEEN IN RIGHT OF CANADA AS REPRESENTED BY THE MINISTER OF NATIONAL REVENUE		
HR191309	2003/04/17	CHARGE		*** COMPLETELY DELETED *** KARA HOLDING INC.	E. LIPTAY ENTERPRISES LTD.	
HR191315	2003/04/17	POSTPONEMENT		*** COMPLETELY DELETED *** KARA, YUNUS	E. LIPTAY ENTERPRISES LTD.	
	REMARKS: H807390 TO HR191309					
HR191317	2003/04/17	CHARGE		*** COMPLETELY DELETED *** KARA HOLDING INC.	E. LIPTAY ENTERPRISES LTD.	
HR191320	2003/04/17	POSTPONEMENT		*** COMPLETELY DELETED *** KARA, YUNUS	E. LIPTAY ENTERPRISES LTD.	
	REMARKS: H807390 TO HR191317					
HR191323	2003/04/17	CHARGE		*** COMPLETELY DELETED *** KARA HOLDING INC.	E. LIPTAY ENTERPRISES LTD.	
HR191326	2003/04/17	POSTPONEMENT		*** COMPLETELY DELETED *** KARA, YUNUS	E. LIPTAY ENTERPRISES LTD.	
	REMARKS: H807390 TO HR191323					

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
HR204912	2003/06/20	CHARGE		*** COMPLETELY DELETED *** KARA HOLDING INC.	1057854 ONTARIO INC.	
	REMARKS: DELETED 2018/02/07 PER HR654890.					
HR204915	2003/06/20	DISCH OF CHARGE		*** COMPLETELY DELETED *** E. LIPTAY ENTERPRISES LTD.		
	REMARKS: RE: HR191323					
HR204916	2003/06/20	DISCH OF CHARGE		*** COMPLETELY DELETED *** E. LIPTAY ENTERPRISES LTD.		
	REMARKS: RE: HR92347					
HR204917	2003/06/20	DISCH OF CHARGE		*** COMPLETELY DELETED *** E. LIPTAY ENTERPRISES LTD.		
	REMARKS: RE: HR191309					
HR204918	2003/06/20	DISCH OF CHARGE		*** COMPLETELY DELETED *** E. LIPTAY ENTERPRISES LTD.		
	REMARKS: RE: HR191317					
HR204919	2003/06/20	DISCH OF CHARGE		*** COMPLETELY DELETED *** KARA, YUNUS		
	REMARKS: RE: H807390					
HR204983	2003/06/20	NO ASSGN RENT GEN		*** COMPLETELY DELETED *** KARA HOLDING INC.	1057854 ONTARIO INC.	
	REMARKS: HR204912					
HR205234	2003/06/23	DISCHARGE INTEREST		*** COMPLETELY DELETED ***	HER MAJESTY THE QUEEN IN RIGHT OF CANADA AS REPRESENTED BY THE MINISTER OF NATIONAL REVENUE	
	REMARKS: RE: HR177057					
HR246878	2003/11/28	CHARGE		*** COMPLETELY DELETED *** KARA HOLDING INC.	CANADIAN IMPERIAL BANK OF COMMERCE	
HR248428	2003/12/03	LIEN		*** COMPLETELY DELETED *** HER MAJESTY THE QUEEN IN RIGHT OF CANADA AS REPRESENTED BY THE MINISTER OF NATIONAL REVENUE		
	REMARKS: $47,492.63					
HR267437	2004/03/01	CHARGE		*** COMPLETELY DELETED ***		

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
				KARA HOLDING INC.	E. LIPTAY ENTERPRISES LTD.	
HR323373	2004/09/28	CONSTRUCTION LIEN		*** COMPLETELY DELETED *** KARP NAMISNIAK YAMAMOTO ARCHITECTS INC.		
HR335312	2004/11/12	CERTIFICATE		*** COMPLETELY DELETED *** KARP NAMISNIAK YAMAMOTO ARCHITECTS INC.		
	REMARKS: HR323373					
HR369326	2005/04/13	CHARGE		*** COMPLETELY DELETED *** KARA HOLDING INC.	MURRAY RONALD MCENIRY	
HR369327	2005/04/13	CHARGE		*** COMPLETELY DELETED *** KARA HOLDING INC.	MURRAY RONALD MCENIRY	
HR388549	2005/06/27	TRANSFER OF CHARGE		*** COMPLETELY DELETED *** 1057854 ONTARIO INC.	MINTZ, IRWIN	
	REMARKS: HR204912					
HR388563	2005/06/27	NO ASSGN RENT GEN		*** COMPLETELY DELETED *** 1057854 ONTARIO INC.	MINTZ, IRWIN	
	REMARKS: ASSIGNMENT OF ASSIGNMENT OF RENTS - HR204983					
HR391089	2005/07/05	CAUTION-LAND		*** COMPLETELY DELETED *** KARA HOLDING INC.	KARA HOLDING INC.	
HR447358	2006/01/17	LIEN		*** COMPLETELY DELETED *** HER MAJESTY THE QUEEN IN RIGHT OF CANADA AS REPRESENTED BY THE MINISTER OF NATIONAL REVENUE		
HR654890	2008/04/11	TRANS POWER SALE		*** COMPLETELY DELETED *** MINTZ, IRWIN	2118218 ONTARIO INC.	
	REMARKS: HR204912					
HR654891	2008/04/11	CHARGE		*** COMPLETELY DELETED *** 2118218 ONTARIO INC.	781526 ONTARIO INC.	
HR654892	2008/04/11	NO ASSGN RENT GEN		*** COMPLETELY DELETED *** 2118218 ONTARIO INC.	781526 ONTARIO INC.	
	REMARKS: HR654891					
HR654893	2008/04/11	CHARGE		*** COMPLETELY DELETED *** 2118218 ONTARIO INC.	MINTZ, IRWIN	

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
HR654980	2008/04/11	APL (GENERAL)		*** COMPLETELY DELETED *** 2118218 ONTARIO INC.		
	REMARKS: DELETE HR92245 & HR92325					
HR654981	2008/04/11	APL (GENERAL)		*** COMPLETELY DELETED *** 2118218 ONTARIO INC.		
	REMARKS: DELETE HR92246 & HR92326					
HR654982	2008/04/11	APL (GENERAL)		*** COMPLETELY DELETED *** 2118218 ONTARIO INC.		
	REMARKS: DELETE HR92247 & HR92327					
HR654983	2008/04/11	APL (GENERAL)		*** COMPLETELY DELETED *** 2118218 ONTARIO INC.		
	REMARKS: DELETE HR92248 & HR92328					
HR654984	2008/04/11	APL (GENERAL)		*** COMPLETELY DELETED *** 2118218 ONTARIO INC.		
	REMARKS: DELETE HR92250 & HR92330					
HR654985	2008/04/11	APL (GENERAL)		*** COMPLETELY DELETED *** 2118218 ONTARIO INC.		
	REMARKS: DELETE HR92251 & HR92331					
HR654986	2008/04/11	APL (GENERAL)		*** COMPLETELY DELETED *** 2118218 ONTARIO INC.		
	REMARKS: DELETE HR92252 & HR92332					
HR655407	2008/04/15	DISCH OF CHARGE		*** COMPLETELY DELETED *** CIBC MORTGAGES INC.		
	REMARKS: RE: HR92220					
HR655410	2008/04/15	NO ASSG LESSOR INT		*** COMPLETELY DELETED *** CIBC MORTGAGES INC.	2118218 ONTARIO INC.	
	REMARKS: HR92249 & HR92329					
HR655411	2008/04/15	NO ASSG LESSOR INT		*** COMPLETELY DELETED *** CIBC MORTGAGES INC.	2118218 ONTARIO INC.	
	REMARKS: HR92253 & HR92333					
HR681099	2008/07/17	CAUTION-LAND		*** COMPLETELY DELETED *** 2118218 ONTARIO INC.	KARA HOLDING INC.	

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
HR1550381	2018/06/20	APL (GENERAL)		*** COMPLETELY DELETED *** THE CORPORATION OF THE CITY OF BURLINGTON		
	REMARKS: DELETE Z286594, Z306168, Z362226 AND 286596					
HR1591709	2018/12/10	APL (GENERAL)		*** COMPLETELY DELETED *** 2118218 ONTARIO INC.		
	REMARKS: HR92249, HR92329, HR92333, HR655411,					
HR1591710	2018/12/10	DISCH OF CHARGE		*** COMPLETELY DELETED *** 781526 ONTARIO INC.		
	REMARKS: HR654891.					
HR1591711	2018/12/10	DISCH OF CHARGE		*** COMPLETELY DELETED *** MINTZ, IRWIN		
	REMARKS: HR654893.					
HR1592017	2018/12/11	TRANSFER	$6,200,000	2118218 ONTARIO INC.	ARCHANGEL RAPHAEL & ST. MARINA COPTIC ORTHODOX CHURCH	C
	REMARKS: PLANNING ACT STATEMENTS.					
HR1592018	2018/12/11	CHARGE	$4,250,000	ARCHANGEL RAPHAEL & ST. MARINA COPTIC ORTHODOX CHURCH	THE BANK OF NOVA SCOTIA	C
HR1592019	2018/12/11	NO ASSGN RENT GEN		ARCHANGEL RAPHAEL & ST. MARINA COPTIC ORTHODOX CHURCH	THE BANK OF NOVA SCOTIA	C
	REMARKS: HR1592018.					

Appendix E: Ecolog ERIS Report

ENVIRONMENTAL RISK INFORMATION SERVICES

DATABASE REPORT

Project Property:	*1160 Blair Road, Burlington, ON* *1160 Blair Road* *Burlington ON L7M 1K9*
Project No:	*HAM-00801245-G0*
Report Type:	*RSC Report (Urban)*
Order No:	*20180518055*
Requested by:	*exp Services Inc.*
Date Completed:	*May 24, 2018*

Environmental Risk Information Services
A division of Glacier Media Inc.
P: 1.866.517.5204
E: info@erisinfo.com

www.erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....6
Executive Summary: Site Report Summary - Surrounding Properties.....8
Executive Summary: Summary By Data Source.....35
Map.....69
Aerial.....70
Topographic Map.....71
Detail Report.....72
Unplottable Summary.....480
Unplottable Report.....482
Appendix: Database Descriptions.....491
Definitions.....500

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Limited Partnership ("ERIS") using various sources of information, including information provided by Federal and Provincial government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report(s) are protected by copyright owned by ERIS Information Limited Partnership. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:	*1160 Blair Road, Burlington, ON* *1160 Blair Road Burlington ON L7M 1K9*
Project No:	*HAM-00801245-G0*

Order Information:

Order No:	*20180518055*
Date Requested:	*May 18, 2018*
Requested by:	*exp Services Inc.*
Report Type:	*RSC Report (Urban)*

Historical/Products:

Topographic Map	*Ontario Base Map (OBM)*

Executive Summary: Report Summary

Database	Name	Searched	Project Property	Boundary to 0.30km	Total
AAGR	*Abandoned Aggregate Inventory*	Y	0	0	0
AGR	*Aggregate Inventory*	Y	0	0	0
AMIS	*Abandoned Mine Information System*	Y	0	0	0
ANDR	*Anderson's Waste Disposal Sites*	Y	0	0	0
AUWR	*Automobile Wrecking & Supplies*	Y	0	0	0
BORE	*Borehole*	Y	0	2	2
CA	*Certificates of Approval*	Y	0	24	24
CFOT	*Commercial Fuel Oil Tanks*	Y	0	0	0
CHEM	*Chemical Register*	Y	0	4	4
CNG	*Compressed Natural Gas Stations*	Y	0	0	0
COAL	*Inventory of Coal Gasification Plants and Coal Tar Sites*	Y	0	0	0
CONV	*Compliance and Convictions*	Y	0	0	0
CPU	*Certificates of Property Use*	Y	0	0	0
DRL	*Drill Hole Database*	Y	0	0	0
DRYCLEANERS	*Dry Cleaning Facilities*	Y	0	0	0
EASR	*Environmental Activity and Sector Registry*	Y	0	1	1
EBR	*Environmental Registry*	Y	0	19	19
ECA	*Environmental Compliance Approval*	Y	0	19	19
EEM	*Environmental Effects Monitoring*	Y	0	0	0
EHS	*ERIS Historical Searches*	Y	1	39	40
EIIS	*Environmental Issues Inventory System*	Y	0	0	0
EMHE	*Emergency Management Historical Event*	Y	0	0	0
EXP	*List of TSSA Expired Facilities*	Y	9	11	20
FCON	*Federal Convictions*	Y	0	0	0
FCS	*Contaminated Sites on Federal Land*	Y	0	0	0
FOFT	*Fisheries & Oceans Fuel Tanks*	Y	0	0	0
FST	*Fuel Storage Tank*	Y	0	0	0
FSTH	*Fuel Storage Tank - Historic*	Y	1	0	1
GEN	*Ontario Regulation 347 Waste Generators Summary*	Y	4	331	335
GHG	*Greenhouse Gas Emissions from Large Facilities*	Y	0	0	0
HINC	*TSSA Historic Incidents*	Y	0	0	0
IAFT	*Indian & Northern Affairs Fuel Tanks*	Y	0	0	0
INC	*TSSA Incidents*	Y	0	0	0
LIMO	*Landfill Inventory Management Ontario*	Y	0	0	0
MINE	*Canadian Mine Locations*	Y	0	0	0
MISA PENALTY	*Environmental Penalty Annual Report*	Y	0	0	0

Database	Name	Searched	Project Property	Boundary to 0.30km	Total
MNR	Mineral Occurrences	Y	0	0	0
NATE	National Analysis of Trends in Emergencies System (NATES)	Y	0	0	0
NCPL	Non-Compliance Reports	Y	0	0	0
NDFT	National Defense & Canadian Forces Fuel Tanks	Y	0	0	0
NDSP	National Defense & Canadian Forces Spills	Y	0	0	0
NDWD	National Defence & Canadian Forces Waste Disposal Sites	Y	0	0	0
NEBI	National Energy Board Pipeline Incidents	Y	0	0	0
NEBW	National Energy Board Wells	Y	0	0	0
NEES	National Environmental Emergencies System (NEES)	Y	0	0	0
NPCB	National PCB Inventory	Y	0	3	3
NPRI	National Pollutant Release Inventory	Y	0	49	49
OGW	Oil and Gas Wells	Y	0	0	0
OOGW	Ontario Oil and Gas Wells	Y	0	0	0
OPCB	Inventory of PCB Storage Sites	Y	0	2	2
ORD	Orders	Y	0	0	0
PAP	Canadian Pulp and Paper	Y	0	5	5
PCFT	Parks Canada Fuel Storage Tanks	Y	0	0	0
PES	Pesticide Register	Y	0	1	1
PINC	TSSA Pipeline Incidents	Y	0	0	0
PRT	Private and Retail Fuel Storage Tanks	Y	2	2	4
PTTW	Permit to Take Water	Y	0	0	0
REC	Ontario Regulation 347 Waste Receivers Summary	Y	0	4	4
RSC	Record of Site Condition	Y	0	2	2
RST	Retail Fuel Storage Tanks	Y	0	0	0
SCT	Scott's Manufacturing Directory	Y	4	130	134
SPL	Ontario Spills	Y	1	10	11
SRDS	Wastewater Discharger Registration Database	Y	0	0	0
TANK	Anderson's Storage Tanks	Y	0	0	0
TCFT	Transport Canada Fuel Storage Tanks	Y	0	0	0
VAR	TSSA Variances for Abandonment of Underground Storage Tanks	Y	0	0	0
WDS	Waste Disposal Sites - MOE CA Inventory	Y	0	0	0
WDSH	Waste Disposal Sites - MOE 1991 Historical Approval Inventory	Y	0	0	0
WWIS	Water Well Information System	Y	1	25	26
	Total:		23	683	706

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
1	EHS		1160 Blair Rd Burlington ON L7M1K9	-/0.0	0.10	72
1	EXP	GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD	1160 BLAIR RD BURLINGTON ON	-/0.0	0.10	72
1	EXP	GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD	1160 BLAIR RD BURLINGTON ON	-/0.0	0.10	72
1	EXP	GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD	1160 BLAIR RD BURLINGTON ON L7M 1K9	-/0.0	0.10	72
1	EXP	GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD	1160 BLAIR RD BURLINGTON ON	-/0.0	0.10	73
1	EXP	GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD	1160 BLAIR RD BURLINGTON ON L7M 1K9	-/0.0	0.10	73
1	EXP	LOOMIS COURIER SERVICE	1160 BLAIR RD BURLINGTON ON	-/0.0	0.10	73
1	EXP	LOOMIS COURIER SERVICE	1160 BLAIR RD BURLINGTON ON	-/0.0	0.10	73
1	EXP	GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD	1160 BLAIR RD BURLINGTON ON L7M 1K9	-/0.0	0.10	74
1	EXP	GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD	1160 BLAIR RD BURLINGTON ON L7M 1K9	-/0.0	0.10	74
1	FSTH	GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD	1160 BLAIR RD BURLINGTON ON L7M 1K9	-/0.0	0.10	74
1	GEN	Royal Lepage State Realty Brokerage	1160 Blair Road Burlington ON L7M 1K9	-/0.0	0.10	75
1	GEN	s.e. sales and service ltd	1160 blair rd burlington ON L7M 1K9	-/0.0	0.10	75
1	GEN	JENMAR COLOUR SEPARATIONS INC.	1160 BLAIR RD. BURLINGTON ON L7M 1K9	-/0.0	0.10	75
1	GEN	JENMAR COLOUR SEPARATIONS INC. 22-133	1160 BLAIR RD. BURLINGTON ON L7M 1K9	-/0.0	0.10	76
1	PRT	GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD	1160 BLAIR RD BURLINGTON ON L7M 1K9	-/0.0	0.10	76

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
1	PRT	LOOMIS COURIER SERVICE	1160 BLAIR RD BURLINGTON ON	-/0.0	0.10	76
1	SCT	Northcote Industrial Products	1160 Blair Rd Floor 2 Unit D Burlington ON L7M 1K9	-/0.0	0.10	76
1	SCT	Northcote Industrial Products Inc.	1160 Blair Rd Floor 2 Unit D Burlington ON L7M 1K9	-/0.0	0.10	76
1	SCT	ALL-TIG LTD	1160 BLAIR RD UNIT A1 BURLINGTON ON L7M 1K9	-/0.0	0.10	77
1	SCT	VERSA-HOE EQUIPMENT CORP.	1160 Blair Rd Floor 2 Unit D Burlington ON L7M 1K9	-/0.0	0.10	77
1	SPL	LOOMIS COURIER	1160 BLAIR ROAD BURLINGTON CITY ON L7M 1K9	-/0.0	0.10	77
2	WWIS		lot 12 con 2 BURLINGTON ON	-/0.0	-0.05	78

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
3	SCT	Atlas Copco Construction and Mining Canada	Burlington ON L7M 1P9	NNE/13.4	0.18	80
4	GEN	SIMON CRANE RENTAL LTD.	1150 BLAIR ROAD, UNIT 6 BURLINGTON ON L7M 1K9	ESE/18.9	-0.90	80
4	GEN	SIMON CRANE RENTAL LTD.	1150 BLAIR ROAD, UNIT 6 BURLINGTON ON L7M 1K9	ESE/18.9	-0.90	81
4	GEN	SIMON CRANE RENTAL LTD.	1150 BLAIR ROAD, UNIT 6 BURLINGTON ON L7M 1K9	ESE/18.9	-0.90	81
4	GEN	SIMON CRANE RENTAL LTD.	1150 BLAIR ROAD, UNIT 6 BURLINGTON ON L7M 1K9	ESE/18.9	-0.90	82
4	GEN	SIMON CRANE RENTAL LTD.	1150 BLAIR ROAD, UNIT 6 BURLINGTON ON L7M 3T4	ESE/18.9	-0.90	82
4	GEN	SIMON CRANE RENTAL LTD.	1150 BLAIR ROAD, UNIT 6 BURLINGTON ON L7M 3T4	ESE/18.9	-0.90	82
4	GEN	SIMON CRANE RENTAL LTD.	1150 BLAIR ROAD, UNIT #6 BURLINGTON ON L7M 3T4	ESE/18.9	-0.90	83
4	GEN	A.W. CHESTERTON COMPANY LTD.	1150 BLAIR ROAD BURLINGTON ON L7M 3T4	ESE/18.9	-0.90	83
4	GEN	A.W. CHESTERTON	1150 BLAIR ROAD BURLINGTON ON L7M 3T4	ESE/18.9	-0.90	84
4	GEN	SIMON CRANE RENTAL LTD.	1150 BLAIR ROAD, UNIT 6 BURLINGTON ON L7M 3T4	ESE/18.9	-0.90	84
4	GEN	SIMON CRANE RENTAL LTD.	1150 BLAIR ROAD, UNIT 6 BURLINGTON ON L7M 3T4	ESE/18.9	-0.90	85
4	GEN	SIMON CRANE RENTAL LTD.	1150 BLAIR ROAD, UNIT 6 BURLINGTON ON	ESE/18.9	-0.90	85
4	SCT	Northern Industrial Supply	1150 Blair Rd Unit 1S Burlington ON L7M 3T4	ESE/18.9	-0.90	85
4	SCT	KENWARD TOOL & DIE LTD	1150 BLAIR RD BURLINGTON ON L7M 3T4	ESE/18.9	-0.90	86
4	SCT	J R TOOL & DIE	1150 BLAIR RD UNIT 5 BURLINGTON ON L7M 3T4	ESE/18.9	-0.90	86
4	SCT	A W CHESTERTON COMPANY LTD.	1150 BLAIR RD BURLINGTON ON L7M 3T4	ESE/18.9	-0.90	86
4	SCT	S O S Cylinders Inc.	1150 Blair Rd Unit 2 Burlington ON L7M 3T4	ESE/18.9	-0.90	87
4	SCT	Northern Integrated Systems Co	1150 Blair Rd Unit 1 Burlington ON L7M 3T4	ESE/18.9	-0.90	87
4	SCT	J R Tool & Die Ltd.	1150 Blair Rd Unit 5 Burlington ON L7M 3T4	ESE/18.9	-0.90	87
4	WWIS		BURLINGTON ON	ESE/18.9	-0.90	87
5	BORE		ON	SW/32.1	-0.05	90
6	BORE		ON	SW/34.7	-0.93	90

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
7	CA	Atlas Copco Canada Inc.	1157 Blair Road Burlington ON L7M 1P9	NNE/57.1	0.43	91
7	EBR	Atlas Copco Canada Inc.	1157 Blair Road Burlington Ontario Burlington ON	NNE/57.1	0.43	91
7	EBR	Wardco Window and Door Manufacturing Inc.	1157 Blair Road Burlington, Regional Municipality of Halton L7M 1P9 CITY OF BURLINGTON ON	NNE/57.1	0.43	91
7	ECA	Atlas Copco Canada Inc.	1157 Blair Road Burlington ON H8N 3A9	NNE/57.1	0.43	92
7	ECA	Wardco Window and Door Manufacturing Inc.	1157 Blair Road City of Burlington ON	NNE/57.1	0.43	92
7	ECA	Wardco Window and Door Manufacturing Inc.	1157 Blair Rd Burlington ON	NNE/57.1	0.43	92
7	EHS		1157 BLAIR RD BURLINGTON ON L7M 1P9	NNE/57.1	0.43	92
7	GEN	FAGERSTA SECOROC LTD 15-019	1157 BLAIR RD BURLINGTON ON L7M 1P9	NNE/57.1	0.43	93
7	GEN	Wardco Window & Door Manufacturing	1157 Blair Road Burlington ON L7M 1P9	NNE/57.1	0.43	93
7	GEN	Atlas Copco Canada Inc.	1157 Blair Road Burlington ON L7M 7P9	NNE/57.1	0.43	93
7	GEN	Atlas Copco Canada Inc.	1157 Blair Road Burlington ON L7M 1P9	NNE/57.1	0.43	94
7	GEN	FAGERSTA SECOROC LTD	1157 BLAIR RD BURLINGTON ON L7M 1P9	NNE/57.1	0.43	94
7	GEN	Atlas Copco Canada	1157 Blair Road Burlington ON L7M 1P9	NNE/57.1	0.43	94
7	GEN	Atlas Copco Canada Inc.	1157 Blair Road Burlington ON L7M 7P9	NNE/57.1	0.43	95
7	GEN	Atlas Copco Canada Inc.	1157 Blair Road Burlington ON L7M 1P9	NNE/57.1	0.43	95
7	GEN	FAGERSTA SECOROC LTD.(OUT OF BUSINESS)	1157 BLAIR ROAD BURLINGTON ON L7M 1P9	NNE/57.1	0.43	95
7	GEN	XCG Consultants Ltd.	1157 Blair Road Burlington ON	NNE/57.1	0.43	96
7	GEN	Atlas Copco Canada Inc.	1157 Blair Road Burlington ON L7M 1P9	NNE/57.1	0.43	96
7	GEN	Atlas Copco Canada Inc.	1157 Blair Road Burlington ON L7M 1P9	NNE/57.1	0.43	96
7	GEN	Atlas Copco Canada Inc.	1157 Blair Road Burlington ON L7M 7P9	NNE/57.1	0.43	97
7	GEN	Wardco Window & Door Manufacturing	1157 Blair Road Burlington ON L7M 1P9	NNE/57.1	0.43	97
7	GEN	Wardco Window & Door Manufacturing	1157 Blair Road Burlington ON L7M 1P9	NNE/57.1	0.43	97
7	GEN	Screenplay Designs Inc	1157 Blair Road Burlington ON L7M 1P9	NNE/57.1	0.43	98
7	GEN	Atlas Copco Canada Inc.	1157 Blair Road Burlington ON L7M 1P9	NNE/57.1	0.43	98
7	GEN	Wardco Window & Door Manufacturing	1157 Blair Road Burlington ON	NNE/57.1	0.43	98

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
7	GEN	Wardco Window & Door Manufacturing	1157 Blair Road Burlington ON L7M 1P9	NNE/57.1	0.43	99
7	GEN	Atlas Copco Canada Inc.	1157 Blair Road Burlington ON L7M 7P9	NNE/57.1	0.43	99
7	GEN	Atlas Copco Canada Inc.	1157 Blair Road Burlington ON	NNE/57.1	0.43	99
7	GEN	Wardco Window & Door Manufacturing	1157 Blair Road Burlington ON	NNE/57.1	0.43	100
7	SCT	ATLAS COPCO CONSTRUCTION	1157 BLAIR RD BURLINGTON ON L7M 1P9	NNE/57.1	0.43	10
7	SCT	Atlas Copco Construction and Mining Canada	1157 Blair Rd Burlington ON L7M 1P9	NNE/57.1	0.43	100
7	SPL	Atlas Copco Canada Inc.<UNOFFICIAL>	1157 Blair Rd., Burlington Burlington ON L7M 1P9	NNE/57.1	0.43	100
7	WWIS		BURLINGTON ON	NNE/57.1	0.43	101
7	WWIS		Burlington ON	NNE/57.1	0.43	103
8	SCT	Conspec Controls Ltd.	1180 Blair Rd Burlington ON L7M 1K9	N/67.0	1.07	121
9	WWIS		ON	ENE/69.0	-1.42	121
10	GEN	SWISSLINE INDUSTRIES LTD. 36-732	3300 MAINWAY BURLINGTON ON L7M 1A7	W/69.8	1.07	122
10	SCT	JCP Belt Components Inc.	3300 Mainway Burlington ON L7M 1A7	W/69.8	1.07	122
10	SCT	VERNS METAL STAMPING INC.	3300 MAINWAY DR UNIT 1 BURLINGTON ON L7M 1A7	W/69.8	1.07	12
10	SCT	JONES TOOL & MACHINE CO. LTD.	3300 MAINWAY DR UNIT 1 BURLINGTON ON L7M 1A7	W/69.8	1.07	12
10	SCT	JCP Belt Components Inc.	3300 Mainway Dr Burlington ON L7M 1A7	W/69.8	1.07	123
11	EHS		1140 Blair Rd Burlington ON L7M1K9	SE/75.3	-1.91	123
11	EHS		1140 Blair Rd Burlington ON L7M1K9	SE/75.3	-1.91	123
11	GEN	JONES NEON DISPLAYS LIMITED	1140 BLAIR ROAD BURLINGTON ON L7M 1K9	SE/75.3	-1.91	124
11	GEN	JONES NEON DISPLAYS LIMITED	1140 BLAIR ROAD BURLINGTON ON L7M 1K9	SE/75.3	-1.91	124
11	GEN	JONES NEON DISPLAYS LIMITED	1140 BLAIR ROAD BURLINGTON ON L7M 1K9	SE/75.3	-1.91	124
11	GEN	JONES NEON DISPLAYS LIMITED	1140 BLAIR ROAD BURLINGTON ON L7M 1K9	SE/75.3	-1.91	125
11	GEN	JONES NEON DISPLAYS LIMITED	1140 BLAIR ROAD BURLINGTON ON L7M 1K9	SE/75.3	-1.91	125
11	GEN	JONES NEON DISPLAYS LIMITED	1140 BLAIR ROAD BURLINGTON ON L7M 1K9	SE/75.3	-1.91	125
11	GEN	JONES NEON DISPLAYS LIMITED	1140 BLAIR ROAD BURLINGTON ON L7M 1K9	SE/75.3	-1.91	125
11	GEN	JONES NEON DISPLAYS LIMITED	1140 BLAIR ROAD BURLINGTON ON L7M 1K9	SE/75.3	-1.91	126

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
11	GEN	JONES NEON DISPLAYS LIMITED	1140 BLAIR ROAD BURLINGTON ON L7M 1K9	SE/75.3	-1.91	126
11	GEN	JONES NEON DISPLAYS LIMITED	1140 BLAIR ROAD BURLINGTON ON	SE/75.3	-1.91	126
11	SCT	Jones Neon Displays Ltd.	1140 Blair Rd Burlington ON L7M 1K9	SE/75.3	-1.91	12
11	SPL	BURLINGTON HYDRO-ELECTRIC COMM	1140 BLAIR ROAD TRANSFORMER BURLINGTON CITY ON L7M 1K9	SE/75.3	-1.91	127
12	CA	690661 Ontario Limited	3388 Mainway Drive Burlington ON L7M 1A8	N/75.9	1.07	127
12	EBR	690661 Ontario Limited	3388 Mainway Drive Burlington Ontario L7M 1A8 Burlington ON	N/75.9	1.07	128
12	ECA	690661 Ontario Limited	3388 Mainway Drive Burlington ON L7M 1A8	N/75.9	1.07	128
12	GEN	THOMAS WIRE DIE LIMITED 37-113	P.O. BOX 352 3388 MAINWAY DRIVE BURLINGTON ON L7M 1A8	N/75.9	1.07	128
12	GEN	THOMAS WIRE DIE LIMITED	P.O. BOX 352 3388 MAINWAY DRIVE BURLINGTON ON L7M 1A8	N/75.9	1.07	129
12	GEN	CANFANCO INC.	3388 Mainway Burlington ON L7M 1A8	N/75.9	1.07	129
12	SCT	CANFANCO INC.	3388 Mainway Dr Burlington ON L7M 1A8	N/75.9	1.07	129
12	SCT	CANADIAN FANNER CO. LTD.	3388 MAINWAY DR BURLINGTON ON L7M 1A8	N/75.9	1.07	13
13	EHS		3330 Mainway Burlington ON L7M1A7	NW/77.8	1.07	130
14	WWIS		BURLINGTON ON	SW/78.6	0.00	130
15	CA		3400 Landmark Road Burlington ON L7M 1S8	ENE/79.1	-1.79	133
15	CA	Airmax Compressor Services Ltd.	3400 Landmark Rd Burlington ON L7M 1S8	ENE/79.1	-1.79	133
15	EBR	Airmax Compressor Services Ltd.	3400 Landmark Road Burlington Regional Municipality Of Halton L7M 1S8 CITY OF BURLINGTON ON	ENE/79.1	-1.79	133
15	EBR	Millcraft Systems Inc.	3400 Landmark Road Burlington Ontario L7M 1S8 Burlington ON	ENE/79.1	-1.79	134
15	ECA	Airmax Compressor Services Ltd.	3400 Landmark Rd Burlington ON L7M 1S8	ENE/79.1	-1.79	134
15	EHS		3400 Landmark Road Burlington ON L7M 1S8	ENE/79.1	-1.79	134
15	GEN	Airmax Compressor Services Ltd.	3400 Landmark Rd. Units 9 & 10 Burlington ON L7M 1S8	ENE/79.1	-1.79	135
15	GEN	Airmax Compressor Services Ltd.	3400 Landmark Rd. Units 9 & 10 Burlington ON L7M 1S8	ENE/79.1	-1.79	135
15	GEN	Airmax Compressor Services Ltd.	3400 Landmark Rd. Units 9 & 10 Burlington ON L7M 1S8	ENE/79.1	-1.79	136
15	GEN	Airmax Compressor Services Ltd.	3400 Landmark Rd. Units 9 & 10 Burlington ON L7M 1S8	ENE/79.1	-1.79	136
15	GEN	L & A Diecrafts Ltd.	3400 Landmark Rd. #5-10 Burlington ON L7M 1S8	ENE/79.1	-1.79	136

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
15	GEN	Airmax Compressor Services Ltd.	3400 Landmark Rd. Units 9 & 10 Burlington ON L7M 1S8	ENE/79.1	-1.79	137
15	GEN	Ascona Management & Consulting Inc.	3400 Landmark Road Units 1 & 2 Burlington ON L7M 1S8	ENE/79.1	-1.79	137
15	GEN	Airmax Compressor Services Ltd.	3400 Landmark Rd. Units 9 & 10 Burlington ON L7M 1S8	ENE/79.1	-1.79	138
15	GEN	Airmax Compressor Services Ltd.	3400 Landmark Rd. Units 9 & 10 Burlington ON L7M 1S8	ENE/79.1	-1.79	138
15	GEN	Airmax Compressor Services Ltd.	3400 Landmark Rd. Units 9 & 10 Burlington ON L7M 1S8	ENE/79.1	-1.79	138
15	SCT	NATURAL TEMPTATIONS INC	3400 LANDMARK RD UNIT 4 BURLINGTON ON L7M 1S8	ENE/79.1	-1.79	13
15	SCT	Natural Temptations Inc.	3400 Landmark Rd Unit 4 Burlington ON L7M 1S8	ENE/79.1	-1.79	139
15	SCT	Millcraft Systems Inc.	3400 Landmark Rd Unit 1-2 Burlington ON L7M 1S8	ENE/79.1	-1.79	139
15	SCT	L & A DIECRAFTS LTD	3400 LANDMARK RD UNIT 5-10 BURLINGTON ON L7M 1S8	ENE/79.1	-1.79	14
15	SCT	L & A Diecrafts Ltd.	3400 Landmark Rd Unit 5-10 Burlington ON L7M 1S8	ENE/79.1	-1.79	140
15	SCT	CANADIAN COUNTRY CANDLES	3400 LANDMARK RD UNIT 2 BURLINGTON ON L7M 1S8	ENE/79.1	-1.79	14
16	EXP	AUTOMOTIVE MANAGER BELL CANADA	1171 PIONEER RD BURLINGTON ON	SW/82.9	-0.88	141
16	EXP	AUTOMOTIVE MANAGER BELL CANADA	1171 PIONEER RD BURLINGTON ON	SW/82.9	-0.88	141
16	EXP	AUTOMOTIVE MANAGER BELL CANADA	1171 PIONEER RD BURLINGTON ON	SW/82.9	-0.88	141
16	EXP	AUTOMOTIVE MANAGER BELL CANADA	1171 PIONEER RD BURLINGTON ON L7M 1K5	SW/82.9	-0.88	141
16	EXP	AUTOMOTIVE MANAGER BELL CANADA	1171 PIONEER RD BURLINGTON ON	SW/82.9	-0.88	142
16	EXP	AUTOMOTIVE MANAGER BELL CANADA	1171 PIONEER RD BURLINGTON ON L7M 1K5	SW/82.9	-0.88	142
16	EXP	AUTOMOTIVE MANAGER BELL CANADA	1171 PIONEER RD BURLINGTON ON L7M 1K5	SW/82.9	-0.88	142
16	GEN	Bell Canada	1171 Pioneer Rd Burlington ON L7M 1K5	SW/82.9	-0.88	142
16	GEN	BELL CANADA 05-525	1171 PIONEER RD., BURLINGTON C/O 20 NORELCO DRIVE NORTH YORK ON L7M 1K5	SW/82.9	-0.88	143
16	GEN	Bell Canada	1171 Pioneer Rd Burlington ON L7M 1K5	SW/82.9	-0.88	144
16	GEN	BELL CANADA	1171 PIONEER RD. BURLINGTON ON L7M 1K5	SW/82.9	-0.88	145
16	GEN	BELL CANADA	1171 PIONEER ROAD BURLINGTON ON L7M 1K5	SW/82.9	-0.88	145
16	GEN	Bell Canada	1171 Pioneer Rd Burlington ON L7M 1K5	SW/82.9	-0.88	146
16	GEN	Bell Canada	1171 Pioneer Rd Burlington ON L7M 1K5	SW/82.9	-0.88	147
16	GEN	Bell Canada	1171 Pioneer Rd Burlington ON L7M 1K5	SW/82.9	-0.88	147

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
16	GEN	Bell Canada	1171 Pioneer Rd Burlington ON L7M 1K5	SW/82.9	-0.88	148
16	GEN	Bell Canada	1171 Pioneer Rd Burlington ON L7M 1K5	SW/82.9	-0.88	149
16	GEN	Bell Canada	1171 Pioneer Rd Burlington ON L7M 1K5	SW/82.9	-0.88	150
16	GEN	BELL CANADA	1171 PIONEER RD., BURLINGTON C/O 483 BAY ST. FL. 6 S. TOWER TORONTO ON L7M 1K5	SW/82.9	-0.88	150
16	GEN	BELL CANADA 05-525	1171 PIONEER ROAD BURLINGTON ON L7M 1K5	SW/82.9	-0.88	151
16	GEN	Bell Canada	1171 Pioneer Rd Burlington ON	SW/82.9	-0.88	152
16	PRT	AUTOMOTIVE MANAGER BELL CANADA	1171 PIONEER RD BURLINGTON ON L7M 1K5	SW/82.9	-0.88	15
17	CA	Canadian Hazmat & Decon Services Inc.	1153 Pioneer Rd Burlington ON L7M 1K5	SSW/88.5	-1.93	153
17	ECA	Canadian Hazmat & Decon Services Inc.	1153 Pioneer Rd Burlington ON L7M 1K5	SSW/88.5	-1.93	153
17	EHS		1153 Pioneer Road Burlington ON	SSW/88.5	-1.93	153
17	GEN	BCG PRECISION GRINDING AND HONING INC	1153 Pioneer Road Unit 10 Burlington ON L7M 1K5	SSW/88.5	-1.93	153
17	GEN	MILL PACK INDUSTRIAL MAINTENANCE INC.	1153 PIONEER ROAD, UNIT 7 BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	154
17	GEN	MILL PACK INDUSTRIAL MAINTENANCE INC.	1153 PIONEER ROAD, UNIT 7 BURLINGTON ON	SSW/88.5	-1.93	154
17	GEN	BURLINGTON CENTERLESS GRINDING	1153 PIONEER ROAD, UNIT 10 BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	154
17	GEN	BURLINGTON CENTERLESS GRINDING	1153 Pioneer Road Unit 10 Burlington ON L7M 1K5	SSW/88.5	-1.93	154
17	GEN	K.C. GRAPHICS	1153 PIONEER RD. UNIT F BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	155
17	GEN	MACHINERY REPAIR TECHNOLOGIES	1153 PIONEER ROAD, UNIT K BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	155
17	GEN	931344 ontario inc.	1153 -H PIONEER RD BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	155
17	GEN	BCG PRECISION GRINDING AND HONING INC	1153 Pioneer Road Unit 10 Burlington ON L7M 1K5	SSW/88.5	-1.93	156
17	GEN	BURLINGTON CENTERLESS GRINDING	1153 Pioneer Road Unit 10 Burlington ON L7M 1K5	SSW/88.5	-1.93	156
17	GEN	CANADIAN INDUCTION PROCESSING INC	1153 PIONEER ROAD, UNIT #6 BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	156
17	GEN	CANADIAN INDUCTION PROCESSING INC.08-020	1153 PIONEER ROAD, UNIT #6 BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	156
17	GEN	K.C. GRAPHICS	1153 PIONEER ROAD, UNIT F BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	157
17	GEN	MILL PACK INDUSTRIAL MAINTENANCE INC.	1153 PIONEER ROAD, UNIT 7 BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	157
17	GEN	K.C. GRAPHICS 23-422	1153 PIONEER RD. UNIT F BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	157
17	GEN	BCG PRECISION GRINDING AND HONING INC	1153 Pioneer Road Unit 10 Burlington ON L7M 1K5	SSW/88.5	-1.93	158

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
17	GEN	BURLINGTON CENTERLESS GRINDING	1153 Pioneer Road Unit 10 Burlington ON L7M 1K5	SSW/88.5	-1.93	158
17	GEN	CANADIAN INDUCTION PROCESSING INC	1153 PIONEER RD. UNIT #6 BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	158
17	GEN	BURLINGTON CENTERLESS GRINDING	1153 Pioneer Road Unit 10 Burlington ON L7M 1K5	SSW/88.5	-1.93	158
17	GEN	BURLINGTON CENTERLESS GRINDING	1153 Pioneer Road Unit 10 Burlington ON L7M 1K5	SSW/88.5	-1.93	159
17	GEN	MILL PACK INDUSTRIAL MAINTENANCE INC.	1153 PIONEER ROAD, UNIT 7 BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	159
17	GEN	CANADIAN INDUCTION PROCESSING INC.	1153 PIONEER ROAD, UNIT #6 BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	159
17	GEN	CANADIAN I(OUT OF BUSINESS)NG INC.	1153 PIONEER ROAD, UNIT #6 BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	160
17	GEN	MACHINERY REPAIR TECHNOLOGIES	1153 PIONEER ROAD, UNIT K BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	160
17	GEN	BCG PRECISION GRINDING AND HONING INC	1153 Pioneer Road Unit 10 Burlington ON L7M 1K5	SSW/88.5	-1.93	160
17	GEN	MILL PACK INDUSTRIAL MAINTENANCE INC.	1153 PIONEER ROAD, UNIT 7 BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	161
17	GEN	MACHINERY REPAIR TECHNOLOGIES	1153 PIONEER ROAD, UNIT K BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	161
17	GEN	BCG PRECISION GRINDING AND HONING INC	1153 Pioneer Road Unit 10 Burlington ON	SSW/88.5	-1.93	161
17	GEN	MILL PACK INDUSTRIAL MAINTENANCE INC.	1153 PIONEER ROAD, UNIT 7 BURLINGTON ON	SSW/88.5	-1.93	161
17	SCT	K C GRAPHICS	1153 Pioneer Rd Unit F Burlington ON L7M 1K5	SSW/88.5	-1.93	162
17	SCT	HOMEMADE WINE CRAFTS CANADA	1153 Pioneer Rd Unit E Burlington ON L7M 1K5	SSW/88.5	-1.93	162
17	SCT	M. I. R. Fabric Products	1153 Pioneer Rd Unit L Burlington ON L7M 1K5	SSW/88.5	-1.93	162
17	SCT	LASER F/X INTERNATIONAL	1153 Pioneer Rd Unit P Burlington ON L7M 1K5	SSW/88.5	-1.93	163
17	SCT	ORGANIZERS PLUS	1153 PIONEER RD UNIT K BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	16
17	SCT	BURLINGTON CENTRELESS GRINDING	1153 PIONEER RD BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	163
17	SCT	All Racking and Conveyors	1153 Pioneer Rd Unit 2 Burlington ON L7M 1K5	SSW/88.5	-1.93	163
17	SCT	Homemade Wine Crafts Canada Ltd.	1153 Pioneer Rd Unit E Burlington ON L7M 1K5	SSW/88.5	-1.93	164
17	SCT	Downtown Signs	1153 Pioneer Rd Unit J Burlington ON L7M 1K5	SSW/88.5	-1.93	16
17	SCT	HOMEMADE WINE CRAFTS LTD	1153 PIONEER RD UNIT E BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	16
17	SCT	Brant Custom Grinding Limited	1153 Pioneer Rd Unit 11 Burlington ON L7M 1K5	SSW/88.5	-1.93	16
17	SCT	CANADIAN INDUCTION PROCESSING	1153 PIONEER RD UNIT 4-6 BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	16
17	SCT	WORLD WIDE KILN SERVICE	1153 PIONEER RD UNIT 7 BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	16

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
17	SCT	EXOTIC SIGNS	1153 PIONEER RD UNIT J BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	16
17	SCT	K. C. GRAPHICS	1153 PIONEER RD BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	165
17	SCT	LASER F X INTERNATIONAL	1153 PIONEER RD UNIT P BURLINGTON ON L7M 1K5	SSW/88.5	-1.93	16
17	SCT	Burlington Centerless Grinding	1153 Pioneer Rd Unit 10 Burlington ON L7M 1K5	SSW/88.5	-1.93	166
18	GEN	CHEM SYSTEMS INCORPORATED	3390 MAINWAY DRIVE BURLINGTON ON L7M 1A8	N/91.3	1.07	166
18	GEN	CHEM SYSTEMS INC.	3390 MAINWAY DRIVE BURLINGTON ON L7M 1A8	N/91.3	1.07	167
18	GEN	HAYWARD GORDON LTD.	3390 MAINWAY DRIVE BURLINGTON ON L7M 1A8	N/91.3	1.07	167
18	SCT	Hayward Gordon Ltd.	3390 Mainway Burlington ON L7M 1A8	N/91.3	1.07	167
18	SCT	CHEM SYSTEMS INC.	3390 MAINWAY DR BURLINGTON ON L7M 1A8	N/91.3	1.07	168
18	SCT	CHEM SYSTEMS INC.	3390 MAINWAY BURLINGTON ON L7M 1A8	N/91.3	1.07	16
19	WWIS		Burlington ON	NE/91.9	-0.14	168
20	SCT	WEIGH-MATIC SYSTEMS INC.	3312 MAINWAY DR BURLINGTON ON L7M 1A7	WNW/102.1	1.07	179
20	SCT	CARLISLE TECHNOLOGY	3312 MAINWAY DR BURLINGTON ON L7M 1A7	WNW/102.1	1.07	18
20	SCT	Carlisle Technology Inc.	3312 Mainway Burlington ON L7M 1A7	WNW/102.1	1.07	180
21	SCT	Integrity Worldwide Inc.	3310 Mainway Burlington ON L7M 1A7	WNW/102.2	1.07	181
22	WWIS		lot 12 con 2 ON	SSE/102.9	-2.87	182
23	GEN	Mayne Logistics Loomis Inc.	3330 MAINWAY DRIVE BURLINGTON ON	NW/103.5	1.07	182
23	GEN	LOOMIS COURIER SERVICE	3330 MAINWAY DRIVE BURLINGTON ON L7M 1A7	NW/103.5	1.07	182
23	GEN	LOOMIS COURIER SERVICE(OUT OF BUSINESS)	3330 MAINWAY DRIVE BURLINGTON ON L7M 1A7	NW/103.5	1.07	183
24	EHS		3310-3312 Mainway Dr Burlington ON L7M 1A7	WNW/103.8	1.07	183
25	EHS		3330-3342 MAINWAY BURLINGTON ON L7M 1A7	NW/105.3	1.79	184
26	SCT	ConverTec Inc.	3340 Mainway Suite 200 Burlington ON L7M 1A7	NNW/107.0	2.07	184
27	SCT	HAMILTON DIGITAL DESIGNS LTD.	3342 Mainway Dr Burlington ON L7M 1A7	NNW/108.2	2.07	184
27	SCT	Hamilton Digital Designs Ltd.	3342 Mainway Burlington ON L7M 1A7	NNW/108.2	2.07	185
27	SCT	HAMILTON DIGITAL DESIGNS LTD.	3142 MAINWAY DR BURLINGTON ON L7M 1A7	NNW/108.2	2.07	18
28	GEN	1187188 Ont Ltd.	3344 Mainway Burlington ON L7M 1A7	NNW/109.1	2.07	185

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
28	GEN	1187188 Ont Ltd.	3344 Mainway Burlington ON	NNW/109.1	2.07	185
28	GEN	1187188 Ont Ltd.	3344 Mainway Burlington ON L7M 1A7	NNW/109.1	2.07	186
28	GEN	1187188 Ont Ltd.	3344 Mainway Burlington ON L7M 1A7	NNW/109.1	2.07	186
28	GEN	1187188 Ont Ltd.	3344 Mainway Burlington ON L7M 1A7	NNW/109.1	2.07	186
29	WWIS		Burlington ON	WSW/122.7	-0.36	186
30	GEN	ANTEL OPTRONICS INC. 03-117	3329 MAINWAY BURLINGTON ON L7M 1A6	WNW/123.4	1.19	188
30	GEN	ANTEL OPTRONICS INC.	3329 MAINWAY BURLINGTON ON L7M 1A6	WNW/123.4	1.19	189
30	SCT	DRAKE WATER SYSTEMS INC.	3329 MAINWAY DR BURLINGTON ON L7M 1A6	WNW/123.4	1.19	18
31	EHS		3355 Mainway Burlington ON L7M 1A6	NW/124.3	1.78	189
32	ECA	EcoSynthetix Inc.	3365 Mainway Dr Burlington ON L7M 1A6	NW/124.8	2.07	189
32	EHS		3365 Mainway Burlington ON L7M 1A6	NW/124.8	2.07	190
33	GEN	EUROLINE CUSTOM CABINETS	3415 LANDMARK ROAD BURLINGTON ON L7M 1T4	NNE/128.1	0.98	190
33	GEN	COR-MAG INC. 07-629	3415 LANDMARK RD. BURLINGTON ON L7M 1T4	NNE/128.1	0.98	190
33	GEN	COR-MAG INC.(OUT OF BUS) 07-629	3415 LANDMARK RD. BURLINGTON ON L7M 1T4	NNE/128.1	0.98	190
33	GEN	IndustAutoCo Inc.	3415 Lanmark Road Burlington ON L7M 1T4	NNE/128.1	0.98	191
33	GEN	IndustAutoCo Inc.	3415 Lanmark Road Burlington ON L7M 1T4	NNE/128.1	0.98	191
33	GEN	EUROLINE (OUT OF BUSINESS)	3415 LANDMARK ROAD BURLINGTON ON L7M 1T4	NNE/128.1	0.98	191
33	SCT	EUROLINE CUSTOM CABINETS INC.	3415 LANDMARK RD BURLINGTON ON L7M 1T4	NNE/128.1	0.98	19
33	SCT	EUROLINE CUSTOM CABINETS	3415 LANDMARK RD BURLINGTON ON L7M 1T4	NNE/128.1	0.98	19
34	WWIS		Burlington ON	SW/140.0	-0.91	192
35	WWIS		Burlington ON	NNE/142.8	1.07	194
36	EHS		3264 Mainway Burlington ON L7M1A7	WSW/143.0	-0.75	204
37	CA	Pennzoil Quaker-State Canada Incorporated	1101 Blair Road Burlington ON L7M 1T3	E/143.2	-3.27	205
37	EBR	Pennzoil Quaker-State Canada Incorporated	1101 Blair Road Burlington Ontario L7M 1T3 Burlington ON	E/143.2	-3.27	205
37	ECA	Pennzoil Quaker-State Canada Incorporated	1101 Blair Road Burlington ON L7M 1T3	E/143.2	-3.27	205
37	EHS		1101 Blair Road Burlington ON L7M 1T3	E/143.2	-3.27	205

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
37	GEN	SHELL CANADA PRODUCTS	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	E/143.2	-3.27	206
37	GEN	SHELL CANADA PRODUCTS	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	E/143.2	-3.27	206
37	GEN	QUAKER STATE INC. 32-001	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	E/143.2	-3.27	206
37	GEN	SHELL CANADA PRODUCTS	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	E/143.2	-3.27	207
37	GEN	QUAKER STATE INC	1101 BLAIR RD. BURLINGTON ON L7M 1T3	E/143.2	-3.27	207
37	GEN	QUAKER STATE INC 32-001	1101 BLAIR RD. BURLINGTON ON L7M 1T3	E/143.2	-3.27	208
37	GEN	PENNZOIL QUAKER STATE CANADA COMPANY	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	E/143.2	-3.27	208
37	GEN	PENNZOIL QUAKER STATE CANADA COMPANY	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	E/143.2	-3.27	208
37	GEN	QUAKER STATE INC.	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	E/143.2	-3.27	209
37	GEN	SHELL CANADA PRODUCTS	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	E/143.2	-3.27	209
37	GEN	QUAKER STATE INC	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	E/143.2	-3.27	209
37	GEN	SHELL CANADA PRODUCTS	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	E/143.2	-3.27	210
37	GEN	PENNZOIL QUAKER STATE CANADA COMPANY	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	E/143.2	-3.27	210
37	GEN	SHELL CANADA PRODUCTS	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	E/143.2	-3.27	211
37	GEN	SHELL CANADA PRODUCTS	1101 BLAIR ROAD BURLINGTON ON	E/143.2	-3.27	211
37	SCT	Pennzoil-Quaker State Canada	1101 Blair Rd Burlington ON L7M 1T3	E/143.2	-3.27	211
37	SCT	QUAKER STATE INC.	1101 BLAIR RD BURLINGTON ON L7M 1T3	E/143.2	-3.27	21
37	SCT	Pennzoil-Quaker State Canada Company	1101 Blair Rd Burlington ON L7M 1T3	E/143.2	-3.27	212
37	SCT	PENNZOIL QUAKER STATE CANADA C	1101 BLAIR RD BURLINGTON ON L7M 1T3	E/143.2	-3.27	21
37	SPL	PENZOIL QUAKER STATE	1101 BLAIR ROAD 1101 BLAIR ROAD,BURLINGTON BURLINGTON CITY ON L7M 1T3	E/143.2	-3.27	212
38	CA	RIEGER PRINTING INK CO. LTD.	3410 MAINWAY DRIVE BURLINGTON CITY ON L7M 1A8	NNE/152.1	1.57	21
38	EBR	Rieger Printing Ink Co. Ltd.	3410 Mainway Drive CITY OF BURLINGTON ON	NNE/152.1	1.57	213
38	EHS		3410 Mainway Burlington ON L7M 1A8	NNE/152.1	1.57	214
38	GEN	221063 Ontario Inc.	3410 Mainway Burlington ON L7M 1A8	NNE/152.1	1.57	214
38	GEN	RIEGER PRINTING INK CO LTD	C/O 4515 CHESSWOOD DRIVE 3410 MAINWAY DRIVE DOWNSVIEW ON L7M 1A8	NNE/152.1	1.57	214

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
38	GEN	REGIER PRINTING INK	3410 MAINWAY DRIVE BURLINGTON ON L7M 1A8	NNE/152.1	1.57	214
38	GEN	RIEGER PRINTING INK CO. LTD.	3410 MAINWAY DRIVE BURLINGTON ON L7M 1A8	NNE/152.1	1.57	215
38	GEN	RIEGER PRINTING INK CO. LTD. 33-087	3410 MAINWAY DR. BURLINGTON ON L7M 1A8	NNE/152.1	1.57	215
38	GEN	RIEGER PRINTING INK CO LTD	3410 MAINWAY DR. BURLINGTON ON L7M 1A8	NNE/152.1	1.57	216
38	GEN	221063 Ontario Inc.	3410 Mainway Burlington ON L7M 1A8	NNE/152.1	1.57	216
38	GEN	RIEGER PRINTING INK CO. LTD.	3410 MAINWAY DRIVE (SITE), C/O 4515-A CHESSWOOD DR., DOWNSVIEW M3J2V6 BURLINGTON ON L7M 1A8	NNE/152.1	1.57	216
38	NPCB	RIEGER PRINTING INK COMPANY LTD.	3410 MAINWAY DRIVE BURLINGTON ON L7M 1A8	NNE/152.1	1.57	216
38	NPCB	RIEGER PRINTING INK CO LTD	3410 MAINWAY DRIVE BURLINGTON ON L7M 1A8	NNE/152.1	1.57	21
38	OPCB	RIEGER PRINTING INK CO LTD	3410 MAINWAY DRIVE BURLINGTON ON L7M 1A8	NNE/152.1	1.57	218
38	REC	RIEGER PRINTING INK CO. LTD.	3410 MAINWAY DR. BURLINGTON ON L7M 1A8	NNE/152.1	1.57	218
38	REC	RIEGER PRINTING INK CO. LTD.	3410 MAINWAY DRIVE (SITE), C/O 4515-A CHESSWOOD DR., DOWNSVIEW M3J2V6 BURLINGTON ON L7M 1A8	NNE/152.1	1.57	218
38	REC	RIEGER PRINTING INK CO. LTD.	3410 MAINWAY DRIVE, BURLINGTON C/O 4515 CHESSWOOD DRIVE, SUITE A DOWNSVIEW ON L7M 1A8	NNE/152.1	1.57	219
38	REC	RIEGER PRINTING INK CO. LTD.	3410 MAINWAY DRIVE BURLINGTON ON L7M 1A8	NNE/152.1	1.57	219
38	RSC	2210263 Ontario Inc.	3410 MAINWAY DR, BURLINGTON, ON, L7M 1A8, ON L7M 1A8	NNE/152.1	1.57	219
38	SCT	Rieger Printing Ink Co. Ltd.	3410 Mainway Burlington ON L7M 1A8	NNE/152.1	1.57	220
38	SCT	RIEGER PRINTING INK CO. LTD.	3410 MAINWAY DR BURLINGTON ON L7M 1A8	NNE/152.1	1.57	22
39	GEN	MODULAR CONTROLS LIMITED	3339 MAINWAY BURLINGTON ON L7M 1A6	NW/156.3	2.07	220
39	GEN	MODULAR CONTROLS LTD.	3339 MAINWAY BURLINGTON ON L7M 1A6	NW/156.3	2.07	221
39	GEN	MODULAR CONTROLS LTD. 27-010	3339 MAINWAY BURLINGTON ON L7M 1A6	NW/156.3	2.07	221
39	GEN	MODULAR CONTROLS LTD	3339 MAINWAY BURLINGTON ON L7M 1A6	NW/156.3	2.07	221
40	WWIS		lot 13 con 2 BURLINGTON ON	W/157.4	-0.22	222
40	WWIS		lot 13 con 2 BURLINGTON ON	W/157.4	-0.22	224
41	GEN	GATES AIR SYSTEMS LTD.	3317 MAINWAY DRIVE BURLINGTON ON L7M 1A6	WNW/157.8	1.18	227
41	SCT	ORGANIZERS PLUS	3317 Mainway Dr Unit C Burlington ON L7M 1A6	WNW/157.8	1.18	227

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
41	SCT	Halton Sheet Metal Ltd.	3317 Mainway Dr Burlington ON L7M 1A6	WNW/157.8	1.18	228
42	GEN	FibreCast Inc.	3264 Mainway Burlington ON L7M 1A7	WSW/158.4	-0.87	228
42	GEN	FibreCast Inc.	3264 Mainway Burlington ON L7M 1A7	WSW/158.4	-0.87	228
42	GEN	AISCO SYSTEMS LIMITED	3264 MAINWAY BURLINGTON ON L7R 3Y5	WSW/158.4	-0.87	229
42	GEN	AISCO INC.	3264 MAINWAY P.O. BOX 655 BURLINGTON ON L7M 1A7	WSW/158.4	-0.87	229
42	GEN	AISCO SYSTEMS LTD.	3264 MAINWAY P.O. BOX 655 BURLINGTON ON L7M 1A7	WSW/158.4	-0.87	229
42	GEN	AISCO SYSTEMS LIMITED 01-392	3264 MAINWAY BURLINGTON ON L7R 3Y5	WSW/158.4	-0.87	230
42	SCT	AISCO SYSTEMS INC.	3264 MAINWAY DR BURLINGTON ON L7M 1A7	WSW/158.4	-0.87	23
42	SCT	Fibrecast Inc.	3264 Mainway Burlington ON L7M 1A7	WSW/158.4	-0.87	230
42	SCT	FIBRECAST INC.	3264 Mainway Dr Burlington ON L7M 1A7	WSW/158.4	-0.87	231
43	CA	REHAU INDUSTRIES INC.	1149 PIONEER ROAD BURLINGTON CITY ON L7M 1K5	S/160.4	-2.97	23
43	EHS		1149 Pioneer Road Burlington ON L7M 1K5	S/160.4	-2.97	232
43	GEN	REHAU INDUSTRIES INC.	1149 PIONEER ROAD BURLINGTON ON L7M 1K5	S/160.4	-2.97	232
43	GEN	REHAU INDUSTRIES INC. 33-227	1149 PIONEER RD. BURLINGTON ON L7M 1K5	S/160.4	-2.97	232
43	GEN	REHAU INDUSTRIES INC.	1149 PIONEER RD. BURLINGTON ON L7M 1K5	S/160.4	-2.97	233
43	SCT	Rehau Industries Inc.	1149 Pioneer Rd Burlington ON L7M 1K5	S/160.4	-2.97	23
43	SPL	REHAU INDUSTRIES INC.	BURLINGTON PLANT 1149 PIONEER ROAD BURLINGTON CITY ON L7M 1K5	S/160.4	-2.97	23
44	CHEM	QUADRA CHEMICALS LTD	1100 BLAIR RD BURLINGTON ON L7M 1K9	SE/166.2	-3.51	234
44	EHS		1100 Blair Road Burlington ON L7M 1K9	SE/166.2	-3.51	234
44	GEN	QUADRA CHEMICALS LTD. 32-219	1100 BLAIR ROAD BURLINGTON ON L7M 1K9	SE/166.2	-3.51	235
44	GEN	QUADRA CHEMICALS LTD.	1100 BLAIR ROAD BURLINGTON ON L7M 1K9	SE/166.2	-3.51	235
44	GEN	QUADRA CHEMICALS LTD.	1100 Blair Road Burlington ON L7M 1K9	SE/166.2	-3.51	236
44	GEN	DOMINION (SEE & USE ON0199100 ACCO)	CANADIAN MATERIAL HANDLING 1100 BLAIR RD. BURLINGTON ON L7M 1K9	SE/166.2	-3.51	236
44	GEN	QUADRA CHEMICALS LTD.	1100 Blair Road Burlington ON L7M 1K9	SE/166.2	-3.51	236
44	GEN	ACCO CANADIAN MATERIAL HANDLING	1100 BLAIR RD. BURLINGTON ON L7M 1K9	SE/166.2	-3.51	237

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
44	GEN	ACCO CANADIAN MATERIAL HANDLING	BABCOCK INDUSTRIES CANADA INC, A DIV. OF 1100 BLAIR ROAD BURLINGTON ON L7M 1K9	SE/166.2	-3.51	237
44	GEN	QUADRA CHEMICALS LTD.	1100 Blair Road Burlington ON L7M 1K9	SE/166.2	-3.51	238
44	GEN	ACCO CANADIAN MATERIAL HANDLING 01-019	A DIV. OF BABCOCK INDUSTRIES CANADA INC 1100 BLAIR ROAD BURLINGTON ON L7M 1K9	SE/166.2	-3.51	238
44	GEN	QUADRA CHEMICALS LTD.	1100 Blair Road Burlington ON L7M 1K9	SE/166.2	-3.51	239
44	GEN	ACCO CANADIAN MATERIAL HANDLING	A DIV. OF BABCOCK INDUSTRIES CANADA INC 1100 BLAIR ROAD BURLINGTON ON L7M 1K9	SE/166.2	-3.51	239
44	GEN	QUADRA CHEMICALS LTD	1100 BLAIR ROAD BURLINGTON ON L7M 1K9	SE/166.2	-3.51	240
44	PAP	Quadra Chemicals	1100 Blair Rd Burlington ON L7M 1K9	SE/166.2	-3.51	240
44	SPL	QUADRA CHEMICALS LTD.	1100 BLAIR ROAD BURLINGTON SITE 1100 BLAIR RD. BURLINGTON CITY ON L7M 1K9	SE/166.2	-3.51	24
45	GEN	BROWN FALCON MACHINE & TOOL	3295 MAINWAY UNIT 6 BURLINGTON ON L7M 1A6	WNW/166.2	1.07	241
45	GEN	BROWN FALCON MAC(OUT OF BUSINESS) 05-352	3295 MAINWAY UNIT 6 BURLINGTON ON L7M 1A6	WNW/166.2	1.07	241
45	SCT	Tymatic Controls - Div. of Tyrrell Air Controls Ltd.	3295 Mainway Unit 6 Burlington ON L7M 1A6	WNW/166.2	1.07	241
45	SCT	ERODALL LTD.	3295 MAINWAY DR UNIT 3 BURLINGTON ON L7M 1A6	WNW/166.2	1.07	24
45	SCT	Erodall Ltd.	3295 Mainway Unit 3 Burlington ON L7M 1A6	WNW/166.2	1.07	242
45	SCT	RAINBOW CERAMICS	3295 Mainway Unit 1 Burlington ON L7M 1A6	WNW/166.2	1.07	242
46	GEN	METAL EQUIPMENT SERVICES LTD.	3337 MAINWAY DRIVE BURLINGTON ON L7M 1A6	NW/167.9	2.07	242
46	SCT	METAL EQUIPMENT SERVICES LTD.	3337 MAINWAY DR BURLINGTON ON L7M 1A6	NW/167.9	2.07	24
47	EHS		3424 Landmark Road Burlington ON L7M 1S8	NE/168.6	-0.63	243
47	EXP	HUMPTY DUMPTY FOODS LTD	3424 LANDMARK RD BURLINGTON ON	NE/168.6	-0.63	243
47	EXP	HUMPTY DUMPTY FOODS LTD	3424 LANDMARK RD BURLINGTON ON L7M 1S8	NE/168.6	-0.63	243
47	EXP	HUMPTY DUMPTY FOODS LTD	3424 LANDMARK RD BURLINGTON ON	NE/168.6	-0.63	243
47	EXP	HUMPTY DUMPTY FOODS LTD	3424 LANDMARK RD BURLINGTON ON L7M 1S8	NE/168.6	-0.63	244
47	PRT	HUMPTY DUMPTY FOODS LTD	3424 LANDMARK RD BURLINGTON ON L7M 1S8	NE/168.6	-0.63	24
47	SCT	SMALL FRY SNACK FOODS INC.	3424 LANDMARK RD BURLINGTON ON L7M 1S8	NE/168.6	-0.63	24
48	CHEM	QUADRA CHEMICALS LTD	1100 BLAIR RD BURLINGTON ON L7M1K9	SE/169.5	-3.78	244
48	CHEM	QUADRA CHEMICALS LTD	1100 BLAIR RD BURLINGTON ON L7M1K9	SE/169.5	-3.78	245

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
48	CHEM	QUADRA CHEMICALS LTD	1100 BLAIR RD BURLINGTON ON L7M1K9	SE/169.5	-3.78	245
48	GEN	QUADRA CHEMICALS LTD.	1100 Blair Road Burlington ON L7M 1K9	SE/169.5	-3.78	245
48	GEN	QUADRA CHEMICALS LTD.	1100 Blair Road Burlington ON L7M 1K9	SE/169.5	-3.78	246
48	GEN	QUADRA CHEMICALS LTD.	1100 Blair Road Burlington ON L7M 1K9	SE/169.5	-3.78	248
48	GEN	QUADRA CHEMICALS LTD.	1100 Blair Road Burlington ON L7M 1K9	SE/169.5	-3.78	249
48	GEN	QUADRA CHEMICALS LTD.	1100 Blair Road Burlington ON	SE/169.5	-3.78	249
49	WWIS		Burlington ON	ENE/171.6	-0.96	250
50	GEN	TOROMONT INDUSTRIES LTD	3385 MAINWAY BURLINGTON ON L7M 1A6	NNW/171.9	2.07	257
50	GEN	KINGSBURY MACHINE TOOL (CDA) LTD	3385 MAINWAY DRIVE BURLINGTON ON L7M 1A6	NNW/171.9	2.07	258
50	GEN	KINGSBURY MACHINE TOOL (CANADA) LIMITED	3385 MAINWAY DRIVE BURLINGTON ON L7M 1A6	NNW/171.9	2.07	258
50	GEN	KINGSBURY CANADA INC.	3385 MAINWAY DRIVE BURLINGTON ON L7M 1A6	NNW/171.9	2.07	259
50	GEN	KINGSBURY MACHINE TOOL (CDA) LTD 23-070	3385 MAINWAY DRIVE BURLINGTON ON L7M 1A6	NNW/171.9	2.07	259
50	GEN	KINGSBURY MACHINE TOOL (CDA) LTD.	3385 MAINWAY DRIVE BURLINGTON ON L7M 1A6	NNW/171.9	2.07	260
50	GEN	KINGSBURY CANADA INC.	3385 MAINWAY BURLINGTON ON L7M 1A6	NNW/171.9	2.07	260
50	SCT	Kingsbury Canada Inc.	3385 Mainway Burlington ON L7M 1A6	NNW/171.9	2.07	261
50	SCT	KINGSBURY CANADA INC	3385 MAINWAY DR BURLINGTON ON L7M 1A6	NNW/171.9	2.07	26
50	SCT	KINGSBURY CANADA INC.	3385 Mainway Dr Burlington ON L7M 1A6	NNW/171.9	2.07	262
50	SCT	Keltour Controls Inc.	3385 Mainway Burlington ON L7M 1A6	NNW/171.9	2.07	262
51	CA	RIEGER PRINTING INK CO. LTD.	3410 MAIN DRIVE BURLINGTON CITY ON	N/172.5	2.07	26
52	GEN	PRINTING HOUSE LTD., THE	3285 MAINWAY, UNIT 1 BURLINGTON ON L7M 1A6	W/176.1	0.00	262
52	GEN	PRINTING HOUSE LTD., THE	3285 MAINWAY, UNIT 1 BURLINGTON ON L7M 1A6	W/176.1	0.00	263
52	GEN	PRINTING HOUSE LTD., THE	3285 MAINWAY, UNIT 1 BURLINGTON ON L7M 1A6	W/176.1	0.00	263
52	GEN	PRINTING HOUSE LTD., THE	3285 MAINWAY, UNIT 1 BURLINGTON ON L7M 1A6	W/176.1	0.00	264
52	GEN	COOPER FLUID POWER INC.	3285 MAINWAY DRIVE, #6 BURLINGTON ON L7M 1A6	W/176.1	0.00	264
52	GEN	PRINTING HOUSE LTD., THE	3285 MAINWAY, UNIT 1 BURLINGTON ON	W/176.1	0.00	265
52	GEN	PRINTING HOUSE LTD., THE	3285 MAINWAY, UNIT 1 BURLINGTON ON L7M 1A6	W/176.1	0.00	265

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
52	GEN	PRINTING HOUSE LTD., THE	3285 MAINWAY, UNIT 1 BURLINGTON ON L7M 1A6	W/176.1	0.00	266
52	GEN	PRINTING HOUSE LTD., THE	3285 MAINWAY, UNIT 1 BURLINGTON ON L7M 1A6	W/176.1	0.00	266
52	GEN	COOPER FLUID POWER INC.	3285 MAINWAY DRIVE, UNIT 6 BURLINGTON ON L7M 1A6	W/176.1	0.00	266
52	GEN	COTSWOLD PRECISION COMPANY LTD.	3285 MAINWAY DRIVE, UNIT 3 BURLINGTON ON L7M 1A6	W/176.1	0.00	267
52	GEN	PRINTING HOUSE LTD., THE	3285 MAINWAY, UNIT 1 BURLINGTON ON L7M 1A6	W/176.1	0.00	267
52	GEN	PRINTING HOUSE LTD., THE	3285 MAINWAY, UNIT 1 BURLINGTON ON L7M 1A6	W/176.1	0.00	268
52	GEN	Precision Metalworks Inc	3285 Mainway unit 5 Burlington ON L7M 1A6	W/176.1	0.00	268
52	GEN	Precision Metalworks Inc	3285 Mainway unit 5 Burlington ON L7M 1A6	W/176.1	0.00	268
52	GEN	PRINTING HOUSE LTD., THE	3285 MAINWAY UNIT #1 BURLINGTON ON L7M 1A6	W/176.1	0.00	269
52	GEN	Sympro CNC Macining and Manufacturing	3285 Main Way, Unit 6 Burlington ON L7M 1A6	W/176.1	0.00	269
52	GEN	precision print	3285 Mainway drive burlington ON	W/176.1	0.00	269
52	GEN	COTSWOLD PRECISION COMPANY LTD.	3285 MAINWAY DRIVE, UNIT #3 BURLINGTON ON L7M 1A6	W/176.1	0.00	269
52	SCT	COTSWOLD PRECISION CO. LTD	3285 MAINWAY DR UNIT 3 BURLINGTON ON L7M 1A6	W/176.1	0.00	27
52	SCT	TPH The Printing House Limited	3285 Mainway Unit 1 Burlington ON L7M 1A6	W/176.1	0.00	270
52	SCT	Precision Print Inc.	3285 Mainway Dr Burlington ON L7M 1A6	W/176.1	0.00	271
52	SCT	THE PRINTING HOUSE LTD.	3285 Mainway Dr Unit 1 Burlington ON L7M 1A6	W/176.1	0.00	271
52	SCT	VERSA-HOE EQUIPMENT CORP.	3285 MAINWAY DR UNIT 4 BURLINGTON ON L7M 1A6	W/176.1	0.00	27
52	SCT	THE PRINTING HOUSE LTD	3285 MAINWAY DR UNIT 1 BURLINGTON ON L7M 1A6	W/176.1	0.00	27
52	SCT	Precision Print Inc.	3285 Mainway Unit 2 Burlington ON L7M 1A6	W/176.1	0.00	272
52	SCT	Intek Inc.	3285 Mainway Dr Unit 4 Burlington ON L7M 1A6	W/176.1	0.00	272
53	EHS		3410 Mainway Burlington ON L7M1A8	N/178.3	2.07	272
53	EHS		3410 Mainway Burlington ON L7M1A8	N/178.3	2.07	272
53	GEN	ACTIVITYPLEX BURLINGTON CORP.	3410 MAINWAY BURLINGTON ON L7M 1A8	N/178.3	2.07	273
53	GEN	MPI GROUP INC.	3410 MAINWAY BURLINGTON ON L7M 1A8	N/178.3	2.07	273
53	RSC		3410 MAINWAY, BURLINGTON, ON L7M 1A8 Burlington ON	N/178.3	2.07	273
54	CA	GENNUM CORPORATION	3435 LANDMARK ROAD BURLINGTON CITY ON L7M 1T4	NNE/181.1	1.07	275

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
54	CA	Bosch Rexroth Canada Corp.	3435 Landmark Road Burlington ON L7M 1T4	NNE/181.1	1.07	275
54	CA		3435 Landmark Road Burlington ON L7M 1T4	NNE/181.1	1.07	275
54	EBR	Bosch Rexroth Canada Corp.	3435 Landmark Road Burlington Ontario L7M 1T4 Burlington ON	NNE/181.1	1.07	275
54	ECA	Bosch Rexroth Canada Corp.	3435 Landmark Road Burlington ON L7M 1A8	NNE/181.1	1.07	276
54	EHS		3435 Landmark Rd Burlington ON L7M 1T4	NNE/181.1	1.07	276
54	EHS		3435 Landmark Road Burlington ON L7M 1T4	NNE/181.1	1.07	276
54	GEN	Laker Energy Products Ltd.	3435 Landmark Road Burlington ON L7M 1T4	NNE/181.1	1.07	277
54	GEN	Laker Energy Products Ltd.	3435 Landmark Road Burlington ON L7M 1T4	NNE/181.1	1.07	277
54	GEN	GENNUM (SEE&USE ON0488001)	3435 LANDMARK ROAD BURLINGTON ON L7M 1T4	NNE/181.1	1.07	277
54	GEN	GENNUM CORPORATION	3435 LANDMARK ROAD BURLINGTON ON L7M 1T4	NNE/181.1	1.07	278
54	GEN	Laker Energy Products Ltd.	3435 Landmark Road Burlington ON	NNE/181.1	1.07	278
54	GEN	Laker Energy Products Ltd.	3435 Landmark Road Burlington ON L7M 1T4	NNE/181.1	1.07	279
54	GEN	GENNUM CORPORATION 24-187	3435 LANDMARK ROAD BURLINGTON ON L7M 1T4	NNE/181.1	1.07	279
54	GEN	LINERAR TECHNOLOGY INC.	3435 LANDMARK ROAD BURLINGTON ON L7M 1T4	NNE/181.1	1.07	280
54	GEN	GENNUM (SEE&USE ON0488001) 17-187	3435 LANDMARK ROAD BURLINGTON ON L7M 1T4	NNE/181.1	1.07	280
54	GEN	GENNUM CORPORATION	3435 LANDMARK ROAD BURLINGTON ON L7M 1T4	NNE/181.1	1.07	280
54	GEN	Laker Energy Products Ltd.	3435 Landmark Road Burlington ON	NNE/181.1	1.07	281
54	NPRI	GENNUM CORPORATION	3435 LANDMARK ROAD NOT AVAILABLE BURLINGTON ON L7M 1T4	NNE/181.1	1.07	281
54	NPRI	GENNUM CORPORATION	3435 LANDMARK ROAD NOT AVAILABLE BURLINGTON ON L7M 1T4	NNE/181.1	1.07	282
54	NPRI	GENNUM CORPORATION	3435 LANDMARK ROAD NOT AVAILABLE BURLINGTON ON L7M 1T4	NNE/181.1	1.07	283
54	NPRI	GENNUM CORPORATION	3435 LANDMARK ROAD NOT AVAILABLE BURLINGTON ON L7M 1T4	NNE/181.1	1.07	284
54	NPRI	GENNUM CORPORATION	3435 LANDMARK ROAD NOT AVAILABLE BURLINGTON ON L7M 1T4	NNE/181.1	1.07	285
54	NPRI	GENNUM CORPORATION	3435 LANDMARK ROAD NOT AVAILABLE BURLINGTON ON L7M 1T4	NNE/181.1	1.07	285
54	NPRI	GENNUM CORPORATION	3435 LANDMARK ROAD NOT AVAILABLE BURLINGTON ON L7M 1T4	NNE/181.1	1.07	286
54	NPRI	GENNUM CORPORATION	3435 LANDMARK ROAD NOT AVAILABLE BURLINGTON ON L7M 1T4	NNE/181.1	1.07	287
54	NPRI	GENNUM CORPORATION	3435 LANDMARK ROAD NOT AVAILABLE BURLINGTON ON L7M 1T4	NNE/181.1	1.07	288

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
54	WWIS		BURLINGTON ON	NNE/181.1	1.07	289
55	GEN	GENNUM CORPORATION	P.O. BOX 489, STATION "A" BURLINGTON ON L7R 3Y3	NE/182.0	0.45	291
56	GEN	JC CNC (OUT OF BUSINESS)	3319B MAINWAY ROAD BURLINGTON ON L7M 1A6	WNW/183.0	1.89	292
56	GEN	JC CNC WORKS INC.	3319B MAINWAY ROAD BURLINGTON ON L7M 1A6	WNW/183.0	1.89	292
56	SCT	J.C. CNC WORKS INC.	3319 Mainway Rd Unit B Burlington ON L7M 1A6	WNW/183.0	1.89	292
57	EHS		3365 Mainway Burlington ON	NW/186.4	2.07	293
58	EHS		3267 Mainway Road Burlington ON	WSW/189.9	-0.92	293
58	NPRI	BURLINGTON TECHNOLOGIES INC.	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	WSW/189.9	-0.92	293
58	NPRI	BURLINGTON TECHNOLOGIES INDUSTRIES	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	WSW/189.9	-0.92	295
59	NPRI	BURLINGTON TECHNOLOGIES INC.	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	WSW/190.2	-0.92	298
59	NPRI	BURLINGTON TECHNOLOGIES INDUSTRIES	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	WSW/190.2	-0.92	299
59	NPRI	BURLINGTON TECHNOLOGIES INDUSTRIES	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	WSW/190.2	-0.92	301
59	NPRI	BURLINGTON TECHNOLOGIES INC.	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	WSW/190.2	-0.92	304
59	NPRI	BURLINGTON TECHNOLOGIES INC.	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	WSW/190.2	-0.92	306
59	NPRI	BURLINGTON TECHNOLOGIES INDUSTRIES	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	WSW/190.2	-0.92	307
59	NPRI	BURLINGTON TECHNOLOGIES INDUSTRIES	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	WSW/190.2	-0.92	309
59	NPRI	BURLINGTON TECHNOLOGIES: BURLINGTON DIVISION	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	WSW/190.2	-0.92	311
59	NPRI	BURLINGTON TECHNOLOGIES INC.	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	WSW/190.2	-0.92	312
59	NPRI	BURLINGTON TECHNOLOGIES INC.	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	WSW/190.2	-0.92	313
59	NPRI	BURLINGTON TECHOLOGIES INC.	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	WSW/190.2	-0.92	314
59	NPRI	BURLINGTON TECHNOLOGIES INDUSTRIES	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	WSW/190.2	-0.92	315
60	GEN	BELL CANADA	1191 PIONEER ROAD BURLINGTON ON L7M 1K5	SW/193.3	-1.93	317
61	SCT	PST Machining Ltd.	1163 Pioneer Rd Unit I Burlington ON L7M 1K5	SW/195.4	-2.69	318
62	GEN	Accurate Concrete Cutting	3333 Mainway, Suite B Burlington ON L7M 1A6	NW/195.8	2.07	318
62	GEN	Accurate Concrete Cutting	3333 Mainway, Suite B Burlington ON L7M 1A6	NW/195.8	2.07	318
62	SCT	ALLEN INDUSTRIAL RUBBER PROD	3333 Mainway Dr Unit A Burlington ON L7M 1A6	NW/195.8	2.07	319

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
62	SCT	ALLEN INDUSTRIAL RUBBER PROD	3333A MAINWAY DR BURLINGTON ON L7M 1A6	NW/195.8	2.07	31
62	SCT	Allen Industrial Rubber Products (1988) Ltd.	3333 Mainway Dr Unit A Burlington ON L7M 1A6	NW/195.8	2.07	319
62	SCT	ALLEN INDUSTRIAL RUBBER PRODS	3333 A MAINWAY DR BURLINGTON ON L7M 1A6	NW/195.8	2.07	319
62	SCT	Allen Industrial Rubber Prod	3333 Mainway Unit A Burlington ON L7M 1A6	NW/195.8	2.07	320
63	WWIS		Burlington ON	SW/204.5	-2.96	320
64	EBR	EcoSynthetix Inc.	3365 Mainway Drive Burlington, Regional Municipality of Halton L7M 1A6 CITY OF BURLINGTON ON	NW/204.9	2.69	328
64	EHS		3365 Mainway Burlington ON L7M1A6	NW/204.9	2.69	328
64	GEN	EcoSynthetix Inc	3365 Mainway Burlington ON L7M 1A6	NW/204.9	2.69	329
64	GEN	EcoSynthetix Inc	3365 Mainway Burlington ON L7M 1A6	NW/204.9	2.69	329
64	GEN	EcoSynthetix Inc	3365 Mainway Burlington ON L7M 1A6	NW/204.9	2.69	330
64	GEN	EcoSynthetix Inc EcoSynthetix Corporation	3365 Mainway Burlington ON L7M 1A6	NW/204.9	2.69	330
64	GEN	EcoSynthetix Inc	3365 Mainway Burlington ON	NW/204.9	2.69	331
64	GEN	EcoSynthetix Inc	3365 Mainway Burlington ON	NW/204.9	2.69	331
64	SCT	Mahle Clevite Canada ULC	3365 Mainway Unit 2 Burlington ON L7M 1A6	NW/204.9	2.69	332
65	EHS		Pioneer Road Burlington ON	SSE/209.0	-3.93	332
66	CA	Bosch Rexroth Canada Corp.	3426 Mainway Burlington ON L7M 1A8	NNE/209.4	1.89	332
66	GEN	BOSCH REXROTH CANADA CORP.	3426 MAINWAY DRIVE BURLINGTON ON L7M 1A8	NNE/209.4	1.89	332
66	GEN	KERNIC EQUIPMENT (OUT OF BUSINESS)23-112	3426 MAINWAY BURLINGTON ON L7M 1A8	NNE/209.4	1.89	333
66	GEN	BOSCH REXROTH CANADA CORP.	3426 MAINWAY DRIVE BURLINGTON ON L7M 1A8	NNE/209.4	1.89	333
66	GEN	KERNIC EQUIPMENT SALES LIMITED	3426 MAINWAY BURLINGTON ON L7M 1A8	NNE/209.4	1.89	334
66	GEN	BASIC TECHNOLOGIES	3426 MAINWAY BURLINGTON ON L7M 1A8	NNE/209.4	1.89	334
66	GEN	BASIC TECHNOLOGIES	3426 MAINWAY DRIVE BURLINGTON ON L7M 1A8	NNE/209.4	1.89	334
66	GEN	BOSCH REXROTH CANADA CORP.	3426 MAINWAY DRIVE BURLINGTON ON L7M 1A8	NNE/209.4	1.89	335
66	GEN	BOSCH REXROTH CANADA CORP.	3426 MAINWAY DRIVE BURLINGTON ON ON L7M 1A8	NNE/209.4	1.89	335
66	GEN	BOSCH REXROTH CANADA CORP.	3426 MAINWAY DRIVE BURLINGTON ON L7M 1A8	NNE/209.4	1.89	336

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
66	GEN	BOSCH REXROTH CANADA CORP.	3426 MAINWAY DRIVE BURLINGTON ON L7M 1A8	NNE/209.4	1.89	336
66	PAP	Bosch Rexroth Canada Corporation - Pneumatics Division	3426 Mainway Dr Burlington ON L7M 1A8	NNE/209.4	1.89	337
66	PAP	Bosch Rexroth Canada Corporation - Linear Division	3426 Mainway Dr Burlington ON L7M 1A8	NNE/209.4	1.89	337
66	PAP	Bosch Rexroth Canada Corporation - Controls Division	3426 Mainway Dr Burlington ON L7M 1A8	NNE/209.4	1.89	337
66	SCT	Bosch Rexroth Canada Corp.	3426 Mainway Burlington ON L7M 1A8	NNE/209.4	1.89	337
66	SCT	Bosch Rexroth Canada Corp.	3426 Mainway Dr Burlington ON L7M 1A8	NNE/209.4	1.89	338
66	SCT	BASIC TECHNOLOGIES CORP.	3426 MAINWAY DR BURLINGTON ON L7M 1A8	NNE/209.4	1.89	33
67	GEN	Alkano Grinding and Stamping Company Limited	3321 Mainway, Unit A & B Burlington ON L7M 1A6	WNW/209.9	2.07	339
67	GEN	Alkano Grinding and Stamping Company Limited	3321 Mainway, Unit A & B Burlington ON L7M 1A6	WNW/209.9	2.07	339
67	GEN	Alkano Grinding and Stamping Company Limited	3321 Mainway, Unit A & B Burlington ON L7M 1A6	WNW/209.9	2.07	340
67	GEN	Alkano Grinding and Stamping Company Limited	3321 Mainway, Unit A & B Burlington ON L7M 1A6	WNW/209.9	2.07	340
67	GEN	QUALITY CYLINDER SERVICE	3321 MAINWAY BURLINGTON ON L7M 1A6	WNW/209.9	2.07	340
67	GEN	Alkano Grinding and Stamping Company Limited	3321 Mainway, Unit A & B Burlington ON	WNW/209.9	2.07	341
67	GEN	QUALITY HYDRAULIC SERVICE	3321 MAINWAY BURLINGTON ON L7M 1A6	WNW/209.9	2.07	341
67	GEN	WELCAN MACHINE SHOP	3321 MAINWAY DRIVE BURLINGTON ON L7M 1A6	WNW/209.9	2.07	341
67	GEN	Alkano Grinding and Stamping Company Limited	3321 Mainway, Unit A & B Burlington ON	WNW/209.9	2.07	342
67	GEN	Airon HVAC Service Ltd	3321 Mainway Drive Unit A & B Burlington ON L7M 1A6	WNW/209.9	2.07	342
67	GEN	QUALITY (OUT OF BUSINESS) 33-183	3321 MAINWAY BURLINGTON ON L7M 1A6	WNW/209.9	2.07	342
67	SCT	WELCAN MACHINE SHOP	3321 MAINWAY DR BURLINGTON ON L7M 1A6	WNW/209.9	2.07	34
68	GEN	EAGLE-QUIP INC.	3331 MAINWAY BURLINGTON ON L7M 1A6	NW/212.4	2.13	343
68	GEN	FAIRWAY INDUSTRIAL	3331 MAINWAY BURLINGTON ON L7M 1A6	NW/212.4	2.13	343
68	GEN	FAIRWAY INDUSTRIAL	3331 MAINWAY BURLINGTON ON L7M 1A6	NW/212.4	2.13	343
68	GEN	FAIRWAY INDUSTRIAL 14-355	3331 MAINWAY BURLINGTON ON L7M 1A6	NW/212.4	2.13	344
68	SCT	Halton Metal Outlet Ltd.	3331 Mainway Burlington ON L7M 1A6	NW/212.4	2.13	344
68	SCT	HALTON METAL OUTLET LTD.	3331 Mainway Dr Burlington ON L7M 1A6	NW/212.4	2.13	344
69	WWIS		Burlington ON	SSW/216.4	-3.53	345

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
70	CA	HUNTER DRUMS LIMITED	1121 PIONEER RD. BURLINGTON CITY ON L7M 1K5	SSE/220.5	-3.93	34
70	CA	HUNTER DRUMS LIMITED	1121 PIONEER ROAD BURLINGTON CITY ON L7M 1K5	SSE/220.5	-3.93	34
70	CA	Hunter Drums Limited	1121 Pioneer Road Burlington ON L7M 1K5	SSE/220.5	-3.93	347
70	EASR	MAUSER CANADA LTD.	1121 PIONEER RD BURLINGTON ON L7M 1K5	SSE/220.5	-3.93	348
70	EBR	Mauser Canada Ltd.	1121 Pioneer Road Burlington, Regional Municipality of Halton CITY OF BURLINGTON ON	SSE/220.5	-3.93	348
70	EBR	Hunter Drums Limited	1121 Pioneer Road Burlington Ontario L7M 1K5 Burlington ON	SSE/220.5	-3.93	348
70	ECA	Mauser Canada Ltd.	1121 Pioneer Rd Burlington ON	SSE/220.5	-3.93	348
70	ECA	Hunter Drums Limited	1121 Pioneer Road Burlington ON L7M 1K5	SSE/220.5	-3.93	349
70	ECA	Mauser Canada Ltd.	1121 Pioneer Road Burlington ON	SSE/220.5	-3.93	349
70	EHS		1121 Pioneer Rd. Burlington ON L7M 1K5	SSE/220.5	-3.93	349
70	EHS		1121 Pioneer Rd Burlington ON L7M1K5	SSE/220.5	-3.93	349
70	EHS		1121 Pioneer road n/a ON L7M 1K5	SSE/220.5	-3.93	350
70	EHS		1121 Pioneer road n/a ON L7M 1K5	SSE/220.5	-3.93	350
70	EHS		1121 Pioneer Road Burlington ON	SSE/220.5	-3.93	350
70	EHS		1121 Pioneer road n/a ON L7M 1K5	SSE/220.5	-3.93	351
70	GEN	MAUSER CANADA LTD.	1121 PIONEER ROAD BURLINGTON ON L7M 1K5	SSE/220.5	-3.93	351
70	GEN	MAUSER CANADA LTD.	1121 PIONEER ROAD BURLINGTON ON L7M 1K5	SSE/220.5	-3.93	351
70	GEN	MAUSER CANADA LTD.	1121 PIONEER ROAD BURLINGTON ON	SSE/220.5	-3.93	352
70	GEN	MAUSER CANADA LTD.	1121 PIONEER ROAD BURLINGTON ON L7M1K5	SSE/220.5	-3.93	353
70	GEN	HUNTER DRUMS LTD	1121 PIONEER RD BURLINGTON ON L7M 1K5	SSE/220.5	-3.93	353
70	GEN	MAUSER CANADA LTD. STEEL DIVISION	1121 PIONEER ROAD BURLINGTON ON L7M1K5	SSE/220.5	-3.93	354
70	GEN	MAUSER CANADA LTD.	1121 PIONEER ROAD BURLINGTON ON L7M1K5	SSE/220.5	-3.93	354
70	GEN	RUSSELL-STANLEY	1121 PIONEER ROAD BURLINGTON ON L7M 1K5	SSE/220.5	-3.93	355
70	GEN	HUNTER DRUMS LIMITED	1121 PIONEER ROAD BURLINGTON ON L7M 1K5	SSE/220.5	-3.93	355
70	GEN	MAUSER CANADA LTD.	1121 PIONEER ROAD BURLINGTON ON L7M 1K5	SSE/220.5	-3.93	356

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
70	GEN	HUNTER DRUMS LIMITED 20-020	1121 PIONEER ROAD BURLINGTON ON L7M 1K5	SSE/220.5	-3.93	357
70	GEN	MAUSER CANADA LTD.	1121 PIONEER ROAD BURLINGTON ON L7M1K5	SSE/220.5	-3.93	357
70	GEN	MAUSER CANADA LTD.	1121 PIONEER ROAD BURLINGTON ON L7M 1K5	SSE/220.5	-3.93	358
70	GEN	MAUSER CANADA LTD.	1121 PIONEER ROAD BURLINGTON ON L7M 1K5	SSE/220.5	-3.93	359
70	NPCB	HUNTER DRUMS LIMITED	1121 PIONEER ROAD BURLINGTON ON L7M 1K5	SSE/220.5	-3.93	36
70	NPRI	Mauser Canada Ltd.	1121 Pioneer Road Burlington ON l7m1k5	SSE/220.5	-3.93	361
70	NPRI	MAUSER CANADA LIMITED	1121 Pioneer Road Burlington ON l7m1k5	SSE/220.5	-3.93	363
70	NPRI	MAUSER CANADA LTD.	1121 Pioneer Road Burlington ON l7m1k5	SSE/220.5	-3.93	365
70	NPRI	MAUSER CANADA LIMITED	1121 Pioneer Road Burlington ON l7m1k5	SSE/220.5	-3.93	367
70	NPRI	HUNTER DRUMS LIMITED	1121 PIONEER ROAD NOT AVAILABLE BURLINGTON ON L7M1K5	SSE/220.5	-3.93	369
70	NPRI	MAUSER CANADA LTD.	1121 Pioneer Road Burlington ON l7m1k5	SSE/220.5	-3.93	371
70	NPRI	MAUSER CANADA LTD.	1121 Pioneer Road Burlington ON l7m1k5	SSE/220.5	-3.93	373
70	NPRI	MAUSER CANADA LIMITED	1121 Pioneer Road Burlington ON l7m1k5	SSE/220.5	-3.93	375
70	NPRI	MAUSER CANADA LTD.	1121 Pioneer Road Burlington ON l7m1k5	SSE/220.5	-3.93	377
70	NPRI	MAUSER CANADA LTD.	1121 Pioneer Road Burlington ON l7m1k5	SSE/220.5	-3.93	379
70	NPRI	HUNTER DRUMS LIMITED	1121 PIONEER ROAD NOT AVAILABLE BURLINGTON ON L7M1K5	SSE/220.5	-3.93	381
70	NPRI	Mauser Canada Ltd.	1121 Pioneer Road Burlington ON l7m1k5	SSE/220.5	-3.93	383
70	NPRI	MAUSER CANADA LIMITED	1121 Pioneer Road Burlington ON l7m1k5	SSE/220.5	-3.93	385
70	NPRI	MAUSER CANADA LIMITED	1121 Pioneer Road Burlington ON l7m1k5	SSE/220.5	-3.93	388
70	NPRI	MAUSER CANADA LIMITED	1121 Pioneer Road Burlington ON l7m1k5	SSE/220.5	-3.93	390
70	NPRI	Mauser Canada Ltd.	1121 Pioneer Road Burlington ON l7m1k5	SSE/220.5	-3.93	393
70	OPCB	HUNTER DRUMS LIMITED	1121 PIONEER ROAD BURLINGTON ON L7M 1K5	SSE/220.5	-3.93	394
70	SCT	HUNTER DRUMS LIMITED	1121 PIONEER RD BURLINGTON ON L7M 1K5	SSE/220.5	-3.93	39
71	ECA	Bosch Rexroth Canada Corp.	3426 Mainway Burlington ON L7M 1A8	NNE/221.8	2.07	395
71	GEN	BOSCH REXROTH CANADA CORP.	3426 MAINWAY DRIVE BURLINGTON ON	NNE/221.8	2.07	395
72	SCT	Sandtron Automation Ltd.	1221 Dillon Rd Burlington ON L7M 1K6	N/224.1	2.41	396

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
73	SCT	Mauser Canada Ltd.	1121 Pioneer Rd Burlington ON L7M 1K5	S/226.0	-4.31	396
73	SCT	Hunter Drums Ltd.	1121 Pioneer Rd Burlington ON L7L 6C7	S/226.0	-4.31	396
74	EBR	Bosch Rexroth Canada Corp.	3426 Mainway Drive Burlington, Regional Municipality of Halton L7M 1A8 CITY OF BURLINGTON ON	N/227.0	2.07	397
74	GEN	BOSCH REXROTH CANADA CORP.	3426 MAINWAY DRIVE BURLINGTON ON L7M 1A8	N/227.0	2.07	397
74	GEN	BOSCH REXROTH CANADA CORP.	3426 MAINWAY DRIVE BURLINGTON ON L7M 1A8	N/227.0	2.07	398
74	GEN	BOSCH REXROTH CANADA CORP.	3426 MAINWAY DRIVE BURLINGTON ON L7M 1A8	N/227.0	2.07	398
74	GEN	BOSCH REXROTH CANADA CORP.	3426 MAINWAY DRIVE BURLINGTON ON L7M 1A8	N/227.0	2.07	399
75	WWIS		 BURLINGTON ON	SW/228.4	-1.93	400
76	GEN	NIXON INTEGRATED MACHINING DESIGN LTD.	3291 Mainway Drive Units 5 & 6 Burlington ON L7M 1A6	WNW/232.7	1.52	402
76	GEN	NIXON INTEGRATED MACHINING DESIGN LTD.	3291 Mainway Drive Units 5 & 6 Burlington ON L7M 1A6	WNW/232.7	1.52	403
76	GEN	NIXON INTEGRATED MACHINING DESIGN LTD.	3291 Mainway Drive Units 5 & 6 Burlington ON L7M 1A6	WNW/232.7	1.52	403
76	GEN	NIXON INTEGRATED MACHINING DESIGN LTD.	3291 Mainway Drive Units 5 & 6 Burlington ON L7M 1A6	WNW/232.7	1.52	403
76	GEN	NIXON INTEGRATED MACHINING DESIGN LTD.	3291 MAINWAY DRIVE, UNITS 5 & 6 BURLINGTON ON L7M 1A6	WNW/232.7	1.52	404
76	GEN	NIXON INTEGRATED MACHINING DESIGN LTD.	3291 Mainway Drive Units 5 & 6 Burlington ON L7M 1A6	WNW/232.7	1.52	404
76	GEN	NIXON INTEGRATED MACHINING DESIGN LTD.	3291 Mainway Drive Units 5 & 6 Burlington ON L7M 1A6	WNW/232.7	1.52	404
76	GEN	BROWN FALCON MACHINE & TOOL	3291 MAINWAY, UNIT 1 & 2 BURLINGTON ON L7M 1A6	WNW/232.7	1.52	405
76	GEN	NIXON INTEGRATED MACHINING DESIGN LTD.	3291 Mainway Drive Units 5 & 6 Burlington ON L7M 1A6	WNW/232.7	1.52	405
76	GEN	NIXON INTEGRATED MACHINING DESIGN LTD.	3291 Mainway Drive Units 5 & 6 Burlington ON L7M 1A6	WNW/232.7	1.52	406
76	GEN	NIXON INTEGRATED MACHINING DESIGN LTD.	3291 Mainway Drive Units 5 & 6 Burlington ON	WNW/232.7	1.52	406
76	GEN	NIXON INTEGRATED MACHINING DESIGN LTD.	3291 Mainway Drive Units 5 & 6 Burlington ON L7M 1A6	WNW/232.7	1.52	406
76	GEN	NIXON INTEGRATED MACHINING DESIGN LTD.	3291 Mainway Drive Units 5,6,7,8and9 Burlington ON L7M 1A6	WNW/232.7	1.52	407
76	GEN	BROWN FALCON MACHINE & TOOL	3291 MAINWAY, UNITS 1-2 BURLINGTON ON L7M 1A6	WNW/232.7	1.52	407
76	PES	SOLOMON, J.N. ENTERPRISES LIMITED	3291 MAINWAY #5 BURLINGTON ON L7M 1A6	WNW/232.7	1.52	40
76	SCT	BROWN FALCON MACHINE & TOOL	3291 MAINWAY DR UNIT 1-2 BURLINGTON ON L7M 1A6	WNW/232.7	1.52	40
76	SCT	Nixon Integrated Machining	3291 Mainway Unit 5-6 Burlington ON L7M 1A6	WNW/232.7	1.52	408

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
76	SCT	MCKELLAR MACHINE PRODUCTS LTD.	3291 MAINWAY DR BURLINGTON ON L7M 1A6	WNW/232.7	1.52	40
76	SCT	BROWN FALCON MACHINE,TOOL/DIE	3291 Mainway Dr Unit 1-2 Burlington ON L7M 1A6	WNW/232.7	1.52	408
76	SCT	BROWN FALCON MACHINE,TOOL & DI	3291 MAINWAY DR UNIT 1-2 BURLINGTON ON L7M 1A6	WNW/232.7	1.52	40
76	SCT	Brown Falcon Machine,Tool & Die Ltd.	3291 Mainway Unit 1-2 Burlington ON L7M 1A6	WNW/232.7	1.52	409
77	WWIS		ON	E/232.9	-2.92	409
78	EHS		1101 Blair Road Burlington ON	ENE/233.7	-2.98	410
79	GEN	TRAVIS INDUSTRIAL MAINTENANCE	3327 MAINWAY, UNIT C BURLINGTON ON L7M 1A6	NW/236.4	2.64	410
79	GEN	TRAVIS INDUSTRIAL MAINTENANCE LIMITED	3327 MAINWAY, UNIT C BURLINGTON ON L7M 1A6	NW/236.4	2.64	410
79	GEN	TRAVIS INDUSTRIAL MAINTENANCE LIMITED	3327 MAINWAY DRIVE UNIT C BURLINGTON ON L7M 1A6	NW/236.4	2.64	411
79	SCT	D F ELECTRONICS INC	3327 MAINWAY UNIT A BURLINGTON ON L7M 1A6	NW/236.4	2.64	41
79	SCT	OnDrive Inc.	3327 Mainway Unit C Burlington ON L7M 1A6	NW/236.4	2.64	411
79	SCT	Firecraft Kilns Sales & Service	3327 Mainway Dr Unit B Burlington ON L7M 1A6	NW/236.4	2.64	411
80	SCT	HELEC INSULATION LTD	3323 MAINWAY DR UNIT D BURLINGTON ON L7M 1A6	WNW/237.9	2.07	41
80	SCT	Helec Insulation Ltd.	3323 Mainway Unit D Burlington ON L7M 1A6	WNW/237.9	2.07	412
80	SCT	PST MACHINING LTD.	3323 Mainway Dr Unit C Burlington ON L7M 1A6	WNW/237.9	2.07	412
80	SCT	HELEC INSULATION LTD.	3323 Mainway Dr Unit D Burlington ON L7M 1A6	WNW/237.9	2.07	412
80	SCT	P S T MACHINING LIMITED	3323 MAINWAY DR UNIT C BURLINGTON ON L7M 1A6	WNW/237.9	2.07	41
81	WWIS		BURLINGTON ON	SSW/238.1	-2.99	413
82	WWIS		Burlington ON	SW/242.0	-1.93	415
83	GEN	BRAMKAL CONTRACTORS INC.	3450 LANDMARK ROAD BURLINGTON ON L7M 1S8	NE/243.6	-0.08	423
83	GEN	BramKal Contractors Inc.	3450 Landmark Rd. Burlington ON L7M 1S8	NE/243.6	-0.08	423
83	GEN	Burlington Cutting and Finishing Inc.	3450 landmark rd Unit B Burlington ON L7M 1S8	NE/243.6	-0.08	424
83	GEN	Burlington Cutting and Finishing Inc.	3450 landmark rd Unit B Burlington ON L7M 1S8	NE/243.6	-0.08	424
83	GEN	Bramkal contractors Inc.	3450 Landmark Road Burlington ON L7M 1S8	NE/243.6	-0.08	424
83	GEN	A-1 Asphalt Maintenance Ltd.	3450 Landmark Road Unit B Burlington ON L7M 1S8	NE/243.6	-0.08	425
83	SCT	Tach West Technologies Ltd.	3450C Landmark Rd Burlington ON L7M 1S8	NE/243.6	-0.08	425

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
83	SCT	Burlington Cutting & Finishing	3450B Landmark Rd Burlington ON L7M 1S8	NE/243.6	-0.08	425
84	EHS		3455 Landmark Rd Burlington ON L7M1T4	NE/245.8	1.07	426
84	GEN	COMSTOCK CANADA LTD.	3455 Landmark Road Burlington ON L7M 1T4	NE/245.8	1.07	426
84	GEN	COMSTOCK CANADA LTD.	3455 Landmark Road Burlington ON L7M 1T4	NE/245.8	1.07	426
84	GEN	COMSTOCK CANADA LTD.	3455 LANDMARK ROAD BURLINGTON ON L7M 1T4	NE/245.8	1.07	427
84	GEN	COMSTOCK CANADA LTD.	3455 Landmark Road Burlington ON L7M1T4	NE/245.8	1.07	427
84	GEN	COMSTOCK CANADA LTD.	3455 Landmark Road Burlington ON L7M 1T4	NE/245.8	1.07	428
84	GEN	COMSTOCK CANADA LTD.	3455 Landmark Road Burlington ON L7M 1T4	NE/245.8	1.07	428
84	GEN	COMSTOCK CANADA	3455 LANDMARK ROAD BURLINGTON ON L7M 1T4	NE/245.8	1.07	429
84	GEN	COMSTOCK CANADA LTD.	3455 Landmark Road Burlington ON	NE/245.8	1.07	429
84	PAP	Comstock Canada Ltd.	3455 Landmark Rd Burlington ON L7M 1T4	NE/245.8	1.07	430
85	CA	Burlington Technologies Inc.	Burlington ON	WSW/248.1	0.04	430
85	EBR	Burlington Technologies Inc.	3267 Mainway Burlington, Regional Municipality Of Halton CITY OF BURLINGTON ON	WSW/248.1	0.04	430
85	EBR	Revstone Industries Burlington Inc., o/aBurlington Technologies Inc.	3267 Mainway Burlington, Regional Municipality Of Halton CITY OF BURLINGTON ON	WSW/248.1	0.04	431
85	EBR	Burlington Technologies Inc.	3267 Mainway Burlington Ontario L7M 1A6 Burlington ON	WSW/248.1	0.04	431
85	EBR	Burlington Technologies Inc.	3267 Mainway Burlington Ontario L7M 1A6 Burlington ON	WSW/248.1	0.04	431
85	EBR	Burlington Technologies Inc.	3267 Mainway Burlington Ontario L7M 1A6 Burlington ON	WSW/248.1	0.04	432
85	ECA	Burlington Technologies Inc.	3267 Mainway Burlington ON L7M 1A6	WSW/248.1	0.04	432
85	ECA	Burlington Technologies Inc.	3267 Mainway Burlington ON L7M 1A6	WSW/248.1	0.04	432
85	ECA	Burlington Technologies Inc.	3267 Mainway Burlington ON L7M 1A6	WSW/248.1	0.04	433
85	ECA	Burlington Technologies Inc.	3267 Mainway Burlington ON L7M 1A6	WSW/248.1	0.04	433
85	NPRI	BURLINGTON TECHNOLOGIES INC.	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	WSW/248.1	0.04	433
86	SCT	HTM Sensors	3419 Mainway Burlington ON L7M 1A9	N/248.4	2.07	434
86	SPL	TRANSPORT TRUCK	DEC EXPRESS, 3419 MAINWAY TRANSPORT TRUCK (CARGO) BURLINGTON CITY ON L7M 1A9	N/248.4	2.07	43

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
87	CA		3267 Mainway Burlington ON L7M 1A6	W/251.3	1.07	435
87	CA	BURLINGTON TECHNOLOGIES INC.	3267 MAINWAY BURLINGTON CITY ON L7M 1A6	W/251.3	1.07	43
87	CA	Burlington Technologies Inc.	3267 Mainway Burlington ON L7M 1A6	W/251.3	1.07	436
87	CA	Burlington Technologies Inc.	3267 Mainway Burlington ON L7M 1A6	W/251.3	1.07	436
87	CA		3267 Mainway Burlington ON L7M 1A6	W/251.3	1.07	436
87	EHS		3267 Mainway Burlington ON L7M1A6	W/251.3	1.07	437
87	EHS		3267 Mainway Burlington ON L7M 1A6	W/251.3	1.07	437
87	EHS		3267 Mainway Drive Burlington ON L7M 1A6	W/251.3	1.07	437
87	GEN	REVSTONE INDUSTRIES BURLINGTON INC.	3267 MAINWAY BURLINGTON ON L7M 1A6	W/251.3	1.07	438
87	GEN	REVSTONE INDUSTRIES BURLINGTON INC.	3267 MAINWAY BURLINGTON ON L7M 1A6	W/251.3	1.07	438
87	GEN	NATIONAL RIGGING & TRANSPORTATION LTD.	3267 MAINWAY DR. BURLINGTON ON	W/251.3	1.07	439
87	GEN	BURLINGTON TECHNOLOGIES 06-271	BURLINGTON DIVISION 3267 MAINWAY BURLINGTON ON L7M 1A6	W/251.3	1.07	439
87	GEN	BURLINGTON TECHNOLOGIESINCORPORATED	3267 MAINWAY BURLINGTON ON L7M 1A6	W/251.3	1.07	439
87	GEN	BURLINGTON DIE CASTING	3267 MAINWAY BURLINGTON ON L7M 1A6	W/251.3	1.07	440
87	GEN	REVSTONE INDUSTRIES BURLINGTON INC.	3267 MAINWAY BURLINGTON ON L7M 1A6	W/251.3	1.07	440
87	GEN	BURLINGTON TECHNOLOGIES INCORPORATED	3267 MAINWAY BURLINGTON ON L7M 1A6	W/251.3	1.07	441
87	GEN	BURLINGTON TECHNOLOGIES	3267 MAINWAY BURLINGTON DIVISION BURLINGTON ON L7M 1A6	W/251.3	1.07	441
87	GEN	REVSTONE INDUSTRIES BURLINGTON INC.	3267 MAINWAY BURLINGTON ON L7M 1A6	W/251.3	1.07	442
87	SCT	BURLINGTON TECHNOLOGIES INC. -	3267 MAINWAY DR BURLINGTON ON L7M 1A6	W/251.3	1.07	44
87	SCT	Burlington Technologies Indus	3267 Mainway Burlington ON L7M 1A6	W/251.3	1.07	443
87	SCT	BURLINGTON TECHNOLOGIES INC.	3267 MAINWAY DR BURLINGTON ON L7M 1A6	W/251.3	1.07	44
87	SCT	Burlington Technologies Inc. - Burlington Division	3267 Mainway Dr Burlington ON L7M 1A6	W/251.3	1.07	444
87	SPL	Burlington Technologies Inc.	3267 Mainway Burlington ON L7M 1A6	W/251.3	1.07	444
87	SPL	Burlington Technologies Inc.	3267 Mainway Burlington ON L7M 1A6	W/251.3	1.07	445
88	SCT	NELSON BUSINESS MACHINES LTD.	3460 MAINWAY DR BURLINGTON ON L7M 1A8	NNE/253.4	2.07	445
89	WWIS		BURLINGTON ON	SW/255.5	-1.13	445

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
90	SCT	Feed Rite Automation inc.	3325A Mainway Burlington ON L7M 1A6	NW/255.8	3.07	448
91	WWIS		ON	W/256.1	1.07	448
92	NPRI	HOWELL PACKAGING LIMITED	3230 MAINWAY AVENUE NOT AVAILABLE BURLINGTON ON L7M 1A5	WSW/259.4	-0.29	449
92	NPRI	HOWELL PACKAGING LIMITED	3230 MAINWAY AVENUE NOT AVAILABLE BURLINGTON ON L7M 1A5	WSW/259.4	-0.29	450
92	NPRI	HOWELL PACKAGING LIMITED	3230 MAINWAY AVENUE NOT AVAILABLE BURLINGTON ON L7M 1A5	WSW/259.4	-0.29	451
92	NPRI	HOWELL PACKAGING LIMITED	3230 MAINWAY AVENUE NOT AVAILABLE BURLINGTON ON L7M 1A5	WSW/259.4	-0.29	452
92	NPRI	HOWELL PACKAGING	3230 MAINWAY AVENUE NOT AVAILABLE BURLINGTON ON L7M 1A5	WSW/259.4	-0.29	453
92	NPRI	HOWELL PACKAGING LIMITED	3230 MAINWAY AVENUE NOT AVAILABLE BURLINGTON ON L7M 1A5	WSW/259.4	-0.29	454
92	NPRI	HOWELL PACKAGING LIMITED	3230 MAINWAY AVENUE NOT AVAILABLE BURLINGTON ON L7M 1A5	WSW/259.4	-0.29	456
92	NPRI	DOVER PACKAGING LIMITED (FORMERLY HOWELL PACKAGING LIMITED)	3230 MAINWAY AVENUE NOT AVAILABLE BURLINGTON ON L7M 1A5	WSW/259.4	-0.29	457
92	NPRI	HOWELL PACKAGING LIMITED	3230 MAINWAY AVENUE NOT AVAILABLE BURLINGTON ON L7M 1A5	WSW/259.4	-0.29	458
92	WWIS		Burlington ON	WSW/259.4	-0.29	459
93	EHS		3245 Mainway Burlington ON L7M1A6	WSW/262.4	1.07	467
94	EHS		1232 Dillon Road Burlington ON L7M 1N3	NNW/269.6	3.24	467
94	EHS		1232 Dillon Rd Burlington ON L7M1N3	NNW/269.6	3.24	468
94	GEN	JC CNC WORKS INC.	1232 DILLON ROAD, UNIT 1 BURLINGTON ON L7M 1N3	NNW/269.6	3.24	468
94	GEN	JC CNC WORKS INC.	1232 DILLON ROAD, UNIT 1 BURLINGTON ON L7M 1N3	NNW/269.6	3.24	468
94	GEN	X-PERT METAL FINISHING LTD.	1232 DILLON RD. BURLINGTON ON L7M 1N3	NNW/269.6	3.24	469
94	GEN	X-PERT METAL FINISHING LTD.	1232 DILLON ROAD BURLINGTON ON L7M 1N3	NNW/269.6	3.24	469
94	GEN	JC CNC WORKS INC.	1232 DILLON ROAD, UNIT 1 BURLINGTON ON L7M 1N3	NNW/269.6	3.24	469
94	GEN	JC CNC WORKS INC.	1232 DILLON ROAD, UNIT 1 BURLINGTON ON L7M 1N3	NNW/269.6	3.24	470
94	GEN	JC CNC WORKS INC.	1232 DILLON ROAD, UNIT 1 BURLINGTON ON L7M 1N3	NNW/269.6	3.24	470
94	GEN	JC CNC WORKS INC.	1232 DILLON ROAD, UNIT 1 BURLINGTON ON L7M 1N3	NNW/269.6	3.24	470
94	GEN	Hahn and Sons Ltd	1232 Dillon Road, Unit #3 Burlington ON L7M 1N3	NNW/269.6	3.24	470

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
94	GEN	JC CNC WORKS INC.	1232 DILLON ROAD, UNIT 1 BURLINGTON ON L7M 1N3	NNW/269.6	3.24	471
94	GEN	Hahn and Sons Ltd	1232 Dillon Road, Unit #3 Burlington ON L7M 1N3	NNW/269.6	3.24	471
94	GEN	Hahn and Sons Ltd	1232 Dillon Road, Unit #3 Burlington ON L7M 1N3	NNW/269.6	3.24	471
94	GEN	Hahn and Sons Ltd	1232 Dillon Road, Unit #3 Burlington ON L7M 1N3	NNW/269.6	3.24	472
94	GEN	X-PERT METAL FINISHING LTD. 43-024	1232 DILLON RD. BURLINGTON ON L7M 1N3	NNW/269.6	3.24	472
94	GEN	JC CNC WORKS INC.	1232 DILLON ROAD, UNIT 1 BURLINGTON ON L7M 1N3	NNW/269.6	3.24	472
94	GEN	Hahn and Sons Ltd	1232 Dillon Road, Unit #3 Burlington ON	NNW/269.6	3.24	473
94	SCT	J.C. CNC Works Inc.	1232 Dillon Rd Unit 1 Burlington ON L7M 1N3	NNW/269.6	3.24	473
94	SCT	Force Enterprises Ltd.	1232 Dillon Rd Unit 2 Burlington ON L7M 1N3	NNW/269.6	3.24	473
94	SPL	EXPERT METALS	1232 DILLON RD. BURLINGTON PLANT 1232 DILLON ROAD BURLINGTON CITY ON L7M 1N3	NNW/269.6	3.24	47
95	SPL	Purolator Courier Ltd.	3255 Mainway Drive Burlington ON L7M 1A6	WSW/282.2	0.53	474
96	WWIS		lot 12 con 2 ON	E/284.7	-3.93	474
97	GEN	Burlington Racquet Club	1233 Dillon ROad Burlington ON L7M 1K6	N/288.5	3.82	475
98	WWIS		ON	NE/290.0	-0.83	475
99	EHS		1233 Dillon Rd Burlington ON L7M1K6	N/292.8	3.07	476
100	CA	L. A. Rubber Inc.	3466 Landmark Road Burlington ON L7M 1S8	NE/295.1	-0.91	476
100	CA	L. A. Rubber Inc.	3466 Landmark Rd Burlington ON L7M 1S8	NE/295.1	-0.91	477
100	EBR	L. A. Rubber Inc.	3466 Landmark Road Burlington Regional Municipality of Halton L7M 1S8 CITY OF BURLINGTON ON	NE/295.1	-0.91	477
100	EBR	L. A. Rubber Inc.	3466 Landmark Road Burlington Ontario L7M 1S8 Burlington ON	NE/295.1	-0.91	477
100	ECA	L. A. Rubber Inc.	3466 Landmark Rd Burlington ON L7M 1S8	NE/295.1	-0.91	478
100	ECA	L. A. Rubber Inc.	3466 Landmark Road Burlington ON L7M 1S8	NE/295.1	-0.91	478
100	GEN	L.A. RUBBER INC.	3466 LANDMARK ROAD BURLINGTON ON L7M 1S8	NE/295.1	-0.91	478
100	SCT	L A RUBBER INC	3466 LANDMARK RD BURLINGTON ON L7M 1S8	NE/295.1	-0.91	47
100	SCT	L.A. Rubber Inc.	3466 Landmark Rd Burlington ON L7M 1S8	NE/295.1	-0.91	479

Executive Summary: Summary By Data Source

BORE - Borehole

A search of the BORE database, dated 1875-Jul 2014 has found that there are 2 BORE site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	ON	32.1	5
	ON	34.7	6

CA - Certificates of Approval

A search of the CA database, dated 1985-Oct 30, 2011* has found that there are 24 CA site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Atlas Copco Canada Inc.	1157 Blair Road Burlington ON L7M 1P9	57.1	7
690661 Ontario Limited	3388 Mainway Drive Burlington ON L7M 1A8	75.9	12
	3400 Landmark Road Burlington ON L7M 1S8	79.1	15
Airmax Compressor Services Ltd.	3400 Landmark Rd Burlington ON L7M 1S8	79.1	15
Canadian Hazmat & Decon Services Inc.	1153 Pioneer Rd Burlington ON L7M 1K5	88.5	17
Pennzoil Quaker-State Canada Incorporated	1101 Blair Road Burlington ON L7M 1T3	143.2	37
RIEGER PRINTING INK CO. LTD.	3410 MAINWAY DRIVE BURLINGTON CITY ON L7M 1A8	152.1	38
REHAU INDUSTRIES INC.	1149 PIONEER ROAD BURLINGTON CITY ON L7M 1K5	160.4	43
RIEGER PRINTING INK CO. LTD.	3410 MAIN DRIVE BURLINGTON CITY ON	172.5	51
GENNUM CORPORATION	3435 LANDMARK ROAD BURLINGTON CITY ON L7M 1T4	181.1	54
Bosch Rexroth Canada Corp.	3435 Landmark Road Burlington ON L7M 1T4	181.1	54
	3435 Landmark Road Burlington ON L7M 1T4	181.1	54
Bosch Rexroth Canada Corp.	3426 Mainway Burlington ON L7M 1A8	209.4	66

Site	Address	Distance (m)	Map Key
HUNTER DRUMS LIMITED	1121 PIONEER RD. BURLINGTON CITY ON L7M 1K5	220.5	70
HUNTER DRUMS LIMITED	1121 PIONEER ROAD BURLINGTON CITY ON L7M 1K5	220.5	70
Hunter Drums Limited	1121 Pioneer Road Burlington ON L7M 1K5	220.5	70
Burlington Technologies Inc.	Burlington ON	248.1	85
	3267 Mainway Burlington ON L7M 1A6	251.3	87
BURLINGTON TECHNOLOGIES INC.	3267 MAINWAY BURLINGTON CITY ON L7M 1A6	251.3	87
Burlington Technologies Inc.	3267 Mainway Burlington ON L7M 1A6	251.3	87
Burlington Technologies Inc.	3267 Mainway Burlington ON L7M 1A6	251.3	87
	3267 Mainway Burlington ON L7M 1A6	251.3	87
L. A. Rubber Inc.	3466 Landmark Road Burlington ON L7M 1S8	295.1	100
L. A. Rubber Inc.	3466 Landmark Rd Burlington ON L7M 1S8	295.1	100

CHEM - Chemical Register

A search of the CHEM database, dated 1999-Jan 31, 2018 has found that there are 4 CHEM site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
QUADRA CHEMICALS LTD	1100 BLAIR RD BURLINGTON ON L7M 1K9	166.2	44
QUADRA CHEMICALS LTD	1100 BLAIR RD BURLINGTON ON L7M1K9	169.5	48
QUADRA CHEMICALS LTD	1100 BLAIR RD BURLINGTON ON L7M1K9	169.5	48
QUADRA CHEMICALS LTD	1100 BLAIR RD BURLINGTON ON L7M1K9	169.5	48

EASR - Environmental Activity and Sector Registry

A search of the EASR database, dated Oct 2011-Jan 31, 2018 has found that there are 1 EASR site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
MAUSER CANADA LTD.	1121 PIONEER RD BURLINGTON ON L7M 1K5	220.5	70

EBR - Environmental Registry

A search of the EBR database, dated 1994-Feb 28, 2018 has found that there are 19 EBR site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Atlas Copco Canada Inc.	1157 Blair Road Burlington Ontario Burlington ON	57.1	7
Wardco Window and Door Manufacturing Inc.	1157 Blair Road Burlington, Regional Municipality of Halton L7M 1P9 CITY OF BURLINGTON ON	57.1	7
690661 Ontario Limited	3388 Mainway Drive Burlington Ontario L7M 1A8 Burlington ON	75.9	12
Airmax Compressor Services Ltd.	3400 Landmark Road Burlington Regional Municipality Of Halton L7M 1S8 CITY OF BURLINGTON ON	79.1	15
Millcraft Systems Inc.	3400 Landmark Road Burlington Ontario L7M 1S8 Burlington ON	79.1	15
Pennzoil Quaker-State Canada Incorporated	1101 Blair Road Burlington Ontario L7M 1T3 Burlington ON	143.2	37
Rieger Printing Ink Co. Ltd.	3410 Mainway Drive CITY OF BURLINGTON ON	152.1	38
Bosch Rexroth Canada Corp.	3435 Landmark Road Burlington Ontario L7M 1T4 Burlington ON	181.1	54
EcoSynthetix Inc.	3365 Mainway Drive Burlington, Regional Municipality of Halton L7M 1A6 CITY OF BURLINGTON ON	204.9	64
Hunter Drums Limited	1121 Pioneer Road Burlington Ontario L7M 1K5 Burlington ON	220.5	70
Mauser Canada Ltd.	1121 Pioneer Road Burlington, Regional Municipality of Halton CITY OF BURLINGTON ON	220.5	70
Bosch Rexroth Canada Corp.	3426 Mainway Drive Burlington, Regional Municipality of Halton L7M 1A8 CITY OF BURLINGTON ON	227.0	74
Burlington Technologies Inc.	3267 Mainway Burlington, Regional Municipality Of Halton CITY OF BURLINGTON ON	248.1	85
Revstone Industries Burlington Inc., o/aBurlington Technologies Inc.	3267 Mainway Burlington, Regional Municipality Of Halton CITY OF BURLINGTON ON	248.1	85
Burlington Technologies Inc.	3267 Mainway Burlington Ontario L7M 1A6 Burlington ON	248.1	85
Burlington Technologies Inc.	3267 Mainway Burlington Ontario L7M 1A6 Burlington ON	248.1	85
Burlington Technologies Inc.	3267 Mainway Burlington Ontario L7M 1A6 Burlington ON	248.1	85
L. A. Rubber Inc.	3466 Landmark Road Burlington Regional Municipality of Halton L7M 1S8 CITY OF BURLINGTON ON	295.1	100

Site	Address	Distance (m)	Map Key
L. A. Rubber Inc.	3466 Landmark Road Burlington Ontario L7M 1S8 Burlington ON	295.1	100

ECA - Environmental Compliance Approval

A search of the ECA database, dated Oct 2011-Jan 31, 2018 has found that there are 19 ECA site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Atlas Copco Canada Inc.	1157 Blair Road Burlington ON H8N 3A9	57.1	7
Wardco Window and Door Manufacturing Inc.	1157 Blair Road City of Burlington ON	57.1	7
Wardco Window and Door Manufacturing Inc.	1157 Blair Rd Burlington ON	57.1	7
690661 Ontario Limited	3388 Mainway Drive Burlington ON L7M 1A8	75.9	12
Airmax Compressor Services Ltd.	3400 Landmark Rd Burlington ON L7M 1S8	79.1	15
Canadian Hazmat & Decon Services Inc.	1153 Pioneer Rd Burlington ON L7M 1K5	88.5	17
EcoSynthetix Inc.	3365 Mainway Dr Burlington ON L7M 1A6	124.8	32
Pennzoil Quaker-State Canada Incorporated	1101 Blair Road Burlington ON L7M 1T3	143.2	37
Bosch Rexroth Canada Corp.	3435 Landmark Road Burlington ON L7M 1A8	181.1	54
Mauser Canada Ltd.	1121 Pioneer Rd Burlington ON	220.5	70
Hunter Drums Limited	1121 Pioneer Road Burlington ON L7M 1K5	220.5	70
Mauser Canada Ltd.	1121 Pioneer Road Burlington ON	220.5	70
Bosch Rexroth Canada Corp.	3426 Mainway Burlington ON L7M 1A8	221.8	71
Burlington Technologies Inc.	3267 Mainway Burlington ON L7M 1A6	248.1	85
Burlington Technologies Inc.	3267 Mainway Burlington ON L7M 1A6	248.1	85
Burlington Technologies Inc.	3267 Mainway Burlington ON L7M 1A6	248.1	85
Burlington Technologies Inc.	3267 Mainway Burlington ON L7M 1A6	248.1	85
L. A. Rubber Inc.	3466 Landmark Rd Burlington ON L7M 1S8	295.1	100

Site	Address	Distance (m)	Map Key
L. A. Rubber Inc.	3466 Landmark Road Burlington ON L7M 1S8	295.1	100

EHS - ERIS Historical Searches

A search of the EHS database, dated 1999-Feb 28, 2018 has found that there are 40 EHS site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	1160 Blair Rd Burlington ON L7M1K9	0.0	1
	1157 BLAIR RD BURLINGTON ON L7M 1P9	57.1	7
	1140 Blair Rd Burlington ON L7M1K9	75.3	11
	1140 Blair Rd Burlington ON L7M1K9	75.3	11
	3330 Mainway Burlington ON L7M1A7	77.8	13
	3400 Landmark Road Burlington ON L7M 1S8	79.1	15
	1153 Pioneer Road Burlington ON	88.5	17
	3310-3312 Mainway Dr Burlington ON L7M 1A7	103.8	24
	3330-3342 MAINWAY BURLINGTON ON L7M 1A7	105.3	25
	3355 Mainway Burlington ON L7M 1A6	124.3	31
	3365 Mainway Burlington ON L7M 1A6	124.8	32
	3264 Mainway Burlington ON L7M1A7	143.0	36
	1101 Blair Road Burlington ON L7M 1T3	143.2	37
	3410 Mainway Burlington ON L7M 1A8	152.1	38
	1149 Pioneer Road Burlington ON L7M 1K5	160.4	43
	1100 Blair Road Burlington ON L7M 1K9	166.2	44
	3424 Landmark Road Burlington ON L7M 1S8	168.6	47
	3410 Mainway Burlington ON L7M1A8	178.3	53

Site	Address	Distance (m)	Map Key
	3410 Mainway Burlington ON L7M1A8	178.3	53
	3435 Landmark Road Burlington ON L7M 1T4	181.1	54
	3435 Landmark Rd Burlington ON L7M 1T4	181.1	54
	3365 Mainway Burlington ON	186.4	57
	3267 Mainway Road Burlington ON	189.9	58
	3365 Mainway Burlington ON L7M1A6	204.9	64
	Pioneer Road Burlington ON	209.0	65
	1121 Pioneer Rd. Burlington ON L7M 1K5	220.5	70
	1121 Pioneer Rd Burlington ON L7M1K5	220.5	70
	1121 Pioneer road n/a ON L7M 1K5	220.5	70
	1121 Pioneer road n/a ON L7M 1K5	220.5	70
	1121 Pioneer Road Burlington ON	220.5	70
	1121 Pioneer road n/a ON L7M 1K5	220.5	70
	1101 Blair Road Burlington ON	233.7	78
	3455 Landmark Rd Burlington ON L7M1T4	245.8	84
	3267 Mainway Burlington ON L7M1A6	251.3	87
	3267 Mainway Burlington ON L7M 1A6	251.3	87
	3267 Mainway Drive Burlington ON L7M 1A6	251.3	87
	3245 Mainway Burlington ON L7M1A6	262.4	93
	1232 Dillon Road Burlington ON L7M 1N3	269.6	94
	1232 Dillon Rd Burlington ON L7M1N3	269.6	94
	1233 Dillon Rd Burlington ON L7M1K6	292.8	99

EXP - List of TSSA Expired Facilities

A search of the EXP database, dated Feb 28, 2017 has found that there are 20 EXP site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD	1160 BLAIR RD BURLINGTON ON	0.0	1
GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD	1160 BLAIR RD BURLINGTON ON	0.0	1
GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD	1160 BLAIR RD BURLINGTON ON L7M 1K9	0.0	1
GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD	1160 BLAIR RD BURLINGTON ON	0.0	1
GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD	1160 BLAIR RD BURLINGTON ON L7M 1K9	0.0	1
LOOMIS COURIER SERVICE	1160 BLAIR RD BURLINGTON ON	0.0	1
LOOMIS COURIER SERVICE	1160 BLAIR RD BURLINGTON ON	0.0	1
GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD	1160 BLAIR RD BURLINGTON ON L7M 1K9	0.0	1
GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD	1160 BLAIR RD BURLINGTON ON L7M 1K9	0.0	1
AUTOMOTIVE MANAGER BELL CANADA	1171 PIONEER RD BURLINGTON ON	82.9	16
AUTOMOTIVE MANAGER BELL CANADA	1171 PIONEER RD BURLINGTON ON L7M 1K5	82.9	16
AUTOMOTIVE MANAGER BELL CANADA	1171 PIONEER RD BURLINGTON ON L7M 1K5	82.9	16
AUTOMOTIVE MANAGER BELL CANADA	1171 PIONEER RD BURLINGTON ON	82.9	16
AUTOMOTIVE MANAGER BELL CANADA	1171 PIONEER RD BURLINGTON ON	82.9	16
AUTOMOTIVE MANAGER BELL CANADA	1171 PIONEER RD BURLINGTON ON	82.9	16
AUTOMOTIVE MANAGER BELL CANADA	1171 PIONEER RD BURLINGTON ON L7M 1K5	82.9	16
HUMPTY DUMPTY FOODS LTD	3424 LANDMARK RD BURLINGTON ON	168.6	47
HUMPTY DUMPTY FOODS LTD	3424 LANDMARK RD BURLINGTON ON L7M 1S8	168.6	47
HUMPTY DUMPTY FOODS LTD	3424 LANDMARK RD BURLINGTON ON	168.6	47
HUMPTY DUMPTY FOODS LTD	3424 LANDMARK RD BURLINGTON ON L7M 1S8	168.6	47

FSTH - Fuel Storage Tank - Historic

A search of the FSTH database, dated Pre-Jan 2010* has found that there are 1 FSTH site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD	1160 BLAIR RD BURLINGTON ON L7M 1K9	0.0	1

GEN - Ontario Regulation 347 Waste Generators Summary

A search of the GEN database, dated 1986-December 31, 2017 has found that there are 335 GEN site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Royal Lepage State Realty Brokerage	1160 Blair Road Burlington ON L7M 1K9	0.0	1
s.e. sales and service ltd	1160 blair rd burlington ON L7M 1K9	0.0	1
JENMAR COLOUR SEPARATIONS INC.	1160 BLAIR RD. BURLINGTON ON L7M 1K9	0.0	1
JENMAR COLOUR SEPARATIONS INC. 22-133	1160 BLAIR RD. BURLINGTON ON L7M 1K9	0.0	1
SIMON CRANE RENTAL LTD.	1150 BLAIR ROAD, UNIT 6 BURLINGTON ON L7M 1K9	18.9	4
SIMON CRANE RENTAL LTD.	1150 BLAIR ROAD, UNIT 6 BURLINGTON ON L7M 1K9	18.9	4
SIMON CRANE RENTAL LTD.	1150 BLAIR ROAD, UNIT 6 BURLINGTON ON L7M 1K9	18.9	4
SIMON CRANE RENTAL LTD.	1150 BLAIR ROAD, UNIT 6 BURLINGTON ON L7M 1K9	18.9	4
SIMON CRANE RENTAL LTD.	1150 BLAIR ROAD, UNIT 6 BURLINGTON ON L7M 3T4	18.9	4
SIMON CRANE RENTAL LTD.	1150 BLAIR ROAD, UNIT 6 BURLINGTON ON L7M 3T4	18.9	4
A.W. CHESTERTON	1150 BLAIR ROAD BURLINGTON ON L7M 3T4	18.9	4
SIMON CRANE RENTAL LTD.	1150 BLAIR ROAD, UNIT 6 BURLINGTON ON L7M 3T4	18.9	4
SIMON CRANE RENTAL LTD.	1150 BLAIR ROAD, UNIT 6 BURLINGTON ON L7M 3T4	18.9	4
SIMON CRANE RENTAL LTD.	1150 BLAIR ROAD, UNIT 6 BURLINGTON ON	18.9	4
SIMON CRANE RENTAL LTD.	1150 BLAIR ROAD, UNIT #6 BURLINGTON ON L7M 3T4	18.9	4
A.W. CHESTERTON COMPANY LTD.	1150 BLAIR ROAD BURLINGTON ON L7M 3T4	18.9	4

Site	Address	Distance (m)	Map Key
FAGERSTA SECOROC LTD 15-019	1157 BLAIR RD BURLINGTON ON L7M 1P9	57.1	7
Wardco Window & Door Manufacturing	1157 Blair Road Burlington ON L7M 1P9	57.1	7
Atlas Copco Canada Inc.	1157 Blair Road Burlington ON L7M 7P9	57.1	7
Atlas Copco Canada Inc.	1157 Blair Road Burlington ON L7M 1P9	57.1	7
FAGERSTA SECOROC LTD	1157 BLAIR RD BURLINGTON ON L7M 1P9	57.1	7
Atlas Copco Canada	1157 Blair Road Burlington ON L7M 1P9	57.1	7
Atlas Copco Canada Inc.	1157 Blair Road Burlington ON L7M 7P9	57.1	7
Atlas Copco Canada Inc.	1157 Blair Road Burlington ON L7M 1P9	57.1	7
FAGERSTA SECOROC LTD.(OUT OF BUSINESS)	1157 BLAIR ROAD BURLINGTON ON L7M 1P9	57.1	7
XCG Consultants Ltd.	1157 Blair Road Burlington ON	57.1	7
Atlas Copco Canada Inc.	1157 Blair Road Burlington ON L7M 1P9	57.1	7
Atlas Copco Canada Inc.	1157 Blair Road Burlington ON L7M 1P9	57.1	7
Atlas Copco Canada Inc.	1157 Blair Road Burlington ON L7M 7P9	57.1	7
Wardco Window & Door Manufacturing	1157 Blair Road Burlington ON L7M 1P9	57.1	7
Wardco Window & Door Manufacturing	1157 Blair Road Burlington ON L7M 1P9	57.1	7
Screenplay Designs Inc	1157 Blair Road Burlington ON L7M 1P9	57.1	7
Atlas Copco Canada Inc.	1157 Blair Road Burlington ON L7M 1P9	57.1	7
Wardco Window & Door Manufacturing	1157 Blair Road Burlington ON	57.1	7
Wardco Window & Door Manufacturing	1157 Blair Road Burlington ON L7M 1P9	57.1	7
Atlas Copco Canada Inc.	1157 Blair Road Burlington ON L7M 7P9	57.1	7
Atlas Copco Canada Inc.	1157 Blair Road Burlington ON	57.1	7
Wardco Window & Door Manufacturing	1157 Blair Road Burlington ON	57.1	7
SWISSLINE INDUSTRIES LTD. 36-732	3300 MAINWAY BURLINGTON ON L7M 1A7	69.8	10

Site	Address	Distance (m)	Map Key
JONES NEON DISPLAYS LIMITED	1140 BLAIR ROAD BURLINGTON ON L7M 1K9	75.3	11
JONES NEON DISPLAYS LIMITED	1140 BLAIR ROAD BURLINGTON ON L7M 1K9	75.3	11
JONES NEON DISPLAYS LIMITED	1140 BLAIR ROAD BURLINGTON ON L7M 1K9	75.3	11
JONES NEON DISPLAYS LIMITED	1140 BLAIR ROAD BURLINGTON ON L7M 1K9	75.3	11
JONES NEON DISPLAYS LIMITED	1140 BLAIR ROAD BURLINGTON ON L7M 1K9	75.3	11
JONES NEON DISPLAYS LIMITED	1140 BLAIR ROAD BURLINGTON ON L7M 1K9	75.3	11
JONES NEON DISPLAYS LIMITED	1140 BLAIR ROAD BURLINGTON ON L7M 1K9	75.3	11
JONES NEON DISPLAYS LIMITED	1140 BLAIR ROAD BURLINGTON ON L7M 1K9	75.3	11
JONES NEON DISPLAYS LIMITED	1140 BLAIR ROAD BURLINGTON ON	75.3	11
THOMAS WIRE DIE LIMITED 37-113	P.O. BOX 352 3388 MAINWAY DRIVE BURLINGTON ON L7M 1A8	75.9	12
THOMAS WIRE DIE LIMITED	P.O. BOX 352 3388 MAINWAY DRIVE BURLINGTON ON L7M 1A8	75.9	12
CANFANCO INC.	3388 Mainway Burlington ON L7M 1A8	75.9	12
Airmax Compressor Services Ltd.	3400 Landmark Rd. Units 9 & 10 Burlington ON L7M 1S8	79.1	15
Airmax Compressor Services Ltd.	3400 Landmark Rd. Units 9 & 10 Burlington ON L7M 1S8	79.1	15
Airmax Compressor Services Ltd.	3400 Landmark Rd. Units 9 & 10 Burlington ON L7M 1S8	79.1	15
Airmax Compressor Services Ltd.	3400 Landmark Rd. Units 9 & 10 Burlington ON L7M 1S8	79.1	15
L & A Diecrafts Ltd.	3400 Landmark Rd. #5-10 Burlington ON L7M 1S8	79.1	15
Airmax Compressor Services Ltd.	3400 Landmark Rd. Units 9 & 10 Burlington ON L7M 1S8	79.1	15
Ascona Management & Consulting Inc.	3400 Landmark Road Units 1 & 2 Burlington ON L7M 1S8	79.1	15
Airmax Compressor Services Ltd.	3400 Landmark Rd. Units 9 & 10 Burlington ON L7M 1S8	79.1	15
Airmax Compressor Services Ltd.	3400 Landmark Rd. Units 9 & 10 Burlington ON L7M 1S8	79.1	15
Airmax Compressor Services Ltd.	3400 Landmark Rd. Units 9 & 10 Burlington ON L7M 1S8	79.1	15

Site		Address	Distance (m)	Map Key
Bell Canada		1171 Pioneer Rd Burlington ON L7M 1K5	82.9	16
BELL CANADA	05-525	1171 PIONEER RD., BURLINGTON C/O 20 NORELCO DRIVE NORTH YORK ON L7M 1K5	82.9	16
Bell Canada		1171 Pioneer Rd Burlington ON L7M 1K5	82.9	16
BELL CANADA		1171 PIONEER RD. BURLINGTON ON L7M 1K5	82.9	16
BELL CANADA		1171 PIONEER ROAD BURLINGTON ON L7M 1K5	82.9	16
Bell Canada		1171 Pioneer Rd Burlington ON L7M 1K5	82.9	16
Bell Canada		1171 Pioneer Rd Burlington ON L7M 1K5	82.9	16
Bell Canada		1171 Pioneer Rd Burlington ON L7M 1K5	82.9	16
Bell Canada		1171 Pioneer Rd Burlington ON L7M 1K5	82.9	16
Bell Canada		1171 Pioneer Rd Burlington ON L7M 1K5	82.9	16
Bell Canada		1171 Pioneer Rd Burlington ON L7M 1K5	82.9	16
BELL CANADA		1171 PIONEER RD., BURLINGTON C/O 483 BAY ST. FL. 6 S. TOWER TORONTO ON L7M 1K5	82.9	16
BELL CANADA	05-525	1171 PIONEER ROAD BURLINGTON ON L7M 1K5	82.9	16
Bell Canada		1171 Pioneer Rd Burlington ON	82.9	16
BCG PRECISION GRINDING AND HONING INC		1153 Pioneer Road Unit 10 Burlington ON L7M 1K5	88.5	17
MILL PACK INDUSTRIAL MAINTENANCE INC.		1153 PIONEER ROAD, UNIT 7 BURLINGTON ON L7M 1K5	88.5	17
MILL PACK INDUSTRIAL MAINTENANCE INC.		1153 PIONEER ROAD, UNIT 7 BURLINGTON ON	88.5	17
BURLINGTON CENTERLESS GRINDING		1153 PIONEER ROAD, UNIT 10 BURLINGTON ON L7M 1K5	88.5	17
BURLINGTON CENTERLESS GRINDING		1153 Pioneer Road Unit 10 Burlington ON L7M 1K5	88.5	17
K.C. GRAPHICS		1153 PIONEER RD. UNIT F BURLINGTON ON L7M 1K5	88.5	17
MACHINERY REPAIR TECHNOLOGIES		1153 PIONEER ROAD, UNIT K BURLINGTON ON L7M 1K5	88.5	17
931344 ontario inc.		1153 -H PIONEER RD BURLINGTON ON L7M 1K5	88.5	17
BCG PRECISION GRINDING AND HONING INC		1153 Pioneer Road Unit 10 Burlington ON L7M 1K5	88.5	17

Site	Address	Distance (m)	Map Key
BURLINGTON CENTERLESS GRINDING	1153 Pioneer Road Unit 10 Burlington ON L7M 1K5	88.5	17
CANADIAN INDUCTION PROCESSING INC	1153 PIONEER ROAD, UNIT #6 BURLINGTON ON L7M 1K5	88.5	17
CANADIAN INDUCTION PROCESSING INC.08-020	1153 PIONEER ROAD, UNIT #6 BURLINGTON ON L7M 1K5	88.5	17
K.C. GRAPHICS	1153 PIONEER ROAD, UNIT F BURLINGTON ON L7M 1K5	88.5	17
MILL PACK INDUSTRIAL MAINTENANCE INC.	1153 PIONEER ROAD, UNIT 7 BURLINGTON ON L7M 1K5	88.5	17
K.C. GRAPHICS 23-422	1153 PIONEER RD. UNIT F BURLINGTON ON L7M 1K5	88.5	17
BCG PRECISION GRINDING AND HONING INC	1153 Pioneer Road Unit 10 Burlington ON L7M 1K5	88.5	17
BURLINGTON CENTERLESS GRINDING	1153 Pioneer Road Unit 10 Burlington ON L7M 1K5	88.5	17
CANADIAN INDUCTION PROCESSING INC	1153 PIONEER RD. UNIT #6 BURLINGTON ON L7M 1K5	88.5	17
BURLINGTON CENTERLESS GRINDING	1153 Pioneer Road Unit 10 Burlington ON L7M 1K5	88.5	17
BURLINGTON CENTERLESS GRINDING	1153 Pioneer Road Unit 10 Burlington ON L7M 1K5	88.5	17
MILL PACK INDUSTRIAL MAINTENANCE INC.	1153 PIONEER ROAD, UNIT 7 BURLINGTON ON L7M 1K5	88.5	17
CANADIAN INDUCTION PROCESSING INC.	1153 PIONEER ROAD, UNIT #6 BURLINGTON ON L7M 1K5	88.5	17
CANADIAN I(OUT OF BUSINESS)NG INC.	1153 PIONEER ROAD, UNIT #6 BURLINGTON ON L7M 1K5	88.5	17
MACHINERY REPAIR TECHNOLOGIES	1153 PIONEER ROAD, UNIT K BURLINGTON ON L7M 1K5	88.5	17
BCG PRECISION GRINDING AND HONING INC	1153 Pioneer Road Unit 10 Burlington ON L7M 1K5	88.5	17
MILL PACK INDUSTRIAL MAINTENANCE INC.	1153 PIONEER ROAD, UNIT 7 BURLINGTON ON L7M 1K5	88.5	17
MACHINERY REPAIR TECHNOLOGIES	1153 PIONEER ROAD, UNIT K BURLINGTON ON L7M 1K5	88.5	17
BCG PRECISION GRINDING AND HONING INC	1153 Pioneer Road Unit 10 Burlington ON	88.5	17
MILL PACK INDUSTRIAL MAINTENANCE INC.	1153 PIONEER ROAD, UNIT 7 BURLINGTON ON	88.5	17
CHEM SYSTEMS INCORPORATED	3390 MAINWAY DRIVE BURLINGTON ON L7M 1A8	91.3	18
CHEM SYSTEMS INC.	3390 MAINWAY DRIVE BURLINGTON ON L7M 1A8	91.3	18
HAYWARD GORDON LTD.	3390 MAINWAY DRIVE BURLINGTON ON L7M 1A8	91.3	18

Site	Address	Distance (m)	Map Key
Mayne Logistics Loomis Inc.	3330 MAINWAY DRIVE BURLINGTON ON	103.5	23
LOOMIS COURIER SERVICE	3330 MAINWAY DRIVE BURLINGTON ON L7M 1A7	103.5	23
LOOMIS COURIER SERVICE(OUT OF BUSINESS)	3330 MAINWAY DRIVE BURLINGTON ON L7M 1A7	103.5	23
1187188 Ont Ltd.	3344 Mainway Burlington ON L7M 1A7	109.1	28
1187188 Ont Ltd.	3344 Mainway Burlington ON	109.1	28
1187188 Ont Ltd.	3344 Mainway Burlington ON L7M 1A7	109.1	28
1187188 Ont Ltd.	3344 Mainway Burlington ON L7M 1A7	109.1	28
1187188 Ont Ltd.	3344 Mainway Burlington ON L7M 1A7	109.1	28
ANTEL OPTRONICS INC. 03-117	3329 MAINWAY BURLINGTON ON L7M 1A6	123.4	30
ANTEL OPTRONICS INC.	3329 MAINWAY BURLINGTON ON L7M 1A6	123.4	30
EUROLINE CUSTOM CABINETS	3415 LANDMARK ROAD BURLINGTON ON L7M 1T4	128.1	33
COR-MAG INC. 07-629	3415 LANDMARK RD. BURLINGTON ON L7M 1T4	128.1	33
COR-MAG INC.(OUT OF BUS) 07-629	3415 LANDMARK RD. BURLINGTON ON L7M 1T4	128.1	33
IndustAutoCo Inc.	3415 Lanmark Road Burlington ON L7M 1T4	128.1	33
IndustAutoCo Inc.	3415 Lanmark Road Burlington ON L7M 1T4	128.1	33
EUROLINE (OUT OF BUSINESS)	3415 LANDMARK ROAD BURLINGTON ON L7M 1T4	128.1	33
SHELL CANADA PRODUCTS	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	143.2	37
SHELL CANADA PRODUCTS	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	143.2	37
QUAKER STATE INC. 32-001	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	143.2	37
SHELL CANADA PRODUCTS	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	143.2	37
QUAKER STATE INC	1101 BLAIR RD. BURLINGTON ON L7M 1T3	143.2	37
QUAKER STATE INC 32-001	1101 BLAIR RD. BURLINGTON ON L7M 1T3	143.2	37
PENNZOIL QUAKER STATE CANADA COMPANY	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	143.2	37

Site	Address	Distance (m)	Map Key
PENNZOIL QUAKER STATE CANADA COMPANY	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	143.2	37
QUAKER STATE INC.	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	143.2	37
SHELL CANADA PRODUCTS	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	143.2	37
QUAKER STATE INC	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	143.2	37
SHELL CANADA PRODUCTS	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	143.2	37
PENNZOIL QUAKER STATE CANADA COMPANY	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	143.2	37
SHELL CANADA PRODUCTS	1101 BLAIR ROAD BURLINGTON ON L7M 1T3	143.2	37
SHELL CANADA PRODUCTS	1101 BLAIR ROAD BURLINGTON ON	143.2	37
221063 Ontario Inc.	3410 Mainway Burlington ON L7M 1A8	152.1	38
RIEGER PRINTING INK CO LTD	C/O 4515 CHESSWOOD DRIVE 3410 MAINWAY DRIVE DOWNSVIEW ON L7M 1A8	152.1	38
REGIER PRINTING INK	3410 MAINWAY DRIVE BURLINGTON ON L7M 1A8	152.1	38
RIEGER PRINTING INK CO. LTD.	3410 MAINWAY DRIVE BURLINGTON ON L7M 1A8	152.1	38
RIEGER PRINTING INK CO. LTD. 33-087	3410 MAINWAY DR. BURLINGTON ON L7M 1A8	152.1	38
RIEGER PRINTING INK CO LTD	3410 MAINWAY DR. BURLINGTON ON L7M 1A8	152.1	38
221063 Ontario Inc.	3410 Mainway Burlington ON L7M 1A8	152.1	38
RIEGER PRINTING INK CO. LTD.	3410 MAINWAY DRIVE (SITE), C/O 4515-A CHESSWOOD DR., DOWNSVIEW M3J2V6 BURLINGTON ON L7M 1A8	152.1	38
MODULAR CONTROLS LIMITED	3339 MAINWAY BURLINGTON ON L7M 1A6	156.3	39
MODULAR CONTROLS LTD.	3339 MAINWAY BURLINGTON ON L7M 1A6	156.3	39
MODULAR CONTROLS LTD. 27-010	3339 MAINWAY BURLINGTON ON L7M 1A6	156.3	39
MODULAR CONTROLS LTD	3339 MAINWAY BURLINGTON ON L7M 1A6	156.3	39
GATES AIR SYSTEMS LTD.	3317 MAINWAY DRIVE BURLINGTON ON L7M 1A6	157.8	41
FibreCast Inc.	3264 Mainway Burlington ON L7M 1A7	158.4	42
FibreCast Inc.	3264 Mainway Burlington ON L7M 1A7	158.4	42

Site	Address	Distance (m)	Map Key
AISCO SYSTEMS LIMITED	3264 MAINWAY BURLINGTON ON L7R 3Y5	158.4	42
AISCO INC.	3264 MAINWAY P.O. BOX 655 BURLINGTON ON L7M 1A7	158.4	42
AISCO SYSTEMS LTD.	3264 MAINWAY P.O. BOX 655 BURLINGTON ON L7M 1A7	158.4	42
AISCO SYSTEMS LIMITED 01-392	3264 MAINWAY BURLINGTON ON L7R 3Y5	158.4	42
REHAU INDUSTRIES INC.	1149 PIONEER ROAD BURLINGTON ON L7M 1K5	160.4	43
REHAU INDUSTRIES INC. 33-227	1149 PIONEER RD. BURLINGTON ON L7M 1K5	160.4	43
REHAU INDUSTRIES INC.	1149 PIONEER RD. BURLINGTON ON L7M 1K5	160.4	43
QUADRA CHEMICALS LTD. 32-219	1100 BLAIR ROAD BURLINGTON ON L7M 1K9	166.2	44
QUADRA CHEMICALS LTD.	1100 BLAIR ROAD BURLINGTON ON L7M 1K9	166.2	44
QUADRA CHEMICALS LTD.	1100 Blair Road Burlington ON L7M 1K9	166.2	44
DOMINION (SEE & USE ON0199100 ACCO)	CANADIAN MATERIAL HANDLING 1100 BLAIR RD. BURLINGTON ON L7M 1K9	166.2	44
QUADRA CHEMICALS LTD.	1100 Blair Road Burlington ON L7M 1K9	166.2	44
ACCO CANADIAN MATERIAL HANDLING	1100 BLAIR RD. BURLINGTON ON L7M 1K9	166.2	44
ACCO CANADIAN MATERIAL HANDLING	BABCOCK INDUSTRIES CANADA INC, A DIV. OF 1100 BLAIR ROAD BURLINGTON ON L7M 1K9	166.2	44
QUADRA CHEMICALS LTD.	1100 Blair Road Burlington ON L7M 1K9	166.2	44
ACCO CANADIAN MATERIAL HANDLING 01-019	A DIV. OF BABCOCK INDUSTRIES CANADA INC 1100 BLAIR ROAD BURLINGTON ON L7M 1K9	166.2	44
QUADRA CHEMICALS LTD.	1100 Blair Road Burlington ON L7M 1K9	166.2	44
ACCO CANADIAN MATERIAL HANDLING	A DIV. OF BABCOCK INDUSTRIES CANADA INC 1100 BLAIR ROAD BURLINGTON ON L7M 1K9	166.2	44
QUADRA CHEMICALS LTD	1100 BLAIR ROAD BURLINGTON ON L7M 1K9	166.2	44
BROWN FALCON MACHINE & TOOL	3295 MAINWAY UNIT 6 BURLINGTON ON L7M 1A6	166.2	45
BROWN FALCON MAC(OUT OF BUSINESS) 05-352	3295 MAINWAY UNIT 6 BURLINGTON ON L7M 1A6	166.2	45
METAL EQUIPMENT SERVICES LTD.	3337 MAINWAY DRIVE BURLINGTON ON L7M 1A6	167.9	46
QUADRA CHEMICALS LTD.	1100 Blair Road Burlington ON L7M 1K9	169.5	48

Site	Address	Distance (m)	Map Key
QUADRA CHEMICALS LTD.	1100 Blair Road Burlington ON L7M 1K9	169.5	48
QUADRA CHEMICALS LTD.	1100 Blair Road Burlington ON L7M 1K9	169.5	48
QUADRA CHEMICALS LTD.	1100 Blair Road Burlington ON L7M 1K9	169.5	48
QUADRA CHEMICALS LTD.	1100 Blair Road Burlington ON	169.5	48
TOROMONT INDUSTRIES LTD	3385 MAINWAY BURLINGTON ON L7M 1A6	171.9	50
KINGSBURY MACHINE TOOL (CDA) LTD	3385 MAINWAY DRIVE BURLINGTON ON L7M 1A6	171.9	50
KINGSBURY MACHINE TOOL (CANADA) LIMITED	3385 MAINWAY DRIVE BURLINGTON ON L7M 1A6	171.9	50
KINGSBURY CANADA INC.	3385 MAINWAY DRIVE BURLINGTON ON L7M 1A6	171.9	50
KINGSBURY MACHINE TOOL (CDA) LTD 23-070	3385 MAINWAY DRIVE BURLINGTON ON L7M 1A6	171.9	50
KINGSBURY MACHINE TOOL (CDA) LTD.	3385 MAINWAY DRIVE BURLINGTON ON L7M 1A6	171.9	50
KINGSBURY CANADA INC.	3385 MAINWAY BURLINGTON ON L7M 1A6	171.9	50
PRINTING HOUSE LTD., THE	3285 MAINWAY, UNIT 1 BURLINGTON ON L7M 1A6	176.1	52
PRINTING HOUSE LTD., THE	3285 MAINWAY, UNIT 1 BURLINGTON ON L7M 1A6	176.1	52
PRINTING HOUSE LTD., THE	3285 MAINWAY, UNIT 1 BURLINGTON ON L7M 1A6	176.1	52
PRINTING HOUSE LTD., THE	3285 MAINWAY, UNIT 1 BURLINGTON ON L7M 1A6	176.1	52
COOPER FLUID POWER INC.	3285 MAINWAY DRIVE, #6 BURLINGTON ON L7M 1A6	176.1	52
PRINTING HOUSE LTD., THE	3285 MAINWAY, UNIT 1 BURLINGTON ON	176.1	52
PRINTING HOUSE LTD., THE	3285 MAINWAY, UNIT 1 BURLINGTON ON L7M 1A6	176.1	52
PRINTING HOUSE LTD., THE	3285 MAINWAY, UNIT 1 BURLINGTON ON L7M 1A6	176.1	52
PRINTING HOUSE LTD., THE	3285 MAINWAY, UNIT 1 BURLINGTON ON L7M 1A6	176.1	52
COOPER FLUID POWER INC.	3285 MAINWAY DRIVE, UNIT 6 BURLINGTON ON L7M 1A6	176.1	52
COTSWOLD PRECISION COMPANY LTD.	3285 MAINWAY DRIVE, UNIT 3 BURLINGTON ON L7M 1A6	176.1	52
PRINTING HOUSE LTD., THE	3285 MAINWAY, UNIT 1 BURLINGTON ON L7M 1A6	176.1	52

Site	Address	Distance (m)	Map Key
PRINTING HOUSE LTD., THE	3285 MAINWAY, UNIT 1 BURLINGTON ON L7M 1A6	176.1	52
Precision Metalworks Inc	3285 Mainway unit 5 Burlington ON L7M 1A6	176.1	52
Precision Metalworks Inc	3285 Mainway unit 5 Burlington ON L7M 1A6	176.1	52
PRINTING HOUSE LTD., THE	3285 MAINWAY UNIT #1 BURLINGTON ON L7M 1A6	176.1	52
Sympro CNC Macining and Manufacturing	3285 Main Way, Unit 6 Burlington ON L7M 1A6	176.1	52
precision print	3285 Mainway drive burlington ON	176.1	52
COTSWOLD PRECISION COMPANY LTD.	3285 MAINWAY DRIVE, UNIT #3 BURLINGTON ON L7M 1A6	176.1	52
ACTIVITYPLEX BURLINGTON CORP.	3410 MAINWAY BURLINGTON ON L7M 1A8	178.3	53
MPI GROUP INC.	3410 MAINWAY BURLINGTON ON L7M 1A8	178.3	53
Laker Energy Products Ltd.	3435 Landmark Road Burlington ON L7M 1T4	181.1	54
Laker Energy Products Ltd.	3435 Landmark Road Burlington ON L7M 1T4	181.1	54
GENNUM (SEE&USE ON0488001)	3435 LANDMARK ROAD BURLINGTON ON L7M 1T4	181.1	54
GENNUM CORPORATION	3435 LANDMARK ROAD BURLINGTON ON L7M 1T4	181.1	54
Laker Energy Products Ltd.	3435 Landmark Road Burlington ON	181.1	54
Laker Energy Products Ltd.	3435 Landmark Road Burlington ON L7M 1T4	181.1	54
GENNUM CORPORATION 24-187	3435 LANDMARK ROAD BURLINGTON ON L7M 1T4	181.1	54
LINERAR TECHNOLOGY INC.	3435 LANDMARK ROAD BURLINGTON ON L7M 1T4	181.1	54
GENNUM (SEE&USE ON0488001) 17-187	3435 LANDMARK ROAD BURLINGTON ON L7M 1T4	181.1	54
GENNUM CORPORATION	3435 LANDMARK ROAD BURLINGTON ON L7M 1T4	181.1	54
Laker Energy Products Ltd.	3435 Landmark Road Burlington ON	181.1	54
GENNUM CORPORATION	P.O. BOX 489, STATION "A" BURLINGTON ON L7R 3Y3	182.0	55
JC CNC (OUT OF BUSINESS)	3319B MAINWAY ROAD BURLINGTON ON L7M 1A6	183.0	56
JC CNC WORKS INC.	3319B MAINWAY ROAD BURLINGTON ON L7M 1A6	183.0	56

Site	Address	Distance (m)	Map Key
BELL CANADA	1191 PIONEER ROAD BURLINGTON ON L7M 1K5	193.3	60
Accurate Concrete Cutting	3333 Mainway, Suite B Burlington ON L7M 1A6	195.8	62
Accurate Concrete Cutting	3333 Mainway, Suite B Burlington ON L7M 1A6	195.8	62
EcoSynthetix Inc	3365 Mainway Burlington ON L7M 1A6	204.9	64
EcoSynthetix Inc	3365 Mainway Burlington ON L7M 1A6	204.9	64
EcoSynthetix Inc	3365 Mainway Burlington ON L7M 1A6	204.9	64
EcoSynthetix Inc EcoSynthetix Corporation	3365 Mainway Burlington ON L7M 1A6	204.9	64
EcoSynthetix Inc	3365 Mainway Burlington ON	204.9	64
EcoSynthetix Inc	3365 Mainway Burlington ON	204.9	64
BOSCH REXROTH CANADA CORP.	3426 MAINWAY DRIVE BURLINGTON ON L7M 1A8	209.4	66
KERNIC EQUIPMENT (OUT OF BUSINESS)23-112	3426 MAINWAY BURLINGTON ON L7M 1A8	209.4	66
BOSCH REXROTH CANADA CORP.	3426 MAINWAY DRIVE BURLINGTON ON L7M 1A8	209.4	66
KERNIC EQUIPMENT SALES LIMITED	3426 MAINWAY BURLINGTON ON L7M 1A8	209.4	66
BASIC TECHNOLOGIES	3426 MAINWAY BURLINGTON ON L7M 1A8	209.4	66
BASIC TECHNOLOGIES	3426 MAINWAY DRIVE BURLINGTON ON L7M 1A8	209.4	66
BOSCH REXROTH CANADA CORP.	3426 MAINWAY DRIVE BURLINGTON ON L7M 1A8	209.4	66
BOSCH REXROTH CANADA CORP.	3426 MAINWAY DRIVE BURLINGTON ON ON L7M 1A8	209.4	66
BOSCH REXROTH CANADA CORP.	3426 MAINWAY DRIVE BURLINGTON ON L7M 1A8	209.4	66
BOSCH REXROTH CANADA CORP.	3426 MAINWAY DRIVE BURLINGTON ON L7M 1A8	209.4	66
Alkano Grinding and Stamping Company Limited	3321 Mainway, Unit A & B Burlington ON L7M 1A6	209.9	67
Alkano Grinding and Stamping Company Limited	3321 Mainway, Unit A & B Burlington ON L7M 1A6	209.9	67
Alkano Grinding and Stamping Company Limited	3321 Mainway, Unit A & B Burlington ON L7M 1A6	209.9	67
Alkano Grinding and Stamping Company Limited	3321 Mainway, Unit A & B Burlington ON L7M 1A6	209.9	67

Site	Address	Distance (m)	Map Key
QUALITY CYLINDER SERVICE	3321 MAINWAY BURLINGTON ON L7M 1A6	209.9	67
Alkano Grinding and Stamping Company Limited	3321 Mainway, Unit A & B Burlington ON	209.9	67
QUALITY HYDRAULIC SERVICE	3321 MAINWAY BURLINGTON ON L7M 1A6	209.9	67
WELCAN MACHINE SHOP	3321 MAINWAY DRIVE BURLINGTON ON L7M 1A6	209.9	67
Alkano Grinding and Stamping Company Limited	3321 Mainway, Unit A & B Burlington ON	209.9	67
Airon HVAC Service Ltd	3321 Mainway Drive Unit A & B Burlington ON L7M 1A6	209.9	67
QUALITY (OUT OF BUSINESS) 33-183	3321 MAINWAY BURLINGTON ON L7M 1A6	209.9	67
EAGLE-QUIP INC.	3331 MAINWAY BURLINGTON ON L7M 1A6	212.4	68
FAIRWAY INDUSTRIAL	3331 MAINWAY BURLINGTON ON L7M 1A6	212.4	68
FAIRWAY INDUSTRIAL	3331 MAINWAY BURLINGTON ON L7M 1A6	212.4	68
FAIRWAY INDUSTRIAL 14-355	3331 MAINWAY BURLINGTON ON L7M 1A6	212.4	68
MAUSER CANADA LTD.	1121 PIONEER ROAD BURLINGTON ON L7M 1K5	220.5	70
MAUSER CANADA LTD.	1121 PIONEER ROAD BURLINGTON ON L7M 1K5	220.5	70
MAUSER CANADA LTD.	1121 PIONEER ROAD BURLINGTON ON	220.5	70
MAUSER CANADA LTD.	1121 PIONEER ROAD BURLINGTON ON L7M1K5	220.5	70
HUNTER DRUMS LTD	1121 PIONEER RD BURLINGTON ON L7M 1K5	220.5	70
MAUSER CANADA LTD. STEEL DIVISION	1121 PIONEER ROAD BURLINGTON ON L7M1K5	220.5	70
MAUSER CANADA LTD.	1121 PIONEER ROAD BURLINGTON ON L7M1K5	220.5	70
RUSSELL-STANLEY	1121 PIONEER ROAD BURLINGTON ON L7M 1K5	220.5	70
HUNTER DRUMS LIMITED	1121 PIONEER ROAD BURLINGTON ON L7M 1K5	220.5	70
MAUSER CANADA LTD.	1121 PIONEER ROAD BURLINGTON ON L7M 1K5	220.5	70
HUNTER DRUMS LIMITED 20-020	1121 PIONEER ROAD BURLINGTON ON L7M 1K5	220.5	70
MAUSER CANADA LTD.	1121 PIONEER ROAD BURLINGTON ON L7M1K5	220.5	70

Site	Address	Distance (m)	Map Key
MAUSER CANADA LTD.	1121 PIONEER ROAD BURLINGTON ON L7M 1K5	220.5	70
MAUSER CANADA LTD.	1121 PIONEER ROAD BURLINGTON ON L7M 1K5	220.5	70
BOSCH REXROTH CANADA CORP.	3426 MAINWAY DRIVE BURLINGTON ON	221.8	71
BOSCH REXROTH CANADA CORP.	3426 MAINWAY DRIVE BURLINGTON ON L7M 1A8	227.0	74
BOSCH REXROTH CANADA CORP.	3426 MAINWAY DRIVE BURLINGTON ON L7M 1A8	227.0	74
BOSCH REXROTH CANADA CORP.	3426 MAINWAY DRIVE BURLINGTON ON L7M 1A8	227.0	74
BOSCH REXROTH CANADA CORP.	3426 MAINWAY DRIVE BURLINGTON ON L7M 1A8	227.0	74
NIXON INTEGRATED MACHINING DESIGN LTD.	3291 Mainway Drive Units 5,6,7,8and9 Burlington ON L7M 1A6	232.7	76
BROWN FALCON MACHINE & TOOL	3291 MAINWAY, UNITS 1-2 BURLINGTON ON L7M 1A6	232.7	76
NIXON INTEGRATED MACHINING DESIGN LTD.	3291 Mainway Drive Units 5 & 6 Burlington ON	232.7	76
NIXON INTEGRATED MACHINING DESIGN LTD.	3291 Mainway Drive Units 5 & 6 Burlington ON L7M 1A6	232.7	76
NIXON INTEGRATED MACHINING DESIGN LTD.	3291 Mainway Drive Units 5 & 6 Burlington ON L7M 1A6	232.7	76
NIXON INTEGRATED MACHINING DESIGN LTD.	3291 Mainway Drive Units 5 & 6 Burlington ON L7M 1A6	232.7	76
NIXON INTEGRATED MACHINING DESIGN LTD.	3291 Mainway Drive Units 5 & 6 Burlington ON L7M 1A6	232.7	76
NIXON INTEGRATED MACHINING DESIGN LTD.	3291 Mainway Drive Units 5 & 6 Burlington ON L7M 1A6	232.7	76
NIXON INTEGRATED MACHINING DESIGN LTD.	3291 MAINWAY DRIVE, UNITS 5 & 6 BURLINGTON ON L7M 1A6	232.7	76
NIXON INTEGRATED MACHINING DESIGN LTD.	3291 Mainway Drive Units 5 & 6 Burlington ON L7M 1A6	232.7	76
NIXON INTEGRATED MACHINING DESIGN LTD.	3291 Mainway Drive Units 5 & 6 Burlington ON L7M 1A6	232.7	76
BROWN FALCON MACHINE & TOOL	3291 MAINWAY, UNIT 1 & 2 BURLINGTON ON L7M 1A6	232.7	76
NIXON INTEGRATED MACHINING DESIGN LTD.	3291 Mainway Drive Units 5 & 6 Burlington ON L7M 1A6	232.7	76
NIXON INTEGRATED MACHINING DESIGN LTD.	3291 Mainway Drive Units 5 & 6 Burlington ON L7M 1A6	232.7	76
TRAVIS INDUSTRIAL MAINTENANCE	3327 MAINWAY, UNIT C BURLINGTON ON L7M 1A6	236.4	79
TRAVIS INDUSTRIAL MAINTENANCE LIMITED	3327 MAINWAY, UNIT C BURLINGTON ON L7M 1A6	236.4	79

Site	Address	Distance (m)	Map Key
TRAVIS INDUSTRIAL MAINTENANCE LIMITED	3327 MAINWAY DRIVE UNIT C BURLINGTON ON L7M 1A6	236.4	79
BRAMKAL CONTRACTORS INC.	3450 LANDMARK ROAD BURLINGTON ON L7M 1S8	243.6	83
BramKal Contractors Inc.	3450 Landmark Rd. Burlington ON L7M 1S8	243.6	83
Burlington Cutting and Finishing Inc.	3450 landmark rd Unit B Burlington ON L7M 1S8	243.6	83
Burlington Cutting and Finishing Inc.	3450 landmark rd Unit B Burlington ON L7M 1S8	243.6	83
Bramkal contractors Inc.	3450 Landmark Road Burlington ON L7M 1S8	243.6	83
A-1 Asphalt Maintenance Ltd.	3450 Landmark Road Unit B Burlington ON L7M 1S8	243.6	83
COMSTOCK CANADA LTD.	3455 Landmark Road Burlington ON L7M 1T4	245.8	84
COMSTOCK CANADA LTD.	3455 Landmark Road Burlington ON L7M 1T4	245.8	84
COMSTOCK CANADA LTD.	3455 LANDMARK ROAD BURLINGTON ON L7M 1T4	245.8	84
COMSTOCK CANADA LTD.	3455 Landmark Road Burlington ON L7M1T4	245.8	84
COMSTOCK CANADA LTD.	3455 Landmark Road Burlington ON L7M 1T4	245.8	84
COMSTOCK CANADA LTD.	3455 Landmark Road Burlington ON	245.8	84
COMSTOCK CANADA LTD.	3455 Landmark Road Burlington ON L7M 1T4	245.8	84
COMSTOCK CANADA	3455 LANDMARK ROAD BURLINGTON ON L7M 1T4	245.8	84
REVSTONE INDUSTRIES BURLINGTON INC.	3267 MAINWAY BURLINGTON ON L7M 1A6	251.3	87
REVSTONE INDUSTRIES BURLINGTON INC.	3267 MAINWAY BURLINGTON ON L7M 1A6	251.3	87
NATIONAL RIGGING & TRANSPORTATION LTD.	3267 MAINWAY DR. BURLINGTON ON	251.3	87
BURLINGTON TECHNOLOGIES 06-271	BURLINGTON DIVISION 3267 MAINWAY BURLINGTON ON L7M 1A6	251.3	87
BURLINGTON TECHNOLOGIESINCORPORATED	3267 MAINWAY BURLINGTON ON L7M 1A6	251.3	87
BURLINGTON DIE CASTING	3267 MAINWAY BURLINGTON ON L7M 1A6	251.3	87
REVSTONE INDUSTRIES BURLINGTON INC.	3267 MAINWAY BURLINGTON ON L7M 1A6	251.3	87
BURLINGTON TECHNOLOGIES INCORPORATED	3267 MAINWAY BURLINGTON ON L7M 1A6	251.3	87

Site	Address	Distance (m)	Map Key
BURLINGTON TECHNOLOGIES	3267 MAINWAY BURLINGTON DIVISION BURLINGTON ON L7M 1A6	251.3	87
REVSTONE INDUSTRIES BURLINGTON INC.	3267 MAINWAY BURLINGTON ON L7M 1A6	251.3	87
JC CNC WORKS INC.	1232 DILLON ROAD, UNIT 1 BURLINGTON ON L7M 1N3	269.6	94
JC CNC WORKS INC.	1232 DILLON ROAD, UNIT 1 BURLINGTON ON L7M 1N3	269.6	94
X-PERT METAL FINISHING LTD.	1232 DILLON RD. BURLINGTON ON L7M 1N3	269.6	94
X-PERT METAL FINISHING LTD.	1232 DILLON ROAD BURLINGTON ON L7M 1N3	269.6	94
JC CNC WORKS INC.	1232 DILLON ROAD, UNIT 1 BURLINGTON ON L7M 1N3	269.6	94
JC CNC WORKS INC.	1232 DILLON ROAD, UNIT 1 BURLINGTON ON L7M 1N3	269.6	94
JC CNC WORKS INC.	1232 DILLON ROAD, UNIT 1 BURLINGTON ON L7M 1N3	269.6	94
JC CNC WORKS INC.	1232 DILLON ROAD, UNIT 1 BURLINGTON ON L7M 1N3	269.6	94
Hahn and Sons Ltd	1232 Dillon Road, Unit #3 Burlington ON L7M 1N3	269.6	94
JC CNC WORKS INC.	1232 DILLON ROAD, UNIT 1 BURLINGTON ON L7M 1N3	269.6	94
Hahn and Sons Ltd	1232 Dillon Road, Unit #3 Burlington ON L7M 1N3	269.6	94
Hahn and Sons Ltd	1232 Dillon Road, Unit #3 Burlington ON L7M 1N3	269.6	94
Hahn and Sons Ltd	1232 Dillon Road, Unit #3 Burlington ON L7M 1N3	269.6	94
X-PERT METAL FINISHING LTD. 43-024	1232 DILLON RD. BURLINGTON ON L7M 1N3	269.6	94
JC CNC WORKS INC.	1232 DILLON ROAD, UNIT 1 BURLINGTON ON L7M 1N3	269.6	94
Hahn and Sons Ltd	1232 Dillon Road, Unit #3 Burlington ON	269.6	94
Burlington Racquet Club	1233 Dillon ROad Burlington ON L7M 1K6	288.5	97
L.A. RUBBER INC.	3466 LANDMARK ROAD BURLINGTON ON L7M 1S8	295.1	100

NPCB - National PCB Inventory

A search of the NPCB database, dated 1988-2008* has found that there are 3 NPCB site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
RIEGER PRINTING INK CO LTD	3410 MAINWAY DRIVE BURLINGTON ON L7M 1A8	152.1	38
RIEGER PRINTING INK COMPANY LTD.	3410 MAINWAY DRIVE BURLINGTON ON L7M 1A8	152.1	38
HUNTER DRUMS LIMITED	1121 PIONEER ROAD BURLINGTON ON L7M 1K5	220.5	70

NPRI - National Pollutant Release Inventory

A search of the NPRI database, dated 1993-May 2017 has found that there are 49 NPRI site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
GENNUM CORPORATION	3435 LANDMARK ROAD NOT AVAILABLE BURLINGTON ON L7M 1T4	181.1	54
GENNUM CORPORATION	3435 LANDMARK ROAD NOT AVAILABLE BURLINGTON ON L7M 1T4	181.1	54
GENNUM CORPORATION	3435 LANDMARK ROAD NOT AVAILABLE BURLINGTON ON L7M 1T4	181.1	54
GENNUM CORPORATION	3435 LANDMARK ROAD NOT AVAILABLE BURLINGTON ON L7M 1T4	181.1	54
GENNUM CORPORATION	3435 LANDMARK ROAD NOT AVAILABLE BURLINGTON ON L7M 1T4	181.1	54
GENNUM CORPORATION	3435 LANDMARK ROAD NOT AVAILABLE BURLINGTON ON L7M 1T4	181.1	54
GENNUM CORPORATION	3435 LANDMARK ROAD NOT AVAILABLE BURLINGTON ON L7M 1T4	181.1	54
GENNUM CORPORATION	3435 LANDMARK ROAD NOT AVAILABLE BURLINGTON ON L7M 1T4	181.1	54
GENNUM CORPORATION	3435 LANDMARK ROAD NOT AVAILABLE BURLINGTON ON L7M 1T4	181.1	54
BURLINGTON TECHNOLOGIES INC.	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	189.9	58
BURLINGTON TECHNOLOGIES INDUSTRIES	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	189.9	58
BURLINGTON TECHNOLOGIES INC.	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	190.2	59
BURLINGTON TECHNOLOGIES INDUSTRIES	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	190.2	59
BURLINGTON TECHNOLOGIES INDUSTRIES	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	190.2	59
BURLINGTON TECHNOLOGIES INC.	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	190.2	59
BURLINGTON TECHNOLOGIES INC.	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	190.2	59

Site	Address	Distance (m)	Map Key
BURLINGTON TECHNOLOGIES INDUSTRIES	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	190.2	59
BURLINGTON TECHNOLOGIES INDUSTRIES	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	190.2	59
BURLINGTON TECHNOLOGIES: BURLINGTON DIVISION	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	190.2	59
BURLINGTON TECHNOLOGIES INC.	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	190.2	59
BURLINGTON TECHNOLOGIES INC.	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	190.2	59
BURLINGTON TECHOLOGIES INC.	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	190.2	59
BURLINGTON TECHNOLOGIES INDUSTRIES	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	190.2	59
Mauser Canada Ltd.	1121 Pioneer Road Burlington ON l7m1k5	220.5	70
MAUSER CANADA LIMITED	1121 Pioneer Road Burlington ON l7m1k5	220.5	70
MAUSER CANADA LTD.	1121 Pioneer Road Burlington ON l7m1k5	220.5	70
MAUSER CANADA LIMITED	1121 Pioneer Road Burlington ON l7m1k5	220.5	70
HUNTER DRUMS LIMITED	1121 PIONEER ROAD NOT AVAILABLE BURLINGTON ON L7M1K5	220.5	70
MAUSER CANADA LTD.	1121 Pioneer Road Burlington ON l7m1k5	220.5	70
MAUSER CANADA LTD.	1121 Pioneer Road Burlington ON l7m1k5	220.5	70
MAUSER CANADA LIMITED	1121 Pioneer Road Burlington ON l7m1k5	220.5	70
MAUSER CANADA LTD.	1121 Pioneer Road Burlington ON l7m1k5	220.5	70
MAUSER CANADA LTD.	1121 Pioneer Road Burlington ON l7m1k5	220.5	70
HUNTER DRUMS LIMITED	1121 PIONEER ROAD NOT AVAILABLE BURLINGTON ON L7M1K5	220.5	70
Mauser Canada Ltd.	1121 Pioneer Road Burlington ON l7m1k5	220.5	70
MAUSER CANADA LIMITED	1121 Pioneer Road Burlington ON l7m1k5	220.5	70
MAUSER CANADA LIMITED	1121 Pioneer Road Burlington ON l7m1k5	220.5	70
MAUSER CANADA LIMITED	1121 Pioneer Road Burlington ON l7m1k5	220.5	70
Mauser Canada Ltd.	1121 Pioneer Road Burlington ON l7m1k5	220.5	70

Site	Address	Distance (m)	Map Key
BURLINGTON TECHNOLOGIES INC.	3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	248.1	85
HOWELL PACKAGING LIMITED	3230 MAINWAY AVENUE NOT AVAILABLE BURLINGTON ON L7M 1A5	259.4	92
HOWELL PACKAGING LIMITED	3230 MAINWAY AVENUE NOT AVAILABLE BURLINGTON ON L7M 1A5	259.4	92
HOWELL PACKAGING	3230 MAINWAY AVENUE NOT AVAILABLE BURLINGTON ON L7M 1A5	259.4	92
HOWELL PACKAGING LIMITED	3230 MAINWAY AVENUE NOT AVAILABLE BURLINGTON ON L7M 1A5	259.4	92
HOWELL PACKAGING LIMITED	3230 MAINWAY AVENUE NOT AVAILABLE BURLINGTON ON L7M 1A5	259.4	92
DOVER PACKAGING LIMITED (FORMERLY HOWELL PACKAGING LIMITED)	3230 MAINWAY AVENUE NOT AVAILABLE BURLINGTON ON L7M 1A5	259.4	92
HOWELL PACKAGING LIMITED	3230 MAINWAY AVENUE NOT AVAILABLE BURLINGTON ON L7M 1A5	259.4	92
HOWELL PACKAGING LIMITED	3230 MAINWAY AVENUE NOT AVAILABLE BURLINGTON ON L7M 1A5	259.4	92
HOWELL PACKAGING LIMITED	3230 MAINWAY AVENUE NOT AVAILABLE BURLINGTON ON L7M 1A5	259.4	92

OPCB - Inventory of PCB Storage Sites

A search of the OPCB database, dated 1987-Oct 2004; 2012-Dec 2013 has found that there are 2 OPCB site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
RIEGER PRINTING INK CO LTD	3410 MAINWAY DRIVE BURLINGTON ON L7M 1A8	152.1	38
HUNTER DRUMS LIMITED	1121 PIONEER ROAD BURLINGTON ON L7M 1K5	220.5	70

PAP - Canadian Pulp and Paper

A search of the PAP database, dated 1999, 2002, 2004, 2005, 2009 has found that there are 5 PAP site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Quadra Chemicals	1100 Blair Rd Burlington ON L7M 1K9	166.2	44
Bosch Rexroth Canada Corporation - Linear Division	3426 Mainway Dr Burlington ON L7M 1A8	209.4	66
Bosch Rexroth Canada Corporation - Pneumatics Division	3426 Mainway Dr Burlington ON L7M 1A8	209.4	66
Bosch Rexroth Canada Corporation - Controls Division	3426 Mainway Dr Burlington ON L7M 1A8	209.4	66

Site	Address	Distance (m)	Map Key
Comstock Canada Ltd.	3455 Landmark Rd Burlington ON L7M 1T4	245.8	84

PES - Pesticide Register

A search of the PES database, dated 1988-Mar 2018 has found that there are 1 PES site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
SOLOMON, J.N. ENTERPRISES LIMITED	3291 MAINWAY #5 BURLINGTON ON L7M 1A6	232.7	76

PRT - Private and Retail Fuel Storage Tanks

A search of the PRT database, dated 1989-1996* has found that there are 4 PRT site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD	1160 BLAIR RD BURLINGTON ON L7M 1K9	0.0	1
LOOMIS COURIER SERVICE	1160 BLAIR RD BURLINGTON ON	0.0	1
AUTOMOTIVE MANAGER BELL CANADA	1171 PIONEER RD BURLINGTON ON L7M 1K5	82.9	16
HUMPTY DUMPTY FOODS LTD	3424 LANDMARK RD BURLINGTON ON L7M 1S8	168.6	47

REC - Ontario Regulation 347 Waste Receivers Summary

A search of the REC database, dated 1986-2016 has found that there are 4 REC site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
RIEGER PRINTING INK CO. LTD.	3410 MAINWAY DRIVE (SITE), C/O 4515-A CHESSWOOD DR., DOWNSVIEW M3J2V6 BURLINGTON ON L7M 1A8	152.1	38
RIEGER PRINTING INK CO. LTD.	3410 MAINWAY DRIVE BURLINGTON ON L7M 1A8	152.1	38
RIEGER PRINTING INK CO. LTD.	3410 MAINWAY DR. BURLINGTON ON L7M 1A8	152.1	38
RIEGER PRINTING INK CO. LTD.	3410 MAINWAY DRIVE, BURLINGTON C/O 4515 CHESSWOOD DRIVE, SUITE A DOWNSVIEW ON L7M 1A8	152.1	38

RSC - Record of Site Condition

A search of the RSC database, dated 1997-Sept 2001, Oct 2004-Nov 2017 has found that there are 2 RSC site(s) within approximately

0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
2210263 Ontario Inc.	3410 MAINWAY DR, BURLINGTON, ON, L7M 1A8, ON L7M 1A8	152.1	38
	3410 MAINWAY, BURLINGTON, ON L7M 1A8 Burlington ON	178.3	53

SCT - Scott's Manufacturing Directory

A search of the SCT database, dated 1992-Mar 2011* has found that there are 134 SCT site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Northcote Industrial Products	1160 Blair Rd Floor 2 Unit D Burlington ON L7M 1K9	0.0	1
Northcote Industrial Products Inc.	1160 Blair Rd Floor 2 Unit D Burlington ON L7M 1K9	0.0	1
ALL-TIG LTD	1160 BLAIR RD UNIT A1 BURLINGTON ON L7M 1K9	0.0	1
VERSA-HOE EQUIPMENT CORP.	1160 Blair Rd Floor 2 Unit D Burlington ON L7M 1K9	0.0	1
Atlas Copco Construction and Mining Canada	Burlington ON L7M 1P9	13.4	3
Northern Industrial Supply	1150 Blair Rd Unit 1S Burlington ON L7M 3T4	18.9	4
KENWARD TOOL & DIE LTD	1150 BLAIR RD BURLINGTON ON L7M 3T4	18.9	4
J R TOOL & DIE	1150 BLAIR RD UNIT 5 BURLINGTON ON L7M 3T4	18.9	4
A W CHESTERTON COMPANY LTD.	1150 BLAIR RD BURLINGTON ON L7M 3T4	18.9	4
S O S Cylinders Inc.	1150 Blair Rd Unit 2 Burlington ON L7M 3T4	18.9	4
Northern Integrated Systems Co	1150 Blair Rd Unit 1 Burlington ON L7M 3T4	18.9	4
J R Tool & Die Ltd.	1150 Blair Rd Unit 5 Burlington ON L7M 3T4	18.9	4
ATLAS COPCO CONSTRUCTION	1157 BLAIR RD BURLINGTON ON L7M 1P9	57.1	7
Atlas Copco Construction and Mining Canada	1157 Blair Rd Burlington ON L7M 1P9	57.1	7
Conspec Controls Ltd.	1180 Blair Rd Burlington ON L7M 1K9	67.0	8
JCP Belt Components Inc.	3300 Mainway Burlington ON L7M 1A7	69.8	10
VERNS METAL STAMPING INC.	3300 MAINWAY DR UNIT 1 BURLINGTON ON L7M 1A7	69.8	10

Site	Address	Distance (m)	Map Key
JONES TOOL & MACHINE CO. LTD.	3300 MAINWAY DR UNIT 1 BURLINGTON ON L7M 1A7	69.8	10
JCP Belt Components Inc.	3300 Mainway Dr Burlington ON L7M 1A7	69.8	10
Jones Neon Displays Ltd.	1140 Blair Rd Burlington ON L7M 1K9	75.3	11
CANFANCO INC.	3388 Mainway Dr Burlington ON L7M 1A8	75.9	12
CANADIAN FANNER CO. LTD.	3388 MAINWAY DR BURLINGTON ON L7M 1A8	75.9	12
NATURAL TEMPTATIONS INC	3400 LANDMARK RD UNIT 4 BURLINGTON ON L7M 1S8	79.1	15
Natural Temptations Inc.	3400 Landmark Rd Unit 4 Burlington ON L7M 1S8	79.1	15
Millcraft Systems Inc.	3400 Landmark Rd Unit 1-2 Burlington ON L7M 1S8	79.1	15
L & A DIECRAFTS LTD	3400 LANDMARK RD UNIT 5-10 BURLINGTON ON L7M 1S8	79.1	15
L & A Diecrafts Ltd.	3400 Landmark Rd Unit 5-10 Burlington ON L7M 1S8	79.1	15
CANADIAN COUNTRY CANDLES	3400 LANDMARK RD UNIT 2 BURLINGTON ON L7M 1S8	79.1	15
K C GRAPHICS	1153 Pioneer Rd Unit F Burlington ON L7M 1K5	88.5	17
HOMEMADE WINE CRAFTS CANADA	1153 Pioneer Rd Unit E Burlington ON L7M 1K5	88.5	17
M. I. R. Fabric Products	1153 Pioneer Rd Unit L Burlington ON L7M 1K5	88.5	17
LASER F/X INTERNATIONAL	1153 Pioneer Rd Unit P Burlington ON L7M 1K5	88.5	17
ORGANIZERS PLUS	1153 PIONEER RD UNIT K BURLINGTON ON L7M 1K5	88.5	17
BURLINGTON CENTRELESS GRINDING	1153 PIONEER RD BURLINGTON ON L7M 1K5	88.5	17
All Racking and Conveyors	1153 Pioneer Rd Unit 2 Burlington ON L7M 1K5	88.5	17
Homemade Wine Crafts Canada Ltd.	1153 Pioneer Rd Unit E Burlington ON L7M 1K5	88.5	17
Downtown Signs	1153 Pioneer Rd Unit J Burlington ON L7M 1K5	88.5	17
HOMEMADE WINE CRAFTS LTD	1153 PIONEER RD UNIT E BURLINGTON ON L7M 1K5	88.5	17
Brant Custom Grinding Limited	1153 Pioneer Rd Unit 11 Burlington ON L7M 1K5	88.5	17
CANADIAN INDUCTION PROCESSING	1153 PIONEER RD UNIT 4-6 BURLINGTON ON L7M 1K5	88.5	17

Site	Address	Distance (m)	Map Key
WORLD WIDE KILN SERVICE	1153 PIONEER RD UNIT 7 BURLINGTON ON L7M 1K5	88.5	17
EXOTIC SIGNS	1153 PIONEER RD UNIT J BURLINGTON ON L7M 1K5	88.5	17
K. C. GRAPHICS	1153 PIONEER RD BURLINGTON ON L7M 1K5	88.5	17
LASER F X INTERNATIONAL	1153 PIONEER RD UNIT P BURLINGTON ON L7M 1K5	88.5	17
Burlington Centerless Grinding	1153 Pioneer Rd Unit 10 Burlington ON L7M 1K5	88.5	17
Hayward Gordon Ltd.	3390 Mainway Burlington ON L7M 1A8	91.3	18
CHEM SYSTEMS INC.	3390 MAINWAY DR BURLINGTON ON L7M 1A8	91.3	18
CHEM SYSTEMS INC.	3390 MAINWAY BURLINGTON ON L7M 1A8	91.3	18
WEIGH-MATIC SYSTEMS INC.	3312 MAINWAY DR BURLINGTON ON L7M 1A7	102.1	20
CARLISLE TECHNOLOGY	3312 MAINWAY DR BURLINGTON ON L7M 1A7	102.1	20
Carlisle Technology Inc.	3312 Mainway Burlington ON L7M 1A7	102.1	20
Integrity Worldwide Inc.	3310 Mainway Burlington ON L7M 1A7	102.2	21
ConverTec Inc.	3340 Mainway Suite 200 Burlington ON L7M 1A7	107.0	26
HAMILTON DIGITAL DESIGNS LTD.	3342 Mainway Dr Burlington ON L7M 1A7	108.2	27
Hamilton Digital Designs Ltd.	3342 Mainway Burlington ON L7M 1A7	108.2	27
HAMILTON DIGITAL DESIGNS LTD.	3142 MAINWAY DR BURLINGTON ON L7M 1A7	108.2	27
DRAKE WATER SYSTEMS INC.	3329 MAINWAY DR BURLINGTON ON L7M 1A6	123.4	30
EUROLINE CUSTOM CABINETS INC.	3415 LANDMARK RD BURLINGTON ON L7M 1T4	128.1	33
EUROLINE CUSTOM CABINETS	3415 LANDMARK RD BURLINGTON ON L7M 1T4	128.1	33
Pennzoil-Quaker State Canada	1101 Blair Rd Burlington ON L7M 1T3	143.2	37
QUAKER STATE INC.	1101 BLAIR RD BURLINGTON ON L7M 1T3	143.2	37
Pennzoil-Quaker State Canada Company	1101 Blair Rd Burlington ON L7M 1T3	143.2	37
PENNZOIL QUAKER STATE CANADA C	1101 BLAIR RD BURLINGTON ON L7M 1T3	143.2	37

Site	Address	Distance (m)	Map Key
Rieger Printing Ink Co. Ltd.	3410 Mainway Burlington ON L7M 1A8	152.1	38
RIEGER PRINTING INK CO. LTD.	3410 MAINWAY DR BURLINGTON ON L7M 1A8	152.1	38
ORGANIZERS PLUS	3317 Mainway Dr Unit C Burlington ON L7M 1A6	157.8	41
Halton Sheet Metal Ltd.	3317 Mainway Dr Burlington ON L7M 1A6	157.8	41
AISCO SYSTEMS INC.	3264 MAINWAY DR BURLINGTON ON L7M 1A7	158.4	42
Fibrecast Inc.	3264 Mainway Burlington ON L7M 1A7	158.4	42
FIBRECAST INC.	3264 Mainway Dr Burlington ON L7M 1A7	158.4	42
Rehau Industries Inc.	1149 Pioneer Rd Burlington ON L7M 1K5	160.4	43
Tymatic Controls - Div. of Tyrrell Air Controls Ltd.	3295 Mainway Unit 6 Burlington ON L7M 1A6	166.2	45
ERODALL LTD.	3295 MAINWAY DR UNIT 3 BURLINGTON ON L7M 1A6	166.2	45
Erodall Ltd.	3295 Mainway Unit 3 Burlington ON L7M 1A6	166.2	45
RAINBOW CERAMICS	3295 Mainway Unit 1 Burlington ON L7M 1A6	166.2	45
METAL EQUIPMENT SERVICES LTD.	3337 MAINWAY DR BURLINGTON ON L7M 1A6	167.9	46
SMALL FRY SNACK FOODS INC.	3424 LANDMARK RD BURLINGTON ON L7M 1S8	168.6	47
KINGSBURY CANADA INC.	3385 Mainway Dr Burlington ON L7M 1A6	171.9	50
Keltour Controls Inc.	3385 Mainway Burlington ON L7M 1A6	171.9	50
Kingsbury Canada Inc.	3385 Mainway Burlington ON L7M 1A6	171.9	50
KINGSBURY CANADA INC	3385 MAINWAY DR BURLINGTON ON L7M 1A6	171.9	50
COTSWOLD PRECISION CO. LTD	3285 MAINWAY DR UNIT 3 BURLINGTON ON L7M 1A6	176.1	52
TPH The Printing House Limited	3285 Mainway Unit 1 Burlington ON L7M 1A6	176.1	52
Precision Print Inc.	3285 Mainway Dr Burlington ON L7M 1A6	176.1	52
THE PRINTING HOUSE LTD.	3285 Mainway Dr Unit 1 Burlington ON L7M 1A6	176.1	52
VERSA-HOE EQUIPMENT CORP.	3285 MAINWAY DR UNIT 4 BURLINGTON ON L7M 1A6	176.1	52

Site	Address	Distance (m)	Map Key
THE PRINTING HOUSE LTD	3285 MAINWAY DR UNIT 1 BURLINGTON ON L7M 1A6	176.1	52
Precision Print Inc.	3285 Mainway Unit 2 Burlington ON L7M 1A6	176.1	52
Intek Inc.	3285 Mainway Dr Unit 4 Burlington ON L7M 1A6	176.1	52
J.C. CNC WORKS INC.	3319 Mainway Rd Unit B Burlington ON L7M 1A6	183.0	56
PST Machining Ltd.	1163 Pioneer Rd Unit I Burlington ON L7M 1K5	195.4	61
ALLEN INDUSTRIAL RUBBER PROD	3333 Mainway Dr Unit A Burlington ON L7M 1A6	195.8	62
ALLEN INDUSTRIAL RUBBER PROD	3333A MAINWAY DR BURLINGTON ON L7M 1A6	195.8	62
Allen Industrial Rubber Products (1988) Ltd.	3333 Mainway Dr Unit A Burlington ON L7M 1A6	195.8	62
ALLEN INDUSTRIAL RUBBER PRODS	3333 A MAINWAY DR BURLINGTON ON L7M 1A6	195.8	62
Allen Industrial Rubber Prod	3333 Mainway Unit A Burlington ON L7M 1A6	195.8	62
Mahle Clevite Canada ULC	3365 Mainway Unit 2 Burlington ON L7M 1A6	204.9	64
Bosch Rexroth Canada Corp.	3426 Mainway Burlington ON L7M 1A8	209.4	66
Bosch Rexroth Canada Corp.	3426 Mainway Dr Burlington ON L7M 1A8	209.4	66
BASIC TECHNOLOGIES CORP.	3426 MAINWAY DR BURLINGTON ON L7M 1A8	209.4	66
WELCAN MACHINE SHOP	3321 MAINWAY DR BURLINGTON ON L7M 1A6	209.9	67
Halton Metal Outlet Ltd.	3331 Mainway Burlington ON L7M 1A6	212.4	68
HALTON METAL OUTLET LTD.	3331 Mainway Dr Burlington ON L7M 1A6	212.4	68
HUNTER DRUMS LIMITED	1121 PIONEER RD BURLINGTON ON L7M 1K5	220.5	70
Sandtron Automation Ltd.	1221 Dillon Rd Burlington ON L7M 1K6	224.1	72
Mauser Canada Ltd.	1121 Pioneer Rd Burlington ON L7M 1K5	226.0	73
Hunter Drums Ltd.	1121 Pioneer Rd Burlington ON L7L 6C7	226.0	73
BROWN FALCON MACHINE & TOOL	3291 MAINWAY DR UNIT 1-2 BURLINGTON ON L7M 1A6	232.7	76
Nixon Integrated Machining	3291 Mainway Unit 5-6 Burlington ON L7M 1A6	232.7	76

Site	Address	Distance (m)	Map Key
MCKELLAR MACHINE PRODUCTS LTD.	3291 MAINWAY DR BURLINGTON ON L7M 1A6	232.7	76
BROWN FALCON MACHINE,TOOL/DIE	3291 Mainway Dr Unit 1-2 Burlington ON L7M 1A6	232.7	76
BROWN FALCON MACHINE,TOOL & DI	3291 MAINWAY DR UNIT 1-2 BURLINGTON ON L7M 1A6	232.7	76
Brown Falcon Machine,Tool & Die Ltd.	3291 Mainway Unit 1-2 Burlington ON L7M 1A6	232.7	76
D F ELECTRONICS INC	3327 MAINWAY UNIT A BURLINGTON ON L7M 1A6	236.4	79
OnDrive Inc.	3327 Mainway Unit C Burlington ON L7M 1A6	236.4	79
Firecraft Kilns Sales & Service	3327 Mainway Dr Unit B Burlington ON L7M 1A6	236.4	79
HELEC INSULATION LTD	3323 MAINWAY DR UNIT D BURLINGTON ON L7M 1A6	237.9	80
Helec Insulation Ltd.	3323 Mainway Unit D Burlington ON L7M 1A6	237.9	80
P S T MACHINING LIMITED	3323 MAINWAY DR UNIT C BURLINGTON ON L7M 1A6	237.9	80
PST MACHINING LTD.	3323 Mainway Dr Unit C Burlington ON L7M 1A6	237.9	80
HELEC INSULATION LTD.	3323 Mainway Dr Unit D Burlington ON L7M 1A6	237.9	80
Tach West Technologies Ltd.	3450C Landmark Rd Burlington ON L7M 1S8	243.6	83
Burlington Cutting & Finishing	3450B Landmark Rd Burlington ON L7M 1S8	243.6	83
HTM Sensors	3419 Mainway Burlington ON L7M 1A9	248.4	86
BURLINGTON TECHNOLOGIES INC. -	3267 MAINWAY DR BURLINGTON ON L7M 1A6	251.3	87
Burlington Technologies Indus	3267 Mainway Burlington ON L7M 1A6	251.3	87
BURLINGTON TECHNOLOGIES INC.	3267 MAINWAY DR BURLINGTON ON L7M 1A6	251.3	87
Burlington Technologies Inc. - Burlington Division	3267 Mainway Dr Burlington ON L7M 1A6	251.3	87
NELSON BUSINESS MACHINES LTD.	3460 MAINWAY DR BURLINGTON ON L7M 1A8	253.4	88
Feed Rite Automation inc.	3325A Mainway Burlington ON L7M 1A6	255.8	90
J.C. CNC Works Inc.	1232 Dillon Rd Unit 1 Burlington ON L7M 1N3	269.6	94
Force Enterprises Ltd.	1232 Dillon Rd Unit 2 Burlington ON L7M 1N3	269.6	94

Site	Address	Distance (m)	Map Key
L A RUBBER INC	3466 LANDMARK RD BURLINGTON ON L7M 1S8	295.1	100
L.A. Rubber Inc.	3466 Landmark Rd Burlington ON L7M 1S8	295.1	100

SPL - Ontario Spills

A search of the SPL database, dated 1988-Feb 2018 has found that there are 11 SPL site(s) within approximately 0.30 kilometers of the project property.


Site	Address	Distance (m)	Map Key
LOOMIS COURIER	1160 BLAIR ROAD BURLINGTON CITY ON L7M 1K9	0.0	1
Atlas Copco Canada Inc.<UNOFFICIAL>	1157 Blair Rd., Burlington Burlington ON L7M 1P9	57.1	7
BURLINGTON HYDRO-ELECTRIC COMM	1140 BLAIR ROAD TRANSFORMER BURLINGTON CITY ON L7M 1K9	75.3	11
PENZOIL QUAKER STATE	1101 BLAIR ROAD 1101 BLAIR ROAD,BURLINGTON BURLINGTON CITY ON L7M 1T3	143.2	37
REHAU INDUSTRIES INC.	BURLINGTON PLANT 1149 PIONEER ROAD BURLINGTON CITY ON L7M 1K5	160.4	43
QUADRA CHEMICALS LTD.	1100 BLAIR ROAD BURLINGTON SITE 1100 BLAIR RD. BURLINGTON CITY ON L7M 1K9	166.2	44
TRANSPORT TRUCK	DEC EXPRESS, 3419 MAINWAY TRANSPORT TRUCK (CARGO) BURLINGTON CITY ON L7M 1A9	248.4	86
Burlington Technologies Inc.	3267 Mainway Burlington ON L7M 1A6	251.3	87
Burlington Technologies Inc.	3267 Mainway Burlington ON L7M 1A6	251.3	87
EXPERT METALS	1232 DILLON RD. BURLINGTON PLANT 1232 DILLON ROAD BURLINGTON CITY ON L7M 1N3	269.6	94
Purolator Courier Ltd.	3255 Mainway Drive Burlington ON L7M 1A6	282.2	95

WWIS - Water Well Information System

A search of the WWIS database, dated Mar 31, 2017 has found that there are 26 WWIS site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	lot 12 con 2 BURLINGTON ON	0.0	2
	BURLINGTON ON	18.9	4
	BURLINGTON ON	57.1	7

Site	Address	Distance (m)	Map Key
	Burlington ON	57.1	7
	ON	69.0	9
	BURLINGTON ON	78.6	14
	Burlington ON	91.9	19
	lot 12 con 2 ON	102.9	22
	Burlington ON	122.7	29
	Burlington ON	140.0	34
	Burlington ON	142.8	35
	lot 13 con 2 BURLINGTON ON	157.4	40
	lot 13 con 2 BURLINGTON ON	157.4	40
	Burlington ON	171.6	49
	BURLINGTON ON	181.1	54
	Burlington ON	204.5	63
	Burlington ON	216.4	69
	BURLINGTON ON	228.4	75
	ON	232.9	77
	BURLINGTON ON	238.1	81
	Burlington ON	242.0	82
	BURLINGTON ON	255.5	89
	ON	256.1	91
	Burlington ON	259.4	92
	lot 12 con 2 ON	284.7	96
	ON	290.0	98



Map : 0.3 Kilometer Radius

Order No: 20180518055

Address: 1160 Blair Road, Burlington, ON, L7M 1K9

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES


- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Expressway
- Principal Highway
- Secondary Highway
- Major Road
- Local road
- Trail
- Proposed Road
- Ferry Route/Ice Road
- Industrial and Resource - Regions
- Main Line
- Sidetrack
- Transit Line
- Abandoned Line
- National Park
- Provincial or Territorial Park
- Other Park
- Golf Course or Driving Range
- Park or Sports Field
- Other Recreation Area

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership

79°48'W

43°22'30"N



Aerial (2017)


Address: 1160 Blair Road, Burlington, ON, L7M 1K9

Source: ESRI World Imagery

Order No: 20180518055

ERIS ENVIRONMENTAL RISK INFORMATION SERVICES

© ERIS Information Limited Partnership



Topographic Map

Address: 1160 Blair Road, Burlington, ON, L7M 1K9

Source: ESRI World Topographic Map

Order No: 20180518055

ERIS ENVIRONMENTAL RISK INFORMATION SERVICES

© ERIS Information Limited Partnership

Detail Report

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	1 of 22	-/0.0	123.9 / 0.10	1160 Blair Rd Burlington ON L7M1K9	EHS

Order ID:	549656	**Date Received:**	06-DEC-17
Order No:	20171206073	**Lot/Building Size:**	
Customer ID:	177314	**Municipality:**	
Company ID:	97	**Client Prov/State:**	ON
Status:	C	**Search Radius (km):**	1
Report Code:	4CAN	**Large Radius:**	1
Report Type:	Custom Report	**X:**	-79.799632
Report Date:	08-DEC-17	**Y:**	43.365538

Report Requested by: exp Services Inc.
Nearest Intersection:
Previous Site Name:
Additional Info Ordered:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	2 of 22	-/0.0	123.9 / 0.10	GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD 1160 BLAIR RD BURLINGTON ON	EXP

Instance No: 11082835
Instance ID: 67426
Instance Type: FS Piping
Description: FS Piping
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	3 of 22	-/0.0	123.9 / 0.10	GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD 1160 BLAIR RD BURLINGTON ON	EXP

Instance No: 9918564
Instance ID: 398786
Instance Type: FS Facility
Description: Fuels Safety Private Fuel Outlet - Self Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	4 of 22	-/0.0	123.9 / 0.10	GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD 1160 BLAIR RD BURLINGTON ON L7M 1K9	EXP

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Instance No:		11082822			
Instance ID:					
Instance Type:		FS Liquid Fuel Tank			
Description:					
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					
Facility Type:					
Expired Date:		10/3/1989			
1	5 of 22	-/0.0	123.9 / 0.10	GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD 1160 BLAIR RD BURLINGTON ON	EXP
Instance No:		11082809			
Instance ID:		67403			
Instance Type:		FS Piping			
Description:		FS Piping			
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					
Facility Type:					
Expired Date:					
1	6 of 22	-/0.0	123.9 / 0.10	GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD 1160 BLAIR RD BURLINGTON ON L7M 1K9	EXP
Instance No:		11082789			
Instance ID:					
Instance Type:		FS Liquid Fuel Tank			
Description:					
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					
Facility Type:					
Expired Date:		10/3/1989			
1	7 of 22	-/0.0	123.9 / 0.10	LOOMIS COURIER SERVICE 1160 BLAIR RD BURLINGTON ON	EXP
Instance No:		9204839			
Instance ID:		378147			
Instance Type:		FS Facility			
Description:		FS Propane Refill Cntr - Cylr Fill			
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					
Facility Type:					
Expired Date:					
1	8 of 22	-/0.0	123.9 / 0.10	LOOMIS COURIER SERVICE 1160 BLAIR RD BURLINGTON ON	EXP

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance No: 11082775
Instance ID: 68454
Instance Type: FS Propane Tank
Description: FS Propane Tank
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	9 of 22	-/0.0	123.9 / 0.10	GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD 1160 BLAIR RD BURLINGTON ON L7M 1K9	EXP

Instance No: 11082822
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: Fuels Safety Private Fuel Outlet - Self Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 10/3/1989

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	10 of 22	-/0.0	123.9 / 0.10	GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD 1160 BLAIR RD BURLINGTON ON L7M 1K9	EXP

Instance No: 11082789
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: Fuels Safety Private Fuel Outlet - Self Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 10/3/1989

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	11 of 22	-/0.0	123.9 / 0.10	GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD 1160 BLAIR RD BURLINGTON ON L7M 1K9	FSTH

License Issue Date: 3/19/1992
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1989
Corrosion Protection:
Capacity: 45460
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Status: Active
Year of Installation: 1989
Corrosion Protection:
Capacity: 45460
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

---

1 | 12 of 22 | -/0.0 | 123.9 / 0.10 | **Royal Lepage State Realty Brokerage**
1160 Blair Road
Burlington ON L7M 1K9 | GEN

Generator No.: ON8863663
Status:
Approval Years: 07,08
Contam. Facility:
MHSW Facility:
SIC Code: 531210
SIC Description: Offices of Real Estate Agents and Brokers

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

---

1 | 13 of 22 | -/0.0 | 123.9 / 0.10 | **s.e. sales and service ltd**
1160 blair rd
burlington ON L7M 1K9 | GEN

Generator No.: ON5984348
Status:
Approval Years: 05
Contam. Facility:
MHSW Facility:
SIC Code: 531310
SIC Description: Real Estate Property Managers

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 233
Waste Description: OTHER POLYMERIC WASTES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

1 | 14 of 22 | -/0.0 | 123.9 / 0.10 | **JENMAR COLOUR SEPARATIONS INC.**
1160 BLAIR RD.
BURLINGTON ON L7M 1K9 | GEN

Generator No.: ON0646200
Status:
Approval Years: 86,87,88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 2821
SIC Description: PLATEMAKING, ETC.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 264

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Description:		PHOTOPROCESSING WASTES			

1	15 of 22	-/0.0	123.9 / 0.10	JENMAR COLOUR SEPARATIONS INC. 22-133 1160 BLAIR RD. BURLINGTON ON L7M 1K9	GEN

Generator No.: ON0646200
Status:
Approval Years: 92,93,94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 2821
SIC Description: PLATEMAKING, ETC.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 264
Waste Description: PHOTOPROCESSING WASTES

1	16 of 22	-/0.0	123.9 / 0.10	GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD 1160 BLAIR RD BURLINGTON ON L7M 1K9	PRT

Location ID: 18419
Type: private
Expiry Date:
Capacity (L): 4399.00
Licence #: 0076359389

1	17 of 22	-/0.0	123.9 / 0.10	LOOMIS COURIER SERVICE 1160 BLAIR RD BURLINGTON ON	PRT

Location ID: 18419
Type: retail
Expiry Date: 1992-09-30
Capacity (L): 2000
Licence #: 0000020201

1	18 of 22	-/0.0	123.9 / 0.10	Northcote Industrial Products 1160 Blair Rd Floor 2 Unit D Burlington ON L7M 1K9	SCT

Established: 1969
Plant Size (ft²): 8000
Employment: 8

--Details--
Description: All Other Industrial Machinery Manufacturing
SIC/NAICS Code: 333299

1	19 of 22	-/0.0	123.9 / 0.10	Northcote Industrial Products Inc. 1160 Blair Rd Floor 2 Unit D Burlington ON L7M 1K9	SCT

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Established: 1969
Plant Size (ft²): 8000
Employment: 8

---

1 | 20 of 22 | -/0.0 | 123.9 / 0.10 | **ALL-TIG LTD**
1160 BLAIR RD UNIT A1
BURLINGTON ON L7M 1K9 | SCT

Established: 1989
Plant Size (ft²): 0
Employment: 4

--Details--
Description: FABRICATED METAL PRODUCTS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3499

---

1 | 21 of 22 | -/0.0 | 123.9 / 0.10 | **VERSA-HOE EQUIPMENT CORP.**
1160 Blair Rd Floor 2 Unit D
Burlington ON L7M 1K9 | SCT

Established: 1969
Plant Size (ft²): 8000
Employment: 8

--Details--
Description: All Other Industrial Machinery Manufacturing
SIC/NAICS Code: 333299

---

1 | 22 of 22 | -/0.0 | 123.9 / 0.10 | **LOOMIS COURIER**
1160 BLAIR ROAD
BURLINGTON CITY ON L7M 1K9 | SPL

Ref No:	29899	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	1/16/1990	**Client Type:**	
Year:		**Sector Type:**	
Incident Cause:	OTHER CONTAINER LEAK	**Source Type:**	
Incident Event:		**Nearest Watercourse:**	
Contaminant Code:		**Site Name:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site County/District:**	
Contaminant UN No 1:		**Site Postal Code:**	
Contaminant Qty:		**Site Region:**	
Environment Impact:		**Site Municipality:**	14101
Nature of Impact:		**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
Health/Env Conseq:		**Easting:**	BURLINGTON FD
MOE Response:		**Site Geo Ref Accu:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Meth:**	
MOE Reported Dt:	1/16/1990	**Site Map Datum:**	
Dt Document Closed:			
SAC Action Class:			

Incident Reason: OVERSTRESS/OVERPRESSURE
Incident Summary: LOOMIS- 8 LTR OF CARBON TETRACHLORIDE LEAKS FROM A FREIGHT CONTAINER

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
2	1 of 1	-/0.0	123.7 / -0.05	lot 12 con 2 BURLINGTON ON	WWIS

Well ID: 7176421
Construction Date:
Primary Water Use: Monitoring
Sec. Water Use:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z130540
Tag: A094770
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 2/9/2012
Selected Flag: 1
Abandonment Rec:
Contractor: 6607
Form Version: 7
Owner:
Street Name: GRASS EASEMENT IN FRONT OF 1160 BLAIR RD
County: HALTON
Municipality: BURLINGTON CITY
Site Info:
Lot: 012
Concession: 02
Concession Name: DS S
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1003690906
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 123.94429
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind:
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr
Org CS: UTM83
Date Completed: 12/9/2011

Overburden and Bedrock Materials Interval

Formation ID: 1004062409
Layer: 1
Color: 6
General Color: BROWN
Mat1: 02
Most Common Material: TOPSOIL
Mat2:
Other Materials:
Mat3: 85
Other Materials: SOFT
Formation Top Depth: 0.00
Formation End Depth: 0.60
Formation End Depth UOM: m

Formation ID: 1004062410
Layer: 2
Color: 6

General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	
Other Materials:	
Mat3:	66
Other Materials:	DENSE
Formation Top Depth:	0.60
Formation End Depth:	2.20
Formation End Depth UOM:	m
Formation ID:	1004062411
Layer:	3
Color:	7
General Color:	RED
Mat1:	17
Most Common Material:	SHALE
Mat2:	15
Other Materials:	LIMESTONE
Mat3:	74
Other Materials:	LAYERED
Formation Top Depth:	2.20
Formation End Depth:	7.60
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004062418
Layer:	1
Plug From:	0.00
Plug To:	0.30
Plug Depth UOM:	m
Plug ID:	1004062419
Layer:	2
Plug From:	0.30
Plug To:	4.20
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1004062417
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1004062408
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004062414
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.10

Depth To: 4.50
Casing Diameter: 5.10
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004062415
Layer: 1
Slot: 10
Screen Top Depth: 4.50
Screen End Depth: 7.60
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.40

Water Details

Water ID: 1004062413
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 3.00
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004062412
Diameter: 21.00
Depth From: 0.00
Depth To: 7.60
Hole Depth UOM: m
Hole Diameter UOM: cm

---

3 | ***1 of 1*** | ***NNE/13.4*** | ***124.0 / 0.18*** | ***Atlas Copco Construction and Mining Canada***
Burlington ON L7M 1P9 | ***SCT***

Established: 1923
Plant Size (ft²):
Employment: 1

---

4 | ***1 of 20*** | ***ESE/18.9*** | ***122.9 / -0.90*** | ***SIMON CRANE RENTAL LTD.***
1150 BLAIR ROAD, UNIT 6
BURLINGTON ON L7M 1K9 | ***GEN***

Generator No.: ON2027300
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 232240, 532410
SIC Description: 232240, CONSTRUCTION, TRANSPORTATION, MINING, AND FORESTRY MACHINERY AND EQUIPMENT RENTAL AND LEASING

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Steve Simon
Phone No. Admin: 905-336-0552 Ext.

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 221
Waste Description: LIGHT FUELS

---

4 **2 of 20** **ESE/18.9** **122.9 / -0.90** **SIMON CRANE RENTAL LTD.**
1150 BLAIR ROAD, UNIT 6
BURLINGTON ON L7M 1K9 **GEN**

Generator No.: ON2027300
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 232240, 532410
SIC Description: 232240, CONSTRUCTION, TRANSPORTATION, MINING, AND FORESTRY MACHINERY AND EQUIPMENT RENTAL AND LEASING

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Steve Simon
Phone No. Admin: 905-336-0552 Ext.

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 221
Waste Description: LIGHT FUELS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

---

4 **3 of 20** **ESE/18.9** **122.9 / -0.90** **SIMON CRANE RENTAL LTD.**
1150 BLAIR ROAD, UNIT 6
BURLINGTON ON L7M 1K9 **GEN**

Generator No.: ON2027300
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country: Canada
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213 L
Waste Description: Petroleum distillates

Waste Code: 213 I
Waste Description: Petroleum distillates

Waste Code: 252 L
Waste Description: Waste crankcase oils and lubricants

Waste Code: 212 L
Waste Description: Aliphatic solvents and residues

Waste Code: 221 I

Waste Description: Light fuels

---

4 **4 of 20** **ESE/18.9** **122.9 / -0.90** **SIMON CRANE RENTAL LTD.**
1150 BLAIR ROAD, UNIT 6
BURLINGTON ON L7M 1K9 **GEN**

Generator No.: ON2027300
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 232240, 532410
SIC Description: 232240, CONSTRUCTION, TRANSPORTATION, MINING, AND FORESTRY MACHINERY AND EQUIPMENT RENTAL AND LEASING

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Steve Simon
Phone No. Admin: 905-336-0552 Ext.

--Details--
Waste Code: 221
Waste Description: LIGHT FUELS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

---

4 **5 of 20** **ESE/18.9** **122.9 / -0.90** **SIMON CRANE RENTAL LTD.**
1150 BLAIR ROAD, UNIT 6
BURLINGTON ON L7M 3T4 **GEN**

Generator No.: ON2027300
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 232240, 532410
SIC Description: , Construction Transportation Mining and Forestry Machinery and Equipment Rental and Leasing

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 221
Waste Description: LIGHT FUELS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

4 **6 of 20** **ESE/18.9** **122.9 / -0.90** **SIMON CRANE RENTAL LTD.**
1150 BLAIR ROAD, UNIT 6
BURLINGTON ON L7M 3T4 **GEN**

Generator No.: ON2027300
Status:

PO Box No.:
Country:

Approval Years:	99,00,01,03,04	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	9911		
SIC Description:	IND. MACH. RENTAL		

--Details--

Waste Code:	212
Waste Description:	ALIPHATIC SOLVENTS
Waste Code:	213
Waste Description:	PETROLEUM DISTILLATES
Waste Code:	252
Waste Description:	WASTE OILS & LUBRICANTS

---

4 **7 of 20** **ESE/18.9** **122.9 / -0.90**

SIMON CRANE RENTAL LTD.
1150 BLAIR ROAD, UNIT #6
BURLINGTON ON L7M 3T4

GEN

Generator No.:	ON2027300	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	95,96,97,98	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	9911		
SIC Description:	IND. MACH. RENTAL		

--Details--

Waste Code:	212
Waste Description:	ALIPHATIC SOLVENTS
Waste Code:	213
Waste Description:	PETROLEUM DISTILLATES
Waste Code:	252
Waste Description:	WASTE OILS & LUBRICANTS

---

4 **8 of 20** **ESE/18.9** **122.9 / -0.90**

A.W. CHESTERTON COMPANY LTD.
1150 BLAIR ROAD
BURLINGTON ON L7M 3T4

GEN

Generator No.:	ON1801101	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	99,00,01	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	3912		
SIC Description:	OTHER INSTRUMENTS		

--Details--

Waste Code:	263
Waste Description:	ORGANIC LABORATORY CHEMICALS
Waste Code:	148
Waste Description:	INORGANIC LABORATORY CHEMICALS
Waste Code:	213
Waste Description:	PETROLEUM DISTILLATES

Waste Code: 232
Waste Description: POLYMERIC RESINS

Waste Code: 241
Waste Description: HALOGENATED SOLVENTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

4 | **9 of 20** | **ESE/18.9** | **122.9 / -0.90** | **A.W. CHESTERTON**
1150 BLAIR ROAD
BURLINGTON ON L7M 3T4 | **GEN**

Generator No.: ON1801101
Status:
Approval Years: 94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 3912
SIC Description: OTHER INSTRUMENTS

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 232
Waste Description: POLYMERIC RESINS

Waste Code: 241
Waste Description: HALOGENATED SOLVENTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

---

4 | **10 of 20** | **ESE/18.9** | **122.9 / -0.90** | **SIMON CRANE RENTAL LTD.**
1150 BLAIR ROAD, UNIT 6
BURLINGTON ON L7M 3T4 | **GEN**

Generator No.: ON2027300
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 232240, 532410
SIC Description: , Construction Transportation Mining and Forestry Machinery and Equipment Rental and Leasing

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 221
Waste Description: LIGHT FUELS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

---

4 **11 of 20** **ESE/18.9** **122.9 / -0.90** **SIMON CRANE RENTAL LTD.** **GEN**
1150 BLAIR ROAD, UNIT 6
BURLINGTON ON L7M 3T4

Generator No.: ON2027300
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 232240, 532410
SIC Description: Construction Transportation Mining and Forestry Machinery and Equipment Rental and Leasing

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 221
Waste Description: LIGHT FUELS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

---

4 **12 of 20** **ESE/18.9** **122.9 / -0.90** **SIMON CRANE RENTAL LTD.** **GEN**
1150 BLAIR ROAD, UNIT 6
BURLINGTON ON

Generator No.: ON2027300
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 232240, 532410
SIC Description: CONSTRUCTION, TRANSPORTATION, MINING, AND FORESTRY MACHINERY AND EQUIPMENT RENTAL AND LEASING

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 221
Waste Description: LIGHT FUELS

---

4 **13 of 20** **ESE/18.9** **122.9 / -0.90** **Northern Industrial Supply** **SCT**
1150 Blair Rd Unit 1S
Burlington ON L7M 3T4

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Established: 01-JAN-88
Plant Size (ft²): 10000
Employment:

--Details--
Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Description: Plumbing, Heating and Air-Conditioning Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 416120

Description: Plumbing, Heating and Air-Conditioning Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 416120

Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
4	14 of 20	ESE/18.9	122.9 / -0.90	KENWARD TOOL & DIE LTD 1150 BLAIR RD BURLINGTON ON L7M 3T4	SCT

Established:
Plant Size (ft²): 0
Employment: 1

--Details--
Description: SPECIAL DIES & TOOLS & INDUSTRIAL MOLDS
SIC/NAICS Code: 3544

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
4	15 of 20	ESE/18.9	122.9 / -0.90	J R TOOL & DIE 1150 BLAIR RD UNIT 5 BURLINGTON ON L7M 3T4	SCT

Established: 1989
Plant Size (ft²): 4000
Employment: 5

--Details--
Description: MACHINE TOOLS, METAL CUTTING TYPES
SIC/NAICS Code: 3541

Description: SPECIAL DIES AND TOOLS, DIE SETS, JIGS AND FIXTURES, AND INDUSTRIAL MOLDS
SIC/NAICS Code: 3544

Description: INDUSTRIAL AND COMMERCIAL MACHINERY AND EQUIPMENT, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3599

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
4	16 of 20	ESE/18.9	122.9 / -0.90	A W CHESTERTON COMPANY LTD. 1150 BLAIR RD BURLINGTON ON L7M 3T4	SCT

Established: 1974
Plant Size (ft²): 8000
Employment: 20

--Details--
Description: INDUSTRIAL MACHINERY AND EQUIPMENT

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
SIC/NAICS Code:		5084			
Description:		INDUSTRIAL SUPPLIES			
SIC/NAICS Code:		5085			

4	17 of 20	ESE/18.9	122.9 / -0.90	**S O S Cylinders Inc.** **1150 Blair Rd Unit 2** **Burlington ON L7M 3T4**	SCT

Established:
Plant Size (ft²): 10000
Employment: 20

--Details--
Description: All Other General-Purpose Machinery Manufacturing
SIC/NAICS Code: 333990

4	18 of 20	ESE/18.9	122.9 / -0.90	**Northern Integrated Systems Co** **1150 Blair Rd Unit 1** **Burlington ON L7M 3T4**	SCT

Established: 01-SEP-96
Plant Size (ft²): 2000
Employment:

--Details--
Description: Pump and Compressor Manufacturing
SIC/NAICS Code: 333910

Description: All Other Plastic Product Manufacturing
SIC/NAICS Code: 326198

Description: All Other General-Purpose Machinery Manufacturing
SIC/NAICS Code: 333990

Description: Industrial and Commercial Fan and Blower and Air Purification Equipment Manufacturing
SIC/NAICS Code: 333413

Description: Industrial and Commercial Fan and Blower and Air Purification Equipment Manufacturing
SIC/NAICS Code: 333413

4	19 of 20	ESE/18.9	122.9 / -0.90	**J R Tool & Die Ltd.** **1150 Blair Rd Unit 5** **Burlington ON L7M 3T4**	SCT

Established: 01-JUN-92
Plant Size (ft²):
Employment:

--Details--
Description: Machine Shops
SIC/NAICS Code: 332710

4	20 of 20	ESE/18.9	122.9 / -0.90	**BURLINGTON ON**	WWIS

Well ID:	7041585	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:		***Date Received:***	3/13/2007
Sec. Water Use:		***Selected Flag:***	1
Final Well Status:	Observation Wells	***Abandonment Rec:***	
Water Type:		***Contractor:***	6607
Casing Material:		***Form Version:***	3
Audit No:	Z17120	***Owner:***	
Tag:	A049120	***Street Name:***	1150 BLAIR RD
Construction Method:		***County:***	HALTON
Elevation (m):		***Municipality:***	BURLINGTON CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	11764078	***Spatial Status:***	
DP2BR:		***Cluster Kind:***	
Code OB:	o	***UTMRC:***	3
Code OB Desc:	Overburden	***UTMRC Desc:***	margin of error : 10 - 30 m
Open Hole:		***Location Method:***	wwr
Elevation:	122.320808	***Org CS:***	UTM83
Elevrc:		***Date Completed:***	1/22/2007
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	933094470
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	01
Most Common Material:	FILL
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0.00
Formation End Depth:	1.50
Formation End Depth UOM:	m

Formation ID:	933094471
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Other Materials:	GRAVEL
Mat3:	91

Other Materials: WATER-BEARING
Formation Top Depth: 1.50
Formation End Depth: 3.00
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933315409
Layer: 1
Plug From: 0.00
Plug To: 1.00
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 967041585
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 11771768
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930896801
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.00
Depth To: 1.50
Casing Diameter: 5.10
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933423535
Layer: 1
Slot: 10
Screen Top Depth: 1.50
Screen End Depth: 3.00
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.40

Water Details

Water ID: 934084646
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 1.50
Water Found Depth UOM: m

Hole Diameter

Hole ID:	11850276
Diameter:	15.00
Depth From:	0.00
Depth To:	3.00
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

5 ***1 of 1*** ***SW/32.1*** ***123.7 / -0.05*** ***ON*** ***BORE***

Borehole ID:	624322	***Type:***	Borehole
Use:	Geotechnical/Geological Investigation	***Status::***	
Drill Method::	Power auger	***UTM Zone::***	17
Easting::	597155	***Northing::***	4802023
Location Accuracy::		***Orig. Ground Elev m::***	122
Elev. Reliability Note::		***DEM Ground Elev m::***	123
Total Depth m::	3	***Primary Name::***	
Township::		***Concession::***	
Lot::		***Municipality:***	
Completion Date::	MAY-1969	***Static Water Level::***	-999.9
Primary Water Use::	Not Used	***Sec. Water Use::***	

--Details--

Stratum ID:	218433288	***Top Depth(m):***	0.0
Bottom Depth(m):	1.4	***Stratum Desc:***	FILL,SAND,SILT,SOIL.BROWN,MAN-MADE,LOOSE, AGE POST-GLACIAL.
Stratum ID:	218433289	***Top Depth(m):***	1.4
Bottom Depth(m):	1.7	***Stratum Desc:***	SILT,SAND. BROWN,AGE GLACIAL.
Stratum ID:	218433290	***Top Depth(m):***	1.7
Bottom Depth(m):	3.0	***Stratum Desc:***	GRAVEL,STONES. AGE GLACIAL. 00000006000450100005512000040

---

6 ***1 of 1*** ***SW/34.7*** ***122.8 / -0.93*** ***ON*** ***BORE***

Borehole ID:	624323	***Type:***	Borehole
Use:	Geotechnical/Geological Investigation	***Status::***	
Drill Method::	Power auger	***UTM Zone::***	17
Easting::	597175	***Northing::***	4802003
Location Accuracy::		***Orig. Ground Elev m::***	123
Elev. Reliability Note::		***DEM Ground Elev m::***	123
Total Depth m::	4.6	***Primary Name::***	
Township::		***Concession::***	
Lot::		***Municipality:***	
Completion Date::	MAY-1969	***Static Water Level::***	-999.9
Primary Water Use::	Not Used	***Sec. Water Use::***	

--Details--

Stratum ID:	218433291	***Top Depth(m):***	0.0
Bottom Depth(m):	2.6	***Stratum Desc:***	TILL,SILT,SAND,CLAY.BROWN,GLACIAL,VERY SOFT, AGE GLACIAL.
Stratum ID:	218433292	***Top Depth(m):***	2.6
Bottom Depth(m):	3.0	***Stratum Desc:***	TILL,SILT,SAND,CLAY.BROWN,GLACIAL,VERY HARD, AGE GLACIAL.

Stratum ID:	218433293	**Top Depth(m):**	3.0
Bottom Depth(m):	4.6	**Stratum Desc:**	TILL,SILT,SAND. BROWN,GLACIAL,HARD, AGE GLACIAL. 00000031000850600010007000090

---

7 **1 of 34** **NNE/57.1** **124.2 / 0.43** **Atlas Copco Canada Inc.** **CA**
1157 Blair Road
Burlington ON L7M 1P9

Certificate #:	2401-5N9PNB
Application Year:	2003
Issue Date:	6/7/2003
Approval Type:	Air
Status:	Approved
Application Type:	
Client Name::	
Client Address::	
Client City::	
Client Postal Code::	
Project Description::	
Contaminants::	
Emission Control::	

---

7 **2 of 34** **NNE/57.1** **124.2 / 0.43** **Atlas Copco Canada Inc.** **EBR**
1157 Blair Road Burlington Ontario Burlington ON

EBR Registry No.:	IA03E0340
Ministry Ref. No.:	4308-5JVU3C
Company Name:	Atlas Copco Canada Inc.
Notice Type:	Instrument Decision
Notice Date:	June 10, 2003
Proposal Date:	March 13, 2003
Year:	2003
Proponent Address:	2555 Dollard , 203, LaSalle QUÉBEC, H8N 3A9
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:	

Location:

1157 Blair Road Burlington Ontario Burlington

---

7 **3 of 34** **NNE/57.1** **124.2 / 0.43** **Wardco Window and Door Manufacturing Inc.** **EBR**
1157 Blair Road Burlington, Regional Municipality of Halton L7M 1P9 CITY OF BURLINGTON
ON

EBR Registry No.:	011-7342
Ministry Ref. No.:	2125-8YYP3G
Company Name:	Wardco Window and Door Manufacturing Inc.
Notice Type:	Instrument Decision
Notice Date:	May 21, 2014
Proposal Date:	October 16, 2012
Year:	2012
Proponent Address:	1157 Blair Road, Burlington Ontario, Canada L7L 1E0
Instrument Type:	(EPA Part II.1-air) - Environmental Compliance Approval (project type: air)
Location Other:	

Location:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

1157 Blair Road Burlington, Regional Municipality of Halton L7M 1P9 CITY OF BURLINGTON

---

7 **4 of 34** **NNE/57.1** **124.2 / 0.43** **Atlas Copco Canada Inc.** **ECA**
1157 Blair Road
Burlington ON H8N 3A9

Approval No:	2401-5N9PNB	**MOE District:**	Halton-Peel
Approval Type:	ECA-AIR	**SWP Area Name:**	Halton
Status:	Approved	**Address:**	1157 Blair Road
Approval Date:	2003-06-07	**City:**	Burlington
Record Type:	ECA	**Longitude:**	-79.7985839999999
Project Type:	AIR	**Latitude:**	43.366665
Link Source:	IDS		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/4308-5JVU3C-14.pdf		

---

7 **5 of 34** **NNE/57.1** **124.2 / 0.43** **Wardco Window and Door Manufacturing Inc.** **ECA**
1157 Blair Road
City of Burlington ON

Approval No:	6917-9BWP65	**MOE District:**	
Approval Type:		**SWP Area Name:**	
Status:	Approved	**Address:**	
Approval Date:	5/15/14	**City:**	City of Burlington
Record Type:		**Longitude:**	
Project Type:	Air/Noise	**Latitude:**	
Link Source:			
Full Address:	1157 Blair Road City of Burlington, Regional Municipality ofaH lton		
Full PDF Link:			

---

7 **6 of 34** **NNE/57.1** **124.2 / 0.43** **Wardco Window and Door Manufacturing Inc.** **ECA**
1157 Blair Rd
Burlington ON

Approval No:	6917-9BWP65	**MOE District:**	
Approval Type:	ECA-AIR	**SWP Area Name:**	
Status:	Approved	**Address:**	1157 Blair Rd
Approval Date:	2014-05-15	**City:**	Burlington
Record Type:	ECA	**Longitude:**	
Project Type:	AIR	**Latitude:**	
Link Source:	IDS		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/2125-8YYP3G-14.pdf		

---

7 **7 of 34** **NNE/57.1** **124.2 / 0.43** **1157 BLAIR RD** **EHS**
BURLINGTON ON L7M 1P9

Order ID:	183088	**Date Received:**	2/18/2011 11:36:39 AM
Order No:	20110218017	**Lot/Building Size:**	
Customer ID:	45487	**Municipality:**	
Company ID:	313	**Client Prov/State:**	ON
Status:	C	**Search Radius (km):**	0.25
Report Code:	3CAN	**Large Radius:**	2
Report Type:	Standard Report	**X:**	-79.798519
Report Date:	3/1/2011	**Y:**	43.366615
Report Requested by:	SCM Risk Management Services Inc.		
Nearest Intersection:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site		DB

Previous Site Name:
Additional Info Ordered:

---

7 ***8 of 34*** ***NNE/57.1*** ***124.2 / 0.43*** ***FAGERSTA SECOROC LTD*** ***15-019*** ***GEN***
1157 BLAIR RD
BURLINGTON ON L7M 1P9

Generator No.:	ON0079400	***PO Box No.:***	
Status:		***Country:***	
Approval Years:	92,93,94,95,96,97	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No. Admin:***	
SIC Code:	5722		
SIC Description:	MINING MACHINERY		

--Details--
Waste Code: 241
Waste Description: HALOGENATED SOLVENTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

7 ***9 of 34*** ***NNE/57.1*** ***124.2 / 0.43*** ***Wardco Window & Door Manufacturing*** ***GEN***
1157 Blair Road
Burlington ON L7M 1P9

Generator No.:	ON3921582	***PO Box No.:***	
Status:	Registered	***Country:***	Canada
Approval Years:	As of Dec 2017	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No. Admin:***	
SIC Code:			
SIC Description:			

--Details--
Waste Code: 145 L
Waste Description: Wastes from the use of pigments, coatings and paints

---

7 ***10 of 34*** ***NNE/57.1*** ***124.2 / 0.43*** ***Atlas Copco Canada Inc.*** ***GEN***
1157 Blair Road
Burlington ON L7M 7P9

Generator No.:	ON8708441	***PO Box No.:***	
Status:	Registered	***Country:***	Canada
Approval Years:	As of Dec 2017	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No. Admin:***	
SIC Code:			
SIC Description:			

--Details--
Waste Code: 146 R
Waste Description: Other specified inorganic sludges, slurries or solids

Waste Code: 241 L
Waste Description: Halogenated solvents and residues

Waste Code: 251 L

Waste Description: Waste oils/sludges (petroleum based)

Waste Code: 146 L
Waste Description: Other specified inorganic sludges, slurries or solids

---

7 **11 of 34** **NNE/57.1** **124.2 / 0.43** **Atlas Copco Canada Inc.** **GEN**
1157 Blair Road
Burlington ON L7M 1P9

Generator No.: ON8708441
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 423810
SIC Description:

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 241
Waste Description: HALOGENATED SOLVENTS

---

7 **12 of 34** **NNE/57.1** **124.2 / 0.43** **FAGERSTA SECOROC LTD** **GEN**
1157 BLAIR RD
BURLINGTON ON L7M 1P9

Generator No.: ON0079400
Status:
Approval Years: 86,87,88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 5722
SIC Description: MINING MACHINERY

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 253
Waste Description: EMULSIFIED OILS

Waste Code: 241
Waste Description: HALOGENATED SOLVENTS

---

7 **13 of 34** **NNE/57.1** **124.2 / 0.43** **Atlas Copco Canada** **GEN**
1157 Blair Road
Burlington ON L7M 1P9

Generator No.: ON7641550
Status:
Approval Years: 02,03,04
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

---

7 ***14 of 34*** ***NNE/57.1*** ***124.2 / 0.43*** ***Atlas Copco Canada Inc.*** ***GEN***
1157 Blair Road
Burlington ON L7M 7P9

Generator No.: ON8708441
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 423810
SIC Description: 423810

PO Box No.:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Daniel Brenner
Phone No. Admin: 5197415774 Ext.286

--Details--
Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 241
Waste Description: HALOGENATED SOLVENTS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

---

7 ***15 of 34*** ***NNE/57.1*** ***124.2 / 0.43*** ***Atlas Copco Canada Inc.*** ***GEN***
1157 Blair Road
Burlington ON L7M 1P9

Generator No.: ON8708441
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 423810
SIC Description:

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 241
Waste Description: HALOGENATED SOLVENTS

---

7 ***16 of 34*** ***NNE/57.1*** ***124.2 / 0.43*** ***FAGERSTA SECOROC LTD.(OUT OF BUSINESS)*** ***GEN***
1157 BLAIR ROAD
BURLINGTON ON L7M 1P9

Generator No.: ON0079400
Status:
Approval Years: 98
Contam. Facility:
MHSW Facility:
SIC Code: 5722
SIC Description: MINING MACHINERY

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Waste Code: 241
Waste Description: HALOGENATED SOLVENTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

7 ***17 of 34*** ***NNE/57.1*** ***124.2 / 0.43*** ***XCG Consultants Ltd.*** ***GEN***
1157 Blair Road
Burlington ON

Generator No.: ON4426767
Status:
Approval Years: 03,04,05,06
Contam. Facility:
MHSW Facility:
SIC Code: 541620
SIC Description: Environmental Consulting Services

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

---

7 ***18 of 34*** ***NNE/57.1*** ***124.2 / 0.43*** ***Atlas Copco Canada Inc.*** ***GEN***
1157 Blair Road
Burlington ON L7M 1P9

Generator No.: ON8708441
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 423810
SIC Description:

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 241
Waste Description: HALOGENATED SOLVENTS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

---

7 ***19 of 34*** ***NNE/57.1*** ***124.2 / 0.43*** ***Atlas Copco Canada Inc.*** ***GEN***
1157 Blair Road
Burlington ON L7M 1P9

Generator No.: ON8708441
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 423810
SIC Description:

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 241
Waste Description: HALOGENATED SOLVENTS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

---

7 ***20 of 34*** ***NNE/57.1*** ***124.2 / 0.43*** ***Atlas Copco Canada Inc.*** ***GEN***
1157 Blair Road
Burlington ON L7M 7P9

Generator No.: ON8708441
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 423810
SIC Description: 423810

PO Box No.:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Tyler Schierholtz
Phone No. Admin: 5197415774 Ext.240

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 241
Waste Description: HALOGENATED SOLVENTS

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

---

7 ***21 of 34*** ***NNE/57.1*** ***124.2 / 0.43*** ***Wardco Window & Door Manufacturing*** ***GEN***
1157 Blair Road
Burlington ON L7M 1P9

Generator No.: ON3921582
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 339990
SIC Description: ALL OTHER MISCELLANEOUS MANUFACTURING

PO Box No.:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Tony Sayegh
Phone No. Admin: 905-333-4521 Ext.211

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

---

7 ***22 of 34*** ***NNE/57.1*** ***124.2 / 0.43*** ***Wardco Window & Door Manufacturing*** ***GEN***
1157 Blair Road
Burlington ON L7M 1P9

Generator No.: ON3921582
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 339990

PO Box No.:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Tony Sayegh
Phone No. Admin: 905-333-4521 Ext.

SIC Description: ALL OTHER MISCELLANEOUS MANUFACTURING

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

---

7 | **23 of 34** | **NNE/57.1** | **124.2 / 0.43** | **Screenplay Designs Inc**
1157 Blair Road
Burlington ON L7M 1P9 | **GEN**

Generator No.: ON3505916
Status:
Approval Years: 07,08
Contam. Facility:
MHSW Facility:
SIC Code: 339990
SIC Description: All Other Miscellaneous Manufacturing

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 265
Waste Description: GRAPHIC ART WASTES

---

7 | **24 of 34** | **NNE/57.1** | **124.2 / 0.43** | **Atlas Copco Canada Inc.**
1157 Blair Road
Burlington ON L7M 1P9 | **GEN**

Generator No.: ON8708441
Status:
Approval Years: 07,08
Contam. Facility:
MHSW Facility:
SIC Code: 562910
SIC Description: Remediation Services

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 241
Waste Description: HALOGENATED SOLVENTS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

---

7 | **25 of 34** | **NNE/57.1** | **124.2 / 0.43** | **Wardco Window & Door Manufacturing**
1157 Blair Road
Burlington ON | **GEN**

Generator No.: ON3921582
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 339990
SIC Description: All Other Miscellaneous Manufacturing

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

7 **26 of 34** **NNE/57.1** **124.2 / 0.43** **Wardco Window & Door Manufacturing** **GEN**
1157 Blair Road
Burlington ON L7M 1P9

Generator No.:	ON3921582	**PO Box No.:**	
Status:		**Country:**	Canada
Approval Years:	2016	**Choice of Contact:**	CO_ADMIN
Contam. Facility:	No	**Co Admin:**	Tony Sayegh
MHSW Facility:	No	**Phone No. Admin:**	905-333-4521 Ext.211
SIC Code:	339990		
SIC Description:	ALL OTHER MISCELLANEOUS MANUFACTURING		

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 232
Waste Description: POLYMERIC RESINS

7 **27 of 34** **NNE/57.1** **124.2 / 0.43** **Atlas Copco Canada Inc.** **GEN**
1157 Blair Road
Burlington ON L7M 7P9

Generator No.:	ON8708441	**PO Box No.:**	
Status:		**Country:**	Canada
Approval Years:	2015	**Choice of Contact:**	CO_ADMIN
Contam. Facility:	No	**Co Admin:**	Daniel Brenner
MHSW Facility:	No	**Phone No. Admin:**	5197415774 Ext.286
SIC Code:	423810		
SIC Description:	423810		

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 241
Waste Description: HALOGENATED SOLVENTS

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

7 **28 of 34** **NNE/57.1** **124.2 / 0.43** **Atlas Copco Canada Inc.** **GEN**
1157 Blair Road
Burlington ON

Generator No.:	ON8708441	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	2013	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	423810		
SIC Description:			

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 241
Waste Description: HALOGENATED SOLVENTS

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

---

7 | **29 of 34** | **NNE/57.1** | **124.2 / 0.43** | **Wardco Window & Door Manufacturing** | **GEN**
1157 Blair Road
Burlington ON

Generator No.: ON3921582
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 339990
SIC Description: ALL OTHER MISCELLANEOUS MANUFACTURING

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

---

7 | **30 of 34** | **NNE/57.1** | **124.2 / 0.43** | **ATLAS COPCO CONSTRUCTION** | **SCT**
1157 BLAIR RD
BURLINGTON ON L7M 1P9

Established: 0000
Plant Size (ft²): 0
Employment: 3

--Details--
Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

---

7 | **31 of 34** | **NNE/57.1** | **124.2 / 0.43** | **Atlas Copco Construction and Mining Canada** | **SCT**
1157 Blair Rd
Burlington ON L7M 1P9

Established:
Plant Size (ft²):
Employment: 3

--Details--
Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

---

7 | **32 of 34** | **NNE/57.1** | **124.2 / 0.43** | **Atlas Copco Canada Inc.<UNOFFICIAL>** | **SPL**
1157 Blair Rd., Burlington
Burlington ON L7M 1P9

Ref No: 1402-7B6UBV
Site No:
Incident Dt:
Year:
Incident Cause: Valve / Fitting Leak Or Failure
Incident Event:

Discharger Report:
Material Group:
Client Type:
Sector Type: Other
Source Type:
Nearest Watercourse:

Contaminant Code:	28	**Site Name:**	Atlas Copco Canada Inc.<UNOFFICIAL>
Contaminant Name:	POTASSIUM PERMANGANATE	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	Halton-Peel
Contam Limit Freq 1:		**Site County/District:**	
Contaminant UN No 1:		**Site Postal Code:**	
Contaminant Qty:	2 L	**Site Region:**	
Environment Impact:	Not Anticipated	**Site Municipality:**	Burlington
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	
Health/Env Conseq:		**Easting:**	
MOE Response:	No Field Response	**Site Geo Ref Accu:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Meth:**	
MOE Reported Dt:	1/24/2008	**Site Map Datum:**	
Dt Document Closed:	9/8/2008		
SAC Action Class:	Land Spills		
Incident Reason:	Ice/Frost - Freezing		
Incident Summary:	Atlas Copco Canada Inc: Spill of 2 L of KMnO4 to ground		

7 **33 of 34** **NNE/57.1** **124.2 / 0.43** **BURLINGTON ON** **WWIS**

Well ID:	7043039	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	4/27/2007
Sec. Water Use:		**Selected Flag:**	1
Final Well Status:	Observation Wells	**Abandonment Rec:**	
Water Type:		**Contractor:**	7238
Casing Material:		**Form Version:**	3
Audit No:	Z56169	**Owner:**	
Tag:	A048720	**Street Name:**	1157 BLAIR RD
Construction Method:		**County:**	HALTON
Elevation (m):		**Municipality:**	BURLINGTON CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	11765487	**Spatial Status:**	
DP2BR:	7	**Cluster Kind:**	
Code OB:	r	**UTMRC:**	3
Code OB Desc:	Bedrock	**UTMRC Desc:**	margin of error : 10 - 30 m
Open Hole:		**Location Method:**	wwr
Elevation:	123.376441	**Org CS:**	UTM83
Elevrc:		**Date Completed:**	3/31/2007
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID: 933098855
Layer: 1
Color: 7
General Color: RED
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Other Materials: SILT
Mat3:
Other Materials:
Formation Top Depth: 0.00
Formation End Depth: 2.00
Formation End Depth UOM: m

Formation ID: 933098856
Layer: 2
Color: 7
General Color: RED
Mat1: 17
Most Common Material: SHALE
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 2.00
Formation End Depth: 12.00
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933317751
Layer: 1
Plug From: 0.00
Plug To: 9.00
Plug Depth UOM: m

Plug ID: 933317752
Layer: 2
Plug From: 9.00
Plug To: 12.00
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 967043039
Method Construction Code: 4
Method Construction: Rotary (Air)
Other Method Construction:

Pipe Information

Pipe ID: 11773177
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930898506

Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.00
Depth To:	9.00
Casing Diameter:	
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	933424182
Layer:	1
Slot:	10
Screen Top Depth:	9.00
Screen End Depth:	12.00
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	

Water Details

Water ID:	934085601
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	3.00
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	11851850
Diameter:	22.00
Depth From:	0.00
Depth To:	4.00
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Hole ID:	11851851
Diameter:	8.00
Depth From:	4.00
Depth To:	12.00
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

7 | ***34 of 34*** | ***NNE/57.1*** | ***124.2 / 0.43*** | ***Burlington ON*** | ***WWIS***

Well ID:	7118834	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring	**Date Received:**	2/2/2009
Sec. Water Use:		**Selected Flag:**	1
Final Well Status:	Test Hole	**Abandonment Rec:**	
Water Type:		**Contractor:**	6607
Casing Material:		**Form Version:**	5
Audit No:	M02429	**Owner:**	
Tag:	A069716	**Street Name:**	1157 BLAIR RD
Construction Method:		**County:**	HALTON
Elevation (m):		**Municipality:**	BURLINGTON CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	

Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1003224755
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 123.623649
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 6/11/2008

Annular Space/Abandonment Sealing Record

Plug ID: 1003224759
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003224758
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1003224760
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1003224762
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.50
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID:	1003224761
Layer:	
Slot:	
Screen Top Depth:	4.50
Screen End Depth:	7.60
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pump Test ID:	1003224763
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1003224757
Diameter:	15.00
Depth From:	
Depth To:	7.60
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1003224710	***Spatial Status:***	
DP2BR:		***Cluster Kind:***	This is a record from cluster log sheet
Code OB:		***UTMRC:***	3
Code OB Desc:		***UTMRC Desc:***	margin of error : 10 - 30 m
Open Hole:		***Location Method:***	wwr
Elevation:	124.381683	***Org CS:***	UTM83
Elevrc:		***Date Completed:***	6/10/2008
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1003224714
Layer:	

Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003224713
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1003224715
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1003224717
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.50
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1003224716
Layer:
Slot:
Screen Top Depth: 4.50
Screen End Depth: 7.50
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1003224718
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID:	1003224712
Diameter:	15.00
Depth From:	
Depth To:	7.50
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1003224719	***Spatial Status:***	
DP2BR:		***Cluster Kind:***	This is a record from cluster log sheet
Code OB:		***UTMRC:***	3
Code OB Desc:		***UTMRC Desc:***	margin of error : 10 - 30 m
Open Hole:		***Location Method:***	wwr
Elevation:	124.446594	***Org CS:***	UTM83
Elevrc:		***Date Completed:***	6/10/2008
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1003224723
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1003224722
Method Construction Code:	
Method Construction:	
Other Method Construction:	BORING

Pipe Information

Pipe ID:	1003224724
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1003224726
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	4.60
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1003224725
Layer:	
Slot:	
Screen Top Depth:	4.60
Screen End Depth:	7.60
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pump Test ID:	1003224727
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1003224721
Diameter:	15.00
Depth From:	
Depth To:	7.60
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1003224764	***Spatial Status:***	
DP2BR:		***Cluster Kind:***	This is a record from cluster log sheet
Code OB:		***UTMRC:***	3
Code OB Desc:		***UTMRC Desc:***	margin of error : 10 - 30 m
Open Hole:		***Location Method:***	wwr
Elevation:	123.669067	***Org CS:***	UTM83
Elevrc:		***Date Completed:***	6/11/2008
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1003224768

Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID:	1003224767
Method Construction Code:	
Method Construction:	
Other Method Construction:	BORING

Pipe Information

Pipe ID:	1003224769
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1003224771
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	2.50
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1003224770
Layer:	
Slot:	
Screen Top Depth:	2.50
Screen End Depth:	4.50
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pump Test ID:	1003224772
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1003224766
Diameter:	15.00
Depth From:	
Depth To:	4.50
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1003224701	***Spatial Status:***	
DP2BR:		***Cluster Kind:***	This is a record from cluster log sheet
Code OB:		***UTMRC:***	3
Code OB Desc:		***UTMRC Desc:***	margin of error : 10 - 30 m
Open Hole:		***Location Method:***	wwr
Elevation:	124.425079	***Org CS:***	UTM83
Elevrc:		***Date Completed:***	6/10/2008
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1003224705
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1003224704
Method Construction Code:	
Method Construction:	
Other Method Construction:	BORING

Pipe Information

Pipe ID:	1003224706
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1003224708
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	4.50
Casing Diameter:	
Casing Diameter UOM:	

Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1003224707
Layer:
Slot:
Screen Top Depth: 4.50
Screen End Depth: 7.50
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1003224709
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1003224703
Diameter: 15.00
Depth From:
Depth To: 7.50
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1003224728
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 124.484947
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 6/11/2008

Annular Space/Abandonment Sealing Record

Plug ID: 1003224732
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003224731
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1003224733
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1003224735
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 1.00
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1003224734
Layer:
Slot:
Screen Top Depth: 1.00
Screen End Depth: 4.00
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1003224736
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:

Flowing:

Hole Diameter

Hole ID: 1003224730
Diameter: 15.00
Depth From:
Depth To: 4.00
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1003224782
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 123.582092
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 6/11/2008

Annular Space/Abandonment Sealing Record

Plug ID: 1003224786
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003224785
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1003224787
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1003224789
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 1.00
Casing Diameter:

Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1003224788
Layer:
Slot:
Screen Top Depth: 1.00
Screen End Depth: 4.00
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1003224790
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1003224784
Diameter: 15.00
Depth From:
Depth To: 4.00
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1003224773
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 123.560005
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 6/11/2008

Annular Space/Abandonment Sealing Record

Plug ID: 1003224777
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003224776
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1003224778
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1003224780
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.50
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1003224779
Layer:
Slot:
Screen Top Depth: 4.50
Screen End Depth: 7.60
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1003224781
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:

Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1003224775
Diameter: 15.00
Depth From:
Depth To: 7.60
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1003224737
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 124.416778
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 6/11/2008

Annular Space/Abandonment Sealing Record

Plug ID: 1003224741
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003224740
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1003224742
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1003224744
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 1.00

Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1003224743
Layer:
Slot:
Screen Top Depth: 1.00
Screen End Depth: 4.00
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1003224745
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1003224739
Diameter: 15.00
Depth From:
Depth To: 4.00
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1003224746
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 124.177062
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 6/11/2008

Annular Space/Abandonment

Sealing Record

Plug ID:	1003224750
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1003224749
Method Construction Code:	
Method Construction:	
Other Method Construction:	BORING

Pipe Information

Pipe ID:	1003224751
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1003224753
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	1.00
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1003224752
Layer:	
Slot:	
Screen Top Depth:	1.00
Screen End Depth:	4.00
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pump Test ID:	1003224754
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	

Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1003224748
Diameter: 15.00
Depth From:
Depth To: 4.00
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1001980385
DP2BR:
Code OB:
Code OB Desc:
Open Hole: N
Elevation: 124.425079
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Spatial Status:
Cluster Kind:
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr
Org CS: UTM83
Date Completed: 6/10/2008

Overburden and Bedrock Materials Interval

Formation ID: 1003224793
Layer: 1
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 28
Other Materials: SAND
Mat3: 05
Other Materials: CLAY
Formation Top Depth: 0.00
Formation End Depth: 2.00
Formation End Depth UOM: m

Formation ID: 1003224794
Layer: 2
Color: 6
General Color: BROWN
Mat1: 17
Most Common Material: SHALE
Mat2: 15
Other Materials: LIMESTONE
Mat3:
Other Materials:
Formation Top Depth: 2.00
Formation End Depth: 7.50
Formation End Depth UOM: m

Annular Space/Abandonment

Sealing Record

Plug ID:	1003224796
Layer:	1
Plug From:	0.00
Plug To:	0.30
Plug Depth UOM:	m

Plug ID:	1003224797
Layer:	2
Plug From:	0.30
Plug To:	4.40
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1003224802
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1003224791
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1003224799
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.00
Depth To:	7.50
Casing Diameter:	5.90
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1003224800
Layer:	1
Slot:	10
Screen Top Depth:	
Screen End Depth:	
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.40

Results of Well Yield Testing

Pump Test ID:	1003224792
Pump Set At:	
Static Level:	0.00
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	

Recommended Pump Rate:
Levels UOM: m
Rate UOM:
Water State After Test Code: 0
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1003224798
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 0.00
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1003224795
Diameter: 15.00
Depth From: 0.00
Depth To: 7.50
Hole Depth UOM: m
Hole Diameter UOM: cm

---

8 | **1 of 1** | **N/67.0** | **124.8 / 1.07** | **Conspec Controls Ltd.**
1180 Blair Rd
Burlington ON L7M 1K9 | **SCT**

Established: 01-SEP-68
Plant Size (ft²):
Employment:

--Details--
Description: Measuring, Medical and Controlling Devices Manufacturing
SIC/NAICS Code: 334512

Description: Measuring, Medical and Controlling Devices Manufacturing
SIC/NAICS Code: 334512

---

9 | **1 of 1** | **ENE/69.0** | **122.4 / -1.42** | **ON** | **WWIS**

Well ID: 7218600
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status:
Water Type:
Casing Material:
Audit No: C24731
Tag: A159761
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:

Data Entry Status: Date Entry is incomplete
Data Src:
Date Received: 3/28/2014
Selected Flag: 1
Abandonment Rec:
Contractor: 7215
Form Version: 8
Owner:
Street Name:
County: HALTON
Municipality: BURLINGTON CITY
Site Info:
Lot:
Concession:
Concession Name:

Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1004727065
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 122.104881
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Spatial Status:
Cluster Kind:
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr
Org CS: UTM83
Date Completed: 2/11/2014

---

10 | ***1 of 5*** | ***W/69.8*** | ***124.8 / 1.07*** | ***SWISSLINE INDUSTRIES LTD.*** ***36-732*** | ***GEN***
3300 MAINWAY
BURLINGTON ON L7M 1A7

Generator No.: ON1283600
Status:
Approval Years: 92,93,94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 3081
SIC Description: MACHINE SHOP IND.
PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

---

10 | ***2 of 5*** | ***W/69.8*** | ***124.8 / 1.07*** | ***JCP Belt Components Inc.*** | ***SCT***
3300 Mainway
Burlington ON L7M 1A7

Established: 1995
Plant Size (ft²):
Employment:

--Details--
Description: Material Handling Equipment Manufacturing
SIC/NAICS Code: 333920

---

10 | ***3 of 5*** | ***W/69.8*** | ***124.8 / 1.07*** | ***VERNS METAL STAMPING INC.*** | ***SCT***
3300 MAINWAY DR UNIT 1
BURLINGTON ON L7M 1A7

Established: 1989
Plant Size (ft²): 0
Employment: 3

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Description: METAL STAMPINGS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3469

Description: FABRICATED METAL PRODUCTS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3499

---

10 ***4 of 5*** ***W/69.8*** ***124.8 / 1.07*** ***JONES TOOL & MACHINE CO. LTD.***
3300 MAINWAY DR UNIT 1
BURLINGTON ON L7M 1A7 ***SCT***

Established: 1946
Plant Size (ft²): 3000
Employment: 4

--Details--
Description: MILLWORK
SIC/NAICS Code: 2431

Description: SPECIAL DIES AND TOOLS, DIE SETS, JIGS AND FIXTURES, AND INDUSTRIAL MOLDS
SIC/NAICS Code: 3544

Description: INDUSTRIAL AND COMMERCIAL MACHINERY AND EQUIPMENT, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3599

---

10 ***5 of 5*** ***W/69.8*** ***124.8 / 1.07*** ***JCP Belt Components Inc.***
3300 Mainway Dr
Burlington ON L7M 1A7 ***SCT***

Established: 1995
Plant Size (ft²):
Employment: 3

--Details--
Description: Material Handling Equipment Manufacturing
SIC/NAICS Code: 333920

---

11 ***1 of 14*** ***SE/75.3*** ***121.9 / -1.91*** ***1140 Blair Rd***
Burlington ON L7M1K9 ***EHS***

Order ID:	484593	***Date Received:***	31-OCT-16
Order No:	20161031139	***Lot/Building Size:***	
Customer ID:	85427	***Municipality:***	
Company ID:	53985	***Client Prov/State:***	NY
Status:	C	***Search Radius (km):***	.25
Report Code:	3CAN	***Large Radius:***	.35
Report Type:	Standard Report	***X:***	-79.798466
Report Date:	07-NOV-16	***Y:***	43.364832

Report Requested by: The Lotis Engineering Group
Nearest Intersection:
Previous Site Name:
Additional Info Ordered: City Directory; Aerial Photos

---

11 ***2 of 14*** ***SE/75.3*** ***121.9 / -1.91*** ***1140 Blair Rd***
Burlington ON L7M1K9 ***EHS***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Order ID:	368860	**Date Received:**	06-JAN-15
Order No:	20150106031	**Lot/Building Size:**	
Customer ID:	110548	**Municipality:**	Burlington
Company ID:	20784	**Client Prov/State:**	ON
Status:	C	**Search Radius (km):**	.25
Report Code:	3CAN	**Large Radius:**	.5
Report Type:	Standard Report	**X:**	-79.798466
Report Date:	12-JAN-15	**Y:**	43.364832
Report Requested by:	MTE Consultants Inc.		
Nearest Intersection:			
Previous Site Name:			
Additional Info Ordered:	City Directory		

---

11 | ***3 of 14*** | ***SE/75.3*** | ***121.9 / -1.91*** | ***JONES NEON DISPLAYS LIMITED*** | ***GEN***
1140 BLAIR ROAD
BURLINGTON ON L7M 1K9

Generator No.:	ON2208000	**PO Box No.:**	
Status:		**Country:**	Canada
Approval Years:	2016	**Choice of Contact:**	CO_OFFICIAL
Contam. Facility:	No	**Co Admin:**	Heather Jones
MHSW Facility:	No	**Phone No. Admin:**	905-335-6664 Ext.
SIC Code:	339950		
SIC Description:	SIGN MANUFACTURING		

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

---

11 | ***4 of 14*** | ***SE/75.3*** | ***121.9 / -1.91*** | ***JONES NEON DISPLAYS LIMITED*** | ***GEN***
1140 BLAIR ROAD
BURLINGTON ON L7M 1K9

Generator No.:	ON2208000	**PO Box No.:**	
Status:		**Country:**	Canada
Approval Years:	2014	**Choice of Contact:**	CO_OFFICIAL
Contam. Facility:	No	**Co Admin:**	Dan Nolte
MHSW Facility:	No	**Phone No. Admin:**	905-335-6664 Ext.
SIC Code:	339950		
SIC Description:	SIGN MANUFACTURING		

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

---

11 | ***5 of 14*** | ***SE/75.3*** | ***121.9 / -1.91*** | ***JONES NEON DISPLAYS LIMITED*** | ***GEN***
1140 BLAIR ROAD
BURLINGTON ON L7M 1K9

Generator No.:	ON2208000	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	2009	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	339950		
SIC Description:	Sign Manufacturing		

--Details--

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

---

11 **6 of 14** **SE/75.3** **121.9 / -1.91** **JONES NEON DISPLAYS LIMITED** **GEN**
1140 BLAIR ROAD
BURLINGTON ON L7M 1K9

Generator No.: ON2208000
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 339950
SIC Description: SIGN MANUFACTURING

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Heather Jones
Phone No. Admin: 905-335-6664 Ext.

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

---

11 **7 of 14** **SE/75.3** **121.9 / -1.91** **JONES NEON DISPLAYS LIMITED** **GEN**
1140 BLAIR ROAD
BURLINGTON ON L7M 1K9

Generator No.: ON2208000
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 339950
SIC Description: Sign Manufacturing

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

---

11 **8 of 14** **SE/75.3** **121.9 / -1.91** **JONES NEON DISPLAYS LIMITED** **GEN**
1140 BLAIR ROAD
BURLINGTON ON L7M 1K9

Generator No.: ON2208000
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 339950
SIC Description: Sign Manufacturing

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

---

11 **9 of 14** **SE/75.3** **121.9 / -1.91** **JONES NEON DISPLAYS LIMITED** **GEN**
1140 BLAIR ROAD
BURLINGTON ON L7M 1K9

Generator No.: ON2208000

PO Box No.:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: **Country:**
Approval Years: 2012 **Choice of Contact:**
Contam. Facility: **Co Admin:**
MHSW Facility: **Phone No. Admin:**
SIC Code: 339950
SIC Description: Sign Manufacturing

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

---

11 ***10 of 14*** ***SE/75.3*** ***121.9 / -1.91*** ***JONES NEON DISPLAYS LIMITED*** ***GEN***
1140 BLAIR ROAD
BURLINGTON ON L7M 1K9

Generator No.: ON2208000 **PO Box No.:**
Status: **Country:**
Approval Years: 97,98,99,00,01,02,03,04,05,06,07,08 **Choice of Contact:**
Contam. Facility: **Co Admin:**
MHSW Facility: **Phone No. Admin:**
SIC Code: 3971
SIC Description: SIGN & DISPLAY IND.

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

---

11 ***11 of 14*** ***SE/75.3*** ***121.9 / -1.91*** ***JONES NEON DISPLAYS LIMITED*** ***GEN***
1140 BLAIR ROAD
BURLINGTON ON L7M 1K9

Generator No.: ON2208000 **PO Box No.:**
Status: Registered **Country:** Canada
Approval Years: As of Dec 2017 **Choice of Contact:**
Contam. Facility: **Co Admin:**
MHSW Facility: **Phone No. Admin:**
SIC Code:
SIC Description:

--Details--
Waste Code: 145 H
Waste Description: Wastes from the use of pigments, coatings and paints

---

11 ***12 of 14*** ***SE/75.3*** ***121.9 / -1.91*** ***JONES NEON DISPLAYS LIMITED*** ***GEN***
1140 BLAIR ROAD
BURLINGTON ON

Generator No.: ON2208000 **PO Box No.:**
Status: **Country:**
Approval Years: 2013 **Choice of Contact:**
Contam. Facility: **Co Admin:**
MHSW Facility: **Phone No. Admin:**
SIC Code: 339950
SIC Description: SIGN MANUFACTURING

--Details--
Waste Code: 145

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Description:		PAINT/PIGMENT/COATING RESIDUES			

11	13 of 14	SE/75.3	121.9 / -1.91	**Jones Neon Displays Ltd.** **1140 Blair Rd** **Burlington ON L7M 1K9**	SCT

Established: 01-SEP-41
Plant Size (ft²): 35000
Employment:

--Details--
Description: Showcase, Partition, Shelving and Locker Manufacturing
SIC/NAICS Code: 337215

Description: Sign Manufacturing
SIC/NAICS Code: 339950

Description: Sign Manufacturing
SIC/NAICS Code: 339950

Description: Service Establishment Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417920

11	14 of 14	SE/75.3	121.9 / -1.91	**BURLINGTON HYDRO-ELECTRIC COMM** **1140 BLAIR ROAD TRANSFORMER** **BURLINGTON CITY ON L7M 1K9**	SPL

Ref No:	197914	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	4/8/2001	**Client Type:**	
Year:		**Sector Type:**	
Incident Cause:	COOLING SYSTEM LEAK	**Source Type:**	
Incident Event:		**Nearest Watercourse:**	
Contaminant Code:		**Site Name:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site County/District:**	
Contaminant UN No 1:		**Site Postal Code:**	
Contaminant Qty:		**Site Region:**	
Environment Impact:	Possible	**Site Municipality:**	14101
Nature of Impact:	Soil contamination	**Site Lot:**	
Receiving Medium:	Land	**Site Conc:**	
Receiving Env:		**Northing:**	
Health/Env Conseq:		**Easting:**	
MOE Response:		**Site Geo Ref Accu:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Meth:**	
MOE Reported Dt:	4/8/2001	**Site Map Datum:**	
Dt Document Closed:			
SAC Action Class:			

Incident Reason: STORM, FLOOD
Incident Summary: BURLINGTON HYDRO:ROTTEN POLE BROKE DUE TO WIND 10 L NON PCB OIL TO SOIL

12	1 of 8	N/75.9	124.8 / 1.07	**690661 Ontario Limited** **3388 Mainway Drive** **Burlington ON L7M 1A8**	CA

Certificate #: 9175-5WJJNE
Application Year: 2004
Issue Date: 2/26/2004
Approval Type: Air

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: Approved
Application Type:
Client Name::
Client Address::
Client City::
Client Postal Code::
Project Description::
Contaminants::
Emission Control::

---

12 **2 of 8** **N/75.9** **124.8 / 1.07** **690661 Ontario Limited** **EBR**
3388 Mainway Drive Burlington Ontario L7M 1A8
Burlington
ON

EBR Registry No.: IA03E1045
Ministry Ref. No.: 3430-5PKLP3
Company Name: 690661 Ontario Limited
Notice Type: Instrument Decision
Notice Date: March 08, 2004
Proposal Date: July 23, 2003
Year: 2003
Proponent Address: 128 Queen Street South, Mississauga Ontario, L5M 4Z0
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:

Location:

3388 Mainway Drive Burlington Ontario L7M 1A8 Burlington

---

12 **3 of 8** **N/75.9** **124.8 / 1.07** **690661 Ontario Limited** **ECA**
3388 Mainway Drive
Burlington ON L7M 1A8

Approval No: 9175-5WJJNE
Approval Type: ECA-AIR
Status: Approved
Approval Date: 2004-02-26
Record Type: ECA
Project Type: AIR
Link Source: IDS
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3430-5PKLP3-14.pdf

MOE District: Halton-Peel
SWP Area Name: Halton
Address: 3388 Mainway Drive
City: Burlington
Longitude: -79.80024
Latitude: 43.367367

---

12 **4 of 8** **N/75.9** **124.8 / 1.07** **THOMAS WIRE DIE LIMITED** **37-113** **GEN**
P.O. BOX 352 3388 MAINWAY DRIVE
BURLINGTON ON L7M 1A8

Generator No.: ON0477400
Status:
Approval Years: 92,93,94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 3081
SIC Description: MACHINE SHOP IND.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

12 **5 of 8** **N/75.9** **124.8 / 1.07** **THOMAS WIRE DIE LIMITED** **GEN**
P.O. BOX 352 3388 MAINWAY DRIVE
BURLINGTON ON L7M 1A8

Generator No.: ON0477400
Status:
Approval Years: 86,87,88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 3081
SIC Description: MACHINE SHOP IND.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

12 **6 of 8** **N/75.9** **124.8 / 1.07** **CANFANCO INC.** **GEN**
3388 Mainway
Burlington ON L7M 1A8

Generator No.: ON9163541
Status:
Approval Years: 02,03,04
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

---

12 **7 of 8** **N/75.9** **124.8 / 1.07** **CANFANCO INC.** **SCT**
3388 Mainway Dr
Burlington ON L7M 1A8

Established: 1949
Plant Size (ft²): 24000
Employment: 10

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Description: Stamping
SIC/NAICS Code: 332118

Description: All Other Industrial Machinery Manufacturing
SIC/NAICS Code: 333299

---

12 | ***8 of 8*** | ***N/75.9*** | ***124.8 / 1.07*** | ***CANADIAN FANNER CO. LTD.***
3388 MAINWAY DR
BURLINGTON ON L7M 1A8 | ***SCT***

Established: 1949
Plant Size (ft²): 24000
Employment: 12

--Details--
Description: METAL STAMPINGS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3469

Description: INDUSTRIAL AND COMMERCIAL MACHINERY AND EQUIPMENT, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3599

---

13 | ***1 of 1*** | ***NW/77.8*** | ***124.8 / 1.07*** | ***3330 Mainway***
Burlington ON L7M1A7 | ***EHS***

Order ID:	366558	***Date Received:***	19-DEC-14
Order No:	20141219036	***Lot/Building Size:***	
Customer ID:	56847	***Municipality:***	
Company ID:	77	***Client Prov/State:***	ON
Status:	C	***Search Radius (km):***	.25
Report Code:	4CAN	***Large Radius:***	.5
Report Type:	Custom Report	***X:***	-79.800662
Report Date:	29-DEC-14	***Y:***	43.366291
Report Requested by:	Pinchin Ltd		
Nearest Intersection:			
Previous Site Name:			
Additional Info Ordered:			

---

14 | ***1 of 1*** | ***SW/78.6*** | ***123.8 / 0.00*** | ***BURLINGTON ON*** | ***WWIS***

Well ID:	7101370	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:	Monitoring	***Date Received:***	1/29/2008
Sec. Water Use:		***Selected Flag:***	1
Final Well Status:	Observation Wells	***Abandonment Rec:***	Yes
Water Type:		***Contractor:***	7282
Casing Material:		***Form Version:***	4
Audit No:	Z62828	***Owner:***	
Tag:	A055831	***Street Name:***	3230 MAINWAY RD.
Construction Method:		***County:***	HALTON
Elevation (m):		***Municipality:***	BURLINGTON CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	

Flow Rate:
Clear/Cloudy:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	1001483006	***Spatial Status:***	
DP2BR:		***Cluster Kind:***	
Code OB:		***UTMRC:***	3
Code OB Desc:		***UTMRC Desc:***	margin of error : 10 - 30 m
Open Hole:		***Location Method:***	wwr
Elevation:	123.466911	***Org CS:***	UTM83
Elevrc:		***Date Completed:***	11/6/2007
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1001537213
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	01
Most Common Material:	FILL
Mat2:	
Other Materials:	
Mat3:	77
Other Materials:	LOOSE
Formation Top Depth:	0.00
Formation End Depth:	0.50
Formation End Depth UOM:	m

Formation ID:	1001537214
Layer:	2
Color:	7
General Color:	RED
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Other Materials:	CLAY
Mat3:	73
Other Materials:	HARD
Formation Top Depth:	0.50
Formation End Depth:	5.40
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1001537216
Layer:	1
Plug From:	1.80
Plug To:	0.30
Plug Depth UOM:	m

Plug ID:	1001537217
Layer:	2
Plug From:	0.30

Plug To: 0.00
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1001537222
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1001537211
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1001537219
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 2.40
Casing Diameter: 0.05
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1001537220
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material: 5
Screen Depth UOM:
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1001537212
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code: 0
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing: N

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Water Details

Water ID: 1001537218
Layer: 1
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1001537215
Diameter: 20.60
Depth From:
Depth To: 5.40
Hole Depth UOM: m
Hole Diameter UOM: cm

---

15 | ***1 of 22*** | ***ENE/79.1*** | ***122.0 / -1.79*** | ***3400 Landmark Road Burlington ON L7M 1S8*** | ***CA***

Certificate #:
Application Year: 01
Issue Date: 4/25/01
Approval Type: Industrial air
Status: Cancelled
Application Type: New Certificate of Approval
Client Name:: Millcraft Systems Inc.
Client Address:: 3400 Landmark Road
Client City:: Burlington
Client Postal Code:: L7M 1S8
Project Description:: Installation of an exterior dust collector to control particulate emissions from the manufacturing of wood products. The flow rate from the baghouse will be 2.93 cubic metres per second. The baghouse has a capacity of 4.39 cubic metres and has a filter area of 12.26 cubic metres.
Contaminants::
Emission Control::

---

15 | ***2 of 22*** | ***ENE/79.1*** | ***122.0 / -1.79*** | ***Airmax Compressor Services Ltd. 3400 Landmark Rd Burlington ON L7M 1S8*** | ***CA***

Certificate #: 5389-7FPJ75
Application Year: 2008
Issue Date: 6/17/2008
Approval Type: Air
Status: Approved
Application Type:
Client Name::
Client Address::
Client City::
Client Postal Code::
Project Description::
Contaminants::
Emission Control::

---

15 | ***3 of 22*** | ***ENE/79.1*** | ***122.0 / -1.79*** | ***Airmax Compressor Services Ltd. 3400 Landmark Road Burlington Regional Municipality Of Halton L7M 1S8 CITY OF BURLINGTON ON*** | ***EBR***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

EBR Registry No.: 010-1295
Ministry Ref. No.: 2815-74ZQKW
Company Name: Airmax Compressor Services Ltd.
Notice Type: Instrument Decision
Notice Date: July 17, 2008
Proposal Date: August 07, 2007
Year: 2007
Proponent Address: 3400 Landmark Road , Unit 9, Burlington Ontario, Canada L7M 1S8
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:

Location:

3400 Landmark Road Burlington Regional Municipality Of Halton L7M 1S8 CITY OF BURLINGTON

15	*4 of 22*	*ENE/79.1*	*122.0 / -1.79*	***Millcraft Systems Inc.*** ***3400 Landmark Road Burlington Ontario L7M 1S8 Burlington*** ***ON***	***EBR***

EBR Registry No.: IA01E0407
Ministry Ref. No.: 2526-4UWSPK
Company Name: Millcraft Systems Inc.
Notice Type: Instrument Decision
Notice Date: April 25, 2001
Proposal Date: March 26, 2001
Year: 2001
Proponent Address: 3400 Landmark Road, Burlington Ontario, L7M 1S8
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:

Location:

3400 Landmark Road Burlington Ontario L7M 1S8 Burlington

15	*5 of 22*	*ENE/79.1*	*122.0 / -1.79*	***Airmax Compressor Services Ltd.*** ***3400 Landmark Rd*** ***Burlington ON L7M 1S8***	***ECA***

Approval No: 5389-7FPJ75
Approval Type: ECA-AIR
Status: Approved
Approval Date: 2008-06-17
Record Type: ECA
Project Type: AIR
Link Source: IDS
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2815-74ZQKW-13.pdf

MOE District: Halton-Peel
SWP Area Name: Halton
Address: 3400 Landmark Rd
City: Burlington
Longitude: -79.79763
Latitude: 43.366096

15	*6 of 22*	*ENE/79.1*	*122.0 / -1.79*	***3400 Landmark Road*** ***Burlington ON L7M 1S8***	***EHS***

Order ID: 198071
Order No: 20111111001
Customer ID: 81947
Company ID: 17921
Status: C
Report Code: 3CAN
Report Type: Standard Report

Date Received: 11/11/2011 9:10:20 AM
Lot/Building Size:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
Large Radius: 2
X: -79.797884

Report Date: 11/21/2011 **Y:** 43.36625
Report Requested by: Inspec-Sol Inc.
Nearest Intersection:
Previous Site Name:
Additional Info Ordered:

---

15 **7 of 22** **ENE/79.1** **122.0 / -1.79** **Airmax Compressor Services Ltd.** **GEN**
3400 Landmark Rd. Units 9 & 10
Burlington ON L7M 1S8

Generator No.: ON5474652 **PO Box No.:**
Status: **Country:**
Approval Years: 07,08 **Choice of Contact:**
Contam. Facility: **Co Admin:**
MHSW Facility: **Phone No. Admin:**
SIC Code: 811310
SIC Description: Commercial and Industrial Machinery and Equipment (except Automotive and Electronic) Repair and Maintenance

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

15 **8 of 22** **ENE/79.1** **122.0 / -1.79** **Airmax Compressor Services Ltd.** **GEN**
3400 Landmark Rd. Units 9 & 10
Burlington ON L7M 1S8

Generator No.: ON5474652 **PO Box No.:**
Status: **Country:**
Approval Years: 2011 **Choice of Contact:**
Contam. Facility: **Co Admin:**
MHSW Facility: **Phone No. Admin:**
SIC Code: 811310
SIC Description: Commercial and Industrial Machinery and Equipment (except Automotive and Electronic) Repair and Maintenance

--Details--
Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	9 of 22	ENE/79.1	122.0 / -1.79	Airmax Compressor Services Ltd. 3400 Landmark Rd. Units 9 & 10 Burlington ON L7M 1S8	GEN

Generator No.: ON5474652
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 811310
SIC Description: Commercial and Industrial Machinery and Equipment (except Automotive and Electronic) Repair and Maintenance

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	10 of 22	ENE/79.1	122.0 / -1.79	Airmax Compressor Services Ltd. 3400 Landmark Rd. Units 9 & 10 Burlington ON L7M 1S8	GEN

Generator No.: ON5474652
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 811310
SIC Description: Commercial and Industrial Machinery and Equipment (except Automotive and Electronic) Repair and Maintenance

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	11 of 22	ENE/79.1	122.0 / -1.79	L & A Diecrafts Ltd. 3400 Landmark Rd. #5-10	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Burlington ON L7M 1S8

Generator No.: ON6285414
Status:
Approval Years: 05
Contam. Facility:
MHSW Facility:
SIC Code: 339990
SIC Description: All Other Miscellaneous Manufacturing

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

15 ***12 of 22*** ***ENE/79.1*** ***122.0 / -1.79*** ***GEN***

Airmax Compressor Services Ltd.
3400 Landmark Rd. Units 9 & 10
Burlington ON L7M 1S8

Generator No.: ON5474652
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 811310
SIC Description: COMMERCIAL AND INDUSTRIAL MACHINERY AND EQUIPMENT (EXCEPT AUTOMOTIVE AND ELECTRONIC) REPAIR AND MAINTENANCE

PO Box No.:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Denise Wharton
Phone No. Admin: 905-681-6687 Ext.21

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

---

15 ***13 of 22*** ***ENE/79.1*** ***122.0 / -1.79*** ***GEN***

Ascona Management & Consulting Inc.
3400 Landmark Road Units 1 & 2
Burlington ON L7M 1S8

Generator No.: ON9705375
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 531310
SIC Description: Real Estate Property Managers

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	14 of 22	ENE/79.1	122.0 / -1.79	Airmax Compressor Services Ltd. 3400 Landmark Rd. Units 9 & 10 Burlington ON L7M 1S8	GEN

Generator No.: ON5474652
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country: Canada
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213 T
Waste Description: Petroleum distillates

Waste Code: 252 L
Waste Description: Waste crankcase oils and lubricants

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	15 of 22	ENE/79.1	122.0 / -1.79	Airmax Compressor Services Ltd. 3400 Landmark Rd. Units 9 & 10 Burlington ON L7M 1S8	GEN

Generator No.: ON5474652
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 811310
SIC Description: COMMERCIAL AND INDUSTRIAL MACHINERY AND EQUIPMENT (EXCEPT AUTOMOTIVE AND ELECTRONIC) REPAIR AND MAINTENANCE

PO Box No.:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Denise Wharton
Phone No. Admin: 905-681-6687 Ext.21

--Details--
Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	16 of 22	ENE/79.1	122.0 / -1.79	Airmax Compressor Services Ltd. 3400 Landmark Rd. Units 9 & 10 Burlington ON L7M 1S8	GEN

Generator No.: ON5474652
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 811310
SIC Description: COMMERCIAL AND INDUSTRIAL MACHINERY AND EQUIPMENT (EXCEPT AUTOMOTIVE AND

PO Box No.:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Denise Wharton
Phone No. Admin: 905-681-6687 Ext.21

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

ELECTRONIC) REPAIR AND MAINTENANCE

--Details--
Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	17 of 22	ENE/79.1	122.0 / -1.79	NATURAL TEMPTATIONS INC 3400 LANDMARK RD UNIT 4 BURLINGTON ON L7M 1S8	SCT

Established: 1965
Plant Size (ft²): 5800
Employment: 11

--Details--
Description: BREAD AND OTHER BAKERY PRODUCTS, EXCEPT COOKIES AND CRACKERS
SIC/NAICS Code: 2051

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	18 of 22	ENE/79.1	122.0 / -1.79	Natural Temptations Inc. 3400 Landmark Rd Unit 4 Burlington ON L7M 1S8	SCT

Established: 1947
Plant Size (ft²): 6000
Employment: 20

--Details--
Description: Commercial Bakeries and Frozen Bakery Product Manufacturing
SIC/NAICS Code: 311814

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	19 of 22	ENE/79.1	122.0 / -1.79	Millcraft Systems Inc. 3400 Landmark Rd Unit 1-2 Burlington ON L7M 1S8	SCT

Established: 1979
Plant Size (ft²): 10000
Employment: 7

--Details--
Description: Wood Window and Door Manufacturing
SIC/NAICS Code: 321911

Description: Other Millwork
SIC/NAICS Code: 321919

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	20 of 22	ENE/79.1	122.0 / -1.79	L & A DIECRAFTS LTD 3400 LANDMARK RD UNIT 5-10 BURLINGTON ON L7M 1S8	SCT

Established: 1976
Plant Size (ft²): 0
Employment: 15

--Details--
Description: DIE-CUT PAPER AND PAPERBOARD AND CARDBOARD
SIC/NAICS Code: 2675

Description: SIGNS AND ADVERTISING SPECIALTIES
SIC/NAICS Code: 3993

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	21 of 22	ENE/79.1	122.0 / -1.79	L & A Diecrafts Ltd. 3400 Landmark Rd Unit 5-10 Burlington ON L7M 1S8	SCT

Established: 1976
Plant Size (ft²):
Employment: 18

--Details--
Description: Stationery Product Manufacturing
SIC/NAICS Code: 322230

Description: Sign Manufacturing
SIC/NAICS Code: 339950

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	22 of 22	ENE/79.1	122.0 / -1.79	CANADIAN COUNTRY CANDLES 3400 LANDMARK RD UNIT 2 BURLINGTON ON L7M 1S8	SCT

Established: 1988
Plant Size (ft²): 0
Employment: 9

--Details--
Description: PRESSED AND BLOWN GLASS AND GLASSWARE, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3229

Description: POTTERY PRODUCTS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3269

Description: FABRICATED METAL PRODUCTS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3499

Description: SILVERWARE, PLATED WARE, AND STAINLESS STEELWARE
SIC/NAICS Code: 3914

Description: MANUFACTURING INDUSTRIES, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3999

Description: Pottery, Ceramics and Plumbing Fixture Manufacturing
SIC/NAICS Code: 327110

Description: Glass Manufacturing

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC/NAICS Code: 327214

Description: All Other Miscellaneous Fabricated Metal Product Manufacturing
SIC/NAICS Code: 332999

Description: Jewellery and Silverware Manufacturing
SIC/NAICS Code: 339910

Description: All Other Miscellaneous Manufacturing
SIC/NAICS Code: 339990

---

16 | ***1 of 22*** | ***SW/82.9*** | ***122.9 / -0.88*** | ***AUTOMOTIVE MANAGER BELL CANADA***
1171 PIONEER RD
BURLINGTON ON | ***EXP***

Instance No: 10633547
Instance ID: 31452
Instance Type: FS Piping
Description: FS Piping
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

16 | ***2 of 22*** | ***SW/82.9*** | ***122.9 / -0.88*** | ***AUTOMOTIVE MANAGER BELL CANADA***
1171 PIONEER RD
BURLINGTON ON | ***EXP***

Instance No: 9372294
Instance ID: 385880
Instance Type: FS Facility
Description: Fuels Safety Private Fuel Outlet - Self Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

16 | ***3 of 22*** | ***SW/82.9*** | ***122.9 / -0.88*** | ***AUTOMOTIVE MANAGER BELL CANADA***
1171 PIONEER RD
BURLINGTON ON | ***EXP***

Instance No: 11420168
Instance ID: 83806
Instance Type: FS Liquid Fuel Tank
Description: FS Liquid Fuel Tank
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

16 | ***4 of 22*** | ***SW/82.9*** | ***122.9 / -0.88*** | ***AUTOMOTIVE MANAGER BELL CANADA***
1171 PIONEER RD
BURLINGTON ON L7M 1K5 | ***EXP***

Instance No: 10633522
Instance ID:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance Type: FS Liquid Fuel Tank
Description:
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date: 12/8/1990

---

16 | **5 of 22** | **SW/82.9** | **122.9 / -0.88** | **AUTOMOTIVE MANAGER BELL CANADA**
1171 PIONEER RD
BURLINGTON ON | **EXP**

Instance No: 11420185
Instance ID: 83242
Instance Type: FS Piping
Description: FS Piping
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

16 | **6 of 22** | **SW/82.9** | **122.9 / -0.88** | **AUTOMOTIVE MANAGER BELL CANADA**
1171 PIONEER RD
BURLINGTON ON L7M 1K5 | **EXP**

Instance No: 10633522
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: Fuels Safety Private Fuel Outlet - Self Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 12/8/1990

---

16 | **7 of 22** | **SW/82.9** | **122.9 / -0.88** | **AUTOMOTIVE MANAGER BELL CANADA**
1171 PIONEER RD
BURLINGTON ON L7M 1K5 | **EXP**

Instance No: 11420168
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: Fuels Safety Private Fuel Outlet - Self Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 12/8/1990

---

16 | **8 of 22** | **SW/82.9** | **122.9 / -0.88** | **Bell Canada**
1171 Pioneer Rd
Burlington ON L7M 1K5 | **GEN**

Generator No.: ON0473703
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Julie Labelle
Phone No. Admin: 514-870-0688 Ext.

SIC Code: 517110, 517210, 517510
SIC Description: WIRED TELECOMMUNICATIONS CARRIERS, WIRELESS TELECOMMUNICATIONS CARRIERS (EXCEPT SATELLITE), 517510

--Details--
Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 331
Waste Description: WASTE COMPRESSED GASES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 131
Waste Description: NEUTRALIZED WASTES - HEAVY METALS

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

16	9 of 22	SW/82.9	122.9 / -0.88	BELL CANADA 05-525 1171 PIONEER RD., BURLINGTON C/O 20 NORELCO DRIVE NORTH YORK ON L7M 1K5	GEN

Generator No.: ON0473703
Status:
Approval Years: 94,95
Contam. Facility:
MHSW Facility:
SIC Code: 6351
SIC Description: GARAGES(GEN. REPAIR)

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252

Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 131
Waste Description: NEUTRALIZED WASTES - HEAVY METALS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

---

16 | **10 of 22** | **SW/82.9** | **122.9 / -0.88** | **Bell Canada**
1171 Pioneer Rd
Burlington ON L7M 1K5 | **GEN**

Generator No.: ON0473703
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 517110, 517210, 517510
SIC Description: WIRED TELECOMMUNICATIONS CARRIERS, WIRELESS TELECOMMUNICATIONS CARRIERS (EXCEPT SATELLITE), 517510

PO Box No.:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Julie Labelle
Phone No. Admin: 514-870-0688 Ext.

--Details--

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 331
Waste Description: WASTE COMPRESSED GASES

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 131
Waste Description: NEUTRALIZED WASTES - HEAVY METALS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
16	11 of 22	SW/82.9	122.9 / -0.88	BELL CANADA 1171 PIONEER RD. BURLINGTON ON L7M 1K5	GEN

Generator No.: ON0473703
Status:
Approval Years: 88,89
Contam. Facility:
MHSW Facility:
SIC Code: 6351
SIC Description: GARAGES(GEN. REPAIR)

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 131
Waste Description: NEUTRALIZED WASTES - HEAVY METALS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
16	12 of 22	SW/82.9	122.9 / -0.88	BELL CANADA 1171 PIONEER ROAD BURLINGTON ON L7M 1K5	GEN

Generator No.: ON0473703
Status:
Approval Years: 92,93,97,98,99,00,01,02,03,04,05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code: 6351
SIC Description: GARAGES(GEN. REPAIR)

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 131
Waste Description: NEUTRALIZED WASTES - HEAVY METALS

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES

Waste Code: 331
Waste Description: WASTE COMPRESSED GASES

---

16 | ***13 of 22*** | ***SW/82.9*** | ***122.9 / -0.88*** | ***Bell Canada***
1171 Pioneer Rd
Burlington ON L7M 1K5 | ***GEN***

Generator No.: ON0473703
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 517110, 517210, 517510
SIC Description: Wired Telecommunications Carriers, Wireless Telecommunications Carriers (except Satellite), Cable and Other Program Distribution

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 131
Waste Description: NEUTRALIZED WASTES - HEAVY METALS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES

Waste Code: 331

Waste Description: WASTE COMPRESSED GASES

---

16 | ***14 of 22*** | ***SW/82.9*** | ***122.9 / -0.88*** | ***Bell Canada*** | ***GEN***
1171 Pioneer Rd
Burlington ON L7M 1K5

Generator No.:	ON0473703	***PO Box No.:***	
Status:		***Country:***	
Approval Years:	2011	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No. Admin:***	

SIC Code: 517110, 517210, 517510
SIC Description: Wired Telecommunications Carriers, Wireless Telecommunications Carriers (except Satellite), Cable and Other Program Distribution

--Details--

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 331
Waste Description: WASTE COMPRESSED GASES

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES

Waste Code: 131
Waste Description: NEUTRALIZED WASTES - HEAVY METALS

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

---

16 | ***15 of 22*** | ***SW/82.9*** | ***122.9 / -0.88*** | ***Bell Canada*** | ***GEN***
1171 Pioneer Rd
Burlington ON L7M 1K5

Generator No.:	ON0473703	***PO Box No.:***	
Status:		***Country:***	
Approval Years:	2010	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No. Admin:***	

SIC Code: 517110, 517210, 517510
SIC Description: Wired Telecommunications Carriers, Wireless Telecommunications Carriers (except Satellite), Cable and Other Program Distribution

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 331
Waste Description: WASTE COMPRESSED GASES

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 131
Waste Description: NEUTRALIZED WASTES - HEAVY METALS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

---

16 | **16 of 22** | **SW/82.9** | **122.9 / -0.88** | **Bell Canada**
1171 Pioneer Rd
Burlington ON L7M 1K5 | **GEN**

Generator No.: ON0473703
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country: Canada
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 251 L
Waste Description: Waste oils/sludges (petroleum based)

Waste Code: 145 L
Waste Description: Wastes from the use of pigments, coatings and paints

Waste Code: 212 L
Waste Description: Aliphatic solvents and residues

Waste Code: 121 C
Waste Description: Alkaline slutions - containing heavy metals

Waste Code: 252 L
Waste Description: Waste crankcase oils and lubricants

Waste Code: 213 I
Waste Description: Petroleum distillates

Waste Code: 331 I
Waste Description: Waste compressed gases including cylinders

Waste Code: 251 T
Waste Description: Waste oils/sludges (petroleum based)

---

16 | **17 of 22** | **SW/82.9** | **122.9 / -0.88** | **Bell Canada**
1171 Pioneer Rd
Burlington ON L7M 1K5 | **GEN**

Generator No.: ON0473703
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 517110, 517210, 517510
SIC Description: WIRED TELECOMMUNICATIONS CARRIERS, WIRELESS TELECOMMUNICATIONS CARRIERS (EXCEPT SATELLITE), 517510

PO Box No.:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Chloé Lamothe-Luneau
Phone No. Admin: 514-391-1021 Ext.

--Details--

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 331
Waste Description: WASTE COMPRESSED GASES

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 131
Waste Description: NEUTRALIZED WASTES - HEAVY METALS

---

16 **18 of 22** **SW/82.9** **122.9 / -0.88** **Bell Canada** **GEN**
1171 Pioneer Rd
Burlington ON L7M 1K5

Generator No.: ON0473703
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 517110, 517210, 517510
SIC Description: Wired Telecommunications Carriers, Wireless Telecommunications Carriers (except Satellite), Cable and Other Program Distribution

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--

Waste Code: 131
Waste Description: NEUTRALIZED WASTES - HEAVY METALS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 331
Waste Description: WASTE COMPRESSED GASES

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

---

16 **19 of 22** **SW/82.9** **122.9 / -0.88** **BELL CANADA** **GEN**
1171 PIONEER RD., BURLINGTON C/O 483 BAY
ST. FL. 6 S. TOWER
TORONTO ON L7M 1K5

Generator No.: ON0473703
Status:
Approval Years: 90

PO Box No.:
Country:
Choice of Contact:

Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No. Admin:***
SIC Code: 6351
SIC Description: GARAGES(GEN. REPAIR)

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 131
Waste Description: NEUTRALIZED WASTES - HEAVY METALS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

16 ***20 of 22*** ***SW/82.9*** ***122.9 / -0.88*** ***BELL CANADA*** ***05-525*** ***GEN***
1171 PIONEER ROAD
BURLINGTON ON L7M 1K5

Generator No.: ON0473703 ***PO Box No.:***
Status: ***Country:***
Approval Years: 96 ***Choice of Contact:***
Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No. Admin:***
SIC Code: 6351
SIC Description: GARAGES(GEN. REPAIR)

--Details--
Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 131
Waste Description: NEUTRALIZED WASTES - HEAVY METALS

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 331

Waste Description: WASTE COMPRESSED GASES

---

16 | **21 of 22** | **SW/82.9** | **122.9 / -0.88** | **Bell Canada**
1171 Pioneer Rd
Burlington ON | **GEN**

Generator No.: ON0473703
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 517110, 517210, 517510
SIC Description: WIRED TELECOMMUNICATIONS CARRIERS, WIRELESS TELECOMMUNICATIONS CARRIERS (EXCEPT SATELLITE)

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 131
Waste Description: NEUTRALIZED WASTES - HEAVY METALS

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 331
Waste Description: WASTE COMPRESSED GASES

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES

---

16 | **22 of 22** | **SW/82.9** | **122.9 / -0.88** | **AUTOMOTIVE MANAGER BELL CANADA**
1171 PIONEER RD
BURLINGTON ON L7M 1K5 | **PRT**

Location ID: 2468
Type: private
Expiry Date:
Capacity (L): 25000.00
Licence #: 0001046484

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	1 of 49	SSW/88.5	121.8 / -1.93	Canadian Hazmat & Decon Services Inc. 1153 Pioneer Rd Burlington ON L7M 1K5	CA

Certificate #: 3651-7FRR7Z
Application Year: 2008
Issue Date: 7/3/2008
Approval Type: Waste Management Systems
Status: Approved
Application Type:
Client Name::
Client Address::
Client City::
Client Postal Code::
Project Description::
Contaminants::
Emission Control::

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	2 of 49	SSW/88.5	121.8 / -1.93	Canadian Hazmat & Decon Services Inc. 1153 Pioneer Rd Burlington ON L7M 1K5	ECA

Approval No: 3651-7FRR7Z
Approval Type: ECA-WASTE MANAGEMENT SYSTEMS
Status: Approved
Approval Date: 2008-07-03
Record Type: ECA
Project Type: WASTE MANAGEMENT SYSTEMS
Link Source: IDS
Full Address:
MOE District: Halton-Peel
SWP Area Name: Halton
Address: 1153 Pioneer Rd
City: Burlington
Longitude: -79.8006499999999
Latitude: 43.363758
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2471-7DJQ25-14.pdf

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	3 of 49	SSW/88.5	121.8 / -1.93	1153 Pioneer Road Burlington ON	EHS

Order ID: 547760
Order No: 20171126002
Customer ID: 121408
Company ID: 289
Status: C
Report Code: 27CAN
Report Type: Standard Express Report
Report Date: 26-NOV-17
Report Requested by: Hemmera
Nearest Intersection:
Previous Site Name:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; City Directory
Date Received: 26-NOV-17
Lot/Building Size:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
Large Radius: 2
X: -79.800729
Y: 43.363976

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	4 of 49	SSW/88.5	121.8 / -1.93	BCG PRECISION GRINDING AND HONING INC 1153 Pioneer Road Unit 10 Burlington ON L7M 1K5	GEN

Generator No.: ON2677300
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 332710
PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Laura M James
Phone No. Admin: 9053355038 Ext.

SIC Description: MACHINE SHOPS

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

17 **5 of 49** **SSW/88.5** **121.8 / -1.93**

MILL PACK INDUSTRIAL MAINTENANCE INC.
1153 PIONEER ROAD, UNIT 7
BURLINGTON ON L7M 1K5

GEN

Generator No.: ON7232747
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 332710
SIC Description: MACHINE SHOPS

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

17 **6 of 49** **SSW/88.5** **121.8 / -1.93**

MILL PACK INDUSTRIAL MAINTENANCE INC.
1153 PIONEER ROAD, UNIT 7
BURLINGTON ON

GEN

Generator No.: ON7232747
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 332710
SIC Description: Machine Shops

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

---

17 **7 of 49** **SSW/88.5** **121.8 / -1.93**

BURLINGTON CENTERLESS GRINDING
1153 PIONEER ROAD, UNIT 10
BURLINGTON ON L7M 1K5

GEN

Generator No.: ON2677300
Status:
Approval Years: 01
Contam. Facility:
MHSW Facility:
SIC Code: 3081
SIC Description: MACHINE SHOP IND.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

17 **8 of 49** **SSW/88.5** **121.8 / -1.93**

BURLINGTON CENTERLESS GRINDING
1153 Pioneer Road Unit 10
Burlington ON L7M 1K5

GEN

Generator No.: ON2677300
Status:

PO Box No.:
Country:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Years: 02,03,04,05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

17 **9 of 49** **SSW/88.5** **121.8 / -1.93** **K.C. GRAPHICS**
1153 PIONEER RD. UNIT F
BURLINGTON ON L7M 1K5
GEN

Generator No.: ON1253200
Status:
Approval Years: 89,99
Contam. Facility:
MHSW Facility:
SIC Code: 2819
SIC Description: OTHER COMM. PRINTING
PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

---

17 **10 of 49** **SSW/88.5** **121.8 / -1.93** **MACHINERY REPAIR TECHNOLOGIES**
1153 PIONEER ROAD, UNIT K
BURLINGTON ON L7M 1K5
GEN

Generator No.: ON2317200
Status:
Approval Years: 04
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

---

17 **11 of 49** **SSW/88.5** **121.8 / -1.93** **931344 ontario inc.**
1153 -H PIONEER RD
BURLINGTON ON L7M 1K5
GEN

Generator No.: ON7019664
Status:
Approval Years: 02,03,04
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	12 of 49	SSW/88.5	121.8 / -1.93	BCG PRECISION GRINDING AND HONING INC 1153 Pioneer Road Unit 10 Burlington ON L7M 1K5	GEN

Generator No.: ON2677300
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country: Canada
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252 L
Waste Description: Waste crankcase oils and lubricants

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	13 of 49	SSW/88.5	121.8 / -1.93	BURLINGTON CENTERLESS GRINDING 1153 Pioneer Road Unit 10 Burlington ON L7M 1K5	GEN

Generator No.: ON2677300
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 332710
SIC Description: Machine Shops

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	14 of 49	SSW/88.5	121.8 / -1.93	CANADIAN INDUCTION PROCESSING INC 1153 PIONEER ROAD, UNIT #6 BURLINGTON ON L7M 1K5	GEN

Generator No.: ON0268200
Status:
Approval Years: 97
Contam. Facility:
MHSW Facility:
SIC Code: 3099
SIC Description: OTHER METAL FAB. IND.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 253
Waste Description: EMULSIFIED OILS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	15 of 49	SSW/88.5	121.8 / -1.93	CANADIAN INDUCTION PROCESSING INC.08-020 1153 PIONEER ROAD, UNIT #6 BURLINGTON ON L7M 1K5	GEN

Generator No.: ON0268200

PO Box No.:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: **Country:**
Approval Years: 92,93,94,95,96 **Choice of Contact:**
Contam. Facility: **Co Admin:**
MHSW Facility: **Phone No. Admin:**
SIC Code: 3099
SIC Description: OTHER METAL FAB. IND

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

17 **16 of 49** **SSW/88.5** **121.8 / -1.93** **K.C. GRAPHICS** **GEN**
1153 PIONEER ROAD, UNIT F
BURLINGTON ON L7M 1K5

Generator No.: ON1253200 **PO Box No.:**
Status: **Country:**
Approval Years: 00,01 **Choice of Contact:**
Contam. Facility: **Co Admin:**
MHSW Facility: **Phone No. Admin:**
SIC Code: 2819
SIC Description: OTHER COMM. PRINTING

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

---

17 **17 of 49** **SSW/88.5** **121.8 / -1.93** **MILL PACK INDUSTRIAL MAINTENANCE INC.** **GEN**
1153 PIONEER ROAD, UNIT 7
BURLINGTON ON L7M 1K5

Generator No.: ON7232747 **PO Box No.:**
Status: Registered **Country:** Canada
Approval Years: As of Dec 2017 **Choice of Contact:**
Contam. Facility: **Co Admin:**
MHSW Facility: **Phone No. Admin:**
SIC Code:
SIC Description:

--Details--
Waste Code: 252 L
Waste Description: Waste crankcase oils and lubricants

---

17 **18 of 49** **SSW/88.5** **121.8 / -1.93** **K.C. GRAPHICS** **23-422** **GEN**
1153 PIONEER RD. UNIT F
BURLINGTON ON L7M 1K5

Generator No.: ON1253200 **PO Box No.:**
Status: **Country:**
Approval Years: 92,93,94,95,96,97,98 **Choice of Contact:**
Contam. Facility: **Co Admin:**
MHSW Facility: **Phone No. Admin:**
SIC Code: 2819
SIC Description: OTHER COMM. PRINTING

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

---

17 ***19 of 49*** ***SSW/88.5*** ***121.8 / -1.93*** ***BCG PRECISION GRINDING AND HONING INC*** ***GEN***
1153 Pioneer Road Unit 10
Burlington ON L7M 1K5

Generator No.: ON2677300
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 332710
SIC Description: MACHINE SHOPS

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Laura M James
Phone No. Admin: 9053355038 Ext.

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

17 ***20 of 49*** ***SSW/88.5*** ***121.8 / -1.93*** ***BURLINGTON CENTERLESS GRINDING*** ***GEN***
1153 Pioneer Road Unit 10
Burlington ON L7M 1K5

Generator No.: ON2677300
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 332710
SIC Description: Machine Shops

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

17 ***21 of 49*** ***SSW/88.5*** ***121.8 / -1.93*** ***CANADIAN INDUCTION PROCESSING INC*** ***GEN***
1153 PIONEER RD. UNIT #6
BURLINGTON ON L7M 1K5

Generator No.: ON0268200
Status:
Approval Years: 86,87,88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 3099
SIC Description: OTHER METAL FAB. IND.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

---

17 ***22 of 49*** ***SSW/88.5*** ***121.8 / -1.93*** ***BURLINGTON CENTERLESS GRINDING*** ***GEN***
1153 Pioneer Road Unit 10
Burlington ON L7M 1K5

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No.: ON2677300
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 332710
SIC Description: Machine Shops

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

17 | **23 of 49** | **SSW/88.5** | **121.8 / -1.93**

BURLINGTON CENTERLESS GRINDING
1153 Pioneer Road Unit 10
Burlington ON L7M 1K5

GEN

Generator No.: ON2677300
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 332710
SIC Description: Machine Shops

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

17 | **24 of 49** | **SSW/88.5** | **121.8 / -1.93**

MILL PACK INDUSTRIAL MAINTENANCE INC.
1153 PIONEER ROAD, UNIT 7
BURLINGTON ON L7M 1K5

GEN

Generator No.: ON7232747
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 332710
SIC Description: MACHINE SHOPS

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

17 | **25 of 49** | **SSW/88.5** | **121.8 / -1.93**

CANADIAN INDUCTION PROCESSING INC.
1153 PIONEER ROAD, UNIT #6
BURLINGTON ON L7M 1K5

GEN

Generator No.: ON0268200
Status:
Approval Years: 98,99
Contam. Facility:
MHSW Facility:
SIC Code: 3099
SIC Description: OTHER METAL FAB. IND.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

17 ***26 of 49*** ***SSW/88.5*** ***121.8 / -1.93*** ***CANADIAN I(OUT OF BUSINESS)NG INC.*** ***GEN***
1153 PIONEER ROAD, UNIT #6
BURLINGTON ON L7M 1K5

Generator No.: ON0268200
Status:
Approval Years: 00,01
Contam. Facility:
MHSW Facility:
SIC Code: 3099
SIC Description: OTHER METAL FAB. IND.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

17 ***27 of 49*** ***SSW/88.5*** ***121.8 / -1.93*** ***MACHINERY REPAIR TECHNOLOGIES*** ***GEN***
1153 PIONEER ROAD, UNIT K
BURLINGTON ON L7M 1K5

Generator No.: ON2317200
Status:
Approval Years: 97,98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 3081
SIC Description: MACHINE SHOP IND.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

17 ***28 of 49*** ***SSW/88.5*** ***121.8 / -1.93*** ***BCG PRECISION GRINDING AND HONING INC*** ***GEN***
1153 Pioneer Road Unit 10
Burlington ON L7M 1K5

Generator No.: ON2677300
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 332710
SIC Description: MACHINE SHOPS

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Laura M James
Phone No. Admin: 9053355038 Ext.

--Details--

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

17 **29 of 49** **SSW/88.5** **121.8 / -1.93**

MILL PACK INDUSTRIAL MAINTENANCE INC.
1153 PIONEER ROAD, UNIT 7
BURLINGTON ON L7M 1K5

GEN

Generator No.: ON7232747
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 332710
SIC Description: MACHINE SHOPS

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

17 **30 of 49** **SSW/88.5** **121.8 / -1.93**

MACHINERY REPAIR TECHNOLOGIES
1153 PIONEER ROAD, UNIT K
BURLINGTON ON L7M 1K5

GEN

Generator No.: ON2317200
Status:
Approval Years: 02,03
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

---

17 **31 of 49** **SSW/88.5** **121.8 / -1.93**

BCG PRECISION GRINDING AND HONING INC
1153 Pioneer Road Unit 10
Burlington ON

GEN

Generator No.: ON2677300
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 332710
SIC Description: MACHINE SHOPS

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

17 **32 of 49** **SSW/88.5** **121.8 / -1.93**

MILL PACK INDUSTRIAL MAINTENANCE INC.
1153 PIONEER ROAD, UNIT 7
BURLINGTON ON

GEN

Generator No.: ON7232747
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 332710

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description: MACHINE SHOPS

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

17 | ***33 of 49*** | ***SSW/88.5*** | ***121.8 / -1.93*** | ***K C GRAPHICS***
1153 Pioneer Rd Unit F
Burlington ON L7M 1K5 | ***SCT***

Established: 1985
Plant Size (ft²): 0
Employment: 1

--Details--
Description: Textile and Fabric Finishing
SIC/NAICS Code: 313310

---

17 | ***34 of 49*** | ***SSW/88.5*** | ***121.8 / -1.93*** | ***HOMEMADE WINE CRAFTS CANADA***
1153 Pioneer Rd Unit E
Burlington ON L7M 1K5 | ***SCT***

Established: 1976
Plant Size (ft²): 0
Employment: 2

--Details--
Description: Doll, Toy and Game Manufacturing
SIC/NAICS Code: 339930

---

17 | ***35 of 49*** | ***SSW/88.5*** | ***121.8 / -1.93*** | ***M. I. R. Fabric Products***
1153 Pioneer Rd Unit L
Burlington ON L7M 1K5 | ***SCT***

Established:
Plant Size (ft²):
Employment:

--Details--
Description: All Other Miscellaneous Manufacturing
SIC/NAICS Code: 339990

Description: Material Handling Equipment Manufacturing
SIC/NAICS Code: 333920

Description: All Other General-Purpose Machinery Manufacturing
SIC/NAICS Code: 333990

Description: All Other Miscellaneous Fabricated Metal Product Manufacturing
SIC/NAICS Code: 332999

Description: Medical Equipment and Supplies Manufacturing
SIC/NAICS Code: 339110

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	36 of 49	SSW/88.5	121.8 / -1.93	LASER F/X INTERNATIONAL 1153 Pioneer Rd Unit P Burlington ON L7M 1K5	SCT

Established: 1975
Plant Size (ft²): 0
Employment: 2

--Details--
Description: Periodical Publishers
SIC/NAICS Code: 511120

Description: Database and Directory Publishers
SIC/NAICS Code: 511140

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	37 of 49	SSW/88.5	121.8 / -1.93	ORGANIZERS PLUS 1153 PIONEER RD UNIT K BURLINGTON ON L7M 1K5	SCT

Established: 1986
Plant Size (ft²): 1200
Employment: 3

--Details--
Description: MILLWORK
SIC/NAICS Code: 2431

Description: WOOD KITCHEN CABINETS
SIC/NAICS Code: 2434

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	38 of 49	SSW/88.5	121.8 / -1.93	BURLINGTON CENTRELESS GRINDING 1153 PIONEER RD BURLINGTON ON L7M 1K5	SCT

Established: 1969
Plant Size (ft²): 0
Employment: 5

--Details--
Description: INDUSTRIAL & COMMERCIAL MACHINERY & EQUIPMENT, N.E.C.
SIC/NAICS Code: 3599

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	39 of 49	SSW/88.5	121.8 / -1.93	All Racking and Conveyors 1153 Pioneer Rd Unit 2 Burlington ON L7M 1K5	SCT

Established: 1997
Plant Size (ft²): 9500
Employment: 4

--Details--
Description: Showcase, Partition, Shelving and Locker Manufacturing
SIC/NAICS Code: 337215

Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: Other Ornamental and Architectural Metal Products Manufacturing
SIC/NAICS Code: 332329

Description: All Other Miscellaneous Fabricated Metal Product Manufacturing
SIC/NAICS Code: 332999

Description: Material Handling Equipment Manufacturing
SIC/NAICS Code: 333920

17	40 of 49	SSW/88.5	121.8 / -1.93	**Homemade Wine Crafts Canada Ltd.** **1153 Pioneer Rd Unit E** **Burlington ON L7M 1K5**	SCT

Established: 1976
Plant Size (ft²):
Employment: 2

17	41 of 49	SSW/88.5	121.8 / -1.93	**Downtown Signs** **1153 Pioneer Rd Unit J** **Burlington ON L7M 1K5**	SCT

Established: 1993
Plant Size (ft²): 1200
Employment:

--Details--
Description: Other Metal Container Manufacturing
SIC/NAICS Code: 332439

Description: Sign Manufacturing
SIC/NAICS Code: 339950

17	42 of 49	SSW/88.5	121.8 / -1.93	**HOMEMADE WINE CRAFTS LTD** **1153 PIONEER RD UNIT E** **BURLINGTON ON L7M 1K5**	SCT

Established: 1976
Plant Size (ft²): 0
Employment: 2

--Details--
Description: MANUFACTURING INDUSTRIES, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3999

17	43 of 49	SSW/88.5	121.8 / -1.93	**Brant Custom Grinding Limited** **1153 Pioneer Rd Unit 11** **Burlington ON L7M 1K5**	SCT

Established: 01-AUG-88
Plant Size (ft²):
Employment:

--Details--
Description: Coating, Engraving, Heat Treating and Allied Activities
SIC/NAICS Code: 332810

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: Machine Shops
SIC/NAICS Code: 332710

Description: Other Plate Work and Fabricated Structural Product Manufacturing
SIC/NAICS Code: 332319

---

17 | 44 of 49 | SSW/88.5 | 121.8 / -1.93 | **CANADIAN INDUCTION PROCESSING**
1153 PIONEER RD UNIT 4-6
BURLINGTON ON L7M 1K5 | SCT

Established: 1979
Plant Size (ft²): 0
Employment: 10

--Details--
Description: METAL HEAT TREATING
SIC/NAICS Code: 3398

Description: Coating, Engraving, Heat Treating and Allied Activities
SIC/NAICS Code: 332810

---

17 | 45 of 49 | SSW/88.5 | 121.8 / -1.93 | **WORLD WIDE KILN SERVICE**
1153 PIONEER RD UNIT 7
BURLINGTON ON L7M 1K5 | SCT

Established: 1990
Plant Size (ft²): 0
Employment: 5

--Details--
Description: INDUSTRIAL PROCESS FURNACES AND OVENS
SIC/NAICS Code: 3567

Description: INDUSTRIAL MACHINERY AND EQUIPMENT
SIC/NAICS Code: 5084

Description: All Other General-Purpose Machinery Manufacturing
SIC/NAICS Code: 333990

---

17 | 46 of 49 | SSW/88.5 | 121.8 / -1.93 | **EXOTIC SIGNS**
1153 PIONEER RD UNIT J
BURLINGTON ON L7M 1K5 | SCT

Established: 1993
Plant Size (ft²): 0
Employment: 3

--Details--
Description: SIGNS AND ADVERTISING SPECIALTIES
SIC/NAICS Code: 3993

---

17 | 47 of 49 | SSW/88.5 | 121.8 / -1.93 | **K. C. GRAPHICS**
1153 PIONEER RD
BURLINGTON ON L7M 1K5 | SCT

Established: 1984

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Plant Size (ft²): 1850
Employment: 3

--Details--
Description: WOMEN'S, CHILDREN'S, & INFANTS' CLOTHING & ACCESSORIES
SIC/NAICS Code: 5137

Description: AUTOMOTIVE TRIMMINGS & RELATED PRODUCTS
SIC/NAICS Code: 2396

Description: MEN'S & BOYS' CLOTHING & FURNISHINGS
SIC/NAICS Code: 5136

17	48 of 49	SSW/88.5	121.8 / -1.93	LASER F X INTERNATIONAL 1153 PIONEER RD UNIT P BURLINGTON ON L7M 1K5	SCT

Established: 1975
Plant Size (ft²): 0
Employment: 1

--Details--
Description: MISCELLANEOUS PUBLISHING
SIC/NAICS Code: 2741

17	49 of 49	SSW/88.5	121.8 / -1.93	Burlington Centerless Grinding 1153 Pioneer Rd Unit 10 Burlington ON L7M 1K5	SCT

Established: 01-JUL-69
Plant Size (ft²):
Employment:

--Details--
Description: Coating, Engraving, Heat Treating and Allied Activities
SIC/NAICS Code: 332810

Description: Machine Shops
SIC/NAICS Code: 332710

Description: Coating, Engraving, Heat Treating and Allied Activities
SIC/NAICS Code: 332810

18	1 of 6	N/91.3	124.8 / 1.07	CHEM SYSTEMS INCORPORATED 3390 MAINWAY DRIVE BURLINGTON ON L7M 1A8	GEN

Generator No.: ON2340100
Status:
Approval Years: 97,98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 3099
SIC Description: OTHER METAL FAB. IND.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213

Waste Description: PETROLEUM DISTILLATES

---

18 **2 of 6** **N/91.3** **124.8 / 1.07** **CHEM SYSTEMS INC.** **GEN**
3390 MAINWAY DRIVE
BURLINGTON ON L7M 1A8

Generator No.: ON2340100
Status:
Approval Years: 02,03
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

---

18 **3 of 6** **N/91.3** **124.8 / 1.07** **HAYWARD GORDON LTD.** **GEN**
3390 MAINWAY DRIVE
BURLINGTON ON L7M 1A8

Generator No.: ON2340100
Status:
Approval Years: 04,05,06
Contam. Facility:
MHSW Facility:
SIC Code: 325999
SIC Description: All Other Miscellaneous Chemical Product Manufacturing

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 331
Waste Description: WASTE COMPRESSED GASES

Waste Code: 232
Waste Description: POLYMERIC RESINS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

18 **4 of 6** **N/91.3** **124.8 / 1.07** **Hayward Gordon Ltd.** **SCT**
3390 Mainway
Burlington ON L7M 1A8

Established: 1992
Plant Size (ft²):
Employment: 80

--Details--
Description: All Other Industrial Machinery Manufacturing
SIC/NAICS Code: 333299

Description: Material Handling Equipment Manufacturing
SIC/NAICS Code: 333920

Description: All Other General-Purpose Machinery Manufacturing
SIC/NAICS Code: 333990

---

18 ***5 of 6*** ***N/91.3*** ***124.8 / 1.07*** ***CHEM SYSTEMS INC.***
3390 MAINWAY DR
BURLINGTON ON L7M 1A8 ***SCT***

Established: 1992
Plant Size (ft²): 0
Employment: 10

--Details--
Description: SPECIAL INDUSTRY MACHINERY, N.E.C.
SIC/NAICS Code: 3559

---

18 ***6 of 6*** ***N/91.3*** ***124.8 / 1.07*** ***CHEM SYSTEMS INC.***
3390 MAINWAY
BURLINGTON ON L7M 1A8 ***SCT***

Established: 1992
Plant Size (ft²): 0
Employment: 10

--Details--
Description: SPECIAL INDUSTRY MACHINERY, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3559

Description: All Other Industrial Machinery Manufacturing
SIC/NAICS Code: 333299

Description: Material Handling Equipment Manufacturing
SIC/NAICS Code: 333920

Description: All Other General-Purpose Machinery Manufacturing
SIC/NAICS Code: 333990

---

19 ***1 of 1*** ***NE/91.9*** ***123.6 / -0.14*** ***Burlington ON*** ***WWIS***

Well ID:	7155584	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:	Monitoring	***Date Received:***	12/8/2010
Sec. Water Use:		***Selected Flag:***	1
Final Well Status:	Test Hole	***Abandonment Rec:***	
Water Type:		***Contractor:***	6607
Casing Material:		***Form Version:***	5
Audit No:	M07344	***Owner:***	
Tag:	A100987	***Street Name:***	LANDMARK ROAD & BLAIR ROAD
Construction Method:		***County:***	HALTON
Elevation (m):		***Municipality:***	BURLINGTON CITY

Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1006146954
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation:
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: WWR
Org CS: UTM83
Date Completed: 9/22/2010

Annular Space/Abandonment Sealing Record

Plug ID: 1006146958
Layer:
Plug From:
Plug To:
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1006146957
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1006146959
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006146961
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.50
Casing Diameter:
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID:	1006146960
Layer:	1
Slot:	
Screen Top Depth:	4.50
Screen End Depth:	7.60
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	

Results of Well Yield Testing

Pump Test ID:	1006146962
Pump Set At:	
Static Level:	5.80
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1006146956
Diameter:	15.00
Depth From:	
Depth To:	7.60
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1006146981	***Spatial Status:***	
DP2BR:		***Cluster Kind:***	This is a record from cluster log sheet
Code OB:		***UTMRC:***	3
Code OB Desc:		***UTMRC Desc:***	margin of error : 10 - 30 m
Open Hole:		***Location Method:***	WWR
Elevation:		***Org CS:***	UTM83
Elevrc:		***Date Completed:***	9/22/2010
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1006146985

Layer:
Plug From:
Plug To:
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1006146984
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1006146986
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006146988
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.50
Casing Diameter:
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1006146987
Layer: 1
Slot:
Screen Top Depth: 4.50
Screen End Depth: 7.60
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1006146989
Pump Set At:
Static Level: 5.60
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID:	1006146983
Diameter:	15.00
Depth From:	
Depth To:	7.60
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1006146972	***Spatial Status:***	
DP2BR:		***Cluster Kind:***	This is a record from cluster log sheet
Code OB:		***UTMRC:***	3
Code OB Desc:		***UTMRC Desc:***	margin of error : 10 - 30 m
Open Hole:		***Location Method:***	WWR
Elevation:		***Org CS:***	UTM83
Elevrc:		***Date Completed:***	9/22/2010
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1006146976
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1006146975
Method Construction Code:	
Method Construction:	
Other Method Construction:	BORING

Pipe Information

Pipe ID:	1006146977
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006146979
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	4.50
Casing Diameter:	
Casing Diameter UOM:	cm

Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1006146978
Layer: 1
Slot:
Screen Top Depth: 4.50
Screen End Depth: 7.60
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1006146980
Pump Set At:
Static Level: 5.60
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1006146974
Diameter: 15.00
Depth From:
Depth To: 7.60
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1006146945
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation:
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: WWR
Org CS: UTM83
Date Completed: 9/22/2010

Annular Space/Abandonment Sealing Record

Plug ID: 1006146949
Layer:
Plug From:
Plug To:
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1006146948
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1006146950
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006146952
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.50
Casing Diameter:
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1006146951
Layer: 1
Slot:
Screen Top Depth: 4.50
Screen End Depth: 7.60
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1006146953
Pump Set At:
Static Level: 5.80
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:

Flowing:

Hole Diameter

Hole ID: 1006146947
Diameter: 15.00
Depth From:
Depth To: 7.60
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1006146963
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation:
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: WWR
Org CS: UTM83
Date Completed: 9/22/2010

Annular Space/Abandonment Sealing Record

Plug ID: 1006146967
Layer:
Plug From:
Plug To:
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1006146966
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1006146968
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006146970
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.50
Casing Diameter:

Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1006146969
Layer: 1
Slot:
Screen Top Depth: 4.50
Screen End Depth: 7.60
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1006146971
Pump Set At:
Static Level: 5.60
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1006146965
Diameter: 15.00
Depth From:
Depth To: 7.60
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1003431932
DP2BR:
Code OB:
Code OB Desc:
Open Hole: N
Elevation: 123.263771
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind:
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 9/22/2010

Overburden and Bedrock Materials Interval

Formation ID: 1006146992
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Other Materials: GRAVEL
Mat3: 77
Other Materials: LOOSE
Formation Top Depth: 0.00
Formation End Depth: 1.20
Formation End Depth UOM: m

Formation ID: 1006146993
Layer: 2
Color: 7
General Color: RED
Mat1: 17
Most Common Material: SHALE
Mat2: 28
Other Materials: SAND
Mat3: 66
Other Materials: DENSE
Formation Top Depth: 1.20
Formation End Depth: 3.00
Formation End Depth UOM: m

Formation ID: 1006146994
Layer: 3
Color: 7
General Color: RED
Mat1: 17
Most Common Material: SHALE
Mat2:
Other Materials:
Mat3: 79
Other Materials: PACKED
Formation Top Depth: 3.00
Formation End Depth: 4.50
Formation End Depth UOM: m

Formation ID: 1006146995
Layer: 4
Color: 7
General Color: RED
Mat1: 17
Most Common Material: SHALE
Mat2: 15
Other Materials: LIMESTONE
Mat3: 74
Other Materials: LAYERED
Formation Top Depth: 4.50
Formation End Depth: 6.00
Formation End Depth UOM: m

Formation ID: 1006146996
Layer: 5
Color: 7
General Color: RED
Mat1: 17
Most Common Material: SHALE
Mat2:
Other Materials:
Mat3: 60

Other Materials:	CEMENTED
Formation Top Depth:	6.00
Formation End Depth:	7.60
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1006146998
Layer:	1
Plug From:	0.00
Plug To:	0.30
Plug Depth UOM:	m

Plug ID:	1006146999
Layer:	2
Plug From:	0.30
Plug To:	4.20
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1006147005
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1006146990
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006147001
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.00
Depth To:	4.50
Casing Diameter:	5.10
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Casing ID:	1006147002
Layer:	2
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	4.50
Depth To:	7.60
Casing Diameter:	5.10
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1006147003
Layer:	1
Slot:	20

Screen Top Depth:
Screen End Depth:
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.40

Results of Well Yield Testing

Pump Test ID: 1006146991
Pump Set At:
Static Level: 5.80
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM:
Water State After Test Code: 0
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1006147000
Layer: 1
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1006146997
Diameter: 15.00
Depth From: 0.00
Depth To: 7.60
Hole Depth UOM: m
Hole Diameter UOM: cm

---

20 | ***1 of 3*** | ***WNW/102.1*** | ***124.8 / 1.07*** | ***WEIGH-MATIC SYSTEMS INC.***
3312 MAINWAY DR
BURLINGTON ON L7M 1A7 | ***SCT***

Established: 1985
Plant Size (ft²): 12000
Employment: 15

--Details--
Description: CUTTING TOOLS & MACHINISTS' PRECISION MEASURING DEVICES
SIC/NAICS Code: 3545

Description: PACKAGING MACHINERY
SIC/NAICS Code: 3565

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	2 of 3	WNW/102.1	124.8 / 1.07	CARLISLE TECHNOLOGY 3312 MAINWAY DR BURLINGTON ON L7M 1A7	SCT

Established: 1990
Plant Size (ft²): 12000
Employment: 15

--Details--
Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Description: Computer, Computer Peripheral and Pre-Packaged Software Wholesaler-Distributors
SIC/NAICS Code: 417310

Description: Office and Store Machinery and Equipment Wholesaler-Distributors
SIC/NAICS Code: 417910

Description: Stationery and Office Supplies Wholesaler-Distributors
SIC/NAICS Code: 418210

Description: PRINTING TRADES MACHINERY AND EQUIPMENT
SIC/NAICS Code: 3555

Description: CALCULATING AND ACCOUNTING MACHINES, EXCEPT ELECTRONIC COMPUTERS
SIC/NAICS Code: 3578

Description: ELECTRONIC COMPONENTS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3679

Description: COMPUTERS AND COMPUTER PERIPHERAL EQUIPMENT AND SOFTWARE
SIC/NAICS Code: 5045

Description: COMMERCIAL EQUIPMENT, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 5046

Description: INDUSTRIAL MACHINERY AND EQUIPMENT
SIC/NAICS Code: 5084

Description: INDUSTRIAL AND PERSONAL SERVICE PAPER
SIC/NAICS Code: 5113

Description: All Other Industrial Machinery Manufacturing
SIC/NAICS Code: 333299

Description: Computer and Peripheral Equipment Manufacturing
SIC/NAICS Code: 334110

Description: Semiconductor and Other Electronic Component Manufacturing
SIC/NAICS Code: 334410

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	3 of 3	WNW/102.1	124.8 / 1.07	Carlisle Technology Inc. 3312 Mainway Burlington ON L7M 1A7	SCT

Established: 01-JAN-85
Plant Size (ft²):
Employment:

--Details--
Description: Electronic Components, Navigational and Communications Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417320

Description: Computer Systems Design and Related Services
SIC/NAICS Code: 541510

Description: Measuring, Medical and Controlling Devices Manufacturing
SIC/NAICS Code: 334512

Description: Computer and Peripheral Equipment Manufacturing
SIC/NAICS Code: 334110

Description: Stamping
SIC/NAICS Code: 332118

Description: Other Communications Equipment Manufacturing
SIC/NAICS Code: 334290

Description: Computer Systems Design and Related Services
SIC/NAICS Code: 541510

Description: Service Establishment Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417920

Description: Professional Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417930

Description: All Other Industrial Machinery Manufacturing
SIC/NAICS Code: 333299

Description: Computer, Computer Peripheral and Pre-Packaged Software Wholesaler-Distributors
SIC/NAICS Code: 417310

Description: Prefabricated Metal Building and Component Manufacturing
SIC/NAICS Code: 332311

Description: All Other General-Purpose Machinery Manufacturing
SIC/NAICS Code: 333990

Description: Office and Store Machinery and Equipment Wholesaler-Distributors
SIC/NAICS Code: 417910

Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

21	*1 of 1*	*WNW/102.2*	*124.8 / 1.07*	***Integrity Worldwide Inc.*** ***3310 Mainway*** ***Burlington ON L7M 1A7***	***SCT***

Established:
Plant Size (ft²):
Employment:

--Details--
Description: All Other Miscellaneous Fabricated Metal Product Manufacturing
SIC/NAICS Code: 332999

Description: Other Ornamental and Architectural Metal Product Manufacturing
SIC/NAICS Code: 332329

Description: Other Ornamental and Architectural Metal Product Manufacturing
SIC/NAICS Code: 332329

Description: All Other Specialty Trade Contractors
SIC/NAICS Code: 238990

Description: All Other Textile Product Mills
SIC/NAICS Code: 314990

---

22 | **1 of 1** | **SSE/102.9** | **120.9 / -2.87** | **lot 12 con 2 ON** | **WWIS**

Well ID: 7176343
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status:
Water Type:
Casing Material:
Audit No: M10497
Tag: A110314
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status: Date Entry is incomplete
Data Src:
Date Received: 2/9/2012
Selected Flag: 1
Abandonment Rec:
Contractor: 6607
Form Version: 5
Owner:
Street Name:
County: HALTON
Municipality: BURLINGTON CITY
Site Info:
Lot: 012
Concession: 02
Concession Name: DS S
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1003689611
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 121.315628
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind:
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr
Org CS: UTM83
Date Completed: 12/6/2011

---

23 | **1 of 3** | **NW/103.5** | **124.8 / 1.07** | **Mayne Logistics Loomis Inc.**
3330 MAINWAY DRIVE
BURLINGTON ON | **GEN**

Generator No.: ON0899008
Status:
Approval Years: 03,04
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

---

23 | **2 of 3** | **NW/103.5** | **124.8 / 1.07** | **LOOMIS COURIER SERVICE**
3330 MAINWAY DRIVE
BURLINGTON ON L7M 1A7 | **GEN**

Generator No.:	ON0899008	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	96,97	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	4599		
SIC Description:	OTHER TRANS. SERV.		

--Details--

Waste Code:	145
Waste Description:	PAINT/PIGMENT/COATING RESIDUES
Waste Code:	148
Waste Description:	INORGANIC LABORATORY CHEMICALS
Waste Code:	242
Waste Description:	HALOGENATED PESTICIDES
Waste Code:	263
Waste Description:	ORGANIC LABORATORY CHEMICALS
Waste Code:	269
Waste Description:	NON-HALOGENATED PESTICIDES

---

23 | ***3 of 3*** | ***NW/103.5*** | ***124.8 / 1.07*** | ***LOOMIS COURIER SERVICE(OUT OF BUSINESS)***
3330 MAINWAY DRIVE
BURLINGTON ON L7M 1A7 | ***GEN***

Generator No.:	ON0899008	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	98,99	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	4599		
SIC Description:	OTHER TRANS. SERV.		

--Details--

Waste Code:	145
Waste Description:	PAINT/PIGMENT/COATING RESIDUES
Waste Code:	148
Waste Description:	INORGANIC LABORATORY CHEMICALS
Waste Code:	242
Waste Description:	HALOGENATED PESTICIDES
Waste Code:	263
Waste Description:	ORGANIC LABORATORY CHEMICALS
Waste Code:	269
Waste Description:	NON-HALOGENATED PESTICIDES

---

24 | ***1 of 1*** | ***WNW/103.8*** | ***124.8 / 1.07*** | ***3310-3312 Mainway Dr***
Burlington ON L7M 1A7 | ***EHS***

Order ID:	1584	**Date Received:**	11/23/00
Order No:	20001123004	**Lot/Building Size:**	
Customer ID:	9498	**Municipality:**	
Company ID:	313	**Client Prov/State:**	ON
Status:	C	**Search Radius (km):**	1.00

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Report Code:	4CAN	**Large Radius:**	0.00
Report Type:	Custom Report	**X:**	-113.446678
Report Date:	12/1/00	**Y:**	53.576942
Report Requested by:	CGI Information Systems & Management Consultants Inc.		
Nearest Intersection:			
Previous Site Name:			
Additional Info Ordered:			

---

25 | ***1 of 1*** | ***NW/105.3*** | ***125.6 / 1.79*** | ***3330-3342 MAINWAY BURLINGTON ON L7M 1A7*** | ***EHS***

Order ID:	131199	**Date Received:**	3/20/2008
Order No:	20080320008	**Lot/Building Size:**	
Customer ID:	45487	**Municipality:**	
Company ID:	313	**Client Prov/State:**	ON
Status:	C	**Search Radius (km):**	0.25
Report Code:	4CAN	**Large Radius:**	2
Report Type:	Custom Report	**X:**	-79.800261
Report Date:	3/31/2008	**Y:**	43.366512
Report Requested by:	CGI Risk Management Services		
Nearest Intersection:			
Previous Site Name:			
Additional Info Ordered:			

---

26 | ***1 of 1*** | ***NNW/107.0*** | ***125.8 / 2.07*** | ***ConverTec Inc.***
 3340 Mainway Suite 200
 Burlington ON L7M 1A7 | ***SCT***

Established: 1998
Plant Size (ft²):
Employment:

--Details--
Description: Telephone Apparatus Manufacturing
SIC/NAICS Code: 334210

Description: Computer Systems Design and Related Services
SIC/NAICS Code: 541510

---

27 | ***1 of 3*** | ***NNW/108.2*** | ***125.8 / 2.07*** | ***HAMILTON DIGITAL DESIGNS LTD.***
 3342 Mainway Dr
 Burlington ON L7M 1A7 | ***SCT***

Established: 1974
Plant Size (ft²): 18800
Employment: 17

--Details--
Description: Radio and Television Broadcasting and Wireless Communications Equipment Manufacturing
SIC/NAICS Code: 334220

Description: Measuring, Medical and Controlling Devices Manufacturing
SIC/NAICS Code: 334512

Description: Sign Manufacturing
SIC/NAICS Code: 339950

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
27	2 of 3	NNW/108.2	125.8 / 2.07	Hamilton Digital Designs Ltd. 3342 Mainway Burlington ON L7M 1A7	SCT

Established: 01-JUN-74
Plant Size (ft²): 18800
Employment:

--Details--
Description: Commercial and Industrial Machinery and Equipment (except Automotive and Electronic) Repair and Maintenance
SIC/NAICS Code: 811310

Description: Sign Manufacturing
SIC/NAICS Code: 339950

Description: Sign Manufacturing
SIC/NAICS Code: 339950

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
27	3 of 3	NNW/108.2	125.8 / 2.07	HAMILTON DIGITAL DESIGNS LTD. 3142 MAINWAY DR BURLINGTON ON L7M 1A7	SCT

Established: 1974
Plant Size (ft²): 18800
Employment: 17

--Details--
Description: SIGNS AND ADVERTISING SPECIALTIES
SIC/NAICS Code: 3993

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
28	1 of 5	NNW/109.1	125.8 / 2.07	1187188 Ont Ltd. 3344 Mainway Burlington ON L7M 1A7	GEN

Generator No.: ON6337896
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 623110
SIC Description: 623110

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 312
Waste Description: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
28	2 of 5	NNW/109.1	125.8 / 2.07	1187188 Ont Ltd. 3344 Mainway Burlington ON	GEN

Generator No.: ON6337896
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 623110
SIC Description:

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Waste Code: 312
Waste Description: PATHOLOGICAL WASTES

---

28 ***3 of 5*** ***NNW/109.1*** ***125.8 / 2.07*** ***1187188 Ont Ltd.***
3344 Mainway
Burlington ON L7M 1A7 ***GEN***

Generator No.: ON6337896
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 623110
SIC Description: Nursing Care Facilities

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 312
Waste Description: PATHOLOGICAL WASTES

---

28 ***4 of 5*** ***NNW/109.1*** ***125.8 / 2.07*** ***1187188 Ont Ltd.***
3344 Mainway
Burlington ON L7M 1A7 ***GEN***

Generator No.: ON6337896
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 623110
SIC Description: Nursing Care Facilities

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 312
Waste Description: PATHOLOGICAL WASTES

---

28 ***5 of 5*** ***NNW/109.1*** ***125.8 / 2.07*** ***1187188 Ont Ltd.***
3344 Mainway
Burlington ON L7M 1A7 ***GEN***

Generator No.: ON6337896
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 623110
SIC Description: Nursing Care Facilities

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 312
Waste Description: PATHOLOGICAL WASTES

---

29 ***1 of 1*** ***WSW/122.7*** ***123.4 / -0.36*** ***Burlington ON*** ***WWIS***

Well ID:	7263060	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Test Hole	**Date Received:**	5/18/2016
Sec. Water Use:		**Selected Flag:**	1
Final Well Status:	Monitoring and Test Hole	**Abandonment Rec:**	
Water Type:		**Contractor:**	7383
Casing Material:		**Form Version:**	7
Audit No:	Z231771	**Owner:**	
Tag:	A203606	**Street Name:**	3264 MAINWAY
Construction Method:		**County:**	HALTON
Elevation (m):		**Municipality:**	BURLINGTON CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1005992671	**Spatial Status:**	
DP2BR:		**Cluster Kind:**	
Code OB:		**UTMRC:**	4
Code OB Desc:		**UTMRC Desc:**	margin of error : 30 m - 100 m
Open Hole:		**Location Method:**	wwr
Elevation:	123.135475	**Org CS:**	UTM83
Elevrc:		**Date Completed:**	1/27/2016
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1006092779
Layer:	1
Plug From:	0.00
Plug To:	1.00
Plug Depth UOM:	ft

Plug ID:	1006092780
Layer:	2
Plug From:	1.00
Plug To:	5.00
Plug Depth UOM:	ft

Plug ID:	1006092781
Layer:	3
Plug From:	5.00
Plug To:	11.00
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1006092778

Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1006092771
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006092775
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.00
Depth To: 6.00
Casing Diameter: 1.00
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1006092776
Layer: 1
Slot:
Screen Top Depth: 6.00
Screen End Depth: 11.00
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 1.37

Water Details

Water ID: 1006092774
Layer: 1
Kind Code:
Kind:
Water Found Depth: 7.00
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1006092773
Diameter: 3.00
Depth From: 0.00
Depth To: 11.00
Hole Depth UOM: ft
Hole Diameter UOM: inch

30	1 of 3	WNW/123.4	125.0 / 1.19	ANTEL OPTRONICS INC. 3329 MAINWAY BURLINGTON ON L7M 1A6	03-117	GEN

Generator No.: ON0529400
Status:
Approval Years: 92,93,94
Contam. Facility:
PO Box No.:
Country:
Choice of Contact:
Co Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MHSW Facility: **Phone No. Admin:**
SIC Code: 0007
SIC Description: LETTER ACKNOWLEDG.

---

30 **2 of 3** **WNW/123.4** **125.0 / 1.19** **ANTEL OPTRONICS INC.** **GEN**
3329 MAINWAY
BURLINGTON ON L7M 1A6

Generator No.: ON0529400 **PO Box No.:**
Status: **Country:**
Approval Years: 86,87,88,89 **Choice of Contact:**
Contam. Facility: **Co Admin:**
MHSW Facility: **Phone No. Admin:**
SIC Code: 0007
SIC Description: LETTER ACKNOWLEDG.

---

30 **3 of 3** **WNW/123.4** **125.0 / 1.19** **DRAKE WATER SYSTEMS INC.** **SCT**
3329 MAINWAY DR
BURLINGTON ON L7M 1A6

Established: 1986
Plant Size (ft²): 3200
Employment: 10

--Details--
Description: BOTTLED AND CANNED SOFT DRINKS AND CARBONATED WATERS
SIC/NAICS Code: 2086

Description: SERVICE INDUSTRY MACHINERY, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3589

Description: PLUMBING AND HEATING EQUIPMENT AND SUPPLIES (HYDRONICS)
SIC/NAICS Code: 5074

---

31 **1 of 1** **NW/124.3** **125.6 / 1.78** **3355 Mainway** **EHS**
Burlington ON L7M 1A6

Order ID: 47557 **Date Received:** 11/26/04
Order No: 20041126005 **Lot/Building Size:** 3 acres
Customer ID: 36467 **Municipality:**
Company ID: 185 **Client Prov/State:** ON
Status: C **Search Radius (km):** 0.25
Report Code: 3CAN **Large Radius:** 2
Report Type: Complete Report **X:** -79.800308
Report Date: 11/30/04 **Y:** 43.367359
Report Requested by: Stantec Consulting Ltd.
Nearest Intersection:
Previous Site Name:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

---

32 **1 of 2** **NW/124.8** **125.8 / 2.07** **EcoSynthetix Inc.** **ECA**
3365 Mainway Dr
Burlington ON L7M 1A6

Approval No: 8915-A4LRZB **MOE District:**
Approval Type: ECA-AIR **SWP Area Name:**
Status: Approved **Address:** 3365 Mainway Dr
Approval Date: 2015-11-27 **City:** Burlington

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Record Type: ECA
Project Type: AIR
Link Source: IDS
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/4679-9AJRL6-14.pdf
Longitude:
Latitude:

---

32 | **2 of 2** | **NW/124.8** | **125.8 / 2.07** | **3365 Mainway, Burlington ON L7M 1A6** | **EHS**

Order ID: 96055
Order No: 20070228002
Customer ID: 36467
Company ID: 185
Status: C
Report Code: 3CAN
Report Type: CAN - Complete Report
Report Date: 3/5/2007
Report Requested by: Stantec Consulting Ltd.
Nearest Intersection:
Previous Site Name:
Additional Info Ordered:
Date Received: 2/28/2007
Lot/Building Size:
Municipality:
Client Prov/State:
Search Radius (km): 0.25
Large Radius: 2
X: -79.800855
Y: 43.366875

---

33 | **1 of 8** | **NNE/128.1** | **124.8 / 0.98** | **EUROLINE CUSTOM CABINETS, 3415 LANDMARK ROAD, BURLINGTON ON L7M 1T4** | **GEN**

Generator No.: ON2021900
Status:
Approval Years: 95,96,97,98,99
Contam. Facility:
MHSW Facility:
SIC Code: 2542
SIC Description: WOODEN KITCHEN CAB.
PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

---

33 | **2 of 8** | **NNE/128.1** | **124.8 / 0.98** | **COR-MAG INC. 07-629, 3415 LANDMARK RD., BURLINGTON ON L7M 1T4** | **GEN**

Generator No.: ON1663900
Status:
Approval Years: 94,95
Contam. Facility:
MHSW Facility:
SIC Code: 3371
SIC Description: ELECT. TRANSFORMER
PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

33 | **3 of 8** | **NNE/128.1** | **124.8 / 0.98** | **COR-MAG INC.(OUT OF BUS) 07-629, 3415 LANDMARK RD., BURLINGTON ON L7M 1T4** | **GEN**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No.: ON1663900
Status:
Approval Years: 92,93,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 3371
SIC Description: ELECT. TRANSFORMER

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

33 ***4 of 8*** ***NNE/128.1*** ***124.8 / 0.98*** ***GEN***

IndustAutoCo Inc.
3415 Lanmark Road
Burlington ON L7M 1T4

Generator No.: ON8298028
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 417990
SIC Description: ALL OTHER MACHINERY, EQUIPMENT AND SUPPLIES WHOLESALER-DISTRIBUTORS

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 243
Waste Description: PCBS

---

33 ***5 of 8*** ***NNE/128.1*** ***124.8 / 0.98*** ***GEN***

IndustAutoCo Inc.
3415 Lanmark Road
Burlington ON L7M 1T4

Generator No.: ON8298028
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 417990
SIC Description: ALL OTHER MACHINERY, EQUIPMENT AND SUPPLIES WHOLESALER-DISTRIBUTORS

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 243
Waste Description: PCBS

---

33 ***6 of 8*** ***NNE/128.1*** ***124.8 / 0.98*** ***GEN***

EUROLINE (OUT OF BUSINESS)
3415 LANDMARK ROAD
BURLINGTON ON L7M 1T4

Generator No.: ON2021900
Status:
Approval Years: 00,01
Contam. Facility:
MHSW Facility:
SIC Code: 2542
SIC Description: WOODEN KITCHEN CAB.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

---

33 **7 of 8** **NNE/128.1** **124.8 / 0.98** **EUROLINE CUSTOM CABINETS INC.** **SCT**
3415 LANDMARK RD
BURLINGTON ON L7M 1T4

Established: 1986
Plant Size (ft²): 21000
Employment: 20

--Details--
Description: Other Wood Household Furniture Manufacturing
SIC/NAICS Code: 337123

Description: Wood Window and Door Manufacturing
SIC/NAICS Code: 321911

Description: Other Millwork
SIC/NAICS Code: 321919

---

33 **8 of 8** **NNE/128.1** **124.8 / 0.98** **EUROLINE CUSTOM CABINETS** **SCT**
3415 LANDMARK RD
BURLINGTON ON L7M 1T4

Established: 1986
Plant Size (ft²): 21000
Employment: 20

--Details--
Description: MILLWORK
SIC/NAICS Code: 2431

Description: WOOD HOUSEHOLD FURNITURE, EXCEPT UPHOLSTERED
SIC/NAICS Code: 2511

---

34 **1 of 1** **SW/140.0** **122.9 / -0.91** **WWIS**
Burlington ON

Well ID:	7263059	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:	Test Hole	***Date Received:***	5/18/2016
Sec. Water Use:		***Selected Flag:***	1
Final Well Status:	Monitoring and Test Hole	***Abandonment Rec:***	
Water Type:		***Contractor:***	7383
Casing Material:		***Form Version:***	7
Audit No:	Z231770	***Owner:***	
Tag:	A203607	***Street Name:***	3264 MAINWAY
Construction Method:		***County:***	HALTON
Elevation (m):		***Municipality:***	BURLINGTON CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	

Clear/Cloudy:

Bore Hole Information

Bore Hole ID:	1005992668	***Spatial Status:***	
DP2BR:		***Cluster Kind:***	
Code OB:		***UTMRC:***	4
Code OB Desc:		***UTMRC Desc:***	margin of error : 30 m - 100 m
Open Hole:		***Location Method:***	wwr
Elevation:	122.780433	***Org CS:***	UTM83
Elevrc:		***Date Completed:***	1/27/2016
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1006092756
Layer:	1
Plug From:	0.00
Plug To:	1.00
Plug Depth UOM:	ft

Plug ID:	1006092757
Layer:	2
Plug From:	1.00
Plug To:	5.00
Plug Depth UOM:	ft

Plug ID:	1006092758
Layer:	3
Plug From:	5.00
Plug To:	11.00
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1006092755
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	PERCUSSION

Pipe Information

Pipe ID:	1006092748
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006092752
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.00

Depth To:	6.00
Casing Diameter:	1.00
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1006092753
Layer:	1
Slot:	10
Screen Top Depth:	6.00
Screen End Depth:	11.00
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	1.37

Water Details

Water ID:	1006092751
Layer:	1
Kind Code:	
Kind:	
Water Found Depth:	7.00
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1006092750
Diameter:	3.00
Depth From:	0.00
Depth To:	11.00
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

35 ***1 of 1*** ***NNE/142.8*** ***124.8 / 1.07*** ***Burlington ON*** ***WWIS***

Well ID:	7140992	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Test Hole	**Date Received:**	3/4/2010
Sec. Water Use:		**Selected Flag:**	1
Final Well Status:	Test Hole	**Abandonment Rec:**	
Water Type:		**Contractor:**	6988
Casing Material:		**Form Version:**	5
Audit No:	M04132	**Owner:**	
Tag:	A076476	**Street Name:**	3410 MAINWAY
Construction Method:		**County:**	HALTON
Elevation (m):		**Municipality:**	BURLINGTON CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1003283333	**Spatial Status:**	

DP2BR:		***Cluster Kind:***	This is a record from cluster log sheet
Code OB:		***UTMRC:***	4
Code OB Desc:		***UTMRC Desc:***	margin of error : 30 m - 100 m
Open Hole:		***Location Method:***	wwr
Elevation:	125.74691	***Org CS:***	UTM83
Elevrc:		***Date Completed:***	3/18/2009
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1003283337
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1003283336
Method Construction Code:	
Method Construction:	
Other Method Construction:	BORING

Pipe Information

Pipe ID:	1003283338
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1003283340
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	1.80
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1003283339
Layer:	
Slot:	
Screen Top Depth:	1.80
Screen End Depth:	9.10
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pump Test ID:	1003283341
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1003283335
Diameter:	15.00
Depth From:	
Depth To:	9.10
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1003283324	***Spatial Status:***	
DP2BR:		***Cluster Kind:***	This is a record from cluster log sheet
Code OB:		***UTMRC:***	4
Code OB Desc:		***UTMRC Desc:***	margin of error : 30 m - 100 m
Open Hole:		***Location Method:***	wwr
Elevation:	125.795333	***Org CS:***	UTM83
Elevrc:		***Date Completed:***	3/18/2009
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1003283328
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1003283327
Method Construction Code:	
Method Construction:	
Other Method Construction:	BORING

Pipe Information

Pipe ID:	1003283329
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1003283331
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	1.20
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1003283330
Layer:	
Slot:	
Screen Top Depth:	1.20
Screen End Depth:	3.60
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pump Test ID:	1003283332
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1003283326
Diameter:	15.00
Depth From:	
Depth To:	3.60
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID: 1003283342
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 124.954017
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr
Org CS: UTM83
Date Completed: 3/18/2009

Annular Space/Abandonment Sealing Record

Plug ID: 1003283346
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003283345
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1003283347
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1003283349
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 1.50
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1003283348
Layer:
Slot:
Screen Top Depth: 1.50
Screen End Depth: 7.30
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID:	1003283350
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1003283344
Diameter:	15.00
Depth From:	
Depth To:	7.30
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1002946375	***Spatial Status:***	
DP2BR:		***Cluster Kind:***	
Code OB:		***UTMRC:***	4
Code OB Desc:		***UTMRC Desc:***	margin of error : 30 m - 100 m
Open Hole:		***Location Method:***	wwr
Elevation:	125.74691	***Org CS:***	UTM83
Elevrc:		***Date Completed:***	3/19/2009
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1003283352
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	12
Other Materials:	STONES
Mat3:	85
Other Materials:	SOFT
Formation Top Depth:	0.00
Formation End Depth:	0.60
Formation End Depth UOM:	m

Formation ID:	1003283353
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Other Materials:	CLAY
Mat3:	
Other Materials:	
Formation Top Depth:	0.60
Formation End Depth:	1.80
Formation End Depth UOM:	m

Formation ID:	1003283354
Layer:	3
Color:	7
General Color:	RED
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Other Materials:	SAND
Mat3:	
Other Materials:	
Formation Top Depth:	1.80
Formation End Depth:	3.60
Formation End Depth UOM:	m

Formation ID:	1003283355
Layer:	4
Color:	6
General Color:	BROWN
Mat1:	17
Most Common Material:	SHALE
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	3.60
Formation End Depth:	9.10
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1003283357
Layer:	1
Plug From:	0.00
Plug To:	1.20
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1003283362
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1003283351

Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1003283358
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.00
Depth To: 1.80
Casing Diameter: 5.10
Casing Diameter UOM: cm
Casing Depth UOM: m

Casing ID: 1003283359
Layer: 2
Material: 5
Open Hole or Material: PLASTIC
Depth From: 1.80
Depth To: 8.00
Casing Diameter: 5.10
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1003283360
Layer: 1
Slot: 10
Screen Top Depth:
Screen End Depth:
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.00

Hole Diameter

Hole ID: 1003283356
Diameter: 15.00
Depth From: 0.00
Depth To: 9.10
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1003283306
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 125.621803
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr
Org CS: UTM83
Date Completed: 3/18/2009

Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID:	1003283310
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1003283309
Method Construction Code:	
Method Construction:	
Other Method Construction:	BORING

Pipe Information

Pipe ID:	1003283311
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1003283313
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	1.50
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1003283312
Layer:	
Slot:	
Screen Top Depth:	1.50
Screen End Depth:	7.30
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pump Test ID:	1003283314
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	

Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1003283308
Diameter: 10.00
Depth From:
Depth To: 7.30
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1003283315
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 125.66011
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr
Org CS: UTM83
Date Completed: 3/18/2009

Annular Space/Abandonment Sealing Record

Plug ID: 1003283319
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003283318
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1003283320
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1003283322

Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 1.50
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1003283321
Layer:
Slot:
Screen Top Depth: 1.50
Screen End Depth: 7.30
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1003283323
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1003283317
Diameter: 10.00
Depth From:
Depth To: 7.30
Hole Depth UOM: m
Hole Diameter UOM: cm

---

36 ***1 of 1*** ***WSW/143.0*** ***123.0 / -0.75*** ***3264 Mainway Burlington ON L7M1A7*** ***EHS***

Order ID: 422874
Order No: 20150820027
Customer ID: 9366
Company ID: 232
Status: C
Report Code: 3CAN
Report Type: Standard Report
Report Date: 26-AUG-15
Report Requested by: Briggs Canada Ltd.
Nearest Intersection:

Date Received: 20-AUG-15
Lot/Building Size:
Municipality: Burlington
Client Prov/State: ON
Search Radius (km): .25
Large Radius: .3
X: -79.802274
Y: 43.364385

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Previous Site Name:		Aisco			
Additional Info Ordered:					

37	1 of 24	E/143.2	120.5 / -3.27	**Pennzoil Quaker-State Canada Incorporated** **1101 Blair Road** **Burlington ON L7M 1T3**	CA

Certificate #:	7455-6LCMC7
Application Year:	2006
Issue Date:	3/7/2006
Approval Type:	Air
Status:	Approved
Application Type:	
Client Name::	
Client Address::	
Client City::	
Client Postal Code::	
Project Description::	
Contaminants::	
Emission Control::	

37	2 of 24	E/143.2	120.5 / -3.27	**Pennzoil Quaker-State Canada Incorporated** **1101 Blair Road Burlington Ontario L7M 1T3** **Burlington** **ON**	EBR

EBR Registry No.:	IA05E0208
Ministry Ref. No.:	4880-6983VG
Company Name:	Pennzoil Quaker-State Canada Incorporated
Notice Type:	Instrument Decision
Notice Date:	March 09, 2006
Proposal Date:	February 18, 2005
Year:	2005
Proponent Address:	1101 Blair Road, Burlington Ontario, L7M 1T3
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:	

Location:

1101 Blair Road Burlington Ontario L7M 1T3 Burlington

37	3 of 24	E/143.2	120.5 / -3.27	**Pennzoil Quaker-State Canada Incorporated** **1101 Blair Road** **Burlington ON L7M 1T3**	ECA

Approval No:	7455-6LCMC7	**MOE District:**	Halton-Peel
Approval Type:	ECA-AIR	**SWP Area Name:**	Halton
Status:	Approved	**Address:**	1101 Blair Road
Approval Date:	2006-03-07	**City:**	Burlington
Record Type:	ECA	**Longitude:**	-79.79554
Project Type:	AIR	**Latitude:**	43.3663
Link Source:	IDS		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/4880-6983VG-14.pdf		

37	4 of 24	E/143.2	120.5 / -3.27	**1101 Blair Road** **Burlington ON L7M 1T3**	EHS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Order ID:	165565	**Date Received:**	6/22/2009
Order No:	20090622016	**Lot/Building Size:**	
Customer ID:	59327	**Municipality:**	
Company ID:	132	**Client Prov/State:**	ON
Status:	C	**Search Radius (km):**	0.25
Report Code:	3CAN	**Large Radius:**	2
Report Type:	Standard Report	**X:**	-79.796473
Report Date:	7/2/2009	**Y:**	43.365244
Report Requested by:	Aqua Terre Solutions Inc.		
Nearest Intersection:	Blair Road and Mainway		
Previous Site Name:			
Additional Info Ordered:	Fire Insur. Maps and/or Sire Plans; Aerial Photos		

---

37 **5 of 24** **E/143.2** **120.5 / -3.27** **SHELL CANADA PRODUCTS** **GEN**
1101 BLAIR ROAD
BURLINGTON ON L7M 1T3

Generator No.:	ON0145300	**PO Box No.:**	
Status:	Registered	**Country:**	Canada
Approval Years:	As of Dec 2017	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:			
SIC Description:			

--Details--
Waste Code: 251 L
Waste Description: Waste oils/sludges (petroleum based)

Waste Code: 252 L
Waste Description: Waste crankcase oils and lubricants

---

37 **6 of 24** **E/143.2** **120.5 / -3.27** **SHELL CANADA PRODUCTS** **GEN**
1101 BLAIR ROAD
BURLINGTON ON L7M 1T3

Generator No.:	ON0145300	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	2011	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	484231		
SIC Description:	Bulk Liquids Trucking Long Distance		

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

---

37 **7 of 24** **E/143.2** **120.5 / -3.27** **QUAKER STATE INC.** **32-001** **GEN**
1101 BLAIR ROAD
BURLINGTON ON L7M 1T3

Generator No.:	ON0145300	**PO Box No.:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: **Country:**
Approval Years: 92,93,96 **Choice of Contact:**
Contam. Facility: **Co Admin:**
MHSW Facility: **Phone No. Admin:**
SIC Code: 3612
SIC Description: LUB. OIL & GREASE

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

---

37 ***8 of 24*** ***E/143.2*** ***120.5 / -3.27*** ***SHELL CANADA PRODUCTS***
1101 BLAIR ROAD
BURLINGTON ON L7M 1T3 ***GEN***

Generator No.: ON0145300 ***PO Box No.:***
Status: ***Country:*** Canada
Approval Years: 2015 ***Choice of Contact:*** CO_OFFICIAL
Contam. Facility: No ***Co Admin:*** Philippe Lissardi
MHSW Facility: No ***Phone No. Admin:*** 1-800-263-6200 Ext.2186
SIC Code: 484231
SIC Description: BULK LIQUIDS TRUCKING, LONG DISTANCE

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

---

37 ***9 of 24*** ***E/143.2*** ***120.5 / -3.27*** ***QUAKER STATE INC***
1101 BLAIR RD.
BURLINGTON ON L7M 1T3 ***GEN***

Generator No.: ON0145300 ***PO Box No.:***
Status: ***Country:***
Approval Years: 86,87,88,89,90 ***Choice of Contact:***
Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No. Admin:***
SIC Code: 3612
SIC Description: LUB. OIL & GREASE

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site		DB
37	10 of 24	E/143.2	120.5 / -3.27	QUAKER STATE INC 1101 BLAIR RD. BURLINGTON ON L7M 1T3	32-001	GEN

Generator No.: ON0145300
Status:
Approval Years: 94,95
Contam. Facility:
MHSW Facility:
SIC Code: 3612
SIC Description: LUB. OIL & GREASE

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
37	11 of 24	E/143.2	120.5 / -3.27	PENNZOIL QUAKER STATE CANADA COMPANY 1101 BLAIR ROAD BURLINGTON ON L7M 1T3	GEN

Generator No.: ON0145300
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 484231
SIC Description: Bulk Liquids Trucking Long Distance

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
37	12 of 24	E/143.2	120.5 / -3.27	PENNZOIL QUAKER STATE CANADA COMPANY 1101 BLAIR ROAD BURLINGTON ON L7M 1T3	GEN

Generator No.: ON0145300
Status:
Approval Years: 02,03,04,05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

37 | ***13 of 24*** | ***E/143.2*** | ***120.5 / -3.27*** | ***QUAKER STATE INC.***
1101 BLAIR ROAD
BURLINGTON ON L7M 1T3 | ***GEN***

Generator No.: ON0145300
Status:
Approval Years: 98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 3612
SIC Description: LUB. OIL & GREASE

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

37 | ***14 of 24*** | ***E/143.2*** | ***120.5 / -3.27*** | ***SHELL CANADA PRODUCTS***
1101 BLAIR ROAD
BURLINGTON ON L7M 1T3 | ***GEN***

Generator No.: ON0145300
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 484231
SIC Description: Bulk Liquids Trucking Long Distance

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

---

37 | ***15 of 24*** | ***E/143.2*** | ***120.5 / -3.27*** | ***QUAKER STATE INC***
1101 BLAIR ROAD
BURLINGTON ON L7M 1T3 | ***GEN***

Generator No.: ON0145300
Status:

PO Box No.:
Country:

Approval Years:	97	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	3612		
SIC Description:	LUB. OIL & GREASE		

--Details--

Waste Code:	211
Waste Description:	AROMATIC SOLVENTS
Waste Code:	251
Waste Description:	OIL SKIMMINGS & SLUDGES
Waste Code:	252
Waste Description:	WASTE OILS & LUBRICANTS

---

37 ***16 of 24*** ***E/143.2*** ***120.5 / -3.27***

SHELL CANADA PRODUCTS
1101 BLAIR ROAD
BURLINGTON ON L7M 1T3

GEN

Generator No.:	ON0145300	**PO Box No.:**	
Status:		**Country:**	Canada
Approval Years:	2016	**Choice of Contact:**	CO_OFFICIAL
Contam. Facility:	No	**Co Admin:**	Philippe Lissardi
MHSW Facility:	No	**Phone No. Admin:**	1-800-263-6200 Ext.2186
SIC Code:	484231		
SIC Description:	BULK LIQUIDS TRUCKING, LONG DISTANCE		

--Details--

Waste Code:	122
Waste Description:	ALKALINE WASTES - OTHER METALS
Waste Code:	252
Waste Description:	WASTE OILS & LUBRICANTS
Waste Code:	251
Waste Description:	OIL SKIMMINGS & SLUDGES

---

37 ***17 of 24*** ***E/143.2*** ***120.5 / -3.27***

PENNZOIL QUAKER STATE CANADA COMPANY
1101 BLAIR ROAD
BURLINGTON ON L7M 1T3

GEN

Generator No.:	ON0145300	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	2010	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	484231		
SIC Description:	Bulk Liquids Trucking Long Distance		

--Details--

Waste Code:	122
Waste Description:	ALKALINE WASTES - OTHER METALS
Waste Code:	252
Waste Description:	WASTE OILS & LUBRICANTS
Waste Code:	251
Waste Description:	OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

37 **18 of 24** **E/143.2** **120.5 / -3.27** **SHELL CANADA PRODUCTS** **GEN**
1101 BLAIR ROAD
BURLINGTON ON L7M 1T3

Generator No.:	ON0145300	**PO Box No.:**	
Status:		**Country:**	Canada
Approval Years:	2014	**Choice of Contact:**	CO_OFFICIAL
Contam. Facility:	No	**Co Admin:**	Philippe Lissardi
MHSW Facility:	No	**Phone No. Admin:**	1-800-263-6200 Ext.2186
SIC Code:	484231		
SIC Description:	BULK LIQUIDS TRUCKING, LONG DISTANCE		

--Details--
Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

37 **19 of 24** **E/143.2** **120.5 / -3.27** **SHELL CANADA PRODUCTS** **GEN**
1101 BLAIR ROAD
BURLINGTON ON

Generator No.:	ON0145300	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	2013	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	484231		
SIC Description:	BULK LIQUIDS TRUCKING, LONG DISTANCE		

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

37 **20 of 24** **E/143.2** **120.5 / -3.27** **Pennzoil-Quaker State Canada** **SCT**
1101 Blair Rd
Burlington ON L7M 1T3

Established: 01-SEP-87
Plant Size (ft²): 60000
Employment:

--Details--
Description: Other New Motor Vehicle Parts and Accessories Wholesaler-Distributors
SIC/NAICS Code: 415290

Description: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
SIC/NAICS Code: 418410

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: Petroleum Product Wholesaler-Distributors
SIC/NAICS Code: 412110

Description: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
SIC/NAICS Code: 418410

---

37 **21 of 24** **E/143.2** **120.5 / -3.27** **QUAKER STATE INC.**
1101 BLAIR RD
BURLINGTON ON L7M 1T3 **SCT**

Established: 1917
Plant Size (ft²): 60000
Employment: 100

--Details--
Description: LUBRICATING OILS AND GREASES
SIC/NAICS Code: 2992

---

37 **22 of 24** **E/143.2** **120.5 / -3.27** **Pennzoil-Quaker State Canada Company**
1101 Blair Rd
Burlington ON L7M 1T3 **SCT**

Established: 1887
Plant Size (ft²): 60000
Employment: 120

--Details--
Description: Motor Vehicle Seating and Interior Trim Manufacturing
SIC/NAICS Code: 336360

Description: Petroleum Product Wholesaler-Distributors
SIC/NAICS Code: 412110

Description: Other New Motor Vehicle Parts and Accessories Wholesaler-Distributors
SIC/NAICS Code: 415290

---

37 **23 of 24** **E/143.2** **120.5 / -3.27** **PENNZOIL QUAKER STATE CANADA C**
1101 BLAIR RD
BURLINGTON ON L7M 1T3 **SCT**

Established: 1887
Plant Size (ft²): 60000
Employment: 100

--Details--
Description: Other Petroleum and Coal Products Manufacturing
SIC/NAICS Code: 324190

---

37 **24 of 24** **E/143.2** **120.5 / -3.27** **PENZOIL QUAKER STATE**
1101 BLAIR ROAD 1101 BLAIR ROAD,BURLINGTON
BURLINGTON CITY ON L7M 1T3 **SPL**

Ref No: 238250 **Discharger Report:**
Site No: **Material Group:**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Incident Dt:	9/5/2002	**Client Type:**	
Year:		**Sector Type:**	
Incident Cause:	OTHER CAUSE (N.O.S.)	**Source Type:**	
Incident Event:		**Nearest Watercourse:**	
Contaminant Code:		**Site Name:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site County/District:**	
Contaminant UN No 1:		**Site Postal Code:**	
Contaminant Qty:		**Site Region:**	
Environment Impact:	POSSIBLE	**Site Municipality:**	14101
Nature of Impact:	Water course or lake	**Site Lot:**	
Receiving Medium:	LAND, WATER	**Site Conc:**	
Receiving Env:		**Northing:**	
Health/Env Conseq:		**Easting:**	
MOE Response:		**Site Geo Ref Accu:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Meth:**	
MOE Reported Dt:	9/5/2002	**Site Map Datum:**	
Dt Document Closed:			
SAC Action Class:			

Incident Reason: OTHER
Incident Summary: PENZOIL-OIL SHEEN ON LOT AND CB,WATERMAIN FAILED, CONTAINED.

---

38 | 1 of 21 | NNE/152.1 | 125.3 / 1.57 | **RIEGER PRINTING INK CO. LTD.**
3410 MAINWAY DRIVE
BURLINGTON CITY ON L7M 1A8 | CA

Certificate #: 8-3472-97-
Application Year: 97
Issue Date: 12/9/1997
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name::
Client Address::
Client City::
Client Postal Code::
Project Description:: DUST COLLECTOR FOR PRINTING INK MIXERS
Contaminants:: Suspended Particulate Matter
Emission Control:: Baghouse (Incl Vent Fil.)

---

38 | 2 of 21 | NNE/152.1 | 125.3 / 1.57 | **Rieger Printing Ink Co. Ltd.**
3410 Mainway Drive CITY OF BURLINGTON
ON | EBR

EBR Registry No.: IA7E1624
Ministry Ref. No.: 8347297 19971007
Company Name: Rieger Printing Ink Co. Ltd.
Notice Type: Instrument Decision
Notice Date: January 19, 1998
Proposal Date: October 31, 1997
Year: 1997
Proponent Address: 3410 Mainway Drive, Burlington Ontario, L7M 1A8
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:

Location:

3410 Mainway Drive CITY OF BURLINGTON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	3 of 21	NNE/152.1	125.3 / 1.57	3410 Mainway Burlington ON L7M 1A8	EHS

Order ID:	46656	**Date Received:**	10/29/04
Order No:	20041029003	**Lot/Building Size:**	
Customer ID:	18981	**Municipality:**	
Company ID:	23	**Client Prov/State:**	OH
Status:	C	**Search Radius (km):**	0.5
Report Code:	2USA	**Large Radius:**	2
Report Type:	Complete Report	**X:**	-79.79921
Report Date:	11/8/04	**Y:**	43.367895
Report Requested by:	Clayton Group Services		
Nearest Intersection:			
Previous Site Name:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	4 of 21	NNE/152.1	125.3 / 1.57	221063 Ontario Inc. 3410 Mainway Burlington ON L7M 1A8	GEN

Generator No.:	ON3157969	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	2009	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	323113		
SIC Description:	Commercial Screen Printing		

--Details--

Waste Code:	252
Waste Description:	WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	5 of 21	NNE/152.1	125.3 / 1.57	RIEGER PRINTING INK CO LTD C/O 4515 CHESSWOOD DRIVE 3410 MAINWAY DRIVE DOWNSVIEW ON L7M 1A8	GEN

Generator No.:	ON0150400	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	86,87,88	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	3791		
SIC Description:	PRINTING INK IND.		

--Details--

Waste Code:	145
Waste Description:	PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	6 of 21	NNE/152.1	125.3 / 1.57	REGIER PRINTING INK 3410 MAINWAY DRIVE BURLINGTON ON L7M 1A8	GEN

Generator No.:	ON0301700	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	86,87,88,89,90,92,93,94	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Code: 0000
SIC Description: *** NOT DEFINED ***

---

38 **7 of 21** **NNE/152.1** **125.3 / 1.57** **RIEGER PRINTING INK CO. LTD.** **GEN**
3410 MAINWAY DRIVE
BURLINGTON ON L7M 1A8

Generator No.: ON0150400
Status:
Approval Years: 98,99,00,01,02,03,04,05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code: 3791
SIC Description: PRINTING INK IND.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 232
Waste Description: POLYMERIC RESINS

Waste Code: 243
Waste Description: PCB'S

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 141
Waste Description: INORGANIC PIGMENT WASTES

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 265
Waste Description: GRAPHIC ART WASTES

---

38 **8 of 21** **NNE/152.1** **125.3 / 1.57** **RIEGER PRINTING INK CO. LTD.** **33-087** **GEN**
3410 MAINWAY DR.
BURLINGTON ON L7M 1A8

Generator No.: ON0150400
Status:
Approval Years: 92,93,94,95,96,97
Contam. Facility:
MHSW Facility:
SIC Code: 3791
SIC Description: PRINTING INK IND.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 141
Waste Description: INORGANIC PIGMENT WASTES

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 243
Waste Description: PCB'S

Waste Code: 265
Waste Description: GRAPHIC ART WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	9 of 21	NNE/152.1	125.3 / 1.57	RIEGER PRINTING INK CO LTD 3410 MAINWAY DR. BURLINGTON ON L7M 1A8	GEN

Generator No.: ON0150400
Status:
Approval Years: 89,90
Contam. Facility:
MHSW Facility:
SIC Code: 3791
SIC Description: PRINTING INK IND.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 141
Waste Description: INORGANIC PIGMENT WASTES

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	10 of 21	NNE/152.1	125.3 / 1.57	221063 Ontario Inc. 3410 Mainway Burlington ON L7M 1A8	GEN

Generator No.: ON3157969
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 323113
SIC Description: Commercial Screen Printing

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	11 of 21	NNE/152.1	125.3 / 1.57	RIEGER PRINTING INK CO. LTD. 3410 MAINWAY DRIVE (SITE), C/O 4515-A CHESSWOOD DR., DOWNSVIEW M3J2V6 BURLINGTON ON L7M 1A8	GEN

Generator No.: A210111
Status:
Approval Years: 86
Contam. Facility:
MHSW Facility:
SIC Code: 030
SIC Description:

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	12 of 21	NNE/152.1	125.3 / 1.57	RIEGER PRINTING INK COMPANY LTD. 3410 MAINWAY DRIVE BURLINGTON ON L7M 1A8	NPCB

Company Code: O005276
Industry: OTHER
Site Status: NO MORE PCB'S ON THIS SITE
Transaction Date:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Inspection Date:					
38	13 of 21	NNE/152.1	125.3 / 1.57	RIEGER PRINTING INK CO LTD 3410 MAINWAY DRIVE BURLINGTON ON L7M 1A8	NPCB

Company Code: F1121
Industry:
Site Status:
Transaction Date: 1/29/1996
Inspection Date:

--Details--
Label:
Serial No.:
PCB Type/Code: Unknown concentration
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 235.00 KG

Label:
Serial No.:
PCB Type/Code: Askarel
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 545.00 KG

Label:
Serial No.:
PCB Type/Code: Unknown concentration
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 3058.00 KG

Label:
Serial No.:
PCB Type/Code: Low 50 - 10,000 ppm
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 4000.00 KG

Label:
Serial No.:
PCB Type/Code: Low 50 - 10,000 ppm
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 150.00 KG

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	14 of 21	NNE/152.1	125.3 / 1.57	RIEGER PRINTING INK CO LTD 3410 MAINWAY DRIVE BURLINGTON ON L7M 1A8	OPCB

Year: 1995
Site Number: 30290A038
Name Owner:
Additional Site Information:

--Details--
Quantity: 13.00
Address Site:
Description: Number of Capacitors with High Level PCBs (>1000 ppm)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	15 of 21	NNE/152.1	125.3 / 1.57	RIEGER PRINTING INK CO. LTD. 3410 MAINWAY DR. BURLINGTON ON L7M 1A8	REC

Rec Op Div:
Co Admin:
Phone No Admin:
Rec Div:
Rec Op Name:
Choice of Contact:
Site Bldg:
Site PO Box:
Receiver #:: 302-90A038
Facility Type: TRANSFER STATION
Approval Yrs:: 90,92,94,95,96,97,98,99,00,01,02,03,04,05,06,07,08

--Details--
Waste Code: 243
Waste Description: PCB'S

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	16 of 21	NNE/152.1	125.3 / 1.57	RIEGER PRINTING INK CO. LTD. 3410 MAINWAY DRIVE (SITE), C/O 4515-A CHESSWOOD DR., DOWNSVIEW M3J2V6 BURLINGTON ON L7M 1A8	REC

Rec Op Div:
Co Admin:
Phone No Admin:
Rec Div:
Rec Op Name:
Choice of Contact:
Site Bldg:
Site PO Box:
Receiver #:: A210111
Facility Type: TRANSFER STATION
Approval Yrs:: 87,88,89,90

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	17 of 21	NNE/152.1	125.3 / 1.57	RIEGER PRINTING INK CO. LTD. 3410 MAINWAY DRIVE, BURLINGTON C/O 4515 CHESSWOOD DRIVE, SUITE A DOWNSVIEW ON L7M 1A8	REC

Rec Op Div:
Co Admin:
Phone No Admin:
Rec Div:
Rec Op Name:
Choice of Contact:
Site Bldg:
Site PO Box:
Receiver #:: A210111
Facility Type: TRANSFER STATION - PROCESSING
Approval Yrs:: 92,93,94,95,96

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 999
Waste Description: ??? UNKNOWN WASTE CLASS ???

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	18 of 21	NNE/152.1	125.3 / 1.57	RIEGER PRINTING INK CO. LTD. 3410 MAINWAY DRIVE BURLINGTON ON L7M 1A8	REC

Rec Op Div:
Co Admin:
Phone No Admin:
Rec Div:
Rec Op Name:
Choice of Contact:
Site Bldg:
Site PO Box:
Receiver #:: A210111
Facility Type: TRANSFER STATION - PROCESSING
Approval Yrs:: 97,98,06,07,08

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	19 of 21	NNE/152.1	125.3 / 1.57	2210263 Ontario Inc. 3410 MAINWAY DR, BURLINGTON, ON, L7M 1A8, ON L7M 1A8	RSC

Reg No: 93116
RA No:
RSC Type:
Curr Property Use: Industrial
District Office: BURLINGTON
Date Submitted: 10-Dec-10
Date Ack:
Date Returned:
Restoration Type:
Soil Type:
Criteria:
Asmt Roll No: 2402-090-903-02406-0000

Cert Date: 4-Nov-10
Cert Prop Use No: No CPU
Intended Prop Use: Industrial
Nm of Qual. Person: Huucu Nguyen
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N): Yes
Accuracy Estimate: 6 to 10 meters
Telephone: 416-3989980
Fax: 416-3981485
Email:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Prop. ID No: 07163-0072 LT
CPU Issued Sect 1686: No
Property Municipal Address: 3410 MAINWAY DR, BURLINGTON, ON, L7M 1A8,
Mailing Address: 1315 Finch Avenue West, Suite 503, Toronto, ON M3J 3G6
Latitude & Latitude: 43.36776110N 79.79875440W (converted from UTM)
UTM Coordinates: NAD83 17-597326-4802356
Consultant:
Filing Owner:
Legal Desc: PT LT 12, CON 2 SOUTH OF DUNDAS STREET, PART 8, 20R311, BURLINGTON/NELSON TWP
Measurement Method: Digitized from a satellite image
Applicable Standards: Full Depth Site Conditions Standard, with Nonpotable Ground Water, Medium/Fine Textured Soil, for Industrial/Commercial/Community property use
RSC PDF:

38	20 of 21	NNE/152.1	125.3 / 1.57	**Rieger Printing Ink Co. Ltd.** **3410 Mainway** **Burlington ON L7M 1A8**	SCT

Established: 1945
Plant Size (ft²): 32000
Employment:

--Details--
Description: Other Printing
SIC/NAICS Code: 323119

Description: Printing Ink Manufacturing
SIC/NAICS Code: 325910

38	21 of 21	NNE/152.1	125.3 / 1.57	**RIEGER PRINTING INK CO. LTD.** **3410 MAINWAY DR** **BURLINGTON ON L7M 1A8**	SCT

Established: 1945
Plant Size (ft²): 32000
Employment: 30

--Details--
Description: PRINTING INK
SIC/NAICS Code: 2893

Description: Printing Ink Manufacturing
SIC/NAICS Code: 325910

39	1 of 4	NW/156.3	125.8 / 2.07	**MODULAR CONTROLS LIMITED** **3339 MAINWAY** **BURLINGTON ON L7M 1A6**	GEN

Generator No.: ON0293500
Status:
Approval Years: 98
Contam. Facility:
MHSW Facility:
SIC Code: 3081
SIC Description: MACHINE SHOP IND.
PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213

Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

39 **2 of 4** **NW/156.3** **125.8 / 2.07** **MODULAR CONTROLS LTD.** **GEN**
3339 MAINWAY
BURLINGTON ON L7M 1A6

Generator No.: ON0293500
Status:
Approval Years: 89,90
Contam. Facility:
MHSW Facility:
SIC Code: 3081
SIC Description: MACHINE SHOP IND.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

39 **3 of 4** **NW/156.3** **125.8 / 2.07** **MODULAR CONTROLS LTD.** **27-010** **GEN**
3339 MAINWAY
BURLINGTON ON L7M 1A6

Generator No.: ON0293500
Status:
Approval Years: 92,93,94,95,96,97
Contam. Facility:
MHSW Facility:
SIC Code: 3081
SIC Description: MACHINE SHOP IND.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

39 **4 of 4** **NW/156.3** **125.8 / 2.07** **MODULAR CONTROLS LTD** **GEN**
3339 MAINWAY
BURLINGTON ON L7M 1A6

Generator No.: ON0293500
Status:
Approval Years: 86,87,88

PO Box No.:
Country:
Choice of Contact:

Contam. Facility:
MHSW Facility:
SIC Code: 3081
SIC Description: MACHINE SHOP IND.
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

---

40 | **1 of 2** | **W/157.4** | **123.6 / -0.22** | **lot 13 con 2 BURLINGTON ON** | **WWIS**

Well ID: 2810161
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z24175
Tag: A016904
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:
Data Entry Status:
Data Src:
Date Received: 2/7/2005
Selected Flag: 1
Abandonment Rec:
Contractor: 6607
Form Version: 3
Owner:
Street Name: 3267 MAINWAY
County: HALTON
Municipality: BURLINGTON CITY
Site Info:
Lot: 013
Concession: 02
Concession Name: DS S
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 11319116
DP2BR: 5
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Elevation: 124.180473
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Spatial Status:
Cluster Kind:
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: org
Org CS: UTM83
Date Completed: 11/9/2004

Overburden and Bedrock Materials Interval

Formation ID: 933007131
Layer: 1
Color: 8
General Color: BLACK
Mat1:
Most Common Material:
Mat2:
Other Materials:

Mat3:
Other Materials:
Formation Top Depth: 0.00
Formation End Depth: 0.10
Formation End Depth UOM: m

Formation ID: 933007132
Layer: 2
Color: 2
General Color: GREY
Mat1: 11
Most Common Material: GRAVEL
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 0.10
Formation End Depth: 0.30
Formation End Depth UOM: m

Formation ID: 933007133
Layer: 3
Color: 7
General Color: RED
Mat1: 06
Most Common Material: SILT
Mat2: 11
Other Materials: GRAVEL
Mat3:
Other Materials:
Formation Top Depth: 0.30
Formation End Depth: 1.50
Formation End Depth UOM: m

Formation ID: 933007134
Layer: 4
Color: 7
General Color: RED
Mat1: 17
Most Common Material: SHALE
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 1.50
Formation End Depth: 6.00
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933265480
Layer: 1
Plug From: 0.00
Plug To: 0.15
Plug Depth UOM: m

Plug ID: 933265482
Layer: 2
Plug From: 0.15
Plug To: 1.20
Plug Depth UOM: m

Plug ID: 933265481
Layer: 3

Plug From:	1.20
Plug To:	6.00
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	962810161
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	11333971
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930860112
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.00
Depth To:	1.50
Casing Diameter:	5.10
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	933411785
Layer:	1
Slot:	10
Screen Top Depth:	1.50
Screen End Depth:	6.00
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.40

Hole Diameter

Hole ID:	11537677
Diameter:	21.00
Depth From:	0.00
Depth To:	6.00
Hole Depth UOM:	m
Hole Diameter UOM:	cm

40	***2 of 2***	***W/157.4***	***123.6 / -0.22***	***lot 13 con 2 BURLINGTON ON***	***WWIS***

Well ID:	2810125	**Data Entry Status:**	
Construction Date:		**Data Src:**	1
Primary Water Use:		**Date Received:**	12/9/2004
Sec. Water Use:		**Selected Flag:**	1
Final Well Status:	Observation Wells	**Abandonment Rec:**	
Water Type:		**Contractor:**	6607

Casing Material:		**Form Version:**	3
Audit No:	Z21563	**Owner:**	
Tag:	A016904	**Street Name:**	3267 MAINWAY
Construction Method:		**County:**	HALTON
Elevation (m):		**Municipality:**	BURLINGTON CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	013
Well Depth:		**Concession:**	02
Overburden/Bedrock:		**Concession Name:**	DS S
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	11174742	**Spatial Status:**	
DP2BR:	5	**Cluster Kind:**	
Code OB:	r	**UTMRC:**	4
Code OB Desc:	Bedrock	**UTMRC Desc:**	margin of error : 30 m - 100 m
Open Hole:		**Location Method:**	wwr
Elevation:	124.165718	**Org CS:**	UTM83
Elevrc:		**Date Completed:**	11/4/2004
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	932975084
Layer:	1
Color:	8
General Color:	BLACK
Mat1:	27
Most Common Material:	OTHER
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0.00
Formation End Depth:	0.10
Formation End Depth UOM:	m

Formation ID:	932975085
Layer:	2
Color:	2
General Color:	GREY
Mat1:	11
Most Common Material:	GRAVEL
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0.10
Formation End Depth:	0.30
Formation End Depth UOM:	m

Formation ID:	932975086

Layer:	3
Color:	7
General Color:	RED
Mat1:	06
Most Common Material:	SILT
Mat2:	11
Other Materials:	GRAVEL
Mat3:	73
Other Materials:	HARD
Formation Top Depth:	0.30
Formation End Depth:	1.50
Formation End Depth UOM:	m

Formation ID:	932975087
Layer:	4
Color:	7
General Color:	RED
Mat1:	17
Most Common Material:	SHALE
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	1.50
Formation End Depth:	6.00
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933256071
Layer:	1
Plug From:	0.00
Plug To:	0.15
Plug Depth UOM:	m

Plug ID:	933256072
Layer:	2
Plug From:	0.15
Plug To:	1.20
Plug Depth UOM:	m

Plug ID:	933256073
Layer:	3
Plug From:	1.20
Plug To:	6.00
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	962810125
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	11183261
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930846047
Layer:	2
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.00
Depth To:	1.50
Casing Diameter:	5.10
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	933409608
Layer:	1
Slot:	10
Screen Top Depth:	1.50
Screen End Depth:	6.00
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.40

Hole Diameter

Hole ID:	11308344
Diameter:	21.00
Depth From:	0.00
Depth To:	6.00
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

41 ***1 of 3*** ***WNW/157.8*** ***125.0 / 1.18*** ***GATES AIR SYSTEMS LTD.***
3317 MAINWAY DRIVE
BURLINGTON ON L7M 1A6 ***GEN***

Generator No.:	ON1735400	***PO Box No.:***	
Status:		***Country:***	
Approval Years:	93,94,95,96,97,98	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No. Admin:***	
SIC Code:	3121		
SIC Description:	COMM. REFRIG. EQUIP.		

--Details--

Waste Code:	252
Waste Description:	WASTE OILS & LUBRICANTS

---

41 ***2 of 3*** ***WNW/157.8*** ***125.0 / 1.18*** ***ORGANIZERS PLUS***
3317 Mainway Dr Unit C
Burlington ON L7M 1A6 ***SCT***

Established:	1986
Plant Size (ft²):	1200
Employment:	3

--Details--

Description:	Other Millwork

SIC/NAICS Code: 321919

Description: Wood Kitchen Cabinet and Counter Top Manufacturing
SIC/NAICS Code: 337110

---

41 | ***3 of 3*** | ***WNW/157.8*** | ***125.0 / 1.18*** | ***Halton Sheet Metal Ltd.***
3317 Mainway Dr
Burlington ON L7M 1A6 | ***SCT***

Established: 1994
Plant Size (ft²): 3002
Employment: 15

--Details--
Description: Coating, Engraving, Heat Treating and Allied Activities
SIC/NAICS Code: 332810

Description: Industrial and Commercial Fan and Blower and Air Purification Equipment Manufacturing
SIC/NAICS Code: 333413

---

42 | ***1 of 9*** | ***WSW/158.4*** | ***122.9 / -0.87*** | ***FibreCast Inc.***
3264 Mainway
Burlington ON L7M 1A7 | ***GEN***

Generator No.: ON9726997
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 327990
SIC Description: ALL OTHER NON-METALLIC MINERAL PRODUCT MANUFACTURING
PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 243
Waste Description: PCBS

---

42 | ***2 of 9*** | ***WSW/158.4*** | ***122.9 / -0.87*** | ***FibreCast Inc.***
3264 Mainway
Burlington ON L7M 1A7 | ***GEN***

Generator No.: ON9726997
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
PO Box No.:
Country: Canada
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252 L
Waste Description: Waste crankcase oils and lubricants

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	3 of 9	WSW/158.4	122.9 / -0.87	AISCO SYSTEMS LIMITED 3264 MAINWAY BURLINGTON ON L7R 3Y5	GEN

Generator No.: ON0386500
Status:
Approval Years: 99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 3199
SIC Description: OTHER MACHINERY

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 232
Waste Description: POLYMERIC RESINS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	4 of 9	WSW/158.4	122.9 / -0.87	AISCO INC. 3264 MAINWAY P.O. BOX 655 BURLINGTON ON L7M 1A7	GEN

Generator No.: ON0386500
Status:
Approval Years: 86,87,88,89
Contam. Facility:
MHSW Facility:
SIC Code: 0000
SIC Description: *** NOT DEFINED ***

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	5 of 9	WSW/158.4	122.9 / -0.87	AISCO SYSTEMS LTD. 3264 MAINWAY P.O. BOX 655 BURLINGTON ON L7M 1A7	GEN

Generator No.: ON0386500
Status:
Approval Years: 90
Contam. Facility:
MHSW Facility:
SIC Code: 3199
SIC Description: OTHER MACHINERY

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

---

42 **6 of 9** **WSW/158.4** **122.9 / -0.87** **AISCO SYSTEMS LIMITED** **01-392** **GEN**
3264 MAINWAY
BURLINGTON ON L7R 3Y5

Generator No.: ON0386500
Status:
Approval Years: 92,93,94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 3199
SIC Description: OTHER MACHINERY

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 232
Waste Description: POLYMERIC RESINS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

---

42 **7 of 9** **WSW/158.4** **122.9 / -0.87** **AISCO SYSTEMS INC.** **SCT**
3264 MAINWAY DR
BURLINGTON ON L7M 1A7

Established: 1973
Plant Size (ft²): 40000
Employment: 120

--Details--
Description: INDUSTRIAL TRUCKS, TRACTORS, TRAILERS, AND STACKERS
SIC/NAICS Code: 3537

Description: SPECIAL INDUSTRY MACHINERY, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3559

Description: SERVICE INDUSTRY MACHINERY, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3589

Description: INDUSTRIAL AND COMMERCIAL MACHINERY AND EQUIPMENT, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3599

---

42 **8 of 9** **WSW/158.4** **122.9 / -0.87** **Fibrecast Inc.** **SCT**
3264 Mainway
Burlington ON L7M 1A7

Established: 01-AUG-93
Plant Size (ft²): 30000
Employment:

--Details--
Description: Engineering Services
SIC/NAICS Code: 541330

Description: Clay Building Material and Refractory Manufacturing
SIC/NAICS Code: 327120

Description: Other Specialty-Line Building Supplies Wholesaler-Distributors
SIC/NAICS Code: 416390

Description: All Other Textile Product Mills
SIC/NAICS Code: 314990

Description: Urethane and Other Foam Product (except Polystyrene) Manufacturing
SIC/NAICS Code: 326150

Description: Polystyrene Foam Product Manufacturing
SIC/NAICS Code: 326140

Description: All Other Non-Metallic Mineral Product Manufacturing
SIC/NAICS Code: 327990

Description: Clay Building Material and Refractory Manufacturing
SIC/NAICS Code: 327120

Description: Plumbing, Heating and Air-Conditioning Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 416120

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	9 of 9	WSW/158.4	122.9 / -0.87	**FIBRECAST INC.** **3264 Mainway Dr** **Burlington ON L7M 1A7**	SCT

Established: 1993
Plant Size (ft²): 30000
Employment: 30

--Details--
Description: All Other Textile Product Mills
SIC/NAICS Code: 314990

Description: Polystyrene Foam Product Manufacturing
SIC/NAICS Code: 326140

Description: Urethane and Other Foam Product (except Polystyrene) Manufacturing
SIC/NAICS Code: 326150

Description: Clay Building Material and Refractory Manufacturing
SIC/NAICS Code: 327120

Description: All Other Non-Metallic Mineral Product Manufacturing
SIC/NAICS Code: 327990

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
43	1 of 7	S/160.4	120.8 / -2.97	**REHAU INDUSTRIES INC.** **1149 PIONEER ROAD** **BURLINGTON CITY ON L7M 1K5**	CA

Certificate #:	8-3097-93-
Application Year:	93
Issue Date:	3/17/1993
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name::	
Client Address::	
Client City::	
Client Postal Code::	
Project Description::	REVOKE EXISTING COFA #8/300/077/89/917
Contaminants::	
Emission Control::	

---

43 | ***2 of 7*** | ***S/160.4*** | ***120.8 / -2.97*** | ***1149 Pioneer Road Burlington ON L7M 1K5*** | ***EHS***

Order ID:	169516	**Date Received:**	11/9/2009
Order No:	20091109003	**Lot/Building Size:**	
Customer ID:	78549	**Municipality:**	
Company ID:	20784	**Client Prov/State:**	ON
Status:	C	**Search Radius (km):**	0.25
Report Code:	3CAN	**Large Radius:**	2
Report Type:	Standard Report	**X:**	-79.799925
Report Date:	11/17/2009	**Y:**	43.363449
Report Requested by:	MTE Consultants Inc.		
Nearest Intersection:			
Previous Site Name:			
Additional Info Ordered:	City Directory		

---

43 | ***3 of 7*** | ***S/160.4*** | ***120.8 / -2.97*** | ***REHAU INDUSTRIES INC. 1149 PIONEER ROAD BURLINGTON ON L7M 1K5*** | ***GEN***

Generator No.:	ON0492101	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	92,93,97,98,99,00,01	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	3731		
SIC Description:	PLASTIC & SYN. RESIN		

--Details--

Waste Code:	212
Waste Description:	ALIPHATIC SOLVENTS
Waste Code:	213
Waste Description:	PETROLEUM DISTILLATES
Waste Code:	232
Waste Description:	POLYMERIC RESINS
Waste Code:	252
Waste Description:	WASTE OILS & LUBRICANTS

---

43 | ***4 of 7*** | ***S/160.4*** | ***120.8 / -2.97*** | ***REHAU INDUSTRIES INC. 1149 PIONEER RD. BURLINGTON ON L7M 1K5*** | ***33-227*** | ***GEN***

Generator No.:	ON0492101	**PO Box No.:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: | **Country:**
Approval Years: 94,95,96 | **Choice of Contact:**
Contam. Facility: | **Co Admin:**
MHSW Facility: | **Phone No. Admin:**
SIC Code: 3731
SIC Description: PLASTIC & SYN. RESIN

--Details--
Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 232
Waste Description: POLYMERIC RESINS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
43	5 of 7	S/160.4	120.8 / -2.97	REHAU INDUSTRIES INC. 1149 PIONEER RD. BURLINGTON ON L7M 1K5	GEN

Generator No.: ON0492101 | **PO Box No.:**
Status: | **Country:**
Approval Years: 86,87,88,89 | **Choice of Contact:**
Contam. Facility: | **Co Admin:**
MHSW Facility: | **Phone No. Admin:**
SIC Code: 3731
SIC Description: PLASTIC & SYN. RESIN

--Details--
Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 232
Waste Description: POLYMERIC RESINS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
43	6 of 7	S/160.4	120.8 / -2.97	Rehau Industries Inc. 1149 Pioneer Rd Burlington ON L7M 1K5	SCT

Established: 01-AUG-52
Plant Size (ft²): 28000
Employment:

--Details--
Description: Lumber, Plywood and Millwork Wholesaler-Distributors
SIC/NAICS Code: 416320

Description: Plumbing, Heating and Air-Conditioning Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 416120

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
SIC/NAICS Code: 418410

Description: Metal Service Centres
SIC/NAICS Code: 416210

Description: Other New Motor Vehicle Parts and Accessories Wholesaler-Distributors
SIC/NAICS Code: 415290

Description: General-Line Building Supplies Wholesaler-Distributors
SIC/NAICS Code: 416310

Description: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
SIC/NAICS Code: 418410

---

43 | **7 of 7** | **S/160.4** | **120.8 / -2.97** | **REHAU INDUSTRIES INC. BURLINGTON PLANT 1149 PIONEER ROAD BURLINGTON CITY ON L7M 1K5** | **SPL**

Ref No: 57252
Site No:
Incident Dt: 9/13/1991
Year:
Incident Cause: VALVE/FITTING LEAK OR FAILURE
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Contaminant Qty:
Environment Impact: POSSIBLE
Nature of Impact: Soil contamination
Receiving Medium: LAND
Receiving Env:
Health/Env Conseq:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 9/13/1991
Dt Document Closed:
SAC Action Class:
Incident Reason: EQUIPMENT FAILURE
Incident Summary: REHAU INDUSTRIES-1000 L PLASTICIZER SPILLED TO DYKED DITCH.

Discharger Report:
Material Group:
Client Type:
Sector Type:
Source Type:
Nearest Watercourse:
Site Name:
Site Address:
Site District Office:
Site County/District:
Site Postal Code:
Site Region:
Site Municipality: 14101
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Geo Ref Meth:
Site Map Datum:

---

44 | **1 of 16** | **SE/166.2** | **120.3 / -3.51** | **QUADRA CHEMICALS LTD 1100 BLAIR RD BURLINGTON ON L7M 1K9** | **CHEM**

Headcode: 00273600
Headcode Desc: CHEMICALS
Phone:
List Name:
Description:

Head Office Province:
Head Office Postal:
Mailing Address:
Mailing Address 2:
Mailing City:

---

44 | **2 of 16** | **SE/166.2** | **120.3 / -3.51** | **1100 Blair Road Burlington ON L7M 1K9** | **EHS**

Order ID: 89936
Order No: 20061205023

Date Received: 12/5/2006
Lot/Building Size: 5.4 acres

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Customer ID:	23385	**Municipality:**	
Company ID:	20784	**Client Prov/State:**	ON
Status:	C	**Search Radius (km):**	0.35
Report Code:	3CAN	**Large Radius:**	2
Report Type:	Complete Report	**X:**	-79.797781
Report Date:	12/7/2006	**Y:**	43.364199
Report Requested by:	MTE Consultants Inc.		
Nearest Intersection:			
Previous Site Name:			
Additional Info Ordered:			

---

44 | ***3 of 16*** | ***SE/166.2*** | ***120.3 / -3.51*** | ***QUADRA CHEMICALS LTD.*** ***1100 BLAIR ROAD*** ***BURLINGTON ON L7M 1K9*** | ***32-219*** | ***GEN***

Generator No.:	ON1701200	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	92,93,94,95,96	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	3711		
SIC Description:	IND. INORGANIC CHEM.		

--Details--

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

---

44 | ***4 of 16*** | ***SE/166.2*** | ***120.3 / -3.51*** | ***QUADRA CHEMICALS LTD.*** ***1100 BLAIR ROAD*** ***BURLINGTON ON L7M 1K9*** | ***GEN***

Generator No.:	ON1701200	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	99,00,01,02,03,04,05,06,07,08	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	3711		
SIC Description:	IND. INORGANIC CHEM.		

--Details--

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 243
Waste Description: PCB'S

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
44	5 of 16	SE/166.2	120.3 / -3.51	QUADRA CHEMICALS LTD. 1100 Blair Road Burlington ON L7M 1K9	GEN

Generator No.: ON1701200
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 418410
SIC Description: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 243
Waste Description: PCBS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
44	6 of 16	SE/166.2	120.3 / -3.51	DOMINION (SEE & USE ON0199100 ACCO) CANADIAN MATERIAL HANDLING 1100 BLAIR RD. BURLINGTON ON L7M 1K9	GEN

Generator No.: ON0047300
Status:
Approval Years: 92,93
Contam. Facility:
MHSW Facility:
SIC Code: 0009
SIC Description: *** ERROR RECORD ***

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
44	7 of 16	SE/166.2	120.3 / -3.51	QUADRA CHEMICALS LTD. 1100 Blair Road Burlington ON L7M 1K9	GEN

Generator No.: ON1701200
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 418410
SIC Description: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 232
Waste Description: POLYMERIC RESINS

Waste Code: 243
Waste Description: PCBS

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

---

44 **8 of 16** **SE/166.2** **120.3 / -3.51** **ACCO CANADIAN MATERIAL HANDLING**
1100 BLAIR RD.
BURLINGTON ON L7M 1K9 **GEN**

Generator No.: ON0199100
Status:
Approval Years: 86,87,88,89
Contam. Facility:
MHSW Facility:
SIC Code: 3029
SIC Description: OTHER FAB. STRUCTURES

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

---

44 **9 of 16** **SE/166.2** **120.3 / -3.51** **ACCO CANADIAN MATERIAL HANDLING**
BABCOCK INDUSTRIES CANADA INC, A DIV. OF
1100 BLAIR ROAD
BURLINGTON ON L7M 1K9 **GEN**

Generator No.: ON0199100
Status:
Approval Years: 98
Contam. Facility:
MHSW Facility:
SIC Code: 3029
SIC Description: OTHER FAB. STRUCTURES

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
44	10 of 16	SE/166.2	120.3 / -3.51	QUADRA CHEMICALS LTD. 1100 Blair Road Burlington ON L7M 1K9	GEN

Generator No.: ON1701200
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 418410
SIC Description: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 232
Waste Description: POLYMERIC RESINS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 243
Waste Description: PCBS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
44	11 of 16	SE/166.2	120.3 / -3.51	ACCO CANADIAN MATERIAL HANDLING 01-019 A DIV. OF BABCOCK INDUSTRIES CANADA INC 1100 BLAIR ROAD BURLINGTON ON L7M 1K9	GEN

Generator No.: ON0199100
Status:
Approval Years: 92,93,94,95,96,97
Contam. Facility:
MHSW Facility:
SIC Code: 3029
SIC Description: OTHER FAB. STRUCTURE

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
44	12 of 16	SE/166.2	120.3 / -3.51	QUADRA CHEMICALS LTD. 1100 Blair Road Burlington ON L7M 1K9	GEN

Generator No.: ON1701200
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 418410
SIC Description: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 232
Waste Description: POLYMERIC RESINS

Waste Code: 243
Waste Description: PCBS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
44	13 of 16	SE/166.2	120.3 / -3.51	ACCO CANADIAN MATERIAL HANDLING A DIV. OF BABCOCK INDUSTRIES CANADA INC 1100 BLAIR ROAD BURLINGTON ON L7M 1K9	GEN

Generator No.: ON0199100
Status:
Approval Years: 90
Contam. Facility:
MHSW Facility:
SIC Code: 3029
SIC Description: OTHER FAB. STRUCTURE

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
44	14 of 16	SE/166.2	120.3 / -3.51	QUADRA CHEMICALS LTD 1100 BLAIR ROAD BURLINGTON ON L7M 1K9	GEN

Generator No.: ON1701200
Status:
Approval Years: 97,98
Contam. Facility:
MHSW Facility:
SIC Code: 3711
SIC Description: IND. INORGANIC CHEM.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
44	15 of 16	SE/166.2	120.3 / -3.51	Quadra Chemicals 1100 Blair Rd Burlington ON L7M 1K9	PAP

Division:
Mailing Address:: 1100 Blair Rd, Burlington ON L7M 1K9
Year: 2009
Company ID: 286407325
Mill Notes::
History::
Operation:
Type:
Status:: Inactive

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
44	16 of 16	SE/166.2	120.3 / -3.51	QUADRA CHEMICALS LTD. 1100 BLAIR ROAD BURLINGTON SITE 1100 BLAIR RD. BURLINGTON CITY ON L7M 1K9	SPL

Ref No: 90804
Site No:
Incident Dt: 9/3/1993
Year:
Incident Cause: BLADDER FAILURE
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Contaminant Qty:
Environment Impact: NOT ANTICIPATED
Nature of Impact:
Receiving Medium: LAND
Receiving Env:
Health/Env Conseq:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 9/3/1993
Dt Document Closed:
SAC Action Class:

Discharger Report:
Material Group:
Client Type:
Sector Type:
Source Type:
Nearest Watercourse:
Site Name:
Site Address:
Site District Office:
Site County/District:
Site Postal Code:
Site Region:
Site Municipality: 14101
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Geo Ref Meth:
Site Map Datum:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Incident Reason: WELD/SEAM FAILURE
Incident Summary: QUADRA CHEMICALS LTD. - 15 KG SODIUM DICHROMATE DIHYDRATE TO DRIVEWAY

---

45 **1 of 6** **WNW/166.2** **124.8 / 1.07** **BROWN FALCON MACHINE & TOOL** **GEN**
3295 MAINWAY UNIT 6
BURLINGTON ON L7M 1A6

Generator No.: ON1270700
Status:
Approval Years: 89
Contam. Facility:
MHSW Facility:
SIC Code: 0000
SIC Description: *** NOT DEFINED ***

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

---

45 **2 of 6** **WNW/166.2** **124.8 / 1.07** **BROWN FALCON MAC(OUT OF BUSINESS) 05-352** **GEN**
3295 MAINWAY UNIT 6
BURLINGTON ON L7M 1A6

Generator No.: ON1270700
Status:
Approval Years: 92,93,94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 2921
SIC Description: STEEL PIPE & TUBE

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

---

45 **3 of 6** **WNW/166.2** **124.8 / 1.07** **Tymatic Controls - Div. of Tyrrell Air Controls Ltd.** **SCT**
3295 Mainway Unit 6
Burlington ON L7M 1A6

Established: 1981
Plant Size (ft²): 3000
Employment: 10

--Details--
Description: Measuring, Medical and Controlling Devices Manufacturing
SIC/NAICS Code: 334512

Description: Switchgear and Switchboard, and Relay and Industrial Control Apparatus Manufacturing
SIC/NAICS Code: 335315

Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

---

45 **4 of 6** **WNW/166.2** **124.8 / 1.07** **ERODALL LTD.** **SCT**
3295 MAINWAY DR UNIT 3
BURLINGTON ON L7M 1A6

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Established: 1965
Plant Size (ft²): 10000
Employment: 7

--Details--
Description: Machine Shops
SIC/NAICS Code: 332710

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
45	5 of 6	WNW/166.2	124.8 / 1.07	Erodall Ltd. 3295 Mainway Unit 3 Burlington ON L7M 1A6	SCT

Established: 01-AUG-65
Plant Size (ft²): 3200
Employment:

--Details--
Description: Machine Shops
SIC/NAICS Code: 332710

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
45	6 of 6	WNW/166.2	124.8 / 1.07	RAINBOW CERAMICS 3295 Mainway Unit 1 Burlington ON L7M 1A6	SCT

Established: 1983
Plant Size (ft²): 4000
Employment: 3

--Details--
Description: Pottery, Ceramics and Plumbing Fixture Manufacturing
SIC/NAICS Code: 327110

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
46	1 of 2	NW/167.9	125.8 / 2.07	METAL EQUIPMENT SERVICES LTD. 3337 MAINWAY DRIVE BURLINGTON ON L7M 1A6	GEN

Generator No.: ON2257000
Status:
Approval Years: 97,98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 3081
SIC Description: MACHINE SHOP IND.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
46	2 of 2	NW/167.9	125.8 / 2.07	METAL EQUIPMENT SERVICES LTD. 3337 MAINWAY DR BURLINGTON ON L7M 1A6	SCT

Established: 1981
Plant Size (ft²): 0

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Employment: 5

--Details--
Description: WOOD OFFICE AND STORE FIXTURES, PARTITIONS, SHELVING, AND LOCKERS
SIC/NAICS Code: 2541

Description: Showcase, Partition, Shelving and Locker Manufacturing
SIC/NAICS Code: 337215

---

47 ***1 of 7*** ***NE/168.6*** ***123.1 / -0.63*** ***3424 Landmark Road Burlington ON L7M 1S8*** ***EHS***

Order ID: 152090
Order No: 20080924019
Customer ID: 73027
Company ID: 20784
Status: C
Report Code: 3CAN
Report Type: Standard Report
Report Date: 10/2/2008
Report Requested by: MTE Consultants Inc.
Nearest Intersection: Blair Road & Landmark Road
Previous Site Name:
Additional Info Ordered:

Date Received: 9/24/2008
Lot/Building Size:
Municipality: Halton
Client Prov/State: ON
Search Radius (km): 0.25
Large Radius: 2
X: -79.797243
Y: 43.366803

---

47 ***2 of 7*** ***NE/168.6*** ***123.1 / -0.63*** ***HUMPTY DUMPTY FOODS LTD 3424 LANDMARK RD BURLINGTON ON*** ***EXP***

Instance No: 9402720
Instance ID: 382452
Instance Type: FS Facility
Description: Fuels Safety Private Fuel Outlet - Self Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

47 ***3 of 7*** ***NE/168.6*** ***123.1 / -0.63*** ***HUMPTY DUMPTY FOODS LTD 3424 LANDMARK RD BURLINGTON ON L7M 1S8*** ***EXP***

Instance No: 10632157
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description:
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date: 6/2/1993

---

47 ***4 of 7*** ***NE/168.6*** ***123.1 / -0.63*** ***HUMPTY DUMPTY FOODS LTD 3424 LANDMARK RD BURLINGTON ON*** ***EXP***

Instance No: 10632184

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance ID: 32009
Instance Type: FS Piping
Description: FS Piping
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
47	5 of 7	NE/168.6	123.1 / -0.63	HUMPTY DUMPTY FOODS LTD 3424 LANDMARK RD BURLINGTON ON L7M 1S8	EXP

Instance No: 10632157
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: Fuels Safety Private Fuel Outlet - Self Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 6/2/1993

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
47	6 of 7	NE/168.6	123.1 / -0.63	HUMPTY DUMPTY FOODS LTD 3424 LANDMARK RD BURLINGTON ON L7M 1S8	PRT

Location ID: 2451
Type: private
Expiry Date:
Capacity (L): 13638.00
Licence #: 0001055665

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
47	7 of 7	NE/168.6	123.1 / -0.63	SMALL FRY SNACK FOODS INC. 3424 LANDMARK RD BURLINGTON ON L7M 1S8	SCT

Established: 1994
Plant Size (ft²): 0
Employment: 18

--Details--
Description: CONFECTIONERY
SIC/NAICS Code: 5145

Description: GROCERIES & RELATED PRODUCTS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 5149

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
48	1 of 8	SE/169.5	120.0 / -3.78	QUADRA CHEMICALS LTD 1100 BLAIR RD BURLINGTON ON L7M1K9	CHEM

Headcode: 00273600
Headcode Desc: CHEMICALS
Phone: 9053360052
List Name: INFO-DIRECT(TM) BUSINESS FILE
Description:
Head Office Province:
Head Office Postal:
Mailing Address:
Mailing Address 2:
Mailing City:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
48	2 of 8	SE/169.5	120.0 / -3.78	QUADRA CHEMICALS LTD 1100 BLAIR RD BURLINGTON ON L7M1K9	CHEM

Headcode: 00273600
Headcode Desc: CHEMICALS
Phone: 9053369133
List Name: Info-direct(TM) BUSINESS FILE
Description:

Head Office Province:
Head Office Postal:
Mailing Address:
Mailing Address 2:
Mailing City:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
48	3 of 8	SE/169.5	120.0 / -3.78	QUADRA CHEMICALS LTD 1100 BLAIR RD BURLINGTON ON L7M1K9	CHEM

Headcode: 00273600
Headcode Desc: CHEMICALS
Phone: 9053369133
List Name:
Description:

Head Office Province:
Head Office Postal:
Mailing Address:
Mailing Address 2:
Mailing City:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
48	4 of 8	SE/169.5	120.0 / -3.78	QUADRA CHEMICALS LTD. 1100 Blair Road Burlington ON L7M 1K9	GEN

Generator No.: ON1701200
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 418410
SIC Description: CHEMICAL (EXCEPT AGRICULTURAL) AND ALLIED PRODUCT WHOLESALER-DISTRIBUTORS

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Walter Banas
Phone No. Admin: 9055923560 Ext.

--Details--

Waste Code: 267
Waste Description: ORGANIC ACIDS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 222
Waste Description: HEAVY FUELS

Waste Code: 262
Waste Description: DETERGENTS/SOAPS

Waste Code: 243
Waste Description: PCBS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 268
Waste Description: AMINES

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 232
Waste Description: POLYMERIC RESINS

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 265
Waste Description: GRAPHIC ART WASTES

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

---

48 | ***5 of 8*** | ***SE/169.5*** | ***120.0 / -3.78*** | ***QUADRA CHEMICALS LTD.***
1100 Blair Road
Burlington ON L7M 1K9 | ***GEN***

Generator No.: ON1701200
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country: Canada
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 265 I
Waste Description: Graphic arts wastes

Waste Code: 267 C
Waste Description: Organic acids

Waste Code: 265 B
Waste Description: Graphic arts wastes

Waste Code: 265 L
Waste Description: Graphic arts wastes

Waste Code: 222 L
Waste Description: Heavy fuels

Waste Code: 252 L
Waste Description: Waste crankcase oils and lubricants

Waste Code: 146 T
Waste Description: Other specified inorganic sludges, slurries or solids

Waste Code: 148 T
Waste Description: Misc. wastes and inorganic chemicals

Waste Code: 148 R
Waste Description: Misc. wastes and inorganic chemicals

Waste Code: 148 C
Waste Description: Misc. wastes and inorganic chemicals

Waste Code: 212 L
Waste Description: Aliphatic solvents and residues

Waste Code: 122 L
Waste Description: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Code: 122 C
Waste Description: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Code: 251 L
Waste Description: Waste oils/sludges (petroleum based)

Waste Code: 211 B
Waste Description: Aromatic solvents and residues

Waste Code: 263 B
Waste Description: Misc. waste organic chemicals

Waste Code: 263 I
Waste Description: Misc. waste organic chemicals

Waste Code: 263 C
Waste Description: Misc. waste organic chemicals

Waste Code: 268 L
Waste Description: Amines

Waste Code: 148 L
Waste Description: Misc. wastes and inorganic chemicals

Waste Code: 213 I
Waste Description: Petroleum distillates

Waste Code: 212 I
Waste Description: Aliphatic solvents and residues

Waste Code: 148 I
Waste Description: Misc. wastes and inorganic chemicals

Waste Code: 232 L
Waste Description: Polymeric resins

Waste Code: 263 L
Waste Description: Misc. waste organic chemicals

Waste Code: 268 I
Waste Description: Amines

Waste Code: 268 C
Waste Description: Amines

Waste Code: 232 R
Waste Description: Polymeric resins

Waste Code: 211 H
Waste Description: Aromatic solvents and residues

Waste Code: 262 L
Waste Description: Detergents and soaps

Waste Code: 212 B
Waste Description: Aliphatic solvents and residues

Waste Code: 145 H
Waste Description: Wastes from the use of pigments, coatings and paints

---

48 **6 of 8** **SE/169.5** **120.0 / -3.78** **QUADRA CHEMICALS LTD.** **GEN**
1100 Blair Road
Burlington ON L7M 1K9

Generator No.: ON1701200
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 418410
SIC Description: CHEMICAL (EXCEPT AGRICULTURAL) AND ALLIED PRODUCT WHOLESALER-DISTRIBUTORS

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Walter Banas
Phone No. Admin: 9055923560 Ext.

--Details--

Waste Code: 222
Waste Description: HEAVY FUELS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 268
Waste Description: AMINES

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 243
Waste Description: PCBS

Waste Code: 232
Waste Description: POLYMERIC RESINS

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 267
Waste Description: ORGANIC ACIDS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 265
Waste Description: GRAPHIC ART WASTES

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
48	7 of 8	SE/169.5	120.0 / -3.78	QUADRA CHEMICALS LTD. 1100 Blair Road Burlington ON L7M 1K9	GEN

Generator No.: ON1701200
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 418410
SIC Description: CHEMICAL (EXCEPT AGRICULTURAL) AND ALLIED PRODUCT WHOLESALER-DISTRIBUTORS

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Walter Banas
Phone No. Admin: 9055923560 Ext.

--Details--

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 232
Waste Description: POLYMERIC RESINS

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 243
Waste Description: PCBS

Waste Code: 265
Waste Description: GRAPHIC ART WASTES

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 267
Waste Description: ORGANIC ACIDS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
48	8 of 8	SE/169.5	120.0 / -3.78	QUADRA CHEMICALS LTD. 1100 Blair Road Burlington ON	GEN

Generator No.: ON1701200
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 418410
SIC Description: CHEMICAL (EXCEPT AGRICULTURAL) AND ALLIED PRODUCT WHOLESALER-DISTRIBUTORS

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--

Waste Code: 232
Waste Description: POLYMERIC RESINS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 267
Waste Description: ORGANIC ACIDS

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 243
Waste Description: PCBS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

---

49 **1 of 1** **ENE/171.6** **122.8 / -0.96** **Burlington ON** **WWIS**

Well ID:	7122411	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring	**Date Received:**	4/28/2009
Sec. Water Use:		**Selected Flag:**	1
Final Well Status:	Test Hole	**Abandonment Rec:**	
Water Type:		**Contractor:**	7238
Casing Material:		**Form Version:**	5
Audit No:	M02358	**Owner:**	
Tag:	A079525	**Street Name:**	3424 LANDMARK RD.
Construction Method:		**County:**	HALTON
Elevation (m):		**Municipality:**	BURLINGTON CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1002420270	**Spatial Status:**	
DP2BR:		**Cluster Kind:**	
Code OB:		**UTMRC:**	4
Code OB Desc:		**UTMRC Desc:**	margin of error : 30 m - 100 m
Open Hole:	N	**Location Method:**	wwr
Elevation:	122.934135	**Org CS:**	UTM83
Elevrc:		**Date Completed:**	2/10/2009
Remarks:			
Elevrc Desc:			

Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1002756285
Layer: 1
Color: 8
General Color: BLACK
Mat1: 02
Most Common Material: TOPSOIL
Mat2:
Other Materials:
Mat3: 79
Other Materials: PACKED
Formation Top Depth: 0.00
Formation End Depth: 0.30
Formation End Depth UOM: m

Formation ID: 1002756286
Layer: 2
Color: 7
General Color: RED
Mat1: 06
Most Common Material: SILT
Mat2:
Other Materials:
Mat3: 73
Other Materials: HARD
Formation Top Depth: 0.30
Formation End Depth: 2.72
Formation End Depth UOM: m

Formation ID: 1002756287
Layer: 3
Color: 7
General Color: RED
Mat1: 17
Most Common Material: SHALE
Mat2:
Other Materials:
Mat3: 73
Other Materials: HARD
Formation Top Depth: 2.72
Formation End Depth: 6.06
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1002756289
Layer: 1
Plug From: 0.00
Plug To: 0.30
Plug Depth UOM: m

Plug ID: 1002756290
Layer: 2
Plug From: 0.30
Plug To: 2.72

Plug Depth UOM:	m
Plug ID:	1002756291
Layer:	3
Plug From:	2.72
Plug To:	6.06
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1002756295
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	AUGER

Pipe Information

Pipe ID:	1002756283
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Screen

Screen ID:	1002756293
Layer:	1
Slot:	10
Screen Top Depth:	
Screen End Depth:	
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.00

Results of Well Yield Testing

Pump Test ID:	1002756284
Pump Set At:	
Static Level:	4.80
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	
Water State After Test Code:	0
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1002756292
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	4.80
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1002756288
Diameter:	23.00
Depth From:	0.00
Depth To:	6.06
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1002756265	***Spatial Status:***	
DP2BR:		***Cluster Kind:***	This is a record from cluster log sheet
Code OB:		***UTMRC:***	3
Code OB Desc:		***UTMRC Desc:***	margin of error : 10 - 30 m
Open Hole:		***Location Method:***	wwr
Elevation:	123.223808	***Org CS:***	UTM83
Elevrc:		***Date Completed:***	2/9/2009
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002756269
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1002756268
Method Construction Code:	
Method Construction:	
Other Method Construction:	BORING

Pipe Information

Pipe ID:	1002756270
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002756272
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	3.03
Casing Diameter:	
Casing Diameter UOM:	

Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002756271
Layer:
Slot:
Screen Top Depth: 2.27
Screen End Depth: 5.30
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002756273
Pump Set At:
Static Level: 3.31
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002756267
Diameter: 23.00
Depth From:
Depth To: 5.30
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002756274
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 122.836738
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 2/10/2009

Annular Space/Abandonment Sealing Record

Plug ID: 1002756278
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002756277
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1002756279
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002756281
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 2.42
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002756280
Layer:
Slot:
Screen Top Depth: 1.51
Screen End Depth: 4.54
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002756282
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:

Flowing:

Hole Diameter

Hole ID: 1002756276
Diameter: 23.00
Depth From:
Depth To: 4.54
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002756256
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 122.934135
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 2/9/2009

Annular Space/Abandonment Sealing Record

Plug ID: 1002756260
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002756259
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1002756261
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002756263
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 3.93
Casing Diameter:

Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002756262
Layer:
Slot:
Screen Top Depth: 3.03
Screen End Depth: 6.06
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002756264
Pump Set At:
Static Level: 4.83
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002756258
Diameter: 23.00
Depth From:
Depth To: 6.81
Hole Depth UOM: m
Hole Diameter UOM: cm

---

50 | ***1 of 11*** | ***NNW/171.9*** | ***125.8 / 2.07*** | ***TOROMONT INDUSTRIES LTD***
3385 MAINWAY
BURLINGTON ON L7M 1A6 | ***GEN***

Generator No.: ON4592875
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country: Canada
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 221 I
Waste Description: Light fuels

Waste Code: 252 L
Waste Description: Waste crankcase oils and lubricants

Waste Code: 213 T
Waste Description: Petroleum distillates

Waste Code: 213 I
Waste Description: Petroleum distillates

---

50 **2 of 11** **NNW/171.9** **125.8 / 2.07** **KINGSBURY MACHINE TOOL (CDA) LTD** **GEN**
3385 MAINWAY DRIVE
BURLINGTON ON L7M 1A6

Generator No.: ON0337400
Status:
Approval Years: 86,87,88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 3199
SIC Description: OTHER MACHINERY

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

50 **3 of 11** **NNW/171.9** **125.8 / 2.07** **KINGSBURY MACHINE TOOL (CANADA) LIMITED** **GEN**
3385 MAINWAY DRIVE
BURLINGTON ON L7M 1A6

Generator No.: ON0337400
Status:
Approval Years: 98,99
Contam. Facility:
MHSW Facility:
SIC Code: 3199
SIC Description: OTHER MACHINERY

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 251

Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

50 | ***4 of 11*** | ***NNW/171.9*** | ***125.8 / 2.07*** | ***KINGSBURY CANADA INC.***
3385 MAINWAY DRIVE
BURLINGTON ON L7M 1A6 | ***GEN***

Generator No.: ON0337400
Status:
Approval Years: 00,01
Contam. Facility:
MHSW Facility:
SIC Code: 3199
SIC Description: OTHER MACHINERY

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

50 | ***5 of 11*** | ***NNW/171.9*** | ***125.8 / 2.07*** | ***KINGSBURY MACHINE TOOL (CDA) LTD 23-070***
3385 MAINWAY DRIVE
BURLINGTON ON L7M 1A6 | ***GEN***

Generator No.: ON0337400
Status:
Approval Years: 94,95,96
Contam. Facility:
MHSW Facility:
SIC Code: 3199
SIC Description: OTHER MACHINERY

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 253
Waste Description: EMULSIFIED OILS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

---

50 | **6 of 11** | **NNW/171.9** | **125.8 / 2.07** | **KINGSBURY MACHINE TOOL (CDA) LTD.**
3385 MAINWAY DRIVE
BURLINGTON ON L7M 1A6 | **GEN**

Generator No.: ON0337400
Status:
Approval Years: 92,93,97
Contam. Facility:
MHSW Facility:
SIC Code: 3199
SIC Description: OTHER MACHINERY

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

---

50 | **7 of 11** | **NNW/171.9** | **125.8 / 2.07** | **KINGSBURY CANADA INC.**
3385 MAINWAY
BURLINGTON ON L7M 1A6 | **GEN**

Generator No.: ON0337400
Status:
Approval Years: 02,03,04
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 243
Waste Description: PCB'S

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

---

50 | **8 of 11** | **NNW/171.9** | **125.8 / 2.07** | **Kingsbury Canada Inc.**
3385 Mainway
Burlington ON L7M 1A6 | **SCT**

Established: 1967
Plant Size (ft²): 33000
Employment: 63

--Details--
Description: Measuring, Medical and Controlling Devices Manufacturing
SIC/NAICS Code: 334512

Description: Switchgear and Switchboard, and Relay and Industrial Control Apparatus Manufacturing
SIC/NAICS Code: 335315

Description: Other Metalworking Machinery Manufacturing
SIC/NAICS Code: 333519

Description: All Other General-Purpose Machinery Manufacturing
SIC/NAICS Code: 333990

---

50 | **9 of 11** | **NNW/171.9** | **125.8 / 2.07** | **KINGSBURY CANADA INC**
3385 MAINWAY DR
BURLINGTON ON L7M 1A6 | **SCT**

Established: 1967
Plant Size (ft²): 33000
Employment: 75

--Details--
Description: FLUID POWER PUMPS AND MOTORS
SIC/NAICS Code: 3594

Description: SWITCHGEAR AND SWITCHBOARD APPARATUS
SIC/NAICS Code: 3613

Description: RELAYS AND INDUSTRIAL CONTROLS
SIC/NAICS Code: 3625

Description: INDUSTRIAL INSTRUMENTS FOR MEASUREMENT, DISPLAY, AND CONTROL OF PROCESS VARIABLES; & RELATED ITEMS
SIC/NAICS Code: 3823

Description: MACHINE TOOLS, METAL FORMING TYPES
SIC/NAICS Code: 3542

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	10 of 11	NNW/171.9	125.8 / 2.07	KINGSBURY CANADA INC. 3385 Mainway Dr Burlington ON L7M 1A6	SCT

Established: 1967
Plant Size (ft²): 33000
Employment: 63

--Details--
Description: Other Metalworking Machinery Manufacturing
SIC/NAICS Code: 333519

Description: All Other General-Purpose Machinery Manufacturing
SIC/NAICS Code: 333990

Description: Measuring, Medical and Controlling Devices Manufacturing
SIC/NAICS Code: 334512

Description: Switchgear and Switchboard, and Relay and Industrial Control Apparatus Manufacturing
SIC/NAICS Code: 335315

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	11 of 11	NNW/171.9	125.8 / 2.07	Keltour Controls Inc. 3385 Mainway Burlington ON L7M 1A6	SCT

Established: 1972
Plant Size (ft²): 15000
Employment:

--Details--
Description: Measuring, Medical and Controlling Devices Manufacturing
SIC/NAICS Code: 334512

Description: Switchgear and Switchboard, and Relay and Industrial Control Apparatus Manufacturing
SIC/NAICS Code: 335315

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
51	1 of 1	N/172.5	125.8 / 2.07	RIEGER PRINTING INK CO. LTD. 3410 MAIN DRIVE BURLINGTON CITY ON	CA

Certificate #: 8-3491-97-
Application Year: 97
Issue Date: 10/23/1997
Approval Type: Industrial air
Status: Cancelled
Application Type:
Client Name::
Client Address::
Client City::
Client Postal Code::
Project Description:: EQUIPMENT INSTALLED IN 1986
Contaminants::
Emission Control::

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
52	1 of 27	W/176.1	123.8 / 0.00	PRINTING HOUSE LTD., THE 3285 MAINWAY, UNIT 1	GEN

BURLINGTON ON L7M 1A6

Generator No.: ON1855505
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 323114
SIC Description: QUICK PRINTING

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Mark Wiedener
Phone No. Admin: 800-287-5416 Ext.26

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 265
Waste Description: GRAPHIC ART WASTES

Waste Code: 264
Waste Description: PHOTOPROCESSING WASTES

---

52 | **2 of 27** | **W/176.1** | **123.8 / 0.00** | **PRINTING HOUSE LTD., THE**
3285 MAINWAY, UNIT 1
BURLINGTON ON L7M 1A6 | **GEN**

Generator No.: ON1855505
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 323114
SIC Description: QUICK PRINTING

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Mark Wiedener
Phone No. Admin: 800-287-5416 Ext.26

--Details--
Waste Code: 264
Waste Description: PHOTOPROCESSING WASTES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 265
Waste Description: GRAPHIC ART WASTES

---

52 | **3 of 27** | **W/176.1** | **123.8 / 0.00** | **PRINTING HOUSE LTD., THE**
3285 MAINWAY, UNIT 1
BURLINGTON ON L7M 1A6 | **GEN**

Generator No.: ON1855505
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:

PO Box No.:
Country: Canada
Choice of Contact:
Co Admin:
Phone No. Admin:

SIC Code:
SIC Description:

--Details--
Waste Code: 251 L
Waste Description: Waste oils/sludges (petroleum based)

Waste Code: 252 L
Waste Description: Waste crankcase oils and lubricants

Waste Code: 145 L
Waste Description: Wastes from the use of pigments, coatings and paints

Waste Code: 264 T
Waste Description: Photoprocessing wastes

Waste Code: 265 L
Waste Description: Graphic arts wastes

Waste Code: 264 L
Waste Description: Photoprocessing wastes

---

52 | ***4 of 27*** | ***W/176.1*** | ***123.8 / 0.00*** | ***PRINTING HOUSE LTD., THE***
3285 MAINWAY, UNIT 1
BURLINGTON ON L7M 1A6 | ***GEN***

Generator No.: ON1855505
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 323114
SIC Description: QUICK PRINTING

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Mark Wiedener
Phone No. Admin: 800-287-5416 Ext.26

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 265
Waste Description: GRAPHIC ART WASTES

Waste Code: 264
Waste Description: PHOTOPROCESSING WASTES

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

---

52 | ***5 of 27*** | ***W/176.1*** | ***123.8 / 0.00*** | ***COOPER FLUID POWER INC.***
3285 MAINWAY DRIVE, #6
BURLINGTON ON L7M 1A6 | ***GEN***

Generator No.: ON2176600
Status:
Approval Years: 96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 3081
SIC Description: MACHINE SHOP IND.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

52 | 6 of 27 | W/176.1 | 123.8 / 0.00 | PRINTING HOUSE LTD., THE
3285 MAINWAY, UNIT 1
BURLINGTON ON | GEN

Generator No.: ON1855505
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 323114
SIC Description: QUICK PRINTING

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 264
Waste Description: PHOTOPROCESSING WASTES

Waste Code: 265
Waste Description: GRAPHIC ART WASTES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

---

52 | 7 of 27 | W/176.1 | 123.8 / 0.00 | PRINTING HOUSE LTD., THE
3285 MAINWAY, UNIT 1
BURLINGTON ON L7M 1A6 | GEN

Generator No.: ON1855505
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 323114
SIC Description: Quick Printing

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 264
Waste Description: PHOTOPROCESSING WASTES

Waste Code: 265
Waste Description: GRAPHIC ART WASTES

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
52	8 of 27	W/176.1	123.8 / 0.00	PRINTING HOUSE LTD., THE 3285 MAINWAY, UNIT 1 BURLINGTON ON L7M 1A6	GEN

Generator No.: ON1855505
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 323114
SIC Description: Quick Printing

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 265
Waste Description: GRAPHIC ART WASTES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 264
Waste Description: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
52	9 of 27	W/176.1	123.8 / 0.00	PRINTING HOUSE LTD., THE 3285 MAINWAY, UNIT 1 BURLINGTON ON L7M 1A6	GEN

Generator No.: ON1855505
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 323114
SIC Description: Quick Printing

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 264
Waste Description: PHOTOPROCESSING WASTES

Waste Code: 265
Waste Description: GRAPHIC ART WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
52	10 of 27	W/176.1	123.8 / 0.00	COOPER FLUID POWER INC. 3285 MAINWAY DRIVE, UNIT 6 BURLINGTON ON L7M 1A6	GEN

Generator No.: ON2176600
Status:
Approval Years: 99,00,01
Contam. Facility:

PO Box No.:
Country:
Choice of Contact:
Co Admin:

MHSW Facility: **Phone No. Admin:**
SIC Code: 3081
SIC Description: MACHINE SHOP IND.

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

52 ***11 of 27*** ***W/176.1*** ***123.8 / 0.00*** ***COTSWOLD PRECISION COMPANY LTD.***
3285 MAINWAY DRIVE, UNIT 3
BURLINGTON ON L7M 1A6 ***GEN***

Generator No.: ON1944700 **PO Box No.:**
Status: **Country:**
Approval Years: 99,00,01 **Choice of Contact:**
Contam. Facility: **Co Admin:**
MHSW Facility: **Phone No. Admin:**
SIC Code: 3081
SIC Description: MACHINE SHOP IND.

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

52 ***12 of 27*** ***W/176.1*** ***123.8 / 0.00*** ***PRINTING HOUSE LTD., THE***
3285 MAINWAY, UNIT 1
BURLINGTON ON L7M 1A6 ***GEN***

Generator No.: ON1855505 **PO Box No.:**
Status: **Country:**
Approval Years: 99,00,01,02,03,04,05,06,07,08 **Choice of Contact:**
Contam. Facility: **Co Admin:**
MHSW Facility: **Phone No. Admin:**
SIC Code: 2811
SIC Description: BUSINESS FORMS PRINT.

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 264
Waste Description: PHOTOPROCESSING WASTES

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 265
Waste Description: GRAPHIC ART WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
52	13 of 27	W/176.1	123.8 / 0.00	PRINTING HOUSE LTD., THE 3285 MAINWAY, UNIT 1 BURLINGTON ON L7M 1A6	GEN

Generator No.: ON1855505
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 323114
SIC Description: Quick Printing

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 264
Waste Description: PHOTOPROCESSING WASTES

Waste Code: 265
Waste Description: GRAPHIC ART WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
52	14 of 27	W/176.1	123.8 / 0.00	Precision Metalworks Inc 3285 Mainway unit 5 Burlington ON L7M 1A6	GEN

Generator No.: ON5747429
Status:
Approval Years: 07,08
Contam. Facility:
MHSW Facility:
SIC Code: 332710
SIC Description: Machine Shops

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
52	15 of 27	W/176.1	123.8 / 0.00	Precision Metalworks Inc 3285 Mainway unit 5 Burlington ON L7M 1A6	GEN

Generator No.: ON5747429
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 332710
SIC Description: Machine Shops

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

52 | **16 of 27** | **W/176.1** | **123.8 / 0.00**

PRINTING HOUSE LTD., THE
3285 MAINWAY UNIT #1
BURLINGTON ON L7M 1A6

GEN

Generator No.: ON1855505
Status:
Approval Years: 94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 2811
SIC Description: BUSINESS FORMS PRINT

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 264
Waste Description: PHOTOPROCESSING WASTES

---

52 | **17 of 27** | **W/176.1** | **123.8 / 0.00**

Sympro CNC Macining and Manufacturing
3285 Main Way, Unit 6
Burlington ON L7M 1A6

GEN

Generator No.: ON2173107
Status:
Approval Years: 03,04
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

---

52 | **18 of 27** | **W/176.1** | **123.8 / 0.00**

precision print
3285 Mainway drive
burlington ON

GEN

Generator No.: ON4482109
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 323113
SIC Description: Commercial Screen Printing

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

---

52 | **19 of 27** | **W/176.1** | **123.8 / 0.00**

COTSWOLD PRECISION COMPANY LTD.
3285 MAINWAY DRIVE, UNIT #3
BURLINGTON ON L7M 1A6

GEN

Generator No.: ON1944700
Status:
Approval Years: 94,95,96,97,98

PO Box No.:
Country:
Choice of Contact:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contam. Facility: **Co Admin:**
MHSW Facility: **Phone No. Admin:**
SIC Code: 3081
SIC Description: MACHINE SHOP IND.

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

52	20 of 27	W/176.1	123.8 / 0.00	**COTSWOLD PRECISION CO. LTD** **3285 MAINWAY DR UNIT 3** **BURLINGTON ON L7M 1A6**	SCT

Established: 1984
Plant Size (ft²): 6400
Employment: 7

--Details--
Description: FABRICATED METAL PRODUCTS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3499

Description: OVERHEAD TRAVELLING CRANES, HOISTS, AND MONORAIL SYSTEMS
SIC/NAICS Code: 3536

Description: INDUSTRIAL AND COMMERCIAL MACHINERY AND EQUIPMENT, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3599

Description: Machine Shops
SIC/NAICS Code: 332710

Description: All Other Miscellaneous Fabricated Metal Product Manufacturing
SIC/NAICS Code: 332999

Description: Material Handling Equipment Manufacturing
SIC/NAICS Code: 333920

52	21 of 27	W/176.1	123.8 / 0.00	**TPH The Printing House Limited** **3285 Mainway Unit 1** **Burlington ON L7M 1A6**	SCT

Established: 01-JUL-61
Plant Size (ft²): 1600
Employment:

--Details--
Description: Digital Printing
SIC/NAICS Code: 323115

Description: Quick Printing
SIC/NAICS Code: 323114

Description: Other Printing
SIC/NAICS Code: 323119

Description: Other Printing
SIC/NAICS Code: 323119

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
52	22 of 27	W/176.1	123.8 / 0.00	Precision Print Inc. 3285 Mainway Dr Burlington ON L7M 1A6	SCT

Established: 2001
Plant Size (ft²):
Employment: 2

--Details--
Description: Quick Printing
SIC/NAICS Code: 323114

Description: Digital Printing
SIC/NAICS Code: 323115

Description: Other Printing
SIC/NAICS Code: 323119

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
52	23 of 27	W/176.1	123.8 / 0.00	THE PRINTING HOUSE LTD. 3285 Mainway Dr Unit 1 Burlington ON L7M 1A6	SCT

Established: 1961
Plant Size (ft²): 1600
Employment: 5

--Details--
Description: Quick Printing
SIC/NAICS Code: 323114

Description: Digital Printing
SIC/NAICS Code: 323115

Description: Other Printing
SIC/NAICS Code: 323119

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
52	24 of 27	W/176.1	123.8 / 0.00	VERSA-HOE EQUIPMENT CORP. 3285 MAINWAY DR UNIT 4 BURLINGTON ON L7M 1A6	SCT

Established: 1969
Plant Size (ft²): 8000
Employment: 8

--Details--
Description: SPECIAL INDUSTRY MACHINERY, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3559

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
52	25 of 27	W/176.1	123.8 / 0.00	THE PRINTING HOUSE LTD 3285 MAINWAY DR UNIT 1 BURLINGTON ON L7M 1A6	SCT

Established: 1961
Plant Size (ft²): 1600
Employment: 5

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Description: COMMERCIAL PRINTING, LITHOGRAPHIC
SIC/NAICS Code: 2752

Description: COMMERCIAL PRINTING, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 2759

---

52 | ***26 of 27*** | ***W/176.1*** | ***123.8 / 0.00*** | ***Precision Print Inc.***
3285 Mainway Unit 2
Burlington ON L7M 1A6 | ***SCT***

Established: 7/1/2001
Plant Size (ft²):
Employment:

--Details--
Description: Digital Printing
SIC/NAICS Code: 323115

Description: Sign Manufacturing
SIC/NAICS Code: 339950

Description: Quick Printing
SIC/NAICS Code: 323114

Description: Other Printing
SIC/NAICS Code: 323119

Description: Commercial Screen Printing
SIC/NAICS Code: 323113

---

52 | ***27 of 27*** | ***W/176.1*** | ***123.8 / 0.00*** | ***Intek Inc.***
3285 Mainway Dr Unit 4
Burlington ON L7M 1A6 | ***SCT***

Established: 1986
Plant Size (ft²):
Employment: 8

---

53 | ***1 of 5*** | ***N/178.3*** | ***125.8 / 2.07*** | ***3410 Mainway***
Burlington ON L7M1A8 | ***EHS***

Order ID: 528813
Order No: 20170726040
Customer ID: 98067
Company ID: 77
Status: C
Report Code: 20CAN
Report Type: RSC Report (Urban)
Report Date: 27-JUL-17
Report Requested by: Pinchin Ltd.
Nearest Intersection:
Previous Site Name:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Date Received: 26-JUL-17
Lot/Building Size:
Municipality:
Client Prov/State: ON
Search Radius (km): .3
Large Radius: .35
X: -79.798823
Y: 43.367805

---

53 | ***2 of 5*** | ***N/178.3*** | ***125.8 / 2.07*** | ***3410 Mainway***
Burlington ON L7M1A8 | ***EHS***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Order ID: 480699
Order No: 20161005007
Customer ID: 98067
Company ID: 77
Status: C
Report Code: 3CAN
Report Type: Standard Report
Report Date: 11-OCT-16
Report Requested by: Pinchin Ltd.
Nearest Intersection:
Previous Site Name:
Additional Info Ordered:

Date Received: 05-OCT-16
Lot/Building Size:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
Large Radius: .35
X: -79.798741
Y: 43.367806

---

53 | **3 of 5** | **N/178.3** | **125.8 / 2.07** | **ACTIVITYPLEX BURLINGTON CORP.**
3410 MAINWAY
BURLINGTON ON L7M 1A8 | **GEN**

Generator No.: ON4436419
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country: Canada
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 150 L
Waste Description: Inert organic wastes

---

53 | **4 of 5** | **N/178.3** | **125.8 / 2.07** | **MPI GROUP INC.**
3410 MAINWAY
BURLINGTON ON L7M 1A8 | **GEN**

Generator No.: ON7218147
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 541990
SIC Description: ALL OTHER PROFESSIONAL, SCIENTIFIC AND TECHNICAL SERVICES

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 150
Waste Description: INERT INORGANIC WASTES

---

53 | **5 of 5** | **N/178.3** | **125.8 / 2.07** | **3410 MAINWAY, BURLINGTON, ON L7M 1A8**
Burlington ON | **RSC**

Reg No: 223893
RA No:
RSC Type: Phase 1 and 2 RSC
Curr Property Use: Commercial
District Office: Halton-Peel District Office
Date Submitted: 2017/11/02
Date Ack:
Date Returned:
Restoration Type:
Soil Type:

Cert Date:
Cert Prop Use No:
Intended Prop Use: Community
Nm of Qual. Person: FRANCESCO GAGLIARDI
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N):
Accuracy Estimate:
Telephone:
Fax:

Criteria: ***Email:***
Asmt Roll No: 2402090903024060000
Prop. ID No: 07163-0072 (LT)
CPU Issued Sect 1686:
Property Municipal Address: 3410 MAINWAY, BURLINGTON, ON L7M 1A8
Mailing Address:
Latitude & Latitude:
UTM Coordinates:
Consultant:
Filing Owner: ACTIVITYPLEX BURLINGTON CORP.
Legal Desc:
Measurement Method:
Applicable Standards:
RSC PDF: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument?attachmentId=87652&fileName=BROWNFIELDS-E.pdf

--Details--
Document Heading: Supporting Documents
Document Type: A copy of No Objection Statement from municipality
Document Name: Halton Region Letter.pdf
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument?attachmentId=87657&fileName=Halton+Region+Letter.pdf

Document Heading: Supporting Documents
Document Type: Area(s) of Potential Environmental Concern
Document Name: APECTable.pdf
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument?attachmentId=89219&fileName=APECTable.pdf

Document Heading: Supporting Documents
Document Type: A Current plan of Survey
Document Name: Survey Plan.pdf
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument?attachmentId=87659&fileName=Survey+Plan.pdf

Document Heading: Supporting Documents
Document Type: Phase 2 Conceptual Site Model
Document Name: PhaseTwo.pdf
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument?attachmentId=89220&fileName=PhaseTwo.pdf

Document Heading: Supporting Documents
Document Type: Copy of any deed(s), transfer(s) or other document(s)
Document Name: Transfer deeds.pdf
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument?attachmentId=87663&fileName=Transfer+deeds.pdf

Document Heading: Supporting Documents
Document Type: Table of Current and Past Property Use
Document Name: Current and Past Uses .pdf
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument?attachmentId=87662&fileName=Current+and+Past+Uses+.pdf

Document Heading: Supporting Documents
Document Type: Lawyer's letter consisting of a legal description of the property
Document Name: Lawyer Letter .pdf
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument?attachmentId=87658&fileName=Lawyer+Letter+.pdf

Document Heading: Supporting Documents
Document Type: Certificate of Status
Document Name: Certificate of Status.pdf
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument?attachmentId=87655&fileName=Certificate+of+Status.pdf

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
54	1 of 28	NNE/181.1	124.8 / 1.07	GENNUM CORPORATION 3435 LANDMARK ROAD BURLINGTON CITY ON L7M 1T4	CA

Certificate #: 8-3542-95-966
Application Year: 95
Issue Date: 5/27/96
Approval Type: Industrial air
Status: Received in 1995, Issued in 1996
Application Type:
Client Name::
Client Address::
Client City::
Client Postal Code::
Project Description:: PRINTED CIRCUIT BOARD MFG. PROCESS
Contaminants:: Hydrogen Chloride, Nitric Acid, Phosphoric Acid, Arsine, Hydrogen Peroxide, Ammonia, Sulphuric Acid, Xylene, Toluene(Pentyl Methane)(Methyl Benzene), Fluorides (Gas, Growing Season)
Emission Control:: No Controls, Other Wet Collector

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
54	2 of 28	NNE/181.1	124.8 / 1.07	Bosch Rexroth Canada Corp. 3435 Landmark Road Burlington ON L7M 1T4	CA

Certificate #: 4395-5XESRV
Application Year: 2004
Issue Date: 3/26/2004
Approval Type: Air
Status: Approved
Application Type:
Client Name::
Client Address::
Client City::
Client Postal Code::
Project Description::
Contaminants::
Emission Control::

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
54	3 of 28	NNE/181.1	124.8 / 1.07	3435 Landmark Road Burlington ON L7M 1T4	CA

Certificate #:
Application Year: 02
Issue Date: 10/2/02
Approval Type: Industrial air
Status: Approved
Application Type: Revocation
Client Name:: Gennum Corporation
Client Address:: 970 Fraser Drive
Client City:: Burlington
Client Postal Code:: L7L 5P5
Project Description:: Revocation of CofA 8-3542-95-966
Contaminants::
Emission Control::

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
54	4 of 28	NNE/181.1	124.8 / 1.07	Bosch Rexroth Canada Corp. 3435 Landmark Road Burlington Ontario L7M 1T4 Burlington ON	EBR

EBR Registry No.: IA03E1292

Ministry Ref. No.:	6866-5R3QMW
Company Name:	Bosch Rexroth Canada Corp.
Notice Type:	Instrument Decision
Notice Date:	April 02, 2004
Proposal Date:	September 08, 2003
Year:	2003
Proponent Address:	3426 Mainway Drive, Burlington Ontario, L7M 1A8
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:	

Location:

3435 Landmark Road Burlington Ontario L7M 1T4 Burlington

---

54 ***5 of 28*** ***NNE/181.1*** ***124.8 / 1.07*** ***Bosch Rexroth Canada Corp.*** ***3435 Landmark Road*** ***Burlington ON L7M 1A8*** ***ECA***

Approval No:	4395-5XESRV	***MOE District:***	Halton-Peel
Approval Type:	ECA-AIR	***SWP Area Name:***	Halton
Status:	Approved	***Address:***	3435 Landmark Road
Approval Date:	2004-03-26	***City:***	Burlington
Record Type:	ECA	***Longitude:***	-79.7976099999999
Project Type:	AIR	***Latitude:***	43.367626
Link Source:	IDS		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/6866-5R3QMW-14.pdf		

---

54 ***6 of 28*** ***NNE/181.1*** ***124.8 / 1.07*** ***3435 Landmark Rd*** ***Burlington ON L7M 1T4*** ***EHS***

Order ID:	238438	***Date Received:***	06-MAR-13
Order No:	20130306024	***Lot/Building Size:***	
Customer ID:	81208	***Municipality:***	
Company ID:	51305	***Client Prov/State:***	ON
Status:	C	***Search Radius (km):***	.25
Report Code:	2CAN	***Large Radius:***	2
Report Type:	Standard Select Report	***X:***	0
Report Date:	15-MAR-13	***Y:***	0
Report Requested by:	CVD Engineering Ltd.		
Nearest Intersection:			
Previous Site Name:			
Additional Info Ordered:			

---

54 ***7 of 28*** ***NNE/181.1*** ***124.8 / 1.07*** ***3435 Landmark Road*** ***Burlington ON L7M 1T4*** ***EHS***

Order ID:	180429	***Date Received:***	11/18/2010 2:08:23 PM
Order No:	20101118032	***Lot/Building Size:***	
Customer ID:	56847	***Municipality:***	
Company ID:	77	***Client Prov/State:***	ON
Status:	C	***Search Radius (km):***	0.25
Report Code:	4CAN	***Large Radius:***	2
Report Type:	Custom Report	***X:***	-79.797318
Report Date:	11/25/2010	***Y:***	43.367401
Report Requested by:	Pinchin Environmental		
Nearest Intersection:	Mainway		
Previous Site Name:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

54 **8 of 28** **NNE/181.1** **124.8 / 1.07** **Laker Energy Products Ltd.** **GEN**
3435 Landmark Road
Burlington ON L7M 1T4

Generator No.: ON6276431
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 332710
SIC Description: MACHINE SHOPS

PO Box No.:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Dave Lynch
Phone No. Admin: 905-332-3231 Ext.

--Details--
Waste Code: 253
Waste Description: EMULSIFIED OILS

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 113
Waste Description: ACID WASTE - OTHER METALS

54 **9 of 28** **NNE/181.1** **124.8 / 1.07** **Laker Energy Products Ltd.** **GEN**
3435 Landmark Road
Burlington ON L7M 1T4

Generator No.: ON6276431
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 332710
SIC Description: MACHINE SHOPS

PO Box No.:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Dave Lynch
Phone No. Admin: 905-332-3231 Ext.

--Details--
Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 253
Waste Description: EMULSIFIED OILS

Waste Code: 113
Waste Description: ACID WASTE - OTHER METALS

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

54 **10 of 28** **NNE/181.1** **124.8 / 1.07** **GENNUM (SEE&USE ON0488001)** **GEN**
3435 LANDMARK ROAD
BURLINGTON ON L7M 1T4

Generator No.: ON1105400
Status:
Approval Years: 89
Contam. Facility:

PO Box No.:
Country:
Choice of Contact:
Co Admin:

MHSW Facility: ***Phone No. Admin:***
SIC Code: 3352
SIC Description: ELECT. PARTS & COMP.

--Details--
Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

---

54 ***11 of 28*** ***NNE/181.1*** ***124.8 / 1.07*** ***GENNUM CORPORATION***
3435 LANDMARK ROAD
BURLINGTON ON L7M 1T4 ***GEN***

Generator No.: ON0488001 ***PO Box No.:***
Status: ***Country:***
Approval Years: 88,89,97,98,99,00,01 ***Choice of Contact:***
Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No. Admin:***
SIC Code: 3352
SIC Description: ELECT. PARTS & COMP.

--Details--
Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 241
Waste Description: HALOGENATED SOLVENTS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

---

54 ***12 of 28*** ***NNE/181.1*** ***124.8 / 1.07*** ***Laker Energy Products Ltd.***
3435 Landmark Road
Burlington ON ***GEN***

Generator No.: ON6276431 ***PO Box No.:***
Status: ***Country:***
Approval Years: 2012 ***Choice of Contact:***
Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No. Admin:***
SIC Code: 332710

SIC Description: Machine Shops

---

54 | **13 of 28** | **NNE/181.1** | **124.8 / 1.07** | **Laker Energy Products Ltd.**
3435 Landmark Road
Burlington ON L7M 1T4 | **GEN**

Generator No.: ON6276431
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 332710
SIC Description: MACHINE SHOPS

PO Box No.:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Dave Lynch
Phone No. Admin: 905-332-3231 Ext.

--Details--
Waste Code: 253
Waste Description: EMULSIFIED OILS

Waste Code: 113
Waste Description: ACID WASTE - OTHER METALS

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

---

54 | **14 of 28** | **NNE/181.1** | **124.8 / 1.07** | **GENNUM CORPORATION** | **24-187**
3435 LANDMARK ROAD
BURLINGTON ON L7M 1T4 | **GEN**

Generator No.: ON0488001
Status:
Approval Years: 92,93,94,95,96
Contam. Facility:
MHSW Facility:
SIC Code: 3352
SIC Description: ELECT. PARTS & COMP.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 241
Waste Description: HALOGENATED SOLVENTS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

---

54 **15 of 28** **NNE/181.1** **124.8 / 1.07** **LINERAR TECHNOLOGY INC.** **GEN**
3435 LANDMARK ROAD
BURLINGTON ON L7M 1T4

Generator No.: ON0488001
Status:
Approval Years: 86,87
Contam. Facility:
MHSW Facility:
SIC Code: 3352
SIC Description: ELECT. PARTS & COMP.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 241
Waste Description: HALOGENATED SOLVENTS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

54 **16 of 28** **NNE/181.1** **124.8 / 1.07** **GENNUM (SEE&USE ON0488001)** **17-187** **GEN**
3435 LANDMARK ROAD
BURLINGTON ON L7M 1T4

Generator No.: ON1105400
Status:
Approval Years: 92,93,94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 3352
SIC Description: ELECT. PARTS & COMP.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

---

54 **17 of 28** **NNE/181.1** **124.8 / 1.07** **GENNUM CORPORATION** **GEN**
3435 LANDMARK ROAD
BURLINGTON ON L7M 1T4

Generator No.: ON1105400
Status:
Approval Years: 88
Contam. Facility:
MHSW Facility:
SIC Code: 3352
SIC Description: ELECT. PARTS & COMP.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
54	18 of 28	NNE/181.1	124.8 / 1.07	Laker Energy Products Ltd. 3435 Landmark Road Burlington ON	GEN

Generator No.: ON6276431
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 332710
SIC Description: MACHINE SHOPS

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 253
Waste Description: EMULSIFIED OILS

Waste Code: 113
Waste Description: ACID WASTE - OTHER METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
54	19 of 28	NNE/181.1	124.8 / 1.07	GENNUM CORPORATION 3435 LANDMARK ROAD NOT AVAILABLE BURLINGTON ON L7M 1T4	NPRI

NPRI ID: 354
Other ID: Y
No Other ID: 3
Track ID: 1076
Report ID:
Report Type: NPRI
Rpt Type ID: 1
Report Year: 1996
Not-Current Rpt?: No
Yr of Last Filed Rpt: 2001
Fac ID: 37418
Fac Name: LANDMARK FACILITY
Fac Address1: 3435 LANDMARK ROAD
Fac Address2: NOT AVAILABLE
Fac Postal Zip: L7M 1T4
Facility Lat: 43.367
Facility Long: -79.7987
DLS (Last Filed Rpt):
Facility DLS:
Datum: 1983
Facility Cmnts: FALSE
URL:
No of Empl.: 300
Parent Co.: *
No Parent Co.: 0
Pollut Prev Cmnts: FALSE
Stacks:
No of Stacks:
Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:

Org ID: 49603
Submit Date: 7/11/1997
Last Modified: 5/29/2015 3:28:24 PM
Contact ID: 80466
Cont Type: MED
Contact Title:
Cont First Name: CHRIS
Cont Last Name: TIFFNEY
Contact Position: MANAGER, BUILDING SYTEMS
Contact Fax: 9056322055
Contact Ph.: 9056322996
Cont Area Code: 905
Contact Tel.: 56322996
Contact Ext.: 425
Cont Fax Area Cde: 905
Contact Fax: 56322055
Contact Email: NOT AVAILABLE
Latitude: 43.367
Longitude: -79.7987
UTM Zone: 17
UTM Northing: 4802045
UTM Easting: 597318
Waste Streams: FALSE
No Streams: 0
Waste Off Sites: FALSE
No Off Sites: 0
Shutdown:
No of Shutdown:

NAICS Code (2 digit):	33
NAICS 2 Description:	Manufacturing
NAICS Code (4 digit):	3344
NAICS 4 Description:	Semiconductor and other electronic component manufacturing
NAICS Code (6 digit):	334410
NAICS 6 Description:	Semiconductor and other electronic component manufacturing

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Sulphuric acid
Chem (fr):	Acide sulfurique
Quantity:	.1
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

---

54 | ***20 of 28*** | ***NNE/181.1*** | ***124.8 / 1.07*** | ***GENNUM CORPORATION***
3435 LANDMARK ROAD NOT AVAILABLE
BURLINGTON ON L7M 1T4 | ***NPRI***

NPRI ID:	354	**Org ID:**	49603
Other ID:	Y	**Submit Date:**	9/26/2001
No Other ID:	4	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	1078	**Contact ID:**	80462
Report ID:		**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	CHRIS
Report Year:	1995	**Cont Last Name:**	TIFFNEY
Not-Current Rpt?:	No	**Contact Position:**	NOT AVAILABLE
Yr of Last Filed Rpt:	2001	**Contact Fax:**	9056322055
Fac ID:	37412	**Contact Ph.:**	9056322999
Fac Name:	NOT AVAILABLE	**Cont Area Code:**	905
Fac Address1:	3435 LANDMARK ROAD	**Contact Tel.:**	56322999
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	425
Fac Postal Zip:	L7M 1T4	**Cont Fax Area Cde:**	905
Facility Lat:	43.367	**Contact Fax:**	56322055
Facility Long:	-79.7987	**Contact Email:**	NOT AVAILABLE
DLS (Last Filed Rpt):		**Latitude:**	43.367
Facility DLS:		**Longitude:**	-79.7987
Datum:	1983	**UTM Zone:**	17
Facility Cmnts:	TRUE	**UTM Northing:**	4802045
URL:		**UTM Easting:**	597318
No of Empl.:	280	**Waste Streams:**	FALSE
Parent Co.:	*	**No Streams:**	0
No Parent Co.:	0	**Waste Off Sites:**	FALSE
Pollut Prev Cmnts:	FALSE	**No Off Sites:**	0
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3344		
NAICS 4 Description:	Semiconductor and other electronic component manufacturing		
NAICS Code (6 digit):	334410		
NAICS 6 Description:	Semiconductor and other electronic component manufacturing		

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Sulphuric acid
Chem (fr):	Acide sulfurique
Quantity:	.1
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

54 ***21 of 28*** ***NNE/181.1*** ***124.8 / 1.07*** ***GENNUM CORPORATION***
3435 LANDMARK ROAD NOT AVAILABLE
BURLINGTON ON L7M 1T4 ***NPRI***

NPRI ID:	354	***Org ID:***	49603
Other ID:	Y	***Submit Date:***	5/18/2000
No Other ID:	3	***Last Modified:***	5/29/2015 3:28:24 PM
Track ID:	1073	***Contact ID:***	80463
Report ID:		***Cont Type:***	MED
Report Type:	NPRI	***Contact Title:***	
Rpt Type ID:	1	***Cont First Name:***	CHRIS
Report Year:	1999	***Cont Last Name:***	TIFFNEY
Not-Current Rpt?:	No	***Contact Position:***	MANAGER, BUILDING SYSTEMS
Yr of Last Filed Rpt:	2001	***Contact Fax:***	9056322055
Fac ID:	37418	***Contact Ph.:***	9056322996
Fac Name:	LANDMARK FACILITY	***Cont Area Code:***	905
Fac Address1:	3435 LANDMARK ROAD	***Contact Tel.:***	56322996
Fac Address2:	NOT AVAILABLE	***Contact Ext.:***	2129
Fac Postal Zip:	L7M 1T4	***Cont Fax Area Cde:***	905
Facility Lat:	43.367	***Contact Fax:***	56322055
Facility Long:	-79.7987	***Contact Email:***	CHRIS_T@GENNUM.COM
DLS (Last Filed Rpt):		***Latitude:***	43.367
Facility DLS:		***Longitude:***	-79.7987
Datum:	1983	***UTM Zone:***	17
Facility Cmnts:	False	***UTM Northing:***	4802045
URL:	www.gennum.com	***UTM Easting:***	597318
No of Empl.:	450	***Waste Streams:***	No
Parent Co.:	*	***No Streams:***	0
No Parent Co.:	1	***Waste Off Sites:***	No
Pollut Prev Cmnts:	False	***No Off Sites:***	0
Stacks:		***Shutdown:***	
No of Stacks:		***No of Shutdown:***	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3344		
NAICS 4 Description:	Semiconductor and other electronic component manufacturing		
NAICS Code (6 digit):	334410		
NAICS 6 Description:	Semiconductor and other electronic component manufacturing		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air

Trans Code:	ASta
Chem:	Sulphuric acid
Chem (fr):	Acide sulfurique
Quantity:	.1
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

54 **22 of 28** **NNE/181.1** **124.8 / 1.07**

GENNUM CORPORATION
3435 LANDMARK ROAD NOT AVAILABLE
BURLINGTON ON L7M 1T4

NPRI

NPRI ID:	354	**Org ID:**	49603
Other ID:	Y	**Submit Date:**	6/8/1998
No Other ID:	3	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	1075	**Contact ID:**	80707
Report ID:		**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	CHRISTOPHER
Report Year:	1997	**Cont Last Name:**	TIFFNEY
Not-Current Rpt?:	No	**Contact Position:**	MANAGER, BUILDING SYSTEMS
Yr of Last Filed Rpt:	2001	**Contact Fax:**	9056322055
Fac ID:	37418	**Contact Ph.:**	9066322999
Fac Name:	LANDMARK FACILITY	**Cont Area Code:**	906
Fac Address1:	3435 LANDMARK ROAD	**Contact Tel.:**	66322999
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	1770
Fac Postal Zip:	L7M 1T4	**Cont Fax Area Cde:**	905
Facility Lat:	43.367	**Contact Fax:**	56322055
Facility Long:	-79.7987	**Contact Email:**	NOT AVAILABLE
DLS (Last Filed Rpt):		**Latitude:**	43.367
Facility DLS:		**Longitude:**	-79.7987
Datum:	1983	**UTM Zone:**	17
Facility Cmnts:	FALSE	**UTM Northing:**	4802045
URL:		**UTM Easting:**	597318
No of Empl.:	350	**Waste Streams:**	FALSE
Parent Co.:	*	**No Streams:**	0
No Parent Co.:	1	**Waste Off Sites:**	FALSE
Pollut Prev Cmnts:	FALSE	**No Off Sites:**	0
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3344		
NAICS 4 Description:	Semiconductor and other electronic component manufacturing		
NAICS Code (6 digit):	334410		
NAICS 6 Description:	Semiconductor and other electronic component manufacturing		

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Sulphuric acid
Chem (fr):	Acide sulfurique
Quantity:	.1
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

54 **23 of 28** **NNE/181.1** **124.8 / 1.07** **GENNUM CORPORATION** **NPRI**
3435 LANDMARK ROAD NOT AVAILABLE
BURLINGTON ON L7M 1T4

NPRI ID:	354	**Org ID:**	49603
Other ID:	Y	**Submit Date:**	5/29/2001
No Other ID:	3.00	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	1072	**Contact ID:**	80465
Report ID:		**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	CHRIS
Report Year:	2000	**Cont Last Name:**	TIFFNEY
Not-Current Rpt?:	No	**Contact Position:**	MANAGER, BUILDING SYSTEMS
Yr of Last Filed Rpt:	2001	**Contact Fax:**	9056322055
Fac ID:	37418	**Contact Ph.:**	9056322999
Fac Name:	LANDMARK FACILITY	**Cont Area Code:**	905
Fac Address1:	3435 LANDMARK ROAD	**Contact Tel.:**	56322999
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	2129
Fac Postal Zip:	L7M 1T4	**Cont Fax Area Cde:**	905
Facility Lat:	43.367	**Contact Fax:**	56322055
Facility Long:	-79.7987	**Contact Email:**	CHRIS_T@GENNUM.COM
DLS (Last Filed Rpt):		**Latitude:**	43.367
Facility DLS:		**Longitude:**	-79.7987
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:	www.gennum.com	**UTM Easting:**	
No of Empl.:	25	**Waste Streams:**	No
Parent Co.:	*	**No Streams:**	0
No Parent Co.:	1.00	**Waste Off Sites:**	No
Pollut Prev Cmnts:	False	**No Off Sites:**	0.00
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3344		
NAICS 4 Description:	Semiconductor and other electronic component manufacturing		
NAICS Code (6 digit):	334410		
NAICS 6 Description:	Semiconductor and other electronic component manufacturing		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Sulphuric acid
Chem (fr):	Acide sulfurique
Quantity:	.005
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

54 **24 of 28** **NNE/181.1** **124.8 / 1.07** **GENNUM CORPORATION** **NPRI**
3435 LANDMARK ROAD NOT AVAILABLE
BURLINGTON ON L7M 1T4

NPRI ID:	354	**Org ID:**	49603

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Other ID:		**Submit Date:**	
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	1077	**Contact ID:**	
Report ID:		**Cont Type:**	
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	1993	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2001	**Contact Fax:**	
Fac ID:	37412	**Contact Ph.:**	
Fac Name:	NOT AVAILABLE	**Cont Area Code:**	
Fac Address1:	3435 LANDMARK ROAD	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	L7M 1T4	**Cont Fax Area Cde:**	
Facility Lat:	43.367	**Contact Fax:**	
Facility Long:	-79.7987	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.367
Facility DLS:		**Longitude:**	-79.7987
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:		**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3344		
NAICS 4 Description:	Semiconductor and other electronic component manufacturing		
NAICS Code (6 digit):	334410		
NAICS 6 Description:	Semiconductor and other electronic component manufacturing		

54	***25 of 28***	***NNE/181.1***	***124.8 / 1.07***	***GENNUM CORPORATION*** ***3435 LANDMARK ROAD NOT AVAILABLE*** ***BURLINGTON ON L7M 1T4***	***NPRI***

NPRI ID:	354	**Org ID:**	49603
Other ID:	Y	**Submit Date:**	5/11/1999
No Other ID:	3	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	1074	**Contact ID:**	80708
Report ID:		**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	CHRISTOPHER
Report Year:	1998	**Cont Last Name:**	TIFFNEY
Not-Current Rpt?:	No	**Contact Position:**	MANAGER,BUILDING SYSTEMS
Yr of Last Filed Rpt:	2001	**Contact Fax:**	9056322055
Fac ID:	37418	**Contact Ph.:**	9056322999
Fac Name:	LANDMARK FACILITY	**Cont Area Code:**	905
Fac Address1:	3435 LANDMARK ROAD	**Contact Tel.:**	56322999
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	1770
Fac Postal Zip:	L7M 1T4	**Cont Fax Area Cde:**	905
Facility Lat:	43.367	**Contact Fax:**	56322055
Facility Long:	-79.7987	**Contact Email:**	CHRIS_T@GENNUM.COM
DLS (Last Filed Rpt):		**Latitude:**	43.367
Facility DLS:		**Longitude:**	-79.7987
Datum:	1983	**UTM Zone:**	17
Facility Cmnts:	False	**UTM Northing:**	4802045
URL:	www.gennum.com	**UTM Easting:**	597318
No of Empl.:	400	**Waste Streams:**	False

Parent Co.:	Y	**No Streams:**	0
No Parent Co.:	1	**Waste Off Sites:**	False
Pollut Prev Cmnts:	False	**No Off Sites:**	0
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3344		
NAICS 4 Description:	Semiconductor and other electronic component manufacturing		
NAICS Code (6 digit):	334410		
NAICS 6 Description:	Semiconductor and other electronic component manufacturing		

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Sulphuric acid
Chem (fr):	Acide sulfurique
Quantity:	.15
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
54	26 of 28	NNE/181.1	124.8 / 1.07	**GENNUM CORPORATION** **3435 LANDMARK ROAD NOT AVAILABLE** **BURLINGTON ON L7M 1T4**	NPRI

NPRI ID:	354	**Org ID:**	49603
Other ID:	TRUE	**Submit Date:**	
No Other ID:	1	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	1071	**Contact ID:**	
Report ID:		**Cont Type:**	
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	1994	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2001	**Contact Fax:**	
Fac ID:	37412	**Contact Ph.:**	
Fac Name:	NOT AVAILABLE	**Cont Area Code:**	
Fac Address1:	3435 LANDMARK ROAD	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	L7M 1T4	**Cont Fax Area Cde:**	
Facility Lat:	43.367	**Contact Fax:**	
Facility Long:	-79.7987	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.367
Facility DLS:		**Longitude:**	-79.7987
Datum:	1983	**UTM Zone:**	17
Facility Cmnts:	TRUE	**UTM Northing:**	4802045
URL:		**UTM Easting:**	597318
No of Empl.:	230	**Waste Streams:**	FALSE
Parent Co.:	FALSE	**No Streams:**	0
No Parent Co.:	0	**Waste Off Sites:**	FALSE
Pollut Prev Cmnts:		**No Off Sites:**	0
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			

SIC Code Description:	
American SIC Code:	
NAICS Code (2 digit):	33
NAICS 2 Description:	Manufacturing
NAICS Code (4 digit):	3344
NAICS 4 Description:	Semiconductor and other electronic component manufacturing
NAICS Code (6 digit):	334410
NAICS 6 Description:	Semiconductor and other electronic component manufacturing

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Sulphuric acid
Chem (fr):	Acide sulfurique
Quantity:	.13
Unit:	tonnes
Basis of Estimate Cd:	M
Basis of Estimate Desc:	M- Monitoring or Direct Measurement - In use from 1994 to 2002

---

54 | ***27 of 28*** | ***NNE/181.1*** | ***124.8 / 1.07*** | ***GENNUM CORPORATION***
3435 LANDMARK ROAD NOT AVAILABLE
BURLINGTON ON L7M 1T4 | ***NPRI***

NPRI ID:	354	**Org ID:**	49603
Other ID:	Y	**Submit Date:**	5/29/2002
No Other ID:	3.00	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	1079	**Contact ID:**	80706
Report ID:		**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	CHRISTOPHER
Report Year:	2001	**Cont Last Name:**	TIFFNEY
Not-Current Rpt?:	No	**Contact Position:**	MANAGER, BUILDING SYSTEMS
Yr of Last Filed Rpt:	2001	**Contact Fax:**	9056322055
Fac ID:	37413	**Contact Ph.:**	9056322999
Fac Name:	LANDMARK BUILDING	**Cont Area Code:**	905
Fac Address1:	3435 LANDMARK ROAD	**Contact Tel.:**	56322999
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	2129
Fac Postal Zip:	L7M 1T4	**Cont Fax Area Cde:**	905
Facility Lat:	43.367	**Contact Fax:**	56322055
Facility Long:	-79.7987	**Contact Email:**	CHRIS_T@GENNUM.COM
DLS (Last Filed Rpt):		**Latitude:**	43.367
Facility DLS:		**Longitude:**	-79.7987
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	No	**UTM Northing:**	
URL:	www.gennum.com	**UTM Easting:**	
No of Empl.:	25	**Waste Streams:**	No
Parent Co.:	*	**No Streams:**	0.00
No Parent Co.:	1.00	**Waste Off Sites:**	No
Pollut Prev Cmnts:	No	**No Off Sites:**	0.00
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3344		
NAICS 4 Description:	Semiconductor and other electronic component manufacturing		
NAICS Code (6 digit):	334410		

NAICS 6 Description: Semiconductor and other electronic component manufacturing

Substance Release Report

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Sulphuric acid
Chem (fr): Acide sulfurique
Quantity: .003
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

---

54 ***28 of 28*** ***NNE/181.1*** ***124.8 / 1.07*** ***BURLINGTON ON*** ***WWIS***

Well ID: 7200490
Construction Date:
Primary Water Use: Monitoring
Sec. Water Use:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z159183
Tag: A132178
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 4/18/2013
Selected Flag: 1
Abandonment Rec:
Contractor: 7190
Form Version: 7
Owner:
Street Name: 3435 LANDMARK RD
County: HALTON
Municipality: BURLINGTON CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1004275817
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 124.496513
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind:
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr
Org CS: UTM83
Date Completed: 3/20/2013

Overburden and Bedrock Materials Interval

Formation ID: 1004831042
Layer: 1

Color: 6
General Color: BROWN
Mat1: 01
Most Common Material: FILL
Mat2: 77
Other Materials: LOOSE
Mat3:
Other Materials:
Formation Top Depth: 0.00
Formation End Depth: 4.00
Formation End Depth UOM: ft

Formation ID: 1004831043
Layer: 2
Color: 7
General Color: RED
Mat1: 17
Most Common Material: SHALE
Mat2: 73
Other Materials: HARD
Mat3:
Other Materials:
Formation Top Depth: 4.00
Formation End Depth: 15.00
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004831050
Layer: 1
Plug From: 15.00
Plug To: 3.50
Plug Depth UOM: ft

Plug ID: 1004831051
Layer: 2
Plug From: 3.50
Plug To: 1.00
Plug Depth UOM: ft

Plug ID: 1004831052
Layer: 3
Plug From: 1.00
Plug To: 0.00
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1004831049
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1004831041
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1004831046
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	5.00
Depth To:	0.00
Casing Diameter:	2.00
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004831047
Layer:	1
Slot:	
Screen Top Depth:	15.00
Screen End Depth:	5.00
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.00

Water Details

Water ID:	1004831045
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1004831044
Diameter:	6.00
Depth From:	0.00
Depth To:	15.00
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

55 | ***1 of 1*** | ***NE/182.0*** | ***124.2 / 0.45*** | ***GENNUM CORPORATION***
P.O. BOX 489, STATION "A"
BURLINGTON ON L7R 3Y3 | ***GEN***

Generator No.:	ON0488001	***PO Box No.:***	
Status:		***Country:***	
Approval Years:	02,03,04	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No. Admin:***	
SIC Code:	334410		
SIC Description:	Semiconductor & Electronic Component Mfg.		

--Details--

Waste Code:	121
Waste Description:	ALKALINE WASTES - HEAVY METALS
Waste Code:	146
Waste Description:	OTHER SPECIFIED INORGANICS
Waste Code:	148

Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 241
Waste Description: HALOGENATED SOLVENTS

Waste Code: 243
Waste Description: PCB'S

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

---

56 | ***1 of 3*** | ***WNW/183.0*** | ***125.7 / 1.89*** | ***JC CNC (OUT OF BUSINESS)***
3319B MAINWAY ROAD
BURLINGTON ON L7M 1A6 | ***GEN***

Generator No.: ON2201400
Status:
Approval Years: 01
Contam. Facility:
MHSW Facility:
SIC Code: 4999
SIC Description: OTHER UTILITY IND.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

---

56 | ***2 of 3*** | ***WNW/183.0*** | ***125.7 / 1.89*** | ***JC CNC WORKS INC.***
3319B MAINWAY ROAD
BURLINGTON ON L7M 1A6 | ***GEN***

Generator No.: ON2201400
Status:
Approval Years: 97,98,99,00
Contam. Facility:
MHSW Facility:
SIC Code: 9999
SIC Description: OTHER SERVICES

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

---

56 | ***3 of 3*** | ***WNW/183.0*** | ***125.7 / 1.89*** | ***J.C. CNC WORKS INC.***
3319 Mainway Rd Unit B
Burlington ON L7M 1A6 | ***SCT***

Established: 1990
Plant Size (ft²): 0
Employment: 4

--Details--
Description: Machine Shops
SIC/NAICS Code: 332710

Description: Mining and Oil and Gas Field Machinery Manufacturing
SIC/NAICS Code: 333130

Description: Railroad Rolling Stock Manufacturing
SIC/NAICS Code: 336510

---

57 ***1 of 1*** ***NW/186.4*** ***125.8 / 2.07*** ***3365 Mainway Burlington ON*** ***EHS***

Order ID: 440482
Order No: 20160119029
Customer ID: 53147
Company ID: 77
Status: C
Report Code: 4CAN
Report Type: Custom Report
Report Date: 22-JAN-16
Report Requested by: Pinchin Ltd
Nearest Intersection:
Previous Site Name:
Additional Info Ordered:

Date Received: 19-JAN-16
Lot/Building Size:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
Large Radius: .3
X: -79.801422
Y: 43.367161

---

58 ***1 of 3*** ***WSW/189.9*** ***122.9 / -0.92*** ***3267 Mainway Road Burlington ON*** ***EHS***

Order ID: 469236
Order No: 20160714106
Customer ID: 85548
Company ID: 54105
Status: C
Report Code: 3CAN
Report Type: Standard Report
Report Date: 21-JUL-16
Report Requested by: Spice Environmental Inc.
Nearest Intersection:
Previous Site Name: Burlington Technical Industry Revstone Comstock Canada
Additional Info Ordered: Title Searches; Topographic Maps; Aerial Photos

Date Received: 14-JUL-16
Lot/Building Size:
Municipality: Burlington
Client Prov/State: ON
Search Radius (km): .25
Large Radius: 2
X: -79.803013
Y: 43.364553

---

58 ***2 of 3*** ***WSW/189.9*** ***122.9 / -0.92*** ***BURLINGTON TECHNOLOGIES INC. 3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6*** ***NPRI***

NPRI ID: 3096
Other ID: *
No Other ID: 0
Track ID: 76322
Report ID: 160770
Report Type: NPRI
Rpt Type ID: 1
Report Year: 2002
Not-Current Rpt?: No
Yr of Last Filed Rpt: 2010

Org ID: 40258
Submit Date: 7/9/2003
Last Modified: 5/29/2015 3:28:24 PM
Contact ID: 158737
Cont Type: MED
Contact Title:
Cont First Name: IAN
Cont Last Name: RIDGE
Contact Position: MATERIALS MANAGER
Contact Fax: 9053325122

Fac ID:	113721	***Contact Ph.:***	9053352742
Fac Name:	BURLINGTON DIVISION	***Cont Area Code:***	905
Fac Address1:	3267 MAINWAY	***Contact Tel.:***	53352742
Fac Address2:	NOT AVAILABLE	***Contact Ext.:***	243
Fac Postal Zip:	L7M1A6	***Cont Fax Area Cde:***	905
Facility Lat:	43.3644	***Contact Fax:***	53325122
Facility Long:	-79.8037	***Contact Email:***	IRIDGE@BURLTECH.COM
DLS (Last Filed Rpt):		***Latitude:***	43.3644
Facility DLS:		***Longitude:***	-79.8037
Datum:	1983	***UTM Zone:***	
Facility Cmnts:	False	***UTM Northing:***	
URL:		***UTM Easting:***	
No of Empl.:	235	***Waste Streams:***	False
Parent Co.:	*	***No Streams:***	0
No Parent Co.:	1	***Waste Off Sites:***	Fals
Pollut Prev Cmnts:	False	***No Off Sites:***	1
Stacks:	False	***Shutdown:***	False
No of Stacks:		***No of Shutdown:***	0
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3315		
NAICS 4 Description:	Foundries		
NAICS Code (6 digit):	331523		
NAICS 6 Description:	Non-ferrous die-casting foundries		

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Zinc (and its compounds)
Chem (fr):	Zinc (et ses composés)
Quantity:	.094
Unit:	tonnes
Basis of Estimate Cd:	
Basis of Estimate Desc:	

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Copper (and its compounds)
Chem (fr):	Cuivre (et ses composés)
Quantity:	.097
Unit:	tonnes
Basis of Estimate Cd:	
Basis of Estimate Desc:	

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	5.142
Unit:	tonnes
Basis of Estimate Cd:	O

Basis of Estimate Desc:	O- Engineering Estimates
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Aluminum (fume or dust)
Chem (fr):	Aluminium (fumée ou poussière)
Quantity:	2.602
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	5.927
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

58 | ***3 of 3*** | ***WSW/189.9*** | ***122.9 / -0.92*** | ***BURLINGTON TECHNOLOGIES INDUSTRIES***
3267 MAINWAY NOT AVAILABLE
BURLINGTON ON L7M1A6 | ***NPRI***

NPRI ID:	3096	**Org ID:**	40264
Other ID:	*	**Submit Date:**	2/15/2006
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	32984	**Contact ID:**	121055
Report ID:	92865	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	BETTY
Report Year:	2004	**Cont Last Name:**	LOFTHOUSE
Not-Current Rpt?:	No	**Contact Position:**	HEALTH, SAFETY & ENVIRONMENTAL MANAGER
Yr of Last Filed Rpt:	2010	**Contact Fax:**	9053325122
Fac ID:	113721	**Contact Ph.:**	9053352742
Fac Name:	BURLINGTON DIVISION	**Cont Area Code:**	905
Fac Address1:	3267 MAINWAY	**Contact Tel.:**	53352742
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	229
Fac Postal Zip:	L7M1A6	**Cont Fax Area Cde:**	905
Facility Lat:	43.3644	**Contact Fax:**	53325122
Facility Long:	-79.8037	**Contact Email:**	BLOFTHOUSE@BURLTECH.COM
DLS (Last Filed Rpt):		**Latitude:**	43.3644
Facility DLS:		**Longitude:**	-79.8037
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	True	**UTM Northing:**	
URL:	www.burltech.com	**UTM Easting:**	
No of Empl.:	295	**Waste Streams:**	False
Parent Co.:	N	**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	True	**No Off Sites:**	1
Stacks:	No	**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		

NAICS Code (4 digit): 3315
NAICS 4 Description: Foundries
NAICS Code (6 digit): 331523
NAICS 6 Description: Non-ferrous die-casting foundries

Substance Release Report

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: MSG#3 - Mineral oil
Chem (fr): EMG#3 - Huile minérale
Quantity: 1.142
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Zinc (and its compounds)
Chem (fr): Zinc (et ses composés)
Quantity: .038
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: MSG#3 - Hydrotreated light naphthenic distillate
Chem (fr): EMG#3 - Distillat naphténique léger hydrotraité
Quantity: .103
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr): PM2,5 - Matière particulaire <= 2,5 microns
Quantity: 4.594
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Copper (and its compounds)
Chem (fr): Cuivre (et ses composés)
Quantity: .038
Unit: tonnes
Basis of Estimate Cd: O

Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: MSG#1 - Solvent naphtha medium aliphatic
Chem (fr): EMG#1 - Solvant naphta aliphatique moyen
Quantity: 4.954
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: MSG#3 - Hydrotreated heavy paraffinic mineral spirits
Chem (fr): EMG#3 - Essences minérales paraffiniques lourdes hydrotraitées
Quantity: .072
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Stoddard solvent
Chem (fr): Solvant Stoddard
Quantity: .007
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: MSG#2 - Hydrotreated heavy naphthenic distillate
Chem (fr): EMG#2 - Distillat naphténique lourd hydrotraité
Quantity: 1.775
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Iron (and its compounds)
Chem (fr): Fer (et ses composés)
Quantity: .013
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t

Trans Code:	
Chem:	MSG#3 - Solvent refined heavy paraffinic distillate
Chem (fr):	EMG#3 - Distillat paraffinique lourd raffiné au solvant
Quantity:	.072
Unit:	tonnes
Basis of Estimate Cd:	
Basis of Estimate Desc:	

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	5.406
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Aluminum (fume or dust)
Chem (fr):	Aluminium (fumée ou poussière)
Quantity:	1.012
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

---

59 | ***1 of 12*** | ***WSW/190.2*** | ***122.9 / -0.92*** | ***BURLINGTON TECHNOLOGIES INC.***
3267 MAINWAY NOT AVAILABLE
BURLINGTON ON L7M1A6 | ***NPRI***

NPRI ID:	3096	**Org ID:**	40258
Other ID:	Y	**Submit Date:**	5/31/2000
No Other ID:	1	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	8458	**Contact ID:**	99834
Report ID:		**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	MIKE
Report Year:	1999	**Cont Last Name:**	BOYLE
Not-Current Rpt?:	No	**Contact Position:**	CORPORATE H,S&E MANAGER
Yr of Last Filed Rpt:	2010	**Contact Fax:**	9053325122
Fac ID:	113721	**Contact Ph.:**	9053352742
Fac Name:	BURLINGTON DIVISION	**Cont Area Code:**	905
Fac Address1:	3267 MAINWAY	**Contact Tel.:**	53352742
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	229
Fac Postal Zip:	L7M1A6	**Cont Fax Area Cde:**	905
Facility Lat:	43.3644	**Contact Fax:**	53325122
Facility Long:	-79.8037	**Contact Email:**	NOT AVAILABLE
DLS (Last Filed Rpt):		**Latitude:**	43.3644
Facility DLS:		**Longitude:**	-79.8037
Datum:	1983	**UTM Zone:**	17
Facility Cmnts:	False	**UTM Northing:**	4801582
URL:	www.burltech.com	**UTM Easting:**	596831
No of Empl.:	266	**Waste Streams:**	Yes
Parent Co.:	*	**No Streams:**	0
No Parent Co.:	1	**Waste Off Sites:**	Yes
Pollut Prev Cmnts:	False	**No Off Sites:**	0
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			

Canadian SIC Code:	
SIC Code Description:	
American SIC Code:	
NAICS Code (2 digit):	33
NAICS 2 Description:	Manufacturing
NAICS Code (4 digit):	3315
NAICS 4 Description:	Foundries
NAICS Code (6 digit):	331523
NAICS 6 Description:	Non-ferrous die-casting foundries

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Aluminum (fume or dust)
Chem (fr):	Aluminium (fumée ou poussière)
Quantity:	2.65
Unit:	tonnes
Basis of Estimate Cd:	E
Basis of Estimate Desc:	E- Emission Factor - In use from 1994 to 2002

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Copper (and its compounds)
Chem (fr):	Cuivre (et ses composés)
Quantity:	.08
Unit:	tonnes
Basis of Estimate Cd:	E
Basis of Estimate Desc:	E- Emission Factor - In use from 1994 to 2002

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Zinc (and its compounds)
Chem (fr):	Zinc (et ses composés)
Quantity:	.07
Unit:	tonnes
Basis of Estimate Cd:	E
Basis of Estimate Desc:	E- Emission Factor - In use from 1994 to 2002

---

59 ***2 of 12*** ***WSW/190.2*** ***122.9 / -0.92*** ***BURLINGTON TECHNOLOGIES INDUSTRIES***
3267 MAINWAY NOT AVAILABLE
BURLINGTON ON L7M1A6 ***NPRI***

NPRI ID:	3096	***Org ID:***	40264
Other ID:	*	***Submit Date:***	4/3/2009
No Other ID:		***Last Modified:***	5/29/2015 3:28:24 PM
Track ID:	61880	***Contact ID:***	191152
Report ID:	123112	***Cont Type:***	MED
Report Type:	NPRI	***Contact Title:***	
Rpt Type ID:	1	***Cont First Name:***	MIKE
Report Year:	2008	***Cont Last Name:***	SUGGITT
Not-Current Rpt?:	No	***Contact Position:***	HEALTH, SAFETY & ENVIRONMENTAL MANAGER
Yr of Last Filed Rpt:	2010	***Contact Fax:***	9053325122
Fac ID:	113721	***Contact Ph.:***	9053352742

Fac Name:	BURLINGTON DIVISION	***Cont Area Code:***	905
Fac Address1:	3267 MAINWAY	***Contact Tel.:***	53352742
Fac Address2:	NOT AVAILABLE	***Contact Ext.:***	229
Fac Postal Zip:	L7M1A6	***Cont Fax Area Cde:***	905
Facility Lat:	43.3644	***Contact Fax:***	53325122
Facility Long:	-79.8037	***Contact Email:***	MIS@BURLTECH.COM
DLS (Last Filed Rpt):		***Latitude:***	43.3644
Facility DLS:		***Longitude:***	-79.8037
Datum:	1983	***UTM Zone:***	
Facility Cmnts:	No	***UTM Northing:***	
URL:	www.burltech.com	***UTM Easting:***	
No of Empl.:	189	***Waste Streams:***	No
Parent Co.:	N	***No Streams:***	
No Parent Co.:		***Waste Off Sites:***	Yes
Pollut Prev Cmnts:	No	***No Off Sites:***	1
Stacks:	No	***Shutdown:***	Yes
No of Stacks:		***No of Shutdown:***	1
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3315		
NAICS 4 Description:	Foundries		
NAICS Code (6 digit):	331523		
NAICS 6 Description:	Non-ferrous die-casting foundries		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	2.141
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Copper (and its compounds)
Chem (fr):	Cuivre (et ses composés)
Quantity:	.004
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	1.933
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Aluminum (fume or dust)
Chem (fr):	Aluminium (fumée ou poussière)
Quantity:	.11
Unit:	tonnes
Basis of Estimate Cd:	
Basis of Estimate Desc:	

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Zinc (and its compounds)
Chem (fr):	Zinc (et ses composés)
Quantity:	.028
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

---

59 | **3 of 12** | **WSW/190.2** | **122.9 / -0.92** | **BURLINGTON TECHNOLOGIES INDUSTRIES**
3267 MAINWAY NOT AVAILABLE
BURLINGTON ON L7M1A6 | **NPRI**

NPRI ID:	3096	**Org ID:**	40264
Other ID:	*	**Submit Date:**	2/15/2006
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	32978	**Contact ID:**	121055
Report ID:	155623	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	BETTY
Report Year:	2003	**Cont Last Name:**	LOFTHOUSE
Not-Current Rpt?:	No	**Contact Position:**	HEALTH, SAFETY & ENVIRONMENTAL MANAGER
Yr of Last Filed Rpt:	2010	**Contact Fax:**	9053325122
Fac ID:	113721	**Contact Ph.:**	9053352742
Fac Name:	BURLINGTON DIVISION	**Cont Area Code:**	905
Fac Address1:	3267 MAINWAY	**Contact Tel.:**	53352742
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	229
Fac Postal Zip:	L7M1A6	**Cont Fax Area Cde:**	905
Facility Lat:	43.3644	**Contact Fax:**	53325122
Facility Long:	-79.8037	**Contact Email:**	BLOFTHOUSE@BURLTECH.COM
DLS (Last Filed Rpt):		**Latitude:**	43.3644
Facility DLS:		**Longitude:**	-79.8037
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:	www.burltech.com	**UTM Easting:**	
No of Empl.:	313	**Waste Streams:**	True?
Parent Co.:	*	**No Streams:**	
No Parent Co.:	1	**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	False	**No Off Sites:**	2
Stacks:	True	**Shutdown:**	True
No of Stacks:		**No of Shutdown:**	1
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3315		

NAICS 4 Description: Foundries
NAICS Code (6 digit): 331523
NAICS 6 Description: Non-ferrous die-casting foundries

Substance Release Report

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: MSG#1 - Solvent naphtha medium aliphatic
Chem (fr): EMG#1 - Solvant naphta aliphatique moyen
Quantity: 5.716
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: MSG#2 - Hydrotreated heavy naphthenic distillate
Chem (fr): EMG#2 - Distillat naphténique lourd hydrotraité
Quantity: 2.696
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 3
Category Type Desc: Fugitive
Category Type Desc (fr): Émissions fugitives
Grouping: Total Air
Trans Code: VOCs
Chem: Volatile Organic Compounds (VOCs)
Chem (fr): Composés organiques volatils (COV)
Quantity: 1.474
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: MSG#3 - Hydrotreated light naphthenic distillate
Chem (fr): EMG#3 - Distillat naphténique léger hydrotraité
Quantity: .044
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: MSG#3 - Mineral oil
Chem (fr): EMG#3 - Huile minérale
Quantity: .7
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: MSG#3 - Hydrotreated heavy paraffinic mineral spirits
Chem (fr): EMG#3 - Essences minérales paraffiniques lourdes hydrotraitées
Quantity: .054
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: PM10 - Particulate Matter <= 10 Microns
Chem (fr): PM10 - Matière particulaire <= 10 microns
Quantity: 3.206
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Copper (and its compounds)
Chem (fr): Cuivre (et ses composés)
Quantity: .021
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Aluminum (fume or dust)
Chem (fr): Aluminium (fumée ou poussière)
Quantity: .563
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Zinc (and its compounds)
Chem (fr): Zinc (et ses composés)
Quantity: .021
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:

Chem:	Stoddard solvent
Chem (fr):	Solvant Stoddard
Quantity:	.007
Unit:	tonnes
Basis of Estimate Cd:	
Basis of Estimate Desc:	
Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	MSG#3 - Solvent refined heavy paraffinic distillate
Chem (fr):	EMG#3 - Distillat paraffinique lourd raffiné au solvant
Quantity:	.044
Unit:	tonnes
Basis of Estimate Cd:	
Basis of Estimate Desc:	
Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Iron (and its compounds)
Chem (fr):	Fer (et ses composés)
Quantity:	.007
Unit:	tonnes
Basis of Estimate Cd:	
Basis of Estimate Desc:	
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Volatile Organic Compounds (VOCs)
Chem (fr):	Composés organiques volatils (COV)
Quantity:	9.571
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	2.754
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

59	***4 of 12***	***WSW/190.2***	***122.9 / -0.92***	***BURLINGTON TECHNOLOGIES INC.*** ***3267 MAINWAY NOT AVAILABLE*** ***BURLINGTON ON L7M1A6***	***NPRI***

NPRI ID:	3096	**Org ID:**	40258
Other ID:	Y	**Submit Date:**	5/28/1999
No Other ID:	1	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	8457	**Contact ID:**	110233
Report ID:		**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	

Rpt Type ID:	1	***Cont First Name:***	THOR
Report Year:	1998	***Cont Last Name:***	OLSEN
Not-Current Rpt?:	No	***Contact Position:***	OPERATIONS MANAGER
Yr of Last Filed Rpt:	2010	***Contact Fax:***	9053325122
Fac ID:	113721	***Contact Ph.:***	9053352742
Fac Name:	BURLINGTON DIVISION	***Cont Area Code:***	905
Fac Address1:	3267 MAINWAY	***Contact Tel.:***	53352742
Fac Address2:	NOT AVAILABLE	***Contact Ext.:***	279
Fac Postal Zip:	L7M1A6	***Cont Fax Area Cde:***	905
Facility Lat:	43.3644	***Contact Fax:***	53325122
Facility Long:	-79.8037	***Contact Email:***	NOT AVAILABLE
DLS (Last Filed Rpt):		***Latitude:***	43.3644
Facility DLS:		***Longitude:***	-79.8037
Datum:	1983	***UTM Zone:***	17
Facility Cmnts:	False	***UTM Northing:***	4801582
URL:		***UTM Easting:***	596831
No of Empl.:	266	***Waste Streams:***	False
Parent Co.:	Y	***No Streams:***	0
No Parent Co.:	1	***Waste Off Sites:***	Fals
Pollut Prev Cmnts:	False	***No Off Sites:***	1
Stacks:		***Shutdown:***	
No of Stacks:		***No of Shutdown:***	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3315		
NAICS 4 Description:	Foundries		
NAICS Code (6 digit):	331523		
NAICS 6 Description:	Non-ferrous die-casting foundries		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Zinc (and its compounds)
Chem (fr):	Zinc (et ses composés)
Quantity:	.073
Unit:	tonnes
Basis of Estimate Cd:	M
Basis of Estimate Desc:	M- Monitoring or Direct Measurement - In use from 1994 to 2002

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Copper (and its compounds)
Chem (fr):	Cuivre (et ses composés)
Quantity:	.079
Unit:	tonnes
Basis of Estimate Cd:	M
Basis of Estimate Desc:	M- Monitoring or Direct Measurement - In use from 1994 to 2002

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Aluminum (fume or dust)

Chem (fr):	Aluminium (fumée ou poussière)
Quantity:	2.652
Unit:	tonnes
Basis of Estimate Cd:	M
Basis of Estimate Desc:	M- Monitoring or Direct Measurement - In use from 1994 to 2002

59 **5 of 12** **WSW/190.2** **122.9 / -0.92** **BURLINGTON TECHNOLOGIES INC.**
3267 MAINWAY NOT AVAILABLE
BURLINGTON ON L7M1A6 **NPRI**

NPRI ID:	3096	**Org ID:**	40258
Other ID:	*	**Submit Date:**	5/10/2006
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	34082	**Contact ID:**	121055
Report ID:	95847	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	BETTY
Report Year:	2005	**Cont Last Name:**	LOFTHOUSE
Not-Current Rpt?:	No	**Contact Position:**	HEALTH, SAFETY & ENVIRONMENTAL MANAGER
Yr of Last Filed Rpt:	2010	**Contact Fax:**	9053325122
Fac ID:	113721	**Contact Ph.:**	9053352742
Fac Name:	BURLINGTON DIVISION	**Cont Area Code:**	905
Fac Address1:	3267 MAINWAY	**Contact Tel.:**	53352742
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	229
Fac Postal Zip:	L7M1A6	**Cont Fax Area Cde:**	905
Facility Lat:	43.3644	**Contact Fax:**	53325122
Facility Long:	-79.8037	**Contact Email:**	BLOFTHOUSE@BURLTECH.COM
DLS (Last Filed Rpt):		**Latitude:**	43.3644
Facility DLS:		**Longitude:**	-79.8037
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:	www.burltech.com	**UTM Easting:**	
No of Empl.:	255	**Waste Streams:**	False
Parent Co.:	N	**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	False	**No Off Sites:**	1.00
Stacks:	False	**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3315		
NAICS 4 Description:	Foundries		
NAICS Code (6 digit):	331523		
NAICS 6 Description:	Non-ferrous die-casting foundries		

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Copper (and its compounds)
Chem (fr):	Cuivre (et ses composés)
Quantity:	.035
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	MSG#1 - Solvent naphtha medium aliphatic
Chem (fr):	EMG#1 - Solvant naphta aliphatique moyen
Quantity:	3.874
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Aluminum (fume or dust)
Chem (fr):	Aluminium (fumée ou poussière)
Quantity:	.927
Unit:	tonnes
Basis of Estimate Cd:	
Basis of Estimate Desc:	

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	4.941
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Zinc (and its compounds)
Chem (fr):	Zinc (et ses composés)
Quantity:	.035
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	4.197
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

59	***6 of 12***	***WSW/190.2***	***122.9 / -0.92***	***BURLINGTON TECHNOLOGIES INDUSTRIES 3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6***	***NPRI***

NPRI ID:	3096	***Org ID:***	40264

Other ID:	*	**Submit Date:**	5/19/2010
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	84948	**Contact ID:**	198168
Report ID:	138818	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	PETER
Report Year:	2009	**Cont Last Name:**	BORSE
Not-Current Rpt?:	No	**Contact Position:**	ENGINEERING MANAGER
Yr of Last Filed Rpt:	2010	**Contact Fax:**	9053325122
Fac ID:	113721	**Contact Ph.:**	9053352742
Fac Name:	BURLINGTON DIVISION	**Cont Area Code:**	905
Fac Address1:	3267 MAINWAY	**Contact Tel.:**	53352742
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	274
Fac Postal Zip:	L7M1A6	**Cont Fax Area Cde:**	905
Facility Lat:	43.3644	**Contact Fax:**	53325122
Facility Long:	-79.8037	**Contact Email:**	MIS@BURLTECH.COM
DLS (Last Filed Rpt):		**Latitude:**	43.3644
Facility DLS:		**Longitude:**	-79.8037
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	No	**UTM Northing:**	
URL:	www.burltech.com	**UTM Easting:**	
No of Empl.:	189	**Waste Streams:**	No
Parent Co.:	Y	**No Streams:**	
No Parent Co.:	1	**Waste Off Sites:**	Yes
Pollut Prev Cmnts:	No	**No Off Sites:**	1
Stacks:	No	**Shutdown:**	No
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:

NAICS Code (2 digit):	33
NAICS 2 Description:	Manufacturing
NAICS Code (4 digit):	3315
NAICS 4 Description:	Foundries
NAICS Code (6 digit):	331523
NAICS 6 Description:	Non-ferrous die-casting foundries

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	2.171
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Zinc (and its compounds)
Chem (fr):	Zinc (et ses composés)
Quantity:	.031
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID: 13

Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Copper (and its compounds)
Chem (fr):	Cuivre (et ses composés)
Quantity:	.004
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Aluminum (fume or dust)
Chem (fr):	Aluminium (fumée ou poussière)
Quantity:	.121
Unit:	tonnes
Basis of Estimate Cd:	
Basis of Estimate Desc:	

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	2.4
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

---

59 | ***7 of 12*** | ***WSW/190.2*** | ***122.9 / -0.92*** | ***BURLINGTON TECHNOLOGIES INDUSTRIES***
3267 MAINWAY NOT AVAILABLE
BURLINGTON ON L7M1A6 | ***NPRI***

NPRI ID:	3096	**Org ID:**	40264
Other ID:	*	**Submit Date:**	4/23/2008
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	52180	**Contact ID:**	123656
Report ID:	113626	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	BRAD
Report Year:	2007	**Cont Last Name:**	RAMEY
Not-Current Rpt?:	No	**Contact Position:**	HEALTH, SAFETY & ENVIRONMENTAL MANAGER
Yr of Last Filed Rpt:	2010	**Contact Fax:**	9053325122
Fac ID:	113721	**Contact Ph.:**	9053352742
Fac Name:	BURLINGTON DIVISION	**Cont Area Code:**	905
Fac Address1:	3267 MAINWAY	**Contact Tel.:**	53352742
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	229
Fac Postal Zip:	L7M1A6	**Cont Fax Area Cde:**	905
Facility Lat:	43.3644	**Contact Fax:**	53325122
Facility Long:	-79.8037	**Contact Email:**	BGR@BURLTECH.COM
DLS (Last Filed Rpt):		**Latitude:**	43.3644
Facility DLS:		**Longitude:**	-79.8037
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:	www.burltech.com	**UTM Easting:**	
No of Empl.:	209	**Waste Streams:**	True?
Parent Co.:	N	**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	True

Pollut Prev Cmnts: False
Stacks: True
No of Stacks:
Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 33
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3315
NAICS 4 Description: Foundries
NAICS Code (6 digit): 331523
NAICS 6 Description: Non-ferrous die-casting foundries
No Off Sites: 1.00
Shutdown:
No of Shutdown:

Substance Release Report

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Zinc (and its compounds)
Chem (fr): Zinc (et ses composés)
Quantity: .039
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Copper (and its compounds)
Chem (fr): Cuivre (et ses composés)
Quantity: .005
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr): PM2,5 - Matière particulaire <= 2,5 microns
Quantity: 2.535
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Aluminum (fume or dust)
Chem (fr): Aluminium (fumée ou poussière)
Quantity: .152
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 1

Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	2.824
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

59 | **8 of 12** | **WSW/190.2** | **122.9 / -0.92** | **BURLINGTON TECHNOLOGIES: BURLINGTON DIVISION**
3267 MAINWAY NOT AVAILABLE
BURLINGTON ON L7M1A6 | **NPRI**

NPRI ID:	3096	**Org ID:**	9436
Other ID:		**Submit Date:**	
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	8454	**Contact ID:**	
Report ID:		**Cont Type:**	
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	1993	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2010	**Contact Fax:**	
Fac ID:	44793	**Contact Ph.:**	
Fac Name:	NOT AVAILABLE	**Cont Area Code:**	
Fac Address1:	3267 MAINWAY	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	L7M1A6	**Cont Fax Area Cde:**	
Facility Lat:	43.3644	**Contact Fax:**	
Facility Long:	-79.8037	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.3644
Facility DLS:		**Longitude:**	-79.8037
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:		**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3315		
NAICS 4 Description:	Foundries		
NAICS Code (6 digit):	331523		
NAICS 6 Description:	Non-ferrous die-casting foundries		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	
Chem (fr):	

Quantity:	1.88
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

59 **9 of 12** **WSW/190.2** **122.9 / -0.92** **BURLINGTON TECHNOLOGIES INC.**
3267 MAINWAY NOT AVAILABLE
BURLINGTON ON L7M1A6 **NPRI**

NPRI ID:	3096	**Org ID:**	40258
Other ID:	Y	**Submit Date:**	6/1/2001
No Other ID:	3.00	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	8459	**Contact ID:**	110233
Report ID:		**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	THOR
Report Year:	2000	**Cont Last Name:**	OLSEN
Not-Current Rpt?:	No	**Contact Position:**	OPERATIONS MANAGER
Yr of Last Filed Rpt:	2010	**Contact Fax:**	9053325122
Fac ID:	113721	**Contact Ph.:**	9053352742
Fac Name:	BURLINGTON DIVISION	**Cont Area Code:**	905
Fac Address1:	3267 MAINWAY	**Contact Tel.:**	53352742
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	279
Fac Postal Zip:	L7M1A6	**Cont Fax Area Cde:**	905
Facility Lat:	43.3644	**Contact Fax:**	53325122
Facility Long:	-79.8037	**Contact Email:**	NOT AVAILABLE
DLS (Last Filed Rpt):		**Latitude:**	43.3644
Facility DLS:		**Longitude:**	-79.8037
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:	www.burltech.com	**UTM Easting:**	
No of Empl.:	266	**Waste Streams:**	No
Parent Co.:	*	**No Streams:**	0
No Parent Co.:	1.00	**Waste Off Sites:**	Yes
Pollut Prev Cmnts:	False	**No Off Sites:**	1.00
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3315		
NAICS 4 Description:	Foundries		
NAICS Code (6 digit):	331523		
NAICS 6 Description:	Non-ferrous die-casting foundries		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Aluminum (fume or dust)
Chem (fr):	Aluminium (fumée ou poussière)
Quantity:	3.89
Unit:	tonnes
Basis of Estimate Cd:	E
Basis of Estimate Desc:	E- Emission Factor - In use from 1994 to 2002

Category Type ID:	1
Category Type Desc:	Stack / Point

Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Zinc (and its compounds)
Chem (fr):	Zinc (et ses composés)
Quantity:	.11
Unit:	tonnes
Basis of Estimate Cd:	E
Basis of Estimate Desc:	E- Emission Factor - In use from 1994 to 2002

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Copper (and its compounds)
Chem (fr):	Cuivre (et ses composés)
Quantity:	.12
Unit:	tonnes
Basis of Estimate Cd:	E
Basis of Estimate Desc:	E- Emission Factor - In use from 1994 to 2002

---

59 **10 of 12** **WSW/190.2** **122.9 / -0.92** **BURLINGTON TECHNOLOGIES INC.**
3267 MAINWAY NOT AVAILABLE
BURLINGTON ON L7M1A6 **NPRI**

NPRI ID:	3096	**Org ID:**	40258
Other ID:	Y	**Submit Date:**	5/30/2002
No Other ID:	2.00	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	8455	**Contact ID:**	99835
Report ID:		**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	MIKE
Report Year:	2001	**Cont Last Name:**	BOYLE
Not-Current Rpt?:	No	**Contact Position:**	CORPORATE HS&E MANAGER
Yr of Last Filed Rpt:	2010	**Contact Fax:**	9033325122
Fac ID:	113721	**Contact Ph.:**	9053352742
Fac Name:	BURLINGTON DIVISION	**Cont Area Code:**	905
Fac Address1:	3267 MAINWAY	**Contact Tel.:**	53352742
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	229
Fac Postal Zip:	L7M1A6	**Cont Fax Area Cde:**	903
Facility Lat:	43.3644	**Contact Fax:**	33325122
Facility Long:	-79.8037	**Contact Email:**	MRB@BURLTECH.COM
DLS (Last Filed Rpt):		**Latitude:**	43.3644
Facility DLS:		**Longitude:**	-79.8037
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	No	**UTM Northing:**	
URL:	www.burltech.com	**UTM Easting:**	
No of Empl.:	266	**Waste Streams:**	No
Parent Co.:	*	**No Streams:**	0.00
No Parent Co.:	1.00	**Waste Off Sites:**	Yes
Pollut Prev Cmnts:	No	**No Off Sites:**	1.00
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3315		
NAICS 4 Description:	Foundries		
NAICS Code (6 digit):	331523		
NAICS 6 Description:	Non-ferrous die-casting foundries		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Aluminum (fume or dust)
Chem (fr):	Aluminium (fumée ou poussière)
Quantity:	3.891
Unit:	tonnes
Basis of Estimate Cd:	M
Basis of Estimate Desc:	M- Monitoring or Direct Measurement - In use from 1994 to 2002

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Copper (and its compounds)
Chem (fr):	Cuivre (et ses composés)
Quantity:	.146
Unit:	tonnes
Basis of Estimate Cd:	M
Basis of Estimate Desc:	M- Monitoring or Direct Measurement - In use from 1994 to 2002

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Zinc (and its compounds)
Chem (fr):	Zinc (et ses composés)
Quantity:	.141
Unit:	tonnes
Basis of Estimate Cd:	M
Basis of Estimate Desc:	M- Monitoring or Direct Measurement - In use from 1994 to 2002

---

59 ***11 of 12*** ***WSW/190.2*** ***122.9 / -0.92*** ***BURLINGTON TECHOLOGIES INC.***
3267 MAINWAY NOT AVAILABLE
BURLINGTON ON L7M1A6 ***NPRI***

NPRI ID:	3096	***Org ID:***	9437
Other ID:	Y	***Submit Date:***	8/11/1998
No Other ID:	1	***Last Modified:***	5/29/2015 3:28:24 PM
Track ID:	8456	***Contact ID:***	110233
Report ID:		***Cont Type:***	MED
Report Type:	NPRI	***Contact Title:***	
Rpt Type ID:	1	***Cont First Name:***	THOR
Report Year:	1997	***Cont Last Name:***	OLSEN
Not-Current Rpt?:	No	***Contact Position:***	OPERATIONS MANAGER
Yr of Last Filed Rpt:	2010	***Contact Fax:***	9053325122
Fac ID:	113721	***Contact Ph.:***	9053352742
Fac Name:	BURLINGTON DIVISION	***Cont Area Code:***	905
Fac Address1:	3267 MAINWAY	***Contact Tel.:***	53352742
Fac Address2:	NOT AVAILABLE	***Contact Ext.:***	279
Fac Postal Zip:	L7M1A6	***Cont Fax Area Cde:***	905
Facility Lat:	43.3644	***Contact Fax:***	53325122
Facility Long:	-79.8037	***Contact Email:***	NOT AVAILABLE
DLS (Last Filed Rpt):		***Latitude:***	43.3644
Facility DLS:		***Longitude:***	-79.8037
Datum:	1983	***UTM Zone:***	17
Facility Cmnts:	FALSE	***UTM Northing:***	4801582
URL:		***UTM Easting:***	596831

No of Empl.:	266	**Waste Streams:**	FALSE
Parent Co.:	*	**No Streams:**	0
No Parent Co.:	1	**Waste Off Sites:**	TRUE
Pollut Prev Cmnts:	FALSE	**No Off Sites:**	1
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 33
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3315
NAICS 4 Description: Foundries
NAICS Code (6 digit): 331523
NAICS 6 Description: Non-ferrous die-casting foundries

Substance Release Report

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Copper (and its compounds)
Chem (fr): Cuivre (et ses composés)
Quantity: .07
Unit: tonnes
Basis of Estimate Cd: E
Basis of Estimate Desc: E- Emission Factor - In use from 1994 to 2002

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Zinc (and its compounds)
Chem (fr): Zinc (et ses composés)
Quantity: .062
Unit: tonnes
Basis of Estimate Cd: E
Basis of Estimate Desc: E- Emission Factor - In use from 1994 to 2002

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Aluminum (fume or dust)
Chem (fr): Aluminium (fumée ou poussière)
Quantity: 3.09
Unit: tonnes
Basis of Estimate Cd: E
Basis of Estimate Desc: E- Emission Factor - In use from 1994 to 2002

---

59 | ***12 of 12*** | ***WSW/190.2*** | ***122.9 / -0.92*** | ***BURLINGTON TECHNOLOGIES INDUSTRIES***
3267 MAINWAY NOT AVAILABLE
BURLINGTON ON L7M1A6 | ***NPRI***

NPRI ID:	3096	**Org ID:**	40264
Other ID:	*	**Submit Date:**	5/29/2007
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	45895	**Contact ID:**	121055
Report ID:	108823	**Cont Type:**	MED

Report Type:	NPRI	***Contact Title:***	
Rpt Type ID:	1	***Cont First Name:***	BETTY
Report Year:	2006	***Cont Last Name:***	LOFTHOUSE
Not-Current Rpt?:	No	***Contact Position:***	HEALTH, SAFETY & ENVIRONMENTAL MANAGER
Yr of Last Filed Rpt:	2010	***Contact Fax:***	9053325122
Fac ID:	113721	***Contact Ph.:***	9053352742
Fac Name:	BURLINGTON DIVISION	***Cont Area Code:***	905
Fac Address1:	3267 MAINWAY	***Contact Tel.:***	53352742
Fac Address2:	NOT AVAILABLE	***Contact Ext.:***	229
Fac Postal Zip:	L7M1A6	***Cont Fax Area Cde:***	905
Facility Lat:	43.3644	***Contact Fax:***	53325122
Facility Long:	-79.8037	***Contact Email:***	BLOFTHOUSE@BURLTECH.COM
DLS (Last Filed Rpt):		***Latitude:***	43.3644
Facility DLS:		***Longitude:***	-79.8037
Datum:	1983	***UTM Zone:***	
Facility Cmnts:	False	***UTM Northing:***	
URL:	www.burltech.com	***UTM Easting:***	
No of Empl.:	255	***Waste Streams:***	True?
Parent Co.:	N	***No Streams:***	
No Parent Co.:		***Waste Off Sites:***	Fals
Pollut Prev Cmnts:	False	***No Off Sites:***	1.00
Stacks:	True	***Shutdown:***	
No of Stacks:		***No of Shutdown:***	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3315		
NAICS 4 Description:	Foundries		
NAICS Code (6 digit):	331523		
NAICS 6 Description:	Non-ferrous die-casting foundries		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	3.84
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Copper (and its compounds)
Chem (fr):	Cuivre (et ses composés)
Quantity:	.007
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t

Trans Code:
Chem: MSG#1 - Hydrotreated heavy naphtha
Chem (fr): EMG#1 - Naphta lourd hydrotraité
Quantity: .004
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr): PM2,5 - Matière particulaire <= 2,5 microns
Quantity: 3.434
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Aluminum (fume or dust)
Chem (fr): Aluminium (fumée ou poussière)
Quantity: .233
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: MSG#1 - Solvent naphtha medium aliphatic
Chem (fr): EMG#1 - Solvant naphta aliphatique moyen
Quantity: 4.467
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Zinc (and its compounds)
Chem (fr): Zinc (et ses composés)
Quantity: .059
Unit: tonnes
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

---

60 | ***1 of 1*** | ***SW/193.3*** | ***121.8 / -1.93*** | ***BELL CANADA***
1191 PIONEER ROAD
BURLINGTON ON L7M 1K5 | ***GEN***

Generator No.: ON0473703
Status:
Approval Years: 86,87
Contam. Facility:
MHSW Facility:

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

SIC Code: 4821
SIC Description: TELECOMMUN. CARRRIERS

--Details--
Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 131
Waste Description: NEUTRALIZED WASTES - HEAVY METALS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

61 | **1 of 1** | **SW/195.4** | **121.1 / -2.69** | **PST Machining Ltd.**
1163 Pioneer Rd Unit I
Burlington ON L7M 1K5 | **SCT**

Established: 01-AUG-91
Plant Size (ft²): 5000
Employment:

--Details--
Description: Machine Shops
SIC/NAICS Code: 332710

---

62 | **1 of 7** | **NW/195.8** | **125.8 / 2.07** | **Accurate Concrete Cutting**
3333 Mainway, Suite B
Burlington ON L7M 1A6 | **GEN**

Generator No.: ON6370890
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
PO Box No.:
Country: Canada
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252 L
Waste Description: Waste crankcase oils and lubricants

---

62 | **2 of 7** | **NW/195.8** | **125.8 / 2.07** | **Accurate Concrete Cutting**
3333 Mainway, Suite B
Burlington ON L7M 1A6 | **GEN**

Generator No.: ON6370890
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 327390
SIC Description: OTHER CONCRETE PRODUCT MANUFACTURING
PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
62	3 of 7	NW/195.8	125.8 / 2.07	ALLEN INDUSTRIAL RUBBER PROD 3333 Mainway Dr Unit A Burlington ON L7M 1A6	SCT

Established: 1978
Plant Size (ft²): 1800
Employment: 3

--Details--
Description: Other Rubber Product Manufacturing
SIC/NAICS Code: 326290

Description: All Other Miscellaneous Manufacturing
SIC/NAICS Code: 339990

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
62	4 of 7	NW/195.8	125.8 / 2.07	ALLEN INDUSTRIAL RUBBER PROD 3333A MAINWAY DR BURLINGTON ON L7M 1A6	SCT

Established: 1978
Plant Size (ft²): 1800
Employment: 3

--Details--
Description: GASKETS, PACKING AND SEALING DEVICES
SIC/NAICS Code: 3053

Description: FABRICATED RUBBER PRODUCTS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3069

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
62	5 of 7	NW/195.8	125.8 / 2.07	Allen Industrial Rubber Products (1988) Ltd. 3333 Mainway Dr Unit A Burlington ON L7M 1A6	SCT

Established: 1978
Plant Size (ft²): 1800
Employment: 3

--Details--
Description: Resin and Synthetic Rubber Manufacturing
SIC/NAICS Code: 325210

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
62	6 of 7	NW/195.8	125.8 / 2.07	ALLEN INDUSTRIAL RUBBER PRODS 3333 A MAINWAY DR BURLINGTON ON L7M 1A6	SCT

Established: 1978
Plant Size (ft²): 1800
Employment: 3

--Details--
Description: GASKETS, PACKING & SEALING DEVICES
SIC/NAICS Code: 3053

Description: FABRICATED RUBBER PRODUCTS, N.E.C.

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC/NAICS Code: 3069

---

62 | **7 of 7** | **NW/195.8** | **125.8 / 2.07** | **Allen Industrial Rubber Prod**
3333 Mainway Unit A
Burlington ON L7M 1A6 | **SCT**

Established: 01-AUG-78
Plant Size (ft²): 1800
Employment:

--Details--
Description: All Other Miscellaneous Manufacturing
SIC/NAICS Code: 339990

Description: Other Rubber Product Manufacturing
SIC/NAICS Code: 326290

Description: All Other Plastic Product Manufacturing
SIC/NAICS Code: 326198

Description: Other Rubber Product Manufacturing
SIC/NAICS Code: 326290

---

63 | **1 of 1** | **SW/204.5** | **120.8 / -2.96** | **Burlington ON** | **WWIS**

Well ID: 7136268
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: 0
Water Type:
Casing Material:
Audit No: M05489
Tag: A055831
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 12/17/2009
Selected Flag: 1
Abandonment Rec: Yes
Contractor: 7282
Form Version: 5
Owner:
Street Name: 3230 MAINWAY
County: HALTON
Municipality: BURLINGTON CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1003226671
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 121.627418
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 11/24/2009

Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1003226675
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003226674
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Hole Diameter

Hole ID: 1003226673
Diameter: 20.90
Depth From:
Depth To: 6.00
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1003226706
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 121.259834
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 11/26/2009

Annular Space/Abandonment Sealing Record

Plug ID: 1003226710
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003226709
Method Construction Code:
Method Construction:

Other Method Construction: BORING

Hole Diameter

Hole ID: 1003226708
Diameter: 20.90
Depth From:
Depth To: 7.00
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1003226681
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 120.929916
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 11/24/2009

Annular Space/Abandonment Sealing Record

Plug ID: 1003226685
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003226684
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Hole Diameter

Hole ID: 1003226683
Diameter: 20.90
Depth From:
Depth To: 5.40
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002886840
DP2BR:
Code OB:
Code OB Desc:
Open Hole:

Spatial Status:
Cluster Kind:
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Elevation: 120.929916
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Org CS: UTM83
Date Completed: 11/30/2009

Annular Space/Abandonment Sealing Record

Plug ID: 1003226731
Layer: 1
Plug From: 0.00
Plug To: 5.40
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1003226732
Method Construction Code:
Method Construction:
Other Method Construction:

Bore Hole Information

Bore Hole ID: 1003226696
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 114.536201
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 11/25/2009

Annular Space/Abandonment Sealing Record

Plug ID: 1003226700
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003226699
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Hole Diameter

Hole ID: 1003226698
Diameter: 20.90
Depth From:
Depth To: 9.00
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1003226691
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 115.138679
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 11/25/2009

Annular Space/Abandonment Sealing Record

Plug ID: 1003226695
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003226694
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Hole Diameter

Hole ID: 1003226693
Diameter: 20.90
Depth From:
Depth To: 6.00
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1003226701
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 121.611808
Elevrc:
Remarks:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 11/26/2009

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1003226705
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003226704
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Hole Diameter

Hole ID: 1003226703
Diameter: 20.90
Depth From:
Depth To: 6.00
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1003226716
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 121.070816
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 11/27/2009

Annular Space/Abandonment Sealing Record

Plug ID: 1003226720
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003226719
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Hole Diameter

Hole ID: 1003226718
Diameter: 20.90
Depth From:
Depth To: 6.00
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1003226676
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 121.241088
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 11/24/2009

Annular Space/Abandonment Sealing Record

Plug ID: 1003226680
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003226679
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Hole Diameter

Hole ID: 1003226678
Diameter: 20.90
Depth From:
Depth To: 6.00
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1003226711
Spatial Status:

DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 122.275436
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 11/26/2009

Annular Space/Abandonment Sealing Record

Plug ID: 1003226715
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003226714
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Hole Diameter

Hole ID: 1003226713
Diameter: 20.90
Depth From:
Depth To: 5.50
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1003226686
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 116.44403
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 11/25/2009

Annular Space/Abandonment Sealing Record

Plug ID: 1003226690
Layer:

Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003226689
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Hole Diameter

Hole ID: 1003226688
Diameter: 20.90
Depth From:
Depth To: 6.00
Hole Depth UOM: m
Hole Diameter UOM: cm

---

64 | ***1 of 9*** | ***NW/204.9*** | ***126.5 / 2.69*** | ***EcoSynthetix Inc. 3365 Mainway Drive Burlington, Regional Municipality of Halton L7M 1A6 CITY OF BURLINGTON ON*** | ***EBR***

EBR Registry No.: 011-9893
Ministry Ref. No.: 4679-9AJRL6
Company Name: EcoSynthetix Inc.
Notice Type: Instrument Decision
Notice Date: December 02, 2015
Proposal Date: August 26, 2013
Year: 2013
Proponent Address: 3365 Mainway Drive, Burlington Ontario, Canada L7M 1A6
Instrument Type: (EPA Part II.1-air) - Environmental Compliance Approval (project type: air)
Location Other:

Location:

3365 Mainway Drive Burlington, Regional Municipality of Halton L7M 1A6 CITY OF BURLINGTON

---

64 | ***2 of 9*** | ***NW/204.9*** | ***126.5 / 2.69*** | ***3365 Mainway Burlington ON L7M1A6*** | ***EHS***

Order ID: 278735
Order No: 20131024002
Customer ID: 56847
Company ID: 77
Status: C
Report Code: 4CAN
Report Type: Custom Report
Report Date: 30-OCT-13
Report Requested by: Pinchin Ltd
Nearest Intersection:
Previous Site Name:
Additional Info Ordered:

Date Received: 24-OCT-13
Lot/Building Size:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
Large Radius: 2
X: -79.80162
Y: 43.367248

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	3 of 9	NW/204.9	126.5 / 2.69	EcoSynthetix Inc 3365 Mainway Burlington ON L7M 1A6	GEN

Generator No.: ON3318858
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 541710
SIC Description: RESEARCH AND DEVELOPMENT IN THE PHYSICAL, ENGINEERING AND LIFE SCIENCES

PO Box No.:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Sabina Di Risio
Phone No. Admin: 289-245-4010 Ext.

--Details--

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 233
Waste Description: OTHER POLYMERIC WASTES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 331
Waste Description: WASTE COMPRESSED GASES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	4 of 9	NW/204.9	126.5 / 2.69	EcoSynthetix Inc 3365 Mainway Burlington ON L7M 1A6	GEN

Generator No.: ON3318858
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 541710
SIC Description: RESEARCH AND DEVELOPMENT IN THE PHYSICAL, ENGINEERING AND LIFE SCIENCES

PO Box No.:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Sabina Di Risio
Phone No. Admin: 289-245-4010 Ext.

--Details--

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 331
Waste Description: WASTE COMPRESSED GASES

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 233
Waste Description: OTHER POLYMERIC WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	5 of 9	NW/204.9	126.5 / 2.69	EcoSynthetix Inc 3365 Mainway Burlington ON L7M 1A6	GEN

Generator No.: ON3318858
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 541710
SIC Description: RESEARCH AND DEVELOPMENT IN THE PHYSICAL, ENGINEERING AND LIFE SCIENCES

PO Box No.:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Julien Mesnager
Phone No. Admin: 2892083813 Ext.

--Details--

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 331
Waste Description: WASTE COMPRESSED GASES

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 233
Waste Description: OTHER POLYMERIC WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	6 of 9	NW/204.9	126.5 / 2.69	EcoSynthetix Inc EcoSynthetix Corporation 3365 Mainway Burlington ON L7M 1A6	GEN

Generator No.: ON3318858
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country: Canada
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--

Waste Code: 148 B
Waste Description: Misc. wastes and inorganic chemicals

Waste Code: 263 I
Waste Description: Misc. waste organic chemicals

Waste Code: 233 L
Waste Description: Other polymeric wastes

Waste Code: 148 C
Waste Description: Misc. wastes and inorganic chemicals

Waste Code: 145 L
Waste Description: Wastes from the use of pigments, coatings and paints

Waste Code: 148 L
Waste Description: Misc. wastes and inorganic chemicals

Waste Code: 148 I
Waste Description: Misc. wastes and inorganic chemicals

Waste Code: 263 C
Waste Description: Misc. waste organic chemicals

Waste Code: 263 B
Waste Description: Misc. waste organic chemicals

Waste Code: 252 L
Waste Description: Waste crankcase oils and lubricants

Waste Code: 331 I
Waste Description: Waste compressed gases including cylinders

Waste Code: 263 L
Waste Description: Misc. waste organic chemicals

Waste Code: 263 R
Waste Description: Misc. waste organic chemicals

---

64 **7 of 9** **NW/204.9** **126.5 / 2.69** **EcoSynthetix Inc**
3365 Mainway
Burlington ON
GEN

Generator No.: ON3318858
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 541710
SIC Description: Research and Development in the Physical Engineering and Life Sciences

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

---

64 **8 of 9** **NW/204.9** **126.5 / 2.69** **EcoSynthetix Inc**
3365 Mainway
Burlington ON
GEN

Generator No.: ON3318858
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 541710
SIC Description: RESEARCH AND DEVELOPMENT IN THE PHYSICAL, ENGINEERING AND LIFE SCIENCES

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 233
Waste Description: OTHER POLYMERIC WASTES

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 331
Waste Description: WASTE COMPRESSED GASES

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	9 of 9	NW/204.9	126.5 / 2.69	Mahle Clevite Canada ULC 3365 Mainway Unit 2 Burlington ON L7M 1A6	SCT

Established: 01-AUG-07
Plant Size (ft²):
Employment:

--Details--
Description: Other New Motor Vehicle Parts and Accessories Wholesaler-Distributors
SIC/NAICS Code: 415290

Description: Other New Motor Vehicle Parts and Accessories Wholesaler-Distributors
SIC/NAICS Code: 415290

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
65	1 of 1	SSE/209.0	119.8 / -3.93	Pioneer Road Burlington ON	EHS

Order ID: 46711
Order No: 20041101018
Customer ID: 21483
Company ID: 20463
Status: C
Report Code: 1USA
Report Type: Complete Report
Report Date: 11/10/04
Report Requested by: Enercon Services, Inc.
Nearest Intersection:
Previous Site Name:
Additional Info Ordered:

Date Received: 11/1/04
Lot/Building Size:
Municipality:
Client Prov/State: TX
Search Radius (km): 0.3
Large Radius: 2
X: -79.798633
Y: 43.362914

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
66	1 of 17	NNE/209.4	125.7 / 1.89	Bosch Rexroth Canada Corp. 3426 Mainway Burlington ON L7M 1A8	CA

Certificate #: 9675-8KMJJZ
Application Year: 2011
Issue Date: 10/26/2011
Approval Type: Air
Status: Approved
Application Type:
Client Name::
Client Address::
Client City::
Client Postal Code::
Project Description::
Contaminants::
Emission Control::

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
66	2 of 17	NNE/209.4	125.7 / 1.89	BOSCH REXROTH CANADA CORP. 3426 MAINWAY DRIVE BURLINGTON ON L7M 1A8	GEN

Generator No.: ON0677501
Status:
Approval Years: 2010
Contam. Facility:

PO Box No.:
Country:
Choice of Contact:
Co Admin:

MHSW Facility: **Phone No. Admin:**
SIC Code: 335990
SIC Description: All Other Electrical Equipment and Component Manufacturing

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 268
Waste Description: AMINES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

---

66 | ***3 of 17*** | ***NNE/209.4*** | ***125.7 / 1.89*** | ***KERNIC EQUIPMENT (OUT OF BUSINESS)23-112***
3426 MAINWAY
BURLINGTON ON L7M 1A8 | ***GEN***

Generator No.: ON0489400 **PO Box No.:**
Status: **Country:**
Approval Years: 92,93,94,95,96,97,98 **Choice of Contact:**
Contam. Facility: **Co Admin:**
MHSW Facility: **Phone No. Admin:**
SIC Code: 5711
SIC Description: FARM MACHINERY

---

66 | ***4 of 17*** | ***NNE/209.4*** | ***125.7 / 1.89*** | ***BOSCH REXROTH CANADA CORP.***
3426 MAINWAY DRIVE
BURLINGTON ON L7M 1A8 | ***GEN***

Generator No.: ON0677501 **PO Box No.:**
Status: **Country:**
Approval Years: 2012 **Choice of Contact:**
Contam. Facility: **Co Admin:**
MHSW Facility: **Phone No. Admin:**
SIC Code: 335990
SIC Description: All Other Electrical Equipment and Component Manufacturing

--Details--
Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 263

Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 268
Waste Description: AMINES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

---

66 | ***5 of 17*** | ***NNE/209.4*** | ***125.7 / 1.89*** | ***KERNIC EQUIPMENT SALES LIMITED***
3426 MAINWAY
BURLINGTON ON L7M 1A8 | ***GEN***

Generator No.: ON0489400
Status:
Approval Years: 86,87,88,89
Contam. Facility:
MHSW Facility:
SIC Code: 5711
SIC Description: FARM MACHINERY

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

66 | ***6 of 17*** | ***NNE/209.4*** | ***125.7 / 1.89*** | ***BASIC TECHNOLOGIES***
3426 MAINWAY
BURLINGTON ON L7M 1A8 | ***GEN***

Generator No.: ON0677501
Status:
Approval Years: 97,98
Contam. Facility:
MHSW Facility:
SIC Code: 5792
SIC Description: SERVICE MACH., WH.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

66 | ***7 of 17*** | ***NNE/209.4*** | ***125.7 / 1.89*** | ***BASIC TECHNOLOGIES***
3426 MAINWAY DRIVE
BURLINGTON ON L7M 1A8 | ***GEN***

Generator No.:	ON0677501	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	99,00	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	5792		
SIC Description:	SERVICE MACH., WH.		

--Details--

Waste Code:	213
Waste Description:	PETROLEUM DISTILLATES
Waste Code:	253
Waste Description:	EMULSIFIED OILS

---

66 ***8 of 17*** ***NNE/209.4*** ***125.7 / 1.89*** ***BOSCH REXROTH CANADA CORP.***
3426 MAINWAY DRIVE
BURLINGTON ON L7M 1A8 ***GEN***

Generator No.:	ON0677501	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	2011	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	335990		
SIC Description:	All Other Electrical Equipment and Component Manufacturing		

--Details--

Waste Code:	121
Waste Description:	ALKALINE WASTES - HEAVY METALS
Waste Code:	112
Waste Description:	ACID WASTE - HEAVY METALS
Waste Code:	263
Waste Description:	ORGANIC LABORATORY CHEMICALS
Waste Code:	213
Waste Description:	PETROLEUM DISTILLATES
Waste Code:	268
Waste Description:	AMINES
Waste Code:	252
Waste Description:	WASTE OILS & LUBRICANTS
Waste Code:	251
Waste Description:	OIL SKIMMINGS & SLUDGES
Waste Code:	211
Waste Description:	AROMATIC SOLVENTS

---

66 ***9 of 17*** ***NNE/209.4*** ***125.7 / 1.89*** ***BOSCH REXROTH CANADA CORP.***
3426 MAINWAY DRIVE BURLINGTON
ON ON L7M 1A8 ***GEN***

Generator No.:	ON0677501	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	02,03	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	

SIC Code:
SIC Description:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 268
Waste Description: AMINES

---

66 ***10 of 17*** ***NNE/209.4*** ***125.7 / 1.89*** ***BOSCH REXROTH CANADA CORP.***
3426 MAINWAY DRIVE
BURLINGTON ON L7M 1A8 ***GEN***

Generator No.: ON0677501
Status:
Approval Years: 01,04,05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code: 5792
SIC Description: SERVICE MACH., WH.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 268
Waste Description: AMINES

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

66 ***11 of 17*** ***NNE/209.4*** ***125.7 / 1.89*** ***BOSCH REXROTH CANADA CORP.***
3426 MAINWAY DRIVE
BURLINGTON ON L7M 1A8 ***GEN***

Generator No.: ON0677501
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 335990
SIC Description: All Other Electrical Equipment and Component Manufacturing

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Code:		268			
Waste Description:		AMINES			

66	12 of 17	NNE/209.4	125.7 / 1.89	**Bosch Rexroth Canada Corporation - Pneumatics Division** **3426 Mainway Dr** **Burlington ON L7M 1A8**	PAP

Division:
Mailing Address:: 3426 Mainway Dr, Burlington ON L7M 1A8
Year: 2009
Company ID: 3126138161
Mill Notes::
History::
Operation:
Type:
Status:: Active

66	13 of 17	NNE/209.4	125.7 / 1.89	**Bosch Rexroth Canada Corporation - Linear Division** **3426 Mainway Dr** **Burlington ON L7M 1A8**	PAP

Division:
Mailing Address:: 3426 Mainway Dr, Burlington ON L7M 1A8
Year: 2009
Company ID: 3126091469
Mill Notes::
History::
Operation:
Type:
Status:: Active

66	14 of 17	NNE/209.4	125.7 / 1.89	**Bosch Rexroth Canada Corporation - Controls Division** **3426 Mainway Dr** **Burlington ON L7M 1A8**	PAP

Division:
Mailing Address:: 3426 Mainway Dr, Burlington ON L7M 1A8
Year: 2009
Company ID: 3126131164
Mill Notes::
History::
Operation:
Type:
Status:: Active

66	15 of 17	NNE/209.4	125.7 / 1.89	**Bosch Rexroth Canada Corp.** **3426 Mainway** **Burlington ON L7M 1A8**	SCT

Established: 01-JUL-61
Plant Size (ft²):
Employment:

--Details--
Description: Material Handling Equipment Manufacturing

SIC/NAICS Code: 333920

Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Description: Switchgear and Switchboard, and Relay and Industrial Control Apparatus Manufacturing
SIC/NAICS Code: 335315

Description: All Other Industrial Machinery Manufacturing
SIC/NAICS Code: 333299

Description: Computer, Computer Peripheral and Pre-Packaged Software Wholesaler-Distributors
SIC/NAICS Code: 417310

Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

Description: Other New Motor Vehicle Parts and Accessories Wholesaler-Distributors
SIC/NAICS Code: 415290

Description: Switchgear and Switchboard, and Relay and Industrial Control Apparatus Manufacturing
SIC/NAICS Code: 335315

Description: Measuring, Medical and Controlling Devices Manufacturing
SIC/NAICS Code: 334512

Description: Other Engine and Power Transmission Equipment Manufacturing
SIC/NAICS Code: 333619

Description: Metal Valve Manufacturing
SIC/NAICS Code: 332910

Description: All Other General-Purpose Machinery Manufacturing
SIC/NAICS Code: 333990

Description: Electronic Components, Navigational and Communications Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417320

Description: Motor and Generator Manufacturing
SIC/NAICS Code: 335312

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
66	16 of 17	NNE/209.4	125.7 / 1.89	**Bosch Rexroth Canada Corp.** **3426 Mainway Dr** **Burlington ON L7M 1A8**	SCT

Established: 1983
Plant Size (ft²):
Employment: 60

--Details--
Description: All Other Industrial Machinery Manufacturing
SIC/NAICS Code: 333299

Description: Motor and Generator Manufacturing
SIC/NAICS Code: 335312

Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Description: Metal Valve Manufacturing
SIC/NAICS Code: 332910

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
66	17 of 17	NNE/209.4	125.7 / 1.89	BASIC TECHNOLOGIES CORP. 3426 MAINWAY DR BURLINGTON ON L7M 1A8	SCT

Established: 1983
Plant Size (ft²): 0
Employment: 50

--Details--
Description: All Other General-Purpose Machinery Manufacturing
SIC/NAICS Code: 333990

Description: Measuring, Medical and Controlling Devices Manufacturing
SIC/NAICS Code: 334512

Description: Switchgear and Switchboard, and Relay and Industrial Control Apparatus Manufacturing
SIC/NAICS Code: 335315

Description: INDUSTRIAL TRUCKS, TRACTORS, TRAILERS, AND STACKERS
SIC/NAICS Code: 3537

Description: SPEED CHANGERS, INDUSTRIAL HIGH-SPEED DRIVES, AND GEARS
SIC/NAICS Code: 3566

Description: RELAYS AND INDUSTRIAL CONTROLS
SIC/NAICS Code: 3625

Description: AUTOMATIC CONTROLS FOR REGULATING RESIDENTIAL AND COMMERCIAL ENVIRONMENTS AND APPLIANCES
SIC/NAICS Code: 3822

Description: INDUSTRIAL INSTRUMENTS FOR MEASUREMENT, DISPLAY, AND CONTROL OF PROCESS VARIABLES; & RELATED ITEMS
SIC/NAICS Code: 3823

Description: Other Engine and Power Transmission Equipment Manufacturing
SIC/NAICS Code: 333619

Description: Material Handling Equipment Manufacturing
SIC/NAICS Code: 333920

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
67	1 of 12	WNW/209.9	125.8 / 2.07	Alkano Grinding and Stamping Company Limited 3321 Mainway, Unit A & B Burlington ON L7M 1A6	GEN

Generator No.: ON7689466
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 332710
SIC Description: MACHINE SHOPS

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
67	2 of 12	WNW/209.9	125.8 / 2.07	Alkano Grinding and Stamping Company Limited	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				3321 Mainway, Unit A & B **Burlington ON L7M 1A6**	

Generator No.: ON7689466
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country: Canada
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252 L
Waste Description: Waste crankcase oils and lubricants

---

67 | **3 of 12** | **WNW/209.9** | **125.8 / 2.07** | **Alkano Grinding and Stamping Company Limited**
3321 Mainway, Unit A & B
Burlington ON L7M 1A6 | **GEN**

Generator No.: ON7689466
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 332710
SIC Description: MACHINE SHOPS

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

67 | **4 of 12** | **WNW/209.9** | **125.8 / 2.07** | **Alkano Grinding and Stamping Company Limited**
3321 Mainway, Unit A & B
Burlington ON L7M 1A6 | **GEN**

Generator No.: ON7689466
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 332710
SIC Description: MACHINE SHOPS

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

67 | **5 of 12** | **WNW/209.9** | **125.8 / 2.07** | **QUALITY CYLINDER SERVICE**
3321 MAINWAY
BURLINGTON ON L7M 1A6 | **GEN**

Generator No.: ON0581800
Status:
Approval Years: 86,87,88,89
Contam. Facility:
MHSW Facility:

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Code: 3081
SIC Description: MACHINE SHOP IND.

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

67 | **6 of 12** | **WNW/209.9** | **125.8 / 2.07** | **Alkano Grinding and Stamping Company Limited**
3321 Mainway, Unit A & B
Burlington ON | **GEN**

Generator No.: ON7689466
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 332710
SIC Description: MACHINE SHOPS

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

67 | **7 of 12** | **WNW/209.9** | **125.8 / 2.07** | **QUALITY HYDRAULIC SERVICE**
3321 MAINWAY
BURLINGTON ON L7M 1A6 | **GEN**

Generator No.: ON0581800
Status:
Approval Years: 90
Contam. Facility:
MHSW Facility:
SIC Code: 3081
SIC Description: MACHINE SHOP IND.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

67 | **8 of 12** | **WNW/209.9** | **125.8 / 2.07** | **WELCAN MACHINE SHOP**
3321 MAINWAY DRIVE
BURLINGTON ON L7M 1A6 | **GEN**

Generator No.: ON2147200
Status:
Approval Years: 96,97,98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 3081
SIC Description: MACHINE SHOP IND.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

67 | **9 of 12** | **WNW/209.9** | **125.8 / 2.07** | **Alkano Grinding and Stamping Company Limited**
3321 Mainway, Unit A & B
Burlington ON | **GEN**

Generator No.: ON7689466
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 332710
SIC Description: Machine Shops

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

---

67 | **10 of 12** | **WNW/209.9** | **125.8 / 2.07** | **Airon HVAC Service Ltd**
3321 Mainway Drive Unit A & B
Burlington ON L7M 1A6 | **GEN**

Generator No.: ON7905673
Status:
Approval Years: 06
Contam. Facility:
MHSW Facility:
SIC Code: 238220
SIC Description: Plumbing Heating and Air-Conditioning Contractors

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

67 | **11 of 12** | **WNW/209.9** | **125.8 / 2.07** | **QUALITY (OUT OF BUSINESS)** **33-183**
3321 MAINWAY
BURLINGTON ON L7M 1A6 | **GEN**

Generator No.: ON0581800
Status:
Approval Years: 92,93,94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 3081
SIC Description: MACHINE SHOP IND.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
67	12 of 12	WNW/209.9	125.8 / 2.07	WELCAN MACHINE SHOP 3321 MAINWAY DR BURLINGTON ON L7M 1A6	SCT

Established: 1995
Plant Size (ft²): 5000
Employment: 7

--Details--
Description: STEEL FOUNDRIES, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3325

Description: INDUSTRIAL AND COMMERCIAL MACHINERY AND EQUIPMENT, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3599

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	1 of 6	NW/212.4	125.9 / 2.13	EAGLE-QUIP INC. 3331 MAINWAY BURLINGTON ON L7M 1A6	GEN

Generator No.: ON0910400
Status:
Approval Years: 86,87,88
Contam. Facility:
MHSW Facility:
SIC Code: 5731
SIC Description: IND. MACHINERY, WH.
PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	2 of 6	NW/212.4	125.9 / 2.13	FAIRWAY INDUSTRIAL 3331 MAINWAY BURLINGTON ON L7M 1A6	GEN

Generator No.: ON0910400
Status:
Approval Years: 89,90
Contam. Facility:
MHSW Facility:
SIC Code: 5731
SIC Description: IND. MACHINERY, WH.
PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	3 of 6	NW/212.4	125.9 / 2.13	FAIRWAY INDUSTRIAL 3331 MAINWAY BURLINGTON ON L7M 1A6	GEN

Generator No.: ON0910400
PO Box No.:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:
Approval Years: 92,93,97,98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 5731
SIC Description: IND. MACHINERY, WH.

Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

68 **4 of 6** **NW/212.4** **125.9 / 2.13** **FAIRWAY INDUSTRIAL 14-355**
3331 MAINWAY
BURLINGTON ON L7M 1A6
GEN

Generator No.: ON0910400
Status:
Approval Years: 94,95,96
Contam. Facility:
MHSW Facility:
SIC Code: 5731
SIC Description: IND. MACHINERY, WH.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

68 **5 of 6** **NW/212.4** **125.9 / 2.13** **Halton Metal Outlet Ltd.**
3331 Mainway
Burlington ON L7M 1A6
SCT

Established: 01-AUG-95
Plant Size (ft²):
Employment:

--Details--
Description: Coating, Engraving, Heat Treating and Allied Activities
SIC/NAICS Code: 332810

---

68 **6 of 6** **NW/212.4** **125.9 / 2.13** **HALTON METAL OUTLET LTD.**
3331 Mainway Dr
Burlington ON L7M 1A6
SCT

Established: 1995
Plant Size (ft²): 0
Employment: 3

--Details--
Description: Iron and Steel Mills and Ferro-Alloy Manufacturing
SIC/NAICS Code: 331110

Description: Coating, Engraving, Heat Treating and Allied Activities
SIC/NAICS Code: 332810

---

69 **1 of 1** **SSW/216.4** **120.3 / -3.53** **Burlington ON** **WWIS**

Well ID:	7139909	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Test Hole	**Date Received:**	2/16/2010
Sec. Water Use:		**Selected Flag:**	1
Final Well Status:	Test Hole	**Abandonment Rec:**	
Water Type:		**Contractor:**	7215
Casing Material:		**Form Version:**	7
Audit No:	Z110033	**Owner:**	
Tag:	A095366	**Street Name:**	1149 PIONEER ROAD
Construction Method:		**County:**	HALTON
Elevation (m):		**Municipality:**	BURLINGTON CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1002938005	**Spatial Status:**	
DP2BR:		**Cluster Kind:**	
Code OB:		**UTMRC:**	4
Code OB Desc:		**UTMRC Desc:**	margin of error : 30 m - 100 m
Open Hole:		**Location Method:**	wwr
Elevation:	120.11235	**Org CS:**	UTM83
Elevrc:		**Date Completed:**	1/6/2010
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1003109360
Layer:	1
Plug From:	20.00
Plug To:	8.00
Plug Depth UOM:	ft
Plug ID:	1003109361
Layer:	2
Plug From:	8.00
Plug To:	1.00
Plug Depth UOM:	ft
Plug ID:	1003109362
Layer:	3
Plug From:	1.00

Plug To: 0.00
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1003109367
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1003109356
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1003109364
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1003109365
Layer: 1
Slot: 10
Screen Top Depth: 10.00
Screen End Depth: 20.00
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.00

Water Details

Water ID: 1003109363
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1003109359
Diameter: 8.00
Depth From: 1.00
Depth To: 0.00
Hole Depth UOM: ft
Hole Diameter UOM: inch

Hole ID: 1003109358

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Diameter:		4.50			
Depth From:		20.00			
Depth To:		1.00			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			

70	1 of 48	SSE/220.5	119.8 / -3.93	**HUNTER DRUMS LIMITED** **1121 PIONEER RD.** **BURLINGTON CITY ON L7M 1K5**	CA

Certificate #:	8-3126-89-
Application Year:	89
Issue Date:	11/29/1989
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name::	
Client Address::	
Client City::	
Client Postal Code::	
Project Description::	REPLACEMENT OF PAINT CURING OVEN
Contaminants::	Nitrogen Oxides, Toluene Di-Isocyanate, Isopropyl Alcohol, Ethyl Alcohol,Denat,D
Emission Control::	No Controls

70	2 of 48	SSE/220.5	119.8 / -3.93	**HUNTER DRUMS LIMITED** **1121 PIONEER ROAD** **BURLINGTON CITY ON L7M 1K5**	CA

Certificate #:	8-3455-94-
Application Year:	94
Issue Date:	10/25/1994
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name::	
Client Address::	
Client City::	
Client Postal Code::	
Project Description::	REPLACE DRUM INTERIOR PAINT SPRAY SYSTEM
Contaminants::	N-Propyl Alcohol, Methyl Ethyl Ketone (Butanone), Methane (Incl. Hydrocarbons Expr. As Ch4, Toluene(Pentyl Methane)(Methyl Benzene), Methyl Isobutyl Ketone, Ethylene Glycol Monomethyl Ether
Emission Control::	No Controls

70	3 of 48	SSE/220.5	119.8 / -3.93	**Hunter Drums Limited** **1121 Pioneer Road** **Burlington ON L7M 1K5**	CA

Certificate #:	9413-5WPTR8
Application Year:	2005
Issue Date:	4/5/2005
Approval Type:	Air
Status:	Approved
Application Type:	
Client Name::	
Client Address::	
Client City::	
Client Postal Code::	
Project Description::	
Contaminants::	
Emission Control::	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	4 of 48	SSE/220.5	119.8 / -3.93	MAUSER CANADA LTD. 1121 PIONEER RD BURLINGTON ON L7M 1K5	EASR

Approval No: R-003-7324976176
Status: REGISTERED
Date: 2013-04-12
Record Type: EASR
Link Source: MOFA
Full Address:
SWP Area Name: Halton
MOE District: Halton-Peel
City: BURLINGTON
Latitude: 43.36181
Longitude: -79.799736
Project Type: Heating System
Approval Type: EASR-Heating System
Full PDF Link: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2863

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	5 of 48	SSE/220.5	119.8 / -3.93	Mauser Canada Ltd. 1121 Pioneer Road Burlington, Regional Municipality of Halton CITY OF BURLINGTON ON	EBR

EBR Registry No.: 011-8488
Ministry Ref. No.: 5411-94XJJE
Company Name: Mauser Canada Ltd.
Notice Type: Instrument Decision
Notice Date: August 14, 2013
Proposal Date: March 05, 2013
Year: 2013
Proponent Address: 1121 Pioneer Road, Burlington Ontario, Canada L7M 1K5
Instrument Type: (EPA Part II.1-air) - Environmental Compliance Approval (project type: air)
Location Other:

Location:

1121 Pioneer Road Burlington, Regional Municipality of Halton CITY OF BURLINGTON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	6 of 48	SSE/220.5	119.8 / -3.93	Hunter Drums Limited 1121 Pioneer Road Burlington Ontario L7M 1K5 Burlington ON	EBR

EBR Registry No.: IA03E1275
Ministry Ref. No.: 7799-5QSGGF
Company Name: Hunter Drums Limited
Notice Type: Instrument Decision
Notice Date: April 06, 2005
Proposal Date: August 17, 2004
Year: 2004
Proponent Address: 1121 Pioneer Road, Burlington Ontario, L7M 1K5
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:

Location:

1121 Pioneer Road Burlington Ontario L7M 1K5 Burlington

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	7 of 48	SSE/220.5	119.8 / -3.93	Mauser Canada Ltd. 1121 Pioneer Rd Burlington ON	ECA

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval No:	6227-9A3P99	**MOE District:**	Halton-Peel
Approval Type:	ECA-AIR	**SWP Area Name:**	Halton
Status:	Approved	**Address:**	1121 Pioneer Rd
Approval Date:	2013-08-08	**City:**	Burlington
Record Type:	ECA	**Longitude:**	-79.79964
Project Type:	AIR	**Latitude:**	43.3617799999999
Link Source:	IDS		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/5411-94XJJE-14.pdf		

70	8 of 48	SSE/220.5	119.8 / -3.93	**Hunter Drums Limited** **1121 Pioneer Road** **Burlington ON L7M 1K5**	ECA

Approval No:	9413-5WPTR8	**MOE District:**	Halton-Peel
Approval Type:	ECA-AIR	**SWP Area Name:**	Halton
Status:	Revoked and/or Replaced	**Address:**	1121 Pioneer Road
Approval Date:	2005-04-05	**City:**	Burlington
Record Type:	ECA	**Longitude:**	-79.80314
Project Type:	AIR	**Latitude:**	43.364292
Link Source:	IDS		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/7799-5QSGGF-14.pdf		

70	9 of 48	SSE/220.5	119.8 / -3.93	**Mauser Canada Ltd.** **1121 Pioneer Road** **Burlington ON**	ECA

Approval No:	6227-9A3P99	**MOE District:**	
Approval Type:		**SWP Area Name:**	
Status:	Approved	**Address:**	
Approval Date:	08-AUG-13	**City:**	Burlington
Record Type:		**Longitude:**	
Project Type:	Air/Noise	**Latitude:**	
Link Source:			
Full Address:	1121 Pioneer Road		
Full PDF Link:			

70	10 of 48	SSE/220.5	119.8 / -3.93	**1121 Pioneer Rd.** **Burlington ON L7M 1K5**	EHS

Order ID:	49714	**Date Received:**	2/20/2005
Order No:	20050220001	**Lot/Building Size:**	
Customer ID:	33086	**Municipality:**	
Company ID:	27524	**Client Prov/State:**	MA
Status:	C	**Search Radius (km):**	0.25
Report Code:	1USA	**Large Radius:**	2
Report Type:		**X:**	-79.799621
Report Date:	3/1/2005	**Y:**	43.361955
Report Requested by:	ENVIRON		
Nearest Intersection:			
Previous Site Name:			
Additional Info Ordered:	City Directory Search; Fire Insur. Maps and/or Site Plans; Aerials Photos and/or Topographical Maps		

70	11 of 48	SSE/220.5	119.8 / -3.93	**1121 Pioneer Rd** **Burlington ON L7M1K5**	EHS

Order ID:	489942	**Date Received:**	02-DEC-16
Order No:	20161202169	**Lot/Building Size:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Customer ID:	90251	**Municipality:**	
Company ID:	17501	**Client Prov/State:**	IL
Status:	C	**Search Radius (km):**	.03
Report Code:	1CAN	**Large Radius:**	.35
Report Type:	Site Report	**X:**	-79.799062
Report Date:	05-DEC-16	**Y:**	43.362606
Report Requested by:	GaiaTech		
Nearest Intersection:			
Previous Site Name:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	12 of 48	SSE/220.5	119.8 / -3.93	1121 Pioneer road n/a ON L7M 1K5	EHS

Order ID:	118077	**Date Received:**	10/30/2007
Order No:	20071030029w	**Lot/Building Size:**	
Customer ID:	24244	**Municipality:**	
Company ID:	307	**Client Prov/State:**	
Status:	C	**Search Radius (km):**	0.25
Report Code:	11USA	**Large Radius:**	2
Report Type:	USA - Online Mapless	**X:**	
Report Date:	10/30/2007	**Y:**	
Report Requested by:	AIG Consultants, Inc.		
Nearest Intersection:			
Previous Site Name:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	13 of 48	SSE/220.5	119.8 / -3.93	1121 Pioneer road n/a ON L7M 1K5	EHS

Order ID:	118079	**Date Received:**	10/30/2007
Order No:	20071030030w	**Lot/Building Size:**	
Customer ID:	24244	**Municipality:**	
Company ID:	307	**Client Prov/State:**	
Status:	C	**Search Radius (km):**	0.25
Report Code:	11USA	**Large Radius:**	2
Report Type:	USA - Online Mapless	**X:**	
Report Date:	10/30/2007	**Y:**	
Report Requested by:	AIG Consultants, Inc.		
Nearest Intersection:			
Previous Site Name:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	14 of 48	SSE/220.5	119.8 / -3.93	1121 Pioneer Road Burlington ON	EHS

Order ID:	282564	**Date Received:**	18-NOV-13
Order No:	20131118036	**Lot/Building Size:**	
Customer ID:	82267	**Municipality:**	
Company ID:	44305	**Client Prov/State:**	ON
Status:	C	**Search Radius (km):**	.25
Report Code:	4CAN	**Large Radius:**	2
Report Type:	Custom Report	**X:**	-79.799162
Report Date:	27-NOV-13	**Y:**	43.362668
Report Requested by:	ENVIRON EC (CANADA) Inc.		
Nearest Intersection:			
Previous Site Name:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	15 of 48	SSE/220.5	119.8 / -3.93	1121 Pioneer road n/a ON L7M 1K5	EHS

Order ID:	118076	**Date Received:**	10/30/2007
Order No:	20071030028w	**Lot/Building Size:**	
Customer ID:	24244	**Municipality:**	
Company ID:	307	**Client Prov/State:**	
Status:	C	**Search Radius (km):**	0.25
Report Code:	11USA	**Large Radius:**	2
Report Type:	USA - Online Mapless	**X:**	
Report Date:	10/30/2007	**Y:**	
Report Requested by:	AIG Consultants, Inc.		
Nearest Intersection:			
Previous Site Name:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	16 of 48	SSE/220.5	119.8 / -3.93	MAUSER CANADA LTD. 1121 PIONEER ROAD BURLINGTON ON L7M 1K5	GEN

Generator No.:	ON0098700	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	2011	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	332439		
SIC Description:	Other Metal Container Manufacturing		

--Details--

Waste Code:	122
Waste Description:	ALKALINE WASTES - OTHER METALS
Waste Code:	251
Waste Description:	OIL SKIMMINGS & SLUDGES
Waste Code:	121
Waste Description:	ALKALINE WASTES - HEAVY METALS
Waste Code:	212
Waste Description:	ALIPHATIC SOLVENTS
Waste Code:	262
Waste Description:	DETERGENTS/SOAPS
Waste Code:	211
Waste Description:	AROMATIC SOLVENTS
Waste Code:	252
Waste Description:	WASTE OILS & LUBRICANTS
Waste Code:	148
Waste Description:	INORGANIC LABORATORY CHEMICALS
Waste Code:	145
Waste Description:	PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	17 of 48	SSE/220.5	119.8 / -3.93	MAUSER CANADA LTD. 1121 PIONEER ROAD BURLINGTON ON L7M 1K5	GEN

Generator No.:	ON0098700	**PO Box No.:**	
Status:		**Country:**	

Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 332439
SIC Description: Other Metal Container Manufacturing
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 262
Waste Description: DETERGENTS/SOAPS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

---

70 | **18 of 48** | **SSE/220.5** | **119.8 / -3.93** | **MAUSER CANADA LTD.**
1121 PIONEER ROAD
BURLINGTON ON | **GEN**

Generator No.: ON0098700
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 332439
SIC Description: OTHER METAL CONTAINER MANUFACTURING
PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 262
Waste Description: DETERGENTS/SOAPS

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

---

70 | **19 of 48** | **SSE/220.5** | **119.8 / -3.93** | **MAUSER CANADA LTD.**
1121 PIONEER ROAD
BURLINGTON ON L7M1K5 | **GEN**

Generator No.: ON0098700
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 332439
SIC Description: OTHER METAL CONTAINER MANUFACTURING

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No. Admin:

--Details--

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 262
Waste Description: DETERGENTS/SOAPS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

---

70 | **20 of 48** | **SSE/220.5** | **119.8 / -3.93** | **HUNTER DRUMS LTD**
1121 PIONEER RD
BURLINGTON ON L7M 1K5 | **GEN**

Generator No.: ON0098700
Status:
Approval Years: 86,87,88,89
Contam. Facility:
MHSW Facility:

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

SIC Code: 3042
SIC Description: METAL CLOSURE & CONT.

--Details--
Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

70 | ***21 of 48*** | ***SSE/220.5*** | ***119.8 / -3.93*** | ***MAUSER CANADA LTD. STEEL DIVISION***
1121 PIONEER ROAD
BURLINGTON ON L7M1K5 | ***GEN***

Generator No.: ON0098700
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country: Canada
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 122 C
Waste Description: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Code: 252 L
Waste Description: Waste crankcase oils and lubricants

Waste Code: 212 H
Waste Description: Aliphatic solvents and residues

Waste Code: 145 L
Waste Description: Wastes from the use of pigments, coatings and paints

Waste Code: 251 L
Waste Description: Waste oils/sludges (petroleum based)

Waste Code: 212 I
Waste Description: Aliphatic solvents and residues

Waste Code: 145 I
Waste Description: Wastes from the use of pigments, coatings and paints

---

70 | ***22 of 48*** | ***SSE/220.5*** | ***119.8 / -3.93*** | ***MAUSER CANADA LTD.***
1121 PIONEER ROAD
BURLINGTON ON L7M1K5 | ***GEN***

Generator No.: ON0098700
PO Box No.:

Status:		**Country:**	Canada
Approval Years:	2016	**Choice of Contact:**	CO_OFFICIAL
Contam. Facility:	No	**Co Admin:**	
MHSW Facility:	No	**Phone No. Admin:**	
SIC Code:	332439		
SIC Description:	OTHER METAL CONTAINER MANUFACTURING		

--Details--

Waste Code:	148
Waste Description:	INORGANIC LABORATORY CHEMICALS
Waste Code:	262
Waste Description:	DETERGENTS/SOAPS
Waste Code:	212
Waste Description:	ALIPHATIC SOLVENTS
Waste Code:	122
Waste Description:	ALKALINE WASTES - OTHER METALS
Waste Code:	252
Waste Description:	WASTE OILS & LUBRICANTS
Waste Code:	145
Waste Description:	PAINT/PIGMENT/COATING RESIDUES
Waste Code:	121
Waste Description:	ALKALINE WASTES - HEAVY METALS
Waste Code:	211
Waste Description:	AROMATIC SOLVENTS
Waste Code:	251
Waste Description:	OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	23 of 48	SSE/220.5	119.8 / -3.93	**RUSSELL-STANLEY** **1121 PIONEER ROAD** **BURLINGTON ON L7M 1K5**	GEN

Generator No.:	ON0098700	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	02,03,04	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:			
SIC Description:			

--Details--

Waste Code:	145
Waste Description:	PAINT/PIGMENT/COATING RESIDUES
Waste Code:	211
Waste Description:	AROMATIC SOLVENTS
Waste Code:	252
Waste Description:	WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	24 of 48	SSE/220.5	119.8 / -3.93	**HUNTER DRUMS LIMITED** **1121 PIONEER ROAD** **BURLINGTON ON L7M 1K5**	GEN

Generator No.:	ON0098700	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	97,98,99,00,01	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	3042		
SIC Description:	METAL CLOSURE & CONT.		

--Details--

Waste Code:	112
Waste Description:	ACID WASTE - HEAVY METALS
Waste Code:	122
Waste Description:	ALKALINE WASTES - OTHER METALS
Waste Code:	145
Waste Description:	PAINT/PIGMENT/COATING RESIDUES
Waste Code:	211
Waste Description:	AROMATIC SOLVENTS
Waste Code:	212
Waste Description:	ALIPHATIC SOLVENTS
Waste Code:	243
Waste Description:	PCB'S
Waste Code:	251
Waste Description:	OIL SKIMMINGS & SLUDGES
Waste Code:	252
Waste Description:	WASTE OILS & LUBRICANTS
Waste Code:	213
Waste Description:	PETROLEUM DISTILLATES

---

70 | ***25 of 48*** | ***SSE/220.5*** | ***119.8 / -3.93*** | ***MAUSER CANADA LTD.***
1121 PIONEER ROAD
BURLINGTON ON L7M 1K5 | ***GEN***

Generator No.:	ON0098700	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	2009	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	332439		
SIC Description:	Other Metal Container Manufacturing		

--Details--

Waste Code:	121
Waste Description:	ALKALINE WASTES - HEAVY METALS
Waste Code:	122
Waste Description:	ALKALINE WASTES - OTHER METALS
Waste Code:	145
Waste Description:	PAINT/PIGMENT/COATING RESIDUES
Waste Code:	148
Waste Description:	INORGANIC LABORATORY CHEMICALS
Waste Code:	211

Waste Description: AROMATIC SOLVENTS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 262
Waste Description: DETERGENTS/SOAPS

---

70 ***26 of 48*** ***SSE/220.5*** ***119.8 / -3.93*** ***HUNTER DRUMS LIMITED 20-020 GEN***
1121 PIONEER ROAD
BURLINGTON ON L7M 1K5

Generator No.: ON0098700
Status:
Approval Years: 92,93,94,95,96
Contam. Facility:
MHSW Facility:
SIC Code: 3042
SIC Description: METAL CLOSURE & CONT

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 243
Waste Description: PCB'S

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

70 ***27 of 48*** ***SSE/220.5*** ***119.8 / -3.93*** ***MAUSER CANADA LTD. GEN***
1121 PIONEER ROAD
BURLINGTON ON L7M1K5

Generator No.: ON0098700
Status:
Approval Years: 2015

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL

Contam. Facility:	No	**Co Admin:**	
MHSW Facility:	No	**Phone No. Admin:**	
SIC Code:	332439		
SIC Description:	OTHER METAL CONTAINER MANUFACTURING		

--Details--

Waste Code:	251
Waste Description:	OIL SKIMMINGS & SLUDGES
Waste Code:	262
Waste Description:	DETERGENTS/SOAPS
Waste Code:	212
Waste Description:	ALIPHATIC SOLVENTS
Waste Code:	121
Waste Description:	ALKALINE WASTES - HEAVY METALS
Waste Code:	122
Waste Description:	ALKALINE WASTES - OTHER METALS
Waste Code:	145
Waste Description:	PAINT/PIGMENT/COATING RESIDUES
Waste Code:	211
Waste Description:	AROMATIC SOLVENTS
Waste Code:	148
Waste Description:	INORGANIC LABORATORY CHEMICALS
Waste Code:	252
Waste Description:	WASTE OILS & LUBRICANTS

---

70 | ***28 of 48*** | ***SSE/220.5*** | ***119.8 / -3.93*** | ***MAUSER CANADA LTD.***
1121 PIONEER ROAD
BURLINGTON ON L7M 1K5 | ***GEN***

Generator No.:	ON0098700	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	2010	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	332439		
SIC Description:	Other Metal Container Manufacturing		

--Details--

Waste Code:	211
Waste Description:	AROMATIC SOLVENTS
Waste Code:	145
Waste Description:	PAINT/PIGMENT/COATING RESIDUES
Waste Code:	212
Waste Description:	ALIPHATIC SOLVENTS
Waste Code:	262
Waste Description:	DETERGENTS/SOAPS
Waste Code:	122
Waste Description:	ALKALINE WASTES - OTHER METALS
Waste Code:	252

Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

---

70 | ***29 of 48*** | ***SSE/220.5*** | ***119.8 / -3.93*** | ***MAUSER CANADA LTD.***
1121 PIONEER ROAD
BURLINGTON ON L7M 1K5 | ***GEN***

Generator No.: ON0098700
Status:
Approval Years: 05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code: 332439
SIC Description: Other Metal Container Manufacturing

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 262
Waste Description: DETERGENTS/SOAPS

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 243
Waste Description: PCB'S

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	30 of 48	SSE/220.5	119.8 / -3.93	HUNTER DRUMS LIMITED 1121 PIONEER ROAD BURLINGTON ON L7M 1K5	NPCB

Company Code: F1085
Industry:
Site Status:
Transaction Date: 1/29/1996
Inspection Date:

--Details--
Label:
Serial No.:
PCB Type/Code: Askarel
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 0.00 KG

Label:
Serial No.:
PCB Type/Code: Askarel
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 104.00 KG

Label:
Serial No.:
PCB Type/Code: Unknown concentration
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 360.00 KG

Label:
Serial No.:
PCB Type/Code: Low 50 - 10,000 ppm
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 500.00 KG

Label:
Serial No.:
PCB Type/Code: Askarel
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 800.00 KG

Label:
Serial No.:
PCB Type/Code: Low 50 - 10,000 ppm
Location:

Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 2250.00 KG

Label:
Serial No.:
PCB Type/Code: Low 50 - 10,000 ppm
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 2800.00 KG

Label:
Serial No.:
PCB Type/Code: Askarel
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 48415.00 KG

---

70 | ***31 of 48*** | ***SSE/220.5*** | ***119.8 / -3.93*** | ***Mauser Canada Ltd.***
1121 Pioneer Road
Burlington ON l7m1k5 | ***NPRI***

NPRI ID:	10568	***Org ID:***	106454
Other ID:		***Submit Date:***	9/9/2015
No Other ID:		***Last Modified:***	11/18/2016 8:28:05 AM
Track ID:	134901	***Contact ID:***	241947
Report ID:	55944	***Cont Type:***	MEM
Report Type:	NPRI	***Contact Title:***	
Rpt Type ID:	1	***Cont First Name:***	Paul
Report Year:	2014	***Cont Last Name:***	Ruse
Not-Current Rpt?:	No	***Contact Position:***	Plant Manager
Yr of Last Filed Rpt:	2012	***Contact Fax:***	
Fac ID:	234040	***Contact Ph.:***	9053324800
Fac Name:	Mauser Canada Limited - Burlington	***Cont Area Code:***	905
Fac Address1:	1121 Pioneer Road	***Contact Tel.:***	53324800
Fac Address2:		***Contact Ext.:***	
Fac Postal Zip:	l7m1k5	***Cont Fax Area Cde:***	
Facility Lat:	43.3625	***Contact Fax:***	
Facility Long:	-79.7991	***Contact Email:***	paul.ruse@mausergroup.com
DLS (Last Filed Rpt):		***Latitude:***	43.3625
Facility DLS:		***Longitude:***	-79.7991
Datum:	1983	***UTM Zone:***	
Facility Cmnts:		***UTM Northing:***	
URL:		***UTM Easting:***	
No of Empl.:	58	***Waste Streams:***	
Parent Co.:		***No Streams:***	
No Parent Co.:		***Waste Off Sites:***	
Pollut Prev Cmnts:		***No Off Sites:***	
Stacks:		***Shutdown:***	
No of Stacks:		***No of Shutdown:***	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		

NAICS Code (4 digit): 3312
NAICS 4 Description: Steel product manufacturing from purchased steel
NAICS Code (6 digit): 331221
NAICS 6 Description: Cold-rolled steel shape manufacturing

Substance Release Report

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Manganese (and its compounds)
Chem (fr): Manganèse (et ses composés)
Quantity: .03
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Xylene (all isomers)
Chem (fr): Xylène (tous les isomères)
Quantity: 15.64
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Methyl ethyl ketone
Chem (fr): Méthyléthylcétone
Quantity: 38.31
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Volatile Organic Compounds (VOCs)
Chem (fr): Composés organiques volatils (COV)
Quantity: 121.88
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Chromium (and its compounds)
Chem (fr): Chrome (et ses composés)
Quantity: .06
Unit: tonnes
Basis of Estimate Cd: C

Basis of Estimate Desc: C- Mass Balance

---

70 | **32 of 48** | **SSE/220.5** | **119.8 / -3.93** | **MAUSER CANADA LIMITED**
1121 Pioneer Road
Burlington ON l7m1k5 | **NPRI**

NPRI ID:	10568	**Org ID:**	57200
Other ID:	N	**Submit Date:**	6/2/2005
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	27947	**Contact ID:**	197291
Report ID:	89804	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	PAUL
Report Year:	2004	**Cont Last Name:**	RUSE
Not-Current Rpt?:	No	**Contact Position:**	PLANT MANAGER
Yr of Last Filed Rpt:	2012	**Contact Fax:**	
Fac ID:	234040	**Contact Ph.:**	9053324800
Fac Name:	Mauser Canada Limited - Burlington	**Cont Area Code:**	905
Fac Address1:	1121 Pioneer Road	**Contact Tel.:**	53324800
Fac Address2:		**Contact Ext.:**	
Fac Postal Zip:	l7m1k5	**Cont Fax Area Cde:**	
Facility Lat:	43.3625	**Contact Fax:**	
Facility Long:	-79.7991	**Contact Email:**	PRUSE@RUSSELL-STANLEY.COM
DLS (Last Filed Rpt):		**Latitude:**	43.3625
Facility DLS:		**Longitude:**	-79.7991
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	True	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	79	**Waste Streams:**	False
Parent Co.:	Y	**No Streams:**	
No Parent Co.:	1	**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	True	**No Off Sites:**	1
Stacks:	No	**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3312		
NAICS 4 Description:	Steel product manufacturing from purchased steel		
NAICS Code (6 digit):	331221		
NAICS 6 Description:	Cold-rolled steel shape manufacturing		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Heavy aromatic solvent naphtha
Chem (fr):	Solvant naphta aromatique lourd
Quantity:	1.8
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	

Chem: Chromium (and its compounds)
Chem (fr): Chrome (et ses composés)
Quantity: .047
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Toluene
Chem (fr): Toluène
Quantity: 4.8
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Volatile Organic Compounds (VOCs)
Chem (fr): Composés organiques volatils (COV)
Quantity: 208
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: 1,2,4-Trimethylbenzene
Chem (fr): 1,2,4-Triméthylbenzène
Quantity: 5.3
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Mineral spirits
Chem (fr): Essences minérales
Quantity: 7.04
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Manganese (and its compounds)
Chem (fr): Manganèse (et ses composés)
Quantity: .047
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Methyl ethyl ketone
Chem (fr):	Méthyléthylcétone
Quantity:	51
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Light aromatic solvent naphtha
Chem (fr):	Solvant naphta aromatique léger
Quantity:	5.3
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Xylene (all isomers)
Chem (fr):	Xylène (tous les isomères)
Quantity:	92.2
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

---

70 | ***33 of 48*** | ***SSE/220.5*** | ***119.8 / -3.93*** | ***MAUSER CANADA LTD.***
1121 Pioneer Road
Burlington ON l7m1k5 | ***NPRI***

NPRI ID:	10568	**Org ID:**	57203
Other ID:		**Submit Date:**	6/26/2012
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	100768	**Contact ID:**	197300
Report ID:	4935	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	2011	**Cont Last Name:**	
Not-Current Rpt?:	Yes	**Contact Position:**	
Yr of Last Filed Rpt:	2012	**Contact Fax:**	
Fac ID:	234040	**Contact Ph.:**	
Fac Name:	Mauser Canada Limited - Burlington	**Cont Area Code:**	
Fac Address1:	1121 Pioneer Road	**Contact Tel.:**	
Fac Address2:		**Contact Ext.:**	
Fac Postal Zip:	l7m1k5	**Cont Fax Area Cde:**	
Facility Lat:	43.3625	**Contact Fax:**	
Facility Long:	-79.7991	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.3625
Facility DLS:		**Longitude:**	-79.7991
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	58	**Waste Streams:**	
Parent Co.:		**No Streams:**	

No Parent Co.: ***Waste Off Sites:***
Pollut Prev Cmnts: ***No Off Sites:***
Stacks: ***Shutdown:***
No of Stacks: ***No of Shutdown:***
Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 33
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3312
NAICS 4 Description: Steel product manufacturing from purchased steel
NAICS Code (6 digit): 331221
NAICS 6 Description: Cold-rolled steel shape manufacturing

Substance Release Report

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Volatile Organic Compounds (VOCs)
Chem (fr): Composés organiques volatils (COV)
Quantity: 137
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Manganese (and its compounds)
Chem (fr): Manganèse (et ses composés)
Quantity: .03
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Methyl ethyl ketone
Chem (fr): Méthyléthylcétone
Quantity: 27.2
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Xylene (all isomers)
Chem (fr): Xylène (tous les isomères)
Quantity: 32.6
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Chromium (and its compounds)
Chem (fr):	Chrome (et ses composés)
Quantity:	.06
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

---

70 | ***34 of 48*** | ***SSE/220.5*** | ***119.8 / -3.93*** | ***MAUSER CANADA LIMITED*** | ***NPRI***

1121 Pioneer Road
Burlington ON l7m1k5

NPRI ID:	10568	**Org ID:**	57200
Other ID:	N	**Submit Date:**	5/31/2006
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	39490	**Contact ID:**	197291
Report ID:	99374	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	PAUL
Report Year:	2005	**Cont Last Name:**	RUSE
Not-Current Rpt?:	No	**Contact Position:**	PLANT MANAGER
Yr of Last Filed Rpt:	2012	**Contact Fax:**	
Fac ID:	234040	**Contact Ph.:**	9053324800
Fac Name:	Mauser Canada Limited - Burlington	**Cont Area Code:**	905
Fac Address1:	1121 Pioneer Road	**Contact Tel.:**	53324800
Fac Address2:		**Contact Ext.:**	
Fac Postal Zip:	l7m1k5	**Cont Fax Area Cde:**	
Facility Lat:	43.3625	**Contact Fax:**	
Facility Long:	-79.7991	**Contact Email:**	PRUSE@RUSSELL-STANLEY.COM
DLS (Last Filed Rpt):		**Latitude:**	43.3625
Facility DLS:		**Longitude:**	-79.7991
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	Fals	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	79	**Waste Streams:**	False
Parent Co.:	N	**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	False	**No Off Sites:**	1.00
Stacks:	False	**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3312		
NAICS 4 Description:	Steel product manufacturing from purchased steel		
NAICS Code (6 digit):	331221		
NAICS 6 Description:	Cold-rolled steel shape manufacturing		

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Manganese (and its compounds)
Chem (fr):	Manganèse (et ses composés)

Quantity: .032
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Chromium (and its compounds)
Chem (fr): Chrome (et ses composés)
Quantity: .064
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Methyl ethyl ketone
Chem (fr): Méthyléthylcétone
Quantity: 56.4
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Ethylbenzene
Chem (fr): Éthylbenzène
Quantity: 12
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Toluene
Chem (fr): Toluène
Quantity: 7.81
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Formaldehyde
Chem (fr): Formaldéhyde
Quantity: 1.7
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1

Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Xylene (all isomers)
Chem (fr):	Xylène (tous les isomères)
Quantity:	155
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	n-Butyl alcohol
Chem (fr):	Butan-1-ol
Quantity:	11.9
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	1,2,4-Trimethylbenzene
Chem (fr):	1,2,4-Triméthylbenzène
Quantity:	9.27
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Volatile Organic Compounds (VOCs)
Chem (fr):	Composés organiques volatils (COV)
Quantity:	320
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

---

70 | ***35 of 48*** | ***SSE/220.5*** | ***119.8 / -3.93*** | ***HUNTER DRUMS LIMITED***
1121 PIONEER ROAD NOT AVAILABLE
BURLINGTON ON L7M1K5 | ***NPRI***

NPRI ID:	10568	**Org ID:**	51838
Other ID:	N	**Submit Date:**	11/29/2004
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	75537	**Contact ID:**	206279
Report ID:	156051	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	ROBERT
Report Year:	2003	**Cont Last Name:**	MOSER
Not-Current Rpt?:	No	**Contact Position:**	VICE PRESIDENT
Yr of Last Filed Rpt:	2012	**Contact Fax:**	
Fac ID:	153026	**Contact Ph.:**	9053322382
Fac Name:	HUNTER DRUMS - BURLINGTON	**Cont Area Code:**	905
Fac Address1:	1121 PIONEER ROAD	**Contact Tel.:**	53322382
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	

Fac Postal Zip:	L7M1K5	**Cont Fax Area Cde:**	
Facility Lat:	43.3625	**Contact Fax:**	
Facility Long:	-79.7991	**Contact Email:**	BMOSER@RUSSELL-STANLEY.COM
DLS (Last Filed Rpt):		**Latitude:**	43.3625
Facility DLS:		**Longitude:**	-79.7991
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	79	**Waste Streams:**	True?
Parent Co.:	Y	**No Streams:**	
No Parent Co.:	1	**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	False	**No Off Sites:**	1
Stacks:	True	**Shutdown:**	True
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 33
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3312
NAICS 4 Description: Steel product manufacturing from purchased steel
NAICS Code (6 digit): 331221
NAICS 6 Description: Cold-rolled steel shape manufacturing

Substance Release Report

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Nickel (and its compounds)
Chem (fr): Nickel (et ses composés)
Quantity: .033
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Xylene (all isomers)
Chem (fr): Xylène (tous les isomères)
Quantity: 77.5
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Methyl ethyl ketone
Chem (fr): Méthyléthylcétone
Quantity: 56.5
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 13
Category Type Desc: All Media

Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Cobalt (and its compounds)
Chem (fr):	Cobalt (et ses composés)
Quantity:	.033
Unit:	tonnes
Basis of Estimate Cd:	
Basis of Estimate Desc:	

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Volatile Organic Compounds (VOCs)
Chem (fr):	Composés organiques volatils (COV)
Quantity:	191
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Manganese (and its compounds)
Chem (fr):	Manganèse (et ses composés)
Quantity:	.033
Unit:	tonnes
Basis of Estimate Cd:	
Basis of Estimate Desc:	

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Chromium (and its compounds)
Chem (fr):	Chrome (et ses composés)
Quantity:	.033
Unit:	tonnes
Basis of Estimate Cd:	
Basis of Estimate Desc:	

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	1,2,4-Trimethylbenzene
Chem (fr):	1,2,4-Triméthylbenzène
Quantity:	3.75
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	36 of 48	SSE/220.5	119.8 / -3.93	**MAUSER CANADA LTD.** **1121 Pioneer Road** **Burlington ON l7m1k5**	NPRI

NPRI ID:	10568	**Org ID:**	57203
Other ID:		**Submit Date:**	4/9/2015
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM

Track ID:	124994	**Contact ID:**	197300
Report ID:	41450	**Cont Type:**	MEM
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	2012	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2012	**Contact Fax:**	
Fac ID:	234040	**Contact Ph.:**	
Fac Name:	Mauser Canada Limited - Burlington	**Cont Area Code:**	
Fac Address1:	1121 Pioneer Road	**Contact Tel.:**	
Fac Address2:		**Contact Ext.:**	
Fac Postal Zip:	l7m1k5	**Cont Fax Area Cde:**	
Facility Lat:	43.3625	**Contact Fax:**	
Facility Long:	-79.7991	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.3625
Facility DLS:		**Longitude:**	-79.7991
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	58	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3312		
NAICS 4 Description:	Steel product manufacturing from purchased steel		
NAICS Code (6 digit):	331221		
NAICS 6 Description:	Cold-rolled steel shape manufacturing		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Xylene (all isomers)
Chem (fr):	Xylène (tous les isomères)
Quantity:	32.78
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Chromium (and its compounds)
Chem (fr):	Chrome (et ses composés)
Quantity:	.058
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels

Grouping:	Total Air
Trans Code:	ASta
Chem:	Volatile Organic Compounds (VOCs)
Chem (fr):	Composés organiques volatils (COV)
Quantity:	116
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Manganese (and its compounds)
Chem (fr):	Manganèse (et ses composés)
Quantity:	.029
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Methyl ethyl ketone
Chem (fr):	Méthyléthylcétone
Quantity:	28.32
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

---

70 | ***37 of 48*** | ***SSE/220.5*** | ***119.8 / -3.93*** | ***MAUSER CANADA LTD.***
1121 Pioneer Road
Burlington ON l7m1k5 | ***NPRI***

NPRI ID:	10568	**Org ID:**	57203
Other ID:		**Submit Date:**	4/9/2015
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	124993	**Contact ID:**	197300
Report ID:	41449	**Cont Type:**	MEM
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	2011	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2012	**Contact Fax:**	
Fac ID:	234040	**Contact Ph.:**	
Fac Name:	Mauser Canada Limited - Burlington	**Cont Area Code:**	
Fac Address1:	1121 Pioneer Road	**Contact Tel.:**	
Fac Address2:		**Contact Ext.:**	
Fac Postal Zip:	l7m1k5	**Cont Fax Area Cde:**	
Facility Lat:	43.3625	**Contact Fax:**	
Facility Long:	-79.7991	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.3625
Facility DLS:		**Longitude:**	-79.7991
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	58	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 33
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3312
NAICS 4 Description: Steel product manufacturing from purchased steel
NAICS Code (6 digit): 331221
NAICS 6 Description: Cold-rolled steel shape manufacturing

Substance Release Report

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Manganese (and its compounds)
Chem (fr): Manganèse (et ses composés)
Quantity: .03
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Volatile Organic Compounds (VOCs)
Chem (fr): Composés organiques volatils (COV)
Quantity: 137
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Chromium (and its compounds)
Chem (fr): Chrome (et ses composés)
Quantity: .06
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Xylene (all isomers)
Chem (fr): Xylène (tous les isomères)
Quantity: 32.6
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air

Trans Code:	ASta
Chem:	Methyl ethyl ketone
Chem (fr):	Méthyléthylcétone
Quantity:	27.2
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

70 | **38 of 48** | **SSE/220.5** | **119.8 / -3.93** | **MAUSER CANADA LIMITED**
1121 Pioneer Road
Burlington ON l7m1k5 | **NPRI**

NPRI ID:	10568	**Org ID:**	57200
Other ID:	N	**Submit Date:**	5/29/2009
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	68329	**Contact ID:**	197291
Report ID:	129126	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	PAUL
Report Year:	2008	**Cont Last Name:**	RUSE
Not-Current Rpt?:	No	**Contact Position:**	PLANT MANAGER
Yr of Last Filed Rpt:	2012	**Contact Fax:**	
Fac ID:	234040	**Contact Ph.:**	9053324800
Fac Name:	Mauser Canada Limited - Burlington	**Cont Area Code:**	905
Fac Address1:	1121 Pioneer Road	**Contact Tel.:**	53324800
Fac Address2:		**Contact Ext.:**	
Fac Postal Zip:	l7m1k5	**Cont Fax Area Cde:**	
Facility Lat:	43.3625	**Contact Fax:**	
Facility Long:	-79.7991	**Contact Email:**	PRUSE@RUSSELL-STANLEY.COM
DLS (Last Filed Rpt):		**Latitude:**	43.3625
Facility DLS:		**Longitude:**	-79.7991
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	No	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	60	**Waste Streams:**	No
Parent Co.:	N	**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	Yes
Pollut Prev Cmnts:	No	**No Off Sites:**	1
Stacks:	No	**Shutdown:**	Yes
No of Stacks:		**No of Shutdown:**	1
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3312		
NAICS 4 Description:	Steel product manufacturing from purchased steel		
NAICS Code (6 digit):	331221		
NAICS 6 Description:	Cold-rolled steel shape manufacturing		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Methyl ethyl ketone
Chem (fr):	Méthyléthylcétone
Quantity:	44
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Ethylbenzene
Chem (fr): Éthylbenzène
Quantity: 6.49
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Manganese (and its compounds)
Chem (fr): Manganèse (et ses composés)
Quantity: .033
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Xylene (all isomers)
Chem (fr): Xylène (tous les isomères)
Quantity: 69.7
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Chromium (and its compounds)
Chem (fr): Chrome (et ses composés)
Quantity: .065
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Toluene
Chem (fr): Toluène
Quantity: 3.17
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta

Chem:	Volatile Organic Compounds (VOCs)
Chem (fr):	Composés organiques volatils (COV)
Quantity:	158
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	1,2,4-Trimethylbenzene
Chem (fr):	1,2,4-Triméthylbenzène
Quantity:	3.53
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	n-Butyl alcohol
Chem (fr):	Butan-1-ol
Quantity:	4.58
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

---

70 | ***39 of 48*** | ***SSE/220.5*** | ***119.8 / -3.93*** | ***MAUSER CANADA LTD.***
1121 Pioneer Road
Burlington ON l7m1k5 | ***NPRI***

NPRI ID:	10568	**Org ID:**	57203
Other ID:	Y	**Submit Date:**	6/16/2011
No Other ID:	1	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	92028	**Contact ID:**	
Report ID:	146086	**Cont Type:**	
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	2010	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2012	**Contact Fax:**	
Fac ID:	234040	**Contact Ph.:**	
Fac Name:	Mauser Canada Limited - Burlington	**Cont Area Code:**	
Fac Address1:	1121 Pioneer Road	**Contact Tel.:**	
Fac Address2:		**Contact Ext.:**	
Fac Postal Zip:	l7m1k5	**Cont Fax Area Cde:**	
Facility Lat:	43.3625	**Contact Fax:**	
Facility Long:	-79.7991	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.3625
Facility DLS:		**Longitude:**	-79.7991
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	No	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	57	**Waste Streams:**	No
Parent Co.:	*	**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	Yes
Pollut Prev Cmnts:	No	**No Off Sites:**	1
Stacks:	No	**Shutdown:**	No
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			

SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 33
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3312
NAICS 4 Description: Steel product manufacturing from purchased steel
NAICS Code (6 digit): 331221
NAICS 6 Description: Cold-rolled steel shape manufacturing

Substance Release Report

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Manganese (and its compounds)
Chem (fr): Manganèse (et ses composés)
Quantity: .039
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: n-Butyl alcohol
Chem (fr): Butan-1-ol
Quantity: 5.78
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Chromium (and its compounds)
Chem (fr): Chrome (et ses composés)
Quantity: .078
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Methyl ethyl ketone
Chem (fr): Méthyléthylcétone
Quantity: 45.4
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Volatile Organic Compounds (VOCs)

Chem (fr): Composés organiques volatils (COV)
Quantity: 181
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Ethylbenzene
Chem (fr): Éthylbenzène
Quantity: 6.71
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Xylene (all isomers)
Chem (fr): Xylène (tous les isomères)
Quantity: 76.4
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Toluene
Chem (fr): Toluène
Quantity: 5
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: 1,2,4-Trimethylbenzene
Chem (fr): 1,2,4-Triméthylbenzène
Quantity: 4.11
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

---

70 | **40 of 48** | **SSE/220.5** | **119.8 / -3.93** | **MAUSER CANADA LTD.**
1121 Pioneer Road
Burlington ON l7m1k5 | **NPRI**

NPRI ID: 10568
Other ID:
No Other ID:
Track ID: 109013
Report ID: 20128
Report Type: NPRI
Rpt Type ID: 1

Org ID: 57203
Submit Date: 5/29/2013
Last Modified: 5/29/2015 3:28:24 PM
Contact ID: 197300
Cont Type: MED
Contact Title:
Cont First Name:

Report Year:	2012	**Cont Last Name:**	
Not-Current Rpt?:	Yes	**Contact Position:**	
Yr of Last Filed Rpt:	2012	**Contact Fax:**	
Fac ID:	234040	**Contact Ph.:**	
Fac Name:	Mauser Canada Limited - Burlington	**Cont Area Code:**	
Fac Address1:	1121 Pioneer Road	**Contact Tel.:**	
Fac Address2:		**Contact Ext.:**	
Fac Postal Zip:	l7m1k5	**Cont Fax Area Cde:**	
Facility Lat:	43.3625	**Contact Fax:**	
Facility Long:	-79.7991	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.3625
Facility DLS:		**Longitude:**	-79.7991
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	58	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3312		
NAICS 4 Description:	Steel product manufacturing from purchased steel		
NAICS Code (6 digit):	331221		
NAICS 6 Description:	Cold-rolled steel shape manufacturing		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Methyl ethyl ketone
Chem (fr):	Méthyléthylcétone
Quantity:	24.97
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Xylene (all isomers)
Chem (fr):	Xylène (tous les isomères)
Quantity:	28.9
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Volatile Organic Compounds (VOCs)
Chem (fr):	Composés organiques volatils (COV)

Quantity:	116
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance
Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Manganese (and its compounds)
Chem (fr):	Manganèse (et ses composés)
Quantity:	.029
Unit:	tonnes
Basis of Estimate Cd:	NA
Basis of Estimate Desc:	NA- Not Applicable
Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Chromium (and its compounds)
Chem (fr):	Chrome (et ses composés)
Quantity:	.058
Unit:	tonnes
Basis of Estimate Cd:	NA
Basis of Estimate Desc:	NA- Not Applicable

---

70 | ***41 of 48*** | ***SSE/220.5*** | ***119.8 / -3.93*** | ***HUNTER DRUMS LIMITED***
1121 PIONEER ROAD NOT AVAILABLE
BURLINGTON ON L7M1K5 | ***NPRI***

NPRI ID:	10568	**Org ID:**	51838
Other ID:	*	**Submit Date:**	9/29/2003
No Other ID:	0	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	19932	**Contact ID:**	167819
Report ID:	164514	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	JOE
Report Year:	2002	**Cont Last Name:**	LEKHRAM
Not-Current Rpt?:	No	**Contact Position:**	PLANT MANAGER
Yr of Last Filed Rpt:	2012	**Contact Fax:**	
Fac ID:	153026	**Contact Ph.:**	9053322382
Fac Name:	HUNTER DRUMS - BURLINGTON	**Cont Area Code:**	905
Fac Address1:	1121 PIONEER ROAD	**Contact Tel.:**	53322382
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	L7M1K5	**Cont Fax Area Cde:**	
Facility Lat:	43.3625	**Contact Fax:**	
Facility Long:	-79.7991	**Contact Email:**	JLEKHRAM@RUSSELL-STANLEY.COM
DLS (Last Filed Rpt):		**Latitude:**	43.3625
Facility DLS:		**Longitude:**	-79.7991
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	79	**Waste Streams:**	False
Parent Co.:	Y	**No Streams:**	0
No Parent Co.:	1	**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	False	**No Off Sites:**	1
Stacks:	False	**Shutdown:**	False
No of Stacks:		**No of Shutdown:**	0
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			

NAICS Code (2 digit):	33
NAICS 2 Description:	Manufacturing
NAICS Code (4 digit):	3312
NAICS 4 Description:	Steel product manufacturing from purchased steel
NAICS Code (6 digit):	331221
NAICS 6 Description:	Cold-rolled steel shape manufacturing

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Methyl ethyl ketone
Chem (fr):	Méthyléthylcétone
Quantity:	73.5
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	Nickel (and its compounds)
Chem (fr):	Nickel (et ses composés)
Quantity:	.031
Unit:	tonnes
Basis of Estimate Cd:	E
Basis of Estimate Desc:	E- Emission Factor - In use from 1994 to 2002

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Volatile Organic Compounds (VOCs)
Chem (fr):	Composés organiques volatils (COV)
Quantity:	214.2
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Xylene (mixed isomers)
Chem (fr):	Xylène (mélange d'isomères)
Quantity:	82.286
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	Manganese (and its compounds)
Chem (fr):	Manganèse (et ses composés)
Quantity:	.031

Unit:	tonnes
Basis of Estimate Cd:	E
Basis of Estimate Desc:	E- Emission Factor - In use from 1994 to 2002
Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	Cobalt (and its compounds)
Chem (fr):	Cobalt (et ses composés)
Quantity:	.031
Unit:	tonnes
Basis of Estimate Cd:	E
Basis of Estimate Desc:	E- Emission Factor - In use from 1994 to 2002
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Chromium (and its compounds)
Chem (fr):	Chrome (et ses composés)
Quantity:	.031
Unit:	tonnes
Basis of Estimate Cd:	E
Basis of Estimate Desc:	E- Emission Factor - In use from 1994 to 2002
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	1,2,4-Trimethylbenzene
Chem (fr):	1,2,4-Triméthylbenzène
Quantity:	3.715
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	42 of 48	SSE/220.5	119.8 / -3.93	**Mauser Canada Ltd.** **1121 Pioneer Road** **Burlington ON l7m1k5**	NPRI

NPRI ID:	10568	**Org ID:**	106454
Other ID:		**Submit Date:**	9/9/2015
No Other ID:		**Last Modified:**	11/18/2016 8:28:05 AM
Track ID:	134829	**Contact ID:**	241947
Report ID:	39260	**Cont Type:**	MEM
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	Paul
Report Year:	2013	**Cont Last Name:**	Ruse
Not-Current Rpt?:	No	**Contact Position:**	Plant Manager
Yr of Last Filed Rpt:	2012	**Contact Fax:**	
Fac ID:	234040	**Contact Ph.:**	9053324800
Fac Name:	Mauser Canada Limited - Burlington	**Cont Area Code:**	905
Fac Address1:	1121 Pioneer Road	**Contact Tel.:**	53324800
Fac Address2:		**Contact Ext.:**	
Fac Postal Zip:	l7m1k5	**Cont Fax Area Cde:**	
Facility Lat:	43.3625	**Contact Fax:**	
Facility Long:	-79.7991	**Contact Email:**	paul.ruse@mausergroup.com
DLS (Last Filed Rpt):		**Latitude:**	43.3625
Facility DLS:		**Longitude:**	-79.7991
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	

URL: ***UTM Easting:***
No of Empl.: 57 ***Waste Streams:***
Parent Co.: ***No Streams:***
No Parent Co.: ***Waste Off Sites:***
Pollut Prev Cmnts: ***No Off Sites:***
Stacks: ***Shutdown:***
No of Stacks: ***No of Shutdown:***
Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 33
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3312
NAICS 4 Description: Steel product manufacturing from purchased steel
NAICS Code (6 digit): 331221
NAICS 6 Description: Cold-rolled steel shape manufacturing

Substance Release Report

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Chromium (and its compounds)
Chem (fr): Chrome (et ses composés)
Quantity: .059
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Volatile Organic Compounds (VOCs)
Chem (fr): Composés organiques volatils (COV)
Quantity: 123.9
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Xylene (all isomers)
Chem (fr): Xylène (tous les isomères)
Quantity: 24.65
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Ethylbenzene
Chem (fr): Éthylbenzène
Quantity: 4.12
Unit: tonnes

Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Acetone
Chem (fr):	Acétone
Quantity:	9.5
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance
Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Manganese (and its compounds)
Chem (fr):	Manganèse (et ses composés)
Quantity:	.029
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Toluene
Chem (fr):	Toluène
Quantity:	5.33
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Methyl ethyl ketone
Chem (fr):	Méthyléthylcétone
Quantity:	27.8
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	43 of 48	SSE/220.5	119.8 / -3.93	**MAUSER CANADA LIMITED** **1121 Pioneer Road** **Burlington ON l7m1k5**	NPRI

NPRI ID:	10568	**Org ID:**	57200
Other ID:	N	**Submit Date:**	5/27/2010
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	83653	**Contact ID:**	197300
Report ID:	137514	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	2009	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2012	**Contact Fax:**	

Fac ID:	234040	**Contact Ph.:**	
Fac Name:	Mauser Canada Limited - Burlington	**Cont Area Code:**	
Fac Address1:	1121 Pioneer Road	**Contact Tel.:**	
Fac Address2:		**Contact Ext.:**	
Fac Postal Zip:	l7m1k5	**Cont Fax Area Cde:**	
Facility Lat:	43.3625	**Contact Fax:**	
Facility Long:	-79.7991	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.3625
Facility DLS:		**Longitude:**	-79.7991
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	No	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	60	**Waste Streams:**	No
Parent Co.:	N	**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	Yes
Pollut Prev Cmnts:	No	**No Off Sites:**	1
Stacks:	No	**Shutdown:**	No
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3312		
NAICS 4 Description:	Steel product manufacturing from purchased steel		
NAICS Code (6 digit):	331221		
NAICS 6 Description:	Cold-rolled steel shape manufacturing		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Volatile Organic Compounds (VOCs)
Chem (fr):	Composés organiques volatils (COV)
Quantity:	171
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Xylene (all isomers)
Chem (fr):	Xylène (tous les isomères)
Quantity:	68.6
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	1,2,4-Trimethylbenzene
Chem (fr):	1,2,4-Triméthylbenzène
Quantity:	3.63
Unit:	tonnes
Basis of Estimate Cd:	C

Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: n-Butyl alcohol
Chem (fr): Butan-1-ol
Quantity: 5.23
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Toluene
Chem (fr): Toluène
Quantity: 4.8
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Ethylbenzene
Chem (fr): Éthylbenzène
Quantity: 6.13
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Chromium (and its compounds)
Chem (fr): Chrome (et ses composés)
Quantity: .057
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Methyl ethyl ketone
Chem (fr): Méthyléthylcétone
Quantity: 47.6
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t

Trans Code:	
Chem:	Manganese (and its compounds)
Chem (fr):	Manganèse (et ses composés)
Quantity:	.029
Unit:	tonnes
Basis of Estimate Cd:	
Basis of Estimate Desc:	

70 | **44 of 48** | **SSE/220.5** | **119.8 / -3.93** | **MAUSER CANADA LIMITED**
1121 Pioneer Road
Burlington ON l7m1k5 | **NPRI**

NPRI ID:	10568	**Org ID:**	57200
Other ID:	N	**Submit Date:**	6/1/2007
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	49570	**Contact ID:**	197291
Report ID:	105503	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	PAUL
Report Year:	2006	**Cont Last Name:**	RUSE
Not-Current Rpt?:	No	**Contact Position:**	PLANT MANAGER
Yr of Last Filed Rpt:	2012	**Contact Fax:**	
Fac ID:	234040	**Contact Ph.:**	9053324800
Fac Name:	Mauser Canada Limited - Burlington	**Cont Area Code:**	905
Fac Address1:	1121 Pioneer Road	**Contact Tel.:**	53324800
Fac Address2:		**Contact Ext.:**	
Fac Postal Zip:	l7m1k5	**Cont Fax Area Cde:**	
Facility Lat:	43.3625	**Contact Fax:**	
Facility Long:	-79.7991	**Contact Email:**	PRUSE@RUSSELL-STANLEY.COM
DLS (Last Filed Rpt):		**Latitude:**	43.3625
Facility DLS:		**Longitude:**	-79.7991
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	Fals	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	79	**Waste Streams:**	True?
Parent Co.:	N	**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	False	**No Off Sites:**	1.00
Stacks:	True	**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3312		
NAICS 4 Description:	Steel product manufacturing from purchased steel		
NAICS Code (6 digit):	331221		
NAICS 6 Description:	Cold-rolled steel shape manufacturing		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	1,2,4-Trimethylbenzene
Chem (fr):	1,2,4-Triméthylbenzène
Quantity:	3.31
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Xylene (all isomers)
Chem (fr): Xylène (tous les isomères)
Quantity: 64.88
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Volatile Organic Compounds (VOCs)
Chem (fr): Composés organiques volatils (COV)
Quantity: 154
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: n-Butyl alcohol
Chem (fr): Butan-1-ol
Quantity: 4.43
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Chromium (and its compounds)
Chem (fr): Chrome (et ses composés)
Quantity: .068
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Manganese (and its compounds)
Chem (fr): Manganèse (et ses composés)
Quantity: .034
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta

Chem:	Ethylbenzene
Chem (fr):	Éthylbenzène
Quantity:	6
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Toluene
Chem (fr):	Toluène
Quantity:	3.36
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance
Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Formaldehyde
Chem (fr):	Formaldéhyde
Quantity:	.61
Unit:	tonnes
Basis of Estimate Cd:	
Basis of Estimate Desc:	
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Methyl ethyl ketone
Chem (fr):	Méthyléthylcétone
Quantity:	45.33
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

70 | ***45 of 48*** | ***SSE/220.5*** | ***119.8 / -3.93*** | ***MAUSER CANADA LIMITED*** ***1121 Pioneer Road*** ***Burlington ON l7m1k5*** | ***NPRI***

NPRI ID:	10568	**Org ID:**	57200
Other ID:	N	**Submit Date:**	5/28/2008
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	54430	**Contact ID:**	197291
Report ID:	114065	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	PAUL
Report Year:	2007	**Cont Last Name:**	RUSE
Not-Current Rpt?:	No	**Contact Position:**	PLANT MANAGER
Yr of Last Filed Rpt:	2012	**Contact Fax:**	
Fac ID:	234040	**Contact Ph.:**	9053324800
Fac Name:	Mauser Canada Limited - Burlington	**Cont Area Code:**	905
Fac Address1:	1121 Pioneer Road	**Contact Tel.:**	53324800
Fac Address2:		**Contact Ext.:**	
Fac Postal Zip:	l7m1k5	**Cont Fax Area Cde:**	
Facility Lat:	43.3625	**Contact Fax:**	
Facility Long:	-79.7991	**Contact Email:**	PRUSE@RUSSELL-STANLEY.COM
DLS (Last Filed Rpt):		**Latitude:**	43.3625

Facility DLS:		**Longitude:**	-79.7991
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	79	**Waste Streams:**	True?
Parent Co.:	N	**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	True
Pollut Prev Cmnts:	False	**No Off Sites:**	1.00
Stacks:	True	**Shutdown:**	
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 33
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3312
NAICS 4 Description: Steel product manufacturing from purchased steel
NAICS Code (6 digit): 331221
NAICS 6 Description: Cold-rolled steel shape manufacturing

Substance Release Report

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Methyl ethyl ketone
Chem (fr): Méthyléthylcétone
Quantity: 31.5
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: n-Butyl alcohol
Chem (fr): Butan-1-ol
Quantity: 4.33
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Manganese (and its compounds)
Chem (fr): Manganèse (et ses composés)
Quantity: .031
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Volatile Organic Compounds (VOCs)

Chem (fr): Composés organiques volatils (COV)
Quantity: 134
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: 1,2,4-Trimethylbenzene
Chem (fr): 1,2,4-Triméthylbenzène
Quantity: 3.33
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Ethylbenzene
Chem (fr): Éthylbenzène
Quantity: 5.35
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Toluene
Chem (fr): Toluène
Quantity: 3
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Xylene (all isomers)
Chem (fr): Xylène (tous les isomères)
Quantity: 61.4
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Chromium (and its compounds)
Chem (fr): Chrome (et ses composés)
Quantity: .062
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	46 of 48	SSE/220.5	119.8 / -3.93	Mauser Canada Ltd. 1121 Pioneer Road Burlington ON l7m1k5	NPRI

NPRI ID:	10568	**Org ID:**	106454
Other ID:		**Submit Date:**	6/1/2016
No Other ID:		**Last Modified:**	11/18/2016 8:28:05 AM
Track ID:	136073	**Contact ID:**	241945
Report ID:	68724	**Cont Type:**	MEM
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	Paul
Report Year:	2015	**Cont Last Name:**	Ruse
Not-Current Rpt?:	No	**Contact Position:**	Plant Manager
Yr of Last Filed Rpt:	2012	**Contact Fax:**	9053325515
Fac ID:	234040	**Contact Ph.:**	9053322377
Fac Name:	Mauser Canada Limited - Burlington	**Cont Area Code:**	905
Fac Address1:	1121 Pioneer Road	**Contact Tel.:**	53322377
Fac Address2:		**Contact Ext.:**	
Fac Postal Zip:	l7m1k5	**Cont Fax Area Cde:**	905
Facility Lat:	43.3625	**Contact Fax:**	53325515
Facility Long:	-79.7991	**Contact Email:**	paul.ruse@mausergroup.com
DLS (Last Filed Rpt):		**Latitude:**	43.3625
Facility DLS:		**Longitude:**	-79.7991
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	54	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3312		
NAICS 4 Description:	Steel product manufacturing from purchased steel		
NAICS Code (6 digit):	331221		
NAICS 6 Description:	Cold-rolled steel shape manufacturing		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	
Chem (fr):	
Quantity:	23.83
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	
Chem (fr):	

Quantity: .06
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem:
Chem (fr):
Quantity: .03
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem:
Chem (fr):
Quantity: 87.61
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem:
Chem (fr):
Quantity: 10.79
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

70	***47 of 48***	***SSE/220.5***	***119.8 / -3.93***	***HUNTER DRUMS LIMITED*** ***1121 PIONEER ROAD*** ***BURLINGTON ON L7M 1K5***	***OPCB***

Year: 1995
Site Number: 30286A025
Name Owner:
Additional Site Information:

--Details--
Quantity: 9.00
Address Site:
Description: Number of Capacitors with High Level PCBs (>1000 ppm)

70	***48 of 48***	***SSE/220.5***	***119.8 / -3.93***	***HUNTER DRUMS LIMITED*** ***1121 PIONEER RD*** ***BURLINGTON ON L7M 1K5***	***SCT***

Established: 1963
Plant Size (ft²): 0
Employment: 45

--Details--
Description: METAL SHIPPING BARRELS, DRUMS, KEGS, AND PAILS
SIC/NAICS Code: 3412

---

71 ***1 of 2*** ***NNE/221.8*** ***125.8 / 2.07*** ***Bosch Rexroth Canada Corp.***
3426 Mainway
Burlington ON L7M 1A8 ***ECA***

Approval No:	9675-8KMJJZ	***MOE District:***	Halton-Peel
Approval Type:	ECA-AIR	***SWP Area Name:***	Halton
Status:	Approved	***Address:***	3426 Mainway
Approval Date:	2011-10-26	***City:***	Burlington
Record Type:	ECA	***Longitude:***	-79.799095
Project Type:	AIR	***Latitude:***	43.3684159999999
Link Source:	IDS		
Full Address:			

Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/6390-8ESKM2-13.pdf

---

71 ***2 of 2*** ***NNE/221.8*** ***125.8 / 2.07*** ***BOSCH REXROTH CANADA CORP.***
3426 MAINWAY DRIVE
BURLINGTON ON ***GEN***

Generator No.:	ON0677501	***PO Box No.:***	
Status:		***Country:***	
Approval Years:	2013	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No. Admin:***	
SIC Code:	335990		

SIC Description: ALL OTHER ELECTRICAL EQUIPMENT AND COMPONENT MANUFACTURING

--Details--

Waste Code:	231
Waste Description:	LATEX WASTES
Waste Code:	112
Waste Description:	ACID WASTE - HEAVY METALS
Waste Code:	263
Waste Description:	ORGANIC LABORATORY CHEMICALS
Waste Code:	251
Waste Description:	OIL SKIMMINGS & SLUDGES
Waste Code:	265
Waste Description:	GRAPHIC ART WASTES
Waste Code:	268
Waste Description:	AMINES
Waste Code:	331
Waste Description:	WASTE COMPRESSED GASES
Waste Code:	213
Waste Description:	PETROLEUM DISTILLATES
Waste Code:	121
Waste Description:	ALKALINE WASTES - HEAVY METALS
Waste Code:	252
Waste Description:	WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
72	1 of 1	N/224.1	126.2 / 2.41	**Sandtron Automation Ltd.** **1221 Dillon Rd** **Burlington ON L7M 1K6**	SCT

Established: 01-SEP-66
Plant Size (ft²):
Employment:

--Details--
Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

Description: Electronic Components, Navigational and Communications Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417320

Description: Professional Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417930

Description: Electronic Components, Navigational and Communications Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417320

Description: Wholesale Trade Agents and Brokers
SIC/NAICS Code: 419120

Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	1 of 2	S/226.0	119.5 / -4.31	**Mauser Canada Ltd.** **1121 Pioneer Rd** **Burlington ON L7M 1K5**	SCT

Established: 01-JUL-63
Plant Size (ft²):
Employment:

--Details--
Description: All Other Plastic Product Manufacturing
SIC/NAICS Code: 326198

Description: Other Metal Container Manufacturing
SIC/NAICS Code: 332439

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	2 of 2	S/226.0	119.5 / -4.31	**Hunter Drums Ltd.** **1121 Pioneer Rd** **Burlington ON L7L 6C7**	SCT

Established: 1963
Plant Size (ft²):
Employment: 100

--Details--
Description: All Other Plastic Product Manufacturing
SIC/NAICS Code: 326198

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: Other Metal Container Manufacturing
SIC/NAICS Code: 332439

Description: Coating, Engraving, Heat Treating and Allied Activities
SIC/NAICS Code: 332810

---

74 **1 of 5** **N/227.0** **125.8 / 2.07** **Bosch Rexroth Canada Corp.**
3426 Mainway Drive Burlington, Regional Municipality of Halton L7M 1A8 CITY OF BURLINGTON
ON
EBR

EBR Registry No.: 011-2948
Ministry Ref. No.: 6390-8ESKM2
Company Name: Bosch Rexroth Canada Corp.
Notice Type: Instrument Decision
Notice Date: November 02, 2011
Proposal Date: March 22, 2011
Year: 2011
Proponent Address: 3426 Mainway Drive, Burlington Ontario, Canada L7M 1A8
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:

Location:

3426 Mainway Drive Burlington, Regional Municipality of Halton L7M 1A8 CITY OF BURLINGTON

---

74 **2 of 5** **N/227.0** **125.8 / 2.07** **BOSCH REXROTH CANADA CORP.**
3426 MAINWAY DRIVE
BURLINGTON ON L7M 1A8
GEN

Generator No.: ON0677501
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 335990
SIC Description: ALL OTHER ELECTRICAL EQUIPMENT AND COMPONENT MANUFACTURING

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Faizan Sajid
Phone No. Admin: 905-335-5511 Ext.356

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 231
Waste Description: LATEX WASTES

Waste Code: 265
Waste Description: GRAPHIC ART WASTES

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 268
Waste Description: AMINES

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 331
Waste Description: WASTE COMPRESSED GASES

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

---

74 **3 of 5** **N/227.0** **125.8 / 2.07** **BOSCH REXROTH CANADA CORP.**
3426 MAINWAY DRIVE
BURLINGTON ON L7M 1A8 **GEN**

Generator No.: ON0677501
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country: Canada
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252 L
Waste Description: Waste crankcase oils and lubricants

Waste Code: 145 I
Waste Description: Wastes from the use of pigments, coatings and paints

Waste Code: 213 I
Waste Description: Petroleum distillates

Waste Code: 263 L
Waste Description: Misc. waste organic chemicals

Waste Code: 262 L
Waste Description: Detergents and soaps

Waste Code: 331 I
Waste Description: Waste compressed gases including cylinders

Waste Code: 251 L
Waste Description: Waste oils/sludges (petroleum based)

---

74 **4 of 5** **N/227.0** **125.8 / 2.07** **BOSCH REXROTH CANADA CORP.**
3426 MAINWAY DRIVE
BURLINGTON ON L7M 1A8 **GEN**

Generator No.: ON0677501
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 335990
SIC Description: ALL OTHER ELECTRICAL EQUIPMENT AND COMPONENT MANUFACTURING

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Faizan Sajid
Phone No. Admin: 905-335-5511 Ext.356

--Details--

Waste Code: 265
Waste Description: GRAPHIC ART WASTES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 331
Waste Description: WASTE COMPRESSED GASES

Waste Code: 268
Waste Description: AMINES

Waste Code: 231
Waste Description: LATEX WASTES

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

---

74 ***5 of 5*** ***N/227.0*** ***125.8 / 2.07*** ***BOSCH REXROTH CANADA CORP.***
3426 MAINWAY DRIVE
BURLINGTON ON L7M 1A8 ***GEN***

Generator No.: ON0677501
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 335990
SIC Description: ALL OTHER ELECTRICAL EQUIPMENT AND COMPONENT MANUFACTURING

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Faizan Sajid
Phone No. Admin: 905-335-5511 Ext.356

--Details--

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 331
Waste Description: WASTE COMPRESSED GASES

Waste Code: 268
Waste Description: AMINES

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 265
Waste Description: GRAPHIC ART WASTES

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 231
Waste Description: LATEX WASTES

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

---

75 **1 of 1** **SW/228.4** **121.8 / -1.93** **BURLINGTON ON** **WWIS**

Well ID: 7044304
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z56180
Tag: A048742
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 5/31/2007
Selected Flag: 1
Abandonment Rec:
Contractor: 7238
Form Version: 3
Owner:
Street Name: 3230 MAINWAY RD
County: HALTON
Municipality: BURLINGTON CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 11766814
DP2BR: 3
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Elevation: 122.362968

Spatial Status:
Cluster Kind:
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83

Elevrc: ***Date Completed:*** 5/10/2007
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 933102530
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Other Materials: GRAVEL
Mat3:
Other Materials:
Formation Top Depth: 0.00
Formation End Depth: 1.00
Formation End Depth UOM: m

Formation ID: 933102531
Layer: 2
Color: 7
General Color: RED
Mat1: 17
Most Common Material: SHALE
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 1.00
Formation End Depth: 4.50
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933319974
Layer: 1
Plug From: 0.00
Plug To: 1.00
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 967044304
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 11774504
Casing No: 1
Comment:

Alt Name:

Construction Record - Casing

Casing ID: 930900067
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.00
Depth To: 1.00
Casing Diameter:
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933424695
Layer: 1
Slot: 10
Screen Top Depth: 1.00
Screen End Depth: 4.50
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter:

Water Details

Water ID: 934086557
Layer: 1
Kind Code:
Kind:
Water Found Depth: 1.00
Water Found Depth UOM: m

Hole Diameter

Hole ID: 11853314
Diameter: 15.00
Depth From: 0.00
Depth To: 4.50
Hole Depth UOM: m
Hole Diameter UOM: cm

---

76 | **1 of 21** | **WNW/232.7** | **125.3 / 1.52** | **NIXON INTEGRATED MACHINING DESIGN LTD.**
3291 Mainway Drive Units 5 & 6
Burlington ON L7M 1A6 | **GEN**

Generator No.: ON2153000
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 332710
SIC Description: MACHINE SHOPS

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 253
Waste Description: EMULSIFIED OILS

Waste Code: 252

Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

---

76 **2 of 21** **WNW/232.7** **125.3 / 1.52** **GEN**

NIXON INTEGRATED MACHINING DESIGN LTD.
3291 Mainway Drive Units 5 & 6
Burlington ON L7M 1A6

Generator No.: ON2153000
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 332710
SIC Description: MACHINE SHOPS

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

76 **3 of 21** **WNW/232.7** **125.3 / 1.52** **GEN**

NIXON INTEGRATED MACHINING DESIGN LTD.
3291 Mainway Drive Units 5 & 6
Burlington ON L7M 1A6

Generator No.: ON2153000
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 332710
SIC Description: MACHINE SHOPS

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 253
Waste Description: EMULSIFIED OILS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

76 **4 of 21** **WNW/232.7** **125.3 / 1.52** **GEN**

NIXON INTEGRATED MACHINING DESIGN LTD.
3291 Mainway Drive Units 5 & 6
Burlington ON L7M 1A6

Generator No.: ON2153000
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:

PO Box No.:
Country: Canada
Choice of Contact:
Co Admin:
Phone No. Admin:

SIC Description:

--Details--
Waste Code: 252 L
Waste Description: Waste crankcase oils and lubricants

Waste Code: 253 L
Waste Description: Emulsified oils

Waste Code: 213 I
Waste Description: Petroleum distillates

---

76 ***5 of 21*** ***WNW/232.7*** ***125.3 / 1.52*** ***NIXON INTEGRATED MACHINING DESIGN LTD.*** ***GEN***
3291 MAINWAY DRIVE, UNITS 5 & 6
BURLINGTON ON L7M 1A6

Generator No.: ON2153000
Status:
Approval Years: 96,97,98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 3081
SIC Description: MACHINE SHOP IND.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

76 ***6 of 21*** ***WNW/232.7*** ***125.3 / 1.52*** ***NIXON INTEGRATED MACHINING DESIGN LTD.*** ***GEN***
3291 Mainway Drive Units 5 & 6
Burlington ON L7M 1A6

Generator No.: ON2153000
Status:
Approval Years: 07,08
Contam. Facility:
MHSW Facility:
SIC Code: 332710
SIC Description: Machine Shops

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

76 ***7 of 21*** ***WNW/232.7*** ***125.3 / 1.52*** ***NIXON INTEGRATED MACHINING DESIGN LTD.*** ***GEN***
3291 Mainway Drive Units 5 & 6

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Burlington ON L7M 1A6	

Generator No.: ON2153000
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 332710
SIC Description: Machine Shops

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

76 **8 of 21** **WNW/232.7** **125.3 / 1.52**

BROWN FALCON MACHINE & TOOL
3291 MAINWAY, UNIT 1 & 2
BURLINGTON ON L7M 1A6

GEN

Generator No.: ON1270701
Status:
Approval Years: 93,94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 2921
SIC Description: STEEL PIPE & TUBE

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

---

76 **9 of 21** **WNW/232.7** **125.3 / 1.52**

NIXON INTEGRATED MACHINING DESIGN LTD.
3291 Mainway Drive Units 5 & 6
Burlington ON L7M 1A6

GEN

Generator No.: ON2153000
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 332710
SIC Description: Machine Shops

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 253
Waste Description: EMULSIFIED OILS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
76	10 of 21	WNW/232.7	125.3 / 1.52	NIXON INTEGRATED MACHINING DESIGN LTD. 3291 Mainway Drive Units 5 & 6 Burlington ON L7M 1A6	GEN

Generator No.: ON2153000
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 332710
SIC Description: Machine Shops

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
76	11 of 21	WNW/232.7	125.3 / 1.52	NIXON INTEGRATED MACHINING DESIGN LTD. 3291 Mainway Drive Units 5 & 6 Burlington ON	GEN

Generator No.: ON2153000
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 332710
SIC Description: MACHINE SHOPS

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 253
Waste Description: EMULSIFIED OILS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
76	12 of 21	WNW/232.7	125.3 / 1.52	NIXON INTEGRATED MACHINING DESIGN LTD. 3291 Mainway Drive Units 5 & 6 Burlington ON L7M 1A6	GEN

Generator No.: ON2153000
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 332710
SIC Description: Machine Shops

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

76 **13 of 21** **WNW/232.7** **125.3 / 1.52** **GEN**

NIXON INTEGRATED MACHINING DESIGN LTD.
3291 Mainway Drive Units 5,6,7,8and9
Burlington ON L7M 1A6

Generator No.: ON2153000
Status:
Approval Years: 02,03,04,05,06
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

76 **14 of 21** **WNW/232.7** **125.3 / 1.52** **GEN**

BROWN FALCON MACHINE & TOOL
3291 MAINWAY, UNITS 1-2
BURLINGTON ON L7M 1A6

Generator No.: ON1270701
Status:
Approval Years: 99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 2921
SIC Description: STEEL PIPE & TUBE

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

---

76 **15 of 21** **WNW/232.7** **125.3 / 1.52** **PES**

SOLOMON, J.N. ENTERPRISES LIMITED
3291 MAINWAY #5
BURLINGTON ON L7M 1A6

Licence No:
Detail Licence No:
Licence Type Code:
Licence Type: Vendor
Licence Class:
Licence Control:
Trade Name:
Post Office Box:
Lot:
Concession:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Oper Phone Area Cd:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Region:				**Ext:**	
District:				**Oper Phone No:**	
County:				**Proponent Ext:**	

76	16 of 21	WNW/232.7	125.3 / 1.52	**BROWN FALCON MACHINE & TOOL** **3291 MAINWAY DR UNIT 1-2** **BURLINGTON ON L7M 1A6**	SCT

Established: 1985
Plant Size (ft²): 7500
Employment: 8

--Details--
Description: SPECIAL DIES AND TOOLS, DIE SETS, JIGS AND FIXTURES, AND INDUSTRIAL MOLDS
SIC/NAICS Code: 3544

Description: INDUSTRIAL AND COMMERCIAL MACHINERY AND EQUIPMENT, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3599

76	17 of 21	WNW/232.7	125.3 / 1.52	**Nixon Integrated Machining** **3291 Mainway Unit 5-6** **Burlington ON L7M 1A6**	SCT

Established: 01-JAN-93
Plant Size (ft²): 6000
Employment:

--Details--
Description: Machine Shops
SIC/NAICS Code: 332710

76	18 of 21	WNW/232.7	125.3 / 1.52	**MCKELLAR MACHINE PRODUCTS LTD.** **3291 MAINWAY DR** **BURLINGTON ON L7M 1A6**	SCT

Established: 1978
Plant Size (ft²): 4700
Employment: 15

--Details--
Description: SCREW MACHINE PRODUCTS
SIC/NAICS Code: 3451

76	19 of 21	WNW/232.7	125.3 / 1.52	**BROWN FALCON MACHINE,TOOL/DIE** **3291 Mainway Dr Unit 1-2** **Burlington ON L7M 1A6**	SCT

Established: 1985
Plant Size (ft²): 7500
Employment: 8

--Details--
Description: Machine Shops
SIC/NAICS Code: 332710

Description: Industrial Mould Manufacturing
SIC/NAICS Code: 333511

Description: Other Metalworking Machinery Manufacturing
SIC/NAICS Code: 333519

---

76 | **20 of 21** | **WNW/232.7** | **125.3 / 1.52** | **BROWN FALCON MACHINE,TOOL & DI**
3291 MAINWAY DR UNIT 1-2
BURLINGTON ON L7M 1A6 | **SCT**

Established: 1985
Plant Size (ft²): 7500
Employment: 8

--Details--
Description: Machine Shops
SIC/NAICS Code: 332710

Description: Industrial Mould Manufacturing
SIC/NAICS Code: 333511

Description: Other Metalworking Machinery Manufacturing
SIC/NAICS Code: 333519

---

76 | **21 of 21** | **WNW/232.7** | **125.3 / 1.52** | **Brown Falcon Machine,Tool & Die Ltd.**
3291 Mainway Unit 1-2
Burlington ON L7M 1A6 | **SCT**

Established: 1985
Plant Size (ft²): 7500
Employment: 8

---

77 | **1 of 1** | **E/232.9** | **120.9 / -2.92** | **ON** | **WWIS**

Well ID: 7255086
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status:
Water Type:
Casing Material:
Audit No: C25919
Tag: A179971
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status: Date Entry is incomplete
Data Src:
Date Received: 12/30/2015
Selected Flag: 1
Abandonment Rec:
Contractor: 6607
Form Version: 8
Owner:
Street Name:
County: HALTON
Municipality: BURLINGTON CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1005847273
Spatial Status:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 121.114967
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Cluster Kind:
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr
Org CS: UTM83
Date Completed: 5/4/2015

---

78 | **1 of 1** | **ENE/233.7** | **120.8 / -2.98** | **1101 Blair Road Burlington ON** | **EHS**

Order ID: 458743
Order No: 20160517161
Customer ID: 143093
Company ID: 89885
Status: C
Report Code: 4CAN
Report Type: Custom Report
Report Date: 24-MAY-16
Report Requested by: Snc Lavalin
Nearest Intersection:
Previous Site Name:
Additional Info Ordered:
Date Received: 17-MAY-16
Lot/Building Size:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
Large Radius: .5
X: -79.795635
Y: 43.36624

---

79 | **1 of 6** | **NW/236.4** | **126.4 / 2.64** | **TRAVIS INDUSTRIAL MAINTENANCE 3327 MAINWAY, UNIT C BURLINGTON ON L7M 1A6** | **GEN**

Generator No.: ON0944101
Status:
Approval Years: 95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 9949
SIC Description: OTHER REPAIR SERV.
PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

79 | **2 of 6** | **NW/236.4** | **126.4 / 2.64** | **TRAVIS INDUSTRIAL MAINTENANCE LIMITED 3327 MAINWAY, UNIT C BURLINGTON ON L7M 1A6** | **GEN**

Generator No.: ON0944101
Status:
Approval Years: 99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 9949
SIC Description: OTHER REPAIR SERV.
PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

79 ***3 of 6*** ***NW/236.4*** ***126.4 / 2.64*** ***TRAVIS INDUSTRIAL MAINTENANCE LIMITED***
3327 MAINWAY DRIVE UNIT C
BURLINGTON ON L7M 1A6 ***GEN***

Generator No.: ON0944101
Status:
Approval Years: 02,03,04
Contam. Facility:
MHSW Facility:
SIC Code: 232590
SIC Description: Other Building Equipment Installation

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

79 ***4 of 6*** ***NW/236.4*** ***126.4 / 2.64*** ***D F ELECTRONICS INC***
3327 MAINWAY UNIT A
BURLINGTON ON L7M 1A6 ***SCT***

Established: 0000
Plant Size (ft²): 0
Employment: 8

--Details--
Description: SPECIAL INDUSTRY MACHINERY, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3559

---

79 ***5 of 6*** ***NW/236.4*** ***126.4 / 2.64*** ***OnDrive Inc.***
3327 Mainway Unit C
Burlington ON L7M 1A6 ***SCT***

Established:
Plant Size (ft²):
Employment:

--Details--
Description: Measuring, Medical and Controlling Devices Manufacturing
SIC/NAICS Code: 334512

Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

---

79 ***6 of 6*** ***NW/236.4*** ***126.4 / 2.64*** ***Firecraft Kilns Sales & Service***
3327 Mainway Dr Unit B ***SCT***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Burlington ON L7M 1A6	

Established: 1977
Plant Size (ft²):
Employment: 6

--Details--
Description: All Other Industrial Machinery Manufacturing
SIC/NAICS Code: 333299

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
80	1 of 5	WNW/237.9	125.8 / 2.07	**HELEC INSULATION LTD** **3323 MAINWAY DR UNIT D** **BURLINGTON ON L7M 1A6**	SCT

Established: 1980
Plant Size (ft²): 2000
Employment: 6

--Details--
Description: PLASTICS PRODUCTS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3089

Description: MINERAL WOOL
SIC/NAICS Code: 3296

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
80	2 of 5	WNW/237.9	125.8 / 2.07	**Helec Insulation Ltd.** **3323 Mainway Unit D** **Burlington ON L7M 1A6**	SCT

Established: 1980
Plant Size (ft²): 4000
Employment:

--Details--
Description: All Other Plastic Product Manufacturing
SIC/NAICS Code: 326198

Description: All Other Non-Metallic Mineral Product Manufacturing
SIC/NAICS Code: 327990

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
80	3 of 5	WNW/237.9	125.8 / 2.07	**PST MACHINING LTD.** **3323 Mainway Dr Unit C** **Burlington ON L7M 1A6**	SCT

Established: 1991
Plant Size (ft²): 2000
Employment: 3

--Details--
Description: Machine Shops
SIC/NAICS Code: 332710

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
80	4 of 5	WNW/237.9	125.8 / 2.07	**HELEC INSULATION LTD.** **3323 Mainway Dr Unit D**	SCT

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Burlington ON L7M 1A6	

Established: 1980
Plant Size (ft²): 2000
Employment: 6

--Details--
Description: All Other Plastic Product Manufacturing
SIC/NAICS Code: 326198

Description: All Other Non-Metallic Mineral Product Manufacturing
SIC/NAICS Code: 327990

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
80	5 of 5	WNW/237.9	125.8 / 2.07	***P S T MACHINING LIMITED*** ***3323 MAINWAY DR UNIT C*** ***BURLINGTON ON L7M 1A6***	SCT

Established: 1991
Plant Size (ft²): 2000
Employment: 3

--Details--
Description: INDUSTRIAL AND COMMERCIAL MACHINERY AND EQUIPMENT, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3599

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
81	1 of 1	SSW/238.1	120.8 / -2.99	***BURLINGTON ON***	WWIS

Well ID:	2810458	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:	Not Used	***Date Received:***	1/5/2006
Sec. Water Use:		***Selected Flag:***	1
Final Well Status:		***Abandonment Rec:***	
Water Type:		***Contractor:***	7238
Casing Material:		***Form Version:***	3
Audit No:	Z39700	***Owner:***	
Tag:	A035816	***Street Name:***	3230 MAINWAY
Construction Method:		***County:***	HALTON
Elevation (m):		***Municipality:***	BURLINGTON CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	11552368	***Spatial Status:***	
DP2BR:	8	***Cluster Kind:***	
Code OB:	r	***UTMRC:***	3
Code OB Desc:	Bedrock	***UTMRC Desc:***	margin of error : 10 - 30 m
Open Hole:		***Location Method:***	wwr
Elevation:	121.027351	***Org CS:***	UTM83
Elevrc:		***Date Completed:***	12/1/2005
Remarks:			

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 933043246
Layer: 1
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 0.00
Formation End Depth: 2.40
Formation End Depth UOM: m

Formation ID: 933043247
Layer: 2
Color: 7
General Color: RED
Mat1: 17
Most Common Material: SHALE
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 2.40
Formation End Depth: 6.00
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933287236
Layer: 1
Plug From: 0.00
Plug To: 2.40
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 962810458
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 11561975
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID:	930874660
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.00
Depth To:	3.00
Casing Diameter:	5.00
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	933416960
Layer:	1
Slot:	10
Screen Top Depth:	3.00
Screen End Depth:	6.00
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.40

Hole Diameter

Hole ID:	11683477
Diameter:	21.00
Depth From:	0.00
Depth To:	6.00
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

82 ***1 of 1*** ***SW/242.0*** ***121.8 / -1.93*** ***Burlington ON*** ***WWIS***

Well ID:	7121191	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:		***Date Received:***	3/16/2009
Sec. Water Use:		***Selected Flag:***	1
Final Well Status:	0	***Abandonment Rec:***	Yes
Water Type:		***Contractor:***	7282
Casing Material:		***Form Version:***	5
Audit No:	M03118	***Owner:***	
Tag:	A055816	***Street Name:***	3230 MAINWAY
Construction Method:		***County:***	HALTON
Elevation (m):		***Municipality:***	BURLINGTON CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1003226943	***Spatial Status:***	
DP2BR:		***Cluster Kind:***	This is a record from cluster log sheet
Code OB:		***UTMRC:***	9

Code OB Desc:		***UTMRC Desc:***	unknown UTM
Open Hole:		***Location Method:***	na
Elevation:		***Org CS:***	
Elevrc:		***Date Completed:***	12/9/2008
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1003226947
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1003226946
Method Construction Code:	
Method Construction:	
Other Method Construction:	ROTARY

Hole Diameter

Hole ID:	1003226945
Diameter:	20.30
Depth From:	
Depth To:	3.90
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1003226968	***Spatial Status:***	
DP2BR:		***Cluster Kind:***	This is a record from cluster log sheet
Code OB:		***UTMRC:***	3
Code OB Desc:		***UTMRC Desc:***	margin of error : 10 - 30 m
Open Hole:		***Location Method:***	wwr
Elevation:	123.641052	***Org CS:***	UTM83
Elevrc:		***Date Completed:***	12/11/2008
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1003226972
Layer:	
Plug From:	
Plug To:	

Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003226971
Method Construction Code:
Method Construction:
Other Method Construction: ROTARY

Hole Diameter

Hole ID: 1003226970
Diameter: 20.30
Depth From:
Depth To: 5.70
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1003226973
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 122.53057
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 12/11/2008

Annular Space/Abandonment Sealing Record

Plug ID: 1003226977
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003226976
Method Construction Code:
Method Construction:
Other Method Construction: ROTARY

Hole Diameter

Hole ID: 1003226975
Diameter: 20.30
Depth From:
Depth To: 5.50
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID:	1003226963	***Spatial Status:***	
DP2BR:		***Cluster Kind:***	This is a record from cluster log sheet
Code OB:		***UTMRC:***	9
Code OB Desc:		***UTMRC Desc:***	unknown UTM
Open Hole:		***Location Method:***	na
Elevation:		***Org CS:***	
Elevrc:		***Date Completed:***	12/11/2008
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1003226967
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1003226966
Method Construction Code:	
Method Construction:	
Other Method Construction:	ROTARY

Hole Diameter

Hole ID:	1003226965
Diameter:	20.30
Depth From:	
Depth To:	4.30
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1003226978	***Spatial Status:***	
DP2BR:		***Cluster Kind:***	This is a record from cluster log sheet
Code OB:		***UTMRC:***	9
Code OB Desc:		***UTMRC Desc:***	unknown UTM
Open Hole:		***Location Method:***	na
Elevation:		***Org CS:***	
Elevrc:		***Date Completed:***	12/11/2008
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID: 1003226982
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003226981
Method Construction Code:
Method Construction:
Other Method Construction: ROTARY

Hole Diameter

Hole ID: 1003226980
Diameter: 20.30
Depth From:
Depth To: 4.30
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002036519
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 121.08142
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind:
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr
Org CS: UTM83
Date Completed: 2/18/2009

Annular Space/Abandonment Sealing Record

Plug ID: 1003226983
Layer: 1
Plug From: 0.00
Plug To: 6.09
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1003226984
Method Construction Code:
Method Construction:
Other Method Construction:

Bore Hole Information

Bore Hole ID: 1003226948
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation:
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na
Org CS:
Date Completed: 12/10/2008

Annular Space/Abandonment Sealing Record

Plug ID: 1003226952
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003226951
Method Construction Code:
Method Construction:
Other Method Construction: ROTARY

Hole Diameter

Hole ID: 1003226950
Diameter: 20.30
Depth From:
Depth To: 5.50
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1003226958
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation:
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na
Org CS:
Date Completed: 12/10/2008

Annular Space/Abandonment Sealing Record

Plug ID: 1003226962
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003226961
Method Construction Code:
Method Construction:
Other Method Construction: ROTARY

Hole Diameter

Hole ID: 1003226960
Diameter: 20.30
Depth From:
Depth To: 4.20
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1003226933
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation:
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na
Org CS:
Date Completed: 12/9/2008

Annular Space/Abandonment Sealing Record

Plug ID: 1003226937
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003226936
Method Construction Code:
Method Construction:
Other Method Construction: ROTARY

Hole Diameter

Hole ID: 1003226935
Diameter: 20.30

Depth From:
Depth To: 5.70
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1003226938
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation:
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na
Org CS:
Date Completed: 12/9/2008

Annular Space/Abandonment Sealing Record

Plug ID: 1003226942
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003226941
Method Construction Code:
Method Construction:
Other Method Construction: ROTARY

Hole Diameter

Hole ID: 1003226940
Diameter: 20.30
Depth From:
Depth To: 5.80
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1003226953
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation:
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na
Org CS:
Date Completed: 12/10/2008

Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1003226957
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1003226956
Method Construction Code:
Method Construction:
Other Method Construction: ROTARY

Hole Diameter

Hole ID: 1003226955
Diameter: 20.30
Depth From:
Depth To: 4.20
Hole Depth UOM: m
Hole Diameter UOM: cm

---

83 | ***1 of 8*** | ***NE/243.6*** | ***123.7 / -0.08*** | ***BRAMKAL CONTRACTORS INC.***
3450 LANDMARK ROAD
BURLINGTON ON L7M 1S8 | ***GEN***

Generator No.: ON5452746
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 238990
SIC Description: ALL OTHER SPECIALTY TRADE CONTRACTORS

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 135
Waste Description: REACTIVE ANION WASTES

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

83 | ***2 of 8*** | ***NE/243.6*** | ***123.7 / -0.08*** | ***BramKal Contractors Inc.***
3450 Landmark Rd.
Burlington ON L7M 1S8 | ***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No.: ON9322298
Status:
Approval Years: 06
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

83 | ***3 of 8*** | ***NE/243.6*** | ***123.7 / -0.08*** | ***Burlington Cutting and Finishing Inc.*** ***3450 landmark rd Unit B*** ***Burlington ON L7M 1S8*** | ***GEN***

Generator No.: ON7899615
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 332710
SIC Description: Machine Shops

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 253
Waste Description: EMULSIFIED OILS

---

83 | ***4 of 8*** | ***NE/243.6*** | ***123.7 / -0.08*** | ***Burlington Cutting and Finishing Inc.*** ***3450 landmark rd Unit B*** ***Burlington ON L7M 1S8*** | ***GEN***

Generator No.: ON7899615
Status:
Approval Years: 07,08
Contam. Facility:
MHSW Facility:
SIC Code: 332710
SIC Description: Machine Shops

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 253
Waste Description: EMULSIFIED OILS

---

83 | ***5 of 8*** | ***NE/243.6*** | ***123.7 / -0.08*** | ***Bramkal contractors Inc.*** ***3450 Landmark Road*** ***Burlington ON L7M 1S8*** | ***GEN***

Generator No.: ON2617745
Status:
Approval Years: 07,08
Contam. Facility:
MHSW Facility:
SIC Code: 339990
SIC Description: All Other Miscellaneous Manufacturing

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

83 | ***6 of 8*** | ***NE/243.6*** | ***123.7 / -0.08*** | ***A-1 Asphalt Maintenance Ltd.***
3450 Landmark Road Unit B
Burlington ON L7M 1S8 | ***GEN***

Generator No.: ON2854590
Status:
Approval Years: 02,03,04,05
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 222
Waste Description: HEAVY FUELS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

83 | ***7 of 8*** | ***NE/243.6*** | ***123.7 / -0.08*** | ***Tach West Technologies Ltd.***
3450C Landmark Rd
Burlington ON L7M 1S8 | ***SCT***

Established:
Plant Size (ft²):
Employment:

--Details--
Description: Semiconductor and Other Electronic Component Manufacturing
SIC/NAICS Code: 334410

Description: Measuring, Medical and Controlling Devices Manufacturing
SIC/NAICS Code: 334512

Description: Professional Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417930

Description: Other New Motor Vehicle Parts and Accessories Wholesaler-Distributors
SIC/NAICS Code: 415290

---

83 | ***8 of 8*** | ***NE/243.6*** | ***123.7 / -0.08*** | ***Burlington Cutting & Finishing***
3450B Landmark Rd
Burlington ON L7M 1S8 | ***SCT***

Established: 1988
Plant Size (ft²): 12000

Employment:

--Details--
Description: Stamping
SIC/NAICS Code: 332118

---

84 ***1 of 10*** ***NE/245.8*** ***124.8 / 1.07*** ***3455 Landmark Rd Burlington ON L7M1T4*** ***EHS***

Order ID:	464756	***Date Received:***	15-JUN-16
Order No:	20160615128	***Lot/Building Size:***	
Customer ID:	87207	***Municipality:***	
Company ID:	55385	***Client Prov/State:***	ON
Status:	C	***Search Radius (km):***	.25
Report Code:	3CAN	***Large Radius:***	2
Report Type:	Standard Report	***X:***	-79.797138
Report Date:	22-JUN-16	***Y:***	43.368092
Report Requested by:	Hallex Environmental Ltd.		
Nearest Intersection:			
Previous Site Name:			
Additional Info Ordered:			

---

84 ***2 of 10*** ***NE/245.8*** ***124.8 / 1.07*** ***COMSTOCK CANADA LTD. 3455 Landmark Road Burlington ON L7M 1T4*** ***GEN***

Generator No.:	ON0678305	***PO Box No.:***	
Status:		***Country:***	
Approval Years:	2012	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No. Admin:***	
SIC Code:	493190		
SIC Description:	Other Warehousing and Storage		

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

---

84 ***3 of 10*** ***NE/245.8*** ***124.8 / 1.07*** ***COMSTOCK CANADA LTD. 3455 Landmark Road Burlington ON L7M 1T4*** ***GEN***

Generator No.:	ON0678305	***PO Box No.:***	
Status:		***Country:***	
Approval Years:	2011	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No. Admin:***	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Code: 493190
SIC Description: Other Warehousing and Storage

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

---

84 **4 of 10** **NE/245.8** **124.8 / 1.07** **COMSTOCK CANADA LTD.**
3455 LANDMARK ROAD
BURLINGTON ON L7M 1T4 **GEN**

Generator No.: ON0678305
Status:
Approval Years: 99,00,01,02,03,04,05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code: 4255
SIC Description: MILLWRIGHT & RIGGING
PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 241
Waste Description: HALOGENATED SOLVENTS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

84 **5 of 10** **NE/245.8** **124.8 / 1.07** **COMSTOCK CANADA LTD.**
3455 Landmark Road
Burlington ON L7M1T4 **GEN**

Generator No.: ON0678305
PO Box No.:

Status:		**Country:**	Canada
Approval Years:	2014	**Choice of Contact:**	CO_ADMIN
Contam. Facility:	No	**Co Admin:**	Jacqueline Quinn
MHSW Facility:	No	**Phone No. Admin:**	905 335 3333 Ext.
SIC Code:	493190		
SIC Description:	OTHER WAREHOUSING AND STORAGE		

--Details--

Waste Code:	122
Waste Description:	ALKALINE WASTES - OTHER METALS
Waste Code:	148
Waste Description:	INORGANIC LABORATORY CHEMICALS
Waste Code:	263
Waste Description:	ORGANIC LABORATORY CHEMICALS
Waste Code:	252
Waste Description:	WASTE OILS & LUBRICANTS
Waste Code:	213
Waste Description:	PETROLEUM DISTILLATES

---

84 | ***6 of 10*** | ***NE/245.8*** | ***124.8 / 1.07*** | ***COMSTOCK CANADA LTD.***
3455 Landmark Road
Burlington ON L7M 1T4 | ***GEN***

Generator No.:	ON0678305	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	2010	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	493190		
SIC Description:	Other Warehousing and Storage		

--Details--

Waste Code:	148
Waste Description:	INORGANIC LABORATORY CHEMICALS
Waste Code:	252
Waste Description:	WASTE OILS & LUBRICANTS
Waste Code:	263
Waste Description:	ORGANIC LABORATORY CHEMICALS
Waste Code:	122
Waste Description:	ALKALINE WASTES - OTHER METALS
Waste Code:	213
Waste Description:	PETROLEUM DISTILLATES

---

84 | ***7 of 10*** | ***NE/245.8*** | ***124.8 / 1.07*** | ***COMSTOCK CANADA LTD.***
3455 Landmark Road
Burlington ON L7M 1T4 | ***GEN***

Generator No.:	ON0678305	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	2009	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	493190		

SIC Description: Other Warehousing and Storage

--Details--
Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

---

84 | ***8 of 10*** | ***NE/245.8*** | ***124.8 / 1.07*** | ***COMSTOCK CANADA***
3455 LANDMARK ROAD
BURLINGTON ON L7M 1T4 | ***GEN***

Generator No.: ON0678305
Status:
Approval Years: 95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 4255
SIC Description: MILLWRIGHT & RIGGING
PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 145
Waste Description: PAINT/PIGMENT/COATING RESIDUES

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 241
Waste Description: HALOGENATED SOLVENTS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

84 | ***9 of 10*** | ***NE/245.8*** | ***124.8 / 1.07*** | ***COMSTOCK CANADA LTD.***
3455 Landmark Road
Burlington ON | ***GEN***

Generator No.: ON0678305
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 493190
SIC Description: OTHER WAREHOUSING AND STORAGE
PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213

Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS

---

84 | ***10 of 10*** | ***NE/245.8*** | ***124.8 / 1.07*** | ***Comstock Canada Ltd.***
3455 Landmark Rd
Burlington ON L7M 1T4 | ***PAP***

Division:
Mailing Address:: 3455 Landmark Rd, Burlington ON L7M 1T4
Year: 2009
Company ID: 146985731
Mill Notes::
History::
Operation:
Type: Head Office
Status:: Active

---

85 | ***1 of 11*** | ***WSW/248.1*** | ***123.8 / 0.04*** | ***Burlington Technologies Inc.***
Burlington ON | ***CA***

Certificate #: 6171-6MVLFD
Application Year: 2006
Issue Date: 5/17/2006
Approval Type: Air
Status: Approved
Application Type:
Client Name::
Client Address::
Client City::
Client Postal Code::
Project Description::
Contaminants::
Emission Control::

---

85 | ***2 of 11*** | ***WSW/248.1*** | ***123.8 / 0.04*** | ***Burlington Technologies Inc.***
3267 Mainway Burlington, Regional Municipality
Of Halton CITY OF BURLINGTON
ON | ***EBR***

EBR Registry No.: 010-3460
Ministry Ref. No.: 2549-7DSSQF
Company Name: Burlington Technologies Inc.
Notice Type: Instrument Decision
Notice Date: January 28, 2010
Proposal Date: May 01, 2008
Year: 2008
Proponent Address: 3267 Main Way, Burlington Ontario, Canada L7M 1A6
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)

Location Other:

Location:

3267 Mainway Burlington, Regional Municipality Of Halton CITY OF BURLINGTON

---

85 ***3 of 11*** ***WSW/248.1*** ***123.8 / 0.04*** ***Revstone Industries Burlington Inc., o/aBurlington Technologies Inc. 3267 Mainway Burlington, Regional Municipality Of Halton CITY OF BURLINGTON ON*** ***EBR***

EBR Registry No.: 011-1390
Ministry Ref. No.: 8914-89PRRP
Company Name: Revstone Industries Burlington Inc., o/aBurlington Technologies Inc.
Notice Type: Instrument Decision
Notice Date: October 06, 2015
Proposal Date: October 25, 2010
Year: 2010
Proponent Address: 3267 Mainway Drive, Burlington Ontario, Canada L7M 1A6
Instrument Type: (EPA Part II.1-air) - Environmental Compliance Approval (project type: air)
Location Other:

Location:

3267 Mainway Burlington, Regional Municipality Of Halton CITY OF BURLINGTON

---

85 ***4 of 11*** ***WSW/248.1*** ***123.8 / 0.04*** ***Burlington Technologies Inc. 3267 Mainway Burlington Ontario L7M 1A6 Burlington ON*** ***EBR***

EBR Registry No.: IA04E0442
Ministry Ref. No.: 3153-5XCNPJ
Company Name: Burlington Technologies Inc.
Notice Type: Instrument Decision
Notice Date: November 04, 2004
Proposal Date: March 29, 2004
Year: 2004
Proponent Address: 3267 Mainway, Burlington Ontario, L7M 1A6
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:

Location:

3267 Mainway Burlington Ontario L7M 1A6 Burlington

---

85 ***5 of 11*** ***WSW/248.1*** ***123.8 / 0.04*** ***Burlington Technologies Inc. 3267 Mainway Burlington Ontario L7M 1A6 Burlington ON*** ***EBR***

EBR Registry No.: IA9E1347
Ministry Ref. No.: 8674-4E5Q8A
Company Name: Burlington Technologies Inc.
Notice Type: Instrument Decision
Notice Date: November 02, 2000
Proposal Date: December 06, 1999

Year: 1999
Proponent Address: 3267 Mainway, Burlington Ontario, L7M 1A6
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:

Location:

3267 Mainway Burlington Ontario L7M 1A6 Burlington

---

85 | ***6 of 11*** | ***WSW/248.1*** | ***123.8 / 0.04*** | ***Burlington Technologies Inc.***
3267 Mainway Burlington Ontario L7M 1A6
Burlington
ON | ***EBR***

EBR Registry No.: IA00E0376
Ministry Ref. No.: 8727-4GQSRZ
Company Name: Burlington Technologies Inc.
Notice Type: Instrument Decision
Notice Date: September 15, 2005
Proposal Date: February 22, 2000
Year: 2000
Proponent Address: 3267 Mainway, Burlington Ontario, L7M 1A6
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:

Location:

3267 Mainway Burlington Ontario L7M 1A6 Burlington

---

85 | ***7 of 11*** | ***WSW/248.1*** | ***123.8 / 0.04*** | ***Burlington Technologies Inc.***
3267 Mainway
Burlington ON L7M 1A6 | ***ECA***

Approval No: 2259-7S2S3L
Approval Type: ECA-AIR
Status: Approved
Approval Date: 2010-01-23
Record Type: ECA
Project Type: AIR
Link Source: IDS
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2549-7DSSQF-14.pdf

MOE District: Halton-Peel
SWP Area Name: Halton
Address: 3267 Mainway
City: Burlington
Longitude: -79.803314
Latitude: 43.364273

---

85 | ***8 of 11*** | ***WSW/248.1*** | ***123.8 / 0.04*** | ***Burlington Technologies Inc.***
3267 Mainway
Burlington ON L7M 1A6 | ***ECA***

Approval No: 4553-4KLPEH
Approval Type: ECA-AIR
Status: Revoked and/or Replaced
Approval Date: 2000-05-29
Record Type: ECA
Project Type: AIR
Link Source: IDS
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/8727-4GQSRZ-14.pdf

MOE District: Halton-Peel
SWP Area Name: Halton
Address: 3267 Mainway
City: Burlington
Longitude: -79.803314
Latitude: 43.364273

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
85	9 of 11	WSW/248.1	123.8 / 0.04	Burlington Technologies Inc. 3267 Mainway Burlington ON L7M 1A6	ECA

Approval No: 5263-63XRY7
Approval Type: ECA-AIR
Status: Revoked and/or Replaced
Approval Date: 2004-10-18
Record Type: ECA
Project Type: AIR
Link Source: IDS
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3153-5XCNPJ-14.pdf

MOE District: Halton-Peel
SWP Area Name: Halton
Address: 3267 Mainway
City: Burlington
Longitude: -79.803314
Latitude: 43.364273

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
85	10 of 11	WSW/248.1	123.8 / 0.04	Burlington Technologies Inc. 3267 Mainway Burlington ON L7M 1A6	ECA

Approval No: 1405-4JRQVP
Approval Type: ECA-AIR
Status: Approved
Approval Date: 2000-10-27
Record Type: ECA
Project Type: AIR
Link Source: IDS
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/8674-4E5Q8A-14.pdf

MOE District: Halton-Peel
SWP Area Name: Halton
Address: 3267 Mainway
City: Burlington
Longitude: -79.803314
Latitude: 43.364273

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
85	11 of 11	WSW/248.1	123.8 / 0.04	BURLINGTON TECHNOLOGIES INC. 3267 MAINWAY NOT AVAILABLE BURLINGTON ON L7M1A6	NPRI

NPRI ID: 3096
Other ID: Y
No Other ID: 1
Track ID: 92861
Report ID: 146913
Report Type: NPRI
Rpt Type ID: 1
Report Year: 2010
Not-Current Rpt?: No
Yr of Last Filed Rpt: 2010
Fac ID: 113721
Fac Name: BURLINGTON DIVISION
Fac Address1: 3267 MAINWAY
Fac Address2: NOT AVAILABLE
Fac Postal Zip: L7M1A6
Facility Lat: 43.3644
Facility Long: -79.8037
DLS (Last Filed Rpt):
Facility DLS:
Datum: 1983
Facility Cmnts: No
URL:
No of Empl.: 243
Parent Co.: Y
No Parent Co.: 1
Pollut Prev Cmnts: No
Stacks: No
No of Stacks:
Canadian SIC Code (2 digit):
Canadian SIC Code:

Org ID: 40258
Submit Date: 5/13/2011
Last Modified: 5/29/2015 3:28:24 PM
Contact ID: 181737
Cont Type: MED
Contact Title:
Cont First Name: MAC
Cont Last Name: WHITE
Contact Position: QA/ENG MANAGER
Contact Fax: 9053325122
Contact Ph.: 9053352742
Cont Area Code: 905
Contact Tel.: 53352742
Contact Ext.: 294
Cont Fax Area Cde: 905
Contact Fax: 53325122
Contact Email: MWHITE@BURLTECH.COM
Latitude: 43.3644
Longitude: -79.8037
UTM Zone:
UTM Northing:
UTM Easting:
Waste Streams: No
No Streams:
Waste Off Sites: Yes
No Off Sites: 2
Shutdown: No
No of Shutdown:

SIC Code Description:	
American SIC Code:	
NAICS Code (2 digit):	33
NAICS 2 Description:	Manufacturing
NAICS Code (4 digit):	3315
NAICS 4 Description:	Foundries
NAICS Code (6 digit):	331523
NAICS 6 Description:	Non-ferrous die-casting foundries

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	3.814
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	4.187
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Zinc (and its compounds)
Chem (fr):	Zinc (et ses composés)
Quantity:	.051
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Copper (and its compounds)
Chem (fr):	Cuivre (et ses composés)
Quantity:	.006
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

86	***1 of 2***	***N/248.4***	***125.8 / 2.07***	***HTM Sensors*** ***3419 Mainway*** ***Burlington ON L7M 1A9***	***SCT***

Established:	01-AUG-66

Plant Size (ft²):
Employment:

--Details--
Description: Electronic Components, Navigational and Communications Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417320

Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

---

86 | **2 of 2** | **N/248.4** | **125.8 / 2.07** | **TRANSPORT TRUCK**
DEC EXPRESS, 3419 MAINWAY TRANSPORT
TRUCK (CARGO)
BURLINGTON CITY ON L7M 1A9 | **SPL**

Ref No: 178097
Site No:
Incident Dt: 3/1/2000
Year:
Incident Cause: VALVE/FITTING LEAK OR FAILURE
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Contaminant Qty:
Environment Impact: POSSIBLE
Nature of Impact: Water course or lake
Receiving Medium: LAND / WATER
Receiving Env:
Health/Env Conseq:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/1/2000
Dt Document Closed:
SAC Action Class:
Incident Reason: DAMAGE BY MOVING EQUIPMENT
Incident Summary: TRANSPORT TRUCK (N.O.S.)- 568 L DIESEL FUEL TO LOT AND DRAIN/STORM SEWER.

Discharger Report:
Material Group:
Client Type:
Sector Type:
Source Type:
Nearest Watercourse:
Site Name:
Site Address:
Site District Office:
Site County/District:
Site Postal Code:
Site Region:
Site Municipality: 14101
Site Lot:
Site Conc:
Northing:
Easting: F/D
Site Geo Ref Accu:
Site Geo Ref Meth:
Site Map Datum:

---

87 | **1 of 24** | **W/251.3** | **124.8 / 1.07** | **3267 Mainway**
Burlington ON L7M 1A6 | **CA**

Certificate #: 4553-4KLPEH
Application Year: 00
Issue Date: 5/29/00
Approval Type: Industrial air
Status: Approved
Application Type: Amended CofA
Client Name:: Burlington Technologies Inc.
Client Address:: 3267 Mainway
Client City:: Burlington
Client Postal Code:: L7M 1A6
Project Description:: This is an application for an amendment to an air certificate of approval to allow for the venting of thirteen existing die cast machines via wall mounted exhausts.
Contaminants::
Emission Control::

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
87	2 of 24	W/251.3	124.8 / 1.07	BURLINGTON TECHNOLOGIES INC. 3267 MAINWAY BURLINGTON CITY ON L7M 1A6	CA

Certificate #:	8-3250-97-
Application Year:	97
Issue Date:	4/22/1998
Approval Type:	Industrial air
Status:	
Application Type:	
Client Name::	
Client Address::	
Client City::	
Client Postal Code::	
Project Description::	ADD AIR MAKE-UP UNIT
Contaminants::	
Emission Control::	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
87	3 of 24	W/251.3	124.8 / 1.07	Burlington Technologies Inc. 3267 Mainway Burlington ON L7M 1A6	CA

Certificate #:	5263-63XRY7
Application Year:	2004
Issue Date:	10/18/2004
Approval Type:	Air
Status:	Revoked and/or Replaced
Application Type:	
Client Name::	
Client Address::	
Client City::	
Client Postal Code::	
Project Description::	
Contaminants::	
Emission Control::	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
87	4 of 24	W/251.3	124.8 / 1.07	Burlington Technologies Inc. 3267 Mainway Burlington ON L7M 1A6	CA

Certificate #:	2259-7S2S3L
Application Year:	2010
Issue Date:	1/23/2010
Approval Type:	Air
Status:	Approved
Application Type:	
Client Name::	
Client Address::	
Client City::	
Client Postal Code::	
Project Description::	
Contaminants::	
Emission Control::	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
87	5 of 24	W/251.3	124.8 / 1.07	3267 Mainway Burlington ON L7M 1A6	CA

Certificate #:	1405-4JRQVP
Application Year:	00
Issue Date:	10/27/00

Approval Type:	Industrial air
Status:	Approved
Application Type:	New Certificate of Approval
Client Name::	Burlington Technologies Inc.
Client Address::	3267 Mainway
Client City::	Burlington
Client Postal Code::	L7M 1A6
Project Description::	This application is for: 1. an exhaust venting from the tool room where dies are steam cleaned prior to re-use; and 2. an additional roof top exhaust venting one of the existing die cast units.
Contaminants::	
Emission Control::	

---

87 **6 of 24** **W/251.3** **124.8 / 1.07** **3267 Mainway**
Burlington ON L7M1A6 **EHS**

Order ID:	511733	**Date Received:**	24-APR-17
Order No:	20170424007	**Lot/Building Size:**	
Customer ID:	140269	**Municipality:**	
Company ID:	77	**Client Prov/State:**	ON
Status:	C	**Search Radius (km):**	.25
Report Code:	3CAN	**Large Radius:**	.35
Report Type:	Standard Report	**X:**	-79.803879
Report Date:	27-APR-17	**Y:**	43.365006
Report Requested by:	Pinchin Ltd.		
Nearest Intersection:			
Previous Site Name:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

---

87 **7 of 24** **W/251.3** **124.8 / 1.07** **3267 Mainway**
Burlington ON L7M 1A6 **EHS**

Order ID:	163909	**Date Received:**	4/23/2009
Order No:	20090423015	**Lot/Building Size:**	
Customer ID:	65667	**Municipality:**	
Company ID:	44305	**Client Prov/State:**	ON
Status:	C	**Search Radius (km):**	0.25
Report Code:	3CAN	**Large Radius:**	2
Report Type:	Standard Report	**X:**	-79.803945
Report Date:	5/4/2009	**Y:**	43.364862
Report Requested by:	ENVIRON EC (CANADA) Inc.		
Nearest Intersection:			
Previous Site Name:			
Additional Info Ordered:			

---

87 **8 of 24** **W/251.3** **124.8 / 1.07** **3267 Mainway Drive**
Burlington ON L7M 1A6 **EHS**

Order ID:	201899	**Date Received:**	2/7/2012 10:01:32 AM
Order No:	20120207005	**Lot/Building Size:**	27000m2
Customer ID:	90053	**Municipality:**	City of Burlington
Company ID:	44305	**Client Prov/State:**	ON
Status:	C	**Search Radius (km):**	0.25
Report Code:	3CAN	**Large Radius:**	2
Report Type:	Standard Report	**X:**	-79.804199
Report Date:	2/15/2012 10:03:34 AM	**Y:**	43.364866
Report Requested by:	ENVIRON EC (CANADA) Inc.		
Nearest Intersection:			
Previous Site Name:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans;		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
87	9 of 24	W/251.3	124.8 / 1.07	REVSTONE INDUSTRIES BURLINGTON INC. 3267 MAINWAY BURLINGTON ON L7M 1A6	GEN

Generator No.: ON0923500
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 331523
SIC Description: Non-Ferrous Die-Casting Foundries

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 253
Waste Description: EMULSIFIED OILS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
87	10 of 24	W/251.3	124.8 / 1.07	REVSTONE INDUSTRIES BURLINGTON INC. 3267 MAINWAY BURLINGTON ON L7M 1A6	GEN

Generator No.: ON0923500
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 331523
SIC Description: Non-Ferrous Die-Casting Foundries

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 253
Waste Description: EMULSIFIED OILS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

---

87 **11 of 24** **W/251.3** **124.8 / 1.07** **NATIONAL RIGGING & TRANSPORTATION LTD.** **GEN**
3267 MAINWAY DR.
BURLINGTON ON

Generator No.: ON3888426
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 493190
SIC Description: Other Warehousing and Storage

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

---

87 **12 of 24** **W/251.3** **124.8 / 1.07** **BURLINGTON TECHNOLOGIES 06-271** **GEN**
BURLINGTON DIVISION 3267 MAINWAY
BURLINGTON ON L7M 1A6

Generator No.: ON0923500
Status:
Approval Years: 94,95,96
Contam. Facility:
MHSW Facility:
SIC Code: 2961
SIC Description: ALUMINUM ROLL., ETC.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

---

87 **13 of 24** **W/251.3** **124.8 / 1.07** **BURLINGTON TECHNOLOGIESINCORPORATED** **GEN**
3267 MAINWAY
BURLINGTON ON L7M 1A6

Generator No.: ON0923500
Status:
Approval Years: 99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 2961

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

SIC Description: ALUMINUM ROLL., ETC.

--Details--
Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

87 | ***14 of 24*** | ***W/251.3*** | ***124.8 / 1.07*** | ***BURLINGTON DIE CASTING***
3267 MAINWAY
BURLINGTON ON L7M 1A6 | ***GEN***

Generator No.: ON0923500
Status:
Approval Years: 86,87,88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 2961
SIC Description: ALUMINUM ROLL., ETC.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

87 | ***15 of 24*** | ***W/251.3*** | ***124.8 / 1.07*** | ***REVSTONE INDUSTRIES BURLINGTON INC.***
3267 MAINWAY
BURLINGTON ON L7M 1A6 | ***GEN***

Generator No.: ON0923500
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 331523
SIC Description: Non-Ferrous Die-Casting Foundries

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 213

Waste Description: PETROLEUM DISTILLATES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

87 ***16 of 24*** ***W/251.3*** ***124.8 / 1.07*** ***BURLINGTON TECHNOLOGIES INCORPORATED 3267 MAINWAY BURLINGTON ON L7M 1A6*** ***GEN***

Generator No.: ON0923500
Status:
Approval Years: 02,03,04,05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

87 ***17 of 24*** ***W/251.3*** ***124.8 / 1.07*** ***BURLINGTON TECHNOLOGIES 3267 MAINWAY BURLINGTON DIVISION BURLINGTON ON L7M 1A6*** ***GEN***

Generator No.: ON0923500
Status:
Approval Years: 92,93,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 2961
SIC Description: ALUMINUM ROLL., ETC.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 146
Waste Description: OTHER SPECIFIED INORGANICS

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

87 | **18 of 24** | **W/251.3** | **124.8 / 1.07** | **REVSTONE INDUSTRIES BURLINGTON INC.**
3267 MAINWAY
BURLINGTON ON L7M 1A6 | **GEN**

Generator No.: ON0923500
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 331523
SIC Description: Non-Ferrous Die-Casting Foundries

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 122
Waste Description: ALKALINE WASTES - OTHER METALS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 212
Waste Description: ALIPHATIC SOLVENTS

Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

87 | **19 of 24** | **W/251.3** | **124.8 / 1.07** | **BURLINGTON TECHNOLOGIES INC. -**
3267 MAINWAY DR
BURLINGTON ON L7M 1A6 | **SCT**

Established: 1965
Plant Size (ft²): 0
Employment: 250

--Details--
Description: Non-Ferrous Foundries (except Die-Casting)
SIC/NAICS Code: 331529

Description: Industrial Mould Manufacturing
SIC/NAICS Code: 333511

Description: Other Metalworking Machinery Manufacturing
SIC/NAICS Code: 333519

Description: Automobile and Light-Duty Motor Vehicle Manufacturing
SIC/NAICS Code: 336110

Description: Heavy-Duty Truck Manufacturing
SIC/NAICS Code: 336120

---

87 | **20 of 24** | **W/251.3** | **124.8 / 1.07** | **Burlington Technologies Indus**
3267 Mainway
Burlington ON L7M 1A6 | **SCT**

Established: 01-JUN-65
Plant Size (ft²): 150000
Employment:

--Details--
Description: Other Motor Vehicle Parts Manufacturing
SIC/NAICS Code: 336390

Description: Machine Shops
SIC/NAICS Code: 332710

Description: Heavy-Duty Truck Manufacturing
SIC/NAICS Code: 336120

Description: Motor Vehicle Brake System Manufacturing
SIC/NAICS Code: 336340

Description: Non-Ferrous Die-Casting Foundries
SIC/NAICS Code: 331523

Description: Motor Vehicle Steering and Suspension Components (except Spring) Manufacturing
SIC/NAICS Code: 336330

Description: Automobile and Light-Duty Motor Vehicle Manufacturing
SIC/NAICS Code: 336110

Description: Motor Vehicle Gasoline Engine and Engine Parts Manufacturing
SIC/NAICS Code: 336310

Description: Motor Vehicle Transmission and Power Train Parts Manufacturing
SIC/NAICS Code: 336350

---

87 | **21 of 24** | **W/251.3** | **124.8 / 1.07** | **BURLINGTON TECHNOLOGIES INC.**
3267 MAINWAY DR
BURLINGTON ON L7M 1A6 | **SCT**

Established: 1965
Plant Size (ft²): 0
Employment: 250

--Details--
Description: ALUMINUM FOUNDRIES
SIC/NAICS Code: 3365

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: SPECIAL DIES AND TOOLS, DIE SETS, JIGS AND FIXTURES, AND INDUSTRIAL MOLDS
SIC/NAICS Code: 3544

Description: MOTOR VEHICLE PARTS AND ACCESSORIES
SIC/NAICS Code: 3714

---

87 | **22 of 24** | **W/251.3** | **124.8 / 1.07** | **Burlington Technologies Inc. - Burlington Division**
3267 Mainway Dr
Burlington ON L7M 1A6 | **SCT**

Established: 1965
Plant Size (ft²):
Employment: 300

--Details--
Description: All Other Miscellaneous Fabricated Metal Product Manufacturing
SIC/NAICS Code: 332999

Description: Motor Vehicle Steering and Suspension Components (except Spring) Manufacturing
SIC/NAICS Code: 336330

Description: Motor Vehicle Brake System Manufacturing
SIC/NAICS Code: 336340

Description: Other Motor Vehicle Parts Manufacturing
SIC/NAICS Code: 336390

Description: Non-Ferrous Die-Casting Foundries
SIC/NAICS Code: 331523

Description: Machine Shops
SIC/NAICS Code: 332710

Description: Non-Ferrous Foundries (except Die-Casting)
SIC/NAICS Code: 331529

Description: Automobile and Light-Duty Motor Vehicle Manufacturing
SIC/NAICS Code: 336110

---

87 | **23 of 24** | **W/251.3** | **124.8 / 1.07** | **Burlington Technologies Inc.**
3267 Mainway
Burlington ON L7M 1A6 | **SPL**

Ref No:	7805-658SNH	**Discharger Report:**	
Site No:		**Material Group:**	OIL
Incident Dt:	9/27/2004	**Client Type:**	
Year:		**Sector Type:**	
Incident Cause:		**Source Type:**	
Incident Event:		**Nearest Watercourse:**	
Contaminant Code:		**Site Name:**	3267 MAINWAY
Contaminant Name:	OIL (PETROLEUM BASED, NOT SPECIFIED)	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	Halton-Peel
Contam Limit Freq 1:		**Site County/District:**	
Contaminant UN No 1:		**Site Postal Code:**	
Contaminant Qty:		**Site Region:**	Central
Environment Impact:		**Site Municipality:**	Burlington
Nature of Impact:		**Site Lot:**	
Receiving Medium:	Water	**Site Conc:**	
Receiving Env:		**Northing:**	NA
Health/Env Conseq:		**Easting:**	NA

MOE Response:		**Site Geo Ref Accu:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Meth:**	
MOE Reported Dt:	9/27/2004	**Site Map Datum:**	
Dt Document Closed:			
SAC Action Class:			
Incident Reason:			
Incident Summary:	Burlington Technologies: cutting oil to creek		

---

87 | **24 of 24** | **W/251.3** | **124.8 / 1.07** | **Burlington Technologies Inc.**
3267 Mainway
Burlington ON L7M 1A6 | **SPL**

Ref No:	4307-6FUG9D	**Discharger Report:**	0
Site No:		**Material Group:**	Oil
Incident Dt:	8/29/2005	**Client Type:**	
Year:		**Sector Type:**	Other Plant
Incident Cause:		**Source Type:**	
Incident Event:		**Nearest Watercourse:**	
Contaminant Code:		**Site Name:**	Burlington Technologies Inc.<UNOFFICIAL>
Contaminant Name:	HYDRAULIC OIL	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	Halton-Peel
Contam Limit Freq 1:		**Site County/District:**	
Contaminant UN No 1:		**Site Postal Code:**	
Contaminant Qty:		**Site Region:**	
Environment Impact:	Possible	**Site Municipality:**	Burlington
Nature of Impact:	Surface Water Pollution	**Site Lot:**	
Receiving Medium:	Water	**Site Conc:**	
Receiving Env:		**Northing:**	
Health/Env Conseq:		**Easting:**	
MOE Response:		**Site Geo Ref Accu:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Meth:**	
MOE Reported Dt:	9/2/2005	**Site Map Datum:**	
Dt Document Closed:			
SAC Action Class:	Spills to Land		
Incident Reason:			
Incident Summary:	Burlington Tech: 20 L to onsite CB, clned, 2005/08/29		

---

88 | **1 of 1** | **NNE/253.4** | **125.8 / 2.07** | **NELSON BUSINESS MACHINES LTD.**
3460 MAINWAY DR
BURLINGTON ON L7M 1A8 | **SCT**

Established:	1954
Plant Size (ft²):	10000
Employment:	27

--Details--

Description:	ELECTRONIC COMPUTERS
SIC/NAICS Code:	3571
Description:	COMPUTERS & COMPUTER PERIPHERAL EQUIPMENT & SOFTWARE
SIC/NAICS Code:	5045

---

89 | **1 of 1** | **SW/255.5** | **122.7 / -1.13** | **BURLINGTON ON** | **WWIS**

Well ID:	7044262	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Livestock	**Date Received:**	5/28/2007
Sec. Water Use:	Not Used	**Selected Flag:**	1
Final Well Status:	Observation Wells	**Abandonment Rec:**	

Water Type:		***Contractor:***	6032
Casing Material:		***Form Version:***	3
Audit No:	Z66439	***Owner:***	
Tag:	A005237	***Street Name:***	3230 MAINWAY
Construction Method:		***County:***	HALTON
Elevation (m):		***Municipality:***	BURLINGTON CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	11766696	***Spatial Status:***	
DP2BR:	8	***Cluster Kind:***	
Code OB:	r	***UTMRC:***	3
Code OB Desc:	Bedrock	***UTMRC Desc:***	margin of error : 10 - 30 m
Open Hole:		***Location Method:***	wwr
Elevation:	123.154495	***Org CS:***	UTM83
Elevrc:		***Date Completed:***	5/3/2007
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	933102425
Layer:	1
Color:	2
General Color:	GREY
Mat1:	
Most Common Material:	
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0.00
Formation End Depth:	0.20
Formation End Depth UOM:	m

Formation ID:	933102426
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Other Materials:	GRAVEL
Mat3:	
Other Materials:	
Formation Top Depth:	0.20
Formation End Depth:	0.80
Formation End Depth UOM:	m

Formation ID:	933102427
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	05
Most Common Material:	CLAY
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0.80
Formation End Depth:	2.40
Formation End Depth UOM:	m

Formation ID:	933102428
Layer:	4
Color:	7
General Color:	RED
Mat1:	26
Most Common Material:	ROCK
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	2.40
Formation End Depth:	4.60
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933319899
Layer:	1
Plug From:	0.00
Plug To:	0.30
Plug Depth UOM:	m

Plug ID:	933319900
Layer:	2
Plug From:	0.30
Plug To:	1.00
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	967044262
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	11774386
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930900027
Layer:	1

Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.00
Depth To:	1.50
Casing Diameter:	5.00
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	933424674
Layer:	1
Slot:	10
Screen Top Depth:	1.50
Screen End Depth:	4.60
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.00

Hole Diameter

Hole ID:	11853266
Diameter:	10.00
Depth From:	0.00
Depth To:	4.60
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

90 | ***1 of 1*** | ***NW/255.8*** | ***126.8 / 3.07*** | ***Feed Rite Automation inc.***
3325A Mainway
Burlington ON L7M 1A6 | ***SCT***

Established:	01-JUL-98
Plant Size (ft²):	
Employment:	

--Details--

Description:	Material Handling Equipment Manufacturing
SIC/NAICS Code:	333920
Description:	Other Plate Work and Fabricated Structural Product Manufacturing
SIC/NAICS Code:	332319
Description:	Cutlery and Hand Tool Manufacturing
SIC/NAICS Code:	332210
Description:	All Other General-Purpose Machinery Manufacturing
SIC/NAICS Code:	333990
Description:	Rubber and Plastic Hose and Belting Manufacturing
SIC/NAICS Code:	326220

---

91 | ***1 of 1*** | ***W/256.1*** | ***124.8 / 1.07*** | ***ON*** | ***WWIS***

Well ID:	7270750	**Data Entry Status:**	Date Entry is incomplete
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	9/8/2016
Sec. Water Use:		**Selected Flag:**	1
Final Well Status:		**Abandonment Rec:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Water Type:		**Contractor:**	7251
Casing Material:		**Form Version:**	8
Audit No:	C34240	**Owner:**	
Tag:	A206661	**Street Name:**	
Construction Method:		**County:**	HALTON
Elevation (m):		**Municipality:**	BURLINGTON CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1006234736	**Spatial Status:**	
DP2BR:		**Cluster Kind:**	
Code OB:		**UTMRC:**	4
Code OB Desc:		**UTMRC Desc:**	margin of error : 30 m - 100 m
Open Hole:		**Location Method:**	wwr
Elevation:	125.174133	**Org CS:**	UTM83
Elevrc:		**Date Completed:**	8/11/2016
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

92	1 of 10	WSW/259.4	123.5 / -0.29	***HOWELL PACKAGING LIMITED*** ***3230 MAINWAY AVENUE NOT AVAILABLE*** ***BURLINGTON ON L7M 1A5***	NPRI

NPRI ID:	400	**Org ID:**	13799
Other ID:		**Submit Date:**	
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	1280	**Contact ID:**	
Report ID:		**Cont Type:**	
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	1993	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2002	**Contact Fax:**	
Fac ID:	106212	**Contact Ph.:**	
Fac Name:	NOT AVAILABLE	**Cont Area Code:**	
Fac Address1:	3230 MAINWAY AVENUE	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	L7M 1A5	**Cont Fax Area Cde:**	
Facility Lat:		**Contact Fax:**	
Facility Long:		**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.364
Facility DLS:		**Longitude:**	-79.8051
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:		**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	

No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3222		
NAICS 4 Description:	Converted paper product manufacturing		
NAICS Code (6 digit):	322212		
NAICS 6 Description:	Folding paperboard box manufacturing		

Substance Release Report

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	
Chem (fr):	
Quantity:	22.56
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	7
Category Type Desc:	Direct Discharges
Category Type Desc (fr):	Évacuation directes
Grouping:	Total Water
Trans Code:	WatD
Chem:	
Chem (fr):	
Quantity:	.44
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

---

92 **2 of 10** **WSW/259.4** **123.5 / -0.29** ***HOWELL PACKAGING LIMITED***
3230 MAINWAY AVENUE NOT AVAILABLE
BURLINGTON ON L7M 1A5 ***NPRI***

NPRI ID:	400	**Org ID:**	13799
Other ID:	Y	**Submit Date:**	5/15/2001
No Other ID:	1.00	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	1277	**Contact ID:**	80490
Report ID:		**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	CHRIS
Report Year:	2000	**Cont Last Name:**	WOODS
Not-Current Rpt?:	No	**Contact Position:**	V. P. AND GENERAL MANAGER
Yr of Last Filed Rpt:	2002	**Contact Fax:**	9053357092
Fac ID:	106212	**Contact Ph.:**	9053350050
Fac Name:	NOT AVAILABLE	**Cont Area Code:**	905
Fac Address1:	3230 MAINWAY AVENUE	**Contact Tel.:**	53350050
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	L7M 1A5	**Cont Fax Area Cde:**	905
Facility Lat:		**Contact Fax:**	53357092
Facility Long:		**Contact Email:**	NOT AVAILABLE
DLS (Last Filed Rpt):		**Latitude:**	43.364
Facility DLS:		**Longitude:**	-79.8051
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:		**UTM Easting:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

No of Empl.:	158	**Waste Streams:**	No
Parent Co.:	Y	**No Streams:**	0
No Parent Co.:	1.00	**Waste Off Sites:**	Yes
Pollut Prev Cmnts:	False	**No Off Sites:**	1.00
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3222		
NAICS 4 Description:	Converted paper product manufacturing		
NAICS Code (6 digit):	322212		
NAICS 6 Description:	Folding paperboard box manufacturing		

Substance Release Report

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	Methyl ethyl ketone
Chem (fr):	Méthyléthylcétone
Quantity:	20.701
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	Isopropyl alcohol
Chem (fr):	Alcool iso-propylique
Quantity:	17.227
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

92	*3 of 10*	*WSW/259.4*	*123.5 / -0.29*	***HOWELL PACKAGING LIMITED*** ***3230 MAINWAY AVENUE NOT AVAILABLE*** ***BURLINGTON ON L7M 1A5***	*NPRI*

NPRI ID:	400	**Org ID:**	13799
Other ID:	Y	**Submit Date:**	9/26/2001
No Other ID:	2	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	1274	**Contact ID:**	75716
Report ID:		**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	ALAN
Report Year:	1995	**Cont Last Name:**	BUTLER
Not-Current Rpt?:	No	**Contact Position:**	NOT AVAILABLE
Yr of Last Filed Rpt:	2002	**Contact Fax:**	9053357092
Fac ID:	106212	**Contact Ph.:**	9053350050
Fac Name:	NOT AVAILABLE	**Cont Area Code:**	905
Fac Address1:	3230 MAINWAY AVENUE	**Contact Tel.:**	53350050
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	209
Fac Postal Zip:	L7M 1A5	**Cont Fax Area Cde:**	905
Facility Lat:		**Contact Fax:**	53357092
Facility Long:		**Contact Email:**	NOT AVAILABLE

DLS (Last Filed Rpt):		***Latitude:***	43.364
Facility DLS:		***Longitude:***	-79.8051
Datum:	1983	***UTM Zone:***	17
Facility Cmnts:	FALSE	***UTM Northing:***	4801700
URL:		***UTM Easting:***	596800
No of Empl.:	158	***Waste Streams:***	FALSE
Parent Co.:	Y	***No Streams:***	0
No Parent Co.:	1	***Waste Off Sites:***	TRUE
Pollut Prev Cmnts:	FALSE	***No Off Sites:***	2
Stacks:		***Shutdown:***	
No of Stacks:		***No of Shutdown:***	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3222		
NAICS 4 Description:	Converted paper product manufacturing		
NAICS Code (6 digit):	322212		
NAICS 6 Description:	Folding paperboard box manufacturing		

Substance Release Report

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	Methyl ethyl ketone
Chem (fr):	Méthyléthylcétone
Quantity:	7.795
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	Isopropyl alcohol
Chem (fr):	Alcool iso-propylique
Quantity:	6.89
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

---

92 ***4 of 10*** ***WSW/259.4*** ***123.5 / -0.29*** ***HOWELL PACKAGING LIMITED***
3230 MAINWAY AVENUE NOT AVAILABLE
BURLINGTON ON L7M 1A5 ***NPRI***

NPRI ID:	400	***Org ID:***	13799
Other ID:	Y	***Submit Date:***	5/14/1999
No Other ID:	1	***Last Modified:***	5/29/2015 3:28:24 PM
Track ID:	1282	***Contact ID:***	110577
Report ID:		***Cont Type:***	MED
Report Type:	NPRI	***Contact Title:***	
Rpt Type ID:	1	***Cont First Name:***	TOM
Report Year:	1998	***Cont Last Name:***	FREY
Not-Current Rpt?:	No	***Contact Position:***	DIRECTOR OF MANUFACTURING OPER
Yr of Last Filed Rpt:	2002	***Contact Fax:***	9053357092
Fac ID:	106212	***Contact Ph.:***	9053350050
Fac Name:	NOT AVAILABLE	***Cont Area Code:***	905

Fac Address1:	3230 MAINWAY AVENUE	**Contact Tel.:**	53350050
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	L7M 1A5	**Cont Fax Area Cde:**	905
Facility Lat:		**Contact Fax:**	53357092
Facility Long:		**Contact Email:**	NOT AVAILABLE
DLS (Last Filed Rpt):		**Latitude:**	43.364
Facility DLS:		**Longitude:**	-79.8051
Datum:	1983	**UTM Zone:**	17
Facility Cmnts:	False	**UTM Northing:**	4801700
URL:		**UTM Easting:**	596800
No of Empl.:	158	**Waste Streams:**	False
Parent Co.:	Y	**No Streams:**	0
No Parent Co.:	1	**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	False	**No Off Sites:**	1
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3222		
NAICS 4 Description:	Converted paper product manufacturing		
NAICS Code (6 digit):	322212		
NAICS 6 Description:	Folding paperboard box manufacturing		

Substance Release Report

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	Methyl ethyl ketone
Chem (fr):	Méthyl éthyl cétone
Quantity:	10.974
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	Isopropyl alcohol
Chem (fr):	Alcool isopropylique
Quantity:	18.4
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

---

92 **5 of 10** **WSW/259.4** **123.5 / -0.29** **HOWELL PACKAGING**
3230 MAINWAY AVENUE NOT AVAILABLE
BURLINGTON ON L7M 1A5 **NPRI**

NPRI ID:	400	**Org ID:**	13792
Other ID:	Y	**Submit Date:**	7/11/1997
No Other ID:	2	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	1275	**Contact ID:**	80493
Report ID:		**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	CHRIS

Report Year:	1996	**Cont Last Name:**	WOODS
Not-Current Rpt?:	No	**Contact Position:**	VICE PRESIDENT / SALES MANAGER
Yr of Last Filed Rpt:	2002	**Contact Fax:**	9053357092
Fac ID:	37621	**Contact Ph.:**	9053350050
Fac Name:	MAINWAY PLANT	**Cont Area Code:**	905
Fac Address1:	3230 MAINWAY AVENUE	**Contact Tel.:**	53350050
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	208
Fac Postal Zip:	L7M 1A5	**Cont Fax Area Cde:**	905
Facility Lat:	43.364	**Contact Fax:**	53357092
Facility Long:	-79.8051	**Contact Email:**	NOT AVAILABLE
DLS (Last Filed Rpt):		**Latitude:**	43.364
Facility DLS:		**Longitude:**	-79.8051
Datum:	1983	**UTM Zone:**	17
Facility Cmnts:	TRUE	**UTM Northing:**	4801700
URL:		**UTM Easting:**	596800
No of Empl.:	160	**Waste Streams:**	FALSE
Parent Co.:	Y	**No Streams:**	0
No Parent Co.:	1	**Waste Off Sites:**	TRUE
Pollut Prev Cmnts:	FALSE	**No Off Sites:**	1
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3222		
NAICS 4 Description:	Converted paper product manufacturing		
NAICS Code (6 digit):	322212		
NAICS 6 Description:	Folding paperboard box manufacturing		

Substance Release Report

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	Methyl ethyl ketone
Chem (fr):	Méthyléthylcétone
Quantity:	6.486
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

---

92 | ***6 of 10*** | ***WSW/259.4*** | ***123.5 / -0.29*** | ***HOWELL PACKAGING LIMITED 3230 MAINWAY AVENUE NOT AVAILABLE BURLINGTON ON L7M 1A5*** | ***NPRI***

NPRI ID:	400	**Org ID:**	13799
Other ID:	TRUE	**Submit Date:**	
No Other ID:	2	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	1279	**Contact ID:**	75834
Report ID:		**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	ALAN T.
Report Year:	1994	**Cont Last Name:**	BUTLER
Not-Current Rpt?:	No	**Contact Position:**	NOT AVAILABLE
Yr of Last Filed Rpt:	2002	**Contact Fax:**	9053357092
Fac ID:	106212	**Contact Ph.:**	9053350050
Fac Name:	NOT AVAILABLE	**Cont Area Code:**	905
Fac Address1:	3230 MAINWAY AVENUE	**Contact Tel.:**	53350050
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	208

Fac Postal Zip:	L7M 1A5	***Cont Fax Area Cde:***	905
Facility Lat:		***Contact Fax:***	53357092
Facility Long:		***Contact Email:***	NOT AVAILABLE
DLS (Last Filed Rpt):		***Latitude:***	43.364
Facility DLS:		***Longitude:***	-79.8051
Datum:	1983	***UTM Zone:***	17
Facility Cmnts:	FALSE	***UTM Northing:***	4801700
URL:		***UTM Easting:***	596800
No of Empl.:	160	***Waste Streams:***	FALSE
Parent Co.:	TRUE	***No Streams:***	1
No Parent Co.:	1	***Waste Off Sites:***	TRUE
Pollut Prev Cmnts:		***No Off Sites:***	2
Stacks:		***Shutdown:***	
No of Stacks:		***No of Shutdown:***	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3222		
NAICS 4 Description:	Converted paper product manufacturing		
NAICS Code (6 digit):	322212		
NAICS 6 Description:	Folding paperboard box manufacturing		

Substance Release Report

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	Isopropyl alcohol
Chem (fr):	Alcool iso-propylique
Quantity:	35.724
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	Methyl ethyl ketone
Chem (fr):	Méthyléthylcétone
Quantity:	7.109
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

Category Type ID:	7
Category Type Desc:	Direct Discharges
Category Type Desc (fr):	Évacuation directes
Grouping:	Total Water
Trans Code:	WatD
Chem:	Isopropyl alcohol
Chem (fr):	Alcool iso-propylique
Quantity:	.44
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
92	7 of 10	WSW/259.4	123.5 / -0.29	HOWELL PACKAGING LIMITED 3230 MAINWAY AVENUE NOT AVAILABLE BURLINGTON ON L7M 1A5	NPRI

NPRI ID:	400	**Org ID:**	13799
Other ID:	*	**Submit Date:**	8/4/1998
No Other ID:	0	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	1278	**Contact ID:**	110577
Report ID:		**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	TOM
Report Year:	1997	**Cont Last Name:**	FREY
Not-Current Rpt?:	No	**Contact Position:**	DIRECTOR OF MANUFACTURING OPER
Yr of Last Filed Rpt:	2002	**Contact Fax:**	9053357092
Fac ID:	106212	**Contact Ph.:**	9053350050
Fac Name:	NOT AVAILABLE	**Cont Area Code:**	905
Fac Address1:	3230 MAINWAY AVENUE	**Contact Tel.:**	53350050
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	L7M 1A5	**Cont Fax Area Cde:**	905
Facility Lat:		**Contact Fax:**	53357092
Facility Long:		**Contact Email:**	NOT AVAILABLE
DLS (Last Filed Rpt):		**Latitude:**	43.364
Facility DLS:		**Longitude:**	-79.8051
Datum:	1983	**UTM Zone:**	17
Facility Cmnts:	FALSE	**UTM Northing:**	4801700
URL:		**UTM Easting:**	596800
No of Empl.:	158	**Waste Streams:**	FALSE
Parent Co.:	Y	**No Streams:**	0
No Parent Co.:	1	**Waste Off Sites:**	TRUE
Pollut Prev Cmnts:	FALSE	**No Off Sites:**	1
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3222		
NAICS 4 Description:	Converted paper product manufacturing		
NAICS Code (6 digit):	322212		
NAICS 6 Description:	Folding paperboard box manufacturing		

Substance Release Report

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	Isopropyl alcohol
Chem (fr):	Alcool isopropylique
Quantity:	11.768
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	Methyl ethyl ketone
Chem (fr):	Méthyléthylcétone
Quantity:	9.317

Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

92 | **8 of 10** | **WSW/259.4** | **123.5 / -0.29** | **DOVER PACKAGING LIMITED (FORMERLY HOWELL PACKAGING LIMITED)**
3230 MAINWAY AVENUE NOT AVAILABLE
BURLINGTON ON L7M 1A5 | **NPRI**

NPRI ID:	400	**Org ID:**	45994
Other ID:	Y	**Submit Date:**	5/28/2002
No Other ID:	1.00	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	1276	**Contact ID:**	80491
Report ID:		**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	CHRIS
Report Year:	2001	**Cont Last Name:**	WOODS
Not-Current Rpt?:	No	**Contact Position:**	V.P. AND GENERAL MANAGER
Yr of Last Filed Rpt:	2002	**Contact Fax:**	9053357092
Fac ID:	106212	**Contact Ph.:**	9053350050
Fac Name:	NOT AVAILABLE	**Cont Area Code:**	905
Fac Address1:	3230 MAINWAY AVENUE	**Contact Tel.:**	53350050
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	L7M 1A5	**Cont Fax Area Cde:**	905
Facility Lat:		**Contact Fax:**	53357092
Facility Long:		**Contact Email:**	CWOODS@DOVERGRP.COM
DLS (Last Filed Rpt):		**Latitude:**	43.364
Facility DLS:		**Longitude:**	-79.8051
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	No	**UTM Northing:**	
URL:	dovergrp.com.	**UTM Easting:**	
No of Empl.:	150	**Waste Streams:**	No
Parent Co.:	Y	**No Streams:**	0.00
No Parent Co.:	1.00	**Waste Off Sites:**	Yes
Pollut Prev Cmnts:	No	**No Off Sites:**	1.00
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3222		
NAICS 4 Description:	Converted paper product manufacturing		
NAICS Code (6 digit):	322212		
NAICS 6 Description:	Folding paperboard box manufacturing		

Substance Release Report

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	Methyl ethyl ketone
Chem (fr):	Méthyléthylcétone
Quantity:	23.4
Unit:	tonnes
Basis of Estimate Cd:	M
Basis of Estimate Desc:	M- Monitoring or Direct Measurement - In use from 1994 to 2002

Category Type ID:	3
Category Type Desc:	Fugitive

Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	Isopropyl alcohol
Chem (fr):	Alcool iso-propylique
Quantity:	27.8
Unit:	tonnes
Basis of Estimate Cd:	M
Basis of Estimate Desc:	M- Monitoring or Direct Measurement - In use from 1994 to 2002

92 | **9 of 10** | **WSW/259.4** | **123.5 / -0.29** | **HOWELL PACKAGING LIMITED**
3230 MAINWAY AVENUE NOT AVAILABLE
BURLINGTON ON L7M 1A5 | **NPRI**

NPRI ID:	400	**Org ID:**	13799
Other ID:	Y	**Submit Date:**	5/26/2000
No Other ID:	1	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	1281	**Contact ID:**	80490
Report ID:		**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	CHRIS
Report Year:	1999	**Cont Last Name:**	WOODS
Not-Current Rpt?:	No	**Contact Position:**	V. P. AND GENERAL MANAGER
Yr of Last Filed Rpt:	2002	**Contact Fax:**	9053357092
Fac ID:	106212	**Contact Ph.:**	9053350050
Fac Name:	NOT AVAILABLE	**Cont Area Code:**	905
Fac Address1:	3230 MAINWAY AVENUE	**Contact Tel.:**	53350050
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	L7M 1A5	**Cont Fax Area Cde:**	905
Facility Lat:		**Contact Fax:**	53357092
Facility Long:		**Contact Email:**	NOT AVAILABLE
DLS (Last Filed Rpt):		**Latitude:**	43.364
Facility DLS:		**Longitude:**	-79.8051
Datum:	1983	**UTM Zone:**	17
Facility Cmnts:	False	**UTM Northing:**	4801700
URL:		**UTM Easting:**	596800
No of Empl.:	158	**Waste Streams:**	Yes
Parent Co.:	Y	**No Streams:**	0
No Parent Co.:	1	**Waste Off Sites:**	Yes
Pollut Prev Cmnts:	False	**No Off Sites:**	0
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3222		
NAICS 4 Description:	Converted paper product manufacturing		
NAICS Code (6 digit):	322212		
NAICS 6 Description:	Folding paperboard box manufacturing		

Substance Release Report

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	Isopropyl alcohol
Chem (fr):	Alcool iso-propylique
Quantity:	20.5
Unit:	tonnes

Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance
Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	Methyl ethyl ketone
Chem (fr):	Méthyléthylcétone
Quantity:	15.034
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

92 **10 of 10** **WSW/259.4** **123.5 / -0.29** **Burlington ON** **WWIS**

Well ID:	7108681	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring	**Date Received:**	7/25/2008
Sec. Water Use:		**Selected Flag:**	1
Final Well Status:	0	**Abandonment Rec:**	
Water Type:		**Contractor:**	7282
Casing Material:		**Form Version:**	5
Audit No:	M03101	**Owner:**	
Tag:	A055816	**Street Name:**	3230 MAINWAY RD.
Construction Method:		**County:**	HALTON
Elevation (m):		**Municipality:**	BURLINGTON CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1002677212	**Spatial Status:**	
DP2BR:		**Cluster Kind:**	This is a record from cluster log sheet
Code OB:		**UTMRC:**	3
Code OB Desc:		**UTMRC Desc:**	margin of error : 10 - 30 m
Open Hole:		**Location Method:**	wwr
Elevation:	122.312248	**Org CS:**	UTM83
Elevrc:		**Date Completed:**	6/20/2008
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002677216
Layer:	
Plug From:	
Plug To:	

Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002677215
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1002677217
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002677219
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 6.00
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002677218
Layer:
Slot:
Screen Top Depth: 6.00
Screen End Depth: 9.10
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002677220
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002677214
Diameter: 20.90
Depth From:
Depth To: 9.10
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1001688893
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 175.225112
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind:
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 7/9/2008

Overburden and Bedrock Materials Interval

Formation ID: 1002677231
Layer: 1
Color: 6
General Color: BROWN
Mat1: 01
Most Common Material: FILL
Mat2: 28
Other Materials: SAND
Mat3: 05
Other Materials: CLAY
Formation Top Depth: 0.00
Formation End Depth: 2.10
Formation End Depth UOM: m

Formation ID: 1002677232
Layer: 2
Color: 7
General Color: RED
Mat1: 17
Most Common Material: SHALE
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 2.10
Formation End Depth: 6.00
Formation End Depth UOM: m

Formation ID: 1002677233
Layer: 3
Color: 7
General Color: RED
Mat1: 17
Most Common Material: SHALE
Mat2:
Other Materials:

Mat3:
Other Materials:
Formation Top Depth: 6.00
Formation End Depth: 7.30
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1002677235
Layer: 1
Plug From: 0.00
Plug To: 3.60
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1002677239
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1002677230
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002677236
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.00
Depth To: 7.30
Casing Diameter: 5.25
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002677237
Layer: 1
Slot: 10
Screen Top Depth:
Screen End Depth:
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.00

Hole Diameter

Hole ID: 1002677234
Diameter: 20.90
Depth From: 0.00
Depth To: 7.30
Hole Depth UOM: m

Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002677194
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 175.225112
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 6/19/2008

Annular Space/Abandonment Sealing Record

Plug ID: 1002677198
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002677197
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1002677199
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002677201
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.20
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002677200
Layer:
Slot:
Screen Top Depth: 4.20

Screen End Depth: 7.30
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002677202
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002677196
Diameter: 20.90
Depth From:
Depth To: 7.30
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002677221
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 123.831703
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 6/20/2008

Annular Space/Abandonment Sealing Record

Plug ID: 1002677225
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002677224
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1002677226
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002677228
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 6.00
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002677227
Layer:
Slot:
Screen Top Depth: 6.00
Screen End Depth: 9.10
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002677229
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002677223
Diameter: 20.90
Depth From:
Depth To: 9.10

Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002677203
DP2BR:
Code OB:
Code OB Desc:
Open Hole:
Elevation: 120.961273
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Spatial Status:
Cluster Kind: This is a record from cluster log sheet
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr
Org CS: UTM83
Date Completed: 6/19/2008

Annular Space/Abandonment Sealing Record

Plug ID: 1002677207
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002677206
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1002677208
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002677210
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.20
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002677209
Layer:
Slot:

Screen Top Depth: 4.20
Screen End Depth: 7.30
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002677211
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002677205
Diameter: 20.90
Depth From:
Depth To: 7.30
Hole Depth UOM: m
Hole Diameter UOM: cm

---

93 | ***1 of 1*** | ***WSW/262.4*** | ***124.8 / 1.07*** | ***3245 Mainway, Burlington ON L7M1A6*** | ***EHS***

Order ID: 544793
Order No: 20171108181
Customer ID: 176708
Company ID: 50
Status: C
Report Code: 20CAN
Report Type: RSC Report (Urban)
Report Date: 15-NOV-17
Report Requested by: Golder Associates Ltd.
Nearest Intersection:
Previous Site Name:
Additional Info Ordered:

Date Received: 08-NOV-17
Lot/Building Size:
Municipality:
Client Prov/State: ON
Search Radius (km): .3
Large Radius: .3
X: -79.804006
Y: 43.364876

---

94 | ***1 of 21*** | ***NNW/269.6*** | ***127.0 / 3.24*** | ***1232 Dillon Road, Burlington ON L7M 1N3*** | ***EHS***

Order ID: 212118
Order No: 20120704011
Customer ID: 92310
Company ID: 20784
Status: C
Report Code: 3CAN
Report Type: Standard Report
Report Date: 12-JUL-12

Date Received: 04-JUL-12
Lot/Building Size:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
Large Radius: 2
X: -79.800789
Y: 43.368764

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Report Requested by: MTE Consultants Inc.
Nearest Intersection:
Previous Site Name:
Additional Info Ordered:

---

94 **2 of 21** **NNW/269.6** **127.0 / 3.24** **1232 Dillon Rd**
Burlington ON L7M1N3 **EHS**

Order ID: 560502
Order No: 20180220017
Customer ID: 98067
Company ID: 77
Status: C
Report Code: 3CAN
Report Type: Standard Report
Report Date: 23-FEB-18
Report Requested by: Pinchin Ltd.
Nearest Intersection:
Previous Site Name:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Date Received: 20-FEB-18
Lot/Building Size:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
Large Radius: .35
X: -79.800989
Y: 43.368536

---

94 **3 of 21** **NNW/269.6** **127.0 / 3.24** **JC CNC WORKS INC.**
1232 DILLON ROAD, UNIT 1
BURLINGTON ON L7M 1N3 **GEN**

Generator No.: ON2201401
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country: Canada
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 253 L
Waste Description: Emulsified oils

Waste Code: 251 L
Waste Description: Waste oils/sludges (petroleum based)

---

94 **4 of 21** **NNW/269.6** **127.0 / 3.24** **JC CNC WORKS INC.**
1232 DILLON ROAD, UNIT 1
BURLINGTON ON L7M 1N3 **GEN**

Generator No.: ON2201401
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 332710
SIC Description:

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
94	5 of 21	NNW/269.6	127.0 / 3.24	X-PERT METAL FINISHING LTD. 1232 DILLON RD. BURLINGTON ON L7M 1N3	GEN

Generator No.: ON0191700
Status:
Approval Years: 86,87,88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 3041
SIC Description: COATING OF METAL PR.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
94	6 of 21	NNW/269.6	127.0 / 3.24	X-PERT METAL FINISHING LTD. 1232 DILLON ROAD BURLINGTON ON L7M 1N3	GEN

Generator No.: ON0191700
Status:
Approval Years: 98
Contam. Facility:
MHSW Facility:
SIC Code: 3041
SIC Description: COATING OF METAL PR.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
94	7 of 21	NNW/269.6	127.0 / 3.24	JC CNC WORKS INC. 1232 DILLON ROAD, UNIT 1 BURLINGTON ON L7M 1N3	GEN

Generator No.: ON2201401
Status:
Approval Years: 01,02,03,04,05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code: 4259
SIC Description: OTHER MECH. SPEC.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

---

94 **8 of 21** **NNW/269.6** **127.0 / 3.24** **JC CNC WORKS INC.** **GEN**
1232 DILLON ROAD, UNIT 1
BURLINGTON ON L7M 1N3

Generator No.: ON2201401
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 332710
SIC Description: Machine Shops

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

---

94 **9 of 21** **NNW/269.6** **127.0 / 3.24** **JC CNC WORKS INC.** **GEN**
1232 DILLON ROAD, UNIT 1
BURLINGTON ON L7M 1N3

Generator No.: ON2201401
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 332710
SIC Description: Machine Shops

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

---

94 **10 of 21** **NNW/269.6** **127.0 / 3.24** **JC CNC WORKS INC.** **GEN**
1232 DILLON ROAD, UNIT 1
BURLINGTON ON L7M 1N3

Generator No.: ON2201401
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 332710
SIC Description: MACHINE SHOPS

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

Waste Code: 253
Waste Description: EMULSIFIED OILS

---

94 **11 of 21** **NNW/269.6** **127.0 / 3.24** **Hahn and Sons Ltd** **GEN**
1232 Dillon Road, Unit #3

Burlington ON L7M 1N3

Generator No.: ON7096048
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 333299
SIC Description: ALL OTHER INDUSTRIAL MACHINERY MANUFACTURING

PO Box No.:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Paul B Hahn
Phone No. Admin: 905-335-3200 Ext.

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

94 ***12 of 21*** ***NNW/269.6*** ***127.0 / 3.24*** ***GEN***

JC CNC WORKS INC.
1232 DILLON ROAD, UNIT 1
BURLINGTON ON L7M 1N3

Generator No.: ON2201401
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 332710
SIC Description: MACHINE SHOPS

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 253
Waste Description: EMULSIFIED OILS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

---

94 ***13 of 21*** ***NNW/269.6*** ***127.0 / 3.24*** ***GEN***

Hahn and Sons Ltd
1232 Dillon Road, Unit #3
Burlington ON L7M 1N3

Generator No.: ON7096048
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 333299
SIC Description: ALL OTHER INDUSTRIAL MACHINERY MANUFACTURING

PO Box No.:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Paul B Hahn
Phone No. Admin: 905-335-3200 Ext.

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

94 ***14 of 21*** ***NNW/269.6*** ***127.0 / 3.24*** ***GEN***

Hahn and Sons Ltd
1232 Dillon Road, Unit #3
Burlington ON L7M 1N3

Generator No.: ON7096048
Status:
Approval Years: 2014
Contam. Facility: No

PO Box No.:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Verena I Freitag

MHSW Facility: No
Phone No. Admin: 905-335-3200 Ext.
SIC Code: 333299
SIC Description: ALL OTHER INDUSTRIAL MACHINERY MANUFACTURING

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

94 **15 of 21** **NNW/269.6** **127.0 / 3.24** **GEN**

Hahn and Sons Ltd
1232 Dillon Road, Unit #3
Burlington ON L7M 1N3

Generator No.: ON7096048
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No.:
Country: Canada
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 252 L
Waste Description: Waste crankcase oils and lubricants

---

94 **16 of 21** **NNW/269.6** **127.0 / 3.24** **GEN**

X-PERT METAL FINISHING LTD. ***43-024***
1232 DILLON RD.
BURLINGTON ON L7M 1N3

Generator No.: ON0191700
Status:
Approval Years: 92,93,94,95,96,97
Contam. Facility:
MHSW Facility:
SIC Code: 3041
SIC Description: COATING OF METAL PR.

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 112
Waste Description: ACID WASTE - HEAVY METALS

Waste Code: 121
Waste Description: ALKALINE WASTES - HEAVY METALS

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

---

94 **17 of 21** **NNW/269.6** **127.0 / 3.24** **GEN**

JC CNC WORKS INC.
1232 DILLON ROAD, UNIT 1
BURLINGTON ON L7M 1N3

Generator No.: ON2201401
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 332710
SIC Description: MACHINE SHOPS

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No. Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES

---

94 ***18 of 21*** ***NNW/269.6*** ***127.0 / 3.24*** ***Hahn and Sons Ltd*** ***GEN***
1232 Dillon Road, Unit #3
Burlington ON

Generator No.: ON7096048 ***PO Box No.:***
Status: ***Country:***
Approval Years: 2013 ***Choice of Contact:***
Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No. Admin:***
SIC Code: 333299
SIC Description: ALL OTHER INDUSTRIAL MACHINERY MANUFACTURING

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

---

94 ***19 of 21*** ***NNW/269.6*** ***127.0 / 3.24*** ***J.C. CNC Works Inc.*** ***SCT***
1232 Dillon Rd Unit 1
Burlington ON L7M 1N3

Established: 01-AUG-90
Plant Size (ft²): 6000
Employment:

--Details--
Description: Machine Shops
SIC/NAICS Code: 332710

Description: Railroad Rolling Stock Manufacturing
SIC/NAICS Code: 336510

Description: Mining and Oil and Gas Field Machinery Manufacturing
SIC/NAICS Code: 333130

---

94 ***20 of 21*** ***NNW/269.6*** ***127.0 / 3.24*** ***Force Enterprises Ltd.*** ***SCT***
1232 Dillon Rd Unit 2
Burlington ON L7M 1N3

Established: 01-AUG-91
Plant Size (ft²):
Employment:

--Details--
Description: Coating, Engraving, Heat Treating and Allied Activities
SIC/NAICS Code: 332810

Description: Other Plate Work and Fabricated Structural Product Manufacturing
SIC/NAICS Code: 332319

---

94 ***21 of 21*** ***NNW/269.6*** ***127.0 / 3.24*** ***EXPERT METALS*** ***SPL***
1232 DILLON RD. BURLINGTON PLANT

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

1232 DILLON ROAD
BURLINGTON CITY ON L7M 1N3

Ref No:	45306	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	1/2/1991	**Client Type:**	
Year:		**Sector Type:**	
Incident Cause:	PIPE/HOSE LEAK	**Source Type:**	
Incident Event:		**Nearest Watercourse:**	
Contaminant Code:		**Site Name:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site County/District:**	
Contaminant UN No 1:		**Site Postal Code:**	
Contaminant Qty:		**Site Region:**	
Environment Impact:	POSSIBLE	**Site Municipality:**	14101
Nature of Impact:	Water course or lake	**Site Lot:**	
Receiving Medium:	LAND / WATER	**Site Conc:**	
Receiving Env:		**Northing:**	
Health/Env Conseq:		**Easting:**	FIRE, SPILL RESPONSE TEAM
MOE Response:		**Site Geo Ref Accu:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Meth:**	
MOE Reported Dt:	1/2/1991	**Site Map Datum:**	
Dt Document Closed:			
SAC Action Class:			
Incident Reason:	UNKNOWN		
Incident Summary:	EXPERT METAL FINISHING: FLOOD ON PREMISES LEAKED CHEMICALS INTO SEWER.		

---

95 | **1 of 1** | **WSW/282.2** | **124.3 / 0.53** | **Purolator Courier Ltd.**
3255 Mainway Drive
Burlington ON L7M 1A6 | **SPL**

Ref No:	4013-7TKN72	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:		**Client Type:**	
Year:		**Sector Type:**	Motor Vehicle
Incident Cause:	Unknown	**Source Type:**	
Incident Event:		**Nearest Watercourse:**	
Contaminant Code:		**Site Name:**	Client<UNOFFICIAL>
Contaminant Name:	CitroTech Classic	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site County/District:**	
Contaminant UN No 1:		**Site Postal Code:**	
Contaminant Qty:	27 L	**Site Region:**	
Environment Impact:	Not Anticipated	**Site Municipality:**	Burlington
Nature of Impact:	Soil Contamination	**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	
Health/Env Conseq:		**Easting:**	
MOE Response:	No Field Response	**Site Geo Ref Accu:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Meth:**	
MOE Reported Dt:	7/2/2009	**Site Map Datum:**	
Dt Document Closed:			
SAC Action Class:	Land Spills		
Incident Reason:	Unknown - Reason not determined		
Incident Summary:	Purolator: 27L Citrotech to asphalt, contd, clng		

---

96 | **1 of 1** | **E/284.7** | **119.8 / -3.93** | **lot 12 con 2**
ON | **WWIS**

Well ID:	7274659	**Data Entry Status:**	Date Entry is incomplete
Construction Date:		**Data Src:**	

Primary Water Use:		**Date Received:**	11/8/2016
Sec. Water Use:		**Selected Flag:**	1
Final Well Status:		**Abandonment Rec:**	
Water Type:		**Contractor:**	6607
Casing Material:		**Form Version:**	8
Audit No:	C27760	**Owner:**	
Tag:	A196797	**Street Name:**	
Construction Method:		**County:**	HALTON
Elevation (m):		**Municipality:**	BURLINGTON CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	012
Well Depth:		**Concession:**	02
Overburden/Bedrock:		**Concession Name:**	DS S
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1006290052	**Spatial Status:**	
DP2BR:		**Cluster Kind:**	
Code OB:		**UTMRC:**	4
Code OB Desc:		**UTMRC Desc:**	margin of error : 30 m - 100 m
Open Hole:		**Location Method:**	wwr
Elevation:	120.533012	**Org CS:**	UTM83
Elevrc:		**Date Completed:**	6/10/2016
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

97 | ***1 of 1*** | ***N/288.5*** | ***127.6 / 3.82*** | ***Burlington Racquet Club*** | ***GEN***
1233 Dillon ROad
Burlington ON L7M 1K6

Generator No.:	ON5812126	**PO Box No.:**	
Status:	Registered	**Country:**	Canada
Approval Years:	As of Dec 2017	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:			
SIC Description:			

--Details--

Waste Code:	251 L
Waste Description:	Waste oils/sludges (petroleum based)

---

98 | ***1 of 1*** | ***NE/290.0*** | ***123.0 / -0.83*** | ***ON*** | ***WWIS***

Well ID:	7223759	**Data Entry Status:**	Date Entry is incomplete
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	7/14/2014
Sec. Water Use:		**Selected Flag:**	1
Final Well Status:		**Abandonment Rec:**	
Water Type:		**Contractor:**	7215
Casing Material:		**Form Version:**	8

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Audit No:	C23464	**Owner:**	
Tag:	A155206	**Street Name:**	
Construction Method:		**County:**	HALTON
Elevation (m):		**Municipality:**	BURLINGTON CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004924595	**Spatial Status:**	
DP2BR:		**Cluster Kind:**	
Code OB:		**UTMRC:**	4
Code OB Desc:		**UTMRC Desc:**	margin of error : 30 m - 100 m
Open Hole:		**Location Method:**	wwr
Elevation:	124.012062	**Org CS:**	UTM83
Elevrc:		**Date Completed:**	9/19/2013
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

99 **1 of 1** **N/292.8** **126.8 / 3.07**

1233 Dillon Rd
Burlington ON L7M1K6

EHS

Order ID:	457545	**Date Received:**	11-MAY-16
Order No:	20160511055	**Lot/Building Size:**	
Customer ID:	70327	**Municipality:**	
Company ID:	32046	**Client Prov/State:**	ON
Status:	C	**Search Radius (km):**	.25
Report Code:	27CAN	**Large Radius:**	2
Report Type:	Standard Express Report	**X:**	-79.799994
Report Date:	11-MAY-16	**Y:**	43.369056
Report Requested by:	RiskCheck Environmental Ltd.		
Nearest Intersection:			
Previous Site Name:			
Additional Info Ordered:			

---

100 **1 of 9** **NE/295.1** **122.9 / -0.91**

L. A. Rubber Inc.
3466 Landmark Road
Burlington ON L7M 1S8

CA

Certificate #:	1548-5KVQV8
Application Year:	2003
Issue Date:	12/4/2003
Approval Type:	Air
Status:	Revoked and/or Replaced
Application Type:	
Client Name::	
Client Address::	
Client City::	
Client Postal Code::	
Project Description::	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminants::
Emission Control::

---

100 | ***2 of 9*** | ***NE/295.1*** | ***122.9 / -0.91*** | ***L. A. Rubber Inc.***
3466 Landmark Rd
Burlington ON L7M 1S8 | ***CA***

Certificate #: 0959-7PDTGZ
Application Year: 2009
Issue Date: 3/3/2009
Approval Type: Air
Status: Approved
Application Type:
Client Name::
Client Address::
Client City::
Client Postal Code::
Project Description::
Contaminants::
Emission Control::

---

100 | ***3 of 9*** | ***NE/295.1*** | ***122.9 / -0.91*** | ***L. A. Rubber Inc.***
3466 Landmark Road Burlington Regional Municipality of Halton L7M 1S8 CITY OF BURLINGTON
ON | ***EBR***

EBR Registry No.: 010-0777
Ministry Ref. No.: 1370-73GPEA
Company Name: L. A. Rubber Inc.
Notice Type: Instrument Decision
Notice Date: March 10, 2009
Proposal Date: June 08, 2007
Year: 2007
Proponent Address: 3466 Landmark Road, Burlington Ontario, Canada L7M 1S8
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:

Location:

3466 Landmark Road Burlington Regional Municipality of Halton L7M 1S8 CITY OF BURLINGTON

---

100 | ***4 of 9*** | ***NE/295.1*** | ***122.9 / -0.91*** | ***L. A. Rubber Inc.***
3466 Landmark Road Burlington Ontario L7M 1S8 Burlington
ON | ***EBR***

EBR Registry No.: IA02E1440
Ministry Ref. No.: 2078-5FZSEK
Company Name: L. A. Rubber Inc.
Notice Type: Instrument Decision
Notice Date: December 08, 2003
Proposal Date: November 19, 2002
Year: 2002
Proponent Address: 3466 Landmark Road, Burlington Ontario, L7M 1S8
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Location Other:

Location:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

3466 Landmark Road Burlington Ontario L7M 1S8 Burlington

---

100 **5 of 9** **NE/295.1** **122.9 / -0.91** **L. A. Rubber Inc.** **ECA**
3466 Landmark Rd
Burlington ON L7M 1S8

Approval No:	0959-7PDTGZ	**MOE District:**	Halton-Peel
Approval Type:	ECA-AIR	**SWP Area Name:**	Halton
Status:	Approved	**Address:**	3466 Landmark Rd
Approval Date:	2009-03-03	**City:**	Burlington
Record Type:	ECA	**Longitude:**	-79.79567
Project Type:	AIR	**Latitude:**	43.367657
Link Source:	IDS		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/1370-73GPEA-14.pdf		

---

100 **6 of 9** **NE/295.1** **122.9 / -0.91** **L. A. Rubber Inc.** **ECA**
3466 Landmark Road
Burlington ON L7M 1S8

Approval No:	1548-5KVQV8	**MOE District:**	Halton-Peel
Approval Type:	ECA-AIR	**SWP Area Name:**	Halton
Status:	Revoked and/or Replaced	**Address:**	3466 Landmark Road
Approval Date:	2003-12-04	**City:**	Burlington
Record Type:	ECA	**Longitude:**	-79.79567
Project Type:	AIR	**Latitude:**	43.367657
Link Source:	IDS		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/2078-5FZSEK-14.pdf		

---

100 **7 of 9** **NE/295.1** **122.9 / -0.91** **L.A. RUBBER INC.** **GEN**
3466 LANDMARK ROAD
BURLINGTON ON L7M 1S8

Generator No.:	ON2466800	**PO Box No.:**	
Status:		**Country:**	
Approval Years:	99,00,01,02,03,04,05	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No. Admin:**	
SIC Code:	1599		
SIC Description:	OTHER RUBBER PROD.		

--Details--
Waste Code: 233
Waste Description: OTHER POLYMERIC WASTES

---

100 **8 of 9** **NE/295.1** **122.9 / -0.91** **L A RUBBER INC** **SCT**
3466 LANDMARK RD
BURLINGTON ON L7M 1S8

Established: 1970
Plant Size (ft²): 10000
Employment: 18

--Details--
Description: GASKETS, PACKING AND SEALING DEVICES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC/NAICS Code: 3053

Description: FABRICATED RUBBER PRODUCTS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3069

---

100 | ***9 of 9*** | ***NE/295.1*** | ***122.9 / -0.91*** | ***L.A. Rubber Inc.***
3466 Landmark Rd
Burlington ON L7M 1S8 | ***SCT***

Established: 01-JAN-70
Plant Size (ft²): 10000
Employment:

--Details--
Description: Resin and Synthetic Rubber Manufacturing
SIC/NAICS Code: 325210

Description: Other Rubber Product Manufacturing
SIC/NAICS Code: 326290

Description: All Other Miscellaneous Manufacturing
SIC/NAICS Code: 339990

Description: All Other Plastic Product Manufacturing
SIC/NAICS Code: 326198

Description: Other Rubber Product Manufacturing
SIC/NAICS Code: 326290

Description: Material Handling Equipment Manufacturing
SIC/NAICS Code: 333920

Unplottable Summary

Total: 17 Unplottable sites

DB	Company Name/Site Name	Address	City	Postal
CA	COOPER CORPORATION LIMITED	MAINWAY BUS. CENTRE	BURLINGTON CITY ON	
CA	REGIONAL MUNICIPALITY OF HALTON	PT. LOT 13, CONC. 1 & 2	BURLINGTON CITY ON	
CONV	PUROLATOR COURIER LTD.		ON	
CPU	O.R.E. Development Corporation	3230 Mainway, Lot 15, Registered Plan 1055, former the Township of Nelson, Burlington, Ontario, Regional Municipality of Halton CITY OF BURLINGTON	ON	
EHS		Mainway	Burlington ON	
EHS		Mainway	Burlington ON	
GEN	VAC AERO International Incorporated	Mainway	Burlington ON	L7L 5N9
GEN	VAC AERO International Incorporated	Mainway	Burlington ON	
GEN	VAC AERO International Incorporated	Mainway	Burlington ON	L7L 5N9
GEN	VAC AERO International Incorporated Head Office	Mainway	Burlington ON	L7L 5N9
GEN	VAC AERO International Incorporated	Mainway	Burlington ON	L7L 5N9
SPL	BURLINGTON HYDRO-ELECTRIC COMM	MOTOR VEHICLE (OPERATING FLUID)	BURLINGTON CITY ON	
SPL		Mainway, East of Appleby Line	Burlington ON	
SPL	Zenon Environmental Inc.	Mainway Ave,	Burlington ON	
SPL	BURLINGTON HYDRO-ELECTRIC COMM	TRANSFORMER	BURLINGTON CITY ON	
WWIS		lot 11 con 2	ON	

Unplottable Report

Site: ***COOPER CORPORATION LIMITED***
MAINWAY BUS. CENTRE BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-0399-88-
Application Year: 88
Issue Date: 3/30/1988
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name::
Client Address::
Client City::
Client Postal Code::
Project Description::
Contaminants::
Emission Control::

Site: ***REGIONAL MUNICIPALITY OF HALTON***
PT. LOT 13, CONC. 1 & 2 BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-1212-92-
Application Year: 92
Issue Date: 1/5/1993
Approval Type: Municipal water
Status: Approved in 1993
Application Type:
Client Name::
Client Address::
Client City::
Client Postal Code::
Project Description::
Contaminants::
Emission Control::

Site: ***PUROLATOR COURIER LTD.***
ON

Database: ***CONV***

File No.:
Publication Title:
Publication City:
Url:
Crown Brief No.: 99-0022-0138
Ministry District: METRO
Region: CENTRAL REGION
Description: FAILURE TO NOTIFY THE MINISTRY OF A DISCHARGE OF DIESEL FUEL, OUT OF THE NORMAL COURSE OF EVENTS, INTO THE NATURAL ENVIRONMENT.

--Details--
Publication Date:
Count: 1
Act: EPA
Regulation:
Section: 15(1)
Act/Regulation/Section: EPA- -15(1)
Date Charged: 10/13/99

Charge Disposition: SUSPENDED SENTENCE
Fine: $1,800.00

Site: ***O.R.E. Development Corporation***
3230 Mainway, Lot 15, Registered Plan 1055, former the Township of Nelson, Burlington, Ontario, Regional Municipality of Halton CITY OF BURLINGTON ON

Database: ***CPU***

EBR Registry No.: 010-8527
Ministry Ref. No.: 6631-7RQGKZ
Company Name: O.R.E. Development Corporation
Notice Type: Instrument Decision
Notice Date: February 12, 2010
Proposal Date: December 07, 2009
Proponent Address: 3230 Main Way, Burlington Ontario, Canada L7M 1A5
Year: 2009
Instrument Type: (EPA s. 168.6) - Certificate of Property Use
Location: 3230 Mainway, Lot 15, Registered Plan 1055, former the Township of Nelson, Burlington, Ontario, Regional Municipality of Halton CITY OF BURLINGTON
Location Other:

Site:
Mainway Burlington ON

Database: ***EHS***

Order ID: 198663
Order No: 20111123010
Customer ID: 54087
Company ID: 93
Status: C
Report Code: 4CAN
Report Type: Custom Report
Report Date: 11/24/2011
Report Requested by: Terraprobe Ltd
Nearest Intersection:
Previous Site Name:
Additional Info Ordered:

Date Received: 11/23/2011 11:13:03 AM
Lot/Building Size:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
Large Radius: 0.25
X: -79.771198
Y: 1

Site:
Mainway Burlington ON

Database: ***EHS***

Order ID: 197922
Order No: 20111108016
Customer ID: 54087
Company ID: 93
Status: C
Report Code: 4CAN
Report Type: Custom Report
Report Date: 11/16/2011
Report Requested by: Terraprobe Ltd
Nearest Intersection:
Previous Site Name:
Additional Info Ordered:

Date Received: 11/8/2011
Lot/Building Size:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
Large Radius: 0.25
X: -79.76883
Y: 43.39215

Site: ***VAC AERO International Incorporated***
Mainway Burlington ON L7L 5N9

Database: ***GEN***

Generator No.: ON8346163
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 333990
SIC Description: ALL OTHER GENERAL-PURPOSE MACHINERY MANUFACTURING

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Wade Maloney
Phone No. Admin: 905 336 0673 Ext.127

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Site: ***VAC AERO International Incorporated***
Mainway Burlington ON

Database: ***GEN***

Generator No.: ON8346163
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 333990
SIC Description: ALL OTHER GENERAL-PURPOSE MACHINERY MANUFACTURING

PO Box No.:
Country:
Choice of Contact:
Co Admin:
Phone No. Admin:

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Site: ***VAC AERO International Incorporated***
Mainway Burlington ON L7L 5N9

Database: ***GEN***

Generator No.: ON8346163
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 333990
SIC Description: ALL OTHER GENERAL-PURPOSE MACHINERY MANUFACTURING

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Wade Maloney
Phone No. Admin: 905 336 0673 Ext.127

--Details--
Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Site: ***VAC AERO International Incorporated Head Office***
Mainway Burlington ON L7L 5N9

Database: ***GEN***

Generator No.: ON8346163
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:

PO Box No.:
Country: Canada
Choice of Contact:
Co Admin:
Phone No. Admin:

SIC Code:
SIC Description:

--Details--
Waste Code: 211 H
Waste Description: Aromatic solvents and residues

Waste Code: 252 L
Waste Description: Waste crankcase oils and lubricants

Waste Code: 145 I
Waste Description: Wastes from the use of pigments, coatings and paints

Waste Code: 213 I
Waste Description: Petroleum distillates

Site: ***VAC AERO International Incorporated***
Mainway Burlington ON L7L 5N9

Database: ***GEN***

Generator No.: ON8346163
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 333990
SIC Description: ALL OTHER GENERAL-PURPOSE MACHINERY MANUFACTURING

PO Box No.:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Wade Maloney
Phone No. Admin: 905 336 0673 Ext.127

--Details--
Waste Code: 252
Waste Description: WASTE OILS & LUBRICANTS

Waste Code: 211
Waste Description: AROMATIC SOLVENTS

Waste Code: 213
Waste Description: PETROLEUM DISTILLATES

Site: ***BURLINGTON HYDRO-ELECTRIC COMM***
MOTOR VEHICLE (OPERATING FLUID) BURLINGTON CITY ON

Database: ***SPL***

Ref No: 68601
Site No:
Incident Dt: 3/19/1992
Year:
Incident Cause: PIPE/HOSE LEAK
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Contaminant Qty:
Environment Impact: NOT ANTICIPATED
Nature of Impact:
Receiving Medium: LAND
Receiving Env:
Health/Env Conseq:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/19/1992
Dt Document Closed:
SAC Action Class:
Incident Reason: OVERSTRESS/OVERPRESSURE
Incident Summary: BACKENTRY BURLINGTON HYDRO - 15 L. OF HYDRAULIC FLUID TO GROUND

Discharger Report:
Material Group:
Client Type:
Sector Type:
Source Type:
Nearest Watercourse:
Site Name:
Site Address:
Site District Office:
Site County/District:
Site Postal Code:
Site Region:
Site Municipality: 14101
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Geo Ref Meth:
Site Map Datum:

Site:
Mainway, East of Appleby Line Burlington ON

Database: ***SPL***

Ref No:	8713-AB9RLC	***Discharger Report:***	
Site No:	NA	***Material Group:***	
Incident Dt:	2016/06/25	***Client Type:***	
Year:		***Sector Type:***	Municipal Sewage
Incident Cause:		***Source Type:***	
Incident Event:	Overflow/Surcharge	***Nearest Watercourse:***	
Contaminant Code:	44	***Site Name:***	Manhole #MH7550<UNOFFICIAL>
Contaminant Name:	SEWAGE,RAW UNCHLORINATED	***Site Address:***	Mainway, East of Appleby Line
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:	0.5 m³	***Site Region:***	
Environment Impact:		***Site Municipality:***	Burlington
Nature of Impact:		***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:	Surface Water	***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:	No	***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	2016/06/25	***Site Map Datum:***	
Dt Document Closed:	2016/07/14		
SAC Action Class:	Land Spills		
Incident Reason:	Blockage		
Incident Summary:	Region of Halton: 0.5m3 Raw Swg to CB and Road. Cleaned.		

Site: ***Zenon Environmental Inc.***
Mainway Ave, Burlington ON

Database: ***SPL***

Ref No:	4442-67746L	***Discharger Report:***	
Site No:		***Material Group:***	Waste
Incident Dt:	11/26/2004	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	Other Discharges	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	ZENON ENVIRONMENTAL - PRODUCTION PLANT<UNOFFICIAL>
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	Halton-Peel
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	Central
Environment Impact:	Confirmed	***Site Municipality:***	Burlington
Nature of Impact:	Human Health/Safety; Other Impact(s); Soil Contamination	***Site Lot:***	
Receiving Medium:	Land	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	11/28/2004	***Site Map Datum:***	
Dt Document Closed:			
SAC Action Class:			
Incident Reason:			
Incident Summary:	Hotline: Unkn Sub from Zenon, Stained Cars		

Site: ***BURLINGTON HYDRO-ELECTRIC COMM***
TRANSFORMER BURLINGTON CITY ON

Database: ***SPL***

Ref No:	159820	***Discharger Report:***	
Site No:		***Material Group:***	

Incident Dt:	9/6/1998	***Client Type:***	
Year:		***Sector Type:***	
Incident Cause:	COOLING SYSTEM LEAK	***Source Type:***	
Incident Event:		***Nearest Watercourse:***	
Contaminant Code:		***Site Name:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site County/District:***	
Contaminant UN No 1:		***Site Postal Code:***	
Contaminant Qty:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	14101
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
Health/Env Conseq:		***Easting:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Meth:***	
MOE Reported Dt:	9/6/1998	***Site Map Datum:***	
Dt Document Closed:			
SAC Action Class:			
Incident Reason:	OVERSTRESS/OVERPRESSURE		
Incident Summary:	BURLINGTON HYDRO-<127L TRANSFORMER OIL TO VAULT.CHLOR-N-OIL POSITIVE.		

Site:

lot 11 con 2 ON

Database: ***WWIS***

Well ID:	2809664	***Data Entry Status:***	
Construction Date:		***Data Src:***	1
Primary Water Use:	Domestic	***Date Received:***	11/26/2002
Sec. Water Use:		***Selected Flag:***	1
Final Well Status:	Water Supply	***Abandonment Rec:***	
Water Type:		***Contractor:***	4005
Casing Material:		***Form Version:***	1
Audit No:	241397	***Owner:***	
Tag:		***Street Name:***	
Construction Method:		***County:***	HALTON
Elevation (m):		***Municipality:***	BURLINGTON CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	011
Well Depth:		***Concession:***	02
Overburden/Bedrock:		***Concession Name:***	NS
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	10531837	***Spatial Status:***	
DP2BR:	0	***Cluster Kind:***	
Code OB:	r	***UTMRC:***	9
Code OB Desc:	Bedrock	***UTMRC Desc:***	unknown UTM
Open Hole:		***Location Method:***	na
Elevation:		***Org CS:***	
Elevrc:		***Date Completed:***	11/14/2002
Remarks:			
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock

Materials Interval

Formation ID:	932886857
Layer:	1
Color:	2
General Color:	GREY
Mat1:	15
Most Common Material:	LIMESTONE
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0.00
Formation End Depth:	60.00
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	962809664
Method Construction Code:	5
Method Construction:	Air Percussion
Other Method Construction:	

Pipe Information

Pipe ID:	11080407
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930265039
Layer:	1
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	5.00
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pump Test ID:	992809664
Pump Set At:	
Static Level:	29.00
Final Level After Pumping:	50.00
Recommended Pump Depth:	
Pumping Rate:	15.00
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	1
Pumping Duration HR:	1
Pumping Duration MIN:	0
Flowing:	N

Draw Down & Recovery

Pump Test Detail ID:	934176284

Test Type: Recovery
Test Duration: 15
Test Level: 24.00
Test Level UOM: ft

Pump Test Detail ID: 934978535
Test Type: Recovery
Test Duration: 60
Test Level: 24.00
Test Level UOM: ft

Water Details

Water ID: 934024877
Layer: 1
Kind Code: 5
Kind: Not stated
Water Found Depth: 43.00
Water Found Depth UOM: ft

Water ID: 934024878
Layer: 2
Kind Code: 5
Kind: Not stated
Water Found Depth: 53.00
Water Found Depth UOM: ft

Site:
lot 13 ON

Database:
WWIS

Well ID: 2809928
Construction Date:
Primary Water Use: Not Used
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: 242196
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 5/26/2004
Selected Flag: 1
Abandonment Rec:
Contractor: 1660
Form Version: 2
Owner:
Street Name:
County: HALTON
Municipality: BURLINGTON CITY
Site Info:
Lot: 013
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 11098148
DP2BR:
Code OB: _
Code OB Desc: No formation data
Open Hole:
Elevation:
Elevrc:
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:

Spatial Status:
Cluster Kind:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na
Org CS:
Date Completed: 7/16/2003

Supplier Comment:

Method of Construction & Well Use

Method Construction ID: 962809928
Method Construction Code: 0
Method Construction: Not Known
Other Method Construction:

Pipe Information

Pipe ID: 11101863
Casing No: 1
Comment:
Alt Name:

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ***Note:*** *Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.*

Abandoned Aggregate Inventory: Provincial AAGR

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

Government Publication Date: Sept 2002*

Aggregate Inventory: Provincial AGR

The Ontario Ministry of Natural Resources maintains a database of all active pits and quarries. The database provides information regarding the registered owner/operator, location name, operation type, approval type, and maximum annual tonnage.

Government Publication Date: Up to Sep 2017

Abandoned Mine Information System: Provincial AMIS

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

Government Publication Date: 1800-Nov 2016

Anderson's Waste Disposal Sites: Private ANDR

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1860s-Present

Automobile Wrecking & Supplies: Private AUWR

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

Government Publication Date: 1999-Jan 31, 2018

Borehole: Provincial BORE

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

Government Publication Date: 1875-Jul 2014

Certificates of Approval: Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

Government Publication Date: 1985-Oct 30, 2011*

Commercial Fuel Oil Tanks: Provincial CFOT

Since May 2002, Ontario developed a new act where it became mandatory for fuel oil tanks to be registered with Technical Standards & Safety Authority (TSSA). This data would include all commercial underground fuel oil tanks in Ontario with fields such as location, registration number, tank material, age of tank and tank size.

Government Publication Date: Feb 28, 2017

Chemical Register: Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

Government Publication Date: 1999-Jan 31, 2018

Compressed Natural Gas Stations: Private CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

Government Publication Date: Dec 31, 2012

Inventory of Coal Gasification Plants and Coal Tar Sites: Provincial COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

Government Publication Date: Apr 1987 and Nov 1988*

Compliance and Convictions: Provincial CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

Government Publication Date: 1989-Nov 2017

Certificates of Property Use: Provincial CPU

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include all CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

Government Publication Date: 1994-Feb 28, 2018

Drill Hole Database: Provincial DRL

The Ontario Drill Hole Database contains information on more than 113,000 percussion, overburden, sonic and diamond drill holes from assessment files on record with the department of Mines and Minerals. Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted to the MNDM. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

Government Publication Date: 1886-Nov 30, 2017

Dry Cleaning Facilities: Federal DRYCLEANERS

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.

Government Publication Date: Jan 2004-Dec 2016

Environmental Activity and Sector Registry: Provincial EASR

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval), Please see our ECA database.

Government Publication Date: Oct 2011-Jan 31, 2018

Environmental Registry: Provincial EBR

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

Government Publication Date: 1994-Feb 28, 2018

Environmental Compliance Approval: Provincial ECA

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

Government Publication Date: Oct 2011-Jan 31, 2018

Environmental Effects Monitoring: Federal EEM

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

Government Publication Date: 1992-2007*

ERIS Historical Searches: Private EHS

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

Government Publication Date: 1999-Feb 28, 2018

Environmental Issues Inventory System: Federal EIIS

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

Government Publication Date: 1992-2001*

Emergency Management Historical Event: Provincial EMHE

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

Government Publication Date: Dec 31, 2016

List of TSSA Expired Facilities: Provincial EXP

List of facilities with removed tanks which were once registered with the Fuels Safety Program of the Technical Standards and Safety Authority (TSSA). Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc. Tanks which have been removed automatically fall under the expired facilities inventory held by TSSA.

Government Publication Date: Feb 28, 2017

Federal Convictions: Federal FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

Government Publication Date: 1988-Jun 2007*

Contaminated Sites on Federal Land: Federal FCS

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government.

Government Publication Date: Jun 2000-Mar 2018

Fisheries & Oceans Fuel Tanks: Federal FOFT

Fisheries & Oceans Canada maintains an inventory of aboveground & underground fuel storage tanks located on Fisheries & Oceans property or controlled by DFO. Our inventory provides information on the site name, location, tank owner, tank operator, facility type, storage tank location, tank contents & capacity, and date of tank installation.

Government Publication Date: 1964-Sep 2017

Fuel Storage Tank: Provincial FST

The Technical Standards & Safety Authority (TSSA), under the Technical Standards & Safety Act of 2000 maintains a database of registered private and retail fuel storage tanks in Ontario with fields such as location, tank status, license date, tank type, tank capacity, fuel type, installation year and facility type.

Government Publication Date: Feb 28, 2017

Fuel Storage Tank - Historic: Provincial FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

Government Publication Date: Pre-Jan 2010*

Ontario Regulation 347 Waste Generators Summary: Provincial GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

Government Publication Date: 1986-December 31, 2017

Greenhouse Gas Emissions from Large Facilities: Federal GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO2 eq).

Government Publication Date: 2013-Dec 2015

TSSA Historic Incidents: Provincial HINC

This database will cover all incidences recorded by TSSA with their older system, before they moved to their new management system. TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. The TSSA works to protect the public, the environment and property from fuel-related hazards such as spills, fires and explosions. This database will include spills and leaks from pipelines, diesel, fuel oil, gasoline, natural gas, propane and hydrogen recorded by the TSSA.

Government Publication Date: 2006-June 2009*

Indian & Northern Affairs Fuel Tanks: Federal IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

Government Publication Date: 1950-Aug 2003*

TSSA Incidents: Provincial INC

TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Includes incidents from fuel-related hazards such as spills, fires and explosions. This database will include spills and leaks from diesel, fuel oil, gasoline, natural gas, propane and hydrogen recorded by the TSSA.

Government Publication Date: Feb 28, 2017

Landfill Inventory Management Ontario: Provincial LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the ministry compiles new and updated information. The inventory will include small and large landfills. Additionally, each year the ministry will request operators of the larger landfills complete a landfill data collection form that will be used to update LIMO and will include the following information from the previous operating year. This will include additional information such as estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills will include information such as site owner, site location and certificate of approval # and status.

Government Publication Date: Dec 31, 2013

Canadian Mine Locations: Private MINE

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

Government Publication Date: 1998-2009*

Environmental Penalty Annual Report: Provincial MISA PENALTY

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment and Climate Change. These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

Government Publication Date: Jan 1, 2011 - Dec 31, 2017

Mineral Occurrences: Provincial MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

Government Publication Date: 1846-Jan 2018

National Analysis of Trends in Emergencies System (NATES): Federal NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

Government Publication Date: 1974-1994*

Non-Compliance Reports: Provincial NCPL

The Ministry of the Environment provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act.

Government Publication Date: Dec 31, 2016

National Defense & Canadian Forces Fuel Tanks: Federal NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

Government Publication Date: Up to May 2001*

National Defense & Canadian Forces Spills: Federal NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

Government Publication Date: Mar 1999-Aug 2010

National Defence & Canadian Forces Waste Disposal Sites: Federal NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

Government Publication Date: 2001-Apr 2007*

National Energy Board Pipeline Incidents: Federal NEBI

Locations of pipeline incidents from 2008 to present, made available by the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

Government Publication Date: 2008-Dec 31, 2017

National Energy Board Wells: Federal NEBW

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release date.

Government Publication Date: 1920-Feb 2003*

National Environmental Emergencies System (NEES): Federal NEES

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December 2004.

Government Publication Date: 1974-2003*

National PCB Inventory: Federal NPCB

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

Government Publication Date: 1988-2008*

National Pollutant Release Inventory: Federal NPRI

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances.

Government Publication Date: 1993-May 2017

Oil and Gas Wells: Private OGW

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

Government Publication Date: 1988-December 31, 2017

Ontario Oil and Gas Wells: Provincial OOGW

In 1998, the MNR handed over to the Ontario Oil, Gas and Salt Resources Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database include well owner/operator, location, permit issue date, and well cap date, license No., status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provide for each well record.

Government Publication Date: 1800-Oct 2017

Inventory of PCB Storage Sites: Provincial OPCB

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

Government Publication Date: 1987-Oct 2004; 2012-Dec 2013

Orders: Provincial ORD

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include all Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

Government Publication Date: 1994-Feb 28, 2018

Canadian Pulp and Paper: Private PAP

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

Government Publication Date: 1999, 2002, 2004, 2005, 2009

Parks Canada Fuel Storage Tanks: Federal PCFT

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

Government Publication Date: 1920-Jan 2005*

Pesticide Register: Provincial PES

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

Government Publication Date: 1988-Mar 2018

TSSA Pipeline Incidents: Provincial PINC

TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. This database will include spills, strike and leaks from recorded by the TSSA.

Government Publication Date: Feb 28, 2017

Private and Retail Fuel Storage Tanks: Provincial PRT

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

Government Publication Date: 1989-1996*

Permit to Take Water: Provincial PTTW

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include all PTTW's on the registry such as OWRA s. 34 - Permit to take water.

Government Publication Date: 1994-Feb 28, 2018

Ontario Regulation 347 Waste Receivers Summary: Provincial REC

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

Government Publication Date: 1986-2016

Record of Site Condition: Provincial RSC

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up.
RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09).

Government Publication Date: 1997-Sept 2001, Oct 2004-Nov 2017

Retail Fuel Storage Tanks: Private RST

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

Government Publication Date: 1999-Jan 31, 2018

Scott's Manufacturing Directory: Private SCT

Scott's Directories is a data bank containing information on over 200,000 manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, and main products are included in this database.

Government Publication Date: 1992-Mar 2011*

Ontario Spills: Provincial SPL

This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X.

Government Publication Date: 1988-Feb 2018

Wastewater Discharger Registration Database: Provincial SRDS

Information under this heading is combination of the following 2 programs. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment maintained a database of all direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation; Mining; Petroleum Refining; Organic Chemicals; Inorganic Chemicals; Pulp & Paper; Metal Casting; Iron & Steel; and Quarries. All sampling information is now collected and stored within the Sample Result Data Store (SRDS).

Government Publication Date: 1990-Dec 31, 2016

Anderson's Storage Tanks: Private TANK

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1915-1953*

Transport Canada Fuel Storage Tanks: Federal TCFT

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

Government Publication Date: 1970-Aug 2017

TSSA Variances for Abandonment of Underground Storage Tanks: Provincial VAR

List of variances granted for abandoned tanks. Under the Technical Standards and Safety Authority (TSSA) Liquid Fuels Handling Code and Fuel Oil Code, all underground storage tanks must be removed within two years of disuse. If removal of a tank is not feasible, an application may be sought for a variance from this code requirement.

Government Publication Date: Feb 28, 2017

Waste Disposal Sites - MOE CA Inventory: Provincial WDS

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

Government Publication Date: Oct 2011-Jan 31, 2018

Waste Disposal Sites - MOE 1991 Historical Approval Inventory: Provincial WDSH

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

Government Publication Date: Up to Oct 1990*

Water Well Information System: Provincial WWIS

This database describes locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table.

Government Publication Date: Mar 31, 2017

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

Appendix F: Municipal Records

Copy Service Canada

www.lgicscanada.com
alantos@lgicscanada.com
Phone : 613 875-7387

City Directory Information Source
Vernon's Burlington, Ancaster, Dundas, Stoney Creek, Waterdown ON City Directory

PROJECT NUMBER: HAM-00801245-A0	
Site Address:	1160 Blair Road, Burlington, Ontario
Year: 2011	
Site Listing:	-Multi Tenant Office
Adjacent Properties:	
Blair Road (All)	1101-Pennzoil Quaker State Inc -Shell - 1100-Quadra Chemicals Ltd 1140-Container REsale Inc -Jones Neon Displays Ltd 1150-Horton Automatics -JR Tool & Die -Rogers Industrial Services -Anita Jupp & Co -Burlington Sandblasting -Canada Blower Co -Carrier Find Ltd -Technipal Inc

	1176-Burlington City Repp Hockey Club 1182-Oecta Halton Elementary Unit -Ontario English Catholic Teachers' Association Halton
Landmark Road (All)	3455-Comstock Canada - 3400-Airmax Compressor Services Ltd Paintball Adventures -TMR Canada 3424-Marks Supply -Watermarks 3450-Burlington Cutting & Finishing Inc -Tach West Instruments Ltd -Bob Jarvis Insulation Ltd 3466-LA Rubber Inc 3472-A&A Deluxe Taxi -Burlington Taxi -Dial a Ride
Mainway (3260-3390)	3331-Halton Metal Outlet Ltd 3333-Accurate Concrete Cutting -Allen Industrial Rubber Products -Gourmet Coffee & Office 3337-Customswag 3339-Joseph Mechanical Ltd -Evergreen Heating AC Services 3365-Gottardo Construction Ltd -Mahle Clevite Canada 3385-Broadcast Services Int'l Inc -Royal Lepage King - 3264-Fibre Cast Inc -Olympus Pools

	3280-Autofun 3300-MWE Belting Company 3310-Integrity Worldwide Inc 3312-Carlisle Technology -Weigh Matic Systems Inc 3330-Mid USA Canada Motorcycle Parts 3332-Keep It Lite With Nicki 3334-Medset Specialty 3340-Esprit Solutions Int'l Inc 3342-Hamilton Digital Designs Ltd -Smart Thought 3344-Quality Health Services -Quality Underwriting Services 3388-Discount Car & Truck Rentals -Ontario Auto Collision Carstar 3390-Rock This Way
Pioneer Road (All)	1121-Mauser Canada Ltd 1149-Rehau Industries Inc -Willis Supply Company 1153-Pioneer Industrial Mall -World Wide Kiln Service -Brant Custom Grinding Ltd -Burlington Centreless Grinding Ltd -Process Equipment Inc Brewers Car Parts Plus -CHDS Inc -Global Products canada Inc -JD Restorations -MCM Contracting -MCM Garage Doors -MIR Fabric Products -Machinery Repair Technologies -Mill Pack Industrial -Maintenance Inc -PST Maching Ltd

	-Phillips Customer Service Inc -Phoenix Amusements -Question Ltd -Scholars in Collars Drog Training Tonic Appliance Repair --Winmar - 1122-HRL Waste Systems -Halton Recycling -Emterra Environmental

PROJECT NUMBER: HAM-00801245-A0	
Site Address:	1160 Blair Road, Burlington, Ontario
Year: 2005	
Site Listing:	-Multi Tenant Office -Auburn Industrial Services
Adjacent Properties:	
Blair Road (All)	1101-Pennzoil Quaker State Inc 1157-Screenplay Designs Inc 1100-Quadra Chemicals Ltd -Argos Telecom Inc 1140-Jones Neon Displays Ltd -Container Resale Inc 1150-JR Tool & Die -Rogers Industrial Services -Simon Crane Rental Ltd -Rogers Industrial Services -Northern Industrial -Jupp Anita & Co -Mason KEmp Ltd -Elite Automation

	-Rubaroc Safety Surfacing -Canada Blower 1176-Elementary Teachers Federation of Ontario-Halton 1180-Conspec Controls Ltd 1182-Ontario English Catholic Teachers' Association OECTA 1190-Burlington City Rep Hockey Club
Landmark Road (All)	3415-Nuway Transportation 3455-Comstock Canada 3400-L&A Diecrafts Ltd -Natural Temptations Inc -Millcraft Systems Inc -Millcraft construction & Renovations Inc -Millcraft Landscape Paintball Adventures -TMR Canada 3424-Marks Supply 3450-Calorific Construction Ltd -Bramkal Contractors Inc -International Paving -A-1 Asphalt Maintenance -Diamonds Paving -Arrowhead Paving Inc 3466-LA Rubber Inc 3472-A&A Deluxe Taxi -Burlington Taxi
Mainway (3260-3390)	3267-Burlington Technologies Inc 3285-TPH The Printing House Ltd -Cotswold Precision Co Ltd -Sympro CNC Machining & Manufacturing Inc -Intek Inc -ATS Spartec Inc -Precision Print -Legal Office -Bormill Inc

	3291-Brown Falcon Machine & Tool -McKellar Machine Products Ltd -Nixon Integrated Machining Designs Ltd Mainway Machine Tools New & Used 3295-Tymatic Controls Div of Tyrrell Air Controls Ltd -Burlington Jiu Jitsu -Erodall Ltd -D Sharp Dental Instruments -Seibert Machine & Technology -Fastway Couriers 3317-Halton Sheet Metal -Timbertols -RKP Packing 3319-Spectrum Flooring 3321-Airon HVAC and Control -RJP Packaging 3323-Audio Market Sales -Helec Insulation Ltd 3325-West Windows -Legal Office -AGL Services -Advance Kilns & Supplies -Evergreen Stucco -Evergreen Heating & Air Conditioning 3327-Taurus Sales -Firecraft Kilns Sales & Service -Underworld Customs Inc -Special Effects Motorcycle Co -Safont Ltd -OnDrive Inc 3329-AS&S Courier 3331-Halton Metal Outlet Ltd -Norm's Pump Sales & Service 3333-Allen Industrial Rubber Products -Accurate Concrete Cutting -B&B Ironworks 3337-United Distribution Surplus Inc 3339-Hamilton Oliver Thermal Control

	-Joseph Mechanical Ltd 3385-Kingsbury Canada Inc -Keltour Controls -Veltronix Inc - 3264-Fibre Cast Inc -Olympus Pools 3280-Autofun 3300-MWE Belting Company 3310-Cansaw Services Ltd -US Saw 3312-Weigh-Matic Systems Inc -Carlisle Technology 3330-Mid USA Canada Motorcycle Parts 3332-Mighty Transportation Services 3334-Medset Specialty 3340-Esprit Solutions Int'l Inc -Convertec Inc 3344-Bodimetric Profiles Canadaes 3388-Ontario Auto Collision Carstar -Aro Motors Car Star 3390-Chem Systems Inc
Pioneer Road (All)	1149-Rehau Industries Inc 1153-Pioneer Industrial Mall -World Wide Kiln Service -Sealtech -Machinery Repair Technologies -BG Screen Fabrication Inc -MIR Fabric Products -Phillips Customer Service Inc -Universal ATM Services Inc -Hothedz -KGM Sales -Global Products Canada Inc

	-Mill Pack Industrial Maintenance Inc -Sunrise Roofing -Arkove Inc -Apex Composites Inc -JD Restorations -Hahn and Sons Restoration -Process Equipment Inc -Cyop Information Systems -Impact Souvenirs -JD Restorations -Burlington Centreless Grinding Ltd -Brant custom Grinding Ltd -Homemade Wine Crafts Ltd -KC Graphics -Downtown Signs -Winmar -All Racing & Conveying Solutions - 1122-HRL Waste Systems -Halton Recycling

PROJECT NUMBER: HAM-00801245-A0	
Site Address:	1160 Blair Road, Burlington, Ontario
Year: 2000	
Site Listing:	-Best Cut -Kara Holdings Inc -B&B Piano Movers -Burlington Movers -Advance Moving & Storage -Pharmawise Design Consultants -ABCO Engineering & Operations Management Ltd -Canadian HVAC Distributors Ltd -Blair Business Center

Adjacent Properties:	
Blair Road (All)	1101-Pennzoil Quaker State Inc 1157-Secoroc A Div of Atlas Copco Canada Inc - 1100-Quadra Chemicals Ltd 1140-Jones Neon Displays Ltd 1150-SOS Cylinders -JR Tool & Die -Rogers Industrial Services -Simon Crane Rental Ltd -Linton's Roundhouse Warehousing -Burlington Sandblasting & Painting -Northern Industrial -Nelson Business Machines Ltd -Talk 2 Me Technology -Jupp Anita & Co 1176-Elementary Teachers Federation of Ontario-Halton 1180-Halton Secondary Teachers 1182-Ontario English Catholic Teachers' Association OECTA 1190-Burlington City Rep Hockey Club
Landmark Road (All)	3415-Euroline Custom Cabinets 3455-Comstock Canada - 3400-L&A Diecrafts Ltd -Henderson Tutorial Instruction -Natural Temptations Inc -Canadian Country Candies 3424-Humpty Dumpty Foods Ltd 3450-Calorific Construction Ltd -Shuttle Express Inc -Bramkal Contractors Inc

	3466-LA Rubber Inc 3472-Dayside Industries
Mainway (3260-3390)	3267-Burlington Technologies Inc 3285-Mainway Machine Tools New & Used -TPH The Printing House Ltd -Cotswold Precision Co Ltd -Versa-Hoe Equipment Corp -Aubrun Industrial Services Ltd -Task Force Management Inc -Sympro CNC Machining & Manufacturing Inc 3291-Brown Falcon Machine & Tool -McKellar Machine Products Ltd -Nixon Integrated Machining Designs Ltd 3295-Rainbow Ceramics -Erodall LTd -Aikido Yoshinkan of Burlington -Steel City Mill Work -Tymatic Controls Div of Tyrell Air Controls Ltd -Burlington Jiu Jitsu -Gillen Construction 3317-Halton Sheet Metal -Organizers Plus 3319-JC Machinery -Tri Mechanical -Spectrum Flooring 3321-Airon HVAC and Control 3323-Audio Market Sales -Burlington Upholstering -Music of the Night Compact Disc Jockey Service -Helec Insulation Ltd 3325-West Windows -Legal Office 3327-Mid USA Canada Motor Cycle Parts -Travis Industrial Maintenance Ltd -Taurus Sales Inc 3329-AS&S Courier

	3331-Halton Metal Outlet Ltd 3333-Allen Industrial Rubber Products -Accurate Concrete Cutting -Norm's Pump Sales & Service -AJ Heating & Air Conditioning 3335-Water Energy Technologies -Force Fitness Systems 3337-A&B Metal Equipment Services 3339-Hamilton Oliver Thermal Control -RW Sheet Metal & Designs 3385-Kingsbury Canada Inc -Keltour Controls - 3264-Renters News Locators Services -Fibre Cast Inc 3280-Autofun 3300-MWE Belting Company 3310-Mark's Supply 3312-Weigh-Matic Systems Inc -Carlisle Technology 3330-Direct Home Delivery 3334-Meridian Golf 3336-Knowledge Grove Inc 3342-Hamilton Digital Designs Ltd 3344-Town & Country Bookkeeping Service Ltd 3388-Canfanco 3390-Chem Systems Inc
Pioneer Road (All)	1149-Rehau Industries Inc 1153-Pioneer Industrial Mall -Canadian Induction Processing Inc -World Wide Kiln Service

	-Sealtech -Andris Interiors -Machinery Repair Technologies -BG Screen Fabrication Inc -Kleen Rite Carpet Cleaning -MIR Fabric Products -Burlington Centreless Grinding -Brant Custom Grinding Ltd -Homemade Wine Crafts Ltd -KC Graphics -Huffman Custom Woodworking -Downtown Signs -Winmar Warehouse -Laser FX Int'l -Yellow Performance -All Racking & Conveying Solutions - 1122-Halton Recycling

PROJECT NUMBER: HAM-00801245-A0	
Site Address:	1160 Blair Road, Burlington, Ontario
Year: 1995	
Site Listing:	-Rotunda Office Building -Loomis Courier Service Ltd
Adjacent Properties:	
Blair Road (All)	1101-Pennzoil Quaker State Inc 1157-Secoroc A Div of Atlas Copco Canada Inc - 1100-Quadra Chemicals Ltd 1140-Jones Neon Displays Ltd

	1150-Rogers P & Company Ltd -Kenward Tool & Die -Easton Builders -Semcoat Technologies -Jenmar Colour Separations Inc -Simon Crane Rental Ltd 1170-Chamberlain Companies 1176-Elementary Teachers Federation of Ontario-Halton 1180-Buster Brown Apparel Inc 1182-Ontario English Catholic Teachers' Association OECTA 1190-Halton Secondary School Teachers' Federation OSSTF
Landmark Road (All)	3455-Comstock Canada - 3400-Brown Packaging Inc -L&A Diecrafts Ltd 3424-Humpty Dumpty Foods Ltd 3450-Calorific Construction Ltd -Dealt Construction -GCI Industries -Anjo Engineering & Consulting Ltd 3466-LA Rubber Inc 3472-Dayside Industries
Mainway (3260-3390)	3267-Burlington Technologies Inc 3285-Mainway Machine Tools New & Used Acme Saw Ltd -Tubex Technology Machinery Inc -TPH The Printing House Ltd -Mainway Engraving Systems -Cotswold Precision Co Ltd -Halton Electronics Auburn Industrial Services Ltd -Versa-Hoe Equipment Corpn 3291-Chicago Blower Sales

	-MWE Belting Company Ltd -Brown Falcon MAchine & Tool -McKellar Machine Products Ltd -Nixon Integrated Machining Designs Ltd 3295-AH Casting Services Ltd 3317-Halton Sheet Metal 3319-Rogers P & Company Ltd 3323-Maintemp Heating & Air Conditioning -Quantum Communications -Helec Insulation Ltd 3325-B&D Fabricating -West Windows -Hutten's Ground MAintenance -Try Mechanical 3327-DF Electronics -KGM Sales -Travis Industrial Maintenance Ltd 3329-Drake Water Systems Inc 3333-Allen Industrial Rubber Products 3335-Acre Aluminum Inc 3337-A&B Mitchell Industries Inc 3339-Frost Refrigeration & Air Conditioning -BS&S Courier 3385-Kingsbury Canada Inc -Keltour Controls - 3264-Aisco Systems Inc 3300-Prok Int'l -Jones Tool & Machine Co -Vern's Metal Stamping Inc -Pro Railing & Structural Iron 3310-Douwe Egberts Limited 3332-OECTA Halton Secondary Unit 3340-Mary Lee Interiors

	-Dental Power 3342-Bakker Advertising 3344-Town & Country Bookkeeping Service Ltd 3388-Canadian Fanner Co Ltd -Thomas Wire Die Ltd
Pioneer Road (All)	1149-Rehau Industries Inc 1153-Pioneer Industrial Mall -Reuse Centre -Tiyga Inc -Canadian Induction Processing Inc -JAB De-Reeler Systems Ltd -Burlington Centreless Grinding -Brant Custom Grinding Ltd -K&G Productions -World Wide Kiln Service -Anderson Cable Enterprises -Homemade Wine Crafts Ltd -KC Graphic -KCI Medical Canada Inc -Huffman Custom Woodworking -Exotic Signs -Ostram Sylvana Lighting Service -Laser FX Int'l - 1122-Diamond Canapower

PROJECT NUMBER: HAM-00801245-A0	
Site Address:	1160 Blair Road, Burlington, Ontario
Year: 1990	
Site Listing:	-Rotunda Office Building -Town & Country Bookkeeping Service Ltd -Loomis Courier Service Ltd -Adam Irrigation Systems

	-CSR Business Products Inc -Robinson's -Wurth Paul Ltd
Adjacent Properties:	
Blair Road (All)	1101-Pennzoil Quaker State Inc 1157-Secoroc A Div of Atlas Copco Canada Inc - 1100-ACCO Canadian Material Handling -Matthews Conveyor Company of Canada 1140-Jones Neon Displays Ltd 1150-S&S Delivery & Courier Service Ontario Ltd -Basciano-O'Connor Landscape Architects Ltd -Rhucon Construction Inc -Kangas Systems Inc -Burlington Concrete Service -GCI Equipment Rentals -Gotfryd Contracting -Investors Group -Jenmar Colour Separations Inc 1170-DSA Realty Ltd -Mac's Convenience Store 1176-Elementary Teachers Federation of Ontario-Halton 1190-Halton Secondary Teachers' association OSSTF
Landmark Road (All)	3415-Cor-Magnetics Inc 3455-Comstock Canada - 3400-Brown Packaging Inc -L&A Diecrafts Ltd 3424-Humpty Dumpty Foods Ltd 3450-Calorific Construction Ltd

	3466-LA Rubber Inc 3472-Burlington Ceramics & Supply
Mainway (3260-3390)	3267-Burlington Die Castings Co 3285-Multi Mainway Centre -Acme Saw Ltd -Tubex Technology Machinery Inc -TPH The Printing House Ltd -Laker Tool & Industrial Supply -Cotswold Precision Co Ltd -Auburn Industrial Services Ltd -Versa-Hoe Equipment Corpn 3291-Water Jet Specialties -Automation Specialties -Service Filtration of Canada 3295-Bennett & Wright Ltd -Brown Falcon MAchine & Tool 3317-Gates Air Systems Ltd 3319-Rogers P & Company Ltd 3321-Quality Cylinder Service & Machining Ltd 3323-Jobsite Equipment Inc -Chatelaine Kitchen & Bath Design -Helec Insulation Ltd 3325-Sealand Quality Foods -Antel Optronics Inc -Val Design Interior Inc -Try Mechanical -Micat Heat Exchanger Inc 3327-Sharp Valve & Instrumentation Inc -Lumeco Inc -Polyurcon Ltd -West Windows and Doors Ltd 3329-Antel Optronics Inc 3331-Eagle Quip Inc -Fairway Industrial 3333-Allen Industrial Rubber Products

	-Gourmet Coffee & Office Services 3335-BCMD Forming Co 3339-Modular Controls Canada 3385-Kingsbury Canada Inc -Keltour Controls - 3264-Aisco Systems Inc 3300-Swissline Industries Ltd -Jones Tool & Machine Co 3310-Douwe Egberts Limited 3312-Durkin Hayes Publishing Ltd 3330-Buster Brown Apparel Inc 3332-Cadcorp Inc 3334-Landstone Developments -Northnet REsearch Inc 3336-Stars Disc Jockey Service -Lakeview Livery Service 3340-Trade Arbed Canada Inc 3342-Canpeco Int'l Inc -Canada Kiln Service Ltd -ACEC Power Systems Canada -Kiln Technology Ltd 3388-Canadian Fanner Co Ltd -Thomas Wire Die Ltd
Pioneer Road (All)	1121-Hunter Drums Ltd 1149-Rehau Industries Inc 1153-Pioneer Industrial Mall -Long Garage Doors -Cain Cartage -MJ Drywall Services -Canadian Induction Processing Inc -Guenther AW Ltd -Hanna Canada Ltd

	-Skyway Saw Service Co Ltd -Burlington Centreless Grinding -Brant Custom Grinding Ltd -Burlington Hydraulics -Rotoflex Int'l -Wiltschek Henry A Sales & Service Inc -Rae Hydraulics -KC Graphics Basic Blanks -Cuddy Cabinets -Sylvana Lighting Service -Bes Construction -Desi's Roofing Company Ltd -All Four SEasons Roofing -One Custom Upholstery -Wilmar Printing Graphic Studio 1171-Bell Canada - 1122-Diamond Canapower

PROJECT NUMBER: HAM-00801245-A0	
Site Address:	1160 Blair Road, Burlington, Ontario
Year: 1985	
Site Listing:	-Rotunda Office Building -Town & Country Bookkeeping Service LTd -Robinson GW Ltd -CSR Business Products Ltd -Hunter JD Packaging -CA Supplies -Temprite Industries Ltd Indl Htrs -Robinson GW Co Ltd -Wurth Paul Ltd -Alchem Inc sls ofce -Paletta Brothers Meat Products Ltd

Adjacent Properties:	
Blair Road (All)	1101-Pennzoil Quaker State Inc 1157-Fagersta Secoroc Ltd - 1100-ACCO Canadian Material Handling 1140-Designs By Maynard -Aquaspa Industries Ltd -Pool Technology Ltd 1180-Alchem Inc sls ofce 1190-Paletta Brothers Meat Products Ltd
Landmark Road (All)	3415-Cor-Mag Inc 3435-Linear Technology 3455-Comstock Canada - 3400-Brown Packaging -W&F Distributors -L&A Diecrafts Ltd -Diplomat Coffee System -Aiton Power Ltd wrhse 3424-Humpty Dumpty Foods Ltd 3450-Calorific Construction Ltd 3466-LA Rubber Inc
Mainway (3260-3390)	3285-Multi Mainway Centre -TPH The Printing House Ltd -Cotswold Precision Co Ltd -Auburn Industrial Services Ltd -Acme Saw Ltd 3295-Bennett & Wright Ltd -Canadian Refractories

	-Computerland 3317-Gates Air Systems Ltd -Protech Audio Ltd 3323-Servicom -Chatelaine Kitchen Design -CCSI Sanitation Store -Helec Insulation Ltd 3325-Mano Bourdon Inc -Agnew Electrical Corporation 3327-ASPS Industrial Valves & Instrumentation Ltd -Peninsula Water Treatment -Polyurcon Ltd -Precision Repairs 3331-Eagle Quip Inc 3333-Allen Industrial Rubber Products 3335-Flexibox Canada Inc 3339-Modular Controls Canada 3385-Kingsbury Canada Inc -Keltour Controls - 3264-McKerlie Millen Automotive -Aisco Inc -Jones Tool & Machine Co 3280-Artwin Products Ltd 3300-Swissline Industries Ltd -Aisco Inc 3310-Douwe Egberts Limited 3312-Durkin Hayes Publishing Ltd 3330-Buster Brown Apparel Inc 3332-BF Business Forms Ltd 3334-Liburdi Engineering 3338-BMI Mechanical elect instrumentation contrs -Canadian Fanners Co Ltd fnry spls

Pioneer Road (All)	1121-Hunter Drums Ltd -Hunter Packaging Ltd 1149-Rehau Industries Inc 1153-Pioneer Industrial Mall -Cain Cartage -Combustion -Canadian Induction Processing Inc -Guenther AW Ltd -Skyway Saw Service Co Ltd -Salvisburg Holdings -Burlington Centreless Grinding -Harper Graphics -Pinedale Flowers 1171-Bell Canada - 1122-Diamond Canapower 1140-King Sanford Ltd

PROJECT NUMBER: HAM-00801245-A0	
Site Address:	1160 Blair Road, Burlington, Ontario
Year: 1980	
Site Listing:	-Rotunda Office Building -Town & Country Bookkeeping Service - Deere John Ltd -Cities Service Chemicals Ltd carbon block mfrs -White Motor Credit Corp of Canada -Mayfair Travel Ltd -Chef Coffee House -Educational Progress Company Ltd educ publishers -Hayes Publishing Ltd -Gibbes Wire & Steel Company Ltd -EAman-Riggs Lt

	-Temprite Industries Ltd indl htrs
Adjacent Properties:	
Blair Road (All)	1101-Quaker State Oil refining Company of Canada 1157-Fagersta Secoroc Ltd - 1100-ACCO Canadian Material Handling 1140-Western Supplies Ltd 1170-Norton Company Chemical Process Prod iv 1176-Skyline Steel Industries Ltd 1180-International Harvester Credit Corporation fin sls 1190-Alchem Inc sls ofce
Landmark Road (All)	3415-Cor-Mag Inc 3435-Linear Technology 3455-Comstock Int'l - 3400-Brown Packaging Co -Lightmaster Corporation Ltd -L&A Diecrafts Ltd -Diplomat Coffee System -Tri Automatic Vending Services Ltd -Keen Vending Enterprises Ltd -Aiton Power Ltd wrhse 3424-Humpty Dumpty Foods Ltd 3450-Steel & Stainless Fabricators Ltd 3466-LA Rubber & Plastics Ltd
Mainway (3260-3390)	3267-Burlington Die Castings Ltd

	3285-Multi Mainway Centre -TPH The Printing House Ltd -Frontier Refrigeration -Re-Jen Aire Systems Ltd -Kingston Mechanical Contracting Ltd 3295-Bennett & Wright Ltd -B&M Chemicals Ltd -Una Kem Pool Chemicals 3317-Gates Air Systems Ltd -Allen Industrial Rubber Products Co 3319-Stokes Plumbing Ltd 3321-Rieger Printing Ink Co Ltd 3323-Halton Tool & Fabricators Ltd -Chatelaine Kitchen Design -CK&D Wood Crafts -Machitech Ltd 3325-Dominion Safe-Aid Products -BMNK Tool & Machine Co -Abrasive Supply Co Ltd 3327-Trusty Treats Inc -Polyurcon Ltd -Solar Power Developments Ltd 3331-France Compressor Products of Canada 3333-Burlington Custom Refinishing Ltd -Air Craft Label Inc 3335-Flexibox Canada Inc -Photoflair Ltd 3337-Wear-Cote Canada div of Aisco Inc 3339-Quality Doll Inc -McInnis Equipment Ltd 3385-Kingsbury Canada Inc -Keltour Controls - 3264-McKerlie Millen Automotive -Aisco Inc -Jones Tool & Machine Co

	-Agnew Electrical Corporation 3280-Direct Welding & Industrial Supplies Ltd 3300-Swissline Industries Ltd -Hymatic Controls Company Ltd fluid power spec 3310-Douwe Egberts Limited 3312-TG Mechanical Products Ltd distr -Pneutech TG Ltd 3332-Automated Business Forms Ltd 3334-Kearns Advertising Group 3336-Culnane Fattori Associates Ltd adv agcy 3338-Burroughs Business Machines 3388-Canadian Fanners Co Ltd fndry spls
Pioneer Road (All)	1121-Hunter Drums Ltd 1153-Pioneer Industrial Mall -Sears Ltd Simpson Sears Burl Dely Depot McKay Metallurgical -Guenther AW Ltd -Skyway Saw Service Co Ltd -Snowshoe Insulation -Burlington Centreless Grinding ITT Canada Ltd Terryphone iv -Wholesale Florist 1171-Bell Canada - 1122-Diamond Canapower Ltd blr equip mfrs

PROJECT NUMBER: HAM-00801245-A0	
Site Address:	1160 Blair Road, Burlington, Ontario
Year: 1975	

Site Listing:	-Rotunda Office Building -Town & Country Bookkeeping Service -Deere John Ltd -Cities Service Chemicals Ltd carbon block mfrs -White Motor Credit Corp of Canada -Equipment Components Ltd equip distrs -Temprite Industries Ltd indl htrs -Chef Coffee Hse -Aiton Pipework & Process Plant Ltd -Mayfair Travel Ltd -Educational Progress Co Ltd -Gibbs Wire & Stl Co of Canada Ltd stl wire -Tec Contrs Ltd -Children's Aid Society of Halton -Bell Canada Eng -Ont Chicken Producers mktg
Adjacent Properties:	
Blair Road (All)	1101-Quaker State Oil refining Company of Canada 1157-Fagersta Secoroc Ltd - 1100-ACCO Canadian Material Handling 1170-Pratt & Lambert Incorp paints -Norton Co Chemical Process Prod Div 1176-Headland Homes 1180-Intl Harvester Cred Corpn fin sls 1190-IH Canada agric & consumer prod sls
Landmark Road (All)	3435-Linear Technology -Comstock Int'l - 3434-Humpty Dumpty Food Ltd

Mainway (3260-3390)	3267-Burlington Die Castings Ltd 3285-Mainway Trailers sls & serv -Marlboro RV Ltd -Stewart JM Indl & Automotive spls 3295-Travel Equip Canada Ltd 3321-Duny Mach Ltd 3329-Hermoff Mfg Co Ltd 3331-Boon's Crane Serv 3333-Fitzpatrick Stair Ltd 3335-Halton Renovations Ltd -Quality Signs trk lettering 3339-McInnis Equipment Ltd 3385-Kingsbury Canada Inc -Keltour Controls - 3264-Complete Mobile Wash Ltd -Jones TI & Mach Co Mainway Contrg -Mainway Sauna -Van der Meulen Constr -Westghse Canada Ltd 3280-B&M Chemicals Ltd janitorial spls -Una-Kem Mfg swimming pool chem 3300-Swissline Industries Ltd -Hymatic Controls Company Ltd fluid power spec 3310-Douwe Egberts Limited 3312-TG Mechanical Products Ltd distr -Johnson Controls Ltd htg & ventilating 3330-State Farm Ins claims 3332-Monogram Sant Prod of Canada Ltd 3334-Elastometal Ltd 3336-Culnane Fattori Associates Ltd adv agcy -Willis RG & Co Ltd

	3338-Int'l Harvester Canada constr & indl 3388-Can Fanner Co Ltd 3340-Settlement Corpn Ltd -Settlers of Niagara Ltd -Braun Rudy Lt
Pioneer Road (All)	1121-Hunter Drums Ltd 1149-Muntz Canada Ltd 1153-Pioneer Industrial Mall -Sears Ltd Simpson Sears Burl Dely Depot -Wylie Webb Co Ltd golf cart -P&M Vacuum Heat Treating -Endur Lubrication Ltd -Inomation Mfrs spring mkg mach -Burlington Centreless Grinding -ITT Canada Ltd Terryphone iv -Amex Automotive -Gordana Ind Ltd whol auto parts 1171-Bell Canada - 1122-Diamond Canapower Ltd blr equip mfrs

PROJECT NUMBER: HAM-00801245-A0	
Site Address:	1160 Blair Road, Burlington, Ontario
Year: 1970	
Site Listing:	-Address Not Listed
Adjacent Properties:	
Blair Road (All)	-Street Not Listed

Landmark Road (All)	-Street Not Listed
Mainway (3260-3390)	3267-Burlington Die Castings Ltd 3285-Mainway Trailers sls & serv -Mainway Mfg Co Ltd -Travel Equip of Can Ltd - 3264-Trailcar PRod Mfg Lt -Jones TI & Mach Co -Ivan's Tire Sls -Van der Meulen Constr Co Ltd 3280-Guenther-HildebrantL td mfr custom -Ont TI & Eng 3300-MCC Precision Prod Ltd -Remco Tire Distrs Ltd 3310-Douwe Egberts Limited
Pioneer Road (All)	1122-Diamond Canapower Ltd blr equip mfr

PROJECT NUMBER: HAM-00801245-A0	
Site Address:	1160 Blair Road, Burlington, Ontario
Year: 1965	
Site Listing:	-Address Not Listed
Adjacent Properties:	

Blair Road (All)	-Street Not Listed
Landmark Road (All)	-Street Not Listed
Mainway (3260-3390)	-Addresses Not Listed
Pioneer Road (All)	-Not Built On

PROJECT NUMBER: HAM-00801245-A0	
Site Address:	1160 Blair Road, Burlington, Ontario
Year: 1957	
Site Listing:	-Address Not Listed
Adjacent Properties:	
Blair Road (All)	-Street Not Listed
Landmark Road (All)	-Street Not Listed
Mainway (3260-3390)	-Street Not Listed
Pioneer Road (All)	-Street Not Listed

905-335-7600 x7701
905-335-7675
twyla.nicholson@burlington.ca

June 8, 2018

Ms. Kelsey Proks
Environmental Specialist
EXP Services Inc.
80 Bancroft Sreet
Hamilton, ON L8E 2W5

VIA EMAIL Kelsey.proks@exp.com

Dear Ms. Proks:

Re: Request for Access to Information
File No. 180-04-18-67

Thank you for your request received June 1, 2018 pursuant to the *Municipal Freedom of Information and Protection of Privacy Act* (the *Act*) for:

Re: 1160 Blair Road, Burlington
Date range: 1875 to Present
Requesting records:

- *Water course/sanitary and storm sewers*
- *Environmental concerns (general correspondence, occurrence reports, abatement*
- *Orders*
- *Spills*
- *Investigations/prosecutions*
- *Waste Issues/Landfills*

A search for responsive records was completed and no records were located. As such, access to the information requested cannot be granted, pursuant to section 22 (1) of the *Act*, as no such records exist at the City of Burlington. However, the request was transferred to Halton Region on June 5, 2018 as it may have custody of the records you seek.

Please note that Phase One and Phase Two Environmental Site Assessments and other related documents are publicly available on the city's website at:

https://www.burlington.ca/en/services-for-you/Archangel-Raphael-and-Marina-1160-blair-rd.asp

If you have any questions about this matter please feel free to contact Twyla Nicholson, Access & Privacy Coordinator for the City of Burlington at 905-335-7600, extension 7701.

As Head of the institution, I am responsible for this decision. You may request that this decision be reviewed by The Information and Privacy Commissioner of Ontario, 2 Bloor Street East, Suite 1400, Toronto, Ontario, M4W 1A8, telephone: 1-800-387-0073 or 416-326-3333. You have 30 days from the receipt of this letter to request a review. If you decide to request a review, please provide the Commissioner's office with a cheque for $25.00, the file number on this letter, a copy of this decision letter, and a copy of the original request for records that you submitted to the City.

Sincerely,

per A Holland

Angela Morgan
City Clerk

Legislative & Planning Services
Planning Services
1151 Bronte Road
Oakville ON L6M 3L1

July 3, 2018

Kelly Proks
Exp
80 Bancroft Street
Hamilton, ON L8E 2W5

Dear Kelly Proks:

RE: **Environmental Source Information Inventory Request**
Subject Property: **1160 Blair Road, Burlington**

This is in reference to your written request for information and signed waiver dated **May 22, 2018** and received on **June 5, 2018**. Halton Region staff reviewed Halton Region's **Environmental Source Information GIS Database** (previously known as Halton Region's Hazardous Land Use and Chemical Occurrence Environmental Protection GIS Database) and a summary of the information is provided in Table 1, attached, for the subject property mentioned above.

Please be reminded that the information in Table 1 was obtained from a variety of sources and dates as listed and the information may include confidential privileged information intended only for the addressee(s). Halton Region cannot guarantee or warrant that this information is accurate or complete nor can the Region be held responsible for any claim or liability that can or may arise from the provision of this information. Any use which a third party makes of this information, or any reliance on or decisions to be made based on this information, are the responsibility of such third parties. Halton Region accepts no responsibility for damages, if any, suffered by any third party as a result of decisions made or actions taken on the information contained in this document.

If you would like to obtain information regarding sewers discharge violations or spills to the sanitary sewer please contact David Large, Supervisor, Industrial Waste, Public Works Department, Wastewater Services Department, Ext 7723.

If you have any questions regarding this information, please contact the undersigned at ext. 3241.

Sincerely,

Behnam Doulatyari
Planner – Groundwater and Hydrology, Sustainable Planning

Table 1: Inventory Search for: **1160 Blair Road, Burlington**

Database and Sources	Validity Range	Last Updated	Information
Current or Historic Land Uses:			
Land Use Designations in Halton Region [1, 6, 7]	1950 - 2014	Jul 2015	Intake Protection Zone (Source Water Protection Plan)
Regional Planning Files[1]	1988 - 2017	Mar 2017	No records found
Halton Region's Employment Survey	2015	Dec 2015	BuildType: Light Industrial/Office Multiple-Unit Plaza NAICS Codes: 442298, 238210, 511211, 541213, 484210, 451120, 611610, 813990, 611620
Halton Region's Business Directories[1]	1977 - 2008	Aug 2008	SIC_DESC STONE, CLAY, GLASS, AND CONCRETE PRODUCTS, ABRASIVE, ASBESTOS, AND MISCELLANEOUS NONMETALLIC MINERAL PRODUCTS, NONCLAY REFRACTORIES NAICS 32712503 SIC_DESC EATING AND DRINKING PLACES, EATING AND DRINKING PLACES, EATING PLACES NAICS 72211019 SIC_DESC MOTOR FREIGHT TRANSPORTATION AND WAREHOUSING, TRUCKING AND COURIER SERVICES, EXCEPT AIR, LOCAL TRUCKING WITH STORAGE NAICS 48411009 SIC_DESC CONSTRUCTION-SPECIAL TRADE CONTRACTORS, MISCELLANEOUS SPECIAL TRADE CONTRACTORS, SPECIAL TRADE CONTRACTORS, NOT ELSEWHERE CLASSIFIED NAICS 23899026 SIC_DESC AMUSEMENT AND RECREATION SERVICES, MISCELLANEOUS

Database and Sources	Validity Range	Last Updated	Information
			AMUSEMENT AND RECREATION SERVICES, AMUSEMENT AND RECREATION SERVICES, NOT ELSEWHERE CLASSIFIED NAICS 71399031 SIC_DESC LEGAL SERVICES NAICS 54111002 SIC_DESC MISCELLANEOUS RETAIL, MISCELLANEOUS SHOPPING GOODS STORES, HOBBY, TOY, AND GAME SHOPS NAICS 45112021 SIC_DESC ENGINEERING, ACCOUNTING, RESEARCH, MANAGEMENT, AND RELATED SERVICES, ACCOUNTING, AUDITING, AND BOOKKEEPING SERVICES NAICS 54121910 SIC_DESC HOME FURNITURE, FURNISHINGS, AND EQUIPMENT STORES, RADIO, TELEVISION, CONSUMER ELECTRONICS, AND MUSIC STORES, COMPUTER AND COMPUTER SOFTWARE STORES NAICS 44312007 SIC_DESC AMUSEMENT AND RECREATION SERVICES, THEATRICAL PRODUCERS (EXCEPT MOTION PICTURE), BANDS, ORCHESTRAS, A, THEATRICAL PRODUCERS (EXCEPT MOTION PICTURE) AND MISCELLANEOUS TH NAICS 56131120 SIC_DESC BUSINESS SERVICES, CONSUMER CREDIT REPORTING AGENCIES, MERCANTILE REPORTING AGENCIES,, ADJUSTMENT AND COLLECTION SERVICES NAICS 56144002

The information contained in this document may include confidential privileged information intended only for the addressee(s). This material may be subject to the provisions of the Municipal Freedom of Information & Protection of Privacy Act. The information contained in this document may have been obtained from a variety of sources. Halton `Region accepts no responsibility for the accuracy and completeness of the information or the omission of data. Any use which a third party makes of this information, or any reliance on or decisions to be made based on this information, are the responsibility of such third parties. Halton Region accepts no responsibility for damages, if any, suffered by any third party as a result of decisions made or actions taken on the information contained in this document.

Database and Sources	Validity Range	Last Updated	Information
			SIC_DESC ENGINEERING, ACCOUNTING, RESEARCH, MANAGEMENT, AND RELATED SERVICES, MANAGEMENT AND PUBLIC RELATIONS SERVICES, BUSINESS CONSULTING SERVICES, NOT ELSEWHERE CLASSIFIED NAICS 54169033 SIC_DESC AUTOMOTIVE DEALERS AND GASOLINE SERVICE STATIONS, MOTORCYCLE DEALERS NAICS 52421001 SIC_DESC AMUSEMENT AND RECREATION SERVICES, MISCELLANEOUS AMUSEMENT AND RECREATION SERVICES, AMUSEMENT AND RECREATION SERVICES, NOT ELSEWHERE CLASSIFIED NAICS 61162014
Halton Region Fire Insurance Plans[1]	1950 - 2005	Jun 2006	No records found
Potentially Hazardous Land/Chemical Uses:			
National Pollutant Release Inventory[2]	1993 - 2015	Apr 2017	No records found
Inventory of Retail Fuel Storage Tanks [3]	1950 - 2009	Jan 2009	TNK_INSTAL 1/1/1989 TNK_MAT Steel TNK_FUEL Diesel
Inventory of PCB Storage Sites[4]	1986 - 2015	May 2017	No records found
Pesticide Licensee Database[4]	1986 - 2016	Apr 2017	No records found
Environmental Instruments:			
Environmental Compliance Approvals/ Certificates of	1996 – 2016	Apr 2017	No records found

The information contained in this document may include confidential privileged information intended only for the addressee(s). This material may be subject to the provisions of the Municipal Freedom of Information & Protection of Privacy Act. The information contained in this document may have been obtained from a variety of sources. Halton Region accepts no responsibility for the accuracy and completeness of the information or the omission of data. Any use which a third party makes of this information, or any reliance on or decisions to be made based on this information, are the responsibility of such third parties. Halton Region accepts no responsibility for damages, if any, suffered by any third party as a result of decisions made or actions taken on the information contained in this document.

Database and Sources	Validity Range	Last Updated	Information
Approval [4]			
Permits to Take Water [4]	1962 - 2016	May 2017	No records found
Environmental Incidents:			
Spills Action Centre Database[4]	1989 - 2014	Jul 2015	No records found
Environmental Non-Compliance[4]	1994 – 2015	May 2017	No records found
Environmental Orders[5]	1995-2016	May 2017	No records found
Waste Management Sites and Records [1, 4]	1950 - 2011	Jul 2015	No records found
Hazardous Waste Information System[4]	1986 - 2015	May 2017	**CARRIERS** CAR_NAME AUBURN INDUSTRIAL SERVICES LTD. Waste_Type_Codes (2002 – 2015): N/A **GENERATORS** GEN_NAME s.e. sales and service ltd Waste_Type_Codes (2015): 252 Waste_Char (2015): LIQUID INDUSTRIAL WASTE
Sources: [1]Halton Region; [2]Environment Canada; [3]Technical Standards and Safety Authority; [4] Ministry of the Environment and Climate Change; [5] Environmental Registry; [6] Ministry of Natural Resources and Forestry; [7] Niagara Escarpment Commission			

The information contained in this document may include confidential privileged information intended only for the addressee(s). This material may be subject to the provisions of the Municipal Freedom of Information & Protection of Privacy Act. The information contained in this document may have been obtained from a variety of sources. Halton `Region accepts no responsibility for the accuracy and completeness of the information or the omission of data. Any use which a third party makes of this information, or any reliance on or decisions to be made based on this information, are the responsibility of such third parties. Halton Region accepts no responsibility for damages, if any, suffered by any third party as a result of decisions made or actions taken on the information contained in this document.

Appendix G: Other Government Records

Facsimile Transmittal

To:	Ministry of the Environment	Date:	July 12, 2017
	Freedom of Information Office	Fax #:	1-416-314-4285

Subject:	Freedom of Information Request		
Sender:	Kelsey Proks	Pages:	3

Good day,

Please find enclosed a Freedom of Information Request for the property at 1160 Blair Road, Burlington, Ontario with the associated form and payment.

Should you have any questions, please feel free to contact me by email kelsey.proks@exp.com, or by phone 905-573-4000.

Thanks.

Regards,

Kelsey Proks, B.Sc.
Environmental Specialist
exp Services Inc.
t: +1.905.573.4000 x5075 f: 905-573-9693
80 Bancroft Street,
Hamilton, ON L8E 2W5
CANADA

exp.com | *legal disclaimer*

keep it green, read from the screen

Ontario Ministry of the Environment

Freedom of Information Request

This form is for requesting documents which are in the Ministry's files on environmental concerns related to properties. Please refer to the guide on the completion and use of this form. Our fax no. is (416) 314-4285.

Requester Data			For Ministry Use Only	
Name, Title, Company Name and Mailing Address of Requester Ms. Kelsey Proks **exp** Services Inc. 80 Bancroft Street Hamilton, Ontario L8E 2W5 Email Address: stephanie.hsia@exp.com			FOI Request No.	Date Request Received
			Fee Paid ☐ ACCT ☐ CHQ ☐ VISA/MC ☐ CASH	
Telephone/Fax Nos. Tel : (905) 573-4000 Fax : (905) 573-9693	Your Project/Reference No. HAM-00801245-A0	Signature of Requester	☐ CNR ☐ ER ☐ NOR ☐ SWR ☐ WCR ☐ SAC ☐ IEB ☐ EAA ☐ EMR ☐ SWA	

Request Parameters

Municipal Address / Lot, Concession, Geographic Township (**Municipal address essential for cities, towns or regions**)

1160 Blair Rd, Burlington, ON L7M 1K9

Present Property Owner(s) and Date(s) of Ownership

N/A

Previous Property Owner(s) and Date(s) of Ownership

N/A

Present/Previous Tenant(s),(if applicable)

N/A

Search Parameters Files older than 2 years may require $60.00 retrieval cost. There is no guarantee that records responsive to your request will be located.	**Specify Year(s) Requested**
Environmental concerns (General correspondence, occurrence reports, abatement)	1940-present
Orders	1940-present
Spills	1940-present
Investigations/prosecutions ▸ Owner/tenant information must be provided	1940-present
Waste Generator number/classes	1940-present

Certificates of Approval ▸ Proponent information must be provided

1985 and prior records are searched manually. **Search fees in excess of $300.00** could be incurred, depending on the types and years to be searched. Specify Certificates of Approval number (s) (if known). **If supporting documents are also required, mark SD box** and specify type e.g. maps, plans, hydrogeological reports, etc.

		SD	Specify Year(s) Requested
air - *emissions*			All years
water - *mains, treatment, ground level, standpipes & elevated storage, pumping stations (local & booster)*			All years
sewage - *sanitary, storm, treatment, stormwater, leachate & leachate treatment & sewage pump stations*			All years
waste water - *industrial discharge*			All years
waste sites - *disposal, landfill sites, transfer stations, processing sites, incinerator sites*			All years
waste systems	*- haulers: sewage, non-hazardous & hazardous waste*		All years
	- mobile waste processing units		All years
	- PCB destruction		All years
pesticides - *licenses*			All years

A $5.00 non-refundable application fee, payable to the Minister of Finance, is mandatory. The cost of locating on-site and/or preparing any record is $30.00/hour and 20 cents/page for photocopying and you will be contacted for approval for fees in excess of $30.00.

Ministry of the Environment and Climate Change

Freedom of Information and Protection of Privacy Office

12th Floor
40 St. Clair Avenue West
Toronto ON M4V 1M2
Tel: (416) 314-4075
Fax: (416) 314-4285

Ministère de l'Environnement et de l'Action en matière de changement climatique

Bureau de l'accès à l'information et de la protection de la vie privée

12e étage
40, avenue St. Clair ouest
Toronto ON M4V 1M2
Tél. : (416) 314-4075
Téléc. : (416) 314-4285

RECEIVED JUL 3 1 2017

Ontario

July 26, 2017

Kelsey Proks
exp Services Inc.
80 Bancroft St
Hamilton, ON L8E 2W5

Dear Kelsey Proks:

RE: *Freedom of Information and Protection of Privacy Act* Request
Our File #: A-2017-04944, Your Reference #: HAM-00801245-A0

This letter is in response to your request made pursuant to the *Freedom of Information and Protection of Privacy Act* relating to 1160 Blair Road, Burlington.

After a thorough search of the Ministry's Halton-Peel District Office, Investigations and Enforcement Branch, Environmental Monitoring and Reporting Branch, Sector Compliance Branch and Safe Drinking Water Branch, records were located in response to your request. It is my decision to provide partial access to the attached information. To protect privacy, personal information has been withheld in accordance with Section 21(1)(f) of the Act.

In accordance with Section 57 of the *Freedom of Information and Protection of Privacy Act*, detailed below are our charges:

• Search Time 1 hour @ $30/hour	$ 30.00
• Copying 16 pages @ $0.20/page	3.20
• Delivery	3.00
• **Total**	**$ 36.20**
• Deposit Received	- 30.00
• **BALANCE WAIVED (NOT REQUIRED)**	**$ 6.20**

To conduct a search through the files of the Environmental Approvals Branch requires an additional 8 hours. If you would like us to search for Environmental Compliance Approvals/Certificates of Approval at the Environmental Approvals Branch (EAB), please forward to me at the above address payment by money order or cheque (made payable to the "Minister of Finance (FOI)") or by credit card in the amount of $240.00. **As EAB may have filed approval records by the proponent of the approval (current/former property owner/tenants of the property) rather than the site address, you will be required to provide all current/former property owner/tenant names for the search years you requested in your application when submitting payment for this search.** Please note that there is no guarantee any records will be located responsive to your request. Credit card forms are available on the Ministry's website http://www.ontario.ca/environment-and-energy/freedom-information-request-form-credit-card-form. Please note, a request for records must usually be answered within 30 calendar days, however Section 27 allows for time extensions under certain circumstances. If you choose to have the search conducted at the Environmental Approvals Branch, the time for answering your request will be extended for an additional 30 days.

The District Office has advised that there may be inactive records in the Records Centre, Mississauga. To retrieve these files there is a charge of $60.00 with no guarantee that any records will be located responsive to your request. If you would like us to retrieve these files, please forward to me at the above address payment by money order or cheque (made payable to the "Minister of Finance (FOI)") or by credit card in the amount of $60.00. Credit card forms are available on the Ministry's website http://www.ontario.ca/environment-and-energy/freedom-information-request-form-credit-card-form. Please note, a request for records must usually be answered within 30 calendar days, however Section 27 allows for time extensions under certain circumstances. If you choose to have the files retrieved from the Records Centre, the time for answering your request will be extended for an additional 30 days.

You may request a review of my decision by contacting the Information and Privacy Commissioner/Ontario, 2 Bloor Street East, Suite 1400, Toronto, ON M4W 1A8 (800-387-0073 or 416-326-3333). Please note that there is a $25.00 fee and you only have 30 days from receipt of this letter to request a review.

If you have any questions regarding this matter, please contact Michael Kolaric at 416-327-3036.

Yours truly,

Janet Dadufalza
FOI Manager

Attachments

Ontario

Ministry of the Environment
Ministère de l'Environnement

INCIDENT REPORT

Reference Number:	2174-966NQF	File Storage Number:	SI HP BU BL 100
Module:	Incident Reporting	Module Type:	Pollution Incident Report (PIR)
Cross Reference:	(doc link)	Task Link:	0014-966NVA
Originating Document:		Created by:	Karen Wassink
Incident Report Reference Number:		2174-966NQF	
Date Created:	2013/03/26	Date Completed:	2013/12/05
Bring Forward Date:		Bring Forward Reason:	
Status:	Closed		
Program	Waste - Solid/Non-hazardous	Activity:	Pollution Incident Reports

Is this an air emission (measured or modelled) or wastewater (sewage) discharge exceedance that will become part of the Environmental Compliance Report?

(legislation, certificate of approval, order, or guideline)

○ Yes ● No ○ To be determined *Click here for Guidance*

Caller or PO Information

s.21

[redacted]

MOE Information

Date & Time Reported to MOE:	2013/03/26 13:39		
Office Receiving Incident Report:	Halton-Peel District Office		
Incident Info Received By:	Karen Wassink		
MOE Response:	Planned Field Response	Site Region:	Central
Date & Time of MOE Arrival at Scene:	2013/03/26 10:45		
Master Incident Report Number:			

SAC Action Class:			
Non-Standard Procedure:	No		
ERP Call-out Initiated:			

Client(s)

Client Details

Site(s)

Site Details
1160 Blair Road Address: 1160 Blair Rd, Burlington, City, Regional Municipality of Halton District Office: Halton-Peel Site #: 1935-966NPG

Incident Information

Incident Summary:	Garbage *cannot be longer than 60 characters*
Incident Description:	Email from [redacted] March 21, 2013. I have a big issue with some dumping of furniture, oil filters, paint cans, debris, some electronics...[redacted] it is a water runoff ditch between properties that has been basically blocked off with all this debris and has reduced any water flow. [redacted] and there could be some contamination. So if your not to busy would be happy to give you a tour. April 8/13 spoke with Craig Powell, CofB, meeting Wed. April 10/13 at site. April 10/13; Met Craig Powell on site. He will look to see who ownes the property and if it falls under the CofB. April 25/13; Powell indicated it is not City property. Drove by the site, more landscaping debris on site. Left vm for real estate 416.674.7900. Also noted on sign: Elliott Goldspink 905.599.1702. Chris Wicken, 416.859.9425. May 10/13; Spoke with Elliot he provided Chris's email. chris.wicken@cbre.com - email: Hello Chris, I spoke with your colleague Elliot and he provided me your contact information. Can you please provide the contact information for the property manager at the 1160 Blair Road location? Phone number and/or email would be great. Thank you for your help. Karen Karen – please see below Thanks, Debbie Quattrin Senior Property Manager Prime Real Estate Group Inc. Phone number: 416-749-9954 ext. 225 Fax number: 416-748-9163

s.21

s.21

	Toll Free: 1-866-998-2227 d.quattrin@primerealestategroup.ca Spoke with Debbie who indicated that they are aware of the issue and have been trying to clean it up. She said that people have been illegally dumping waste back there. [redacted] will keep on the issue. I informed her that I will check with the neighbours to see if anyone has surveillance cameras. Left a message for [redacted] to update [redacted] and see if [redacted] has cameras. October 9/13:KW The garbage has been cleaned up in this area and a berm has been put in place to stop people from illegally dumping there. NFAR.

Links & Comments:	
Attachments Names:	

Date & Time of Incident	Incident Date Confirmation? Estimated 2013/03/21		
Source Type:		Sector Type:	
Nearest Watercourse:		Watershed Category Code:	
Environmental Impact:	Possible		
Nature of Impact:			
Incident Event:		Incident Reason:	
Damaged Party:	No		

Contaminants Table

Contaminant Name	Code	UN#	Limit	Quantity	[units]	[freq]

Controller of Material:		Owner of Material:	
Estimated Clean Up Cost:		Who Cleaned Up:	
% Clean Up:	%	MOE/Other Agencies Involved:	

Voluntary / Mandatory Abatement

Is there Voluntary Abatement Activity?	○ Yes	● No	○ To be determined

Voluntary / Mandatory Compliance Items

Type	Parent RefNo	Work Summary (may be truncated)	Date	AttainList

Offence(s)

Suspected Violation(s)/Offence(s):	
Act - Regulation - Section, Description (General Offence)	

Provincial Officer:

Name: Karen Wassink
Badge No: 758

Work Unit:
District/Area Office: Halton-Peel District Office
Date: 2013/10/11

Signature:

Supervisor:

Name: Ryan Thorsley

Work Unit:
District/Area Office: Halton-Peel District Office
Date: 2013/12/05

Signature:



Ontario

Ministry of the Environment
Ministère de l'Environnement

INCIDENT REPORT

Reference Number:	0434-98VGG9	File Storage Number:	SI HP BU BL 100
Module:	Incident Reporting	Module Type:	Pollution Incident Report (PIR)
Cross Reference:	(doc link)	Task Link:	3260-98VGM2
Originating Document:		Created by:	Karen Wassink
Incident Report Reference Number:		0434-98VGG9	
Date Created:	2013/06/21	Date Completed:	2013/12/05
Bring Forward Date:		Bring Forward Reason:	
Status:	Closed		
Program	Air	Activity:	Pollution Incident Reports

Is this an air emission (measured or modelled) or wastewater (sewage) discharge exceedance that will become part of the Environmental Compliance Report?

(legislation, certificate of approval, order, or guideline)

○ Yes ● No ○ To be determined *Click here for Guidance*

Caller or PO Information

Reported By:			
First Name: Karen	Last Name: Wassink		
Contact Mailing Address			
Municipality:			
Burlington			

Reported By:	

MOE Information

Date & Time Reported to MOE:	2013/06/21 08:19		
Office Receiving Incident Report:	Halton-Peel District Office		
Incident Info Received By:	Karen Wassink		
MOE Response:	Deferred Field Response	Site Region:	Central
Date & Time of MOE Arrival at Scene:	2013/06/21		
Master Incident Report Number:			
SAC Action Class:			
Non-Standard Procedure:	No		
ERP Call-out Initiated:			

Client(s)

Client Details

Site(s)

Site Details
1160 Blair Road Address: 1160 Blair Rd, Burlington, City, Regional Municipality of Halton District Office: Halton-Peel LIO GeoReference: Zone: 17, UTM Easting: 597254.56, UTM Northing: 4802100.5, Latitude: 43.36547, Longitude: -79.79968 Site #: 1935-966NPG

Incident Information

Incident Summary:	paint spray *cannot be longer than 60 characters*
Incident Description:	During a drive by I observed a person spray painting a metal structure half way into the bay door on site. Because of my safety I chose not to stop and speak to anyone at that time. Company name: Absolute Custom Steel Fabricating, Unit #2 905.320.6627. At the office I emailed the property management company regarding the above. Debbie Quattrin Senior Property Manager Prime Real Estate Group Inc. 416.749.9954 x 225 Debbie indicated that the company is not permitted to spray paint and will speak to them and that if they are she will call me back. September 18/13 No calls or emails rec'd by Debbie. Drove by site, did not observe any spray painting and no evidence of spray painting outside of the garage door. NFA at this time.

Links & Comments:	
Attachments Names:	

Date & Time of Incident	**Incident Date Confirmation?** Actual 2013/06/19 10:00		
Source Type:		**Sector Type:**	
Nearest Watercourse:		**Watershed Category Code:**	
Environmental Impact:			
Nature of Impact:			
Incident Event:		**Incident Reason:**	
Damaged Party:	No		

Contaminants Table

Contaminant Name	Code	UN#	Limit	Quantity	[units]	[freq]

Controller of Material:		Owner of Material:	
Estimated Clean Up Cost:		Who Cleaned Up:	
% Clean Up:	%	MOE/Other Agencies Involved:	

Voluntary / Mandatory Abatement

Is there Voluntary Abatement Activity?	○ Yes	● No	○ To be determined

Voluntary / Mandatory Compliance Items

Type	Parent RefNo	Work Summary (may be truncated)	Date	AttainList

Offence(s)

Suspected Violation(s)/Offence(s):	
Act - Regulation - Section, Description (General Offence)	

Provincial Officer:

Name: Karen Wassink
Badge No: 758
Work Unit:
District/Area Office: Halton-Peel District Office
Date: 2013/09/19
Signature:

Supervisor:

Name: Ryan Thorsley
Work Unit:
District/Area Office: Halton-Peel District Office
Date: 2013/12/05
Signature:





Generator Details

Registration/Notification Number

ON8863663

Legal Company Name

Primary Name	Royal Lepage State Realty Brokerage	Division Name	NA

Company Operating Name

Primary Name	Royal Lepage State Realty Brokerage	Division Name	NA

Mailing Address

Division Building	NA	Post Box Number	NA
Address Line 1	987 Rymal Road East	Address Line 2	NA
Town/City	Hamilton	Postal Code / Zip Code	L8W3M2
County (if inside Ontario)	HAMILTON-WENTWORTH R. M.	Province/State (If inside Canada/US)	ONTARIO
County (if outside Ontario)	NA	Province / State (If outside Canada / US)	NA
Country	Canada		

Site Location

This should be the street address of the site that is being registered. You are required to register each site that generates hazardous waste separately.

Division Building	NA	Post Box Number	NA
Address Line 1	1160 Blair Road		
Address Line 2	NA		
Town/City	Burlington	Postal Code / Zip Code	L7M1K9
County (if inside Ontario)	HALTON (R. M.)	Province / State (If inside Canada / US)	ONTARIO
County (if outside Ontario)	NA	Province / State (If outside Canada / US)	NA
Country	Canada		

Company Official



Company Name: **Royal Lepage State Realty Brokerage**
Company Number: **ON8863663 (Generator)**

Active Waste Classes

Active Waste Class Listing

Add New Waste Class Inactive waste classes

Active On-site Waste Classes

Waste Class	View Details	Hazardous Waste Number (per waste stream)	Reg. 347 Schedules	Disposal Method	Part 2B required	Part 2B complete	Physical State	Off-Site	Status
146 - L	View Details	N/A					Solid	Off-Site	Active

Back

Ontario This site maintained by the Government of Ontario

Technical inquires to Webmaster.
© 2002 Queen's Printer for Ontario



Generator Details

Registration/Notification Number

ON5984348

Legal Company Name

Primary Name:	s.e. sales and service ltd	Division Name:	NA

Company Operating Name

Primary Name:	s.e. sales and service ltd	Division Name:	NA

Mailing Address


Division Building:	NA	Post Box Number:	NA
Address Line 1:	1490 speers rd #1	Address Line 2:	NA
Town/City:	oakville	Postal Code / Zip Code:	L6L2X6
County: (if inside Ontario)	HALTON (R. M.)	Province/State (If inside Canada/US)	ONTARIO
County: (if outside Ontario)	NA	Province / State (If outside Canada / US)	NA
Country:	Canada		

Site Location

This should be the street address of the site that is being registered. You are required to register each site that generates hazardous waste separately.

Division Building:	NA	Post Box Number:	NA
Address Line 1:	1160 blair rd		
Address Line 2:	NA		
Town/City:	burlington	Postal Code / Zip Code:	L8N1A9
County: (if inside Ontario)	HALTON (R. M.)	Province / State (If inside Canada / US)	ONTARIO
County: (if outside Ontario)	NA	Province / State (If outside Canada / US)	NA
Country:	Canada		

Company Official



Company Name: s.e. sales and service ltd
Company Number: ON5984348 (Generator)

Active Waste Classes

Active Waste Class Listing

Add New Waste Class Inactive waste classes

Active Off-site Waste Classes

Waste Class	View Details	Hazardous Waste Number (per waste stream)	Reg. 347 Schedules	Disposal Method	Part 2B required	Part 2B complete	Physical State	Off-Site	Status	UnRegister Waste Class
213 - I	View details	Incomplete		Incomplete	Incomplete	Incomplete	Liquid	Off-Site	Active	☐
233 - H	View Details	Incomplete		Incomplete	Incomplete	Incomplete	Solid	Off-Site	Active	☐
233 - I	View Details	Incomplete		Incomplete	Incomplete	Incomplete	Liquid	Off-Site	Active	☐
252 - L	View Details	N/A					Liquid	Off-Site	Active	☐

Unregister Selected Classes

Back

Ministry of the Environment
Ontario

Ministère de l'Environnement

135 St. Clair Avenue West
Suite 100
Toronto, Ontario
M4V 1P5

135 avenue St. Clair ouest
Bureau 100
Toronto (Ontario)
M4V 1P5

May 29, 1987

Jenmar Colour Separations Inc.
1160 Blair Rd.
Burlington, Ont.
L7M 1K9

Attn: Mr. E. McGhie
President

Dear Mr. McGhie:

RE: Acknowledgement of Subject Waste Registration

As prescribed by Section 15(3) of Ontario Regulation 309, this letter acknowledges receipt of your Generator Registration Report(s) dated **September 23, 1986 and telephone conversation of May 20/87 with you** for the following site:

1160 Blair Rd.
Burlington, Ont.

The Generator Registration Number assigned to your company at this site is:

ON0646200

Please note that this Generator Registration Number must be used only in conjunction with the site for which it was issued.

Please ensure that the company name shown on this letter is complete and accurate. This would be the corporate name or, if a partnership or proprietorship, the name of the principal(s). If you intend to carry on business under a separate name or style, this should also be entered. If there is a discrepancy, it is your responsibility to re-register providing us with your complete and accurate company name.

A list of the waste stream(s) covered by this acknowledgement is attached to this letter as Schedule "A".

For off-site disposal of subject wastes, the waste number(s) describing the waste stream(s) in Schedule "A"

International Year of Shelter for the Homeless
1987
Année internationale du logement des sans-abri

.../2

and the Generator Registration Number must be entered on manifest forms for each waste transaction after you have received this generator registration document. A copy of an example manifest form is attached for your information.

For on-site disposal of subject wastes covered by this acknowledgement, including on-site incineration, landfilling and discharges to sanitary sewers, every generator shall retain records for a period of at least two years. These records shall include the generator registration number, waste name(s), waste number(s), quantity and disposition of the waste(s).

For off-site disposal of any registerable solid wastes shown in Schedule "A" (waste classes ending in the letter "N"), manifesting is not required at this time. These wastes can be disposed of at most approved municipal landfilling sites.

The selection of accurate waste classes is the responsibility of each waste generator. This acknowledgement must not be considered as a confirmation of the accuracy of information submitted by you. Based on the information you have provided, the waste class(es) that has (have) been selected appear(s) to be correct. If, due to new information or re-assessment of information submitted, you feel your waste is inappropriately classified, you should apply for a revision to your registration using the Generator Registration Report, Form 2. Should the waste class(es) that you have selected be deemed incorrect by the Ministry, or improper waste disposal occurs at any time, you may be subject to legal action as provided by the Environmental Protection Act and Regulation 309.

Your Generator Registration Report has now been forwarded to the District Office of this Ministry that is closest to your generating site. The District Office will be conducting a post-registration audit and may be contacting you for additional information or may be conducting site visits.

It is important to note that under Section 15(4) of Ontario Regulation 309, a new Generator Registration Report must be submitted to the Ministry within fifteen (15) days for any of the following reasons:

1. If the name, address or telephone number of your company or waste generating site changes.

2. If the description, the waste class or physical or chemical characteristics of your registered wastes change(s).

3. If you generate a hazardous or liquid industrial waste that has not been registered with the Ministry.

If the quantity of registered wastes or your carrier or receiver changes, automatic re-registration is not required. However, in order to update our file, we may periodically request additional information when we observe or suspect a significant change as compared to the most recent information submitted by you for registration purposes.

Should you have any questions concerning generator registration or manifesting requirements, please contact the Waste Management Branch Reviewer identified below at 323-5227.

Yours truly,

Director
Regulation 309, R.R.O., 1980
Environmental Protection Act

Waste Management Branch Reviewer: T. Jaffer

EAS/gwm

Enclosure

LE 03 07

ADDITIONAL COMMENTS:

The number of wastes reported in Field 11 of Part 1 of your Generator Registration Report (GRR) does not correspond to the number of wastes included in Part 2 of the GRR (i.e., does not correspond to the number of copies of page 2 submitted in your GRR). Should there be additional wastes which require registration, other than those shown in Schedule "A" of this letter, re-registration would be required for these additional wastes.

.../4

SCHEDULE "A"

This attached Schedule forms part of the acknowledgement of generator registration for the facility and site identified by Generator Registration Number ON0646200, dated at Toronto, this 29th day of May, 1987.

	Waste Stream	Waste Class
1.	Spent photo processing fixer	264T

Waste Management Branch Reviewer: _____
T. Jaffer

9/9.75

Kelsey Proks

From: Public Information Services <publicinformationservices@tssa.org>
Sent: Tuesday, July 18, 2017 4:32 PM
To: Kelsey Proks
Subject: RE: Tank search for Burlington, Ontario

Hello Kelsey,

Thank you for your inquiry.

I have searched the below noted address (addresses) and I have located the following record:

- 1160 Blair Road, Burlington, Ontario: 1 expired propane tank, 1 expired propane refill center, 2 expired liquid fuel tanks, and 1 expired private fuel outlet.
- 1171 Pioneer Road, Burlington, Ontario: 2 expired liquid fuel tanks, and 1 expired private fuel outlet.

For a more detailed report including underground fuel storage tank details and copies of all inspection reports, please submit your request in writing to Public Information Services via e-mail (publicinformationservices@tssa.org) or through mail along with a fee of $56.50 (including HST) per location. The fee is payable with credit card (Visa or MasterCard) or with a cheque made payable to TSSA.

Thank you and have a great,

Sherees

Sherees Thompson | Public Information Agent
Facilities
345 Carlingview Drive
Toronto, Ontario M9W 6N9
Tel: +1-416-734-3363 | Fax: +1-416-231-6183 | E-Mail: sthompson@tssa.org
www.tssa.org

Employeur remarquable du Canada 2016 PARTENARIAT EN ÉDUCATION
Canada's Outstanding Employer 2016 THE LEARNING PARTNERSHIP

From: Kelsey Proks [mailto:Kelsey.Proks@exp.com]
Sent: Wednesday, July 12, 2017 1:54 PM
To: Public Information Services
Subject: Tank search for Burlington, Ontario

Good afternoon,

Could you please perform a tank search for the following properties located Burlington, ON;

- 1140 Blair Road
- 1150 Blair Road
- 1157 Blair Road

- 1160 Blair Road
- 1176 Blair Road
- 1180 Blair Road
- 1153 Pioneer Road
- 1171 Pioneer Road
- 3310 Mainway
- 3312 Mainway

Your assistance is greatly appreciated,

Kelsey

Kelsey Proks, B.Sc.
Environmental Specialist
exp Services Inc.
t: +1.905.573.4000 x5075 | e: kelsey.proks@**exp**.com
80 Bancroft Street,
Hamilton, ON L8E 2W5
CANADA

This electronic message and any attached documents are intended only for the named recipients. This communication from the Technical Standards and Safety Authority may contain information that is privileged, confidential or otherwise protected from disclosure and it must not be disclosed, copied, forwarded or distributed without authorization. If you have received this message in error, please notify the sender immediately and delete the original message.

TECHNICAL STANDARDS & SAFETY AUTHORITY
TSSA

345 Carlingview Drive
Toronto Ontario M9W 6N9
Tel 416 734 3300
Fax. 416 231 1626
Toll Free 1 877 682 8772

www.tssa.org

RECEIVED AUG 2 2 2017

Tel: (416) 734-3570
Fax: (416) 734-3568

18 August 2017
File No: FS 63025

Erik Enders
Environmental Geoscientist
EXP SERVICES INC.
80 Bancroft Street
HAMILTON ON L8E 2W5

Dear Sir:

RE: 1160 Blair Road, Burlington, Ontario

This is with reference to your request and fee of $50.00 + HST, for information on the above location.

Enclosed are computerised screen prints showing an expired private fuel outlet and an expired propane refill centre along with equipment details showing underground fuel storage tank details and above ground propane storage tank details.

The *Technical Standards and Safety Act* and associated regulations do not require the registration of private fuel outlets. Nor does it require that any documentation on these facilities be submitted to, or reviewed or approved by TSSA. As a result TSSA has limited information on these facilities. TSSA cautions that any information provided may be inaccurate, incomplete or out of date.

After a search of our files, TSSA has no record of any further outstanding instructions, incident reports, fuel oil spills, or contamination records respecting the above-mentioned property.

This is all the information the Fuels Safety Division has at this time regarding the above address.

It should be noted that the Fuels Safety Division did not register private fuel underground/aboveground storage tanks prior to January of 1990 or furnace oil tanks prior to May 1, 2002. Also note that the Fuels Safety Division does not register waste oil tanks in apartments, office buildings, residences etc. or ABOVEGROUND gas or diesel tanks.

.. 2

TSSA does not make any representations or warranties with respect to the accuracy or completeness of any records released by TSSA, and the user assumes all risk in using or relying on released records.

Yours truly,

Prem Lal
Coordinator, Public Information Services

Oracle Installed Base

Navigator Favorites Home Profile Sign Out Help

Item Instances

Item Instances | Transactions | Systems

Quick Find Item Instance Go Advanced Search

Logged In As PLAL

General
Additional Attributes
Assets
Party Relationships
Owner
Parties
Accounts
Contacts
Summary
Pricing
Counters
Contracts
Notes
Transactions
Service Requests
Repair Orders
History
Operating Units
Configuration

Item Instance Details

Item Instance: 9918564
Item: FS PRIVATE FUEL OUTLET - SELF SERVE
Item Description: Fuels Safety Private Fuel Outlet - Self Serve

General Attributes

Organization Name TSSA Item Master
Instance Name
Last Version Label 1
Version Label Date 16-MAR-1992 0:00
Revision
New Version Label
System Go
External Reference
Item Instance Type
Accounting Classification Customer Product
Operational Status Not Used
Lot Number : not lot-controlled
Status EXPIRED
Condition
Quantity 1
UOM Each
Start Date 16-MAR-1992
Start Time 0:00
Shipped On Date
Shipped On Time
End Date 17-MAR-1992
End Time 0:00
Return By Date
Return By Time
Actual Return Date
Actual Return Time

* Indicates required field.
Time format is HH24:MM
Note: You do not have permission to make updates in this page.

☑ Creation Completed

Owner

Party Type Party
Party Name: GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD
Party Number: 170337
Account Number: 77034
Account Name GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD

Current Location

* Type Party Site Go
Party Name GOTFRYD CONTR Go
Party Number 170337 Go
*Line 1 1160 BLAIR RD Go
Site Number 172313 Go
Address 1160 BLAIR RD
BURLINGTON, L7M 1K9, CA

Installed At

Installed Date 16-MAR-1992 Installed Time 0:00

Time format is HH24:MM

Change in installed date does not change contract date.

Type [ ] Go

Order

Sales Order Number

Sales Order Date

Sales Order Line

Purchase Order Number

Agreement Name

Item Flags

- [x] BOM Enabled
- [x] IB Trackable
- [x] Inventory Trackable
- [x] Sellable
- [ ] Shippable

Item Views

- [ ] Merchant
- [x] Customer

Descriptive Flexfields

Context Value: FS Facility

Select Context Value and click 'Go' to show relevant fields.

Facility Type 2

Facility Type 3

Total Capacity - Liquid Fuel Tanks (L): 0

Total Capacity - Propane Tank s (USWG)

* Previous Facility Type

Previous Instance Number

Item Instances Home Profile Sign Out Help

Copyright 2006, Oracle Corporation. All rights reserved.

Installed Base

View : Item Instance : 11082822

Item	**FS LIQUID FUEL TANK**	System Owner	**GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD**
Item Description	**FS Liquid Fuel Tank**	Account Number	**77034**

Other Item Instance Details

- Transaction History
- Item Instance History
- Operating Units
- Contracts
- Orders
- Service Requests
- Orders and Directives
- View Relationship Graphically
- OMS Orders

General | Location | Associations | Configuration | Counters | Notes

External Reference		New Version Label	
Organization	**TSSA Item Master**	Last Version Label	**1**
Revision		Creation Date	**02-Oct-1989 00:00:00**
Instance Name		Status	**EXPIRED**
Quantity	**1**	Install Date	**02-Oct-1989 00:00:00**
UOM	**Each**	Expiration Date	**03-Oct-1989 00:00:00**
Item Instance Type		Shipped On Date	
Item Condition		Return By Date	
Accounting Classification	**Customer Product**	Actual Return Date	
Operational Status Code	**Not Used**		

⊟Hide Instance Flex Fields

⊞Show Additional Attributes

Fuel Type1	**Diesel** Diesel
Fuel Type2	
Fuel Type3	
Capacity (L)	**45460**
Tank Material	**Steel** Steel
Tank Type	**Liquid Fuel Single Wall UST** Liquid Fuel Single Wall UST
FS Corrosion Protection	**Sacrificial anode** Sacrificial anode
Overfill Protection Type	
Installation Year	**1989**
ULC Standard	
Manufacturer	
Model	
Serial Number	
Description	**2008V UNDERGROUND TANK**

Return to Instance Search

Item Instance Counters Mass Update Home Logout Preferences Help

Privacy Statement

Copyright (c) 2006, Oracle. All rights reserved.

Installed Base

Item	**FS LIQUID FUEL TANK**	System	
		Owner	**GOTFRYD CONTRACTING LTD ATTN EDDY GOTFRYD**
Item Description	**FS Liquid Fuel Tank**	Account Number	**77034**

General | Location | Associations | Configuration | Counters | Notes

External Reference		New Version Label	
Organization	**TSSA Item Master**	Last Version Label	**1**
Revision		Creation Date	**02-Oct-1989 00:00:00**
Instance Name		Status	**EXPIRED**
Quantity	**1**	Install Date	**02-Oct-1989 00:00:00**
UOM	**Each**	Expiration Date	**03-Oct-1989 00:00:00**
Item Instance Type		Shipped On Date	
Item Condition		Return By Date	
Accounting Classification	**Customer Product**	Actual Return Date	
Operational Status Code	**Not Used**		

Other Item Instance Details

Transaction History
Item Instance History
Operating Units
Contracts Orders
Service Requests
Orders and Directives
View Relationship Graphically
OMS Orders

Hide Instance Flex Fields

Fuel Type1	**Diesel** Diesel
Fuel Type2	
Fuel Type3	
Capacity (L)	**45460**
Tank Material	**Steel** Steel
Tank Type	**Liquid Fuel Single Wall UST** Liquid Fuel Single Wall UST
FS Corrosion Protection	**Sacrificial anode** Sacrificial anode
Overfill Protection Type	
Installation Year	**1989**
ULC Standard	
Manufacturer	
Model	
Serial Number	
Description	**2008V UNDERGROUND TANK**

Show Additional Attributes

Oracle Installed Base

Navigator Favorites Home Profile Sign Out Help

Item Instances

Item Instances | Transactions | Systems

Quick Find Item Instance Go Advanced Search

Logged In As PLAL

General
Additional Attributes
Assets
Party Relationships
Owner
Parties
Accounts
Contacts
Summary
Pricing
Counters
Contracts
Notes
Transactions
Service Requests
Repair Orders
History
Operating Units
Configuration

Item Instance Details

Item Instance: 9204839
Item: FS PROPANE REFILL CNTR - CYLR FILL
Item Description: FS Propane Refill Cntr - Cylr Fill

General Attributes

Organization Name TSSA Item Master
Instance Name
Last Version Label 1
Version Label Date 11-SEP-1991 0:00
Revision
New Version Label
System Go
External Reference
Item Instance Type
Accounting Classification Customer Product
Operational Status Not Used
Lot Number : not lot-controlled
Status EXPIRED
Condition
Quantity 1
UOM Each
Start Date 11-SEP-1991
Start Time 0:00
Shipped On Date
Shipped On Time
End Date 17-JUN-1992
End Time 0:00
Return By Date
Return By Time
Actual Return Date
Actual Return Time

* Indicates required field.
Time format is HH24:MM
Note: You do not have permission to make updates in this page.

☑ Creation Completed

Owner

Party Type Party
Party Name: LOOMIS COURIER SERVICE
Party Number: 233980
Account Number: 107074
Account Name LOOMIS COURIER SERVICE

Current Location

* Type Party Site Go
Party Name LOOMIS COURIER Go
Party Number 233980 Go
*Line 1 1160 BLAIR RD Go
Site Number 234993 Go
Address 1160 BLAIR RD
BURLINGTON, L7M 1K9, CA

Installed At

Installed Date 11-SEP-1991 Installed Time 0:00

Time format is HH24:MM

Change in installed date does not change contract date.

Type [ ] Go

Order

Sales Order Number

Sales Order Date

Sales Order Line

Purchase Order Number

Agreement Name

Item Flags

- [x] BOM Enabled
- [x] IB Trackable
- [ ] Inventory Trackable
- [x] Sellable
- [ ] Shippable

Item Views

- [ ] Merchant
- [x] Customer

Descriptive Flexfields

Context Value: FS Facility

Select Context Value and click 'Go' to show relevant fields.

Facility Type 2

Facility Type 3

Total Capacity - Liquid Fuel Tanks (L)

Total Capacity - Propane Tank s (USWG): 0

* Previous Facility Type

Previous Instance Number

Item Instances Home Profile Sign Out Help

Copyright 2006, Oracle Corporation. All rights reserved



Installed Base

Item	**FS PROPANE TANK**	System	
Item Description	**FS Propane Tank**	Owner	**LOOMIS COURIER SERVICE**
		Account Number	**107074**

Other Item Instance Details

Transaction History
Item Instance History
Operating Units
Contracts Orders
Service Requests
Orders and Directives
View Relationship Graphically
OMS Orders

General | **Location** | **Associations** | **Configuration** | **Counters** | **Notes**

External Reference		New Version Label	
Organization	**TSSA Item Master**	Last Version Label	**1**
Revision		Creation Date	**16-Jun-1992 00:00:00**
Instance Name		Status	**EXPIRED**
Quantity	**1**	Install Date	**16-Jun-1992 00:00:00**
UOM	**Each**	Expiration Date	**17-Jun-1992 00:00:00**
Item Instance Type		Shipped On Date	
Item Condition		Return By Date	
Accounting Classification	**Customer Product**	Actual Return Date	
Operational Status Code	**Not Used**		

Hide Instance Flex Fields

Tank Capacity (USWG)	**2000**
Propane Tank Orientation	**Horizontal** Horizontal
OIN or CRN	
Year Manufactured	
Serial Number	
Model Number	
Corrosion Protection	**Coating** Coating
Description	**2008V ABOVE GROUND TANK - HORIZONTAL**
Installation Year	
PSIG Rating	

Show Additional Attributes

Return to Instance Search

Item Instance Counters Mass Update Home Logout Preferences Help

Privacy Statement

Copyright (c) 2006, Oracle. All rights reserved.

Appendix H: Aerial Photographs



EXP Services Inc.
t: +1.905.573.4000 | f: +1.905.573.9693
80 Bancroft Street
Hamilton, ON L8E 2W5
Canada
www.exp.com

•BUILDINGS • EARTH & ENVIRONMENT • ENERGY •
• INDUSTRIAL • INFRASTRUCTURE • SUSTAINABILITY •

Approximate Site Boundary

0 50 100 150 200 250 m

TITLE AND LOCATION:

1959 AERIAL PHOTOGRAPH
Phase One Environmental Site Assessment
1160 Blair Road
Burlington, Ontario

PROJECT No.: HAM-00801245-G0	DWN: AC
SCALE: AS NOTED	CHKD: EE
DATE: MAY 2018	FIG. No.: H1



EXP Services Inc.
t: +1.905.573.4000 | f: +1.905.573.9693
80 Bancroft Street
Hamilton, ON L8E 2W5
Canada
www.exp.com

• BUILDINGS • EARTH & ENVIRONMENT • ENERGY •
• INDUSTRIAL • INFRASTRUCTURE • SUSTAINABILITY •

Approximate Site Boundary

0 50 100 150 200 250 m

TITLE AND LOCATION:

1978 AERIAL PHOTOGRAPH
Phase One Environmental Site Assessment
1160 Blair Road
Burlington, Ontario

PROJECT No.: HAM-00801245-G0	DWN: AC
SCALE: AS NOTED	CHKD: EE
DATE: MAY 2018	FIG. No.: H2



EXP Services Inc.
t: +1.905.573.4000 | f: +1.905.573.9693
80 Bancroft Street
Hamilton, ON L8E 2W5
Canada
www.exp.com

• BUILDINGS • EARTH & ENVIRONMENT • ENERGY •
• INDUSTRIAL • INFRASTRUCTURE • SUSTAINABILITY •

Approximate Site Boundary

0 50 100 150 200 250 m

TITLE AND LOCATION:

2002 AERIAL PHOTOGRAPH
Phase One Environmental Site Assessment
1160 Blair Road
Burlington, Ontario

PROJECT No.: HAM-00801245-G0	DWN: AC
SCALE: AS NOTED	CHKD: EE
DATE: MAY 2018	FIG. No.: H3



EXP Services Inc.
t: +1.905.573.4000 | f: +1.905.573.9693
80 Bancroft Street
Hamilton, ON L8E 2W5
Canada
www.exp.com

• BUILDINGS • EARTH & ENVIRONMENT • ENERGY •
• INDUSTRIAL • INFRASTRUCTURE • SUSTAINABILITY •

Approximate Site Boundary

0 50 100 150 200 250 m

TITLE AND LOCATION:

2017 AERIAL PHOTOGRAPH
Phase One Environmental Site Assessment
1160 Blair Road
Burlington, Ontario

PROJECT No.: HAM-00801245-G0	DWN: AC
SCALE: AS NOTED	CHKD: EE
DATE: MAY 2018	FIG. No.: H4

Appendix I: Site Photographs



Photo 1: View of the front of Site building facing west



Photo 2: View of typical household cleaning products observed during the Site visit



Photo 3: Water damage on ceiling tile



Photo 4: Roof mounted HVAC units



Photo 5: View of north side of Site building facing south



Photo 6: View of south side of Site building facing north

exp. EXP Services Inc. 80 Bancroft Street Hamilton, Ontario L8E 2W5 T: 905-573-4000 F: 905-573-9693	**SITE PHOTOGRAPHS** PROJ. NO: HAM-00801245-G0	Phase One ESA 1160 Blair Road Burlington, Ontario	SCALE: NTS DRAWN: KP CHECKED: EE	FIGURE I1 JULY 2017

Appendix J:
Phase One Conceptual Site Model

Phase One ESA Conceptual Site Model-
1160 Blair Road, Burlington, ON

This section presents the Phase One Conceptual Site Model (P1CSM), as it relates to the Site addressed as 1160 Blair Road, in Burlington, Ontario providing a narrative and graphical description integrating information related to the areas of potential environmental concern/potential contaminating activities and the presence and distribution of potential contaminants of concern. The P1CSM was completed in accordance with Ontario Regulation 153/04, as amended (O.Reg.153/04), as defined by the Ontario Ministry of the Environment and Climate Change (MOECC).

1.1 Introduction

The Site is located on the southwest side of Blair Road in Burlington, Ontario (Figures 1 and 2). The Site measures approximately 1.7 hectares (4.1 acres) in area. The Site is currently occupied by a two-storey industrial/commercial building with approximately 7,205 m² (77,555 ft²) of floor area. The Site building is currently occupied by various commercial tenants including: including: Creative Edge Dance Studio, RDC (Responsible Distribution Canada) (office), Ciscon Landscaping (showroom, office and yard), Body by PT (exercise gym), Canadian Dance Company, Burlington Movers (storage and office), Eurostar Renos, Absolute Custom Steel Fabrications (workshop), Insatax (office), Nuway Software (office) and the Archangel Raphael and Saint Marina Coptic Orthodox Church.

At the time of the Site visit, three (3) of the units were vacant, two (2) of which were located on the second floor.

Refer to Table 1 for the Site identification information.

Table 1: Site Identification Information

Civic Address	1160 Blair Road, Burlington, ON
Current Land Use	Commercial
Proposed Land Use	Community (Church)
Legal Description	Part of Lot 12, Concession 2, South of Dundas Street, “Nelson”, designated as Parts 9, 10 and 11, Reference Plan 20R-11755, Burlington
Property Identification Number (PIN)	07163-0083(LT)
Assessment Roll Number (ARN)	2402-090-903-41100-000
Universal Transverse Mercator (UTM) coordinates	NAD83 17, 597267E 4802107N
Site Area	1.67212 hectares
Property Owners	Archangel Raphael and Saint Marina Coptic Orthodox Church

1.2 Background

Based on a review of historical aerial photographs, chain of title information, historical maps, and other records, the Site building was constructed in the early 1970s. Prior to Site development, the Site was used for agricultural purposes, including an orchard.

The areas surrounding the Site buildings consist of asphalt parking areas.

1.3 Geological and Hydrogeological Conditions

The Site is located in the physiographic region described as Till Plains (Drumlinized). The Site and surrounding areas are dominated by Halton Till deposits which predominately consist of clay and silt till. The bedrock in the general area was part of a group belonging to the Queenston Formation, consisting of shale, limestone, dolostone, and siltstone. Based on available water well records, shale bedrock is expected to be at depths ranging between 2 to 5 m below ground surface.

Based on the information provided on the topographic map, regional groundwater is expected to flow to the south / southeast towards Lake Ontario.

Based on the review of available resources from the Ministry of Natural Resources and Forestry and MOECC, no areas of natural significance were identified within the Phase ON ESA study area.

1.4 Previous Investigations

A report titled "*Update Phase I Environmental Site Assessment, 1160 Blair Road, Burlington Ontario*" was prepared by Trow Consulting Engineers Ltd. (now EXP) in January 1999.

The report reviewed indicated the following pertinent information:

- "The Site has been occupied by a commercial building since 1973 and the Site and surrounding area have historically been agricultural use since the early 1900s;
- Based on the date of building construction, asbestos containing materials (ACM) may be present in various types of building materials; and
- Lead based paint may be present on original painted surfaces."

1.5 Underground Utilities

Potable water is provided to the Site building through the municipal water distribution system and sanitary wastewater is discharged to the municipal sewer system. Electrical service to the Site building is supplied by local hydro. Lighting in the building is supplied by fluorescent, incandescent, compact fluorescent and LED lighting fixtures. Electrical services to Site building by local hydro via pole mounted transformers off-site near the northwestern side of the Site.

The natural gas line enters the Site near the northeast corner from Blair Road.

Given that underground utilities are located on the Site, there is the potential for the distribution and transport of contaminants via the underground utilities.

1.6 Potentially Contaminating Activities and Areas of Potential Environmental Concern:

Refer to Table 2 and Figure 3 for the list of potentially contaminating activities (PCAs) that have occurred within the Phase One Study Area, which includes the Site and properties within 250 m radius of the Site boundaries.

Table 2: Potentially Contaminating Activities

PCA Identifier	Address	Location of Activity (in relation to Site)[1]	Potentially Contaminating Activity (PCA)[2]	Approximate timeline that PCA occurred	Contributes to APEC (Yes or No)?
1 (1A, 1B, 1C)	1160 Blair Road	On-Site	40 – Pesticides (including Herbicides, Fungicides and Anti Fouling Agents) manufacturing, processing, bulk storage and large-scale applications 34 – Metal Fabrication 52 – Storage, maintenance, fuelling and repair of equipment, vehicles and materials used to maintain transportation systems	Based on the 1959 aerial photograph, the Site was used for permanent crops (orchard). As such, there is the potential for the historic use of recalcitrant pesticides to have posed an environmental impact to the Site. According to the 1999 Trow Phase I ESA report, Best Cut (metal processing) was located onsite, circa 1997 to 1999. According to the 1999 Trow Phase I ESA report, Gowan's Repair and Service was located onsite, circa 1997.	Yes
2(2A. 2B, 2C)	1150 Blair Road	Off-Site (southeast adjacent)	28- Gasoline and Associate Products Storage in Fixed Tank 34- Metal Fabrication Not listed – Generator of hazardous wastes	Gotfryd Contracting Ltd. was listed as having an expired private liquid fuel outlet (Self-Serve) at 1160 Blair Road. Expiry year is 1989. A single walled diesel underground storage tank was present. A review of city directories indicated that Gotfryd Contracting Ltd was a tenant at 1150 Blair Road in 1990. Given the absence of any other records of fuel storage on Site, it is considered that the TSSA listed the expired fuel tank at 1160 Blair Road instead of the correct address of 1150 Blair Road.	Yes, based on proximity to the Site and local groundwater flow.

PCA Identifier	Address	Location of Activity (in relation to Site)[1]	Potentially Contaminating Activity (PCA)[2]	Approximate timeline that PCA occurred	Contributes to APEC (Yes or No)?
				The location of two (2) diesel USTs and one (1) solvent spill containment tank was confirmed by EXP during a supplemental records review. According to the Ecolog ERIS report, Kenwar Tool & Die Ltd. is listed in Scott's Directory, with the following operations: "special dies and tool and industrial molds". JR Tool and Die is listed in Scott's Directory, with the following operations: "Machine tools, metal cutting types; special dies and tools, die sets, jigs and fixtures and industrial molds; industrial and commercial machinery and equipment". A.W. Chesterton was listed in Scott's Directory, with the following operations, "Industrial machinery and equipment" and also registered as a waste generator of various wastes including emulsified oils, polymeric resins, inorganic & organic laboratory chemicals, halogenated solvents and petroleum distillates from 1994 to 2001.	
3	1157 Blair Road	Off-Site (approx 30 m north)	Not listed – Generator of hazardous wastes	Fagersta Secoroc Ltd. was registered as a waste generator of emulsified oils and halogenated solvents from 1986 to 1998 and was listed in the city directories at this address between 1975 and 2000. Screenplay Designs Inc. was registered as a waste generator of waste oils & lubricants for 2007 and 2008 and graphic art wastes in 2008. Wardco Window & Door Manufacturing was registered as a waste generator of paint/pigment/coating residues from 2013 to 2017. XCG Consultants Ltd. was registered as a waste generator of oil skimmings & sludges from 2003 to 2006. Atlas Copco Canada was registered as a waste generator of oil skimmings & sludges for 2002/2003/2007 and halogenated solvents, other specified inorganics, oil skimming & sludges from 2008 to 2017.	Yes, based on proximity to the Site and local groundwater flow.
4	3300 Mainway	Off-Site (west adjacent)	34 – Metal Fabrication Not listed – Generator of hazardous wastes	Verns Metal Stamping Inc. is listed in Scott's Directory, with the following operations: "Metal stampings; fabricated metal products". Jones Tool & Machine Co. Ltd. is listed in Scott's Directory, with the following description of operations: "Special dies and tools, die sets, jogs and fixtures and industrial molds; industrial and commercial machinery and equipment". Swissline Industries Ltd. was listed as waste generator of petroleum distillates from 1992 to 1998.	No, based on local groundwater flow.
5	1140 Blair Road	Off-Site (approx. 45 m southeast)	Not listed – Spill incident	A spill incident associated with this address included a 10 L spill of PCB oil to soil in 2001 due to a rotten hydro pole breaking. Environmental impact was deemed possible.	No, based on small quantity of spill.
6(6A, 6B, 6C)	3388 Mainway	Off-Site (approx. 30 m north)	Not listed – Generator of hazardous wastes 34 – Metal Fabrication	Thomas Wire Die Limited was listed as a waste generator of aromatic solvents and emulsified oils from 1986 to 1998. Canfanco Inc. was listed as a waste generator of alkaline wastes-heavy metals, paint/pigment/coating residues, aromatic solvent, waste oils & lubricant and organic laboratory chemicals from 2002 to 2004 and is listed in Scott's Directory, with the following operations: "Stamping and all other machinery manufacturing".	Yes, based on proximity to the Site and local groundwater flow.

PCA Identifier	Address	Location of Activity (in relation to Site)[1]	Potentially Contaminating Activity (PCA)[2]	Approximate timeline that PCA occurred	Contributes to APEC (Yes or No)?
			27- Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Canadian Fanner Co. Ltd. is listed in Scott's Directory, with the following operations: "Metal stamping; industrial and commercial machinery and equipment" and was listed in the city directories between 1975 and 1995 Ontario Auto Collision/Aro Motors Car Star is listed in the Burlington City directories in 2005 and was still present during the visual reconnaissance of adjacent properties.	
7	3390 Mainway	Off-Site (approx. 30 m north)	Not listed – Generator of hazardous wastes	Chem Systems Inc. was listed as a waste generator of petroleum distillates from 2002 to 2003 and was listed in the city directories in 2000. Hayward Gordon Ltd. was listed as a waste generator of petroleum distillates, paint/pigment/coating residues, inorganic/organic laboratory chemicals, waste compressed gases, polymeric resin, waste oils and lubricants from 2004 to 2006. Listed in Scott's Directory, with the following operations: "Material handling equipment manufacturing, all other general-purpose machinery".	Yes, based on proximity to the Site and local groundwater flow.
8	3400 Landmark Road	Off-Site (approx. 40 m east)	Not listed – Generator of hazardous wastes	Airmax Compressor Services Ltd. (Units 9 & 10) was registered as a waste generator of alkaline wastes, heavy metals, waste oils & lubricants, acid wastes, petroleum distillates from 2007 to 2016. L&A Diecrafts Ltd. (Units 5-10) was registered as a waste generator of waste oils & lubricants in 2005 and is listed in Scott's Directory, with the following operations: "Die-cut paper and paperboard and cardboard; signs and advertising specialties; sign manufacturing". Febau Canada (Units 3,4,5 and 6) was registered as a waste generator of inert inorganic wastes in 2007. Ascona Management & Consulting Inc. was registered as a waste generator of paint/pigment/coating residues in 2009.	No, based on nature of waste streams and proximity to the Site.
9(9A, 9B)	1171 Pioneer Road	Off-Site (southwest adjacent)	28- Gasoline and Associate Products Storage in Fixed Tank Not listed – Generator of hazardous wastes	Automotive Manager Bell Canada was listed as having an expired private fuel outlet (Self-Serve) and piping. Expiry year was 1990. The capacity of the tank was 25,000 L. Bell Canada was listed as a waste generator of various wastes including acid-waste- heavy metals, alkaline wastes, heavy metals, oil skimmings and sludges, aliphatic solvent, petroleum distillates, waste compressed gases, waste oils and lubricants, paint/pigments/coating residues, neutralized wastes- heavy metals, pathological wastes, organic/inorganic laboratory chemicals from 1988 to 2017.	Yes, based on proximity to the Site.
10(10A, 10B, 10C, 10D)	1153 Pioneer Road	Off-Site (south adjacent)	33 – Metal Treatment, Coating, Plating and Finishing 34 – Metal Fabrication 54 – Textile Manufacturing and Processing Not listed – Generator of hazardous wastes	BCG Precision Grinding and Honing Inc. was listed as a waste generator of waste oils and lubricants from 2013 to 2017 and was observed during the visual reconnaissance of adjacent properties. Mill Pack Industrial Maintenance Inc. was listed as a waste generator of waste oils and lubricants from 2012 to 2017 and was observed during the visual reconnaissance of adjacent properties. Burlington Centreless Grinding was listed as a waste generator of waste oils and lubricants from 2001 to 2012 and listed in Scott's Directory, with the following operations, "Industrial and commercial machinery and equipment; coating, engraving, heat treating and allied	No, based on local groundwater flow.

PCA Identifier	Address	Location of Activity (in relation to Site)[1]	Potentially Contaminating Activity (PCA)[2]	Approximate timeline that PCA occurred	Contributes to APEC (Yes or No)?
				activities". This tenant was observed during the visual reconnaissance of adjacent properties. K.C Graphics was listed as a waste generator of petroleum distillates from 1989 to 2001 and listed in Scott's Directory, as a textile and fabric finishing manufacturing business. 931344 Ontario Inc. was listed as a waste generator of petroleum distillates and paint/pigment/coating residues from 2002 to 2004. Canadian Induction Processing Inc. was listed as a waste generator of oil skimming and sludges and emulsified oils from 1986 to 2001 and listed in Scott's Directory, with the following operations: "Coating, engraving, heat treating and allied activates". Machinery Repair Technologies was listed as a waste generator of petroleum distillates and waste oils and lubricants from 1997 to 2003. Brant Custom Grinding Limited was listed in Scott's Directory, with the following operations: "coating, engraving, heat treatment and allied activities; machine shops; other plate work and fabricated structural product manufacturing". This tenant was observed during the visual reconnaissance of adjacent properties. Singlepoint MFG. Inc., M.I.R Fabric Products Ltd., TPREX Inc. and P.S.T Machining were observed during the visual reconnaissance of adjacent properties.	
11(11A, 11B)	3312 Mainway	Off-Site (northwest adjacent)	34 – Metal Fabrication 19 – Electronic and Computer Equipment Manufacturing	Weigh-Matic Systems Inc. was listed in Scott's Directory, with the following operations: "Cutting Tools & Machinists' Precision Measuring Devices; packaging machinery". Carlisle Technology Inc. was listed in Scott's Directory, with the following operations: "Computer and peripheral equipment, semiconductor and other electronic component manufacturing". This tenant was observed during the visual reconnaissance of adjacent properties. Integrity Worldwide Inc. was listed in Scott's Directory, with the following operations: "Ornamental and architectural metal product manufacturing".	No, based on local groundwater flow.
12(12A, 12B)	3330 – 3344 Mainway	Off-Site (northwest adjacent)	Not listed – Generator of hazardous wastes 19 – Electronic and Computer Equipment Manufacturing	Loomis Courier Service (3330 Mainway) was listed as a waste generator of paint/pigment/coating residues, inorganic/organic laboratory chemicals, halogenated pesticides and non-halogenated pesticides from 1996 to 1999. Hamilton Digital Designs Ltd. was listed in Scott's Directory, with the following operations: "Radio and television broadcasting and wireless communication equipment manufacturing; measuring, medical and controlling devices manufacturing; sign manufacturing". 1187188 Ontario Ltd. (3344 Mainway) was listed as a waste generator of pathological wastes from 2010 to 2014.	No, based on local groundwater flow.
13(13A, 13B, 13C, 13D, 13E, 13F)	3317 – 3339 Mainway	Off-Site (approx. 120 m northwest)	Not listed – Generator of hazardous wastes	Antel Optronics Inc. was listed as a waste generator from 1986 to 1994, however no additional details were provided.	No, based on proximity to the Site.

PCA Identifier	Address	Location of Activity (in relation to Site)[1]	Potentially Contaminating Activity (PCA)[2]	Approximate timeline that PCA occurred	Contributes to APEC (Yes or No)?
			33 – Metal Treatment, Coating, Plating and Finishing 34 – Metal Fabrication 47 - Rubber Manufacturing and Processing 43 – Plastics (including Fibreglass) Manufacturing and Processing Not listed – Spill incident	Modular Controls Limited was listed as a waste generator of petroleum distillates, waste oils and lubricants and emulsified oils from 1986 to 1998. Gates Air Systems Ltd. was listed as a waste generator of waste oils and lubricants from 1993 to 1998. Organizers Plus Modular Controls Limited was listed in Scott's Directory, with the following operations, "Wood kitchen cabinet and counter top manufacturing and other millwork". Halton Sheet Metal Ltd. was listed in Scott's Directory, with the following operations: "Industrial and commercial fan and blower and air purification equipment manufacturing and coating, engraving, heat treating and allied activities". JC CNC was listed as a waste generator of oil skimming and sludges from 1997 to 2001. The business was listed as a waste and listed under Scott's Directory with the following operations: "Machine Shop, mining and oil and gas field machinery manufacturing and railroad rolling stock manufacturing". Accurate Concrete Cutting was listed as a waste generator of waste crankcase oils and lubricants from 2016 to 2017. Allen Industrial Rubber Prod was listed in Scott's Directory, with the following description of operations: "Gaskets, packing and sealing devices; fabricated rubber products; resin and synthetic rubber manufacturing; other rubber product manufacturing and other miscellaneous manufacturing". This tenant was observed during the visual reconnaissance of adjacent properties. Alkano Grinding and Stamping Company was listed as a waste generator of waste oils and lubricants from 2012 to 2017. This tenant was observed during the visual reconnaissance of adjacent properties. Quality Cylinder Service was listed as a waste generator of waste oils and lubricants from 1986 to 1989. Quality Hydraulic Service was listed as a waste generator of petroleum distillates and waste oils and lubricants from 1990 to 1998. Welcan Machine Shop was listed as a waste generator of waste oils and lubricants and emulsified oils from 1996 to 2001. This business was listed in Scott's Directory, with the following description of operations: "Industrial and commercial machinery and equipment and steel foundries, not elsewhere classified". Airon HVAC Service Ltd was listed as a waste generator of aliphatic solvents and waste oils and lubricants for 2006. Eagle-Quip Inc. was listed as a waste generator of petroleum distillates and waste oils and lubricants from 1986 to 1988. Fairway Industrial was listed as a waste generator of petroleum distillates and waste oils and lubricants from 1989 to 2001.	

PCA Identifier	Address	Location of Activity (in relation to Site)[1]	Potentially Contaminating Activity (PCA)[2]	Approximate timeline that PCA occurred	Contributes to APEC (Yes or No)?
				Halton Metal Outlet Ltd. was listed in Scott's Directory with the following description of operations: "Coating, engraving, heat treating and allied activities; iron and steel mills and ferro-alloy manufacturing". Travis Industrial Maintenance was listed as a waste generator of petroleum distillates and waste oils and lubricants from 1995 to 2004. Firecraft Kilns Sales and Service was listed in Scott's Directory, with the following description of operation: "All other industrial machinery manufacturing". Helec Insulation Ltd. was listed in Scott's Directory, with the following description of operations: "Plastic products, not elsewhere classified and mineral wool". This tenant was observed during the visual reconnaissance of adjacent properties. Feed Rite Automatic Inc. was listed in Scott's Directory with the following description operations: "Material handling equipment manufacturing; other plate work and fabricated structural product manufacturing; cutlery and hand tool manufacturing; all other general-purpose machinery manufacturing; rubber and plastic hose and belting manufacturing". A spill incident associated with this property (3255 Mainway) included 27 L of Citrotech to asphalt. Environmental impact was not anticipated.	
14(14A, 14B)	3415 Landmark Road	Off-Site (approx. 95 m northeast)	Not listed – Generator of hazardous wastes 34 – Metal Fabrication	Euroline Custom Cabinets was listed as a waste generator of paint/pigment/coating residues from 1995 to 2001 and in Scott's Directory, with the following operations: "Wood household furniture, window and door manufacturing and millwork". Cor-Mag Inc. was listed as a waste generator of waste oils and lubricants from 1992 to 1998 and was listed in the City directories between 1980 and 1990. IndustAutoCo Inc. was listed as a waste generator of PCBs from 2014 to 2015. TCR Machining Ltd. (Custom & Production CNC Machining) occupied the property during the visual reconnaissance of the surrounding properties.	No, based on proximity to the Site.
15(15A, 15B)	1101 Blair Road	Off-Site (approx. 90 m east)	Not listed – Generator of hazardous wastes (PCA-15A) Not listed – Spill incident	Shell Canada Products was listed as a waste generator of waste oils/sludges (petroleum based), waste crankcase oils and lubricants as of December 2017. Waste oils and lubricants, alkaline wastes-other metals and oil skimming and sludges from 2011 to 2016. Quaker State Inc. was listed as a waste generator of oil skimmings and sludges, waste oils and lubricants and aromatic solvents from 1986 to 2001. Pennzoil Quaker State Canada Company was listed as a waste generator of oil skimmings and sludges, waste oils and lubricants and aromatic solvents from 2002 to 2010; emulsified oils from 2002 to 2008. A spill incident in 2002 associated with this property included oil sheen on the lot and catchbasin due to watermain failure. The spill was contained, although environmental impact was deemed possible.	No, based on proximity to the Site.

PCA Identifier	Address	Location of Activity (in relation to Site)[1]	Potentially Contaminating Activity (PCA)[2]	Approximate timeline that PCA occurred	Contributes to APEC (Yes or No)?
16(16A, 16B, 16C, 16D)	1121 Pioneer Road	Off-Site (approx. 125 m south)	Not listed – PCB Storage Site Not listed – Generator of hazardous wastes 33 – Metal Treatment, Coating, Plating and Finishing 43 – Plastic (including Fibreglass) Manufacturing and Processing	Hunter Drums Limited was registered in the Ontario PCB Storage Database. And was listed as a waste generator of acid wastes-heavy metals, paint/pigment/coating residues, aromatic solvents, aliphatic solvents, petroleum distillates and waste oil and lubricants from 1986 to 1989. Listed in Scott's Directory with the following operations: "Metal shipping barrels, drums, kegs and pails; all other plastic product manufacturing; other metal container manufacturing and coating, engraving, heat treating and allied activities". Mauser Canada Ltd. was listed as a waste generator of alkaline waste-other/heavy metals, oil skimmings and sludges, aliphatic solvents, detergents/soaps, aromatic solvents, waste oils and lubricants, inorganic laboratory chemicals and paint/pigment/coating residues from 2005 to 2017. Listed in Scott's Directory with the following operations: "All other plastic product manufacturing and other metal container manufacturing". Russel-Stanley was listed as a waste generator of paint/pigment/coating residues, aromatic solvents, waste oils and lubricants from 1997 to 2004 and acid wastes-heavy metals, alkaline wastes-other metals, aliphatic solvents, PCBs, oil skimmings and sludges and petroleum distillates from 1997 to 2001.	No, based on proximity to the Site.
17(17A, 17B, 17C)	3410 Mainway	Off-Site (approx. 100 m north)	Not listed – PCB Storage Site 31 – Ink Manufacturing, Processing and Bulk Storage Not listed – Generator of hazardous wastes	Reiger Printing Ink Co Ltd. was registered in the Ontario PCB Storage Database, any PCBs stored on the property were removed as of 1996. The company was also listed as a waste generator of paint/pigment/coating residues from 1986 to 2008 and petroleum distillates, polymeric resins, PCB's, waste oils and lubricants, inorganic pigment wastes, graphic art wastes from 1992 to 2008. This business was in Scott's Directory with the following operations: "Printing Ink Manufacturing and other printing". 2210263 Ontario Inc. was registered as a RSC property (2010) and listed as a waste generator of waste oils and lubricants from 2009 to 2010. The intended property use was community. No soil was remediated within 3 m of the property boundary. Activityplex Burlington Corp. was listed as a waste generator of inert organic waste as of December 2017. MIP Group Inc. was listed as a waste generator of inert organic waste in 2016.	No, based on proximity to the Site.
18(18A,18B, 18C)	3264 Mainway	Off-Site (approx. 105 m west)	Not listed – Generator of hazardous wastes 26 – Foam and Expanded Foam Manufacturing and Processing 57 – Vehicle and Associated Parts Manufacturing	FibreCast Inc. was listed as a waste generator of waste oils and lubricants and PCBs in 2016 and waste crankcase oils and lubricants in 2017. The business was also listed under Scott's Directory, with the following operations: "Engineering services; clay building material and refractory manufacturing; other specialty line building supplies wholesaler-distributors; all other textile product mills; urethane and other foam products (except Polystyrene) manufacturing; polystyrene foam product manufacturing; all other non-metallic mineral product manufacturing; plumbing, heating and air conditioning equipment and supplies wholesaler distributors". AISCO Systems Limited was listed as a waste generator of paint/pigment/coating residues in 1990 and paint/pigment/coating	No, based on proximity to the Site.

PCA Identifier	Address	Location of Activity (in relation to Site)[1]	Potentially Contaminating Activity (PCA)[2]	Approximate timeline that PCA occurred	Contributes to APEC (Yes or No)?
				residues, inorganic laboratory chemicals, petroleum distillated, polymeric resins, oil skimming and sludges and alkaline wastes-other metals from 1992 to 2001. The business was also listed as a waste generator from 1986 to 1989, however no additional details were provided. The business was listed under Scott's Directory, with the following operations: "Industrial and commercial machinery and equipment, service/special industry machinery and industrial truck, tractors, trailers and stackers".	
19(19A, 19B)	1149 Pioneer Road	Off-Site (approx. 50 m south)	Not listed – Generator of hazardous wastes Not listed – Spill incident	Rehau Industries Inc. was listed as a waste generator of aliphatic solvent, petroleum distillates, polymeric resins and waste oils and lubricants from 1986 to 2001. This tenant was observed during the visual reconnaissance of the surrounding properties. A spill incident in 1991 associated with this property included 1000 L of plasticizer spilled to the ditch due to equipment failure relating to a valve/fitting leak. The receiving medium was land and environmental impact was deemed possible.	No, based on local groundwater flow.
20(20A, 20B, 20C)	1100 Blair Road	Off-Site (approx. 115 m southeast)	8 – Chemical Manufacturing, Processing and Bulk Storage Not listed – Generator of hazardous wastes Not listed – Spill incident	Quadra Chemicals Ltd. was listed under the Chemical Registry which provides a listing of facilities that manufacture or distribute chemicals and listed under the Canadian Pulp and Paper Directory. This business was also listed as a waste generator of inorganic/organic laboratory chemicals from 1992 to 2012; paint/pigment/coating residues, alkaline wastes- other metals, PCBs and other specified inorganics from 1999 to 2012 and polymeric resins in 2012. Organic acids, paint/pigment/coating residues, aliphatic solvent, organic/inorganic laboratory chemicals, heavy fuels, detergents/soaps, PCBs, waste oils and lubricants, oil skimmings and sludges, aromatic solvents, amines, petroleum distillates, polymeric resins, other specified inorganics, graphic art wastes and alkaline wastes- other metals were listed for 2013 to 2017. Acco Canadian Material Handling was listed as a waste generator of paint/pigment/coating residues from 1986 to 1997 and alkaline wastes-other metals and waste oils and lubricants from 1990 to 1998. A spill incident in 1993 associated with this property included 15 kilograms of sodium dichromate dihydrate to the driveway due to weld/seam failure. The receiving medium was land and environmental impact was not anticipated.	No, based on proximity to the Site.
21(21A, 21B, 21C)	3285 - 3295 Mainway	Off-Site (approx. 115 m west)	31 – Ink Manufacturing, Processing and Bulk Storage 34 – Metal Fabrication	Brown Falcon Machine & Tool (3295 Mainway) was listed as a waste generator of petroleum distillates from 1992 to 1998. Tymatic Controls (Div. of Tyrrell Air Controls Ltd.) (3295 Mainway) was listed under Scott's Directory with the following operations: "Measuring, medical and controlling devices manufacturing; switchgear and switchboard and relay and industrial control apparatus manufacturing;	No, based on proximity to the Site.

PCA Identifier	Address	Location of Activity (in relation to Site)[1]	Potentially Contaminating Activity (PCA)[2]	Approximate timeline that PCA occurred	Contributes to APEC (Yes or No)?
			Not listed – Generator of hazardous wastes	electrical wiring and construction supplies wholesaler-distributors and industrial machinery, equipment and supplies wholesaler-distributors". Erodall Ltd. (3295 Mainway) was listed under Scott's Directory with the following operation: "Machine shops". Printing House Ltd. (3285 Mainway) was listed as a waste generator of oil skimmings and sludges, paint/pigment/coating residues, graphic art wastes and photoprocessing wastes from 1999 to 2017. Cooper Fluid Power Inc. (3285 Mainway) was listed as a waste generator of aliphatic solvents, petroleum distillates, oil skimming and sludges and waste oils and lubricants from 1996 to 2001. Cotswold Precision Company Ltd. (3285 Mainway) was listed as a waste generator of waste oils and lubricants and emulsified oils from 1994 to 2001. This business was listed under Scott's Directory with the following operations: "Fabricated metal products; overhead travelling cranes, hoist and monorail systems; industrial and commercial machinery and equipment; machine shops; all other miscellaneous fabricated product manufacturing; material handling equipment manufacturing". Precision Metalworks Inc. (3285 Mainway) was listed as a waste generator of oil skimming and sludges and waste oils and lubricants from 2007 to 2009. Sympro CNC Machining and Manufacturing (3285 Mainway) was listed as a waste generator from 2003 to 2004, however no additional details were provided. Precision Print (3285 Mainway) was listed as a waste generator of paint/pigment/coating residues in 2010. This business was listed under Scott's Directory with the following operations: "Digital printing, quick printing and other printing". McKellar Machine Products and The Printing House were observed during the reconnaissance of surrounding properties..	
22	3424 Landmark Road	Off-Site (approx. 115 m northeast)	28- Gasoline and Associate Products Storage in Fixed Tank	Humpty Dumpty Foods Ltd. was listed under TSSA Expired Facilities as having a private (self-serve) fuel outlet, expiring in 1993.	No, based on proximity to the Site.
23(23A, 23B)	3385 Mainway	Off-Site (approx. 130 m northwest)	Not listed – Generator of hazardous wastes 34 – Metal Fabrication	Toromont Industries Ltd. was listed as a waste generator of light fuels, waste crankcase and lubricants and petroleum distillates as of December 2017. Kingsbury Machine Toll (CDA) Ltd. was listed as a waste generator of paint/pigment/coating residues, aromatic solvents, petroleum distillates, oil skimming and sludges, waste oils and lubricants and emulsified oils from 1986 to 2004. The business was listed under Scott's Directory with the following operations: "Measuring, medical and controlling devices manufacturing, switchgear and switchboard and relay and industrial control apparatus manufacturing, other metalworking machinery manufacturing and all other general-purpose machinery manufacturing".	No, based on proximity to the Site.

PCA Identifier	Address	Location of Activity (in relation to Site)[1]	Potentially Contaminating Activity (PCA)[2]	Approximate timeline that PCA occurred	Contributes to APEC (Yes or No)?
24	3435 Landmark Road	Off-Site (approx. 160 m northeast)	Not listed – Generator of hazardous wastes	Laker Energy Products Ltd. was listed as a waste generator of emulsified oils, inorganic laboratory chemical, other specified inorganics and acid waste- other metals from 2012 to 2016. Gennum was listed as a waste generator of aromatic solvent, aliphatic solvents, halogenated solvents, waste oils and lubricants, organic laboratory chemicals, acid waste-heavy metals, alkaline wastes-heavy metals and other specified inorganic from 1988 to 2004. Linerar Technology Inc. was listed as a waste generator of aromatic solvents, halogenated solvent, waste oils and lubricants from 1986 to 1987.	No, based on proximity to the Site.
25	3365 Mainway	Off-Site (approx. 130 m northwest)	Not listed – Generator of hazardous wastes	Ecosynthetix Inc. was listed as a waste generator for inorganic/organic laboratory chemicals, paint/pigment/coating residues, other polymeric wastes, waste oils and lubricants, waste compressed gases from 2012 to 2017. This tenant was observed during the visual reconnaissance of adjacent properties.	No, based on proximity to the Site.
26	3426 Mainway	Off-Site (approx. 175 m north)	Not listed – Generator of hazardous wastes	Bosch Rexroth Canada Corp was listed as a waste generator for acid waste-heavy metals, organic laboratory chemicals, alkaline wastes-heavy metals and aromatic solvents from 2010 to 2017 and for waste oils and lubricants and petroleum distillates, oil skimming and sludges and amines from 2001 to 2017. This business was also listed under the Canadian Pulp and Paper Directory and listed under Scott's Directory with the following operations: "Material handling Equipment Manufacturing; industrial machinery, equipment and supplies wholesaler-distributions; switchgear and switchboard and relay and industrial control apparatus manufacturing; computer, computer peripheral and pre-packing software wholesaler-distributors; measures, medical and controlling devices manufacturing; other engine and power transmission equipment manufacturing, metal valve manufacturing, motor and generator manufacturing; all other general-purpose machinery manufacturing." Kernic Equipment was listed as a waste generator of aromatic solvents and waste oils and lubricants from 1992 to 1998. Basic Technologies was listed as a waste generator of petroleum distillates and emulsified soils from 1997 to 2000.	No, based on proximity to the Site.
27(27A, 27B)	3291 Mainway	Off-Site (approx. 215 m west)	Not listed – Generator of hazardous wastes 34 – Metal Fabrication	Nixon Integrated Machining Design Ltd. was listed as a waste generator of emulsified oils, waste oils and lubricants and petroleum distillates from 1996 to 2017 and was listed under Scott's Directory as a machine shop. Brown Flacon Machine and Tool was listed as a waste generator of petroleum distillates from 1993 to 2001 and was listed in Scott's Directory with the following operations: "Special dies and told, die sets, jigs and fixtures and industrial moulds; industrial and commercial machinery and equipment, not elsewhere classified".	No, based on proximity to the Site.

PCA Identifier	Address	Location of Activity (in relation to Site)[1]	Potentially Contaminating Activity (PCA)[2]	Approximate timeline that PCA occurred	Contributes to APEC (Yes or No)?
28(28A, 28B)	3450 Landmark Road	Off-Site (approx. 215 m northeast)	Not listed – Generator of hazardous wastes 19 – Electronic and Computer Equipment Manufacturing	Bramkal Contractors Inc. was listed as a waste generator of paint/pigment/coating residues, reactive anion wastes, aromatic solvents, organic laboratory chemicals and emulsified oils in 2016 and as a waste generator of waste oils and lubricants and petroleum distillates from 2006 to 2008. Burlington Cutting and Finishing Inc. was listed as a waste generator of emulsified oils from 2007 to 2009 and was listed in Scott's Directory with the following operation: "Stamping". A-1 Asphalt Maintenance Ltd. was listed as a waste generator of paint/pigment/coating residues, petroleum distillates, heavy fuels and waste oils and lubricants from 2002 to 2005. Tach West Technologies Ltd. was listed in Scott's Directory with the following operations: "Semiconductor and other electronic component manufacturing; measuring, medical and controlling devices manufacturing; professional machinery, equipment and supplies wholesaler-distributors and other new motor vehicle parts and accessories wholesaler-distributors".	No, based on proximity to the Site.
29	3455 Landmark Road	Off-Site (approx. 215 m northeast)	Not listed – Generator of hazardous wastes	Comstock Canada Ltd. was listed as a waste generator of petroleum distillates, inorganic/organic laboratory chemicals, waste oils and lubricants, alkaline wastes- other metals from 1999 to 2014 and acid wastes, paint/pigment/coating residues, halogenated solvents from 1995 to 2008.	No, based on proximity to the Site.
30	3419 Mainway	Off-Site (approx. 235 m north)	Not listed – Spill incident	A spill incident in 2000 associated with this property included 568 L of diesel fuel to the parking lot and drain/storm sewer due to a valve/fitting leak or failure to moving equipment. The receiving medium was land/water and environmental impact was deemed possible.	No, based on proximity to the Site.
31(31A, 31B, 31C)	3267 Mainway	Off-Site (approx. 150 m west)	Not listed – Generator of hazardous wastes 57 – Vehicle and Associated Part Manufacturing Not listed – Spill incident	Revstone Industries Burlington Inc. was listed as a waste generator of petroleum distillates, aliphatic solvents, acid-wastes-heavy metals, emulsified oils, waste oils and lubricants, oil skimmings and sludges, alkaline wastes-other metals from 2009 to 2012. National Rigging and Transportation Ltd. was listed as a waste generator in 2012, however no additional details were provided. Burlington Technologies was listed as a waste generator for waste oils and lubricants, emulsified oils, other specified inorganics, aliphatic solvent, petroleum distillates and oil skimmings and sludges from 1992 to 2008. Burlington Die Casting was listed as a waste generator of waste oils and lubricants and emulsified oils from 1986 to 1990 and was listed in Scott's Directory with the following operations: "Non-ferrous foundries (except die-casting); industrial mould manufacturing; other metalworking machinery manufacturing; automobile and light duty motor vehicle manufacturing; heavy-duty truck manufacturing". A spill incident in 2004 associated with this property included an unknown quantity of cutting oil (petroleum based, not specified) to a	No, based on proximity to the Site.

PCA Identifier	Address	Location of Activity (in relation to Site)(1)	Potentially Contaminating Activity (PCA)(2)	Approximate timeline that PCA occurred	Contributes to APEC (Yes or No)?
				creek. The receiving medium was water and environmental impact was not noted in the report. A spill incident in 2005 associated with this property included approximately 20 L of hydraulic oil to an onsite catch basin. The receiving medium was water and environmental impact was deemed possible.	
32(32A, 32B, 32C, 32D)	1232 Dillon Road	Off-Site (approx. 220 m northwest)	Not listed – Generator of hazardous wastes 33 – Metal Treatment, Coating, Plating and Processing 34 – Metal Fabrication Not listed – Spill incident	JC CNC Works Inc. was listed as a waste generator of emulsified oils and waste oils/sludges (petroleum based) from 2011 to 2017 and was listed in Scott's Directory with the following description operations: "Railroad rolling stock manufacturing; mining and oil and gas field machinery manufacturing; coating, engraving, heat treating and allied activities; other plate work and fabricated structural product manufacturing". This tenant was observed during the visual reconnaissance of adjacent properties. X-Pert Metal Finishing Ltd. was listed as a waste generator of acid waste-heavy metals, alkaline wastes- heavy metals and oil skimming and sludges from 1986 to 1998. Hahn and Sons Ltd. was listed as a waste generator of waste oil and lubricants from 2013 to 2017. This tenant was observed during the visual reconnaissance of adjacent properties. X-Pert Metals reported a spill incident in 1991 associated with a flood on site that leaked an unknown quantity of chemicals into a sewer. The receiving medium was watercourse or lake and environmental impact was deemed possible.	No, based on proximity to the Site.
33	3280 Mainway	Off-Site (approx. 60 m west)	27- Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	The property at 3280 Mainway was occupied by Fix Auto Collision during the visual reconnaissance of the surrounding properties.	No, based on local groundwater flow.

(1) Distances are approximate. Precise distances are not possible due to the age of some listings and the aggregation and/or loss of addresses.

(2) Potentially contaminating activity means a use or activity set out in Column A of Table 2 of Schedule D (O.Reg 153/04, as amended) that is occurring or has occurred in a phase one Study area.

1.7 Areas of Potential Environmental Concern

Based on the evaluation of the PCAs located within the Phase One Study Area, the following areas of potential environmental concern (APECs) were identified, as presented in Table 3 and Figure 4.

Table 3: Areas of Potential Environmental Concern

Area of Potential Environmental Concern (APEC)[1]	Location of APEC on Phase One Property	Potentially Contaminating Activity (PCA)[2]	Location of PCA (on-Site or off-Site)	Contaminants of Potential Concern	Media Potentially Impacted (Groundwater, soil and/or sediment)
APEC 1A **APEC 1B** **APEC 1C**	Entire Site Southeast Industrial Unit Northwest Industrial Unit	40 – Pesticides (including Herbicides, Fungicides and Anti Fouling Agents) manufacturing, processing, bulk storage and large-scale applications 34 – Metal Fabrication 52 – Storage, maintenance, fueling and repair of equipment, vehicles and materials used to maintain transportation systems	On-Site (1160 Blair Road)	Organochlorine Pesticides, Metals, As, Sb, Se Metals, VOCs and PHCs VOCs and PHCs	Soil Soil and Groundwater Soil and Groundwater
APEC 2	Southeast adjacent to property line	28 – Gasoline and Associate Products in Fixed Tanks, 34 – Metal Fabrication	Off-Site (1150 Blair Road)	VOCs and PHCs, Metals	Soil and Groundwater
APEC 3	Southern corner of property	28- Gasoline and Associate Products Storage in Fixed Tank Not listed – Generator of hazardous wastes	Off-Site (1171 Blair Road)	PHCs, VOCs, BTEX, Metals	Groundwater
APEC 4	Northeast adjacent to property boundary	Not listed – Generator of hazardous wastes	Off-Site (1157 Blair Road)	PHCs, VOCs, BTEX, Metals	Groundwater
APEC 5	Northern corner of property	Not listed – Generator of hazardous wastes 34 – Metal Fabrication 27- Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Off-Site (3388 Mainway)	PHCs, VOCs, BTEX, Metals	Groundwater
APEC 6	Northern corner of property	Not listed – Generator of hazardous wastes	Off-Site (3390 Mainway)	PHCs, VOCs, BTEX, Metals	Groundwater

(1) Area of Potential Environmental Concern means the area on, in or under a phase one study area where one or more contaminants are potentially present, as determined through the PI ESA, including through (a) identification of post or present uses on, in or under the phase one property, and (b) identification of potentially contaminating activities.
(2) Potentially contaminating activity means a use or activity set out in Column A of Table 2 of Schedule D (O.Reg.153/04, as amended) that is occurring or has occurred in a phase one Study area.

Based on the findings of the Phase One ESA and conclusions, a Phase Two ESA is required to assess the soil and groundwater conditions at the Site prior to submitting a RSC.