FISHER ENGINEERING

**ENGINEERING**

Professional Engineers Ontario

**LABORATORY**

CALA
Canadian Association for Laboratory Accreditation Inc.

# PHASE I
# ENVIRONMENTAL SITE ASSESSMENT



## 5051 HARVESTER ROAD
## BURLINGTON, ONTARIO

400 Esna Park Drive, Unit 15
Markham, ON
L3R 3K2

Tel: (905) 475-7755
www.fishereng.com

Project No. FE 23-13262

September 13, 2023

| | |
|---|---|
| **Issued to:** | Dymon Group of Companies |
| **Contact:** | James Byck<br>2-1830 Walkley Road<br>Ottawa, Ontario K1H 8K3 |
| **Project Name:** | Phase I Environmental Site Assessment |
| **Project Address:** | 5051 Harvester Road, Burlington, Ontario |
| **Project Number:** | FE 23-13262 |
| **Issued on:** | September 13, 2023 |

**Prepared by:**
**(Primary Contact)**


Lena Johnston, C.E.T.
Project Manager
lena@fishereng.com


**Reviewed by:**





David Fisher, B.A.Sc., C. Chem., P. Eng.
President
dave@fishereng.com

Bernard Chan, C. Chem., P. Eng.
Senior Project Manager
bernard@fishereng.com

# TABLE OF CONTENTS

**1. EXECUTIVE SUMMARY ..... 1**

**2. INTRODUCTION ..... 3**

2.1. OBJECTIVES ..... 3
2.2. REGULATORY FRAMEWORK ..... 3
2.3. SCOPE OF WORK ..... 4

**3. CURRENT SITE DESCRIPTION ..... 4**

**4. RECORDS REVIEW ..... 5**

4.1 DOCUMENTATION OF SOURCES AND SEARCH DISTANCES ..... 5
*4.1.1. Aerial Photographs ..... 6*
*4.1.2. Fire Insurance Plans ..... 7*
*4.1.3. Municipal Directories ..... 7*
*4.1.4. Title Search and Assessment Rolls ..... 7*
*4.1.5. Previous Environmental, Geological and Geotechnical Reports ..... 7*
*4.1.6. Company Records ..... 8*
*4.1.7. Environmental Source Information ..... 8*
*4.1.8. Topographical, Geological and Hydrogeological Sources ..... 13*
4.2 OTHER AVAILABLE RECORDS ..... 15

**5. SITE RECONNAISSANCE ..... 15**

5.1. GENERAL ..... 15
*5.1.1. Methodology ..... 15*
*5.1.2. Limitations ..... 15*
*5.1.3. Current Property Use and Activities ..... 16*
*5.1.4. Hazardous Materials Inventory ..... 16*
*5.1.5. Fuels and Chemicals ..... 16*
*5.1.6. Waste Generation and Storage ..... 16*
*5.1.7. Unidentified Substances ..... 16*
*5.1.8. Air Discharges and Odours ..... 17*
*5.1.9. Potable Water Supply ..... 17*
5.2. EXTERIOR OBSERVATIONS ..... 17
*5.2.1. Exterior of Building and Structures ..... 17*
*5.2.2. Wells, Pits, Lagoons, Watercourses, Ditches or Standing Water ..... 17*
*5.2.3. Sewage and Waste Water Disposal ..... 17*
*5.2.4. Stained Materials, Stressed Vegetation and Fill Materials ..... 18*
5.3. INTERIOR OBSERVATIONS ..... 18

*5.3.1. Interior of Building and Structures ..... 18*
*5.3.2. Heating and Cooling ..... 18*
*5.3.3. Stains ..... 18*
*5.3.4. Drains, Sumps and Oil/Water Separators ..... 18*
*5.3.5. Hydraulic Equipment ..... 19*
*5.3.6. Designated Substances and Other Special Attention Items ..... 19*
5.4. ADJOINING PROPERTIES OBSERVATION AND INFORMATION ..... 21
**6. INTERVIEWS ..... 22**
6.1. METHODOLOGY ..... 22
6.2. LIMITATIONS ..... 22
6.3. INTERVIEW PARTICIPANTS ..... 22
**7. CONCLUSIONS AND RECOMMENDATIONS ..... 23**
**8. LIMITATIONS ..... 24**
**9. QUALIFICATIONS OF THE ASSESSOR ..... 25**
**10. REFERENCES ..... 26**
**APPENDIX A – FIGURES ..... A**
**APPENDIX B – RECORDS REVIEW DOCUMENTS ..... B**
**APPENDIX C – SITE PHOTOGRAPHS ..... C**
**APPENDIX D – DOCUMENTATION OF INTERVIEW ..... D**

# GLOSSARY OF ACRONYMS

| | |
|---|---|
| ACM | Asbestos-Containing Material |
| asl: | Above Sea Level |
| AST: | Aboveground Storage Tank |
| bgs: | Below Ground Surface |
| BTEX: | Benzene, Toluene, Ethylbenzene and Xylenes |
| CA: | Certificate of Approval |
| CPC: | Contaminant of Potential Concern |
| CSA: | Canadian Standards Association |
| EASR: | Environmental Activity and Sector Registry |
| EBR: | Environmental Registry |
| ECA: | Environmental Compliance Approval |
| EPA: | Environmental Protection Act |
| ESA: | Environmental Site Assessment |
| FIP: | Fire Insurance Plan |
| HVAC: | Heating, Ventilation, and Air Conditioning |
| MECP: | Ministry of the Environment, Conservation and Parks |
| MNRF: | Ministry of Natural Resources and Forestry |
| MOE: | Ministry of the Environment |
| MOL: | Ministry of Labour |
| NPRI: | National Pollutant Release Inventory |
| NAD: | North American Datum |
| O. Reg.: | Ontario Regulation |
| ODS: | Ozone Depleting Substance |
| OHSA: | Occupational Health and Safety Act |
| PAHs: | Polycyclic Aromatic (Polyaromatic) Hydrocarbons |
| PCA: | Potentially Contaminating Activity |
| PCBs: | Polychlorinated Biphenyls |
| PHC (F1-F4): | Petroleum Hydrocarbons Fractions F1 to F4 |
| RSC: | Record of Site Condition |
| TSSA: | Technical Standards and Safety Authority |
| UFFI: | Urea Formaldehyde Foam Insulation |
| UST: | Underground Storage Tank |
| VOCs: | Volatile Organic Compounds |

# 1. EXECUTIVE SUMMARY

Fisher Engineering Limited (Fisher) was retained by Dymon Group of Companies to conduct a Phase I Environmental Site Assessment (ESA) of the property located at 5051 Harvester Road, Burlington, Ontario, herein referred to as the "Site". The purpose of the Phase I ESA was to conduct an environmental due diligence and liability assessment in support of property sale purposes and redevelopment.

The Phase I ESA was conducted in general accordance with the Canadian Standards Association (CSA) Standard Z768-01 (reaffirmed 2022), *Phase I Environmental Site Assessment*.

The Site is located on the northwest corner of the intersection of Harvester Road and South Service Road. It has an area of approximately 2.27 hectares (5.61 acres). The Site is bounded by Harvester Road followed by commercial developments to the south, South Service Road followed by commercial buildings to the east, an Esso gasoline service station adjacent to the southwest, and Appleby Line followed by commercial developments to the west, and a commercial building to the north.

Historical records available for the Site and properties within 250 m surrounding the Site (the "phase I study area") were reviewed. Findings from the records review and interviews with a person with detailed knowledge of historical Site activities indicated that the Site was previously undeveloped/agricultural land, and was developed for the current commercial use sometime in the 1990s. The Site had been occupied by Tim Hortons as a coffee shop.

Based on our Site reconnaissance on August 29, 2023, the southern portion of the Site is occupied by a one-storey commercial building (the "subject building"). Areas surrounding the subject building were asphalt paved for parking and driving. The remaining areas of the Site are undeveloped/vegetated. Current Site operations include a "Tim Hortons" coffee shop and a "Wendy's" restaurant.

The potential presence of designated substances and other special attention items inside the building identified during our Site reconnaissance are not considered of concern provided they are properly managed and disposed or are not disturbed. However, a designated substance survey (DSS) should be conducted at the Site prior to any demolition or significant renovation of the building.

The findings of the current Phase I ESA have revealed evidence of potential contamination associated with other neighbouring properties within the phase I study area. The potential environmental concerns are listed and described in the following table:

| **TABLE 1: Potential Environmental Contamination That May Affect the Site** |
|---|
| Areas of Potential Environmental Contamination |
| **1. Presence of an off-site fueling facility:** Various fueling facilities with underground storage tanks (USTs) were located at 875 Appleby Line, adjacent to the southwest of the Site. Phase II ESA works should be conducted at the Site along the southwestern property boundary. |
| **2. Presence of an off-site automobile service garage:** During the Site Reconnaissance, an auto service facility with drums of oil was observed at 5105 Harvester Road, approximately 15 m east of the Site. Phase II ESA works should be conducted at the Site along the eastern property boundary. |

Considering the above recognized environmental conditions, it is recommended that a Phase II ESA be conducted at the identified areas of potential environmental concern at the Site, to determine the location and concentration of potential contaminants in the land or water on, in or under the Site.

# 2. INTRODUCTION

## 2.1. Objectives

Fisher Engineering Limited (Fisher) was retained by Dymon Group of Companies (the "Client") to conduct a Phase I Environmental Site Assessment (ESA) of the property located at 5051 Harvester Road, Burlington, Ontario, herein referred to as the "Site". The purpose of the Phase I ESA was to conduct an environmental due diligence and liability assessment in support of property sale purposes and redevelopment.

The Phase I ESA was conducted to develop a preliminary determination of the likelihood that one or more contaminants have affected any land or water on, in or under the Site, and to determine the need and provide the basis for carrying out any Phase II ESA, if required.

## 2.2. Regulatory Framework

The Phase I ESA carried out by Fisher on the Site was conducted in general accordance with the Canadian Standards Association (CSA) Standard Z768-01 (reaffirmed 2022), *Phase I Environmental Site Assessment*. A Phase I ESA is the systematic preliminary process by which an assessor seeks to determine whether a particular property is subject to actual or potential contamination. A Phase I ESA does not involve the investigative procedures of sampling, analyzing, and measuring, unless enhancements are agreed upon between the Client and the assessor.

The roles and powers of the Ministry of the Environment, Conservation and Parks (MECP) when dealing with contaminated sites are outlined primarily in the Environmental Protection Act (EPA), R.S.O. 1990. The MECP has a mandate to address conditions where there is an adverse effect, or the likelihood of an adverse effect, associated with the presence or discharge of a contaminant. Ontario Regulation (O. Reg.) 153/04 (Records of Site Condition – Part XV.1 of the EPA), as amended, provides roles and responsibilities to property owners and consultants to use when assessing the environmental condition of a property, when determining whether or not restoration is required, and in determining the kind of restoration needed to allow continued use or reuse of the property. The O. Reg. 153/04, as amended, also establishes a standard work program for conducting Phase I ESA in support of filing a Record of Site Condition (RSC) in the Environmental Site Registry for proposed changes in property use to more sensitive land use.

Since it is not the Client's intention to file a RSC for the Site, this Phase I ESA conducted for the Site does not meet all requirements of the O. Reg. 153/04, as amended, and cannot be used to support the filing of RSC.

### *2.3. Scope of Work*

The scope of work for this Phase I ESA consisted of the following:

1. A records review;
2. Site reconnaissance;
3. Interviews;
4. Identification of recognized environmental conditions at the Site;
5. Evaluation of collected information;
6. Preparation of a written report; and
7. Submission of the report to the Client (Dymon Group of Companies).

## 3. CURRENT SITE DESCRIPTION

The Site is located on the northwest corner of the intersection of Harvester Road and South Service Road. It has an area of approximately 2.27 hectares (5.61 acres). The Site is bounded by Harvester Road followed by commercial developments to the south, South Service Road followed by commercial buildings to the east, an Esso gasoline service station adjacent to the southwest, and Appleby Line and commercial developments to the west, and a commercial building to the north. For purposes of discussion, Appleby Line is referenced to run north-south, and Harvester Road is referenced to run east-west. Please refer to Appendix A for the Site Location Map (Figure A).

Based on our Site reconnaissance on August 29, 2023, the southern portion of the Site is occupied by a one-storey commercial building occupied by a "Tim Hortons" coffee shop and a "Wendy's" restaurant (the "subject building"). Areas surrounding the Site are asphalt paved for parking and driving with landscaping along the perimeter. The northern portion of the Site is undeveloped vegetated land.

A general description of the Site is presented in the following table:

| TABLE 2: Site Information | |
|---|---|
| Municipal Address: | 5051 Harvester Road, Burlington, Ontario L7L 6S1 |
| Current Site Occupant: | Tim Hortons and Wendy's |
| Legal Description: | Not provided |
| Geographical Coordinates of the Centroid of the Site: | Universal Transverse Mercator (UTM) Grid Coordinates, based on North American Datum of 1983 (NAD83):<br>17T 599845 m Easting 4803685 m Northing |
| Site Area: | 2.27 hectares (5.61 acres) |
| Utility Providers: | Water: Halton Region |
| | Storm & Sanitary Sewer: Halton Region |
| | Electricity: Burlington Hydro |
| | Natural gas: Enbridge |
| Building Area: | Approximately 600 m² |
| Number of Levels: | 1 |
| Basement: | No |
| Year Built: | Approximately 1990s |
| General Construction: | Concrete block and brick walls, slab-on-grade foundation, tar and gravel roof |
| Building Use: | Commercial |

# 4. RECORDS REVIEW

The specific objectives of a records review are to obtain information on the current and past uses of, and activities at, or affecting the Site in order to determine if a recognized environmental condition exists at the Site and to interpret any recognized environmental condition at the Site. Additionally, a review of records that relate to neighbouring properties, determines if a recognized environmental condition exists at the Site and assists interpretation of any recognized environmental condition at the Site.

## *4.1 Documentation of Sources and Search Distances*

The applicable search distance for records review included the Site, properties located, wholly or partly, within 250 m from the nearest point on a boundary of the Site (the "phase I study area"),

and other neighbouring properties where activities considered to be potential sources of environmental contamination, were apparent.

### 4.1.1. Aerial Photographs

Aerial photographs of various years from 1960 to 2022 were obtained from Environmental Risk Information Services (ERIS). A copy of the aerial photographs (Figures E.1 to E.4) is included in Appendix A.

The aerial photographs were examined stereoscopically to assess Site conditions and were described below:

**TABLE 3: Description of Aerial Photographs**

| Year | Site | Surrounding Area |
|---|---|---|
| 1960 | The Site consisted of undeveloped agricultural land. | Surrounding areas consist of agricultural land. Appleby Line was located to the west. Highway 403/Queen Elizabeth Way (QEW) had been constructed further to the north, and access ramps from Appleby Line to Highway 403/QEW are visible further to the north and northwest. A commercial development is observed to the south. |
| 1974 | Same as in 1960. | Similar as in 1960. Harvester Road has been constructed to the south. Increased commercial development is observed to the south, southwest across the intersection of Appleby Line and Harvester Road, and west across Appleby Line. |
| 1988 | Same as in 1974. | North: Vacant land and on-ramp to Highway 403.<br>East: Commercial buildings.<br>South/southwest: A gasoline service station followed by commercial buildings.<br>West: Commercial buildings and on-ramp to Highway 403/QEW. |
| 2022 | The southern portion of the Site was developed with the current commercial building. Remaining areas remained undeveloped. | Similar as in 1988 with increased commercial development to the north, south and west. |

Based on a review of aerial photographs, potential environmental concerns were revealed from the adjacent properties within the phase I study area as follows:

**NEIGHBOURING PROPERTIES**

- Operation of a gas station adjacent to the southwest of the Site (currently 875 Appleby Line), from 1988 to present.

Due to the nature of operations, intervening distances and/or cross/downgradient locations from the Site, other operations at other properties within the phase I study area are considered unlikely to represent a source of contamination on and/or under the Site.

### 4.1.2. Fire Insurance Plans

Fire Insurance Plans (FIPs) were originally created to provide insurance companies with detailed information so that they could assess insurance risks as a fire hazard.

Opta Information Intelligence (Opta) was contacted to obtain FIPs and other fire insurance products related to the Site and surrounding properties through an Opta Enviroscan™ report. No FIPs were indicated to be available for the Site or surrounding properties, and no insurance reports were available for the Site. Please refer to Appendix B for a copy of the Opta Enviroscan™ report.

### 4.1.3. Municipal Directories

A review of municipal directories was conducted to obtain a listing of previous occupants for the Site and areas within 250 m surrounding the Site. This information is useful in determining the past and/or present uses and associated environmental risks in the phase I study area.

Environmental Risk Information Services (ERIS) was contacted to obtain city directories for the Site and surrounding properties. At the time of report issuance, the city directories search result had not yet been received from ERIS. Fisher will advise the Client if any outstanding environmental source information changes the conclusion or recommendations of this report.

### 4.1.4. Title Search and Assessment Rolls

A title or assessment roll search was not performed as part of this assessment.

### 4.1.5. Previous Environmental, Geological and Geotechnical Reports

No previous reports were available to Fisher for review.

### 4.1.6. Company Records

No company records were available for review.

### 4.1.7. Environmental Source Information

Reasonable accessible information and documents pertaining to the Site and other properties within the phase I study area have been searched by making inquiries to various Federal and Provincial environmental sources, including an ERIS Report that assists in the assessment and evaluation of environmental risks. Please refer to the ERIS Database Report attached in Appendix B. Relevant results from the search are presented as follows:

| **TABLE 4A: Environmental Sources of Information – Site** | |
|---|---|
| Source | Relevant Findings |
| National Pollutant Release Inventory (NPRI) information maintained by Environment Canada | Based on the ERIS report, the Site was not listed in the database. |
| Ontario Inventory of PCB Storage Sites (OPCB), October 2004 and December 2013, and<br>National Inventory of PCB in Use and PCB Wastes in Storage in Canada (NPCB), information maintained by Environmental Canada 2008 | Based on the ERIS report, the Site was not listed in the databases. |
| Certificates of Approval (CA), Environmental Bill of Rights Registry (EBR), Environmental Compliance Approval (ECA), Chemical Manufacturers and Distributors (CHEM), Chemical Register (CHM), Permit to Take Water (PTTW), Certificates of Property Use (CPU) or similar instruments | Based on the ERIS report, no records of any CA, EBR, ECA, CHEM, CHM, PTTW, CPU or similar instruments were listed for the Site. |
| Inventory of Coal Gasification Plant Waste Sites in Ontario, MOE, April 1987 | The Site was not listed as a former coal gasification plant waste site. |

| TABLE 4A: Environmental Sources of Information – Site | |
|---|---|
| Source | Relevant Findings |
| Compliance and conviction records regarding environmental notices, orders, offences, spills and inspection reports of the Ministry, or submitted to the Ministry | Based on the ERIS report, no spill records were reported for the Site.<br><br>Fisher has submitted a request to the Environmental Property Information (EPI) Program and a Freedom of Information (FOI) and Protection of Privacy Act request for a search of available records relevant to the Site to the MECP on August 22, 2023. At the time of report issuance, a response from the MECP had not yet been received. Fisher will advise the Client if any outstanding environmental source information changes the conclusion or recommendations of this report. A copy of the MECP FOI request is provided in Appendix B. |
| Private and retail fuel storage tanks and other information maintained by the Technical Standards and Safety Authority (TSSA) | Based on the ERIS report, no records of fuel tanks were reported for the Site.<br><br>A reply to Fisher's electronic inquiry to the TSSA, dated August 22, 2023, indicated that no records of fuel storage tanks were found for the Site or surrounding properties. It should be noted that the Fuels Safety Division of TSSA did not register private underground storage tanks (USTs) or aboveground storage tanks (ASTs) for fuel prior to January 1990 or furnace oil tanks prior to May 1, 2002.<br><br>A copy of the TSSA response letter is provided in Appendix B. |
| MECP Regulation 347 Public Information Data Set and the MOE's Hazardous Waste Information Network (HWIN) | Based on the ERIS report, the Site was listed as a generator of hazardous wastes (GEN) as follows:<br><br>• Barhav Development Timwhen Partnership was listed as a Hazardous Waste Generator for waste class: waste oils/sludges (petroleum based) (251 L) as of December 2018, as of July 2020 and as of November 2021 and oil skimmings and sludges (251 L) as of October 2022.<br><br>Based on the business name in which the waste was registered and relatively short period for the waste registration, it is likely that the waste generated would be limited in quantity and the business has its own disposal protocol in place, and it is unlikely that any release would have impacted the environmental quality of soil and groundwater at the Site. |
| Waste Disposal Site Inventories, MOE, June 1991; Anderson's Waste Disposal Sites, O. Reg. 347 Waste Receiver. | Based on the ERIS Report, the Site was not listed as a waste disposal site. |
| Notices and instruments, including Record of Site Condition (RSC), posted in the Environmental Site Registry | Based on the ERIS Report and a search for RSC in the Environmental Site Registry on August 22, 2023, no RSC, under O. Reg. 153/04 (Part XV.1 of the EPA), had been registered for the Site. |

| TABLE 4A: Environmental Sources of Information – Site | |
|---|---|
| Source | Relevant Findings |
| Well head protection areas (WHPA) information from planning authorities | Based on the MECP - Source Protection Information Atlas, the Site and phase I study area is located within the vicinity of the Halton Region Source Protection Area, Intake Protection Zone 2. A copy of the map is provided in Appendix B. |
| Information on areas of natural significance maintained by the Ministry of Natural Resources and Forestry (MNRF) and Conservation Authorities | The MNRF Natural Heritage Areas online interface used to identify any areas of natural significance in or around the phase I study area. No part of the phase I study area is located within or in the vicinity of such an area. A copy of the MNRF Natural Heritage Area Map is provided in Appendix B. |

| TABLE 4B: Environmental Sources of Information – Surrounding Properties | |
|---|---|
| Property Location Approximate Distance/ Direction From Site | Database Findings Pertaining to the Property |
| 875 Appleby Line,<br><br>0 m/Southwest | **SPL**<br><br>Esso Petroleum Canada – a spill of 10 L of gasoline to asphalt from a tank vent was reported in 1994. Environmental impact was reported as “Not Anticipated”.<br><br>**PRT**<br><br>Nissan Esso was listed in the Private and Retail Fuel Storage Tanks (PRT) database as a retail facility installed in 1992.<br><br>779584 Ontario Inc. Jules Esso was listed in the Private and Retail Fuel Storage Tanks (PRT) database as a retail facility installed in 1995.<br><br>**RST**<br><br>Shannon’s Esso was listed in the Retail Storage Tank (RST) database.<br><br>**FSTH**<br><br>Adil S Wain was listed in the Fuel Storage Tank – Historical (FSTH) database with three (3) gasoline USTs with capacities of 50,000 L (2) and 25,000 L (1) and one (1) diesel UST with a capacity of 25,000 L installed in 1983 and three (3) gasoline USTs with capacities of 46.400 L installed in 2000.<br><br>**CA, ECA**<br><br>Imperial Oil Limited. – one (1) CA and one (1) ECA, associated with industrial sewage works, were approved in 2009.<br><br>**DTNK**<br><br>Nissan Esso was listed in the Delisted Fuel Tank (DTNK) database as an expired fuel facility in 2013.<br><br>Al Truistic Inc. was listed in the Delisted Fuel Tank (DTNK) database with four (4) expired fuel tanks in 1989.<br><br>The property was listed in the Delisted Fuel Tank (DTNK) database as an expired fuel facility in 2021. |

| TABLE 4B: Environmental Sources of Information – Surrounding Properties | |
|---|---|
| Property Location Approximate Distance/ Direction From Site | Database Findings Pertaining to the Property |
| | **FST**<br>Mac's Convenience Stored Inc. was listed in the Fuel Storage Tank (FST) database with three (3) gasoline USTs with a capacity of 46,400 L installed in 2009.<br>Al Truistic Inc. was listed in the Fuel Storage Tank (FST) database with four (4) gasoline USTs with capacities of 25,000 L (2) and 50,000 L (2) installed in 1983.<br>1317942 Ontario Ltd. Esso Gas Station was listed in the Fuel Storage Tank (FST) database for one (1) gasoline UST with a capacity of 139,200 L installed in 2000.<br>**GEN**<br>Mac's Convenience Stores Inc. was listed as a generator of hazardous wastes (GEN) – waste class: waste oils/sludges (petroleum based) as of July 2020, as of November 2021 and as of October 2022. |
| 5006 South Service Road<br>15 m/Northeast | **GEN**<br>American Optics Ltd. was listed as a generator of hazardous wastes (GEN) – waste class: waste oils and lubricants (252), among others for the years 2014 to 2016 and waste crankcase oils and lubricants (252 L) as of December 2018 and as of October 2019.<br>Based on the nature of the operations and relatively short timeframe of waste generation, the above is not considered as a concern for the Site. |
| 5002 South Service Road<br>10 m/East | **SPL**<br>Union Gas Limited – a natural gas meter was damaged in 2018.<br>Based on the nature of the spill record, the above is not considered as a concern for the Site. |
| Intersection of Harvester Road and South Service Road<br>0 m/southeast | **SPL**<br>Diesel fuel released to the road due to equipment failure was reported in 2010. Soil contamination was confirmed.<br>Based on the cross to down gradient location, the above is not considered as a concern for the Site. |
| 5035 South Service Road<br>0 m/North | **CA**<br>Newcourt Financial Ltd. – one (1) CA, associated with a diesel generator was approved in 1998.<br>**SPL**<br>Small quantity of diesel fuel released to the road was reported in 2001.<br>Based on the type of operations and small volume of spill onto the road, the above is not considered as a concern for the Site. |

| TABLE 4B: Environmental Sources of Information – Surrounding Properties | |
|---|---|
| Property Location Approximate Distance/ Direction From Site | Database Findings Pertaining to the Property |
| 5044 South Service Road<br>50 m/Northeast | **GEN**<br>Aslan Technologies Inc., described as material handling equipment manufacturing, was listed as a generator of hazardous wastes (GEN) – waste class: waste oils and lubricants (252), among others for the year 2009.<br>Based on the short time frame of the above, the above is not considered as a concern for the Site. |
| 914 Appleby Line<br>40 m/West | **GEN**<br>Oak-Burl Industries Limited, described as machine shop industry, was listed as a generator of hazardous wastes (GEN) – waste class: emulsified oils (253) and waste oils and lubricants (252) for the years 1989 to 2012; waste oils and lubricants (252), oil skimmings and sludges (251) and emulsified oils (253) for the years to 2013 to 2016; and waste oils/sludges (petroleum based) (251 L), waste crankcase oils and sludges (252 L) and emulsified oils (253 L) as of December 2018, as of July 2020, as of November 2021 and as of October 2022.<br>Based on the cross-gradient location, the above is not considered as a concern for the Site. |
| 5109 Harvester Road<br>85 m/East | **SPL**<br>800 L spill of polymer solution released to parking lot was reported in 1993. Environmental impact was not anticipated.<br>**GEN**<br>Hardy Sales and Service Inc., described as tire etc. stores, was listed as a generator of hazardous wastes (GEN) – waste class: petroleum distillates (213) for the years 1995 to 1999.<br>Ainsworth Inc., described as tire etc. stores, was listed as a generator of hazardous wastes (GEN) – waste class: petroleum distillates (213) and oil skimmings and sludges (251) for the years 2000 to 2001.<br>Bazco Precision, described as machine shop ind., was listed as a generator of hazardous wastes (GEN) – waste class: oil skimmings and sludges (251), paint/pigment/coating residues (145), petroleum distillates (213), waste oils and lubricants (252) and emulsified oils (253) for the years 2001 to 2006 and emulsified oils for the years 2011 to 2016, as of December 2017, as of December 2018, as of July 2020, as of November 2021 and as of October 2022.<br>Based on the cross to down gradient location, the above is not considered as a concern for the Site. |
| Others | Databases reported for other properties were also reviewed, and were indicated to be associated with GEN, EASR and SPL records. Due to the nature of operations suggested by these records and/or intervening distances, these records at other properties within the phase I study area are considered unlikely to represent a source of contamination on and/or under the Site. |

Unplotted records in the ERIS report were also reviewed. These records were associated with CA, ECA, NPCB, SPL and GEN databases. No detailed address/information is available for those databases; thus, the environmental concern from those databases to the Site could not be determined.

Based on a review of records from the ERIS report and various environmental sources, potential environmental concerns were revealed from the adjacent properties within the phase I study area as follows:

**NEIGHBOURING PROPERTIES**

- 875 Appleby Line (adjacent to the south of the Site) – Operation of various gasoline service stations from the 1990s to present.

Due to the nature of operations suggested by the records reviewed, intervening distances and/or cross/downgradient locations from the Site, other records at the Site and other properties within the phase I study area are considered unlikely to represent a source of contamination on and/or under the Site.

### 4.1.8. Topographical, Geological and Hydrogeological Sources

Regional Topographical, Geological and Hydrogeological Conditions are presented in the following table:

| **TABLE 5: Topographical, Geological and Hydrogeological Sources** | |
|---|---|
| Topography and Drainage | |
| Source: | Natural Resources Canada – The Atlas of Canada online topography map. |
| Regional Conditions: | Grade elevation along Appleby Line slopes towards southeast from approximately 129 m above sea level (asl) at the intersection with Highway 403/QEW to approximately 102 m asl at the intersection with Pinedale Avenue. Grade elevation along Harvester Road is relatively flat at 110 m asl. |
| Site Conditions: | The Site area is generally flat, and the ground surface elevation of the Site is approximately 112 m asl.<br>Run-off drainage is expected to be directed towards on-site and street catch basins or infiltration at unpaved areas. |

| TABLE 5: Topographical, Geological and Hydrogeological Sources | |
|---|---|
| Surficial Geology | |
| Source: | Surficial Geology of Southern Ontario, Ontario Geological Survey 2010; ERIS report MECP Water Well Records. |
| Regional Stratigraphic Conditions: | Paleozoic bedrock.<br>A review of the well records listed within the phase I study area indicated that the local stratigraphy generally consists of brown gravel (0 – 0.31 m below ground surface, bgs) overlying red shale. |
| Site Conditions: | It is expected that subsurface soil conditions at the Site approach regional stratigraphic conditions. |
| Bedrock Geology | |
| Source: | Bedrock Geology of Ontario, Ontario Geological Survey 2011. |
| Regional Bedrock Conditions: | Shale, limestone, dolostone, siltstone Queenston Formation<br>Approximate depth to bedrock in the area is 2 m below grade. |
| Site Conditions: | It is expected that bedrock conditions underlying the Site approach regional stratigraphic conditions. |
| Hydrogeology | |
| Source: | Freeze and Cheery 1979; Holtz and Kovacs 1981; ERIS report MECP Water Well Records. |
| Regional Conditions: | A review of the well records listed within the phase I study area indicated that the local stratigraphy generally consists of brown gravel (0 – 0.31 m below ground surface, bgs) overlying red shale. The surficial deposits within the study area consist mainly of shale, with a typical range of hydraulic conductivity of $10^{-7}$ – $10^{-10}$ cm/sec. |
| Site Conditions: | It is expected that hydrogeological conditions underlying the Site approach regional conditions. |
| Nearest Open Water Body: | Appleby Creek, located approximately 360 m east of the Site and flows in a southerly direction towards Lake Ontario, located approximately 2.9 km south of the Site. |
| Inferred Groundwater Flow Direction: | Southeast, based on regional topography and proximity to nearest open water body |

Regional Topographical and Geological Maps (Figures B, C and D) that include the phase I study area are attached in Appendix A.

## 4.2 Other Available Records

No other records pertaining to the phase I study area were available for review.

# 5. SITE RECONNAISSANCE

A visit at the Site, and at remaining publicly accessible phase I study area, was conducted by Mrs. Lena Johnston of Fisher on August 29, 2023. The assessor was not accompanied during the Site visit. Selected photographs taken at the phase I study area visit are included in Appendix C.

## 5.1. General

The objectives of the site reconnaissance are to determine if recognized environmental conditions exist on, in or under the Site, and to identify details of potential contaminants of concern, potential contaminant pathways and potential source areas of contamination on, in or under the Site.

### 5.1.1. Methodology

Methodology of the site reconnaissance is presented in the following table:

| **TABLE 6: Site Reconnaissance Methodology** | |
|---|---|
| Date and Time of Investigation: | August 29, 2023, 10:30 a.m. |
| Weather Conditions: | Sunny, 20°C |
| Duration of the Investigation: | 1 hour |
| Operational Industrial or Commercial Facility: | Yes, commercial |
| Observation Methods: | Visual assessment and photographs of the Site's interior and exterior features. |
| Name and Qualifications of Assessor: | Lena Johnston, C.E.T. |

### 5.1.2. Limitations

At the time of the Site visit, the main kitchen area of Tim Hortons and Wendy's was not fully accessed. The roof was not accessed as it was not part of the scope of work for this investigation.

### 5.1.3. Current Property Use and Activities

The Site is located on the northwest corner of the intersection of Harvester Road and South Service Road. It has an area of approximately 2.27 hectares (5.61 acres). The Site is bounded by Harvester Road followed by commercial developments to the south, South Service Road followed by commercial buildings to the east, an Esso gasoline service station adjacent to the southwest, and Appleby Line followed by commercial developments to the west, and a commercial building to the north.

Based on our Site reconnaissance on August 29, 2023, the southern portion of the Site is occupied by a one-storey commercial building occupied by a “Tim Hortons” coffee shop and a “Wendy’s” restaurant (the “subject building”). Areas surrounding the Site are asphalt paved for parking and driving with landscaping along the perimeter. The northern portion of the Site is undeveloped vegetated land.

No current Site activities representing a potential environmental concern to the Site were identified at the time of the Site visit.

### 5.1.4. Hazardous Materials Inventory

No hazardous materials were identified on-site at the time of our visit.

### 5.1.5. Fuels and Chemicals

No fuels or chemicals were observed at the time of our visit.

### 5.1.6. Waste Generation and Storage

No waste materials, other than domestic wastes, are generated at the Site, which are stored in the waste bin located to the north of the subject building.

### 5.1.7. Unidentified Substances

No unidentified substances or unidentified substances storage were noted on-site at the time of our visit.

### 5.1.8. Air Discharges and Odours

No sources of air emissions that are suspected to result in residual contamination to the property were identified on the Site. Furthermore, no strong, pungent, or unusual odours were identified during the Site visit.

### 5.1.9. Potable Water Supply

Properties within the phase I study area rely on municipal water obtained from surface water bodies as a source of drinking water. No water wells used for potable, domestic or livestock use were found in the MECP Water Well Information based on the ERIS report attached in Appendix B.

## *5.2. Exterior Observations*

### 5.2.1. Exterior of Building and Structures

The Site has an area of approximately 2.27 hectares (5.61 acres). The southern portion of the Site is occupied by a one-storey commercial building. Areas surrounding the subject building were asphalt paved for parking and driving. The remaining areas of the Site are undeveloped/ vegetated. A pad-mounted transformer is located at the central portion of the Site. Current Site operations include a “Tim Hortons” coffee shop and a “Wendy’s” restaurant.

The exterior concrete block and brick walls, as well as tar and gravel roof, were in good condition, with no evident signs of cracks, structural damage or staining.

### 5.2.2. Wells, Pits, Lagoons, Watercourses, Ditches or Standing Water

No evidence of abandoned or existing wells, pits, lagoons, watercourses, ditches or standing water was identified on the Site.

### 5.2.3. Sewage and Waste Water Disposal

Storm water accumulated on the paved areas is draining by overland flow towards on-site catch basins located to the north, east and south of the subject building, and off-site catch basin along Harvester Road to the south and South Service Road to the east. No wastewater discharges, other than domestic wastewater, were identified to be produced on the Site at the time of the visit.

Domestic wastewater is inferred to be discharged into the municipal sanitary sewer system running under Harvester Road to the south or South Service Road to the east.

### 5.2.4. Stained Materials, Stressed Vegetation and Fill Materials

No stained material or stressed vegetation was observed at the Site. No staining was observed on the concrete pad around the on-site pad-mounted transformer or garbage bins.

The grade of the Site is similar to adjacent properties. No obvious evidence of imported fill materials was noted on-site. Considering the on-site building and property use, it is unlikely that significant quantities of fill materials from uncontrolled sources were brought onto the Site prior to or during Site development.

## *5.3. Interior Observations*

### 5.3.1. Interior of Building and Structures

The building consists of the following areas: seating area, kitchen, refrigeration and washrooms.

The building materials include floor coverings of ceramic tiles and concrete; walls consist of drywall; and ceilings consist of drywall. Incandescent lighting was observed in all areas of the building. Thermostats were observed in various areas of the building.

### 5.3.2. Heating and Cooling

The building is provided with heating and cooling by roof-top, natural gas-fired HVAC units.

### 5.3.3. Stains

No evidence of stains was observed inside the building during the Site visit.

### 5.3.4. Drains, Sumps and Oil/Water Separators

Floor drains were observed in the washrooms.

No sumps, interceptors, trenches or oil/water separators were observed inside the building.

### 5.3.5. Hydraulic Equipment

No hydraulic equipment related to building systems and/or on-site operations was identified.

### 5.3.6. Designated Substances and Other Special Attention Items

The Occupational Health and Safety Act (OHSA), R.S.O. 1990 defines a toxic substance as a chemical, biological or physical agent whose presence or use in the workplace may endanger the health and safety of a worker. The parts of the Act that deals with toxic substances are intended to:

1) ensure that worker exposure to toxic substances is controlled;
2) ensure that toxic substances in the workplace are clearly identified and that workers receive enough information about them to be able to handle them safely; and
3) provide the general public with access to information about toxic substances used by industry in their communities.

The Act allows a toxic substance to be “designated”, and its use in the workplace to be either prohibited or strictly controlled. Designation is reserved for substances that are particularly hazardous.

All accessible spaces within the building were visually inspected for the potential presence of Designated Substances and Other Special Attention Items of concern, and the following findings were noted:

**TABLE 7: Designated Substances and Other Special Attention Items**

| Designated Substances and Other Special Attention Items | Matrix/ Source | Present On-Site | Location On-Site | Matrix/ Source Condition |
|---|---|---|---|---|
| Friable Asbestos-Containing Materials (ACMs) | Pipe Elbow Insulation, Drywall Joint Compound, Plaster, Texture Coats | No | Not Applicable | Not Applicable |
| Non-friable ACMs | Vinyl Floor Tiles, Ceiling Tiles | No | Not Applicable | Not Applicable |
| Polychlorinated Biphenyls (PCBs) | Fluorescent Light Ballasts, Transformer | No | Not Applicable | Not Applicable |

| TABLE 7: Designated Substances and Other Special Attention Items | | | | |
|---|---|---|---|---|
| Designated Substances and Other Special Attention Items | Matrix/ Source | Present On-Site | Location On-Site | Matrix/ Source Condition |
| Lead-Based Material | Interior Paint | No | Not Applicable | Not Applicable |
| Urea Formaldehyde Foam Insulation (UFFI) | Wall Insulation | No | Not Applicable | Not Applicable |
| Ozone-Depleting Substances (ODSs) | Refrigerator, Freezer, HVAC Equipment, Air Conditioner | Potentially | Interior of building, roof | Not inspected |
| Mould | Interior Walls, Ceilings | No | Not Applicable | Not Applicable |
| Radon Gas | Uranium rich Black shale and/or granite bedrock | No | Not Applicable | Not Applicable |
| Noise and Vibration | Not Applicable | No | Not Applicable | Not Applicable |

The assessment of the Site for potential presence of hazardous building materials was based on the age of the building and components, and a non-intrusive visual investigation of the Site. No sampling of materials was conducted.

Potential concerns and recommendations related to designated substances and other special attention items identified at the Site are listed and described in the following table:

| TABLE 8: Potential Concerns and Recommendations Associated with Designated Substances and Other Special Attention Items Identified at the Site | | | | |
|---|---|---|---|---|
| Matrix/ Source | Potentially Impacted Media | Potential Concern | Comments | Relative Degree of Environmental Risk and Recommendations |
| Refrigeration or HVAC equipment on the roof | Air | ODSs | MECP implemented O. Reg. 356, ODSs, under EPA, regarding the use, disposal and recycling of ODSs. Bulk storage of ODSs was not observed at the Site. | Low<br><br>If any ODS is encountered during renovation/demolition, disposal and recycling should be undertaken in accordance to O. Reg. 356, ODSs. |

The potential presence of ODS containing equipment identified at the Site are not considered of concern provided they are not disturbed or properly managed and disposed of. However, a designated substance survey (DSS) should be conducted at the Site prior to any demolition or significant renovation of the building.

## 5.4. Adjoining Properties Observation and Information

Surrounding properties adjacent to the Site at the time of the visit were identified as follows:

**TABLE 9: Current Use of Neighbouring Properties**

| Direction/Distance from/to Site | Address | Occupant | Across |
|---|---|---|---|
| 15 m east | 5105 Harvester Road | Lancaster Auto and Tire Discounter | South Service Road |
| 85 m east | 5109 Harvester Road | Architectural Accents Windows Doors and More | South Service Road |
| 0 m southwest | 875 Appleby Line | Esso Gas Station | N/A |
| 30 m west | N/A | Appleby Cemetery | Appleby Line |
| 40 m west | 914 Appleby Line | Oak-Burl Industries Ltd. | Appleby Line |
| 0 m north | 5100 South Service Road | Advanced Innovations Inc. | N/A |
| 30 m south | 821 Appleby Line | Fearmans Pork Inc., Sofina Foods | Harvester Road |

Potential environmental concerns were identified from the adjacent and neighbouring properties during the site visit as follows:

- Operation of an automobile service garage (Lancaster Auto and Tire Discounter) at 5105 Harvester Road, 15 m east of the Site. Drums of oil were observed;
- Operation of a gasoline service station (Esso Gas Station) at 875 Appleby Line, adjacent to the southwest.

# 6. INTERVIEWS

Interviews with persons relevant to the objectives of the Phase I ESA are conducted to obtain information determining if a recognized environmental condition exists at the Site, and to identify details of potentially contaminating activities or potential pathways in, on or under the Site.

## 6.1. Methodology

Fisher's Standard Questionnaire was used to conduct interviews with the Site owner. Interviews were conducted on August 29, 2023, in writing by electronic mail.

## 6.2. Limitations

All interview participants answered the asked questions to the best of their knowledge.

## 6.3. Interview Participants

**a. Property Owner: James Byck, Dymon Group of Companies**

The date, time, duration, method and place of the interview, name of interviewed person and reason for person selection, key questions and answers for each of the topics of the interview are included in Documentation of Interview form in Appendix D.

# 7. CONCLUSIONS AND RECOMMENDATIONS

The findings of the current Phase I ESA have revealed evidence of potential contamination associated with neighbouring properties within the phase I study area. The potential environmental concerns are listed and described in the following table:

**TABLE 10: Potential Contamination Associated with Other Properties Surrounding the Site**

| Area of Potential Contamination | Potentially Impacted Media | Potential Contaminants of Concern | Comments | Relative Degree of Environmental Risk and Recommendations |
|---|---|---|---|---|
| Operation of a gasoline service station at 875 Appleby Line, adjacent to the southwest. | Soil and groundwater | Metals, PHCs, PAHs. | Aerial photographs indicated that the property was developed as a gasoline service station since 1988.<br>Based on the ERIS report, various gasoline service stations occupied the property since the 1990s. Diesel fuel UST was historically listed for the property. | Moderate<br>Conduct Phase II ESA works on-site along the southwestern property boundary. |
| Operation of an autobody shop at 5105 Harvester Road, 15 m east of the Site. | Soil and groundwater | Metals, PHCs, VOCs. | An autobody shop was observed during the Site reconnaissance. | Moderate<br>Conduct Phase II ESA works on-site along the eastern property boundary. |

Considering the recognized environmental conditions within the phase I study area, it is recommended that a Phase II ESA be conducted at the identified areas of potential environmental concern and along the potential contaminant transport pathways at the Site, to determine the location and concentration of potential contaminants in the land or water on, in or under the Site.

The potential presence of designated substances and other special attention items inside the building identified during our Site reconnaissance are not considered of concern provided they are properly managed and disposed or are not disturbed. However, a designated substance survey (DSS) should be conducted at the Site prior to any demolition or significant renovation of the building.

# 8. LIMITATIONS

This report was prepared for use by Dymon Group of Companies and is based on the work as described in the Scope of Work. The conclusions presented in this report reflect existing Site conditions within the scope of this assignment.

As conducted, the current investigation may lack information that are specific requirements for the purpose of filling a Record of Site Condition (RSC). Should a RSC be required, then complementary investigations should be undertaken under the RSC filing process.

There is no warranty, expressed or implied, by Fisher Engineering Limited that this environmental assessment has identified all potential sources of contaminants or contaminants at the Site or adjacent properties, or that the Site is free from any and all contamination from past or current practices other than that noted, nor that all issues of environmental compliance have been addressed.

Some information presented in this report was provided through existing documents and interviews. Although attempts were made, whenever possible, to consult alternative sources of information, in certain cases Fisher Engineering Limited has been required to assume that the information provided is accurate. We accept no responsibility for any deficiency, misstatements or inaccuracies contained in this report as a result of omissions, misinterpretations or fraudulent acts of the persons contacted.

No investigation method can eliminate the possibility of obtaining partially imprecise or incomplete information; it can only reduce the possibility to an acceptable level. Professional judgment was exercised in gathering and analyzing the information obtained and the formulation of the conclusions and recommendations. Like all professional persons rendering advice, we do not act as absolute insurers of the conclusions reached, but commit ourselves to care and competence in reaching those conclusions. No warranty, whether expressed or implied, is included or intended in this report.

The scope of services performed may not be appropriate for the purposes of other users. This report should not be used in contexts other than pertaining to the evaluation of the property at the current time. Written authorization must be obtained from Fisher Engineering Limited prior to use by any other parties, or any future use of this document or its findings, conclusions, or recommendations represented herein. Any use that a third party makes of this report, or any reliance on or decisions made on the basis of it, are the responsibility of the third parties. Fisher Engineering Limited accepts no responsibility for damages, if any, suffered by any third party as a result of decisions made or actions based on this report.

# 9. QUALIFICATIONS OF THE ASSESSOR

The current investigation was conducted and managed by Mrs. Lena Johnston, C.E.T., who has been trained and has 9 years of experience in conducting Phase I ESAs in accordance with the CSA Standard. Mrs. Johnston has conducted more than 250 Phase I ESAs for commercial/ industrial/residential clients and government agencies and is routinely engaged in this field.

This report was reviewed by Mr. Bernard Chan, who is a Professional Engineer with Professional Engineers Ontario and has over 20 years of experience in conducting, management and supervision of Phase One ESAs. Mr. Chan was also involved in providing oversight and technical support during the course of this assessment.


As a Qualified Person who conducts and supervises Phase I ESAs, Mr. David Fisher, president of Fisher Engineering Limited, is a senior Managerial and Environmental Engineering Specialist with over 30 years of progressive, innovative experience in the Petrochemical and Environmental Engineering Industry. Mr. Fisher is responsible for the development and management of a progressive environmental consulting engineering company specializing in environmental site assessments and remediation, geotechnical and hydrogeological investigations, tank removals, PCB waste treatment, land reclamation, recycling, hazardous waste disposal, and associated laboratory analytical practices.

Fisher Engineering Limited has been established as a team of engineers and consultants since 1989, and continues to develop a strong, wide client base. The company is staffed with personnel holding graduate or postgraduate qualifications at the Toronto headquarters, as well as specialist associates offering a broad range of expertise and knowledge in environmental consulting. With a background in the petroleum industry, extensive experience has been gained in the prevention and cleanup of contamination in air, water and soil.

# 10. REFERENCES


- Canadian Standards Association (CSA) Standard Z768-01 (reaffirmed in 2022), *Phase I Environmental Site Assessment*;
- Ontario Regulation 153/04 (Records of Site Condition – Part XV.1 of the EPA), as amended;
- Occupational Health and Safety Act (OHSA), R.S.O. 1990, Ministry of Labour;
- Environmental Risk Information Services (ERIS) Aerial Photograph Database, Aerial Photographs 1960, 1974, 1988 and 2022;
- Google Earth Maps;
- Opta Information Intelligence (Opta) – Enviroscan™ Report, Fire Insurance Records;
- ERIS Database Report, Project No. 23081700823, August 22, 2023;
- Ministry of the Environment, Conservation and Parks (MECP) Freedom of Information (FOI) and Privacy Protection Office;
- Technical Standards and Safety Authority (TSSA);
- Ontario Environmental Site Registry;
- Ministry of Natural Resources and Forestry (MNRF) Natural Heritage Map;
- Natural Resources Canada - The Atlas of Canada online topography map;
- *Surficial Geology of Southern Ontario,* Ontario Geological Survey, 2010;
- *Bedrock Geology of Ontario,* Ontario Geological Survey 2011;
- *Groundwater,* Freeze and Cherry 1979; and
- *An Introduction to Geotechnical Engineering,* Holtz and Kovacs 1981.

# APPENDIX A – FIGURES




FISHER ENGINEERING

400 Esna Park Dr., #15
Markham, Ontario
L3R 3K2

Tel: 905 475-7755

NORTH

N

LEGEND

PROJECT NAME AND ADDRESS


PHASE I ESA

5051 Harvester Road,
Burlington, ON

FIGURE A:

SITE LOCATION MAP

| PROJECT NO. | SHEET NO. |
|---|---|
| FE 23-13262 | A |
| DATE: 31 August 2023 | |
| SCALE: AS SHOWN | |




FISHER ENGINEERING

400 Esna Park Dr., #15
Markham, Ontario
L3R 3K2

Tel: 905 475-7755

NORTH

N

LEGEND

SITE BOUNDARY

PROJECT NAME AND ADDRESS

PHASE I ESA

5051 Harvester Road,
Burlington, ON

FIGURE B:

TOPOGRAPHICAL MAP

| PROJECT NO. | SHEET NO. |
|---|---|
| FE 23-13262 | B |
| DATE: 31 August 2023 | |
| SCALE: AS SHOWN | |




FISHER ENGINEERING

400 Esna Park Dr., #15
Markham, Ontario
L3R 3K2

Tel: 905 475-7755
Fax: 905 475-7718

NORTH

N

LEGEND

**3 PALEOZOIC BEDROCK**

**5D TILL**
Clay to silt-textured till (derived from glaciolacustrine deposits or shale)

PROJECT NAME AND ADDRESS

# PHASE I ESA

5051 Harvester Road,
Burlington, ON

FIGURE C:

SURFICIAL GEOLOGY

| PROJECT NO. | SHEET NO. |
|---|---|
| FE 23-13262 | C |
| DATE: 31 August 2023 | |
| SCALE: AS SHOWN | |




FISHER ENGINEERING

400 Esna Park Dr., #15
Markham, Ontario
L3R 3K2

Tel: 905 475-7755

NORTH

N

LEGEND

**55A:**
Shale, limestone, dolostone, siltstone
Queenston Formation

**55B:**
Shale, limestone, dolostone, siltstone
Georgian Bay Formation; Blue Mountain Formation; Billings Formation; Collingwood Member; Eastview Member

**56C:**
Sandstone, shale, dolostone, siltstone
Armabel Formation

**56D:**
Sandstone, shale, dolostone, siltstone
Clinton Group; Cataract Group

PROJECT NAME AND ADDRESS

# PHASE I ESA

5051 Harvester Road,
Burlington, ON

FIGURE D:

BEDROCK GEOLOGY

| PROJECT NO. | SHEET NO. |
|---|---|
| FE 23-13262 | D |
| DATE: 31 August 2023 | |
| SCALE: AS SHOWN | |




FISHER ENGINEERING

400 Esna Park Dr., #15
Markham, Ontario
L3R 3K2

Tel: 905 475-7755

NORTH

N

LEGEND

SITE BOUNDARY

PROJECT NAME AND ADDRESS

# PHASE I ESA

5051 Harvester Road,
Burlington, ON

FIGURE E.1:

AERIAL PHOTOGRAPH 1960

| PROJECT NO. | SHEET NO. |
|---|---|
| FE 23-13262 | E.1 |
| DATE: 31 August 2023 | |
| SCALE: AS SHOWN | |




FISHER ENGINEERING

400 Esna Park Dr., #15
Markham, Ontario
L3R 3K2

Tel: 905 475-7755

NORTH

N

LEGEND

SITE BOUNDARY

PROJECT NAME AND ADDRESS

# PHASE I ESA

5051 Harvester Road,
Burlington, ON

FIGURE E.2:

AERIAL PHOTOGRAPH 1974

| PROJECT NO. | SHEET NO. |
|---|---|
| FE 23-13262 | E.2 |
| DATE: 31 August 2023 | |
| SCALE: AS SHOWN | |




FISHER ENGINEERING

400 Esna Park Dr., #15
Markham, Ontario
L3R 3K2

Tel: 905 475-7755

NORTH

N

LEGEND

SITE BOUNDARY

PROJECT NAME AND ADDRESS

# PHASE I ESA

5051 Harvester Road,
Burlington, ON

FIGURE E.3:

AERIAL PHOTOGRAPH 1988

| PROJECT NO. | SHEET NO. |
|---|---|
| FE 23-13262 | E.3 |
| DATE: 31 August 2023 | |
| SCALE: AS SHOWN | |




FISHER ENGINEERING

400 Esna Park Dr., #15
Markham, Ontario
L3R 3K2

Tel: 905 475-7755

NORTH

N

LEGEND

SITE BOUNDARY

PROJECT NAME AND ADDRESS

# PHASE I ESA

5051 Harvester Road,
Burlington, ON

FIGURE E.4:

AERIAL PHOTOGRAPH 2022

| PROJECT NO. | SHEET NO. |
|---|---|
| FE 23-13262 | E.4 |
| DATE: 31 August 2023 | |
| SCALE: AS SHOWN | |

# APPENDIX B – RECORDS REVIEW DOCUMENTS

# DATABASE REPORT

| | |
|---|---|
| **Project Property:** | *PH I ESA*<br>*5051 Harvester Road*<br>*Burlington ON L7L 5Y7* |
| **Project No:** | |
| **Report Type:** | *Standard Express Report* |
| **Order No:** | *23081700823* |
| **Requested by:** | *Fisher Engineering Limited* |
| **Date Completed:** | *August 17, 2023* |

**Environmental Risk Information Services**
*A division of Glacier Media Inc.*
1.866.517.5204 | info@erisinfo.com | erisinfo.com

# Table of Contents


Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....6
Executive Summary: Site Report Summary - Surrounding Properties.....7
Executive Summary: Summary By Data Source.....19
Map.....35
Aerial.....36
Topographic Map.....37
Detail Report.....38
Unplottable Summary.....119
Unplottable Report.....123
Appendix: Database Descriptions.....150
Definitions.....160



**Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY**

**Reliance on information in Report:** This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a database review of environmental records.

**License for use of information in Report:** No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

**Your Liability for misuse:** Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

**No warranty of Accuracy or Liability for ERIS:** The information contained in this report has been produced by ERIS Information Limited Partnership ("ERIS") using various sources of information, including information provided by Federal and Provincial government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

**Trademark and Copyright:** You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Limited Partnership. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

# Executive Summary

***Property Information:***

| | |
|---|---|
| **Project Property:** | *PH I ESA*<br>*5051 Harvester Road  Burlington ON L7L 5Y7* |
| **Project No:** | |

**Coordinates:**

| | |
|---|---|
| **Latitude:** | *43.3791272* |
| **Longitude:** | *-79.7674121* |
| **UTM Northing:** | *4,803,655.32* |
| **UTM Easting:** | *599,846.75* |
| **UTM Zone:** | *17T* |

| | |
|---|---|
| **Elevation:** | *368 FT*<br>*112.26 M* |

***Order Information:***

| | |
|---|---|
| **Order No:** | *23081700823* |
| **Date Requested:** | *August 17, 2023* |
| **Requested by:** | *Fisher Engineering Limited* |
| **Report Type:** | *Standard Express Report* |

***Historical/Products:***

| | |
|---|---|
| **Aerial Photographs** | *Aerials - National Collection* |
| **City Directory Search** | *CD - QUOTE Custom City Directory Search* |
| **ERIS Xplorer** | *ERIS Xplorer* |

# Executive Summary: Report Summary

| Database | Name | Searched | Project Property | Within 0.25 km | Total |
|---|---|---|---|---|---|
| AAGR | Abandoned Aggregate Inventory | Y | 0 | 0 | 0 |
| AGR | Aggregate Inventory | Y | 0 | 0 | 0 |
| AMIS | Abandoned Mine Information System | Y | 0 | 0 | 0 |
| ANDR | Anderson's Waste Disposal Sites | Y | 0 | 0 | 0 |
| AST | Aboveground Storage Tanks | Y | 0 | 0 | 0 |
| AUWR | Automobile Wrecking & Supplies | Y | 0 | 0 | 0 |
| BORE | Borehole | Y | 0 | 0 | 0 |
| CA | Certificates of Approval | Y | 0 | 2 | 2 |
| CDRY | Dry Cleaning Facilities | Y | 0 | 0 | 0 |
| CFOT | Commercial Fuel Oil Tanks | Y | 0 | 0 | 0 |
| CHEM | Chemical Manufacturers and Distributors | Y | 0 | 0 | 0 |
| CHM | Chemical Register | Y | 0 | 0 | 0 |
| CNG | Compressed Natural Gas Stations | Y | 0 | 0 | 0 |
| COAL | Inventory of Coal Gasification Plants and Coal Tar Sites | Y | 0 | 0 | 0 |
| CONV | Compliance and Convictions | Y | 0 | 0 | 0 |
| CPU | Certificates of Property Use | Y | 0 | 0 | 0 |
| DRL | Drill Hole Database | Y | 0 | 0 | 0 |
| DTNK | Delisted Fuel Tanks | Y | 0 | 8 | 8 |
| EASR | Environmental Activity and Sector Registry | Y | 0 | 1 | 1 |
| EBR | Environmental Registry | Y | 0 | 0 | 0 |
| ECA | Environmental Compliance Approval | Y | 0 | 1 | 1 |
| EEM | Environmental Effects Monitoring | Y | 0 | 0 | 0 |
| EHS | ERIS Historical Searches | Y | 0 | 15 | 15 |
| EIIS | Environmental Issues Inventory System | Y | 0 | 0 | 0 |
| EMHE | Emergency Management Historical Event | Y | 0 | 0 | 0 |
| EPAR | Environmental Penalty Annual Report | Y | 0 | 0 | 0 |
| EXP | List of Expired Fuels Safety Facilities | Y | 0 | 0 | 0 |
| FCON | Federal Convictions | Y | 0 | 0 | 0 |
| FCS | Contaminated Sites on Federal Land | Y | 0 | 0 | 0 |
| FOFT | Fisheries & Oceans Fuel Tanks | Y | 0 | 0 | 0 |
| FRST | Federal Identification Registry for Storage Tank Systems (FIRSTS) | Y | 0 | 0 | 0 |
| FST | Fuel Storage Tank | Y | 0 | 8 | 8 |
| FSTH | Fuel Storage Tank - Historic | Y | 0 | 2 | 2 |
| GEN | Ontario Regulation 347 Waste Generators Summary | Y | 4 | 73 | 77 |
| GHG | Greenhouse Gas Emissions from Large Facilities | Y | 0 | 0 | 0 |
| HINC | TSSA Historic Incidents | Y | 0 | 0 | 0 |
| IAFT | Indian & Northern Affairs Fuel Tanks | Y | 0 | 0 | 0 |

| Database | Name | Searched | Project Property | Within 0.25 km | Total |
|---|---|---|---|---|---|
| INC | Fuel Oil Spills and Leaks | Y | 0 | 0 | 0 |
| LIMO | Landfill Inventory Management Ontario | Y | 0 | 0 | 0 |
| MINE | Canadian Mine Locations | Y | 0 | 0 | 0 |
| MNR | Mineral Occurrences | Y | 0 | 0 | 0 |
| NATE | National Analysis of Trends in Emergencies System (NATES) | Y | 0 | 0 | 0 |
| NCPL | Non-Compliance Reports | Y | 0 | 0 | 0 |
| NDFT | National Defense & Canadian Forces Fuel Tanks | Y | 0 | 0 | 0 |
| NDSP | National Defense & Canadian Forces Spills | Y | 0 | 0 | 0 |
| NDWD | National Defence & Canadian Forces Waste Disposal Sites | Y | 0 | 0 | 0 |
| NEBI | National Energy Board Pipeline Incidents | Y | 0 | 0 | 0 |
| NEBP | National Energy Board Wells | Y | 0 | 0 | 0 |
| NEES | National Environmental Emergencies System (NEES) | Y | 0 | 0 | 0 |
| NPCB | National PCB Inventory | Y | 0 | 0 | 0 |
| NPR2 | National Pollutant Release Inventory 1993-2020 | Y | 0 | 0 | 0 |
| NPRI | National Pollutant Release Inventory - Historic | Y | 0 | 1 | 1 |
| OGWE | Oil and Gas Wells | Y | 0 | 0 | 0 |
| OOGW | Ontario Oil and Gas Wells | Y | 0 | 0 | 0 |
| OPCB | Inventory of PCB Storage Sites | Y | 0 | 0 | 0 |
| ORD | Orders | Y | 0 | 0 | 0 |
| PAP | Canadian Pulp and Paper | Y | 0 | 0 | 0 |
| PCFT | Parks Canada Fuel Storage Tanks | Y | 0 | 0 | 0 |
| PES | Pesticide Register | Y | 0 | 0 | 0 |
| PINC | Pipeline Incidents | Y | 0 | 0 | 0 |
| PRT | Private and Retail Fuel Storage Tanks | Y | 0 | 2 | 2 |
| PTTW | Permit to Take Water | Y | 0 | 0 | 0 |
| REC | Ontario Regulation 347 Waste Receivers Summary | Y | 0 | 0 | 0 |
| RSC | Record of Site Condition | Y | 0 | 0 | 0 |
| RST | Retail Fuel Storage Tanks | Y | 0 | 1 | 1 |
| SCT | Scott's Manufacturing Directory | Y | 0 | 22 | 22 |
| SPL | Ontario Spills | Y | 0 | 10 | 10 |
| SRDS | Wastewater Discharger Registration Database | Y | 0 | 0 | 0 |
| TANK | Anderson's Storage Tanks | Y | 0 | 0 | 0 |
| TCFT | Transport Canada Fuel Storage Tanks | Y | 0 | 0 | 0 |
| VAR | Variances for Abandonment of Underground Storage Tanks | Y | 0 | 0 | 0 |
| WDS | Waste Disposal Sites - MOE CA Inventory | Y | 0 | 0 | 0 |
| WDSH | Waste Disposal Sites - MOE 1991 Historical Approval Inventory | Y | 0 | 0 | 0 |
| WWIS | Water Well Information System | Y | 0 | 10 | 10 |
| | **Total:** | | 4 | 156 | 160 |

# Executive Summary: Site Report Summary - Project Property

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 1 | GEN | BARHAV DEVELOPMENT TIMWEN PARTNERSHIP | 5051 HARVESTER RD BURLINGTON ON L7L 6S1 | NE/16.6 | -0.45 | 38 |
| 1 | GEN | BARHAV DEVELOPMENT TIMWEN PARTNERSHIP | 5051 HARVESTER RD BURLINGTON ON L7L 6S1 | NE/16.6 | -0.45 | 38 |
| 1 | GEN | BARHAV DEVELOPMENT TIMWEN PARTNERSHIP | 5051 HARVESTER RD BURLINGTON ON L7L 6S1 | NE/16.6 | -0.45 | 38 |
| 1 | GEN | BARHAV DEVELOPMENT TIMWEN PARTNERSHIP | 5051 HARVESTER RD BURLINGTON ON L7L 6S1 | NE/16.6 | -0.45 | 39 |

# Executive Summary: Site Report Summary - Surrounding Properties

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 2 | SPL | ESSO PETROLEUM CANADA | JULIE'S ESSO SERVICE STATION AT 875 APPLEBY LINE, TEL 905-681-8874. SERVICE STATION BURLINGTON CITY ON L7L 5R4 | SSE/58.8 | -1.68 | 39 |
| 2 | PRT | NISSAN ESSO | 875 APPLEBY LINE BURLINGTON ON L7L 5R4 | SSE/58.8 | -1.68 | 40 |
| 2 | PRT | 779584 ONTARIO INC JULIES ESSO | 875 APPLEBY LINE BURLINGTON ON L7L5R4 | SSE/58.8 | -1.68 | 40 |
| 2 | RST | SHANNON'S ESSO | 875 APPLEBY LINE BURLINGTON ON L7L5R4 | SSE/58.8 | -1.68 | 40 |
| 2 | FSTH | ADIL S WAIN | 875 APPLEBY LINE BURLINGTON ON L7L 5R4 | SSE/58.8 | -1.68 | 40 |
| 2 | FSTH | ADIL S WAIN | 875 APPLEBY LINE BURLINGTON ON L7L 5R4 | SSE/58.8 | -1.68 | 41 |
| 2 | CA | Imperial Oil Limited | 845 Appleby Line Burlington ON | SSE/58.8 | -1.68 | 41 |
| 2 | DTNK | NISSAN ESSO | 875 APPLEBY LINE BURLINGTON ON L7L 5R4 | SSE/58.8 | -1.68 | 42 |
| 2 | DTNK | ADIL S WAIN | 875 APPLEBY LINE BURLINGTON ON | SSE/58.8 | -1.68 | 42 |
| 2 | FST | MAC'S CONVENIENCE STORES INC | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA ON | SSE/58.8 | -1.68 | 43 |
| 2 | FST | MAC'S CONVENIENCE STORES INC | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA ON | SSE/58.8 | -1.68 | 44 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 2 | FST | MAC'S CONVENIENCE STORES INC | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA ON | SSE/58.8 | -1.68 | 44 |
| 2 | DTNK | ALTRUISTIC INC | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA ON | SSE/58.8 | -1.68 | 45 |
| 2 | DTNK | ALTRUISTIC INC | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA ON | SSE/58.8 | -1.68 | 45 |
| 2 | DTNK | ALTRUISTIC INC | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA ON | SSE/58.8 | -1.68 | 46 |
| 2 | DTNK | ALTRUISTIC INC | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA ON | SSE/58.8 | -1.68 | 46 |
| 2 | DTNK | 1317942 ONTARIO LTD O/A ESSO GAS STATION | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA ON | SSE/58.8 | -1.68 | 47 |
| 2 | EHS | | 875 Appleby Line Burlington ON L7L5R4 | SSE/58.8 | -1.68 | 48 |
| 2 | ECA | Imperial Oil Limited | 845 Appleby Line Burlington ON M3C 1K5 | SSE/58.8 | -1.68 | 48 |
| 2 | GEN | Mac's Convenience Stores Inc. | 875 Appleby Line Burlington ON L7L 5R4 | SSE/58.8 | -1.68 | 48 |
| 2 | FST | ALTRUISTIC INC | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA ON | SSE/58.8 | -1.68 | 49 |
| 2 | FST | ALTRUISTIC INC | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA ON | SSE/58.8 | -1.68 | 49 |
| 2 | DTNK | | 875 APPLEBY LINE BURLINGTON ON L7L 5R4 | SSE/58.8 | -1.68 | 50 |
| 2 | FST | ALTRUISTIC INC | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA ON | SSE/58.8 | -1.68 | 50 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 2 | FST | 1317942 ONTARIO LTD O/A ESSO GAS STATION | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA<br>ON | SSE/58.8 | -1.68 | 51 |
| 2 | FST | ALTRUISTIC INC | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA<br>ON | SSE/58.8 | -1.68 | 51 |
| 2 | GEN | Mac's Convenience Stores Inc. | 875 Appleby Line<br>Burlington ON L7L 5R4 | SSE/58.8 | -1.68 | 52 |
| 2 | GEN | Mac's Convenience Stores Inc. | 875 Appleby Line<br>Burlington ON L7L 5R4 | SSE/58.8 | -1.68 | 52 |
| 3 | SCT | American Optics Inc. | 5006 South Service Rd Unit 3-4<br>Burlington ON L7L 5Y7 | NNE/117.6 | 1.63 | 52 |
| 3 | GEN | American Optics Inc. | 5006 South Service Rd., Unit 4<br>Burlington ON | NNE/117.6 | 1.63 | 53 |
| 3 | GEN | American Optics Ltd. | 5006 South Service Rd., Unit 4<br>Burlington ON L7L 5Y7 | NNE/117.6 | 1.63 | 53 |
| 3 | GEN | American Optics Inc. | 5006 South Service Rd., Unit 4<br>Burlington ON L7L 5Y7 | NNE/117.6 | 1.63 | 53 |
| 3 | GEN | American Optics Inc. | 5006 South Service Rd., Unit 4<br>Burlington ON L7L 5Y7 | NNE/117.6 | 1.63 | 54 |
| 3 | GEN | American Optics Ltd. | 5006 South Service Rd., Unit 4<br>Burlington ON L7L 5Y7 | NNE/117.6 | 1.63 | 54 |
| 3 | GEN | American Optics Ltd. | 5006 South Service Rd., Unit 4<br>Burlington ON L7L 5Y7 | NNE/117.6 | 1.63 | 55 |
| 4 | SCT | Burkert Contromatic Inc. | 5002 South Service Rd<br>Burlington ON L7L 5Y7 | NE/120.9 | -1.11 | 55 |
| 4 | SPL | Union Gas Limited | 5002 South Service Road<br>Burlington ON | NE/120.9 | -1.11 | 55 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 5 | WWIS | | lot 5 con 3<br>ON<br>**Well ID:** 7385973 | ENE/122.7 | -2.45 | 56 |
| 6 | EHS | | Appleby Line & Harvester Road<br>Burlington ON L7L 4W9 | E/128.7 | -3.40 | 57 |
| 7 | SPL | MF Grading Sevice<UNOFFICIAL> | Intersection of Harvester Rd and South Service Rd<br>Burlington ON | E/129.2 | -3.40 | 57 |
| 8 | WWIS | | lot 5 con 3<br>ON<br>**Well ID:** 7381453 | ENE/131.6 | -2.44 | 58 |
| 9 | WWIS | | lot 5 con 3<br>ON<br>**Well ID:** 7385972 | E/132.2 | -3.18 | 59 |
| 10 | WWIS | | lot 5 con 3<br>ON<br>**Well ID:** 7385969 | ENE/144.5 | -2.40 | 59 |
| 11 | WWIS | | lot 5 con 3<br>ON<br>**Well ID:** 7385971 | ENE/152.3 | -3.44 | 60 |
| 12 | CA | NEWCOURT FINANCIAL LTD. | 5035 SOUTH SERVICE ROAD<br>BURLINGTON ON L7L 6M9 | NW/160.7 | 2.59 | 61 |
| 12 | NPRI | O&Y ENTERPRISE | 5035 SOUTH SERVICE Road<br>BURLINGTON ON L7R4C8 | NW/160.7 | 2.59 | 61 |
| 13 | EHS | | 5105 & 5109 Harvester and 5002 South Service Road<br>Burlington ON L7L 5Y9 | NE/184.7 | -1.31 | 63 |
| 13 | EHS | | 5105 & 5109 Harvester and 5002 South Service Road<br>Burlington ON L7L 5Y9 | NE/184.7 | -1.31 | 63 |
| 14 | SPL | SEARS CANADA INC. | APPLEBY & HARVESTER RD MOTOR VEHICLE (OPERATING FLUID)<br>BURLINGTON CITY ON | S/184.9 | -5.19 | 63 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 14 | SPL | Union Gas Limited | Harvester Road and Appleby Line<br>Burlington ON | S/184.9 | -5.19 | 64 |
| 14 | SPL | Rothsay, Member of Maple Leaf Foods | Lights at Harvester Road and Appleby Line<br>Burlington ON | S/184.9 | -5.19 | 64 |
| 15 | SCT | Aslan Technologies Inc. | 5044 South Service Rd<br>Burlington ON L7L 5Y7 | N/191.1 | 3.65 | 65 |
| 15 | SCT | SSI EQUIPMENT INC. | 5044A SOUTH SERVICE RD<br>BURLINGTON ON L7L 5Y7 | N/191.1 | 3.65 | 65 |
| 15 | SCT | SSI EQUIPMENT INC. | 5044 SOUTH SERVICE RD<br>BURLINGTON ON L7L 5Y7 | N/191.1 | 3.65 | 66 |
| 15 | GEN | ASLAN TECHNOLOGIES INC. | 5044 SOUTH SERVICE ROAD<br>BURLINGTON ON L7L 5Y7 | N/191.1 | 3.65 | 66 |
| 15 | EHS | | 5044 South Service Rd<br>Burlington ON L7L 5Y7 | N/191.1 | 3.65 | 67 |
| 15 | EHS | | 5044 South Service Road<br>Burlington ON L7L 5Y7 | N/191.1 | 3.65 | 67 |
| 15 | EHS | | 5044 South Service Road<br>Burlington ON L7L 5Y7 | N/191.1 | 3.65 | 67 |
| 16 | WWIS | | 870 APPLEBY LINE<br>BURLINGTON ON<br>***Well ID:*** 7289963 | SSW/193.6 | -2.22 | 67 |
| 17 | WWIS | | 821 APPLEBY LINE<br>BURLINGTON ON<br>***Well ID:*** 7345219 | ESE/194.2 | -5.72 | 70 |
| 18 | GEN | Long Wing International | 5012 South Service Road<br>Burlington ON L7L5Y7 | NNE/199.5 | 2.13 | 74 |
| 19 | WWIS | | 870 APPLEBY LINE<br>BURLINGTON ON<br>***Well ID:*** 7289962 | SSW/201.8 | -4.30 | 74 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 20 | SCT | Oak-Burl Industries Ltd. | 914 Appleby Line<br>Burlington ON L7L 2Y8 | WSW/205.5 | 2.59 | 77 |
| 20 | GEN | OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE<br>BURLINGTON ON L7L 2Y8 | WSW/205.5 | 2.59 | 77 |
| 20 | GEN | OAK-BURL INDUSTRIES LIMITED 29-482 | 914 APPLEBY LINE<br>BURLINGTON ON L7L 2Y8 | WSW/205.5 | 2.59 | 78 |
| 20 | GEN | OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE<br>BURLINGTON ON L7L 2Y8 | WSW/205.5 | 2.59 | 78 |
| 20 | GEN | OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE<br>BURLINGTON ON L7L 2Y8 | WSW/205.5 | 2.59 | 79 |
| 20 | GEN | OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE<br>BURLINGTON ON L7L 2Y8 | WSW/205.5 | 2.59 | 79 |
| 20 | GEN | OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE<br>BURLINGTON ON L7L 2Y8 | WSW/205.5 | 2.59 | 79 |
| 20 | GEN | OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE<br>BURLINGTON ON | WSW/205.5 | 2.59 | 80 |
| 20 | GEN | OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE<br>BURLINGTON ON L7L 2Y8 | WSW/205.5 | 2.59 | 80 |
| 20 | GEN | OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE<br>BURLINGTON ON L7L 2Y8 | WSW/205.5 | 2.59 | 81 |
| 20 | GEN | OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE<br>BURLINGTON ON L7L 2Y8 | WSW/205.5 | 2.59 | 81 |
| 20 | GEN | OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE<br>BURLINGTON ON L7L 2Y8 | WSW/205.5 | 2.59 | 82 |
| 20 | GEN | OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE<br>BURLINGTON ON L7L 2Y8 | WSW/205.5 | 2.59 | 82 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 20 | GEN | OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE<br>BURLINGTON ON L7L 2Y8 | WSW/205.5 | 2.59 | 82 |
| 20 | GEN | OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE<br>BURLINGTON ON L7L 2Y8 | WSW/205.5 | 2.59 | 83 |
| 21 | WWIS | | lot 5 con 3<br>ON<br>***Well ID:*** 2803618 | E/218.2 | -5.44 | 83 |
| 22 | EHS | | 5035 & 5045 South Service Road<br>Burlington ON | NW/225.3 | 2.54 | 87 |
| 22 | EHS | | 5035 South Service Road<br>Burlington ON L7L 4X4 | NW/225.3 | 2.54 | 87 |
| 23 | SPL | CONTROLCHEM CANADA LTD. | 5109 HARVESTOR RD. BURLINGTON<br>PLANT 5109 HARVESTER ROAD<br>BURLINGTON CITY ON | NE/225.5 | -1.27 | 87 |
| 23 | SCT | New Forms Inc. | 5109 Harvester Rd Unit 10B<br>Burlington ON L7L 5Y9 | NE/225.5 | -1.27 | 88 |
| 23 | SCT | CONTROL CHEM CANADA LIMITED | 5109 HARVESTER RD UNIT 7B<br>BURLINGTON ON L7L 5Y9 | NE/225.5 | -1.27 | 88 |
| 23 | SCT | COMPUT-A-SIGNS | 5109 Harvester Rd Unit B13<br>Burlington ON L7L 5Y4 | NE/225.5 | -1.27 | 88 |
| 23 | SCT | DIAGRAPH CANADA | 5109 Harvester Rd Unit 5B<br>Burlington ON L7L 5Y9 | NE/225.5 | -1.27 | 89 |
| 23 | SCT | Lakeland Protective Wear Inc. | 5109 Harvester Rd Unit B7<br>Burlington ON L7L 5Y9 | NE/225.5 | -1.27 | 89 |
| 23 | SCT | Bazco Precision | 5109 Harvest Rd Unit 12-14<br>Burlington ON L7L 5Y9 | NE/225.5 | -1.27 | 89 |
| 23 | SCT | Diagraph Corporation | 5109 Harvester Rd Unit 5B<br>Burlington ON L7L 5Y9 | NE/225.5 | -1.27 | 89 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 23 | SCT | Fastenal Canada Co. | 5109 Harvester Rd Unit A4<br>Burlington ON L7L 5Y9 | NE/225.5 | -1.27 | 89 |
| 23 | SCT | Denclare Technologies Inc | 5109 Harvester Rd<br>Burlington ON L7R 5Y9 | NE/225.5 | -1.27 | 90 |
| 23 | GEN | HARDY SALES & SERVICE INC. | 5109 HARVESTER ROAD, UNIT #12<br>BURLINGTON ON L7L 5Y9 | NE/225.5 | -1.27 | 90 |
| 23 | GEN | HARDY SALES & SERVICE INC. | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | NE/225.5 | -1.27 | 91 |
| 23 | GEN | DIAGRAPH CORPORATION (CANADA) | 5109 HARVESTER ROAD, UNIT 5B<br>BURLINGTON ON L7L 5Y9 | NE/225.5 | -1.27 | 91 |
| 23 | GEN | HARDY (SEE & USE ON2056701) | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | NE/225.5 | -1.27 | 91 |
| 23 | GEN | AINSWORTH INC. | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON | NE/225.5 | -1.27 | 92 |
| 23 | GEN | CLASSIC CARE PHARMACY INC. | 5109 HARVESTER ROAD, UNIT 8A<br>BURLINGTON ON L7L 5Y9 | NE/225.5 | -1.27 | 92 |
| 23 | GEN | BAZCO PRECISION | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | NE/225.5 | -1.27 | 92 |
| 23 | SCT | Lakeland Protective Wear Inc. | B7-5109 Harvester Rd<br>Burlington ON L7L 5Y9 | NE/225.5 | -1.27 | 93 |
| 23 | SCT | Bazco Precision | 5109 Harvester Rd Unit 12-14<br>Burlington ON L7L 5Y9 | NE/225.5 | -1.27 | 93 |
| 23 | GEN | Classic Care Pharmacy | 5109 Harvester Rd Unit# 8A<br>Burlington ON | NE/225.5 | -1.27 | 93 |
| 23 | GEN | Miller Polymer Corporation | 5109 Harvester Rd. #B3<br>Burlington ON L7L 5Y9 | NE/225.5 | -1.27 | 94 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 23 | SCT | Quantum Feeder Systems Inc. | 5109 Harvester Rd Unit 8A<br>Burlington ON L7L 5Y9 | NE/225.5 | -1.27 | 94 |
| 23 | SCT | Denclare Technologies Inc. | 5109 Harvester Rd Unit B12<br>Burlington ON L7L 5Y9 | NE/225.5 | -1.27 | 94 |
| 23 | SCT | Dedicated Plastic Tanks Inc. | 5109 Harvester Rd Unit 5B<br>Burlington ON L7L 7Y9 | NE/225.5 | -1.27 | 96 |
| 23 | SCT | Mega Industries Inc. | 5109 Harvester Rd Unit 3A<br>Burlington ON L7L 5Y9 | NE/225.5 | -1.27 | 96 |
| 23 | GEN | Ellsworth Corp | 5109 Harvester Rd. #B3<br>Burlington ON L7L 5Y9 | NE/225.5 | -1.27 | 96 |
| 23 | GEN | Ellsworth Corp | 5109 Harvester Rd. #B3<br>Burlington ON | NE/225.5 | -1.27 | 97 |
| 23 | GEN | Ellsworth Corp | 5109 Harvester Rd. #B3<br>Burlington ON | NE/225.5 | -1.27 | 97 |
| 23 | GEN | BAZCO PRECISION | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | NE/225.5 | -1.27 | 98 |
| 23 | GEN | Ellsworth Corp | 5109 Harvester Rd. #B3<br>Burlington ON | NE/225.5 | -1.27 | 98 |
| 23 | GEN | BAZCO PRECISION | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | NE/225.5 | -1.27 | 99 |
| 23 | GEN | BAZCO PRECISION | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON | NE/225.5 | -1.27 | 99 |
| 23 | GEN | BAZCO PRECISION | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | NE/225.5 | -1.27 | 99 |
| 23 | GEN | BAZCO PRECISION | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | NE/225.5 | -1.27 | 100 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 23 | GEN | Copper wire stripper ltd | 5109 Harvester rd A3<br>Burlington ON L7L 5Y4 | NE/225.5 | -1.27 | 100 |
| 23 | GEN | BAZCO PRECISION | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | NE/225.5 | -1.27 | 100 |
| 23 | GEN | Copper wire stripper ltd | 5109 Harvester rd A3<br>Burlington ON L7L 5Y4 | NE/225.5 | -1.27 | 101 |
| 23 | GEN | BAZCO PRECISION | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | NE/225.5 | -1.27 | 101 |
| 23 | GEN | Hisco Can Inc | 5109 Harvester Rd<br>Burlington ON L7L 5Y9 | NE/225.5 | -1.27 | 102 |
| 23 | GEN | Brierly Technolgies, Inc. | 5109 Harvester Rd. B8<br>Burlington ON L7L5Y4 | NE/225.5 | -1.27 | 102 |
| 23 | GEN | BAZCO PRECISION | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | NE/225.5 | -1.27 | 102 |
| 23 | GEN | Bellamia kitchen & Bath Design Inc. Bellamia kitchen & Bath Design Inc. | 1-5109A Harvester Road<br>Burlington ON L7L5Y9 | NE/225.5 | -1.27 | 103 |
| 23 | GEN | BAZCO PRECISION | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | NE/225.5 | -1.27 | 103 |
| 23 | GEN | BAZCO PRECISION | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | NE/225.5 | -1.27 | 103 |
| 24 | EHS | | 870 Appleby Line<br>Burlington ON L7L2Y8 | SSW/227.0 | -2.39 | 104 |
| 25 | SCT | Tecoustics Limited | 5036 South Service Rd<br>Burlington ON L7L 5Y7 | N/227.0 | 3.60 | 104 |
| 25 | GEN | ALS Canada Limited | 5036 South Service Road<br>Burlington ON L7L 5Y7 | N/227.0 | 3.60 | 104 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 25 | EASR | ALS CANADA LTD. | 5036 Service RD S<br>Burlington ON L7L 5Y7 | N/227.0 | 3.60 | 105 |
| 25 | GEN | ALS Canada Limited | 5036 South Service Road<br>Burlington ON L7L 5Y7 | N/227.0 | 3.60 | 105 |
| 25 | GEN | ALS Canada Limited | 5036 South Service Road<br>Burlington ON L7L 5Y7 | N/227.0 | 3.60 | 106 |
| 25 | GEN | ALS Canada Limited | 5036 South Service Road<br>Burlington ON L7L 5Y7 | N/227.0 | 3.60 | 106 |
| 26 | EHS | | 5035-5045 South Service Road<br>Burlington ON L7L 5Y7 | NW/231.8 | 2.59 | 107 |
| 27 | EHS | | 5018 South Service Rd<br>Burlington ON L7L 5Y7 | NNE/246.2 | 2.09 | 107 |
| 27 | GEN | Garry Construction & Restoration | 5018 South Service Road<br>Burlington ON L7L5Y7 | NNE/246.2 | 2.09 | 108 |
| 27 | GEN | Garry Construction & Restoration Ltd. | 5018 South Service Road<br>Burlington ON L7L 5Y7 | NNE/246.2 | 2.09 | 108 |
| 27 | GEN | Garry Construction & Restoration | 5018 South Service Road<br>Burlington ON L7L5Y7 | NNE/246.2 | 2.09 | 108 |
| 28 | WWIS | | ON<br>***Well ID:*** 7308706 | E/246.9 | -6.48 | 109 |
| 29 | GEN | INDUSTRIAL TASK FORCE | 5100 HARVESTER ROAD<br>BURLINGTON ON L7L 4X4 | E/247.4 | -5.41 | 110 |
| 29 | GEN | INDUSTRIAL TASK FORCE 21-372 | 5100 HARVESTER ROAD<br>BURLINGTON ON L7L 4X4 | E/247.4 | -5.41 | 110 |
| 29 | SPL | Choice Reefers Systems Limited | 5100 HARVESTER RD.<UNOFFICIAL><br>Burlington ON L7L 4X4 | E/247.4 | -5.41 | 111 |

| Map Key | DB | Company/Site Name | Address | Dir/Dist (m) | Elev Diff (m) | Page Number |
|---|---|---|---|---|---|---|
| 29 | EHS | | 5100 Harvester Road<br>Burlington ON L7L 4X4 | E/247.4 | -5.41 | 111 |
| 29 | SPL | | 5100 Harvestor Rd<br>Burlington ON L7L 4X4 | E/247.4 | -5.41 | 112 |
| 29 | SPL | Maple Leaf Foods Inc. | 5100 Harvester Road<br>Burlington ON | E/247.4 | -5.41 | 112 |
| 29 | GEN | Maple Leaf Foods Inc. | 5100 Harvester Road<br>Burlington ON | E/247.4 | -5.41 | 113 |
| 29 | GEN | Maple Leaf Foods Inc. | 5100 Harvester Road<br>Burlington ON L7L 4X4 | E/247.4 | -5.41 | 114 |
| 29 | GEN | Maple Leaf Foods Inc. | 5100 Harvester Road<br>Burlington ON L7L 4X4 | E/247.4 | -5.41 | 115 |
| 29 | GEN | Approved Cold Storage Inc. | 5100 Harvester Road<br>Burlington ON L7L4X4 | E/247.4 | -5.41 | 116 |
| 29 | GEN | Approved Cold Storage Inc. | 5100 Harvester Road<br>Burlington ON L7L4X4 | E/247.4 | -5.41 | 116 |
| 29 | GEN | Approved Cold Storage Inc. | 5100 Harvester Road<br>Burlington ON L7L4X4 | E/247.4 | -5.41 | 117 |
| 29 | GEN | Approved Cold Storage Inc. | 5100 Harvester Road<br>Burlington ON L7L4X4 | E/247.4 | -5.41 | 117 |
| 29 | EHS | | 5100 Harvester Road<br>Burlington ON L7L 4X4 | E/247.4 | -5.41 | 117 |
| 29 | EHS | | 5100 Harvester Road<br>Burlington ON L7L 4X4 | E/247.4 | -5.41 | 118 |

# Executive Summary: Summary By Data Source

## CA - Certificates of Approval

A search of the CA database, dated 1985-Oct 30, 2011* has found that there are 2 CA site(s) within approximately 0.25 kilometers of the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| NEWCOURT FINANCIAL LTD. | 5035 SOUTH SERVICE ROAD BURLINGTON ON L7L 6M9 | NW | 160.66 | 12 |

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| Imperial Oil Limited | 845 Appleby Line Burlington ON | SSE | 58.79 | 2 |

## DTNK - Delisted Fuel Tanks

A search of the DTNK database, dated Feb 28, 2022 has found that there are 8 DTNK site(s) within approximately 0.25 kilometers of the project property.

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| ALTRUISTIC INC | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA ON | SSE | 58.79 | 2 |
| ALTRUISTIC INC | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA ON | SSE | 58.79 | 2 |
| 1317942 ONTARIO LTD O/A ESSO GAS STATION | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA ON | SSE | 58.79 | 2 |
| ALTRUISTIC INC | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA ON | SSE | 58.79 | 2 |
| NISSAN ESSO | 875 APPLEBY LINE BURLINGTON ON L7L 5R4 | SSE | 58.79 | 2 |

| | | | | |
|---|---|---|---|---|
| ALTRUISTIC INC | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA ON | SSE | 58.79 | 2 |
| | 875 APPLEBY LINE BURLINGTON ON L7L 5R4 | SSE | 58.79 | 2 |
| ADIL S WAIN | 875 APPLEBY LINE BURLINGTON ON | SSE | 58.79 | 2 |

## EASR - Environmental Activity and Sector Registry

A search of the EASR database, dated Oct 2011- Jun 30, 2023 has found that there are 1 EASR site(s) within approximately 0.25 kilometers of the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| ALS CANADA LTD. | 5036 Service RD S Burlington ON L7L 5Y7 | N | 227.04 | 25 |

## ECA - Environmental Compliance Approval

A search of the ECA database, dated Oct 2011- Jun 30, 2023 has found that there are 1 ECA site(s) within approximately 0.25 kilometers of the project property.

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| Imperial Oil Limited | 845 Appleby Line Burlington ON M3C 1K5 | SSE | 58.79 | 2 |

## EHS - ERIS Historical Searches

A search of the EHS database, dated 1999-Jun 30, 2023 has found that there are 15 EHS site(s) within approximately 0.25 kilometers of the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| | 5044 South Service Rd Burlington ON L7L 5Y7 | N | 191.15 | 15 |
| | 5044 South Service Road Burlington ON L7L 5Y7 | N | 191.15 | 15 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| | 5044 South Service Road<br>Burlington ON L7L 5Y7 | N | 191.15 | 15 |
| | 5035 & 5045 South Service Road<br>Burlington ON | NW | 225.31 | 22 |
| | 5035 South Service Road<br>Burlington ON L7L 4X4 | NW | 225.31 | 22 |
| | 5035-5045 South Service Road<br>Burlington ON L7L 5Y7 | NW | 231.84 | 26 |
| | 5018 South Service Rd<br>Burlington ON L7L 5Y7 | NNE | 246.23 | 27 |

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| | 875 Appleby Line<br>Burlington ON L7L5R4 | SSE | 58.79 | 2 |
| | Appleby Line & Harvester Road<br>Burlington ON L7L 4W9 | E | 128.73 | 6 |
| | 5105 & 5109 Harvester and 5002 South Service Road<br>Burlington ON L7L 5Y9 | NE | 184.69 | 13 |
| | 5105 & 5109 Harvester and 5002 South Service Road<br>Burlington ON L7L 5Y9 | NE | 184.69 | 13 |
| | 870 Appleby Line<br>Burlington ON L7L2Y8 | SSW | 227.02 | 24 |
| | 5100 Harvester Road<br>Burlington ON L7L 4X4 | E | 247.39 | 29 |

| | | | | |
|---|---|---|---|---|
| | 5100 Harvester Road<br>Burlington ON L7L 4X4 | E | 247.39 | 29 |
| | 5100 Harvester Road<br>Burlington ON L7L 4X4 | E | 247.39 | 29 |

## FST - Fuel Storage Tank

A search of the FST database, dated Feb 28, 2022 has found that there are 8 FST site(s) within approximately 0.25 kilometers of the project property.

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| ALTRUISTIC INC | 875 APPLEBY LINE BURLINGTON<br>L7L 5R4 ON CA<br>ON | SSE | 58.79 | 2 |
| 1317942 ONTARIO LTD O/A ESSO GAS STATION | 875 APPLEBY LINE BURLINGTON<br>L7L 5R4 ON CA<br>ON | SSE | 58.79 | 2 |
| ALTRUISTIC INC | 875 APPLEBY LINE BURLINGTON<br>L7L 5R4 ON CA<br>ON | SSE | 58.79 | 2 |
| ALTRUISTIC INC | 875 APPLEBY LINE BURLINGTON<br>L7L 5R4 ON CA<br>ON | SSE | 58.79 | 2 |
| MAC'S CONVENIENCE STORES INC | 875 APPLEBY LINE BURLINGTON<br>L7L 5R4 ON CA<br>ON | SSE | 58.79 | 2 |
| MAC'S CONVENIENCE STORES INC | 875 APPLEBY LINE BURLINGTON<br>L7L 5R4 ON CA<br>ON | SSE | 58.79 | 2 |
| MAC'S CONVENIENCE STORES INC | 875 APPLEBY LINE BURLINGTON<br>L7L 5R4 ON CA<br>ON | SSE | 58.79 | 2 |
| ALTRUISTIC INC | 875 APPLEBY LINE BURLINGTON<br>L7L 5R4 ON CA<br>ON | SSE | 58.79 | 2 |

## FSTH - Fuel Storage Tank - Historic

A search of the FSTH database, dated Pre-Jan 2010* has found that there are 2 FSTH site(s) within approximately 0.25 kilometers of the project property.

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| ADIL S WAIN | 875 APPLEBY LINE<br>BURLINGTON ON L7L 5R4 | SSE | 58.79 | 2 |
| ADIL S WAIN | 875 APPLEBY LINE<br>BURLINGTON ON L7L 5R4 | SSE | 58.79 | 2 |

## GEN - Ontario Regulation 347 Waste Generators Summary

A search of the GEN database, dated 1986-Oct 31, 2022 has found that there are 73 GEN site(s) within approximately 0.25 kilometers of the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| American Optics Inc. | 5006 South Service Rd., Unit 4<br>Burlington ON | NNE | 117.57 | 3 |
| American Optics Ltd. | 5006 South Service Rd., Unit 4<br>Burlington ON L7L 5Y7 | NNE | 117.57 | 3 |
| American Optics Inc. | 5006 South Service Rd., Unit 4<br>Burlington ON L7L 5Y7 | NNE | 117.57 | 3 |
| American Optics Inc. | 5006 South Service Rd., Unit 4<br>Burlington ON L7L 5Y7 | NNE | 117.57 | 3 |
| American Optics Ltd. | 5006 South Service Rd., Unit 4<br>Burlington ON L7L 5Y7 | NNE | 117.57 | 3 |
| American Optics Ltd. | 5006 South Service Rd., Unit 4<br>Burlington ON L7L 5Y7 | NNE | 117.57 | 3 |
| ASLAN TECHNOLOGIES INC. | 5044 SOUTH SERVICE ROAD<br>BURLINGTON ON L7L 5Y7 | N | 191.15 | 15 |
| Long Wing International | 5012 South Service Road<br>Burlington ON L7L5Y7 | NNE | 199.49 | 18 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE BURLINGTON ON L7L 2Y8 | WSW | 205.48 | 20 |
| OAK-BURL INDUSTRIES LIMITED 29-482 | 914 APPLEBY LINE BURLINGTON ON L7L 2Y8 | WSW | 205.48 | 20 |
| OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE BURLINGTON ON L7L 2Y8 | WSW | 205.48 | 20 |
| OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE BURLINGTON ON L7L 2Y8 | WSW | 205.48 | 20 |
| OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE BURLINGTON ON L7L 2Y8 | WSW | 205.48 | 20 |
| OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE BURLINGTON ON L7L 2Y8 | WSW | 205.48 | 20 |
| OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE BURLINGTON ON | WSW | 205.48 | 20 |
| OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE BURLINGTON ON L7L 2Y8 | WSW | 205.48 | 20 |
| OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE BURLINGTON ON L7L 2Y8 | WSW | 205.48 | 20 |
| OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE BURLINGTON ON L7L 2Y8 | WSW | 205.48 | 20 |
| OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE BURLINGTON ON L7L 2Y8 | WSW | 205.48 | 20 |

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE BURLINGTON ON L7L 2Y8 | WSW | 205.48 | 20 |
| OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE BURLINGTON ON L7L 2Y8 | WSW | 205.48 | 20 |
| OAK-BURL INDUSTRIES LIMITED | 914 APPLEBY LINE BURLINGTON ON L7L 2Y8 | WSW | 205.48 | 20 |
| ALS Canada Limited | 5036 South Service Road Burlington ON L7L 5Y7 | N | 227.04 | 25 |
| ALS Canada Limited | 5036 South Service Road Burlington ON L7L 5Y7 | N | 227.04 | 25 |
| ALS Canada Limited | 5036 South Service Road Burlington ON L7L 5Y7 | N | 227.04 | 25 |
| ALS Canada Limited | 5036 South Service Road Burlington ON L7L 5Y7 | N | 227.04 | 25 |
| Garry Construction & Restoration | 5018 South Service Road Burlington ON L7L5Y7 | NNE | 246.23 | 27 |
| Garry Construction & Restoration Ltd. | 5018 South Service Road Burlington ON L7L 5Y7 | NNE | 246.23 | 27 |
| Garry Construction & Restoration | 5018 South Service Road Burlington ON L7L5Y7 | NNE | 246.23 | 27 |

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| BARHAV DEVELOPMENT TIMWEN PARTNERSHIP | 5051 HARVESTER RD BURLINGTON ON L7L 6S1 | NE | 16.59 | 1 |

| | | | | |
|---|---|---|---|---|
| BARHAV DEVELOPMENT TIMWEN PARTNERSHIP | 5051 HARVESTER RD BURLINGTON ON L7L 6S1 | NE | 16.59 | 1 |
| BARHAV DEVELOPMENT TIMWEN PARTNERSHIP | 5051 HARVESTER RD BURLINGTON ON L7L 6S1 | NE | 16.59 | 1 |
| BARHAV DEVELOPMENT TIMWEN PARTNERSHIP | 5051 HARVESTER RD BURLINGTON ON L7L 6S1 | NE | 16.59 | 1 |
| Mac's Convenience Stores Inc. | 875 Appleby Line Burlington ON L7L 5R4 | SSE | 58.79 | 2 |
| Mac's Convenience Stores Inc. | 875 Appleby Line Burlington ON L7L 5R4 | SSE | 58.79 | 2 |
| Mac's Convenience Stores Inc. | 875 Appleby Line Burlington ON L7L 5R4 | SSE | 58.79 | 2 |
| HARDY SALES & SERVICE INC. | 5109 HARVESTER ROAD, UNIT #12 BURLINGTON ON L7L 5Y9 | NE | 225.55 | 23 |
| HARDY SALES & SERVICE INC. | 5109 HARVESTER ROAD, UNIT 12 BURLINGTON ON L7L 5Y9 | NE | 225.55 | 23 |
| DIAGRAPH CORPORATION (CANADA) | 5109 HARVESTER ROAD, UNIT 5B BURLINGTON ON L7L 5Y9 | NE | 225.55 | 23 |
| HARDY (SEE & USE ON2056701) | 5109 HARVESTER ROAD, UNIT 12 BURLINGTON ON L7L 5Y9 | NE | 225.55 | 23 |
| AINSWORTH INC. | 5109 HARVESTER ROAD, UNIT 12 BURLINGTON ON | NE | 225.55 | 23 |
| CLASSIC CARE PHARMACY INC. | 5109 HARVESTER ROAD, UNIT 8A BURLINGTON ON L7L 5Y9 | NE | 225.55 | 23 |
| BAZCO PRECISION | 5109 HARVESTER ROAD, UNIT 12 BURLINGTON ON L7L 5Y9 | NE | 225.55 | 23 |

| | | | | |
|---|---|---|---|---|
| Classic Care Pharmacy | 5109 Harvester Rd Unit# 8A<br>Burlington ON | NE | 225.55 | 23 |
| Miller Polymer Corporation | 5109 Harvester Rd. #B3<br>Burlington ON L7L 5Y9 | NE | 225.55 | 23 |
| Ellsworth Corp | 5109 Harvester Rd. #B3<br>Burlington ON L7L 5Y9 | NE | 225.55 | 23 |
| Ellsworth Corp | 5109 Harvester Rd. #B3<br>Burlington ON | NE | 225.55 | 23 |
| Ellsworth Corp | 5109 Harvester Rd. #B3<br>Burlington ON | NE | 225.55 | 23 |
| BAZCO PRECISION | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | NE | 225.55 | 23 |
| Ellsworth Corp | 5109 Harvester Rd. #B3<br>Burlington ON | NE | 225.55 | 23 |
| BAZCO PRECISION | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | NE | 225.55 | 23 |
| BAZCO PRECISION | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON | NE | 225.55 | 23 |
| BAZCO PRECISION | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | NE | 225.55 | 23 |
| BAZCO PRECISION | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | NE | 225.55 | 23 |
| Copper wire stripper ltd | 5109 Harvester rd A3<br>Burlington ON L7L 5Y4 | NE | 225.55 | 23 |

| | | | | |
|---|---|---|---|---|
| BAZCO PRECISION | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | NE | 225.55 | 23 |
| Copper wire stripper ltd | 5109 Harvester rd A3<br>Burlington ON L7L 5Y4 | NE | 225.55 | 23 |
| BAZCO PRECISION | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | NE | 225.55 | 23 |
| Hisco Can Inc | 5109 Harvester Rd<br>Burlington ON L7L 5Y9 | NE | 225.55 | 23 |
| Brierly Technolgies, Inc. | 5109 Harvester Rd. B8<br>Burlington ON L7L5Y4 | NE | 225.55 | 23 |
| BAZCO PRECISION | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | NE | 225.55 | 23 |
| Bellamia kitchen & Bath Design Inc. Bellamia kitchen & Bath Design Inc. | 1-5109A Harvester Road<br>Burlington ON L7L5Y9 | NE | 225.55 | 23 |
| BAZCO PRECISION | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | NE | 225.55 | 23 |
| BAZCO PRECISION | 5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | NE | 225.55 | 23 |
| INDUSTRIAL TASK FORCE | 5100 HARVESTER ROAD<br>BURLINGTON ON L7L 4X4 | E | 247.39 | 29 |
| INDUSTRIAL TASK FORCE 21-372 | 5100 HARVESTER ROAD<br>BURLINGTON ON L7L 4X4 | E | 247.39 | 29 |
| Maple Leaf Foods Inc. | 5100 Harvester Road<br>Burlington ON | E | 247.39 | 29 |
| Maple Leaf Foods Inc. | 5100 Harvester Road<br>Burlington ON L7L 4X4 | E | 247.39 | 29 |

| | | | | |
|---|---|---|---|---|
| Maple Leaf Foods Inc. | 5100 Harvester Road<br>Burlington ON L7L 4X4 | E | 247.39 | 29 |
| Approved Cold Storage Inc. | 5100 Harvester Road<br>Burlington ON L7L4X4 | E | 247.39 | 29 |
| Approved Cold Storage Inc. | 5100 Harvester Road<br>Burlington ON L7L4X4 | E | 247.39 | 29 |
| Approved Cold Storage Inc. | 5100 Harvester Road<br>Burlington ON L7L4X4 | E | 247.39 | 29 |
| Approved Cold Storage Inc. | 5100 Harvester Road<br>Burlington ON L7L4X4 | E | 247.39 | 29 |

### NPRI - National Pollutant Release Inventory - Historic

A search of the NPRI database, dated 1993-May 2017 has found that there are 1 NPRI site(s) within approximately 0.25 kilometers of the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| O&Y ENTERPRISE | 5035 SOUTH SERVICE Road<br>BURLINGTON ON L7R4C8 | NW | 160.66 | 12 |

### PRT - Private and Retail Fuel Storage Tanks

A search of the PRT database, dated 1989-1996* has found that there are 2 PRT site(s) within approximately 0.25 kilometers of the project property.

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| 779584 ONTARIO INC JULIES ESSO | 875 APPLEBY LINE<br>BURLINGTON ON L7L5R4 | SSE | 58.79 | 2 |
| NISSAN ESSO | 875 APPLEBY LINE<br>BURLINGTON ON L7L 5R4 | SSE | 58.79 | 2 |

### RST - Retail Fuel Storage Tanks

A search of the RST database, dated 1999-Feb 28, 2023 has found that there are 1 RST site(s) within approximately 0.25 kilometers of the project property.

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| SHANNON'S ESSO | 875 APPLEBY LINE<br>BURLINGTON ON L7L5R4 | SSE | 58.79 | 2 |

## SCT - Scott's Manufacturing Directory

A search of the SCT database, dated 1992-Mar 2011* has found that there are 22 SCT site(s) within approximately 0.25 kilometers of the project property.

| Equal/Higher Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| American Optics Inc. | 5006 South Service Rd Unit 3-4<br>Burlington ON L7L 5Y7 | NNE | 117.57 | 3 |
| Aslan Technologies Inc. | 5044 South Service Rd<br>Burlington ON L7L 5Y7 | N | 191.15 | 15 |
| SSI EQUIPMENT INC. | 5044A SOUTH SERVICE RD<br>BURLINGTON ON L7L 5Y7 | N | 191.15 | 15 |
| SSI EQUIPMENT INC. | 5044 SOUTH SERVICE RD<br>BURLINGTON ON L7L 5Y7 | N | 191.15 | 15 |
| Oak-Burl Industries Ltd. | 914 Appleby Line<br>Burlington ON L7L 2Y8 | WSW | 205.48 | 20 |
| Tecoustics Limited | 5036 South Service Rd<br>Burlington ON L7L 5Y7 | N | 227.04 | 25 |

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| Burkert Contromatic Inc. | 5002 South Service Rd<br>Burlington ON L7L 5Y7 | NE | 120.93 | 4 |
| CONTROL CHEM CANADA LIMITED | 5109 HARVESTER RD UNIT 7B<br>BURLINGTON ON L7L 5Y9 | NE | 225.55 | 23 |

| | | | | |
|---|---|---|---|---|
| New Forms Inc. | 5109 Harvester Rd Unit 10B<br>Burlington ON L7L 5Y9 | NE | 225.55 | 23 |
| Mega Industries Inc. | 5109 Harvester Rd Unit 3A<br>Burlington ON L7L 5Y9 | NE | 225.55 | 23 |
| Dedicated Plastic Tanks Inc. | 5109 Harvester Rd Unit 5B<br>Burlington ON L7L 7Y9 | NE | 225.55 | 23 |
| Denclare Technologies Inc. | 5109 Harvester Rd Unit B12<br>Burlington ON L7L 5Y9 | NE | 225.55 | 23 |
| Quantum Feeder Systems Inc. | 5109 Harvester Rd Unit 8A<br>Burlington ON L7L 5Y9 | NE | 225.55 | 23 |
| Bazco Precision | 5109 Harvester Rd Unit 12-14<br>Burlington ON L7L 5Y9 | NE | 225.55 | 23 |
| Lakeland Protective Wear Inc. | B7-5109 Harvester Rd<br>Burlington ON L7L 5Y9 | NE | 225.55 | 23 |
| Denclare Technologies Inc | 5109 Harvester Rd<br>Burlington ON L7R 5Y9 | NE | 225.55 | 23 |
| Fastenal Canada Co. | 5109 Harvester Rd Unit A4<br>Burlington ON L7L 5Y9 | NE | 225.55 | 23 |
| COMPUT-A-SIGNS | 5109 Harvester Rd Unit B13<br>Burlington ON L7L 5Y4 | NE | 225.55 | 23 |
| DIAGRAPH CANADA | 5109 Harvester Rd Unit 5B<br>Burlington ON L7L 5Y9 | NE | 225.55 | 23 |
| Lakeland Protective Wear Inc. | 5109 Harvester Rd Unit B7<br>Burlington ON L7L 5Y9 | NE | 225.55 | 23 |

| | | | | |
|---|---|---|---|---|
| Diagraph Corporation | 5109 Harvester Rd Unit 5B<br>Burlington ON L7L 5Y9 | NE | 225.55 | 23 |
| Bazco Precision | 5109 Harvest Rd Unit 12-14<br>Burlington ON L7L 5Y9 | NE | 225.55 | 23 |

## SPL - Ontario Spills

A search of the SPL database, dated 1988-Oct 2021 has found that there are 10 SPL site(s) within approximately 0.25 kilometers of the project property.

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| ESSO PETROLEUM CANADA | JULIE'S ESSO SERVICE STATION AT 875 APPLEBY LINE, TEL 905-681-8874. SERVICE STATION<br>BURLINGTON CITY ON L7L 5R4 | SSE | 58.79 | 2 |
| Union Gas Limited | 5002 South Service Road<br>Burlington ON | NE | 120.93 | 4 |
| MF Grading Sevice<UNOFFICIAL> | Intersection of Harvester Rd and South Service Rd<br>Burlington ON | E | 129.23 | 7 |
| Rothsay, Member of Maple Leaf Foods | Lights at Harvester Road and Appleby Line<br>Burlington ON | S | 184.95 | 14 |
| Union Gas Limited | Harvester Road and Appleby Line<br>Burlington ON | S | 184.95 | 14 |
| SEARS CANADA INC. | APPLEBY & HARVESTER RD<br>MOTOR VEHICLE (OPERATING FLUID)<br>BURLINGTON CITY ON | S | 184.95 | 14 |
| CONTROLCHEM CANADA LTD. | 5109 HARVESTOR RD. BURLINGTON PLANT 5109 HARVESTER ROAD<br>BURLINGTON CITY ON | NE | 225.55 | 23 |
| | 5100 Harvestor Rd<br>Burlington ON L7L 4X4 | E | 247.39 | 29 |

| | | | | |
|---|---|---|---|---|
| Maple Leaf Foods Inc. | 5100 Harvester Road<br>Burlington ON | E | 247.39 | 29 |
| Choice Reefers Systems Limited | 5100 HARVESTER RD.<br><UNOFFICIAL><br>Burlington ON L7L 4X4 | E | 247.39 | 29 |

## WWIS - Water Well Information System


A search of the WWIS database, dated Mar 31 2023 has found that there are 10 WWIS site(s) within approximately 0.25 kilometers of the project property.

| Lower Elevation | Address | Direction | Distance (m) | Map Key |
|---|---|---|---|---|
| | lot 5 con 3<br>ON<br>***Well ID:*** 7385973 | ENE | 122.65 | 5 |
| | lot 5 con 3<br>ON<br>***Well ID:*** 7381453 | ENE | 131.59 | 8 |
| | lot 5 con 3<br>ON<br>***Well ID:*** 7385972 | E | 132.15 | 9 |
| | lot 5 con 3<br>ON<br>***Well ID:*** 7385969 | ENE | 144.54 | 10 |
| | lot 5 con 3<br>ON<br>***Well ID:*** 7385971 | ENE | 152.35 | 11 |
| | 870 APPLEBY LINE<br>BURLINGTON ON<br>***Well ID:*** 7289963 | SSW | 193.62 | 16 |
| | 821 APPLEBY LINE<br>BURLINGTON ON<br>***Well ID:*** 7345219 | ESE | 194.20 | 17 |
| | 870 APPLEBY LINE<br>BURLINGTON ON<br>***Well ID:*** 7289962 | SSW | 201.82 | 19 |
| | lot 5 con 3<br>ON | E | 218.20 | 21 |

***Well ID:*** 2803618

| | | | |
|---|---|---|---|
| ON | E | 246.90 | **28** |

***Well ID:*** 7308706




# Map: 0.25 Kilometer Radius


Order Number: 23081700823

Address: 5051 Harvester Road, Burlington, ON

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

**Source:** © 2021 ESRI StreetMap Premium. © ERIS Information Limited Partnership

79°46'30"W





# Aerial **Year: 2022**

Order Number: 23081700823

**Address: 5051 Harvester Road, Burlington, ON**

**Source:** ESRI World Imagery

© ERIS Information Limited Partnership




# Topographic Map

Order Number: 23081700823

**Address: 5051 Harvester Road, ON**

**Source:** ESRI World Topographic Map

© ERIS Information Limited Partnership

# Detail Report

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 1 | 1 of 4 | NE/16.6 | 111.8 / -0.45 | BARHAV DEVELOPMENT TIMWEN PARTNERSHIP<br>5051 HARVESTER RD<br>BURLINGTON ON L7L 6S1 | GEN |

**Generator No:** ON5450178
**SIC Code:**
**SIC Description:**
**Approval Years:** As of Dec 2018
**PO Box No:**
**Country:** Canada
**Status:** Registered
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 251 L
**Waste Class Name:** Waste oils/sludges (petroleum based)

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 1 | 2 of 4 | NE/16.6 | 111.8 / -0.45 | BARHAV DEVELOPMENT TIMWEN PARTNERSHIP<br>5051 HARVESTER RD<br>BURLINGTON ON L7L 6S1 | GEN |

**Generator No:** ON5450178
**SIC Code:**
**SIC Description:**
**Approval Years:** As of Jul 2020
**PO Box No:**
**Country:** Canada
**Status:** Registered
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 251 L
**Waste Class Name:** Waste oils/sludges (petroleum based)

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 1 | 3 of 4 | NE/16.6 | 111.8 / -0.45 | BARHAV DEVELOPMENT TIMWEN PARTNERSHIP<br>5051 HARVESTER RD<br>BURLINGTON ON L7L 6S1 | GEN |

**Generator No:** ON5450178
**SIC Code:**

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**SIC Description:**
**Approval Years:** As of Nov 2021
**PO Box No:**
**Country:** Canada
**Status:** Registered
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 251 L
**Waste Class Name:** Waste oils/sludges (petroleum based)

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 1 | 4 of 4 | NE/16.6 | 111.8 / -0.45 | BARHAV DEVELOPMENT TIMWEN PARTNERSHIP<br>5051 HARVESTER RD<br>BURLINGTON ON L7L 6S1 | GEN |

**Generator No:** ON5450178
**SIC Code:**
**SIC Description:**
**Approval Years:** As of Oct 2022
**PO Box No:**
**Country:** Canada
**Status:** Registered
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 251 L
**Waste Class Name:** OIL SKIMMINGS & SLUDGES

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 2 | 1 of 28 | SSE/58.8 | 110.6 / -1.68 | ESSO PETROLEUM CANADA<br>JULIE'S ESSO SERVICE STATION AT 875 APPLEBY LINE, TEL 905-681-8874. SERVICE STATION<br>BURLINGTON CITY ON L7L 5R4 | SPL |

**Ref No:** 97151
**Site No:**
**Incident Dt:** 3/8/1994
**Year:**
**Incident Cause:** PIPE/HOSE LEAK
**Incident Event:**
**Environment Impact:** NOT ANTICIPATED
**Nature of Impact:**
**MOE Response:**
**Dt MOE Arvl on Scn:**
**MOE Reported Dt:** 3/8/1994
**Dt Document Closed:**
**Municipality No:** 14101
**System Facility Address:**
**Client Type:**
**Call Report Location Geodata:**
**Contaminant Code:**

**Contaminant Qty:**
**Nature of Damage:**
**Discharger Report:**
**Material Group:**
**Health/Env Conseq:**
**Agency Involved:**
**Site Lot:**
**Site Conc:**
**Site Geo Ref Accu:**
**Site Map Datum:**
**Northing:**
**Easting:**

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

| | |
|---|---|
| **Contaminant Name:** | |
| **Contaminant Limit 1:** | |
| **Contam Limit Freq 1:** | |
| **Contaminant UN No 1:** | |
| **Receiving Medium:** | LAND |
| **Receiving Environment:** | |
| **Incident Reason:** | OTHER |
| **Incident Summary:** | JULLIE'S ESSO SERVICE STN-10L GASOLINE TO ASPHALT FROM TANK VENT,CLEANED UP |
| **Site Region:** | |
| **Site Municipality:** | BURLINGTON CITY |
| **Activity Preceding Spill:** | |
| **Property 2nd Watershed:** | |
| **Property Tertiary Watershed:** | |
| **Sector Type:** | |
| **SAC Action Class:** | |
| **Source Type:** | |
| **Site County/District:** | |
| **Site Geo Ref Meth:** | |
| **Site District Office:** | |
| **Nearest Watercourse:** | |
| **Site Name:** | |
| **Site Address:** | |
| **Client Name:** | |

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 2 | 2 of 28 | SSE/58.8 | 110.6 / -1.68 | NISSAN ESSO<br>875 APPLEBY LINE<br>BURLINGTON ON L7L 5R4 | PRT |

| | |
|---|---|
| **Location ID:** | 18738 |
| **Type:** | retail |
| **Expiry Date:** | 1992-11-30 |
| **Capacity (L):** | 32996 |
| **Licence #:** | 0076341288 |

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 2 | 3 of 28 | SSE/58.8 | 110.6 / -1.68 | 779584 ONTARIO INC JULIES ESSO<br>875 APPLEBY LINE<br>BURLINGTON ON L7L5R4 | PRT |

| | |
|---|---|
| **Location ID:** | 18738 |
| **Type:** | retail |
| **Expiry Date:** | 1995-10-31 |
| **Capacity (L):** | 150000 |
| **Licence #:** | 0076385921 |

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 2 | 4 of 28 | SSE/58.8 | 110.6 / -1.68 | SHANNON'S ESSO<br>875 APPLEBY LINE<br>BURLINGTON ON L7L5R4 | RST |

| | |
|---|---|
| **Headcode:** | 1186800 |
| **Headcode Desc:** | Service Stations-Gasoline, Oil & Natural Gas |
| **Phone:** | 9053336756 |
| **List Name:** | |
| **Description:** | |

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 2 | 5 of 28 | SSE/58.8 | 110.6 / -1.68 | ADIL S WAIN<br>875 APPLEBY LINE<br>BURLINGTON ON L7L 5R4 | FSTH |

| | |
|---|---|
| **License Issue Date:** | 4/19/2007 |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Tank Status:*** Licensed
***Tank Status As Of:*** August 2007
***Operation Type:*** Retail Fuel Outlet
***Facility Type:*** Gasoline Station - Self Serve

***--Details--***
***Status:*** Removed
***Year of Installation:*** 1983
***Corrosion Protection:***
***Capacity:*** 50000
***Tank Fuel Type:*** Liquid Fuel Single Wall UST - Gasoline

***Status:*** Removed
***Year of Installation:*** 1983
***Corrosion Protection:***
***Capacity:*** 25000
***Tank Fuel Type:*** Liquid Fuel Single Wall UST - Diesel

***Status:*** Removed
***Year of Installation:*** 1983
***Corrosion Protection:***
***Capacity:*** 25000
***Tank Fuel Type:*** Liquid Fuel Single Wall UST - Gasoline

***Status:*** Removed
***Year of Installation:*** 1983
***Corrosion Protection:***
***Capacity:*** 50000
***Tank Fuel Type:*** Liquid Fuel Single Wall UST - Gasoline

---

| | | | | | |
|---|---|---|---|---|---|
| 2 | 6 of 28 | SSE/58.8 | 110.6 / -1.68 | ADIL S WAIN<br>875 APPLEBY LINE<br>BURLINGTON ON L7L 5R4 | FSTH |

***License Issue Date:*** 4/19/2007 10:33:00 AM
***Tank Status:*** Licensed
***Tank Status As Of:*** December 2008
***Operation Type:*** Retail Fuel Outlet
***Facility Type:*** Gasoline Station - Self Serve

***--Details--***
***Status:*** Active
***Year of Installation:*** 2000
***Corrosion Protection:***
***Capacity:*** 46400
***Tank Fuel Type:*** Liquid Fuel Double Wall UST - Gasoline

***Status:*** Active
***Year of Installation:*** 2000
***Corrosion Protection:***
***Capacity:*** 46400
***Tank Fuel Type:*** Liquid Fuel Double Wall UST - Gasoline

***Status:*** Active
***Year of Installation:*** 2000
***Corrosion Protection:***
***Capacity:*** 46400
***Tank Fuel Type:*** Liquid Fuel Double Wall UST - Gasoline

---

| | | | | | |
|---|---|---|---|---|---|
| 2 | 7 of 28 | SSE/58.8 | 110.6 / -1.68 | Imperial Oil Limited | CA |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| | | | | ***845 Appleby Line***<br>***Burlington ON*** | |

***Certificate #:*** 8027-7NPJXL
***Application Year:*** 2009
***Issue Date:*** 1/27/2009
***Approval Type:*** Industrial Sewage Works
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

| | | | | | |
|---|---|---|---|---|---|
| 2 | ***8 of 28*** | ***SSE/58.8*** | ***110.6 / -1.68*** | ***NISSAN ESSO***<br>***875 APPLEBY LINE***<br>***BURLINGTON ON L7L 5R4*** | ***DTNK*** |

***Delisted Expired Fuel Safety Facilities***

***Instance No:*** 9881601
***Status:*** EXPIRED
***Instance ID:***
***Instance Type:*** FS Facility
***Instance Creation Dt:***
***Instance Install Dt:***
***Item Description:***
***Manufacturer:***
***Model:***
***Serial No:***
***ULC Standard:***
***Quantity:***
***Unit of Measure:***
***Overfill Prot Type:***
***Creation Date:***
***Next Periodic Str DT:***
***TSSA Base Sched Cycle 2:***
***TSSAMax Hazard Rank 1:***
***TSSA Risk Based Periodic Yn:***
***TSSA Volume of Directives:***
***TSSA Periodic Exempt:***
***TSSA Statutory Interval:***
***TSSA Recd Insp Interva:***
***TSSA Recd Tolerance:***
***TSSA Program Area:***
***TSSA Program Area 2:***
***Description:***
***Original Source:*** EXP
***Record Date:*** Up to May 2013

***Expired Date:*** 11/20/1991
***Max Hazard Rank:***
***Facility Location:***
***Facility Type:***
***Fuel Type 2:***
***Fuel Type 3:***
***Panam Related:***
***Panam Venue Nm:***
***External Identifier:***
***Item:***
***Piping Steel:***
***Piping Galvanized:***
***Tank Single Wall St:***
***Piping Underground:***
***Tank Underground:***
***Source:***

---

| | | | | | |
|---|---|---|---|---|---|
| 2 | ***9 of 28*** | ***SSE/58.8*** | ***110.6 / -1.68*** | ***ADIL S WAIN***<br>***875 APPLEBY LINE***<br>***BURLINGTON ON*** | ***DTNK*** |

***Delisted Expired Fuel Safety Facilities***

| | | | |
|---|---|---|---|
| **Instance No:** | 11318181 | **Expired Date:** | |
| **Status:** | EXPIRED | **Max Hazard Rank:** | |
| **Instance ID:** | 78450 | **Facility Location:** | |
| **Instance Type:** | FS Piping | **Facility Type:** | |
| **Instance Creation Dt:** | | **Fuel Type 2:** | |
| **Instance Install Dt:** | | **Fuel Type 3:** | |
| **Item Description:** | | **Panam Related:** | |
| **Manufacturer:** | | **Panam Venue Nm:** | |
| **Model:** | | **External Identifier:** | |
| **Serial No:** | | **Item:** | |
| **ULC Standard:** | | **Piping Steel:** | |
| **Quantity:** | | **Piping Galvanized:** | |
| **Unit of Measure:** | | **Tank Single Wall St:** | |
| **Overfill Prot Type:** | | **Piping Underground:** | |
| **Creation Date:** | | **Tank Underground:** | |
| **Next Periodic Str DT:** | | **Source:** | |
| **TSSA Base Sched Cycle 2:** | | | |
| **TSSAMax Hazard Rank 1:** | | | |
| **TSSA Risk Based Periodic Yn:** | | | |
| **TSSA Volume of Directives:** | | | |
| **TSSA Periodic Exempt:** | | | |
| **TSSA Statutory Interval:** | | | |
| **TSSA Recd Insp Interva:** | | | |
| **TSSA Recd Tolerance:** | | | |
| **TSSA Program Area:** | | | |
| **TSSA Program Area 2:** | | | |
| **Description:** | FS Piping | | |
| **Original Source:** | EXP | | |
| **Record Date:** | Up to Mar 2012 | | |

**2** | ***10 of 28*** | ***SSE/58.8*** | ***110.6 / -1.68*** | ***MAC'S CONVENIENCE STORES INC***
***875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA***
***CA***
***ON*** | ***FST***

| | | | |
|---|---|---|---|
| **Instance No:** | 11600925 | **Manufacturer:** | |
| **Status:** | | **Serial No:** | |
| **Cont Name:** | | **Ulc Standard:** | |
| **Instance Type:** | FS Liquid Fuel Tank | **Quantity:** | |
| **Item:** | | **Unit of Measure:** | |
| **Item Description:** | FS Liquid Fuel Tank | **Fuel Type:** | Gasoline |
| **Tank Type:** | Double Wall UST | **Fuel Type2:** | NULL |
| **Install Date:** | 8/27/2009 8:07:54 AM | **Fuel Type3:** | NULL |
| **Install Year:** | 2000 | **Piping Steel:** | |
| **Years in Service:** | | **Piping Galvanized:** | |
| **Model:** | NULL | **Tanks Single Wall St:** | |
| **Description:** | | **Piping Underground:** | |
| **Capacity:** | 46400 | **No Underground:** | |
| **Tank Material:** | Fiberglass (FRP) | **Panam Related:** | |
| **Corrosion Protect:** | Fiberglass | **Panam Venue:** | |
| **Overfill Protect:** | | | |
| **Facility Type:** | FS Liquid Fuel Tank | | |
| **Parent Facility Type:** | FS Gasoline Station - Self Serve | | |
| **Facility Location:** | | | |
| **Device Installed Location:** | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA | | |

***Liquid Fuel Tank Details***

| | |
|---|---|
| **Overfill Protection:** | |
| **Owner Account Name:** | MAC'S CONVENIENCE STORES INC |
| **Item:** | FS LIQUID FUEL TANK |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 2 | 11 of 28 | SSE/58.8 | 110.6 / -1.68 | MAC'S CONVENIENCE STORES INC<br>875 APPLEBY LINE BURLINGTON L7L 5R4 ON<br>CA<br>ON | FST |

| | | | |
|---|---|---|---|
| **Instance No:** | 11600939 | **Manufacturer:** | |
| **Status:** | | **Serial No:** | |
| **Cont Name:** | | **Ulc Standard:** | |
| **Instance Type:** | FS Liquid Fuel Tank | **Quantity:** | |
| **Item:** | | **Unit of Measure:** | |
| **Item Description:** | FS Liquid Fuel Tank | **Fuel Type:** | Gasoline |
| **Tank Type:** | Double Wall UST | **Fuel Type2:** | NULL |
| **Install Date:** | 8/27/2009 8:08:40 AM | **Fuel Type3:** | NULL |
| **Install Year:** | 2000 | **Piping Steel:** | |
| **Years in Service:** | | **Piping Galvanized:** | |
| **Model:** | NULL | **Tanks Single Wall St:** | |
| **Description:** | | **Piping Underground:** | |
| **Capacity:** | 46400 | **No Underground:** | |
| **Tank Material:** | Fiberglass (FRP) | **Panam Related:** | |
| **Corrosion Protect:** | Fiberglass | **Panam Venue:** | |
| **Overfill Protect:** | | | |

**Facility Type:** FS Liquid Fuel Tank
**Parent Facility Type:** FS Gasoline Station - Self Serve
**Facility Location:**
**Device Installed Location:** 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA

***Liquid Fuel Tank Details***

**Overfill Protection:**
**Owner Account Name:** MAC'S CONVENIENCE STORES INC
**Item:** FS LIQUID FUEL TANK

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 2 | 12 of 28 | SSE/58.8 | 110.6 / -1.68 | MAC'S CONVENIENCE STORES INC<br>875 APPLEBY LINE BURLINGTON L7L 5R4 ON<br>CA<br>ON | FST |

| | | | |
|---|---|---|---|
| **Instance No:** | 11600931 | **Manufacturer:** | |
| **Status:** | | **Serial No:** | |
| **Cont Name:** | | **Ulc Standard:** | |
| **Instance Type:** | FS Liquid Fuel Tank | **Quantity:** | |
| **Item:** | | **Unit of Measure:** | |
| **Item Description:** | FS Liquid Fuel Tank | **Fuel Type:** | Gasoline |
| **Tank Type:** | Double Wall UST | **Fuel Type2:** | NULL |
| **Install Date:** | 8/27/2009 8:08:19 AM | **Fuel Type3:** | NULL |
| **Install Year:** | 2000 | **Piping Steel:** | |
| **Years in Service:** | | **Piping Galvanized:** | |
| **Model:** | NULL | **Tanks Single Wall St:** | |
| **Description:** | | **Piping Underground:** | |
| **Capacity:** | 46400 | **No Underground:** | |
| **Tank Material:** | Fiberglass (FRP) | **Panam Related:** | |
| **Corrosion Protect:** | Fiberglass | **Panam Venue:** | |
| **Overfill Protect:** | | | |

**Facility Type:** FS Liquid Fuel Tank
**Parent Facility Type:** FS Gasoline Station - Self Serve
**Facility Location:**
**Device Installed Location:** 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA

***Liquid Fuel Tank Details***

**Overfill Protection:**
**Owner Account Name:** MAC'S CONVENIENCE STORES INC
**Item:** FS LIQUID FUEL TANK

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 2 | 13 of 28 | SSE/58.8 | 110.6 / -1.68 | ALTRUISTIC INC<br>875 APPLEBY LINE BURLINGTON L7L 5R4 ON<br>CA<br>ON | DTNK |

***Delisted Expired Fuel Safety Facilities***

| | | | |
|---|---|---|---|
| **Instance No:** | 11318145 | **Expired Date:** | |
| **Status:** | EXPIRED | **Max Hazard Rank:** | NULL |
| **Instance ID:** | | **Facility Location:** | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA |
| **Instance Type:** | | **Facility Type:** | FS LIQUID FUEL TANK |
| **Instance Creation Dt:** | 10/2/1989 | **Fuel Type 2:** | NULL |
| **Instance Install Dt:** | 10/2/1989 | **Fuel Type 3:** | NULL |
| **Item Description:** | FS Liquid Fuel Tank | **Panam Related:** | NULL |
| **Manufacturer:** | NULL | **Panam Venue Nm:** | NULL |
| **Model:** | NULL | **External Identifier:** | NULL |
| **Serial No:** | NULL | **Item:** | |
| **ULC Standard:** | NULL | **Piping Steel:** | |
| **Quantity:** | 1 | **Piping Galvanized:** | |
| **Unit of Measure:** | EA | **Tank Single Wall St:** | |
| **Overfill Prot Type:** | NULL | **Piping Underground:** | |
| **Creation Date:** | 7/5/2009 1:24:44 AM | **Tank Underground:** | |
| **Next Periodic Str DT:** | NULL | **Source:** | FS Liquid Fuel Tank |
| **TSSA Base Sched Cycle 2:** | NULL | | |
| **TSSAMax Hazard Rank 1:** | NULL | | |
| **TSSA Risk Based Periodic Yn:** | NULL | | |
| **TSSA Volume of Directives:** | NULL | | |
| **TSSA Periodic Exempt:** | NULL | | |
| **TSSA Statutory Interval:** | NULL | | |
| **TSSA Recd Insp Interva:** | NULL | | |
| **TSSA Recd Tolerance:** | NULL | | |
| **TSSA Program Area:** | NULL | | |
| **TSSA Program Area 2:** | NULL | | |
| **Description:** | U/G TANK | | |
| **Original Source:** | EXP | | |
| **Record Date:** | 31-JUL-2020 | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 2 | 14 of 28 | SSE/58.8 | 110.6 / -1.68 | ALTRUISTIC INC<br>875 APPLEBY LINE BURLINGTON L7L 5R4 ON<br>CA<br>ON | DTNK |

***Delisted Expired Fuel Safety Facilities***

| | | | |
|---|---|---|---|
| **Instance No:** | 11090051 | **Expired Date:** | |
| **Status:** | EXPIRED | **Max Hazard Rank:** | NULL |
| **Instance ID:** | | **Facility Location:** | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA |
| **Instance Type:** | | **Facility Type:** | FS LIQUID FUEL TANK |
| **Instance Creation Dt:** | 10/2/1989 | **Fuel Type 2:** | NULL |
| **Instance Install Dt:** | 10/2/1989 | **Fuel Type 3:** | NULL |
| **Item Description:** | FS Liquid Fuel Tank | **Panam Related:** | NULL |
| **Manufacturer:** | NULL | **Panam Venue Nm:** | NULL |
| **Model:** | NULL | **External Identifier:** | NULL |
| **Serial No:** | NULL | **Item:** | |
| **ULC Standard:** | NULL | **Piping Steel:** | |
| **Quantity:** | 1 | **Piping Galvanized:** | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

| | | | |
|---|---|---|---|
| **Unit of Measure:** | EA | **Tank Single Wall St:** | |
| **Overfill Prot Type:** | NULL | **Piping Underground:** | |
| **Creation Date:** | 7/5/2009 1:23:45 AM | **Tank Underground:** | |
| **Next Periodic Str DT:** | NULL | **Source:** | FS Liquid Fuel Tank |
| **TSSA Base Sched Cycle 2:** | NULL | | |
| **TSSAMax Hazard Rank 1:** | NULL | | |
| **TSSA Risk Based Periodic Yn:** | NULL | | |
| **TSSA Volume of Directives:** | NULL | | |
| **TSSA Periodic Exempt:** | NULL | | |
| **TSSA Statutory Interval:** | NULL | | |
| **TSSA Recd Insp Interva:** | NULL | | |
| **TSSA Recd Tolerance:** | NULL | | |
| **TSSA Program Area:** | NULL | | |
| **TSSA Program Area 2:** | NULL | | |
| **Description:** | U/G TANK | | |
| **Original Source:** | EXP | | |
| **Record Date:** | 31-JUL-2020 | | |

---

| | | | | | |
|---|---|---|---|---|---|
| 2 | 15 of 28 | SSE/58.8 | 110.6 / -1.68 | **ALTRUISTIC INC**<br>**875 APPLEBY LINE BURLINGTON L7L 5R4 ON**<br>**CA**<br>**ON** | DTNK |

***Delisted Expired Fuel Safety Facilities***

| | | | |
|---|---|---|---|
| **Instance No:** | 11318164 | **Expired Date:** | |
| **Status:** | EXPIRED | **Max Hazard Rank:** | NULL |
| **Instance ID:** | | **Facility Location:** | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA |
| **Instance Type:** | | **Facility Type:** | FS LIQUID FUEL TANK |
| **Instance Creation Dt:** | 10/2/1989 | **Fuel Type 2:** | NULL |
| **Instance Install Dt:** | 10/2/1989 | **Fuel Type 3:** | NULL |
| **Item Description:** | FS Liquid Fuel Tank | **Panam Related:** | NULL |
| **Manufacturer:** | NULL | **Panam Venue Nm:** | NULL |
| **Model:** | NULL | **External Identifier:** | NULL |
| **Serial No:** | NULL | **Item:** | |
| **ULC Standard:** | NULL | **Piping Steel:** | |
| **Quantity:** | 1 | **Piping Galvanized:** | |
| **Unit of Measure:** | EA | **Tank Single Wall St:** | |
| **Overfill Prot Type:** | NULL | **Piping Underground:** | |
| **Creation Date:** | 7/5/2009 1:24:38 AM | **Tank Underground:** | |
| **Next Periodic Str DT:** | NULL | **Source:** | FS Liquid Fuel Tank |
| **TSSA Base Sched Cycle 2:** | NULL | | |
| **TSSAMax Hazard Rank 1:** | NULL | | |
| **TSSA Risk Based Periodic Yn:** | NULL | | |
| **TSSA Volume of Directives:** | NULL | | |
| **TSSA Periodic Exempt:** | NULL | | |
| **TSSA Statutory Interval:** | NULL | | |
| **TSSA Recd Insp Interva:** | NULL | | |
| **TSSA Recd Tolerance:** | NULL | | |
| **TSSA Program Area:** | NULL | | |
| **TSSA Program Area 2:** | NULL | | |
| **Description:** | U/G TANK | | |
| **Original Source:** | EXP | | |
| **Record Date:** | 31-JUL-2020 | | |

---

| | | | | | |
|---|---|---|---|---|---|
| 2 | 16 of 28 | SSE/58.8 | 110.6 / -1.68 | **ALTRUISTIC INC**<br>**875 APPLEBY LINE BURLINGTON L7L 5R4 ON**<br>**CA**<br>**ON** | DTNK |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Delisted Expired Fuel Safety Facilities***

| | | | |
|---|---|---|---|
| ***Instance No:*** | 11318124 | ***Expired Date:*** | |
| ***Status:*** | EXPIRED | ***Max Hazard Rank:*** | NULL |
| ***Instance ID:*** | | ***Facility Location:*** | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA |
| ***Instance Type:*** | | ***Facility Type:*** | FS LIQUID FUEL TANK |
| ***Instance Creation Dt:*** | 10/2/1989 | ***Fuel Type 2:*** | NULL |
| ***Instance Install Dt:*** | 10/2/1989 | ***Fuel Type 3:*** | NULL |
| ***Item Description:*** | FS Liquid Fuel Tank | ***Panam Related:*** | NULL |
| ***Manufacturer:*** | NULL | ***Panam Venue Nm:*** | NULL |
| ***Model:*** | NULL | ***External Identifier:*** | NULL |
| ***Serial No:*** | NULL | ***Item:*** | |
| ***ULC Standard:*** | NULL | ***Piping Steel:*** | |
| ***Quantity:*** | 1 | ***Piping Galvanized:*** | |
| ***Unit of Measure:*** | EA | ***Tank Single Wall St:*** | |
| ***Overfill Prot Type:*** | NULL | ***Piping Underground:*** | |
| ***Creation Date:*** | 7/5/2009 1:24:41 AM | ***Tank Underground:*** | |
| ***Next Periodic Str DT:*** | NULL | ***Source:*** | FS Liquid Fuel Tank |
| ***TSSA Base Sched Cycle 2:*** | NULL | | |
| ***TSSAMax Hazard Rank 1:*** | NULL | | |
| ***TSSA Risk Based Periodic Yn:*** | NULL | | |
| ***TSSA Volume of Directives:*** | NULL | | |
| ***TSSA Periodic Exempt:*** | NULL | | |
| ***TSSA Statutory Interval:*** | NULL | | |
| ***TSSA Recd Insp Interva:*** | NULL | | |
| ***TSSA Recd Tolerance:*** | NULL | | |
| ***TSSA Program Area:*** | NULL | | |
| ***TSSA Program Area 2:*** | NULL | | |
| ***Description:*** | U/G TANK | | |
| ***Original Source:*** | EXP | | |
| ***Record Date:*** | 31-JUL-2020 | | |

| | | | | | |
|---|---|---|---|---|---|
| 2 | ***17 of 28*** | ***SSE/58.8*** | ***110.6 / -1.68*** | ***1317942 ONTARIO LTD O/A ESSO GAS STATION 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA ON*** | ***DTNK*** |

***Delisted Expired Fuel Safety Facilities***

| | | | |
|---|---|---|---|
| ***Instance No:*** | 11600946 | ***Expired Date:*** | |
| ***Status:*** | EXPIRED | ***Max Hazard Rank:*** | NULL |
| ***Instance ID:*** | | ***Facility Location:*** | 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA |
| ***Instance Type:*** | | ***Facility Type:*** | FS LIQUID FUEL TANK |
| ***Instance Creation Dt:*** | 2/8/2000 | ***Fuel Type 2:*** | NULL |
| ***Instance Install Dt:*** | 2/8/2000 | ***Fuel Type 3:*** | NULL |
| ***Item Description:*** | FS Liquid Fuel Tank | ***Panam Related:*** | NULL |
| ***Manufacturer:*** | NULL | ***Panam Venue Nm:*** | NULL |
| ***Model:*** | NULL | ***External Identifier:*** | NULL |
| ***Serial No:*** | NULL | ***Item:*** | |
| ***ULC Standard:*** | NULL | ***Piping Steel:*** | |
| ***Quantity:*** | 1 | ***Piping Galvanized:*** | |
| ***Unit of Measure:*** | EA | ***Tank Single Wall St:*** | |
| ***Overfill Prot Type:*** | NULL | ***Piping Underground:*** | |
| ***Creation Date:*** | 7/5/2009 1:26:16 AM | ***Tank Underground:*** | |
| ***Next Periodic Str DT:*** | NULL | ***Source:*** | FS Liquid Fuel Tank |
| ***TSSA Base Sched Cycle 2:*** | NULL | | |
| ***TSSAMax Hazard Rank 1:*** | NULL | | |

| | |
|---|---|
| ***TSSA Risk Based Periodic Yn:*** | NULL |
| ***TSSA Volume of Directives:*** | NULL |
| ***TSSA Periodic Exempt:*** | NULL |
| ***TSSA Statutory Interval:*** | NULL |
| ***TSSA Recd Insp Interva:*** | NULL |
| ***TSSA Recd Tolerance:*** | NULL |
| ***TSSA Program Area:*** | NULL |
| ***TSSA Program Area 2:*** | NULL |
| ***Description:*** | INACCURATE RECORD |
| ***Original Source:*** | EXP |
| ***Record Date:*** | 31-JUL-2020 |

**2** ***18 of 28*** ***SSE/58.8*** ***110.6 / -1.68*** ***875 Appleby Line***
***Burlington ON L7L5R4*** ***EHS***

| | | | |
|---|---|---|---|
| ***Order No:*** | 20150428100 | ***Nearest Intersection:*** | |
| ***Status:*** | C | ***Municipality:*** | Burlington |
| ***Report Type:*** | Standard Report | ***Client Prov/State:*** | ON |
| ***Report Date:*** | 05-MAY-15 | ***Search Radius (km):*** | .25 |
| ***Date Received:*** | 28-APR-15 | ***X:*** | -79.767408 |
| ***Previous Site Name:*** | | ***Y:*** | 43.378264 |
| ***Lot/Building Size:*** | | | |
| ***Additional Info Ordered:*** | City Directory | | |

**2** ***19 of 28*** ***SSE/58.8*** ***110.6 / -1.68*** ***Imperial Oil Limited***
***845 Appleby Line***
***Burlington ON M3C 1K5*** ***ECA***

| | | | |
|---|---|---|---|
| ***Approval No:*** | 8027-7NPJXL | ***MOE District:*** | |
| ***Approval Date:*** | 2009-01-27 | ***City:*** | |
| ***Status:*** | Approved | ***Longitude:*** | |
| ***Record Type:*** | ECA | ***Latitude:*** | |
| ***Link Source:*** | IDS | ***Geometry X:*** | |
| ***SWP Area Name:*** | | ***Geometry Y:*** | |
| ***Approval Type:*** | ECA-INDUSTRIAL SEWAGE WORKS | | |
| ***Project Type:*** | INDUSTRIAL SEWAGE WORKS | | |
| ***Business Name:*** | Imperial Oil Limited | | |
| ***Address:*** | 845 Appleby Line | | |
| ***Full Address:*** | | | |
| ***Full PDF Link:*** | https://www.accessenvironment.ene.gov.on.ca/instruments/4987-7MTRUY-14.pdf | | |
| ***PDF Site Location:*** | | | |

**2** ***20 of 28*** ***SSE/58.8*** ***110.6 / -1.68*** ***Mac's Convenience Stores Inc.***
***875 Appleby Line***
***Burlington ON L7L 5R4*** ***GEN***

| | |
|---|---|
| ***Generator No:*** | ON8569169 |
| ***SIC Code:*** | |
| ***SIC Description:*** | |
| ***Approval Years:*** | As of Jul 2020 |
| ***PO Box No:*** | |
| ***Country:*** | Canada |
| ***Status:*** | Registered |
| ***Co Admin:*** | |
| ***Choice of Contact:*** | |
| ***Phone No Admin:*** | |
| ***Contaminated Facility:*** | |
| ***MHSW Facility:*** | |

***Detail(s)***

**Waste Class:** 251 L
**Waste Class Name:** Waste oils/sludges (petroleum based)

---

**2** **21 of 28** **SSE/58.8** **110.6 / -1.68** **ALTRUISTIC INC** **FST**
**875 APPLEBY LINE BURLINGTON L7L 5R4 ON**
**CA**
**ON**

**Instance No:** 11090051
**Status:**
**Cont Name:**
**Instance Type:**
**Item:**
**Item Description:** FS Liquid Fuel Tank
**Tank Type:** Liquid Fuel Single Wall UST
**Install Date:** 10/2/1989
**Install Year:** 1983
**Years in Service:**
**Model:** NULL
**Description:**
**Capacity:** 25000
**Tank Material:** Steel
**Corrosion Protect:** Sacrificial anode
**Overfill Protect:**
**Facility Type:** FS Liquid Fuel Tank
**Parent Facility Type:**
**Facility Location:**
**Device Installed Location:** 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA

**Manufacturer:**
**Serial No:**
**Ulc Standard:**
**Quantity:**
**Unit of Measure:**
**Fuel Type:** Gasoline
**Fuel Type2:** NULL
**Fuel Type3:** NULL
**Piping Steel:**
**Piping Galvanized:**
**Tanks Single Wall St:**
**Piping Underground:**
**No Underground:**
**Panam Related:**
**Panam Venue:**

***Liquid Fuel Tank Details***

**Overfill Protection:**
**Owner Account Name:** ALTRUISTIC INC
**Item:** FS LIQUID FUEL TANK

---

**2** **22 of 28** **SSE/58.8** **110.6 / -1.68** **ALTRUISTIC INC** **FST**
**875 APPLEBY LINE BURLINGTON L7L 5R4 ON**
**CA**
**ON**

**Instance No:** 11318124
**Status:**
**Cont Name:**
**Instance Type:**
**Item:**
**Item Description:** FS Liquid Fuel Tank
**Tank Type:** Liquid Fuel Single Wall UST
**Install Date:** 10/2/1989
**Install Year:** 1983
**Years in Service:**
**Model:** NULL
**Description:**
**Capacity:** 50000
**Tank Material:** Steel
**Corrosion Protect:** Sacrificial anode
**Overfill Protect:**
**Facility Type:** FS Liquid Fuel Tank
**Parent Facility Type:**
**Facility Location:**
**Device Installed Location:** 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA

**Manufacturer:**
**Serial No:**
**Ulc Standard:**
**Quantity:**
**Unit of Measure:**
**Fuel Type:** Gasoline
**Fuel Type2:** NULL
**Fuel Type3:** NULL
**Piping Steel:**
**Piping Galvanized:**
**Tanks Single Wall St:**
**Piping Underground:**
**No Underground:**
**Panam Related:**
**Panam Venue:**

***Liquid Fuel Tank Details***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Overfill Protection:**
**Owner Account Name:** ALTRUISTIC INC
**Item:** FS LIQUID FUEL TANK

---

**2** | **23 of 28** | **SSE/58.8** | **110.6 / -1.68** | **875 APPLEBY LINE BURLINGTON ON L7L 5R4** | **DTNK**

***Delisted Fuel Storage Tank***

| | | | |
|---|---|---|---|
| **Instance No:** | 9990056 | **Creation Date:** | |
| **Status:** | Active | **Overfill Prot Type:** | |
| **Instance Type:** | | **Facility Location:** | |
| **Fuel Type:** | | **Piping SW Steel:** | 0 |
| **Cont Name:** | | **Piping SW Galvan:** | 0 |
| **Capacity:** | | **Tanks SW Steel:** | 0 |
| **Tank Material:** | | **Piping Underground:** | 3 |
| **Corrosion Prot:** | | **No Underground:** | 3 |
| **Tank Type:** | | **Max Hazard Rank:** | |
| **Install Year:** | | **Max Hazard Rank 1:** | |
| **Facility Type:** | | **Nxt Period Start Dt:** | |
| **Device Installed Loc:** | | **Program Area 1:** | |
| **Fuel Type 2:** | | **Program Area 2:** | |
| **Fuel Type 3:** | | **Nxt Period Strt Dt 2:** | |
| **Item:** | FS GASOLINE STATION - SELF SERVE | **Risk Based Periodic:** | |
| **Item Description:** | | **Vol of Directives:** | |
| **Model:** | | **Years in Service:** | |
| **Description:** | | **Created Date:** | |
| **Instance Creation Dt:** | | **Federal Device:** | |
| **Instance Install Dt:** | | **Periodic Exempt:** | |
| **Manufacturer:** | | **Statutory Interval:** | |
| **Serial No:** | | **Rcomnd Insp Interval:** | |
| **ULC Standard:** | | **Recommended Toler:** | |
| **Quantity:** | | **Panam Venue Name:** | |
| **Unit of Measure:** | | **External Identifier:** | |
| **Parent Fac Type:** | | | |
| **TSSA Base Sched Cycle 1:** | | | |
| **TSSA Base Sched Cycle 2:** | | | |
| **Original Source:** | FST | | |
| **Record Date:** | 31-MAY-2021 | | |

---

**2** | **24 of 28** | **SSE/58.8** | **110.6 / -1.68** | **ALTRUISTIC INC 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA ON** | **FST**

| | | | |
|---|---|---|---|
| **Instance No:** | 11318145 | **Manufacturer:** | |
| **Status:** | | **Serial No:** | |
| **Cont Name:** | | **Ulc Standard:** | |
| **Instance Type:** | | **Quantity:** | |
| **Item:** | | **Unit of Measure:** | |
| **Item Description:** | FS Liquid Fuel Tank | **Fuel Type:** | Gasoline |
| **Tank Type:** | Liquid Fuel Single Wall UST | **Fuel Type2:** | NULL |
| **Install Date:** | 10/2/1989 | **Fuel Type3:** | NULL |
| **Install Year:** | 1983 | **Piping Steel:** | |
| **Years in Service:** | | **Piping Galvanized:** | |
| **Model:** | NULL | **Tanks Single Wall St:** | |
| **Description:** | | **Piping Underground:** | |
| **Capacity:** | 50000 | **No Underground:** | |
| **Tank Material:** | Steel | **Panam Related:** | |
| **Corrosion Protect:** | Sacrificial anode | **Panam Venue:** | |
| **Overfill Protect:** | | | |
| **Facility Type:** | FS Liquid Fuel Tank | | |

***Parent Facility Type:***
***Facility Location:***
***Device Installed Location:*** 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA

***Liquid Fuel Tank Details***

***Overfill Protection:***
***Owner Account Name:*** ALTRUISTIC INC
***Item:*** FS LIQUID FUEL TANK

---

**2** | ***25 of 28*** | ***SSE/58.8*** | ***110.6 / -1.68*** | ***1317942 ONTARIO LTD O/A ESSO GAS STATION***
***875 APPLEBY LINE BURLINGTON L7L 5R4 ON***
***CA***
***ON*** | ***FST***

***Instance No:*** 11600946
***Status:***
***Cont Name:***
***Instance Type:***
***Item:***
***Item Description:*** FS Liquid Fuel Tank
***Tank Type:*** Liquid Fuel Double Wall UST
***Install Date:*** 2/8/2000
***Install Year:*** 2000
***Years in Service:***
***Model:*** NULL
***Description:***
***Capacity:*** 139200
***Tank Material:*** Fiberglass (FRP)
***Corrosion Protect:*** Fiberglass
***Overfill Protect:***
***Manufacturer:***
***Serial No:***
***Ulc Standard:***
***Quantity:***
***Unit of Measure:***
***Fuel Type:*** Gasoline
***Fuel Type2:*** NULL
***Fuel Type3:*** NULL
***Piping Steel:***
***Piping Galvanized:***
***Tanks Single Wall St:***
***Piping Underground:***
***No Underground:***
***Panam Related:***
***Panam Venue:***
***Facility Type:*** FS Liquid Fuel Tank
***Parent Facility Type:***
***Facility Location:***
***Device Installed Location:*** 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA

***Liquid Fuel Tank Details***

***Overfill Protection:***
***Owner Account Name:*** 1317942 ONTARIO LTD O/A ESSO GAS STATION
***Item:*** FS LIQUID FUEL TANK

---

**2** | ***26 of 28*** | ***SSE/58.8*** | ***110.6 / -1.68*** | ***ALTRUISTIC INC***
***875 APPLEBY LINE BURLINGTON L7L 5R4 ON***
***CA***
***ON*** | ***FST***

***Instance No:*** 11318164
***Status:***
***Cont Name:***
***Instance Type:***
***Item:***
***Item Description:*** FS Liquid Fuel Tank
***Tank Type:*** Liquid Fuel Single Wall UST
***Install Date:*** 10/2/1989
***Install Year:*** 1983
***Years in Service:***
***Model:*** NULL
***Description:***
***Capacity:*** 25000
***Tank Material:*** Steel
***Corrosion Protect:*** Sacrificial anode
***Overfill Protect:***
***Manufacturer:***
***Serial No:***
***Ulc Standard:***
***Quantity:***
***Unit of Measure:***
***Fuel Type:*** Diesel
***Fuel Type2:*** NULL
***Fuel Type3:*** NULL
***Piping Steel:***
***Piping Galvanized:***
***Tanks Single Wall St:***
***Piping Underground:***
***No Underground:***
***Panam Related:***
***Panam Venue:***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Facility Type:*** FS Liquid Fuel Tank
***Parent Facility Type:***
***Facility Location:***
***Device Installed Location:*** 875 APPLEBY LINE BURLINGTON L7L 5R4 ON CA

***Liquid Fuel Tank Details***

***Overfill Protection:***
***Owner Account Name:*** ALTRUISTIC INC
***Item:*** FS LIQUID FUEL TANK

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 2 | 27 of 28 | SSE/58.8 | 110.6 / -1.68 | Mac's Convenience Stores Inc.<br>875 Appleby Line<br>Burlington ON L7L 5R4 | GEN |

***Generator No:*** ON8569169
***SIC Code:***
***SIC Description:***
***Approval Years:*** As of Nov 2021
***PO Box No:***
***Country:*** Canada
***Status:*** Registered
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 251 L
***Waste Class Name:*** Waste oils/sludges (petroleum based)

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 2 | 28 of 28 | SSE/58.8 | 110.6 / -1.68 | Mac's Convenience Stores Inc.<br>875 Appleby Line<br>Burlington ON L7L 5R4 | GEN |

***Generator No:*** ON8569169
***SIC Code:***
***SIC Description:***
***Approval Years:*** As of Oct 2022
***PO Box No:***
***Country:*** Canada
***Status:*** Registered
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 251 L
***Waste Class Name:*** OIL SKIMMINGS & SLUDGES

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 3 | 1 of 7 | NNE/117.6 | 113.9 / 1.63 | American Optics Inc.<br>5006 South Service Rd Unit 3-4<br>Burlington ON L7L 5Y7 | SCT |

***Established:*** 01-SEP-01
***Plant Size (ft²):*** 3000

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Employment:***

***--Details--***
***Description:*** Glass Product Manufacturing from Purchased Glass
***SIC/NAICS Code:*** 327215

---

**3** ***2 of 7*** ***NNE/117.6*** ***113.9 / 1.63*** ***American Optics Inc.***
***5006 South Service Rd., Unit 4***
***Burlington ON*** ***GEN***

***Generator No:*** ON3337491
***SIC Code:*** 339990
***SIC Description:*** ALL OTHER MISCELLANEOUS MANUFACTURING
***Approval Years:*** 2013
***PO Box No:***
***Country:***
***Status:***
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 262
***Waste Class Name:*** DETERGENTS/SOAPS

---

**3** ***3 of 7*** ***NNE/117.6*** ***113.9 / 1.63*** ***American Optics Ltd.***
***5006 South Service Rd., Unit 4***
***Burlington ON L7L 5Y7*** ***GEN***

***Generator No:*** ON3337491
***SIC Code:*** 339990
***SIC Description:*** ALL OTHER MISCELLANEOUS MANUFACTURING
***Approval Years:*** 2016
***PO Box No:***
***Country:*** Canada
***Status:***
***Co Admin:*** Marion Gaw
***Choice of Contact:*** CO_ADMIN
***Phone No Admin:*** 9056315377 Ext.
***Contaminated Facility:*** No
***MHSW Facility:*** No

***Detail(s)***

***Waste Class:*** 262
***Waste Class Name:*** DETERGENTS/SOAPS

***Waste Class:*** 252
***Waste Class Name:*** WASTE OILS & LUBRICANTS

---

**3** ***4 of 7*** ***NNE/117.6*** ***113.9 / 1.63*** ***American Optics Inc.***
***5006 South Service Rd., Unit 4***
***Burlington ON L7L 5Y7*** ***GEN***

***Generator No:*** ON3337491
***SIC Code:*** 339990
***SIC Description:*** ALL OTHER MISCELLANEOUS MANUFACTURING

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Approval Years:*** 2015
***PO Box No:***
***Country:*** Canada
***Status:***
***Co Admin:*** Marion Gaw
***Choice of Contact:*** CO_ADMIN
***Phone No Admin:*** 9056315377 Ext.
***Contaminated Facility:*** No
***MHSW Facility:*** No

***Detail(s)***

***Waste Class:*** 262
***Waste Class Name:*** DETERGENTS/SOAPS

***Waste Class:*** 252
***Waste Class Name:*** WASTE OILS & LUBRICANTS

---

**3** ***5 of 7*** ***NNE/117.6*** ***113.9 / 1.63*** ***American Optics Inc.***
***5006 South Service Rd., Unit 4***
***Burlington ON L7L 5Y7*** ***GEN***

***Generator No:*** ON3337491
***SIC Code:*** 339990
***SIC Description:*** ALL OTHER MISCELLANEOUS MANUFACTURING
***Approval Years:*** 2014
***PO Box No:***
***Country:*** Canada
***Status:***
***Co Admin:***
***Choice of Contact:*** CO_OFFICIAL
***Phone No Admin:***
***Contaminated Facility:*** No
***MHSW Facility:*** No

***Detail(s)***

***Waste Class:*** 252
***Waste Class Name:*** WASTE OILS & LUBRICANTS

***Waste Class:*** 262
***Waste Class Name:*** DETERGENTS/SOAPS

---

**3** ***6 of 7*** ***NNE/117.6*** ***113.9 / 1.63*** ***American Optics Ltd.***
***5006 South Service Rd., Unit 4***
***Burlington ON L7L 5Y7*** ***GEN***

***Generator No:*** ON3337491
***SIC Code:***
***SIC Description:***
***Approval Years:*** As of Dec 2018
***PO Box No:***
***Country:*** Canada
***Status:*** Registered
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Waste Class:** 252 L
**Waste Class Name:** Waste crankcase oils and lubricants

**Waste Class:** 262 L
**Waste Class Name:** Detergents and soaps

---

**3** | **7 of 7** | **NNE/117.6** | **113.9 / 1.63** | **American Optics Ltd.**
**5006 South Service Rd., Unit 4**
**Burlington ON L7L 5Y7** | **GEN**

**Generator No:** ON3337491
**SIC Code:**
**SIC Description:**
**Approval Years:** As of Oct 2019
**PO Box No:**
**Country:** Canada
**Status:** Registered
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 252 L
**Waste Class Name:** Waste crankcase oils and lubricants

**Waste Class:** 262 L
**Waste Class Name:** Detergents and soaps

---

**4** | **1 of 2** | **NE/120.9** | **111.1 / -1.11** | **Burkert Contromatic Inc.**
**5002 South Service Rd**
**Burlington ON L7L 5Y7** | **SCT**

**Established:** 01-AUG-90
**Plant Size (ft²):** 15000
**Employment:**

***--Details--***
**Description:** Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
**SIC/NAICS Code:** 417230

**Description:** Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
**SIC/NAICS Code:** 417230

---

**4** | **2 of 2** | **NE/120.9** | **111.1 / -1.11** | **Union Gas Limited**
**5002 South Service Road**
**Burlington ON** | **SPL**

**Ref No:** 7217-B6Q5LM
**Site No:** NA
**Incident Dt:** 2018/11/20
**Year:**
**Incident Cause:**
**Incident Event:** Operator/Human error
**Environment Impact:**
**Nature of Impact:**
**MOE Response:** No
**Dt MOE Arvl on Scn:**
**MOE Reported Dt:** 2018/11/20

**Contaminant Qty:** 1 n/a
**Nature of Damage:**
**Discharger Report:**
**Material Group:**
**Health/Env Conseq:** 4 - Medium Environment
**Agency Involved:**
**Site Lot:**
**Site Conc:**
**Site Geo Ref Accu:**
**Site Map Datum:**
**Northing:**

| | | | |
|---|---|---|---|
| **Dt Document Closed:** | | **Easting:** | |
| **Municipality No:** | | | |
| **System Facility Address:** | | | |
| **Client Type:** | Corporation | | |
| **Call Report Location Geodata:** | | | |
| **Contaminant Code:** | 35 | | |
| **Contaminant Name:** | NATURAL GAS (METHANE) | | |
| **Contaminant Limit 1:** | | | |
| **Contam Limit Freq 1:** | | | |
| **Contaminant UN No 1:** | 1075 | | |
| **Receiving Medium:** | | | |
| **Receiving Environment:** | Air | | |
| **Incident Reason:** | Operator/Human Error | | |
| **Incident Summary:** | TSSAfsb: Union Gas - Commercial gas meter damaged. South Service Rd. | | |
| **Site Region:** | Central | | |
| **Site Municipality:** | Burlington | | |
| **Activity Preceding Spill:** | | | |
| **Property 2nd Watershed:** | | | |
| **Property Tertiary Watershed:** | | | |
| **Sector Type:** | Miscellaneous Industrial | | |
| **SAC Action Class:** | Air Spills - Gases and Vapours | | |
| **Source Type:** | Pipeline/Components | | |
| **Site County/District:** | Regional Municipality of Halton | | |
| **Site Geo Ref Meth:** | | | |
| **Site District Office:** | Halton-Peel | | |
| **Nearest Watercourse:** | | | |
| **Site Name:** | Commercial gas meter damaged<UNOFFICIAL> | | |
| **Site Address:** | 5002 South Service Road | | |
| **Client Name:** | Union Gas Limited | | |

**5** **1 of 1** **ENE/122.7** **109.8 / -2.45** **lot 5 con 3 ON** **WWIS**

| | | | |
|---|---|---|---|
| **Well ID:** | 7385973 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | | **Data Entry Status:** | Yes |
| **Use 2nd:** | | **Data Src:** | |
| **Final Well Status:** | | **Date Received:** | 04/28/2021 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | Z358983 | **Contractor:** | 7241 |
| **Tag:** | A317893 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | HALTON |
| **Elevatn Reliabilty:** | | **Lot:** | 005 |
| **Depth to Bedrock:** | | **Concession:** | 03 |
| **Well Depth:** | | **Concession Name:** | DS S |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | BURLINGTON CITY | | |
| **Site Info:** | | | |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1008654032 | **Elevation:** | |
| **DP2BR:** | | **Elevrc:** | |
| **Spatial Status:** | | **Zone:** | 17 |
| **Code OB:** | | **East83:** | 599955.00 |
| **Code OB Desc:** | | **North83:** | 4803713.00 |
| **Open Hole:** | | **Org CS:** | UTM83 |
| **Cluster Kind:** | | **UTMRC:** | 4 |

| | | | |
|---|---|---|---|
| **Date Completed:** | 03/17/2021 | **UTMRC Desc:** | margin of error : 30 m - 100 m |
| **Remarks:** | | **Location Method:** | wwr |
| **Loc Method Desc:** | on Water Well Record | | |
| **Elevrc Desc:** | | | |
| **Location Source Date:** | | | |
| **Improvement Location Source:** | | | |
| **Improvement Location Method:** | | | |
| **Source Revision Comment:** | | | |
| **Supplier Comment:** | | | |

***Links***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1008654032 | **Tag No:** | A317893 |
| **Depth M:** | | **Contractor:** | 7241 |
| **Year Completed:** | 2021 | **Latitude:** | 43.3796320061963 |
| **Well Completed Dt:** | 03/17/2021 | **Longitude:** | -79.7660655801765 |
| **Audit No:** | Z358983 | **Y:** | 43.379632003875905 |
| **Path:** | | **X:** | -79.76606543055377 |

---

**6** | ***1 of 1*** | ***E/128.7*** | ***108.9 / -3.40*** | ***Appleby Line & Harvester Road Burlington ON L7L 4W9*** | ***EHS***

| | | | |
|---|---|---|---|
| **Order No:** | 20140124038 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | Burlington |
| **Report Type:** | Custom Report | **Client Prov/State:** | ON |
| **Report Date:** | 04-FEB-14 | **Search Radius (km):** | .25 |
| **Date Received:** | 24-JAN-14 | **X:** | -79.76583 |
| **Previous Site Name:** | | **Y:** | 43.37902 |
| **Lot/Building Size:** | 13 400 m^2 | | |
| **Additional Info Ordered:** | Fire Insur. Maps and/or Site Plans; Aerial Photos | | |

---

**7** | ***1 of 1*** | ***E/129.2*** | ***108.9 / -3.40*** | ***MF Grading Sevice<UNOFFICIAL> Intersection of Harvester Rd and South Service Rd Burlington ON*** | ***SPL***

| | | | |
|---|---|---|---|
| **Ref No:** | 1341-86HR9P | **Contaminant Qty:** | 300 L |
| **Site No:** | | **Nature of Damage:** | |
| **Incident Dt:** | | **Discharger Report:** | |
| **Year:** | | **Material Group:** | |
| **Incident Cause:** | Container Leak (Fuel Tank Barrels) | **Health/Env Conseq:** | |
| **Incident Event:** | | **Agency Involved:** | |
| **Environment Impact:** | Confirmed | **Site Lot:** | |
| **Nature of Impact:** | Human Health/Safety; Soil Contamination; Vegetation Damage | **Site Conc:** | |
| **MOE Response:** | Deferred Field Response | **Site Geo Ref Accu:** | |
| **Dt MOE Arvl on Scn:** | 6/18/2010 | **Site Map Datum:** | |
| **MOE Reported Dt:** | 6/17/2010 | **Northing:** | |
| **Dt Document Closed:** | | **Easting:** | |
| **Municipality No:** | | | |
| **System Facility Address:** | | | |
| **Client Type:** | | | |
| **Call Report Location Geodata:** | | | |
| **Contaminant Code:** | 13 | | |
| **Contaminant Name:** | DIESEL FUEL | | |
| **Contaminant Limit 1:** | | | |
| **Contam Limit Freq 1:** | | | |
| **Contaminant UN No 1:** | | | |
| **Receiving Medium:** | | | |
| **Receiving Environment:** | | | |
| **Incident Reason:** | Equipment Failure | | |
| **Incident Summary:** | MVA - Harvester Rd/ South Service Rd, dsl spill | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Site Region:**
**Site Municipality:**
**Activity Preceding Spill:**
**Property 2nd Watershed:**
**Property Tertiary Watershed:**
**Sector Type:** Transport Truck
**SAC Action Class:** Primary Assessment of Spills
**Source Type:**
**Site County/District:**
**Site Geo Ref Meth:**
**Site District Office:**
**Nearest Watercourse:**
**Site Name:** Intersection<UNOFFICIAL>
**Site Address:**
**Client Name:** MF Grading Sevice<UNOFFICIAL>

---

**8** | **1 of 1** | **ENE/131.6** | **109.8 / -2.44** | **lot 5 con 3 ON** | **WWIS**

| | | | |
|---|---|---|---|
| **Well ID:** | 7381453 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | | **Data Entry Status:** | Yes |
| **Use 2nd:** | | **Data Src:** | |
| **Final Well Status:** | | **Date Received:** | 02/23/2021 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | Z355979 | **Contractor:** | 7241 |
| **Tag:** | A311986 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | HALTON |
| **Elevatn Reliabilty:** | | **Lot:** | 005 |
| **Depth to Bedrock:** | | **Concession:** | 03 |
| **Well Depth:** | | **Concession Name:** | DS S |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | BURLINGTON CITY | | |
| **Site Info:** | | | |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1008634723 | **Elevation:** | |
| **DP2BR:** | | **Elevrc:** | |
| **Spatial Status:** | | **Zone:** | 17 |
| **Code OB:** | | **East83:** | 599959.00 |
| **Code OB Desc:** | | **North83:** | 4803724.00 |
| **Open Hole:** | | **Org CS:** | UTM83 |
| **Cluster Kind:** | | **UTMRC:** | 4 |
| **Date Completed:** | 01/14/2021 | **UTMRC Desc:** | margin of error : 30 m - 100 m |
| **Remarks:** | | **Location Method:** | wwr |
| **Loc Method Desc:** | on Water Well Record | | |
| **Elevrc Desc:** | | | |
| **Location Source Date:** | | | |
| **Improvement Location Source:** | | | |
| **Improvement Location Method:** | | | |
| **Source Revision Comment:** | | | |
| **Supplier Comment:** | | | |

***Links***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1008634723 | **Tag No:** | A311986 |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

| | | | |
|---|---|---|---|
| **Depth M:** | | **Contractor:** | 7241 |
| **Year Completed:** | 2021 | **Latitude:** | 43.3797304998439 |
| **Well Completed Dt:** | 01/14/2021 | **Longitude:** | -79.7660142032663 |
| **Audit No:** | Z355979 | **Y:** | 43.37973049757252 |
| **Path:** | | **X:** | -79.76601405411371 |

**9** **1 of 1** **E/132.2** **109.1 / -3.18** **lot 5 con 3 ON** **WWIS**

| | | | |
|---|---|---|---|
| **Well ID:** | 7385972 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | | **Data Entry Status:** | Yes |
| **Use 2nd:** | | **Data Src:** | |
| **Final Well Status:** | | **Date Received:** | 04/28/2021 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | Z358984 | **Contractor:** | 7241 |
| **Tag:** | A317892 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | HALTON |
| **Elevatn Reliabilty:** | | **Lot:** | 005 |
| **Depth to Bedrock:** | | **Concession:** | 03 |
| **Well Depth:** | | **Concession Name:** | DS S |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | BURLINGTON CITY | | |
| **Site Info:** | | | |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1008654029 | **Elevation:** | |
| **DP2BR:** | | **Elevrc:** | |
| **Spatial Status:** | | **Zone:** | 17 |
| **Code OB:** | | **East83:** | 599974.00 |
| **Code OB Desc:** | | **North83:** | 4803691.00 |
| **Open Hole:** | | **Org CS:** | UTM83 |
| **Cluster Kind:** | | **UTMRC:** | 4 |
| **Date Completed:** | 03/17/2021 | **UTMRC Desc:** | margin of error : 30 m - 100 m |
| **Remarks:** | | **Location Method:** | wwr |
| **Loc Method Desc:** | on Water Well Record | | |
| **Elevrc Desc:** | | | |
| **Location Source Date:** | | | |
| **Improvement Location Source:** | | | |
| **Improvement Location Method:** | | | |
| **Source Revision Comment:** | | | |
| **Supplier Comment:** | | | |

***Links***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1008654029 | **Tag No:** | A317892 |
| **Depth M:** | | **Contractor:** | 7241 |
| **Year Completed:** | 2021 | **Latitude:** | 43.3794314227469 |
| **Well Completed Dt:** | 03/17/2021 | **Longitude:** | -79.7658350982372 |
| **Audit No:** | Z358984 | **Y:** | 43.379431420387306 |
| **Path:** | | **X:** | -79.7658349489937 |

**10** **1 of 1** **ENE/144.5** **109.9 / -2.40** **lot 5 con 3 ON** **WWIS**

| | | | |
|---|---|---|---|
| **Well ID:** | 7385969 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |

| | | | |
|---|---|---|---|
| **Use 1st:** | | **Data Entry Status:** | Yes |
| **Use 2nd:** | | **Data Src:** | |
| **Final Well Status:** | | **Date Received:** | 04/28/2021 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | Z358987 | **Contractor:** | 7241 |
| **Tag:** | A317889 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | HALTON |
| **Elevatn Reliabilty:** | | **Lot:** | 005 |
| **Depth to Bedrock:** | | **Concession:** | 03 |
| **Well Depth:** | | **Concession Name:** | DS S |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | BURLINGTON CITY | | |
| **Site Info:** | | | |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1008654020 | **Elevation:** | |
| **DP2BR:** | | **Elevrc:** | |
| **Spatial Status:** | | **Zone:** | 17 |
| **Code OB:** | | **East83:** | 599966.00 |
| **Code OB Desc:** | | **North83:** | 4803737.00 |
| **Open Hole:** | | **Org CS:** | UTM83 |
| **Cluster Kind:** | | **UTMRC:** | 4 |
| **Date Completed:** | 03/16/2021 | **UTMRC Desc:** | margin of error : 30 m - 100 m |
| **Remarks:** | | **Location Method:** | wwr |
| **Loc Method Desc:** | on Water Well Record | | |
| **Elevrc Desc:** | | | |
| **Location Source Date:** | | | |
| **Improvement Location Source:** | | | |
| **Improvement Location Method:** | | | |
| **Source Revision Comment:** | | | |
| **Supplier Comment:** | | | |

***Links***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1008654020 | **Tag No:** | A317889 |
| **Depth M:** | | **Contractor:** | 7241 |
| **Year Completed:** | 2021 | **Latitude:** | 43.3798465986755 |
| **Well Completed Dt:** | 03/16/2021 | **Longitude:** | -79.7659254345858 |
| **Audit No:** | Z358987 | **Y:** | 43.37984659682779 |
| **Path:** | 738\7385969.pdf | **X:** | -79.7659252862086 |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 11 | 1 of 1 | ENE/152.3 | 108.8 / -3.44 | lot 5 con 3 ON | WWIS |

| | | | |
|---|---|---|---|
| **Well ID:** | 7385971 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | | **Data Entry Status:** | Yes |
| **Use 2nd:** | | **Data Src:** | |
| **Final Well Status:** | | **Date Received:** | 04/28/2021 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | Z358985 | **Contractor:** | 7241 |
| **Tag:** | A317891 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | HALTON |
| **Elevatn Reliabilty:** | | **Lot:** | 005 |
| **Depth to Bedrock:** | | **Concession:** | 03 |

**Well Depth:**
**Overburden/Bedrock:**
**Pump Rate:**
**Static Water Level:**
**Clear/Cloudy:**
**Municipality:** BURLINGTON CITY
**Site Info:**
**Concession Name:** DS S
**Easting NAD83:**
**Northing NAD83:**
**Zone:**
**UTM Reliability:**

***Bore Hole Information***

**Bore Hole ID:** 1008654026
**DP2BR:**
**Spatial Status:**
**Code OB:**
**Code OB Desc:**
**Open Hole:**
**Cluster Kind:**
**Date Completed:** 03/16/2021
**Remarks:**
**Loc Method Desc:** on Water Well Record
**Elevrc Desc:**
**Location Source Date:**
**Improvement Location Source:**
**Improvement Location Method:**
**Source Revision Comment:**
**Supplier Comment:**
**Elevation:**
**Elevrc:**
**Zone:** 17
**East83:** 599993.00
**North83:** 4803698.00
**Org CS:** UTM83
**UTMRC:** 4
**UTMRC Desc:** margin of error : 30 m - 100 m
**Location Method:** wwr

***Links***

**Bore Hole ID:** 1008654026
**Depth M:**
**Year Completed:** 2021
**Well Completed Dt:** 03/16/2021
**Audit No:** Z358985
**Path:**
**Tag No:** A317891
**Contractor:** 7241
**Latitude:** 43.379491908377
**Longitude:** -79.7655993207969
**Y:** 43.37949190568869
**X:** -79.76559917184389

---

| 12 | 1 of 2 | NW/160.7 | 114.8 / 2.59 | NEWCOURT FINANCIAL LTD.<br>5035 SOUTH SERVICE ROAD<br>BURLINGTON ON L7L 6M9 | CA |
|---|---|---|---|---|---|

**Certificate #:** 8-3660-98-
**Application Year:** 98
**Issue Date:** 12/4/1998
**Approval Type:** Industrial air
**Status:** Approved
**Application Type:**
**Client Name:**
**Client Address:**
**Client City:**
**Client Postal Code:**
**Project Description:** DIESEL GENERATOR FOR EMERGENCY ELECT.PO
**Contaminants:** Nitrogen Oxides
**Emission Control:** No Controls

---

| 12 | 2 of 2 | NW/160.7 | 114.8 / 2.59 | O&Y ENTERPRISE<br>5035 SOUTH SERVICE Road<br>BURLINGTON ON L7R4C8 | NPRI |
|---|---|---|---|---|---|

**NPRI ID:** 8800001977
**Other ID:**
**No Other ID:**
**Track ID:**
**Org ID:**
**Submit Date:**
**Last Modified:**
**Contact ID:**

| | | | |
|---|---|---|---|
| **Report ID:** | | **Cont Type:** | MED |
| **Report Type:** | | **Contact Title:** | Ms. |
| **Rpt Type ID:** | | **Cont First Name:** | Lena |
| **Report Year:** | 2004 | **Cont Last Name:** | Malone |
| **Not-Current Rpt?:** | | **Contact Position:** | Property Manager |
| **Yr of Last Filed Rpt:** | | **Contact Fax:** | |
| **Fac ID:** | | **Contact Ph.:** | |
| **Fac Name:** | C.I.T. BUSINESS CENTRE - 5035 S. SERVICE RD. | **Cont Area Code:** | 905 |
| **Fac Address1:** | | **Contact Tel.:** | 8485595 |
| **Fac Address2:** | | **Contact Ext.:** | |
| **Fac Postal Zip:** | | **Cont Fax Area Cde:** | 905 |
| **Facility Lat:** | | **Contact Fax:** | 8482004 |
| **Facility Long:** | | **Contact Email:** | lmalone@oyenterprise.com |
| **DLS (Last Filed Rpt):** | | **Latitude:** | |
| **Facility DLS:** | | **Longitude:** | |
| **Datum:** | | **UTM Zone:** | |
| **Facility Cmnts:** | | **UTM Northing:** | |
| **URL:** | | **UTM Easting:** | |
| **No of Empl.:** | 1 | **Waste Streams:** | |
| **Parent Co.:** | | **No Streams:** | |
| **No Parent Co.:** | | **Waste Off Sites:** | |
| **Pollut Prev Cmnts:** | | **No Off Sites:** | |
| **Stacks:** | | **Shutdown:** | |
| **No of Stacks:** | | **No of Shutdown:** | |
| **Canadian SIC Code (2 digit):** | | | |
| **Canadian SIC Code:** | | | |
| **SIC Code Description:** | | | |
| **American SIC Code:** | | | |
| **NAICS Code (2 digit):** | 53 | | |
| **NAICS 2 Description:** | Real Estate and Rental and Leasing | | |
| **NAICS Code (4 digit):** | 5311 | | |
| **NAICS 4 Description:** | Lessors of Real Estate | | |
| **NAICS Code (6 digit):** | 531120 | | |
| **NAICS 6 Description:** | Lessors of Non-Residential Buildings (except Mini-Warehouses) | | |

***Substance Release Report***

| | |
|---|---|
| **CAS No:** | 7446-09-5 |
| **Report ID:** | |
| **Rpt Period:** | 2004 |
| **Subst Released:** | Sulphur dioxide |
| **Air:** | |
| **Water:** | |
| **Land:** | |
| **Total Releases:** | |
| **Units:** | tonnes |

| | |
|---|---|
| **CAS No:** | 11104-93-1 |
| **Report ID:** | |
| **Rpt Period:** | 2004 |
| **Subst Released:** | Nitrogen oxides (expressed as NO2) |
| **Air:** | |
| **Water:** | |
| **Land:** | |
| **Total Releases:** | |
| **Units:** | tonnes |

| | |
|---|---|
| **CAS No:** | 811-97-2 |
| **Report ID:** | |
| **Rpt Period:** | 2004 |
| **Subst Released:** | HFC-134a Hydrofluorocarbon |
| **Air:** | |
| **Water:** | |
| **Land:** | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| **Total Releases:** | | | | | |
| **Units:** | | tonnes | | | |

---

**13** **1 of 2** **NE/184.7** **110.9 / -1.31** **5105 & 5109 Harvester and 5002 South Service Road**
**Burlington ON L7L 5Y9** **EHS**

| | | | |
|---|---|---|---|
| **Order No:** | 20291800064 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Custom Report | **Client Prov/State:** | ON |
| **Report Date:** | 23-SEP-20 | **Search Radius (km):** | .25 |
| **Date Received:** | 18-SEP-20 | **X:** | -79.76579794 |
| **Previous Site Name:** | | **Y:** | 43.38030139 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | Fire Insur. Maps and/or Site Plans | | |

---

**13** **2 of 2** **NE/184.7** **110.9 / -1.31** **5105 & 5109 Harvester and 5002 South Service Road**
**Burlington ON L7L 5Y9** **EHS**

| | | | |
|---|---|---|---|
| **Order No:** | 20291800064 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Custom Report | **Client Prov/State:** | ON |
| **Report Date:** | 23-SEP-20 | **Search Radius (km):** | .25 |
| **Date Received:** | 18-SEP-20 | **X:** | -79.76579794 |
| **Previous Site Name:** | | **Y:** | 43.38030139 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | Fire Insur. Maps and/or Site Plans | | |

---

**14** **1 of 3** **S/184.9** **107.1 / -5.19** **SEARS CANADA INC.**
**APPLEBY & HARVESTER RD MOTOR VEHICLE (OPERATING FLUID)**
**BURLINGTON CITY ON** **SPL**

| | | | |
|---|---|---|---|
| **Ref No:** | 209160 | **Contaminant Qty:** | |
| **Site No:** | | **Nature of Damage:** | |
| **Incident Dt:** | 8/16/2001 | **Discharger Report:** | |
| **Year:** | | **Material Group:** | |
| **Incident Cause:** | OTHER TRANSPORTATION ACCIDENT | **Health/Env Conseq:** | |
| **Incident Event:** | | **Agency Involved:** | FIRE DEPT., WORKS |
| **Environment Impact:** | Possible | **Site Lot:** | |
| **Nature of Impact:** | Water course or lake | **Site Conc:** | |
| **MOE Response:** | | **Site Geo Ref Accu:** | |
| **Dt MOE Arvl on Scn:** | | **Site Map Datum:** | |
| **MOE Reported Dt:** | 8/16/2001 | **Northing:** | |
| **Dt Document Closed:** | | **Easting:** | |
| **Municipality No:** | 14101 | | |
| **System Facility Address:** | | | |
| **Client Type:** | | | |
| **Call Report Location Geodata:** | | | |
| **Contaminant Code:** | | | |
| **Contaminant Name:** | | | |
| **Contaminant Limit 1:** | | | |
| **Contam Limit Freq 1:** | | | |
| **Contaminant UN No 1:** | | | |
| **Receiving Medium:** | Land, Water | | |
| **Receiving Environment:** | | | |
| **Incident Reason:** | UNKNOWN | | |
| **Incident Summary:** | SEARS: SML QTY DIESEL FUEL TO ROAD AND STORM. MVA. CLEANING. WORKS, FD. | | |
| **Site Region:** | | | |
| **Site Municipality:** | BURLINGTON CITY | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Activity Preceding Spill:***
***Property 2nd Watershed:***
***Property Tertiary Watershed:***
***Sector Type:***
***SAC Action Class:***
***Source Type:***
***Site County/District:***
***Site Geo Ref Meth:***
***Site District Office:***
***Nearest Watercourse:***
***Site Name:***
***Site Address:***
***Client Name:***

---

**14** | ***2 of 3*** | ***S/184.9*** | ***107.1 / -5.19*** | ***Union Gas Limited***
***Harvester Road and Appleby Line***
***Burlington ON*** | ***SPL***

***Ref No:*** 0356-6D6P3Y
***Site No:***
***Incident Dt:*** 6/8/2005
***Year:***
***Incident Cause:*** Pipe Or Hose Leak
***Incident Event:***
***Environment Impact:*** Possible
***Nature of Impact:*** Air Pollution
***MOE Response:***
***Dt MOE Arvl on Scn:***
***MOE Reported Dt:*** 6/8/2005
***Dt Document Closed:***
***Municipality No:***
***System Facility Address:***
***Client Type:***
***Call Report Location Geodata:***
***Contaminant Code:***
***Contaminant Name:*** NATURAL GAS (METHANE)
***Contaminant Limit 1:***
***Contam Limit Freq 1:***
***Contaminant UN No 1:***
***Receiving Medium:*** Water
***Receiving Environment:***
***Incident Reason:*** Equipment Failure
***Incident Summary:*** CN Rail - line ruptured/ Natural gas to atm
***Site Region:***
***Site Municipality:*** Burlington
***Activity Preceding Spill:***
***Property 2nd Watershed:***
***Property Tertiary Watershed:***
***Sector Type:*** Pipeline
***SAC Action Class:*** Spills to Air - gases and vapours
***Source Type:***
***Site County/District:***
***Site Geo Ref Meth:***
***Site District Office:*** Halton-Peel
***Nearest Watercourse:***
***Site Name:*** Appleby Go Station<UNOFFICIAL>
***Site Address:***
***Client Name:*** Union Gas Limited

***Contaminant Qty:*** 2
***Nature of Damage:***
***Discharger Report:*** 0
***Material Group:*** Gases/Particulate
***Health/Env Conseq:***
***Agency Involved:***
***Site Lot:***
***Site Conc:***
***Site Geo Ref Accu:***
***Site Map Datum:***
***Northing:***
***Easting:***

---

**14** | ***3 of 3*** | ***S/184.9*** | ***107.1 / -5.19*** | ***Rothsay, Member of Maple Leaf Foods***
***Lights at Harvester Road and Appleby Line***
***Burlington ON*** | ***SPL***

| | | | |
|---|---|---|---|
| ***Ref No:*** | 2454-8ATQ4R | ***Contaminant Qty:*** | 100 lb |
| ***Site No:*** | | ***Nature of Damage:*** | |
| ***Incident Dt:*** | | ***Discharger Report:*** | |
| ***Year:*** | | ***Material Group:*** | |
| ***Incident Cause:*** | Valve / Fitting Leak Or Failure | ***Health/Env Conseq:*** | |
| ***Incident Event:*** | | ***Agency Involved:*** | |
| ***Environment Impact:*** | Confirmed | ***Site Lot:*** | |
| ***Nature of Impact:*** | Other Impact(s) | ***Site Conc:*** | |
| ***MOE Response:*** | No Field Response | ***Site Geo Ref Accu:*** | |
| ***Dt MOE Arvl on Scn:*** | | ***Site Map Datum:*** | |
| ***MOE Reported Dt:*** | 11/2/2010 | ***Northing:*** | |
| ***Dt Document Closed:*** | | ***Easting:*** | |
| ***Municipality No:*** | | | |
| ***System Facility Address:*** | | | |
| ***Client Type:*** | | | |
| ***Call Report Location Geodata:*** | | | |
| ***Contaminant Code:*** | 46 | | |
| ***Contaminant Name:*** | ANIMAL WASTES | | |
| ***Contaminant Limit 1:*** | | | |
| ***Contam Limit Freq 1:*** | | | |
| ***Contaminant UN No 1:*** | | | |
| ***Receiving Medium:*** | | | |
| ***Receiving Environment:*** | | | |
| ***Incident Reason:*** | Equipment Failure | | |
| ***Incident Summary:*** | Maple Leaf Foods: pork spill, 100 lbs to road | | |
| ***Site Region:*** | | | |
| ***Site Municipality:*** | | | |
| ***Activity Preceding Spill:*** | | | |
| ***Property 2nd Watershed:*** | | | |
| ***Property Tertiary Watershed:*** | | | |
| ***Sector Type:*** | Other | | |
| ***SAC Action Class:*** | Land Spills | | |
| ***Source Type:*** | | | |
| ***Site County/District:*** | | | |
| ***Site Geo Ref Meth:*** | | | |
| ***Site District Office:*** | | | |
| ***Nearest Watercourse:*** | | | |
| ***Site Name:*** | Road<UNOFFICIAL> | | |
| ***Site Address:*** | | | |
| ***Client Name:*** | | | |

**15** ***1 of 7*** ***N/191.1*** ***115.9 / 3.65*** ***Aslan Technologies Inc.***
***5044 South Service Rd***
***Burlington ON L7L 5Y7*** ***SCT***

| | |
|---|---|
| ***Established:*** | 01-AUG-91 |
| ***Plant Size (ft²):*** | 6000 |
| ***Employment:*** | |

***--Details--***

| | |
|---|---|
| ***Description:*** | Commercial and Service Industry Machinery Manufacturing |
| ***SIC/NAICS Code:*** | 333310 |
| ***Description:*** | All Other Industrial Machinery Manufacturing |
| ***SIC/NAICS Code:*** | 333299 |

**15** ***2 of 7*** ***N/191.1*** ***115.9 / 3.65*** ***SSI EQUIPMENT INC.***
***5044A SOUTH SERVICE RD***
***BURLINGTON ON L7L 5Y7*** ***SCT***

| | |
|---|---|
| ***Established:*** | 1991 |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Plant Size (ft²):** 10000
**Employment:** 25

***--Details--***
**Description:** FABRICATED STRUCTURAL METAL
**SIC/NAICS Code:** 3441

**Description:** INDUSTRIAL VALVES
**SIC/NAICS Code:** 3491

**Description:** GENERAL INDUSTRIAL MACHINERY AND EQUIPMENT, NOT ELSEWHERE CLASSIFIED
**SIC/NAICS Code:** 3569

---

| | | | | | |
|---|---|---|---|---|---|
| 15 | 3 of 7 | N/191.1 | 115.9 / 3.65 | **SSI EQUIPMENT INC.**<br>**5044 SOUTH SERVICE RD**<br>**BURLINGTON ON L7L 5Y7** | SCT |

**Established:** 1991
**Plant Size (ft²):** 0
**Employment:** 25

***--Details--***
**Description:** GASKETS, PACKING & SEALING DEVICES
**SIC/NAICS Code:** 3053

**Description:** FABRICATED STRUCTURAL METAL
**SIC/NAICS Code:** 3441

**Description:** INDUSTRIAL VALVES
**SIC/NAICS Code:** 3491

**Description:** GENERAL INDUSTRIAL MACHINERY & EQUIPMENT, N.E.C.
**SIC/NAICS Code:** 3569

---

| | | | | | |
|---|---|---|---|---|---|
| 15 | 4 of 7 | N/191.1 | 115.9 / 3.65 | **ASLAN TECHNOLOGIES INC.**<br>**5044 SOUTH SERVICE ROAD**<br>**BURLINGTON ON L7L 5Y7** | GEN |

**Generator No:** ON7443841
**SIC Code:** 333920
**SIC Description:** Material Handling Equipment Manufacturing
**Approval Years:** 2009
**PO Box No:**
**Country:**
**Status:**
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 148
**Waste Class Name:** INORGANIC LABORATORY CHEMICALS

**Waste Class:** 252
**Waste Class Name:** WASTE OILS & LUBRICANTS

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 15 | 5 of 7 | N/191.1 | 115.9 / 3.65 | 5044 South Service Rd<br>Burlington ON L7L 5Y7 | EHS |

| | | | |
|---|---|---|---|
| **Order No:** | 20130402022 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Custom Report | **Client Prov/State:** | ON |
| **Report Date:** | 09-APR-13 | **Search Radius (km):** | .25 |
| **Date Received:** | 02-APR-13 | **X:** | 0 |
| **Previous Site Name:** | | **Y:** | 0 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 15 | 6 of 7 | N/191.1 | 115.9 / 3.65 | 5044 South Service Road<br>Burlington ON L7L 5Y7 | EHS |

| | | | |
|---|---|---|---|
| **Order No:** | 21040500077 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Standard Report | **Client Prov/State:** | ON |
| **Report Date:** | 08-APR-21 | **Search Radius (km):** | .25 |
| **Date Received:** | 05-APR-21 | **X:** | -79.7676301 |
| **Previous Site Name:** | | **Y:** | 43.3808408 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 15 | 7 of 7 | N/191.1 | 115.9 / 3.65 | 5044 South Service Road<br>Burlington ON L7L 5Y7 | EHS |

| | | | |
|---|---|---|---|
| **Order No:** | 21040500077 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Standard Report | **Client Prov/State:** | ON |
| **Report Date:** | 08-APR-21 | **Search Radius (km):** | .25 |
| **Date Received:** | 05-APR-21 | **X:** | -79.7676301 |
| **Previous Site Name:** | | **Y:** | 43.3808408 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 16 | 1 of 1 | SSW/193.6 | 110.0 / -2.22 | 870 APPLEBY LINE<br>BURLINGTON ON | WWIS |

| | | | |
|---|---|---|---|
| **Well ID:** | 7289963 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | Test Hole | **Data Entry Status:** | |
| **Use 2nd:** | Monitoring | **Data Src:** | |
| **Final Well Status:** | Observation Wells | **Date Received:** | 07/07/2017 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | Z258358 | **Contractor:** | 7241 |
| **Tag:** | A221635 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | HALTON |
| **Elevatn Reliabilty:** | | **Lot:** | |
| **Depth to Bedrock:** | | **Concession:** | |
| **Well Depth:** | | **Concession Name:** | |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | BURLINGTON CITY | | |
| **Site Info:** | | | |

**PDF URL (Map):**

***Additional Detail(s) (Map)***

***Well Completed Date:*** 05/19/2017
***Year Completed:*** 2017
***Depth (m):*** 6.096
***Latitude:*** 43.3775411889741
***Longitude:*** -79.7684040360917
***Path:***

***Bore Hole Information***

***Bore Hole ID:*** 1006616652
***DP2BR:***
***Spatial Status:***
***Code OB:***
***Code OB Desc:***
***Open Hole:***
***Cluster Kind:***
***Date Completed:*** 05/19/2017
***Remarks:***
***Loc Method Desc:*** on Water Well Record
***Elevrc Desc:***
***Location Source Date:***
***Improvement Location Source:***
***Improvement Location Method:***
***Source Revision Comment:***
***Supplier Comment:***

***Elevation:***
***Elevrc:***
***Zone:*** 17
***East83:*** 599769.00
***North83:*** 4803478.00
***Org CS:*** UTM83
***UTMRC:*** 4
***UTMRC Desc:*** margin of error : 30 m - 100 m
***Location Method:*** wwr

***Overburden and Bedrock Materials Interval***

***Formation ID:*** 1006668022
***Layer:*** 2
***Color:*** 7
***General Color:*** RED
***Mat1:*** 17
***Most Common Material:*** SHALE
***Mat2:***
***Mat2 Desc:***
***Mat3:***
***Mat3 Desc:***
***Formation Top Depth:*** 4.0
***Formation End Depth:*** 20.0
***Formation End Depth UOM:*** ft

***Overburden and Bedrock Materials Interval***

***Formation ID:*** 1006668021
***Layer:*** 1
***Color:*** 6
***General Color:*** BROWN
***Mat1:*** 11
***Most Common Material:*** GRAVEL
***Mat2:***
***Mat2 Desc:***
***Mat3:***
***Mat3 Desc:***
***Formation Top Depth:*** 0.0
***Formation End Depth:*** 4.0
***Formation End Depth UOM:*** ft

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1006668031 |
| ***Layer:*** | 2 |
| ***Plug From:*** | 1.0 |
| ***Plug To:*** | 9.0 |
| ***Plug Depth UOM:*** | ft |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1006668032 |
| ***Layer:*** | 3 |
| ***Plug From:*** | 9.0 |
| ***Plug To:*** | 20.0 |
| ***Plug Depth UOM:*** | ft |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1006668030 |
| ***Layer:*** | 1 |
| ***Plug From:*** | 0.0 |
| ***Plug To:*** | 1.0 |
| ***Plug Depth UOM:*** | ft |

***Method of Construction & Well Use***

| | |
|---|---|
| ***Method Construction ID:*** | 1006668029 |
| ***Method Construction Code:*** | D |
| ***Method Construction:*** | Direct Push |
| ***Other Method Construction:*** | |

***Pipe Information***

| | |
|---|---|
| ***Pipe ID:*** | 1006668020 |
| ***Casing No:*** | 0 |
| ***Comment:*** | |
| ***Alt Name:*** | |

***Construction Record - Casing***

| | |
|---|---|
| ***Casing ID:*** | 1006668025 |
| ***Layer:*** | 1 |
| ***Material:*** | 5 |
| ***Open Hole or Material:*** | PLASTIC |
| ***Depth From:*** | 0.0 |
| ***Depth To:*** | 10.0 |
| ***Casing Diameter:*** | 2.0 |
| ***Casing Diameter UOM:*** | inch |
| ***Casing Depth UOM:*** | ft |

***Construction Record - Screen***

| | |
|---|---|
| ***Screen ID:*** | 1006668026 |
| ***Layer:*** | 1 |
| ***Slot:*** | 10 |

| | |
|---|---|
| **Screen Top Depth:** | 10.0 |
| **Screen End Depth:** | 20.0 |
| **Screen Material:** | 5 |
| **Screen Depth UOM:** | ft |
| **Screen Diameter UOM:** | inch |
| **Screen Diameter:** | 2.25 |

***Water Details***

| | |
|---|---|
| **Water ID:** | 1006668024 |
| **Layer:** | |
| **Kind Code:** | |
| **Kind:** | |
| **Water Found Depth:** | |
| **Water Found Depth UOM:** | ft |

***Hole Diameter***

| | |
|---|---|
| **Hole ID:** | 1006668023 |
| **Diameter:** | 6.0 |
| **Depth From:** | 0.0 |
| **Depth To:** | 20.0 |
| **Hole Depth UOM:** | ft |
| **Hole Diameter UOM:** | inch |

***Links***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1006616652 | **Tag No:** | A221635 |
| **Depth M:** | 6.096 | **Contractor:** | 7241 |
| **Year Completed:** | 2017 | **Latitude:** | 43.3775411889741 |
| **Well Completed Dt:** | 05/19/2017 | **Longitude:** | -79.7684040360917 |
| **Audit No:** | Z258358 | **Y:** | 43.377541186709465 |
| **Path:** | 728\7289963.pdf | **X:** | -79.7684038866131 |

---

**17** | ***1 of 1*** | ***ESE/194.2*** | ***106.5 / -5.72*** | ***821 APPLEBY LINE BURLINGTON ON*** | ***WWIS***

| | | | |
|---|---|---|---|
| **Well ID:** | 7345219 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | Monitoring | **Data Entry Status:** | |
| **Use 2nd:** | | **Data Src:** | |
| **Final Well Status:** | Observation Wells | **Date Received:** | 10/22/2019 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | 8NOJNGUI | **Contractor:** | 6607 |
| **Tag:** | A246109 | **Form Version:** | 9 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | HALTON |
| **Elevatn Reliabilty:** | | **Lot:** | |
| **Depth to Bedrock:** | | **Concession:** | |
| **Well Depth:** | | **Concession Name:** | |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | BURLINGTON CITY | | |
| **Site Info:** | BH-1 | | |

***PDF URL (Map):*** https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/734\7345219.pdf

***Additional Detail(s) (Map)***

| | |
|---|---|
| **Well Completed Date:** | 10/08/2019 |
| **Year Completed:** | 2019 |
| **Depth (m):** | 10.6 |
| **Latitude:** | 43.3780681970772 |
| **Longitude:** | -79.765504761868 |
| **Path:** | 734\7345219.pdf |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1007684251 | **Elevation:** | |
| **DP2BR:** | | **Elevrc:** | |
| **Spatial Status:** | | **Zone:** | 17 |
| **Code OB:** | | **East83:** | 600003.00 |
| **Code OB Desc:** | | **North83:** | 4803540.00 |
| **Open Hole:** | | **Org CS:** | UTM83 |
| **Cluster Kind:** | | **UTMRC:** | 4 |
| **Date Completed:** | 10/08/2019 | **UTMRC Desc:** | margin of error : 30 m - 100 m |
| **Remarks:** | | **Location Method:** | wwr |
| **Loc Method Desc:** | on Water Well Record | | |
| **Elevrc Desc:** | | | |
| **Location Source Date:** | | | |
| **Improvement Location Source:** | | | |
| **Improvement Location Method:** | | | |
| **Source Revision Comment:** | | | |
| **Supplier Comment:** | | | |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| **Formation ID:** | 1007684833 |
| **Layer:** | 1 |
| **Color:** | 6 |
| **General Color:** | BROWN |
| **Mat1:** | 28 |
| **Most Common Material:** | SAND |
| **Mat2:** | 11 |
| **Mat2 Desc:** | GRAVEL |
| **Mat3:** | 01 |
| **Mat3 Desc:** | FILL |
| **Formation Top Depth:** | 0.0 |
| **Formation End Depth:** | 1.0 |
| **Formation End Depth UOM:** | m |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| **Formation ID:** | 1007684834 |
| **Layer:** | 2 |
| **Color:** | 6 |
| **General Color:** | BROWN |
| **Mat1:** | 17 |
| **Most Common Material:** | SHALE |
| **Mat2:** | |
| **Mat2 Desc:** | |
| **Mat3:** | 92 |
| **Mat3 Desc:** | WEATHERED |
| **Formation Top Depth:** | 1.0 |
| **Formation End Depth:** | 4.5 |
| **Formation End Depth UOM:** | m |

***Overburden and Bedrock Materials Interval***

***Formation ID:*** 1007684835
***Layer:*** 3
***Color:*** 7
***General Color:*** RED
***Mat1:*** 17
***Most Common Material:*** SHALE
***Mat2:***
***Mat2 Desc:***
***Mat3:*** 26
***Mat3 Desc:*** ROCK
***Formation Top Depth:*** 4.5
***Formation End Depth:*** 10.600000381469727
***Formation End Depth UOM:*** m

***Annular Space/Abandonment Sealing Record***

***Plug ID:*** 1007685350
***Layer:*** 2
***Plug From:*** 0.30000001192092896
***Plug To:*** 8.800000190734863
***Plug Depth UOM:*** m

***Annular Space/Abandonment Sealing Record***

***Plug ID:*** 1007685349
***Layer:*** 1
***Plug From:*** 0.0
***Plug To:*** 0.30000001192092896
***Plug Depth UOM:*** m

***Annular Space/Abandonment Sealing Record***

***Plug ID:*** 1007685235
***Layer:*** 1
***Plug From:***
***Plug To:***
***Plug Depth UOM:*** m

***Method of Construction & Well Use***

***Method Construction ID:*** 1007684615
***Method Construction Code:*** 7
***Method Construction:*** Diamond
***Other Method Construction:***

***Method of Construction & Well Use***

***Method Construction ID:*** 1007684614
***Method Construction Code:*** 6
***Method Construction:*** Boring
***Other Method Construction:***

***Pipe Information***

***Pipe ID:*** 1007684483

***Casing No:*** 0
***Comment:***
***Alt Name:***

***Construction Record - Casing***

***Casing ID:*** 1007685013
***Layer:*** 1
***Material:*** 5
***Open Hole or Material:*** PLASTIC
***Depth From:*** 0.0
***Depth To:*** 9.100000381469727
***Casing Diameter:*** 5.099999904632568
***Casing Diameter UOM:*** cm
***Casing Depth UOM:*** m

***Construction Record - Screen***

***Screen ID:*** 1007685089
***Layer:*** 1
***Slot:*** 10
***Screen Top Depth:*** 9.100000381469727
***Screen End Depth:*** 10.600000381469727
***Screen Material:*** 5
***Screen Depth UOM:*** m
***Screen Diameter UOM:*** cm
***Screen Diameter:*** 6.400000095367432

***Results of Well Yield Testing***

***Pumping Test Method Desc:***
***Pump Test ID:*** 1007684484
***Pump Set At:***
***Static Level:***
***Final Level After Pumping:***
***Recommended Pump Depth:***
***Pumping Rate:***
***Flowing Rate:***
***Recommended Pump Rate:***
***Levels UOM:*** m
***Rate UOM:*** LPM
***Water State After Test Code:***
***Water State After Test:***
***Pumping Test Method:***
***Pumping Duration HR:***
***Pumping Duration MIN:***
***Flowing:***

***Hole Diameter***

***Hole ID:*** 1007685145
***Diameter:*** 15.0
***Depth From:*** 0.0
***Depth To:*** 4.199999809265137
***Hole Depth UOM:*** m
***Hole Diameter UOM:*** cm

***Hole Diameter***

***Hole ID:*** 1007685146
***Diameter:*** 9.600000381469727
***Depth From:*** 4.199999809265137

| | |
|---|---|
| **Depth To:** | 10.600000381469727 |
| **Hole Depth UOM:** | m |
| **Hole Diameter UOM:** | cm |

***Links***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 1007684251 | **Tag No:** | A246109 |
| **Depth M:** | 10.6 | **Contractor:** | 6607 |
| **Year Completed:** | 2019 | **Latitude:** | 43.3780681970772 |
| **Well Completed Dt:** | 10/08/2019 | **Longitude:** | -79.765504761868 |
| **Audit No:** | 8NOJNGUI | **Y:** | 43.378068194742276 |
| **Path:** | 734\7345219.pdf | **X:** | -79.76550461263686 |

---

**18** | ***1 of 1*** | ***NNE/199.5*** | ***114.4 / 2.13*** | ***Long Wing International 5012 South Service Road Burlington ON L7L5Y7*** | ***GEN***

| | |
|---|---|
| **Generator No:** | ON9594931 |
| **SIC Code:** | |
| **SIC Description:** | |
| **Approval Years:** | As of Oct 2019 |
| **PO Box No:** | |
| **Country:** | Canada |
| **Status:** | Registered |
| **Co Admin:** | |
| **Choice of Contact:** | |
| **Phone No Admin:** | |
| **Contaminated Facility:** | |
| **MHSW Facility:** | |

***Detail(s)***

| | |
|---|---|
| **Waste Class:** | 263 C |
| **Waste Class Name:** | Misc. waste organic chemicals |
| **Waste Class:** | 146 C |
| **Waste Class Name:** | Other specified inorganic sludges, slurries or solids |

---

**19** | ***1 of 1*** | ***SSW/201.8*** | ***108.0 / -4.30*** | ***870 APPLEBY LINE BURLINGTON ON*** | ***WWIS***

| | | | |
|---|---|---|---|
| **Well ID:** | 7289962 | **Flowing (Y/N):** | |
| **Construction Date:** | | **Flow Rate:** | |
| **Use 1st:** | Test Hole | **Data Entry Status:** | |
| **Use 2nd:** | Monitoring | **Data Src:** | |
| **Final Well Status:** | Observation Wells | **Date Received:** | 07/07/2017 |
| **Water Type:** | | **Selected Flag:** | TRUE |
| **Casing Material:** | | **Abandonment Rec:** | |
| **Audit No:** | Z258359 | **Contractor:** | 7241 |
| **Tag:** | A221634 | **Form Version:** | 7 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | HALTON |
| **Elevatn Reliabilty:** | | **Lot:** | |
| **Depth to Bedrock:** | | **Concession:** | |
| **Well Depth:** | | **Concession Name:** | |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | BURLINGTON CITY | | |
| **Site Info:** | | | |

***PDF URL (Map):***

***Additional Detail(s) (Map)***

***Well Completed Date:*** 05/19/2017
***Year Completed:*** 2017
***Depth (m):*** 5.4864
***Latitude:*** 43.3773660219189
***Longitude:*** -79.7680249076681
***Path:***

***Bore Hole Information***

***Bore Hole ID:*** 1006616649
***DP2BR:***
***Spatial Status:***
***Code OB:***
***Code OB Desc:***
***Open Hole:***
***Cluster Kind:***
***Date Completed:*** 05/19/2017
***Remarks:***
***Loc Method Desc:*** on Water Well Record
***Elevrc Desc:***
***Location Source Date:***
***Improvement Location Source:***
***Improvement Location Method:***
***Source Revision Comment:***
***Supplier Comment:***

***Elevation:***
***Elevrc:***
***Zone:*** 17
***East83:*** 599800.00
***North83:*** 4803459.00
***Org CS:*** UTM83
***UTMRC:*** 4
***UTMRC Desc:*** margin of error : 30 m - 100 m
***Location Method:*** wwr

***Overburden and Bedrock Materials Interval***

***Formation ID:*** 1006667959
***Layer:*** 1
***Color:*** 6
***General Color:*** BROWN
***Mat1:*** 06
***Most Common Material:*** SILT
***Mat2:*** 05
***Mat2 Desc:*** CLAY
***Mat3:***
***Mat3 Desc:***
***Formation Top Depth:*** 0.0
***Formation End Depth:*** 4.0
***Formation End Depth UOM:*** ft

***Overburden and Bedrock Materials Interval***

***Formation ID:*** 1006667960
***Layer:*** 2
***Color:*** 7
***General Color:*** RED
***Mat1:*** 17
***Most Common Material:*** SHALE
***Mat2:***
***Mat2 Desc:***
***Mat3:***
***Mat3 Desc:***
***Formation Top Depth:*** 4.0
***Formation End Depth:*** 18.0
***Formation End Depth UOM:*** ft

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1006667968 |
| ***Layer:*** | 1 |
| ***Plug From:*** | 0.0 |
| ***Plug To:*** | 1.0 |
| ***Plug Depth UOM:*** | ft |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1006667970 |
| ***Layer:*** | 3 |
| ***Plug From:*** | 7.0 |
| ***Plug To:*** | 18.0 |
| ***Plug Depth UOM:*** | ft |

***Annular Space/Abandonment Sealing Record***

| | |
|---|---|
| ***Plug ID:*** | 1006667969 |
| ***Layer:*** | 2 |
| ***Plug From:*** | 1.0 |
| ***Plug To:*** | 7.0 |
| ***Plug Depth UOM:*** | ft |

***Method of Construction & Well Use***

| | |
|---|---|
| ***Method Construction ID:*** | 1006667967 |
| ***Method Construction Code:*** | D |
| ***Method Construction:*** | Direct Push |
| ***Other Method Construction:*** | |

***Pipe Information***

| | |
|---|---|
| ***Pipe ID:*** | 1006667958 |
| ***Casing No:*** | 0 |
| ***Comment:*** | |
| ***Alt Name:*** | |

***Construction Record - Casing***

| | |
|---|---|
| ***Casing ID:*** | 1006667963 |
| ***Layer:*** | 1 |
| ***Material:*** | 5 |
| ***Open Hole or Material:*** | PLASTIC |
| ***Depth From:*** | 0.0 |
| ***Depth To:*** | 8.0 |
| ***Casing Diameter:*** | 2.0 |
| ***Casing Diameter UOM:*** | inch |
| ***Casing Depth UOM:*** | ft |

***Construction Record - Screen***

| | |
|---|---|
| ***Screen ID:*** | 1006667964 |
| ***Layer:*** | 1 |
| ***Slot:*** | 10 |

***Screen Top Depth:*** 8.0
***Screen End Depth:*** 18.0
***Screen Material:*** 5
***Screen Depth UOM:*** ft
***Screen Diameter UOM:*** inch
***Screen Diameter:*** 2.25

***Water Details***

***Water ID:*** 1006667962
***Layer:***
***Kind Code:***
***Kind:***
***Water Found Depth:***
***Water Found Depth UOM:*** ft

***Hole Diameter***

***Hole ID:*** 1006667961
***Diameter:*** 6.0
***Depth From:*** 0.0
***Depth To:*** 18.0
***Hole Depth UOM:*** ft
***Hole Diameter UOM:*** inch

***Links***

***Bore Hole ID:*** 1006616649
***Depth M:*** 5.4864
***Year Completed:*** 2017
***Well Completed Dt:*** 05/19/2017
***Audit No:*** Z258359
***Path:*** 728\7289962.pdf
***Tag No:*** A221634
***Contractor:*** 7241
***Latitude:*** 43.3773660219189
***Longitude:*** -79.7680249076681
***Y:*** 43.377366019698755
***X:*** -79.76802475907131

---

**20** ***1 of 15*** ***WSW/205.5*** ***114.8 / 2.59*** ***Oak-Burl Industries Ltd.***
***914 Appleby Line***
***Burlington ON L7L 2Y8*** ***SCT***

***Established:*** 01-AUG-62
***Plant Size (ft²):*** 10000
***Employment:***

***--Details--***
***Description:*** Machine Shops
***SIC/NAICS Code:*** 332710

***Description:*** Machine Shops
***SIC/NAICS Code:*** 332710

---

**20** ***2 of 15*** ***WSW/205.5*** ***114.8 / 2.59*** ***OAK-BURL INDUSTRIES LIMITED***
***914 APPLEBY LINE***
***BURLINGTON ON L7L 2Y8*** ***GEN***

***Generator No:*** ON1267400
***SIC Code:*** 3081
***SIC Description:*** MACHINE SHOP IND.
***Approval Years:*** 89,99,00,01,02,03,04,05,07,08
***PO Box No:***
***Country:***
***Status:***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 253
***Waste Class Name:*** EMULSIFIED OILS

***Waste Class:*** 252
***Waste Class Name:*** WASTE OILS & LUBRICANTS

---

**20** | ***3 of 15*** | ***WSW/205.5*** | ***114.8 / 2.59*** | ***OAK-BURL INDUSTRIES LIMITED 29-482***
***914 APPLEBY LINE***
***BURLINGTON ON L7L 2Y8*** | ***GEN***

***Generator No:*** ON1267400
***SIC Code:*** 3081
***SIC Description:*** MACHINE SHOP IND.
***Approval Years:*** 92,93,94,95,96,97,98
***PO Box No:***
***Country:***
***Status:***
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 252
***Waste Class Name:*** WASTE OILS & LUBRICANTS

***Waste Class:*** 253
***Waste Class Name:*** EMULSIFIED OILS

---

**20** | ***4 of 15*** | ***WSW/205.5*** | ***114.8 / 2.59*** | ***OAK-BURL INDUSTRIES LIMITED***
***914 APPLEBY LINE***
***BURLINGTON ON L7L 2Y8*** | ***GEN***

***Generator No:*** ON1267400
***SIC Code:*** 332710
***SIC Description:*** Machine Shops
***Approval Years:*** 2009
***PO Box No:***
***Country:***
***Status:***
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 252
***Waste Class Name:*** WASTE OILS & LUBRICANTS

***Waste Class:*** 253

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| **Waste Class Name:** | | EMULSIFIED OILS | | | |

| | | | | | |
|---|---|---|---|---|---|
| 20 | 5 of 15 | WSW/205.5 | 114.8 / 2.59 | OAK-BURL INDUSTRIES LIMITED<br>914 APPLEBY LINE<br>BURLINGTON ON L7L 2Y8 | GEN |

**Generator No:** ON1267400
**SIC Code:** 332710
**SIC Description:** Machine Shops
**Approval Years:** 2010
**PO Box No:**
**Country:**
**Status:**
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 252
**Waste Class Name:** WASTE OILS & LUBRICANTS

**Waste Class:** 253
**Waste Class Name:** EMULSIFIED OILS

| | | | | | |
|---|---|---|---|---|---|
| 20 | 6 of 15 | WSW/205.5 | 114.8 / 2.59 | OAK-BURL INDUSTRIES LIMITED<br>914 APPLEBY LINE<br>BURLINGTON ON L7L 2Y8 | GEN |

**Generator No:** ON1267400
**SIC Code:** 332710
**SIC Description:** Machine Shops
**Approval Years:** 2011
**PO Box No:**
**Country:**
**Status:**
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 252
**Waste Class Name:** WASTE OILS & LUBRICANTS

**Waste Class:** 253
**Waste Class Name:** EMULSIFIED OILS

| | | | | | |
|---|---|---|---|---|---|
| 20 | 7 of 15 | WSW/205.5 | 114.8 / 2.59 | OAK-BURL INDUSTRIES LIMITED<br>914 APPLEBY LINE<br>BURLINGTON ON L7L 2Y8 | GEN |

**Generator No:** ON1267400
**SIC Code:** 332710
**SIC Description:** Machine Shops
**Approval Years:** 2012
**PO Box No:**
**Country:**

***Status:***
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 253
***Waste Class Name:*** EMULSIFIED OILS

***Waste Class:*** 252
***Waste Class Name:*** WASTE OILS & LUBRICANTS

---

**20** | ***8 of 15*** | ***WSW/205.5*** | ***114.8 / 2.59*** | ***OAK-BURL INDUSTRIES LIMITED 914 APPLEBY LINE BURLINGTON ON*** | ***GEN***

***Generator No:*** ON1267400
***SIC Code:*** 332710
***SIC Description:*** MACHINE SHOPS
***Approval Years:*** 2013
***PO Box No:***
***Country:***
***Status:***
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 252
***Waste Class Name:*** WASTE OILS & LUBRICANTS

***Waste Class:*** 251
***Waste Class Name:*** OIL SKIMMINGS & SLUDGES

***Waste Class:*** 253
***Waste Class Name:*** EMULSIFIED OILS

---

**20** | ***9 of 15*** | ***WSW/205.5*** | ***114.8 / 2.59*** | ***OAK-BURL INDUSTRIES LIMITED 914 APPLEBY LINE BURLINGTON ON L7L 2Y8*** | ***GEN***

***Generator No:*** ON1267400
***SIC Code:*** 332710
***SIC Description:*** MACHINE SHOPS
***Approval Years:*** 2016
***PO Box No:***
***Country:*** Canada
***Status:***
***Co Admin:*** Brent Shedden
***Choice of Contact:*** CO_ADMIN
***Phone No Admin:*** 905-637-2388 Ext.
***Contaminated Facility:*** No
***MHSW Facility:*** No

***Detail(s)***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Waste Class:** 251
**Waste Class Name:** OIL SKIMMINGS & SLUDGES

**Waste Class:** 253
**Waste Class Name:** EMULSIFIED OILS

**Waste Class:** 252
**Waste Class Name:** WASTE OILS & LUBRICANTS

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 10 of 15 | WSW/205.5 | 114.8 / 2.59 | OAK-BURL INDUSTRIES LIMITED<br>914 APPLEBY LINE<br>BURLINGTON ON L7L 2Y8 | GEN |

**Generator No:** ON1267400
**SIC Code:** 332710
**SIC Description:** MACHINE SHOPS
**Approval Years:** 2015
**PO Box No:**
**Country:** Canada
**Status:**
**Co Admin:** Brent Shedden
**Choice of Contact:** CO_ADMIN
**Phone No Admin:** 905-637-2388 Ext.
**Contaminated Facility:** No
**MHSW Facility:** No

***Detail(s)***

**Waste Class:** 252
**Waste Class Name:** WASTE OILS & LUBRICANTS

**Waste Class:** 253
**Waste Class Name:** EMULSIFIED OILS

**Waste Class:** 251
**Waste Class Name:** OIL SKIMMINGS & SLUDGES

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 11 of 15 | WSW/205.5 | 114.8 / 2.59 | OAK-BURL INDUSTRIES LIMITED<br>914 APPLEBY LINE<br>BURLINGTON ON L7L 2Y8 | GEN |

**Generator No:** ON1267400
**SIC Code:** 332710
**SIC Description:** MACHINE SHOPS
**Approval Years:** 2014
**PO Box No:**
**Country:** Canada
**Status:**
**Co Admin:** Brent Shedden
**Choice of Contact:** CO_ADMIN
**Phone No Admin:** 905-637-2388 Ext.
**Contaminated Facility:** No
**MHSW Facility:** No

***Detail(s)***

**Waste Class:** 252
**Waste Class Name:** WASTE OILS & LUBRICANTS

**Waste Class:** 251
**Waste Class Name:** OIL SKIMMINGS & SLUDGES

**Waste Class:** 253

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| **Waste Class Name:** | | EMULSIFIED OILS | | | |

| | | | | | |
|---|---|---|---|---|---|
| 20 | 12 of 15 | WSW/205.5 | 114.8 / 2.59 | OAK-BURL INDUSTRIES LIMITED<br>914 APPLEBY LINE<br>BURLINGTON ON L7L 2Y8 | GEN |

**Generator No:** ON1267400
**SIC Code:**
**SIC Description:**
**Approval Years:** As of Dec 2018
**PO Box No:**
**Country:** Canada
**Status:** Registered
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 251 L
**Waste Class Name:** Waste oils/sludges (petroleum based)

**Waste Class:** 252 L
**Waste Class Name:** Waste crankcase oils and lubricants

**Waste Class:** 253 L
**Waste Class Name:** Emulsified oils

| | | | | | |
|---|---|---|---|---|---|
| 20 | 13 of 15 | WSW/205.5 | 114.8 / 2.59 | OAK-BURL INDUSTRIES LIMITED<br>914 APPLEBY LINE<br>BURLINGTON ON L7L 2Y8 | GEN |

**Generator No:** ON1267400
**SIC Code:**
**SIC Description:**
**Approval Years:** As of Jul 2020
**PO Box No:**
**Country:** Canada
**Status:** Registered
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 251 L
**Waste Class Name:** Waste oils/sludges (petroleum based)

**Waste Class:** 252 L
**Waste Class Name:** Waste crankcase oils and lubricants

**Waste Class:** 253 L
**Waste Class Name:** Emulsified oils

| | | | | | |
|---|---|---|---|---|---|
| 20 | 14 of 15 | WSW/205.5 | 114.8 / 2.59 | OAK-BURL INDUSTRIES LIMITED<br>914 APPLEBY LINE<br>BURLINGTON ON L7L 2Y8 | GEN |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Generator No:** ON1267400
**SIC Code:**
**SIC Description:**
**Approval Years:** As of Nov 2021
**PO Box No:**
**Country:** Canada
**Status:** Registered
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 253 L
**Waste Class Name:** Emulsified oils

**Waste Class:** 252 L
**Waste Class Name:** Waste crankcase oils and lubricants

**Waste Class:** 251 L
**Waste Class Name:** Waste oils/sludges (petroleum based)

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 20 | 15 of 15 | WSW/205.5 | 114.8 / 2.59 | OAK-BURL INDUSTRIES LIMITED<br>914 APPLEBY LINE<br>BURLINGTON ON L7L 2Y8 | GEN |

**Generator No:** ON1267400
**SIC Code:**
**SIC Description:**
**Approval Years:** As of Oct 2022
**PO Box No:**
**Country:** Canada
**Status:** Registered
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 251 L
**Waste Class Name:** OIL SKIMMINGS & SLUDGES

**Waste Class:** 252 L
**Waste Class Name:** WASTE OILS & LUBRICANTS

**Waste Class:** 253 L
**Waste Class Name:** EMULSIFIED OILS

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 21 | 1 of 1 | E/218.2 | 106.8 / -5.44 | lot 5 con 3<br>ON | WWIS |

**Well ID:** 2803618
**Construction Date:**
**Use 1st:** Not Used
**Use 2nd:** 0
**Final Well Status:** Abandoned-Supply
**Water Type:**
**Casing Material:**
**Audit No:**

**Flowing (Y/N):**
**Flow Rate:**
**Data Entry Status:**
**Data Src:** 1
**Date Received:** 09/14/1971
**Selected Flag:** TRUE
**Abandonment Rec:**
**Contractor:** 5417

| | | | |
|---|---|---|---|
| **Tag:** | | **Form Version:** | 1 |
| **Constructn Method:** | | **Owner:** | |
| **Elevation (m):** | | **County:** | HALTON |
| **Elevatn Reliabilty:** | | **Lot:** | 005 |
| **Depth to Bedrock:** | | **Concession:** | 03 |
| **Well Depth:** | | **Concession Name:** | DS S |
| **Overburden/Bedrock:** | | **Easting NAD83:** | |
| **Pump Rate:** | | **Northing NAD83:** | |
| **Static Water Level:** | | **Zone:** | |
| **Clear/Cloudy:** | | **UTM Reliability:** | |
| **Municipality:** | BURLINGTON CITY | | |
| **Site Info:** | | | |

**PDF URL (Map):** https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/280\2803618.pdf

***Additional Detail(s) (Map)***

| | |
|---|---|
| **Well Completed Date:** | 08/17/1971 |
| **Year Completed:** | 1971 |
| **Depth (m):** | 14.3256 |
| **Latitude:** | 43.3789872338701 |
| **Longitude:** | -79.7647256829698 |
| **Path:** | 280\2803618.pdf |

***Bore Hole Information***

| | | | |
|---|---|---|---|
| **Bore Hole ID:** | 10150154 | **Elevation:** | |
| **DP2BR:** | | **Elevrc:** | |
| **Spatial Status:** | | **Zone:** | 17 |
| **Code OB:** | | **East83:** | 600064.60 |
| **Code OB Desc:** | | **North83:** | 4803643.00 |
| **Open Hole:** | | **Org CS:** | |
| **Cluster Kind:** | | **UTMRC:** | 4 |
| **Date Completed:** | 08/17/1971 | **UTMRC Desc:** | margin of error : 30 m - 100 m |
| **Remarks:** | | **Location Method:** | p4 |
| **Loc Method Desc:** | Original Pre1985 UTM Rel Code 4: margin of error : 30 m - 100 m | | |
| **Elevrc Desc:** | | | |
| **Location Source Date:** | | | |
| **Improvement Location Source:** | | | |
| **Improvement Location Method:** | | | |
| **Source Revision Comment:** | | | |
| **Supplier Comment:** | | | |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| **Formation ID:** | 931432662 |
| **Layer:** | 1 |
| **Color:** | 7 |
| **General Color:** | RED |
| **Mat1:** | 05 |
| **Most Common Material:** | CLAY |
| **Mat2:** | |
| **Mat2 Desc:** | |
| **Mat3:** | |
| **Mat3 Desc:** | |
| **Formation Top Depth:** | 0.0 |
| **Formation End Depth:** | 3.0 |
| **Formation End Depth UOM:** | ft |

***Overburden and Bedrock Materials Interval***

| | |
|---|---|
| ***Formation ID:*** | 931432663 |
| ***Layer:*** | 2 |
| ***Color:*** | 7 |
| ***General Color:*** | RED |
| ***Mat1:*** | 17 |
| ***Most Common Material:*** | SHALE |
| ***Mat2:*** | |
| ***Mat2 Desc:*** | |
| ***Mat3:*** | |
| ***Mat3 Desc:*** | |
| ***Formation Top Depth:*** | 3.0 |
| ***Formation End Depth:*** | 47.0 |
| ***Formation End Depth UOM:*** | ft |

***Method of Construction & Well Use***

| | |
|---|---|
| ***Method Construction ID:*** | 962803618 |
| ***Method Construction Code:*** | 1 |
| ***Method Construction:*** | Cable Tool |
| ***Other Method Construction:*** | |

***Pipe Information***

| | |
|---|---|
| ***Pipe ID:*** | 10698724 |
| ***Casing No:*** | 1 |
| ***Comment:*** | |
| ***Alt Name:*** | |

***Construction Record - Casing***

| | |
|---|---|
| ***Casing ID:*** | 930255345 |
| ***Layer:*** | 1 |
| ***Material:*** | |
| ***Open Hole or Material:*** | |
| ***Depth From:*** | |
| ***Depth To:*** | |
| ***Casing Diameter:*** | 6.0 |
| ***Casing Diameter UOM:*** | inch |
| ***Casing Depth UOM:*** | ft |

***Results of Well Yield Testing***

| | |
|---|---|
| ***Pumping Test Method Desc:*** | BAILER |
| ***Pump Test ID:*** | 992803618 |
| ***Pump Set At:*** | |
| ***Static Level:*** | 8.0 |
| ***Final Level After Pumping:*** | 40.0 |
| ***Recommended Pump Depth:*** | |
| ***Pumping Rate:*** | 1.0 |
| ***Flowing Rate:*** | |
| ***Recommended Pump Rate:*** | |
| ***Levels UOM:*** | ft |
| ***Rate UOM:*** | GPM |
| ***Water State After Test Code:*** | 1 |
| ***Water State After Test:*** | CLEAR |
| ***Pumping Test Method:*** | 2 |
| ***Pumping Duration HR:*** | 3 |
| ***Pumping Duration MIN:*** | 0 |
| ***Flowing:*** | No |

***Draw Down & Recovery***

***Pump Test Detail ID:*** 934451158
***Test Type:*** Draw Down
***Test Duration:*** 30
***Test Level:*** 40.0
***Test Level UOM:*** ft

***Draw Down & Recovery***

***Pump Test Detail ID:*** 934970259
***Test Type:*** Draw Down
***Test Duration:*** 60
***Test Level:*** 40.0
***Test Level UOM:*** ft

***Draw Down & Recovery***

***Pump Test Detail ID:*** 934710363
***Test Type:*** Draw Down
***Test Duration:*** 45
***Test Level:*** 40.0
***Test Level UOM:*** ft

***Draw Down & Recovery***

***Pump Test Detail ID:*** 934167211
***Test Type:*** Draw Down
***Test Duration:*** 15
***Test Level:*** 40.0
***Test Level UOM:*** ft

***Water Details***

***Water ID:*** 933606111
***Layer:*** 1
***Kind Code:*** 1
***Kind:*** FRESH
***Water Found Depth:*** 20.0
***Water Found Depth UOM:*** ft

***Water Details***

***Water ID:*** 933606112
***Layer:*** 2
***Kind Code:*** 1
***Kind:*** FRESH
***Water Found Depth:*** 44.0
***Water Found Depth UOM:*** ft

***Links***

***Bore Hole ID:*** 10150154
***Depth M:*** 14.3256
***Year Completed:*** 1971
***Well Completed Dt:*** 08/17/1971
***Audit No:***
***Path:*** 280\2803618.pdf

***Tag No:***
***Contractor:*** 5417
***Latitude:*** 43.3789872338701
***Longitude:*** -79.7647256829698
***Y:*** 43.378987231861394
***X:*** -79.76472553360213

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 22 | 1 of 2 | NW/225.3 | 114.8 / 2.54 | 5035 & 5045 South Service Road<br>Burlington ON | EHS |

**Order No:** 20110706002
**Status:** C
**Report Type:** Custom Report
**Report Date:** 7/11/2011
**Date Received:** 7/6/2011 8:11:40 AM
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:**

**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** ON
**Search Radius (km):** 0.25
**X:** -79.769389
**Y:** 43.380554

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 22 | 2 of 2 | NW/225.3 | 114.8 / 2.54 | 5035 South Service Road<br>Burlington ON L7L 4X4 | EHS |

**Order No:** 20181219125
**Status:** C
**Report Type:** Standard Report
**Report Date:** 31-DEC-18
**Date Received:** 19-DEC-18
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:**

**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** ON
**Search Radius (km):** .25
**X:** -79.769389
**Y:** 43.380554

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 23 | 1 of 44 | NE/225.5 | 111.0 / -1.27 | CONTROLCHEM CANADA LTD.<br>5109 HARVESTOR RD. BURLINGTON PLANT<br>5109 HARVESTER ROAD<br>BURLINGTON CITY ON | SPL |

**Ref No:** 88693
**Site No:**
**Incident Dt:** 7/20/1993
**Year:**
**Incident Cause:** OTHER CONTAINER LEAK
**Incident Event:**
**Environment Impact:** NOT ANTICIPATED
**Nature of Impact:**
**MOE Response:**
**Dt MOE Arvl on Scn:**
**MOE Reported Dt:** 7/20/1993
**Dt Document Closed:**
**Municipality No:** 14101
**System Facility Address:**
**Client Type:**
**Call Report Location Geodata:**
**Contaminant Code:**
**Contaminant Name:**
**Contaminant Limit 1:**
**Contam Limit Freq 1:**
**Contaminant UN No 1:**
**Receiving Medium:** LAND
**Receiving Environment:**
**Incident Reason:** DAMAGE BY MOVING EQUIPMENT
**Incident Summary:** CONTROLCHEM CANADA LTD: 800 L POLYMER SOLUTION TO PARKING LOT.
**Site Region:**
**Site Municipality:** BURLINGTON CITY
**Activity Preceding Spill:**
**Property 2nd Watershed:**
**Property Tertiary Watershed:**
**Sector Type:**
**SAC Action Class:**
**Source Type:**

**Contaminant Qty:**
**Nature of Damage:**
**Discharger Report:**
**Material Group:**
**Health/Env Conseq:**
**Agency Involved:**
**Site Lot:**
**Site Conc:**
**Site Geo Ref Accu:**
**Site Map Datum:**
**Northing:**
**Easting:**

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Site County/District:***
***Site Geo Ref Meth:***
***Site District Office:***
***Nearest Watercourse:***
***Site Name:***
***Site Address:***
***Client Name:***

---

**23** | ***2 of 44*** | ***NE/225.5*** | ***111.0 / -1.27*** | ***New Forms Inc.***
***5109 Harvester Rd Unit 10B***
***Burlington ON L7L 5Y9*** | ***SCT***

***Established:*** 01-AUG-90
***Plant Size (ft²):*** 6000
***Employment:***

***--Details--***
***Description:*** Coating, Engraving, Heat Treating and Allied Activities
***SIC/NAICS Code:*** 332810

***Description:*** Manifold Business Forms Printing
***SIC/NAICS Code:*** 323116

***Description:*** Other Printing
***SIC/NAICS Code:*** 323119

***Description:*** Manifold Business Forms Printing
***SIC/NAICS Code:*** 323116

---

**23** | ***3 of 44*** | ***NE/225.5*** | ***111.0 / -1.27*** | ***CONTROL CHEM CANADA LIMITED***
***5109 HARVESTER RD UNIT 7B***
***BURLINGTON ON L7L 5Y9*** | ***SCT***

***Established:*** 1987
***Plant Size (ft²):*** 0
***Employment:*** 13

***--Details--***
***Description:*** CYCLIC ORGANIC CRUDES AND INTERMEDIATES, AND ORGANIC DYES AND PIGMENTS
***SIC/NAICS Code:*** 2865

***Description:*** INDUSTRIAL ORGANIC CHEMICALS, NOT ELSEWHERE CLASSIFIED
***SIC/NAICS Code:*** 2869

---

**23** | ***4 of 44*** | ***NE/225.5*** | ***111.0 / -1.27*** | ***COMPUT-A-SIGNS***
***5109 Harvester Rd Unit B13***
***Burlington ON L7L 5Y4*** | ***SCT***

***Established:*** 1994
***Plant Size (ft²):*** 0
***Employment:*** 2

***--Details--***
***Description:*** Sign Manufacturing
***SIC/NAICS Code:*** 339950

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 23 | 5 of 44 | NE/225.5 | 111.0 / -1.27 | DIAGRAPH CANADA<br>5109 Harvester Rd Unit 5B<br>Burlington ON L7L 5Y9 | SCT |

**Established:** 0000
**Plant Size (ft²):** 0
**Employment:** 7

**--Details--**
**Description:** All Other Industrial Machinery Manufacturing
**SIC/NAICS Code:** 333299

**Description:** Commercial and Service Industry Machinery Manufacturing
**SIC/NAICS Code:** 333310

**Description:** Office Supplies (except Paper) Manufacturing
**SIC/NAICS Code:** 339940

**Description:** Sign Manufacturing
**SIC/NAICS Code:** 339950

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 23 | 6 of 44 | NE/225.5 | 111.0 / -1.27 | Lakeland Protective Wear Inc.<br>5109 Harvester Rd Unit B7<br>Burlington ON L7L 5Y9 | SCT |

**Established:** 1994
**Plant Size (ft²):** 12000
**Employment:** 811

**--Details--**
**Description:** Clothing and Clothing Accessories Wholesaler-Distributors
**SIC/NAICS Code:** 414110

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 23 | 7 of 44 | NE/225.5 | 111.0 / -1.27 | Bazco Precision<br>5109 Harvest Rd Unit 12-14<br>Burlington ON L7L 5Y9 | SCT |

**Established:** 1988
**Plant Size (ft²):** 3000
**Employment:** 3

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 23 | 8 of 44 | NE/225.5 | 111.0 / -1.27 | Diagraph Corporation<br>5109 Harvester Rd Unit 5B<br>Burlington ON L7L 5Y9 | SCT |

**Established:**
**Plant Size (ft²):**
**Employment:** 7

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 23 | 9 of 44 | NE/225.5 | 111.0 / -1.27 | Fastenal Canada Co.<br>5109 Harvester Rd Unit A4<br>Burlington ON L7L 5Y9 | SCT |

**Established:** 1995
**Plant Size (ft²):**
**Employment:** 14

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***--Details--***
***Description:*** Hardware Wholesaler-Distributors
***SIC/NAICS Code:*** 416330

***Description:*** Construction and Forestry Machinery, Equipment and Supplies Wholesaler-Distributors
***SIC/NAICS Code:*** 417210

***Description:*** Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
***SIC/NAICS Code:*** 417230

***Description:*** Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
***SIC/NAICS Code:*** 418410

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 23 | 10 of 44 | NE/225.5 | 111.0 / -1.27 | **Denclare Technologies Inc**<br>**5109 Harvester Rd**<br>**Burlington ON L7R 5Y9** | SCT |

***Established:***
***Plant Size (ft²):*** 3000
***Employment:*** 4

***--Details--***
***Description:*** Clothing and Clothing Accessories Wholesaler-Distributors
***SIC/NAICS Code:*** 414110

***Description:*** Floor Covering Wholesaler-Distributors
***SIC/NAICS Code:*** 414320

***Description:*** Electrical Wiring and Construction Supplies Wholesaler-Distributors
***SIC/NAICS Code:*** 416110

***Description:*** Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
***SIC/NAICS Code:*** 417230

***Description:*** Professional Machinery, Equipment and Supplies Wholesaler-Distributors
***SIC/NAICS Code:*** 417930

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 23 | 11 of 44 | NE/225.5 | 111.0 / -1.27 | **HARDY SALES & SERVICE INC.**<br>**5109 HARVESTER ROAD, UNIT #12**<br>**BURLINGTON ON L7L 5Y9** | GEN |

***Generator No:*** ON1868001
***SIC Code:*** 6342
***SIC Description:*** TIRE, ETC. STORES
***Approval Years:*** 95,96,97,98
***PO Box No:***
***Country:***
***Status:***
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 213
***Waste Class Name:*** PETROLEUM DISTILLATES

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 23 | 12 of 44 | NE/225.5 | 111.0 / -1.27 | HARDY SALES & SERVICE INC.<br>5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | GEN |

**Generator No:** ON1868001
**SIC Code:** 6342
**SIC Description:** TIRE, ETC. STORES
**Approval Years:** 99
**PO Box No:**
**Country:**
**Status:**
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 213
**Waste Class Name:** PETROLEUM DISTILLATES

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 23 | 13 of 44 | NE/225.5 | 111.0 / -1.27 | DIAGRAPH CORPORATION (CANADA)<br>5109 HARVESTER ROAD, UNIT 5B<br>BURLINGTON ON L7L 5Y9 | GEN |

**Generator No:** ON2522300
**SIC Code:** 3199
**SIC Description:** OTHER MACHINERY
**Approval Years:** 99,00,01
**PO Box No:**
**Country:**
**Status:**
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 212
**Waste Class Name:** ALIPHATIC SOLVENTS

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 23 | 14 of 44 | NE/225.5 | 111.0 / -1.27 | HARDY (SEE & USE ON2056701)<br>5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | GEN |

**Generator No:** ON1868001
**SIC Code:** 6342
**SIC Description:** TIRE, ETC. STORES
**Approval Years:** 00,01
**PO Box No:**
**Country:**
**Status:**
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**Waste Class:** 213
**Waste Class Name:** PETROLEUM DISTILLATES

---

**23** **15 of 44** **NE/225.5** **111.0 / -1.27** **AINSWORTH INC.**
**5109 HARVESTER ROAD, UNIT 12**
**BURLINGTON ON** **GEN**

**Generator No:** ON2056701
**SIC Code:** 6342
**SIC Description:** TIRE, ETC. STORES
**Approval Years:** 00,01
**PO Box No:**
**Country:**
**Status:**
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 213
**Waste Class Name:** PETROLEUM DISTILLATES

**Waste Class:** 251
**Waste Class Name:** OIL SKIMMINGS & SLUDGES

---

**23** **16 of 44** **NE/225.5** **111.0 / -1.27** **CLASSIC CARE PHARMACY INC.**
**5109 HARVESTER ROAD, UNIT 8A**
**BURLINGTON ON L7L 5Y9** **GEN**

**Generator No:** ON2553200
**SIC Code:** 6031
**SIC Description:** PHARMACIES
**Approval Years:** 00,01
**PO Box No:**
**Country:**
**Status:**
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 261
**Waste Class Name:** PHARMACEUTICALS

---

**23** **17 of 44** **NE/225.5** **111.0 / -1.27** **BAZCO PRECISION**
**5109 HARVESTER ROAD, UNIT 12**
**BURLINGTON ON L7L 5Y9** **GEN**

**Generator No:** ON2333901
**SIC Code:** 3081
**SIC Description:** MACHINE SHOP IND.
**Approval Years:** 01,02,03,04,05,06
**PO Box No:**
**Country:**
**Status:**

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 251
***Waste Class Name:*** OIL SKIMMINGS & SLUDGES

***Waste Class:*** 145
***Waste Class Name:*** PAINT/PIGMENT/COATING RESIDUES

***Waste Class:*** 211
***Waste Class Name:*** AROMATIC SOLVENTS

***Waste Class:*** 213
***Waste Class Name:*** PETROLEUM DISTILLATES

***Waste Class:*** 252
***Waste Class Name:*** WASTE OILS & LUBRICANTS

***Waste Class:*** 253
***Waste Class Name:*** EMULSIFIED OILS

---

| | | | | | |
|---|---|---|---|---|---|
| 23 | ***18 of 44*** | ***NE/225.5*** | ***111.0 / -1.27*** | ***Lakeland Protective Wear Inc.***<br>***B7-5109 Harvester Rd***<br>***Burlington ON L7L 5Y9*** | ***SCT*** |

***Established:*** 1994
***Plant Size (ft²):*** 10000
***Employment:*** 8

***--Details--***
***Description:*** Clothing and Clothing Accessories Wholesaler-Distributors
***SIC/NAICS Code:*** 414110

---

| | | | | | |
|---|---|---|---|---|---|
| 23 | ***19 of 44*** | ***NE/225.5*** | ***111.0 / -1.27*** | ***Bazco Precision***<br>***5109 Harvester Rd Unit 12-14***<br>***Burlington ON L7L 5Y9*** | ***SCT*** |

***Established:*** 01-JUL-88
***Plant Size (ft²):*** 3500
***Employment:***

***--Details--***
***Description:*** Machine Shops
***SIC/NAICS Code:*** 332710

---

| | | | | | |
|---|---|---|---|---|---|
| 23 | ***20 of 44*** | ***NE/225.5*** | ***111.0 / -1.27*** | ***Classic Care Pharmacy***<br>***5109 Harvester Rd Unit# 8A***<br>***Burlington ON*** | ***GEN*** |

***Generator No:*** ON5089580
***SIC Code:*** 414510
***SIC Description:*** Pharmaceuticals & Pharmacy Supplies Whl.
***Approval Years:*** 03,04,06
***PO Box No:***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Country:***
***Status:***
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 261
***Waste Class Name:*** PHARMACEUTICALS

***Waste Class:*** 312
***Waste Class Name:*** PATHOLOGICAL WASTES

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 23 | 21 of 44 | NE/225.5 | 111.0 / -1.27 | **Miller Polymer Corporation**<br>**5109 Harvester Rd. #B3**<br>**Burlington ON L7L 5Y9** | GEN |

***Generator No:*** ON3953922
***SIC Code:*** 418410
***SIC Description:*** Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
***Approval Years:*** 04,05
***PO Box No:***
***Country:***
***Status:***
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 232
***Waste Class Name:*** POLYMERIC RESINS

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 23 | 22 of 44 | NE/225.5 | 111.0 / -1.27 | **Quantum Feeder Systems Inc.**<br>**5109 Harvester Rd Unit 8A**<br>**Burlington ON L7L 5Y9** | SCT |

***Established:*** 1994
***Plant Size (ft²):***
***Employment:***

***--Details--***
***Description:*** All Other Industrial Machinery Manufacturing
***SIC/NAICS Code:*** 333299

***Description:*** Material Handling Equipment Manufacturing
***SIC/NAICS Code:*** 333920

***Description:*** All Other General-Purpose Machinery Manufacturing
***SIC/NAICS Code:*** 333990

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 23 | 23 of 44 | NE/225.5 | 111.0 / -1.27 | **Denclare Technologies Inc.**<br>**5109 Harvester Rd Unit B12**<br>**Burlington ON L7L 5Y9** | SCT |

***Established:*** 01-JAN-97
***Plant Size (ft²):*** 3000
***Employment:***

***--Details--***
***Description:*** Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
***SIC/NAICS Code:*** 417230

***Description:*** Electrical Wiring and Construction Supplies Wholesaler-Distributors
***SIC/NAICS Code:*** 416110

***Description:*** Paint and Coating Manufacturing
***SIC/NAICS Code:*** 325510

***Description:*** Other Home Furnishings Wholesaler-Distributors
***SIC/NAICS Code:*** 414390

***Description:*** Institutional Furniture Manufacturing
***SIC/NAICS Code:*** 337127

***Description:*** Material Handling Equipment Manufacturing
***SIC/NAICS Code:*** 333920

***Description:*** Wiring Device Manufacturing
***SIC/NAICS Code:*** 335930

***Description:*** All Other Plastic Product Manufacturing
***SIC/NAICS Code:*** 326198

***Description:*** Other Fabricated Wire Product Manufacturing
***SIC/NAICS Code:*** 332619

***Description:*** Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
***SIC/NAICS Code:*** 417230

***Description:*** Measuring, Medical and Controlling Devices Manufacturing
***SIC/NAICS Code:*** 334512

***Description:*** Other Paper and Disposable Plastic Product Wholesaler-Distributors
***SIC/NAICS Code:*** 418220

***Description:*** Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
***SIC/NAICS Code:*** 418410

***Description:*** Floor Covering Wholesaler-Distributors
***SIC/NAICS Code:*** 414320

***Description:*** Other Rubber Product Manufacturing
***SIC/NAICS Code:*** 326290

***Description:*** Corrugated and Solid Fibre Box Manufacturing
***SIC/NAICS Code:*** 322211

***Description:*** Service Establishment Machinery, Equipment and Supplies Wholesaler-Distributors
***SIC/NAICS Code:*** 417920

***Description:*** Professional Machinery, Equipment and Supplies Wholesaler-Distributors
***SIC/NAICS Code:*** 417930

***Description:*** Resin and Synthetic Rubber Manufacturing
***SIC/NAICS Code:*** 325210

***Description:*** Computer, Computer Peripheral and Pre-Packaged Software Wholesaler-Distributors
***SIC/NAICS Code:*** 417310

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| **Description:** | | Footwear Wholesaler-Distributors | | | |
| **SIC/NAICS Code:** | | 414120 | | | |

| | | | | | |
|---|---|---|---|---|---|
| 23 | 24 of 44 | NE/225.5 | 111.0 / -1.27 | **Dedicated Plastic Tanks Inc.**<br>**5109 Harvester Rd Unit 5B**<br>**Burlington ON L7L 7Y9** | SCT |

**Established:** 01-JAN-08
**Plant Size (ft²):** 3000
**Employment:**

***--Details--***

**Description:** All Other Miscellaneous Fabricated Metal Product Manufacturing
**SIC/NAICS Code:** 332999

**Description:** Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
**SIC/NAICS Code:** 417230

**Description:** All Other Machinery, Equipment and Supplies Wholesaler-Distributors
**SIC/NAICS Code:** 417990

**Description:** Other Specialty-Line Building Supplies Wholesaler-Distributors
**SIC/NAICS Code:** 416390

**Description:** Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
**SIC/NAICS Code:** 417230

| | | | | | |
|---|---|---|---|---|---|
| 23 | 25 of 44 | NE/225.5 | 111.0 / -1.27 | **Mega Industries Inc.**<br>**5109 Harvester Rd Unit 3A**<br>**Burlington ON L7L 5Y9** | SCT |

**Established:** 01-JUL-85
**Plant Size (ft²):** 8200
**Employment:**

***--Details--***

**Description:** Measuring, Medical and Controlling Devices Manufacturing
**SIC/NAICS Code:** 334512

**Description:** Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
**SIC/NAICS Code:** 417230

**Description:** All Other General-Purpose Machinery Manufacturing
**SIC/NAICS Code:** 333990

**Description:** All Other General-Purpose Machinery Manufacturing
**SIC/NAICS Code:** 333990

**Description:** Material Handling Equipment Manufacturing
**SIC/NAICS Code:** 333920

**Description:** All Other Industrial Machinery Manufacturing
**SIC/NAICS Code:** 333299

| | | | | | |
|---|---|---|---|---|---|
| 23 | 26 of 44 | NE/225.5 | 111.0 / -1.27 | **Ellsworth Corp**<br>**5109 Harvester Rd. #B3**<br>**Burlington ON L7L 5Y9** | GEN |

**Generator No:** ON3953922

***SIC Code:*** 418410
***SIC Description:*** Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
***Approval Years:*** 07,08
***PO Box No:***
***Country:***
***Status:***
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 231
***Waste Class Name:*** LATEX WASTES

***Waste Class:*** 232
***Waste Class Name:*** POLYMERIC RESINS

---

**23** | ***27 of 44*** | ***NE/225.5*** | ***111.0 / -1.27*** | ***Ellsworth Corp***
***5109 Harvester Rd. #B3***
***Burlington ON*** | ***GEN***

***Generator No:*** ON3953922
***SIC Code:*** 418410
***SIC Description:*** Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
***Approval Years:*** 2009
***PO Box No:***
***Country:***
***Status:***
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 231
***Waste Class Name:*** LATEX WASTES

***Waste Class:*** 232
***Waste Class Name:*** POLYMERIC RESINS

***Waste Class:*** 263
***Waste Class Name:*** ORGANIC LABORATORY CHEMICALS

***Waste Class:*** 331
***Waste Class Name:*** WASTE COMPRESSED GASES

---

**23** | ***28 of 44*** | ***NE/225.5*** | ***111.0 / -1.27*** | ***Ellsworth Corp***
***5109 Harvester Rd. #B3***
***Burlington ON*** | ***GEN***

***Generator No:*** ON3953922
***SIC Code:*** 418410
***SIC Description:*** Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
***Approval Years:*** 2010
***PO Box No:***
***Country:***
***Status:***
***Co Admin:***

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 232
***Waste Class Name:*** POLYMERIC RESINS

***Waste Class:*** 331
***Waste Class Name:*** WASTE COMPRESSED GASES

***Waste Class:*** 263
***Waste Class Name:*** ORGANIC LABORATORY CHEMICALS

***Waste Class:*** 231
***Waste Class Name:*** LATEX WASTES

---

**23** | ***29 of 44*** | ***NE/225.5*** | ***111.0 / -1.27*** | ***BAZCO PRECISION***
***5109 HARVESTER ROAD, UNIT 12***
***BURLINGTON ON L7L 5Y9*** | ***GEN***

***Generator No:*** ON2333901
***SIC Code:*** 332710
***SIC Description:***
***Approval Years:*** 2011
***PO Box No:***
***Country:***
***Status:***
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 253
***Waste Class Name:*** EMULSIFIED OILS

---

**23** | ***30 of 44*** | ***NE/225.5*** | ***111.0 / -1.27*** | ***Ellsworth Corp***
***5109 Harvester Rd. #B3***
***Burlington ON*** | ***GEN***

***Generator No:*** ON3953922
***SIC Code:*** 418410
***SIC Description:*** Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
***Approval Years:*** 2011
***PO Box No:***
***Country:***
***Status:***
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 232
***Waste Class Name:*** POLYMERIC RESINS

**Waste Class:** 263
**Waste Class Name:** ORGANIC LABORATORY CHEMICALS

**Waste Class:** 231
**Waste Class Name:** LATEX WASTES

**Waste Class:** 331
**Waste Class Name:** WASTE COMPRESSED GASES

---

**23** | **31 of 44** | **NE/225.5** | **111.0 / -1.27** | **BAZCO PRECISION**
**5109 HARVESTER ROAD, UNIT 12**
**BURLINGTON ON L7L 5Y9** | **GEN**

**Generator No:** ON2333901
**SIC Code:** 332710
**SIC Description:** Machine Shops
**Approval Years:** 2012
**PO Box No:**
**Country:**
**Status:**
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 253
**Waste Class Name:** EMULSIFIED OILS

---

**23** | **32 of 44** | **NE/225.5** | **111.0 / -1.27** | **BAZCO PRECISION**
**5109 HARVESTER ROAD, UNIT 12**
**BURLINGTON ON** | **GEN**

**Generator No:** ON2333901
**SIC Code:** 332710
**SIC Description:** MACHINE SHOPS
**Approval Years:** 2013
**PO Box No:**
**Country:**
**Status:**
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 253
**Waste Class Name:** EMULSIFIED OILS

---

**23** | **33 of 44** | **NE/225.5** | **111.0 / -1.27** | **BAZCO PRECISION**
**5109 HARVESTER ROAD, UNIT 12**
**BURLINGTON ON L7L 5Y9** | **GEN**

**Generator No:** ON2333901
**SIC Code:** 332710
**SIC Description:** MACHINE SHOPS
**Approval Years:** 2016

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

**PO Box No:**
**Country:** Canada
**Status:**
**Co Admin:** adam Ibbotson
**Choice of Contact:** CO_ADMIN
**Phone No Admin:** 905-333-6444 Ext.
**Contaminated Facility:** No
**MHSW Facility:** No

***Detail(s)***

**Waste Class:** 253
**Waste Class Name:** EMULSIFIED OILS

---

| | | | | | |
|---|---|---|---|---|---|
| 23 | 34 of 44 | NE/225.5 | 111.0 / -1.27 | **BAZCO PRECISION**<br>**5109 HARVESTER ROAD, UNIT 12**<br>**BURLINGTON ON L7L 5Y9** | GEN |

**Generator No:** ON2333901
**SIC Code:** 332710
**SIC Description:** MACHINE SHOPS
**Approval Years:** 2015
**PO Box No:**
**Country:** Canada
**Status:**
**Co Admin:** adam Ibbotson
**Choice of Contact:** CO_ADMIN
**Phone No Admin:** 905-333-6444 Ext.
**Contaminated Facility:** No
**MHSW Facility:** No

***Detail(s)***

**Waste Class:** 253
**Waste Class Name:** EMULSIFIED OILS

---

| | | | | | |
|---|---|---|---|---|---|
| 23 | 35 of 44 | NE/225.5 | 111.0 / -1.27 | **Copper wire stripper ltd**<br>**5109 Harvester rd A3**<br>**Burlington ON L7L 5Y4** | GEN |

**Generator No:** ON2868759
**SIC Code:** 417990
**SIC Description:** ALL OTHER MACHINERY, EQUIPMENT AND SUPPLIES WHOLESALER-DISTRIBUTORS
**Approval Years:** 2015
**PO Box No:**
**Country:** Canada
**Status:**
**Co Admin:**
**Choice of Contact:** CO_OFFICIAL
**Phone No Admin:**
**Contaminated Facility:** No
**MHSW Facility:** No

***Detail(s)***

**Waste Class:** 251
**Waste Class Name:** OIL SKIMMINGS & SLUDGES

---

| | | | | | |
|---|---|---|---|---|---|
| 23 | 36 of 44 | NE/225.5 | 111.0 / -1.27 | **BAZCO PRECISION**<br>**5109 HARVESTER ROAD, UNIT 12**<br>**BURLINGTON ON L7L 5Y9** | GEN |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Generator No:*** ON2333901
***SIC Code:*** 332710
***SIC Description:*** MACHINE SHOPS
***Approval Years:*** 2014
***PO Box No:***
***Country:*** Canada
***Status:***
***Co Admin:*** adam Ibbotson
***Choice of Contact:*** CO_ADMIN
***Phone No Admin:*** 905-333-6444 Ext.
***Contaminated Facility:*** No
***MHSW Facility:*** No

***Detail(s)***

***Waste Class:*** 253
***Waste Class Name:*** EMULSIFIED OILS

---

**23** | ***37 of 44*** | ***NE/225.5*** | ***111.0 / -1.27*** | ***Copper wire stripper ltd***
***5109 Harvester rd A3***
***Burlington ON L7L 5Y4*** | ***GEN***

***Generator No:*** ON2868759
***SIC Code:*** 417990
***SIC Description:*** ALL OTHER MACHINERY, EQUIPMENT AND SUPPLIES WHOLESALER-DISTRIBUTORS
***Approval Years:*** 2014
***PO Box No:***
***Country:*** Canada
***Status:***
***Co Admin:***
***Choice of Contact:*** CO_OFFICIAL
***Phone No Admin:***
***Contaminated Facility:*** No
***MHSW Facility:*** No

***Detail(s)***

***Waste Class:*** 251
***Waste Class Name:*** OIL SKIMMINGS & SLUDGES

---

**23** | ***38 of 44*** | ***NE/225.5*** | ***111.0 / -1.27*** | ***BAZCO PRECISION***
***5109 HARVESTER ROAD, UNIT 12***
***BURLINGTON ON L7L 5Y9*** | ***GEN***

***Generator No:*** ON2333901
***SIC Code:***
***SIC Description:***
***Approval Years:*** As of Dec 2018
***PO Box No:***
***Country:*** Canada
***Status:*** Registered
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 253 L
***Waste Class Name:*** Emulsified oils

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 23 | 39 of 44 | NE/225.5 | 111.0 / -1.27 | Hisco Can Inc<br>5109 Harvester Rd<br>Burlington ON L7L 5Y9 | GEN |

**Generator No:** ON6722964
**SIC Code:**
**SIC Description:**
**Approval Years:** As of Dec 2017
**PO Box No:**
**Country:** Canada
**Status:** Registered
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 212 I
**Waste Class Name:** Aliphatic solvents and residues

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 23 | 40 of 44 | NE/225.5 | 111.0 / -1.27 | Brierly Technolgies, Inc.<br>5109 Harvester Rd. B8<br>Burlington ON L7L5Y4 | GEN |

**Generator No:** ON5823173
**SIC Code:**
**SIC Description:**
**Approval Years:** As of Dec 2018
**PO Box No:**
**Country:** Canada
**Status:** Registered
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 146 L
**Waste Class Name:** Other specified inorganic sludges, slurries or solids

**Waste Class:** 150 L
**Waste Class Name:** Inert organic wastes

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 23 | 41 of 44 | NE/225.5 | 111.0 / -1.27 | BAZCO PRECISION<br>5109 HARVESTER ROAD, UNIT 12<br>BURLINGTON ON L7L 5Y9 | GEN |

**Generator No:** ON2333901
**SIC Code:**
**SIC Description:**
**Approval Years:** As of Jul 2020
**PO Box No:**
**Country:** Canada
**Status:** Registered
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| ***Contaminated Facility:*** | | | | | |
| ***MHSW Facility:*** | | | | | |

***Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 253 L |
| ***Waste Class Name:*** | Emulsified oils |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 23 | 42 of 44 | NE/225.5 | 111.0 / -1.27 | ***Bellamia kitchen & Bath Design Inc. Bellamia kitchen & Bath Design Inc.***<br>***1-5109A Harvester Road***<br>***Burlington ON L7L5Y9*** | GEN |

| | |
|---|---|
| ***Generator No:*** | ON9879989 |
| ***SIC Code:*** | |
| ***SIC Description:*** | |
| ***Approval Years:*** | As of Jan 2021 |
| ***PO Box No:*** | |
| ***Country:*** | Canada |
| ***Status:*** | Registered |
| ***Co Admin:*** | |
| ***Choice of Contact:*** | |
| ***Phone No Admin:*** | |
| ***Contaminated Facility:*** | |
| ***MHSW Facility:*** | |

***Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 145 L |
| ***Waste Class Name:*** | Wastes from the use of pigments, coatings and paints |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 23 | 43 of 44 | NE/225.5 | 111.0 / -1.27 | ***BAZCO PRECISION***<br>***5109 HARVESTER ROAD, UNIT 12***<br>***BURLINGTON ON L7L 5Y9*** | GEN |

| | |
|---|---|
| ***Generator No:*** | ON2333901 |
| ***SIC Code:*** | |
| ***SIC Description:*** | |
| ***Approval Years:*** | As of Nov 2021 |
| ***PO Box No:*** | |
| ***Country:*** | Canada |
| ***Status:*** | Registered |
| ***Co Admin:*** | |
| ***Choice of Contact:*** | |
| ***Phone No Admin:*** | |
| ***Contaminated Facility:*** | |
| ***MHSW Facility:*** | |

***Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 253 L |
| ***Waste Class Name:*** | Emulsified oils |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 23 | 44 of 44 | NE/225.5 | 111.0 / -1.27 | ***BAZCO PRECISION***<br>***5109 HARVESTER ROAD, UNIT 12***<br>***BURLINGTON ON L7L 5Y9*** | GEN |

| | |
|---|---|
| ***Generator No:*** | ON2333901 |
| ***SIC Code:*** | |
| ***SIC Description:*** | |
| ***Approval Years:*** | As of Oct 2022 |

***PO Box No:***
***Country:*** Canada
***Status:*** Registered
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 253 L
***Waste Class Name:*** EMULSIFIED OILS

---

**24** | ***1 of 1*** | ***SSW/227.0*** | ***109.9 / -2.39*** | ***870 Appleby Line, Burlington ON L7L2Y8*** | ***EHS***

***Order No:*** 20170502003
***Status:*** C
***Report Type:*** Standard Report
***Report Date:*** 08-MAY-17
***Date Received:*** 02-MAY-17
***Previous Site Name:***
***Lot/Building Size:***
***Additional Info Ordered:*** Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos
***Nearest Intersection:***
***Municipality:***
***Client Prov/State:*** ON
***Search Radius (km):*** .25
***X:*** -79.768603
***Y:*** 43.377277

---

**25** | ***1 of 6*** | ***N/227.0*** | ***115.9 / 3.60*** | ***Tecoustics Limited, 5036 South Service Rd, Burlington ON L7L 5Y7*** | ***SCT***

***Established:*** 01-SEP-90
***Plant Size (ft²):*** 3000
***Employment:***

***--Details--***
***Description:*** Wholesale Trade Agents and Brokers
***SIC/NAICS Code:*** 419120

***Description:*** Wholesale Trade Agents and Brokers
***SIC/NAICS Code:*** 419120

---

**25** | ***2 of 6*** | ***N/227.0*** | ***115.9 / 3.60*** | ***ALS Canada Limited, 5036 South Service Road, Burlington ON L7L 5Y7*** | ***GEN***

***Generator No:*** ON7886459
***SIC Code:***
***SIC Description:***
***Approval Years:*** As of Dec 2018
***PO Box No:***
***Country:*** Canada
***Status:*** Registered
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

**Waste Class:** 113 C
**Waste Class Name:** Acid solutions - containing other metals and non-metals

**Waste Class:** 212 L
**Waste Class Name:** Aliphatic solvents and residues

**Waste Class:** 221 I
**Waste Class Name:** Light fuels

**Waste Class:** 241 H
**Waste Class Name:** Halogenated solvents and residues

**Waste Class:** 252 L
**Waste Class Name:** Waste crankcase oils and lubricants

**Waste Class:** 252 T
**Waste Class Name:** Waste crankcase oils and lubricants

---

25 | 3 of 6 | N/227.0 | 115.9 / 3.60 | **ALS CANADA LTD.**
**5036 Service RD S**
**Burlington ON L7L 5Y7** | EASR

**Approval No:** R-010-7111151666
**Status:** REGISTERED
**Date:** 2019-03-29
**Record Type:** EASR
**Link Source:** MOFA
**Project Type:** Air Emissions
**Full Address:**
**Approval Type:** EASR-Air Emissions
**SWP Area Name:** Halton
**PDF URL:**
**PDF Site Location:**

**MOE District:** Halton-Peel
**Municipality:** Burlington
**Latitude:** 43.38111111
**Longitude:** -79.76722222
**Geometry X:**
**Geometry Y:**

---

25 | 4 of 6 | N/227.0 | 115.9 / 3.60 | **ALS Canada Limited**
**5036 South Service Road**
**Burlington ON L7L 5Y7** | GEN

**Generator No:** ON7886459
**SIC Code:**
**SIC Description:**
**Approval Years:** As of Jul 2020
**PO Box No:**
**Country:** Canada
**Status:** Registered
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 241 H
**Waste Class Name:** Halogenated solvents and residues

**Waste Class:** 252 T
**Waste Class Name:** Waste crankcase oils and lubricants

**Waste Class:** 212 H
**Waste Class Name:** Aliphatic solvents and residues

**Waste Class:** 212 L
**Waste Class Name:** Aliphatic solvents and residues

**Waste Class:** 221 I
**Waste Class Name:** Light fuels

**Waste Class:** 113 C
**Waste Class Name:** Acid solutions - containing other metals and non-metals

**Waste Class:** 252 L
**Waste Class Name:** Waste crankcase oils and lubricants

---

**25** | **5 of 6** | **N/227.0** | **115.9 / 3.60** | **ALS Canada Limited**
**5036 South Service Road**
**Burlington ON L7L 5Y7** | **GEN**

**Generator No:** ON7886459
**SIC Code:**
**SIC Description:**
**Approval Years:** As of Nov 2021
**PO Box No:**
**Country:** Canada
**Status:** Registered
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 241 H
**Waste Class Name:** Halogenated solvents and residues

**Waste Class:** 212 L
**Waste Class Name:** Aliphatic solvents and residues

**Waste Class:** 113 C
**Waste Class Name:** Acid solutions - containing other metals and non-metals

**Waste Class:** 212 H
**Waste Class Name:** Aliphatic solvents and residues

**Waste Class:** 252 L
**Waste Class Name:** Waste crankcase oils and lubricants

**Waste Class:** 221 I
**Waste Class Name:** Light fuels

**Waste Class:** 252 T
**Waste Class Name:** Waste crankcase oils and lubricants

---

**25** | **6 of 6** | **N/227.0** | **115.9 / 3.60** | **ALS Canada Limited**
**5036 South Service Road**
**Burlington ON L7L 5Y7** | **GEN**

**Generator No:** ON7886459
**SIC Code:**
**SIC Description:**
**Approval Years:** As of Oct 2022
**PO Box No:**
**Country:** Canada

**Status:** Registered
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 221 I
**Waste Class Name:** LIGHT FUELS

**Waste Class:** 212 L
**Waste Class Name:** ALIPHATIC SOLVENTS

**Waste Class:** 252 L
**Waste Class Name:** WASTE OILS & LUBRICANTS

**Waste Class:** 148 L
**Waste Class Name:** INORGANIC LABORATORY CHEMICALS

**Waste Class:** 252 T
**Waste Class Name:** WASTE OILS & LUBRICANTS

**Waste Class:** 241 H
**Waste Class Name:** HALOGENATED SOLVENTS

**Waste Class:** 212 H
**Waste Class Name:** ALIPHATIC SOLVENTS

**Waste Class:** 112 C
**Waste Class Name:** ACID WASTE - HEAVY METALS

**Waste Class:** 113 C
**Waste Class Name:** ACID WASTE - OTHER METALS

---

**26** | **1 of 1** | **NW/231.8** | **114.8 / 2.59** | **5035-5045 South Service Road Burlington ON L7L 5Y7** | **EHS**

**Order No:** 20060508003
**Status:** C
**Report Type:** Custom Report
**Report Date:** 5/16/2006
**Date Received:** 5/8/2006
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:**

**Nearest Intersection:**
**Municipality:** Halton
**Client Prov/State:** ON
**Search Radius (km):** 0.25
**X:** -79.76937
**Y:** 43.380586

---

**27** | **1 of 4** | **NNE/246.2** | **114.3 / 2.09** | **5018 South Service Rd Burlington ON L7L 5Y7** | **EHS**

**Order No:** 19991202002
**Status:** C
**Report Type:** Site Report
**Report Date:** 12/3/99
**Date Received:** 12/3/99
**Previous Site Name:**
**Lot/Building Size:** 500 sq meters
**Additional Info Ordered:**

**Nearest Intersection:** Appleby Line / Harvester Rd
**Municipality:** Halton
**Client Prov/State:** ON
**Search Radius (km):** 0.25
**X:** -79.767261
**Y:** 43.38027

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 27 | 2 of 4 | NNE/246.2 | 114.3 / 2.09 | Garry Construction & Restoration<br>5018 South Service Road<br>Burlington ON L7L5Y7 | GEN |

**Generator No:** ON5986257
**SIC Code:** 236110
**SIC Description:** RESIDENTIAL BUILDING CONSTRUCTION
**Approval Years:** 2015
**PO Box No:**
**Country:** Canada
**Status:**
**Co Admin:** Kim Willson
**Choice of Contact:** CO_OFFICIAL
**Phone No Admin:** 906816100 Ext.
**Contaminated Facility:** No
**MHSW Facility:** No

***Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 27 | 3 of 4 | NNE/246.2 | 114.3 / 2.09 | Garry Construction & Restoration Ltd.<br>5018 South Service Road<br>Burlington ON L7L 5Y7 | GEN |

**Generator No:** ON3410597
**SIC Code:** 238350
**SIC Description:** FINISH CARPENTRY CONTRACTORS
**Approval Years:** 2015
**PO Box No:**
**Country:** Canada
**Status:**
**Co Admin:**
**Choice of Contact:** CO_OFFICIAL
**Phone No Admin:**
**Contaminated Facility:** No
**MHSW Facility:** No

***Detail(s)***

**Waste Class:** 331
**Waste Class Name:** WASTE COMPRESSED GASES

**Waste Class:** 148
**Waste Class Name:** INORGANIC LABORATORY CHEMICALS

**Waste Class:** 262
**Waste Class Name:** DETERGENTS/SOAPS

**Waste Class:** 263
**Waste Class Name:** ORGANIC LABORATORY CHEMICALS

**Waste Class:** 145
**Waste Class Name:** PAINT/PIGMENT/COATING RESIDUES

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 27 | 4 of 4 | NNE/246.2 | 114.3 / 2.09 | Garry Construction & Restoration<br>5018 South Service Road<br>Burlington ON L7L5Y7 | GEN |

**Generator No:** ON5986257
**SIC Code:** 236110
**SIC Description:** RESIDENTIAL BUILDING CONSTRUCTION

**Approval Years:** 2016
**PO Box No:**
**Country:** Canada
**Status:**
**Co Admin:** Kim Willson
**Choice of Contact:** CO_OFFICIAL
**Phone No Admin:** 906816100 Ext.
**Contaminated Facility:** No
**MHSW Facility:** No

***Detail(s)***

**Waste Class:** 312
**Waste Class Name:** PATHOLOGICAL WASTES

---

**28** | ***1 of 1*** | ***E/246.9*** | ***105.8 / -6.48*** | ***ON*** | ***WWIS***

**Well ID:** 7308706
**Construction Date:**
**Use 1st:**
**Use 2nd:**
**Final Well Status:**
**Water Type:**
**Casing Material:**
**Audit No:** C37774
**Tag:** A225530
**Constructn Method:**
**Elevation (m):**
**Elevatn Reliabilty:**
**Depth to Bedrock:**
**Well Depth:**
**Overburden/Bedrock:**
**Pump Rate:**
**Static Water Level:**
**Clear/Cloudy:**
**Municipality:** BURLINGTON CITY
**Site Info:**

**Flowing (Y/N):**
**Flow Rate:**
**Data Entry Status:** Yes
**Data Src:**
**Date Received:** 03/29/2018
**Selected Flag:** TRUE
**Abandonment Rec:**
**Contractor:** 6988
**Form Version:** 8
**Owner:**
**County:** HALTON
**Lot:**
**Concession:**
**Concession Name:**
**Easting NAD83:**
**Northing NAD83:**
**Zone:**
**UTM Reliability:**

**PDF URL (Map):**

***Additional Detail(s) (Map)***

**Well Completed Date:** 05/19/2017
**Year Completed:** 2017
**Depth (m):**
**Latitude:** 43.3787137751635
**Longitude:** -79.7644176823111
**Path:**

***Bore Hole Information***

**Bore Hole ID:** 1007009828
**DP2BR:**
**Spatial Status:**
**Code OB:**
**Code OB Desc:**
**Open Hole:**
**Cluster Kind:**
**Date Completed:** 05/19/2017
**Remarks:**
**Loc Method Desc:** on Water Well Record

**Elevation:**
**Elevrc:**
**Zone:** 17
**East83:** 600090.00
**North83:** 4803613.00
**Org CS:** UTM83
**UTMRC:** 4
**UTMRC Desc:** margin of error : 30 m - 100 m
**Location Method:** wwr

***Elevrc Desc:***
***Location Source Date:***
***Improvement Location Source:***
***Improvement Location Method:***
***Source Revision Comment:***
***Supplier Comment:***

***Links***

| | | | |
|---|---|---|---|
| ***Bore Hole ID:*** | 1007009828 | ***Tag No:*** | A225530 |
| ***Depth M:*** | | ***Contractor:*** | 6988 |
| ***Year Completed:*** | 2017 | ***Latitude:*** | 43.3787137751635 |
| ***Well Completed Dt:*** | 05/19/2017 | ***Longitude:*** | -79.7644176823111 |
| ***Audit No:*** | C37774 | ***Y:*** | 43.37871377232883 |
| ***Path:*** | | ***X:*** | -79.76441753285394 |

---

**29** ***1 of 15*** ***E/247.4*** ***106.8 / -5.41*** ***INDUSTRIAL TASK FORCE***
***5100 HARVESTER ROAD***
***BURLINGTON ON L7L 4X4*** ***GEN***

| | |
|---|---|
| ***Generator No:*** | ON1099400 |
| ***SIC Code:*** | 0000 |
| ***SIC Description:*** | *** NOT DEFINED *** |
| ***Approval Years:*** | 88,89,90 |
| ***PO Box No:*** | |
| ***Country:*** | |
| ***Status:*** | |
| ***Co Admin:*** | |
| ***Choice of Contact:*** | |
| ***Phone No Admin:*** | |
| ***Contaminated Facility:*** | |
| ***MHSW Facility:*** | |

***Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 213 |
| ***Waste Class Name:*** | PETROLEUM DISTILLATES |
| ***Waste Class:*** | 252 |
| ***Waste Class Name:*** | WASTE OILS & LUBRICANTS |

---

**29** ***2 of 15*** ***E/247.4*** ***106.8 / -5.41*** ***INDUSTRIAL TASK FORCE 21-372***
***5100 HARVESTER ROAD***
***BURLINGTON ON L7L 4X4*** ***GEN***

| | |
|---|---|
| ***Generator No:*** | ON1099400 |
| ***SIC Code:*** | 2561 |
| ***SIC Description:*** | WOODEN BOX & PALLET |
| ***Approval Years:*** | 92,93,94,95,96,97,98 |
| ***PO Box No:*** | |
| ***Country:*** | |
| ***Status:*** | |
| ***Co Admin:*** | |
| ***Choice of Contact:*** | |
| ***Phone No Admin:*** | |
| ***Contaminated Facility:*** | |
| ***MHSW Facility:*** | |

***Detail(s)***

| | |
|---|---|
| ***Waste Class:*** | 213 |
| ***Waste Class Name:*** | PETROLEUM DISTILLATES |

**Waste Class:** 252
**Waste Class Name:** WASTE OILS & LUBRICANTS

---

**29** **3 of 15** **E/247.4** **106.8 / -5.41** **Choice Reefers Systems Limited** **SPL**
**5100 HARVESTER RD.<UNOFFICIAL>**
**Burlington ON L7L 4X4**

**Ref No:** 3206-63SLP3
**Site No:**
**Incident Dt:** 8/12/2004
**Year:**
**Incident Cause:** Pipe Or Hose Leak
**Incident Event:**
**Environment Impact:** Possible
**Nature of Impact:** Soil Contamination
**MOE Response:**
**Dt MOE Arvl on Scn:**
**MOE Reported Dt:** 8/12/2004
**Dt Document Closed:**
**Municipality No:**
**System Facility Address:**
**Client Type:**
**Call Report Location Geodata:**
**Contaminant Code:** 13
**Contaminant Name:** DIESEL FUEL
**Contaminant Limit 1:**
**Contam Limit Freq 1:**
**Contaminant UN No 1:**
**Receiving Medium:** Land
**Receiving Environment:**
**Incident Reason:** Equipment Failure
**Incident Summary:** Choice Reefer Sys,30 L DSL to pvmt,Maple Leaf clng
**Site Region:** Central
**Site Municipality:** Burlington
**Activity Preceding Spill:**
**Property 2nd Watershed:**
**Property Tertiary Watershed:**
**Sector Type:** Other
**SAC Action Class:** Spill to Land
**Source Type:**
**Site County/District:**
**Site Geo Ref Meth:**
**Site District Office:** Halton-Peel
**Nearest Watercourse:**
**Site Name:** 5100 HARVESTER RD.<UNOFFICIAL>
**Site Address:**
**Client Name:** Choice Reefers Systems Limited

**Contaminant Qty:** 30 L
**Nature of Damage:**
**Discharger Report:**
**Material Group:** Oil
**Health/Env Conseq:**
**Agency Involved:**
**Site Lot:**
**Site Conc:**
**Site Geo Ref Accu:**
**Site Map Datum:**
**Northing:**
**Easting:**

---

**29** **4 of 15** **E/247.4** **106.8 / -5.41** **5100 Harvester Road** **EHS**
**Burlington ON L7L 4X4**

**Order No:** 20081106020
**Status:** C
**Report Type:** Standard Report
**Report Date:** 11/12/2008
**Date Received:** 11/6/2008
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:**

**Nearest Intersection:** Harvester Road & Appleby Line
**Municipality:** Burlington
**Client Prov/State:** ON
**Search Radius (km):** 0.25
**X:** -79.764157
**Y:** 43.379115

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 29 | 5 of 15 | E/247.4 | 106.8 / -5.41 | 5100 Harvestor Rd<br>Burlington ON L7L 4X4 | SPL |

| | | | |
|---|---|---|---|
| **Ref No:** | 7138-8EYKWY | **Contaminant Qty:** | 80 L |
| **Site No:** | | **Nature of Damage:** | |
| **Incident Dt:** | 3/15/2011 | **Discharger Report:** | |
| **Year:** | | **Material Group:** | |
| **Incident Cause:** | Pipe Or Hose Leak | **Health/Env Conseq:** | |
| **Incident Event:** | | **Agency Involved:** | |
| **Environment Impact:** | Confirmed | **Site Lot:** | |
| **Nature of Impact:** | Soil Contamination | **Site Conc:** | |
| **MOE Response:** | No Field Response | **Site Geo Ref Accu:** | |
| **Dt MOE Arvl on Scn:** | | **Site Map Datum:** | |
| **MOE Reported Dt:** | 3/15/2011 | **Northing:** | |
| **Dt Document Closed:** | 3/22/2011 | **Easting:** | |
| **Municipality No:** | | | |
| **System Facility Address:** | | | |
| **Client Type:** | | | |
| **Call Report Location Geodata:** | | | |
| **Contaminant Code:** | 13 | | |
| **Contaminant Name:** | DIESEL FUEL | | |
| **Contaminant Limit 1:** | | | |
| **Contam Limit Freq 1:** | | | |
| **Contaminant UN No 1:** | | | |
| **Receiving Medium:** | | | |
| **Receiving Environment:** | | | |
| **Incident Reason:** | Equipment/Vehicles | | |
| **Incident Summary:** | Maple Leaf Foods: diesel fuel 70-80 Litres to pavement | | |
| **Site Region:** | | | |
| **Site Municipality:** | Burlington | | |
| **Activity Preceding Spill:** | | | |
| **Property 2nd Watershed:** | | | |
| **Property Tertiary Watershed:** | | | |
| **Sector Type:** | Transport Truck | | |
| **SAC Action Class:** | Land Spills | | |
| **Source Type:** | | | |
| **Site County/District:** | | | |
| **Site Geo Ref Meth:** | | | |
| **Site District Office:** | | | |
| **Nearest Watercourse:** | | | |
| **Site Name:** | Maple Leaf Foods, Ontario Distribution Centre<UNOFFICIAL> | | |
| **Site Address:** | 5100 Harvestor Rd | | |
| **Client Name:** | | | |

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 29 | 6 of 15 | E/247.4 | 106.8 / -5.41 | Maple Leaf Foods Inc.<br>5100 Harvester Road<br>Burlington ON | SPL |

| | | | |
|---|---|---|---|
| **Ref No:** | 1617-8XZ7JY | **Contaminant Qty:** | 400 L |
| **Site No:** | | **Nature of Damage:** | |
| **Incident Dt:** | 09-SEP-12 | **Discharger Report:** | |
| **Year:** | | **Material Group:** | |
| **Incident Cause:** | Leak/Break | **Health/Env Conseq:** | |
| **Incident Event:** | | **Agency Involved:** | |
| **Environment Impact:** | Confirmed | **Site Lot:** | |
| **Nature of Impact:** | Other Impact(s) | **Site Conc:** | |
| **MOE Response:** | No Field Response | **Site Geo Ref Accu:** | |
| **Dt MOE Arvl on Scn:** | | **Site Map Datum:** | |
| **MOE Reported Dt:** | 10-SEP-12 | **Northing:** | |
| **Dt Document Closed:** | 24-DEC-12 | **Easting:** | |
| **Municipality No:** | | | |
| **System Facility Address:** | | | |
| **Client Type:** | | | |
| **Call Report Location Geodata:** | | | |

| | |
|---|---|
| **Contaminant Code:** | 13 |
| **Contaminant Name:** | DIESEL FUEL |
| **Contaminant Limit 1:** | |
| **Contam Limit Freq 1:** | |
| **Contaminant UN No 1:** | |
| **Receiving Medium:** | |
| **Receiving Environment:** | |
| **Incident Reason:** | Equipment Failure |
| **Incident Summary:** | Maple Leaf Foods: 400L Diesel from Refer to PL, cln |
| **Site Region:** | |
| **Site Municipality:** | Burlington |
| **Activity Preceding Spill:** | |
| **Property 2nd Watershed:** | |
| **Property Tertiary Watershed:** | |
| **Sector Type:** | Truck - Transport/Hauling |
| **SAC Action Class:** | Land Spills |
| **Source Type:** | |
| **Site County/District:** | |
| **Site Geo Ref Meth:** | |
| **Site District Office:** | |
| **Nearest Watercourse:** | |
| **Site Name:** | Maple Leaf Foods<UNOFFICIAL> |
| **Site Address:** | 5100 Harvester Road |
| **Client Name:** | Maple Leaf Foods Inc. |

| | | | | | |
|---|---|---|---|---|---|
| **29** | ***7 of 15*** | ***E/247.4*** | ***106.8 / -5.41*** | ***Maple Leaf Foods Inc.***<br>***5100 Harvester Road***<br>***Burlington ON*** | ***GEN*** |

| | |
|---|---|
| **Generator No:** | ON4828489 |
| **SIC Code:** | 493120 |
| **SIC Description:** | REFRIGERATED WAREHOUSING AND STORAGE |
| **Approval Years:** | 2013 |
| **PO Box No:** | |
| **Country:** | |
| **Status:** | |
| **Co Admin:** | |
| **Choice of Contact:** | |
| **Phone No Admin:** | |
| **Contaminated Facility:** | |
| **MHSW Facility:** | |

***Detail(s)***

| | |
|---|---|
| **Waste Class:** | 232 |
| **Waste Class Name:** | POLYMERIC RESINS |
| **Waste Class:** | 148 |
| **Waste Class Name:** | INORGANIC LABORATORY CHEMICALS |
| **Waste Class:** | 135 |
| **Waste Class Name:** | REACTIVE ANION WASTES |
| **Waste Class:** | 241 |
| **Waste Class Name:** | HALOGENATED SOLVENTS |
| **Waste Class:** | 267 |
| **Waste Class Name:** | ORGANIC ACIDS |
| **Waste Class:** | 114 |
| **Waste Class Name:** | OTHER INORGANIC ACID WASTES |
| **Waste Class:** | 252 |

**Waste Class Name:** WASTE OILS & LUBRICANTS

**Waste Class:** 251
**Waste Class Name:** OIL SKIMMINGS & SLUDGES

**Waste Class:** 262
**Waste Class Name:** DETERGENTS/SOAPS

**Waste Class:** 212
**Waste Class Name:** ALIPHATIC SOLVENTS

**Waste Class:** 123
**Waste Class Name:** ALKALINE PHOSPHATES

**Waste Class:** 145
**Waste Class Name:** PAINT/PIGMENT/COATING RESIDUES

**Waste Class:** 263
**Waste Class Name:** ORGANIC LABORATORY CHEMICALS

**Waste Class:** 331
**Waste Class Name:** WASTE COMPRESSED GASES

---

| 29 | 8 of 15 | E/247.4 | 106.8 / -5.41 | **Maple Leaf Foods Inc.**<br>**5100 Harvester Road**<br>**Burlington ON L7L 4X4** | GEN |
|---|---|---|---|---|---|

**Generator No:** ON4828489
**SIC Code:** 493120
**SIC Description:** REFRIGERATED WAREHOUSING AND STORAGE
**Approval Years:** 2015
**PO Box No:**
**Country:** Canada
**Status:**
**Co Admin:** Patrick Huynh
**Choice of Contact:** CO_OFFICIAL
**Phone No Admin:** 9052855721 Ext.
**Contaminated Facility:** No
**MHSW Facility:** No

***Detail(s)***

**Waste Class:** 251
**Waste Class Name:** OIL SKIMMINGS & SLUDGES

**Waste Class:** 123
**Waste Class Name:** ALKALINE PHOSPHATES

**Waste Class:** 232
**Waste Class Name:** POLYMERIC RESINS

**Waste Class:** 241
**Waste Class Name:** HALOGENATED SOLVENTS

**Waste Class:** 262
**Waste Class Name:** DETERGENTS/SOAPS

**Waste Class:** 145
**Waste Class Name:** PAINT/PIGMENT/COATING RESIDUES

**Waste Class:** 148
**Waste Class Name:** INORGANIC LABORATORY CHEMICALS

**Waste Class:** 331

**Waste Class Name:** WASTE COMPRESSED GASES

**Waste Class:** 252
**Waste Class Name:** WASTE OILS & LUBRICANTS

**Waste Class:** 263
**Waste Class Name:** ORGANIC LABORATORY CHEMICALS

**Waste Class:** 114
**Waste Class Name:** OTHER INORGANIC ACID WASTES

**Waste Class:** 135
**Waste Class Name:** REACTIVE ANION WASTES

**Waste Class:** 212
**Waste Class Name:** ALIPHATIC SOLVENTS

**Waste Class:** 267
**Waste Class Name:** ORGANIC ACIDS

---

| | | | | | |
|---|---|---|---|---|---|
| 29 | 9 of 15 | E/247.4 | 106.8 / -5.41 | **Maple Leaf Foods Inc.**<br>**5100 Harvester Road**<br>**Burlington ON L7L 4X4** | GEN |

**Generator No:** ON4828489
**SIC Code:** 493120
**SIC Description:** REFRIGERATED WAREHOUSING AND STORAGE
**Approval Years:** 2014
**PO Box No:**
**Country:** Canada
**Status:**
**Co Admin:** Patrick Huynh
**Choice of Contact:** CO_OFFICIAL
**Phone No Admin:** 9052855721 Ext.
**Contaminated Facility:** No
**MHSW Facility:** No

***Detail(s)***

**Waste Class:** 252
**Waste Class Name:** WASTE OILS & LUBRICANTS

**Waste Class:** 331
**Waste Class Name:** WASTE COMPRESSED GASES

**Waste Class:** 212
**Waste Class Name:** ALIPHATIC SOLVENTS

**Waste Class:** 123
**Waste Class Name:** ALKALINE PHOSPHATES

**Waste Class:** 148
**Waste Class Name:** INORGANIC LABORATORY CHEMICALS

**Waste Class:** 251
**Waste Class Name:** OIL SKIMMINGS & SLUDGES

**Waste Class:** 135
**Waste Class Name:** REACTIVE ANION WASTES

**Waste Class:** 241
**Waste Class Name:** HALOGENATED SOLVENTS

**Waste Class:** 262

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|

***Waste Class Name:*** DETERGENTS/SOAPS

***Waste Class:*** 114
***Waste Class Name:*** OTHER INORGANIC ACID WASTES

***Waste Class:*** 145
***Waste Class Name:*** PAINT/PIGMENT/COATING RESIDUES

***Waste Class:*** 263
***Waste Class Name:*** ORGANIC LABORATORY CHEMICALS

***Waste Class:*** 267
***Waste Class Name:*** ORGANIC ACIDS

***Waste Class:*** 232
***Waste Class Name:*** POLYMERIC RESINS

---

| | | | | | |
|---|---|---|---|---|---|
| **29** | ***10 of 15*** | ***E/247.4*** | ***106.8 / -5.41*** | ***Approved Cold Storage Inc.***<br>***5100 Harvester Road***<br>***Burlington ON L7L4X4*** | ***GEN*** |

***Generator No:*** ON7121903
***SIC Code:***
***SIC Description:***
***Approval Years:*** As of Dec 2018
***PO Box No:***
***Country:*** Canada
***Status:*** Registered
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 252 L
***Waste Class Name:*** Waste crankcase oils and lubricants

---

| | | | | | |
|---|---|---|---|---|---|
| **29** | ***11 of 15*** | ***E/247.4*** | ***106.8 / -5.41*** | ***Approved Cold Storage Inc.***<br>***5100 Harvester Road***<br>***Burlington ON L7L4X4*** | ***GEN*** |

***Generator No:*** ON7121903
***SIC Code:***
***SIC Description:***
***Approval Years:*** As of Jul 2020
***PO Box No:***
***Country:*** Canada
***Status:*** Registered
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 252 L
***Waste Class Name:*** Waste crankcase oils and lubricants

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 29 | 12 of 15 | E/247.4 | 106.8 / -5.41 | Approved Cold Storage Inc.<br>5100 Harvester Road<br>Burlington ON L7L4X4 | GEN |

**Generator No:** ON7121903
**SIC Code:**
**SIC Description:**
**Approval Years:** As of Nov 2021
**PO Box No:**
**Country:** Canada
**Status:** Registered
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 263 L
**Waste Class Name:** Misc. waste organic chemicals

**Waste Class:** 252 L
**Waste Class Name:** Waste crankcase oils and lubricants

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 29 | 13 of 15 | E/247.4 | 106.8 / -5.41 | Approved Cold Storage Inc.<br>5100 Harvester Road<br>Burlington ON L7L4X4 | GEN |

**Generator No:** ON7121903
**SIC Code:**
**SIC Description:**
**Approval Years:** As of Oct 2022
**PO Box No:**
**Country:** Canada
**Status:** Registered
**Co Admin:**
**Choice of Contact:**
**Phone No Admin:**
**Contaminated Facility:**
**MHSW Facility:**

***Detail(s)***

**Waste Class:** 263 L
**Waste Class Name:** ORGANIC LABORATORY CHEMICALS

**Waste Class:** 252 L
**Waste Class Name:** WASTE OILS & LUBRICANTS

---

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 29 | 14 of 15 | E/247.4 | 106.8 / -5.41 | 5100 Harvester Road<br>Burlington ON L7L 4X4 | EHS |

**Order No:** 22060100021
**Status:** C
**Report Type:** Standard Report
**Report Date:** 06-JUN-22
**Date Received:** 01-JUN-22
**Previous Site Name:**
**Lot/Building Size:**
**Additional Info Ordered:** Fire Insur. Maps and/or Site Plans

**Nearest Intersection:**
**Municipality:**
**Client Prov/State:** ON
**Search Radius (km):** .25
**X:** -79.7643586
**Y:** 43.3791437

| Map Key | Number of Records | Direction/ Distance (m) | Elev/Diff (m) | Site | DB |
|---|---|---|---|---|---|
| 29 | 15 of 15 | E/247.4 | 106.8 / -5.41 | 5100 Harvester Road<br>Burlington ON L7L 4X4 | EHS |

| | | | |
|---|---|---|---|
| **Order No:** | 22060100021 | **Nearest Intersection:** | |
| **Status:** | C | **Municipality:** | |
| **Report Type:** | Standard Report | **Client Prov/State:** | ON |
| **Report Date:** | 06-JUN-22 | **Search Radius (km):** | .25 |
| **Date Received:** | 01-JUN-22 | **X:** | -79.7643586 |
| **Previous Site Name:** | | **Y:** | 43.3791437 |
| **Lot/Building Size:** | | | |
| **Additional Info Ordered:** | Fire Insur. Maps and/or Site Plans | | |

# Unplottable Summary

**Total: 65 Unplottable sites**

| DB | Company Name/Site Name | Address | City | Postal |
|---|---|---|---|---|
| CA | MONARCH CONSTRUCTION LIMITED | RING RD/APPLEBY LINE | BURLINGTON CITY ON | |
| CA | R.M. OF HALTON APPLEBY LINE | APPLEBY LINE | BURLINGTON CITY ON | |
| CA | MYTRAX DEVELOPMENTS INC. | S. SERVICE RD. PRIV. IND. DEV. | BURLINGTON CITY ON | |
| CA | T.C.A. LEASING-PT. LOT 11, CONC. 3 SDS | VINCENT CT./HARVESTER RD. | BURLINGTON CITY ON | |
| CA | BERL-TON INVESTMENTS LIMITED | HARVESTER RD. | BURLINGTON CITY ON | |
| CA | BOYD POLLOCK | HARVESTER RD. | BURLINGTON CITY ON | |
| CA | LAKELAND DEVELOPMENT CORPORATION | HARVESTER ROAD | BURLINGTON CITY ON | |
| CA | LAKELAND DEVELOPMENT CORPORATION | HARVESTER ROAD PRIVATE | BURLINGTON CITY ON | |
| CA | R.M. OF HALTON | PALETTA COURT | BURLINGTON CITY ON | |
| CA | CICERELLA INVEST. LTD.-PT. LOT 9/CONC. 3 | HARVESTER RD./CNR OAKVILLE SUB | BURLINGTON CITY ON | |
| CA | PUDGEWAL DEVELOPMENT CORP. - PLAN #M-192 | HARVESTER ROAD | BURLINGTON CITY ON | |
| CA | CICERELLA INVEST. LTD.-PT. LOT 9/CONC.3 | HARVESTER RD./CNR OAKVILLE SUB | BURLINGTON CITY ON | |
| CA | D. GREENFIELD ASSOC. LTD. | EASEMENT APPLEBY LINE | BURLINGTON CITY ON | |
| CA | BOYD POLLOCK | HARVESTER RD. | BURLINGTON CITY ON | |
| CA | R.M. OF HALTON APPLEBY LINE | APPLEBY LINE | BURLINGTON CITY ON | |
| CA | T.E. TAYLOR CONSTRUCTION | AUTO 2000 HARVESTER RD. | BURLINGTON CITY ON | |
| CA | The Regional Municipality of Halton | Appleby Line | Burlington ON | |

| | | | | |
|---|---|---|---|---|
| CA | PALETTA INTERNATIONAL CORP. | PT.LOT 5/C-2, APPLEBY LINE | BURLINGTON CITY ON | |
| CA | WOODSUMMIT INVESTMENTS LTD. COL-LAM INVE | HARVESTER RD. | BURLINGTON CITY ON | |
| CA | PEPLAR INVEST. LTD.- LOT 7, CONC. 3 | HARVESTER RD./S.W.M. DET. POND | BURLINGTON CITY ON | |
| CA | | Within the Right of Way of Appleby Line | Burlington ON | |
| CA | T.C.A. LEASING PT. LOT 11, CONC. 3 SDS | VINCENT CT./HARVESTER RD. | BURLINGTON CITY ON | |
| CA | R.M. OF HALTON | HWY.5/WALKERS/APPLEBY LINES | BURLINGTON CITY ON | |
| CA | T.E. TAYLOR CONSTRUCTION LTD. | HARVESTER RD. W. OF WALKER LN | BURLINGTON CITY ON | |
| CA | 485046 ONTARIO INC. | HARVESTER RD. | BURLINGTON CITY ON | |
| CA | ENSR OPERATIONS LIMITED (X# A 841059) | PALETTA COURT, UNIT J | BURLINGTON CITY ON | |
| CA | Paletta International Corporation | Appleby Line, North of Dundas Street | Burlington ON | |
| CA | The Regional Municipality of Halton | From Appleby Line to Hampton Heath Rd | Burlington ON | |
| CA | R.M. OF HALTON | APPLEBY LINE/LOT 5, CONC. 1 | BURLINGTON CITY ON | |
| ECA | The Regional Municipality of Halton | Within the Right of Way of Appleby Line | Burlington ON | L6M 3L1 |
| ECA | The Regional Municipality of Halton | Appleby Line | Burlington ON | L6M 3L1 |
| ECA | The Regional Municipality of Halton | Appleby Line | Burlington ON | L6M 3L1 |
| ECA | The Regional Municipality of Halton | Appleby Line | Burlington ON | L6M 3L1 |
| ECA | Paletta International Corporation | Appleby Line, North of Dundas Street | Burlington ON | L7L 5R2 |
| GEN | SANEXEN INTERNATIONAL INC. | 153 SIXTH AVENUE, P.O.BOX 640, LOT 22 CONC. 2 C/O 3027 HARVESTER RD. | BURLINGTON ON | L7N 3G7 |
| GEN | HANSON BRICK LIMITED | PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE | BURLINGTON ON | L7R 3Y2 |
| GEN | HANSON BRICK LIMITED | PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE | BURLINGTON ON | |
| GEN | HANSON BRICK LIMITED | PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE | BURLINGTON ON | |
| GEN | FORTERRA BRICK LTD | PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE | BURLINGTON ON | L7R 3Y2 |

| | | | | |
|---|---|---|---|---|
| GEN | CANADA BRICK 08-559 | HWY 5 EAST OF APPLEBY LINE, LOT 4, CONC. 1 N. OF DUNDAS ST.,BOX 248 | BURLINGTON ON | L7R 3Y2 |
| GEN | HANSON BRICK LIMITED | PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE | BURLINGTON ON | |
| GEN | MERIDIAN BRICK CANADA LTD | PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE | BURLINGTON ON | L7R 3Y2 |
| GEN | MERIDIAN BRICK CANADA LTD | PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE | BURLINGTON ON | L7R 3Y2 |
| GEN | HANSON BRICK LIMITED | PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE | BURLINGTON ON | |
| GEN | HANSON BRICK LIMITED | PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE | BURLINGTON ON | L7R 3Y2 |
| GEN | MERIDIAN BRICK CANADA LTD | PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE | BURLINGTON ON | L7R 3Y2 |
| GEN | SANEXEN INTERNATIONAL INC. 34-431 | 153 SIXTH AVENUE, P.O.BOX 640, LOT 22 CONC. 2 C/O 3027 HARVESTER RD. | BURLINGTON ON | L7N 3G7 |
| GEN | MERIDIAN BRICK CANADA LTD | PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE | BURLINGTON ON | L7R 3Y2 |
| GEN | HANSON BRICK LIMITED | PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE | BURLINGTON ON | L7R 3Y2 |
| NPCB | REGIONAL MUNICIPALITY OF HALTON | BOX 7000; 2316 SOUTH SERVICE RD. WEST SKYWAY WATER POLLUTION CONTROL; PLANT | OAKVILLE ON | L6J 6E1 |
| PES | QUEENSLAND LAWN TREATMENT INC NUTRI-LAWN | 15-4087 HARVESTER RD | BURLINGTON ON | L7L 5M3 |
| REC | SANEXEN INTERNATIONAL (1988) INC. | 2202 EGLINTON AVE. E, SCARBOROUGH C/O 3027 HARVESTER ROAD UNIT 202 | BURLINGTON ON | L7N 3G7 |
| SCT | Bibico Electric Inc. | 5 Harvester Rd Unit 4087 | Burlington ON | L7L 5M3 |
| SCT | Pro-Tect Plastic Fabricators | 115 Harvester Rd Unit 1-5 | Burlington ON | L7L 0A3 |
| SPL | | Fairview St. east of Appleby Line at the GO station | Burlington ON | |
| SPL | Metro Waste Paper Recovery Inc. | Appleby Line | Burlington ON | |
| SPL | TRANSPORT TRUCK | ROBIN HOOD MULTI-FOODS, HARVESTER RD MOTOR VEHICLE (OPERATING FLUID) | BURLINGTON CITY ON | |
| SPL | | Walker's Line, South of Harvester's Road | Burlington ON | |
| SPL | UNKNOWN | APPELBY CREEK AT HARVESTER RD & PINEDALE RD BRIDGES. | BURLINGTON CITY ON | |
| SPL | | Mainway, East of Appleby Line | Burlington ON | |
| SPL | | APPLEBY LINE & HEADON RD<UNOFFICIAL> | Burlington ON | |

| | | | |
|---|---|---|---|
| SPL | GO TRANSIT | CREEK IN SHERWOOD FOREST PARK,OFF FAIRVIEW, EAST OF APPLEBY LINE STORAGE TANK | BURLINGTON CITY ON |
| SPL | | at Harvester Rd | Burlington ON |
| SPL | ROTHSAY | QEW WESTBOUND, JUST PAST THE APPLEBY LINE ONRAMP TRANSPORT TRUCK (CARGO) | BURLINGTON CITY ON |
| SPL | BURLINGTON HYDRO-ELECTRIC COMM | 4316 DAIRY RD, WEST OF APPLEBY LINE TRANSFORMER | BURLINGTON CITY ON |

# Unplottable Report

**Site:** ***MONARCH CONSTRUCTION LIMITED***
***RING RD/APPLEBY LINE BURLINGTON CITY ON***

**Database:** ***CA***

| | |
|---|---|
| ***Certificate #:*** | 3-1354-95-006 |
| ***Application Year:*** | 95 |
| ***Issue Date:*** | 11/21/95 |
| ***Approval Type:*** | Municipal sewage |
| ***Status:*** | Approved |
| ***Application Type:*** | |
| ***Client Name:*** | |
| ***Client Address:*** | |
| ***Client City:*** | |
| ***Client Postal Code:*** | |
| ***Project Description:*** | |
| ***Contaminants:*** | |
| ***Emission Control:*** | |

---

**Site:** ***R.M. OF HALTON APPLEBY LINE***
***APPLEBY LINE BURLINGTON CITY ON***

**Database:** ***CA***

| | |
|---|---|
| ***Certificate #:*** | 7-0508-88- |
| ***Application Year:*** | 88 |
| ***Issue Date:*** | 5/10/1988 |
| ***Approval Type:*** | Municipal water |
| ***Status:*** | Approved |
| ***Application Type:*** | |
| ***Client Name:*** | |
| ***Client Address:*** | |
| ***Client City:*** | |
| ***Client Postal Code:*** | |
| ***Project Description:*** | |
| ***Contaminants:*** | |
| ***Emission Control:*** | |

---

**Site:** ***MYTRAX DEVELOPMENTS INC.***
***S. SERVICE RD. PRIV. IND. DEV. BURLINGTON CITY ON***

**Database:** ***CA***

| | |
|---|---|
| ***Certificate #:*** | 7-0020-89- |
| ***Application Year:*** | 89 |
| ***Issue Date:*** | 4/21/1989 |
| ***Approval Type:*** | Municipal water |
| ***Status:*** | Cancelled |
| ***Application Type:*** | |
| ***Client Name:*** | |
| ***Client Address:*** | |
| ***Client City:*** | |
| ***Client Postal Code:*** | |
| ***Project Description:*** | |
| ***Contaminants:*** | |
| ***Emission Control:*** | |

---

**Site:** ***T.C.A. LEASING-PT. LOT 11, CONC. 3 SDS***
***VINCENT CT./HARVESTER RD. BURLINGTON CITY ON***

**Database:** ***CA***

| | |
|---|---|
| ***Certificate #:*** | 3-1186-91- |
| ***Application Year:*** | 91 |

***Issue Date:*** 8/7/1991
***Approval Type:*** Municipal sewage
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

***Site:*** ***BERL-TON INVESTMENTS LIMITED***
***HARVESTER RD. BURLINGTON CITY ON***

***Database:*** ***CA***

***Certificate #:*** 3-2183-87-
***Application Year:*** 87
***Issue Date:*** 12/17/1987
***Approval Type:*** Municipal sewage
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

***Site:*** ***BOYD POLLOCK***
***HARVESTER RD. BURLINGTON CITY ON***

***Database:*** ***CA***

***Certificate #:*** 7-1005-88-
***Application Year:*** 88
***Issue Date:*** 7/13/1988
***Approval Type:*** Municipal water
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

***Site:*** ***LAKELAND DEVELOPMENT CORPORATION***
***HARVESTER ROAD BURLINGTON CITY ON***

***Database:*** ***CA***

***Certificate #:*** 7-0388-89-
***Application Year:*** 89
***Issue Date:*** 6/5/1990
***Approval Type:*** Municipal water
***Status:*** Cancelled
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

***Site:*** ***LAKELAND DEVELOPMENT CORPORATION***
***HARVESTER ROAD PRIVATE BURLINGTON CITY ON***

***Database:*** ***CA***

***Certificate #:*** 3-0455-89-
***Application Year:*** 89
***Issue Date:*** 6/5/1990
***Approval Type:*** Municipal sewage
***Status:*** Cancelled
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

***Site:*** ***R.M. OF HALTON***
***PALETTA COURT BURLINGTON CITY ON***

***Database:*** ***CA***

***Certificate #:*** 3-0029-87-
***Application Year:*** 87
***Issue Date:*** 2/5/1987
***Approval Type:*** Municipal sewage
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

***Site:*** ***CICERELLA INVEST. LTD.-PT. LOT 9/CONC. 3***
***HARVESTER RD./CNR OAKVILLE SUB BURLINGTON CITY ON***

***Database:*** ***CA***

***Certificate #:*** 7-0524-91-
***Application Year:*** 91
***Issue Date:*** 5/22/1991
***Approval Type:*** Municipal water
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

***Site:*** ***PUDGEWAL DEVELOPMENT CORP. - PLAN #M-192***
***HARVESTER ROAD BURLINGTON CITY ON***

***Database:*** ***CA***

***Certificate #:*** 7-0018-90-
***Application Year:*** 90
***Issue Date:*** 1/23/1990
***Approval Type:*** Municipal water
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***

***Contaminants:***
***Emission Control:***

---

***Site:*** ***CICERELLA INVEST. LTD.-PT.LOT 9/CONC.3***
***HARVESTER RD./CNR OAKVILLE SUB BURLINGTON CITY ON***

***Database:*** ***CA***

***Certificate #:*** 3-0645-91-
***Application Year:*** 91
***Issue Date:*** 5/22/1991
***Approval Type:*** Municipal sewage
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

***Site:*** ***D. GREENFIELD ASSOC. LTD.***
***EASEMENT APPLEBY LINE BURLINGTON CITY ON***

***Database:*** ***CA***

***Certificate #:*** 3-0855-89-
***Application Year:*** 89
***Issue Date:*** 5/29/1989
***Approval Type:*** Municipal sewage
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

***Site:*** ***BOYD POLLOCK***
***HARVESTER RD. BURLINGTON CITY ON***

***Database:*** ***CA***

***Certificate #:*** 3-1159-88-
***Application Year:*** 88
***Issue Date:*** 7/13/1988
***Approval Type:*** Municipal sewage
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

***Site:*** ***R.M. OF HALTON APPLEBY LINE***
***APPLEBY LINE BURLINGTON CITY ON***

***Database:*** ***CA***

***Certificate #:*** 3-0572-88-
***Application Year:*** 88
***Issue Date:*** 5/10/1988
***Approval Type:*** Municipal sewage
***Status:*** Approved
***Application Type:***

***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

***Site:*** ***T.E. TAYLOR CONSTRUCTION***
***AUTO 2000 HARVESTER RD. BURLINGTON CITY ON***

***Database:*** ***CA***

***Certificate #:*** 3-0632-87-
***Application Year:*** 87
***Issue Date:*** 5/4/1987
***Approval Type:*** Municipal sewage
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

***Site:*** ***The Regional Municipality of Halton***
***Appleby Line Burlington ON***

***Database:*** ***CA***

***Certificate #:*** 4380-62LQKU
***Application Year:*** 2004
***Issue Date:*** 7/6/2004
***Approval Type:*** Municipal and Private Sewage Works
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

***Site:*** ***PALETTA INTERNATIONAL CORP.***
***PT.LOT 5/C-2, APPLEBY LINE BURLINGTON CITY ON***

***Database:*** ***CA***

***Certificate #:*** 7-0460-97-
***Application Year:*** 97
***Issue Date:*** 6/2/1997
***Approval Type:*** Municipal water
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

***Site:*** ***WOODSUMMIT INVESTMENTS LTD. COL-LAM INVE***
***HARVESTER RD. BURLINGTON CITY ON***

***Database:*** ***CA***

***Certificate #:*** 7-0445-86-

***Application Year:*** 86
***Issue Date:*** 5/15/1986
***Approval Type:*** Municipal water
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

***Site:*** ***PEPLAR INVEST. LTD.- LOT 7, CONC. 3***
***HARVESTER RD./S.W.M. DET. POND BURLINGTON CITY ON***

***Database:*** ***CA***

***Certificate #:*** 3-1140-92-
***Application Year:*** 92
***Issue Date:*** 11/2/1992
***Approval Type:*** Municipal sewage
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

***Site:***
***Within the Right of Way of Appleby Line Burlington ON***

***Database:*** ***CA***

***Certificate #:*** 7555-4TGS7R
***Application Year:*** 01
***Issue Date:*** 2/5/01
***Approval Type:*** Municipal & Private water
***Status:*** Approved
***Application Type:*** New Certificate of Approval
***Client Name:*** Corporation of the Regional Municipality of Halton
***Client Address:*** 1151 Bronte Road
***Client City:*** Oakville
***Client Postal Code:*** L6M 3L1
***Project Description:*** Installation of watermains on Appleby Line and Birett Drive in the City of Burlington.
***Contaminants:***
***Emission Control:***

---

***Site:*** ***T.C.A. LEASING PT. LOT 11, CONC. 3 SDS***
***VINCENT CT./HARVESTER RD. BURLINGTON CITY ON***

***Database:*** ***CA***

***Certificate #:*** 7-0949-91-
***Application Year:*** 91
***Issue Date:*** 8/7/1991
***Approval Type:*** Municipal water
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

***Site:*** ***R.M. OF HALTON***
***HWY.5/WALKERS/APPLEBY LINES BURLINGTON CITY ON***

***Database:*** ***CA***

| | |
|---|---|
| ***Certificate #:*** | 7-0532-95- |
| ***Application Year:*** | 95 |
| ***Issue Date:*** | 6/30/1995 |
| ***Approval Type:*** | Municipal water |
| ***Status:*** | Approved |
| ***Application Type:*** | |
| ***Client Name:*** | |
| ***Client Address:*** | |
| ***Client City:*** | |
| ***Client Postal Code:*** | |
| ***Project Description:*** | |
| ***Contaminants:*** | |
| ***Emission Control:*** | |

***Site:*** ***T.E. TAYLOR CONSTRUCTION LTD.***
***HARVESTER RD. W. OF WALKER LN BURLINGTON CITY ON***

***Database:*** ***CA***

| | |
|---|---|
| ***Certificate #:*** | 7-0531-87- |
| ***Application Year:*** | 87 |
| ***Issue Date:*** | 5/4/1987 |
| ***Approval Type:*** | Municipal water |
| ***Status:*** | Approved |
| ***Application Type:*** | |
| ***Client Name:*** | |
| ***Client Address:*** | |
| ***Client City:*** | |
| ***Client Postal Code:*** | |
| ***Project Description:*** | |
| ***Contaminants:*** | |
| ***Emission Control:*** | |

***Site:*** ***485046 ONTARIO INC.***
***HARVESTER RD. BURLINGTON CITY ON***

***Database:*** ***CA***

| | |
|---|---|
| ***Certificate #:*** | 3-1095-89- |
| ***Application Year:*** | 89 |
| ***Issue Date:*** | 6/14/1989 |
| ***Approval Type:*** | Municipal sewage |
| ***Status:*** | Approved |
| ***Application Type:*** | |
| ***Client Name:*** | |
| ***Client Address:*** | |
| ***Client City:*** | |
| ***Client Postal Code:*** | |
| ***Project Description:*** | |
| ***Contaminants:*** | |
| ***Emission Control:*** | |

***Site:*** ***ENSR OPERATIONS LIMITED (X# A 841059)***
***PALETTA COURT, UNIT J BURLINGTON CITY ON***

***Database:*** ***CA***

| | |
|---|---|
| ***Certificate #:*** | 8-3294-91- |
| ***Application Year:*** | 91 |
| ***Issue Date:*** | 12/18/1991 |
| ***Approval Type:*** | Industrial air |
| ***Status:*** | Preliminary approval |
| ***Application Type:*** | |
| ***Client Name:*** | |
| ***Client Address:*** | |
| ***Client City:*** | |
| ***Client Postal Code:*** | |

***Project Description:*** SYSTEM 50 TECHNOLOGY-MOBILE WASTE DISP.
***Contaminants:***
***Emission Control:***

---

***Site:*** ***Paletta International Corporation***
***Appleby Line, North of Dundas Street Burlington ON***

***Database:*** ***CA***

***Certificate #:*** 9237-5QBL6P
***Application Year:*** 2003
***Issue Date:*** 8/26/2003
***Approval Type:*** Municipal and Private Sewage Works
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

***Site:*** ***The Regional Municipality of Halton***
***From Appleby Line to Hampton Heath Rd Burlington ON***

***Database:*** ***CA***

***Certificate #:*** 6278-7WCMY5
***Application Year:*** 2009
***Issue Date:*** 10/2/2009
***Approval Type:*** Municipal and Private Sewage Works
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

***Site:*** ***R.M. OF HALTON***
***APPLEBY LINE/LOT 5, CONC. 1 BURLINGTON CITY ON***

***Database:*** ***CA***

***Certificate #:*** 7-0117-93-
***Application Year:*** 93
***Issue Date:*** 4/26/1993
***Approval Type:*** Municipal water
***Status:*** Approved
***Application Type:***
***Client Name:***
***Client Address:***
***Client City:***
***Client Postal Code:***
***Project Description:***
***Contaminants:***
***Emission Control:***

---

***Site:*** ***The Regional Municipality of Halton***
***Within the Right of Way of Appleby Line Burlington ON L6M 3L1***

***Database:*** ***ECA***

***Approval No:*** 7555-4TGS7R
***Approval Date:*** 2001-02-05
***Status:*** Approved
***Record Type:*** ECA
***Link Source:*** IDS
***MOE District:***
***City:***
***Longitude:***
***Latitude:***
***Geometry X:***

***SWP Area Name:*** ***Geometry Y:***
***Approval Type:*** ECA-Municipal and Private Water Works
***Project Type:*** Municipal and Private Water Works
***Business Name:*** The Regional Municipality of Halton
***Address:*** Within the Right of Way of Appleby Line
***Full Address:***
***Full PDF Link:***
***PDF Site Location:***

---

***Site:*** ***The Regional Municipality of Halton*** ***Database:*** ***ECA***
***Appleby Line Burlington ON L6M 3L1***

***Approval No:*** 4380-62LQKU ***MOE District:***
***Approval Date:*** 2004-07-06 ***City:***
***Status:*** Approved ***Longitude:***
***Record Type:*** ECA ***Latitude:***
***Link Source:*** IDS ***Geometry X:***
***SWP Area Name:*** ***Geometry Y:***
***Approval Type:*** ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
***Project Type:*** MUNICIPAL AND PRIVATE SEWAGE WORKS
***Business Name:*** The Regional Municipality of Halton
***Address:*** Appleby Line
***Full Address:***
***Full PDF Link:*** https://www.accessenvironment.ene.gov.on.ca/instruments/9635-623QN5-14.pdf
***PDF Site Location:***

---

***Site:*** ***The Regional Municipality of Halton*** ***Database:*** ***ECA***
***Appleby Line Burlington ON L6M 3L1***

***Approval No:*** 8170-5Y9RZU ***MOE District:***
***Approval Date:*** 2004-04-23 ***City:***
***Status:*** Approved ***Longitude:***
***Record Type:*** ECA ***Latitude:***
***Link Source:*** IDS ***Geometry X:***
***SWP Area Name:*** ***Geometry Y:***
***Approval Type:*** ECA-Municipal Drinking Water Systems
***Project Type:*** Municipal Drinking Water Systems
***Business Name:*** The Regional Municipality of Halton
***Address:*** Appleby Line
***Full Address:***
***Full PDF Link:***
***PDF Site Location:***

---

***Site:*** ***The Regional Municipality of Halton*** ***Database:*** ***ECA***
***Appleby Line Burlington ON L6M 3L1***

***Approval No:*** 7967-5NTPCY ***MOE District:***
***Approval Date:*** 2003-06-25 ***City:***
***Status:*** Approved ***Longitude:***
***Record Type:*** ECA ***Latitude:***
***Link Source:*** IDS ***Geometry X:***
***SWP Area Name:*** ***Geometry Y:***
***Approval Type:*** ECA-Municipal Drinking Water Systems
***Project Type:*** Municipal Drinking Water Systems
***Business Name:*** The Regional Municipality of Halton
***Address:*** Appleby Line
***Full Address:***
***Full PDF Link:***
***PDF Site Location:***

---

***Site:*** ***Paletta International Corporation*** ***Database:*** ***ECA***
***Appleby Line, North of Dundas Street Burlington ON L7L 5R2***

| | | | |
|---|---|---|---|
| ***Approval No:*** | 9237-5QBL6P | ***MOE District:*** | |
| ***Approval Date:*** | 2003-08-26 | ***City:*** | |
| ***Status:*** | Approved | ***Longitude:*** | |
| ***Record Type:*** | ECA | ***Latitude:*** | |
| ***Link Source:*** | IDS | ***Geometry X:*** | |
| ***SWP Area Name:*** | | ***Geometry Y:*** | |

***Approval Type:*** ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
***Project Type:*** MUNICIPAL AND PRIVATE SEWAGE WORKS
***Business Name:*** Paletta International Corporation
***Address:*** Appleby Line, North of Dundas Street
***Full Address:***
***Full PDF Link:*** https://www.accessenvironment.ene.gov.on.ca/instruments/4691-5Q5HWJ-14.pdf
***PDF Site Location:***

---

***Site:*** ***SANEXEN INTERNATIONAL INC.***
***153 SIXTH AVENUE, P.O.BOX 640, LOT 22 CONC. 2 C/O 3027 HARVESTER RD. BURLINGTON ON L7N 3G7***

***Database:*** ***GEN***

***Generator No:*** ON1120002
***SIC Code:*** 0000
***SIC Description:*** *** NOT DEFINED ***
***Approval Years:*** 88,89
***PO Box No:***
***Country:***
***Status:***
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

---

***Site:*** ***HANSON BRICK LIMITED***
***PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE BURLINGTON ON L7R 3Y2***

***Database:*** ***GEN***

***Generator No:*** ON0043604
***SIC Code:*** 339990
***SIC Description:*** All Other Miscellaneous Manufacturing
***Approval Years:*** 2012
***PO Box No:***
***Country:***
***Status:***
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 112
***Waste Class Name:*** ACID WASTE - HEAVY METALS

***Waste Class:*** 113
***Waste Class Name:*** ACID WASTE - OTHER METALS

***Waste Class:*** 252
***Waste Class Name:*** WASTE OILS & LUBRICANTS

***Waste Class:*** 146
***Waste Class Name:*** OTHER SPECIFIED INORGANICS

***Waste Class:*** 251
***Waste Class Name:*** OIL SKIMMINGS & SLUDGES

***Waste Class:*** 213
***Waste Class Name:*** PETROLEUM DISTILLATES

***Waste Class:*** 263

***Waste Class Name:*** ORGANIC LABORATORY CHEMICALS

***Waste Class:*** 148
***Waste Class Name:*** INORGANIC LABORATORY CHEMICALS

***Waste Class:*** 212
***Waste Class Name:*** ALIPHATIC SOLVENTS

---

***Site:*** ***HANSON BRICK LIMITED***
***PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE BURLINGTON ON***

***Database:*** ***GEN***

***Generator No:*** ON0043604
***SIC Code:*** 339990
***SIC Description:*** All Other Miscellaneous Manufacturing
***Approval Years:*** 2011
***PO Box No:***
***Country:***
***Status:***
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 212
***Waste Class Name:*** ALIPHATIC SOLVENTS

***Waste Class:*** 213
***Waste Class Name:*** PETROLEUM DISTILLATES

***Waste Class:*** 263
***Waste Class Name:*** ORGANIC LABORATORY CHEMICALS

***Waste Class:*** 251
***Waste Class Name:*** OIL SKIMMINGS & SLUDGES

***Waste Class:*** 112
***Waste Class Name:*** ACID WASTE - HEAVY METALS

***Waste Class:*** 148
***Waste Class Name:*** INORGANIC LABORATORY CHEMICALS

***Waste Class:*** 146
***Waste Class Name:*** OTHER SPECIFIED INORGANICS

***Waste Class:*** 252
***Waste Class Name:*** WASTE OILS & LUBRICANTS

***Waste Class:*** 113
***Waste Class Name:*** ACID WASTE - OTHER METALS

---

***Site:*** ***HANSON BRICK LIMITED***
***PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE BURLINGTON ON***

***Database:*** ***GEN***

***Generator No:*** ON0043604
***SIC Code:*** 339990
***SIC Description:*** All Other Miscellaneous Manufacturing
***Approval Years:*** 2009
***PO Box No:***
***Country:***
***Status:***
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 113
***Waste Class Name:*** ACID WASTE - OTHER METALS

***Waste Class:*** 146
***Waste Class Name:*** OTHER SPECIFIED INORGANICS

***Waste Class:*** 148
***Waste Class Name:*** INORGANIC LABORATORY CHEMICALS

***Waste Class:*** 212
***Waste Class Name:*** ALIPHATIC SOLVENTS

***Waste Class:*** 213
***Waste Class Name:*** PETROLEUM DISTILLATES

***Waste Class:*** 251
***Waste Class Name:*** OIL SKIMMINGS & SLUDGES

***Waste Class:*** 252
***Waste Class Name:*** WASTE OILS & LUBRICANTS

***Waste Class:*** 112
***Waste Class Name:*** ACID WASTE - HEAVY METALS

---

***Site:*** ***FORTERRA BRICK LTD***
***PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE BURLINGTON ON L7R 3Y2***

***Database:*** ***GEN***

***Generator No:*** ON0043604
***SIC Code:*** 339990
***SIC Description:*** ALL OTHER MISCELLANEOUS MANUFACTURING
***Approval Years:*** 2015
***PO Box No:***
***Country:*** Canada
***Status:***
***Co Admin:*** John Lourenco
***Choice of Contact:*** CO_OFFICIAL
***Phone No Admin:*** 905 335 3401 Ext.7254
***Contaminated Facility:*** No
***MHSW Facility:*** No

***Detail(s)***

***Waste Class:*** 112
***Waste Class Name:*** ACID WASTE - HEAVY METALS

***Waste Class:*** 148
***Waste Class Name:*** INORGANIC LABORATORY CHEMICALS

***Waste Class:*** 251
***Waste Class Name:*** OIL SKIMMINGS & SLUDGES

***Waste Class:*** 212
***Waste Class Name:*** ALIPHATIC SOLVENTS

***Waste Class:*** 113
***Waste Class Name:*** ACID WASTE - OTHER METALS

***Waste Class:*** 146
***Waste Class Name:*** OTHER SPECIFIED INORGANICS

***Waste Class:*** 263
***Waste Class Name:*** ORGANIC LABORATORY CHEMICALS

***Waste Class:*** 213
***Waste Class Name:*** PETROLEUM DISTILLATES

***Waste Class:*** 252
***Waste Class Name:*** WASTE OILS & LUBRICANTS

---

***Site:*** ***CANADA BRICK 08-559***
***HWY 5 EAST OF APPLEBY LINE, LOT 4, CONC.1 N. OF DUNDAS ST.,BOX 248 BURLINGTON ON L7R 3Y2***

***Database:*** ***GEN***

***Generator No:*** ON0043604
***SIC Code:*** 3511
***SIC Description:*** DOMESTIC CLAY PROD.
***Approval Years:*** 94,95,96
***PO Box No:***
***Country:***
***Status:***
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 112
***Waste Class Name:*** ACID WASTE - HEAVY METALS

***Waste Class:*** 213
***Waste Class Name:*** PETROLEUM DISTILLATES

***Waste Class:*** 251
***Waste Class Name:*** OIL SKIMMINGS & SLUDGES

***Waste Class:*** 252
***Waste Class Name:*** WASTE OILS & LUBRICANTS

---

***Site:*** ***HANSON BRICK LIMITED***
***PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE BURLINGTON ON***

***Database:*** ***GEN***

***Generator No:*** ON0043604
***SIC Code:*** 339990
***SIC Description:*** All Other Miscellaneous Manufacturing
***Approval Years:*** 2010
***PO Box No:***
***Country:***
***Status:***
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 251
***Waste Class Name:*** OIL SKIMMINGS & SLUDGES

***Waste Class:*** 213
***Waste Class Name:*** PETROLEUM DISTILLATES

***Waste Class:*** 112
***Waste Class Name:*** ACID WASTE - HEAVY METALS

***Waste Class:*** 113
***Waste Class Name:*** ACID WASTE - OTHER METALS

***Waste Class:*** 146
***Waste Class Name:*** OTHER SPECIFIED INORGANICS

***Waste Class:*** 263
***Waste Class Name:*** ORGANIC LABORATORY CHEMICALS

***Waste Class:*** 252
***Waste Class Name:*** WASTE OILS & LUBRICANTS

***Waste Class:*** 212
***Waste Class Name:*** ALIPHATIC SOLVENTS

***Waste Class:*** 148
***Waste Class Name:*** INORGANIC LABORATORY CHEMICALS

---

***Site:*** ***MERIDIAN BRICK CANADA LTD***
***PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE BURLINGTON ON L7R 3Y2***

***Database:*** ***GEN***

***Generator No:*** ON0043604
***SIC Code:***
***SIC Description:***
***Approval Years:*** As of Dec 2018
***PO Box No:***
***Country:*** Canada
***Status:*** Registered
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 146 T
***Waste Class Name:*** Other specified inorganic sludges, slurries or solids

***Waste Class:*** 148 C
***Waste Class Name:*** Misc. wastes and inorganic chemicals

***Waste Class:*** 148 I
***Waste Class Name:*** Misc. wastes and inorganic chemicals

***Waste Class:*** 212 L
***Waste Class Name:*** Aliphatic solvents and residues

***Waste Class:*** 213 I
***Waste Class Name:*** Petroleum distillates

***Waste Class:*** 213 L
***Waste Class Name:*** Petroleum distillates

***Waste Class:*** 252 L
***Waste Class Name:*** Waste crankcase oils and lubricants

***Waste Class:*** 263 I
***Waste Class Name:*** Misc. waste organic chemicals

---

***Site:*** ***MERIDIAN BRICK CANADA LTD***
***PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE BURLINGTON ON L7R 3Y2***

***Database:*** ***GEN***

***Generator No:*** ON0043604
***SIC Code:***
***SIC Description:***
***Approval Years:*** As of Nov 2021
***PO Box No:***
***Country:*** Canada
***Status:*** Registered
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***

***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 221 I
***Waste Class Name:*** Light fuels

***Waste Class:*** 252 L
***Waste Class Name:*** Waste crankcase oils and lubricants

***Waste Class:*** 212 L
***Waste Class Name:*** Aliphatic solvents and residues

***Waste Class:*** 148 I
***Waste Class Name:*** Misc. wastes and inorganic chemicals

***Waste Class:*** 148 C
***Waste Class Name:*** Misc. wastes and inorganic chemicals

***Waste Class:*** 263 I
***Waste Class Name:*** Misc. waste organic chemicals

***Waste Class:*** 213 L
***Waste Class Name:*** Petroleum distillates

***Waste Class:*** 146 T
***Waste Class Name:*** Other specified inorganic sludges, slurries or solids

***Waste Class:*** 213 I
***Waste Class Name:*** Petroleum distillates

***Waste Class:*** 221 L
***Waste Class Name:*** Light fuels

---

***Site:*** ***HANSON BRICK LIMITED***
***PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE BURLINGTON ON***

***Database:*** ***GEN***

***Generator No:*** ON0043604
***SIC Code:*** 339990
***SIC Description:*** ALL OTHER MISCELLANEOUS MANUFACTURING
***Approval Years:*** 2013
***PO Box No:***
***Country:***
***Status:***
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 263
***Waste Class Name:*** ORGANIC LABORATORY CHEMICALS

***Waste Class:*** 148
***Waste Class Name:*** INORGANIC LABORATORY CHEMICALS

***Waste Class:*** 213
***Waste Class Name:*** PETROLEUM DISTILLATES

***Waste Class:*** 112
***Waste Class Name:*** ACID WASTE - HEAVY METALS

***Waste Class:*** 212
***Waste Class Name:*** ALIPHATIC SOLVENTS

***Waste Class:*** 251

***Waste Class Name:*** OIL SKIMMINGS & SLUDGES

***Waste Class:*** 113
***Waste Class Name:*** ACID WASTE - OTHER METALS

***Waste Class:*** 146
***Waste Class Name:*** OTHER SPECIFIED INORGANICS

***Waste Class:*** 252
***Waste Class Name:*** WASTE OILS & LUBRICANTS

---

***Site:*** ***HANSON BRICK LIMITED***
***PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE BURLINGTON ON L7R 3Y2***

***Database:*** ***GEN***

***Generator No:*** ON0043604
***SIC Code:*** 327120
***SIC Description:*** Clay Building Material & Refractory Mfg.
***Approval Years:*** 02,03,04,05,06,07,08
***PO Box No:***
***Country:***
***Status:***
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 146
***Waste Class Name:*** OTHER SPECIFIED INORGANICS

***Waste Class:*** 112
***Waste Class Name:*** ACID WASTE - HEAVY METALS

***Waste Class:*** 113
***Waste Class Name:*** ACID WASTE - OTHER METALS

***Waste Class:*** 148
***Waste Class Name:*** INORGANIC LABORATORY CHEMICALS

***Waste Class:*** 212
***Waste Class Name:*** ALIPHATIC SOLVENTS

***Waste Class:*** 213
***Waste Class Name:*** PETROLEUM DISTILLATES

***Waste Class:*** 251
***Waste Class Name:*** OIL SKIMMINGS & SLUDGES

***Waste Class:*** 252
***Waste Class Name:*** WASTE OILS & LUBRICANTS

---

***Site:*** ***MERIDIAN BRICK CANADA LTD***
***PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE BURLINGTON ON L7R 3Y2***

***Database:*** ***GEN***

***Generator No:*** ON0043604
***SIC Code:*** 339990
***SIC Description:*** ALL OTHER MISCELLANEOUS MANUFACTURING
***Approval Years:*** 2016
***PO Box No:***
***Country:*** Canada
***Status:***
***Co Admin:*** John Lourenco
***Choice of Contact:*** CO_OFFICIAL
***Phone No Admin:*** 905 335 3401 Ext.7254
***Contaminated Facility:*** No
***MHSW Facility:*** No

***Detail(s)***

***Waste Class:*** 113
***Waste Class Name:*** ACID WASTE - OTHER METALS

***Waste Class:*** 148
***Waste Class Name:*** INORGANIC LABORATORY CHEMICALS

***Waste Class:*** 251
***Waste Class Name:*** OIL SKIMMINGS & SLUDGES

***Waste Class:*** 252
***Waste Class Name:*** WASTE OILS & LUBRICANTS

***Waste Class:*** 146
***Waste Class Name:*** OTHER SPECIFIED INORGANICS

***Waste Class:*** 213
***Waste Class Name:*** PETROLEUM DISTILLATES

***Waste Class:*** 263
***Waste Class Name:*** ORGANIC LABORATORY CHEMICALS

***Waste Class:*** 212
***Waste Class Name:*** ALIPHATIC SOLVENTS

***Waste Class:*** 112
***Waste Class Name:*** ACID WASTE - HEAVY METALS

---

***Site:*** ***SANEXEN INTERNATIONAL INC. 34-431***
***153 SIXTH AVENUE, P.O.BOX 640, LOT 22 CONC. 2 C/O 3027 HARVESTER RD. BURLINGTON ON L7N 3G7***

***Database:*** ***GEN***

***Generator No:*** ON1120002
***SIC Code:*** 0000
***SIC Description:*** *** NOT DEFINED ***
***Approval Years:*** 92,93,94
***PO Box No:***
***Country:***
***Status:***
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

---

***Site:*** ***MERIDIAN BRICK CANADA LTD***
***PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE BURLINGTON ON L7R 3Y2***

***Database:*** ***GEN***

***Generator No:*** ON0043604
***SIC Code:***
***SIC Description:***
***Approval Years:*** As of Jul 2020
***PO Box No:***
***Country:*** Canada
***Status:*** Registered
***Co Admin:***
***Choice of Contact:***
***Phone No Admin:***
***Contaminated Facility:***
***MHSW Facility:***

***Detail(s)***

***Waste Class:*** 221 L
***Waste Class Name:*** Light fuels

***Waste Class:*** 213 L
***Waste Class Name:*** Petroleum distillates

***Waste Class:*** 263 I
***Waste Class Name:*** Misc. waste organic chemicals

***Waste Class:*** 148 I
***Waste Class Name:*** Misc. wastes and inorganic chemicals

***Waste Class:*** 146 T
***Waste Class Name:*** Other specified inorganic sludges, slurries or solids

***Waste Class:*** 212 L
***Waste Class Name:*** Aliphatic solvents and residues

***Waste Class:*** 148 C
***Waste Class Name:*** Misc. wastes and inorganic chemicals

***Waste Class:*** 221 I
***Waste Class Name:*** Light fuels

***Waste Class:*** 252 L
***Waste Class Name:*** Waste crankcase oils and lubricants

***Waste Class:*** 213 I
***Waste Class Name:*** Petroleum distillates

---

***Site:*** ***HANSON BRICK LIMITED***
***PT.LT.4,CON.1,HWY 5 E.OF APPLEBY LINE BURLINGTON ON L7R 3Y2***

***Database:*** ***GEN***

***Generator No:*** ON0043604
***SIC Code:*** 339990
***SIC Description:*** ALL OTHER MISCELLANEOUS MANUFACTURING
***Approval Years:*** 2014
***PO Box No:***
***Country:*** Canada
***Status:***
***Co Admin:*** John Lourenco
***Choice of Contact:*** CO_OFFICIAL
***Phone No Admin:*** 905 335 3401 Ext.7254
***Contaminated Facility:*** No
***MHSW Facility:*** No

***Detail(s)***

***Waste Class:*** 212
***Waste Class Name:*** ALIPHATIC SOLVENTS

***Waste Class:*** 146
***Waste Class Name:*** OTHER SPECIFIED INORGANICS

***Waste Class:*** 251
***Waste Class Name:*** OIL SKIMMINGS & SLUDGES

***Waste Class:*** 148
***Waste Class Name:*** INORGANIC LABORATORY CHEMICALS

***Waste Class:*** 112
***Waste Class Name:*** ACID WASTE - HEAVY METALS

***Waste Class:*** 252
***Waste Class Name:*** WASTE OILS & LUBRICANTS

***Waste Class:*** 213
***Waste Class Name:*** PETROLEUM DISTILLATES

***Waste Class:*** 113
***Waste Class Name:*** ACID WASTE - OTHER METALS

**Waste Class:** 263
**Waste Class Name:** ORGANIC LABORATORY CHEMICALS

---

**Site:** ***REGIONAL MUNICIPALITY OF HALTON***
***BOX 7000; 2316 SOUTH SERVICE RD. WEST SKYWAY WATER POLLUTION CONTROL; PLANT OAKVILLE ON L6J 6E1***

**Database:** ***NPCB***

**Company Code:** O0230I
**Industry:** Government (not Fed)
**Site Status:**
**Transaction Date:** 5/4/1995
**Inspection Date:** 9/11/1990

---

**Site:** ***QUEENSLAND LAWN TREATMENT INC NUTRI-LAWN***
***15-4087 HARVESTER RD BURLINGTON ON L7L 5M3***

**Database:** ***PES***

**Detail Licence No:** 02-01-06993-0
**Licence No:**
**Status:**
**Approval Date:**
**Report Source:**
**Licence Type:** OPERATOR
**Licence Type Code:**
**Licence Class:**
**Licence Control:**
**Latitude:**
**Longitude:**
**Lot:**
**Concession:**
**Region:**
**District:**
**County:**
**Trade Name:**
**PDF URL:**

**Operator Box:**
**Operator Class:**
**Operator No:**
**Operator Type:**
**Oper Area Code:**
**Oper Phone No:**
**Operator Ext:**
**Operator Lot:**
**Oper Concession:**
**Operator Region:**
**Operator District:**
**Operator County:**
**Op Municipality:**
**Post Office Box:**
**MOE District:**
**SWP Area Name:**

---

**Site:** ***SANEXEN INTERNATIONAL (1988) INC.***
***2202 EGLINTON AVE. E, SCARBOROUGH C/O 3027 HARVESTER ROAD UNIT 202 BURLINGTON ON L7N 3G7***

**Database:** ***REC***

**ID:**
**Company ID:**
**Receiver No:** A210235
**Co Admin:**
**Choice of Contact:**
**Rec Div:**
**Rec Op Div:**
**Rec Op Name:**
**Site Bldg:**
**Facility Type:** RECLAIMER/REUSE, PCB DESTRUCTION FACILITY
**Approval Yrs:** 1990; 1992; 1993; 1994; 1995; 1996; 1997; 1998

**Province In:** ONT
**Province Out:**
**County Out:**
**Mail Addr:**
**Site PO Box:**

---

**Site:** ***Bibico Electric Inc.***
***5 Harvester Rd Unit 4087 Burlington ON L7L 5M3***

**Database:** ***SCT***

**Established:**
**Plant Size (ft²):**
**Employment:**

***--Details--***
**Description:** Electrical Wiring and Construction Supplies Wholesaler-Distributors
**SIC/NAICS Code:** 416110

---

**Site:** ***Pro-Tect Plastic Fabricators***

**Database:** ***SCT***

***115 Harvester Rd Unit 1-5 Burlington ON L7L 0A3***

***Established:*** 01-AUG-89
***Plant Size (ft²):***
***Employment:***

***--Details--***
***Description:*** Showcase, Partition, Shelving and Locker Manufacturing
***SIC/NAICS Code:*** 337215

***Description:*** All Other Plastic Product Manufacturing
***SIC/NAICS Code:*** 326198

***Description:*** Showcase, Partition, Shelving and Locker Manufacturing
***SIC/NAICS Code:*** 337215

---

***Site:*** ***Database:*** ***SPL***
***Fairview St. east of Appleby Line at the GO station Burlington ON***

***Ref No:*** 7587-9ZCS8Y
***Site No:*** NA
***Incident Dt:*** 8/13/2015
***Year:***
***Incident Cause:***
***Incident Event:***
***Environment Impact:***
***Nature of Impact:***
***MOE Response:*** No
***Dt MOE Arvl on Scn:***
***MOE Reported Dt:*** 8/13/2015
***Dt Document Closed:*** 8/21/2015
***Municipality No:***
***System Facility Address:***
***Client Type:***
***Call Report Location Geodata:***
***Contaminant Code:*** 98
***Contaminant Name:*** UNKNOWN
***Contaminant Limit 1:***
***Contam Limit Freq 1:***
***Contaminant UN No 1:***
***Receiving Medium:***
***Receiving Environment:***
***Incident Reason:*** Unknown / N/A
***Incident Summary:*** Burlington - unknown substance to Appleby Creek, unctnd, uncld
***Site Region:***
***Site Municipality:*** Burlington
***Activity Preceding Spill:***
***Property 2nd Watershed:***
***Property Tertiary Watershed:***
***Sector Type:*** Unknown / N/A
***SAC Action Class:*** Watercourse Spills
***Source Type:***
***Site County/District:***
***Site Geo Ref Meth:***
***Site District Office:***
***Nearest Watercourse:*** Unknown Name
***Site Name:*** Appleby Creek<UNOFFICIAL>
***Site Address:*** Fairview St. east of Appleby Line at the GO station
***Client Name:***

***Contaminant Qty:*** 0 other - see incident description
***Nature of Damage:***
***Discharger Report:***
***Material Group:***
***Health/Env Conseq:***
***Agency Involved:***
***Site Lot:***
***Site Conc:***
***Site Geo Ref Accu:***
***Site Map Datum:***
***Northing:***
***Easting:***

---

***Site:*** ***Metro Waste Paper Recovery Inc.***
***Appleby Line Burlington ON***

***Database:*** ***SPL***

***Ref No:*** 7027-87UNN3
***Site No:***
***Incident Dt:***

***Contaminant Qty:*** 125 L
***Nature of Damage:***
***Discharger Report:***

| | | | |
|---|---|---|---|
| ***Year:*** | | ***Material Group:*** | |
| ***Incident Cause:*** | | ***Health/Env Conseq:*** | |
| ***Incident Event:*** | | ***Agency Involved:*** | |
| ***Environment Impact:*** | Not Anticipated | ***Site Lot:*** | |
| ***Nature of Impact:*** | | ***Site Conc:*** | |
| ***MOE Response:*** | No Field Response | ***Site Geo Ref Accu:*** | |
| ***Dt MOE Arvl on Scn:*** | | ***Site Map Datum:*** | |
| ***MOE Reported Dt:*** | 7/30/2010 | ***Northing:*** | |
| ***Dt Document Closed:*** | | ***Easting:*** | |
| ***Municipality No:*** | | | |
| ***System Facility Address:*** | | | |
| ***Client Type:*** | | | |
| ***Call Report Location Geodata:*** | | | |
| ***Contaminant Code:*** | 15 | | |
| ***Contaminant Name:*** | HYDRAULIC OIL | | |
| ***Contaminant Limit 1:*** | | | |
| ***Contam Limit Freq 1:*** | | | |
| ***Contaminant UN No 1:*** | | | |
| ***Receiving Medium:*** | | | |
| ***Receiving Environment:*** | | | |
| ***Incident Reason:*** | | | |
| ***Incident Summary:*** | QEW E/Appleby Line: hydraulic oil to road/drain | | |
| ***Site Region:*** | | | |
| ***Site Municipality:*** | | | |
| ***Activity Preceding Spill:*** | | | |
| ***Property 2nd Watershed:*** | | | |
| ***Property Tertiary Watershed:*** | | | |
| ***Sector Type:*** | | | |
| ***SAC Action Class:*** | Land Spills | | |
| ***Source Type:*** | | | |
| ***Site County/District:*** | | | |
| ***Site Geo Ref Meth:*** | | | |
| ***Site District Office:*** | | | |
| ***Nearest Watercourse:*** | | | |
| ***Site Name:*** | Appleby Line<UNOFFICIAL> | | |
| ***Site Address:*** | | | |
| ***Client Name:*** | | | |

---

***Site:*** ***TRANSPORT TRUCK***
***ROBIN HOOD MULTI-FOODS, HARVESTER RD MOTOR VEHICLE (OPERATING FLUID) BURLINGTON CITY ON***

***Database:*** ***SPL***

| | | | |
|---|---|---|---|
| ***Ref No:*** | 152634 | ***Contaminant Qty:*** | |
| ***Site No:*** | | ***Nature of Damage:*** | |
| ***Incident Dt:*** | 2/19/1998 | ***Discharger Report:*** | |
| ***Year:*** | | ***Material Group:*** | |
| ***Incident Cause:*** | OTHER CONTAINER LEAK | ***Health/Env Conseq:*** | |
| ***Incident Event:*** | | ***Agency Involved:*** | |
| ***Environment Impact:*** | NOT ANTICIPATED | ***Site Lot:*** | |
| ***Nature of Impact:*** | | ***Site Conc:*** | |
| ***MOE Response:*** | | ***Site Geo Ref Accu:*** | |
| ***Dt MOE Arvl on Scn:*** | | ***Site Map Datum:*** | |
| ***MOE Reported Dt:*** | 2/19/1998 | ***Northing:*** | |
| ***Dt Document Closed:*** | | ***Easting:*** | |
| ***Municipality No:*** | 14101 | | |
| ***System Facility Address:*** | | | |
| ***Client Type:*** | | | |
| ***Call Report Location Geodata:*** | | | |
| ***Contaminant Code:*** | | | |
| ***Contaminant Name:*** | | | |
| ***Contaminant Limit 1:*** | | | |
| ***Contam Limit Freq 1:*** | | | |
| ***Contaminant UN No 1:*** | | | |
| ***Receiving Medium:*** | LAND | | |
| ***Receiving Environment:*** | | | |
| ***Incident Reason:*** | DAMAGE BY MOVING EQUIPMENT | | |
| ***Incident Summary:*** | BARTLETT TRANSPORT: 5L DIESEL SPILLED TO ASPHALT | | |
| ***Site Region:*** | | | |
| ***Site Municipality:*** | BURLINGTON CITY | | |

***Activity Preceding Spill:***
***Property 2nd Watershed:***
***Property Tertiary Watershed:***
***Sector Type:***
***SAC Action Class:***
***Source Type:***
***Site County/District:***
***Site Geo Ref Meth:***
***Site District Office:***
***Nearest Watercourse:***
***Site Name:***
***Site Address:***
***Client Name:***

---

***Site:*** ***Database:*** ***SPL***
***Walker's Line, South of Harvester's Road  Burlington ON***

| | | | |
|---|---|---|---|
| ***Ref No:*** | 1328-8PSTGJ | ***Contaminant Qty:*** | 0 other - see incident description |
| ***Site No:*** | | ***Nature of Damage:*** | |
| ***Incident Dt:*** | 12/22/2011 | ***Discharger Report:*** | |
| ***Year:*** | | ***Material Group:*** | |
| ***Incident Cause:*** | | ***Health/Env Conseq:*** | |
| ***Incident Event:*** | | ***Agency Involved:*** | |
| ***Environment Impact:*** | Confirmed | ***Site Lot:*** | |
| ***Nature of Impact:*** | Other Impact(s); Surface Water Pollution | ***Site Conc:*** | |
| ***MOE Response:*** | No Field Response | ***Site Geo Ref Accu:*** | |
| ***Dt MOE Arvl on Scn:*** | | ***Site Map Datum:*** | |
| ***MOE Reported Dt:*** | 12/22/2011 | ***Northing:*** | |
| ***Dt Document Closed:*** | | ***Easting:*** | |

***Municipality No:***
***System Facility Address:***
***Client Type:***
***Call Report Location Geodata:***
***Contaminant Code:*** 27
***Contaminant Name:*** DETERGENT FOAM
***Contaminant Limit 1:***
***Contam Limit Freq 1:***
***Contaminant UN No 1:***
***Receiving Medium:*** Sewage - Municipal/Private and Commercial
***Receiving Environment:***
***Incident Reason:***
***Incident Summary:*** Walker's Line vehicle Fire, foam to CB and poss tuck Creek
***Site Region:***
***Site Municipality:*** Burlington
***Activity Preceding Spill:***
***Property 2nd Watershed:***
***Property Tertiary Watershed:***
***Sector Type:*** Other
***SAC Action Class:*** Watercourse Spills
***Source Type:***
***Site County/District:***
***Site Geo Ref Meth:***
***Site District Office:***
***Nearest Watercourse:***
***Site Name:*** Walker's Line<UNOFFICIAL>
***Site Address:*** Walker's Line, South of Harvester's Road
***Client Name:***

---

***Site:*** ***UNKNOWN*** ***Database:*** ***SPL***
***APPELBY CREEK AT HARVESTER RD & PINEDALE RD BRIDGES.  BURLINGTON CITY ON***

| | | | |
|---|---|---|---|
| ***Ref No:*** | 141375 | ***Contaminant Qty:*** | |
| ***Site No:*** | | ***Nature of Damage:*** | |
| ***Incident Dt:*** | 5/3/1997 | ***Discharger Report:*** | |
| ***Year:*** | | ***Material Group:*** | |
| ***Incident Cause:*** | UNKNOWN | ***Health/Env Conseq:*** | |
| ***Incident Event:*** | | ***Agency Involved:*** | WORKS & FD. |

***Environment Impact:*** POSSIBLE
***Nature of Impact:*** Water course or lake
***MOE Response:***
***Dt MOE Arvl on Scn:***
***MOE Reported Dt:*** 5/3/1997
***Dt Document Closed:***
***Municipality No:*** 14101
***System Facility Address:***
***Client Type:***
***Call Report Location Geodata:***
***Contaminant Code:***
***Contaminant Name:***
***Contaminant Limit 1:***
***Contam Limit Freq 1:***
***Contaminant UN No 1:***
***Receiving Medium:*** WATER
***Receiving Environment:***
***Incident Reason:*** UNKNOWN
***Incident Summary:*** SOURCE UKN-OIL/GASOLINE LIKE ODOUR FROM CREEK, WORKS BOOMED CREEK.
***Site Region:***
***Site Municipality:*** BURLINGTON CITY
***Activity Preceding Spill:***
***Property 2nd Watershed:***
***Property Tertiary Watershed:***
***Sector Type:***
***SAC Action Class:***
***Source Type:***
***Site County/District:***
***Site Geo Ref Meth:***
***Site District Office:***
***Nearest Watercourse:***
***Site Name:***
***Site Address:***
***Client Name:***
***Site Lot:***
***Site Conc:***
***Site Geo Ref Accu:***
***Site Map Datum:***
***Northing:***
***Easting:***

---

***Site:***
***Mainway, East of Appleby Line Burlington ON***

***Database:*** ***SPL***

***Ref No:*** 8713-AB9RLC
***Site No:*** NA
***Incident Dt:*** 2016/06/25
***Year:***
***Incident Cause:***
***Incident Event:*** Overflow/Surcharge
***Environment Impact:***
***Nature of Impact:***
***MOE Response:*** No
***Dt MOE Arvl on Scn:***
***MOE Reported Dt:*** 2016/06/25
***Dt Document Closed:*** 2016/07/14
***Municipality No:***
***System Facility Address:***
***Client Type:***
***Call Report Location Geodata:***
***Contaminant Code:*** 44
***Contaminant Name:*** SEWAGE,RAW UNCHLORINATED
***Contaminant Limit 1:***
***Contam Limit Freq 1:***
***Contaminant UN No 1:***
***Receiving Medium:***
***Receiving Environment:*** Surface Water
***Incident Reason:*** Blockage
***Incident Summary:*** Region of Halton: 0.5m3 Raw Swg to CB and Road. Cleaned.
***Site Region:***
***Site Municipality:*** Burlington
***Activity Preceding Spill:***
***Property 2nd Watershed:***
***Property Tertiary Watershed:***
***Contaminant Qty:*** 0.5 $m^3$
***Nature of Damage:***
***Discharger Report:***
***Material Group:***
***Health/Env Conseq:***
***Agency Involved:***
***Site Lot:***
***Site Conc:***
***Site Geo Ref Accu:***
***Site Map Datum:***
***Northing:***
***Easting:***

***Sector Type:*** Municipal Sewage
***SAC Action Class:*** Land Spills
***Source Type:***
***Site County/District:***
***Site Geo Ref Meth:***
***Site District Office:***
***Nearest Watercourse:***
***Site Name:*** Manhole #MH7550<UNOFFICIAL>
***Site Address:*** Mainway, East of Appleby Line
***Client Name:***

---

***Site:*** ***Database:*** ***SPL***
***APPLEBY LINE & HEADON RD<UNOFFICIAL> Burlington ON***

| | | | |
|---|---|---|---|
| ***Ref No:*** | 7121-5SMMHV | ***Contaminant Qty:*** | 204.75 L |
| ***Site No:*** | | ***Nature of Damage:*** | |
| ***Incident Dt:*** | 10/24/2003 | ***Discharger Report:*** | |
| ***Year:*** | | ***Material Group:*** | Oil |
| ***Incident Cause:*** | | ***Health/Env Conseq:*** | |
| ***Incident Event:*** | | ***Agency Involved:*** | |
| ***Environment Impact:*** | Not Anticipated | ***Site Lot:*** | |
| ***Nature of Impact:*** | | ***Site Conc:*** | |
| ***MOE Response:*** | | ***Site Geo Ref Accu:*** | |
| ***Dt MOE Arvl on Scn:*** | | ***Site Map Datum:*** | |
| ***MOE Reported Dt:*** | 10/24/2003 | ***Northing:*** | |
| ***Dt Document Closed:*** | | ***Easting:*** | |

***Municipality No:***
***System Facility Address:***
***Client Type:***
***Call Report Location Geodata:***
***Contaminant Code:*** 13
***Contaminant Name:*** DIESEL FUEL
***Contaminant Limit 1:***
***Contam Limit Freq 1:***
***Contaminant UN No 1:***
***Receiving Medium:*** Land
***Receiving Environment:***
***Incident Reason:***
***Incident Summary:*** Appleby Line - 45 gallon diesel fuel to road
***Site Region:*** Central
***Site Municipality:*** Burlington
***Activity Preceding Spill:***
***Property 2nd Watershed:***
***Property Tertiary Watershed:***
***Sector Type:*** Transport Truck
***SAC Action Class:*** Spill to Highway (Accident)
***Source Type:***
***Site County/District:***
***Site Geo Ref Meth:***
***Site District Office:*** Halton-Peel
***Nearest Watercourse:***
***Site Name:*** APPLEBY LINE & HEADON RD<UNOFFICIAL>
***Site Address:***
***Client Name:***

---

***Site:*** ***GO TRANSIT*** ***Database:*** ***SPL***
***CREEK IN SHERWOOD FOREST PARK,OFF FAIRVIEW, EAST OF APPLEBY LINE STORAGE TANK BURLINGTON CITY ON***

| | | | |
|---|---|---|---|
| ***Ref No:*** | 16082 | ***Contaminant Qty:*** | |
| ***Site No:*** | | ***Nature of Damage:*** | |
| ***Incident Dt:*** | 3/20/1989 | ***Discharger Report:*** | |
| ***Year:*** | | ***Material Group:*** | |
| ***Incident Cause:*** | OTHER CONTAINER LEAK | ***Health/Env Conseq:*** | |
| ***Incident Event:*** | | ***Agency Involved:*** | HALTON SPILLS |
| ***Environment Impact:*** | | ***Site Lot:*** | |
| ***Nature of Impact:*** | | ***Site Conc:*** | |

***MOE Response:***
***Dt MOE Arvl on Scn:***
***MOE Reported Dt:*** 3/20/1989
***Dt Document Closed:***
***Municipality No:*** 14101
***System Facility Address:***
***Client Type:***
***Call Report Location Geodata:***
***Contaminant Code:***
***Contaminant Name:***
***Contaminant Limit 1:***
***Contam Limit Freq 1:***
***Contaminant UN No 1:***
***Receiving Medium:*** WATER
***Receiving Environment:***
***Incident Reason:*** OTHER
***Incident Summary:*** GO TRANSIT-DIESEL RUNOFF FROM BUS DEPOT TO CREEK
***Site Region:***
***Site Municipality:*** BURLINGTON CITY
***Activity Preceding Spill:***
***Property 2nd Watershed:***
***Property Tertiary Watershed:***
***Sector Type:***
***SAC Action Class:***
***Source Type:***
***Site County/District:***
***Site Geo Ref Meth:***
***Site District Office:***
***Nearest Watercourse:***
***Site Name:***
***Site Address:***
***Client Name:***
***Site Geo Ref Accu:***
***Site Map Datum:***
***Northing:***
***Easting:***

---

***Site:***
***at Harvester Rd Burlington ON***

***Database:*** ***SPL***

***Ref No:*** 5755-8M4LLW
***Site No:***
***Incident Dt:*** 9/27/2011
***Year:***
***Incident Cause:*** Other Discharges
***Incident Event:***
***Environment Impact:*** Confirmed
***Nature of Impact:*** Surface Water Pollution
***MOE Response:***
***Dt MOE Arvl on Scn:***
***MOE Reported Dt:*** 9/27/2011
***Dt Document Closed:***
***Municipality No:***
***System Facility Address:***
***Client Type:***
***Call Report Location Geodata:***
***Contaminant Code:***
***Contaminant Name:***
***Contaminant Limit 1:***
***Contam Limit Freq 1:***
***Contaminant UN No 1:***
***Receiving Medium:***
***Receiving Environment:***
***Incident Reason:***
***Incident Summary:*** Tuck Creek: sheen on water, strong odour
***Site Region:***
***Site Municipality:*** Burlington
***Activity Preceding Spill:***
***Property 2nd Watershed:***
***Property Tertiary Watershed:***
***Sector Type:*** Unknown
***SAC Action Class:*** Watercourse Spills
***Contaminant Qty:***
***Nature of Damage:***
***Discharger Report:***
***Material Group:***
***Health/Env Conseq:***
***Agency Involved:***
***Site Lot:***
***Site Conc:***
***Site Geo Ref Accu:***
***Site Map Datum:***
***Northing:***
***Easting:***

***Source Type:***
***Site County/District:***
***Site Geo Ref Meth:***
***Site District Office:***
***Nearest Watercourse:***
***Site Name:*** Tuck Creek:<UNOFFICIAL>
***Site Address:*** at Harvester Rd
***Client Name:***

---

***Site:*** ***ROTHSAY***
***QEW WESTBOUND, JUST PAST THE APPLEBY LINE ONRAMP TRANSPORT TRUCK (CARGO) BURLINGTON CITY ON***

***Database:*** ***SPL***

***Ref No:*** 233395
***Site No:***
***Incident Dt:*** 7/25/2002
***Year:***
***Incident Cause:*** OTHER TRANSPORTATION ACCIDENT
***Incident Event:***
***Environment Impact:*** NOT ANTICIPATED
***Nature of Impact:***
***MOE Response:***
***Dt MOE Arvl on Scn:***
***MOE Reported Dt:*** 7/25/2002
***Dt Document Closed:***
***Municipality No:*** 14101
***System Facility Address:***
***Client Type:***
***Call Report Location Geodata:***
***Contaminant Code:***
***Contaminant Name:***
***Contaminant Limit 1:***
***Contam Limit Freq 1:***
***Contaminant UN No 1:***
***Receiving Medium:*** LAND
***Receiving Environment:***
***Incident Reason:*** UNKNOWN
***Incident Summary:*** QEW WESTBOUND,WEST OF APPLEBY LINE, ROTHSAY CARGO SPILL
***Site Region:***
***Site Municipality:*** BURLINGTON CITY
***Activity Preceding Spill:***
***Property 2nd Watershed:***
***Property Tertiary Watershed:***
***Sector Type:***
***SAC Action Class:***
***Source Type:***
***Site County/District:***
***Site Geo Ref Meth:***
***Site District Office:***
***Nearest Watercourse:***
***Site Name:***
***Site Address:***
***Client Name:***

***Contaminant Qty:***
***Nature of Damage:***
***Discharger Report:***
***Material Group:***
***Health/Env Conseq:***
***Agency Involved:*** OPP, F.D.
***Site Lot:***
***Site Conc:***
***Site Geo Ref Accu:***
***Site Map Datum:***
***Northing:***
***Easting:***

---

***Site:*** ***BURLINGTON HYDRO-ELECTRIC COMM***
***4316 DAIRY RD, WEST OF APPLEBY LINE TRANSFORMER BURLINGTON CITY ON***

***Database:*** ***SPL***

***Ref No:*** 159438
***Site No:***
***Incident Dt:*** 8/26/1998
***Year:***
***Incident Cause:*** COOLING SYSTEM LEAK
***Incident Event:***
***Environment Impact:*** CONFIRMED
***Nature of Impact:*** Soil contamination
***MOE Response:***
***Dt MOE Arvl on Scn:***

***Contaminant Qty:***
***Nature of Damage:***
***Discharger Report:***
***Material Group:***
***Health/Env Conseq:***
***Agency Involved:***
***Site Lot:***
***Site Conc:***
***Site Geo Ref Accu:***
***Site Map Datum:***

***MOE Reported Dt:*** 8/26/1998
***Dt Document Closed:***
***Municipality No:*** 14101
***System Facility Address:***
***Client Type:***
***Call Report Location Geodata:***
***Contaminant Code:***
***Contaminant Name:***
***Contaminant Limit 1:***
***Contam Limit Freq 1:***
***Contaminant UN No 1:***
***Receiving Medium:*** LAND
***Receiving Environment:***
***Incident Reason:*** OTHER
***Incident Summary:*** BURLINGTON HYDRO-77L NON-PCB TRANSFORMER OIL TO SOIL ONLY. CLEANING.
***Site Region:***
***Site Municipality:*** BURLINGTON CITY
***Activity Preceding Spill:***
***Property 2nd Watershed:***
***Property Tertiary Watershed:***
***Sector Type:***
***SAC Action Class:***
***Source Type:***
***Site County/District:***
***Site Geo Ref Meth:***
***Site District Office:***
***Nearest Watercourse:***
***Site Name:***
***Site Address:***
***Client Name:***
***Northing:***
***Easting:***

# Appendix: Database Descriptions

*Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update.* ***Note:*** *Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.*

***Abandoned Aggregate Inventory:*** Provincial AAGR

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

***Government Publication Date: Sept 2002****

***Aggregate Inventory:*** Provincial AGR

The Ontario Ministry of Northern Development, Mines, Natural Resources and Forestry (ONDMNRF) maintains this database of pits and quarries. The database provides information regarding the registered owner/operator, location name, operation type, approval type, and maximum annual tonnage.

***Government Publication Date: Up to Oct 2022***

***Abandoned Mine Information System:*** Provincial AMIS

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

***Government Publication Date: 1800-Mar 2022***

***Anderson's Waste Disposal Sites:*** Private ANDR

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

***Government Publication Date: 1860s-Present***

***Aboveground Storage Tanks:*** Provincial AST

Historical listing of aboveground storage tanks made available by the Department of Natural Resources and Forestry. Includes tanks used to hold water or petroleum. This dataset has been retired as of September 25, 2014 and will no longer be updated.

***Government Publication Date: May 31, 2014***

***Automobile Wrecking & Supplies:*** Private AUWR

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

***Government Publication Date: 1999-Feb 28, 2022***

***Borehole:*** Provincial BORE

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

***Government Publication Date: 1875-Jul 2018***

***Certificates of Approval:*** Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

***Government Publication Date: 1985-Oct 30, 2011****

***Dry Cleaning Facilities:*** Federal CDRY

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.

***Government Publication Date: Jan 2004-Dec 2021***

***Commercial Fuel Oil Tanks:*** Provincial CFOT

Locations of commercial underground fuel oil tanks. This is not a comprehensive or complete inventory of commercial fuel tanks in the province; this listing is a copy of records of registered commercial underground fuel oil tanks obtained under Access to Public Information.
Note that the following types of tanks do not require registration: waste oil tanks in apartments, office buildings, residences, etc.; aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

***Government Publication Date: Feb 28, 2022***

***Chemical Manufacturers and Distributors:*** Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

***Government Publication Date: 1999-Jan 31, 2020***

***Chemical Register:*** Private CHM

This database includes a listing of locations of facilities within the Province or Territory that either manufacture and/or distributes chemicals.

***Government Publication Date: 1999-Feb 28, 2023***

***Compressed Natural Gas Stations:*** Private CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

***Government Publication Date: Dec 2012 -May 2023***

***Inventory of Coal Gasification Plants and Coal Tar Sites:*** Provincial COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

***Government Publication Date: Apr 1987 and Nov 1988****

***Compliance and Convictions:*** Provincial CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

***Government Publication Date: 1989-Apr 2023***

***Certificates of Property Use:*** Provincial CPU

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

***Government Publication Date: 1994 - Jun 30, 2023***

***Drill Hole Database:*** Provincial DRL

The Ontario Drill Hole Database contains information on more than 113,000 percussion, overburden, sonic and diamond drill holes from assessment files on record with the department of Mines and Minerals. Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted to the MNDM. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

***Government Publication Date: 1886 - Oct 2022***

***Delisted Fuel Tanks:*** Provincial DTNK

List of fuel storage tank sites that were once found in - and have since been removed from - the list of fuel storage tanks made available by the regulatory agency under Access to Public Information.

***Government Publication Date: Feb 28, 2022***

***Environmental Activity and Sector Registry:*** Provincial EASR

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval), Please see our ECA database.

***Government Publication Date: Oct 2011- Jun 30, 2023***

***Environmental Registry:*** Provincial EBR

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

***Government Publication Date: 1994 - Jun 30, 2023***

***Environmental Compliance Approval:*** Provincial ECA

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

***Government Publication Date: Oct 2011- Jun 30, 2023***

***Environmental Effects Monitoring:*** Federal EEM

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

***Government Publication Date: 1992-2007****

***ERIS Historical Searches:*** Private EHS

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

***Government Publication Date: 1999-Jun 30, 2023***

***Environmental Issues Inventory System:*** Federal EIIS

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

***Government Publication Date: 1992-2001****

***Emergency Management Historical Event:*** Provincial EMHE

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

***Government Publication Date: Apr 30, 2022***

***Environmental Penalty Annual Report:*** Provincial EPAR

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment and Climate Change. These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

***Government Publication Date: Jan 1, 2011 - Dec 31, 2022***

***List of Expired Fuels Safety Facilities:*** Provincial EXP

List of facilities and tanks for which there was once a fuel registration. This is not a comprehensive or complete inventory of expired tanks/tank facilities in the province; this listing is a copy of previously registered tanks and facilities obtained under Access to Public Information. Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc; includes tanks which have been removed from the ground.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

***Government Publication Date: Feb 28, 2022***

***Federal Convictions:*** Federal FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

***Government Publication Date: 1988-Jun 2007****

***Contaminated Sites on Federal Land:*** Federal FCS

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government. Includes fire training sites and sites at which Per- and Polyfluoroalkyl Substances (PFAS) are a concern.

***Government Publication Date: Jun 2000-Mar 2023***

***Fisheries & Oceans Fuel Tanks:*** Federal FOFT

Fisheries & Oceans Canada maintains an inventory of aboveground & underground fuel storage tanks located on Fisheries & Oceans property or controlled by DFO. Our inventory provides information on the site name, location, tank owner, tank operator, facility type, storage tank location, tank contents & capacity, and date of tank installation.

***Government Publication Date: 1964-Sep 2019***

***Federal Identification Registry for Storage Tank Systems (FIRSTS):*** Federal FRST

A list of federally regulated Storage tanks from the Federal Identification Registry for Storage Tank Systems (FIRSTS). FIRSTS is Environment and Climate Change Canada's database of storage tank systems subject to the Storage Tank for Petroleum Products and Allied Petroleum Products Regulations. The main objective of the Regulations is to prevent soil and groundwater contamination from storage tank systems located on federal and aboriginal lands. Storage tank systems that do not have a valid identification number displayed in a readily visible location on or near the storage tank system may be refused product delivery.

***Government Publication Date: May 31, 2018***

***Fuel Storage Tank:*** Provincial FST

List of registered private and retail fuel storage tanks. This is not a comprehensive or complete inventory of private and retail fuel storage tanks in the province; this listing is a copy of registered private and retail fuel storage tanks, obtained under Access to Public Information.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

***Government Publication Date: Feb 28, 2022***

***Fuel Storage Tank - Historic:*** Provincial FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

***Government Publication Date: Pre-Jan 2010****

***Ontario Regulation 347 Waste Generators Summary:*** Provincial GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

***Government Publication Date: 1986-Oct 31, 2022***

***Greenhouse Gas Emissions from Large Facilities:*** Federal GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO2 eq).

***Government Publication Date: 2013-Dec 2019***

***TSSA Historic Incidents:*** Provincial HINC

List of historic incidences of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen recorded by the TSSA in their previous incident tracking system. The TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of historical fuel spills and leaks in the province. This listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

***Government Publication Date: 2006-June 2009****

***Indian & Northern Affairs Fuel Tanks:*** Federal IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

***Government Publication Date: 1950-Aug 2003****

***Fuel Oil Spills and Leaks:*** Provincial INC

Listing of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen reported to the Spills Action Centre (SAC). This is not a comprehensive or complete inventory of fuel-related leaks, spills, and incidents in the province; this listing in a copy of incidents reported to the SAC, obtained under Access to Public Information. Includes incidents from fuel-related hazards such as spills, fires, and explosions. Records are not verified for accuracy or completeness.

***Government Publication Date: Feb 28, 2022***

***Landfill Inventory Management Ontario:*** Provincial LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the Ministry of the Environment, Conservation and Parks compiles new and updated information. Includes small and large landfills currently operating as well as those which are closed and historic. Operators of larger landfills provide landfill information for the previous operating year to the ministry for LIMO including: estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills include information such as site owner, site location and certificate of approval # and status.

***Government Publication Date: Mar 21, 2022***

***Canadian Mine Locations:*** Private MINE

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

***Government Publication Date: 1998-2009****

***Mineral Occurrences:*** Provincial MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

***Government Publication Date: 1846-Feb 2023***

***National Analysis of Trends in Emergencies System (NATES):*** Federal NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

***Government Publication Date: 1974-1994****

***Non-Compliance Reports:*** Provincial NCPL

The Ministry of the Environment provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act.

***Government Publication Date: Dec 31, 2021***

***National Defense & Canadian Forces Fuel Tanks:*** Federal NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

***Government Publication Date: Up to May 2001****

***National Defense & Canadian Forces Spills:*** Federal NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

***Government Publication Date: Mar 1999-Oct 2022***

***National Defence & Canadian Forces Waste Disposal Sites:*** Federal NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

***Government Publication Date: 2001-Apr 2007****

***National Energy Board Pipeline Incidents:*** Federal NEBI

Locations of pipeline incidents from 2008 to present, made available by the Canada Energy Regulator (CER) - previously the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

***Government Publication Date: 2008-Jun 30, 2021***

***National Energy Board Wells:*** Federal NEBP

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release date.

***Government Publication Date: 1920-Feb 2003****

***National Environmental Emergencies System (NEES):*** Federal NEES

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December 2004.

***Government Publication Date: 1974-2003****

***National PCB Inventory:*** Federal NPCB

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

***Government Publication Date: 1988-2008****

***National Pollutant Release Inventory 1993-2020:*** Federal NPR2

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of pollutant releases (to air, water and land), disposals, and transfers for recycling. The inventory, managed by Environment and Climate Change Canada, tracks over 300 substances. Under the authority of the Canadian Environmental Protection Act (CEPA), owners or operators of facilities that meet published reporting requirements are required to report to the NPRI.

***Government Publication Date: Sep 2020***

***National Pollutant Release Inventory - Historic:*** Federal NPRI

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances. This data holds historic records; current records are found in NPR2.

***Government Publication Date: 1993-May 2017***

***Oil and Gas Wells:*** Private OGWE

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

***Government Publication Date: 1988-May 31, 2023***

***Ontario Oil and Gas Wells:*** Provincial OOGW

In 1998, the MNR handed over to the Ontario Oil, Gas and Salt Resources Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database include well owner/operator, location, permit issue date, and well cap date, license No., status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provide for each well record.

***Government Publication Date: 1800-Aug 2021***

***Inventory of PCB Storage Sites:*** Provincial OPCB

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

***Government Publication Date: 1987-Oct 2004; 2012-Dec 2013***

***Orders:*** Provincial ORD

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

***Government Publication Date: 1994 - Jun 30, 2023***

***Canadian Pulp and Paper:*** Private PAP

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

***Government Publication Date: 1999, 2002, 2004, 2005, 2009-2014***

***Parks Canada Fuel Storage Tanks:*** Federal PCFT

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

***Government Publication Date: 1920-Jan 2005****

***Pesticide Register:*** Provincial PES

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

***Government Publication Date: Oct 2011- Jun 30, 2023***

***Pipeline Incidents:*** Provincial PINC

List of pipeline incidents (strikes, leaks, spills). This is not a comprehensive or complete inventory of pipeline incidents in the province; this listing in an historical copy of records previously obtained under Access to Public Information. Records are not verified for accuracy or completeness.

***Government Publication Date: Feb 28, 2021***

***Private and Retail Fuel Storage Tanks:*** Provincial PRT

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

***Government Publication Date: 1989-1996****

***Permit to Take Water:*** Provincial PTTW

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include PTTW's on the registry such as OWRA s. 34 - Permit to take water.

***Government Publication Date: 1994 - Jun 30, 2023***

***Ontario Regulation 347 Waste Receivers Summary:*** Provincial REC

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

***Government Publication Date: 1986-1990, 1992-2021***

***Record of Site Condition:*** Provincial RSC

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up.
RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09).

***Government Publication Date: 1997-Sept 2001, Oct 2004-May 2023***

***Retail Fuel Storage Tanks:*** Private RST

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

***Government Publication Date: 1999-Feb 28, 2023***

***Scott's Manufacturing Directory:*** Private SCT

Scott's Directories is a data bank containing information on over 200,000 manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, and main products are included in this database.

***Government Publication Date: 1992-Mar 2011****

***Ontario Spills:*** Provincial SPL

List of spills and incidents made available the Ministry of the Environment, Conservation and Parks. This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X. The Ministry of the Environment, Conservation and Parks cites the coronavirus pandemic as an explanation for delays in releasing data pursuant to requests.

***Government Publication Date: 1988-Oct 2021***

***Wastewater Discharger Registration Database:*** Provincial SRDS

Facilities that report either municipal treated wastewater effluent or industrial wastewater discharges under the Effluent Monitoring and Effluent Limits (EMEL) and Municipal/Industrial Strategy for Abatement Regulations. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment keeps record of direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation, Mining, Petroleum Refining, Organic Chemicals, Inorganic Chemicals, Pulp & Paper, Metal Casting, Iron & Steel, and Quarries.

***Government Publication Date: 1990-Dec 31, 2020***

***Anderson's Storage Tanks:*** Private TANK

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

***Government Publication Date: 1915-1953****

***Transport Canada Fuel Storage Tanks:*** Federal TCFT

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

***Government Publication Date: 1970 - Apr 2020***

***Variances for Abandonment of Underground Storage Tanks:*** Provincial VAR

Listing of variances granted for storage tank abandonment. This is not a comprehensive or complete inventory of tank abandonment variances in the province; this listing is a copy of tank abandonment variance records previously obtained under Access to Public Information. In Ontario, registered underground storage tanks must be removed within two years of disuse; if removal of a tank is not feasible, an application may be sought for a variance from this code requirement.
Records are not verified for accuracy or completeness.

***Government Publication Date: Feb 28, 2022***

***Waste Disposal Sites - MOE CA Inventory:*** Provincial WDS

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

***Government Publication Date: Oct 2011- Jun 30, 2023***

***Waste Disposal Sites - MOE 1991 Historical Approval Inventory:*** Provincial WDSH

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

***Government Publication Date: Up to Oct 1990****

***Water Well Information System:*** Provincial WWIS

This database describes locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table.

***Government Publication Date: Mar 31 2023***

# Definitions

***Database Descriptions:*** This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

***Detail Report***: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

***Distance:*** The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

***Direction:*** The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

***Elevation:*** The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

***Executive Summary:*** This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

***Map Key:*** The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

***Unplottables:*** These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

# HISTORICAL AERIALS

**Project Property:** PH I ESA
5051 Harvester Road
Burlington ON L7L 5Y7

**Project No:**

**Requested By:** Fisher Engineering Limited

**Order No:** 23081700823

**Date Completed:** August 24,2023

Aerial Maps included in this report are produced by the sources listed above and are to be used for research purposes including a phase I report. Maps are not to be resold as commercial property. ERIS provides no warranty of accuracy or liability. The information contained in this report has been produced using aerial photos listed in above sources by ERIS Information Inc. (in the US) and ERIS Information Limited Partnership (in Canada), both doing business as 'ERIS'. The maps contained in this report do not purport to be and do not constitute a guarantee of the accuracy of the information contained herein. Although ERIS has endeavored to present information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

**Environmental Risk Information Services**
*A division of Glacier Media Inc.*
1.866.517.5204 | info@erisinfo.com | erisinfo.com

| Date | Source | Scale | Comments |
|---|---|---|---|
| 2022 | MAXAR TECHNOLOGIES | 10,000 | |
| 1990 | Decade Coverage Unavailable | 10,000 | |
| 1988 | National Air Photo Library | 10,000 | Best Adjacent Decade Available |
| 1974 | National Air Photo Library | 10,000 | |
| 1960 | National Air Photo Library | 10,000 | |
| 1950 | Decade Coverage Unavailable | 10,000 | |




Year: 2022
Source: MAXAR
Scale: 10,000
Comment:

Address: 5051 Harvester Road, Burlington, ON
Approx Center: -79.7674121,43.3791272

Order No: 23081700823

ERIS




Year: 1988
Source: NAPL
Scale: 10,000
Comment: Best Adjacent Decade Available

Address: 5051 Harvester Road, Burlington, ON
Approx Center: -79.7674121,43.3791272

Order No: 23081700823

ERIS




Year: 1974
Source: NAPL
Scale: 10,000
Comment:

Address: 5051 Harvester Road, Burlington, ON
Approx Center: -79.7674121,43.3791272

Order No: 23081700823

ERIS




Year: 1960
Source: NAPL
Scale: 10,000
Comment:

Address: 5051 Harvester Road, Burlington, ON
Approx Center: -79.7674121,43.3791272

Order No: 23081700823

ERIS

Ontario


**Ministry of Natural Resources and Forestry**

Make-a-Map: Natural Heritage Areas

# 5051 Harvester Road, Burlington, Ontario

Map created: 9/12/2023

**Notes:**




## Legend

- Assessment Parcel
- Greenbelt Area Boundary
- Greenbelt Hamlets
- ORM Boundary
- NEP Boundary
- Greenbelt External Connections
- NEP Parks and Open Space System
- NEP Minor Urban Centres
- ANSI
- Earth Science Provincially Significant/sciences de la terre d'importance provinciale
- Earth Science Regionally Significant/sciences de la terre d'importance régionale
- Life Science Provincially Significant/sciences de la vie d'importance provinciale
- Life Science Regionally Significant/sciences de la vie d'importance régionale
- Evaluated Wetland
- Provincially Significant/considérée d'importance provinciale
- Non-Provincially Significant/non considérée d'importance provinciale
- Unevaluated Wetland
- Woodland
- Conservation Reserve
- Provincial Park
- Greenbelt Towns and Villages
- ORM Land Use Designation
- Countryside Area/zone de campagne
- Natural Core Area/zone centrale naturelle
- Natural Linkage Area/lien naturel
- Palgrave Estates Residential Community/communauté résidentielle de Palgrave Estates
- Rural Settlement/zone de peuplement rurale
- Settlement Area/zone de peuplement
- NEP Land Use Designation
- Escarpment Natural Area/zone naturelle de l'escarpement
- Escarpment Protection Area/zone protégée l'escarpement
- Escarpment Recreation Area/zone récréative de l'escarpement
- Escarpment Rural Area/zone rurale de l'escarpement
- Mineral Resource Extraction Area/zone d'extraction de resources minérales
- Urban Area/zone urbaine
- Natural Heritage System
- Greenbelt Specialty Crop Area
- Greenbelt Land Use Designation
- Protected Countryside/campagne protégé
- Urban River Valley/vallée fluviale urbaine

0 0.3 Kilometres

This map should not be relied on as a precise indicator of routes or locations, nor as a guide to navigation. The Ontario Ministry of Natural Resources and Forestry(OMNRF) shall not be liable in any way for the use of, or reliance upon, this map or any information on this map.

© Copyright for Ontario Parcel data is held by King's Printer for Ontario and its licensors and may not be reproduced without permission. THIS IS NOT A PLAN OF SURVEY.

Absence of a feature in the map does not mean they do not exist in this area.


Imagery Copyright Notices: DRAPE © Aéro-Photo (1961) Inc., 2008 - 2009

GTA 2005 / SWOOP 2006 / Simcoe-Muskoka-Dufferin © FirstBase Solutions, 2005 / 2006 / 2008

© King's Printer for Ontario, 2023

Projection: Web Mercator






opta
INFORMATION INTELLIGENCE

# enviroscan







An SCM Company

175 Commerce Valley Drive W
Markham, Ontario L3T 7Z3

T: 905-882-6300
W: www.optaintel.ca

Report Completed By:

**Midori**

Site Address:

**5051 Harvester Road, Burlington, ON, Canada**

Project No:

Requested by:

**Lena Johnston**
**Fisher Engineering Ltd**

Opta Order ID:

**132658**

Date Completed:


**8/22/2023 6:54:24 AM**

# ENVIROSCAN Report

**Search Area: 5051 Harvester Road, Burlington, ON, Canada**

**Requested by:**
Lena Johnston
Date Completed: 08/22/2023 06:54:24

enviroscan
OPTA INFORMATION INTELLIGENCE




This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

# Opta Historical Environmental Services Enviroscan™ Terms and Conditions

## Report

The documents (hereinafter referred to as the "Documents") to be released as part of the report (hereinafter referred to as the "Report") to be delivered to the purchaser as set out above are documents in Opta's records relating to the described property (hereinafter referred to as the "Property"). Opta makes no representations or warranties respecting the Documents whatsoever, including, without limitation, with respect to the completeness, accuracy or usefulness of the Documents, and does not represent or warrant that these are the only plans and reports prepared in association with the Property or in Opta's possession at the time of Report delivery to the purchaser. The Documents are current as of the date(s) indicated on them. Interpretation of the Documents, if any, is by inference based upon the information which is apparent and obvious on the face of the Documents only. Opta does not represent, warrant or guarantee that interpretations other than those referred to do not exist from other sources. The Report will be prepared for use by the purchaser of the services as shown above hereof only.

## Disclaimer

Opta disclaims responsibility for any losses or damages of any kind whatsoever, whether consequential or other, however caused, incurred or suffered, arising directly or indirectly as a result of the services (which services include, but are not limited to, the preparation of the Report provided hereunder), including but not limited to, any losses or damages arising directly or indirectly from any breach of contract, fundamental or otherwise, from reliance on Opta Reports or from any tortious acts or omissions of Opta's agents, employees or representatives.

## Entire Agreement

The parties hereto acknowledge and agree to be bound by the terms and conditions hereof. The request form constitutes the entire agreement between the parties pertaining to the subject matter hereof and supersedes all prior and contemporaneous agreements, negotiations and discussions, whether oral or written, and there are no representations or warranties, or other agreements between the parties in connection with the subject matter hereof except as specifically set forth herein. No supplement, modification, waiver, or termination of the request shall be binding, unless confirmed in writing by the parties hereto.


## Governing Document

In the event of any conflicts or inconsistencies between the provisions hereof and the Reports, the rights and obligations of the parties shall be deemed to be governed by the request form, which shall be the paramount document.

## Law

This agreement shall be governed by and construed in accordance with the laws of the Province of Ontario and the laws of Canada applicable therein.

# 5051 Harvester Road, Burlington




**Legend**

- Issue Contributing Areas
- WHPA-E
- Wellhead Protection Area
  - A
  - B
  - C
  - C1
  - D
  - F
- Intake Protection Zone 1
- Event Based Areas
- Intake Protection Zone 2
- Source Protection Areas

This map should not be relied on as a precise indicator of routes or locations, nor as a guide to navigation. The Ontario Ministry of Environment, Conservation and Parks (MECP) shall not be liable in any way for the use or any information on this map. of, or reliance upon, this map.

Ontario

© King's Printer for Ontario and its licensors, 2023

May Not be Reproduced without Permission.
THIS IS NOT A PLAN OF SURVEY.

Map Created: 8/22/2023
Map Center: 43.37968 N, -79.76729 W

# APPENDIX C – SITE PHOTOGRAPHS



1. View of southern portion of the Site, facing east.



2. View of central portion of the Site, facing east.



3. View of western portion of the Site, facing west.



4. View of northern portion of the Site facing north.




5. View of Subject Building, facing south.



6. View of interior of Subject Building.

# APPENDIX D – DOCUMENTATION OF INTERVIEW

# Phase I ESA Documentation of Interviews

Interviewed Participants:

(a) **Current Site Owner** – Dymon Group of Companies

| | |
|---|---|
| Date, Time and Duration of Interview: | August 29, 2023, |
| Method and Place of Interview: | In writing |
| Name of Person: | Mr. James Byck |
| Reason for Person Selection: | Person with detailed knowledge of current site activities. |

| Key Questions: | Answers: |
|---|---|
| 1. Have a Phase I ESA, Phase II ESA and/or other reports been previously conducted for the Site, when, and are they available for review? | None |
| 2. What is (was) the main current (past) activity conducted at the Site? Since when? | The site building is currently occupied by Tim Hortons and Wendy's. |
| 3. Was there any construction activity conducted at the site in the past years? | None |
| 4. Are there any company records available for review, such as: site plans, process control diagrams, utility drawings, inventory of chemicals, MSDS, waste management records? | None |
| 5. Do you have knowledge of any current or former underground or aboveground storage tanks, and their location at the site? | None |
| 6. Are there any spill reporting and emergency response plans, asbestos surveys and C of A available? | None |
| 7. Do you have knowledge of any activities and events occurred at neighboring properties that may have affected their environmental condition? | None |