PHASE ONE ENVIRONMENTAL SITE ASSESSMENT

1026 Cooke Boulevard, Burlington, Ontario

Client

Ms. Kathleen Dryden
Halton Standard Condominium Corporation No. 416
71095 Maplehurst Plaza
Burlington, Ontario, L7T 4J8

Project Number

BIGC-ENV-605A

Prepared By:

B.I.G. Consulting Inc
12-5500 Tomken Road
Mississauga, Ontario, L4W 2Z4
T: 416.214.4880
www.bigconsultinginc.com

Date Submitted

July 12, 2023

Table of Contents

1. Executive Summary 1
2. Introduction 4
2.1 Phase One Property Information 4
3. Scope of Investigation 6
4. Records Review 7
4.1 General 7
4.2 Environmental Source Information 11
4.3 Physical Setting Sources 20
4.4 Site Operating Records 23
5. Interviews 24
6. Site Reconnaissance 25
6.1 General Requirements 25
6.2 Specific Observations at Phase One ESA Property 25
6.3 Written Description of Investigation 28
7. Review and Evaluation of Information 29
7.1 Current and Past Uses 29
7.2 Potentially Contaminating Activities (PCAs) 29
7.3 Areas of Potential Environmental Concern (APECs) 31
7.4 Phase One ESA Conceptual Site Model 33
8. Conclusions 38
8.1 Whether Phase Two Environment Site Assessment Required Before RSC Submission 38
8.2 Record of Site Condition Based on Phase One Environmental Site Assessment Alone 38
8.3 Signatures 38
9. References 39

List of Figures

Figure 1	Site Location Plan
Figure 2	Phase One Study Area and Potentially Contaminating Activities (PCAs)
Figure 3	Site Plan and Areas of Potential Environmental Concern (APECs)

List of Tables

Table I	Site Environmental Setting Data
Table II	Current and Past Land Uses
Table III	Potentially Contaminating Activities (PCAs)
Table IV	Areas of Potential Environmental Concern (APECs)

List of Appendices

Appendix A	Limitation of Liability, Scope of Report, and Third-Party Reliance
Appendix B	Legal Survey Plan
Appendix C	Qualification of Assessors
Appendix D	Chain of Title Search
Appendix E	Ecolog ERIS Report
Appendix F	City Directory Summary
Appendix G	Other Government Records
Appendix H	Aerial Photographs/Fire Insurance Plans
Appendix I	Site Photographs

Abbreviations and Acronyms

°C	degree Celsius
ANSI	Area of Natural and Scientific Interest
APEC	Area of Potential Environmental Concern
AST	Aboveground Storage Tank
BESR	Brownfields Environmental Site Registry
BIG	B.I.G. Consulting Inc.
BTEX	Benzene, Toluene, Ethylbenzene and Xylenes
CPU	Certificate of Property Use
EBR	Environmental Bill of Rights
EC	Electrical Conductivity
ECA	Environmental Compliance Approval
EPA	Environmental Protection Act
ERIS	Environmental Risk Information Services Ltd.
ESA	Environmental Site Assessment
EASR	Environmental Activity and Sector Registry
FIP	Fire Insurance Plan
FOI	Freedom of Information
ha	hectare(s)
L	litre(s)
m	metre(s)
m asl	metres above sea level
m bgs	metres below ground surface
MECP	Ministry of Environment, Conservation and Parks
PAH	Polycyclic Aromatic Hydrocarbon(s)
PCA	Potentially Contaminating Activity
PCB	Polychlorinated biphenyl
PHC	Petroleum Hydrocarbon(s)
PM	Particulate Matter
QPESA	Qualified Person for Environmental Site Assessment
RSC	Record of Site Condition
SAR	Sodium Adsorption Ratio
SCS	Site Condition Standard
SDS	Safety Data Sheet
TSSA	Technical Standards & Safety Authority
UST	Underground Storage Tank
VOC	Volatile Organic Compound(s)

1. Executive Summary

B.I.G. Consulting Inc. (BIG) was retained by Halton Standard Condominium Corporation No. 416 (Client), to complete a Phase One Environmental Site Assessment (ESA) at the property located at 1026 Cooke Boulevard, in Burlington, Ontario (Site), as shown on Figure 1. The objective of the investigation was to support the filing of a Record of Site Condition (RSC) in accordance with Ontario Regulation 153/04 (O.Reg.153/04), as amended. It is BIG's understanding that the Site will be redeveloped for residential purposes in the future, which would require an RSC.

A Phase One ESA is a systematic qualitative process to assess the environmental condition of a site based on its historical and current uses. This Phase One ESA was conducted in accordance with O.Reg.153/04 and in accordance with generally accepted professional practices.

The Site is located to the west of Cooke Boulevard and north of Plains Road East, in Burlington, Ontario, as shown on Figure 1. For simplicity of the description in this report, Cooke Boulevard is considered running north-south. The Site is rectangular in shape and measures approximately 3,200 m² in size. The Site is currently occupied by a slab-on-grade two-storey commercial building (the Site building). The Site building has a footprint of approximately 1,275 m^2 and occupy approximately 40 % of the Site. The areas surrounding the Site buildings are covered with landscaping and asphalt.

Please note that general environmental management and housekeeping practices were reviewed as part of this assessment insofar as they could impact the environmental condition of the Site. However, a detailed review of regulatory compliance issues was beyond the scope of our investigation. Based on the Phase One ESA findings, the following information is provided in support of the Qualified Person's conclusion:

APEC	Location of APEC on Phase One Property	PCA	Location of PCA (On-Site or Off-Site)	Contaminants of Concern	Media Potentially Impacted (Groundwater, soil and/or sediment)
APEC 1: Importation of unknown quality of fill material	Entire Site	#30 – Importation of Fill Material of Unknown Quality	On-Site	PAHs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Soil and Groundwater
APEC 2: De-icing salts usage	Exterior of the Site Building	"Other" – Usage of De-icing Salts	On-Site	Electrical Conductivity, SAR, Na and Cl-	Soil and Groundwater
APEC 3: Former chemical product manufacturer	Northern portion	#8 – Chemical Manufacturing, Processing and Bulk Storage	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater
APEC 4: Former print shop	Southwestern portion	#31 – Ink Manufacturing, Processing and Bulk Storage	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater
APEC 5: Former auto services	Southeastern portion	#10 – Commercial Autobody Shops	Off-Site	PHCs, BTEX and VOCs	Groundwater

APEC	Location of APEC on Phase One Property	PCA	Location of PCA (On-Site or Off-Site)	Contaminants of Concern	Media Potentially Impacted (Groundwater, soil and/or sediment)
APEC 6: Former UST	Southeastern portion	#28 – Gasoline and Associated Products Storage in Fixed Tanks	Off-Site	PHCs and BTEX	Groundwater
APEC 7: Former dry cleaner	Southwestern portion	#37 – Operation of Dry-Cleaning Equipment (where chemicals are used)	Off-Site	VOCs	Groundwater
APEC 8: Former semiconductor and other electronic component manufacturer	Northeastern portion	#19 – Electronic and Computer Equipment Manufacturing	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater
APEC 9: Former semiconductor and other electronic component manufacturer	Northern portion	#19 – Electronic and Computer Equipment Manufacturing	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater
APEC 10: Former plastic product manufacturer	Northern portion	#43 – Plastics (including Fibreglass) Manufacturing and Processing	Off-Site	VOCs	Groundwater
APEC 11: Former electronic parts manufacturer	Northern portion	#19 – Electronic and Computer Equipment Manufacturing	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater
APEC 12: Print shop	Northern portion	#31 – Ink Manufacturing, Processing and Bulk Storage	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater

1) *Area of Potential Environmental Concern (APEC) means the area on, in or under a Phase One Study Area where one or more contaminants are potentially present, as determined through the Phase One ESA, including through:*
   a) identification of post or current uses on, in or under the phase one property, and
   b) identification of potentially contaminating activities.
2) *Potentially contaminating activity means a use or activity set out in Column A of Table 2 of Schedule D that is occurring or has occurred in a Phase One Study Area.*

3) *PAHs - polycyclic aromatic hydrocarbons, PHCs - petroleum hydrocarbons, BTEX - benzene, toluene, ethylbenzene, xylenes, VOCs - volatile organic compounds, PCBs - polychlorinated biphenyls, SAR – sodium adsorption ratio, As – arsenic, Sb – antimony, Se – selenium, Cr(VI) – chromium VI and Hg – mercury.*

Based on the findings and conclusions of this Phase One ESA, a Phase Two ESA is required to assess the soil and groundwater conditions at the Site prior to submitting an RSC.

This executive summary is a brief synopsis of the report and should not be read in lieu of reading the report in its entirety.

2. Introduction

B.I.G. Consulting Inc. (BIG) was retained by Halton Standard Condominium Corporation No. 416 (Client), to complete a Phase One Environmental Site Assessment (ESA) at the property located at 1026 Cooke Boulevard, in Burlington, Ontario (Site), as shown on Figure 1. The objective of the investigation was to support the filing of a Record of Site Condition (RSC) in accordance with Ontario Regulation 153/04 (O.Reg.153/04), as amended. It is BIG's understanding that the Site will be redeveloped for residential purposes in the future, which would require an RSC.

A Phase One ESA is a systematic qualitative process to assess the environmental condition of a site based on its historical and current uses. This Phase One ESA was conducted in accordance with O.Reg.153/04, as amended, and in accordance with generally accepted professional practices. Subject to this standard of care, BIG makes no express or implied warranties regarding its services and no third-party beneficiaries are intended.

2.1 Phase One Property Information

The Site is located to the west of Cooke Boulevard and north of Plains Road East, in Burlington, Ontario, as shown on Figure 1. For simplicity of the description in this report, Cooke Boulevard is considered running north-south. The Site is rectangular in shape and measures approximately 3,200 m² in size. The Site is currently occupied by a slab-on-grade two-storey commercial building (the Site building). The Site building has a footprint of approximately 1,275 m^2 and occupy approximately 40 % of the Site. The areas surrounding the Site buildings are covered with landscaping and asphalt.

The Site is bound to the north by commercial properties, to the east by Cooke Boulevard followed by commercial and industrial properties, to the south by residential and commercial properties and to the west by residential and commercial properties. The surrounding properties are shown on Figure 2.

The legal description of the Site as obtained from the chain of title are:

- **Unit 1, 1026 Cooke Boulevard:** Unit 1, Level 1, Halton Standard Condominium Plan No. 416 and its Appurtenant Interest. The Description of the Condominium Property is: Lot 6, Plan 20M507, Burlington, Subject to Ease's as Set Out in Schedule 'A' of Declaration HR161930.
- **Unit 2, 1026 Cooke Boulevard:** Unit 2, Level 1, Halton Standard Condominium Plan No. 416 and its Appurtenant Interest. The Description of the Condominium Property is: Lot 6, Plan 20M507, Burlington, Subject to Ease's as Set Out in Schedule 'A' of Declaration HR161930.
- **Unit 3, 1026 Cooke Boulevard**: Unit 3, Level 1, Halton Standard Condominium Plan No. 416 and its Appurtenant Interest. The Description of the Condominium Property is: Lot 6, Plan 20M507, Burlington, Subject to Ease's as Set Out in Schedule 'A' of Declaration HR161930.
- **Unit 4, 1026 Cooke Boulevard**: Unit 4, Level 1, Halton Standard Condominium Plan No. 416 and its Appurtenant Interest. The Description of the Condominium Property is: Lot 6, Plan 20M507, Burlington, Subject to Ease's as Set Out in Schedule 'A' of Declaration HR161930.
- **Unit 5, 1026 Cooke Boulevard**: Unit 5, Level 1, Halton Standard Condominium Plan No. 416 and its Appurtenant Interest. The Description of the Condominium Property is: Lot 6, Plan 20M507, Burlington, Subject to Ease's as Set Out in Schedule 'A' of Declaration HR161930.; City of Burlington.

The Property Identification Numbers (PINs) are as follows. The legal survey plan is included in Appendix B.

- **Unit 1, 1026 Cooke Boulevard**: 25718-0001 (LT)
- **Unit 2, 1026 Cooke Boulevard**: 25718-0002 (LT)

- **Unit 3, 1026 Cooke Boulevard**: 25718-0003 (LT)
- **Unit 4, 1026 Cooke Boulevard**: 25718-0004 (LT)
- **Unit 5, 1026 Cooke Boulevard:** 25718-0005 (LT)

Table 2-1: Site Information

Site Details	
Municipal Addresses	1026 Cooke Boulevard, Burlington, Ontario
Current Owner	Halton Standard Condominium Corporation No. 416
Owner Address	71095 Maplehurst Plaza, Burlington, Ontario, L7T 4J8
Owner Contact Information	Name: Mr. David J. White Email: white@realcaptial.ca
Legal Description	**Unit 1, 1026 Cooke Boulevard**: Unit 1, Level 1, Halton Standard Condominium Plan No. 416 and its Appurtenant Interest. The Description of the Condominium Property is: Lot 6, Plan 20M507, Burlington, Subject to Ease's as Set Out in Schedule 'A' of Declaration HR161930. **Unit 2, 1026 Cooke Boulevard**: Unit 2, Level 1, Halton Standard Condominium Plan No. 416 and its Appurtenant Interest. The Description of the Condominium Property is: Lot 6, Plan 20M507, Burlington, Subject to Ease's as Set Out in Schedule 'A' of Declaration HR161930. **Unit 3, 1026 Cooke Boulevard**: Unit 3, Level 1, Halton Standard Condominium Plan No. 416 and its Appurtenant Interest. The Description of the Condominium Property is: Lot 6, Plan 20M507, Burlington, Subject to Ease's as Set Out in Schedule 'A' of Declaration HR161930. **Unit 4, 1026 Cooke Boulevard**: Unit 4, Level 1, Halton Standard Condominium Plan No. 416 and its Appurtenant Interest. The Description of the Condominium Property is: Lot 6, Plan 20M507, Burlington, Subject to Ease's as Set Out in Schedule 'A' of Declaration HR161930. **Unit 5, 1026 Cooke Boulevard**: Unit 5, Level 1, Halton Standard Condominium Plan No. 416 and its Appurtenant Interest. The Description of the Condominium Property is: Lot 6, Plan 20M507, Burlington, Subject to Ease's as Set Out in Schedule 'A' of Declaration HR161930.; City of Burlington.
Property Identification Numbers (PINs)	**Unit 1, 1026 Cooke Boulevard:** 25718-0001 (LT) **Unit 2, 1026 Cooke Boulevard:** 25718-0002 (LT) **Unit 3, 1026 Cooke Boulevard:** 25718-0003 (LT) **Unit 4, 1026 Cooke Boulevard:** 25718-0004 (LT) **Unit 5, 1026 Cooke Boulevard:** 25718-0005 (LT)
Property Size	3,200 m²
Approximate Universal Transverse Mercator (UTM) coordinates	Zone: 17 Easting: 593051.15 Northing: 4795668.02 (1m, NAD83, QGIS)

3. Scope of Investigation

The scope of work for the Phase One ESA consisted of the following activities:

a) Reviewing the historical occupancy of the Site through the use of available archived and relevant municipal and business directories, Fire Insurance Plans (FIPs), topographical maps, and aerial photographs;
b) Contacting municipal and provincial agencies to determine the existence of records of environmental regulatory non-compliance, if any, and reviewing such records where available;
c) Obtaining an EcoLog Environmental Risk Information Services Ltd. (ERIS) report for the Site and surrounding properties within a 250 metres (m) radius of the Site;
d) Reviewing available geological maps, well records and utility maps for the vicinity of the Site;
e) Obtaining and reviewing a chain of title and assessment rolls for the Site;
f) Reviewing available reports previously completed at the Site;
g) Conducting interviews with designated Site representative(s) as a resource for current and historical Site information, as well as to provide BIG staff with unrestricted access to all areas of the Site and Site buildings as required by O.Reg. 153/04, as amended;
h) Conducting a Site reconnaissance in order to identify any land use practices that may have impacted the environmental condition of the Site;
i) Conducting a reconnaissance of the surrounding properties from the Site and publicly accessible areas in order to identify any land use practices that may have impacted the environmental condition of the Site; and,
j) Preparing a report to document the findings.

The following sections summarize the information gathered by BIG during the Phase One ESA and identifies Potentially Contaminating Activities (PCAs) on the Site and in the Phase One Study Area, and Areas of Potential Environmental Concern (APECs) associated with the Site. APECs and PCAs are defined in O. Reg 153/04, as amended.

In completing the scope of work, BIG did not conduct any intrusive investigations, including sampling, analyses or monitoring.

BIG personnel who conducted assessment work for this project included Mr. Travis Van Holst, M.Env.Sc, G.I.T, Ms. Eileen Liu, M.Env.Sc, P.Geo. and Mr. Darko Strjin, P.Eng.. An outline of their qualifications is provided in Appendix C.

4. Records Review

4.1 General

4.1.1 Phase One Study Area Determination

The Site is located to the west of Cooke Boulevard and north of Plains Road East, in Burlington, Ontario. The Phase One Study Area consists of properties within a distance of 250 m from the Site boundaries. The Phase One Study Area is bound by:

a) Masonry Court followed by residential properties to the north;
b) Residential and commercial properties to the east;
c) Commercial and industrial properties to the west; and,
d) Fairwood Place East followed by residential properties to the south.

The surrounding properties within the Phase One Study Area predominantly consist of residential, commercial and industrial land use. All properties wholly or partly within 250 m from the Site boundaries as presented in Figure 2 were included in the Phase One Study Area.

4.1.2 First Developed Use Determination

Based on the reviewed records, the Site was first developed from vacant and undeveloped to commercial use in 2002.

A more detailed discussion of the Site history based on available documentation is provided in the following sections of the report.

4.1.3 Fire Insurance Plans

BIG contracted Opta Information Intelligence to perform a search for fire insurance plans (FIPs), Property Underwriters Reports and Property Underwriters Plans covering the Site and/or lands within the Phase One Study Area. Based on the search, FIPs dated 1971 and a CGI All Risk Inspection Report dated 2006 from Opta covered the Site and the Phase One Study Area. The FIPs and CGI All Risk Inspection Report obtained from Opta are included in Appendix H.

The following table summarizes the features of the Phase One Study Area as indicated on the reviewed FIPs. Building details were limited on the FIPs as indicated below.

1971	
East	a) Park Lane Motel is located at 53 Plains Road East, approximately 25 m east. b) An auto service centre is located at 71 Plains Road East, approximately 90 m east with an UST situated in the central portion of the property. c) Glen Court Motel is located at 91 Plains Road East, approximately 180 m east.
South	a) An auto service centre is located at 7 Plains Road West, approximately 90 m southwest, with an UST situated in the east-central portion of the property. b) An auto service centre is located at 14 Plains Road East, approximately 100 m south with an UST situated in the southwestern of the property. c) A truck and equipment repair shop is located at 14 to 20 Plains Road West (currently northern portion of 18 Plains Road West), approximately 135 m south with one spray painting workshop in the western portion, one gasoline UST, and one diesel oil UST situated in the central portion of the property. d) A residential dwelling is located at 29 Plains Road West, approximately 180 m west, with one UST situated in the northeastern portion of the property.

West	a) Multiple residential dwellings are located at 1016, 1018, 1022, 1028, 1030, and 1036 Waterdown Road, approximately 90 m west. b) A police station and fire station are located at 1044 Waterdown Road (currently 1044 and 1048 Waterdown Road), approximately 80 m west. c) A residential dwelling with a shed is located at 1052 Waterdown Road (currently 1060 Waterdown Road), approximately 110 m west.
2006	
Site	a) The Site building was constructed in 2002, the walls are concrete block, the floors are concrete, and the roof is steel deck. b) The Site building was heated by natural gas forced warm air, suspended unit heaters and roof-top ventilation and air conditioning system.

Based on the information gathered from the review of the FIPs, the following PCAs were identified:

a) The property located at 71 Plains Road East, approximately 90 m east, was occupied by an auto service centre and had an UST situated in the central portion of the property in 1971. The property is associated with PCA#10 – Commercial Autobody Shops and PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks.

b) The property located at 7 Plains Road West, approximately 90 m southwest, was occupied by an auto service centre with an UST situated in the east-central portion of the property in 1971. The property is associated with PCA#10 – Commercial Autobody Shops and PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks.

c) The property located at 14 Plains Road East, approximately 100 m south, was occupied by an auto service centre with an UST situated in the southwestern portion of the property in 1971. The property is associated with PCA#10 – Commercial Autobody Shops and PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks.

d) The property located at 18 Plains Road West (formerly northern portion of 14 to 20 Plains Road West), approximately 135 m south, was occupied by a truck and equipment repair shop with one spray painting workshop in the western portion, one gasoline UST, and one diesel oil UST situated in the central portion of the property in 1971. The property is associated with PCA#10 – Commercial Autobody Shops, PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks, and PCA#39 – Paints Manufacturing, Processing and Bulk Storage.

e) The property located at 29 Plains Road West, approximately 180 m west, was occupied by a residential dwelling with one UST situated in the northeastern portion of the property in 1971. The property is associated with PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks.

4.1.4 Chain of Title

A chain of title was completed for the Site by Stewart Davey, an independent title searcher. The chronological Chain of Title search back to the Crown provided to BIG is provided in Appendix D, summarized in Table II, and indicated the following entities associated with the ownership as part of the Site:

Year	**Name of Owner**
Unit 1, 1026 Cooke Boulevard - 25718-0001 (LT)	
Prior to 1833	The Crown
1833 to 1855	William Applegarth
1855 to 1880	Alexander Brown (Sr.)
1880 to 1912	Alexander Brown (Jr.) Mary Brown

Year	Name of Owner
1912 to 1924	Mabel Thomson John Sprout
October 1924 to December 1924	Robert L. Scott
1924 to 1928	George D. Filman
1928 to 1953	Florindo DeLuca Roselinda DeLuca
1953 to 1962	J. Cooke (Concrete Blocks) Limited
1962 to 1981	J. Cooke Blocks (Aldershot) Limited
1981 to 1987	Zykra Enterprises Limited
1987 to 1988	William Jacob Cooke
1988 to 2002	The Cooke Group Inc.
2002 to 2013	Megbrook Holdings Inc.
2013 to Present	2155630 Ontario Inc.
Unit 2, 1026 Cooke Boulevard - 25718-0002 (LT)	
Prior to 1833	The Crown
1833 to 1855	William Applegarth
1855 to 1880	Alexander Brown (Sr.)
1880 to 1912	Alexander Brown (Jr.) Mary Brown
1912 to 1924	Mabel Thomson John Sprout
1924 to 1924	Robert L. Scott
1924 to 1928	George D. Filman
1928 to 1953	Florindo DeLuca Roselinda DeLuca
1953 to 1962	J. Cooke (Concrete Blocks) Limited
1962 to 1981	J. Cooke Blocks (Aldershot) Limited
1981 to 1987	Zykra Enterprises Limited
1987 to 1988	William Jacob Cooke
1988 to 2002	The Cooke Group Inc.
2002 to Present	Megbrook Holdings Inc.
Unit 3, 1026 Cooke Boulevard - 25718-0003 (LT)	
Prior to 1833	The Crown
1833 to 1855	William Applegarth
1855 to 1880	Alexander Brown (Sr.)
1880 to 1912	Alexander Brown (Jr.) Mary Brown
1912 to 1924	Mabel Thomson John Sprout
1924 to 1924	Robert L. Scott
1924 to 1928	George D. Filman
1928 to 1953	Florindo DeLuca Roselinda DeLuca
1953 to 1962	J. Cooke (Concrete Blocks) Limited
1962 to 1981	J. Cooke Blocks (Aldershot) Limited
1981 to 1987	Zykra Enterprises Limited

Year	Name of Owner
1987 to 1988	William Jacob Cooke
1988 to 2002	The Cooke Group Inc.
2002 to 2017	Delanic Holdings Ltd.
2017 to Present	1237565 Ontario Ltd.
Unit 4, 1026 Cooke Boulevard - 25718-0004 (LT)	
Prior to 1833	The Crown
1833 to 1855	William Applegarth
1855 to 1880	Alexander Brown (Sr.)
1880 to 1912	Alexander Brown (Jr.) Mary Brown
1912 to 1924	Mabel Thomson John Sprout
1924 to 1924	Robert L. Scott
1924 to 1928	George D. Filman
1928 to 1953	Florindo DeLuca Roselinda DeLuca
1953 to 1962	J. Cooke (Concrete Blocks) Limited
1962 to 1981	J. Cooke Blocks (Aldershot) Limited
1981 to 1987	Zykra Enterprises Limited
1987 to 1988	William Jacob Cooke
1988 to 2005	The Cooke Group Inc.
2005 to 2006	1037231 Ontario Inc.
2006 to 2018	1658139 Ontario Inc.
2018 to 2022	1860247 Ontario Inc.
2022 to Present	1237565 Ontario Ltd.
Unit 5, 1026 Cooke Boulevard - 25718-0005 (LT)	
Prior to 1833	The Crown
1833 to 1855	William Applegarth
1855 to 1880	Alexander Brown (Sr.)
1880 to 1912	Alexander Brown (Jr.) Mary Brown
1912 to 1924	Mabel Thomson John Sprout
1924 to 1924	Robert L. Scott
1924 to 1928	George D. Filman
1928 to 1953	Florindo DeLuca Roselinda DeLuca
1953 to 1962	J. Cooke (Concrete Blocks) Limited
1962 to 1981	J. Cooke Blocks (Aldershot) Limited
1981 to 1987	Zykra Enterprises Limited
1987 to 1988	William Jacob Cooke
1988 to 2003	The Cooke Group Inc.
2003 to 2003	Featurework Inc.
2003 to 2004	The Cooke Group Inc.
2004 to 2011	Controtech Automation Ltd.
2011 to 2022	Scott Arthur Ray
2022 to Present	1237565 Ontario Ltd.

Based on the review of the chain of title, no PCAs were identified.

4.1.5 Environmental Reports

No environmental reports or documents were made available to BIG for review during the preparation of this report.

4.2 Environmental Source Information

4.2.1 Federal and Provincial Database Search

A search of provincial, federal and private environmental databases for records pertaining to the Site and properties within the Phase One Study Area was conducted by ERIS. BIG has confirmed neither the completeness nor the accuracy of the records that were provided. A copy of the ERIS report is provided in Appendix E. A summary of the significant findings is provided below.

4.2.1.1 Waste Disposal Sites

The ERIS search included the following waste disposal sites databases:

a) Anderson's Waste Disposal Sites (1860s to present)
b) Waste Disposal Sites – MOE CA Inventory (October 2011 to February 2023)
c) Waste Disposal Sites MOE 1991 Historical Approval Inventory (Up to October 1990)

No records were identified for the Site or the properties within the Phase One Study Area.

4.2.1.2 Boreholes (1875 to July 2018)

No records were identified for the Site. A total of one (1) borehole record was identified for the properties within the Phase One Study Area which was advanced for geotechnical or geological investigations in 1961. The general stratigraphy of the Phase One Study Area as outlined in the borehole record consists of sand, clay and gravel.

4.2.1.3 Certificates of Approval (1985 to October 2011)

No records were identified for the Site. The following records were identified within the Phase One Study Area and are summarized below:

a) The property located at 1047 Cooke Boulevard, approximately 20 m northeast, occupied by Etratech Printed Circuit Boards Inc. and Etratech Inc., had four (4) certificates of approval for air in 2003, 2006, 2007, and 2009 respectively. Based on the description of the approvals, no PCAs were identified.
b) The property located at 1062 Cooke Boulevard, approximately 90 m north, occupied by Etratech Printed Circuit Boards Inc. and Category 5 Imaging Ltd., had one (1) certificate of approval for industrial air in 1998 and one (1) for air in 2009. Based on the description of the approvals, no PCAs were identified.
c) The property located at 14 Plains Road East, approximately 100 m south, occupied by Imperial Oil Limited, had one (1) certificate of approval for industrial sewage works in 2011. Based on the description of the approvals, no PCAs were identified.
d) The property located at 1074 Cooke Boulevard, approximately 135 m northwest, occupied by Etratech Designs Inc., had two (2) certificates of approval for industrial air in 1993 and 1997 respectively. Based on the description of the approvals, no PCAs were identified.
e) The intersection of Masonry Court and Waterdown Road, approximately 225 m northwest, occupied by Burlington City, had a certificate of approval for municipal sewage in 1991. Based on the description of the approval, no PCAs were identified.

f) The intersection of Lasalle Park Road and Fairwood Place East, approximately 230 m southwest, occupied by the Regional Municipality of Halton, had a certificate of approval for municipal water in 1997. Based on the description of the approval, no PCAs were identified.

4.2.1.4 Ontario Regulation 347 Waste Generator Summary (1986 to October 2022)

No records were identified for the Site. The waste generators that were identified within the Phase One Study Area are summarized below:

a) The property located at 1021 Waterdown Road, southwest adjacent, occupied by Bayshore Tool and Equipment, was listed as a waste generator in 2004. The property was listed as having operations of commercial and industrial machinery and equipment (except automotive and electronic) repair and maintenance. Given the inadequate information provided by ERIS, no PCAs were identified.

b) The property located at 1050 Cooke Boulevard, approximately 45 m north, occupied by Investigative Science Inc., was listed as a waste generator of halogenated solvents and residues between 1997 and 2020. The property was listed as having operation of other scientific and technical consulting services, and testing laboratories. As the laboratory has disposal protocol, no PCAs were identified.

c) The property located at 1047 Cooke Boulevard, approximately 20 m northeast, occupied by Etratech Manufacturing Inc. (Etratech), and Gentherm Canada Ulc., was listed as a waste generator for paint/pigment/coating residues, organic and inorganic laboratory chemicals, aliphatic solvents, polymeric resins, other specified inorganics, waste oils and lubricants, oil skimmings and sludges, alkaline wastes – other metals, amines, graphic art wastes, waste compressed gases including cylinders, slurries or solids, waste oils/sludges (petroleum based) between 1997 and 2021. The property was listed as having operation of electronic parts and components and semiconductor and other electronic component manufacturing. The property is associated with PCA#19 – Electronic and Computer Equipment Manufacturing.

d) The property located at 1044 Waterdown Road, approximately 80 m west, occupied by The City of Burlington Corp Fire Department, was listed as a waste generator of pathological wastes between 2020 and 2022. As the fire station has disposal protocol, no PCAs were identified.

e) The property located at 71 Plains Road East, approximately 90 m east, occupied by Budget Car and Truck Rentals, was listed as a waste generator between 2003 and 2004. The property was listed as having operation of other gasoline stations. The property is associated with PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks.

f) The property located at 1062 Cooke Boulevard, approximately 90 m north, occupied by Etratech Printed Circuit Boards Inc. and Category 5 Imaging, was listed as a waste generator of acid waste – heavy metals, alkaline wastes – heavy metals, neutralized wastes – heavy metals, neutralized wastes – other metals, inorganic laboratory chemicals, organic laboratory chemicals, waste crankcase oils and lubricants and wastes from the use of pigments coatings and paints between 1997 and 2022. The property was listed as having operation of electronic parts and components and other printing. The property is associated with PCA#19 – Electronic and Computer Equipment Manufacturing and PCA#31 – Ink Manufacturing, Processing and Bulk Storage.

g) The property located at 14 Plains Road East, approximately 100 m south, occupied by Esso Imperial Oil Limited, and Imperial Oil Mac's Convenience, was listed as a waste generator for light fuels, oil skimmings and sludges, waste oil and lubricants between 2005 and 2022. The property was listed as having operation of petroleum product agents and brokers, gasoline stations with convenience stores. The property is associated with PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks.

h) The property located at 38 Plains Road East (currently northern portion of 34 Plains Road East), approximately 100 m southeast, occupied by Peel I.T. Consultants Ltd., was listed as a waste generator between 2003 and 2004. Based on the inadequate information provided by ERIS, no PCAs were identified.

i) The property located at 18 Plains Road West (formerly northern portion 14 Plains Road West), approximately 135 m south, occupied by Dan Greer Enterprises Ltd and Mechendie Holdings Limited, was listed as a waste generator for waste oils and lubricants and light fuels between 1988 and 2006. The property was listed as having operations of construction and forestry machinery and lessors of non-residential buildings (except mini-warehouses). Based on the description of the operations, no PCAs were identified.

j) The property located at 1074 Cooke Boulevard, approximately 135 m northwest, occupied by Etratech Manufacturing Inc., Eclipse Colour Ontario Ltd. and PV Labs Ltd, was listed as a waste generator for paint/pigment/coating residues, organic and inorganic laboratory chemicals, aliphatic solvents, miscellaneous waste organic, polymeric resins, graphic art and photo-processing wastes between 1993 and 2022. The property was listed as having operations of electronic parts and components and platemaking. The property is associated with PCA#19 – Electronic and Computer Equipment Manufacturing and PCA#31 – Ink Manufacturing, Processing and Bulk Storage.

k) The property located at 91 Plains Road East, approximately 180 m east, occupied by Eighth Empire Inc., was listed as a waste generator for pathological wastes between 2016 and 2021. The property was listed as having operations of other personal care services. Based on the description of the operation, no PCAs were identified.

l) The property located at 29 Plains Road West, approximately 180 m west, occupied by Bethesda Inc., was listed as a waste generator for pathological wastes between 2020 and 2022. Based on the inadequate information provided by ERIS, no PCAs were identified.

m) The property located at 1120 Cooke Boulevard (formerly 101 Masonry Court), approximately 230 m north, occupied by TCG Materials Limited and Adi Development (Masonry) Inc., was listed as a waste generator for waste oils and lubricants, petroleum distillates between 1992 and 2001 and waste oils/sludges (petroleum based) in 2017. The property was listed as having operations of sand and gravel pits. The property is associated with PCA#12 – Concrete, Cement and Lime Manufacturing.

n) The property located at 105 Plains Road East, approximately 245 m northeast, occupied by plains road animal hospital, was listed as a waste generator of photoprocessing wastes between 2002 and 2004. As the animal hospital has disposal protocol, no PCAs were identified.

4.2.1.5 Dry Cleaning Facilities (January 2004 to December 2021)

No records were identified for the Site or the properties within the Phase One Study Area.

4.2.1.6 National Pollutant Release Inventory (1993 to May 2017)

No records were identified for the Site. The following record was identified within the Phase One Study Area are summarized below:

a) The property located at 1047 Cooke Boulevard, approximately 20 m northeast, occupied by Etratech Inc. (Etratech), was registered for various releases including lead between 2001 and 2015. The property was listed as having operation of manufacturing, other electrical equipment and component manufacturing and writing device manufacturing. The property is associated with PCA#19 – Electronic and Computer Equipment Manufacturing.

4.2.1.7 TSSA Historic Incidents (2006 to June 2009) and Fuel Oil Spills and Leaks (Up to February 2022)

No records were identified for the Site or for the properties within the Phase One Study Area.

4.2.1.8 Pesticide Register (October 2011 to February 2023)

No records were identified for the Site. The following records were identified for the properties within the Phase One Study Area:

a) Two (2) records for the property located at 70 Plains Road East, approximately 150 m east.
b) One (1) record for the property located at 29 Plains Road West, approximately 180 m west.

These records indicated that the properties were either a vendor, limited vendor or retail vendor of pesticides and no manufacturing of pesticides was identified. As such, no PCAs were identified based on these records.

4.2.1.9 Fuel Storage Tanks

The ERIS search included a search of the following fuel storage tank databases:

a) Delisted Fuel Tanks (Up to February 2022)
b) Fuel Storage Tank (Up to February 2022)
c) Historic Fuel Storage Tank (Pre January 2010)
d) List of TSSA Expired Facilities (Up to February 2022)
e) Private and Retail Fuel Storage Tanks (1989 to 1996)
f) Retail Fuel Storage Tanks (1999 to May 2022)
g) Commercial Fuel Oil Tanks (Up to February 2022)
h) TSSA Variances for Abandonment of Underground Storage Tanks (Up to February 2022)
i) Anderson's Storage Tanks (1915 to 1953)

No records were identified for the Site. The following records were identified for the property within the Phase One Study Area:

a) The property located at 7 Plains Road West, approximately 90 m southwest, occupied by Petro Canada Car Wash, had four (4) records of a single wall gasoline UST in 1989 and 1992, four (4) records of expired fuel storage piping in 2012, a record of expired fuel storage facility in 2013, four (4) records of an expired fuel tank in 2009 and one (1) record of a retail fuel tank in 1994. The property is associated with PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks.
b) The property located at 14 Plains Road East, approximately 100 m south, occupied by Mac's Convenience Stores Inc., had four (4) records of a double wall gasoline UST in 2011, three (3) records of a single wall gasoline UST in 1992, one (1) record of self serve gasoline station, three (3) records of expired fuel storage piping in 2012, a record of an expired fuel storage facility in 2013, a record of an expired cylinder exchange facility in 2012, three (3) records for expired fuel tank in 2009 and two (2) records of retail fuel tank in 1996. The property is associated with PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks.
c) The property located at 30 Plains Road East, approximately 100 m southeast, occupied by Moore Smalley Ltd., had a record of retail fuel tank in 1993, a record of an expired propane refill centre in 2012. Bases on the description of the record, no PCAs were identified.
d) The property located at 91 Plains Road East, approximately 180 m east, occupied by Petro-Partners, had a record of a fuel tank. The property is associated with PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks.

e) The property located at 1120 Cooke Boulevard (formerly 101 Masonry Court), approximately 230 m north, occupied by TCG Materials Ltd., had two (2) records of expired fuel storage piping in 2012, a record of an expired fuel storage facility in 2013, two (2) records of a double wall diesel aboveground storage tank (AST) in 1992, two (2) records of an expired fuel tank in 2009 and a record of a retail fuel tank in 1996. The property is associated with PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks.

4.2.1.10 Ontario Spills (1988 to March 2021; May 2021 to October 2021)

No records were identified for the Site. The following spills were identified for the properties within the Phase One Study Area:

a) A natural gas leak occurred in 2015 at 1025 Waterdown Road, southwest adjacent. Based on the description of the spill, no PCAs were identified.
b) A natural gas leak occurred in 2014 at 1045 Waterdown Road, approximately 25 m northwest. Based on the description of the spill, no PCAs were identified.
c) A natural gas incident occurred in 2015 at 1036 Waterdown Road, approximately 80 m southwest. Based on the description of the spill, no PCAs were identified.
d) A natural gas incident occurred in 2015 at 1022 Waterdown Road, approximately 80 m west. Based on the description of the spill, no PCAs were identified.
e) A spill of approximately 16-gallon of transformer oil to the ground due to transport accident occurred in 2002 at 71 Plains Road East, approximately 90 m east. The property is associated with PCA#55 – Transformer Manufacturing, Processing and Use.
f) A gasoline spill due to valve malfunction occurred in 1991 at 14 Plains Road East, approximately 100 m south. The property is associated with PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks.
g) A natural gas leak occurred in 2015 at 1063 Waterdown Road, approximately 100 m northwest. Based on the description of the spill, no PCAs were identified.
h) A leak of approximately 4-litre of grease and water to asphalt occurred in 2017 at 18 Plains Road West, approximately 135 m south, and was cleaned. Based on the description of the spill, no PCAs were identified.
i) Two (2) natural gas incidents occurred in 2020 at 1120 Cooke Boulevard (formerly 101 Masonry Court), approximately 230 m north. Based on the description of the spill, no PCAs were identified.

4.2.1.11 Scott's Manufacturing Directory (1992 to March 2011)

No records were identified for the Site. The following manufacturers were identified for the properties within the Phase One Study Area:

a) The property located at 1038 Cooke Boulevard, north adjacent, occupied by O'Dell Associates Inc. and Lextoner.com, was listed as having operation of wholesale trade agents and brokers in 1987 and all other miscellaneous chemical product manufacturing in 1995. The property is associated with PCA#8 – Chemical Manufacturing, Processing and Bulk Storage.

b) The property located at 1021 Waterdown Road, south adjacent, occupied by Dee Signs Inc., was listed as having operation of all other miscellaneous manufacturing, sign manufacturing, all other miscellaneous wood product manufacturing and other printing in 1993. The property is associated with PCA#31 – Ink Manufacturing, Processing and Bulk Storage.

c) The property located 1047 Cooke Boulevard, approximately 20 m northeast, occupied by Etratech Inc., was listed as having operation of semiconductor and other electronic component manufacturing, measuring and medical and controlling devices manufacturing in 1989. The property is associated with PCA#19 – Electronic and Computer Equipment Manufacturing.

d) The property located at 1050 Cooke Boulevard, approximately 45 m north, occupied by BHC Cable Assemblies Inc. and Primary Fluid Systems Inc., was listed as having operations of semiconductor and other electronic component manufacturing; metal valve manufacturing, industrial machinery, equipment and supplies wholesaler-distributors, all other plastic product manufacturing and glass product manufacturing from purchased glass in 1991. The property is associated with PCA#19 – Electronic and Computer Equipment Manufacturing and PCA#43 – Plastics (including Fibreglass) Manufacturing and Processing.

e) The property located at 2 Masonry Court, approximately 135 m north, occupied by BHC Cable Assemblies Inc., was listed as having operation of semiconductor and other electronic component manufacturing in 1996. The property is associated with PCA#19 – Electronic and Computer Equipment Manufacturing.

f) The property located at 1074 Cooke Boulevard, approximately 135 m north, occupied by Etratech Design Inc., Eclipse Colour Ltd., Town Media and Ontario Golf, was listed as having operations of semiconductors and related services, electronic coils, transformers, and other inductors, electronic components in 1989; support activities for printing in 1993 and periodical publishers in 1977 and 2000. The property is associated with PCA#19 – Electronic and Computer Equipment Manufacturing and PCA#31 – Ink Manufacturing, Processing and Bulk Storage.

g) The property located at 91 Plains Road East, approximately 180 m east, occupied by Abbey Stained Glass, was listed as having operation of glass product manufacturing from purchased glass in 1983. Based on the description of the operation, no PCAs were identified.

h) The property located at 1120 Cooke Boulevard (formerly 101 Masonry Court), approximately 230 m north, occupied by TCG Materials Limited, was listed as having operation of concrete block and brick manufacturing. The property is associated with PCA#12 – Concrete, Cement and Lime Manufacturing.

4.2.1.12 Water Well Information System (Up to Jun 2022)

No records were identified for the Site. Thirty-eight (38) records were identified within the Phase One Study Area. The wells were installed between 2004 to 2021 for monitoring, test hole, and observation purposes at depths ranging from 4.5 m to 13.7 m bgs. Based on the well records, the general soil stratigraphy in the vicinity of the Site consisted of sand and silt underlain by sand, silt and clay.

4.2.2 Municipal City Directories

A search for Burlington City Directories was completed by ERIS in order to identify the occupancy history of the Site and properties within the Phase One Study Area for potential environmental concerns. Based on the review of the directories dated 1957, 1960, 1967, 1972, 1977, 1982, 1987, 1992, 1997, 2002, 2007, 2012, 2017, and 2021, summarized in Appendix F. It should be noted that the 1957 City directories were the earliest available City directories for the Site and Phase One Study Area. The following significant findings were identified:

a) The Site first appeared in 2007, was occupied by Controtech Automation and D De Signs from 2007 to 2017, Megbrook Holdings Inc. from 2017 to 2021, Burlington Steel Systems, Everik International Inc., and K D Installations in 2021. No PCAs were identified.

b) The property located at 35 Plains Road East, southeast adjacent, was occupied by Jim & Ed's Service Station in 1960, Aldershot Landscape from 1972 to 1977, Budget Rent A Car and Sears Rent A Car from 1982 to 1987, Windshield Doctor from 1987 to 1992, and O'Reilley Pat Auto in 1992. The property is associated with PCA#10 – Commercial Autobody Shops and PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks.

c) The property located at 1021 Waterdown Road, south adjacent, was occupied by Post Office in 1957, Neelands Refrigeration Ltd. From 1960 to 1972, Bayshore Tool & Equipment from 2002 to 2012 and Dee Signs from 2017 to 2021. The property is associated with PCA#31 – Ink Manufacturing, Processing and Bulk Storage.

d) The property located at 1025 Waterdown Road, southwest adjacent, was occupied by Daniel Steel Installation Ltd in 1982, Karbelt Sales Co. from 1982 to 1987, Troy & Associates Ltd. from 1987 to 1992, ABC – A Better Cleaner from 1987 to 1997 and in 2012, Smith's Sanitation Supply Co. and M & S Distributing in 1992, Footwear Factory Outlet in 1997, Merle Norman Cosmetics and Serendipity Salon in 2007, Van Der Woerd & Faber & Solicitors from 2007 to 2017, and Birth Baby Needs and Faber Oostdyk in 2021. The property is associated with PCA#37 – Operation of Dry Cleaning Equipment (where chemicals are used).

e) The property located at 1047 Cooke Boulevard, approximately 20 m northeast, was occupied by Etratech Designs Inc. from 2002 to 2017 and Gentherm Electronics in 2021. The property is associated with PCA#19 – Electronic and Computer Equipment Manufacturing.

f) The property located at 1022 Waterdown Road, approximately 80 m west, was occupied by Porteous & Sons from 1957 to 1960, doctor office from 1957 to 1972 and from 2002 to 2007, barber shop from 1957 to 1960, Sherwood Cleaners & Confectionery in 1960, Phoenix Consulting Engineer in 1967, Martin Barber Shop from 1967 to 1987, consulting engineer office and Phoenix & Associates Ltd. in 1972, Wilkinson Engineering Ltd. from 1977 to 2017, Wilkinson & Associates Ltd. From 1977 to 1987, Forensic Engineer Inc. and Forenco Inc. in 1997, Tripoint Medical Inc. in 2002 and 2012, All The Best Paving Ltd. And Ontario Mobility Service from 2002 to 2012, Royal City Soccer Club from 2007 to 2017, Christian Horizons from 2007 to 2012, Participation House in 2007, Wilkinson Engineer Inc. in 2012, Corporate Travel Suites and Able Livings Service Inc. from 2017 to 2021, and Antec Appraisal Group in 2021. The property is associated with PCA#37 – Operation of Dry-Cleaning Equipment (where chemicals are used).

g) The property located at 71 Plains Road East, approximately 90 m east, was occupied by Service Station in 1960, Budget Rent A Car and Sears Rent A Car in 1977, and Burlington Suzuki, Burlington Ride Centre, and Avis Rent A Car in 1987. The property is associated with PCA#10 – Commercial Autobody Shops and PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks.

h) The property located at 1062 Cooke Boulevard, approximately 90 m north, was occupied by Category 5 Imaging from 2007 to 2011, Medgar Sales (Medgar Lighting Group Inc.) from 2007 to 2017, Laurel Oak Marketing Ltd. In 2017, and Category 5 Imaging in 2021. The property is associated with PCA#31 – Ink Manufacturing, Processing and Bulk Storage.

i) The property located at 7 Plains Road West, approximately 90 m southwest, was occupied by George's Lunch Room and Service Station in 1957, La Belle Snack Bar, Alex's Supertest Station, and ABC Taxi in 1960, Joe's Barber Shop in 1967, Plains West Supertest Service Station from 1972 to 1992, Plains West BP Service Station from 1977 to 1982, Ted's Service Center from 1977 to 1992, Plain West Petro-Canada in 1987, Jerry's Auto from 1997 to 2021, Ray's Auto Center & Towing from 2002 to 2017, and Niche For Design in 2021. The property is associated with PCA#10 – Commercial Autobody Shops and PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks.

j) The property located at 14 Plains Road East, approximately 100 m south, was occupied by Jim & Ed's Service Center in 1957, Lloyd's Esso Service Station in 1960, Burl Esso No. 2 in 1967, La Salle Esso Service Station in 1972, Thompson Jack Self Service Esso Station in 1997, Aldershot Automotive Self Service Station in 1982, Moore Auto Service and More Esso Service in 1987, Mac's Convenience Store from 1997 to 2017, Tim Hortons from 2017 to 2021, and Circle K and Esso in 2021. The property is associated with PCA#10 – Commercial Autobody Shops and PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks

k) The property located at 1060 Waterdown Road, approximately 115 m west, was occupied by Howard Concrete & Materials in 1957. The property is associated with PCA#12 – Concrete, Cement and Lime Manufacturing.

l) The property located at 18 Plains Road West (formerly northern portion of 8 Plains Road West), approximately 135 m south, was occupied by Rudolf's Variety Store in 1957 and De La Salle Cleaners in 1960. The property is associated with PCA#37 – Operation of Dry-Cleaning Equipment (where chemicals are used).

m) The property located at 1074 Cooke Boulevard, approximately 135 m north, was occupied by Etratech Designs Inc in 1997, Eclipse Colour Int Ltd. in 2002, Control System Innovators and Canadian Sport Fishing productions Inc. from 2007 to 2017, Town Publishing from 2007 to 2012, Biz Magazine from 2012 to 2017, and PV Labs in 2021. The property is associated with PCA#19 – Electronic and Computer Equipment Manufacturing and PCA#31 – Ink Manufacturing, Processing and Bulk Storage.

n) The property located at 2 Masonry Court, approximately 135 m north, was occupied by BHC from 2007 to 2021, GP2 Inc. in 2017, and Cougar Shoes Inc. in 2021. The property is associated with PCA#19 – Electronic and Computer Equipment Manufacturing.

o) The property located at 91 Plains Road East, approximately 180 m east, was occupied by The Munro Group, Munel Enterprises, Hurley Insurance Broker Ltd., and Sir Loin Steaks in 1982, Gardner Office Equipment in 1987, Nature's Basket Natural Foods in 1992, Viking Norstar Development Corp. and Petro Apartments in 1997, Petro Partners and Spanish Touch in 2002, Abbey Stained Glass from 2002 to 2021, Klippings Hair Salon from 2007 to 2021, Fenworth Travel and Fenworth Florida Homes & Condo from 2012 to 2017, and Eighth Empire Tattoos Piercings in 2021. The property is associated with PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks.

p) The property located at 29 Plains Road West, approximately 180 m west, was occupied by residential in 1960, West Plains Supertest Service Station in 1967, residential from 1967 to 1997, Nature's Basket Natural Foods in 1997, Hauser Factory Outlet from 1997 to 2007, Tim Hortons Donuts from 1997 to 2007, Footwear Factory Outlet and Croft's Casual Sportswear in 2002, Forever Scrapbooks from 2007 to 2017, Hauser Co. Stores and Tim Hortons from 2012 to 2021, Hauser Factory Service in 2012, Hasty Market from 2017 to 2021, and U-Haul Neighborhood Dealer and Pharmasave in 2021. The property is associated with PCA#10 – Commercial Autobody Shops and PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks.

The remaining properties within the Phase One Study Area did not appear to be associated with any PCAs as per Table 2, Schedule D of O.Reg.153/04, as amended.

4.2.3 Ontario Ministry of Environment, Conservation and Parks Records

4.2.3.1 Ministry of the Environment, Conservation and Parks (MECP)

The Ministry of Environment, Conservation and Parks (MECP) was contacted through the Freedom of Information and Protection of Privacy Act (FOI) for copies of any records they had pertaining to the Site on May 30, 2023.

A written response from the MECP is received on June 21, 2023. According to the decision letter from MECP, no records were identified. The response decision letter is included in Appendix G.

4.2.3.2 MECP Databases

The ERIS report summarized in the Federal and Provincial Database Search section of the report included a summary of MECP databases. The databases include the following: MECP Environmental Bill of Rights (EBR), Environmental Activity and Sector Registry (EASR), Environmental Compliance Approval (ECA), MECP Brownfields Environmental Site Registry (BESR), MECP Hazardous Waste Information Network (HWIN) and MECP Waste Disposal Sites. The following record was identified:

a) The property located at 1047 Cooke Boulevard, approximately 20 m northeast, was registered in the EBR database for approval for discharge into the natural environment other than water (i.e. Air) in 1997, 2003, 2005, 2006, and 2007 and for Environmental Compliance Approval (project type: air) in 2013, in the EASR database for heating system in 2013, and had five (5) ECAs on air in 2003, 2006, 2007, 2009, and 2017.
b) The property located at 1044 Waterdown Road, approximately 80 m west, was registered in the EASR database for standby power system in 2015.
c) The property located at 1062 Cooke Boulevard, approximately 90 m north, was registered in the EBR database for approval for discharge into the natural environment other than water (i.e. Air) in 1997 and 2007 and had an ECA on air in 2009.
d) The property located at 14 Plains Road East, approximately 100 m south, had one (1) ECA on industrial sewage works in 2011.
e) The property located at 1074 Cooke Boulevard, approximately 135 m north, was registered in the EBR database for approval for discharge into the natural environment other than water (i.e. Air) in 1996
f) The intersection of Masonry Court and Cooke Boulevard, approximately 220 m northwest, had one (1) ECA on municipal and private sewage works in 2015.
g) The property located at 1120 Cooke Boulevard (formerly 101 Masonry Court), approximately 230 m north, was registered in the EASR database for water taking – construction dewatering in 2017 and had one (1) ECA on municipal and private sewage works in 2018.

Based on the description of the registrations, no PCAs were identified.

4.2.3.3 Record of Site Condition (RSC)

An RSC summarizes the environmental conditions of a property as determined by a qualified person (QP) by conducting a Phase One ESA, and where necessary, a Phase Two ESA, confirmatory sampling and a risk assessment. Upon completion of the necessary environmental Site assessments, an RSC for an assessed property can be filed with the MECP and added to the BESR database. This online, publicly available database can be searched to identify what properties may have potential environmental concerns.

Based on the search of the MECP's BESR database completed by ERIS, no records were identified at the Site. The following records were identified for the properties within the Phase One Study Area:

a) The property located at 35 Plains Road East, southeast adjacent, filed a Phase One and Two RSC for commercial use in 2014 and a Phase One and Two RSC for residential use in 2017. The property has potential environmental concerns due to former use a garage and gasoline outlet and for green housing/landscape contractor's yard. The property is associated with PCA#10 – Commercial Autobody Shops and PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks
b) The property located at 1025 Cooke Boulevard, approximately 20 m northwest, filed a Phase One and Two RSC for residential use in 2018. No PCAs were identified.

c) The property located at 53 Plains Road East, approximately 20 m northwest, filed a Phase One and Two RSC for residential use in 2018. No PCAs were identified.
d) The property located at 71 Plains Road East, approximately 90 m east, filed a Phase One and Two RSC for residential use in 2018. Based on the Phase Two CSM, the property is associated with PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks.
e) The property located at 34 Plains Road East, approximately 100 m southeast, filed a Phase One and Two RSC for residential use in 2014. No PCAs were identified.
f) The property located at 18 Plains Road West (formerly northern portion of 12 Plains Road West), approximately 135 m south, filed an RSC for residential use in 2007. No PCAs were identified.
g) The property located at 92 Plains Road East, approximately 210 m east, filed a Phase One and Two RSC for residential use in 2018. The property has potential environmental concerns due to former 250-gallon heating oil AST prior to 2015. The property is associated with PCA#28 – Gasoline and Associated Products Storage.
h) The property located at 105 Plains Road East, approximately 245 m northeast, filed a Phase One RSC for residential use in 2020. No PCAs were identified.

4.2.4 Technical Standards and Safety Authority

A request was made to the TSSA by email on May 29, 2023 for information regarding fuel storage at the Site and the adjacent properties. A copy of the TSSA request is provided in Appendix G.

An email response from TSSA dated May 29, 2023 was received and is included in Appendix G. No records were found regarding the potential fuel storage tanks at the Site and the adjacent properties in the TSSA database. A copy of the TSSA response is provided in Appendix G.

4.3 Physical Setting Sources

4.3.1 Aerial Photographs

Aerial photographs were obtained in order to review the development and land use history of the Site, as well as to the land in the immediate vicinity of the Site. Aerial photographs dated 1934, 1962, 1979, and 1995 were obtained from City of Burlington Archives and aerial photographs dated 2004 and 2018 were obtained from Google Earth. The aerial photographs were collected based on availability from the archives at available intervals to best capture the changes at the Site. BIG notes that at the time of this Phase One ESA, the 1934 aerial photograph was the earliest available photograph for the Site and Phase One Study Area.

The development and land use history of the Site and adjacent properties as depicted on the reviewed aerial photography is summarized in Table 3-1. Copies of the aerial photographs are included in Appendix H.

Table 4-1: Aerial Photograph Observations

Aerial Photograph Year	Observations
1934	a) The Site appears to have been vacant and undeveloped. b) Plains Road East, Plains Road West and Waterdown Road appear to have been constructed. c) One (1) structure appears to have been developed at 35 Plains Road East, southeast adjacent to the Site. d) The Phase One Study Area appears to be mostly vacant and undeveloped or used as agricultural fields.

Aerial Photograph Year	Observations
1962	a) The Site appears to have been vacant and undeveloped. b) The property located at 1 and 15 Plains Road East, south adjacent, appears to have been developed with a commercial property. c) The property located at 53 Plains Road East, approximately 20 m northwest, appears to have been developed with a commercial property.
1979	a) The Site appears to have been vacant and undeveloped. b) The land located at 1074 Cooke Boulevard and 2 Masonry Court, approximately 135 m north, appear to have been disturbed.
1995	a) The land at the Site appears to be disturbed. b) Cooke Boulevard appears to have been developed northeast adjacent to the Site. c) Masonry Court appears to have been developed approximately 215 m north to the Site. d) The property located at 1062 Cooke Boulevard, approximately 90 m north, appears to have been developed with one (1) building. e) The property located at 1074 Cooke Boulevard, approximately 135 m north, appears to have been developed with one (1) building.
2004	a) The Site appears to have been developed with one (1) building with similar shape and size of the building observed during the Site reconnaissance. The area surrounding the Site buildings is covered with asphalt and landscaping. b) The property located at 1038 Cooke Boulevard, north adjacent, appears to have been developed with one (1) building. c) The property located at 1047 Cooke Boulevard, approximately 20 m northeast, approximately 20 m north, appears to have been developed with one (1) building. d) 1050 Cooke Boulevard, and 45 m north, appears to have been developed with one (1) building.
2018	a) The Site appears to be the same as the 2004 aerial photograph. b) The structure located at 35 Plains Road East, southeast adjacent to the site, appears to have been demolished. c) The property located at 1047 Cooke Boulevard, approximately 20 m northeast, appears to have been developed with an addition on the northern portion of the building.

Based on the review of the aerial photographs, the following PCAs were identified:

a) The land at the Site appears to be disturbed in 1995. The Site appears to have been developed with one (1) building with similar shape and size of the building observed during the Site reconnaissance in 2004. The area surrounding the Site buildings is covered with asphalt used for parking. De-icing salt could potentially be applied in the winter months for health and safety purposes. Fill material may have been brought to regrade the Site. The Site is associated with PCA#30 – Importation of Fill Material of Unknown Quality and PCA "Other" – Usage of De-icing Salts.

4.3.2 Topography, Hydrology and Geology

The following physiographic, geological and soil maps were reviewed on June 27, 2023:

a) Atlas of Canada – Toporama Topographic Map (Toporama);
b) Ontario Base Map (OBM);

c) Ontario Ministry of Energy, Northern Development and Mines (MENDM) website, Bedrock Geology of Ontario, 2011 – MRD 126; and Paleozoic Geology of Southern Ontario, 2007 – MRD 219 (KML format);
d) Ontario MENDM website, Surficial Geology of Southern Ontario, 2010. (KML format); and,
e) Ontario MENDM website, Physiography of Southern Ontario 2007 (KML format).

Based on the review of the above maps, the following information was obtained:

a) The Site is at an elevation of approximately 100 metres above sea level (m asl). The surrounding properties to the north and west are generally at higher elevations than the Site, while the surrounding properties to the south and east are generally at lower elevations than the Site. The Site is relatively flat.
b) No water bodies are located on the Site. A tributary of Grindstone Creek is situated approximately 370 m north of the Site. Lake Ontario is situated approximately 870 m south of the Site. The inferred groundwater flow direction is likely towards the south/southeast.
c) The bedrock in the general area consists of shale, limestone, dolostone and siltstone and is part of the Queenston Formation.
d) The surficial geology of the Site is described as coarse-textured glaciolacustrine deposits consisting of sand, gravel, minor silt, clay and littoral deposits.
e) The physiography of the Site is within Iroquois Plain and is characterized as sand plains.

4.3.3 Fill Material

Fill can be used to re-grade a property and to backfill excavations. Based on the review of the historical information, no fill materials have been imported to the Site.

4.3.4 Water Bodies, Areas of Natural Significance and Ground Water Information

There are no water bodies located on the Site. A tributary of Grindstone Creek is situated approximately 370 m north of the Site. Lake Ontario is situated approximately 870 m south of the Site.

Based on the review of available resources from the City of Burlington and the Ministry of Natural Resources and Forestry (MNRF) on May 25, 2023, no areas of natural significance were identified at the Site or within the Phase One Study Area.

The MECP (2020) Source Protection Information Atlas was accessed on May 25, 2023. The search of the website indicated that the Site is not located within an area designated in a municipal official plan as a well-head protection area or any other designation identified by the municipality for the protection of groundwater.

The property, and all other properties located, in whole or in part, within 250 metres of the boundaries of the property, are supplied by a municipal drinking water system, as defined in the *Safe Drinking Water Act, 2002*.

Based on the well records, no domestic water wells were identified for the Site or Phase One Study Area. Given the area is serviced by municipal system, no private well water user is expected.

4.3.5 Well Records

4.3.5.1 Water Wells

The MECP maintains a database (published from 1955 to present) of water wells drilled in Ontario in accordance with Ontario Regulation 903. The Ontario Well Record website was accessed on May 25, 2023, to identify if any wells exist on the Site or within the Phase One Study Area. Based on the search, no records were identified at the Site.

Fifty (50) records were identified within the Phase One Study Area located to the east, southeast, south, west, and northwest. The wells were installed between 2004 to 2022 for monitoring, test hole, and observation purposes at depths ranging from 4.5 m to 13.7 m bgs. Based on the well records, the general soil stratigraphy in the vicinity of the Site consisted of sand and silt underlain by sand, silt and clay. Bedrock was not encountered in any of the boreholes, the approximate depth to bedrock is unknown.

It should be noted that the ERIS report identified no records on Site and thirty-eight (38) well records within the Phase One Study Area.

4.3.5.2 Oil, Gas, and Salt Well

A search of the Oil, Gas & Salt Resources Library (2014) website was completed to identify oil, gas and salt wells within the vicinity of the Site on May 25, 2023. The search of the website indicated there were no oil, gas or salt wells identified to be located at the Site or within the Phase One Study Area.

4.4 Site Operating Records

ln general, a request is usually made to the property representative for copies of any operating records pertaining to the environmental conditions at the Site. Records would include: regulatory permits; Safety Data Sheets (SDS) for all chemicals that were handled on-Site; underground utility drawings; inventories of chemicals, chemical usage, and chemical storage areas; inventory of aboveground storage tanks (ASTs) and USTs; environmental monitoring data; correspondence pertaining to an order or request by the MECP or TSSA; waste management records; process, production, and maintenance documents; records of spills and records of discharges of chemicals; emergency response and contingency plans, including spill prevention and contingency plans; environmental audit reports; and site plans of the facility showing areas of production and manufacturing.

No Site operating records were available to review.

5. Interviews

An interview was conducted by BIG staff with the individual identified to be the most knowledgeable about both the current and historical Site uses. The interview was conducted during the Site reconnaissance on May 9, 2023, in order to obtain information to assist in identifying details of potentially contaminating activities, potential contaminant pathways in, on, or below the Site, and areas of potential environmental concern. Any information provided during the interviews is presented alongside information from the Site reconnaissance in Section 6.

During the completion of this Phase One ESA, the following individual was interviewed based on their knowledge of the Site operations:

a) Ms. Kathleen Dryden, owner of Halton Standard Condominium Corporation No. 416, currently occupying Unit 1 of the Site, who has knowledge of the Site since 2015.

Information obtained during the interview is provided below, in the relevant sections.

6. Site Reconnaissance

6.1 General Requirements

The Phase One ESA Site reconnaissance was conducted on Tuesday, May 9, 2023 between 9:00 am and 11:00 am by Mr. Travis Van Holst, M.Env.Sc, GIT and Mr. Hongshen Chen, M.Env.Sc. On the day of the Site reconnaissance, the weather was sunny (approximately 15°C). The Site is currently occupied by a slab-on-grade two-storey commercial building.

The Site and the adjoining properties were observed from the Site and/or publicly accessible areas. Photographs documenting the Site visit are included in Appendix I.

6.2 Specific Observations at Phase One ESA Property

6.2.1 Site Description and Buildings

The Site is located to the west of Cooke Boulevard and north of Plains Road East, in Burlington, Ontario, as shown on Figure 1. For simplicity of the description in this report, Cooke Boulevard is considered running north-south. The Site is rectangular in shape and measures approximately 3,200 m² in size. The Site is currently occupied by a slab-on-grade two-storey commercial building (the Site building). The Site building has a footprint of approximately 1,275 m^2 and occupy approximately 40 % of the Site. The areas surrounding the Site buildings are covered with landscaping and asphalt.

The Site building was reportedly constructed in 2002 and the Site was reportedly vacant before the Site building was constructed. The Site building consists of five (5) units. Unit 1 and 4 are occupied by Pure Fishing Inc. Unit 2 is occupied by Megbrook Holdings Inc. Unit 3 is occupied by a furniture staging company. Unit 5 is occupied by a carpet cleaning service company. Given all units are used as general offices and/or storage, no PCAs were identified for the Site building.

The characteristics of the Site buildings are summarized below:

Building Part	Material Description
Interior Wall	Drywall and concrete
Exterior Wall	Brick and concrete
Floor	Carpet and concrete
Ceiling	Drywall, tiles, and steel deck

6.2.2 Heating and Cooling Systems

The Site building was heated by roof top natural gas fired HVAC units, suspended natural gas forced air units and roof-top ventilation and air conditioning system.

6.2.3 Site Utilities and Services

The Site utilities and services were identified at the Site based on the relevant utility infrastructure observed during the Site reconnaissance and the approximate location of utility is summarized in the table below.

Utility	Source	Location	Site Entry
Storm Sewer	Municipality – City of Burlington	Northeast	Catch basins are located on northeastern portion of the Site. A storm sewer line is anticipated to enter the Site from the northeastern Site boundary
Sanitary Sewer	Municipality – City of Burlington	East	Manholes are located along Cooke Boulevard. A sanitary sewer line is anticipated to enter the Site from the eastern Site boundary

Utility	Source	Location	Site Entry
Water	Municipality – City of Burlington	East	Given that the Site is located in a mixed residential, commercial, and industrial area, the water lines are anticipated to run along Cooke Boulevard.
Natural Gas	Enbridge Gas	North	Nature gas pipes and meter are located on the northern portion of the Site building, the natural gas lines are anticipated to run along Cooke Boulevard.
Electricity	Burlington Hydro	Southeast	A transformer is located in the southeastern portion of the Site. Overhead hydro lines were observed along Cooke Boulevard.

6.2.4 Railway Lines or Spurs

No railway lines or spurs were observed at the Site during the Site reconnaissance.

6.2.5 Site Production and Manufacturing

No on-Site production or manufacturing processes were observed at the Site during the Site reconnaissance.

6.2.6 Drains, Pits and Sumps

Based on the Site reconnaissance, catch basins are located on northeastern portion of the Site. Manholes are located along Cooke Boulevard. No other drains, pits or sumps were observed during the Site reconnaissance.

6.2.7 Storage Tanks

6.2.7.1 Underground Storage Tanks (UST)

The presence/absence and condition (if present) of USTs at the Site was assessed during the Site reconnaissance. BIG did not observe any evidence of USTs during the Site reconnaissance, and the Site representative had no knowledge of any historical or current USTs at the Site.

6.2.7.2 Aboveground Storage Tanks (AST)

The presence/absence and condition (if present) of ASTs at the Site was assessed during the Site reconnaissance. BIG did not observe any evidence of ASTs during the Site reconnaissance, and the Site representative had no knowledge of any historical or current ASTs at the Site.

6.2.8 Water Wells

No potable or monitoring wells were observed at the Site. No additional potable or monitoring wells were observed within the Site or Phase One Study Area during the Site reconnaissance.

6.2.9 Site Housekeeping

The Site is well maintained. Five (5) garbage bins for Unit 1 to 5 respectively are located on northwestern portion of the site. No other debris, outdoor storage, or uncontrolled waste storage were noted during the Site reconnaissance.

6.2.10 Chemical Storage and Handling and Floor Condition

Basic household cleaning products were observed at the Site building. No spilling or staining was observed on the surrounding floors. No other chemical storage was observed at the Site at the time of the Site reconnaissance.

6.2.11 Areas of Stained Soil, Pavement or Stressed Vegetation

No staining on the pavement surfaces and no stressed vegetation was observed at the time of the Site reconnaissance.

6.2.12 Fill and Debris

Fill can be used to re-grade a property and to backfill excavations, such as locations of former USTs. No fill piles or debris were observed at the Site during the Site reconnaissance.

6.2.13 Air Emissions

Regulatory control of air emissions in Ontario is the responsibility of the MECP. No sources of active air emissions were noted at the Site or within the Phase One Study Area during the Site reconnaissance.

6.2.14 Polychlorinated Biphenyls (PCBs)

The manufacture of PCBs in North America was prohibited under the Toxic Substances Control Act (1977). Their use as a constituent of new products manufactured in or imported into Canada was prohibited by regulations in 1977 and 1980. As such, sites developed or significantly renovated after 1980 are unlikely to have PCB-containing equipment on the Site. Potential equipment, which could contain PCBs include fluorescent mercury and sodium vapour light ballasts, oil filled capacitors and transformers. Any electrical equipment containing PCBs must be disposed in accordance with Ontario Regulation 362 when it is removed from service. Ongoing operation of equipment containing PCBs is permissible.

A non-PCB oil transformer is located on the southeastern portion of the Site and situated on a concrete pad. No staining was observed. Based on the records review and the Site reconnaissance, no significant sources of PCBs were present on the Site.

6.2.15 Enhanced Investigation Property Observations

An Enhanced Investigation Property is "(i) a property used, or has ever been used, in whole or part, for an industrial purpose, or (ii) a commercial property used as a garage, a bulk liquid dispensing facility, including a gasoline outlet or for the operation of dry-cleaning equipment" (O.Reg. 153/04).

Based on the records review, the Site is not classified as an Enhanced Investigation Property.

6.2.16 Adjacent and Surrounding Properties

A visual inspection of the adjacent properties and properties within the Phase One Study Area was conducted from publicly accessible areas to identify the occupants; and to document any PCAs that may be contributing to an APEC at the Site.

Location of Adjoining Properties	Property Use
North	Commercial, industrial, and residential
South	Commercial and residential
East	Commercial and residential
West	Commercial and residential

Based on the visual inspection of adjacent and surrounding properties within the Phase One Study Area, the following PCA was identified:

a) The property located at 1062 Cooke Boulevard, approximately 90 m north, is occupied by Category 5 Imaging. The property is associated PCA#31 – Ink Manufacturing, Processing and Bulk Storage.
b) The property located at 7 Plains Road West, approximately 90 m southwest, is occupied by Jerry's Automotive. The property is associated with PCA#10 – Commercial Autobody Shops.

c) The property located at 14 Plains Road East, approximately 100 m south, is occupied by Circle K and Esso gas station. The property is associated with PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks.

d) The property located at 1074 Cooke Boulevard, approximately 135 m north, occupied by PV Labs Ltd. The property is associated with PCA#19 – Electronic and Computer Equipment Manufacturing.

6.3 Written Description of Investigation

A reconnaissance of the Site was conducted by BIG to examine the exterior and interior of all on-Site buildings and structures, and to examine the exterior portions of the Site. Access was provided to the interiors of Site buildings, if any. Mechanical equipment (including heating and cooling systems) was documented and characterized, as was any evidence of USTs and ASTs. The exterior portions of the Site were examined for evidence of utilities and related infrastructure; non potable or potable water wells for human consumption or an agricultural use or service by a municipal drinking water system; Site drainage and related infrastructure; stained areas; stressed vegetation; and evidence of fill material.

The reconnaissance included an examination of all properties within the Phase One Study Area from public access ways to document and characterize PCAs, water wells for human or agricultural use or service by a municipal drinking water system, water bodies and areas of natural significance.

7. Review and Evaluation of Information

7.1 Current and Past Uses

Based on the reviewed records, the Site was first developed from vacant and undeveloped to commercial use in 2002. A more detailed discussion of the Site history based on the available documentation is provided in the following sections of the report. The current and past ownership of the Site is summarized in Table II.

7.2 Potentially Contaminating Activities (PCAs)

A list of all the PCAs identified at the Site and within the Phase One Study Area is summarized below and included as Table III and on Figure 2. Based on the inferred groundwater flow direction to the south/southeast, the properties within the Phase One Study Area to the south/southeast of the Site are considered to be hydraulically downgradient of the Site; properties to the north/northwest are considered to be hydraulically upgradient of the Site; and the properties to the west/southwest and east/northeast of the Site were considered to be hydraulically trans-gradient to the Site. Any PCAs located downgradient or trans-gradient of the Site are not considered to be contributing to an APEC on Site.

Furthermore, any PCAs located significantly distant from the Site were considered to be too far to be contributing to an APEC on the Site.

Rationale outlining whether a PCA contributed to an APEC at the Site is summarized below and provided in Table III.

PCA Identifier	Address	PCA	PCA Location	Contributing to APEC at the Site?	Rationale
1.	1026 Cooke Boulevard	Importation of unknown quality of fill material (PCA#30 – Importation of Fill Material of Unknown Quality)	On-Site	Yes	On-Site
2.		De-icing salts usage (PCA "Other" – Usage of De-icing Salts)			
3.	1038 Cooke Boulevard	Former chemical product manufacturer (PCA#8 – Chemical Manufacturing, Processing and Bulk Storage)	Off-Site (north adjacent)	Yes	Located upgradient
4.	1021 Waterdown Road	Former sign manufacturer and print shop (PCA#31 – Ink Manufacturing, Processing and Bulk Storage)	Off-Site (southwest adjacent)	Yes	Close proximity
5.	35 Plains Road East	Former auto services (PCA#10 – Commercial Autobody Shops)	Off-Site (southeast adjacent)	Yes	Close proximity
6.		Former UST (PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks)			
7.	1025 Waterdown Road	Former dry cleaner (PCA#37 – Operation of Dry Cleaning Equipment (where chemicals are used))	Off-Site (southwest adjacent)	Yes	Close proximity

PCA Identifier	Address	PCA	PCA Location	Contributing to APEC at the Site?	Rationale
8.	1047 Cooke Boulevard	Former semiconductor and other electronic component manufacturer (PCA#19 – Electronic and Computer Equipment Manufacturing)	Off-Site (20 m northeast)	Yes	Located upgradient
9.	1050 Cooke Boulevard	Former semiconductor and other electronic component manufacturer (PCA#19 – Electronic and Computer Equipment Manufacturing)	Off-Site (45 m north)	Yes	Located upgradient
10.		Former other plastic product manufacturer (PCA#43 – Plastics (including Fibreglass) Manufacturing and Processing)			
11.	1062 Cooke Boulevard	Former electronic parts manufacturer (PCA#19 – Electronic and Computer Equipment Manufacturing)	Off-Site (90 m north)	Yes	Located upgradient
12.		Print shop (PCA#31 – Ink Manufacturing, Processing and Bulk Storage)			
13.	1022 Waterdown Road	Former dry cleaner (PCA#37 – Operation of Dry-Cleaning Equipment (where chemicals are used))	Off-Site (80 m west)	No	Inferred trans-gradient
14.	7 Plains Road West	Auto service garage (PCA#10 – Commercial Autobody Shops)	Off-Site (90 m southwest)	No	Located downgradient
15.		Former UST (PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks)			
16.	71 Plains Road East	Former service station (PCA#10 – Commercial Autobody Shops)	Off-Site (90 m east)	No	Inferred trans-gradient
17.		Former UST (PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks)			
18.		Former transformer oil spill (PCA#55 – Transformer Manufacturing, Processing and Use)			
19.	14 Plains Road East	Former service station (PCA#10 – Commercial Autobody Shops)	Off-Site (100 m south)	No	Located downgradient
20.		Gas station (PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks)			
21.	1060 Waterdown Road	Former concrete manufacturer (PCA#12 – Concrete, Cement and Lime Manufacturing)	Off-Site (115 m west)	No	Inferred trans-gradient
22.	18 Plains Road West	Former truck repair services (PCA#10 – Commercial Autobody Shops)		No	Located downgradient

PCA Identifier	Address	PCA	PCA Location	Contributing to APEC at the Site?	Rationale
23.		Former USTs (PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks)	Off-Site (135 m south)		
24.		Former dry cleaner (PCA#37 – Operation of Dry-Cleaning Equipment (where chemicals are used).)			
25.		Former painting workshop (PCA#39 Paints Manufacturing, Processing and Bulk Storage)			
26.	1074 Cooke Boulevard	Former semiconductors, electronic coils, inductors, electronic components manufacturer (PCA#19 – Electronic and Computer Equipment Manufacturing)	Off-Site (135 m north)	No	Located at a significant distance
27.		Former print shop (PCA#31 – Ink Manufacturing, Processing and Bulk Storage)			
28.	2 Masonry Court	Former semiconductor and other electronic component manufacturer (PCA#19 – Electronic and Computer Equipment Manufacturing)	Off-Site (135 m north)	No	Located at a significant distance
29.	91 Plains Road East	Former retail fuel tank (PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks)	Off-Site (180 m east)	No	Inferred trans-gradient
30.	29 Plains Road West	Former service station (PCA#10 – Commercial Autobody Shops)	Off-Site (180 m west)	No	Inferred trans-gradient
31.		Former UST (PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks)			
32.	92 Plains Road East	Former heating oil AST (PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks)	Off-Site (210 m east)	No	Inferred trans-gradient
33.	1120 Cooke Boulevard	Former concrete manufacturer (PCA#12 – Concrete, Cement and Lime Manufacturing)	Off-Site (230 m north)	No	Located at a significant distance
34.		Former fuel storage tank (PCA#28 – Gasoline and Associated Products Storage in Fixed Tanks)			

No other PCAs were identified for the surrounding properties.

7.3 Areas of Potential Environmental Concern (APECs)

Based on the rationale provided in Table III, it is the opinion of the Qualified Person for Environmental Site Assessment (QP_{ESA}) that the following PCAs may have contributed to, or may be contributing to, APECs at the Site:

APEC	Location of APEC on Phase One Property	PCA	Location of PCA (On-Site or Off-Site)	Contaminants of Concern	Media Potentially Impacted (Groundwater, soil and/or sediment)
APEC 1: Importation of unknown quality of fill material	Entire Site	#30 – Importation of Fill Material of Unknown Quality	On-Site	PAHs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Soil and Groundwater
APEC 2: De-icing salts usage	Exterior of the Site Building	"Other" – Usage of De-icing Salts	On-Site	Electrical Conductivity, SAR, Na and Cl-	Soil and Groundwater
APEC 3: Former chemical product manufacturer	Northern portion	#8 – Chemical Manufacturing, Processing and Bulk Storage	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater
APEC 4: Former print shop	Southwestern portion	#31 – Ink Manufacturing, Processing and Bulk Storage	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater
APEC 5: Former auto services	Southeastern portion	#10 – Commercial Autobody Shops	Off-Site	PHCs, BTEX and VOCs	Groundwater
APEC 6: Former UST	Southeastern portion	#28 – Gasoline and Associated Products Storage in Fixed Tanks	Off-Site	PHCs and BTEX	Groundwater
APEC 7: Former dry cleaner	Southwestern portion	#37 – Operation of Dry Cleaning Equipment (where chemicals are used)	Off-Site	VOCs	Groundwater
APEC 8: Former semiconductor and other electronic component manufacturer	Northeastern portion	#19 – Electronic and Computer Equipment Manufacturing	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater

APEC	Location of APEC on Phase One Property	PCA	Location of PCA (On-Site or Off-Site)	Contaminants of Concern	Media Potentially Impacted (Groundwater, soil and/or sediment)
APEC 9: Former semiconductor and other electronic component manufacturer	Northern portion	#19 – Electronic and Computer Equipment Manufacturing	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater
APEC 10: Former plastic product manufacturer	Northern portion	#43 – Plastics (including Fibreglass) Manufacturing and Processing	Off-Site	VOCs	Groundwater
APEC 11: Former electronic parts manufacturer	Northern portion	#19 – Electronic and Computer Equipment Manufacturing	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater
APEC 12: Print shop	Northern portion	#31 – Ink Manufacturing, Processing and Bulk Storage	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater

7.4 Phase One ESA Conceptual Site Model

This section presents the Phase One Conceptual Site Model providing a narrative, graphical and tabulated description integrating information related to the Site geologic and hydrogeologic conditions, areas of potential environmental concern/potential contaminating activities, and the presence and distribution of potential contaminants of concern. These components are discussed in the following sections.

Surface Features

The Site is located to the west of Cooke Boulevard and north of Plains Road East, in Burlington, Ontario, as shown on Figure 1. For simplicity of the description in this report, Cooke Boulevard is considered running north south. The Site is rectangular in shape and measures approximately 3,200 m² in size. The Site is currently occupied by a slab-on-grade two-storey commercial building (the Site building). The Site building has a footprint of approximately 1,275 m^2 and occupy approximately 40 % of the Site. The areas surrounding the Site buildings are covered with landscaping and asphalt.

The legal description of the Site as obtained from the chain of title are:

- **Unit 1, 1026 Cooke Boulevard:** Unit 1, Level 1, Halton Standard Condominium Plan No. 416 and its Appurtenant Interest. The Description of the Condominium Property is: Lot 6, Plan 20M507, Burlington, Subject to Ease's as Set Out in Schedule 'A' of Declaration HR161930.

- **Unit 2, 1026 Cooke Boulevard:** Unit 2, Level 1, Halton Standard Condominium Plan No. 416 and its Appurtenant Interest. The Description of the Condominium Property is: Lot 6, Plan 20M507, Burlington, Subject to Ease's as Set Out in Schedule 'A' of Declaration HR161930.
- **Unit 3, 1026 Cooke Boulevard**: Unit 3, Level 1, Halton Standard Condominium Plan No. 416 and its Appurtenant Interest. The Description of the Condominium Property is: Lot 6, Plan 20M507, Burlington, Subject to Ease's as Set Out in Schedule 'A' of Declaration HR161930.
- **Unit 4, 1026 Cooke Boulevard**: Unit 4, Level 1, Halton Standard Condominium Plan No. 416 and its Appurtenant Interest. The Description of the Condominium Property is: Lot 6, Plan 20M507, Burlington, Subject to Ease's as Set Out in Schedule 'A' of Declaration HR161930.
- **Unit 5, 1026 Cooke Boulevard**: Unit 5, Level 1, Halton Standard Condominium Plan No. 416 and its Appurtenant Interest. The Description of the Condominium Property is: Lot 6, Plan 20M507, Burlington, Subject to Ease's as Set Out in Schedule 'A' of Declaration HR161930.; City of Burlington.

The Property Identification Numbers (PINs) are as follows. The legal survey plan is included in Appendix B.

- **Unit 1, 1026 Cooke Boulevard**: 25718-0001 (LT)
- **Unit 2, 1026 Cooke Boulevard**: 25718-0002 (LT)
- **Unit 3, 1026 Cooke Boulevard**: 25718-0003 (LT)
- **Unit 4, 1026 Cooke Boulevard**: 25718-0004 (LT)
- **Unit 5, 1026 Cooke Boulevard:** 25718-0005 (LT)

Surrounding Land Use

The Site is bound to the north by commercial properties, to the east by Cooke Boulevard followed by commercial and industrial properties, to the south by residential and commercial properties and to the west by residential and commercial properties. The surrounding properties are shown on Figure 2.

Geological and Hydrogeological Conditions

The Site is at an elevation of approximately 100 metres above sea level (m asl). The surrounding properties to the north and west are generally at higher elevations than the Site, while the surrounding properties to the south and east are generally at lower elevations than the Site. The Site is relatively flat.

The surficial geology of the Site is described as coarse-textured glaciolacustrine deposits consisting of sand, gravel, minor silt, clay and littoral deposits. The physiography of the Site is within Iroquois Plain and is characterized as sand plain. The bedrock in the general area consists of shale, limestone, dolostone and siltstone and is part of the Queenston Formation.

No water bodies are located on the Site. A tributary of Grindstone Creek is situated approximately 370 m north of the Site. Lake Ontario is situated approximately 870 m south of the Site. The inferred groundwater flow direction is likely towards the south/southeast.

Based on the review of available resources from the City of Burlington and the Ministry of Natural Resources and Forestry (MNRF) on May 25, 2023, no areas of natural significance were identified at the Site or within the Phase One Study Area.

Underground Utilities

The Site utilities and services were identified at the Site based on the relevant utility infrastructure observed during the Site reconnaissance and the approximate location of utility is summarized in the table below.

Utility	Source	Location	Site Entry
Storm Sewer	Municipality – City of Burlington	Northeast	Catch basins are located on northeastern portion of the Site. A storm sewer line is anticipated to enter the Site from the northeastern Site boundary
Sanitary Sewer	Municipality – City of Burlington	East	Manholes are located along Cooke Boulevard. A sanitary sewer line is anticipated to enter the Site from the eastern Site boundary
Water	Municipality – City of Burlington	East	Given that the Site is located in a mixed residential, commercial, and industrial area, the water lines are anticipated to run along Cooke Boulevard.
Natural Gas	Enbridge Gas	North	Nature gas pipes and meter are located on the northern portion of the Site building, the natural gas lines are anticipated to run along Cooke Boulevard.
Electricity	Burlington Hydro	Southeast	A transformer is located in the southeastern portion of the Site. Overhead hydro lines were observed along Cooke Boulevard.

Preferential Pathways

The preferential pathways for contaminants present in soil and groundwater media typically include various underground utilities, building footings, and surface features. Underground utilities were identified at the Site. Preferential pathways would be present along the underground utilities on Site.

Potentially Contaminating Activities and Areas of Potential Environmental Concern:

A total of twelve (12) PCAs were identified on Site and within the Phase One Study Area that may potentially contribute to APECs at the Site, as presented in the following table.

APEC	Location of APEC on Phase One Property	PCA	Location of PCA (On-Site or Off-Site)	Contaminants of Concern	Media Potentially Impacted (Groundwater, soil and/or sediment)
APEC 1: Importation of unknown quality of fill material	Entire Site	#30 – Importation of Fill Material of Unknown Quality	On-Site	PAHs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Soil and Groundwater
APEC 2: De-icing salts usage	Exterior of the Site Building	"Other" – Usage of De-icing Salts	On-Site	Electrical Conductivity, SAR, Na and Cl-	Soil and Groundwater
APEC 3: Former chemical product manufacturer	Northern portion	#8 – Chemical Manufacturing, Processing and Bulk Storage	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater

APEC	Location of APEC on Phase One Property	PCA	Location of PCA (On-Site or Off-Site)	Contaminants of Concern	Media Potentially Impacted (Groundwater, soil and/or sediment)
APEC 4: Former print shop	Southwestern portion	#31 – Ink Manufacturing, Processing and Bulk Storage	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater
APEC 5: Former auto services	Southeastern portion	#10 – Commercial Autobody Shops	Off-Site	PHCs, BTEX and VOCs	Groundwater
APEC 6: Former UST	Southeastern portion	#28 – Gasoline and Associated Products Storage in Fixed Tanks	Off-Site	PHCs and BTEX	Groundwater
APEC 7: Former dry cleaner	Southwestern portion	#37 – Operation of Dry-Cleaning Equipment (where chemicals are used)	Off-Site	VOCs	Groundwater
APEC 8: Former semiconductor and other electronic component manufacturer	Northeastern portion	#19 – Electronic and Computer Equipment Manufacturing	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater
APEC 9: Former semiconductor and other electronic component manufacturer	Northern portion	#19 – Electronic and Computer Equipment Manufacturing	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater
APEC 10: Former plastic product manufacturer	Northern portion	#43 – Plastics (including Fibreglass) Manufacturing and Processing	Off-Site	VOCs	Groundwater

APEC	Location of APEC on Phase One Property	PCA	Location of PCA (On-Site or Off-Site)	Contaminants of Concern	Media Potentially Impacted (Groundwater, soil and/or sediment)
APEC 11: Former electronic parts manufacturer	Northern portion	#19 – Electronic and Computer Equipment Manufacturing	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater
APEC 12: Print shop	Northern portion	#31 – Ink Manufacturing, Processing and Bulk Storage	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater

Uncertainty and Absence of Information

There were no material deviations to the Phase One ESA requirements set out in O.Reg.153/04 that would cause uncertainty or absence of information that would affect the validity of the Phase One Conceptual Site Model or the findings of this Phase One ESA.

8. Conclusions

8.1 Whether Phase Two Environment Site Assessment Required Before RSC Submission

Based on the findings and conclusions of the Phase One ESA, a Phase Two ESA is required to assess the soil and groundwater conditions at the Site before the RSC submission.

8.2 Record of Site Condition Based on Phase One Environmental Site Assessment Alone

Based on the findings and conclusions of the Phase One ESA, the RSC cannot be filed for the Site based on the Phase One ESA alone.

8.3 Signatures


This Phase One ESA was conducted in accordance with O.Reg.153/04, as amended, and in accordance with generally accepted professional practices. Subject to this standard of care, BIG makes no express or implied warranties regarding its services and no third-party beneficiaries are intended. Limitation of liability, scope of report and third-party reliance are outlined in Appendix A.

Yours truly,

B.I.G. Consulting Inc.



Travis Van Holst, M.Env.Sc., GIT
Environmental Scientist



Eileen Liu, MEnvSc, P.Geo.
Manager, Hydrogeology Services




Darko Strajin, P.Eng.
Managing Partner & Consulting Engineer

9. References

1. Burlington City Map available at the City of Burlington website. Accessed online at https://burlington.maps.arcgis.com/apps/MapSeries/index.html?appid=1d1783b1e626434f95076cba33a5e540
2. Ecolog ERIS Ltd. (2023) Database Report— 1026 Cooke Boulevard, Burlington, Ontario. Ecolog ERIS Ltd, April 18, 2023.
3. Environmental Protection Act, Ontario Regulation 153/04, as amended, Records of Site Condition, January 1, 2014
4. Natural Heritage Areas. (2012) Ontario Ministry of Natural Resources and Forestry. Accessed online at http://www.gisapplication.lrc.gov.on.ca/mamnh/Index.html?site=MNR_NHLUPS_NaturalHeritage&viewer=NaturalHeritage&locale=en-US
5. Occupational Health and Safety Act - Ministry of Labour (MOL)
6. Oil, Gas & Salt Resources Library (2023) Petroleum Well, Petroleum Pool, Seismic and Fault Map of Ontario [map interface]. Accessed online at: http://maps.ogsrlibrary.com.
7. Ontario Ministry of Environment, Conservation and Parks, Map: Well Records, 2021. Accessed online at https://www.ontario.ca/environment-and-energy/map-well-records
8. Ontario Ministry of Energy, Northern Development and Mines website, Bedrock Geology of Ontario, 2011 – MRD 126; and Paleozoic Geology of Southern Ontario, 2007 – MRD 219 (KML format)
9. Ontario Ministry of Energy, Northern Development and Mines website, Physiography of Southern Ontario 2007
10. Ontario Ministry of Energy, Northern Development and Mines website, Surficial Geology of Southern Ontario, 2010. (KML format)
11. Ontario Ministry of the Environment (2011) Brownfields Environmental Site Registry. Accessed online at: https://www.lrcsde.lrc.gov.on.ca/besrWebPublic/generalSearch
12. Ontario Ministry of the Environment (2018) Records of Site Condition. Accessed online at: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/searchFiledRsc_search.
13. Opta. (2023). Environscan Report - 1026 Cooke Boulevard, Burlington, Ontario. Opta, April 19, 2023.
14. Topographic Map available at the Natural Resources Canada (NRC) website. Accessed online at http://atlas.gc.ca/toporama/en/

FIGURES



B.I.G. CONSULTING INC.

t: (416) 214 - 4880 f: (416) 551 - 2633
12-5500 Tomken Rd.
Mississauga, ON L4W 2Z4
Canada

bigconsultinginc.com

LEGEND

SITE BOUNDARY

SCALE

100m 0m 100m 200m 300m 400m 500m

IMAGERY OBTAINED FROM TOPORAMA, NATURAL RESOURCES CANADA, DATE 2022

TITLE AND LOCATION

SITE LOCATION PLAN
PHASE ONE ESA
1026 COOKE BOULEVARD,
BURLINGTON, ONTARIO

PROJECT NO.	DWN.
BIGC-ENV-605A	T.S.
SCALE	CK.
AS NOTED	E.L.
DATE	FIG NO.
JUNE 2023	1



B.I.G. CONSULTING INC.

t: (416) 214 - 4880 f: (416) 551 - 2633
12-5500 Tomken Rd.
Mississauga, ON L4W 2Z4
Canada

bigconsultinginc.com

LEGEND

- SITE BOUNDARY
- PHASE ONE STUDY AREA BOUNDARY
- PCA IDENTIFIER CONTRIBUTING APEC
- PCA IDENTIFIER NOT CONTRIBUTING APEC
- LOCATION OF FORMER UNDERGROUND STORAGE TANK (UST)
- TRANSFORMER
- RESIDENTIAL LAND USE
- COMMERCIAL LAND USE
- COMMUNITY LAND USE
- INDUSTRIAL LAND USE
- AGRICULTURAL OR OTHER LAND USE

IMAGERY OBTAINED FROM COSINE ONLINE SERVICES, 2022


TITLE AND LOCATION

PHASE ONE STUDY AREA AND POTENTIALLY CONTAMINATING ACTIVITIES (PCAs)

PHASE ONE ESA

1026 COOKE BOULEVARD,
BURLINGTON, ONTARIO

PROJECT NO.	DWN.
BIGC-ENV-605A	T.S.
SCALE	CK.
AS NOTED	E.L.
DATE	FIG NO.
JULY 2023	2



B.I.G. CONSULTING INC.

t: (416) 214 - 4880 f: (416) 551 - 2633
12-5500 Tomken Rd.
Mississauga, ON L4W 2Z4
Canada

bigconsultinginc.com

LEGEND

- SITE BOUNDARY
- BUILDING FOOTPRINT
- TRANSFORMER (NON-PCB)
- APEC 1
- APEC 2
- APECs 3, 9-12
- APEC 4
- APECs 5-6
- APEC 7
- APEC 8

TITLE AND LOCATION

SITE PLAN AND AREAS OF POTENTIALLY ENVIRONMENTAL CONCERNS (APECs)

PHASE ONE ESA
1026 COOKE BOULEVARD,
BURLINGTON, ONTARIO

PROJECT NO.	DWN.
BIGC-ENV-605A	T.S.
SCALE	CK.
AS NOTED	E.L.
DATE	FIG NO.
JULY 2023	3

TABLES

Table I

SITE ENVIRONMENTAL SETTING DATA
1026 Cooke Boulevard, Burlington, Ontario

NATIVE SOIL AND BEDROCK		
Type	Unknown	
Hydraulic Conductivity	Unknown	
Percent Sand	Unknown	
Depth to Bedrock	unknown	
Bedrock Type	Queenston Formation (shale, limestone, dolostone and siltstone)	
GROUND WATER		
Depth to Water Table	Unknown	
Estimated or Measured	Estimated	
Direction of Flow	South/southeast	
Estimated or Measured	Estimated	
POTABLE WATER AND SEWERS		
Potable Water Source	City of Burlington	
Municipal Water Source	Lake Ontario	
Distance to Nearest Municipal Water Well	None identified within Phase One Study Area	
Distance to Nearest Private Water Well	Unknown	
Sanitary Sewage System	City of Burlington	
Storm Water System	City of Burlington	
SURFACE WATER		
Name of Nearest Water Body	A tributary of Grindstone Creek	Lake Ontario
Distance from Site	370 m	870 m
Elevation Drop from Site	-4 m	25 m
Direct Drainage from Site	No	No

Table II

TABLE OF CURRENT AND PAST LAND USES OF THE SITE (Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04) 1026 Cooke Boulevard, Burlington, Ontario				
Year	**Name of Owner**	**Description of Property Use**	**Property Use**	**Other Observations from Aerial Photographs, Fire Insurance Plans, Etc.**
Unit 1, 1026 Cooke Boulevard - 25718-0001 (LT)				
Prior to 1833	The Crown	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1833 to 1855	William Applegarth	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1855 to 1880	Alexander Brown (Sr.)	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1880 to 1912	Alexander Brown (Jr.) Mary Brown	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1912 to 1924	Mabel Thomson John Sprout	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
October 1924 to December 1924	Robert L. Scott	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1924 to 1928	George D. Filman	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1928 to 1953	Florindo DeLuca Roselinda DeLuca	Undeveloped	Agricultural or other use	Based on the aerial photograph from 1934, the Site appears to be vacant and undeveloped.
1953 to 1962	J. Cooke (Concrete Blocks) Limited	Undeveloped	Agricultural or other use	Based on the aerial photograph from 1962, the Site remains vacant and undeveloped.
1962 to 1981	J. Cooke Blocks (Aldershot) Limited	Undeveloped	Agricultural or other use	Based on the aerial photograph from 1979, the Site appears to remain vacant and undeveloped.
1981 to 1987	Zykra Enterprises Limited	Undeveloped	Agricultural or other use	No FIP or aerial photograph is available between 1981 and 1987. It is assumed the Site remained undeveloped.
1987 to 1988	William Jacob Cooke	Undeveloped	Agricultural or other use	No FIP or aerial photograph is available between 1987 and 1988. It is assumed the Site remained undeveloped.
1988 to 2002	The Cooke Group Inc.	Undeveloped	Agricultural or other use	Based on the aerial photograph from 1995, the land at the Site appears to be disturbed.
2002 to 2013	Megbrook Holdings Inc.	Retail office and storage	Commercial Use	Based on the aerial photograph from 2004, the Site appears to have been developed with a rectangular shaped building with a paved parking lot.

Table II

TABLE OF CURRENT AND PAST LAND USES OF THE SITE (Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04) 1026 Cooke Boulevard, Burlington, Ontario				
Year	**Name of Owner**	**Description of Property Use**	**Property Use**	**Other Observations from Aerial Photographs, Fire Insurance Plans, Etc.**
				Based on the city directory, the Site first appeared in 2007 and was occupied by Controtech Automation and D DeSigns until 2017.
2013 to Present	2155630 Ontario Inc.	Retail office and storage	Commercial Use	Based on the aerial photograph from 2018, the Site appears to have been developed with a rectangular shaped building with a paved parking lot. Based on the city directory, the Site was occupied by Megbrook Holdings Inc. from 2017 to 2021 and Burlington Steel Systems, Everik International Inc, and K D Installations in 2021. Based on the Site reconnaissance conducted by BIG in 2023, the Site was occupied by a slab-on-grade two-storey commercial building.
Unit 2, 1026 Cooke Boulevard - 25718-0002 (LT)				
Prior to 1833	The Crown	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1833 to 1855	William Applegarth	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1855 to 1880	Alexander Brown (Sr.)	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1880 to 1912	Alexander Brown (Jr.) Mary Brown	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1912 to 1924	Mabel Thomson John Sprout	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1924 to 1924	Robert L. Scott	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1924 to 1928	George D. Filman	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1928 to 1953	Florindo DeLuca Roselinda DeLuca	Undeveloped	Agricultural or other use	Based on the aerial photograph from 1934, the Site appears to be vacant and undeveloped.
1953 to 1962	J. Cooke (Concrete Blocks) Limited	Undeveloped	Agricultural or other use	Based on the aerial photograph from 1962, the Site remains vacant and undeveloped.
1962 to 1981	J. Cooke Blocks (Aldershot) Limited	Undeveloped	Agricultural or other use	Based on the aerial photograph from 1979, the Site appears to remain vacant and undeveloped.

Table II

TABLE OF CURRENT AND PAST LAND USES OF THE SITE (Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04) 1026 Cooke Boulevard, Burlington, Ontario				
Year	**Name of Owner**	**Description of Property Use**	**Property Use**	**Other Observations from Aerial Photographs, Fire Insurance Plans, Etc.**
1981 to 1987	Zykra Enterprises Limited	Undeveloped	Agricultural or other use	No FIP or aerial photograph is available between 1981 and 1987. It is assumed the Site remained undeveloped.
1987 to 1988	William Jacob Cooke	Undeveloped	Agricultural or other use	No FIP or aerial photograph is available between 1987 and 1988. It is assumed the Site remained undeveloped.
1988 to 2002	The Cooke Group Inc.	Undeveloped	Agricultural or other use	Based on the aerial photograph from 1995, the land at the Site appears to be disturbed.
2002 to Present	Megbrook Holdings Inc.	Retail office and storage	Commercial Use	Based on the aerial photographs from 2004 and 2018, the Site appears to have been developed with a rectangular shaped building with a paved parking lot. Based on the city directory, the Site first appeared in 2007 and was occupied by Controtech Automation and D DeSigns until 2017, Megbrook Holdings Inc. from 2017 to 2021, and Burlington Steel Systems, Everik International Inc, and K D Installations in 2021. Based on the Site reconnaissance conducted by BIG in 2023, the Site was occupied by a slab-on-grade two-storey commercial building.
Unit 3, 1026 Cooke Boulevard - 25718-0003 (LT)				
Prior to 1833	The Crown	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1833 to 1855	William Applegarth	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1855 to 1880	Alexander Brown (Sr.)	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1880 to 1912	Alexander Brown (Jr.) Mary Brown	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1912 to 1924	Mabel Thomson John Sprout	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1924 to 1924	Robert L. Scott	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1924 to 1928	George D. Filman	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.

Table II

TABLE OF CURRENT AND PAST LAND USES OF THE SITE (Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04) 1026 Cooke Boulevard, Burlington, Ontario				
Year	**Name of Owner**	**Description of Property Use**	**Property Use**	**Other Observations from Aerial Photographs, Fire Insurance Plans, Etc.**
1928 to 1953	Florindo DeLuca Roselinda DeLuca	Undeveloped	Agricultural or other use	Based on the aerial photograph from 1934, the Site appears to be vacant and undeveloped.
1953 to 1962	J. Cooke (Concrete Blocks) Limited	Undeveloped	Agricultural or other use	Based on the aerial photograph from 1962, the Site remains vacant and undeveloped.
1962 to 1981	J. Cooke Blocks (Aldershot) Limited	Undeveloped	Agricultural or other use	Based on the aerial photograph from 1979, the Site appears to remain vacant and undeveloped.
1981 to 1987	Zykra Enterprises Limited	Undeveloped	Agricultural or other use	No FIP or aerial photograph is available between 1981 and 1987. It is assumed the Site remained undeveloped.
1987 to 1988	William Jacob Cooke	Undeveloped	Agricultural or other use	No FIP or aerial photograph is available between 1987 and 1988. It is assumed the Site remained undeveloped.
1988 to 2002	The Cooke Group Inc.	Undeveloped	Agricultural or other use	Based on the aerial photograph from 1995, the land at the Site appears to be disturbed.
2002 to 2017	Delanic Holdings Ltd.	Retail office and storage	Commercial Use	Based on the aerial photograph from 2004, the Site appears to have been developed with a rectangular shaped building with a paved parking lot. Based on the city directory, the Site first appeared in 2007 and was occupied by Controtech Automation and D DeSigns until 2017.
2017 to Present	1237565 Ontario Ltd.	Retail office and storage	Commercial Use	Based on the aerial photograph from 2018, the Site appears to have been developed with a rectangular shaped building with a paved parking lot. Based on the city directory, the Site was occupied by Megbrook Holdings Inc. from 2017 to 2021 and Burlington Steel Systems, Everik International Inc, and K D Installations in 2021. Based on the Site reconnaissance conducted by BIG in 2023, the Site was occupied by a slab-on-grade two-storey commercial building.
Unit 4, 1026 Cooke Boulevard - 25718-0004 (LT)				
Prior to 1833	The Crown	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1833 to 1855	William Applegarth	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1855 to 1880	Alexander Brown (Sr.)	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.

Table II

TABLE OF CURRENT AND PAST LAND USES OF THE SITE (Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04) 1026 Cooke Boulevard, Burlington, Ontario				
Year	**Name of Owner**	**Description of Property Use**	**Property Use**	**Other Observations from Aerial Photographs, Fire Insurance Plans, Etc.**
1880 to 1912	Alexander Brown (Jr.) Mary Brown	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1912 to 1924	Mabel Thomson John Sprout	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1924 to 1924	Robert L. Scott	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1924 to 1928	George D. Filman	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1928 to 1953	Florindo DeLuca Roselinda DeLuca	Undeveloped	Agricultural or other use	Based on the aerial photograph from 1934, the Site appears to be vacant and undeveloped.
1953 to 1962	J. Cooke (Concrete Blocks) Limited	Undeveloped	Agricultural or other use	Based on the aerial photograph from 1962, the Site remains vacant and undeveloped.
1962 to 1981	J. Cooke Blocks (Aldershot) Limited	Undeveloped	Agricultural or other use	Based on the aerial photograph from 1979, the Site appears to remain vacant and undeveloped.
1981 to 1987	Zykra Enterprises Limited	Undeveloped	Agricultural or other use	No FIP or aerial photograph is available between 1981 and 1987. It is assumed the Site remained undeveloped.
1987 to 1988	William Jacob Cooke	Undeveloped	Agricultural or other use	No FIP or aerial photograph is available between 1987 and 1988. It is assumed the Site remained undeveloped.
1988 to 2005	The Cooke Group Inc.	Retail office and storage	Commercial Use	Based on the aerial photograph from 1995, the land at the Site appears to be disturbed. Based on the aerial photograph from 2004, the Site appears to have been developed with a rectangular shaped building with a paved parking lot.
2005 to 2006	1037231 Ontario Ltd.	Retail office and storage	Commercial Use	No FIP or aerial photograph is available between 2005 and 2006. It is assumed the Site remained commercial use.
2006 to 2018	1658139 Ontario Ltd.	Retail office and storage	Commercial Use	Based on the aerial photograph from 2018, the Site appears to have been developed with a rectangular shaped building with a paved parking lot. Based on the city directory, the Site first appeared in 2007 and was occupied by Controtech Automation and D DeSigns until 2017 and Megbrook Holdings Inc. from 2017 to 2021.

Table II

TABLE OF CURRENT AND PAST LAND USES OF THE SITE (Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04) 1026 Cooke Boulevard, Burlington, Ontario				
Year	**Name of Owner**	**Description of Property Use**	**Property Use**	**Other Observations from Aerial Photographs, Fire Insurance Plans, Etc.**
2018 to 2022	1860247 Ontario Ltd.	Retail office and storage	Commercial Use	Based on the city directory, the Site was occupied by Burlington Steel Systems, Everik International Inc, and K D Installations in 2021.
2022 to Present	1237565 Ontario Ltd.	Retail office and storage	Commercial Use	Based on the Site reconnaissance conducted by BIG in 2023, the Site was occupied by a slab-on-grade two-storey commercial building.
Unit 5, 1026 Cooke Boulevard - 25718-0005 (LT)				
Prior to 1833	The Crown	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1833 to 1855	William Applegarth	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1855 to 1880	Alexander Brown (Sr.)	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1880 to 1912	Alexander Brown (Jr.) Mary Brown	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1912 to 1924	Mabel Thomson John Sprout	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1924 to 1924	Robert L. Scott	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1924 to 1928	George D. Filman	Undeveloped	Agricultural or other use	No FIP or aerial photograph coverage available prior to 1934.
1928 to 1953	Florindo DeLuca Roselinda DeLuca	Undeveloped	Agricultural or other use	Based on the aerial photograph from 1934, the Site appears to be vacant and undeveloped.
1953 to 1962	J. Cooke (Concrete Blocks) Limited	Undeveloped	Agricultural or other use	Based on the aerial photograph from 1962, the Site remains vacant and undeveloped.
1962 to 1981	J. Cooke Blocks (Aldershot) Limited	Undeveloped	Agricultural or other use	Based on the aerial photograph from 1979, the Site appears to remain vacant and undeveloped.
1981 to 1987	Zykra Enterprises Limited	Undeveloped	Agricultural or other use	No FIP or aerial photograph is available between 1981 and 1987. It is assumed the Site remained undeveloped.
1987 to 1988	William Jacob Cooke	Undeveloped	Agricultural or other use	No FIP or aerial photograph is available between 1987 and 1988. It is assumed the Site remained undeveloped

Table II

TABLE OF CURRENT AND PAST LAND USES OF THE SITE

(Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04)

1026 Cooke Boulevard, Burlington, Ontario

Year	Name of Owner	Description of Property Use	Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, Etc.
1988 to 2003	The Cooke Group Inc.	Retail office and storage	Commercial Use	Based on the aerial photograph from 1995, the land at the Site appears to be disturbed. Based on the Site representative, the Site building was reported constructed in 2002 for commercial use.
2003 to 2003	Featurework Inc.	Retail office and storage	Commercial Use	No FIP or aerial photograph is available between April 2003 and November 2003. It is assumed the Site remained commercial use.
2003 to 2004	The Cooke Group Inc.	Retail office and storage	Commercial Use	No FIP or aerial photograph is available between 2003 and 2004. It is assumed the Site remained commercial use.
2004 to 2011	Controtech Automation Ltd.	Retail office and storage	Commercial Use	Based on the aerial photograph from 2004, the Site appears to have been developed with a rectangular shaped building with a paved parking lot. Based on the city directory, the Site first appeared in 2007 and was occupied by Controtech Automation and D DeSigns until 2017.
2011 to 2022	Scott Arthur Ray	Retail office and storage	Commercial Use	Based on the aerial photograph from 2018, the Site appears to have been developed with a rectangular shaped building with a paved parking lot. Based on the city directory, the Site was occupied by Megbrook Holdings Inc. from 2017 to 2021 and Burlington Steel Systems, Everik International Inc, and K D Installations in 2021.
2022 to Present	1237565 Ontario Ltd.	Retail office and storage	Commercial Use	Based on the Site reconnaissance conducted by BIG in 2023, the Site was occupied by a slab-on-grade two-storey commercial building.

Notes:

1 - For each owner, specify one of the following types of property use (as defined in O.Reg.153/04) that applies:

- Agricultural or other use
- Commercial use
- Community use
- Industrial use
- Institutional use
- Parkland use
- Residential use

2 - When submitting a Record of Site Condition for filing, a copy at this table must be attached.

Table III

POTENTIALLY CONTAMINATING ACTIVITIES (PCAs) (Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04) 1026 Cooke Boulevard, Burlington, Ontario					
PCA Identifier	**Address**	**Location of Activity (In relation to Site)[1]**	**Potentially Contaminating Activity (PCA)[2]**	**Description and Approximate timeline that PCA Occurred**	**Contribution to APEC at the Site**
1.	1026 Cooke Boulevard	On-Site	PCA#30 – Importation of Fill Material of Unknown Quality	Based on the aerial photographs, Site appears to have been developed with one (1) building with similar shape and size of the building observed during the Site reconnaissance. The area surrounding the Site buildings is covered with asphalt used for parking. De-icing salt could potentially be applied in the winter months for health and safety purposes. Based on Opta report and interview, the Site building was built in 2002. Based on the site reconnaissance conducted by BIG in 2023, the area surrounding the Site building is paved with asphalt and used for parking. De-icing salt could potentially be applied in the winter months for health and safety purposes.	Potential On-Site
2.			"Other" – Usage of De-icing Salts		
3.	1038 Cooke Boulevard	Off-Site (north adjacent)	#8 – Chemical Manufacturing, Processing and Bulk Storage	Based on the ESRI report, the property located at 1038 Cooke Boulevard, north adjacent, occupied by Lextoner.com, was listed as having operation of all other miscellaneous chemical product manufacturing in 1995.	Potential Located upgradient
4.	1021 Waterdown Road	Off-Site (southwest adjacent)	#31 – Ink Manufacturing, Processing and Bulk Storage	Based on the ESRI report, the property located at 1021 Waterdown Road, southwest adjacent, occupied by Dee Signs Inc., was listed as having operation of all other miscellaneous manufacturing, sign manufacturing, all other miscellaneous wood product manufacturing and other printing in 1993.	Potential Close proximity
5.	35 Plains Road East	Off-Site (south adjacent)	#10 – Commercial Autobody Shops	Based on the city directory, the property located at 35 Plains Road East, southeast adjacent, was occupied by Jim & Ed's Service Station 1960. Based on the ESRI report, the property located at 35 Plains Road East, southeast adjacent, filed a Phase One and Two RSC for commercial use in 2014 and a Phase	Potential Close proximity
6.			#28 – Gasoline and Associated Products Storage in Fixed Tanks		

Table III

POTENTIALLY CONTAMINATING ACTIVITIES (PCAs) (Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04) 1026 Cooke Boulevard, Burlington, Ontario					
PCA Identifier	**Address**	**Location of Activity (In relation to Site)[1]**	**Potentially Contaminating Activity (PCA)[2]**	**Description and Approximate timeline that PCA Occurred**	**Contribution to APEC at the Site**
				One and Two RSC for residential use in 2017. The property has potential environmental concerns due to former use a garage and gasoline outlet and for green housing/landscape contractor's yard.	
7.	1025 Waterdown Road	Off-Site (southwest adjacent)	#37 – Operation of Dry-Cleaning Equipment (where chemicals are used)	Based on the city directory, d) The property located at 1025 Waterdown Road, southwest adjacent, was occupied by Daniel Steel Installation Ltd in 1982, Karbelt Sales Co. from 1982 to 1987, Troy & Associates Ltd. from 1987 to 1992, ABC – A Better Cleaner from 1987 to 1997 and in 2012, Smith's Sanitation Supply Co. and M & S Distributing in 1992, Footwear Factory Outlet in 1997, Merle Norman Cosmetics and Serendipity Salon in 2007, Van Der Woerd & Faber & Solicitors from 2007 to 2017, and Birth Baby Needs and Faber Oostdyk in 2021.	Potential Close proximity
8.	1047 Cooke Boulevard	Off-Site (20 m north)	#19 – Electronic and Computer Equipment Manufacturing	Based on the ESRI report, the property located at 1047 Cooke Boulevard, approximately 20 m north, occupied by Etratech Manufacturing Inc. (Etratech), and Gentherm Canada Ulc., was listed as a waste generator for paint/pigment/coating residues, organic and inorganic laboratory chemicals, aliphatic solvents, polymeric resins, other specified inorganics, waste oils and lubricants, oil skimmings and sludges, alkaline wastes – other metals, amines, graphic art wastes, waste compressed gases including cylinders, slurries or solids, waste oils/sludges (petroleum based) between 1997 and 2021 and listed as having operation of electronic parts and components and semiconductor and other electronic component manufacturing. The property was registered for various releases including lead between 2001 and 2015 and was listed as having operation of manufacturing, other electrical equipment	Potential Located upgradient

Table III

POTENTIALLY CONTAMINATING ACTIVITIES (PCAs) (Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04) 1026 Cooke Boulevard, Burlington, Ontario					
PCA Identifier	**Address**	**Location of Activity (In relation to Site)[1]**	**Potentially Contaminating Activity (PCA)[2]**	**Description and Approximate timeline that PCA Occurred**	**Contribution to APEC at the Site**
				and component manufacturing and writing device manufacturing. The property was listed as having operation of semiconductor and other electronic component manufacturing, measuring and medical and controlling devices manufacturing in 1989. Based on the city directory, the property was occupied by Etratech Designs Inc. from 2002 to 2017 and Gentherm Electronics in 2021.	
9.	1050 Cooke Boulevard	Off-Site (45 m north)	#19 – Electronic and Computer Equipment Manufacturing	Based on the ESRI report, the property located at 1050 Cooke Boulevard, approximately 45 m north, occupied by BHC Cable Assemblies Inc. and Primary Fluid Systems Inc., was listed as having operations of semiconductor and other electronic component manufacturing; metal valve manufacturing, industrial machinery, equipment and supplies wholesaler-distributors, all other plastic product manufacturing and glass product manufacturing from purchased glass in 1991.	Potential Located upgradient
10.			#43 – Plastics (including Fibreglass) Manufacturing and Processing		
11.	1062 Cooke Boulevard	Off-Site (90 m north)	#19 – Electronic and Computer Equipment Manufacturing	Based on the ESRI report, the property located at 1062 Cooke Boulevard, approximately 90 m north, occupied by Etratech Printed Circuit Boards Inc. and Category 5 Imaging, was listed as a waste generator of acid waste – heavy metals, alkaline wastes – heavy metals, neutralized wastes – heavy metals, neutralized wastes – other metals, inorganic laboratory chemicals, organic laboratory chemicals, waste crankcase oils and lubricants and wastes from the use of pigments coatings and paints between 1997 and 2022. The property was listed as having operation of electronic parts and components and other printing. Based on the city directory, the property was occupied by Category 5 Imaging from 2007 to 2021.	Potential Located upgradient
12.			#31 – Ink Manufacturing, Processing and Bulk Storage		

Table III

POTENTIALLY CONTAMINATING ACTIVITIES (PCAs) (Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04) 1026 Cooke Boulevard, Burlington, Ontario					
PCA Identifier	**Address**	**Location of Activity (In relation to Site)[1]**	**Potentially Contaminating Activity (PCA)[2]**	**Description and Approximate timeline that PCA Occurred**	**Contribution to APEC at the Site**
13.	1022 Waterdown Road	Off-Site (80 m west)	#37 – Operation of Dry-Cleaning Equipment (where chemicals are used)	Based on the city directory, the property was occupied by Sherwood Cleaners & Confectionery in 1960.	No Inferred trans-gradient
14.	7 Plains Road West	Off-Site (90 m southwest)	#10 – Commercial Autobody Shops	Based on the FIPs, the property located at 7 Plains Road West, approximately 90 m southwest, was occupied by an auto service centre with an UST situated in the east-central portion of the property in 1971. Based on the ESRI report, the property, occupied by Petro Canada Car Wash, had four (4) records of a single wall gasoline UST in 1989 and 1992, four (4) records of expired fuel storage piping in 2012, a record of expired fuel storage facility in 2013, four (4) records of an expired fuel tank in 2009 and one (1) record of a retail fuel tank in 1994. Based on the city directory, the property was occupied by Service Station in 1957, Alex's Supertest Station in 1967, Plains West Supertest Service Station from 1972 to 1992, Plains West BP Service Station from 1977 to 1982, Ted's Service Center from 1977 to 1992, Plain West Petro-Canada in 1987, Jerry's Auto from 1997 to 2021, and Ray's Auto Center & Towing from 2002 to 2017. Based on the site reconnaissance conducted by BIG in 2023, the property is occupied by Jerry's Automotive.	No Located downgradient
15.			#28 – Gasoline and Associated Products Storage in Fixed Tanks		
16.	71 Plains Road East	Off-Site (90 m east)	#10 – Commercial Autobody Shops	Based on the FIPs, the property located at 71 Plains Road East, approximately 90 m east, was occupied by an auto service centre and had an UST situated in the central portion of the property in 1971.	No Inferred trans-gradient
17.			#28 – Gasoline and Associated Products Storage in Fixed Tanks		

Table III

POTENTIALLY CONTAMINATING ACTIVITIES (PCAs) (Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04) 1026 Cooke Boulevard, Burlington, Ontario					
PCA Identifier	**Address**	**Location of Activity (In relation to Site)[1]**	**Potentially Contaminating Activity (PCA)[2]**	**Description and Approximate timeline that PCA Occurred**	**Contribution to APEC at the Site**
18.			#55 – Transformer Manufacturing, Processing and Use	Based on the ESRI report, the property was occupied by Budget Car and Truck Rentals, was listed as a waste generator between 2003 and 2004. The property was listed as having operation of other gasoline stations. A spill of approximately 16-gallon of transformer oil to the ground due to transport accident occurred in 2002 at the property. Based on the city directory, the property was occupied by Service Station in 1960.	
19.	14 Plains Road East	Off-Site (100 m south)	#10 – Commercial Autobody Shops	Based on the FIPs, the property located at 14 Plains Road East, approximately 100 m south, was occupied by an auto service centre with an UST situated in the southwestern portion of the property in 1971. Based on the ESRI report, the property, occupied by Esso Imperial Oil Limited, and Imperial Oil Mac's Convenience, was listed as a waste generator for light fuels, oil skimmings and sludges, waste oil and lubricants between 2005 and 2022. The property was listed as having operation of petroleum product agents and brokers, gasoline stations with convenience stores. The property, occupied by Mac's Convenience Stores Inc., had four (4) records of a double wall gasoline UST in 2011, three (3) records of a single wall gasoline UST in 1992, one (1) record of self serve gasoline station, three (3) records of expired fuel storage piping in 2012, a record of an expired fuel storage facility in 2013, a record of an expired cylinder exchange facility in 2012, three (3) records for expired fuel tank in 2009 and two (2) records of retail fuel tank in 1996. A gasoline spill due to valve malfunction occurred in 1991 at the property.	No Located downgradient
20.			#28 – Gasoline and Associated Products Storage in Fixed Tanks		

Table III

POTENTIALLY CONTAMINATING ACTIVITIES (PCAs) (Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04) 1026 Cooke Boulevard, Burlington, Ontario					
PCA Identifier	**Address**	**Location of Activity (In relation to Site)[1]**	**Potentially Contaminating Activity (PCA)[2]**	**Description and Approximate timeline that PCA Occurred**	**Contribution to APEC at the Site**
				Based on the city directory, the property was occupied by Jim & Ed's Service Center in 1957, Lloyd's Esso Service Station in 1960, Burl Esso No. 2 in 1967, La Salle Esso Service Station in 1972, Thompson Jack Self Service Esso Station in 1997, Aldershot Automotive Self Service Station in 1982, Moore Auto Service and More Esso Service in 1987, Mac's Convenience Store from 1997 to 2017, and Esso in 2021. Based on the site reconnaissance conducted by BIG in 2023, the property is occupied by Esso gas station.	
21.	1060 Waterdown Road	Off-Site (115 m west)	#12 – Concrete, Cement and Lime Manufacturing	Based on the city directory, the property located at 1060 Waterdown Road, approximately 115 m west, was occupied by Howard Concrete & Materials in 1957.	No Inferred trans-gradient
22.	18 Plains Road West	Off-Site (130 m south)	#10 – Commercial Autobody Shops	Based on the city directory, the property located at 18 Plains Road West (formerly northern portion of 8 Plains Road West), approximately 135 m south, was occupied by Rudolf's Variety Store in 1957 and De La Salle Cleaners in 1960. Based on the FIPs, property located at 18 Plains Road West (formerly northern portion of 14 to 20 Plains Road West), approximately 135 m south, was occupied by a truck and equipment repair shop with one spray painting workshop in the western portion, one gasoline UST, and one diesel oil UST situated in the central portion of the property in 1971.	No Located downgradient
23.			#28 – Gasoline and Associated Products Storage in Fixed Tanks		
24.			#37 – Operation of Dry-Cleaning Equipment (where chemicals are used		
25.			#39 Paints Manufacturing, Processing and Bulk Storage		
26.	1074 Cooke Boulevard	Off-Site (135 m north)	#19 – Electronic and Computer Equipment Manufacturing	Based on the ESRI report, the property located at 1074 Cooke Boulevard, approximately 135 m north, occupied by Etratech Manufacturing Inc., Eclipse Colour Ontario Ltd. And PV Labs Ltd, was listed as a waste generator for paint/pigment/coating residues, organic and inorganic	No Located at a significant distance
27.			#31 – Ink Manufacturing,		

Table III

POTENTIALLY CONTAMINATING ACTIVITIES (PCAs) (Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04) 1026 Cooke Boulevard, Burlington, Ontario					
PCA Identifier	**Address**	**Location of Activity (In relation to Site)[1]**	**Potentially Contaminating Activity (PCA)[2]**	**Description and Approximate timeline that PCA Occurred**	**Contribution to APEC at the Site**
			Processing and Bulk Storage	laboratory chemicals, aliphatic solvents, miscellaneous waste organic, polymeric resins, graphic art and photo-processing wastes between 1993 and 2022. The Site was listed as having operations of electronic parts and components and platemaking. The property, occupied by Etratech Inc., was listed as having operation of semiconductor and other electronic component manufacturing, measuring and medical and controlling devices manufacturing in 1989. Based on the city directory, the property was occupied by Etratech Designs Inc in 1997, Eclipse Colour Int Ltd. In 2002, Town Publishing from 2007 to 2012, Biz Magazine from 2012 to 2017, and PV Labs in 2021.	
28.	2 Masonry Court	Off-Site (135 m north)	#19 – Electronic and Computer Equipment Manufacturing	Based on the ESRI report, the property located at 2 Masonry Court, approximately 135 m north, occupied by BHC Cable Assemblies Inc., was listed as having operation of semiconductor and other electronic component manufacturing in 1996. Based on the city directory, the property was occupied by BHC from 2007 to 2021.	No Located at a significant distance
29.	91 Plains Road East	Off-Site (180 m east)	#28 – Gasoline and Associated Products Storage in Fixed Tanks	Based on the ESRI report, the property located at 91 Plains Road East, approximately 180 m east, occupied by Petro-Partners, had a record of a fuel tank. Based on the city directory, the property was occupied by Petro Partners in 2002.	No Inferred trans-gradient
30.	29 Plains Road West	Off-Site (180 m west)	#10 – Commercial Autobody Shops	Based on the FIPs, the property located at 29 Plains Road West, approximately 180 m west, was occupied by a residential dwelling with one UST situated in the northeastern portion of the property in 1971. Based on the city directory, the property was occupied by West Plains Supertest Service Station in 1967.	No Inferred trans-gradient
31.			#28 – Gasoline and Associated Products Storage in Fixed Tanks		

Table III

POTENTIALLY CONTAMINATING ACTIVITIES (PCAs)

(Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04)

1026 Cooke Boulevard, Burlington, Ontario

PCA Identifier	Address	Location of Activity (In relation to Site)[1]	Potentially Contaminating Activity (PCA)[2]	Description and Approximate timeline that PCA Occurred	Contribution to APEC at the Site
32.	92 Plains Road East	Off-Site (210 m east)	#28 – Gasoline and Associated Products Storage in Fixed Tanks	Based on the ESRI report, the property located at 92 Plains Road East, approximately 210 m east, filed a Phase One and Two RSC for residential use in 2018. The property has potential environmental concerns due to former 250-gallon heating oil AST prior to 2015.	No Inferred trans-gradient
33.	1120 Cooke Boulevard	Off-Site (230 m north)	#12 – Concrete, Cement and Lime Manufacturing	Based on the ESRI report, the property located at 1120 Cooke Boulevard (formerly 101 Masonry Court), approximately 230 m north, occupied by TCG Materials Limited and Adi Development (Masonry) Inc., was listed as a waste generator for waste oils and lubricants, petroleum distillates between 1992 and 2001 and waste oils/sludges (petroleum based) in 2017. The Site was listed as having operations of sand and gravel pits. The property, occupied by TCG Materials Ltd., had two (2) records of expired fuel storage piping in 2012, a record of an expired fuel storage facility in 2013, two (2) records of a double wall diesel aboveground storage tank (AST) in 1992, two (2) records of an expired fuel tank in 2009 and a record of a retail fuel tank in 1996. The property, occupied by TCG Materials Limited, was listed as having operation of concrete block and brick manufacturing.	No Located at a significant distance
34.			#28 – Gasoline and Associated Products Storage in Fixed Tanks		

Notes:

(1) Distances are approximately only. Precise distances are not possible due to the age of some listings and the aggregation and/or loss of addresses.

(2) Potentially contaminating activity means a use or activity set out in Column A of Table 2 of Schedule D (O.Reg.153/04. as amended) which is occurring or has occurred in a Phase One Study Area.

Table IV

AREAS OF POTENTIAL ENVIRONMENTAL CONCERN (APECs) (Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04) 1026 Cooke Boulevard, Burlington, Ontario					
Area of Potential Environmental Concern (APEC)[1]	**Location of APEC on Phase One Property**	**Potentially Contaminating Activity (PCA)[2]**	**Location of PCA (On-Site or Off-Site)[2]**	**Potential Contaminants of Concern**	**Media Potentially Impacted (Groundwater, soil and/or sediment)**
APEC 1: Importation of unknown quality of fill material	Entire Site	#30 – Importation of Fill Material of Unknown Quality	On-Site	PAHs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Soil and Groundwater
APEC 2: De-icing salts usage	Exterior of the Site Building	"Other" – Usage of De-icing Salts	On-Site	Electrical Conductivity, SAR, Na and Cl-	Soil and Groundwater
APEC 3: Former chemical product manufacturer	Northern portion	#8 – Chemical Manufacturing, Processing and Bulk Storage	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater
APEC 4: Former print shop	Southwestern portion	#31 – Ink Manufacturing, Processing and Bulk Storage	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater
APEC 5: Former auto services	Southeastern portion	#10 – Commercial Autobody Shops	Off-Site	PHCs, BTEX and VOCs	Groundwater
APEC 6: Former UST	Southeastern portion	#28 – Gasoline and Associated Products Storage in Fixed Tanks	Off-Site	PHCs and BTEX	Groundwater
APEC 7: Former dry cleaner	Southwestern portion	#37 – Operation of Dry Cleaning Equipment (where chemicals are used)	Off-Site	VOCs	Groundwater
APEC 8: Former semiconductor and other electronic component manufacturer	Northeastern portion	#19 – Electronic and Computer Equipment Manufacturing	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater

Table IV

AREAS OF POTENTIAL ENVIRONMENTAL CONCERN (APECs)

(Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04)

1026 Cooke Boulevard, Burlington, Ontario

Area of Potential Environmental Concern (APEC)[1]	Location of APEC on Phase One Property	Potentially Contaminating Activity (PCA)[2]	Location of PCA (On-Site or Off-Site)[2]	Potential Contaminants of Concern	Media Potentially Impacted (Groundwater, soil and/or sediment)
APEC 9: Former semiconductor and other electronic component manufacturer	Northern portion	#19 – Electronic and Computer Equipment Manufacturing	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater
APEC 10: Former plastic product manufacturer	Northern portion	#43 – Plastics (including Fibreglass) Manufacturing and Processing	Off-Site	VOCs	Groundwater
APEC 11: Former electronic parts manufacturer	Northern portion	#19 – Electronic and Computer Equipment Manufacturing	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater
APEC 12: Print shop	Northern portion	#31 – Ink Manufacturing, Processing and Bulk Storage	Off-Site	VOCs, metals, As, Sb, Se, Cr (VI), Hg, B-HWS and CN-	Groundwater

Notes:

1, Area of Potential Environmental Concern means the area on, in or under a phase one study area where one or more contaminants are potentially present, as determined through the P1 ESA, including through,

(a) Identification of post or present uses on, in or under the phase one property, and

(b) Identification of potentially contaminating activities.

2. Potentially contaminating activity means a use or activity set out in Column A of Table 2 of Schedule D that is occurring or has occurred in a phase one study area

3. When completing this column, identify all contaminants of potential concern using the Method Groups as identified in the "Protocol for in the Assessment of Properties under Part XV.1 of the Environmental Protection Act, March 9, 2004, amended as of July 1, 2011, as specified below:

ABNs	PCB:	Metals	Electrical Conductivity
CPs	PAHs	As, Sb, Se	Cr (Vi)
1,4- Dioxane	THMs	Na	Hg
Dioxins/Furans, PCDDs/PCDFs	VOCs	B-HWS	Methyl Mercury

Table IV

AREAS OF POTENTIAL ENVIRONMENTAL CONCERN (APECs)

(Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04)

1026 Cooke Boulevard, Burlington, Ontario

Area of Potential Environmental Concern (APEC)[1]	Location of APEC on Phase One Property	Potentially Contaminating Activity (PCA)[2]	Location of PCA (On-Site or Off-Site)[2]	Potential Contaminants of Concern	Media Potentially Impacted (Groundwater, soil and/or sediment)
Ocs	BTEX	Cl-	high pH		
PHCs	Ca,	Mg	CN-	low pH	

4. When submitting a record of site condition for filing, a copy of this table must be attached

SAR = Sodium Adsorption Ratio
PHCs = Petroleum Hydrocarbons
PCBs = Polychlorinated Biphenyl

(1) Distances are approximately only. Precise distances are not possible due to the age of some listings and the aggregation and/or loss of addresses.

(2) Potentially contaminating activity means a use or activity set out in Column A of Table 2 of Schedule D (O.Reg. 153/04. as amended) which is occurring or has occurred in a Phase One Study Area

APPENDIX A: LIMITATION OF LIABILITY, SCOPE OF REPORT, AND THIRD-PARTY RELIANCE

Limitation of Liability, Scope of Report, and Third Party Reliance

The information presented in this report is based on visual site inspection and following the general guidance provided in the O.Reg.153/04 as amended. The objectives of the investigation were to evaluate the current environmental conditions of the subject property. The observations, conclusions and recommendations presented in this report are based on the site conditions existing at the time of BIG's site visit. If in the future, a Record of Site Condition (RSC) is pursued or additional information is become available or revealed through intrusive on-site testing, BIG should be contacted to re-evaluate the information presented in this report, if required.

This report was prepared for the exclusive use of Halton Standard Condominium Corporation No. 416. BIG's consent is required to reproduce this report in whole or in part. BIG is not responsible for any decision made or reliance by a third party makes of this report. BIG is not responsible for any damages, suffered by a third-party as result of the use of this report.

APPENDIX B: LEGAL SURVEY PLAN

Phase One/Phase Two/RSC Property Boundary

SURVEYOR'S REAL PROPERTY REPORT

PART 1, PLAN OF

LOT 6
REGISTERED PLAN 20M-507
IN THE
CITY OF BURLINGTON
REGIONAL MUNICIPALITY OF HALTON

SCALE 1:150 METRIC

3 1.5 0 3 6 9 metres

R.A. McLAREN, O.L.S. – 2023

PART 2
PLAN 20R-8287
PIN 07122-0104 (LT)

PIN 07122-0100 (LT)

PIN 07122-0095 (LT)

PIN 07122-0087 (LT)

PIN 07122-0061

PIN 07122-0071

PIN 07122-0072

PART 1 PLAN 20R-12403

PART 3 PLAN 20R-5360

PART 3 PLAN 20R-8287

PART 8, PLAN 20R-302

PART 6 PLAN 20R-9468 SUBJECT TO AN EASEMENT AS IN INSTRUMENT H414356

PART 7 PLAN 20R-9468 SUBJECT TO AN EASEMENT AS IN INSTRUMENT H414356

HALTON STANDARD CONDOMINIUM PLAN 345

BLOCK 25646

HALTON STANDARD CONDOMINIUM PLAN 416

BLOCK 25718

SUBJECT TO EASEMENTS AS SET OUT IN SCHEDULE "A" OF DECLARATION HR 16/930

2 STOREY CONCRETE BLOCK BUILDING No. 1038

2 STOREY CONCRETE BLOCK BUILDING No. 1026

N43°33'25"E (71.029 P1) (Msd) 70.967

N42°44'30"E 72.213 (P1 & Msd)

N44°57'45"W 45.459 (P1 & Msd)

N46°27'40"W 44.456 (P1 & Set)

41.148 (P1 & Msd)

4.593 (P1 & Msd)

22.519 (P1 & Msd)

22.51 (P1 & Set)

COOKE BOULEVARD (BY PLAN 62M-507) PIN 07122-0069 (LT)

SITE BENCH MARK
CUTSTAR
ELEV. = 100.55

BENCHMARK:
MONUMENT 3488

MAPLEHURST SCHOOL, 481 PLAINS ROAD EAST (HIGHWAY 2) 1.92 km NORTHEAST OF WATERDOWN ROAD, TABLET IN THE FRONT OF SOUTHEAST CONCRETE FOUNDATION WALL, 1.5 m SOUTHWEST OF THE MOST EASTERLY OF TWO ENTRANCES, 0.1 m BELOW RED BRICK SIDING No 3488

ELEVATION: 98.754 metres

SURVEYOR'S REAL PROPERTY REPORT (PART 2)

LOT 6, PLAN 20M-507
SUBJECT TO AN EASEMENT AS IN INST. H414356 AS ILLUSTRATED ON THE PLAN.

THIS PLAN DOES NOT CERTIFY COMPLIANCE WITH ZONING BY-LAWS.

THIS PLAN WAS PREPARED FOR KATHLEEN DRYDEN

NOTE:

UNDERGROUND SERVICE AND UTILITY LOCATIONS WERE LOCATED BY URBAN ENGINEERING CONSULTANTS DRAWING No. MC-4 (SHEET 2 OF 2)

UNDERGROUND SERVICE AND UTILITY LOCATIONS MUST BE VERIFIED PRIOR TO CONSTRUCTION

INVERTS MUST BE VERIFIED PRIOR TO CONSTRUCTION

BEARING NOTE:
BEARINGS ARE UTM GRID, DERIVED FROM OBSERVED REFERENCE POINTS A AND B, BY REAL TIME NETWORK OBSERVATIONS, UTM ZONE 17, NAD83 (CSRS) (2010.0)

NOTE:
DISTANCES ARE GROUND AND CAN BE CONVERTED TO GRID BY MULTIPLYING BY THE COMBINED SCALE FACTOR OF 0.9996950

INTEGRATION DATA

OBSERVED REFERENCE POINTS (ORP's): UTM ZONE 17, NAD83 (CSRS) (2010.0). COORDINATES TO URBAN ACCURACY PER SEC. 14(2) OF O.REG. 216/10

POINT ID	NORTHING	EASTING
ORP Ⓐ	4795709.943	593058.422
ORP Ⓑ	4795626.321	593041.671

COORDINATES CANNOT, IN THEMSELVES, BE USED TO RE-ESTABLISH CORNERS OR BOUNDARIES SHOWN ON THIS PLAN.

LEGEND:

□	DENOTES	MONUMENT SET
■	-	MONUMENT FOUND
IB	-	IRON BAR
PB	-	PLASTIC BAR
CC	-	CUT CROSS
SIB	-	STANDARD IRON BAR
SSIB	-	SHORT STANDARD IRON BAR
BZA	-	A.T. McLAREN, O.L.S.
OU	-	ORIGIN UNKNOWN
Msd	-	MEASURED
P1	-	HALTON STANDARD CONDOMINIUM PLAN No. 416
CORB	-	CONCRETE CURB
SRW	-	STONE RETAINING WALL
WRW	-	WOOD RETAINING WALL
HV	-	HYDRO VAULT
ELEC	-	ELECTRICAL
FH	-	FIRE HYDRANT
WV	-	WATER VALVE
LSA	-	LANDSCAPED AREA
MF	-	METAL FENCE
DS	-	DOOR SILL
GF	-	GARAGE FLOOR
BOL	-	BOLLARD
CB	-	CATCH BASIN
MH	-	MANHOLE
GM	-	GAS METER
HM	-	HYDRO METER
ø	-	DIAMETER
//	-	NOT TO SCALE

METRIC NOTE:
DISTANCES AND COORDINATES SHOWN ON THIS PLAN ARE IN METRES AND CAN BE CONVERTED TO FEET BY DIVIDING BY 0.3048

SURVEYOR'S CERTIFICATE:

I CERTIFY THAT:
1. THIS SURVEY AND PLAN ARE CORRECT AND IN ACCORDANCE WITH THE SURVEYS ACT, THE SURVEYORS ACT AND THE REGULATIONS MADE UNDER THEM
2. THE SURVEY WAS COMPLETED ON THE 8th DAY OF MAY, 2023

10MAY2023
DATE

ROB A. McLAREN, O.L.S.

THIS PLAN OF SURVEY RELATES TO AOLS PLAN SUBMISSION FORM NUMBER 50786

© R.A. McLAREN, O.L.S. – 2023. NO PERSON MAY COPY REPRODUCE, DISTRIBUTE OR ALTER THIS PLAN IN WHOLE OR IN PART WITHOUT THE WRITTEN PERMISSION OF R.A. McLAREN, O.L.S.

A.T. McLaren Limited
LEGAL AND ENGINEERING SURVEYS
69 JOHN STREET SOUTH, SUITE 230
HAMILTON, ONTARIO, L8N 2B9
PHONE (905) 527-8559 FAX (905) 527-0032

Drawn	Checked	Crew Chief	Scale	Dwg.No.
JB	RBM	DW	1:150	37342

FILE NAME: 37342 Topo 1026 Cooke Boulevard.dwg LAYOUT: D-Size
LAST SAVED BY: Atmcd DATE: May 10, 2023

APPENDIX C: QUALIFICATION OF ASSESSORS

Qualifications of Accessors

The records review and site visit were conducted by Mr. Travis Van Holst, who has been trained to conduct Phase One/I ESAs in accordance with O. Reg 153 and CSA Standard Z768-01. Travis is a Geoscientist in training (GIT) and has a master's degree in Environmental Science from University of Toronto. He has been involved in numerous Phase One and Phase Two environmental site assessments (ESAs) under Ontario jurisdiction.

Ms. Eileen Liu, is a project manager at BIG. Eileen is a Professional Geoscientist in Ontario (P.Geo) and has a master's degree in Environmental Science from the university of Toronto, and has completed numerous Phase One and Phase Two ESA reports under Ontario jurisdiction. She has been involved in Environmental Site Assessments, risk assessments, remediation projects and environmental management report reviews under Federal jurisdiction.

Mr. Darko Strajin, is the Partner of BIG, he is a licensed engineer in province of Ontario and has over 25 years of consulting experience. Darko has been involved in conducting Phase One and Phase Two Environmental Site Assessments for more than 20 years. Darko has been responsible for successfully managing numerous environmental investigations and site assessments. Darko has in depth knowledge of Environmental Regulations including experience in geology, hydrogeology and geotechnical engineering that enables him to provide superior services to his client in the environmental industry. Darko has registered with the MECP as QP (Environmental Site Assessment) and has filed number of Record of Site Condition documents over the years.

APPENDIX D: CHAIN OF TITLE SEARCH

PROJECT # BIGC-ENV-605-A

#1026 COOKE BOULEVARD

PIN 25718-0001

UNIT #1
HALTON STANDARD CONDOMINIUM
PLAN NO. 416

formerly
TOWNSHIP OF EAST FLAMBOROUGH

formerly
TOWN OF BURLINGTON
now
CITY OF BURLINGTON

REGIONAL MUNICIPALITY OF HALTON

PIN	OWNERSHIP	DATES
25718-0001 07122-0089 07122-0063	**2155630 ONTARIO INC.**	**JANUARY 31 2013** **TO PRESENT AS OF** **APRIL 17 2023**
	MEGBROOK HOLDINGS INC.	DECEMBER 22 2002 TO JANUARY 31 2013
	HALTON STANDARD CONDOMINIUM PLAN NO. 416	**NOVEMBER 26 2002**
	REGISTERED PLAN NO. 20M-507	**JULY 18 1989**
EASEMENT	THE CORPORATION OF THE CITY OF BURLINGTON	JULY 18 1989
	THE COOKE GROUP INC.	APRIL 8 1988 TO DECEMBER 22 2002
	WILLIAM JACOB COOKE	SEPTEMBER 27 1987 TO APRIL 8 1988
	ZYKRA ENTERPRISES LIMITED	JULY 30 1981 TO SEPTEMBER 27 1987
	J. COOKE BLOCKS (ALDERSHOT) LIMITED	JANUARY 17 1962 TO JULY 30 1981
	J. COOKE (CONCRETE BLOCKS) LIMITED	OCTOBER 5 1953 TO JANUARY 17 1962
	FLORINDO DeLUCA ROSELINDA DeLUCA	JANUARY 31 1928 TO OCTOBER 5 1953
	GEORGE D. FILMAN	DECEMBER 31 1924 TO JANUARY 31 1928
	ROBERT L. SCOTT	OCTOBER 27 1924 TO DECEMBER 31 1924
	MABEL THOMSON JOHN SPROUT	AUGUST 3 1912 TO OCTOBER 27 1924

PIN	OWNERSHIP	DATES
	ALEXANDER BROWN (JR.) MARY BROWN **ESTATE OF** ALEXANDER BROWN (JR.)	NOVEMBER 27 1880 TO AUGUST 3 1912
	ALEXANDER BROWN (SR.)	NOVEMBER 29 1855 TO NOVEMBER 27 1880
CROWN PATENT	WILLIAM APPLEGARTH	DECEMBER 2 1833 TO NOVEMBER 29 1855

CROWN PATENT: DECEMBER 2 1833

LOT 6 ; CONCESSION 1

GEOGRAPHIC TOWNSHIP OF EAST FLAMBOROUGH

PROPERTY DESCRIPTION: UNIT 1, LEVEL 1, HALTON STANDARD CONDOMINIUM PLAN NO. 416 AND ITS APPURTENANT INTEREST. THE DESCRIPTION OF THE CONDOMINIUM PROPERTY IS : LT 6, PL 20M507, BURLINGTON, S/T EASE'S AS SET OUT IN SCHEDULE 'A' OF DECLARATION HR161930.

PROPERTY REMARKS:

ESTATE/QUALIFIER:
FEE SIMPLE
ABSOLUTE

RECENTLY:
CONDOMINIUM FROM 07122-0089

PIN CREATION DATE:
2002/11/27

OWNERS' NAMES
2155630 ONTARIO INC.

CAPACITY SHARE
ROWN

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
*** PRINTOUT INCLUDES ALL DOCUMENT TYPES AND DELETED INSTRUMENTS SINCE 2002/11/27 ***						
20R8287	1987/09/15	PLAN REFERENCE				C
H354981	1988/04/14	NOTICE		THE COOKE GROUP INC.	THE CORPORATION OF THE CITY OF BURLINGTON	C
20M507	1989/07/18	PLAN SUBDIVISION				C
20R9468	1989/07/25	PLAN REFERENCE				C
H412116	1989/07/31	NOTICE		THE COOKE GROUP INC.	THE REGIONAL MUNICIPALITY OF HALTON	C
H414354	1989/08/18	NOTICE		THE COOKE GROUP INC.	THE CORPORATION OF THE CITY OF BURLINGTON	C
REMARKS: PARTIALLY RELEASED BY H526515						
H414355	1989/08/18	NOTICE		THE COOKE GROUP INC.	THE CORPORATION OF THE CITY OF BURLINGTON	C
H414356	1989/08/18	TRANSFER EASEMENT			THE CORPORATION OF THE CITY OF BURLINGTON	C
H526515	1992/10/08	APL (GENERAL)				C
REMARKS: H414354						
H534040	1992/12/15	NOTICE		THE COOKE GROUP INC.	THE CORPORATION OF THE CITY OF BURLINGTON	C
HR137665	2002/08/08	CHARGE		*** DELETED AGAINST THIS PROPERTY *** THE COOKE GROUP INC.	ROYAL BANK OF CANADA	
HC416	2002/11/26	PLAN CONDOMINIUM				C
CORRECTIONS: REGISTRATION NUMBER CHANGED FROM HSTC416 TO HC416 ON 2010/03/10 BY COLE, ISABELLE.						
HR161930	2002/11/26	DECLARATION CONDO		THE COOKE GROUP INC.	THE COOKE GROUP INC.	C
HR165540	2002/12/10	CONDO BYLAW/98		HALTON STANDARD CONDOMINIUM CORPORATION NO. 416		C
REMARKS: NO. 1						

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
HR165541	2002/12/10	CONDO BYLAW/98		HALTON STANDARD CONDOMINIUM CORPORATION NO. 416		C
	REMARKS: NO. 2					
HR166452	2002/12/13	CONDO BYLAW/98		HALTON STANDARD CONDOMINIUM CORPORATION NO. 416		C
	REMARKS: BY-LAW NO. 3					
HR166453	2002/12/13	CONDO BYLAW/98		HALTON STANDARD CONDOMINIUM CORPORATION NO. 416		C
	REMARKS: BY-LAW NO. 4					
HR166796	2002/12/16	TRANSFER		*** COMPLETELY DELETED *** THE COOKE GROUP INC.	MEGBROOK HOLDINGS INC.	
	REMARKS: PLANNING ACT STATEMENTS					
HR166855	2002/12/16	DISCH OF CHARGE		*** COMPLETELY DELETED *** ROYAL BANK OF CANADA		
	REMARKS: RE: HR137665					
HR1079339	2013/01/31	TRANSFER	$500,000	MEGBROOK HOLDINGS INC.	2155630 ONTARIO INC.	C
HR1080923	2013/02/07	CHARGE	$350,000	2155630 ONTARIO INC.	ROYAL BANK OF CANADA	C

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

PROJECT # BIGC-ENV-605-A

#1026 COOKE BOULEVARD

PIN 25718-0002

UNIT #2
HALTON STANDARD CONDOMINIUM
PLAN NO. 416

formerly
TOWNSHIP OF EAST FLAMBOROUGH

formerly
TOWN OF BURLINGTON
now
CITY OF BURLINGTON

REGIONAL MUNICIPALITY OF HALTON

PIN	OWNERSHIP	DATES
25718-0002 07122-0089 07122-0063	**MEGBROOK HOLDINGS INC.**	**DECEMBER 22 2002** **TO PRESENT** **AS OF APRIL 20 2023**
	HALTON STANDARD CONDOMINIUM PLAN NO. 416	**NOVEMBER 26 2002**
	REGISTERED PLAN NO. 20M-507	**JULY 18 1989**
EASEMENT	THE CORPORATION OF THE CITY OF BURLINGTON	JULY 18 1989
	THE COOKE GROUP INC.	APRIL 8 1988 TO DECEMBER 22 2002
	WILLIAM JACOB COOKE	SEPTEMBER 27 1987 TO APRIL 8 1988
	ZYKRA ENTERPRISES LIMITED	JULY 30 1981 TO SEPTEMBER 27 1987
	J. COOKE BLOCKS (ALDERSHOT) LIMITED	JANUARY 17 1962 TO JULY 30 1981
	J. COOKE (CONCRETE BLOCKS) LIMITED	OCTOBER 5 1953 TO JANUARY 17 1962
	FLORINDO DeLUCA ROSELINDA DeLUCA	JANUARY 31 1928 TO OCTOBER 5 1953
	GEORGE D. FILMAN	DECEMBER 31 1924 TO JANUARY 31 1928
	ROBERT L. SCOTT	OCTOBER 27 1924 TO DECEMBER 31 1924
	MABEL THOMSON JOHN SPROUT	AUGUST 3 1912 TO OCTOBER 27 1924

PIN	OWNERSHIP	DATES
	ALEXANDER BROWN (JR.) MARY BROWN **ESTATE OF** ALEXANDER BROWN (JR.)	NOVEMBER 27 1880 TO AUGUST 3 1912
	ALEXANDER BROWN (SR.)	NOVEMBER 29 1855 TO NOVEMBER 27 1880
CROWN PATENT	WILLIAM APPLEGARTH	DECEMBER 2 1833 TO NOVEMBER 29 1855

CROWN PATENT: DECEMBER 2 1833

LOT 6 ; CONCESSION 1

GEOGRAPHIC TOWNSHIP OF EAST FLAMBOROUGH

PROPERTY DESCRIPTION: UNIT 2, LEVEL 1, HALTON STANDARD CONDOMINIUM PLAN NO. 416 AND ITS APPURTENANT INTEREST. THE DESCRIPTION OF THE CONDOMINIUM PROPERTY IS : LT 6, PL 20M507, BURLINGTON, S/T EASE'S AS SET OUT IN SCHEDULE 'A' OF DECLARATION HR161930.

PROPERTY REMARKS:

ESTATE/QUALIFIER:
FEE SIMPLE
ABSOLUTE

RECENTLY:
CONDOMINIUM FROM 07122-0089

PIN CREATION DATE:
2002/11/27

OWNERS' NAMES
MEGBROOK HOLDINGS INC.

CAPACITY SHARE
BENO

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
*** PRINTOUT INCLUDES ALL DOCUMENT TYPES AND DELETED INSTRUMENTS SINCE 2002/11/27 ***						
20R8287	1987/09/15	PLAN REFERENCE				C
H354981	1988/04/14	NOTICE		THE COOKE GROUP INC.	THE CORPORATION OF THE CITY OF BURLINGTON	C
20M507	1989/07/18	PLAN SUBDIVISION				C
20R9468	1989/07/25	PLAN REFERENCE				C
H412116	1989/07/31	NOTICE		THE COOKE GROUP INC.	THE REGIONAL MUNICIPALITY OF HALTON	C
H414354	1989/08/18	NOTICE		THE COOKE GROUP INC.	THE CORPORATION OF THE CITY OF BURLINGTON	C
REMARKS: PARTIALLY RELEASED BY H526515						
H414355	1989/08/18	NOTICE		THE COOKE GROUP INC.	THE CORPORATION OF THE CITY OF BURLINGTON	C
H414356	1989/08/18	TRANSFER EASEMENT			THE CORPORATION OF THE CITY OF BURLINGTON	C
H526515	1992/10/08	APL (GENERAL)				C
REMARKS: H414354						
H534040	1992/12/15	NOTICE		THE COOKE GROUP INC.	THE CORPORATION OF THE CITY OF BURLINGTON	C
HR137665	2002/08/08	CHARGE		*** DELETED AGAINST THIS PROPERTY *** THE COOKE GROUP INC.	ROYAL BANK OF CANADA	
HC416	2002/11/26	PLAN CONDOMINIUM				C
CORRECTIONS: REGISTRATION NUMBER CHANGED FROM HSTC416 TO HC416 ON 2010/03/10 BY COLE, ISABELLE.						
HR161930	2002/11/26	DECLARATION CONDO		THE COOKE GROUP INC.	THE COOKE GROUP INC.	C
HR165540	2002/12/10	CONDO BYLAW/98		HALTON STANDARD CONDOMINIUM CORPORATION NO. 416		C
REMARKS: NO. 1						

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
HR165541	2002/12/10	CONDO BYLAW/98		HALTON STANDARD CONDOMINIUM CORPORATION NO. 416		C
	REMARKS: NO. 2					
HR166452	2002/12/13	CONDO BYLAW/98		HALTON STANDARD CONDOMINIUM CORPORATION NO. 416		C
	REMARKS: BY-LAW NO. 3					
HR166453	2002/12/13	CONDO BYLAW/98		HALTON STANDARD CONDOMINIUM CORPORATION NO. 416		C
	REMARKS: BY-LAW NO. 4					
HR166792	2002/12/16	TRANSFER	$287,300	THE COOKE GROUP INC.	MEGBROOK HOLDINGS INC.	C
HR166855	2002/12/16	DISCH OF CHARGE		*** COMPLETELY DELETED *** ROYAL BANK OF CANADA		
	REMARKS: RE: HR137665					

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

PROJECT # BIGC-ENV-605-A

#1026 COOKE BOULEVARD

PIN 25718-0003

UNIT #3
HALTON STANDARD CONDOMINIUM
PLAN NO. 416

formerly
TOWNSHIP OF EAST FLAMBOROUGH

formerly
TOWN OF BURLINGTON
now
CITY OF BURLINGTON

REGIONAL MUNICIPALITY OF HALTON

PIN	OWNERSHIP	DATES
25718-0003 07122-0089 07122-0063	**1237565 ONTARIO LTD.**	**FEBRUARY 7 2017** **TO PRESENT** **AS OF APRIL 20 2023**
	DELANIC HOLDINGS LTD.	DECEMBER 23 2002 TO FEBRUARY 7 2017
	HALTON STANDARD CONDOMINIUM PLAN NO. 416	**NOVEMBER 26 2002**
	REGISTERED PLAN NO. 20M-507	**JULY 18 1989**
EASEMENT	THE CORPORATION OF THE CITY OF BURLINGTON	JULY 18 1989
	THE COOKE GROUP INC.	APRIL 8 1988 TO DECEMBER 23 2002
	WILLIAM JACOB COOKE	SEPTEMBER 27 1987 TO APRIL 8 1988
	ZYKRA ENTERPRISES LIMITED	JULY 30 1981 TO SEPTEMBER 27 1987
	J. COOKE BLOCKS (ALDERSHOT) LIMITED	JANUARY 17 1962 TO JULY 30 1981
	J. COOKE (CONCRETE BLOCKS) LIMITED	OCTOBER 5 1953 TO JANUARY 17 1962
	FLORINDO DeLUCA ROSELINDA DeLUCA	JANUARY 31 1928 TO OCTOBER 5 1953
	GEORGE D. FILMAN	DECEMBER 31 1924 TO JANUARY 31 1928
	ROBERT L. SCOTT	OCTOBER 27 1924 TO DECEMBER 31 1924
	MABEL THOMSON JOHN SPROUT	AUGUST 3 1912 TO OCTOBER 27 1924

PIN	OWNERSHIP	DATES
	ALEXANDER BROWN (JR.) MARY BROWN **ESTATE OF** ALEXANDER BROWN (JR.)	NOVEMBER 27 1880 TO AUGUST 3 1912
	ALEXANDER BROWN (SR.)	NOVEMBER 29 1855 TO NOVEMBER 27 1880
CROWN PATENT	WILLIAM APPLEGARTH	DECEMBER 2 1833 TO NOVEMBER 29 1855

CROWN PATENT: DECEMBER 2 1833

LOT 6 ; CONCESSION 1

GEOGRAPHIC TOWNSHIP OF EAST FLAMBOROUGH

PROPERTY DESCRIPTION: UNIT 3, LEVEL 1, HALTON STANDARD CONDOMINIUM PLAN NO. 416 AND ITS APPURTENANT INTEREST. THE DESCRIPTION OF THE CONDOMINIUM PROPERTY IS : LT 6, PL 20M507, BURLINGTON, S/T EASE'S AS SET OUT IN SCHEDULE 'A' OF DECLARATION HR161930.

PROPERTY REMARKS:

ESTATE/QUALIFIER:
FEE SIMPLE
ABSOLUTE

RECENTLY:
CONDOMINIUM FROM 07122-0089

PIN CREATION DATE:
2002/11/27

OWNERS' NAMES
1237565 ONTARIO LTD.

CAPACITY SHARE
ROWN

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
*** PRINTOUT INCLUDES ALL DOCUMENT TYPES AND DELETED INSTRUMENTS SINCE 2002/11/27 **						
20R8287	1987/09/15	PLAN REFERENCE				C
H354981	1988/04/14	NOTICE		THE COOKE GROUP INC.	THE CORPORATION OF THE CITY OF BURLINGTON	C
20M507	1989/07/18	PLAN SUBDIVISION				C
20R9468	1989/07/25	PLAN REFERENCE				C
H412116	1989/07/31	NOTICE		THE COOKE GROUP INC.	THE REGIONAL MUNICIPALITY OF HALTON	C
H414354	1989/08/18	NOTICE		THE COOKE GROUP INC.	THE CORPORATION OF THE CITY OF BURLINGTON	C
REMARKS: PARTIALLY RELEASED BY H526515						
H414355	1989/08/18	NOTICE		THE COOKE GROUP INC.	THE CORPORATION OF THE CITY OF BURLINGTON	C
H414356	1989/08/18	TRANSFER EASEMENT			THE CORPORATION OF THE CITY OF BURLINGTON	C
H526515	1992/10/08	APL (GENERAL)				C
REMARKS: H414354						
H534040	1992/12/15	NOTICE		THE COOKE GROUP INC.	THE CORPORATION OF THE CITY OF BURLINGTON	C
HR137665	2002/08/08	CHARGE		*** DELETED AGAINST THIS PROPERTY *** THE COOKE GROUP INC.	ROYAL BANK OF CANADA	
HC416	2002/11/26	PLAN CONDOMINIUM				C
CORRECTIONS: REGISTRATION NUMBER CHANGED FROM HSTC416 TO HC416 ON 2010/03/10 BY COLE, ISABELLE.						
HR161930	2002/11/26	DECLARATION CONDO		THE COOKE GROUP INC.	THE COOKE GROUP INC.	C
HR165540	2002/12/10	CONDO BYLAW/98		HALTON STANDARD CONDOMINIUM CORPORATION NO. 416		C
REMARKS: NO. 1						

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
HR165541	2002/12/10	CONDO BYLAW/98		HALTON STANDARD CONDOMINIUM CORPORATION NO. 416		C
	REMARKS: NO. 2					
HR166452	2002/12/13	CONDO BYLAW/98		HALTON STANDARD CONDOMINIUM CORPORATION NO. 416		C
	REMARKS: BY-LAW NO. 3					
HR166453	2002/12/13	CONDO BYLAW/98		HALTON STANDARD CONDOMINIUM CORPORATION NO. 416		C
	REMARKS: BY-LAW NO. 4					
HR168793	2002/12/23	TRANSFER		*** COMPLETELY DELETED *** THE COOKE GROUP INC.	DELANIC HOLDINGS LTD.	
HR168802	2002/12/23	DISCH OF CHARGE		*** COMPLETELY DELETED *** ROYAL BANK OF CANADA		
	REMARKS: RE: HR137665					
HR168817	2002/12/23	CHARGE		*** COMPLETELY DELETED *** DELANIC HOLDINGS LTD.	THE TORONTO-DOMINION BANK	
HR168819	2002/12/23	NO ASSGN RENT GEN		*** COMPLETELY DELETED *** THE TORONTO-DOMINION BANK	DELANIC HOLDINGS LTD.	
	REMARKS: HR168817					
HR1430842	2017/02/07	TRANSFER	$350,000	DELANIC HOLDINGS LTD.	1237565 ONTARIO LTD.	C
HR1451535	2017/05/03	CHARGE	$250,000	1237565 ONTARIO LTD.	ROYAL BANK OF CANADA	C
HR1472668	2017/07/17	DISCH OF CHARGE		*** COMPLETELY DELETED *** THE TORONTO-DOMINION BANK		
	REMARKS: HR168817.					

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

PROJECT # BIGC-ENV-605-A

#1026 COOKE BOULEVARD

PIN 25718-0004

UNIT #4
HALTON STANDARD CONDOMINIUM
PLAN NO. 416

formerly
TOWNSHIP OF EAST FLAMBOROUGH

formerly
TOWN OF BURLINGTON
now
CITY OF BURLINGTON

REGIONAL MUNICIPALITY OF HALTON

PIN	OWNERSHIP	DATES
25718-0004 07122-0089 07122-0063	**1237565 ONTARIO LTD.**	**JUNE 1 2022** **TO PRESENT** **AS OF APRIL 20 2023**
	1860247 ONTARIO INC.	OCTOBER 15 2018 TO JUNE 1 2022
	1658139 ONTARIO INC.	MARCH 1 2006 TO OCTOBER 15 2018
	1037231 ONTARIO INC.	JUNE 16 2005 TO MARCH 1 2006
	HALTON STANDARD CONDOMINIUM PLAN NO. 416	**NOVEMBER 26 2002**
	REGISTERED PLAN NO. 20M-507	**JULY 18 1989**
EASEMENT	THE CORPORATION OF THE CITY OF BURLINGTON	JULY 18 1989
	THE COOKE GROUP INC.	APRIL 8 1988 TO JUNE 16 2005
	WILLIAM JACOB COOKE	SEPTEMBER 27 1987 TO APRIL 8 1988
	ZYKRA ENTERPRISES LIMITED	JULY 30 1981 TO SEPTEMBER 27 1987
	J. COOKE BLOCKS (ALDERSHOT) LIMITED	JANUARY 17 1962 TO JULY 30 1981
	J. COOKE (CONCRETE BLOCKS) LIMITED	OCTOBER 5 1953 TO JANUARY 17 1962
	FLORINDO DeLUCA ROSELINDA DeLUCA	JANUARY 31 1928 TO OCTOBER 5 1953
	GEORGE D. FILMAN	DECEMBER 31 1924 TO JANUARY 31 1928

PIN	OWNERSHIP	DATES
	ROBERT L. SCOTT	OCTOBER 27 1924 TO DECEMBER 31 1924
	MABEL THOMSON JOHN SPROUT	AUGUST 3 1912 TO OCTOBER 27 1924
	ALEXANDER BROWN (JR.) MARY BROWN **ESTATE OF** ALEXANDER BROWN (JR.)	NOVEMBER 27 1880 TO AUGUST 3 1912
	ALEXANDER BROWN (SR.)	NOVEMBER 29 1855 TO NOVEMBER 27 1880
CROWN PATENT	WILLIAM APPLEGARTH	DECEMBER 2 1833 TO NOVEMBER 29 1855

CROWN PATENT: DECEMBER 2 1833

LOT 6 ; CONCESSION 1

GEOGRAPHIC TOWNSHIP OF EAST FLAMBOROUGH

PROPERTY DESCRIPTION: UNIT 4, LEVEL 1, HALTON STANDARD CONDOMINIUM PLAN NO. 416 AND ITS APPURTENANT INTEREST. THE DESCRIPTION OF THE CONDOMINIUM PROPERTY IS : LT 6, PL 20M507, BURLINGTON, S/T EASE'S AS SET OUT IN SCHEDULE 'A' OF DECLARATION HR161930.

PROPERTY REMARKS:

ESTATE/QUALIFIER:
FEE SIMPLE
ABSOLUTE

RECENTLY:
CONDOMINIUM FROM 07122-0089

PIN CREATION DATE:
2002/11/27

OWNERS' NAMES
1237565 ONTARIO LTD.

CAPACITY SHARE
ROWN

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
*** PRINTOUT INCLUDES ALL DOCUMENT TYPES AND DELETED INSTRUMENTS SINCE 2002/11/27 **						
20R8287	1987/09/15	PLAN REFERENCE				C
H354981	1988/04/14	NOTICE		THE COOKE GROUP INC.	THE CORPORATION OF THE CITY OF BURLINGTON	C
20M507	1989/07/18	PLAN SUBDIVISION				C
20R9468	1989/07/25	PLAN REFERENCE				C
H412116	1989/07/31	NOTICE		THE COOKE GROUP INC.	THE REGIONAL MUNICIPALITY OF HALTON	C
H414354	1989/08/18	NOTICE		THE COOKE GROUP INC.	THE CORPORATION OF THE CITY OF BURLINGTON	C
REMARKS: PARTIALLY RELEASED BY H526515						
H414355	1989/08/18	NOTICE		THE COOKE GROUP INC.	THE CORPORATION OF THE CITY OF BURLINGTON	C
H414356	1989/08/18	TRANSFER EASEMENT			THE CORPORATION OF THE CITY OF BURLINGTON	C
H526515	1992/10/08	APL (GENERAL)				C
REMARKS: H414354						
H534040	1992/12/15	NOTICE		THE COOKE GROUP INC.	THE CORPORATION OF THE CITY OF BURLINGTON	C
HR137665	2002/08/08	CHARGE		*** DELETED AGAINST THIS PROPERTY *** THE COOKE GROUP INC.	ROYAL BANK OF CANADA	
HC416	2002/11/26	PLAN CONDOMINIUM				C
CORRECTIONS: REGISTRATION NUMBER CHANGED FROM HSTC416 TO HC416 ON 2010/03/10 BY COLE, ISABELLE.						
HR161930	2002/11/26	DECLARATION CONDO		THE COOKE GROUP INC.	THE COOKE GROUP INC.	C
HR165540	2002/12/10	CONDO BYLAW/98		HALTON STANDARD CONDOMINIUM CORPORATION NO. 416		C
REMARKS: NO. 1						

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
HR165541	2002/12/10	CONDO BYLAW/98		HALTON STANDARD CONDOMINIUM CORPORATION NO. 416		C
	REMARKS: NO. 2					
HR166452	2002/12/13	CONDO BYLAW/98		HALTON STANDARD CONDOMINIUM CORPORATION NO. 416		C
	REMARKS: BY-LAW NO. 3					
HR166453	2002/12/13	CONDO BYLAW/98		HALTON STANDARD CONDOMINIUM CORPORATION NO. 416		C
	REMARKS: BY-LAW NO. 4					
HR190251	2003/04/11	DISCH OF CHARGE		*** COMPLETELY DELETED *** ROYAL BANK OF CANADA		
	REMARKS: RE: HR137665					
HR193528	2003/04/30	DISCH OF CHARGE		*** COMPLETELY DELETED *** ROYAL BANK OF CANADA		
	REMARKS: RE: HR137665					
HR385208	2005/06/16	TRANSFER		*** COMPLETELY DELETED *** THE COOKE GROUP INC.	1037231 ONTARIO INC.	
HR458488	2006/03/01	TRANSFER		*** COMPLETELY DELETED *** 1037231 ONTARIO INC.	1658139 ONTARIO INC.	
HR1578811	2018/10/15	TRANSFER		*** COMPLETELY DELETED *** 1658139 ONTARIO INC.	1860247 ONTARIO INC.	
HR1578812	2018/10/15	CHARGE		*** COMPLETELY DELETED *** 1860247 ONTARIO INC.	1658139 ONTARIO INC.	
HR1896585	2022/06/01	TRANSFER	$982,600	1860247 ONTARIO INC.	1237565 ONTARIO LTD.	C
HR1896811	2022/06/02	DISCH OF CHARGE		*** COMPLETELY DELETED *** 1658139 ONTARIO INC.		
	REMARKS: HR1578812.					

PROJECT # BIGC-ENV-605-A

#1026 COOKE BOULEVARD

PIN 25718-0005

UNIT #5
HALTON STANDARD CONDOMINIUM
PLAN NO. 416

formerly
TOWNSHIP OF EAST FLAMBOROUGH

formerly
TOWN OF BURLINGTON
now
CITY OF BURLINGTON

REGIONAL MUNICIPALITY OF HALTON

PIN	OWNERSHIP	DATES
25718-0005 07122-0089 07122-0063	**1237565 ONTARIO LTD.**	**MAY 31 2022** **TO PRESENT** **AS OF APRIL 20 2023**
	SCOTT ARTHUR RAY	FEBRUARY 3 2011 TO MAY 31 2022
	CONTROTECH AUTOMATION LTD.	MAY 3 2004 TO FEBRUARY 3 2011
	THE COOKE GROUP INC.	NOVEMBER 14 2003 TO MAY 3 2004
	FEATUREWORK INC.	APRIL 11 2003 TO NOVEMBER 14 2003
	HALTON STANDARD CONDOMINIUM PLAN NO. 416	**NOVEMBER 26 2002**
	REGISTERED PLAN NO. 20M-507	**JULY 18 1989**
EASEMENT	THE CORPORATION OF THE CITY OF BURLINGTON	JULY 18 1989
	THE COOKE GROUP INC.	APRIL 8 1988 TO APRIL 11 2003
	WILLIAM JACOB COOKE	SEPTEMBER 27 1987 TO APRIL 8 1988
	ZYKRA ENTERPRISES LIMITED	JULY 30 1981 TO SEPTEMBER 27 1987
	J. COOKE BLOCKS (ALDERSHOT) LIMITED	JANUARY 17 1962 TO JULY 30 1981
	J. COOKE (CONCRETE BLOCKS) LIMITED	OCTOBER 5 1953 TO JANUARY 17 1962
	FLORINDO DeLUCA ROSELINDA DeLUCA	JANUARY 31 1928 TO OCTOBER 5 1953

PIN	OWNERSHIP	DATES
	GEORGE D. FILMAN	DECEMBER 31 1924 TO JANUARY 31 1928
	ROBERT L. SCOTT	OCTOBER 27 1924 TO DECEMBER 31 1924
	MABEL THOMSON JOHN SPROUT	AUGUST 3 1912 TO OCTOBER 27 1924
	ALEXANDER BROWN (JR.) MARY BROWN **ESTATE OF** ALEXANDER BROWN (JR.)	NOVEMBER 27 1880 TO AUGUST 3 1912
	ALEXANDER BROWN (SR.)	NOVEMBER 29 1855 TO NOVEMBER 27 1880
CROWN PATENT	WILLIAM APPLEGARTH	DECEMBER 2 1833 TO NOVEMBER 29 1855

CROWN PATENT: DECEMBER 2 1833

LOT 6 ; CONCESSION 1

GEOGRAPHIC TOWNSHIP OF EAST FLAMBOROUGH

PROPERTY DESCRIPTION: UNIT 5, LEVEL 1, HALTON STANDARD CONDOMINIUM PLAN NO. 416 AND ITS APPURTENANT INTEREST. THE DESCRIPTION OF THE CONDOMINIUM PROPERTY IS : LT 6, PL 20M507. S/T EASE'S AS SET OUT IN SCHEDULE 'A' OF DECLARATION HR161930.; CITY OF BURLINGTON

PROPERTY REMARKS:

ESTATE/QUALIFIER:
FEE SIMPLE
ABSOLUTE

RECENTLY:
CONDOMINIUM FROM 07122-0089

PIN CREATION DATE:
2002/11/27

OWNERS' NAMES
1237565 ONTARIO LTD.

CAPACITY SHARE
ROWN

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
*** PRINTOUT INCLUDES ALL DOCUMENT TYPES AND DELETED INSTRUMENTS SINCE 2002/11/27 ***						
20R8287	1987/09/15	PLAN REFERENCE				C
H354981	1988/04/14	NOTICE		THE COOKE GROUP INC.	THE CORPORATION OF THE CITY OF BURLINGTON	C
20M507	1989/07/18	PLAN SUBDIVISION				C
20R9468	1989/07/25	PLAN REFERENCE				C
H412116	1989/07/31	NOTICE		*** DELETED AGAINST THIS PROPERTY *** THE COOKE GROUP INC.	THE REGIONAL MUNICIPALITY OF HALTON	
H414354	1989/08/18	NOTICE		THE COOKE GROUP INC.	THE CORPORATION OF THE CITY OF BURLINGTON	C
REMARKS: PARTIALLY RELEASED BY H526515						
H414355	1989/08/18	NOTICE		THE COOKE GROUP INC.	THE CORPORATION OF THE CITY OF BURLINGTON	C
H414356	1989/08/18	TRANSFER EASEMENT			THE CORPORATION OF THE CITY OF BURLINGTON	C
H526515	1992/10/08	APL (GENERAL)				C
REMARKS: H414354						
H534040	1992/12/15	NOTICE		THE COOKE GROUP INC.	THE CORPORATION OF THE CITY OF BURLINGTON	C
HR137665	2002/08/08	CHARGE		*** DELETED AGAINST THIS PROPERTY *** THE COOKE GROUP INC.	ROYAL BANK OF CANADA	
HC416	2002/11/26	PLAN CONDOMINIUM				C
CORRECTIONS: REGISTRATION NUMBER CHANGED FROM HSTC416 TO HC416 ON 2010/03/10 BY COLE, ISABELLE.						
HR161930	2002/11/26	DECLARATION CONDO		THE COOKE GROUP INC.	THE COOKE GROUP INC.	C
HR165540	2002/12/10	CONDO BYLAW/98		HALTON STANDARD CONDOMINIUM CORPORATION NO. 416		C

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.
NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
	REMARKS: NO. 1					
HR165541	2002/12/10	CONDO BYLAW/98		HALTON STANDARD CONDOMINIUM CORPORATION NO. 416		C
	REMARKS: NO. 2					
HR166452	2002/12/13	CONDO BYLAW/98		HALTON STANDARD CONDOMINIUM CORPORATION NO. 416		C
	REMARKS: BY-LAW NO. 3					
HR166453	2002/12/13	CONDO BYLAW/98		HALTON STANDARD CONDOMINIUM CORPORATION NO. 416		C
	REMARKS: BY-LAW NO. 4					
HR190180	2003/04/11	TRANSFER		*** COMPLETELY DELETED *** THE COOKE GROUP INC.	FEATUREWORK INC.	
HR190181	2003/04/11	CHARGE		*** COMPLETELY DELETED *** FEATUREWORK INC.	THE COOKE GROUP INC.	
HR190182	2003/04/11	CHARGE		*** COMPLETELY DELETED *** FEATUREWORK INC.	SCHREIBER, WILFRED SCHREIBER, AUDREY	
HR190251	2003/04/11	DISCH OF CHARGE		*** COMPLETELY DELETED *** ROYAL BANK OF CANADA		
	REMARKS: RE: HR137665					
HR193528	2003/04/30	DISCH OF CHARGE		*** COMPLETELY DELETED *** ROYAL BANK OF CANADA		
	REMARKS: RE: HR137665					
HR243510	2003/11/14	TRANSFER		*** COMPLETELY DELETED *** FEATUREWORK INC.	THE COOKE GROUP INC.	
HR243524	2003/11/14	DISCH OF CHARGE		*** COMPLETELY DELETED *** THE COOKE GROUP INC.		
	REMARKS: RE: HR190181					
HR243928	2003/11/17	DISCH OF CHARGE		*** COMPLETELY DELETED *** SCHREIBER, WILFRED SCHREIBER, AUDREY		
	REMARKS: RE: HR190182					
HR282520	2004/05/03	TRANSFER		*** COMPLETELY DELETED *** THE COOKE GROUP INC.	CONTROTECH AUTOMATION LTD.	

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
HR282524	2004/05/03	CHARGE		*** COMPLETELY DELETED *** CONTROTECH AUTOMATION LTD.	ROYAL BANK OF CANADA	
HR329866	2004/10/22	NO COMPL SUB AGR		*** COMPLETELY DELETED ***	THE REGIONAL MUNICIPALITY OF HALTON	
	REMARKS: RE: H412116					
HR906289	2011/02/03	TRANSFER		*** COMPLETELY DELETED *** CONTROTECH AUTOMATION LTD.	RAY, SCOTT ARTHUR	
HR1896018	2022/05/31	TRANSFER	$959,225	RAY, SCOTT ARTHUR	1237565 ONTARIO LTD.	C
HR1901846	2022/06/23	DISCH OF CHARGE		*** COMPLETELY DELETED *** ROYAL BANK OF CANADA		
	REMARKS: HR282524.					

APPENDIX E: ECOLOG ERIS REPORT

DATABASE REPORT

Project Property:	*1026 Cooke Boulevard* *1026 Cooke Boulevard* *Burlington ON L7T 4A8*
Project No:	*BIGC-ENV-605A*
Report Type:	*RSC Report (Urban)*
Order No:	*23041300087*
Requested by:	*B.I.G. Consulting Inc.*
Date Completed:	*April 18, 2023*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....6
Executive Summary: Site Report Summary - Surrounding Properties.....7
Executive Summary: Summary By Data Source.....32
Map.....63
Aerial.....64
Topographic Map.....65
Detail Report.....66
Unplottable Summary.....269
Unplottable Report.....271
Appendix: Database Descriptions.....278
Definitions.....287

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Limited Partnership ("ERIS") using various sources of information, including information provided by Federal and Provincial government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Limited Partnership. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:	*1026 Cooke Boulevard* *1026 Cooke Boulevard Burlington ON L7T 4A8*
Project No:	*BIGC-ENV-605A*

Order Information:

Order No:	*23041300087*
Date Requested:	*April 13, 2023*
Requested by:	*B.I.G. Consulting Inc.*
Report Type:	*RSC Report (Urban)*

Historical/Products:

City Directory Search	*CD - Subject Site plus 250m Radius*
ERIS Xplorer	*ERIS Xplorer*
Topographic Map	*RSC Maps*

Executive Summary: Report Summary

Database	Name	Searched	Project Property	Boundary to 0.30km	Total
AAGR	Abandoned Aggregate Inventory	Y	0	0	0
AGR	Aggregate Inventory	Y	0	0	0
AMIS	Abandoned Mine Information System	Y	0	0	0
ANDR	Anderson's Waste Disposal Sites	Y	0	0	0
AST	Aboveground Storage Tanks	Y	0	0	0
AUWR	Automobile Wrecking & Supplies	Y	0	0	0
BORE	Borehole	Y	0	1	1
CA	Certificates of Approval	Y	0	15	15
CDRY	Dry Cleaning Facilities	Y	0	0	0
CFOT	Commercial Fuel Oil Tanks	Y	0	0	0
CHEM	Chemical Manufacturers and Distributors	Y	0	0	0
CHM	Chemical Register	Y	0	0	0
CNG	Compressed Natural Gas Stations	Y	0	0	0
COAL	Inventory of Coal Gasification Plants and Coal Tar Sites	Y	0	0	0
CONV	Compliance and Convictions	Y	0	0	0
CPU	Certificates of Property Use	Y	0	0	0
DRL	Drill Hole Database	Y	0	0	0
DTNK	Delisted Fuel Tanks	Y	0	24	24
EASR	Environmental Activity and Sector Registry	Y	0	3	3
EBR	Environmental Registry	Y	0	9	9
ECA	Environmental Compliance Approval	Y	0	9	9
EEM	Environmental Effects Monitoring	Y	0	0	0
EHS	ERIS Historical Searches	Y	1	51	52
EIIS	Environmental Issues Inventory System	Y	0	0	0
EMHE	Emergency Management Historical Event	Y	0	0	0
EPAR	Environmental Penalty Annual Report	Y	0	0	0
EXP	List of Expired Fuels Safety Facilities	Y	0	0	0
FCON	Federal Convictions	Y	0	0	0
FCS	Contaminated Sites on Federal Land	Y	0	0	0
FOFT	Fisheries & Oceans Fuel Tanks	Y	0	0	0
FRST	Federal Identification Registry for Storage Tank Systems (FIRSTS)	Y	0	0	0
FST	Fuel Storage Tank	Y	0	11	11
FSTH	Fuel Storage Tank - Historic	Y	0	0	0
GEN	Ontario Regulation 347 Waste Generators Summary	Y	0	78	78
GHG	Greenhouse Gas Emissions from Large Facilities	Y	0	0	0
HINC	TSSA Historic Incidents	Y	0	1	1

Database	Name	Searched	Project Property	Boundary to 0.30km	Total
IAFT	Indian & Northern Affairs Fuel Tanks	Y	0	0	0
INC	Fuel Oil Spills and Leaks	Y	0	0	0
LIMO	Landfill Inventory Management Ontario	Y	0	0	0
MINE	Canadian Mine Locations	Y	0	0	0
MNR	Mineral Occurrences	Y	0	0	0
NATE	National Analysis of Trends in Emergencies System (NATES)	Y	0	0	0
NCPL	Non-Compliance Reports	Y	0	0	0
NDFT	National Defense & Canadian Forces Fuel Tanks	Y	0	0	0
NDSP	National Defense & Canadian Forces Spills	Y	0	0	0
NDWD	National Defence & Canadian Forces Waste Disposal Sites	Y	0	0	0
NEBI	National Energy Board Pipeline Incidents	Y	0	0	0
NEBP	National Energy Board Wells	Y	0	0	0
NEES	National Environmental Emergencies System (NEES)	Y	0	0	0
NPCB	National PCB Inventory	Y	0	0	0
NPRI	National Pollutant Release Inventory	Y	0	17	17
OGWE	Oil and Gas Wells	Y	0	0	0
OOGW	Ontario Oil and Gas Wells	Y	0	0	0
OPCB	Inventory of PCB Storage Sites	Y	0	0	0
ORD	Orders	Y	0	0	0
PAP	Canadian Pulp and Paper	Y	0	0	0
PCFT	Parks Canada Fuel Storage Tanks	Y	0	0	0
PES	Pesticide Register	Y	0	3	3
PINC	Pipeline Incidents	Y	0	10	10
PRT	Private and Retail Fuel Storage Tanks	Y	0	5	5
PTTW	Permit to Take Water	Y	0	0	0
REC	Ontario Regulation 347 Waste Receivers Summary	Y	0	0	0
RSC	Record of Site Condition	Y	0	9	9
RST	Retail Fuel Storage Tanks	Y	0	1	1
SCT	Scott's Manufacturing Directory	Y	0	15	15
SPL	Ontario Spills	Y	0	12	12
SRDS	Wastewater Discharger Registration Database	Y	0	0	0
TANK	Anderson's Storage Tanks	Y	0	0	0
TCFT	Transport Canada Fuel Storage Tanks	Y	0	0	0
VAR	Variances for Abandonment of Underground Storage Tanks	Y	0	0	0
WDS	Waste Disposal Sites - MOE CA Inventory	Y	0	0	0
WDSH	Waste Disposal Sites - MOE 1991 Historical Approval Inventory	Y	0	0	0
WWIS	Water Well Information System	Y	0	38	38
	Total:		1	312	313

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
1	EHS		1026 Cooke Blvd Burlington ON L7T4A8	NE/0.0	-0.03	66

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
2	WWIS		ON **Well ID:** 7390909	WSW/15.6	1.97	66
3	WWIS		35 PLAINS ROAD EAST Burlington ON **Well ID:** 7248588	E/16.2	-0.04	67
4	WWIS		ON **Well ID:** 7390911	W/20.4	2.17	69
5	PINC	DUCON UTILITIES LIMITED	1025 WATERDOWN RD,,BURLINGTON, ON,L7T 1N4,CA ON	SW/22.7	1.77	70
5	SPL		1025 Waterdown Rd Burlington ON	SW/22.7	1.77	70
5	PINC	PIPELINE HIT - 1/2"	1025 WATERDOWN RD,,BURLINGTON, ON,L7T 1N4,CA ON	SW/22.7	1.77	71
5	PINC	PIPELINE HIT - 1/2"	1025 WATERDOWN RD,,BURLINGTON, ON,L7T 1N4,CA ON	SW/22.7	1.77	72
6	SCT	Lextoner.com	1038 Cooke Blvd Unit 2 Burlington ON L7T 4A8	WNW/24.5	0.60	72
6	SCT	O'Dell Associates Inc.	1038 Cooke Blvd Unit 3 Burlington ON L7T 4A8	WNW/24.5	0.60	72
6	EHS		1038 Cooke Boulevard Burlington ON L7T 4A8	WNW/24.5	0.60	73
6	EHS		1038 Cooke Boulevard, Unit 1 Burlington ON L7T 4A8	WNW/24.5	0.60	73

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
6	EHS		1038 Cooke Boulevard, Unit 1 Burlington ON L7T 4A8	WNW/24.5	0.60	73
6	EHS		1038 Cooke Boulevard, Unit 1 Burlington ON L7T 4A8	WNW/24.5	0.60	73
7	GEN	Bayshore Tool & Equipment	1021 Waterdown Rd. Burlington ON L7T 1N4	SSW/25.7	1.41	74
7	SCT	Dee Signs Inc.	1021 Waterdown Rd Burlington ON L7T 1N4	SSW/25.7	1.41	74
7	PINC	RONG MAO INDUSTRIAL CO LTD (APEXCARE)	1021 WATERDOWN RD,,BURLINGTON, ON,L7T 1N4,CA ON	SSW/25.7	1.41	74
8	EHS		35 Plains Road East Burlington ON L7T 2B8	ESE/30.3	0.43	75
8	EHS		35 Plains Road East Burlington ON L7T 2B8	ESE/30.3	0.43	75
8	EHS		35 Plains Road East Burlington ON L7T 2B8	ESE/30.3	0.43	75
9	WWIS		ON ***Well ID:*** 7390910	WSW/30.8	2.55	75
10	EHS		35 Plains Road East Burlington ON	ESE/31.4	0.43	76
10	RSC	THE COOKE GROUP INC.	35 PLAINS ROAD EAST, BURLINGTON, ON L7R 2B8 Burlington ON	ESE/31.4	0.43	76
10	RSC	ALDERSHOT PROPERTIES INC.	35 PLAINS ROAD EAST, BURLINGTON, ON L7R 2B8 Burlington ON	ESE/31.4	0.43	78
11	EHS		35 Plains Rd E Burlington On Burlington ON	ESE/34.5	0.43	79

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
12	EHS		1029 Waterdown Road Burlington ON L7T 1N4	WSW/35.9	1.98	79
12	EHS		1029 Waterdown Road Burlington ON L7T 1N4	WSW/35.9	1.98	79
12	EHS		1029 Waterdown Road Burlington ON L7T 1N4	WSW/35.9	1.98	79
13	WWIS		15 PLAINS RD. EAST BURLINGTON ON ***Well ID:*** 7296544	SSE/43.5	0.79	80
14	WWIS		ON ***Well ID:*** 7390906	WSW/46.0	3.51	83
15	WWIS		53 PLAINS RD E Burlington ON ***Well ID:*** 7314783	E/46.2	-0.03	83
16	WWIS		15 PLAINS RD. EAST BURLINGTON ON ***Well ID:*** 7296543	SSE/46.6	1.05	86
17	WWIS		35 PLAINS RD E Burlington ON ***Well ID:*** 7232291	ESE/47.3	1.03	89
17	WWIS		35 PLAINS RD E Burlington ON ***Well ID:*** 7214775	ESE/47.3	1.03	91
18	WWIS		ON ***Well ID:*** 7390908	SW/49.5	2.16	94
19	EHS		15 Plains Rd E Burlington ON L7T2B8	S/50.0	0.84	95
20	WWIS		ON ***Well ID:*** 7390907	W/55.4	4.43	95
21	SPL	Enbridge Gas Distribution Inc.	1045 Waterdown Rd Burlington ON	W/57.1	4.43	96

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
22	EHS		1029 Waterdown Rd Burlington ON L7T 1N4	SW/60.7	2.20	96
23	EHS		1029-1063 Waterdown Road Burlington ON L7T 1N4	W/60.8	4.47	97
23	EHS		1029-1063 Waterdown Road Burlington ON L7T 1N4	W/60.8	4.47	97
23	EHS		1029-1063 Waterdown Road Burlington ON L7T 1N4	W/60.8	4.47	97
24	WWIS		35 PLAINS ROAD EAST Burlington ON ***Well ID:*** 7248589	ESE/60.9	0.90	97
25	SCT	Primary Fluid Systems Inc.	1050 Cooke Blvd Unit 3-4 Burlington ON L7T 4A8	NW/61.3	0.20	100
25	SCT	BHC CABLE ASSEMBLIES INC.	1050 Cooke Blvd Unit 3 Burlington ON L7T 4A8	NW/61.3	0.20	100
25	GEN	INVESTIGATIVE SCIENCE INC.	1050 COOKE BOULEVARD, UNIT 2 BURLINGTON ON L7T 4A8	NW/61.3	0.20	100
25	GEN	INVESTIGATIVE SCIENCE INC.	1050 COOKE BLVD, UNIT 2 BURLINGTON ON L7T 4A8	NW/61.3	0.20	101
25	GEN	INVESTIGATIVE SCIENCE INC.	1050 COOKE BLVD, UNIT 2 BURLINGTON ON	NW/61.3	0.20	101
25	GEN	INVESTIGATIVE SCIENCE INC.	1050 COOKE BLVD, UNIT 2 BURLINGTON ON	NW/61.3	0.20	101
25	GEN	INVESTIGATIVE SCIENCE INC.	1050 COOKE BLVD, UNIT 2 BURLINGTON ON	NW/61.3	0.20	102
25	GEN	INVESTIGATIVE SCIENCE INC.	1050 COOKE BLVD, UNIT 2 BURLINGTON ON L7T 4A8	NW/61.3	0.20	102

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
25	GEN	INVESTIGATIVE SCIENCE INC.	1050 COOKE BLVD, UNIT 2 BURLINGTON ON	NW/61.3	0.20	102
25	GEN	INVESTIGATIVE SCIENCE INC.	1050 COOKE BLVD, UNIT 2 BURLINGTON ON L7T 4A8	NW/61.3	0.20	103
25	GEN	INVESTIGATIVE SCIENCE INC.	1050 COOKE BLVD, UNIT 2 BURLINGTON ON L7T 4A8	NW/61.3	0.20	103
25	GEN	INVESTIGATIVE SCIENCE INC.	1050 COOKE BLVD, UNIT 2 BURLINGTON ON L7T 4A8	NW/61.3	0.20	103
25	GEN	INVESTIGATIVE SCIENCE INC.	1050 COOKE BLVD, UNIT 2 BURLINGTON ON L7T 4A8	NW/61.3	0.20	104
25	EHS		1050 Cooke Blvd Burlington ON L7T 4A8	NW/61.3	0.20	104
25	GEN	INVESTIGATIVE SCIENCE INC.	1050 COOKE BLVD, UNIT 2 BURLINGTON ON L7T 4A8	NW/61.3	0.20	104
26	WWIS		1022 WATERDOWN RD Burlington ON ***Well ID:*** 7236357	SSW/62.4	1.85	105
27	RSC	DARKO VRANICH	1025 COOKE BOULEVARD, BURLINGTON, ON L7T 4A8 Burlington ON	ENE/65.3	0.05	108
28	WWIS		15 PLAINS RD. EAST BURLINGTON ON ***Well ID:*** 7296545	SSE/67.5	0.33	109
29	WWIS		1022 WATERDOWN RD Burlington ON ***Well ID:*** 7236358	SW/69.8	1.87	112
30	RSC	848347 ONTARIO LIMITED	53 PLAINS ROAD EAST, BURLINGTON, ON L7T 2B8 Burlington ON	ENE/72.7	-0.21	115

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
30	EHS		53 Plains Rd E Burlington ON L7T2B8	ENE/72.7	-0.21	116
31	WWIS		1022 WATERDOWN RD Burlington ON ***Well ID:*** 7236354	SW/77.8	2.10	117
32	PINC	EDWARDS VICTORIA APARTMENT INC	1045 WATERDOWN RD,,BURLINGTON, ON,L7T 1N4,CA ON	W/79.8	5.04	119
33	WWIS		1022 WATERDOWN RD Burlington ON ***Well ID:*** 7236355	SW/80.1	2.10	120
34	BORE		ON	S/84.5	0.85	122
35	EHS		1036 Waterdown Rd Burlington ON L7T 1N3	WSW/93.2	4.24	123
35	PINC	DUCON UTILITIES LIMITED	1036 WATERDOWN RD,,BURLINGTON, ON,L7T 1N3,CA ON	WSW/93.2	4.24	124
35	SPL	Union Gas Limited	1036 Waterdown Rd Burlington ON	WSW/93.2	4.24	124
36	WWIS		PLAINS RD EAST (ROAD HOLES) BURLINGTON ON ***Well ID:*** 2810154	ESE/96.0	2.00	125
37	WWIS		1022 WATERDOWN RD Burlington ON ***Well ID:*** 7236356	SW/96.8	1.81	128
38	WWIS		34 PLAINS RD. E. lot 6 BURLINGTON ON ***Well ID:*** 7176158	ESE/101.8	2.09	131
39	WWIS		14 PLAINS RD BURLINGTON ON ***Well ID:*** 2810377	SSE/103.4	1.02	133
40	PINC	PIPELINE HIT - 1/2"	1022 WATERDOWN ROAD,, BURLINGTON,ON,L7T 1N3,CA ON	SW/103.9	2.49	137

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
40	SPL	Union Gas Limited	1022 Waterdown Road Burlington ON L7T 1N3	SW/103.9	2.49	138
40	EHS		1022 Waterdown Rd Burlington ON L7T1N3	SW/103.9	2.49	138
41	WWIS		1028 WATERDOWN ROAD Burlington ON ***Well ID:*** 7229430	SW/104.0	3.64	138
42	WWIS		ON ***Well ID:*** 7361072	E/104.3	1.37	141
43	CA	ETRATECH PRINTED CIRCUIT BOARDS INC.	1062 COOKE BOULEVARD BURLINGTON CITY ON L7T 4A8	WNW/110.4	2.33	142
43	EBR	Etratech Printed Circuit Boards Inc.	1062 Cooke Boulevard Burlington CITY OF BURLINGTON ON	WNW/110.4	2.33	143
43	GEN	ETRATECH PRINTED CIRCUIT BOARDS INC.	1062 COOKE BOULEVARD BURLINGTON ON L7T 4A8	WNW/110.4	2.33	143
43	EHS		1062 Cooke Blvd Burlington ON L7T 4A8	WNW/110.4	2.33	144
43	EBR	Category 5 Imaging Ltd.	1062 Cooke Boulevard Burlington Regional Municipality of Halton L7T 4A8 CITY OF BURLINGTON ON	WNW/110.4	2.33	144
43	GEN	CATEGORY 5 IMAGING	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	WNW/110.4	2.33	144
43	CA	Category 5 Imaging Ltd.	1062 Cooke Blvd Burlington ON L7T 4A8	WNW/110.4	2.33	145
43	GEN	CATEGORY 5 IMAGING	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	WNW/110.4	2.33	145

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
43	GEN	CATEGORY 5 IMAGING	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	WNW/110.4	2.33	145
43	GEN	CATEGORY 5 IMAGING	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	WNW/110.4	2.33	146
43	GEN	CATEGORY 5 IMAGING	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	WNW/110.4	2.33	146
43	GEN	CATEGORY 5 IMAGING	1062 COOKE BLVD. BURLINGTON ON	WNW/110.4	2.33	146
43	ECA	Category 5 Imaging Ltd.	1062 Cooke Blvd Burlington ON L7T 4A8	WNW/110.4	2.33	147
43	GEN	CATEGORY 5 IMAGING	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	WNW/110.4	2.33	147
43	GEN	CATEGORY 5 IMAGING	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	WNW/110.4	2.33	148
43	GEN	CATEGORY 5 IMAGING	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	WNW/110.4	2.33	148
43	GEN	CATEGORY 5 IMAGING	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	WNW/110.4	2.33	148
43	EHS		1062 Cooke Blvd & 1074 Cooke Blvd. Burlington ON L7T 4A8	WNW/110.4	2.33	149
43	GEN	CATEGORY 5 IMAGING INC.	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	WNW/110.4	2.33	149
43	GEN	CATEGORY 5 IMAGING INC.	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	WNW/110.4	2.33	149
43	GEN	CATEGORY 5 IMAGING INC.	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	WNW/110.4	2.33	150

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
44	EASR	CORPORATION OF THE CITY OF BURLINGTON	1044 WATERDOWN RD BURLINGTON ON L7T 1N3	WSW/114.6	5.59	150
44	GEN	The City of Burlington Corp Fire Department	1044 Waterdown Road Burlington ON L7T1N3	WSW/114.6	5.59	150
44	GEN	The City of Burlington Corp Fire Department	1044 Waterdown Road Burlington ON L7T1N3	WSW/114.6	5.59	151
44	GEN	The City of Burlington Corp Fire Department	1044 Waterdown Road Burlington ON L7T1N3	WSW/114.6	5.59	151
45	PRT	PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON ON L7T 1E8	SSW/117.6	0.97	151
45	DTNK	PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON ON L7T 1E8	SSW/117.6	0.97	152
45	DTNK	PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON ON	SSW/117.6	0.97	152
45	DTNK	PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON ON	SSW/117.6	0.97	153
45	DTNK	PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON ON	SSW/117.6	0.97	154
45	DTNK	PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON ON	SSW/117.6	0.97	154
45	DTNK	PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON L7T 1E8 ON CA ON	SSW/117.6	0.97	155
45	DTNK	PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON L7T 1E8 ON CA ON	SSW/117.6	0.97	155
45	DTNK	PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON L7T 1E8 ON CA ON	SSW/117.6	0.97	156

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
45	DTNK	PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON L7T 1E8 ON CA ON	SSW/117.6	0.97	157
45	FST	PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON L7T 1E8 ON CA ON	SSW/117.6	0.97	157
45	FST	PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON L7T 1E8 ON CA ON	SSW/117.6	0.97	158
45	FST	PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON L7T 1E8 ON CA ON	SSW/117.6	0.97	158
45	FST	PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON L7T 1E8 ON CA ON	SSW/117.6	0.97	159
46	WWIS		15 PLAINS RD E Burlington ON ***Well ID:*** 7299235	S/119.4	-0.05	159
47	WWIS		14 PLAINS RD E BURLINGTON ON ***Well ID:*** 7160240	SSE/121.3	0.50	162
48	EHS		40 Plains Rd E Burlington ON L7T2B9	ESE/125.4	0.64	165
49	SCT	Etratech Inc.	1047 Cooke Blvd Burlington ON L7T 4A8	N/125.9	2.03	165
49	EBR	Etratech Designs Inc.	1047 COOKE BOULEVARD, BURLINGTON CITY CITY OF BURLINGTON ON	N/125.9	2.03	165
49	NPRI	ETRATECH INC	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	N/125.9	2.03	166
49	EBR	Etratech Printed Circuit Boards Inc.	1047 Cooke Boulevard Burlington Ontario Burlington ON	N/125.9	2.03	167

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
49	EHS		1047 Cooke Blvd Burlington ON L7T 4A8	N/125.9	2.03	167
49	GEN	ETRATECH MANUFACTURING INC.	1047 COOKE BOULEVARD BURLINGTON ON L7T 4A8	N/125.9	2.03	167
49	GEN	ETRATECH MANUFACTURING INC.	1047 Cooke Boulevard Burlington ON L7T 4A8	N/125.9	2.03	168
49	NPRI	ETRATECH INC.	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	N/125.9	2.03	169
49	NPRI	ETRATECH INC.	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	N/125.9	2.03	170
49	NPRI	ETRATECH	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	N/125.9	2.03	170
49	NPRI	ETRATECH	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	N/125.9	2.03	171
49	NPRI	ETRATECH	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	N/125.9	2.03	172
49	EBR	Etratech Printed Circuit Boards Inc.	1047 Cooke Boulevard Burlington Ontario Burlington ON	N/125.9	2.03	173
49	EBR	Etratech Printed Circuit Boards Inc.	1047 Cooke Boulevard Burlington Ontario Burlington ON	N/125.9	2.03	174
49	EBR	Etratech Printed Circuit Boards Inc.	1047 Cooke Boulevard Burlington Regional Municipality of Halton CITY OF BURLINGTON ON	N/125.9	2.03	174
49	NPRI	ETRATECH	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	N/125.9	2.03	175

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
49	NPRI	ETRATECH	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	N/125.9	2.03	175
49	CA	Etratech Printed Circuit Boards Inc.	1047 Cooke Boulevard Burlington ON	N/125.9	2.03	176
49	CA	Etratech Inc.	1047 Cooke Blvd Burlington ON	N/125.9	2.03	177
49	CA	Etratech Printed Circuit Boards Inc.	1047 Cooke Boulevard Burlington ON	N/125.9	2.03	177
49	CA	Etratech Printed Circuit Boards Inc.	1047 Cooke Boulevard Burlington ON	N/125.9	2.03	177
49	NPRI	ETRATECH	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	N/125.9	2.03	178
49	NPRI	ETRATECH INC.	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	N/125.9	2.03	178
49	GEN	ETRATECH MANUFACTURING INC.	1047 Cooke Boulevard Burlington ON L7T 4A8	N/125.9	2.03	179
49	EASR	1500118 ONTARIO INC.	1047 COOKE BLVD. BURLINGTON ON L7T 4A8	N/125.9	2.03	180
49	NPRI	ETRATECH INC.	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	N/125.9	2.03	180
49	GEN	ETRATECH MANUFACTURING INC.	1047 Cooke Boulevard Burlington ON L7T 4A8	N/125.9	2.03	181
49	GEN	ETRATECH MANUFACTURING INC.	1047 Cooke Boulevard Burlington ON L7T 4A8	N/125.9	2.03	181

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
49	EBR	Etratech Inc.	1047 Cooke Boulevard Burlington, Regional Municipality of Halton CITY OF BURLINGTON ON	N/125.9	2.03	182
49	GEN	ETRATECH MANUFACTURING INC.	1047 Cooke Boulevard Burlington ON L7T 4A8	N/125.9	2.03	182
49	NPRI	ETRATECH INC.	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	N/125.9	2.03	183
49	EHS		1047 Cooke Blvd Burlington ON L7T4A8	N/125.9	2.03	184
49	GEN	ETRATECH MANUFACTURING INC.	1047 Cooke Boulevard Burlington ON	N/125.9	2.03	184
49	NPRI	ETRATECH INC.	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	N/125.9	2.03	184
49	NPRI	ETRATECH INC.	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	N/125.9	2.03	185
49	ECA	Etratech Inc.	1047 Cooke Blvd Burlington ON	N/125.9	2.03	186
49	ECA	Etratech Printed Circuit Boards Inc.	1047 Cooke Boulevard Burlington ON	N/125.9	2.03	186
49	ECA	Etratech Inc.	1047 Cooke Blvd Burlington ON	N/125.9	2.03	187
49	ECA	Etratech Printed Circuit Boards Inc.	1047 Cooke Boulevard Burlington ON	N/125.9	2.03	187
49	ECA	Etratech Printed Circuit Boards Inc.	1047 Cooke Boulevard Burlington ON	N/125.9	2.03	187
49	GEN	ETRATECH MANUFACTURING INC.	1047 Cooke Boulevard Burlington ON L7T 4A8	N/125.9	2.03	188

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
49	GEN	ETRATECH INC.	1047 Cooke Boulevard Burlington ON L7T 4A8	N/125.9	2.03	188
49	GEN	ETRATECH MANUFACTURING INC.	1047 Cooke Boulevard Burlington ON L7T 4A8	N/125.9	2.03	189
49	GEN	Gentherm Canada ULC.	1047 Cooke Boulevard Burlington ON L7T 4A8	N/125.9	2.03	189
49	NPRI	Etratech Inc.	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	N/125.9	2.03	190
49	NPRI	ETRATECH INC.	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	N/125.9	2.03	191
49	NPRI	ETRATECH INC.	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	N/125.9	2.03	192
49	EHS		1047 Cooke Blvd Burlington ON L7T4A8	N/125.9	2.03	193
49	GEN	Gentherm Canada ULC.	1047 Cooke Boulevard Burlington ON L7T 4A8	N/125.9	2.03	193
49	GEN	Gentherm Canada ULC.	1047 Cooke Boulevard Burlington ON L7T 4A8	N/125.9	2.03	194
49	EHS		1047 Cooke Blvd. Burlington ON L7T 4A8	N/125.9	2.03	195
49	EHS		1047 Cooke Blvd. Burlington ON L7T 4A8	N/125.9	2.03	195
49	EHS		1047 Cooke Blvd. Burlington ON L7T 4A8	N/125.9	2.03	195

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
50	SPL	MAC'S MILK	14 PLAINS RD AT LASALLE GAS BAR BURLINGTON CITY ON	SSE/126.3	1.01	196
50	PRT	MACS CONVENIENCE STORES DIV OF SILCORP LTD ATTN MA	14 PLAINS RD E BURLINGTON ON L7T2B9	SSE/126.3	1.01	196
50	PRT		14 PLAINS RD. E. BURLINGTON ON	SSE/126.3	1.01	196
50	EHS		14 Plains Road East Burlington ON L7T 2B9	SSE/126.3	1.01	197
50	GEN	Esso Imperial Oil Limited	14 Plains Road East Burlington ON L7T 2B9	SSE/126.3	1.01	197
50	CA	Imperial Oil Limited	14 Plains Rd E Burlington ON L7T 2B9	SSE/126.3	1.01	197
50	WWIS		14 PLAINS RD E Burlington ON ***Well ID:*** 7167017	SSE/126.3	1.01	198
50	DTNK	MAC'S CONVENIENCE STORES INC**	14 PLAINS RD E BURLINGTON ON	SSE/126.3	1.01	200
50	DTNK	MAC'S CONVENIENCE STORES INC**	14 PLAINS RD E BURLINGTON ON L7T 2B9	SSE/126.3	1.01	201
50	DTNK	MAC'S CONVENIENCE STORES INC**	14 PLAINS RD E BURLINGTON ON	SSE/126.3	1.01	201
50	DTNK	MAC'S CONVENIENCE STORES INC**	14 PLAINS RD E BURLINGTON ON	SSE/126.3	1.01	202
50	DTNK	MAC'S CONVENIENCE STORES INC**	14 PLAINS RD E BURLINGTON ON	SSE/126.3	1.01	202
50	GEN	Imperial Oil	14 Plains Road East Burlington ON L7T 2B9	SSE/126.3	1.01	203

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
50	FST	MAC'S CONVENIENCE STORES INC	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	SSE/126.3	1.01	203
50	FST	MAC'S CONVENIENCE STORES INC	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	SSE/126.3	1.01	204
50	FST	MAC'S CONVENIENCE STORES INC	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	SSE/126.3	1.01	204
50	FST	MAC'S CONVENIENCE STORES INC	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	SSE/126.3	1.01	205
50	GEN	Imperial Oil	14 Plains Road East Burlington ON L7T 2B9	SSE/126.3	1.01	205
50	GEN	Imperial Oil	14 Plains Road East Burlington ON	SSE/126.3	1.01	205
50	DTNK	MAC'S CONVENIENCE STORES INC	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	SSE/126.3	1.01	206
50	DTNK	MAC'S CONVENIENCE STORES INC	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	SSE/126.3	1.01	207
50	DTNK	MAC'S CONVENIENCE STORES INC	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	SSE/126.3	1.01	207
50	EHS		14 Plains Rd E Burlington ON L7T2B9	SSE/126.3	1.01	208
50	ECA	Imperial Oil Limited	14 Plains Rd E Burlington ON M3C 1K5	SSE/126.3	1.01	208
50	GEN	Imperial Oil	14 Plains Road East Burlington ON L7T 2B9	SSE/126.3	1.01	208
50	GEN	Imperial Oil	14 Plains Road East Burlington ON L7T 2B9	SSE/126.3	1.01	209

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
50	GEN	Imperial Oil	14 Plains Road East Burlington ON L7T 2B9	SSE/126.3	1.01	209
50	GEN	MAC'S CONVENIENCE STORES INC.	14 PLAINS ROAD EAST BURLINGTON ON L7T 2B9	SSE/126.3	1.01	210
50	GEN	MAC'S CONVENIENCE STORES INC.	14 PLAINS ROAD EAST BURLINGTON ON L7T 2B9	SSE/126.3	1.01	210
50	DTNK		14 PLAINS RD E BURLINGTON ON L7T 2B9	SSE/126.3	1.01	210
50	FST	MAC'S CONVENIENCE STORES INC	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	SSE/126.3	1.01	211
50	FST	MAC'S CONVENIENCE STORES INC	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	SSE/126.3	1.01	211
50	FST	MAC'S CONVENIENCE STORES INC	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	SSE/126.3	1.01	212
50	GEN	MAC'S CONVENIENCE STORES INC.	14 PLAINS ROAD EAST BURLINGTON ON L7T 2B9	SSE/126.3	1.01	212
50	GEN	MAC'S CONVENIENCE STORES INC.	14 PLAINS ROAD EAST BURLINGTON ON L7T 2B9	SSE/126.3	1.01	213
51	SPL	Union Gas Limited	1063 Waterdown Rd Burlington ON	WNW/126.3	6.30	213
52	PRT	MOORE SMALLEY LTD	30 PLAINS RD BURLINGTON ON	ESE/127.5	1.94	214
52	DTNK	MOORE SMALLEY LTD	30 PLAINS RD E BURLINGTON ON	ESE/127.5	1.94	214

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
53	SPL	BURLINGTON HYDRO	71 PLAINS RD EAST TRANSFORMER BURLINGTON CITY ON L7T 2B8	ENE/129.9	3.02	215
53	EHS		71 Plains Rd E Burlington ON L7T 2B8	ENE/129.9	3.02	215
53	GEN	Budget Car and Truck Rentals	71 Plains Road East Burlington ON L7T 2B8	ENE/129.9	3.02	216
53	RSC	71 BURLINGTON PLAINS INC.	71 PLAINS ROAD EAST, BURLINGTON, ON L7T 2B8 Burlington ON	ENE/129.9	3.02	216
54	RSC	Roman Home Builders Inc.	34 PLAINS ROAD EAST, BURLINGTON, ONTARIO L7T 2B9 Burlington ON	ESE/130.1	1.53	217
54	EHS		34 Plains Rd E Burlington ON L7T2B9	ESE/130.1	1.53	218
55	WWIS		71 PLAINS RDE BURLINGTON ON ***Well ID:*** 2809957	ENE/133.2	2.73	218
56	WWIS		ON ***Well ID:*** 7361071	E/133.6	-0.19	221
57	WWIS		ON ***Well ID:*** 7363235	ESE/136.7	0.08	222
58	PINC	KPM INDUSTRIES LTD O/A KING PAVING & CONSTRUCTION	1063 WATERDOWN RD,,BURLINGTON, ON,L7T 1N4,CA ON	W/138.8	8.75	223
59	EHS		1053, 1057 AND 1063 WATERDOWN ROAD AND 2 MASONRY COURT BURLINGTON ON L7T 1N4	WNW/139.9	5.18	223
59	EHS		1053, 1057 AND 1063 WATERDOWN ROAD AND 2 MASONRY COURT BURLINGTON ON L7T 1N4	WNW/139.9	5.18	223
59	EHS		1053, 1057 AND 1063 WATERDOWN ROAD AND 2 MASONRY COURT BURLINGTON ON L7T 1N4	WNW/139.9	5.18	224

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
60	EHS		1074 ad 1062 Cooke Boulevard Burlington ON L7T 4A8	NW/144.9	2.45	224
60	EHS		1074 ad 1062 Cooke Boulevard Burlington ON L7T 4A8	NW/144.9	2.45	224
60	EHS		1074 ad 1062 Cooke Boulevard Burlington ON L7T 4A8	NW/144.9	2.45	224
61	WWIS		ON ***Well ID:*** 7220632	SSE/151.2	1.01	225
62	GEN	DAN GREER ENTERPRISES LTD.	14 PLAINS RD. W. BURLINGTON ON L7T 1E9	S/152.3	-0.05	226
62	GEN	DAN GREER ENTERPRISES LTD.	14 PLAINS ROAD WEST BURLINGTON ON L7T 1E9	S/152.3	-0.05	226
62	GEN	DAN GREER ENTERPRISES LTD. 12-305	14 PLAINS RD. W. BURLINGTON ON L7T 1E9	S/152.3	-0.05	226
62	GEN	DAN GREER ENTERPRISES LIMITED	14 PLAINS ROAD WEST BURLINGTON ON L7T 1E9	S/152.3	-0.05	227
62	EHS		14 Plains Road West Burlington ON L7T 1E9	S/152.3	-0.05	227
62	RSC	La Salle Court Investments Inc.	12 PLAINS RD W, BURLINGTON, ON, L7T 1E9 BURLINGTON ON L7T 1E9	S/152.3	-0.05	227
62	GEN	Mechendie Holdings Limited	14 Plains Road West Burlington ON	S/152.3	-0.05	228
63	SCT	BHC Cable Assemblies Inc.	2 Masonry Crt Burlington ON L7T 4A8	WNW/154.8	4.84	228
63	EHS		2 Masonry Crt Burlington ON L7T4A8	WNW/154.8	4.84	228

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
64	WWIS		14 PLAINS RD Burlington ON ***Well ID:*** 7118602	S/159.6	0.07	229
65	WWIS		ON ***Well ID:*** 7271535	NNW/160.7	5.46	231
66	WWIS		14 PLAINS RD EAST BURLINGTON ON ***Well ID:*** 7211367	SSE/165.8	0.99	232
67	PES	CANADIAN TIRE/ROBERT C. NEARING HOLDINGS INC.	70 PLAINS ROAD BURLINGTON ON L7T1E9	E/166.6	0.26	234
67	PES	CANADIAN TIRE STORE/PAUL LAMOUREUX ENTERPRISES LTD.	70 PLAINS ROAD BURLINGTON ON L7T1E9	E/166.6	0.26	235
68	SPL	Walker Environmental Group Inc.	18 Plains Road West Burlington ON	S/170.6	-0.05	235
69	EHS		15 Plains Road West Burlington ON L7T 1E8	SSW/173.1	0.85	236
70	CA	ETRATECH DESIGNS INC.	1074 COOKE BOULEVARD BURLINGTON CITY ON L7T 4A8	NW/175.3	4.10	236
70	SCT	ETRATECH DESIGN INC.	1074 COOKE BLVD BURLINGTON ON L7T 4A8	NW/175.3	4.10	236
70	CA	ETRATECH DESIGNS INC.	1074 COOKE BOULEVARD BURLINGTON CITY ON L7T 4A8	NW/175.3	4.10	237
70	SCT	Eclipse Colour Ltd.	1074 Cooke Blvd Burlington ON L7T 4A8	NW/175.3	4.10	237
70	EBR	Etratech Designs Inc.	1074 Cooke Boulevard CITY OF BURLINGTON ON	NW/175.3	4.10	237

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
70	GEN	ETRATECH MANUFACTURING INC.	1074 COOKE BOULEVARD BURLINGTON ON L7T 4A8	NW/175.3	4.10	238
70	GEN	ECLIPSE COLOUR ONTARIO LTD.	1074 COOKE BLVD BURLINGTON ON L7T 4A8	NW/175.3	4.10	238
70	SCT	Townmedia, Laurel Oak	1074 Cooke Blvd Burlington ON L7T 4A8	NW/175.3	4.10	238
70	SCT	Ontario Golf	1074 Cooke Blvd Burlington ON L7T 4A8	NW/175.3	4.10	239
70	SCT	Town Media	1074 Cooke Blvd Burlington ON L7T 4A8	NW/175.3	4.10	239
70	GEN	PV Labs Ltd.	1074 Cooke Boulevard Burlington ON L7T4A8	NW/175.3	4.10	239
70	GEN	PV Labs Ltd.	1074 Cooke Boulevard Burlington ON L7T4A8	NW/175.3	4.10	240
70	GEN	PV Labs Ltd.	1074 Cooke Boulevard Burlington ON L7T4A8	NW/175.3	4.10	240
70	GEN	PV Labs Ltd.	1074 Cooke Boulevard Burlington ON L7T4A8	NW/175.3	4.10	240
71	WWIS		5M SOUTH OF 982 LASALLE PARK RD. 1M WEST OF EDGE OF LASALLE PARK RD. BURLINGTON ON ***Well ID:*** 7267367	SSE/184.9	1.00	241
72	SCT	Abbey Stained Glass	91 Plains Rd E Burlington ON L7T 2C2	ENE/193.7	2.85	244
72	RST	PETRO-PARTNERS	91 PLAINS RD E BURLINGTON ON L7T 2C2	ENE/193.7	2.85	244
72	GEN	Eighth Empire Inc.	91 Plains Road East. Unit 2c Burlington ON L7T 2C2	ENE/193.7	2.85	244

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
72	GEN	Eighth Empire Inc.	91 Plains Road East. Unit 2c Burlington ON L7T 2C2	ENE/193.7	2.85	245
72	GEN	Eighth Empire Inc.	91 Plains Road East. Unit 2c Burlington ON L7T 2C2	ENE/193.7	2.85	245
72	GEN	Eighth Empire Inc.	91 Plains Road East. Unit 2c Burlington ON L7T 2C2	ENE/193.7	2.85	246
73	EHS		29 Plains Rd W Burlington ON L7T1E8	SW/200.8	2.87	246
73	GEN	BETHESDA INC	29 Plains Rd W Burlington ON L7T 1E8	SW/200.8	2.87	246
73	PES	ALDERSHOT HARDWARE LTD	29 Plains Rd W ST W Burlington ON L7T 1E8	SW/200.8	2.87	246
73	GEN	BETHESDA INC	29 Plains Rd W Burlington ON L7T 1E8	SW/200.8	2.87	247
73	GEN	BETHESDA INC	29 Plains Rd W Burlington ON L7T 1E8	SW/200.8	2.87	247
74	WWIS		14 PLAINS RD WEST BURLINGTON ON ***Well ID:*** 2810512	S/216.1	-0.05	248
75	ECA	The Corporation of the City of Burlington	Masonry Crt and Cooke Boulevard Burlington ON L7R 3Z6	NW/218.5	3.03	251
76	WWIS		ON ***Well ID:*** 7301691	E/224.7	0.95	251
77	CA	BURLINGTON CITY - LOT 6, CONC. 1	MASONRY CT./WATERDOWN RD. BURLINGTON CITY ON	WNW/227.2	10.01	252
78	PRT	TCG MATERIALS LTD	101 MASONRY CT BURLINGTON ON	WNW/232.4	6.83	252

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
78	SCT	T C G MATERIALS LIMITED	101 MASONRY CRT BURLINGTON ON L7T 4A8	WNW/232.4	6.83	252
78	GEN	TCG MATERIALS LIMITED 37-466	101 MASONRY COURT BURLINGTON ON L7T 4A8	WNW/232.4	6.83	253
78	GEN	TCG MATERIALS LIMITED	101 MASONRY COURT BURLINGTON ON L7T 4A8	WNW/232.4	6.83	253
78	DTNK	TCG MATERIALS LTD	101 MASONRY CRT BURLINGTON ON L7T 4A8	WNW/232.4	6.83	253
78	DTNK	TCG MATERIALS LTD	101 MASONRY CRT BURLINGTON ON	WNW/232.4	6.83	254
78	DTNK	TCG MATERIALS LTD	101 MASONRY CRT BURLINGTON ON	WNW/232.4	6.83	255
78	DTNK	TCG MATERIALS LTD	101 MASONRY CRT BURLINGTON L7T 4A8 ON CA ON	WNW/232.4	6.83	255
78	DTNK	TCG MATERIALS LTD	101 MASONRY CRT BURLINGTON L7T 4A8 ON CA ON	WNW/232.4	6.83	256
78	EASR	ADI DEVELOPMENTS (MASONRY) INC.	101 Masonry CRT BURLINGTON ON L7T 4A8	WNW/232.4	6.83	256
78	GEN	Adi Development (Masonry) Inc.	101 Masonry Court Burlington ON L7T 4A8	WNW/232.4	6.83	257
78	ECA	Adi Developments (Masonry) Inc.	101 Masonry Crt Burlington ON L7L 6B2	WNW/232.4	6.83	257
78	SPL	Enbridge Gas Inc.	101 Masonary Court Burlington ON L7T 4A8	WNW/232.4	6.83	257

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
78	SPL	Enbridge Gas Inc. operating as Union Gas	101 Masonary Crt. Burlington ON	WNW/232.4	6.83	258
79	EHS		92 Plains Rd E Burlington ON L7T2C1	ENE/235.0	0.95	259
79	RSC	EMBER DOG INC.	92 PLAINS ROAD EAST, BURLINGTON, ON L7T 4B6 Burlington ON	ENE/235.0	0.95	259
79	EHS		92 Plains Rd E Burlington ON L7T2C1	ENE/235.0	0.95	260
80	CA	R.M. OF HALTON	LASALLE PK.RD/FAIRWOOD PL.W. BURLINGTON CITY ON	SSE/235.7	0.95	260
81	WWIS		ON ***Well ID:*** 7374324	ENE/238.1	0.95	261
82	GEN	PEEL I.T. CONSULTANTS Ltd.	38 Plains Rd. Easr Unit B3 Burlington ON	SSW/242.8	-0.05	262
83	EHS		34 and 38 Plains Road West, Burlington Burlington ON L7T 1E9	SSW/244.4	-0.22	262
83	EHS		34 and 38 Plains Road West, Burlington Burlington ON L7T 1E9	SSW/244.4	-0.22	262
83	EHS		34 and 38 Plains Road West, Burlington Burlington ON L7T 1E9	SSW/244.4	-0.22	262
84	EHS		105 Plains Road East Burlington ON L7T 2C2	ENE/252.3	2.07	262
85	GEN	PLAINS ROAD ANIMAL HOSPITAL	105 PLAINS ROAD EAST BURLINGTON ON L7T 2C2	ENE/254.1	1.92	263
85	RSC	KAJAN INC.	105 PLAINS ROAD EAST, BURLINGTON, ON L7T 2C2 Burlington ON	ENE/254.1	1.92	263

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
86	SPL		Adjacent (west) to 40 Plains Rd W Burlington ON	SSW/255.0	-0.35	264
87	CA	FAIRWOOD HOLLOW LIMITED	FAIRWOOD PL.W./PARK AVE. W. BURLINGTON ON	S/258.1	0.19	265
88	CA	R.M. OF HALTON	EMERY AVE/PLAINS RD.W. BURLINGTON CITY ON	SSW/270.5	0.95	265
88	CA	BURLINGTON CITY	EMERY AVE/PLAINS RD.W. BURLINGTON CITY ON	SSW/270.5	0.95	265
88	CA	R.M. OF HALTON	EMERY AVE/PLAINS RD.W. BURLINGTON CITY ON	SSW/270.5	0.95	266
89	HINC		109 PLAINS ROAD EAST BURLINGTON ON L7T 2C2	ENE/276.3	1.95	266
90	PINC	PIPELINE HIT	952 LASALLE PARK RD,,BURLINGTON, ON,L7T 1M9,CA ON	SSE/285.0	-0.05	266
90	SPL	Union Gas Limited	952 LaSalle Park Drive Burlington ON	SSE/285.0	-0.05	267
90	PINC	PIPELINE HIT 1/2"	952 LASALLE PARK RD,,BURLINGTON, ON,L7T 1M9,CA ON	SSE/285.0	-0.05	268
91	EHS		1085 Clearview Avenue Burlington ON L7T 2J2	N/291.4	4.95	268
92	SCT	ABBEY STAINED GLASS	115 Plains Rd E Burlington ON L7T 2C2	ENE/295.2	1.95	268

Executive Summary: Summary By Data Source

BORE - Borehole

A search of the BORE database, dated 1875-Jul 2018 has found that there are 1 BORE site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	ON	84.5	34

CA - Certificates of Approval

A search of the CA database, dated 1985-Oct 30, 2011* has found that there are 15 CA site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
ETRATECH PRINTED CIRCUIT BOARDS INC.	1062 COOKE BOULEVARD BURLINGTON CITY ON L7T 4A8	110.4	43
Category 5 Imaging Ltd.	1062 Cooke Blvd Burlington ON L7T 4A8	110.4	43
Etratech Printed Circuit Boards Inc.	1047 Cooke Boulevard Burlington ON	125.9	49
Etratech Inc.	1047 Cooke Blvd Burlington ON	125.9	49
Etratech Printed Circuit Boards Inc.	1047 Cooke Boulevard Burlington ON	125.9	49
Etratech Printed Circuit Boards Inc.	1047 Cooke Boulevard Burlington ON	125.9	49
Imperial Oil Limited	14 Plains Rd E Burlington ON L7T 2B9	126.3	50

Site	Address	Distance (m)	Map Key
ETRATECH DESIGNS INC.	1074 COOKE BOULEVARD BURLINGTON CITY ON L7T 4A8	175.3	70
ETRATECH DESIGNS INC.	1074 COOKE BOULEVARD BURLINGTON CITY ON L7T 4A8	175.3	70
BURLINGTON CITY - LOT 6, CONC. 1	MASONRY CT./WATERDOWN RD. BURLINGTON CITY ON	227.2	77
R.M. OF HALTON	LASALLE PK.RD/FAIRWOOD PL.W. BURLINGTON CITY ON	235.7	80
FAIRWOOD HOLLOW LIMITED	FAIRWOOD PL.W./PARK AVE. W. BURLINGTON ON	258.1	87
R.M. OF HALTON	EMERY AVE/PLAINS RD.W. BURLINGTON CITY ON	270.5	88
R.M. OF HALTON	EMERY AVE/PLAINS RD.W. BURLINGTON CITY ON	270.5	88
BURLINGTON CITY	EMERY AVE/PLAINS RD.W. BURLINGTON CITY ON	270.5	88

DTNK - Delisted Fuel Tanks

A search of the DTNK database, dated Feb 28, 2022 has found that there are 24 DTNK site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON ON L7T 1E8	117.6	45

Site	Address	Distance (m)	Map Key
PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON ON	117.6	45
PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON ON	117.6	45
PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON ON	117.6	45
PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON L7T 1E8 ON CA ON	117.6	45
PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON L7T 1E8 ON CA ON	117.6	45
PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON L7T 1E8 ON CA ON	117.6	45
PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON L7T 1E8 ON CA ON	117.6	45
PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON ON	117.6	45
MAC'S CONVENIENCE STORES INC**	14 PLAINS RD E BURLINGTON ON	126.3	50
MAC'S CONVENIENCE STORES INC**	14 PLAINS RD E BURLINGTON ON L7T 2B9	126.3	50
MAC'S CONVENIENCE STORES INC**	14 PLAINS RD E BURLINGTON ON	126.3	50
MAC'S CONVENIENCE STORES INC**	14 PLAINS RD E BURLINGTON ON	126.3	50

Site	Address	Distance (m)	Map Key
MAC'S CONVENIENCE STORES INC**	14 PLAINS RD E BURLINGTON ON	126.3	50
MAC'S CONVENIENCE STORES INC	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	126.3	50
MAC'S CONVENIENCE STORES INC	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	126.3	50
MAC'S CONVENIENCE STORES INC	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	126.3	50
	14 PLAINS RD E BURLINGTON ON L7T 2B9	126.3	50
MOORE SMALLEY LTD	30 PLAINS RD E BURLINGTON ON	127.5	52
TCG MATERIALS LTD	101 MASONRY CRT BURLINGTON L7T 4A8 ON CA ON	232.4	78
TCG MATERIALS LTD	101 MASONRY CRT BURLINGTON ON L7T 4A8	232.4	78
TCG MATERIALS LTD	101 MASONRY CRT BURLINGTON ON	232.4	78
TCG MATERIALS LTD	101 MASONRY CRT BURLINGTON ON	232.4	78
TCG MATERIALS LTD	101 MASONRY CRT BURLINGTON L7T 4A8 ON CA ON	232.4	78

EASR - Environmental Activity and Sector Registry

A search of the EASR database, dated Oct 2011- Feb 28, 2023 has found that there are 3 EASR site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
CORPORATION OF THE CITY OF BURLINGTON	1044 WATERDOWN RD BURLINGTON ON L7T 1N3	114.6	44
1500118 ONTARIO INC.	1047 COOKE BLVD. BURLINGTON ON L7T 4A8	125.9	49
ADI DEVELOPMENTS (MASONRY) INC.	101 Masonry CRT BURLINGTON ON L7T 4A8	232.4	78

EBR - Environmental Registry

A search of the EBR database, dated 1994 - Feb 28, 2023 has found that there are 9 EBR site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Etratech Printed Circuit Boards Inc.	1062 Cooke Boulevard Burlington CITY OF BURLINGTON ON	110.4	43
Category 5 Imaging Ltd.	1062 Cooke Boulevard Burlington Regional Municipality of Halton L7T 4A8 CITY OF BURLINGTON ON	110.4	43
Etratech Printed Circuit Boards Inc.	1047 Cooke Boulevard Burlington Ontario Burlington ON	125.9	49
Etratech Printed Circuit Boards Inc.	1047 Cooke Boulevard Burlington Ontario Burlington ON	125.9	49
Etratech Printed Circuit Boards Inc.	1047 Cooke Boulevard Burlington Regional Municipality of Halton CITY OF BURLINGTON ON	125.9	49
Etratech Printed Circuit Boards Inc.	1047 Cooke Boulevard Burlington Ontario Burlington ON	125.9	49

Site	Address	Distance (m)	Map Key
Etratech Designs Inc.	1047 COOKE BOULEVARD, BURLINGTON CITY CITY OF BURLINGTON ON	125.9	49
Etratech Inc.	1047 Cooke Boulevard Burlington, Regional Municipality of Halton CITY OF BURLINGTON ON	125.9	49
Etratech Designs Inc.	1074 Cooke Boulevard CITY OF BURLINGTON ON	175.3	70

ECA - Environmental Compliance Approval

A search of the ECA database, dated Oct 2011- Feb 28, 2023 has found that there are 9 ECA site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Category 5 Imaging Ltd.	1062 Cooke Blvd Burlington ON L7T 4A8	110.4	43
Etratech Printed Circuit Boards Inc.	1047 Cooke Boulevard Burlington ON	125.9	49
Etratech Inc.	1047 Cooke Blvd Burlington ON	125.9	49
Etratech Printed Circuit Boards Inc.	1047 Cooke Boulevard Burlington ON	125.9	49
Etratech Printed Circuit Boards Inc.	1047 Cooke Boulevard Burlington ON	125.9	49
Etratech Inc.	1047 Cooke Blvd Burlington ON	125.9	49

Site	Address	Distance (m)	Map Key
Imperial Oil Limited	14 Plains Rd E Burlington ON M3C 1K5	126.3	50
The Corporation of the City of Burlington	Masonry Crt and Cooke Boulevard Burlington ON L7R 3Z6	218.5	75
Adi Developments (Masonry) Inc.	101 Masonry Crt Burlington ON L7L 6B2	232.4	78

EHS - ERIS Historical Searches

A search of the EHS database, dated 1999-Dec 31, 2022 has found that there are 52 EHS site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	1026 Cooke Blvd Burlington ON L7T4A8	0.0	1
	1038 Cooke Boulevard Burlington ON L7T 4A8	24.5	6
	1038 Cooke Boulevard, Unit 1 Burlington ON L7T 4A8	24.5	6
	1038 Cooke Boulevard, Unit 1 Burlington ON L7T 4A8	24.5	6
	1038 Cooke Boulevard, Unit 1 Burlington ON L7T 4A8	24.5	6
	35 Plains Road East Burlington ON L7T 2B8	30.3	8
	35 Plains Road East Burlington ON L7T 2B8	30.3	8

Site	Address	Distance (m)	Map Key
	35 Plains Road East Burlington ON L7T 2B8	30.3	8
	35 Plains Road East Burlington ON	31.4	10
	35 Plains Rd E Burlington On Burlington ON	34.5	11
	1029 Waterdown Road Burlington ON L7T 1N4	35.9	12
	1029 Waterdown Road Burlington ON L7T 1N4	35.9	12
	1029 Waterdown Road Burlington ON L7T 1N4	35.9	12
	15 Plains Rd E Burlington ON L7T2B8	50.0	19
	1029 Waterdown Rd Burlington ON L7T 1N4	60.7	22
	1029-1063 Waterdown Road Burlington ON L7T 1N4	60.8	23
	1029-1063 Waterdown Road Burlington ON L7T 1N4	60.8	23
	1029-1063 Waterdown Road Burlington ON L7T 1N4	60.8	23

Site	Address	Distance (m)	Map Key
	1050 Cooke Blvd Burlington ON L7T 4A8	61.3	25
	53 Plains Rd E Burlington ON L7T2B8	72.7	30
	1036 Waterdown Rd Burlington ON L7T 1N3	93.2	35
	1022 Waterdown Rd Burlington ON L7T1N3	103.9	40
	1062 Cooke Blvd Burlington ON L7T 4A8	110.4	43
	1062 Cooke Blvd & 1074 Cooke Blvd. Burlington ON L7T 4A8	110.4	43
	40 Plains Rd E Burlington ON L7T2B9	125.4	48
	1047 Cooke Blvd Burlington ON L7T 4A8	125.9	49
	1047 Cooke Blvd Burlington ON L7T4A8	125.9	49
	1047 Cooke Blvd Burlington ON L7T4A8	125.9	49
	1047 Cooke Blvd. Burlington ON L7T 4A8	125.9	49
	1047 Cooke Blvd. Burlington ON L7T 4A8	125.9	49

Site	Address	Distance (m)	Map Key
	1047 Cooke Blvd. Burlington ON L7T 4A8	125.9	49
	14 Plains Road East Burlington ON L7T 2B9	126.3	50
	14 Plains Rd E Burlington ON L7T2B9	126.3	50
	71 Plains Rd E Burlington ON L7T 2B8	129.9	53
	34 Plains Rd E Burlington ON L7T2B9	130.1	54
	1053, 1057 AND 1063 WATERDOWN ROAD AND 2 MASONRY COURT BURLINGTON ON L7T 1N4	139.9	59
	1053, 1057 AND 1063 WATERDOWN ROAD AND 2 MASONRY COURT BURLINGTON ON L7T 1N4	139.9	59
	1053, 1057 AND 1063 WATERDOWN ROAD AND 2 MASONRY COURT BURLINGTON ON L7T 1N4	139.9	59
	1074 ad 1062 Cooke Boulevard Burlington ON L7T 4A8	144.9	60
	1074 ad 1062 Cooke Boulevard Burlington ON L7T 4A8	144.9	60
	1074 ad 1062 Cooke Boulevard Burlington ON L7T 4A8	144.9	60

Site	Address	Distance (m)	Map Key
	14 Plains Road West Burlington ON L7T 1E9	152.3	62
	2 Masonry Crt Burlington ON L7T4A8	154.8	63
	15 Plains Road West Burlington ON L7T 1E8	173.1	69
	29 Plains Rd W Burlington ON L7T1E8	200.8	73
	92 Plains Rd E Burlington ON L7T2C1	235.0	79
	92 Plains Rd E Burlington ON L7T2C1	235.0	79
	34 and 38 Plains Road West, Burlington Burlington ON L7T 1E9	244.4	83
	34 and 38 Plains Road West, Burlington Burlington ON L7T 1E9	244.4	83
	34 and 38 Plains Road West, Burlington Burlington ON L7T 1E9	244.4	83
	105 Plains Road East Burlington ON L7T 2C2	252.3	84
	1085 Clearview Avenue Burlington ON L7T 2J2	291.4	91

FST - Fuel Storage Tank

A search of the FST database, dated Feb 28, 2022 has found that there are 11 FST site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON L7T 1E8 ON CA ON	117.6	45
PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON L7T 1E8 ON CA ON	117.6	45
PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON L7T 1E8 ON CA ON	117.6	45
PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON L7T 1E8 ON CA ON	117.6	45
MAC'S CONVENIENCE STORES INC	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	126.3	50
MAC'S CONVENIENCE STORES INC	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	126.3	50
MAC'S CONVENIENCE STORES INC	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	126.3	50
MAC'S CONVENIENCE STORES INC	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	126.3	50
MAC'S CONVENIENCE STORES INC	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	126.3	50
MAC'S CONVENIENCE STORES INC	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	126.3	50
MAC'S CONVENIENCE STORES INC	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	126.3	50

Site	Address	Distance (m)	Map Key

GEN - Ontario Regulation 347 Waste Generators Summary

A search of the GEN database, dated 1986-Oct 31, 2022 has found that there are 78 GEN site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Bayshore Tool & Equipment	1021 Waterdown Rd. Burlington ON L7T 1N4	25.7	7
INVESTIGATIVE SCIENCE INC.	1050 COOKE BOULEVARD, UNIT 2 BURLINGTON ON L7T 4A8	61.3	25
INVESTIGATIVE SCIENCE INC.	1050 COOKE BLVD, UNIT 2 BURLINGTON ON L7T 4A8	61.3	25
INVESTIGATIVE SCIENCE INC.	1050 COOKE BLVD, UNIT 2 BURLINGTON ON	61.3	25
INVESTIGATIVE SCIENCE INC.	1050 COOKE BLVD, UNIT 2 BURLINGTON ON	61.3	25
INVESTIGATIVE SCIENCE INC.	1050 COOKE BLVD, UNIT 2 BURLINGTON ON	61.3	25
INVESTIGATIVE SCIENCE INC.	1050 COOKE BLVD, UNIT 2 BURLINGTON ON L7T 4A8	61.3	25
INVESTIGATIVE SCIENCE INC.	1050 COOKE BLVD, UNIT 2 BURLINGTON ON	61.3	25
INVESTIGATIVE SCIENCE INC.	1050 COOKE BLVD, UNIT 2 BURLINGTON ON L7T 4A8	61.3	25

Site	Address	Distance (m)	Map Key
INVESTIGATIVE SCIENCE INC.	1050 COOKE BLVD, UNIT 2 BURLINGTON ON L7T 4A8	61.3	25
INVESTIGATIVE SCIENCE INC.	1050 COOKE BLVD, UNIT 2 BURLINGTON ON L7T 4A8	61.3	25
INVESTIGATIVE SCIENCE INC.	1050 COOKE BLVD, UNIT 2 BURLINGTON ON L7T 4A8	61.3	25
INVESTIGATIVE SCIENCE INC.	1050 COOKE BLVD, UNIT 2 BURLINGTON ON L7T 4A8	61.3	25
ETRATECH PRINTED CIRCUIT BOARDS INC.	1062 COOKE BOULEVARD BURLINGTON ON L7T 4A8	110.4	43
CATEGORY 5 IMAGING	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	110.4	43
CATEGORY 5 IMAGING	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	110.4	43
CATEGORY 5 IMAGING	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	110.4	43
CATEGORY 5 IMAGING	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	110.4	43
CATEGORY 5 IMAGING	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	110.4	43
CATEGORY 5 IMAGING	1062 COOKE BLVD. BURLINGTON ON	110.4	43
CATEGORY 5 IMAGING	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	110.4	43

Site	Address	Distance (m)	Map Key
CATEGORY 5 IMAGING	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	110.4	43
CATEGORY 5 IMAGING	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	110.4	43
CATEGORY 5 IMAGING	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	110.4	43
CATEGORY 5 IMAGING INC.	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	110.4	43
CATEGORY 5 IMAGING INC.	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	110.4	43
CATEGORY 5 IMAGING INC.	1062 COOKE BLVD. BURLINGTON ON L7T 4A8	110.4	43
The City of Burlington Corp Fire Department	1044 Waterdown Road Burlington ON L7T1N3	114.6	44
The City of Burlington Corp Fire Department	1044 Waterdown Road Burlington ON L7T1N3	114.6	44
The City of Burlington Corp Fire Department	1044 Waterdown Road Burlington ON L7T1N3	114.6	44
ETRATECH MANUFACTURING INC.	1047 COOKE BOULEVARD BURLINGTON ON L7T 4A8	125.9	49
ETRATECH MANUFACTURING INC.	1047 Cooke Boulevard Burlington ON L7T 4A8	125.9	49

Site	Address	Distance (m)	Map Key
ETRATECH MANUFACTURING INC.	1047 Cooke Boulevard Burlington ON L7T 4A8	125.9	49
ETRATECH MANUFACTURING INC.	1047 Cooke Boulevard Burlington ON L7T 4A8	125.9	49
ETRATECH MANUFACTURING INC.	1047 Cooke Boulevard Burlington ON L7T 4A8	125.9	49
ETRATECH MANUFACTURING INC.	1047 Cooke Boulevard Burlington ON L7T 4A8	125.9	49
ETRATECH MANUFACTURING INC.	1047 Cooke Boulevard Burlington ON	125.9	49
ETRATECH MANUFACTURING INC.	1047 Cooke Boulevard Burlington ON L7T 4A8	125.9	49
ETRATECH INC.	1047 Cooke Boulevard Burlington ON L7T 4A8	125.9	49
ETRATECH MANUFACTURING INC.	1047 Cooke Boulevard Burlington ON L7T 4A8	125.9	49
Gentherm Canada ULC.	1047 Cooke Boulevard Burlington ON L7T 4A8	125.9	49
Gentherm Canada ULC.	1047 Cooke Boulevard Burlington ON L7T 4A8	125.9	49
Gentherm Canada ULC.	1047 Cooke Boulevard Burlington ON L7T 4A8	125.9	49
Esso Imperial Oil Limited	14 Plains Road East Burlington ON L7T 2B9	126.3	50

Site	Address	Distance (m)	Map Key
Imperial Oil	14 Plains Road East Burlington ON L7T 2B9	126.3	50
Imperial Oil	14 Plains Road East Burlington ON L7T 2B9	126.3	50
Imperial Oil	14 Plains Road East Burlington ON	126.3	50
Imperial Oil	14 Plains Road East Burlington ON L7T 2B9	126.3	50
Imperial Oil	14 Plains Road East Burlington ON L7T 2B9	126.3	50
Imperial Oil	14 Plains Road East Burlington ON L7T 2B9	126.3	50
MAC'S CONVENIENCE STORES INC.	14 PLAINS ROAD EAST BURLINGTON ON L7T 2B9	126.3	50
MAC'S CONVENIENCE STORES INC.	14 PLAINS ROAD EAST BURLINGTON ON L7T 2B9	126.3	50
MAC'S CONVENIENCE STORES INC.	14 PLAINS ROAD EAST BURLINGTON ON L7T 2B9	126.3	50
MAC'S CONVENIENCE STORES INC.	14 PLAINS ROAD EAST BURLINGTON ON L7T 2B9	126.3	50
Budget Car and Truck Rentals	71 Plains Road East Burlington ON L7T 2B8	129.9	53

Site	Address	Distance (m)	Map Key
DAN GREER ENTERPRISES LTD.	14 PLAINS RD. W. BURLINGTON ON L7T 1E9	152.3	62
DAN GREER ENTERPRISES LTD.	14 PLAINS ROAD WEST BURLINGTON ON L7T 1E9	152.3	62
DAN GREER ENTERPRISES LTD. 12-305	14 PLAINS RD. W. BURLINGTON ON L7T 1E9	152.3	62
DAN GREER ENTERPRISES LIMITED	14 PLAINS ROAD WEST BURLINGTON ON L7T 1E9	152.3	62
Mechendie Holdings Limited	14 Plains Road West Burlington ON	152.3	62
ETRATECH MANUFACTURING INC.	1074 COOKE BOULEVARD BURLINGTON ON L7T 4A8	175.3	70
ECLIPSE COLOUR ONTARIO LTD.	1074 COOKE BLVD BURLINGTON ON L7T 4A8	175.3	70
PV Labs Ltd.	1074 Cooke Boulevard Burlington ON L7T4A8	175.3	70
PV Labs Ltd.	1074 Cooke Boulevard Burlington ON L7T4A8	175.3	70
PV Labs Ltd.	1074 Cooke Boulevard Burlington ON L7T4A8	175.3	70
PV Labs Ltd.	1074 Cooke Boulevard Burlington ON L7T4A8	175.3	70
Eighth Empire Inc.	91 Plains Road East. Unit 2c Burlington ON L7T 2C2	193.7	72

Site	Address	Distance (m)	Map Key
Eighth Empire Inc.	91 Plains Road East. Unit 2c Burlington ON L7T 2C2	193.7	72
Eighth Empire Inc.	91 Plains Road East. Unit 2c Burlington ON L7T 2C2	193.7	72
Eighth Empire Inc.	91 Plains Road East. Unit 2c Burlington ON L7T 2C2	193.7	72
BETHESDA INC	29 Plains Rd W Burlington ON L7T 1E8	200.8	73
BETHESDA INC	29 Plains Rd W Burlington ON L7T 1E8	200.8	73
BETHESDA INC	29 Plains Rd W Burlington ON L7T 1E8	200.8	73
TCG MATERIALS LIMITED 37-466	101 MASONRY COURT BURLINGTON ON L7T 4A8	232.4	78
TCG MATERIALS LIMITED	101 MASONRY COURT BURLINGTON ON L7T 4A8	232.4	78
Adi Development (Masonry) Inc.	101 Masonry Court Burlington ON L7T 4A8	232.4	78
PEEL I.T. CONSULTANTS Ltd.	38 Plains Rd. Easr Unit B3 Burlington ON	242.8	82
PLAINS ROAD ANIMAL HOSPITAL	105 PLAINS ROAD EAST BURLINGTON ON L7T 2C2	254.1	85

HINC - TSSA Historic Incidents

A search of the HINC database, dated 2006-June 2009* has found that there are 1 HINC site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	109 PLAINS ROAD EAST BURLINGTON ON L7T 2C2	276.3	89

NPRI - National Pollutant Release Inventory

A search of the NPRI database, dated 1993-May 2017 has found that there are 17 NPRI site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
ETRATECH INC	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	125.9	49
ETRATECH INC.	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	125.9	49
ETRATECH INC.	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	125.9	49
ETRATECH	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	125.9	49
ETRATECH	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	125.9	49
ETRATECH	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	125.9	49
ETRATECH	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	125.9	49
ETRATECH	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	125.9	49

Site	Address	Distance (m)	Map Key
ETRATECH	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	125.9	49
ETRATECH INC.	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	125.9	49
ETRATECH INC.	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	125.9	49
ETRATECH INC.	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	125.9	49
ETRATECH INC.	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	125.9	49
ETRATECH INC.	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	125.9	49
Etratech Inc.	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	125.9	49
ETRATECH INC.	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	125.9	49
ETRATECH INC.	1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	125.9	49

PES - Pesticide Register

A search of the PES database, dated Oct 2011- Feb 28, 2023 has found that there are 3 PES site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
CANADIAN TIRE/ROBERT C. NEARING HOLDINGS INC.	70 PLAINS ROAD BURLINGTON ON L7T1E9	166.6	67
CANADIAN TIRE STORE/PAUL LAMOUREUX ENTERPRISES LTD.	70 PLAINS ROAD BURLINGTON ON L7T1E9	166.6	67
ALDERSHOT HARDWARE LTD	29 Plains Rd W ST W Burlington ON L7T 1E8	200.8	73

PINC - Pipeline Incidents

A search of the PINC database, dated Feb 28, 2021 has found that there are 10 PINC site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
PIPELINE HIT - 1/2"	1025 WATERDOWN RD,,BURLINGTON,ON, L7T 1N4,CA ON	22.7	5
PIPELINE HIT - 1/2"	1025 WATERDOWN RD,,BURLINGTON,ON, L7T 1N4,CA ON	22.7	5
DUCON UTILITIES LIMITED	1025 WATERDOWN RD,,BURLINGTON,ON, L7T 1N4,CA ON	22.7	5
RONG MAO INDUSTRIAL CO LTD (APEXCARE)	1021 WATERDOWN RD,,BURLINGTON,ON, L7T 1N4,CA ON	25.7	7
EDWARDS VICTORIA APARTMENT INC	1045 WATERDOWN RD,,BURLINGTON,ON, L7T 1N4,CA ON	79.8	32
DUCON UTILITIES LIMITED	1036 WATERDOWN RD,,BURLINGTON,ON, L7T 1N3,CA ON	93.2	35
PIPELINE HIT - 1/2"	1022 WATERDOWN ROAD,,BURLINGTON, ON,L7T 1N3,CA ON	103.9	40

Site	Address	Distance (m)	Map Key
KPM INDUSTRIES LTD O/A KING PAVING & CONSTRUCTION	1063 WATERDOWN RD,,BURLINGTON,ON, L7T 1N4,CA ON	138.8	58
PIPELINE HIT	952 LASALLE PARK RD,,BURLINGTON,ON, L7T 1M9,CA ON	285.0	90
PIPELINE HIT 1/2"	952 LASALLE PARK RD,,BURLINGTON,ON, L7T 1M9,CA ON	285.0	90

PRT - Private and Retail Fuel Storage Tanks

A search of the PRT database, dated 1989-1996* has found that there are 5 PRT site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
PETRO CANADA CAR WASH ATTN GARY HACKMAN	7 PLAINS RD W BURLINGTON ON L7T 1E8	117.6	45
MACS CONVENIENCE STORES DIV OF SILCORP LTD ATTN MA	14 PLAINS RD E BURLINGTON ON L7T2B9	126.3	50
	14 PLAINS RD. E. BURLINGTON ON	126.3	50
MOORE SMALLEY LTD	30 PLAINS RD BURLINGTON ON	127.5	52
TCG MATERIALS LTD	101 MASONRY CT BURLINGTON ON	232.4	78

RSC - Record of Site Condition

A search of the RSC database, dated 1997-Sept 2001, Oct 2004-Feb 2023 has found that there are 9 RSC site(s) within approximately

0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
THE COOKE GROUP INC.	35 PLAINS ROAD EAST, BURLINGTON, ON L7R 2B8 Burlington ON	31.4	10
ALDERSHOT PROPERTIES INC.	35 PLAINS ROAD EAST, BURLINGTON, ON L7R 2B8 Burlington ON	31.4	10
DARKO VRANICH	1025 COOKE BOULEVARD, BURLINGTON, ON L7T 4A8 Burlington ON	65.3	27
848347 ONTARIO LIMITED	53 PLAINS ROAD EAST, BURLINGTON, ON L7T 2B8 Burlington ON	72.7	30
71 BURLINGTON PLAINS INC.	71 PLAINS ROAD EAST, BURLINGTON, ON L7T 2B8 Burlington ON	129.9	53
Roman Home Builders Inc.	34 PLAINS ROAD EAST, BURLINGTON, ONTARIO L7T 2B9 Burlington ON	130.1	54
La Salle Court Investments Inc.	12 PLAINS RD W, BURLINGTON, ON, L7T 1E9 BURLINGTON ON L7T 1E9	152.3	62
EMBER DOG INC.	92 PLAINS ROAD EAST, BURLINGTON, ON L7T 4B6 Burlington ON	235.0	79
KAJAN INC.	105 PLAINS ROAD EAST, BURLINGTON, ON L7T 2C2 Burlington ON	254.1	85

RST - Retail Fuel Storage Tanks

A search of the RST database, dated 1999-May 31, 2022 has found that there are 1 RST site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
PETRO-PARTNERS	91 PLAINS RD E BURLINGTON ON L7T 2C2	193.7	72

Site	Address	Distance (m)	Map Key

SCT - Scott's Manufacturing Directory

A search of the SCT database, dated 1992-Mar 2011* has found that there are 15 SCT site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
O'Dell Associates Inc.	1038 Cooke Blvd Unit 3 Burlington ON L7T 4A8	24.5	6
Lextoner.com	1038 Cooke Blvd Unit 2 Burlington ON L7T 4A8	24.5	6
Dee Signs Inc.	1021 Waterdown Rd Burlington ON L7T 1N4	25.7	7
Primary Fluid Systems Inc.	1050 Cooke Blvd Unit 3-4 Burlington ON L7T 4A8	61.3	25
BHC CABLE ASSEMBLIES INC.	1050 Cooke Blvd Unit 3 Burlington ON L7T 4A8	61.3	25
Etratech Inc.	1047 Cooke Blvd Burlington ON L7T 4A8	125.9	49
BHC Cable Assemblies Inc.	2 Masonry Crt Burlington ON L7T 4A8	154.8	63
Town Media	1074 Cooke Blvd Burlington ON L7T 4A8	175.3	70
Ontario Golf	1074 Cooke Blvd Burlington ON L7T 4A8	175.3	70

Site	Address	Distance (m)	Map Key
Townmedia, Laurel Oak	1074 Cooke Blvd Burlington ON L7T 4A8	175.3	70
Eclipse Colour Ltd.	1074 Cooke Blvd Burlington ON L7T 4A8	175.3	70
ETRATECH DESIGN INC.	1074 COOKE BLVD BURLINGTON ON L7T 4A8	175.3	70
Abbey Stained Glass	91 Plains Rd E Burlington ON L7T 2C2	193.7	72
T C G MATERIALS LIMITED	101 MASONRY CRT BURLINGTON ON L7T 4A8	232.4	78
ABBEY STAINED GLASS	115 Plains Rd E Burlington ON L7T 2C2	295.2	92

SPL - Ontario Spills

A search of the SPL database, dated 1988-Mar 2021; May 2021-Oct 2021 has found that there are 12 SPL site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	1025 Waterdown Rd Burlington ON	22.7	5
Enbridge Gas Distribution Inc.	1045 Waterdown Rd Burlington ON	57.1	21
Union Gas Limited	1036 Waterdown Rd Burlington ON	93.2	35
Union Gas Limited	1022 Waterdown Road Burlington ON L7T 1N3	103.9	40

Site	Address	Distance (m)	Map Key
MAC'S MILK	14 PLAINS RD AT LASALLE GAS BAR BURLINGTON CITY ON	126.3	50
Union Gas Limited	1063 Waterdown Rd Burlington ON	126.3	51
BURLINGTON HYDRO	71 PLAINS RD EAST TRANSFORMER BURLINGTON CITY ON L7T 2B8	129.9	53
Walker Environmental Group Inc.	18 Plains Road West Burlington ON	170.6	68
Enbridge Gas Inc. operating as Union Gas	101 Masonary Crt. Burlington ON	232.4	78
Enbridge Gas Inc.	101 Masonary Court Burlington ON L7T 4A8	232.4	78
	Adjacent (west) to 40 Plains Rd W Burlington ON	255.0	86
Union Gas Limited	952 LaSalle Park Drive Burlington ON	285.0	90

WWIS - Water Well Information System

A search of the WWIS database, dated Jun 30 2022 has found that there are 38 WWIS site(s) within approximately 0.30 kilometers of the project property.


Site	Address	Distance (m)	Map Key
	ON ***Well ID:*** 7390909	15.6	2

Site	Address	Distance (m)	Map Key
	35 PLAINS ROAD EAST Burlington ON ***Well ID:*** 7248588	16.2	3
	ON ***Well ID:*** 7390911	20.4	4
	ON ***Well ID:*** 7390910	30.8	9
	15 PLAINS RD. EAST BURLINGTON ON ***Well ID:*** 7296544	43.5	13
	ON ***Well ID:*** 7390906	46.0	14
	53 PLAINS RD E Burlington ON ***Well ID:*** 7314783	46.2	15
	15 PLAINS RD. EAST BURLINGTON ON ***Well ID:*** 7296543	46.6	16
	35 PLAINS RD E Burlington ON ***Well ID:*** 7232291	47.3	17
	35 PLAINS RD E Burlington ON ***Well ID:*** 7214775	47.3	17
	ON ***Well ID:*** 7390908	49.5	18
	ON ***Well ID:*** 7390907	55.4	20
	35 PLAINS ROAD EAST Burlington ON	60.9	24

Site	Address	Distance (m)	Map Key
	Well ID: 7248589		
	1022 WATERDOWN RD Burlington ON ***Well ID:*** 7236357	62.4	26
	15 PLAINS RD. EAST BURLINGTON ON ***Well ID:*** 7296545	67.5	28
	1022 WATERDOWN RD Burlington ON ***Well ID:*** 7236358	69.8	29
	1022 WATERDOWN RD Burlington ON ***Well ID:*** 7236354	77.8	31
	1022 WATERDOWN RD Burlington ON ***Well ID:*** 7236355	80.1	33
	PLAINS RD EAST (ROAD HOLES) BURLINGTON ON ***Well ID:*** 2810154	96.0	36
	1022 WATERDOWN RD Burlington ON ***Well ID:*** 7236356	96.8	37
	34 PLAINS RD. E. lot 6 BURLINGTON ON ***Well ID:*** 7176158	101.8	38
	14 PLAINS RD BURLINGTON ON ***Well ID:*** 2810377	103.4	39
	1028 WATERDOWN ROAD Burlington ON ***Well ID:*** 7229430	104.0	41
	ON ***Well ID:*** 7361072	104.3	42

Site	Address	Distance (m)	Map Key
	15 PLAINS RD E Burlington ON ***Well ID:*** 7299235	119.4	46
	14 PLAINS RD E BURLINGTON ON ***Well ID:*** 7160240	121.3	47
	14 PLAINS RD E Burlington ON ***Well ID:*** 7167017	126.3	50
	71 PLAINS RDE BURLINGTON ON ***Well ID:*** 2809957	133.2	55
	ON ***Well ID:*** 7361071	133.6	56
	ON ***Well ID:*** 7363235	136.7	57
	ON ***Well ID:*** 7220632	151.2	61
	14 PLAINS RD Burlington ON ***Well ID:*** 7118602	159.6	64
	ON ***Well ID:*** 7271535	160.7	65
	14 PLAINS RD EAST BURLINGTON ON ***Well ID:*** 7211367	165.8	66
	5M SOUTH OF 982 LASALLE PARK RD. 1M WEST OF EDGE OF LASALLE PARK RD. BURLINGTON ON ***Well ID:*** 7267367	184.9	71
	14 PLAINS RD WEST BURLINGTON ON	216.1	74

Site	Address	Distance (m)	Map Key
	Well ID: 2810512		
	ON	224.7	76
	Well ID: 7301691		
	ON	238.1	81
	Well ID: 7374324		



Map: 0.3 Kilometer Radius

Order Number: 23041300087


Address: 1026 Cooke Boulevard, Burlington, ON

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership

79°51'W



43°18'N

43°18'N

Aerial


Year: 2021

Order Number: 23041300087

Address: 1026 Cooke Boulevard, Burlington, ON

Source: ESRI World Imagery

© ERIS Information Limited Partnership



Topographic Map

Order Number: 23041300087

Address: 1026 Cooke Boulevard, ON

Source: ESRI World Topographic Map

© ERIS Information Limited Partnership

Detail Report

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	1 of 1	NE/0.0	99.9 / -0.03	1026 Cooke Blvd Burlington ON L7T4A8	EHS

Order No:	20161124002	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	29-NOV-16	**Search Radius (km):**	.25
Date Received:	24-NOV-16	**X:**	-79.852393
Previous Site Name:		**Y:**	43.308293
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
2	1 of 1	WSW/15.6	101.9 / 1.97	ON	WWIS

Well ID:	7390909	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	29-Jun-2021 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z365307	**Contractor:**	6946
Tag:	A325560	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008699087	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	593009.00
Code OB Desc:		**North83:**	4795637.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	16-Jun-2021 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			

Supplier Comment:

Links

Bore Hole ID:	1008699087	***Tag No:***	A325560
Depth M:		***Contractor:***	6946
Year Completed:	2021	***Path:***	739\7390909.pdf
Well Completed Dt:	2021/06/16	***Latitude:***	43.3078188524723
Audit No:	Z365307	***Longitude:***	-79.8531653423119

3 ***1 of 1*** ***E/16.2*** ***99.9 / -0.04*** ***35 PLAINS ROAD EAST Burlington ON*** ***WWIS***

Well ID:	7248588	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	21-Sep-2015 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z214809	***Contractor:***	7472
Tag:	A188282	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	HALTON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	2015/08/18
Year Completed:	2015
Depth (m):	9.2
Latitude:	43.3080509205273
Longitude:	-79.8520635812794
Path:	

Bore Hole Information

Bore Hole ID:	1005694573	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	593098.00
Code OB Desc:		***North83:***	4795664.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	18-Aug-2015 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			

Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	1005719755
Layer:	1
Color:	7
General Color:	RED
Mat1:	09
Most Common Material:	MEDIUM SAND
Mat2:	
Mat2 Desc:	
Mat3:	77
Mat3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	9.199999809265137
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1005719763
Layer:	2
Plug From:	5.900000095367432
Plug To:	9.199999809265137
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1005719762
Layer:	1
Plug From:	0.0
Plug To:	5.900000095367432
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1005719761
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1005719754
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005719758
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	6.199999809265137
Casing Diameter:	5.199999809265137

Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1005719759
Layer:	1
Slot:	10
Screen Top Depth:	6.199999809265137
Screen End Depth:	9.199999809265137
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.400000095367432

Water Details

Water ID:	1005719757
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1005719756
Diameter:	18.0
Depth From:	0.0
Depth To:	9.199999809265137
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	1005694573	***Tag No:***	A188282
Depth M:	9.2	***Contractor:***	7472
Year Completed:	2015	***Path:***	724\7248588.pdf
Well Completed Dt:	2015/08/18	***Latitude:***	43.3080509205273
Audit No:	Z214809	***Longitude:***	-79.8520635812794

---

4 ***1 of 1*** ***W/20.4*** ***102.1 / 2.17*** ***ON*** ***WWIS***

Well ID:	7390911	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	29-Jun-2021 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z356930	***Contractor:***	6946
Tag:	A328164	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	HALTON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	

Municipality: BURLINGTON CITY
Site Info:

Bore Hole Information

Bore Hole ID:	1008699093	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	592989.00
Code OB Desc:		***North83:***	4795662.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	17-Jun-2021 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008699093	***Tag No:***	A328164
Depth M:		***Contractor:***	6946
Year Completed:	2021	***Path:***	739\7390911.pdf
Well Completed Dt:	2021/06/17	***Latitude:***	43.3080463945352
Audit No:	Z356930	***Longitude:***	-79.8534076700317

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	*1 of 4*	*SW/22.7*	*101.7 / 1.77*	***DUCON UTILITIES LIMITED*** ***1025 WATERDOWN RD,,BURLINGTON,ON,L7T 1N4,CA*** ***ON***	***PINC***

Incident Id:		***Pipe Material:***	
Incident No:	1692978	***Fuel Category:***	
Incident Reported Dt:	7/31/2015	***Health Impact:***	
Type:	FS-Pipeline Incident	***Environment Impact:***	
Status Code:		***Property Damage:***	
Tank Status:	Pipeline Damage Reason Est	***Service Interrupt:***	
Task No:		***Enforce Policy:***	
Spills Action Centre:		***Public Relation:***	
Fuel Type:		***Pipeline System:***	
Fuel Occurrence Tp:		***PSIG:***	
Date of Occurrence:		***Attribute Category:***	
Occurrence Start Dt:		***Regulator Location:***	
Depth:		***Method Details:***	
Customer Acct Name:	DUCON UTILITIES LIMITED		
Incident Address:	1025 WATERDOWN RD,,BURLINGTON,ON,L7T 1N4,CA		
Operation Type:			
Pipeline Type:			
Regulator Type:			
Summary:			
Reported By:			
Affiliation:			
Occurrence Desc:			
Damage Reason:			
Notes:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	*2 of 4*	*SW/22.7*	*101.7 / 1.77*	***1025 Waterdown Rd***	***SPL***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Burlington ON	

Ref No: 4346-9YVQCL
Site No: NA
Incident Dt: 7/29/2015
Year:
Incident Cause:
Incident Event:
Environment Impact:
Nature of Impact:
MOE Response: No
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/29/2015
Dt Document Closed: 8/26/2015
Municipality No:
System Facility Address:
Client Type:
Call Report Location Geodata:
Contaminant Code: 35
Contaminant Name: METHANE GAS, COMPRESSED (NATURAL GAS)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Receiving Environment:
Incident Reason: Operator/Human Error
Incident Summary: TSSA: line strike 1025 Waterdown, made safe
Site Region:
Site Municipality: Burlington
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Communal
SAC Action Class: Air Spills - Gases and Vapours
Source Type:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: tssa<UNOFFICIAL>
Site Address: 1025 Waterdown Rd
Contaminant Qty: 1 number (count)
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved:
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	3 of 4	SW/22.7	101.7 / 1.77	PIPELINE HIT - 1/2" 1025 WATERDOWN RD,,BURLINGTON,ON,L7T 1N4,CA ON	PINC

Incident Id:
Incident No: 1694054
Incident Reported Dt: 8/4/2015
Type: FS-Pipeline Incident
Status Code:
Tank Status: Cancelled
Task No:
Spills Action Centre:
Fuel Type:
Fuel Occurrence Tp:
Date of Occurrence:
Occurrence Start Dt:
Depth:
Customer Acct Name: PIPELINE HIT - 1/2"
Incident Address: 1025 WATERDOWN RD,,BURLINGTON,ON,L7T 1N4,CA
Operation Type:
Pipe Material:
Fuel Category:
Health Impact:
Environment Impact:
Property Damage:
Service Interrupt:
Enforce Policy:
Public Relation:
Pipeline System:
PSIG:
Attribute Category:
Regulator Location:
Method Details:

Pipeline Type:
Regulator Type:
Summary:
Reported By:
Affiliation:
Occurrence Desc:
Damage Reason:
Notes:

---

5 | ***4 of 4*** | ***SW/22.7*** | ***101.7 / 1.77*** | ***PIPELINE HIT - 1/2"***
1025 WATERDOWN RD,,BURLINGTON,ON,L7T 1N4,CA
ON | ***PINC***

Incident Id:		***Pipe Material:***	
Incident No:	1692972	***Fuel Category:***	
Incident Reported Dt:	7/31/2015	***Health Impact:***	
Type:	FS-Pipeline Incident	***Environment Impact:***	
Status Code:		***Property Damage:***	
Tank Status:	Cancelled	***Service Interrupt:***	
Task No:		***Enforce Policy:***	
Spills Action Centre:		***Public Relation:***	
Fuel Type:		***Pipeline System:***	
Fuel Occurrence Tp:		***PSIG:***	
Date of Occurrence:		***Attribute Category:***	
Occurrence Start Dt:		***Regulator Location:***	
Depth:		***Method Details:***	

Customer Acct Name: PIPELINE HIT - 1/2"
Incident Address: 1025 WATERDOWN RD,,BURLINGTON,ON,L7T 1N4,CA
Operation Type:
Pipeline Type:
Regulator Type:
Summary:
Reported By:
Affiliation:
Occurrence Desc:
Damage Reason:
Notes:

---

6 | ***1 of 6*** | ***WNW/24.5*** | ***100.5 / 0.60*** | ***Lextoner.com***
1038 Cooke Blvd Unit 2
Burlington ON L7T 4A8 | ***SCT***

Established: 9/1/1995
Plant Size (ft²):
Employment:

--Details--
Description: All Other Miscellaneous Chemical Product Manufacturing
SIC/NAICS Code: 325999

Description: All Other Miscellaneous Chemical Product Manufacturing
SIC/NAICS Code: 325999

---

6 | ***2 of 6*** | ***WNW/24.5*** | ***100.5 / 0.60*** | ***O'Dell Associates Inc.***
1038 Cooke Blvd Unit 3
Burlington ON L7T 4A8 | ***SCT***

Established: 01-SEP-87
Plant Size (ft²): 3500

Employment:

--Details--
Description: Wholesale Trade Agents and Brokers
SIC/NAICS Code: 419120

Description: Wholesale Trade Agents and Brokers
SIC/NAICS Code: 419120

---

6 ***3 of 6*** ***WNW/24.5*** ***100.5 / 0.60*** ***1038 Cooke Boulevard***
Burlington ON L7T 4A8 ***EHS***

Order No: 20180919075
Status: C
Report Type: Standard Select Report
Report Date: 25-SEP-18
Date Received: 19-SEP-18
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Title Searches; City Directory; Aerial Photos

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.853047
Y: 43.308403

---

6 ***4 of 6*** ***WNW/24.5*** ***100.5 / 0.60*** ***1038 Cooke Boulevard, Unit 1***
Burlington ON L7T 4A8 ***EHS***

Order No: 22030400021
Status: C
Report Type: Standard Report
Report Date: 09-MAR-22
Date Received: 04-MAR-22
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8530882
Y: 43.3083866

---

6 ***5 of 6*** ***WNW/24.5*** ***100.5 / 0.60*** ***1038 Cooke Boulevard, Unit 1***
Burlington ON L7T 4A8 ***EHS***

Order No: 22030400021
Status: C
Report Type: Standard Report
Report Date: 09-MAR-22
Date Received: 04-MAR-22
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8530882
Y: 43.3083866

---

6 ***6 of 6*** ***WNW/24.5*** ***100.5 / 0.60*** ***1038 Cooke Boulevard, Unit 1***
Burlington ON L7T 4A8 ***EHS***

Order No: 22030400021
Status: C
Report Type: Standard Report
Report Date: 09-MAR-22
Date Received: 04-MAR-22
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8530882
Y: 43.3083866

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
7	1 of 3	SSW/25.7	101.3 / 1.41	Bayshore Tool & Equipment 1021 Waterdown Rd. Burlington ON L7T 1N4	GEN

Generator No: ON6334867
SIC Code: 811310
SIC Description: Commercial and Industrial Machinery and Equipment (except Automotive and Electronic) Repair and Maintenance
Approval Years: 04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
7	2 of 3	SSW/25.7	101.3 / 1.41	Dee Signs Inc. 1021 Waterdown Rd Burlington ON L7T 1N4	SCT

Established: 01-AUG-93
Plant Size (ft²): 1400
Employment:

--Details--
Description: All Other Miscellaneous Manufacturing
SIC/NAICS Code: 339990

Description: Sign Manufacturing
SIC/NAICS Code: 339950

Description: Sign Manufacturing
SIC/NAICS Code: 339950

Description: All Other Miscellaneous Wood Product Manufacturing
SIC/NAICS Code: 321999

Description: Other Printing
SIC/NAICS Code: 323119

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
7	3 of 3	SSW/25.7	101.3 / 1.41	RONG MAO INDUSTRIAL CO LTD (APEXCARE) 1021 WATERDOWN RD,,BURLINGTON,ON,L7T 1N4,CA ON	PINC

Incident Id:
Incident No: 590162
Incident Reported Dt: 5/11/2011
Type: FS-Pipeline Incident
Status Code:
Tank Status: Pipeline Damage Reason Est
Task No:
Spills Action Centre:
Fuel Type:
Fuel Occurrence Tp:
Date of Occurrence:
Occurrence Start Dt:
Depth:
Pipe Material:
Fuel Category:
Health Impact:
Environment Impact:
Property Damage:
Service Interrupt:
Enforce Policy:
Public Relation:
Pipeline System:
PSIG:
Attribute Category:
Regulator Location:
Method Details:
Customer Acct Name: RONG MAO INDUSTRIAL CO LTD (APEXCARE)
Incident Address: 1021 WATERDOWN RD,,BURLINGTON,ON,L7T 1N4,CA

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Operation Type:
Pipeline Type:
Regulator Type:
Summary:
Reported By:
Affiliation:
Occurrence Desc:
Damage Reason:
Notes:

---

8 **1 of 3** **ESE/30.3** **100.3 / 0.43** **35 Plains Road East** **EHS**
Burlington ON L7T 2B8

Order No:	21092400088	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	29-SEP-21	**Search Radius (km):**	.25
Date Received:	24-SEP-21	**X:**	-79.85202086
Previous Site Name:		**Y:**	43.30789928
Lot/Building Size:			
Additional Info Ordered:			

---

8 **2 of 3** **ESE/30.3** **100.3 / 0.43** **35 Plains Road East** **EHS**
Burlington ON L7T 2B8

Order No:	21092400088	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	29-SEP-21	**Search Radius (km):**	.25
Date Received:	24-SEP-21	**X:**	-79.85202086
Previous Site Name:		**Y:**	43.30789928
Lot/Building Size:			
Additional Info Ordered:			

---

8 **3 of 3** **ESE/30.3** **100.3 / 0.43** **35 Plains Road East** **EHS**
Burlington ON L7T 2B8

Order No:	21092400088	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	29-SEP-21	**Search Radius (km):**	.25
Date Received:	24-SEP-21	**X:**	-79.85202086
Previous Site Name:		**Y:**	43.30789928
Lot/Building Size:			
Additional Info Ordered:			

---

9 **1 of 1** **WSW/30.8** **102.4 / 2.55** **ON** **WWIS**

Well ID:	7390910	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	29-Jun-2021 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z356929	**Contractor:**	6946
Tag:	A328165	**Form Version:**	7
Constructn Method:		**Owner:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008699090	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	592985.00
Code OB Desc:		**North83:**	4795640.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	17-Jun-2021 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008699090	**Tag No:**	A328165
Depth M:		**Contractor:**	6946
Year Completed:	2021	**Path:**	739\7390910.pdf
Well Completed Dt:	2021/06/17	**Latitude:**	43.3078488273451
Audit No:	Z356929	**Longitude:**	-79.8534607051373

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	1 of 3	ESE/31.4	100.3 / 0.43	**35 Plains Road East** **Burlington ON**	EHS

Order No:	20131129021	**Nearest Intersection:**	
Status:	C	**Municipality:**	Burlington, Halton Region (Formerly in the Township of Flamborough East, Wentworth County)
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	09-DEC-13	**Search Radius (km):**	.25
Date Received:	29-NOV-13	**X:**	-79.851718
Previous Site Name:		**Y:**	43.307744
Lot/Building Size:	2,000 m2		
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	2 of 3	ESE/31.4	100.3 / 0.43	**THE COOKE GROUP INC.** **35 PLAINS ROAD EAST, BURLINGTON, ON L7R 2B8** **Burlington ON**	RSC

RSC ID:	214146	**Cert Date:**	
RA No:		**Cert Prop Use No:**	
RSC Type:	Phase 1 and 2 RSC	**Intended Prop Use:**	Commercial
Curr Property Use:	Commercial	**Qual Person Name:**	MELISSA KING
Ministry District:	Halton-Peel District Office	**Stratified (Y/N):**	

Filing Date:	2014/09/09	***Audit (Y/N):***	
Date Ack:		***Entire Leg Prop. (Y/N):***	
Date Returned:		***Accuracy Estimate:***	
Restoration Type:		***Telephone:***	
Soil Type:		***Fax:***	
Criteria:		***Email:***	
CPU Issued Sect 1686:			

Asmt Roll No: 2402010106042000000
Prop ID No (PIN): 07122-0076 (LT), 07122-0072 (LT)
Property Municipal Address: 35 PLAINS ROAD EAST, BURLINGTON, ON L7R 2B8
Mailing Address:
Latitude & Latitude:
UTM Coordinates:
Consultant:
Legal Desc:
Measurement Method:
Applicable Standards:
RSC PDF: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=37305&fileName=BROWNFIELDS-E.pdf

Document(s) Detail

Document Heading: Supporting Documents
Document Name: Agent Authorization Letter.pdf
Document Type: Proof of the owner's authorization
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=37306&fileName=Agent+Authorization+Letter.pdf

Document Heading: Supporting Documents
Document Name: lawyer letter - Plains Road - revised.pdf
Document Type: Lawyer's letter consisting of a legal description of the property
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=37298&fileName=lawyer+letter+-+Plains+Road+-+revised.pdf

Document Heading: Supporting Documents
Document Name: Deed - Transfer documents.pdf
Document Type: Copy of any deed(s), transfer(s) or other document(s)
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=37303&fileName=Deed+-+Transfer+documents.pdf

Document Heading: Supporting Documents
Document Name: 13HX035 APEC table- revised.pdf
Document Type: Area(s) of Potential Environmental Concern
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=37299&fileName=13HX035+APEC+table-+revised.pdf

Document Heading: Supporting Documents
Document Name: Plan of Survey.pdf
Document Type: A Current plan of Survey
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=37307&fileName=Plan+of+Survey.pdf

Document Heading: Supporting Documents
Document Name: ON637356-Cooke.PDF
Document Type: Certificate of Status
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=37308&fileName=ON637356-Cooke.PDF

Document Heading: Supporting Documents
Document Name: TABLE OF CURRENT AND PAST USES.pdf
Document Type: Table of Current and Past Property Use
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=37302&fileName=TABLE+OF+CURRENT+AND+PAST+USES.pdf

Document Heading: Supporting Documents
Document Name: PhaseTwoCSM.pdf
Document Type: Phase 2 Conceptual Site Model
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=39520&fileName=PhaseTwoCSM.pdf

---

10 | ***3 of 3*** | ***ESE/31.4*** | ***100.3 / 0.43*** | ***ALDERSHOT PROPERTIES INC.***
35 PLAINS ROAD EAST, BURLINGTON, ON L7R 2B8
Burlington ON | ***RSC***

RSC ID: 224029
RA No:
RSC Type: Phase 1 and 2 RSC
Curr Property Use: Commercial
Ministry District: Halton-Peel District Office
Filing Date: 2017/12/11
Date Ack:
Date Returned:
Restoration Type:
Soil Type:
Criteria:
CPU Issued Sect 1686:
Cert Date:
Cert Prop Use No:
Intended Prop Use: Residential
Qual Person Name: PAUL BLUNT
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N):
Accuracy Estimate:
Telephone:
Fax:
Email:
Asmt Roll No: 2402010106042000000
Prop ID No (PIN): 07122-0072 (LT),
07122-0076 (LT)
Property Municipal Address: 35 PLAINS ROAD EAST, BURLINGTON, ON L7R 2B8
Mailing Address:
Latitude & Latitude:
UTM Coordinates:
Consultant:
Legal Desc:
Measurement Method:
Applicable Standards:
RSC PDF: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=88985&fileName=BROWNFIELDS-E.pdf

Document(s) Detail

Document Heading: Supporting Documents
Document Name: APECTable.pdf
Document Type: Area(s) of Potential Environmental Concern
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=90865&fileName=APECTable.pdf

Document Heading: Supporting Documents
Document Name: Survey.pdf
Document Type: A Current plan of Survey
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=90867&fileName=Survey.pdf

Document Heading: Supporting Documents
Document Name: Table of Current and Past Uses.pdf
Document Type: Table of Current and Past Property Use
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=88981&fileName=Table+of+Current+and+Past+Uses.pdf

Document Heading: Supporting Documents
Document Name: Lawyers Letter.pdf
Document Type: Lawyer's letter consisting of a legal description of the property
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=88984&fileName=Lawyers+Letter.pdf

Document Heading: Supporting Documents
Document Name: PhaseTwo.pdf
Document Type: Phase 2 Conceptual Site Model
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=90866&fileName=PhaseTwo.pdf

Document Heading: Supporting Documents
Document Name: Copy_of_Deed_and_other_Documents.pdf
Document Type: Copy of any deed(s), transfer(s) or other document(s)
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=88986&fileName=Copy_of_Deed_and_other_Documents.pdf

Document Heading: Supporting Documents
Document Name: Certifcate_of_Status.pdf
Document Type: Certificate of Status
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=88980&fileName=Certifcate_of_Status.pdf

---

11 | **1 of 1** | **ESE/34.5** | **100.3 / 0.43** | **35 Plains Rd E Burlington On Burlington ON** | **EHS**

Order No: 20150728175
Status: C
Report Type: RSC Report (Urban)
Report Date: 05-AUG-15
Date Received: 28-JUL-15
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: City Directory; Aerial Photos

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .3
X: -79.851957
Y: 43.307894

---

12 | **1 of 3** | **WSW/35.9** | **101.9 / 1.98** | **1029 Waterdown Road Burlington ON L7T 1N4** | **EHS**

Order No: 21112600068
Status: C
Report Type: Standard Report
Report Date: 01-DEC-21
Date Received: 26-NOV-21
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8533289
Y: 43.3076795

---

12 | **2 of 3** | **WSW/35.9** | **101.9 / 1.98** | **1029 Waterdown Road Burlington ON L7T 1N4** | **EHS**

Order No: 21112600068
Status: C
Report Type: Standard Report
Report Date: 01-DEC-21
Date Received: 26-NOV-21
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8533289
Y: 43.3076795

---

12 | **3 of 3** | **WSW/35.9** | **101.9 / 1.98** | **1029 Waterdown Road Burlington ON L7T 1N4** | **EHS**

Order No: 21112600068
Status: C
Report Type: Standard Report

Nearest Intersection:
Municipality:
Client Prov/State: ON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Report Date:	01-DEC-21	**Search Radius (km):**	.25
Date Received:	26-NOV-21	**X:**	-79.8533289
Previous Site Name:		**Y:**	43.3076795
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

13 **1 of 1** **SSE/43.5** **100.7 / 0.79** **15 PLAINS RD. EAST BURLINGTON ON** **WWIS**

Well ID:	7296544	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Test Hole	**Data Entry Status:**	
Use 2nd:	Monitoring	**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	05-Oct-2017 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z270330	**Contractor:**	7241
Tag:	A233909	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	2017/09/22
Year Completed:	2017
Depth (m):	6.096
Latitude:	43.3075308618125
Longitude:	-79.8522829826216
Path:	

Bore Hole Information

Bore Hole ID:	1006754773	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	593081.00
Code OB Desc:		**North83:**	4795606.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	22-Sep-2017 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock

Materials Interval

Formation ID:	1006952116
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Mat2 Desc:	SAND
Mat3:	91
Mat3 Desc:	WATER-BEARING
Formation Top Depth:	9.0
Formation End Depth:	20.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006952115
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	77
Mat3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	9.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006952126
Layer:	3
Plug From:	0.0
Plug To:	6.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006952125
Layer:	2
Plug From:	6.0
Plug To:	9.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006952124
Layer:	1
Plug From:	9.0
Plug To:	20.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID: 1006952123
Method Construction Code: B
Method Construction: Other Method
Other Method Construction: DIRECT PUSH

Pipe Information

Pipe ID: 1006952114
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006952119
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 2.0
Depth To: 10.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1006952120
Layer: 1
Slot: 10
Screen Top Depth: 10.0
Screen End Depth: 20.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.25

Water Details

Water ID: 1006952118
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1006952117
Diameter: 6.0
Depth From: 0.0
Depth To: 20.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID: 1006754773
Depth M: 6.096
Year Completed: 2017
Well Completed Dt: 2017/09/22
Tag No: A233909
Contractor: 7241
Path: 729\7296544.pdf
Latitude: 43.3075308618125

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Audit No:	Z270330			**Longitude:**	-79.8522829826216

14 **1 of 1** **WSW/46.0** **103.4 / 3.51** **ON** **WWIS**

Well ID:	7390906	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	29-Jun-2021 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z365301	**Contractor:**	6946
Tag:	A325545	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008699078	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	592972.00
Code OB Desc:		**North83:**	4795632.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	15-Jun-2021 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008699078	**Tag No:**	A325545
Depth M:		**Contractor:**	6946
Year Completed:	2021	**Path:**	739\7390906.pdf
Well Completed Dt:	2021/06/15	**Latitude:**	43.3077784114805
Audit No:	Z365301	**Longitude:**	-79.8536223221093

15 **1 of 1** **E/46.2** **99.9 / -0.03** **53 PLAINS RD E Burlington ON** **WWIS**

Well ID:	7314783	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	0	**Date Received:**	18-Jul-2018 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	

Audit No:	Z287113	**Contractor:**	7295
Tag:	A237103	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/731\7314783.pdf

Additional Detail(s) (Map)

Well Completed Date:	2018/03/23
Year Completed:	2018
Depth (m):	9.144
Latitude:	43.308298419462
Longitude:	-79.8516026998065
Path:	731\7314783.pdf

Bore Hole Information

Bore Hole ID:	1007174649	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	593135.00
Code OB Desc:		**North83:**	4795692.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	23-Mar-2018 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1007396189
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	2.0
Formation End Depth:	30.0
Formation End Depth UOM:	ft

Overburden and Bedrock

Materials Interval

Formation ID:	1007396190
Layer:	3
Color:	
General Color:	
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	30.0
Formation End Depth:	
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1007396188
Layer:	1
Color:	8
General Color:	BLACK
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	2.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1007396197
Layer:	1
Plug From:	0.0
Plug To:	21.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1007396196
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1007396187
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007396193
Layer:	1
Material:	5

Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	20.0
Casing Diameter:	11.800000190734863
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1007396194
Layer:	1
Slot:	10
Screen Top Depth:	20.0
Screen End Depth:	30.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.0

Water Details

Water ID:	1007396192
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1007396191
Diameter:	6.0
Depth From:	0.0
Depth To:	30.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1007174649	**Tag No:**	A237103
Depth M:	9.144	**Contractor:**	7295
Year Completed:	2018	**Path:**	731\7314783.pdf
Well Completed Dt:	2018/03/23	**Latitude:**	43.308298419462
Audit No:	Z287113	**Longitude:**	-79.8516026998065

---

16 | ***1 of 1*** | ***SSE/46.6*** | ***100.9 / 1.05*** | ***15 PLAINS RD. EAST BURLINGTON ON*** | ***WWIS***

Well ID:	7296543	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Test Hole	**Data Entry Status:**	
Use 2nd:	Municipal	**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	05-Oct-2017 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z270332	**Contractor:**	7241
Tag:	A199254	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	

Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:

PDF URL (Map):

Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Additional Detail(s) (Map)

Well Completed Date: 2017/09/22
Year Completed: 2017
Depth (m): 5.4864
Latitude: 43.3074325733236
Longitude: -79.8523588132171
Path:

Bore Hole Information

Bore Hole ID: 1006754770
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 22-Sep-2017 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 593075.00
North83: 4795595.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1006952090
Layer: 2
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 28
Mat2 Desc: SAND
Mat3: 91
Mat3 Desc: WATER-BEARING
Formation Top Depth: 8.0
Formation End Depth: 18.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006952089
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28

Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	77
Mat3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	8.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006952099
Layer:	2
Plug From:	6.0
Plug To:	7.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006952100
Layer:	3
Plug From:	0.0
Plug To:	6.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006952098
Layer:	1
Plug From:	7.0
Plug To:	18.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1006952097
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	DIRECT PUSH

Pipe Information

Pipe ID:	1006952088
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006952093
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	2.0
Depth To:	8.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch

Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1006952094
Layer: 1
Slot: 10
Screen Top Depth: 8.0
Screen End Depth: 18.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.25

Water Details

Water ID: 1006952092
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1006952091
Diameter: 6.0
Depth From: 0.0
Depth To: 18.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID: 1006754770
Depth M: 5.4864
Year Completed: 2017
Well Completed Dt: 2017/09/22
Audit No: Z270332
Tag No: A199254
Contractor: 7241
Path: 729\7296543.pdf
Latitude: 43.3074325733236
Longitude: -79.8523588132171

---

17 **1 of 2** **ESE/47.3** **100.9 / 1.03** **35 PLAINS RD E Burlington ON** **WWIS**

Well ID: 7232291
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z189200
Tag: A091393
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 21-Nov-2014 00:00:00
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7484
Form Version: 7
Owner:
County: HALTON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/723\7232291.pdf

Additional Detail(s) (Map)

Well Completed Date: 2014/07/18
Year Completed: 2014
Depth (m):
Latitude: 43.3078678945699
Longitude: -79.8517710994704
Path: 723\7232291.pdf

Bore Hole Information

Bore Hole ID: 1005235838
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 18-Jul-2014 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 593122.00
North83: 4795644.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1005466295
Layer: 1
Plug From: 0.0
Plug To: 26.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1005466294
Method Construction Code:
Method Construction:
Other Method Construction:

Pipe Information

Pipe ID: 1005466288
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005466292
Layer: 1
Material: 5

Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	16.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1005466293
Layer:	1
Slot:	10
Screen Top Depth:	16.0
Screen End Depth:	26.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.5

Water Details

Water ID:	1005466291
Layer:	1
Kind Code:	
Kind:	
Water Found Depth:	20.0
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1005466290
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1005235838	**Tag No:**	A091393
Depth M:		**Contractor:**	7484
Year Completed:	2014	**Path:**	723\7232291.pdf
Well Completed Dt:	2014/07/18	**Latitude:**	43.3078678945699
Audit No:	Z189200	**Longitude:**	-79.8517710994704

---

17 **2 of 2** **ESE/47.3** **100.9 / 1.03** ***35 PLAINS RD E Burlington ON*** **WWIS**

Well ID:	7214775	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	15-Jan-2014 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z156436	**Contractor:**	7484
Tag:	A091393	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	

Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:

PDF URL (Map):

Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Additional Detail(s) (Map)

Well Completed Date: 2013/12/16
Year Completed: 2013
Depth (m): 7.9248
Latitude: 43.3078678945699
Longitude: -79.8517710994704
Path:

Bore Hole Information

Bore Hole ID: 1004685640
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 16-Dec-2013 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 593122.00
North83: 4795644.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1005059985
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Mat2 Desc: GRAVEL
Mat3: 06
Mat3 Desc: SILT
Formation Top Depth: 0.0
Formation End Depth: 26.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005059993
Layer: 2
Plug From: 15.0
Plug To: 0.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005059992
Layer:	1
Plug From:	26.0
Plug To:	15.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1005059991
Method Construction Code:	E
Method Construction:	Auger
Other Method Construction:	

Pipe Information

Pipe ID:	1005059984
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005059988
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	16.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1005059989
Layer:	1
Slot:	10
Screen Top Depth:	16.0
Screen End Depth:	26.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.125

Water Details

Water ID:	1005059987
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	20.0
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1005059986
Diameter:	6.0
Depth From:	0.0
Depth To:	26.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1004685640	**Tag No:**	A091393
Depth M:	7.9248	**Contractor:**	7484
Year Completed:	2013	**Path:**	721\7214775.pdf
Well Completed Dt:	2013/12/16	**Latitude:**	43.3078678945699
Audit No:	Z156436	**Longitude:**	-79.8517710994704

18 ***1 of 1*** ***SW/49.5*** ***102.1 / 2.16*** ***ON*** ***WWIS***

Well ID:	7390908	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	29-Jun-2021 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z365308	**Contractor:**	6946
Tag:	A325559	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008699084	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	592991.00
Code OB Desc:		**North83:**	4795607.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	16-Jun-2021 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008699084	**Tag No:**	A325559
Depth M:		**Contractor:**	6946

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Year Completed:	2021	**Path:**	739\7390908.pdf
Well Completed Dt:	2021/06/16	**Latitude:**	43.3075509934598
Audit No:	Z365308	**Longitude:**	-79.853392322507

19 **1 of 1** **S/50.0** **100.7 / 0.84** **15 Plains Rd E**
Burlington ON L7T2B8 **EHS**

Order No:	20170518099	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	24-MAY-17	**Search Radius (km):**	.25
Date Received:	18-MAY-17	**X:**	-79.852538
Previous Site Name:		**Y:**	43.307308
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

20 **1 of 1** **W/55.4** **104.3 / 4.43**
ON **WWIS**

Well ID:	7390907	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	29-Jun-2021 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z365302	**Contractor:**	6946
Tag:	A325561	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008699081	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	592954.00
Code OB Desc:		**North83:**	4795655.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	15-Jun-2021 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008699081	**Tag No:**	A325561

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Depth M:		**Contractor:**	6946
Year Completed:	2021	**Path:**	739\7390907.pdf
Well Completed Dt:	2021/06/15	**Latitude:**	43.3079876999049
Audit No:	Z365302	**Longitude:**	-79.8538403337979

21 **1 of 1** **W/57.1** **104.3 / 4.43** **Enbridge Gas Distribution Inc.**
1045 Waterdown Rd
Burlington ON
SPL

Ref No:	7425-9RNNDB	**Contaminant Qty:**	0 other - see incident description
Site No:	NA	**Nature of Damage:**	
Incident Dt:	2014/12/10	**Discharger Report:**	
Year:		**Material Group:**	
Incident Cause:	Leak/Break	**Health/Env Conseq:**	
Incident Event:		**Agency Involved:**	
Environment Impact:		**Site Lot:**	
Nature of Impact:	Air	**Site Conc:**	
MOE Response:	N	**Site Geo Ref Accu:**	
Dt MOE Arvl on Scn:		**Site Map Datum:**	
MOE Reported Dt:	2014/12/10	**Northing:**	
Dt Document Closed:	2014/12/20	**Easting:**	
Municipality No:			
System Facility Address:			
Client Type:			
Call Report Location Geodata:			
Contaminant Code:	35		
Contaminant Name:	NATURAL GAS (METHANE)		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:			
Receiving Environment:			
Incident Reason:	Operator/Human Error		
Incident Summary:	TSSA: 1/2" plastic gasline		
Site Region:			
Site Municipality:	Burlington		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Other		
SAC Action Class:	TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill		
Source Type:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Union Gas - pipeline<UNOFFICIAL>		
Site Address:	1045 Waterdown Rd		

22 **1 of 1** **SW/60.7** **102.1 / 2.20** **1029 Waterdown Rd**
Burlington ON L7T 1N4
EHS

Order No:	20120827015	**Nearest Intersection:**	
Status:	C	**Municipality:**	Burlington
Report Type:	RSC Premium Package (Urban)	**Client Prov/State:**	ON
Report Date:	05-SEP-12	**Search Radius (km):**	.3
Date Received:	27-AUG-12	**X:**	-79.853311
Previous Site Name:	Unknown	**Y:**	43.307852
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Title Searches; City Directory		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
23	1 of 3	W/60.8	104.4 / 4.47	1029-1063 Waterdown Road Burlington ON L7T 1N4	EHS

Order No:	21100400745	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	07-OCT-21	**Search Radius (km):**	.25
Date Received:	04-OCT-21	**X:**	-79.85386812
Previous Site Name:		**Y:**	43.308195
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Aerial Photos		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
23	2 of 3	W/60.8	104.4 / 4.47	1029-1063 Waterdown Road Burlington ON L7T 1N4	EHS

Order No:	21100400745	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	07-OCT-21	**Search Radius (km):**	.25
Date Received:	04-OCT-21	**X:**	-79.85386812
Previous Site Name:		**Y:**	43.308195
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Aerial Photos		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
23	3 of 3	W/60.8	104.4 / 4.47	1029-1063 Waterdown Road Burlington ON L7T 1N4	EHS

Order No:	21100400745	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	07-OCT-21	**Search Radius (km):**	.25
Date Received:	04-OCT-21	**X:**	-79.85386812
Previous Site Name:		**Y:**	43.308195
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Aerial Photos		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	1 of 1	ESE/60.9	100.8 / 0.90	35 PLAINS ROAD EAST Burlington ON	WWIS

Well ID:	7248589	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	21-Sep-2015 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z214810	**Contractor:**	7472
Tag:	A188283	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	2015/08/18
Year Completed:	2015
Depth (m):	9.2
Latitude:	43.3076523226045
Longitude:	-79.8518244786427
Path:	

Bore Hole Information

Bore Hole ID:	1005694576	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	593118.00
Code OB Desc:		***North83:***	4795620.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	18-Aug-2015 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1005719765
Layer:	1
Color:	7
General Color:	RED
Mat1:	09
Most Common Material:	MEDIUM SAND
Mat2:	
Mat2 Desc:	
Mat3:	77
Mat3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	9.199999809265137
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1005719773
Layer:	2
Plug From:	5.900000095367432
Plug To:	9.199999809265137
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1005719772
Layer:	1
Plug From:	0.0
Plug To:	5.900000095367432

Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1005719771
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1005719764
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005719768
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 6.199999809265137
Casing Diameter: 5.199999809265137
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1005719769
Layer: 1
Slot: 10
Screen Top Depth: 6.199999809265137
Screen End Depth: 9.199999809265137
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.400000095367432

Water Details

Water ID: 1005719767
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1005719766
Diameter: 18.0
Depth From: 0.0
Depth To: 9.199999809265137
Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Bore Hole ID:	1005694576	**Tag No:**	A188283
Depth M:	9.2	**Contractor:**	7472
Year Completed:	2015	**Path:**	724\7248589.pdf
Well Completed Dt:	2015/08/18	**Latitude:**	43.3076523226045
Audit No:	Z214810	**Longitude:**	-79.8518244786427

25 **1 of 15** **NW/61.3** **100.1 / 0.20**

Primary Fluid Systems Inc.
1050 Cooke Blvd Unit 3-4
Burlington ON L7T 4A8

SCT

Established:	01-AUG-91
Plant Size (ft²):	7000
Employment:	

--Details--

Description:	Metal Valve Manufacturing
SIC/NAICS Code:	332910
Description:	Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code:	417230
Description:	All Other Plastic Product Manufacturing
SIC/NAICS Code:	326198
Description:	Metal Valve Manufacturing
SIC/NAICS Code:	332910
Description:	Glass Product Manufacturing from Purchased Glass
SIC/NAICS Code:	327215

25 **2 of 15** **NW/61.3** **100.1 / 0.20**

BHC CABLE ASSEMBLIES INC.
1050 Cooke Blvd Unit 3
Burlington ON L7T 4A8

SCT

Established:	0000
Plant Size (ft²):	0
Employment:	9

--Details--

Description:	Semiconductor and Other Electronic Component Manufacturing
SIC/NAICS Code:	334410

25 **3 of 15** **NW/61.3** **100.1 / 0.20**

INVESTIGATIVE SCIENCE INC.
1050 COOKE BOULEVARD, UNIT 2
BURLINGTON ON L7T 4A8

GEN

Generator No:	ON2335900
SIC Code:	9999
SIC Description:	OTHER SERVICES
Approval Years:	97,98,99,00,01
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

25 | ***4 of 15*** | ***NW/61.3*** | ***100.1 / 0.20*** | ***INVESTIGATIVE SCIENCE INC.***
1050 COOKE BLVD, UNIT 2
BURLINGTON ON L7T 4A8 | ***GEN***

Generator No: ON2335900
SIC Code:
SIC Description:
Approval Years: 02,03,04,05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

25 | ***5 of 15*** | ***NW/61.3*** | ***100.1 / 0.20*** | ***INVESTIGATIVE SCIENCE INC.***
1050 COOKE BLVD, UNIT 2
BURLINGTON ON | ***GEN***

Generator No: ON2335900
SIC Code: 541690, 541380
SIC Description: Other Scientific and Technical Consulting Services, Testing Laboratories
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

25 | ***6 of 15*** | ***NW/61.3*** | ***100.1 / 0.20*** | ***INVESTIGATIVE SCIENCE INC.***
1050 COOKE BLVD, UNIT 2
BURLINGTON ON | ***GEN***

Generator No: ON2335900
SIC Code: 541690, 541380
SIC Description: Other Scientific and Technical Consulting Services, Testing Laboratories
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

25 ***7 of 15*** ***NW/61.3*** ***100.1 / 0.20*** ***INVESTIGATIVE SCIENCE INC.***
1050 COOKE BLVD, UNIT 2
BURLINGTON ON ***GEN***

Generator No: ON2335900
SIC Code: 541690, 541380
SIC Description: Other Scientific and Technical Consulting Services, Testing Laboratories
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

25 ***8 of 15*** ***NW/61.3*** ***100.1 / 0.20*** ***INVESTIGATIVE SCIENCE INC.***
1050 COOKE BLVD, UNIT 2
BURLINGTON ON L7T 4A8 ***GEN***

Generator No: ON2335900
SIC Code: 541690, 541380
SIC Description: Other Scientific and Technical Consulting Services, Testing Laboratories
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

25 ***9 of 15*** ***NW/61.3*** ***100.1 / 0.20*** ***INVESTIGATIVE SCIENCE INC.***
1050 COOKE BLVD, UNIT 2
BURLINGTON ON ***GEN***

Generator No: ON2335900
SIC Code: 541690, 541380
SIC Description: OTHER SCIENTIFIC AND TECHNICAL CONSULTING SERVICES, TESTING LABORATORIES

Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

25 | ***10 of 15*** | ***NW/61.3*** | ***100.1 / 0.20*** | ***INVESTIGATIVE SCIENCE INC.***
1050 COOKE BLVD, UNIT 2
BURLINGTON ON L7T 4A8 | ***GEN***

Generator No: ON2335900
SIC Code: 541690, 541380
SIC Description: OTHER SCIENTIFIC AND TECHNICAL CONSULTING SERVICES, TESTING LABORATORIES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: NONE NONE
Choice of Contact: CO_OFFICIAL
Phone No Admin: NONE Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

25 | ***11 of 15*** | ***NW/61.3*** | ***100.1 / 0.20*** | ***INVESTIGATIVE SCIENCE INC.***
1050 COOKE BLVD, UNIT 2
BURLINGTON ON L7T 4A8 | ***GEN***

Generator No: ON2335900
SIC Code: 541690, 541380
SIC Description: OTHER SCIENTIFIC AND TECHNICAL CONSULTING SERVICES, TESTING LABORATORIES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: NONE NONE
Choice of Contact: CO_OFFICIAL
Phone No Admin: NONE Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

25 | ***12 of 15*** | ***NW/61.3*** | ***100.1 / 0.20*** | ***INVESTIGATIVE SCIENCE INC.***
1050 COOKE BLVD, UNIT 2 | ***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				BURLINGTON ON L7T 4A8	

Generator No: ON2335900
SIC Code: 541690, 541380
SIC Description: OTHER SCIENTIFIC AND TECHNICAL CONSULTING SERVICES, TESTING LABORATORIES
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: NONE NONE
Choice of Contact: CO_OFFICIAL
Phone No Admin: NONE Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

25	13 of 15	NW/61.3	100.1 / 0.20	**INVESTIGATIVE SCIENCE INC.** **1050 COOKE BLVD, UNIT 2** **BURLINGTON ON L7T 4A8**	GEN

Generator No: ON2335900
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241 H
Waste Class Name: Halogenated solvents and residues

25	14 of 15	NW/61.3	100.1 / 0.20	**1050 Cooke Blvd** **Burlington ON L7T 4A8**	EHS

Order No: 20180828032
Status: C
Report Type: Standard Report
Report Date: 04-SEP-18
Date Received: 28-AUG-18
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.853304
Y: 43.308701

25	15 of 15	NW/61.3	100.1 / 0.20	**INVESTIGATIVE SCIENCE INC.** **1050 COOKE BLVD, UNIT 2** **BURLINGTON ON L7T 4A8**	GEN

Generator No: ON2335900
SIC Code:

SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241 H
Waste Class Name: Halogenated solvents and residues

---

26 | **1 of 1** | **SSW/62.4** | **101.7 / 1.85** | **1022 WATERDOWN RD Burlington ON** | **WWIS**

Well ID: 7236357
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z167427
Tag: A162145
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 27-Jan-2015 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: HALTON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2014/12/04
Year Completed: 2014
Depth (m): 9.144
Latitude: 43.3072517998364
Longitude: -79.8531883344548
Path:

Bore Hole Information

Bore Hole ID: 1005294075
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 04-Dec-2014 00:00:00
Remarks:

Elevation:
Elevrc:
Zone: 17
East83: 593008.00
North83: 4795574.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1005512003
Layer: 3
Color: 6
General Color: BROWN
Mat1: 10
Most Common Material: COARSE SAND
Mat2: 06
Mat2 Desc: SILT
Mat3: 85
Mat3 Desc: SOFT
Formation Top Depth: 20.0
Formation End Depth: 30.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1005512001
Layer: 1
Color: 8
General Color: BLACK
Mat1: 27
Most Common Material: OTHER
Mat2:
Mat2 Desc:
Mat3: 85
Mat3 Desc: SOFT
Formation Top Depth: 0.0
Formation End Depth: 0.5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1005512002
Layer: 2
Color: 6
General Color: BROWN
Mat1: 08
Most Common Material: FINE SAND
Mat2: 06
Mat2 Desc: SILT
Mat3: 85
Mat3 Desc: SOFT
Formation Top Depth: 0.5
Formation End Depth: 20.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005512013
Layer: 3
Plug From: 21.0
Plug To: 30.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005512012
Layer: 2
Plug From: 1.0
Plug To: 21.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005512011
Layer: 1
Plug From: 0.0
Plug To: 1.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1005512010
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1005512000
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005512006
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 22.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1005512007
Layer: 1
Slot: 10
Screen Top Depth: 22.0
Screen End Depth: 30.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch

Screen Diameter: 2.25

Water Details

Water ID: 1005512005
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1005512004
Diameter: 8.0
Depth From: 0.0
Depth To: 30.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID: 1005294075
Depth M: 9.144
Year Completed: 2014
Well Completed Dt: 2014/12/04
Audit No: Z167427
Tag No: A162145
Contractor: 7241
Path: 723\7236357.pdf
Latitude: 43.3072517998364
Longitude: -79.8531883344548

---

27 | ***1 of 1*** | ***ENE/65.3*** | ***99.9 / 0.05*** | ***DARKO VRANICH***
1025 COOKE BOULEVARD, BURLINGTON, ON
L7T 4A8
Burlington ON | ***RSC***

RSC ID: 224821
RA No:
RSC Type: Phase 1 and 2 RSC
Curr Property Use: Commercial
Ministry District: Halton-Peel District Office
Filing Date: 2018/08/15
Date Ack:
Date Returned:
Restoration Type:
Soil Type:
Criteria:
CPU Issued Sect 1686:
Cert Date:
Cert Prop Use No:
Intended Prop Use: Residential
Qual Person Name: STEPHEN SEARS
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N):
Accuracy Estimate:
Telephone:
Fax:
Email:
Asmt Roll No: 24-02-010-106-07440
Prop ID No (PIN): 07122-0064 (LT)
Property Municipal Address: 1025 COOKE BOULEVARD, BURLINGTON, ON L7T 4A8
Mailing Address:
Latitude & Latitude:
UTM Coordinates:
Consultant:
Legal Desc:
Measurement Method:
Applicable Standards:
RSC PDF: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=100597&fileName=BROWNFIELDS-E.pdf

Document(s) Detail

Document Heading: Supporting Documents

Document Name: LawyersLetter.pdf
Document Type: Lawyer's letter consisting of a legal description of the property
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=100601&fileName=LawyersLetter.pdf

Document Heading: Supporting Documents
Document Name: PlanofSurvey.pdf
Document Type: A Current plan of Survey
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=100599&fileName=PlanofSurvey.pdf

Document Heading: Supporting Documents
Document Name: TableofCandPUses.pdf
Document Type: Table of Current and Past Property Use
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=100595&fileName=TableofCandPUses.pdf

Document Heading: Supporting Documents
Document Name: TransferDeed.pdf
Document Type: Copy of any deed(s), transfer(s) or other document(s)
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=100598&fileName=TransferDeed.pdf

Document Heading: Supporting Documents
Document Name: AreaofPEConcern.pdf
Document Type: Area(s) of Potential Environmental Concern
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=100603&fileName=AreaofPEConcern.pdf

Document Heading: Supporting Documents
Document Name: PhaseTwoCSM.pdf
Document Type: Phase 2 Conceptual Site Model
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=102474&fileName=PhaseTwoCSM.pdf

---

28 | **1 of 1** | **SSE/67.5** | **100.2 / 0.33** | **15 PLAINS RD. EAST BURLINGTON ON** | **WWIS**

Well ID:	7296545	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Test Hole	**Data Entry Status:**	
Use 2nd:	Monitoring	**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	05-Oct-2017 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z270331	**Contractor:**	7241
Tag:	A199359	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2017/09/22

Year Completed: 2017
Depth (m): 7.0104
Latitude: 43.3071896215499
Longitude: -79.8523757146371
Path:

Bore Hole Information

Bore Hole ID: 1006754776
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 22-Sep-2017 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 593074.00
North83: 4795568.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1006952143
Layer: 2
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 28
Mat2 Desc: SAND
Mat3: 26
Mat3 Desc: ROCK
Formation Top Depth: 13.0
Formation End Depth: 23.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006952142
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 06
Mat2 Desc: SILT
Mat3: 77
Mat3 Desc: LOOSE
Formation Top Depth: 0.0
Formation End Depth: 13.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006952152
Layer: 2
Plug From: 6.0
Plug To: 12.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006952153
Layer: 3
Plug From: 0.0
Plug To: 6.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006952151
Layer: 1
Plug From: 12.0
Plug To: 23.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1006952150
Method Construction Code: B
Method Construction: Other Method
Other Method Construction: DIRECT PUSH

Pipe Information

Pipe ID: 1006952141
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006952146
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 2.0
Depth To: 12.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1006952147
Layer: 1
Slot: 10
Screen Top Depth: 12.0
Screen End Depth: 23.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch

Screen Diameter: 2.25

Water Details

Water ID: 1006952145
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1006952144
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID: 1006754776
Depth M: 7.0104
Year Completed: 2017
Well Completed Dt: 2017/09/22
Audit No: Z270331
Tag No: A199359
Contractor: 7241
Path: 729\7296545.pdf
Latitude: 43.3071896215499
Longitude: -79.8523757146371

---

29 | ***1 of 1*** | ***SW/69.8*** | ***101.8 / 1.87*** | ***1022 WATERDOWN RD Burlington ON*** | ***WWIS***

Well ID: 7236358
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z167426
Tag: A162144
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 27-Jan-2015 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: HALTON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2014/12/04
Year Completed: 2014
Depth (m): 5.4
Latitude: 43.307207527513
Longitude: -79.853263147693
Path:

Bore Hole Information

Bore Hole ID:	1005294078	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	593002.00
Code OB Desc:		***North83:***	4795569.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	04-Dec-2014 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1005512017
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	09
Most Common Material:	MEDIUM SAND
Mat2:	
Mat2 Desc:	
Mat3:	85
Mat3 Desc:	SOFT
Formation Top Depth:	5.0
Formation End Depth:	5.400000095367432
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1005512016
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	06
Mat3 Desc:	SILT
Formation Top Depth:	0.10000000149011612
Formation End Depth:	5.0
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1005512015
Layer:	1
Color:	8
General Color:	BLACK
Mat1:	27

Most Common Material: OTHER
Mat2:
Mat2 Desc:
Mat3: 85
Mat3 Desc: SOFT
Formation Top Depth: 0.0
Formation End Depth: 0.10000000149011612
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005512026
Layer: 2
Plug From: 0.3100000023841858
Plug To: 2.0999999046325684
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005512027
Layer: 3
Plug From: 2.0999999046325684
Plug To: 5.400000095367432
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005512025
Layer: 1
Plug From: 0.0
Plug To: 0.3100000023841858
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1005512024
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1005512014
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005512020
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 2.4000000953674316
Casing Diameter: 5.199999809265137
Casing Diameter UOM: cm

Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1005512021
Layer: 1
Slot: 10
Screen Top Depth: 2.4000000953674316
Screen End Depth: 5.400000095367432
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.099999904632568

Water Details

Water ID: 1005512019
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1005512018
Diameter: 15.0
Depth From: 0.0
Depth To: 5.400000095367432
Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Bore Hole ID: 1005294078
Depth M: 5.4
Year Completed: 2014
Well Completed Dt: 2014/12/04
Audit No: Z167426
Tag No: A162144
Contractor: 7241
Path: 723\7236358.pdf
Latitude: 43.307207527513
Longitude: -79.853263147693

---

30 | ***1 of 2*** | ***ENE/72.7*** | ***99.7 / -0.21*** | ***848347 ONTARIO LIMITED***
53 PLAINS ROAD EAST, BURLINGTON, ON L7T 2B8
Burlington ON | ***RSC***

RSC ID: 224815
RA No:
RSC Type: Phase 1 and 2 RSC
Curr Property Use: Commercial
Ministry District: Halton-Peel District Office
Filing Date: 2018/08/15
Date Ack:
Date Returned:
Restoration Type:
Soil Type:
Criteria:
CPU Issued Sect 1686:
Cert Date:
Cert Prop Use No:
Intended Prop Use: Residential
Qual Person Name: STEPHEN SEARS
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N):
Accuracy Estimate:
Telephone:
Fax:
Email:
Asmt Roll No: 24-02-010-106-04300
Prop ID No (PIN): 07122-0070 (LT)
Property Municipal Address: 53 PLAINS ROAD EAST, BURLINGTON, ON L7T 2B8
Mailing Address:

Latitude & Latitude:
UTM Coordinates:
Consultant:
Legal Desc:
Measurement Method:
Applicable Standards:
RSC PDF: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=100515&fileName=BROWNFIELDS-E.pdf

Document(s) Detail

Document Heading: Supporting Documents
Document Name: PlanofSurvey.pdf
Document Type: A Current plan of Survey
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=100524&fileName=PlanofSurvey.pdf

Document Heading: Supporting Documents
Document Name: AreaofPEConcern.pdf
Document Type: Area(s) of Potential Environmental Concern
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=100520&fileName=AreaofPEConcern.pdf

Document Heading: Supporting Documents
Document Name: TransferDeed.pdf
Document Type: Copy of any deed(s), transfer(s) or other document(s)
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=100522&fileName=TransferDeed.pdf

Document Heading: Supporting Documents
Document Name: CertofStatus.pdf
Document Type: Certificate of Status
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=100516&fileName=CertofStatus.pdf

Document Heading: Supporting Documents
Document Name: LawyersLetter.pdf
Document Type: Lawyer's letter consisting of a legal description of the property
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=100514&fileName=LawyersLetter.pdf

Document Heading: Supporting Documents
Document Name: TableofCandPUses.pdf
Document Type: Table of Current and Past Property Use
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=100521&fileName=TableofCandPUses.pdf

Document Heading: Supporting Documents
Document Name: PhaseTwoCSM.pdf
Document Type: Phase 2 Conceptual Site Model
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=102473&fileName=PhaseTwoCSM.pdf

---

30 ***2 of 2*** ***ENE/72.7*** ***99.7 / -0.21*** ***53 Plains Rd E Burlington ON L7T2B8*** ***EHS***

Order No: 20170525357
Status: C
Report Type: RSC Report (Urban)
Report Date: 01-JUN-17
Date Received: 25-MAY-17
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality: Burlington
Client Prov/State: ON
Search Radius (km): .3
X: -79.851328
Y: 43.308574

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	1 of 1	SW/77.8	102.0 / 2.10	1022 WATERDOWN RD Burlington ON	WWIS

Well ID: 7236354
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z201343
Tag: A172983
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 27-Jan-2015 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: HALTON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2014/12/05
Year Completed: 2014
Depth (m): 5.1816
Latitude: 43.3072091342955
Longitude: -79.8534234092889
Path:

Bore Hole Information

Bore Hole ID: 1005294066
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 05-Dec-2014 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 592989.00
North83: 4795569.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1005511884
Layer: 1
Color: 6
General Color: BROWN

Mat1: 28
Most Common Material: SAND
Mat2: 11
Mat2 Desc: GRAVEL
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 17.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005511894
Layer: 3
Plug From: 1.0
Plug To: 0.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005511892
Layer: 1
Plug From: 17.0
Plug To: 6.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005511893
Layer: 2
Plug From: 6.0
Plug To: 1.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1005511891
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1005511883
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005511887
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 7.0
Casing Diameter: 2.0

Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1005511888
Layer: 1
Slot: 10
Screen Top Depth: 7.0
Screen End Depth: 17.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.25

Water Details

Water ID: 1005511886
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1005511885
Diameter: 6.0
Depth From: 0.0
Depth To: 17.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID: 1005294066
Depth M: 5.1816
Year Completed: 2014
Well Completed Dt: 2014/12/05
Audit No: Z201343
Tag No: A172983
Contractor: 7241
Path: 723\7236354.pdf
Latitude: 43.3072091342955
Longitude: -79.8534234092889

---

32 ***1 of 1*** ***W/79.8*** ***104.9 / 5.04*** ***EDWARDS VICTORIA APARTMENT INC 1045 WATERDOWN RD,,BURLINGTON,ON,L7T 1N4,CA ON*** ***PINC***

Incident Id:
Incident No: 1539128
Incident Reported Dt: 12/10/2014
Type: FS-Pipeline Incident
Status Code:
Tank Status: Pipeline Damage Reason Est
Task No:
Spills Action Centre:
Fuel Type:
Fuel Occurrence Tp:
Date of Occurrence:
Occurrence Start Dt:
Depth:
Customer Acct Name: EDWARDS VICTORIA APARTMENT INC
Incident Address: 1045 WATERDOWN RD,,BURLINGTON,ON,L7T 1N4,CA
Operation Type:
Pipe Material:
Fuel Category:
Health Impact:
Environment Impact:
Property Damage:
Service Interrupt:
Enforce Policy:
Public Relation:
Pipeline System:
PSIG:
Attribute Category:
Regulator Location:
Method Details:

Pipeline Type:
Regulator Type:
Summary:
Reported By:
Affiliation:
Occurrence Desc:
Damage Reason:
Notes:

---

33 | ***1 of 1*** | ***SW/80.1*** | ***102.0 / 2.10*** | ***1022 WATERDOWN RD Burlington ON*** | ***WWIS***

Well ID:	7236355	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	
Final Well Status:	Monitoring and Test Hole	***Date Received:***	27-Jan-2015 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z201345	***Contractor:***	7241
Tag:	A172839	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	HALTON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	2014/12/05
Year Completed:	2014
Depth (m):	5.1816
Latitude:	43.307145496737
Longitude:	-79.8533629549236
Path:	

Bore Hole Information

Bore Hole ID:	1005294069	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	592994.00
Code OB Desc:		***North83:***	4795562.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	05-Dec-2014 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1005511936
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	17.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005511944
Layer:	1
Plug From:	17.0
Plug To:	6.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005511945
Layer:	2
Plug From:	6.0
Plug To:	1.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005511946
Layer:	3
Plug From:	1.0
Plug To:	0.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1005511943
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1005511935
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005511939
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	7.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1005511940
Layer:	1
Slot:	10
Screen Top Depth:	7.0
Screen End Depth:	17.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.25

Water Details

Water ID:	1005511938
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1005511937
Diameter:	6.0
Depth From:	0.0
Depth To:	17.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1005294069	***Tag No:***	A172839
Depth M:	5.1816	***Contractor:***	7241
Year Completed:	2014	***Path:***	723\7236355.pdf
Well Completed Dt:	2014/12/05	***Latitude:***	43.307145496737
Audit No:	Z201345	***Longitude:***	-79.8533629549236

---

34 ***1 of 1*** ***S/84.5*** ***100.7 / 0.85*** ***ON*** ***BORE***

Borehole ID:	622151	***Inclin FLG:***	No
OGF ID:	215522605	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	AUG-1961	***Municipality:***	
Static Water Level:		***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.306966

Total Depth m:	5	**Longitude DD:**	-79.852867
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	593034
Drill Method:	Power auger	**Northing:**	4795543
Orig Ground Elev m:	99.7	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	101		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218424620	**Mat Consistency:**	Hard
Top Depth:	.1	**Material Moisture:**	
Bottom Depth:	5	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Gravel	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND,CLAY,GRAVEL. BROWN,HARD,AGE GLACIAL. 000020820 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218424619	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.1	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Soil	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SOIL. AGE POST-GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: HAM.txt RecordID: 011510 NTS_Sheet: 30M05C		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
35	1 of 3	WSW/93.2	104.1 / 4.24	1036 Waterdown Rd Burlington ON L7T 1N3	EHS

Order No:	20120827017	**Nearest Intersection:**	
Status:	C	**Municipality:**	Burlington

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Report Type:	RSC Report (Urban)	**Client Prov/State:**	ON
Report Date:	05-SEP-12	**Search Radius (km):**	.3
Date Received:	27-AUG-12	**X:**	-79.853849
Previous Site Name:	Unknown	**Y:**	43.307529
Lot/Building Size:			
Additional Info Ordered:	Title Searches; City Directory		

35 **2 of 3** **WSW/93.2** **104.1 / 4.24** **DUCON UTILITIES LIMITED** **PINC**
1036 WATERDOWN RD,,BURLINGTON,ON,L7T 1N3,CA
ON

Incident Id:		**Pipe Material:**	
Incident No:	1690538	**Fuel Category:**	
Incident Reported Dt:	7/28/2015	**Health Impact:**	
Type:	FS-Pipeline Incident	**Environment Impact:**	
Status Code:		**Property Damage:**	
Tank Status:	Pipeline Damage Reason Est	**Service Interrupt:**	
Task No:		**Enforce Policy:**	
Spills Action Centre:		**Public Relation:**	
Fuel Type:		**Pipeline System:**	
Fuel Occurrence Tp:		**PSIG:**	
Date of Occurrence:		**Attribute Category:**	
Occurrence Start Dt:		**Regulator Location:**	
Depth:		**Method Details:**	
Customer Acct Name:	DUCON UTILITIES LIMITED		
Incident Address:	1036 WATERDOWN RD,,BURLINGTON,ON,L7T 1N3,CA		
Operation Type:			
Pipeline Type:			
Regulator Type:			
Summary:			
Reported By:			
Affiliation:			
Occurrence Desc:			
Damage Reason:			
Notes:			

35 **3 of 3** **WSW/93.2** **104.1 / 4.24** **Union Gas Limited** **SPL**
1036 Waterdown Rd
Burlington ON

Ref No:	2527-9YTSKN	**Contaminant Qty:**	0 other - see incident description
Site No:	NA	**Nature of Damage:**	
Incident Dt:	7/27/2015	**Discharger Report:**	
Year:		**Material Group:**	
Incident Cause:		**Health/Env Conseq:**	
Incident Event:		**Agency Involved:**	
Environment Impact:		**Site Lot:**	
Nature of Impact:		**Site Conc:**	
MOE Response:	No	**Site Geo Ref Accu:**	
Dt MOE Arvl on Scn:		**Site Map Datum:**	
MOE Reported Dt:	7/27/2015	**Northing:**	
Dt Document Closed:	8/26/2015	**Easting:**	
Municipality No:			
System Facility Address:			
Client Type:			
Call Report Location Geodata:			
Contaminant Code:	35		
Contaminant Name:	NATURAL GAS (METHANE)		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			

Receiving Medium:
Receiving Environment:
Incident Reason: Operator/Human Error
Incident Summary: TSSA 4" plstc ln dmg, made safe
Site Region:
Site Municipality: Burlington
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Unknown / N/A
SAC Action Class: TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Source Type:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: New construction site<UNOFFICIAL>
Site Address: 1036 Waterdown Rd

---

36 ***1 of 1*** ***ESE/96.0*** ***101.9 / 2.00*** ***PLAINS RD EAST (ROAD HOLES) BURLINGTON ON*** ***WWIS***

Well ID: 2810154
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z21604
Tag: A016930
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 07-Feb-2005 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 6607
Form Version: 3
Owner:
County: HALTON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/281\2810154.pdf

Additional Detail(s) (Map)

Well Completed Date: 2004/11/22
Year Completed: 2004
Depth (m): 4.5
Latitude: 43.3075219509862
Longitude: -79.8513953757756
Path: 281\2810154.pdf

Bore Hole Information

Bore Hole ID: 11319109
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:

Elevation:
Elevrc:
Zone: 17
East83: 593153.00
North83: 4795606.00
Org CS: UTM83

Cluster Kind:
Date Completed: 22-Nov-2004 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 933007111
Layer: 3
Color:
General Color:
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.30000001192092896
Formation End Depth: 4.5
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 933007110
Layer: 2
Color:
General Color:
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.15000000596046448
Formation End Depth: 0.30000001192092896
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 933007109
Layer: 1
Color: 7
General Color: RED
Mat1: 28
Most Common Material: SAND
Mat2: 06
Mat2 Desc: SILT
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.15000000596046448
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID:	933265362
Layer:	2
Plug From:	0.15000000596046448
Plug To:	1.2000000476837158
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933265363
Layer:	1
Plug From:	0.0
Plug To:	0.15000000596046448
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	962810154
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	11333964
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930860105
Layer:	1
Material:	
Open Hole or Material:	
Depth From:	0.0
Depth To:	1.5
Casing Diameter:	5.0
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	933411750
Layer:	1
Slot:	10
Screen Top Depth:	1.5
Screen End Depth:	4.5
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.400000095367432

Hole Diameter

Hole ID:	11537670
Diameter:	21.0

Depth From:	0.0
Depth To:	4.5
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	11319109	**Tag No:**	A016930
Depth M:	4.5	**Contractor:**	6607
Year Completed:	2004	**Path:**	281\2810154.pdf
Well Completed Dt:	2004/11/22	**Latitude:**	43.3075219509862
Audit No:	Z21604	**Longitude:**	-79.8513953757756

---

37 ***1 of 1*** ***SW/96.8*** ***101.7 / 1.81*** ***1022 WATERDOWN RD Burlington ON*** ***WWIS***

Well ID:	7236356	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	27-Jan-2015 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z201346	**Contractor:**	7241
Tag:	A172832	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	2014/12/05
Year Completed:	2014
Depth (m):	5.4864
Latitude:	43.3070205698601
Longitude:	-79.8534762743314
Path:	

Bore Hole Information

Bore Hole ID:	1005294072	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	592985.00
Code OB Desc:		**North83:**	4795548.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	05-Dec-2014 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			

Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1005511948
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Mat2 Desc: GRAVEL
Mat3: 91
Mat3 Desc: WATER-BEARING
Formation Top Depth: 0.0
Formation End Depth: 18.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005511958
Layer: 2
Plug From: 1.0
Plug To: 7.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005511957
Layer: 1
Plug From: 0.0
Plug To: 1.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005511959
Layer: 3
Plug From: 7.0
Plug To: 18.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1005511956
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction: DIRECT PUSH

Pipe Information

Pipe ID: 1005511947
Casing No: 0

Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1005511952
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	8.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1005511953
Layer:	1
Slot:	10
Screen Top Depth:	8.0
Screen End Depth:	18.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.25

Water Details

Water ID:	1005511951
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1005511949
Diameter:	8.0
Depth From:	0.0
Depth To:	1.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Hole Diameter

Hole ID:	1005511950
Diameter:	6.25
Depth From:	1.0
Depth To:	18.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1005294072	***Tag No:***	A172832
Depth M:	5.4864	***Contractor:***	7241
Year Completed:	2014	***Path:***	723\7236356.pdf
Well Completed Dt:	2014/12/05	***Latitude:***	43.3070205698601
Audit No:	Z201346	***Longitude:***	-79.8534762743314

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	1 of 1	ESE/101.8	102.0 / 2.09	34 PLAINS RD. E. lot 6 BURLINGTON ON	WWIS

Well ID: 7176158
Construction Date:
Use 1st: Monitoring
Use 2nd: Other
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z104052
Tag: A066618
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 01-Feb-2012 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7484
Form Version: 7
Owner:
County: HALTON
Lot: 006
Concession:
Concession Name: FEF BF
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7176158.pdf

Additional Detail(s) (Map)

Well Completed Date: 2011/10/20
Year Completed: 2011
Depth (m): 9.144
Latitude: 43.3075209604693
Longitude: -79.8512967528178
Path: 717\7176158.pdf

Bore Hole Information

Bore Hole ID: 1003645657
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 20-Oct-2011 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 593161.00
North83: 4795606.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1004042275
Layer: 2
Color: 6
General Color: BROWN

Mat1: 28
Most Common Material: SAND
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 22.0
Formation End Depth: 30.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1004042274
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Mat2 Desc: GRAVEL
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 22.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004042283
Layer: 1
Plug From: 0.0
Plug To: 19.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004042284
Layer: 2
Plug From: 19.0
Plug To: 30.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1004042282
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1004042273
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1004042278
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	20.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004042279
Layer:	1
Slot:	10
Screen Top Depth:	20.0
Screen End Depth:	30.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.5

Water Details

Water ID:	1004042277
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	22.0
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1004042276
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1003645657	**Tag No:**	A066618
Depth M:	9.144	**Contractor:**	7484
Year Completed:	2011	**Path:**	717\7176158.pdf
Well Completed Dt:	2011/10/20	**Latitude:**	43.3075209604693
Audit No:	Z104052	**Longitude:**	-79.8512967528178

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	1 of 1	SSE/103.4	100.9 / 1.02	14 PLAINS RD BURLINGTON ON	WWIS

Well ID:	2810377	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	05-Oct-2005 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z35420	**Contractor:**	6607
Tag:	A031759	**Form Version:**	3
Constructn Method:		**Owner:**	

Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/281\2810377.pdf

Additional Detail(s) (Map)

Well Completed Date:	2005/09/12
Year Completed:	2005
Depth (m):	9.1
Latitude:	43.3070142380402
Longitude:	-79.8519474610449
Path:	281\2810377.pdf

Bore Hole Information

Bore Hole ID:	11319332	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	593109.00
Code OB Desc:		**North83:**	4795549.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	12-Sep-2005 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	933007649
Layer:	6
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Mat2 Desc:	SAND
Mat3:	91
Mat3 Desc:	WATER-BEARING
Formation Top Depth:	5.099999904632568
Formation End Depth:	9.100000381469727
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID: 933007648

Layer: 5
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 4.199999809265137
Formation End Depth: 5.099999904632568
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 933007644
Layer: 1
Color: 8
General Color: BLACK
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.15000000596046448
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 933007646
Layer: 3
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 1.5
Formation End Depth: 2.700000047683716
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 933007645
Layer: 2
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 12
Mat2 Desc: STONES
Mat3: 11
Mat3 Desc: GRAVEL
Formation Top Depth: 0.15000000596046448
Formation End Depth: 1.5
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID:	933007647
Layer:	4
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Mat2 Desc:	SAND
Mat3:	
Mat3 Desc:	
Formation Top Depth:	2.700000047683716
Formation End Depth:	4.199999809265137
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933278151
Layer:	2
Plug From:	0.30000001192092896
Plug To:	5.400000095367432
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933278152
Layer:	1
Plug From:	0.0
Plug To:	0.30000001192092896
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	962810377
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	11334187
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930860334
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	6.0
Casing Diameter:	5.099999904632568
Casing Diameter UOM:	cm

Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933414836
Layer: 1
Slot: 10
Screen Top Depth: 6.0
Screen End Depth: 9.100000381469727
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.400000095367432

Hole Diameter

Hole ID: 11537920
Diameter: 21.0
Depth From: 0.0
Depth To: 9.100000381469727
Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Bore Hole ID: 11319332
Depth M: 9.1
Year Completed: 2005
Well Completed Dt: 2005/09/12
Audit No: Z35420
Tag No: A031759
Contractor: 6607
Path: 281\2810377.pdf
Latitude: 43.3070142380402
Longitude: -79.8519474610449

---

40 ***1 of 3*** ***SW/103.9*** ***102.4 / 2.49*** ***PIPELINE HIT - 1/2"*** ***PINC***
1022 WATERDOWN ROAD,,BURLINGTON,ON,
L7T 1N3,CA
ON

Incident Id:
Incident No: 1697416
Incident Reported Dt: 8/7/2015
Type: FS-Pipeline Incident
Status Code:
Tank Status: Pipeline Damage Reason Est
Task No:
Spills Action Centre:
Fuel Type:
Fuel Occurrence Tp:
Date of Occurrence:
Occurrence Start Dt:
Depth:
Customer Acct Name: PIPELINE HIT - 1/2"
Incident Address: 1022 WATERDOWN ROAD,,BURLINGTON,ON,L7T 1N3,CA
Operation Type:
Pipeline Type:
Regulator Type:
Summary:
Reported By:
Affiliation:
Occurrence Desc:
Damage Reason:
Notes:
Pipe Material:
Fuel Category:
Health Impact:
Environment Impact:
Property Damage:
Service Interrupt:
Enforce Policy:
Public Relation:
Pipeline System:
PSIG:
Attribute Category:
Regulator Location:
Method Details:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	2 of 3	SW/103.9	102.4 / 2.49	Union Gas Limited 1022 Waterdown Road Burlington ON L7T 1N3	SPL

Ref No: 5047-9Z6MCC
Site No: NA
Incident Dt: 8/7/2015
Year:
Incident Cause:
Incident Event:
Environment Impact:
Nature of Impact:
MOE Response: No
Dt MOE Arvl on Scn:
MOE Reported Dt: 8/7/2015
Dt Document Closed: 8/26/2015
Municipality No:
System Facility Address:
Client Type:
Call Report Location Geodata:
Contaminant Code: 35
Contaminant Name: NATURAL GAS (METHANE)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Receiving Environment:
Incident Reason: Operator/Human Error
Incident Summary: TSSA/FSB ½ inch plastic, line damage, made safe
Site Region:
Site Municipality: Burlington
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Industrial
SAC Action Class: TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Source Type:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Commercial Site<UNOFFICIAL>
Site Address: 1022 Waterdown Road

Contaminant Qty: 0 other - see incident description
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved:
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	3 of 3	SW/103.9	102.4 / 2.49	1022 Waterdown Rd Burlington ON L7T1N3	EHS

Order No: 20141024046
Status: C
Report Type: Custom Report
Report Date: 30-OCT-14
Date Received: 24-OCT-14
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.853667
Y: 43.307166

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
41	1 of 1	SW/104.0	103.5 / 3.64	1028 WATERDOWN ROAD Burlington ON	WWIS

Well ID: 7229430
Construction Date:
Use 1st:

Flowing (Y/N):
Flow Rate:
Data Entry Status:

Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Supply	**Date Received:**	14-Oct-2014 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z192217	**Contractor:**	7146
Tag:		**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: BURLINGTON CITY
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/722\7229430.pdf

Additional Detail(s) (Map)

Well Completed Date: 2014/08/23
Year Completed: 2014
Depth (m):
Latitude: 43.3072319588967
Longitude: -79.8539038558264
Path: 722\7229430.pdf

Bore Hole Information

Bore Hole ID:	1005161180	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	592950.00
Code OB Desc:		**North83:**	4795571.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	23-Aug-2014 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1005396543
Layer: 4
Plug From: 7.0
Plug To: 5.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005396540
Layer: 1

Plug From: 15.0
Plug To: 14.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005396541
Layer: 2
Plug From: 14.0
Plug To: 13.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005396542
Layer: 3
Plug From: 13.0
Plug To: 7.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1005396539
Method Construction Code:
Method Construction:
Other Method Construction:

Pipe Information

Pipe ID: 1005396532
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005396537
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1005396538
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1005396533
Pump Set At:	
Static Level:	13.0
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	0
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1005396536
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1005396535
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1005161180	***Tag No:***	
Depth M:		***Contractor:***	7146
Year Completed:	2014	***Path:***	722\7229430.pdf
Well Completed Dt:	2014/08/23	***Latitude:***	43.3072319588967
Audit No:	Z192217	***Longitude:***	-79.8539038558264

42 ***1 of 1*** ***E/104.3*** ***101.3 / 1.37*** ***ON*** ***WWIS***

Well ID:	7361072	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	26-Jun-2020 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z332249	***Contractor:***	6946
Tag:	A299539	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	HALTON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	

Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:
Year Completed:
Depth (m):
Latitude: 43.3078238355795
Longitude: -79.8509704618392
Path:

Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1008323068
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed:
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 593187.00
North83: 4795640.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Links

Bore Hole ID: 1008323068
Depth M:
Year Completed:
Well Completed Dt:
Audit No: Z332249

Tag No: A299539
Contractor: 6946
Path: 736\7361072.pdf
Latitude: 43.3078238355795
Longitude: -79.8509704618392

---

43 | ***1 of 21*** | ***WNW/110.4*** | ***102.2 / 2.33*** | ***ETRATECH PRINTED CIRCUIT BOARDS INC.*** ***1062 COOKE BOULEVARD*** ***BURLINGTON CITY ON L7T 4A8*** | ***CA***

Certificate #: 8-3515-97-
Application Year: 97
Issue Date: 1/6/1998
Approval Type: Industrial air
Status:
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: BAG FILTER FOR DRILLING/BOARD PREP.PROC.
Contaminants: Suspended Particulate Matter

Emission Control: Baghouse (Incl Vent Fil.)

---

43 | **2 of 21** | **WNW/110.4** | **102.2 / 2.33** | **Etratech Printed Circuit Boards Inc.**
1062 Cooke Boulevard Burlington CITY OF BURLINGTON
ON | **EBR**

EBR Registry No: IA7E1724
Ministry Ref No: 8351597 19971031
Notice Type: Instrument Decision
Notice Stage:
Notice Date: January 05, 1998
Proposal Date: November 25, 1997
Year: 1997
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Etratech Printed Circuit Boards Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 1047 Cooke Boulevard, Burlington, Ontario, L7T 4A8
Comment Period:
URL:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

1062 Cooke Boulevard Burlington CITY OF BURLINGTON

---

43 | **3 of 21** | **WNW/110.4** | **102.2 / 2.33** | **ETRATECH PRINTED CIRCUIT BOARDS INC.**
1062 COOKE BOULEVARD
BURLINGTON ON L7T 4A8 | **GEN**

Generator No: ON1622302
SIC Code: 3352
SIC Description: ELECT. PARTS & COMP.
Approval Years: 97,98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 131
Waste Class Name: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 132
Waste Class Name: NEUTRALIZED WASTES - OTHER METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

43 | **4 of 21** | **WNW/110.4** | **102.2 / 2.33** | **1062 Cooke Blvd Burlington ON L7T 4A8** | **EHS**

Order No: 20061123011
Status: C
Report Type: Basic Report
Report Date: 12/1/2006
Date Received: 11/23/2006
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.853604
Y: 43.309136

---

43 | **5 of 21** | **WNW/110.4** | **102.2 / 2.33** | **Category 5 Imaging Ltd. 1062 Cooke Boulevard Burlington Regional Municipality of Halton L7T 4A8 CITY OF BURLINGTON ON** | **EBR**

EBR Registry No: 010-0961
Ministry Ref No: 7796-743LL4
Notice Type: Instrument Decision
Notice Stage:
Notice Date: March 03, 2009
Proposal Date: June 29, 2007
Year: 2007

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Category 5 Imaging Ltd.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 1062 Cooke boulevard, Burlington Ontario, Canada L7T 4A8
Comment Period:
URL:

Site Location Details:

1062 Cooke Boulevard Burlington Regional Municipality of Halton L7T 4A8 CITY OF BURLINGTON

---

43 | **6 of 21** | **WNW/110.4** | **102.2 / 2.33** | **CATEGORY 5 IMAGING 1062 COOKE BLVD. BURLINGTON ON L7T 4A8** | **GEN**

Generator No: ON8332190
SIC Code: 323119
SIC Description: Other Printing
Approval Years: 07,08
PO Box No:
Country:
Status:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

43 **7 of 21** **WNW/110.4** **102.2 / 2.33** **Category 5 Imaging Ltd.**
1062 Cooke Blvd
Burlington ON L7T 4A8 **CA**

Certificate #: 3066-7P7RVU
Application Year: 2009
Issue Date: 2/26/2009
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

43 **8 of 21** **WNW/110.4** **102.2 / 2.33** **CATEGORY 5 IMAGING**
1062 COOKE BLVD.
BURLINGTON ON L7T 4A8 **GEN**

Generator No: ON8332190
SIC Code: 323119
SIC Description: Other Printing
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

43 **9 of 21** **WNW/110.4** **102.2 / 2.33** **CATEGORY 5 IMAGING**
1062 COOKE BLVD.
BURLINGTON ON L7T 4A8 **GEN**

Generator No: ON8332190
SIC Code: 323119
SIC Description: Other Printing
Approval Years: 2010
PO Box No:
Country:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
43	10 of 21	WNW/110.4	102.2 / 2.33	CATEGORY 5 IMAGING 1062 COOKE BLVD. BURLINGTON ON L7T 4A8	GEN

Generator No: ON8332190
SIC Code: 323119
SIC Description: Other Printing
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
43	11 of 21	WNW/110.4	102.2 / 2.33	CATEGORY 5 IMAGING 1062 COOKE BLVD. BURLINGTON ON L7T 4A8	GEN

Generator No: ON8332190
SIC Code: 323119
SIC Description: Other Printing
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
43	12 of 21	WNW/110.4	102.2 / 2.33	CATEGORY 5 IMAGING 1062 COOKE BLVD. BURLINGTON ON	GEN

Generator No: ON8332190

SIC Code: 323119
SIC Description: OTHER PRINTING
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

43 **13 of 21** **WNW/110.4** **102.2 / 2.33** **Category 5 Imaging Ltd.**
1062 Cooke Blvd
Burlington ON L7T 4A8 **ECA**

Approval No: 3066-7P7RVU
Approval Date: 2009-02-26
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
MOE District: Halton-Peel
City:
Longitude: -79.85382
Latitude: 43.30895
Geometry X:
Geometry Y:
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Category 5 Imaging Ltd.
Address: 1062 Cooke Blvd
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7796-743LL4-14.pdf
PDF Site Location:

---

43 **14 of 21** **WNW/110.4** **102.2 / 2.33** **CATEGORY 5 IMAGING**
1062 COOKE BLVD.
BURLINGTON ON L7T 4A8 **GEN**

Generator No: ON8332190
SIC Code: 323119
SIC Description: OTHER PRINTING
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Lisa MacPherson
Choice of Contact: CO_ADMIN
Phone No Admin: 905.333.3228 Ext.227
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
43	15 of 21	WNW/110.4	102.2 / 2.33	CATEGORY 5 IMAGING 1062 COOKE BLVD. BURLINGTON ON L7T 4A8	GEN

Generator No: ON8332190
SIC Code: 323119
SIC Description: OTHER PRINTING
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Lisa MacPherson
Choice of Contact: CO_ADMIN
Phone No Admin: 905.333.3228 Ext.227
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
43	16 of 21	WNW/110.4	102.2 / 2.33	CATEGORY 5 IMAGING 1062 COOKE BLVD. BURLINGTON ON L7T 4A8	GEN

Generator No: ON8332190
SIC Code: 323119
SIC Description: OTHER PRINTING
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Alisha Markowski
Choice of Contact: CO_ADMIN
Phone No Admin: 905.333.3228 Ext.227
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
43	17 of 21	WNW/110.4	102.2 / 2.33	CATEGORY 5 IMAGING 1062 COOKE BLVD. BURLINGTON ON L7T 4A8	GEN

Generator No: ON8332190
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:

Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

---

43 | ***18 of 21*** | ***WNW/110.4*** | ***102.2 / 2.33*** | ***1062 Cooke Blvd & 1074 Cooke Blvd. Burlington ON L7T 4A8*** | ***EHS***

Order No: 20180528002
Status: C
Report Type: Standard Report
Report Date: 29-MAY-18
Date Received: 28-MAY-18
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.85392
Y: 43.308872

---

43 | ***19 of 21*** | ***WNW/110.4*** | ***102.2 / 2.33*** | ***CATEGORY 5 IMAGING INC. 1062 COOKE BLVD. BURLINGTON ON L7T 4A8*** | ***GEN***

Generator No: ON8332190
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

---

43 | ***20 of 21*** | ***WNW/110.4*** | ***102.2 / 2.33*** | ***CATEGORY 5 IMAGING INC. 1062 COOKE BLVD. BURLINGTON ON L7T 4A8*** | ***GEN***

Generator No: ON8332190
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

---

43 | ***21 of 21*** | ***WNW/110.4*** | ***102.2 / 2.33*** | ***CATEGORY 5 IMAGING INC.***
1062 COOKE BLVD.
BURLINGTON ON L7T 4A8 | ***GEN***

Generator No: ON8332190
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

---

44 | ***1 of 4*** | ***WSW/114.6*** | ***105.5 / 5.59*** | ***CORPORATION OF THE CITY OF BURLINGTON***
1044 WATERDOWN RD
BURLINGTON ON L7T 1N3 | ***EASR***

Approval No: R-002-3474294691
Status: REGISTERED
Date: 2015-01-06
Record Type: EASR
Link Source: MOFA
Project Type: Standby Power System
Full Address:
Approval Type: EASR-Standby Power System
SWP Area Name: Halton
PDF URL:
PDF Site Location:

MOE District: Halton-Peel
Municipality: BURLINGTON
Latitude: 43.30805556
Longitude: -79.85444444
Geometry X:
Geometry Y:

---

44 | ***2 of 4*** | ***WSW/114.6*** | ***105.5 / 5.59*** | ***The City of Burlington Corp Fire Department***
1044 Waterdown Road
Burlington ON L7T1N3 | ***GEN***

Generator No: ON3217296
SIC Code:
SIC Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

44	*3 of 4*	*WSW/114.6*	*105.5 / 5.59*	***The City of Burlington Corp Fire Department*** ***1044 Waterdown Road*** ***Burlington ON L7T1N3***	*GEN*

Generator No: ON3217296
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

44	*4 of 4*	*WSW/114.6*	*105.5 / 5.59*	***The City of Burlington Corp Fire Department*** ***1044 Waterdown Road*** ***Burlington ON L7T1N3***	*GEN*

Generator No: ON3217296
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

45	*1 of 14*	*SSW/117.6*	*100.9 / 0.97*	***PETRO CANADA CAR WASH ATTN GARY HACKMAN***	*PRT*

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				7 PLAINS RD W BURLINGTON ON L7T 1E8	

Location ID: 2469
Type: retail
Expiry Date: 1994-06-30
Capacity (L): 90800
Licence #: 0076392406

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
45	2 of 14	SSW/117.6	100.9 / 0.97	PETRO CANADA CAR WASH ATTN GARY HACKMAN 7 PLAINS RD W BURLINGTON ON L7T 1E8	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 9456290
Status: EXPIRED
Instance ID:
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description:
Original Source: EXP
Record Date: Up to May 2013

Expired Date: 6/8/1993
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
45	3 of 14	SSW/117.6	100.9 / 0.97	PETRO CANADA CAR WASH ATTN GARY HACKMAN 7 PLAINS RD W BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 10633690
Status: EXPIRED
Instance ID: 29924
Instance Type: FS Piping
Instance Creation Dt:

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

45 | ***4 of 14*** | ***SSW/117.6*** | ***100.9 / 0.97*** | ***PETRO CANADA CAR WASH ATTN GARY HACKMAN
7 PLAINS RD W
BURLINGTON ON*** | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10633559
Status: EXPIRED
Instance ID: 31071
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
45	5 of 14	SSW/117.6	100.9 / 0.97	PETRO CANADA CAR WASH ATTN GARY HACKMAN 7 PLAINS RD W BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10633606	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	31367	***Facility Location:***	
Instance Type:	FS Piping	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
45	6 of 14	SSW/117.6	100.9 / 0.97	PETRO CANADA CAR WASH ATTN GARY HACKMAN 7 PLAINS RD W BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10633648	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	32050	***Facility Location:***	
Instance Type:	FS Piping	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

45	***7 of 14***	***SSW/117.6***	***100.9 / 0.97***	***PETRO CANADA CAR WASH ATTN GARY HACKMAN*** ***7 PLAINS RD W BURLINGTON L7T 1E8 ON CA*** ***ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	10633625	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	NULL
Instance ID:		***Facility Location:***	7 PLAINS RD W BURLINGTON L7T 1E8 ON CA
Instance Type:		***Facility Type:***	FS LIQUID FUEL TANK
Instance Creation Dt:	5/14/1992	***Fuel Type 2:***	NULL
Instance Install Dt:	5/14/1992	***Fuel Type 3:***	NULL
Item Description:	FS Liquid Fuel Tank	***Panam Related:***	NULL
Manufacturer:	NULL	***Panam Venue Nm:***	NULL
Model:	NULL	***External Identifier:***	NULL
Serial No:	NULL	***Item:***	
ULC Standard:	NULL	***Piping Steel:***	
Quantity:	1	***Piping Galvanized:***	
Unit of Measure:	EA	***Tank Single Wall St:***	
Overfill Prot Type:	NULL	***Piping Underground:***	
Creation Date:	7/5/2009 1:20:03 AM	***Tank Underground:***	
Next Periodic Str DT:	NULL	***Source:***	FS Liquid Fuel Tank
TSSA Base Sched Cycle 2:	NULL		
TSSAMax Hazard Rank 1:	NULL		
TSSA Risk Based Periodic Yn:	NULL		
TSSA Volume of Directives:	NULL		
TSSA Periodic Exempt:	NULL		
TSSA Statutory Interval:	NULL		
TSSA Recd Insp Interva:	NULL		
TSSA Recd Tolerance:	NULL		
TSSA Program Area:	NULL		
TSSA Program Area 2:	NULL		
Description:	UNDERGROUND TANK		
Original Source:	EXP		
Record Date:	31-JUL-2020		

45	***8 of 14***	***SSW/117.6***	***100.9 / 0.97***	***PETRO CANADA CAR WASH ATTN GARY HACKMAN*** ***7 PLAINS RD W BURLINGTON L7T 1E8 ON CA*** ***ON***	***DTNK***

Delisted Expired Fuel Safety

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Facilities

Instance No:	10633669	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	NULL
Instance ID:		***Facility Location:***	7 PLAINS RD W BURLINGTON L7T 1E8 ON CA
Instance Type:		***Facility Type:***	FS LIQUID FUEL TANK
Instance Creation Dt:	10/2/1989	***Fuel Type 2:***	NULL
Instance Install Dt:	10/2/1989	***Fuel Type 3:***	NULL
Item Description:	FS Liquid Fuel Tank	***Panam Related:***	NULL
Manufacturer:	NULL	***Panam Venue Nm:***	NULL
Model:	NULL	***External Identifier:***	NULL
Serial No:	NULL	***Item:***	
ULC Standard:	NULL	***Piping Steel:***	
Quantity:	1	***Piping Galvanized:***	
Unit of Measure:	EA	***Tank Single Wall St:***	
Overfill Prot Type:	NULL	***Piping Underground:***	
Creation Date:	7/5/2009 1:20:04 AM	***Tank Underground:***	
Next Periodic Str DT:	NULL	***Source:***	FS Liquid Fuel Tank
TSSA Base Sched Cycle 2:	NULL		
TSSAMax Hazard Rank 1:	NULL		
TSSA Risk Based Periodic Yn:	NULL		
TSSA Volume of Directives:	NULL		
TSSA Periodic Exempt:	NULL		
TSSA Statutory Interval:	NULL		
TSSA Recd Insp Interva:	NULL		
TSSA Recd Tolerance:	NULL		
TSSA Program Area:	NULL		
TSSA Program Area 2:	NULL		
Description:	UNDERGROUND TANK		
Original Source:	EXP		
Record Date:	31-JUL-2020		

45	***9 of 14***	***SSW/117.6***	***100.9 / 0.97***	***PETRO CANADA CAR WASH ATTN GARY HACKMAN*** ***7 PLAINS RD W BURLINGTON L7T 1E8 ON CA*** ***ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	10633580	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	NULL
Instance ID:		***Facility Location:***	7 PLAINS RD W BURLINGTON L7T 1E8 ON CA
Instance Type:		***Facility Type:***	FS LIQUID FUEL TANK
Instance Creation Dt:	5/14/1992	***Fuel Type 2:***	NULL
Instance Install Dt:	5/14/1992	***Fuel Type 3:***	NULL
Item Description:	FS Liquid Fuel Tank	***Panam Related:***	NULL
Manufacturer:	NULL	***Panam Venue Nm:***	NULL
Model:	NULL	***External Identifier:***	NULL
Serial No:	NULL	***Item:***	
ULC Standard:	NULL	***Piping Steel:***	
Quantity:	1	***Piping Galvanized:***	
Unit of Measure:	EA	***Tank Single Wall St:***	
Overfill Prot Type:	NULL	***Piping Underground:***	
Creation Date:	7/5/2009 1:20:09 AM	***Tank Underground:***	
Next Periodic Str DT:	NULL	***Source:***	FS Liquid Fuel Tank
TSSA Base Sched Cycle 2:	NULL		
TSSAMax Hazard Rank 1:	NULL		
TSSA Risk Based Periodic Yn:	NULL		
TSSA Volume of Directives:	NULL		
TSSA Periodic Exempt:	NULL		

TSSA Statutory Interval:	NULL
TSSA Recd Insp Interva:	NULL
TSSA Recd Tolerance:	NULL
TSSA Program Area:	NULL
TSSA Program Area 2:	NULL
Description:	UNDERGROUND TANK
Original Source:	EXP
Record Date:	31-JUL-2020

---

45 ***10 of 14*** ***SSW/117.6*** ***100.9 / 0.97*** ***PETRO CANADA CAR WASH ATTN GARY HACKMAN***
7 PLAINS RD W BURLINGTON L7T 1E8 ON CA
ON ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	10633550	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	NULL
Instance ID:		***Facility Location:***	7 PLAINS RD W BURLINGTON L7T 1E8 ON CA
Instance Type:		***Facility Type:***	FS LIQUID FUEL TANK
Instance Creation Dt:	5/14/1992	***Fuel Type 2:***	NULL
Instance Install Dt:	5/14/1992	***Fuel Type 3:***	NULL
Item Description:	FS Liquid Fuel Tank	***Panam Related:***	NULL
Manufacturer:	NULL	***Panam Venue Nm:***	NULL
Model:	NULL	***External Identifier:***	NULL
Serial No:	NULL	***Item:***	
ULC Standard:	NULL	***Piping Steel:***	
Quantity:	1	***Piping Galvanized:***	
Unit of Measure:	EA	***Tank Single Wall St:***	
Overfill Prot Type:	NULL	***Piping Underground:***	
Creation Date:	7/5/2009 1:20:11 AM	***Tank Underground:***	
Next Periodic Str DT:	NULL	***Source:***	FS Liquid Fuel Tank

TSSA Base Sched Cycle 2:	NULL
TSSAMax Hazard Rank 1:	NULL
TSSA Risk Based Periodic Yn:	NULL
TSSA Volume of Directives:	NULL
TSSA Periodic Exempt:	NULL
TSSA Statutory Interval:	NULL
TSSA Recd Insp Interva:	NULL
TSSA Recd Tolerance:	NULL
TSSA Program Area:	NULL
TSSA Program Area 2:	NULL
Description:	UNDERGROUND TANK
Original Source:	EXP
Record Date:	31-JUL-2020

---

45 ***11 of 14*** ***SSW/117.6*** ***100.9 / 0.97*** ***PETRO CANADA CAR WASH ATTN GARY HACKMAN***
7 PLAINS RD W BURLINGTON L7T 1E8 ON CA
ON ***FST***

Instance No:	10633625	***Manufacturer:***	
Status:		***Serial No:***	
Cont Name:		***Ulc Standard:***	
Instance Type:		***Quantity:***	
Item:		***Unit of Measure:***	
Item Description:	FS Liquid Fuel Tank	***Fuel Type:***	Gasoline
Tank Type:	Liquid Fuel Single Wall UST	***Fuel Type2:***	NULL
Install Date:	5/14/1992	***Fuel Type3:***	NULL
Install Year:	1981	***Piping Steel:***	

Years in Service: ***Piping Galvanized:***
Model: NULL ***Tanks Single Wall St:***
Description: ***Piping Underground:***
Capacity: 22700 ***No Underground:***
Tank Material: Fiberglass (FRP) ***Panam Related:***
Corrosion Protect: Fiberglass ***Panam Venue:***
Overfill Protect:
Facility Type: FS Liquid Fuel Tank
Parent Facility Type:
Facility Location:
Device Installed Location: 7 PLAINS RD W BURLINGTON L7T 1E8 ON CA

Liquid Fuel Tank Details

Overfill Protection:
Owner Account Name: PETRO CANADA CAR WASH ATTN GARY HACKMAN
Item: FS LIQUID FUEL TANK

---

45 ***12 of 14*** ***SSW/117.6*** ***100.9 / 0.97*** ***PETRO CANADA CAR WASH ATTN GARY HACKMAN*** ***FST***
7 PLAINS RD W BURLINGTON L7T 1E8 ON CA
ON

Instance No: 10633669 ***Manufacturer:***
Status: ***Serial No:***
Cont Name: ***Ulc Standard:***
Instance Type: ***Quantity:***
Item: ***Unit of Measure:***
Item Description: FS Liquid Fuel Tank ***Fuel Type:*** Gasoline
Tank Type: Liquid Fuel Single Wall UST ***Fuel Type2:*** NULL
Install Date: 10/2/1989 ***Fuel Type3:*** NULL
Install Year: 1977 ***Piping Steel:***
Years in Service: ***Piping Galvanized:***
Model: NULL ***Tanks Single Wall St:***
Description: ***Piping Underground:***
Capacity: 22700 ***No Underground:***
Tank Material: Steel ***Panam Related:***
Corrosion Protect: Impressed Current ***Panam Venue:***
Overfill Protect:
Facility Type: FS Liquid Fuel Tank
Parent Facility Type:
Facility Location:
Device Installed Location: 7 PLAINS RD W BURLINGTON L7T 1E8 ON CA

Liquid Fuel Tank Details

Overfill Protection:
Owner Account Name: PETRO CANADA CAR WASH ATTN GARY HACKMAN
Item: FS LIQUID FUEL TANK

---

45 ***13 of 14*** ***SSW/117.6*** ***100.9 / 0.97*** ***PETRO CANADA CAR WASH ATTN GARY HACKMAN*** ***FST***
7 PLAINS RD W BURLINGTON L7T 1E8 ON CA
ON

Instance No: 10633580 ***Manufacturer:***
Status: ***Serial No:***
Cont Name: ***Ulc Standard:***
Instance Type: ***Quantity:***
Item: ***Unit of Measure:***
Item Description: FS Liquid Fuel Tank ***Fuel Type:*** Gasoline
Tank Type: Liquid Fuel Single Wall UST ***Fuel Type2:*** NULL
Install Date: 5/14/1992 ***Fuel Type3:*** NULL

Install Year:	1981	***Piping Steel:***	
Years in Service:		***Piping Galvanized:***	
Model:	NULL	***Tanks Single Wall St:***	
Description:		***Piping Underground:***	
Capacity:	22700	***No Underground:***	
Tank Material:	Fiberglass (FRP)	***Panam Related:***	
Corrosion Protect:	Fiberglass	***Panam Venue:***	
Overfill Protect:			
Facility Type:	FS Liquid Fuel Tank		
Parent Facility Type:			
Facility Location:			
Device Installed Location:	7 PLAINS RD W BURLINGTON L7T 1E8 ON CA		

Liquid Fuel Tank Details

Overfill Protection:	
Owner Account Name:	PETRO CANADA CAR WASH ATTN GARY HACKMAN
Item:	FS LIQUID FUEL TANK

---

45 ***14 of 14*** ***SSW/117.6*** ***100.9 / 0.97*** ***PETRO CANADA CAR WASH ATTN GARY HACKMAN***
7 PLAINS RD W BURLINGTON L7T 1E8 ON CA ON ***FST***

Instance No:	10633550	***Manufacturer:***	
Status:		***Serial No:***	
Cont Name:		***Ulc Standard:***	
Instance Type:		***Quantity:***	
Item:		***Unit of Measure:***	
Item Description:	FS Liquid Fuel Tank	***Fuel Type:***	Gasoline
Tank Type:	Liquid Fuel Single Wall UST	***Fuel Type2:***	NULL
Install Date:	5/14/1992	***Fuel Type3:***	NULL
Install Year:	1981	***Piping Steel:***	
Years in Service:		***Piping Galvanized:***	
Model:	NULL	***Tanks Single Wall St:***	
Description:		***Piping Underground:***	
Capacity:	22700	***No Underground:***	
Tank Material:	Fiberglass (FRP)	***Panam Related:***	
Corrosion Protect:	Fiberglass	***Panam Venue:***	
Overfill Protect:			
Facility Type:	FS Liquid Fuel Tank		
Parent Facility Type:			
Facility Location:			
Device Installed Location:	7 PLAINS RD W BURLINGTON L7T 1E8 ON CA		

Liquid Fuel Tank Details

Overfill Protection:	
Owner Account Name:	PETRO CANADA CAR WASH ATTN GARY HACKMAN
Item:	FS LIQUID FUEL TANK

---

46 ***1 of 1*** ***S/119.4*** ***99.8 / -0.05*** ***15 PLAINS RD E***
Burlington ON ***WWIS***

Well ID:	7299235	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	16-Nov-2017 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z272927	***Contractor:***	7295
Tag:	A237129	***Form Version:***	7

Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/729\7299235.pdf

Additional Detail(s) (Map)

Well Completed Date:	2017/10/26
Year Completed:	2017
Depth (m):	10.668
Latitude:	43.3066685726269
Longitude:	-79.8524964884547
Path:	729\7299235.pdf

Bore Hole Information

Bore Hole ID:	1006797613	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	593065.00
Code OB Desc:		**North83:**	4795510.00
Open Hole:		**Org CS:**	dms83
Cluster Kind:		**UTMRC:**	5
Date Completed:	26-Oct-2017 00:00:00	**UTMRC Desc:**	margin of error : 100 m - 300 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1006989799
Layer:	2
Color:	7
General Color:	RED
Mat1:	28
Most Common Material:	SAND
Mat2:	
Mat2 Desc:	
Mat3:	91
Mat3 Desc:	WATER-BEARING
Formation Top Depth:	25.0
Formation End Depth:	35.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006989798
Layer:	1
Color:	7
General Color:	RED
Mat1:	28
Most Common Material:	SAND
Mat2:	
Mat2 Desc:	
Mat3:	91
Mat3 Desc:	WATER-BEARING
Formation Top Depth:	0.0
Formation End Depth:	25.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006989806
Layer:	1
Plug From:	0.0
Plug To:	23.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1006989805
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1006989797
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006989802
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	25.0
Casing Diameter:	1.7999999523162842
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1006989803
Layer:	1
Slot:	10
Screen Top Depth:	25.0
Screen End Depth:	35.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.0

Water Details

Water ID:	1006989801
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1006989800
Diameter:	10.0
Depth From:	0.0
Depth To:	35.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1006797613	***Tag No:***	A237129
Depth M:	10.668	***Contractor:***	7295
Year Completed:	2017	***Path:***	729\7299235.pdf
Well Completed Dt:	2017/10/26	***Latitude:***	43.3066685726269
Audit No:	Z272927	***Longitude:***	-79.8524964884547

---

47 ***1 of 1*** ***SSE/121.3*** ***100.4 / 0.50*** ***14 PLAINS RD E BURLINGTON ON*** ***WWIS***

Well ID:	7160240	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	11-Mar-2011 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z121198	***Contractor:***	6032
Tag:	A093912	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	HALTON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/716\7160240.pdf

Additional Detail(s) (Map)

Well Completed Date:	2011/01/12
Year Completed:	2011
Depth (m):	9.144
Latitude:	43.3067194967699
Longitude:	-79.8521872794307
Path:	716\7160240.pdf

Bore Hole Information

Bore Hole ID:	1003484664	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	593090.00
Code OB Desc:		***North83:***	4795516.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	3
Date Completed:	12-Jan-2011 00:00:00	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1003800674
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	11
Mat3 Desc:	GRAVEL
Formation Top Depth:	15.0
Formation End Depth:	25.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1003800673
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	01
Most Common Material:	FILL
Mat2:	
Mat2 Desc:	
Mat3:	79
Mat3 Desc:	PACKED
Formation Top Depth:	0.0
Formation End Depth:	15.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1003800675
Layer:	3
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	28

Mat2 Desc:	SAND
Mat3:	66
Mat3 Desc:	DENSE
Formation Top Depth:	25.0
Formation End Depth:	30.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003800684
Layer:	2
Plug From:	1.0
Plug To:	18.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003800683
Layer:	1
Plug From:	0.0
Plug To:	1.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1003800681
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1003800672
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1003800678
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1003800679
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft

Screen Diameter UOM: inch
Screen Diameter:

Water Details

Water ID: 1003800677
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1003800676
Diameter: 8.0
Depth From: 0.0
Depth To: 30.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID: 1003484664
Depth M: 9.144
Year Completed: 2011
Well Completed Dt: 2011/01/12
Audit No: Z121198
Tag No: A093912
Contractor: 6032
Path: 716\7160240.pdf
Latitude: 43.3067194967699
Longitude: -79.8521872794307

---

48 | ***1 of 1*** | ***ESE/125.4*** | ***100.5 / 0.64*** | ***40 Plains Rd E, Burlington ON L7T2B9*** | ***EHS***

Order No: 20130729043
Status: C
Report Type: Custom Report
Report Date: 08-AUG-13
Date Received: 29-JUL-13
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Title Searches; City Directory; Aerial Photos
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.850839
Y: 43.307597

---

49 | ***1 of 53*** | ***N/125.9*** | ***101.9 / 2.03*** | ***Etratech Inc., 1047 Cooke Blvd, Burlington ON L7T 4A8*** | ***SCT***

Established: 01-AUG-89
Plant Size (ft²): 46000
Employment:

--Details--
Description: Semiconductor and Other Electronic Component Manufacturing
SIC/NAICS Code: 334410

Description: Measuring, Medical and Controlling Devices Manufacturing
SIC/NAICS Code: 334512

---

49 | ***2 of 53*** | ***N/125.9*** | ***101.9 / 2.03*** | ***Etratech Designs Inc., 1047 COOKE BOULEVARD, BURLINGTON CITY*** | ***EBR***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

CITY OF BURLINGTON
ON

EBR Registry No:	IA7E1222	***Decision Posted:***	
Ministry Ref No:	8319496 19970813	***Exception Posted:***	
Notice Type:	Instrument Decision	***Section:***	
Notice Stage:		***Act 1:***	
Notice Date:	December 16, 1997	***Act 2:***	
Proposal Date:	August 22, 1997	***Site Location Map:***	
Year:	1997		
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)		
Off Instrument Name:			
Posted By:			
Company Name:	Etratech Designs Inc.		
Site Address:			
Location Other:			
Proponent Name:			
Proponent Address:	1074 Cooke Boulevard, Burlington Ontario, L7T 4A8		
Comment Period:			
URL:			

Site Location Details:

1047 COOKE BOULEVARD, BURLINGTON CITY CITY OF BURLINGTON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
49	3 of 53	N/125.9	101.9 / 2.03	***ETRATECH INC*** ***1047 COOKE BOULEVARD NOT AVAILABLE*** ***BURLINGTON ON L7T4A8***	***NPRI***

NPRI ID:	7161	***Org ID:***	12250
Other ID:	*	***Submit Date:***	7/11/2002
No Other ID:	0.00	***Last Modified:***	5/29/2015 3:28:24 PM
Track ID:	18143	***Contact ID:***	230618
Report ID:		***Cont Type:***	MED
Report Type:	NPRI	***Contact Title:***	
Rpt Type ID:	1	***Cont First Name:***	
Report Year:	2001	***Cont Last Name:***	
Not-Current Rpt?:	No	***Contact Position:***	
Yr of Last Filed Rpt:	2014	***Contact Fax:***	
Fac ID:	139661	***Contact Ph.:***	
Fac Name:	NOT AVAILABLE	***Cont Area Code:***	
Fac Address1:	1047 COOKE BOULEVARD	***Contact Tel.:***	
Fac Address2:	NOT AVAILABLE	***Contact Ext.:***	
Fac Postal Zip:	L7T4A8	***Cont Fax Area Cde:***	
Facility Lat:	43.3094	***Contact Fax:***	
Facility Long:	-79.8528	***Contact Email:***	
DLS (Last Filed Rpt):		***Latitude:***	43.3094
Facility DLS:		***Longitude:***	-79.8528
Datum:	1983	***UTM Zone:***	
Facility Cmnts:	No	***UTM Northing:***	
URL:		***UTM Easting:***	
No of Empl.:	95	***Waste Streams:***	No
Parent Co.:	*	***No Streams:***	0.00
No Parent Co.:	1.00	***Waste Off Sites:***	Yes
Pollut Prev Cmnts:	No	***No Off Sites:***	1.00
Stacks:		***Shutdown:***	
No of Stacks:		***No of Shutdown:***	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		

NAICS Code (4 digit): 3359
NAICS 4 Description: Other electrical equipment and component manufacturing
NAICS Code (6 digit): 335930
NAICS 6 Description: Wiring device manufacturing

Substance Release Report

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Lead (and its compounds)
Chem (fr): Plomb (et ses composés)
Quantity: 0
Unit: tonnes
Basis of Estimate Cd: M
Basis of Estimate Desc: M- Monitoring or Direct Measurement - In use from 1994 to 2002

---

49 | **4 of 53** | **N/125.9** | **101.9 / 2.03** | **Etratech Printed Circuit Boards Inc.**
1047 Cooke Boulevard Burlington Ontario
Burlington
ON | **EBR**

EBR Registry No: IA03E0521
Ministry Ref No: 5755-5L9S2H
Notice Type: Instrument Decision
Notice Stage:
Notice Date: August 07, 2003
Proposal Date: April 16, 2003
Year: 2003
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Etratech Printed Circuit Boards Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 1047 Cooke Boulevard, Burlington Ontario, L7T 4A8
Comment Period:
URL:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

1047 Cooke Boulevard Burlington Ontario Burlington

---

49 | **5 of 53** | **N/125.9** | **101.9 / 2.03** | **1047 Cooke Blvd**
Burlington ON L7T 4A8 | **EHS**

Order No: 20031007004
Status: C
Report Type: Basic Report
Report Date: 10/17/03
Date Received: 10/7/03
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans and/or Inspection Reports

Nearest Intersection:
Municipality: Halton
Client Prov/State: ON
Search Radius (km): 0.35
X: -79.853395
Y: 43.309429

---

49 | **6 of 53** | **N/125.9** | **101.9 / 2.03** | **ETRATECH MANUFACTURING INC.** | **GEN**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				1047 COOKE BOULEVARD BURLINGTON ON L7T 4A8	

Generator No: ON1622303
SIC Code: 3352
SIC Description: ELECT. PARTS & COMP.
Approval Years: 97,98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

49	***7 of 53***	***N/125.9***	***101.9 / 2.03***	***ETRATECH MANUFACTURING INC. 1047 Cooke Boulevard Burlington ON L7T 4A8***	***GEN***

Generator No: ON1622301
SIC Code:
SIC Description:
Approval Years: 02,03,04,05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

49 | **8 of 53** | **N/125.9** | **101.9 / 2.03** | **ETRATECH INC.**
1047 COOKE BOULEVARD NOT AVAILABLE
BURLINGTON ON L7T4A8 | **NPRI**

NPRI ID:	7161	**Org ID:**	47638
Other ID:	*	**Submit Date:**	10/15/2003
No Other ID:	0	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	19971	**Contact ID:**	177651
Report ID:	163223	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	LAURA
Report Year:	2002	**Cont Last Name:**	SMERILLI
Not-Current Rpt?:	No	**Contact Position:**	HUMAN RESOURCES MANAGER
Yr of Last Filed Rpt:	2014	**Contact Fax:**	9056817601
Fac ID:	139661	**Contact Ph.:**	9056817544
Fac Name:	NOT AVAILABLE	**Cont Area Code:**	905
Fac Address1:	1047 COOKE BOULEVARD	**Contact Tel.:**	56817544
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	245
Fac Postal Zip:	L7T4A8	**Cont Fax Area Cde:**	905
Facility Lat:	43.3094	**Contact Fax:**	56817601
Facility Long:	-79.8528	**Contact Email:**	NOT AVAILABLE
DLS (Last Filed Rpt):		**Latitude:**	43.3094
Facility DLS:		**Longitude:**	-79.8528
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	95	**Waste Streams:**	False
Parent Co.:	*	**No Streams:**	0
No Parent Co.:	1	**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	False	**No Off Sites:**	1
Stacks:	False	**Shutdown:**	False
No of Stacks:		**No of Shutdown:**	0

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 33
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3359
NAICS 4 Description: Other electrical equipment and component manufacturing
NAICS Code (6 digit): 335930
NAICS 6 Description: Wiring device manufacturing

Substance Release Report

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Lead (and its compounds)
Chem (fr): Plomb (et ses composés)
Quantity: .113
Unit: kg

Basis of Estimate Cd:
Basis of Estimate Desc:

---

49 | ***9 of 53*** | ***N/125.9*** | ***101.9 / 2.03*** | ***ETRATECH INC.*** | ***NPRI***

1047 COOKE BOULEVARD NOT AVAILABLE
BURLINGTON ON L7T4A8

NPRI ID:	7161	***Org ID:***	102208
Other ID:	*	***Submit Date:***	5/12/2004
No Other ID:		***Last Modified:***	5/29/2015 3:28:24 PM
Track ID:	74662	***Contact ID:***	127800
Report ID:	154838	***Cont Type:***	MED
Report Type:	NPRI	***Contact Title:***	
Rpt Type ID:	1	***Cont First Name:***	CAROL
Report Year:	2003	***Cont Last Name:***	DESNOYERS
Not-Current Rpt?:	No	***Contact Position:***	CORPORATE SERVICES MANAGER
Yr of Last Filed Rpt:	2014	***Contact Fax:***	9056817601
Fac ID:	139661	***Contact Ph.:***	9056817544
Fac Name:	NOT AVAILABLE	***Cont Area Code:***	905
Fac Address1:	1047 COOKE BOULEVARD	***Contact Tel.:***	56817544
Fac Address2:	NOT AVAILABLE	***Contact Ext.:***	
Fac Postal Zip:	L7T4A8	***Cont Fax Area Cde:***	905
Facility Lat:	43.3094	***Contact Fax:***	56817601
Facility Long:	-79.8528	***Contact Email:***	NOT AVAILABLE
DLS (Last Filed Rpt):		***Latitude:***	43.3094
Facility DLS:		***Longitude:***	-79.8528
Datum:	1983	***UTM Zone:***	
Facility Cmnts:	False	***UTM Northing:***	
URL:		***UTM Easting:***	
No of Empl.:	95	***Waste Streams:***	True¿
Parent Co.:	*	***No Streams:***	
No Parent Co.:	1	***Waste Off Sites:***	Fals
Pollut Prev Cmnts:	False	***No Off Sites:***	1
Stacks:	True	***Shutdown:***	True
No of Stacks:		***No of Shutdown:***	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 33
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3359
NAICS 4 Description: Other electrical equipment and component manufacturing
NAICS Code (6 digit): 335930
NAICS 6 Description: Wiring device manufacturing

Substance Release Report

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Lead (and its compounds)
Chem (fr): Plomb (et ses composés)
Quantity: .113
Unit: kg
Basis of Estimate Cd:
Basis of Estimate Desc:

---

49 | ***10 of 53*** | ***N/125.9*** | ***101.9 / 2.03*** | ***ETRATECH*** | ***NPRI***

1047 COOKE BOULEVARD NOT AVAILABLE
BURLINGTON ON L7T4A8

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

NPRI ID:	7161	**Org ID:**	47637
Other ID:	*	**Submit Date:**	5/9/2005
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	25143	**Contact ID:**	127807
Report ID:	84694	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	CAROL
Report Year:	2004	**Cont Last Name:**	DESNOYERS
Not-Current Rpt?:	No	**Contact Position:**	DIRECTOR HUMAN RESOURCES
Yr of Last Filed Rpt:	2014	**Contact Fax:**	9056817601
Fac ID:	223627	**Contact Ph.:**	9056817544
Fac Name:	ETRATECH INC.	**Cont Area Code:**	905
Fac Address1:	1047 COOKE BOULEVARD	**Contact Tel.:**	56817544
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	301
Fac Postal Zip:	L7T4A8	**Cont Fax Area Cde:**	905
Facility Lat:	43.3094	**Contact Fax:**	56817601
Facility Long:	-79.8528	**Contact Email:**	NOT AVAILABLE
DLS (Last Filed Rpt):		**Latitude:**	43.3094
Facility DLS:		**Longitude:**	-79.8528
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	True	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	143	**Waste Streams:**	False
Parent Co.:	N	**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	True	**No Off Sites:**	2
Stacks:	No	**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3359		
NAICS 4 Description:	Other electrical equipment and component manufacturing		
NAICS Code (6 digit):	335930		
NAICS 6 Description:	Wiring device manufacturing		

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Lead (and its compounds)
Chem (fr):	Plomb (et ses composés)
Quantity:	.113
Unit:	kg
Basis of Estimate Cd:	
Basis of Estimate Desc:	

---

49 | ***11 of 53*** | ***N/125.9*** | ***101.9 / 2.03*** | ***ETRATECH***
1047 COOKE BOULEVARD NOT AVAILABLE
BURLINGTON ON L7T4A8 | ***NPRI***

NPRI ID:	7161	**Org ID:**	47637
Other ID:	*	**Submit Date:**	5/18/2006
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	34603	**Contact ID:**	127807
Report ID:	96823	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Rpt Type ID:	1	**Cont First Name:**	CAROL
Report Year:	2005	**Cont Last Name:**	DESNOYERS
Not-Current Rpt?:	No	**Contact Position:**	DIRECTOR HUMAN RESOURCES
Yr of Last Filed Rpt:	2014	**Contact Fax:**	9056817601
Fac ID:	223627	**Contact Ph.:**	9056817544
Fac Name:	ETRATECH INC.	**Cont Area Code:**	905
Fac Address1:	1047 COOKE BOULEVARD	**Contact Tel.:**	56817544
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	301
Fac Postal Zip:	L7T4A8	**Cont Fax Area Cde:**	905
Facility Lat:	43.3094	**Contact Fax:**	56817601
Facility Long:	-79.8528	**Contact Email:**	NOT AVAILABLE
DLS (Last Filed Rpt):		**Latitude:**	43.3094
Facility DLS:		**Longitude:**	-79.8528
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	163	**Waste Streams:**	False
Parent Co.:	N	**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	False	**No Off Sites:**	2.00
Stacks:	False	**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3359		
NAICS 4 Description:	Other electrical equipment and component manufacturing		
NAICS Code (6 digit):	335930		
NAICS 6 Description:	Wiring device manufacturing		

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Lead (and its compounds)
Chem (fr):	Plomb (et ses composés)
Quantity:	.113
Unit:	kg
Basis of Estimate Cd:	
Basis of Estimate Desc:	

---

49 | ***12 of 53*** | ***N/125.9*** | ***101.9 / 2.03*** | ***ETRATECH***
1047 COOKE BOULEVARD NOT AVAILABLE
BURLINGTON ON L7T4A8 | ***NPRI***

NPRI ID:	7161	**Org ID:**	47637
Other ID:	*	**Submit Date:**	5/23/2007
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	43983	**Contact ID:**	127807
Report ID:	106571	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	CAROL
Report Year:	2006	**Cont Last Name:**	DESNOYERS
Not-Current Rpt?:	No	**Contact Position:**	DIRECTOR HUMAN RESOURCES
Yr of Last Filed Rpt:	2014	**Contact Fax:**	9056817601
Fac ID:	223627	**Contact Ph.:**	9056817544
Fac Name:	ETRATECH INC.	**Cont Area Code:**	905
Fac Address1:	1047 COOKE BOULEVARD	**Contact Tel.:**	56817544

Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	301
Fac Postal Zip:	L7T4A8	**Cont Fax Area Cde:**	905
Facility Lat:	43.3094	**Contact Fax:**	56817601
Facility Long:	-79.8528	**Contact Email:**	NOT AVAILABLE
DLS (Last Filed Rpt):		**Latitude:**	43.3094
Facility DLS:		**Longitude:**	-79.8528
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	163	**Waste Streams:**	True¿
Parent Co.:	N	**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	False	**No Off Sites:**	3.00
Stacks:	True	**Shutdown:**	
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 33
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3359
NAICS 4 Description: Other electrical equipment and component manufacturing
NAICS Code (6 digit): 335930
NAICS 6 Description: Wiring device manufacturing

Substance Release Report

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Lead (and its compounds)
Chem (fr): Plomb (et ses composés)
Quantity: .17
Unit: kg
Basis of Estimate Cd:
Basis of Estimate Desc:

---

49 | **13 of 53** | **N/125.9** | **101.9 / 2.03** | **Etratech Printed Circuit Boards Inc.**
1047 Cooke Boulevard Burlington Ontario
Burlington
ON | **EBR**

EBR Registry No:	IA05E0782	**Decision Posted:**	
Ministry Ref No:	6132-6BSQ6K	**Exception Posted:**	
Notice Type:	Instrument Decision	**Section:**	
Notice Stage:		**Act 1:**	
Notice Date:	June 06, 2006	**Act 2:**	
Proposal Date:	May 11, 2005	**Site Location Map:**	
Year:	2005		

Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Etratech Printed Circuit Boards Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 1047 Cooke Boulevard, Burlington Ontario, L7T 4A8
Comment Period:
URL:

Site Location Details:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

1047 Cooke Boulevard Burlington Ontario Burlington

---

49 | **14 of 53** | **N/125.9** | **101.9 / 2.03** | **Etratech Printed Circuit Boards Inc.**
1047 Cooke Boulevard Burlington Ontario
Burlington
ON | **EBR**

EBR Registry No:	IA06E0944	**Decision Posted:**	
Ministry Ref No:	1844-6RKQ49	**Exception Posted:**	
Notice Type:	Instrument Decision	**Section:**	
Notice Stage:		**Act 1:**	
Notice Date:	April 02, 2007	**Act 2:**	
Proposal Date:	July 26, 2006	**Site Location Map:**	
Year:	2006		
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)		
Off Instrument Name:			
Posted By:			
Company Name:	Etratech Printed Circuit Boards Inc.		
Site Address:			
Location Other:			
Proponent Name:			
Proponent Address:	1047 Cooke Boulevard, Burlington Ontario, L7T 4A8		
Comment Period:			
URL:			

Site Location Details:

1047 Cooke Boulevard Burlington Ontario Burlington

---

49 | **15 of 53** | **N/125.9** | **101.9 / 2.03** | **Etratech Printed Circuit Boards Inc.**
1047 Cooke Boulevard Burlington Regional
Municipality of Halton CITY OF BURLINGTON
ON | **EBR**

EBR Registry No:	010-2249	**Decision Posted:**	
Ministry Ref No:	1766-78FJ4Z	**Exception Posted:**	
Notice Type:	Instrument Decision	**Section:**	
Notice Stage:		**Act 1:**	
Notice Date:	July 20, 2009	**Act 2:**	
Proposal Date:	December 05, 2007	**Site Location Map:**	
Year:	2007		
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)		
Off Instrument Name:			
Posted By:			
Company Name:	Etratech Printed Circuit Boards Inc.		
Site Address:			
Location Other:			
Proponent Name:			
Proponent Address:	1047 Cooke boulevard, Burlington Ontario, Canada L7T 4A8		
Comment Period:			
URL:			

Site Location Details:

1047 Cooke Boulevard Burlington Regional Municipality of Halton CITY OF BURLINGTON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
49	16 of 53	N/125.9	101.9 / 2.03	ETRATECH 1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	NPRI

NPRI ID:	7161	**Org ID:**	47637
Other ID:	*	**Submit Date:**	4/4/2008
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	52027	**Contact ID:**	127807
Report ID:	113015	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	CAROL
Report Year:	2007	**Cont Last Name:**	DESNOYERS
Not-Current Rpt?:	No	**Contact Position:**	DIRECTOR HUMAN RESOURCES
Yr of Last Filed Rpt:	2014	**Contact Fax:**	9056817601
Fac ID:	223627	**Contact Ph.:**	9056817544
Fac Name:	ETRATECH INC.	**Cont Area Code:**	905
Fac Address1:	1047 COOKE BOULEVARD	**Contact Tel.:**	56817544
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	301
Fac Postal Zip:	L7T4A8	**Cont Fax Area Cde:**	905
Facility Lat:	43.3094	**Contact Fax:**	56817601
Facility Long:	-79.8528	**Contact Email:**	NOT AVAILABLE
DLS (Last Filed Rpt):		**Latitude:**	43.3094
Facility DLS:		**Longitude:**	-79.8528
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	148	**Waste Streams:**	True¿
Parent Co.:	N	**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	True
Pollut Prev Cmnts:	False	**No Off Sites:**	2.00
Stacks:	True	**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3359		
NAICS 4 Description:	Other electrical equipment and component manufacturing		
NAICS Code (6 digit):	335930		
NAICS 6 Description:	Wiring device manufacturing		

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Lead (and its compounds)
Chem (fr):	Plomb (et ses composés)
Quantity:	.25
Unit:	kg
Basis of Estimate Cd:	
Basis of Estimate Desc:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
49	17 of 53	N/125.9	101.9 / 2.03	ETRATECH 1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	NPRI

NPRI ID:	7161	**Org ID:**	47637
Other ID:	*	**Submit Date:**	6/2/2009
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Track ID:	71067	**Contact ID:**	127807
Report ID:	131809	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	CAROL
Report Year:	2008	**Cont Last Name:**	DESNOYERS
Not-Current Rpt?:	No	**Contact Position:**	DIRECTOR HUMAN RESOURCES
Yr of Last Filed Rpt:	2014	**Contact Fax:**	9056817601
Fac ID:	223627	**Contact Ph.:**	9056817544
Fac Name:	ETRATECH INC.	**Cont Area Code:**	905
Fac Address1:	1047 COOKE BOULEVARD	**Contact Tel.:**	56817544
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	301
Fac Postal Zip:	L7T4A8	**Cont Fax Area Cde:**	905
Facility Lat:	43.3094	**Contact Fax:**	56817601
Facility Long:	-79.8528	**Contact Email:**	NOT AVAILABLE
DLS (Last Filed Rpt):		**Latitude:**	43.3094
Facility DLS:		**Longitude:**	-79.8528
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	No	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	136	**Waste Streams:**	No
Parent Co.:	N	**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	Yes
Pollut Prev Cmnts:	No	**No Off Sites:**	2
Stacks:	No	**Shutdown:**	No
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3359		
NAICS 4 Description:	Other electrical equipment and component manufacturing		
NAICS Code (6 digit):	335930		
NAICS 6 Description:	Wiring device manufacturing		

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Lead (and its compounds)
Chem (fr):	Plomb (et ses composés)
Quantity:	.21
Unit:	kg
Basis of Estimate Cd:	
Basis of Estimate Desc:	

---

49 | ***18 of 53*** | ***N/125.9*** | ***101.9 / 2.03*** | ***Etratech Printed Circuit Boards Inc.***
1047 Cooke Boulevard
Burlington ON | ***CA***

Certificate #:	0119-5MYJCZ
Application Year:	2003
Issue Date:	7/31/2003
Approval Type:	Air
Status:	Revoked and/or Replaced
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Project Description:					
Contaminants:					
Emission Control:					

49	19 of 53	N/125.9	101.9 / 2.03	**Etratech Inc.** **1047 Cooke Blvd** **Burlington ON**	CA

Certificate #:	1361-7R5P5X
Application Year:	2009
Issue Date:	7/14/2009
Approval Type:	Air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

49	20 of 53	N/125.9	101.9 / 2.03	**Etratech Printed Circuit Boards Inc.** **1047 Cooke Boulevard** **Burlington ON**	CA

Certificate #:	3526-6QCJDJ
Application Year:	2006
Issue Date:	6/5/2006
Approval Type:	Air
Status:	Revoked and/or Replaced
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

49	21 of 53	N/125.9	101.9 / 2.03	**Etratech Printed Circuit Boards Inc.** **1047 Cooke Boulevard** **Burlington ON**	CA

Certificate #:	6640-6XPJ8Z
Application Year:	2007
Issue Date:	3/10/2007
Approval Type:	Air
Status:	Revoked and/or Replaced
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
49	22 of 53	N/125.9	101.9 / 2.03	ETRATECH 1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	NPRI

NPRI ID:	7161	**Org ID:**	47637
Other ID:	*	**Submit Date:**	3/15/2010
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	82166	**Contact ID:**	127807
Report ID:	135965	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	CAROL
Report Year:	2009	**Cont Last Name:**	DESNOYERS
Not-Current Rpt?:	No	**Contact Position:**	DIRECTOR HUMAN RESOURCES
Yr of Last Filed Rpt:	2014	**Contact Fax:**	9056817601
Fac ID:	223627	**Contact Ph.:**	9056817544
Fac Name:	ETRATECH INC.	**Cont Area Code:**	905
Fac Address1:	1047 COOKE BOULEVARD	**Contact Tel.:**	56817544
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	301
Fac Postal Zip:	L7T4A8	**Cont Fax Area Cde:**	905
Facility Lat:	43.3094	**Contact Fax:**	56817601
Facility Long:	-79.8528	**Contact Email:**	NOT AVAILABLE
DLS (Last Filed Rpt):		**Latitude:**	43.3094
Facility DLS:		**Longitude:**	-79.8528
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	No	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	106	**Waste Streams:**	No
Parent Co.:	N	**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	Yes
Pollut Prev Cmnts:	No	**No Off Sites:**	2
Stacks:	No	**Shutdown:**	No
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3359		
NAICS 4 Description:	Other electrical equipment and component manufacturing		
NAICS Code (6 digit):	335930		
NAICS 6 Description:	Wiring device manufacturing		

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Lead (and its compounds)
Chem (fr):	Plomb (et ses composés)
Quantity:	.21
Unit:	kg
Basis of Estimate Cd:	
Basis of Estimate Desc:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
49	23 of 53	N/125.9	101.9 / 2.03	ETRATECH INC. 1047 COOKE BOULEVARD NOT AVAILABLE BURLINGTON ON L7T4A8	NPRI

NPRI ID:	7161	**Org ID:**	102208
Other ID:	Y	**Submit Date:**	6/7/2011
No Other ID:	1	**Last Modified:**	5/29/2015 3:28:24 PM

Track ID:	91219	**Contact ID:**	127807
Report ID:	145277	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	CAROL
Report Year:	2010	**Cont Last Name:**	DESNOYERS
Not-Current Rpt?:	No	**Contact Position:**	DIRECTOR HUMAN RESOURCES
Yr of Last Filed Rpt:	2014	**Contact Fax:**	9056817601
Fac ID:	223627	**Contact Ph.:**	9056817544
Fac Name:	ETRATECH INC.	**Cont Area Code:**	905
Fac Address1:	1047 COOKE BOULEVARD	**Contact Tel.:**	56817544
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	301
Fac Postal Zip:	L7T4A8	**Cont Fax Area Cde:**	905
Facility Lat:	43.3094	**Contact Fax:**	56817601
Facility Long:	-79.8528	**Contact Email:**	NOT AVAILABLE
DLS (Last Filed Rpt):		**Latitude:**	43.3094
Facility DLS:		**Longitude:**	-79.8528
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	No	**UTM Northing:**	
URL:	etratech.com	**UTM Easting:**	
No of Empl.:	123	**Waste Streams:**	No
Parent Co.:	*	**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	Yes
Pollut Prev Cmnts:	No	**No Off Sites:**	2
Stacks:	No	**Shutdown:**	No
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 33
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3359
NAICS 4 Description: Other electrical equipment and component manufacturing
NAICS Code (6 digit): 335930
NAICS 6 Description: Wiring device manufacturing

Substance Release Report

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Lead (and its compounds)
Chem (fr): Plomb (et ses composés)
Quantity: .18
Unit: kg
Basis of Estimate Cd:
Basis of Estimate Desc:

49	24 of 53	N/125.9	101.9 / 2.03	***ETRATECH MANUFACTURING INC.*** ***1047 Cooke Boulevard*** ***Burlington ON L7T 4A8***	***GEN***

Generator No: ON1622301
SIC Code: 334410
SIC Description: Semiconductor and Other Electronic Component Manufacturing
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

49 | ***25 of 53*** | ***N/125.9*** | ***101.9 / 2.03*** | ***1500118 ONTARIO INC.***
1047 COOKE BLVD.
BURLINGTON ON L7T 4A8 | ***EASR***

Approval No: R-003-9341213792
Status: REGISTERED
Date: 2013-05-29
Record Type: EASR
Link Source: MOFA
Project Type: Heating System
Full Address:
Approval Type: EASR-Heating System
SWP Area Name: Halton
PDF URL:
PDF Site Location:

MOE District: Halton-Peel
Municipality: BURLINGTON
Latitude: 43.309475
Longitude: -79.852936
Geometry X:
Geometry Y:

---

49 | ***26 of 53*** | ***N/125.9*** | ***101.9 / 2.03*** | ***ETRATECH INC.***
1047 COOKE BOULEVARD NOT AVAILABLE
BURLINGTON ON L7T4A8 | ***NPRI***

NPRI ID: 7161
Other ID:
No Other ID:
Track ID: 123055
Report ID: 41394
Report Type: NPRI
Rpt Type ID: 1
Report Year: 2011
Not-Current Rpt?: No
Yr of Last Filed Rpt: 2014
Fac ID: 223627
Fac Name: ETRATECH INC.
Fac Address1: 1047 COOKE BOULEVARD
Fac Address2: NOT AVAILABLE
Fac Postal Zip: L7T4A8
Facility Lat: 43.3094
Facility Long: -79.8528
DLS (Last Filed Rpt):
Facility DLS:
Datum: 1983
Facility Cmnts:
URL: etratech.com
No of Empl.: 150
Parent Co.:
No Parent Co.:
Pollut Prev Cmnts:
Stacks:
No of Stacks:

Org ID: 102208
Submit Date: 6/13/2014
Last Modified: 5/29/2015 3:28:24 PM
Contact ID: 230618
Cont Type: MED
Contact Title:
Cont First Name:
Cont Last Name:
Contact Position:
Contact Fax:
Contact Ph.:
Cont Area Code:
Contact Tel.:
Contact Ext.:
Cont Fax Area Cde:
Contact Fax:
Contact Email:
Latitude: 43.3094
Longitude: -79.8528
UTM Zone:
UTM Northing:
UTM Easting:
Waste Streams:
No Streams:
Waste Off Sites:
No Off Sites:
Shutdown:
No of Shutdown:

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 33
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3359
NAICS 4 Description: Other electrical equipment and component manufacturing
NAICS Code (6 digit): 335930
NAICS 6 Description: Wiring device manufacturing

Substance Release Report

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Lead (and its compounds)
Chem (fr): Plomb (et ses composés)
Quantity: .18
Unit: kg
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

---

49 | ***27 of 53*** | ***N/125.9*** | ***101.9 / 2.03*** | ***ETRATECH MANUFACTURING INC.***
1047 Cooke Boulevard
Burlington ON L7T 4A8 | ***GEN***

Generator No: ON1622301
SIC Code: 334410
SIC Description: Semiconductor and Other Electronic Component Manufacturing
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

49 | ***28 of 53*** | ***N/125.9*** | ***101.9 / 2.03*** | ***ETRATECH MANUFACTURING INC.***
1047 Cooke Boulevard
Burlington ON L7T 4A8 | ***GEN***

Generator No: ON1622301
SIC Code: 334410
SIC Description: Semiconductor and Other Electronic Component Manufacturing
Approval Years: 2011
PO Box No:
Country:

Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

---

49 | ***29 of 53*** | ***N/125.9*** | ***101.9 / 2.03*** | ***Etratech Inc.***
1047 Cooke Boulevard Burlington, Regional Municipality of Halton CITY OF BURLINGTON ON | ***EBR***

EBR Registry No: 011-9503
Ministry Ref No: 1835-987RSV
Notice Type: Instrument Decision
Notice Stage:
Notice Date: March 27, 2017
Proposal Date: July 04, 2013
Year: 2013
Instrument Type: (EPA Part II.1-air) - Environmental Compliance Approval (project type: air)
Off Instrument Name:
Posted By:
Company Name: Etratech Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 1047 Cooke boulevard, Burlington Ontario, Canada L7T 4A8
Comment Period:
URL:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

1047 Cooke Boulevard Burlington, Regional Municipality of Halton CITY OF BURLINGTON

---

49 | ***30 of 53*** | ***N/125.9*** | ***101.9 / 2.03*** | ***ETRATECH MANUFACTURING INC.***
1047 Cooke Boulevard
Burlington ON L7T 4A8 | ***GEN***

Generator No: ON1622301
SIC Code: 334410
SIC Description: Semiconductor and Other Electronic Component Manufacturing
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

---

49 | ***31 of 53*** | ***N/125.9*** | ***101.9 / 2.03*** | ***ETRATECH INC.***
1047 COOKE BOULEVARD NOT AVAILABLE
BURLINGTON ON L7T4A8 | ***NPRI***

NPRI ID:	7161	***Org ID:***	102208
Other ID:		***Submit Date:***	10/15/2014
No Other ID:		***Last Modified:***	5/29/2015 3:28:24 PM
Track ID:	124632	***Contact ID:***	230618
Report ID:	41775	***Cont Type:***	MEM
Report Type:	NPRI	***Contact Title:***	
Rpt Type ID:	1	***Cont First Name:***	
Report Year:	2012	***Cont Last Name:***	
Not-Current Rpt?:	No	***Contact Position:***	
Yr of Last Filed Rpt:	2014	***Contact Fax:***	
Fac ID:	223627	***Contact Ph.:***	
Fac Name:	ETRATECH INC.	***Cont Area Code:***	
Fac Address1:	1047 COOKE BOULEVARD	***Contact Tel.:***	
Fac Address2:	NOT AVAILABLE	***Contact Ext.:***	
Fac Postal Zip:	L7T4A8	***Cont Fax Area Cde:***	
Facility Lat:	43.3094	***Contact Fax:***	
Facility Long:	-79.8528	***Contact Email:***	
DLS (Last Filed Rpt):		***Latitude:***	43.3094
Facility DLS:		***Longitude:***	-79.8528
Datum:	1983	***UTM Zone:***	
Facility Cmnts:		***UTM Northing:***	
URL:	etratech.com	***UTM Easting:***	
No of Empl.:	107	***Waste Streams:***	
Parent Co.:		***No Streams:***	
No Parent Co.:		***Waste Off Sites:***	
Pollut Prev Cmnts:		***No Off Sites:***	
Stacks:		***Shutdown:***	
No of Stacks:		***No of Shutdown:***	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3359		
NAICS 4 Description:	Other electrical equipment and component manufacturing		
NAICS Code (6 digit):	335930		
NAICS 6 Description:	Wiring device manufacturing		

Substance Release Report

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Lead (and its compounds)

Chem (fr): Plomb (et ses composés)
Quantity: .18
Unit: kg
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

---

49 | **32 of 53** | **N/125.9** | **101.9 / 2.03** | **1047 Cooke Blvd, Burlington ON L7T4A8** | **EHS**

Order No: 20140624044
Status: C
Report Type: Standard Report
Report Date: 04-JUL-14
Date Received: 24-JUN-14
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.852975
Y: 43.309428

---

49 | **33 of 53** | **N/125.9** | **101.9 / 2.03** | **ETRATECH MANUFACTURING INC., 1047 Cooke Boulevard, Burlington ON** | **GEN**

Generator No: ON1622301
SIC Code: 334410
SIC Description: SEMICONDUCTOR AND OTHER ELECTRONIC COMPONENT MANUFACTURING
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

49 | **34 of 53** | **N/125.9** | **101.9 / 2.03** | **ETRATECH INC., 1047 COOKE BOULEVARD NOT AVAILABLE, BURLINGTON ON L7T4A8** | **NPRI**

NPRI ID: 7161
Other ID:
No Other ID:
Track ID: 124629
Report ID: 41396
Report Type: NPRI
Rpt Type ID: 1
Report Year: 2013
Not-Current Rpt?: No
Yr of Last Filed Rpt: 2014
Fac ID: 223627
Fac Name: ETRATECH INC.

Org ID: 102208
Submit Date: 10/15/2014
Last Modified: 5/29/2015 3:28:24 PM
Contact ID: 230618
Cont Type: MEM
Contact Title:
Cont First Name:
Cont Last Name:
Contact Position:
Contact Fax:
Contact Ph.:
Cont Area Code:

Fac Address1:	1047 COOKE BOULEVARD	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	L7T4A8	**Cont Fax Area Cde:**	
Facility Lat:	43.3094	**Contact Fax:**	
Facility Long:	-79.8528	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.3094
Facility DLS:		**Longitude:**	-79.8528
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:	etratech.com	**UTM Easting:**	
No of Empl.:	126	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3359		
NAICS 4 Description:	Other electrical equipment and component manufacturing		
NAICS Code (6 digit):	335930		
NAICS 6 Description:	Wiring device manufacturing		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Lead (and its compounds)
Chem (fr):	Plomb (et ses composés)
Quantity:	.18
Unit:	kg
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

49 | **35 of 53** | **N/125.9** | **101.9 / 2.03** | ***ETRATECH INC.***
1047 COOKE BOULEVARD NOT AVAILABLE
BURLINGTON ON L7T4A8 | ***NPRI***

NPRI ID:	7161	**Org ID:**	102208
Other ID:		**Submit Date:**	5/21/2015
No Other ID:		**Last Modified:**	6/10/2015 10:59:04 AM
Track ID:	126367	**Contact ID:**	230618
Report ID:	48386	**Cont Type:**	MEM
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	2014	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2014	**Contact Fax:**	
Fac ID:	223627	**Contact Ph.:**	
Fac Name:	ETRATECH INC.	**Cont Area Code:**	
Fac Address1:	1047 COOKE BOULEVARD	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	L7T4A8	**Cont Fax Area Cde:**	
Facility Lat:	43.3094	**Contact Fax:**	
Facility Long:	-79.8528	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.3094
Facility DLS:		**Longitude:**	-79.8528

Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:	etratech.com	**UTM Easting:**	
No of Empl.:	140	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 33
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3359
NAICS 4 Description: Other electrical equipment and component manufacturing
NAICS Code (6 digit): 335930
NAICS 6 Description: Wiring device manufacturing

Substance Release Report

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Lead (and its compounds)
Chem (fr): Plomb (et ses composés)
Quantity: .18
Unit: kg
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

---

49 | ***36 of 53*** | ***N/125.9*** | ***101.9 / 2.03*** | ***Etratech Inc.***
1047 Cooke Blvd
Burlington ON | ***ECA***

Approval No:	0441-A4RS6Q	**MOE District:**	Halton-Peel
Approval Date:	2017-03-21	**City:**	
Status:	Approved	**Longitude:**	-79.852936
Record Type:	ECA	**Latitude:**	43.309475
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Halton	**Geometry Y:**	

Approval Type: ECA-AIR
Project Type: AIR
Business Name: Etratech Inc.
Address: 1047 Cooke Blvd
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/1835-987RSV-14.pdf
PDF Site Location:

---

49 | ***37 of 53*** | ***N/125.9*** | ***101.9 / 2.03*** | ***Etratech Printed Circuit Boards Inc.***
1047 Cooke Boulevard
Burlington ON | ***ECA***

Approval No:	3526-6QCJDJ	**MOE District:**	Halton-Peel
Approval Date:	2006-06-05	**City:**	
Status:	Revoked and/or Replaced	**Longitude:**	-79.852936
Record Type:	ECA	**Latitude:**	43.309475
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Halton	**Geometry Y:**	

Approval Type: ECA-AIR
Project Type: AIR
Business Name: Etratech Printed Circuit Boards Inc.
Address: 1047 Cooke Boulevard
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/6132-6BSQ6K-14.pdf
PDF Site Location:

---

49 | **38 of 53** | **N/125.9** | **101.9 / 2.03** | **Etratech Inc.**
1047 Cooke Blvd
Burlington ON | **ECA**

Approval No: 1361-7R5P5X
Approval Date: 2009-07-14
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
MOE District: Halton-Peel
City:
Longitude: -79.852936
Latitude: 43.309475
Geometry X:
Geometry Y:
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Etratech Inc.
Address: 1047 Cooke Blvd
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/1766-78FJ4Z-14.pdf
PDF Site Location:

---

49 | **39 of 53** | **N/125.9** | **101.9 / 2.03** | **Etratech Printed Circuit Boards Inc.**
1047 Cooke Boulevard
Burlington ON | **ECA**

Approval No: 6640-6XPJ8Z
Approval Date: 2007-03-10
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
MOE District: Halton-Peel
City:
Longitude: -79.852936
Latitude: 43.309475
Geometry X:
Geometry Y:
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Etratech Printed Circuit Boards Inc.
Address: 1047 Cooke Boulevard
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/1844-6RKQ49-14.pdf
PDF Site Location:

---

49 | **40 of 53** | **N/125.9** | **101.9 / 2.03** | **Etratech Printed Circuit Boards Inc.**
1047 Cooke Boulevard
Burlington ON | **ECA**

Approval No: 0119-5MYJCZ
Approval Date: 2003-07-31
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Halton
MOE District: Halton-Peel
City:
Longitude: -79.852936
Latitude: 43.309475
Geometry X:
Geometry Y:
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Etratech Printed Circuit Boards Inc.
Address: 1047 Cooke Boulevard
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/5755-5L9S2H-14.pdf

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
PDF Site Location:					

49 | 41 of 53 | N/125.9 | 101.9 / 2.03 | ETRATECH MANUFACTURING INC.
1047 Cooke Boulevard
Burlington ON L7T 4A8 | GEN

Generator No: ON1622301
SIC Code: 334410
SIC Description: SEMICONDUCTOR AND OTHER ELECTRONIC COMPONENT MANUFACTURING
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Saha Chartterpaul
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-681-7544 Ext.240
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

49 | 42 of 53 | N/125.9 | 101.9 / 2.03 | ETRATECH INC.
1047 Cooke Boulevard
Burlington ON L7T 4A8 | GEN

Generator No: ON1622301
SIC Code: 334410
SIC Description: SEMICONDUCTOR AND OTHER ELECTRONIC COMPONENT MANUFACTURING
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Dan Wesko
Choice of Contact: CO_ADMIN
Phone No Admin: 905-681-7544 Ext.350
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 146

Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

49	43 of 53	N/125.9	101.9 / 2.03	**ETRATECH MANUFACTURING INC.** **1047 Cooke Boulevard** **Burlington ON L7T 4A8**	GEN

Generator No: ON1622301
SIC Code: 334410
SIC Description: SEMICONDUCTOR AND OTHER ELECTRONIC COMPONENT MANUFACTURING
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Saha Chartterpaul
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-681-7544 Ext.240
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

49	44 of 53	N/125.9	101.9 / 2.03	**Gentherm Canada ULC.** **1047 Cooke Boulevard** **Burlington ON L7T 4A8**	GEN

Generator No: ON1622301
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class:	122 C
Waste Class Name:	Alkaline slutions - containing other metals and non-metals (not cyanide)
Waste Class:	145 I
Waste Class Name:	Wastes from the use of pigments, coatings and paints
Waste Class:	145 L
Waste Class Name:	Wastes from the use of pigments, coatings and paints
Waste Class:	146 L
Waste Class Name:	Other specified inorganic sludges, slurries or solids
Waste Class:	146 T
Waste Class Name:	Other specified inorganic sludges, slurries or solids
Waste Class:	148 R
Waste Class Name:	Misc. wastes and inorganic chemicals
Waste Class:	212 I
Waste Class Name:	Aliphatic solvents and residues
Waste Class:	251 L
Waste Class Name:	Waste oils/sludges (petroleum based)
Waste Class:	252 L
Waste Class Name:	Waste crankcase oils and lubricants
Waste Class:	263 B
Waste Class Name:	Misc. waste organic chemicals
Waste Class:	263 C
Waste Class Name:	Misc. waste organic chemicals
Waste Class:	265 L
Waste Class Name:	Graphic arts wastes
Waste Class:	268 C
Waste Class Name:	Amines
Waste Class:	331 I
Waste Class Name:	Waste compressed gases including cylinders

49 | ***45 of 53*** | ***N/125.9*** | ***101.9 / 2.03*** | ***Etratech Inc.***
1047 COOKE BOULEVARD NOT AVAILABLE
BURLINGTON ON L7T4A8 | ***NPRI***

NPRI ID:	7161	***Org ID:***	105920
Other ID:		***Submit Date:***	5/27/2016
No Other ID:		***Last Modified:***	11/18/2016 8:28:05 AM
Track ID:	137504	***Contact ID:***	237386
Report ID:	70999	***Cont Type:***	MEM
Report Type:	NPRI	***Contact Title:***	
Rpt Type ID:	1	***Cont First Name:***	Carol
Report Year:	2015	***Cont Last Name:***	Desnoyers
Not-Current Rpt?:	No	***Contact Position:***	Director of Human Resourses
Yr of Last Filed Rpt:	2014	***Contact Fax:***	9056817601
Fac ID:	223627	***Contact Ph.:***	9056817544
Fac Name:	ETRATECH INC.	***Cont Area Code:***	905
Fac Address1:	1047 COOKE BOULEVARD	***Contact Tel.:***	56817544
Fac Address2:	NOT AVAILABLE	***Contact Ext.:***	301
Fac Postal Zip:	L7T4A8	***Cont Fax Area Cde:***	905
Facility Lat:	43.3094	***Contact Fax:***	56817601
Facility Long:	-79.8528	***Contact Email:***	cdesnoyers@etratech.com
DLS (Last Filed Rpt):		***Latitude:***	43.3094

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Facility DLS:		**Longitude:**	-79.8528
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	129	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3359		
NAICS 4 Description:	Other electrical equipment and component manufacturing		
NAICS Code (6 digit):	335930		
NAICS 6 Description:	Wiring device manufacturing		

49	**46 of 53**	**N/125.9**	**101.9 / 2.03**	**ETRATECH INC.** **1047 COOKE BOULEVARD NOT AVAILABLE** **BURLINGTON ON L7T4A8**	**NPRI**

NPRI ID:	7161	**Org ID:**	102208
Other ID:		**Submit Date:**	6/13/2014
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	123048	**Contact ID:**	230618
Report ID:	41395	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	2012	**Cont Last Name:**	
Not-Current Rpt?:	Yes	**Contact Position:**	
Yr of Last Filed Rpt:	2014	**Contact Fax:**	
Fac ID:	223627	**Contact Ph.:**	
Fac Name:	ETRATECH INC.	**Cont Area Code:**	
Fac Address1:	1047 COOKE BOULEVARD	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	L7T4A8	**Cont Fax Area Cde:**	
Facility Lat:	43.3094	**Contact Fax:**	
Facility Long:	-79.8528	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.3094
Facility DLS:		**Longitude:**	-79.8528
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	107	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3359		
NAICS 4 Description:	Other electrical equipment and component manufacturing		
NAICS Code (6 digit):	335930		
NAICS 6 Description:	Wiring device manufacturing		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Lead (and its compounds)
Chem (fr):	Plomb (et ses composés)
Quantity:	.18
Unit:	kg
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

49	***47 of 53***	***N/125.9***	***101.9 / 2.03***	***ETRATECH INC.*** ***1047 COOKE BOULEVARD NOT AVAILABLE*** ***BURLINGTON ON L7T4A8***	***NPRI***

NPRI ID:	7161	***Org ID:***	102208
Other ID:		***Submit Date:***	6/11/2014
No Other ID:		***Last Modified:***	5/29/2015 3:28:24 PM
Track ID:	123017	***Contact ID:***	230618
Report ID:	41383	***Cont Type:***	MED
Report Type:	NPRI	***Contact Title:***	
Rpt Type ID:	1	***Cont First Name:***	
Report Year:	2013	***Cont Last Name:***	
Not-Current Rpt?:	Yes	***Contact Position:***	
Yr of Last Filed Rpt:	2014	***Contact Fax:***	
Fac ID:	223627	***Contact Ph.:***	
Fac Name:	ETRATECH INC.	***Cont Area Code:***	
Fac Address1:	1047 COOKE BOULEVARD	***Contact Tel.:***	
Fac Address2:	NOT AVAILABLE	***Contact Ext.:***	
Fac Postal Zip:	L7T4A8	***Cont Fax Area Cde:***	
Facility Lat:	43.3094	***Contact Fax:***	
Facility Long:	-79.8528	***Contact Email:***	
DLS (Last Filed Rpt):		***Latitude:***	43.3094
Facility DLS:		***Longitude:***	-79.8528
Datum:	1983	***UTM Zone:***	
Facility Cmnts:		***UTM Northing:***	
URL:		***UTM Easting:***	
No of Empl.:	126	***Waste Streams:***	
Parent Co.:		***No Streams:***	
No Parent Co.:		***Waste Off Sites:***	
Pollut Prev Cmnts:		***No Off Sites:***	
Stacks:		***Shutdown:***	
No of Stacks:		***No of Shutdown:***	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3359		
NAICS 4 Description:	Other electrical equipment and component manufacturing		
NAICS Code (6 digit):	335930		
NAICS 6 Description:	Wiring device manufacturing		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Chem: Lead (and its compounds)
Chem (fr): Plomb (et ses composés)
Quantity: .18
Unit: kg
Basis of Estimate Cd: O
Basis of Estimate Desc: O- Engineering Estimates

---

49 | **48 of 53** | **N/125.9** | **101.9 / 2.03** | **1047 Cooke Blvd**
Burlington ON L7T4A8 | **EHS**

Order No: 20170713036
Status: C
Report Type: Standard Report
Report Date: 19-JUL-17
Date Received: 13-JUL-17
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.853065
Y: 43.309502

---

49 | **49 of 53** | **N/125.9** | **101.9 / 2.03** | **Gentherm Canada ULC.**
1047 Cooke Boulevard
Burlington ON L7T 4A8 | **GEN**

Generator No: ON1622301
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 148 R
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 263 B
Waste Class Name: Misc. waste organic chemicals

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 146 L
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 268 C
Waste Class Name: Amines

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 265 L
Waste Class Name: Graphic arts wastes

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 263 C
Waste Class Name: Misc. waste organic chemicals

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 145 B
Waste Class Name: Wastes from the use of pigments, coatings and paints

---

49	50 of 53	N/125.9	101.9 / 2.03	Gentherm Canada ULC. 1047 Cooke Boulevard Burlington ON L7T 4A8	GEN

Generator No: ON1622301
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145 B
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 268 C
Waste Class Name: Amines

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 146 L
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 148 R
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 263 B
Waste Class Name: Misc. waste organic chemicals

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 263 C
Waste Class Name: Misc. waste organic chemicals

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 265 L
Waste Class Name: Graphic arts wastes

---

49 | **51 of 53** | **N/125.9** | **101.9 / 2.03** | **1047 Cooke Blvd.**
Burlington ON L7T 4A8 | **EHS**

Order No: 21110900653
Status: C
Report Type: Standard Report
Report Date: 12-NOV-21
Date Received: 09-NOV-21
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; City Directory

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8529358
Y: 43.3095725

---

49 | **52 of 53** | **N/125.9** | **101.9 / 2.03** | **1047 Cooke Blvd.**
Burlington ON L7T 4A8 | **EHS**

Order No: 21110900653
Status: C
Report Type: Standard Report
Report Date: 12-NOV-21
Date Received: 09-NOV-21
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; City Directory

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8529358
Y: 43.3095725

---

49 | **53 of 53** | **N/125.9** | **101.9 / 2.03** | **1047 Cooke Blvd.**
Burlington ON L7T 4A8 | **EHS**

Order No: 21110900653
Status: C
Report Type: Standard Report
Report Date: 12-NOV-21
Date Received: 09-NOV-21
Previous Site Name:
Lot/Building Size:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8529358
Y: 43.3095725

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Additional Info Ordered: Fire Insur. Maps and/or Site Plans; City Directory

---

50 | **1 of 35** | **SSE/126.3** | **100.9 / 1.01** | **MAC'S MILK**
14 PLAINS RD AT LASALLE GAS BAR
BURLINGTON CITY ON | **SPL**

Ref No: 45824
Site No:
Incident Dt: //
Year:
Incident Cause: VALVE/FITTING LEAK OR FAILURE
Incident Event:
Environment Impact: POSSIBLE
Nature of Impact: Soil contamination
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 1/18/1991
Dt Document Closed:
Municipality No: 14101
System Facility Address:
Client Type:
Call Report Location Geodata:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Receiving Environment:
Incident Reason: EQUIPMENT FAILURE
Incident Summary: MAC'S GAS BAR - DRIPPING PUMP FILTER DUE TO VALVE MALFUNCTION ON TANK.
Site Region:
Site Municipality: BURLINGTON CITY
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:

Contaminant Qty:
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved: MCCR
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:

---

50 | **2 of 35** | **SSE/126.3** | **100.9 / 1.01** | **MACS CONVENIENCE STORES DIV OF SILCORP LTD ATTN MA**
14 PLAINS RD E
BURLINGTON ON L7T2B9 | **PRT**

Location ID: 22654
Type: retail
Expiry Date: 1996-02-28
Capacity (L): 131800
Licence #: 0076357524

---

50 | **3 of 35** | **SSE/126.3** | **100.9 / 1.01** | **14 PLAINS RD. E.**
BURLINGTON ON | **PRT**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Location ID: 2484
Type: retail
Expiry Date:
Capacity (L):
Licence #:

---

50 | **4 of 35** | **SSE/126.3** | **100.9 / 1.01** | **14 Plains Road East, Burlington ON L7T 2B9** | **EHS**

Order No: 20050809021
Status: C
Report Type: Complete Report
Report Date: 8/17/2005
Date Received: 8/9/2005
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection: LASalle Park Road / Waterdown Road
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.852131
Y: 43.306714

---

50 | **5 of 35** | **SSE/126.3** | **100.9 / 1.01** | **Esso Imperial Oil Limited, 14 Plains Road East, Burlington ON L7T 2B9** | **GEN**

Generator No: ON1319742
SIC Code: 419120
SIC Description: Petroleum Product Agents and Brokers
Approval Years: 05
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

50 | **6 of 35** | **SSE/126.3** | **100.9 / 1.01** | **Imperial Oil Limited, 14 Plains Rd E, Burlington ON L7T 2B9** | **CA**

Certificate #: 1953-8JWLRW
Application Year: 2011
Issue Date: 8/3/2011
Approval Type: Industrial Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	7 of 35	SSE/126.3	100.9 / 1.01	14 PLAINS RD E Burlington ON	WWIS

Well ID:	7167017	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	09-Aug-2011 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z121307	**Contractor:**	6032
Tag:		**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/716\7167017.pdf

Additional Detail(s) (Map)

Well Completed Date:	2011/05/30
Year Completed:	2011
Depth (m):	
Latitude:	43.3067356463791
Longitude:	-79.8520020248849
Path:	716\7167017.pdf

Bore Hole Information

Bore Hole ID:	1003547751	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	593105.00
Code OB Desc:		**North83:**	4795518.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	30-May-2011 00:00:00	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1003913482
Layer:	1
Plug From:	0.0
Plug To:	35.0

Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003913480
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003913481
Layer: 2
Plug From:
Plug To:
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1003913479
Method Construction Code:
Method Construction:
Other Method Construction:

Pipe Information

Pipe ID: 1003913472
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1003913476
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1003913477
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Water Details

Water ID: 1003913475
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1003913474
Diameter: 8.0
Depth From: 0.0
Depth To: 35.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID: 1003547751
Depth M:
Year Completed: 2011
Well Completed Dt: 2011/05/30
Audit No: Z121307
Tag No:
Contractor: 6032
Path: 716\7167017.pdf
Latitude: 43.3067356463791
Longitude: -79.8520020248849

50	8 of 35	SSE/126.3	100.9 / 1.01	**MAC'S CONVENIENCE STORES INC**** **14 PLAINS RD E** **BURLINGTON ON**	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 10258878
Status: EXPIRED
Instance ID: 14495
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Cylinder Exchange
Original Source: EXP
Record Date: Up to Mar 2012
Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	9 of 35	SSE/126.3	100.9 / 1.01	MAC'S CONVENIENCE STORES INC** 14 PLAINS RD E BURLINGTON ON L7T 2B9	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10051642	***Expired Date:***	1/13/2010 14:45
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:		***Facility Location:***	
Instance Type:	FS Facility	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:			
Original Source:	EXP		
Record Date:	Up to May 2013		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	10 of 35	SSE/126.3	100.9 / 1.01	MAC'S CONVENIENCE STORES INC** 14 PLAINS RD E BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	11220943	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	74401	***Facility Location:***	
Instance Type:	FS Piping	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

50	***11 of 35***	***SSE/126.3***	***100.9 / 1.01***	***MAC'S CONVENIENCE STORES INC***** ***14 PLAINS RD E*** ***BURLINGTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 11220903
Status: EXPIRED
Instance ID: 74416
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

50	***12 of 35***	***SSE/126.3***	***100.9 / 1.01***	***MAC'S CONVENIENCE STORES INC***** ***14 PLAINS RD E*** ***BURLINGTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 11220984
Status: EXPIRED
Instance ID: 73616

Expired Date:
Max Hazard Rank:
Facility Location:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

50	13 of 35	SSE/126.3	100.9 / 1.01	**Imperial Oil** **14 Plains Road East** **Burlington ON L7T 2B9**	GEN

Generator No:	ON5138284
SIC Code:	447110
SIC Description:	
Approval Years:	2011
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

50	14 of 35	SSE/126.3	100.9 / 1.01	**MAC'S CONVENIENCE STORES INC** **14 PLAINS RD E BURLINGTON L7T 2B9 ON CA** **ON**	FST

Instance No:	64508814	**Manufacturer:**	
Status:		**Serial No:**	
Cont Name:		**Ulc Standard:**	
Instance Type:	FS Liquid Fuel Tank	**Quantity:**	
Item:		**Unit of Measure:**	
Item Description:	FS Liquid Fuel Tank	**Fuel Type:**	Gasoline
Tank Type:	Double Wall UST	**Fuel Type2:**	NULL
Install Date:	6/28/2011 1:54:45 PM	**Fuel Type3:**	NULL
Install Year:	2011	**Piping Steel:**	
Years in Service:		**Piping Galvanized:**	
Model:	NULL	**Tanks Single Wall St:**	
Description:		**Piping Underground:**	
Capacity:	50000	**No Underground:**	
Tank Material:	Fiberglass (FRP)	**Panam Related:**	
Corrosion Protect:	NULL	**Panam Venue:**	
Overfill Protect:			

Facility Type: FS Liquid Fuel Tank
Parent Facility Type: FS Gasoline Station - Self Serve
Facility Location:
Device Installed Location: 14 PLAINS RD E BURLINGTON L7T 2B9 ON CA

Liquid Fuel Tank Details

Overfill Protection:
Owner Account Name: MAC'S CONVENIENCE STORES INC
Item: FS LIQUID FUEL TANK

---

50 | ***15 of 35*** | ***SSE/126.3*** | ***100.9 / 1.01*** | ***MAC'S CONVENIENCE STORES INC***
14 PLAINS RD E BURLINGTON L7T 2B9 ON CA
ON | ***FST***

Instance No: 64508815
Status:
Cont Name:
Instance Type: FS Liquid Fuel Tank
Item:
Item Description: FS Liquid Fuel Tank
Tank Type: Double Wall UST
Install Date: 6/28/2011 1:55:59 PM
Install Year: 2011
Years in Service:
Model: NULL
Description:
Capacity: 50000
Tank Material: Fiberglass (FRP)
Corrosion Protect: NULL
Overfill Protect:
Manufacturer:
Serial No:
Ulc Standard:
Quantity:
Unit of Measure:
Fuel Type: Gasoline
Fuel Type2: NULL
Fuel Type3: NULL
Piping Steel:
Piping Galvanized:
Tanks Single Wall St:
Piping Underground:
No Underground:
Panam Related:
Panam Venue:
Facility Type: FS Liquid Fuel Tank
Parent Facility Type: FS Gasoline Station - Self Serve
Facility Location:
Device Installed Location: 14 PLAINS RD E BURLINGTON L7T 2B9 ON CA

Liquid Fuel Tank Details

Overfill Protection:
Owner Account Name: MAC'S CONVENIENCE STORES INC
Item: FS LIQUID FUEL TANK

---

50 | ***16 of 35*** | ***SSE/126.3*** | ***100.9 / 1.01*** | ***MAC'S CONVENIENCE STORES INC***
14 PLAINS RD E BURLINGTON L7T 2B9 ON CA
ON | ***FST***

Instance No: 64508816
Status:
Cont Name:
Instance Type: FS Liquid Fuel Tank
Item:
Item Description: FS Liquid Fuel Tank
Tank Type: Double Wall UST
Install Date: 6/28/2011 1:56:49 PM
Install Year: 2011
Years in Service:
Model: NULL
Description:
Capacity: 50000
Tank Material: Fiberglass (FRP)
Corrosion Protect: NULL
Overfill Protect:
Manufacturer:
Serial No:
Ulc Standard:
Quantity:
Unit of Measure:
Fuel Type: Gasoline
Fuel Type2: NULL
Fuel Type3: NULL
Piping Steel:
Piping Galvanized:
Tanks Single Wall St:
Piping Underground:
No Underground:
Panam Related:
Panam Venue:
Facility Type: FS Liquid Fuel Tank

Parent Facility Type: FS Gasoline Station - Self Serve
Facility Location:
Device Installed Location: 14 PLAINS RD E BURLINGTON L7T 2B9 ON CA

Liquid Fuel Tank Details

Overfill Protection:
Owner Account Name: MAC'S CONVENIENCE STORES INC
Item: FS LIQUID FUEL TANK

---

50 | ***17 of 35*** | ***SSE/126.3*** | ***100.9 / 1.01*** | ***MAC'S CONVENIENCE STORES INC***
14 PLAINS RD E BURLINGTON L7T 2B9 ON CA
ON | ***FST***

Instance No: 64508817
Status:
Cont Name:
Instance Type: FS Liquid Fuel Tank
Item:
Item Description: FS Liquid Fuel Tank
Tank Type: Double Wall UST
Install Date: 6/28/2011 1:57:49 PM
Install Year: 2011
Years in Service:
Model: NULL
Description:
Capacity: 25000
Tank Material: Fiberglass (FRP)
Corrosion Protect: NULL
Overfill Protect:
Manufacturer:
Serial No:
Ulc Standard:
Quantity:
Unit of Measure:
Fuel Type: Diesel
Fuel Type2: NULL
Fuel Type3: NULL
Piping Steel:
Piping Galvanized:
Tanks Single Wall St:
Piping Underground:
No Underground:
Panam Related:
Panam Venue:
Facility Type: FS Liquid Fuel Tank
Parent Facility Type: FS Gasoline Station - Self Serve
Facility Location:
Device Installed Location: 14 PLAINS RD E BURLINGTON L7T 2B9 ON CA

Liquid Fuel Tank Details

Overfill Protection:
Owner Account Name: MAC'S CONVENIENCE STORES INC
Item: FS LIQUID FUEL TANK

---

50 | ***18 of 35*** | ***SSE/126.3*** | ***100.9 / 1.01*** | ***Imperial Oil***
14 Plains Road East
Burlington ON L7T 2B9 | ***GEN***

Generator No: ON5138284
SIC Code: 447110
SIC Description: Gasoline Stations with Convenience Stores
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

---

50 | ***19 of 35*** | ***SSE/126.3*** | ***100.9 / 1.01*** | ***Imperial Oil***
14 Plains Road East
Burlington ON | ***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON8073025
SIC Code: 447110
SIC Description:
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

50	20 of 35	SSE/126.3	100.9 / 1.01	MAC'S CONVENIENCE STORES INC 14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 11220921
Status: EXPIRED
Instance ID:
Instance Type:
Instance Creation Dt: 6/5/1992
Instance Install Dt: 6/5/1992
Item Description: FS Liquid Fuel Tank
Manufacturer: NULL
Model: NULL
Serial No: NULL
ULC Standard: NULL
Quantity: 1
Unit of Measure: EA
Overfill Prot Type: NULL
Creation Date: 7/5/2009 1:24:17 AM
Next Periodic Str DT: NULL
TSSA Base Sched Cycle 2: NULL
TSSAMax Hazard Rank 1: NULL
TSSA Risk Based Periodic Yn: NULL
TSSA Volume of Directives: NULL
TSSA Periodic Exempt: NULL
TSSA Statutory Interval: NULL
TSSA Recd Insp Interva: NULL
TSSA Recd Tolerance: NULL
TSSA Program Area: NULL
TSSA Program Area 2: NULL
Description: UNDERGROUND TANK
Original Source: EXP
Record Date: 31-JUL-2020

Expired Date:
Max Hazard Rank: NULL
Facility Location: 14 PLAINS RD E BURLINGTON L7T 2B9 ON CA
Facility Type: FS LIQUID FUEL TANK
Fuel Type 2: NULL
Fuel Type 3: NULL
Panam Related: NULL
Panam Venue Nm: NULL
External Identifier: NULL
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source: FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	21 of 35	SSE/126.3	100.9 / 1.01	MAC'S CONVENIENCE STORES INC 14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	11220888	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	NULL
Instance ID:		**Facility Location:**	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA
Instance Type:		**Facility Type:**	FS LIQUID FUEL TANK
Instance Creation Dt:	6/5/1992	**Fuel Type 2:**	NULL
Instance Install Dt:	6/5/1992	**Fuel Type 3:**	NULL
Item Description:	FS Liquid Fuel Tank	**Panam Related:**	NULL
Manufacturer:	NULL	**Panam Venue Nm:**	NULL
Model:	NULL	**External Identifier:**	NULL
Serial No:	NULL	**Item:**	
ULC Standard:	NULL	**Piping Steel:**	
Quantity:	1	**Piping Galvanized:**	
Unit of Measure:	EA	**Tank Single Wall St:**	
Overfill Prot Type:	NULL	**Piping Underground:**	
Creation Date:	7/5/2009 1:24:18 AM	**Tank Underground:**	
Next Periodic Str DT:	NULL	**Source:**	FS Liquid Fuel Tank
TSSA Base Sched Cycle 2:	NULL		
TSSAMax Hazard Rank 1:	NULL		
TSSA Risk Based Periodic Yn:	NULL		
TSSA Volume of Directives:	NULL		
TSSA Periodic Exempt:	NULL		
TSSA Statutory Interval:	NULL		
TSSA Recd Insp Interva:	NULL		
TSSA Recd Tolerance:	NULL		
TSSA Program Area:	NULL		
TSSA Program Area 2:	NULL		
Description:	UNDERGROUND TANK		
Original Source:	EXP		
Record Date:	31-JUL-2020		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	22 of 35	SSE/126.3	100.9 / 1.01	MAC'S CONVENIENCE STORES INC 14 PLAINS RD E BURLINGTON L7T 2B9 ON CA ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	11220965	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	NULL
Instance ID:		**Facility Location:**	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA
Instance Type:		**Facility Type:**	FS LIQUID FUEL TANK
Instance Creation Dt:	6/5/1992	**Fuel Type 2:**	NULL
Instance Install Dt:	6/5/1992	**Fuel Type 3:**	NULL
Item Description:	FS Liquid Fuel Tank	**Panam Related:**	NULL
Manufacturer:	NULL	**Panam Venue Nm:**	NULL
Model:	NULL	**External Identifier:**	NULL
Serial No:	NULL	**Item:**	
ULC Standard:	NULL	**Piping Steel:**	
Quantity:	1	**Piping Galvanized:**	
Unit of Measure:	EA	**Tank Single Wall St:**	
Overfill Prot Type:	NULL	**Piping Underground:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Creation Date:	7/5/2009 1:24:23 AM	**Tank Underground:**	
Next Periodic Str DT:	NULL	**Source:**	FS Liquid Fuel Tank
TSSA Base Sched Cycle 2:	NULL		
TSSAMax Hazard Rank 1:	NULL		
TSSA Risk Based Periodic Yn:	NULL		
TSSA Volume of Directives:	NULL		
TSSA Periodic Exempt:	NULL		
TSSA Statutory Interval:	NULL		
TSSA Recd Insp Interva:	NULL		
TSSA Recd Tolerance:	NULL		
TSSA Program Area:	NULL		
TSSA Program Area 2:	NULL		
Description:	UNDERGROUND TANK		
Original Source:	EXP		
Record Date:	31-JUL-2020		

---

50 | ***23 of 35*** | ***SSE/126.3*** | ***100.9 / 1.01*** | ***14 Plains Rd E***
Burlington ON L7T2B9 | ***EHS***

Order No:	20150525047	**Nearest Intersection:**	
Status:	C	**Municipality:**	Burlington/E Flam Twp
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	01-JUN-15	**Search Radius (km):**	.25
Date Received:	25-MAY-15	**X:**	-79.851878
Previous Site Name:		**Y:**	43.306689
Lot/Building Size:			
Additional Info Ordered:	City Directory		

---

50 | ***24 of 35*** | ***SSE/126.3*** | ***100.9 / 1.01*** | ***Imperial Oil Limited***
14 Plains Rd E
Burlington ON M3C 1K5 | ***ECA***

Approval No:	1953-8JWLRW	**MOE District:**	Halton-Peel
Approval Date:	2011-08-03	**City:**	
Status:	Approved	**Longitude:**	-79.851906
Record Type:	ECA	**Latitude:**	43.3067
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Halton	**Geometry Y:**	
Approval Type:	ECA-INDUSTRIAL SEWAGE WORKS		
Project Type:	INDUSTRIAL SEWAGE WORKS		
Business Name:	Imperial Oil Limited		
Address:	14 Plains Rd E		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/9939-8G5KEZ-14.pdf		
PDF Site Location:			

---

50 | ***25 of 35*** | ***SSE/126.3*** | ***100.9 / 1.01*** | ***Imperial Oil***
14 Plains Road East
Burlington ON L7T 2B9 | ***GEN***

Generator No:	ON8073025
SIC Code:	447110
SIC Description:	447110
Approval Years:	2016
PO Box No:	
Country:	Canada
Status:	
Co Admin:	Nicole Bradley
Choice of Contact:	CO_ADMIN
Phone No Admin:	519-652-0099 Ext.4301
Contaminated Facility:	No

MHSW Facility: No

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

50 | ***26 of 35*** | ***SSE/126.3*** | ***100.9 / 1.01*** | ***Imperial Oil***
14 Plains Road East
Burlington ON L7T 2B9 | ***GEN***

Generator No: ON8073025
SIC Code: 447110
SIC Description: 447110
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Nicole Bradley
Choice of Contact: CO_ADMIN
Phone No Admin: 519-652-0099 Ext.4301
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

50 | ***27 of 35*** | ***SSE/126.3*** | ***100.9 / 1.01*** | ***Imperial Oil***
14 Plains Road East
Burlington ON L7T 2B9 | ***GEN***

Generator No: ON8073025
SIC Code: 447110
SIC Description: 447110
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Grant Pettypiece
Choice of Contact: CO_ADMIN
Phone No Admin: 905-695-3217 Ext.3633
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

50 | **28 of 35** | **SSE/126.3** | **100.9 / 1.01** | **MAC'S CONVENIENCE STORES INC.**
14 PLAINS ROAD EAST
BURLINGTON ON L7T 2B9 | **GEN**

Generator No: ON8907851
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

---

50 | **29 of 35** | **SSE/126.3** | **100.9 / 1.01** | **MAC'S CONVENIENCE STORES INC.**
14 PLAINS ROAD EAST
BURLINGTON ON L7T 2B9 | **GEN**

Generator No: ON8907851
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

---

50 | **30 of 35** | **SSE/126.3** | **100.9 / 1.01** | **14 PLAINS RD E**
BURLINGTON ON L7T 2B9 | **DTNK**

Delisted Fuel Storage Tank

Instance No: 64508813
Status: Active
Instance Type:
Fuel Type:
Creation Date:
Overfill Prot Type:
Facility Location:
Piping SW Steel: 0

Cont Name:		**Piping SW Galvan:**	0
Capacity:		**Tanks SW Steel:**	0
Tank Material:		**Piping Underground:**	3
Corrosion Prot:		**No Underground:**	4
Tank Type:		**Max Hazard Rank:**	
Install Year:		**Max Hazard Rank 1:**	
Facility Type:		**Nxt Period Start Dt:**	
Device Installed Loc:		**Program Area 1:**	
Fuel Type 2:		**Program Area 2:**	
Fuel Type 3:		**Nxt Period Strt Dt 2:**	
Item:	FS GASOLINE STATION - SELF SERVE	**Risk Based Periodic:**	
Item Description:		**Vol of Directives:**	
Model:		**Years in Service:**	
Description:		**Created Date:**	
Instance Creation Dt:		**Federal Device:**	
Instance Install Dt:		**Periodic Exempt:**	
Manufacturer:		**Statutory Interval:**	
Serial No:		**Rcomnd Insp Interval:**	
ULC Standard:		**Recommended Toler:**	
Quantity:		**Panam Venue Name:**	
Unit of Measure:		**External Identifier:**	
Parent Fac Type:			
TSSA Base Sched Cycle 1:			
TSSA Base Sched Cycle 2:			
Original Source:	FST		
Record Date:	31-MAY-2021		

50 | ***31 of 35*** | ***SSE/126.3*** | ***100.9 / 1.01*** | ***MAC'S CONVENIENCE STORES INC***
14 PLAINS RD E BURLINGTON L7T 2B9 ON CA
ON | ***FST***

Instance No:	11220888	**Manufacturer:**	
Status:		**Serial No:**	
Cont Name:		**Ulc Standard:**	
Instance Type:		**Quantity:**	
Item:		**Unit of Measure:**	
Item Description:	FS Liquid Fuel Tank	**Fuel Type:**	Gasoline
Tank Type:	Liquid Fuel Single Wall UST	**Fuel Type2:**	NULL
Install Date:	6/5/1992	**Fuel Type3:**	NULL
Install Year:	1981	**Piping Steel:**	
Years in Service:		**Piping Galvanized:**	
Model:	NULL	**Tanks Single Wall St:**	
Description:		**Piping Underground:**	
Capacity:	50000	**No Underground:**	
Tank Material:	Steel	**Panam Related:**	
Corrosion Protect:	Sacrificial anode	**Panam Venue:**	
Overfill Protect:			
Facility Type:	FS Liquid Fuel Tank		
Parent Facility Type:			
Facility Location:			
Device Installed Location:	14 PLAINS RD E BURLINGTON L7T 2B9 ON CA		

Liquid Fuel Tank Details

Overfill Protection:	
Owner Account Name:	MAC'S CONVENIENCE STORES INC
Item:	FS LIQUID FUEL TANK

50 | ***32 of 35*** | ***SSE/126.3*** | ***100.9 / 1.01*** | ***MAC'S CONVENIENCE STORES INC***
14 PLAINS RD E BURLINGTON L7T 2B9 ON CA
ON | ***FST***

Instance No:	11220965	**Manufacturer:**	

Status:		**Serial No:**	
Cont Name:		**Ulc Standard:**	
Instance Type:		**Quantity:**	
Item:		**Unit of Measure:**	
Item Description:	FS Liquid Fuel Tank	**Fuel Type:**	Gasoline
Tank Type:	Liquid Fuel Single Wall UST	**Fuel Type2:**	NULL
Install Date:	6/5/1992	**Fuel Type3:**	NULL
Install Year:	1981	**Piping Steel:**	
Years in Service:		**Piping Galvanized:**	
Model:	NULL	**Tanks Single Wall St:**	
Description:		**Piping Underground:**	
Capacity:	31800	**No Underground:**	
Tank Material:	Steel	**Panam Related:**	
Corrosion Protect:	Sacrificial anode	**Panam Venue:**	
Overfill Protect:			

Facility Type: FS Liquid Fuel Tank
Parent Facility Type:
Facility Location:
Device Installed Location: 14 PLAINS RD E BURLINGTON L7T 2B9 ON CA

Liquid Fuel Tank Details

Overfill Protection:
Owner Account Name: MAC'S CONVENIENCE STORES INC
Item: FS LIQUID FUEL TANK

---

50 | ***33 of 35*** | ***SSE/126.3*** | ***100.9 / 1.01*** | ***MAC'S CONVENIENCE STORES INC***
14 PLAINS RD E BURLINGTON L7T 2B9 ON CA
ON | ***FST***

Instance No:	11220921	**Manufacturer:**	
Status:		**Serial No:**	
Cont Name:		**Ulc Standard:**	
Instance Type:		**Quantity:**	
Item:		**Unit of Measure:**	
Item Description:	FS Liquid Fuel Tank	**Fuel Type:**	Gasoline
Tank Type:	Liquid Fuel Single Wall UST	**Fuel Type2:**	NULL
Install Date:	6/5/1992	**Fuel Type3:**	NULL
Install Year:	1981	**Piping Steel:**	
Years in Service:		**Piping Galvanized:**	
Model:	NULL	**Tanks Single Wall St:**	
Description:		**Piping Underground:**	
Capacity:	50000	**No Underground:**	
Tank Material:	Steel	**Panam Related:**	
Corrosion Protect:	Sacrificial anode	**Panam Venue:**	
Overfill Protect:			

Facility Type: FS Liquid Fuel Tank
Parent Facility Type:
Facility Location:
Device Installed Location: 14 PLAINS RD E BURLINGTON L7T 2B9 ON CA

Liquid Fuel Tank Details

Overfill Protection:
Owner Account Name: MAC'S CONVENIENCE STORES INC
Item: FS LIQUID FUEL TANK

---

50 | ***34 of 35*** | ***SSE/126.3*** | ***100.9 / 1.01*** | ***MAC'S CONVENIENCE STORES INC.***
14 PLAINS ROAD EAST
BURLINGTON ON L7T 2B9 | ***GEN***

Generator No: ON8907851
SIC Code:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	35 of 35	SSE/126.3	100.9 / 1.01	MAC'S CONVENIENCE STORES INC. 14 PLAINS ROAD EAST BURLINGTON ON L7T 2B9	GEN

Generator No: ON8907851
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
51	1 of 1	WNW/126.3	106.2 / 6.30	Union Gas Limited 1063 Waterdown Rd Burlington ON	SPL

Ref No: 2525-9Z5LH9
Site No: NA
Incident Dt: 8/6/2015
Year:
Incident Cause:
Incident Event:
Environment Impact:
Nature of Impact:
MOE Response: No
Dt MOE Arvl on Scn:
MOE Reported Dt: 8/6/2015
Dt Document Closed: 10/3/2015
Municipality No:
System Facility Address:
Client Type:
Call Report Location Geodata:
Contaminant Code: 35
Contaminant Name: NATURAL GAS (METHANE)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:

Contaminant Qty: 0 other - see incident description
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved:
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Receiving Medium:
Receiving Environment:
Incident Reason: Operator/Human Error
Incident Summary: TSSA- 0.5 inch line strike, made safe
Site Region:
Site Municipality: Burlington
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Industrial
SAC Action Class: TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Source Type:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Residential <UNOFFICIAL>
Site Address: 1063 Waterdown Rd

52	*1 of 2*	*ESE/127.5*	*101.8 / 1.94*	***MOORE SMALLEY LTD*** ***30 PLAINS RD*** ***BURLINGTON ON***	***PRT***

Location ID: 19417
Type: retail
Expiry Date: 1993-01-31
Capacity (L): 2000
Licence #: 0076345172

52	*2 of 2*	*ESE/127.5*	*101.8 / 1.94*	***MOORE SMALLEY LTD*** ***30 PLAINS RD E*** ***BURLINGTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 9888959
Status: EXPIRED
Instance ID: 397908
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Refill Cntr - Cylr Fill
Original Source: EXP
Record Date: Up to Mar 2012

---

53 *1 of 4* *ENE/129.9* *102.9 / 3.02* ***BURLINGTON HYDRO***
71 PLAINS RD EAST TRANSFORMER
BURLINGTON CITY ON L7T 2B8 ***SPL***

Ref No: 238085
Site No:
Incident Dt: 9/3/2002
Year:
Incident Cause: OTHER TRANSPORTATION ACCIDENT
Incident Event:
Environment Impact: POSSIBLE
Nature of Impact: Soil contamination
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 9/3/2002
Dt Document Closed:
Municipality No: 14101
System Facility Address:
Client Type:
Call Report Location Geodata:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Receiving Environment:
Incident Reason: ERROR
Incident Summary: BURLINGTON HYDRO--16 GALL-ONS OF TRANSFORMER OIL (<50 PPM) TO GROUND
Site Region:
Site Municipality: BURLINGTON CITY
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Source Type:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:

Contaminant Qty:
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved:
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:

---

53 *2 of 4* *ENE/129.9* *102.9 / 3.02* ***71 Plains Rd E***
Burlington ON L7T 2B8 ***EHS***

Order No: 20040401001
Status: C
Report Type: Site Report
Report Date: 4/2/04
Date Received: 4/1/04
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.783096
Y: 43.341693

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
53	3 of 4	ENE/129.9	102.9 / 3.02	Budget Car and Truck Rentals 71 Plains Road East Burlington ON L7T 2B8	GEN

Generator No: ON3194901
SIC Code: 447190
SIC Description: Other Gasoline Stations
Approval Years: 03,04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
53	4 of 4	ENE/129.9	102.9 / 3.02	71 BURLINGTON PLAINS INC. 71 PLAINS ROAD EAST, BURLINGTON, ON L7T 2B8 Burlington ON	RSC

RSC ID: 224489
RA No:
RSC Type: Phase 1 and 2 RSC
Curr Property Use: Commercial
Ministry District: Halton-Peel District Office
Filing Date: 2018/04/13
Date Ack:
Date Returned:
Restoration Type:
Soil Type:
Criteria:
CPU Issued Sect 1686:
Cert Date:
Cert Prop Use No:
Intended Prop Use: Residential
Qual Person Name: STEPHEN SEARS
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N):
Accuracy Estimate:
Telephone:
Fax:
Email:
Asmt Roll No: 24-02-010-106-04400-0000
Prop ID No (PIN): 07122-0009 (LT)
Property Municipal Address: 71 PLAINS ROAD EAST, BURLINGTON, ON L7T 2B8
Mailing Address:
Latitude & Latitude:
UTM Coordinates:
Consultant:
Legal Desc:
Measurement Method:
Applicable Standards:
RSC PDF: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=95669&fileName=BROWNFIELDS-E.pdf

Document(s) Detail

Document Heading: Supporting Documents
Document Name: LawyersLetter.pdf
Document Type: Lawyer's letter consisting of a legal description of the property
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=95663&fileName=LawyersLetter.pdf

Document Heading: Supporting Documents
Document Name: TableofCandPUses.pdf
Document Type: Table of Current and Past Property Use
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=95672&fileName=TableofCandPUses.pdf

Document Heading: Supporting Documents

Document Name: PlanofSurvey.pdf
Document Type: A Current plan of Survey
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=95668&fileName=PlanofSurvey.pdf

Document Heading: Supporting Documents
Document Name: PhaseTwoCSM.pdf
Document Type: Phase 2 Conceptual Site Model
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=95666&fileName=PhaseTwoCSM.pdf

Document Heading: Supporting Documents
Document Name: AreaofPEConcern.pdf
Document Type: Area(s) of Potential Environmental Concern
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=95670&fileName=AreaofPEConcern.pdf

Document Heading: Supporting Documents
Document Name: CertificateofCompliance.pdf
Document Type: Certificate of Status
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=95667&fileName=CertificateofCompliance.pdf

Document Heading: Supporting Documents
Document Name: TransferDeed.pdf
Document Type: Copy of any deed(s), transfer(s) or other document(s)
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=95671&fileName=TransferDeed.pdf

---

54	*1 of 2*	*ESE/130.1*	*101.4 / 1.53*	***Roman Home Builders Inc.*** ***34 PLAINS ROAD EAST, BURLINGTON, ONTARIO L7T 2B9*** ***Burlington ON***	***RSC***

RSC ID: 212408
RA No:
RSC Type: Phase 1 and 2 RSC
Curr Property Use: Commercial
Ministry District: Halton-Peel District Office
Filing Date: 2014/02/20
Date Ack:
Date Returned:
Restoration Type:
Soil Type:
Criteria:
CPU Issued Sect 1686:
Cert Date:
Cert Prop Use No:
Intended Prop Use: Residential
Qual Person Name: John Monkman
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N):
Accuracy Estimate:
Telephone:
Fax:
Email:
Asmt Roll No: 2402-010-111-10900-0000
Prop ID No (PIN): 07117-0050 [LT]
Property Municipal Address: 34 PLAINS ROAD EAST, BURLINGTON, ONTARIO L7T 2B9
Mailing Address:
Latitude & Latitude:
UTM Coordinates:
Consultant:
Legal Desc:
Measurement Method:
Applicable Standards:
RSC PDF: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=32478&fileName=BROWNFIELDS-E.pdf

Document(s) Detail

Document Heading: Supporting Documents
Document Name: LawyersLetter.pdf

Document Type:	Lawyer's letter consisting of a legal description of the property
Document Link:	https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=32474&fileName=LawyersLetter.pdf
Document Heading:	Supporting Documents
Document Name:	TransferDeed.pdf
Document Type:	Copy of any deed(s), transfer(s) or other document(s)
Document Link:	https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=32475&fileName=TransferDeed.pdf
Document Heading:	Supporting Documents
Document Name:	PlanofSurvey.pdf
Document Type:	A Current plan of Survey
Document Link:	https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=32476&fileName=PlanofSurvey.pdf
Document Heading:	Supporting Documents
Document Name:	CertofStatus.pdf
Document Type:	Certificate of Status
Document Link:	https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=32471&fileName=CertofStatus.pdf
Document Heading:	Supporting Documents
Document Name:	PhaseTwoCSM.pdf
Document Type:	Phase 2 Conceptual Site Model
Document Link:	https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=32473&fileName=PhaseTwoCSM.pdf
Document Heading:	Supporting Documents
Document Name:	AreaofPEConcern.pdf
Document Type:	Area(s) of Potential Environmental Concern
Document Link:	https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=32477&fileName=AreaofPEConcern.pdf
Document Heading:	Supporting Documents
Document Name:	TableofCandPUses.pdf
Document Type:	Table of Current and Past Property Use
Document Link:	https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=32472&fileName=TableofCandPUses.pdf

---

54 | ***2 of 2*** | ***ESE/130.1*** | ***101.4 / 1.53*** | ***34 Plains Rd E Burlington ON L7T2B9*** | ***EHS***

Order No:	20131024010	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	RSC Report (Rural)	**Client Prov/State:**	ON
Report Date:	01-NOV-13	**Search Radius (km):**	.3
Date Received:	24-OCT-13	**X:**	-79.851366
Previous Site Name:		**Y:**	43.30731
Lot/Building Size:			
Additional Info Ordered:			

---

55 | ***1 of 1*** | ***ENE/133.2*** | ***102.6 / 2.73*** | ***71 PLAINS RDE BURLINGTON ON*** | ***WWIS***

Well ID:	2809957	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Not A Well	**Date Received:**	15-Jun-2004 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z11878	**Contractor:**	6607
Tag:	A010773	**Form Version:**	3

Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/280\2809957.pdf

Additional Detail(s) (Map)

Well Completed Date:	2004/05/18
Year Completed:	2004
Depth (m):	10.7
Latitude:	43.3089120582944
Longitude:	-79.8508389861635
Path:	280\2809957.pdf

Bore Hole Information

Bore Hole ID:	11105806	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	593196.00
Code OB Desc:		**North83:**	4795761.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	5
Date Completed:	18-May-2004 00:00:00	**UTMRC Desc:**	margin of error : 100 m - 300 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	932958068
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	71
Mat2 Desc:	FRACTURED
Mat3:	
Mat3 Desc:	
Formation Top Depth:	7.599999904632568
Formation End Depth:	10.699999809265137
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	932958067
Layer:	1
Color:	7
General Color:	RED
Mat1:	01
Most Common Material:	FILL
Mat2:	28
Mat2 Desc:	SAND
Mat3:	01
Mat3 Desc:	FILL
Formation Top Depth:	0.0
Formation End Depth:	7.599999904632568
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933249700
Layer:	1
Plug From:	8.5
Plug To:	7.5
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933249701
Layer:	2
Plug From:	0.0
Plug To:	1.0
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	962809957
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	11111389
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930838613
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	9.100000381469727
Casing Diameter:	5.0
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	933408058
Layer:	1
Slot:	110
Screen Top Depth:	9.100000381469727
Screen End Depth:	10.699999809265137
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	64.0

Hole Diameter

Hole ID:	11111388
Diameter:	21.0
Depth From:	0.0
Depth To:	10.699999809265137
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	11105806	**Tag No:**	A010773
Depth M:	10.7	**Contractor:**	6607
Year Completed:	2004	**Path:**	280\2809957.pdf
Well Completed Dt:	2004/05/18	**Latitude:**	43.3089120582944
Audit No:	Z11878	**Longitude:**	-79.8508389861635

56 ***1 of 1*** ***E/133.6*** ***99.7 / -0.19*** ***ON*** ***WWIS***

Well ID:	7361071	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	26-Jun-2020 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z329875	**Contractor:**	6946
Tag:	A299540	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	
Year Completed:	
Depth (m):	
Latitude:	43.3081253468178
Longitude:	-79.8505085597333
Path:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Bore Hole Information

Bore Hole ID:	1008323065	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	593224.00
Code OB Desc:		***North83:***	4795674.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:		***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008323065	***Tag No:***	A299540
Depth M:		***Contractor:***	6946
Year Completed:		***Path:***	736\7361071.pdf
Well Completed Dt:		***Latitude:***	43.3081253468178
Audit No:	Z329875	***Longitude:***	-79.8505085597333

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
57	1 of 1	ESE/136.7	100.0 / 0.08	ON	WWIS

Well ID:	7363235	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	27-Jul-2020 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z332251	***Contractor:***	6946
Tag:	A299532	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	HALTON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BURLINGTON CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008384456	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	593213.00
Code OB Desc:		***North83:***	4795619.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:		***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Links

Bore Hole ID:	1008384456	***Tag No:***	A299532
Depth M:		***Contractor:***	6946
Year Completed:		***Path:***	736\7363235.pdf
Well Completed Dt:		***Latitude:***	43.3076315563027
Audit No:	Z332251	***Longitude:***	-79.85065349831

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	1 of 1	W/138.8	108.6 / 8.75	KPM INDUSTRIES LTD O/A KING PAVING & CONSTRUCTION 1063 WATERDOWN RD,,BURLINGTON,ON,L7T 1N4,CA ON	PINC

Incident Id:		***Pipe Material:***	
Incident No:	1696420	***Fuel Category:***	
Incident Reported Dt:	8/6/2015	***Health Impact:***	
Type:	FS-Pipeline Incident	***Environment Impact:***	
Status Code:		***Property Damage:***	
Tank Status:	Pipeline Damage Reason Est	***Service Interrupt:***	
Task No:		***Enforce Policy:***	
Spills Action Centre:		***Public Relation:***	
Fuel Type:		***Pipeline System:***	
Fuel Occurrence Tp:		***PSIG:***	
Date of Occurrence:		***Attribute Category:***	
Occurrence Start Dt:		***Regulator Location:***	
Depth:		***Method Details:***	
Customer Acct Name:	KPM INDUSTRIES LTD O/A KING PAVING & CONSTRUCTION		
Incident Address:	1063 WATERDOWN RD,,BURLINGTON,ON,L7T 1N4,CA		
Operation Type:			
Pipeline Type:			
Regulator Type:			
Summary:			
Reported By:			
Affiliation:			
Occurrence Desc:			
Damage Reason:			
Notes:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
59	1 of 3	WNW/139.9	105.1 / 5.18	1053, 1057 AND 1063 WATERDOWN ROAD AND 2 MASONRY COURT BURLINGTON ON L7T 1N4	EHS

Order No:	22011200014	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Custom Report	***Client Prov/State:***	ON
Report Date:	17-JAN-22	***Search Radius (km):***	.25
Date Received:	12-JAN-22	***X:***	-79.8545543
Previous Site Name:		***Y:***	43.30875677
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
59	2 of 3	WNW/139.9	105.1 / 5.18	1053, 1057 AND 1063 WATERDOWN ROAD AND	EHS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				2 MASONRY COURT BURLINGTON ON L7T 1N4	

Order No: 22011200014
Status: C
Report Type: Custom Report
Report Date: 17-JAN-22
Date Received: 12-JAN-22
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8545543
Y: 43.30875677

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
59	3 of 3	WNW/139.9	105.1 / 5.18	1053, 1057 AND 1063 WATERDOWN ROAD AND 2 MASONRY COURT BURLINGTON ON L7T 1N4	EHS

Order No: 22011200014
Status: C
Report Type: Custom Report
Report Date: 17-JAN-22
Date Received: 12-JAN-22
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8545543
Y: 43.30875677

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
60	1 of 3	NW/144.9	102.3 / 2.45	1074 ad 1062 Cooke Boulevard Burlington ON L7T 4A8	EHS

Order No: 21041500520
Status: C
Report Type: RSC Report (Urban)
Report Date: 20-APR-21
Date Received: 15-APR-21
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .3
X: -79.85408965
Y: 43.30919019

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
60	2 of 3	NW/144.9	102.3 / 2.45	1074 ad 1062 Cooke Boulevard Burlington ON L7T 4A8	EHS

Order No: 21041500520
Status: C
Report Type: RSC Report (Urban)
Report Date: 20-APR-21
Date Received: 15-APR-21
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .3
X: -79.85408965
Y: 43.30919019

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
60	3 of 3	NW/144.9	102.3 / 2.45	1074 ad 1062 Cooke Boulevard Burlington ON L7T 4A8	EHS

Order No: 21041500520
Status: C
Report Type: RSC Report (Urban)
Report Date: 20-APR-21
Date Received: 15-APR-21
Previous Site Name:
Lot/Building Size:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .3
X: -79.85408965
Y: 43.30919019

Additional Info Ordered:

61 | ***1 of 1*** | ***SSE/151.2*** | ***100.9 / 1.01*** | ***ON*** | ***WWIS***

Well ID:	7220632	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	20-May-2014 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	C25503	***Contractor:***	7215
Tag:	A162687	***Form Version:***	8
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	HALTON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	2014/04/29
Year Completed:	2014
Depth (m):	
Latitude:	43.3064748127905
Longitude:	-79.8520315940113
Path:	

Bore Hole Information

Bore Hole ID:	1004771754	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	593103.00
Code OB Desc:		***North83:***	4795489.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	29-Apr-2014 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1004771754	***Tag No:***	A162687
Depth M:		***Contractor:***	7215
Year Completed:	2014	***Path:***	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Well Completed Dt: 2014/04/29 **Latitude:** 43.3064748127905
Audit No: C25503 **Longitude:** -79.8520315940113

---

62 **1 of 7** **S/152.3** **99.8 / -0.05** **DAN GREER ENTERPRISES LTD.** **GEN**
14 PLAINS RD. W.
BURLINGTON ON L7T 1E9

Generator No: ON1110100
SIC Code: 5721
SIC Description: CONSTR./FOREST. MACH
Approval Years: 88,89
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

62 **2 of 7** **S/152.3** **99.8 / -0.05** **DAN GREER ENTERPRISES LTD.** **GEN**
14 PLAINS ROAD WEST
BURLINGTON ON L7T 1E9

Generator No: ON1110100
SIC Code: 5721
SIC Description: CONSTR./FOREST. MACH
Approval Years: 92,93,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

62 **3 of 7** **S/152.3** **99.8 / -0.05** **DAN GREER ENTERPRISES LTD. 12-305** **GEN**
14 PLAINS RD. W.
BURLINGTON ON L7T 1E9

Generator No: ON1110100
SIC Code: 5721
SIC Description: CONSTR./FOREST. MACH
Approval Years: 94,95,96
PO Box No:
Country:
Status:
Co Admin:

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

62 | ***4 of 7*** | ***S/152.3*** | ***99.8 / -0.05*** | ***DAN GREER ENTERPRISES LIMITED*** ***14 PLAINS ROAD WEST*** ***BURLINGTON ON L7T 1E9*** | ***GEN***

Generator No: ON1110100
SIC Code: 5721
SIC Description: CONSTR./FOREST. MACH.
Approval Years: 99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

62 | ***5 of 7*** | ***S/152.3*** | ***99.8 / -0.05*** | ***14 Plains Road West*** ***Burlington ON L7T 1E9*** | ***EHS***

Order No: 20051114006
Status: C
Report Type: Complete Report
Report Date: 11/22/2005
Date Received: 11/14/2005
Previous Site Name:
Lot/Building Size: 120' x 60'
Additional Info Ordered:

Nearest Intersection: Plains Road West & Waterdown Road
Municipality: Burlington
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.852865
Y: 43.306406

---

62 | ***6 of 7*** | ***S/152.3*** | ***99.8 / -0.05*** | ***La Salle Court Investments Inc.*** ***12 PLAINS RD W, BURLINGTON, ON, L7T 1E9*** ***BURLINGTON ON L7T 1E9*** | ***RSC***

RSC ID: 18309
RA No:
RSC Type:
Curr Property Use: Commercial
Ministry District: BURLINGTON
Filing Date: 18-Apr-07
Date Ack:

Cert Date: 9-Feb-07
Cert Prop Use No: No CPU
Intended Prop Use: Residential
Qual Person Name: William J. Heck
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N): Yes

Date Returned:		**Accuracy Estimate:**	2 to 5 meters
Restoration Type:		**Telephone:**	905-6397723
Soil Type:		**Fax:**	905-6393806
Criteria:		**Email:**	wjheck@myexcel.ca
CPU Issued Sect 1686:	No		
Asmt Roll No:	2402-010-111-12000-0000		
Prop ID No (PIN):	07119-0129 (LT)		
Property Municipal Address:	12 PLAINS RD W, BURLINGTON, ON, L7T 1E9		
Mailing Address:	Suite 11, 484 PLAINS RD E, BURLINGTON, ON, L7T 2E1		
Latitude & Latitude:	43.30603440N 79.85301390W (converted from UTM)		
UTM Coordinates:	NAD83 17-593024-4795439		
Consultant:			
Legal Desc:	PT LTS 1-6, PL642, PT LT 7, CON BF, PT 1, 20R13144; BURLINGTON/E FLAM. T/W EASE H713491 OVER PT 2, 20R12573		
Measurement Method:	Global Positioning System		
Applicable Standards:	Full Depth Site Conditions Standard, with Nonpotable Ground Water, Coarse Textured Soil, for Residential/Parkland/Institutional property use		
RSC PDF:			

---

62 | ***7 of 7*** | ***S/152.3*** | ***99.8 / -0.05*** | ***Mechendie Holdings Limited*** ***14 Plains Road West*** ***Burlington ON*** | ***GEN***

Generator No:	ON5083285
SIC Code:	531120
SIC Description:	Lessors of Non-Residential Buildings (except Mini-
Approval Years:	06
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	221
Waste Class Name:	LIGHT FUELS

---

63 | ***1 of 2*** | ***WNW/154.8*** | ***104.7 / 4.84*** | ***BHC Cable Assemblies Inc.*** ***2 Masonry Crt*** ***Burlington ON L7T 4A8*** | ***SCT***

Established:	01-JAN-96
Plant Size (ft²):	12000
Employment:	

--Details--

Description:	Semiconductor and Other Electronic Component Manufacturing
SIC/NAICS Code:	334410
Description:	Semiconductor and Other Electronic Component Manufacturing
SIC/NAICS Code:	334410

---

63 | ***2 of 2*** | ***WNW/154.8*** | ***104.7 / 4.84*** | ***2 Masonry Crt*** ***Burlington ON L7T4A8*** | ***EHS***

Order No:	20131203005	**Nearest Intersection:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	09-DEC-13	**Search Radius (km):**	.25
Date Received:	03-DEC-13	**X:**	-79.854561
Previous Site Name:		**Y:**	43.308963
Lot/Building Size:			
Additional Info Ordered:			

64 **1 of 1** **S/159.6** **100.0 / 0.07** **14 PLAINS RD Burlington ON** **WWIS**

Well ID:	7118602	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Not Used	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	29-Jan-2009 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z60481	**Contractor:**	6607
Tag:	A065576	**Form Version:**	4
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/711\7118602.pdf

Additional Detail(s) (Map)

Well Completed Date:	2008/01/10
Year Completed:	2008
Depth (m):	12.1
Latitude:	43.306307842287
Longitude:	-79.8524416250168
Path:	711\7118602.pdf

Bore Hole Information

Bore Hole ID:	1001978291	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	593070.00
Code OB Desc:		**North83:**	4795470.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	10-Jan-2008 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1002592147
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	12.100000381469727
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1002592149
Layer:	1
Plug From:	0.0
Plug To:	9.100000381469727
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1002592154
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1002592146
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002592151
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	9.100000381469727
Casing Diameter:	5.099999904632568
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002592152
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	5

Screen Depth UOM:
Screen Diameter UOM:
Screen Diameter:

Water Details

Water ID: 1002592150
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 60.0
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1002592148
Diameter: 21.0
Depth From:
Depth To: 12.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Bore Hole ID: 1001978291
Depth M: 12.1
Year Completed: 2008
Well Completed Dt: 2008/01/10
Audit No: Z60481
Tag No: A065576
Contractor: 6607
Path: 711\7118602.pdf
Latitude: 43.306307842287
Longitude: -79.8524416250168

---

65 ***1 of 1*** ***NNW/160.7*** ***105.4 / 5.46*** ***ON*** ***WWIS***

Well ID: 7271535
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: C30572
Tag: A189481
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 15-Sep-2016 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7215
Form Version: 8
Owner:
County: HALTON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2015/10/08
Year Completed: 2015
Depth (m):
Latitude: 43.3098708716907

Longitude: -79.8530651032763
Path:

Bore Hole Information

Bore Hole ID:	1006244604	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	593014.00
Code OB Desc:		***North83:***	4795865.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	08-Oct-2015 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1006244604	***Tag No:***	A189481
Depth M:		***Contractor:***	7215
Year Completed:	2015	***Path:***	
Well Completed Dt:	2015/10/08	***Latitude:***	43.3098708716907
Audit No:	C30572	***Longitude:***	-79.8530651032763

66 ***1 of 1*** ***SSE/165.8*** ***100.9 / 0.99*** ***14 PLAINS RD EAST BURLINGTON ON*** ***WWIS***

Well ID:	7211367	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Test Hole	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Test Hole	***Date Received:***	19-Nov-2013 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z163900	***Contractor:***	7215
Tag:	A155238	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	HALTON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/721\7211367.pdf

Additional Detail(s) (Map)

Well Completed Date:	2013/10/08
Year Completed:	2013
Depth (m):	
Latitude:	43.3063395233746

Longitude: -79.8520094802861
Path: 721\7211367.pdf

Bore Hole Information

Bore Hole ID: 1004640892
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 08-Oct-2013 00:00:00
Remarks:
Loc Method Desc:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 593105.00
North83: 4795474.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: digit

Annular Space/Abandonment Sealing Record

Plug ID: 1004909365
Layer: 1
Plug From: 33.0
Plug To: 22.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004909366
Layer: 2
Plug From: 22.0
Plug To: 2.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1004909364
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1004909357
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004909361
Layer: 1
Material: 5
Open Hole or Material: PLASTIC

Depth From:	23.0
Depth To:	0.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004909362
Layer:	1
Slot:	10
Screen Top Depth:	33.0
Screen End Depth:	23.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.0

Water Details

Water ID:	1004909360
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1004909359
Diameter:	9.0
Depth From:	33.0
Depth To:	0.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1004640892	**Tag No:**	A155238
Depth M:		**Contractor:**	7215
Year Completed:	2013	**Path:**	721\7211367.pdf
Well Completed Dt:	2013/10/08	**Latitude:**	43.3063395233746
Audit No:	Z163900	**Longitude:**	-79.8520094802861

---

67 | ***1 of 2*** | ***E/166.6*** | ***100.2 / 0.26*** | ***CANADIAN TIRE/ROBERT C. NEARING HOLDINGS INC.***
70 PLAINS ROAD
BURLINGTON ON L7T1E9 | ***PES***

Detail Licence No:		**Operator Box:**	
Licence No:	10854	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	905
Licence Type:	Retail Vendor Class 03	**Oper Phone No:**	6375291
Licence Type Code:	21	**Operator Ext:**	
Licence Class:	03	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Region:
District:
County:
Trade Name:
PDF URL:

Post Office Box:
MOE District:
SWP Area Name:

---

67 | **2 of 2** | **E/166.6** | **100.2 / 0.26** | **CANADIAN TIRE STORE/PAUL LAMOUREUX ENTERPRISES LTD.**
70 PLAINS ROAD
BURLINGTON ON L7T1E9 | **PES**

Detail Licence No:
Licence No: 05139
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Retail Vendor Class 03
Licence Type Code: 21
Licence Class: 03
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

68 | **1 of 1** | **S/170.6** | **99.8 / -0.05** | **Walker Environmental Group Inc.**
18 Plains Road West
Burlington ON | **SPL**

Ref No: 6574-ARNRUE
Site No: NA
Incident Dt: 9/28/2017
Year:
Incident Cause:
Incident Event: Leak/Break
Environment Impact:
Nature of Impact:
MOE Response: No
Dt MOE Arvl on Scn:
MOE Reported Dt: 9/29/2017
Dt Document Closed:
Municipality No:
System Facility Address:
Client Type: Corporation
Call Report Location Geodata:
Contaminant Code: 14
Contaminant Name: GREASE (N.O.S.)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1: n/a
Receiving Medium:
Receiving Environment: Land
Incident Reason: Operator/Human Error
Incident Summary: Walker Env: ~ 4 L of grease/water spill to asphalt, clned.
Site Region: Central
Site Municipality: Burlington
Activity Preceding Spill:

Contaminant Qty: 4 L
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq: 2 - Minor Environment
Agency Involved:
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: 4795564.64
Easting: 593101.02

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Industrial
SAC Action Class: Land Spills
Source Type: Truck - Transport/Hauling
Site County/District: Regional Municipality of Halton
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: Commercial<UNOFFICIAL>
Site Address: 18 Plains Road West

---

69 | ***1 of 1*** | ***SSW/173.1*** | ***100.8 / 0.85*** | ***15 Plains Road West Burlington ON L7T 1E8*** | ***EHS***

Order No: 20060818012
Status: C
Report Type: Basic Report
Report Date: 8/28/2006
Date Received: 8/18/2006
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection: Waterdown Road
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.853565
Y: 43.306277

---

70 | ***1 of 14*** | ***NW/175.3*** | ***104.0 / 4.10*** | ***ETRATECH DESIGNS INC. 1074 COOKE BOULEVARD BURLINGTON CITY ON L7T 4A8*** | ***CA***

Certificate #: 8-3335-93-
Application Year: 93
Issue Date: 7/14/1993
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: RELOCATION OF (2) EXHAUST SYSTEMS
Contaminants: Tin, Lead, Isopropyl Alcohol, Ethyl-3-Ethoxy Propionate
Emission Control: Mist Eliminator,

---

70 | ***2 of 14*** | ***NW/175.3*** | ***104.0 / 4.10*** | ***ETRATECH DESIGN INC. 1074 COOKE BLVD BURLINGTON ON L7T 4A8*** | ***SCT***

Established: 1989
Plant Size (ft²): 0
Employment: 150

--Details--
Description: SEMICONDUCTORS AND RELATED DEVICES
SIC/NAICS Code: 3674

Description: ELECTRONIC COILS, TRANSFORMERS, AND OTHER INDUCTORS
SIC/NAICS Code: 3677

Description: ELECTRONIC COMPONENTS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3679

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	3 of 14	NW/175.3	104.0 / 4.10	ETRATECH DESIGNS INC. 1074 COOKE BOULEVARD BURLINGTON CITY ON L7T 4A8	CA

Certificate #: 8-3194-96-
Application Year: 96
Issue Date: 12/12/1997
Approval Type: Industrial air
Status: Underwent 1st revision in 97
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: VENT FOR SOLDERING PROCESS
Contaminants: Lead, Tin, Antimony, Isopropyl Alcohol, Toluene(Pentyl Methane)(Methyl Benzene), Ethylene Glycol
Emission Control: No Controls

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	4 of 14	NW/175.3	104.0 / 4.10	Eclipse Colour Ltd. 1074 Cooke Blvd Burlington ON L7T 4A8	SCT

Established: 1993
Plant Size (ft²):
Employment: 15

--Details--
Description: Support Activities for Printing
SIC/NAICS Code: 323120

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	5 of 14	NW/175.3	104.0 / 4.10	Etratech Designs Inc. 1074 Cooke Boulevard CITY OF BURLINGTON ON	EBR

EBR Registry No: IA6E0609
Ministry Ref No: 8319496 19960415
Notice Type: Instrument Decision
Notice Stage:
Notice Date: June 21, 1996
Proposal Date: April 24, 1996
Year: 1996
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Etratech Designs Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 1074 Cooke Boulevard, Burlington Ontario, L7T 4A8
Comment Period:
URL:

Site Location Details:

1074 Cooke Boulevard CITY OF BURLINGTON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	6 of 14	NW/175.3	104.0 / 4.10	ETRATECH MANUFACTURING INC. 1074 COOKE BOULEVARD BURLINGTON ON L7T 4A8	GEN

Generator No: ON1622301
SIC Code: 3352
SIC Description: ELECT. PARTS & COMP.
Approval Years: 93,94,95,96,97,98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	7 of 14	NW/175.3	104.0 / 4.10	ECLIPSE COLOUR ONTARIO LTD. 1074 COOKE BLVD BURLINGTON ON L7T 4A8	GEN

Generator No: ON2634400
SIC Code: 2821
SIC Description: PLATEMAKING, ETC.
Approval Years: 01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	8 of 14	NW/175.3	104.0 / 4.10	Townmedia, Laurel Oak 1074 Cooke Blvd Burlington ON L7T 4A8	SCT

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Established: 1977
Plant Size (ft²):
Employment: 25

--Details--
Description: Periodical Publishers
SIC/NAICS Code: 511120

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	9 of 14	NW/175.3	104.0 / 4.10	Ontario Golf 1074 Cooke Blvd Burlington ON L7T 4A8	SCT

Established: 01-JUL-00
Plant Size (ft²): 4000
Employment:

--Details--
Description: Periodical Publishers
SIC/NAICS Code: 511120

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	10 of 14	NW/175.3	104.0 / 4.10	Town Media 1074 Cooke Blvd Burlington ON L7T 4A8	SCT

Established:
Plant Size (ft²):
Employment:

--Details--
Description: Periodical Publishers
SIC/NAICS Code: 511120

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	11 of 14	NW/175.3	104.0 / 4.10	PV Labs Ltd. 1074 Cooke Boulevard Burlington ON L7T4A8	GEN

Generator No: ON7249235
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 232 R
Waste Class Name: Polymeric resins

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		263 B			
Waste Class Name:		Misc. waste organic chemicals			
70	12 of 14	NW/175.3	104.0 / 4.10	**PV Labs Ltd.** **1074 Cooke Boulevard** **Burlington ON L7T4A8**	GEN
Generator No:		ON7249235			
SIC Code:					
SIC Description:					
Approval Years:		As of Jul 2020			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		263 B			
Waste Class Name:		Misc. waste organic chemicals			
Waste Class:		145 L			
Waste Class Name:		Wastes from the use of pigments, coatings and paints			
Waste Class:		232 R			
Waste Class Name:		Polymeric resins			
70	13 of 14	NW/175.3	104.0 / 4.10	**PV Labs Ltd.** **1074 Cooke Boulevard** **Burlington ON L7T4A8**	GEN
Generator No:		ON7249235			
SIC Code:					
SIC Description:					
Approval Years:		As of Nov 2021			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		263 B			
Waste Class Name:		Misc. waste organic chemicals			
Waste Class:		232 R			
Waste Class Name:		Polymeric resins			
Waste Class:		145 L			
Waste Class Name:		Wastes from the use of pigments, coatings and paints			
70	14 of 14	NW/175.3	104.0 / 4.10	**PV Labs Ltd.** **1074 Cooke Boulevard** **Burlington ON L7T4A8**	GEN

Generator No: ON7249235
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 232 R
Waste Class Name: POLYMERIC RESINS

Waste Class: 145 L
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 263 B
Waste Class Name: ORGANIC LABORATORY CHEMICALS

71	1 of 1	SSE/184.9	100.9 / 1.00	5M SOUTH OF 982 LASALLE PARK RD. 1M WEST OF EDGE OF LASALLE PARK RD. BURLINGTON ON	WWIS

Well ID: 7267367
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z223901
Tag: A196808
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 20-Jul-2016 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 6607
Form Version: 7
Owner:
County: HALTON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/726\7267367.pdf

Additional Detail(s) (Map)

Well Completed Date: 2016/06/10
Year Completed: 2016
Depth (m): 10.6
Latitude: 43.3061419568094
Longitude: -79.8520625183055
Path: 726\7267367.pdf

Bore Hole Information

Bore Hole ID:	1006159615	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	593101.00
Code OB Desc:		**North83:**	4795452.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	10-Jun-2016 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1006172272
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	66
Mat3 Desc:	DENSE
Formation Top Depth:	3.0
Formation End Depth:	7.599999904632568
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1006172273
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	85
Mat3 Desc:	SOFT
Formation Top Depth:	7.599999904632568
Formation End Depth:	10.600000381469727
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1006172271
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	85

Mat3 Desc: SOFT
Formation Top Depth: 0.0
Formation End Depth: 3.0
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006172280
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006172281
Layer: 2
Plug From: 0.30000001192092896
Plug To: 7.300000190734863
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1006172279
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1006172270
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006172276
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 7.599999904632568
Casing Diameter: 5.099999904632568
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1006172277
Layer: 1
Slot: 20
Screen Top Depth: 7.599999904632568
Screen End Depth: 10.600000381469727
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.400000095367432

Water Details

Water ID:	1006172275
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	8.0
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1006172274
Diameter:	21.0
Depth From:	0.0
Depth To:	10.600000381469727
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	1006159615	***Tag No:***	A196808
Depth M:	10.6	***Contractor:***	6607
Year Completed:	2016	***Path:***	726\7267367.pdf
Well Completed Dt:	2016/06/10	***Latitude:***	43.3061419568094
Audit No:	Z223901	***Longitude:***	-79.8520625183055

---

72 ***1 of 6*** ***ENE/193.7*** ***102.7 / 2.85*** ***Abbey Stained Glass*** ***SCT***
91 Plains Rd E
Burlington ON L7T 2C2

Established:	01-JUL-83
Plant Size (ft²):	
Employment:	

--Details--

Description:	Glass Product Manufacturing from Purchased Glass
SIC/NAICS Code:	327215
Description:	Glass Product Manufacturing from Purchased Glass
SIC/NAICS Code:	327215

---

72 ***2 of 6*** ***ENE/193.7*** ***102.7 / 2.85*** ***PETRO-PARTNERS*** ***RST***
91 PLAINS RD E
BURLINGTON ON L7T 2C2

Headcode:	924800
Headcode Desc:	Oils-Fuel
Phone:	9056810500
List Name:	
Description:	

---

72 ***3 of 6*** ***ENE/193.7*** ***102.7 / 2.85*** ***Eighth Empire Inc.*** ***GEN***
91 Plains Road East. Unit 2c
Burlington ON L7T 2C2

Generator No:	ON5858948
SIC Code:	812190

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description: 812190
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

72	4 of 6	ENE/193.7	102.7 / 2.85	**Eighth Empire Inc.** **91 Plains Road East. Unit 2c** **Burlington ON L7T 2C2**	GEN

Generator No: ON5858948
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

72	5 of 6	ENE/193.7	102.7 / 2.85	**Eighth Empire Inc.** **91 Plains Road East. Unit 2c** **Burlington ON L7T 2C2**	GEN

Generator No: ON5858948
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
72	6 of 6	ENE/193.7	102.7 / 2.85	Eighth Empire Inc. 91 Plains Road East. Unit 2c Burlington ON L7T 2C2	GEN

Generator No: ON5858948
SIC Code:
SIC Description:
Approval Years: As of Jan 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	1 of 5	SW/200.8	102.8 / 2.87	29 Plains Rd W Burlington ON L7T1E8	EHS

Order No: 20160802005
Status: C
Report Type: Site Report
Report Date: 03-AUG-16
Date Received: 02-AUG-16
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .001
X: -79.854614
Y: 43.306204

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	2 of 5	SW/200.8	102.8 / 2.87	BETHESDA INC 29 Plains Rd W Burlington ON L7T 1E8	GEN

Generator No: ON3238512
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	3 of 5	SW/200.8	102.8 / 2.87	ALDERSHOT HARDWARE LTD 29 Plains Rd W ST W Burlington ON L7T 1E8	PES

Detail Licence No:
Operator Box:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Licence No:	L-232-1088128640	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	2020-04-30	**Operator Type:**	
Report Source:	PEST-Limited Vendor	**Oper Area Code:**	
Licence Type:	Limited Vendor	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.30611111	**Operator Region:**	
Longitude:	-79.85444444	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Halton
Trade Name:			

PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2242851

---

73 | ***4 of 5*** | ***SW/200.8*** | ***102.8 / 2.87*** | ***BETHESDA INC***
29 Plains Rd W
Burlington ON L7T 1E8 | ***GEN***

Generator No:	ON3238512
SIC Code:	
SIC Description:	
Approval Years:	As of Nov 2021
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

---

73 | ***5 of 5*** | ***SW/200.8*** | ***102.8 / 2.87*** | ***BETHESDA INC***
29 Plains Rd W
Burlington ON L7T 1E8 | ***GEN***

Generator No:	ON3238512
SIC Code:	
SIC Description:	
Approval Years:	As of Oct 2022
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	312 P
Waste Class Name:	PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
74	1 of 1	S/216.1	99.8 / -0.05	14 PLAINS RD WEST BURLINGTON ON	WWIS

Well ID:	2810512	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Not Used	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	05-Apr-2006 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z05193	**Contractor:**	6032
Tag:	A005253	**Form Version:**	3
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BURLINGTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/281\2810512.pdf

Additional Detail(s) (Map)

Well Completed Date:	2006/02/02
Year Completed:	2006
Depth (m):	9.14
Latitude:	43.3057792744496
Longitude:	-79.8527104959981
Path:	281\2810512.pdf

Bore Hole Information

Bore Hole ID:	11552422	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	593049.00
Code OB Desc:		**North83:**	4795411.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	02-Feb-2006 00:00:00	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	933051471
Layer:	3
Color:	2
General Color:	GREY
Mat1:	01

Most Common Material: FILL
Mat2: 05
Mat2 Desc: CLAY
Mat3:
Mat3 Desc:
Formation Top Depth: 9.140000343322754
Formation End Depth: 9.140000343322754
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 933051469
Layer: 1
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 81
Mat2 Desc: SANDY
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 9.140000343322754
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 933051470
Layer: 2
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 81
Mat2 Desc: SANDY
Mat3:
Mat3 Desc:
Formation Top Depth: 9.140000343322754
Formation End Depth: 9.140000343322754
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933292151
Layer: 1
Plug From: 0.0
Plug To: 0.46000000834465027
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933292152
Layer: 2
Plug From: 0.46000000834465027
Plug To: 0.9100000262260437
Plug Depth UOM: m

Annular Space/Abandonment

Sealing Record

Plug ID:	933292153
Layer:	3
Plug From:	0.9100000262260437
Plug To:	5.489999771118164
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	962810512
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	11562029
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930877771
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	6.099999904632568
Casing Diameter:	0.5
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	933418556
Layer:	1
Slot:	10
Screen Top Depth:	6.099999904632568
Screen End Depth:	9.140000343322754
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	0.5

Hole Diameter

Hole ID:	11683537
Diameter:	20.0
Depth From:	0.0
Depth To:	9.140000343322754
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	11552422	***Tag No:***	A005253
Depth M:	9.14	***Contractor:***	6032
Year Completed:	2006	***Path:***	281\2810512.pdf

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Well Completed Dt:	2006/02/02	**Latitude:**	43.3057792744496
Audit No:	Z05193	**Longitude:**	-79.8527104959981

75 | **1 of 1** | **NW/218.5** | **102.9 / 3.03** | **The Corporation of the City of Burlington**
Masonry Crt and Cooke Boulevard
Burlington ON L7R 3Z6 | **ECA**

Approval No:	0464-9WQJCE	**MOE District:**	
Approval Date:	2015-05-26	**City:**	
Status:	Approved	**Longitude:**	
Record Type:	ECA	**Latitude:**	
Link Source:	IDS	**Geometry X:**	
SWP Area Name:		**Geometry Y:**	

Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: The Corporation of the City of Burlington
Address: Masonry Crt and Cooke Boulevard
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/4599-9WAPWN-14.pdf
PDF Site Location:

76 | **1 of 1** | **E/224.7** | **100.8 / 0.95** | **ON** | **WWIS**

Well ID:	7301691	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	18-Dec-2017 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	C39405	**Contractor:**	7464
Tag:	A227571	**Form Version:**	8
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	HALTON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: BURLINGTON CITY
Site Info:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2017/10/27
Year Completed: 2017
Depth (m):
Latitude: 43.308673106652
Longitude: -79.8494624797624
Path:

Bore Hole Information

Bore Hole ID:	1006903861	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	593308.00

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 27-Oct-2017 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

North83: 4795736.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Links

Bore Hole ID: 1006903861
Depth M:
Year Completed: 2017
Well Completed Dt: 2017/10/27
Audit No: C39405

Tag No: A227571
Contractor: 7464
Path:
Latitude: 43.308673106652
Longitude: -79.8494624797624

---

77 | 1 of 1 | WNW/227.2 | 109.9 / 10.01 | **BURLINGTON CITY - LOT 6, CONC. 1 MASONRY CT./WATERDOWN RD. BURLINGTON CITY ON** | CA

Certificate #: 3-1166-91-
Application Year: 91
Issue Date: 7/31/1991
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

78 | 1 of 14 | WNW/232.4 | 106.7 / 6.83 | **TCG MATERIALS LTD 101 MASONRY CT BURLINGTON ON** | PRT

Location ID: 2491
Type: retail
Expiry Date: 1996-02-28
Capacity (L): 50000
Licence #: 0012892001

---

78 | 2 of 14 | WNW/232.4 | 106.7 / 6.83 | **T C G MATERIALS LIMITED 101 MASONRY CRT BURLINGTON ON L7T 4A8** | SCT

Established: 0000
Plant Size (ft²): 0
Employment: 20

--Details--
Description: CONCRETE BLOCK AND BRICK
SIC/NAICS Code: 3271

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
78	3 of 14	WNW/232.4	106.7 / 6.83	TCG MATERIALS LIMITED 37-466 101 MASONRY COURT BURLINGTON ON L7T 4A8	GEN

Generator No: ON0683405
SIC Code: 0821
SIC Description: SAND & GRAVEL PITS
Approval Years: 92,93,94,95,96
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
78	4 of 14	WNW/232.4	106.7 / 6.83	TCG MATERIALS LIMITED 101 MASONRY COURT BURLINGTON ON L7T 4A8	GEN

Generator No: ON0683405
SIC Code: 0821
SIC Description: SAND & GRAVEL PITS
Approval Years: 97,98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
78	5 of 14	WNW/232.4	106.7 / 6.83	TCG MATERIALS LTD 101 MASONRY CRT BURLINGTON ON L7T 4A8	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 9472288 **Expired Date:** 4/5/2010 14:02

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:		**Facility Location:**	
Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:			
Original Source:	EXP		
Record Date:	Up to May 2013		

78	6 of 14	WNW/232.4	106.7 / 6.83	TCG MATERIALS LTD 101 MASONRY CRT BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10634786	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	31462	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Original Source: EXP
Record Date: Up to Mar 2012

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
78	7 of 14	WNW/232.4	106.7 / 6.83	TCG MATERIALS LTD 101 MASONRY CRT BURLINGTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 10634826
Status: EXPIRED
Instance ID: 32080
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
78	8 of 14	WNW/232.4	106.7 / 6.83	TCG MATERIALS LTD 101 MASONRY CRT BURLINGTON L7T 4A8 ON CA ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 10634808
Status: EXPIRED
Instance ID:
Instance Type:
Instance Creation Dt: 5/25/1992
Instance Install Dt: 5/25/1992
Item Description: FS Liquid Fuel Tank
Manufacturer: NULL
Model: NULL
Serial No: NULL
ULC Standard: NULL
Quantity: 1

Expired Date:
Max Hazard Rank: NULL
Facility Location: 101 MASONRY CRT BURLINGTON L7T 4A8 ON CA
Facility Type: FS LIQUID FUEL TANK
Fuel Type 2: NULL
Fuel Type 3: NULL
Panam Related: NULL
Panam Venue Nm: NULL
External Identifier: NULL
Item:
Piping Steel:
Piping Galvanized:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Unit of Measure:	EA	**Tank Single Wall St:**	
Overfill Prot Type:	NULL	**Piping Underground:**	
Creation Date:	7/5/2009 1:20:04 AM	**Tank Underground:**	
Next Periodic Str DT:	NULL	**Source:**	FS Liquid Fuel Tank
TSSA Base Sched Cycle 2:	NULL		
TSSAMax Hazard Rank 1:	NULL		
TSSA Risk Based Periodic Yn:	NULL		
TSSA Volume of Directives:	NULL		
TSSA Periodic Exempt:	NULL		
TSSA Statutory Interval:	NULL		
TSSA Recd Insp Interva:	NULL		
TSSA Recd Tolerance:	NULL		
TSSA Program Area:	NULL		
TSSA Program Area 2:	NULL		
Description:	UNDERGROUND TANK		
Original Source:	EXP		
Record Date:	31-JUL-2020		

78	9 of 14	WNW/232.4	106.7 / 6.83	**TCG MATERIALS LTD** **101 MASONRY CRT BURLINGTON L7T 4A8 ON CA** **ON**	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10634759	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	NULL
Instance ID:		**Facility Location:**	101 MASONRY CRT BURLINGTON L7T 4A8 ON CA
Instance Type:		**Facility Type:**	FS LIQUID FUEL TANK
Instance Creation Dt:	5/25/1992	**Fuel Type 2:**	NULL
Instance Install Dt:	5/25/1992	**Fuel Type 3:**	NULL
Item Description:	FS Liquid Fuel Tank	**Panam Related:**	NULL
Manufacturer:	NULL	**Panam Venue Nm:**	NULL
Model:	NULL	**External Identifier:**	NULL
Serial No:	NULL	**Item:**	
ULC Standard:	NULL	**Piping Steel:**	
Quantity:	1	**Piping Galvanized:**	
Unit of Measure:	EA	**Tank Single Wall St:**	
Overfill Prot Type:	NULL	**Piping Underground:**	
Creation Date:	7/5/2009 1:20:09 AM	**Tank Underground:**	
Next Periodic Str DT:	NULL	**Source:**	FS Liquid Fuel Tank
TSSA Base Sched Cycle 2:	NULL		
TSSAMax Hazard Rank 1:	NULL		
TSSA Risk Based Periodic Yn:	NULL		
TSSA Volume of Directives:	NULL		
TSSA Periodic Exempt:	NULL		
TSSA Statutory Interval:	NULL		
TSSA Recd Insp Interva:	NULL		
TSSA Recd Tolerance:	NULL		
TSSA Program Area:	NULL		
TSSA Program Area 2:	NULL		
Description:	UNDERGROUND TANK		
Original Source:	EXP		
Record Date:	31-JUL-2020		

78	10 of 14	WNW/232.4	106.7 / 6.83	**ADI DEVELOPMENTS (MASONRY) INC.** **101 Masonry CRT** **BURLINGTON ON L7T 4A8**	EASR

Approval No:	R-009-1110140787	**MOE District:**	Halton-Peel

Status:	REGISTERED	**Municipality:**	BURLINGTON
Date:	2017-05-24	**Latitude:**	43.31083333
Record Type:	EASR	**Longitude:**	-79.855
Link Source:	MOFA	**Geometry X:**	
Project Type:	Water Taking - Construction Dewatering	**Geometry Y:**	
Full Address:			
Approval Type:	EASR-Water Taking - Construction Dewatering		
SWP Area Name:	Halton		
PDF URL:			
PDF Site Location:			

---

78 | ***11 of 14*** | ***WNW/232.4*** | ***106.7 / 6.83*** | ***Adi Development (Masonry) Inc.***
101 Masonry Court
Burlington ON L7T 4A8 | ***GEN***

Generator No:	ON4135911
SIC Code:	
SIC Description:	
Approval Years:	As of Dec 2017
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	251 L
Waste Class Name:	Waste oils/sludges (petroleum based)

---

78 | ***12 of 14*** | ***WNW/232.4*** | ***106.7 / 6.83*** | ***Adi Developments (Masonry) Inc.***
101 Masonry Crt
Burlington ON L7L 6B2 | ***ECA***

Approval No:	5899-AZ7KUY	**MOE District:**	
Approval Date:	2018-06-05	**City:**	
Status:	Approved	**Longitude:**	
Record Type:	ECA	**Latitude:**	
Link Source:	IDS	**Geometry X:**	
SWP Area Name:		**Geometry Y:**	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Business Name:	Adi Developments (Masonry) Inc.		
Address:	101 Masonry Crt		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/3296-AYLQE9-14.pdf		
PDF Site Location:			

---

78 | ***13 of 14*** | ***WNW/232.4*** | ***106.7 / 6.83*** | ***Enbridge Gas Inc.***
101 Masonary Court
Burlington ON L7T 4A8 | ***SPL***

Ref No:	0657-BMKRHW	**Contaminant Qty:**	0 other - see incident description
Site No:	NA	**Nature of Damage:**	
Incident Dt:	2020/03/10	**Discharger Report:**	
Year:		**Material Group:**	
Incident Cause:		**Health/Env Conseq:**	2 - Minor Environment
Incident Event:	Leak/Break	**Agency Involved:**	

Environment Impact:		***Site Lot:***	
Nature of Impact:		***Site Conc:***	
MOE Response:	No	***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Map Datum:***	
MOE Reported Dt:	2020/03/10	***Northing:***	
Dt Document Closed:	2020/05/16	***Easting:***	
Municipality No:			
System Facility Address:			
Client Type:	Corporation		
Call Report Location Geodata:			
Contaminant Code:	35		
Contaminant Name:	NATURAL GAS (METHANE)		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:	1075		
Receiving Medium:			
Receiving Environment:	Air		
Incident Reason:	Operator/Human Error		
Incident Summary:	TSSA FSB - 2" plastic dmgd, IP, made safe - Burlington		
Site Region:	Central		
Site Municipality:	Burlington		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Miscellaneous Communal		
SAC Action Class:	TSSA - Fuel Safety Program Notifications		
Source Type:	Valve/Fitting/Piping		
Site County/District:	Regional Municipality of Halton		
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	Residential Subdivision Construction<UNOFFICIAL>		
Site Address:	101 Masonary Court		

78	***14 of 14***	***WNW/232.4***	***106.7 / 6.83***	***Enbridge Gas Inc. operating as Union Gas*** ***101 Masonary Crt.*** ***Burlington ON***	***SPL***

Ref No:	8848-BMUVCC	***Contaminant Qty:***	0 other - see incident description
Site No:	NA	***Nature of Damage:***	
Incident Dt:	2020/03/19	***Discharger Report:***	
Year:		***Material Group:***	
Incident Cause:		***Health/Env Conseq:***	2 - Minor Environment
Incident Event:	Unknown / N/A	***Agency Involved:***	
Environment Impact:		***Site Lot:***	
Nature of Impact:		***Site Conc:***	
MOE Response:	No	***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Map Datum:***	
MOE Reported Dt:	2020/03/19	***Northing:***	
Dt Document Closed:	2020/05/16	***Easting:***	
Municipality No:			
System Facility Address:			
Client Type:	Corporation		
Call Report Location Geodata:			
Contaminant Code:	35		
Contaminant Name:	NATURAL GAS (METHANE)		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:	1075		
Receiving Medium:			
Receiving Environment:	Air		
Incident Reason:	Unknown / N/A		
Incident Summary:	TSSA FSB: Enbridge Gas, 1" plastic IP service line damaged; made safe		
Site Region:	Central		

Site Municipality:	Burlington
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Industrial
SAC Action Class:	TSSA - Fuel Safety Program Notifications
Source Type:	Pipeline/Components
Site County/District:	Regional Municipality of Halton
Site Geo Ref Meth:	
Site District Office:	Halton-Peel
Nearest Watercourse:	
Site Name:	Residential<UNOFFICIAL>
Site Address:	101 Masonary Crt.

---

79 **1 of 3** **ENE/235.0** **100.8 / 0.95** **92 Plains Rd E**
Burlington ON L7T2C1 **EHS**

Order No:	20150212022	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	RSC Report (Urban)	**Client Prov/State:**	ON
Report Date:	19-FEB-15	**Search Radius (km):**	.3
Date Received:	12-FEB-15	**X:**	-79.849354
Previous Site Name:		**Y:**	43.308798
Lot/Building Size:			
Additional Info Ordered:			

---

79 **2 of 3** **ENE/235.0** **100.8 / 0.95** **EMBER DOG INC.**
92 PLAINS ROAD EAST, BURLINGTON, ON L7T 4B6
Burlington ON **RSC**

RSC ID:	224288	**Cert Date:**	
RA No:		**Cert Prop Use No:**	
RSC Type:	Phase 1 and 2 RSC	**Intended Prop Use:**	Residential
Curr Property Use:	Residential	**Qual Person Name:**	ROBIN BROWN
Ministry District:	Halton-Peel District Office	**Stratified (Y/N):**	
Filing Date:	2018/02/21	**Audit (Y/N):**	
Date Ack:		**Entire Leg Prop. (Y/N):**	
Date Returned:		**Accuracy Estimate:**	
Restoration Type:		**Telephone:**	
Soil Type:		**Fax:**	
Criteria:		**Email:**	
CPU Issued Sect 1686:			
Asmt Roll No:	2402010113063000000		
Prop ID No (PIN):	07117-0034 (LT)		
Property Municipal Address:	92 PLAINS ROAD EAST, BURLINGTON, ON L7T 4B6		
Mailing Address:			
Latitude & Latitude:			
UTM Coordinates:			
Consultant:			
Legal Desc:			
Measurement Method:			
Applicable Standards:			
RSC PDF:	https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=92739&fileName=BROWNFIELDS-E.pdf		

Document(s) Detail

Document Heading:	Supporting Documents
Document Name:	PlanofSurvey.pdf

Document Type: A Current plan of Survey
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=92733&fileName=PlanofSurvey.pdf

Document Heading: Supporting Documents
Document Name: PhaseTwo.pdf
Document Type: Phase 2 Conceptual Site Model
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=94530&fileName=PhaseTwo.pdf

Document Heading: Supporting Documents
Document Name: CertofStatus.pdf
Document Type: Certificate of Status
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=92731&fileName=CertofStatus.pdf

Document Heading: Supporting Documents
Document Name: LawyersLetter.pdf
Document Type: Lawyer's letter consisting of a legal description of the property
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=92734&fileName=LawyersLetter.pdf

Document Heading: Supporting Documents
Document Name: TableofCandPUses.pdf
Document Type: Table of Current and Past Property Use
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=92735&fileName=TableofCandPUses.pdf

Document Heading: Supporting Documents
Document Name: APECTable.pdf
Document Type: Area(s) of Potential Environmental Concern
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=92730&fileName=APECTable.pdf

Document Heading: Supporting Documents
Document Name: TransferDeed.pdf
Document Type: Copy of any deed(s), transfer(s) or other document(s)
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=92732&fileName=TransferDeed.pdf

Document Heading: Supporting Documents
Document Name: Authorization.pdf
Document Type: Proof of the owner's authorization
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=92737&fileName=Authorization.pdf

---

79 | **3 of 3** | **ENE/235.0** | **100.8 / 0.95** | **92 Plains Rd E**
Burlington ON L7T2C1 | **EHS**

Order No: 20170907032
Status: C
Report Type: Standard Report
Report Date: 13-SEP-17
Date Received: 07-SEP-17
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.849375
Y: 43.308782

---

80 | **1 of 1** | **SSE/235.7** | **100.8 / 0.95** | **R.M. OF HALTON**
LASALLE PK.RD/FAIRWOOD PL.W.
BURLINGTON CITY ON | **CA**

Certificate #: 7-0213-97-
Application Year: 97

Issue Date: 4/2/1997
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

81 **1 of 1** **ENE/238.1** **100.8 / 0.95** **ON** **WWIS**

Well ID: 7374324
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: C49196
Tag: A294204
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BURLINGTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 08-Dec-2020 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 6988
Form Version: 8
Owner:
County: HALTON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1008520610
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 14-Jul-2020 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 593312.00
North83: 4795767.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Links

Bore Hole ID: 1008520610
Depth M:
Year Completed: 2020
Well Completed Dt: 2020/07/14
Audit No: C49196

Tag No: A294204
Contractor: 6988
Path:
Latitude: 43.3089516968572
Longitude: -79.8494079024258

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
82	1 of 1	SSW/242.8	99.8 / -0.05	PEEL I.T. CONSULTANTS Ltd. 38 Plains Rd. Easr Unit B3 Burlington ON	GEN

Generator No: ON7344688
SIC Code:
SIC Description:
Approval Years: 03,04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
83	1 of 3	SSW/244.4	99.7 / -0.22	34 and 38 Plains Road West, Burlington Burlington ON L7T 1E9	EHS

Order No: 21011800030
Status: C
Report Type: Standard Report
Report Date: 21-JAN-21
Date Received: 18-JAN-21
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8536639
Y: 43.305622

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
83	2 of 3	SSW/244.4	99.7 / -0.22	34 and 38 Plains Road West, Burlington Burlington ON L7T 1E9	EHS

Order No: 21011800030
Status: C
Report Type: Standard Report
Report Date: 21-JAN-21
Date Received: 18-JAN-21
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8536639
Y: 43.305622

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
83	3 of 3	SSW/244.4	99.7 / -0.22	34 and 38 Plains Road West, Burlington Burlington ON L7T 1E9	EHS

Order No: 21011800030
Status: C
Report Type: Standard Report
Report Date: 21-JAN-21
Date Received: 18-JAN-21
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8536639
Y: 43.305622

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
84	1 of 1	ENE/252.3	102.0 / 2.07	105 Plains Road East Burlington ON L7T 2C2	EHS

Order No: 20190904067
Status: C
Nearest Intersection:
Municipality:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Report Type:	Standard Select Report	**Client Prov/State:**	ON
Report Date:	10-SEP-19	**Search Radius (km):**	.25
Date Received:	04-SEP-19	**X:**	-79.849571
Previous Site Name:		**Y:**	43.309601
Lot/Building Size:			
Additional Info Ordered:	City Directory		

---

85 *1 of 2* *ENE/254.1* *101.8 / 1.92*

PLAINS ROAD ANIMAL HOSPITAL
105 PLAINS ROAD EAST
BURLINGTON ON L7T 2C2

GEN

Generator No:	ON5757660
SIC Code:	
SIC Description:	
Approval Years:	02,03,04
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	264
Waste Class Name:	PHOTOPROCESSING WASTES

---

85 *2 of 2* *ENE/254.1* *101.8 / 1.92*

KAJAN INC.
105 PLAINS ROAD EAST, BURLINGTON, ON L7T 2C2
Burlington ON

RSC

RSC ID:	226302	**Cert Date:**	
RA No:		**Cert Prop Use No:**	
RSC Type:	Phase 1 RSC	**Intended Prop Use:**	Residential
Curr Property Use:	Commercial	**Qual Person Name:**	PAUL BLUNT
Ministry District:	Halton-Peel District Office	**Stratified (Y/N):**	
Filing Date:	2020/01/06	**Audit (Y/N):**	
Date Ack:		**Entire Leg Prop. (Y/N):**	
Date Returned:		**Accuracy Estimate:**	
Restoration Type:		**Telephone:**	
Soil Type:		**Fax:**	
Criteria:		**Email:**	
CPU Issued Sect 1686:			

Asmt Roll No:	240201010604700
Prop ID No (PIN):	07122-0006 (LT)
Property Municipal Address:	105 PLAINS ROAD EAST, BURLINGTON, ON L7T 2C2
Mailing Address:	
Latitude & Latitude:	
UTM Coordinates:	
Consultant:	
Legal Desc:	
Measurement Method:	
Applicable Standards:	
RSC PDF:	https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=120910&fileName=BROWNFIELDS-E.pdf

Document(s) Detail

Document Heading: Supporting Documents
Document Name: RSC Property.pdf
Document Type: A Current plan of Survey
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=120908&fileName=RSC+Property.pdf

Document Heading: Supporting Documents
Document Name: Lawyers Letter.pdf
Document Type: Lawyer's letter consisting of a legal description of the property
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=120907&fileName=Lawyers+Letter.pdf

Document Heading: Supporting Documents
Document Name: Table of Current and Past Uses.pdf
Document Type: Table of Current and Past Property Use
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=120904&fileName=Table+of+Current+and+Past+Uses.pdf

Document Heading: Supporting Documents
Document Name: PhaseOne.pdf
Document Type: Phase 1 Conceptual Site Model
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=122919&fileName=PhaseOne.pdf

Document Heading: Supporting Documents
Document Name: Certificate of Status.pdf
Document Type: Certificate of Status
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=120903&fileName=Certificate+of+Status.pdf

Document Heading: Supporting Documents
Document Name: Copy of Deed and Other Documents.pdf
Document Type: Copy of any deed(s), transfer(s) or other document(s)
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=120911&fileName=Copy+of+Deed+and+Other+Documents.pdf

---

86 | ***1 of 1*** | ***SSW/255.0*** | ***99.5 / -0.35*** | ***Adjacent (west) to 40 Plains Rd W Burlington ON*** | ***SPL***

Ref No: 6312-7DCKS4
Site No:
Incident Dt:
Year:
Incident Cause: Other Transport Accident
Incident Event:
Environment Impact: Not Anticipated
Nature of Impact: Soil Contamination
MOE Response: No Field Response
Dt MOE Arvl on Scn:
MOE Reported Dt: 4/3/2008
Dt Document Closed: 4/14/2008
Municipality No:
System Facility Address:
Client Type:
Call Report Location Geodata:
Contaminant Code: 12
Contaminant Name: GASOLINE
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Receiving Environment:
Incident Reason: Equipment/Vehicles
Incident Summary: Gas tank fell off car - 25-50L gas to gnd. No sewers/cbs
Site Region:

Contaminant Qty: 40 L
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved:
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Site Municipality:		Burlington			
Activity Preceding Spill:					
Property 2nd Watershed:					
Property Tertiary Watershed:					
Sector Type:		Other Motor Vehicle			
SAC Action Class:		Land Spills			
Source Type:					
Site County/District:					
Site Geo Ref Meth:					
Site District Office:		Halton-Peel			
Nearest Watercourse:					
Site Name:		Parking lot<UNOFFICIAL>			
Site Address:					

87	1 of 1	S/258.1	100.1 / 0.19	FAIRWOOD HOLLOW LIMITED FAIRWOOD PL.W./PARK AVE. W. BURLINGTON ON	CA
Certificate #:		3-0104-98-			
Application Year:		98			
Issue Date:		2/18/1998			
Approval Type:		Municipal sewage			
Status:		Approved			
Application Type:					
Client Name:					
Client Address:					
Client City:					
Client Postal Code:					
Project Description:					
Contaminants:					
Emission Control:					

88	1 of 3	SSW/270.5	100.8 / 0.95	R.M. OF HALTON EMERY AVE/PLAINS RD.W. BURLINGTON CITY ON	CA
Certificate #:		7-0953-97-			
Application Year:		97			
Issue Date:		9/22/1997			
Approval Type:		Municipal water			
Status:		Approved			
Application Type:					
Client Name:					
Client Address:					
Client City:					
Client Postal Code:					
Project Description:					
Contaminants:					
Emission Control:					

88	2 of 3	SSW/270.5	100.8 / 0.95	BURLINGTON CITY EMERY AVE/PLAINS RD.W. BURLINGTON CITY ON	CA
Certificate #:		3-1259-97-			
Application Year:		97			
Issue Date:		9/22/1997			
Approval Type:		Municipal sewage			
Status:		Approved			
Application Type:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

88 | ***3 of 3*** | ***SSW/270.5*** | ***100.8 / 0.95*** | ***R.M. OF HALTON EMERY AVE/PLAINS RD.W. BURLINGTON CITY ON*** | ***CA***

Certificate #: 3-1260-97-
Application Year: 97
Issue Date: 9/22/1997
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

89 | ***1 of 1*** | ***ENE/276.3*** | ***101.8 / 1.95*** | ***109 PLAINS ROAD EAST BURLINGTON ON L7T 2C2*** | ***HINC***

External File Num: FS INC 0703-01041
Fuel Occurrence Type: CO Release
Date of Occurrence: 2/9/2007
Fuel Type Involved: Fuel Oil
Status Desc: Completed - Causal Analysis(End)
Job Type Desc: Incident/Near-Miss Occurrence (FS)
Oper. Type Involved: Multi-unit Residential
Service Interruptions: No
Property Damage: No
Fuel Life Cycle Stage: Utilization
Root Cause: Root Cause: Equipment/Material/Component:N/A Procedures:N/A Maintenance:Yes Design:Yes Training: Yes Management:Yes Human Factors:Y
Reported Details:
Fuel Category: Unknown
Occurrence Type: Near-miss
Affiliation: Safety Authorities (MOL, ESA, Insurers, etc.)
County Name: Halton
Approx. Quant. Rel:
Nearby body of water:
Enter Drainage Syst.:
Approx. Quant. Unit:
Environmental Impact:

---

90 | ***1 of 3*** | ***SSE/285.0*** | ***99.8 / -0.05*** | ***PIPELINE HIT 952 LASALLE PARK RD,,BURLINGTON,ON,L7T 1M9,CA ON*** | ***PINC***

Incident Id:
Incident No: 1396818
Incident Reported Dt: 5/16/2014
Pipe Material:
Fuel Category:
Health Impact:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Type:	FS-Pipeline Incident	**Environment Impact:**	
Status Code:		**Property Damage:**	
Tank Status:	Pipeline Damage Reason Est	**Service Interrupt:**	
Task No:		**Enforce Policy:**	
Spills Action Centre:		**Public Relation:**	
Fuel Type:		**Pipeline System:**	
Fuel Occurrence Tp:		**PSIG:**	
Date of Occurrence:		**Attribute Category:**	
Occurrence Start Dt:		**Regulator Location:**	
Depth:		**Method Details:**	

Customer Acct Name: PIPELINE HIT
Incident Address: 952 LASALLE PARK RD,,BURLINGTON,ON,L7T 1M9,CA
Operation Type:
Pipeline Type:
Regulator Type:
Summary:
Reported By:
Affiliation:
Occurrence Desc:
Damage Reason:
Notes:

90	2 of 3	SSE/285.0	99.8 / -0.05	**Union Gas Limited** **952 LaSalle Park Drive** **Burlington ON**	SPL

Ref No:	3032-9K5SLW	**Contaminant Qty:**	0 other - see incident description
Site No:	NA	**Nature of Damage:**	
Incident Dt:	2014/05/15	**Discharger Report:**	
Year:		**Material Group:**	
Incident Cause:	Leak/Break	**Health/Env Conseq:**	
Incident Event:		**Agency Involved:**	
Environment Impact:	Not Anticipated	**Site Lot:**	
Nature of Impact:	Air Pollution	**Site Conc:**	
MOE Response:	Not Moe mandate	**Site Geo Ref Accu:**	
Dt MOE Arvl on Scn:		**Site Map Datum:**	
MOE Reported Dt:	2014/05/15	**Northing:**	
Dt Document Closed:	2014/07/15	**Easting:**	

Municipality No:
System Facility Address:
Client Type:
Call Report Location Geodata:
Contaminant Code: 35
Contaminant Name: NATURAL GAS (METHANE)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Receiving Environment:
Incident Reason: Operator/Human Error
Incident Summary: TSSA FSB: ½ pl IP gas srvce dmgd; made safe
Site Region:
Site Municipality: Burlington
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Pipeline/Components
SAC Action Class: Air Spills - Gases and Vapours
Source Type:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: residential<UNOFFICIAL>

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site Address: 952 LaSalle Park Drive

---

90 | **3 of 3** | **SSE/285.0** | **99.8 / -0.05** | **PIPELINE HIT 1/2"** | **PINC**
952 LASALLE PARK RD,,BURLINGTON,ON,L7T 1M9,CA
ON

Incident Id:
Incident No: 1396820
Incident Reported Dt: 5/16/2014
Type: FS-Pipeline Incident
Status Code:
Tank Status: Cancelled
Task No:
Spills Action Centre:
Fuel Type:
Fuel Occurrence Tp:
Date of Occurrence:
Occurrence Start Dt:
Depth:
Customer Acct Name: PIPELINE HIT 1/2"
Incident Address: 952 LASALLE PARK RD,,BURLINGTON,ON,L7T 1M9,CA
Operation Type:
Pipeline Type:
Regulator Type:
Summary:
Reported By:
Affiliation:
Occurrence Desc:
Damage Reason:
Notes:

Pipe Material:
Fuel Category:
Health Impact:
Environment Impact:
Property Damage:
Service Interrupt:
Enforce Policy:
Public Relation:
Pipeline System:
PSIG:
Attribute Category:
Regulator Location:
Method Details:

---

91 | **1 of 1** | **N/291.4** | **104.8 / 4.95** | **1085 Clearview Avenue** | **EHS**
Burlington ON L7T 2J2

Order No: 23012500063
Status: C
Report Type: Standard Express Report
Report Date: 25-JAN-23
Date Received: 25-JAN-23
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8524756
Y: 43.3110968

---

92 | **1 of 1** | **ENE/295.2** | **101.8 / 1.95** | **ABBEY STAINED GLASS** | **SCT**
115 Plains Rd E
Burlington ON L7T 2C2

Established: 0000
Plant Size (ft²): 0
Employment: 0

--Details--
Description: Glass Product Manufacturing from Purchased Glass
SIC/NAICS Code: 327215

Unplottable Summary

Total: 20 Unplottable sites

DB	Company Name/Site Name	Address	City	Postal
CA	FORTINO'S SUPERMARKET LTD.	PLAINS ROAD EAST	BURLINGTON CITY ON	
CA	The Regional Municipality of Halton	Easement (56 m south of Fairwood Place West to 141 m south of Fairwood Place)	Burlington ON	
CA	SAMPURAN ENTERPRISES LTD.	PLAINS RD. EAST KINGS LANDING	BURLINGTON CITY ON	
CA	J. COOKE DEVELOPMENT COMPANY (PRIVATE)	FAIRWOOD PLACE WEST TOWNHOUSE	BURLINGTON CITY ON	
CA	THE COOKE GROUP INC.	COOKE BLVD.	BURLINGTON CITY ON	
CA	J. COOKE DEVELOPMENTS LIMITED	FAIRWOOD PLACE WEST	BURLINGTON CITY ON	
CA	SAMPURAN ENTERPRISES LTD.	PLAINS RD. EAST KINGS LANDING	BURLINGTON CITY ON	
CA	IMPERIAL CITY CORP.	PLAINS RD. E.	BURLINGTON CITY ON	
CA	J. COOKE DEVELOPMENT CO. LTD. (PRIVATE)	FAIRWOOD PLACE WEST	BURLINGTON CITY ON	
CA	BURLINGTON CITY	PLAINS RD. EAST	BURLINGTON CITY ON	
CA	THE COOKE GROUP INC.	COOKE BLVD.	BURLINGTON CITY ON	
CA	THE COOKE GROUP COOKE BUS. PARK	COOKE BLVD.	BURLINGTON CITY ON	
CA	J. COOKE DEVELOPMENT LTD.	FAIRWOOD PLACE WEST	BURLINGTON CITY ON	
CA	J. COOKE DEVELOPMENTS LIMITED	FAIRWOOD PLACE WEST	BURLINGTON CITY ON	
ECA	The Regional Municipality of Halton	Plains Road (Fairview Street) at QEW Interchange	Burlington ON	L6M 3L1
ECA	The Corporation of the City of Burlington	Waterdown Rd	Burlington ON	L7R 3Z6

GEN	Brennan Paving Ltd	Waterdown Rd	Burlington ON	
SCT	T C G MATERIALS LTD	PO BOX 5000 LCD 1	ON	L7R 3Y8
SPL	CONSTRUCTION SITE	DEVELOPMENT SITE AT THE N.W. CORNER OF PLAINS RD. & JOB'S LANE,OPPOSITE FRANCIS (N.O.S.)	BURLINGTON CITY ON	
SPL	TRANSPORT TRUCK	PLAINS ROAD NEAR 403/401. MOTOR VEHICLE (OPERATING FLUID)	BURLINGTON CITY ON	

Unplottable Report

Site: ***FORTINO'S SUPERMARKET LTD.***
PLAINS ROAD EAST BURLINGTON CITY ON

Database: ***CA***

Certificate #:	8-3222-96-
Application Year:	96
Issue Date:	5/7/1996
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	COMMERCIAL KITCHEN EXHAUST HOOD
Contaminants:	Odour/Fumes
Emission Control:	No Controls

Site: ***The Regional Municipality of Halton***
Easement (56 m south of Fairwood Place West to 141 m south of Fairwood Place) Burlington ON

Database: ***CA***

Certificate #:	7768-6A2KTM
Application Year:	2005
Issue Date:	3/2/2005
Approval Type:	Municipal and Private Sewage Works
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Site: ***SAMPURAN ENTERPRISES LTD.***
PLAINS RD. EAST KINGS LANDING BURLINGTON CITY ON

Database: ***CA***

Certificate #:	3-2066-87-
Application Year:	87
Issue Date:	11/20/1987
Approval Type:	Municipal sewage
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Site: ***J. COOKE DEVELOPMENT COMPANY (PRIVATE)***
FAIRWOOD PLACE WEST TOWNHOUSE BURLINGTON CITY ON

Database: ***CA***

Certificate #:	3-1360-88-

Application Year: 88
Issue Date: 8/9/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***THE COOKE GROUP INC.***
COOKE BLVD. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-1366-88-
Application Year: 88
Issue Date: 9/2/1988
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***J. COOKE DEVELOPMENTS LIMITED***
FAIRWOOD PLACE WEST BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-1546-86-
Application Year: 86
Issue Date: 3/11/1987
Approval Type: Municipal water
Status: Approved in 1987
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***SAMPURAN ENTERPRISES LTD.***
PLAINS RD. EAST KINGS LANDING BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-1744-87-
Application Year: 87
Issue Date: 11/20/1987
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***IMPERIAL CITY CORP.***
PLAINS RD. E. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-1379-89-
Application Year: 89
Issue Date: 8/14/1989
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***J. COOKE DEVELOPMENT CO. LTD. (PRIVATE)***
FAIRWOOD PLACE WEST BURLINGTON CITY ON

Database: ***CA***

Certificate #: 7-1171-88-
Application Year: 88
Issue Date: 8/9/1988
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BURLINGTON CITY***
PLAINS RD. EAST BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-1430-92-
Application Year: 92
Issue Date: 11/2/1992
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***THE COOKE GROUP INC.***
COOKE BLVD. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-1682-88-
Application Year: 88
Issue Date: 9/13/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:

Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***THE COOKE GROUP COOKE BUS. PARK***
COOKE BLVD. BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-1594-88-
Application Year: 88
Issue Date: 9/2/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***J. COOKE DEVELOPMENT LTD.***
FAIRWOOD PLACE WEST BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-2032-87-
Application Year: 87
Issue Date: 11/27/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***J. COOKE DEVELOPMENTS LIMITED***
FAIRWOOD PLACE WEST BURLINGTON CITY ON

Database: ***CA***

Certificate #: 3-1938-86-
Application Year: 86
Issue Date: 3/11/1987
Approval Type: Municipal sewage
Status: Approved in 1987
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Regional Municipality of Halton***
Plains Road (Fairview Street) at QEW Interchange Burlington ON L6M 3L1

Database: ***ECA***

Approval No: 2522-6YZQ2Y
Approval Date: 2007-03-13
MOE District:
City:

Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	

Approval Type: ECA-Municipal Drinking Water Systems
Project Type: Municipal Drinking Water Systems
Business Name: The Regional Municipality of Halton
Address: Plains Road (Fairview Street) at QEW Interchange
Full Address:
Full PDF Link:
PDF Site Location:

Site: ***The Corporation of the City of Burlington***
Waterdown Rd Burlington ON L7R 3Z6

Database: ***ECA***

Approval No:	3214-9WQJSN	***MOE District:***	
Approval Date:	2015-05-26	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	

Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: The Corporation of the City of Burlington
Address: Waterdown Rd
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/9798-9WAPER-14.pdf
PDF Site Location:

Site: ***Brennan Paving Ltd***
Waterdown Rd Burlington ON

Database: ***GEN***

Generator No: ON5498956
SIC Code: 237310
SIC Description: HIGHWAY, STREET AND BRIDGE CONSTRUCTION
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Site: ***T C G MATERIALS LTD***
PO BOX 5000 LCD 1 ON L7R 3Y8

Database: ***SCT***

Established:
Plant Size (ft²): 0
Employment: 20

--Details--
Description: CONCRETE BLOCK & BRICK
SIC/NAICS Code: 3271

Site: ***CONSTRUCTION SITE***

Database:

DEVELOPMENT SITE AT THE N.W. CORNER OF PLAINS RD. & JOB'S LANE,OPPOSITE FRANCIS (N.O.S.) BURLINGTON CITY ON ***SPL***

Ref No:	41775	***Contaminant Qty:***	
Site No:		***Nature of Damage:***	
Incident Dt:	10/5/1990	***Discharger Report:***	
Year:		***Material Group:***	
Incident Cause:	OTHER CONTAINER LEAK	***Health/Env Conseq:***	
Incident Event:		***Agency Involved:***	HALTON REGION, BURLINGTON F.D.
Environment Impact:	CONFIRMED	***Site Lot:***	
Nature of Impact:	Soil contamination	***Site Conc:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Map Datum:***	
MOE Reported Dt:	10/5/1990	***Northing:***	
Dt Document Closed:		***Easting:***	
Municipality No:	14101		
System Facility Address:			
Client Type:			
Call Report Location Geodata:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	LAND		
Receiving Environment:			
Incident Reason:	EQUIPMENT FAILURE		
Incident Summary:	CARDEEN CONSTRUCTION - 20 L OF DIESEL FUEL TO GROUND FROM GENERATOR.		
Site Region:			
Site Municipality:	BURLINGTON CITY		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Source Type:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			

Site: ***TRANSPORT TRUCK PLAINS ROAD NEAR 403/401. MOTOR VEHICLE (OPERATING FLUID) BURLINGTON CITY ON*** ***Database:*** ***SPL***

Ref No:	80602	***Contaminant Qty:***	
Site No:		***Nature of Damage:***	
Incident Dt:	1/5/1993	***Discharger Report:***	
Year:		***Material Group:***	
Incident Cause:	TRUCK/TRAILER OVERTURN	***Health/Env Conseq:***	
Incident Event:		***Agency Involved:***	
Environment Impact:	NOT ANTICIPATED	***Site Lot:***	
Nature of Impact:		***Site Conc:***	
MOE Response:		***Site Geo Ref Accu:***	
Dt MOE Arvl on Scn:		***Site Map Datum:***	
MOE Reported Dt:	1/5/1993	***Northing:***	
Dt Document Closed:		***Easting:***	
Municipality No:	14101		
System Facility Address:			
Client Type:			
Call Report Location Geodata:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			

Receiving Medium:	LAND
Receiving Environment:	
Incident Reason:	ERROR
Incident Summary:	FREDERICK TRANSPORT-UNKN QTY DIESEL FUEL TO ROAD DUE TO TRUCK OVERTURN.
Site Region:	
Site Municipality:	BURLINGTON CITY
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Source Type:	
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	
Nearest Watercourse:	
Site Name:	
Site Address:	

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ***Note:*** *Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.*

Abandoned Aggregate Inventory: Provincial AAGR

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

Government Publication Date: Sept 2002*

Aggregate Inventory: Provincial AGR

The Ontario Ministry of Northern Development, Mines, Natural Resources and Forestry (ONDMNRF) maintains this database of pits and quarries. The database provides information regarding the registered owner/operator, location name, operation type, approval type, and maximum annual tonnage.

Government Publication Date: Up to Oct 2022

Abandoned Mine Information System: Provincial AMIS

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

Government Publication Date: 1800-Mar 2022

Anderson's Waste Disposal Sites: Private ANDR

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1860s-Present

Aboveground Storage Tanks: Provincial AST

Historical listing of aboveground storage tanks made available by the Department of Natural Resources and Forestry. Includes tanks used to hold water or petroleum. This dataset has been retired as of September 25, 2014 and will no longer be updated.

Government Publication Date: May 31, 2014

Automobile Wrecking & Supplies: Private AUWR

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

Government Publication Date: 1999-May 31, 2022

Borehole: Provincial BORE

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

Government Publication Date: 1875-Jul 2018

Certificates of Approval: Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

Government Publication Date: 1985-Oct 30, 2011*

Dry Cleaning Facilities: Federal CDRY

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.

Government Publication Date: Jan 2004-Dec 2021

Commercial Fuel Oil Tanks: Provincial CFOT

Locations of commercial underground fuel oil tanks. This is not a comprehensive or complete inventory of commercial fuel tanks in the province; this listing is a copy of records of registered commercial underground fuel oil tanks obtained under Access to Public Information.
Note that the following types of tanks do not require registration: waste oil tanks in apartments, office buildings, residences, etc.; aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Chemical Manufacturers and Distributors: Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

Government Publication Date: 1999-Jan 31, 2020

Chemical Register: Private CHM

This database includes a listing of locations of facilities within the Province or Territory that either manufacture and/or distributes chemicals.

Government Publication Date: 1999-May 31, 2022

Compressed Natural Gas Stations: Private CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

Government Publication Date: Dec 2012 -Sep 2022

Inventory of Coal Gasification Plants and Coal Tar Sites: Provincial COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

Government Publication Date: Apr 1987 and Nov 1988*

Compliance and Convictions: Provincial CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

Government Publication Date: 1989-Feb 2023

Certificates of Property Use: Provincial CPU

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

Government Publication Date: 1994 - Feb 28, 2023

Drill Hole Database: Provincial DRL

The Ontario Drill Hole Database contains information on more than 113,000 percussion, overburden, sonic and diamond drill holes from assessment files on record with the department of Mines and Minerals. Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted to the MNDM. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

Government Publication Date: 1886 - Oct 2022

Delisted Fuel Tanks: Provincial DTNK

List of fuel storage tank sites that were once found in - and have since been removed from - the list of fuel storage tanks made available by the regulatory agency under Access to Public Information.

Government Publication Date: Feb 28, 2022

Environmental Activity and Sector Registry: Provincial EASR

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval), Please see our ECA database.

Government Publication Date: Oct 2011- Feb 28, 2023

Environmental Registry: Provincial EBR

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

Government Publication Date: 1994 - Feb 28, 2023

Environmental Compliance Approval: Provincial ECA

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

Government Publication Date: Oct 2011- Feb 28, 2023

Environmental Effects Monitoring: Federal EEM

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

Government Publication Date: 1992-2007*

ERIS Historical Searches: Private EHS

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

Government Publication Date: 1999-Dec 31, 2022

Environmental Issues Inventory System: Federal EIIS

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

Government Publication Date: 1992-2001*

Emergency Management Historical Event: Provincial EMHE

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

Government Publication Date: Apr 30, 2022

Environmental Penalty Annual Report: Provincial EPAR

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment and Climate Change. These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

Government Publication Date: Jan 1, 2011 - Dec 31, 2021

List of Expired Fuels Safety Facilities: Provincial EXP

List of facilities and tanks for which there was once a fuel registration. This is not a comprehensive or complete inventory of expired tanks/tank facilities in the province; this listing is a copy of previously registered tanks and facilities obtained under Access to Public Information. Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc; includes tanks which have been removed from the ground.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Federal Convictions: Federal FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

Government Publication Date: 1988-Jun 2007*

Contaminated Sites on Federal Land: Federal FCS

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government. Includes fire training sites and sites at which Per- and Polyfluoroalkyl Substances (PFAS) are a concern.

Government Publication Date: Jun 2000-Dec 2022

Fisheries & Oceans Fuel Tanks: Federal FOFT

Fisheries & Oceans Canada maintains an inventory of aboveground & underground fuel storage tanks located on Fisheries & Oceans property or controlled by DFO. Our inventory provides information on the site name, location, tank owner, tank operator, facility type, storage tank location, tank contents & capacity, and date of tank installation.

Government Publication Date: 1964-Sep 2019

Federal Identification Registry for Storage Tank Systems (FIRSTS): Federal FRST

A list of federally regulated Storage tanks from the Federal Identification Registry for Storage Tank Systems (FIRSTS). FIRSTS is Environment and Climate Change Canada's database of storage tank systems subject to the Storage Tank for Petroleum Products and Allied Petroleum Products Regulations. The main objective of the Regulations is to prevent soil and groundwater contamination from storage tank systems located on federal and aboriginal lands. Storage tank systems that do not have a valid identification number displayed in a readily visible location on or near the storage tank system may be refused product delivery.

Government Publication Date: May 31, 2018

Fuel Storage Tank: Provincial FST

List of registered private and retail fuel storage tanks. This is not a comprehensive or complete inventory of private and retail fuel storage tanks in the province; this listing is a copy of registered private and retail fuel storage tanks, obtained under Access to Public Information.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Fuel Storage Tank - Historic: Provincial FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

Government Publication Date: Pre-Jan 2010*

Ontario Regulation 347 Waste Generators Summary: Provincial GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

Government Publication Date: 1986-Oct 31, 2022

Greenhouse Gas Emissions from Large Facilities: Federal GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO2 eq).

Government Publication Date: 2013-Dec 2019

TSSA Historic Incidents: Provincial HINC

List of historic incidences of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen recorded by the TSSA in their previous incident tracking system. The TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of historical fuel spills and leaks in the province. This listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: 2006-June 2009*

Indian & Northern Affairs Fuel Tanks: Federal IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

Government Publication Date: 1950-Aug 2003*

Fuel Oil Spills and Leaks: Provincial INC

Listing of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen reported to the Spills Action Centre (SAC). This is not a comprehensive or complete inventory of fuel-related leaks, spills, and incidents in the province; this listing in a copy of incidents reported to the SAC, obtained under Access to Public Information. Includes incidents from fuel-related hazards such as spills, fires, and explosions. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Landfill Inventory Management Ontario: Provincial LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the Ministry of the Environment, Conservation and Parks compiles new and updated information. Includes small and large landfills currently operating as well as those which are closed and historic. Operators of larger landfills provide landfill information for the previous operating year to the ministry for LIMO including: estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills include information such as site owner, site location and certificate of approval # and status.

Government Publication Date: Mar 21, 2022

Canadian Mine Locations: Private MINE

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

Government Publication Date: 1998-2009*

Mineral Occurrences: Provincial MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

Government Publication Date: 1846-Feb 2023

National Analysis of Trends in Emergencies System (NATES): Federal NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

Government Publication Date: 1974-1994*

Non-Compliance Reports: Provincial NCPL

The Ministry of the Environment provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act.

Government Publication Date: Dec 31, 2021

National Defense & Canadian Forces Fuel Tanks: Federal NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

Government Publication Date: Up to May 2001*

National Defense & Canadian Forces Spills: Federal NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

Government Publication Date: Mar 1999-Apr 2018

National Defence & Canadian Forces Waste Disposal Sites: Federal NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

Government Publication Date: 2001-Apr 2007*

National Energy Board Pipeline Incidents: Federal NEBI

Locations of pipeline incidents from 2008 to present, made available by the Canada Energy Regulator (CER) - previously the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

Government Publication Date: 2008-Jun 30, 2021

National Energy Board Wells: Federal NEBP

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release date.

Government Publication Date: 1920-Feb 2003*

National Environmental Emergencies System (NEES): Federal NEES

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December 2004.

Government Publication Date: 1974-2003*

National PCB Inventory: Federal NPCB

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

Government Publication Date: 1988-2008*

National Pollutant Release Inventory: Federal NPRI

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances.

Government Publication Date: 1993-May 2017

Oil and Gas Wells: Private OGWE

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

Government Publication Date: 1988-Nov 30, 2022

Ontario Oil and Gas Wells: Provincial OOGW

In 1998, the MNR handed over to the Ontario Oil, Gas and Salt Resources Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database include well owner/operator, location, permit issue date, and well cap date, license No., status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provide for each well record.

Government Publication Date: 1800-Aug 2021

Inventory of PCB Storage Sites: Provincial OPCB

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

Government Publication Date: 1987-Oct 2004; 2012-Dec 2013

Orders: Provincial ORD

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

Government Publication Date: 1994 - Feb 28, 2023

Canadian Pulp and Paper: Private PAP

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

Government Publication Date: 1999, 2002, 2004, 2005, 2009-2014

Parks Canada Fuel Storage Tanks: Federal PCFT

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

Government Publication Date: 1920-Jan 2005*

Pesticide Register: Provincial PES

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

Government Publication Date: Oct 2011- Feb 28, 2023

Pipeline Incidents: Provincial PINC

List of pipeline incidents (strikes, leaks, spills). This is not a comprehensive or complete inventory of pipeline incidents in the province; this listing in an historical copy of records previously obtained under Access to Public Information. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2021

Private and Retail Fuel Storage Tanks: Provincial PRT

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

Government Publication Date: 1989-1996*

Permit to Take Water: Provincial PTTW

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include PTTW's on the registry such as OWRA s. 34 - Permit to take water.

Government Publication Date: 1994 - Feb 28, 2023

Ontario Regulation 347 Waste Receivers Summary: Provincial REC

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

Government Publication Date: 1986-1990, 1992-2020

Record of Site Condition: Provincial RSC

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up.
RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09).

Government Publication Date: 1997-Sept 2001, Oct 2004-Feb 2023

Retail Fuel Storage Tanks: Private RST

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

Government Publication Date: 1999-May 31, 2022

Scott's Manufacturing Directory: Private SCT

Scott's Directories is a data bank containing information on over 200,000 manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, and main products are included in this database.

Government Publication Date: 1992-Mar 2011*

Ontario Spills: Provincial SPL

List of spills and incidents made available the Ministry of the Environment, Conservation and Parks. This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X. The Ministry of the Environment, Conservation and Parks cites the coronavirus pandemic as an explanation for delays in releasing data pursuant to requests.

Government Publication Date: 1988-Mar 2021; May 2021-Oct 2021

Wastewater Discharger Registration Database: Provincial SRDS

Facilities that report either municipal treated wastewater effluent or industrial wastewater discharges under the Effluent Monitoring and Effluent Limits (EMEL) and Municipal/Industrial Strategy for Abatement Regulations. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment keeps record of direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation, Mining, Petroleum Refining, Organic Chemicals, Inorganic Chemicals, Pulp & Paper, Metal Casting, Iron & Steel, and Quarries.

Government Publication Date: 1990-Dec 31, 2020

Anderson's Storage Tanks: Private TANK

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1915-1953*

Transport Canada Fuel Storage Tanks: Federal TCFT

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

Government Publication Date: 1970 - Apr 2020

Variances for Abandonment of Underground Storage Tanks: Provincial VAR

Listing of variances granted for storage tank abandonment. This is not a comprehensive or complete inventory of tank abandonment variances in the province; this listing is a copy of tank abandonment variance records previously obtained under Access to Public Information. In Ontario, registered underground storage tanks must be removed within two years of disuse; if removal of a tank is not feasible, an application may be sought for a variance from this code requirement.
Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Waste Disposal Sites - MOE CA Inventory: Provincial WDS

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

Government Publication Date: Oct 2011- Feb 28, 2023

Waste Disposal Sites - MOE 1991 Historical Approval Inventory: Provincial WDSH

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

Government Publication Date: Up to Oct 1990*

Water Well Information System: Provincial WWIS

This database describes locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table.

Government Publication Date: Jun 30 2022

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

APPENDIX F: CITY DIRECTORY SUMMARY

ERIS City Directory Search

as of 05/08/2023

Project Property: 1026 Cooke Boulevard - 1026 Cooke Boulevard, Burlington, ON L7T 4A8 CA

Product Description: CD - Subject Site plus 250m Radius

Notes to Client: Burlington, Ontario is listed until 1957.

ERIS Order No: 23041300087

ADDRESS	YEAR	LISTING	COMMENTS	SOURCE	CITY	COUNTY	STATE
982-992 BIRCHWOOD AVENUE	**2021**	**NO LISTING FOUND**		*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2007	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
	2002	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
	1997	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
	1992	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
	1987	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
	1982	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
	1977	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
	1972	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
	1967	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
	1960	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
	1957	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
990 BIRCHWOOD AVENUE	**2012**	**CIPPARONE, E A DDS**	*OFFICES OF DENTISTS*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2002	**DOCTOR**		*VERNONS*	BURLINGTON	HALTON	ON
	1997	**SANAVOK LTD**		*VERNONS*	BURLINGTON	HALTON	ON
	1997	**DOCTOR'S OFFICE**		*VERNONS*	BURLINGTON	HALTON	ON
	1992	**SANOVAK LTD**		*VERNONS*	BURLINGTON	HALTON	ON
	1992	**DOCTOR'S OFFICE**		*VERNONS*	BURLINGTON	HALTON	ON
	1987	**SANAVOK LTD**		*VERNONS*	BURLINGTON	HALTON	ON
	1987	**DENTAL SURGEON**		*VERNONS*	BURLINGTON	HALTON	ON
	1982	**DENTAL SURGEON**		*VERNONS*	BURLINGTON	HALTON	ON
	1977	**DENTAL SURGEON**		*VERNONS*	BURLINGTON	HALTON	ON
	1972	**DENTAL SURGEON**		*VERNONS*	BURLINGTON	HALTON	ON
	1960	**DENTIST**		*VERNONS*	BURLINGTON	HALTON	ON
	1957	**DENTIST**		*VERNONS*	BURLINGTON	HALTON	ON
992 BIRCHWOOD AVENUE	**2017**	**DRYSDALE DOLORES DDS**	*OFFICES OF DENTISTS*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2017	**CONFIDENT BRIGHT SMILES**	*OFFICES OF DENTISTS*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2012	**DRYSDALE, DOLORES DDS**	*OFFICES OF DENTISTS*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2007	**DOCTOR'S OFFICE**		*VERNONS*	BURLINGTON	HALTON	ON
	2002	**DOCTOR**		*VERNONS*	BURLINGTON	HALTON	ON
	1997	**DOCTOR'S OFFICE**		*VERNONS*	BURLINGTON	HALTON	ON
	1992	**DOCTOR**		*VERNONS*	BURLINGTON	HALTON	ON
	1987	**DENTAL SURGEON**		*VERNONS*	BURLINGTON	HALTON	ON
	1982	**DENTIST**		*VERNONS*	BURLINGTON	HALTON	ON
	1977	**DENTIST**		*VERNONS*	BURLINGTON	HALTON	ON
	1972	**DENTAL SURGEON**		*VERNONS*	BURLINGTON	HALTON	ON
	1960	**DENTIST**		*VERNONS*	BURLINGTON	HALTON	ON
1022-10721019-1045 CLEARVIEW AVENUE	**2021**	**NO LISTING FOUND**		*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
1022-1072, 1019-1045 CLEARVIEW AVENUI	**2007**	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON

	2002	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1997	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1992	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1987	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1982	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1977	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1972	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1967	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1960	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1957	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
1025 CLEARVIEW AVENUE	2017	A STREAMLINE MOBILE WASH	CAR WASHES	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	A STREAMLINE MOBILE WASH	CAR WASHES	DIGITAL BUSINESS DIREC	BURLINGTON		ON
1045 CLEARVIEW AVENUE	2017	RED PANT PRODUCTIONS	CONVENTION & T	DIGITAL BUSINESS DIREC	BURLINGTON		ON
1061 CLEARVIEW AVENUE	2002	PLYMOUTH BRETHEREN CHURCH		VERNONS	BURLINGTON	HALTON	ON
	1997	PLYMOUTH BRETHREN CHURCH		VERNONS	BURLINGTON	HALTON	ON
	1992	PLYMOUTH BRETHREN CHURCH		VERNONS	BURLINGTON	HALTON	ON
	1987	PLYMOUTH BRETHREN CHURCH		VERNONS	BURLINGTON	HALTON	ON
	1982	PLYMOUTH BRETHREN CHURCH		VERNONS	BURLINGTON	HALTON	ON
	1977	PLYMOUTH BRETHREN CHURCH		VERNONS	BURLINGTON	HALTON	ON
	1972	PLYMOUTH BRETHREN CHURCH		VERNONS	BURLINGTON	HALTON	ON
	1967	PLYMOUTH BRETHREN CHURCH		VERNONS	BURLINGTON	HALTON	ON
1025-1074 COOKE BOULEVARD	1992	STREET NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1987	STREET NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1982	NO LISTINGS WITHIN RADIUS		VERNONS	BURLINGTON	HALTON	ON
	1977	STREET NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1972	STREET NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1967	STREET NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1960	STREET NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1957	STREET NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
1026 COOKE BOULEVARD	2021	K D INSTALLATIONS	RACKS (WHLS); VENDI	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	EVERIK INTERNATIONAL INC	AUTOMOBILE PARTS &	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	BURLINGTON STEEL SYSTEMS	VENDING MACHINES-M	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	MEGBROOK HOLDINGS INC	ASSOCIATIONS; REAL E	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	D DE SIGNS	OTHER SVCS RELATED	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	MEGBROOK HOLDINGS INC	OTHER SVCS RELATED	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	CONTROTECH AUTOMATION	MISC GENERAL PURPO	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	D DE SIGNS	OTHER SVCS RELATED	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	CONTROTECH AUTOMATION	MISC GENERAL PURPO	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2007	DESIGNS		VERNONS	BURLINGTON	HALTON	ON
	2007	CONTROTECH AUTOMATION		VERNONS	BURLINGTON	HALTON	ON
	2002	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1997	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
1038 COOKE BOULEVARD	2021	O'DELL ASSOCIATES	RESTAURANT EQUIPM	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	DE LUCA ROOFING INC	ROOFING CONTRACTO	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	BURLINGTON PUMP INC	THAWING SERVICE	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	LEXTONER.COM	OFFICE SUPPLIES &	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	DE LUCA ROOFING INC	ROOFING CONTRS; RO	DIGITAL BUSINESS DIREC	BURLINGTON		ON

	2017	BURLINGTON PUMP INC	INDUSTRIAL MACHINE	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	O'DELL ASSOCIATE	PLUMBING & HV/	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	O'DELL ASSOC	PLUMBING & HV/	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	LEXTONER.COM	OFFICE SUPPLIES &	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	DE LUCA ROOFING INC	ROOFING CONTRS	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	BURLINGTON PUMP INC	INDUSTRIAL MACHINE	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	TEKSMART INC	OTHER COMPUTER REL	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	O'DELL ASSOC	PLUMBING & HV/	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2007	TEKSMART		VERNONS	BURLINGTON	HALTON	ON
	2007	DELUCA ROOFING		VERNONS	BURLINGTON	HALTON	ON
	2007	O'DELL ASSOC		VERNONS	BURLINGTON	HALTON	ON
	2007	LEXTONER.COM		VERNONS	BURLINGTON	HALTON	ON
	2002	LEXTONER.COM		VERNONS	BURLINGTON	HALTON	ON
	2002	BURLINGTON PUMP INC		VERNONS	BURLINGTON	HALTON	ON
	2002	DELUCA ROOFING INC		VERNONS	BURLINGTON	HALTON	ON
	2002	O'DELL ASSOCIATES		VERNONS	BURLINGTON	HALTON	ON
1047 COOKE BOULEVARD	2021	GENTHERM ELECTRONICS	ELECTRONIC RESEARCH	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	ETRATECH INC	RESEARCH & DEV	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	ETRATECH INC	RESEARCH & DEV	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2002	ETRATECH DESIGNS INC		VERNONS	BURLINGTON	HALTON	ON
1050 COOKE BOULEVARD	2021	INVESTIGATIVE SCIENCE INC	FEDERAL GOVERNMEN	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	PRIMARY FLUID SYSTEMS INC	VALVES-WHOLESALE	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	INVESTIGATIVE SCIENCE INC	OTHER TECHNICAL CO	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	PRIMARY FLUID SYSTEMS INC	OTHER METAL VALVE &	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	THERAPY HEALTH CARE INC	VOCATIONAL REHABILI	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	PRIMARY FLUID SYSTEMS INC	OTHER METAL VALVE &	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	INVESTIGATIVE SCIENCE INC	OTHER TECHNICAL CO	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2007	THERAPY HEALTH CARE INC		VERNONS	BURLINGTON	HALTON	ON
	2007	PRIMARY FLUID SYSTEMS INC		VERNONS	BURLINGTON	HALTON	ON
	2007	INVESTIGATIVE SCIENCE INC		VERNONS	BURLINGTON	HALTON	ON
	2002	PRIMARY FLUID INC		VERNONS	BURLINGTON	HALTON	ON
	2002	BHC CABLE ASSEMBLERS INC		VERNONS	BURLINGTON	HALTON	ON
	2002	INVESTIGATIVE SCIENCE		VERNONS	BURLINGTON	HALTON	ON
	1997	BRANTFORD SUB ASSEMBLY		VERNONS	BURLINGTON	HALTON	ON
1062 COOKE BOULEVARD	2021	CATEGORY 5 IMAGING LTD	COMMERCIAL PRINTIN	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	CATEGORY 5 IMAGING LTD	COMMERCIAL LITHOGI	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	MEDGAR LIGHTING GROUP INC	OTHER TECHNICAL CO	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	LAUREL OAK MARKETING LTD	MEDIA REPRESENTATI\	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	MEDGAR SALES LTD	OTHER TECHNICAL CO	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	MEDGAR LIGHTING GROUP INC	OTHER TECHNICAL CO	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2007	MEDGAR SALES		VERNONS	BURLINGTON	HALTON	ON
	2007	CATEGORY 5 IMAGING LTD		VERNONS	BURLINGTON	HALTON	ON
1074 COOKE BOULEVARD	2021	PV LABS	LABORATORIES; FEDER	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	BIZ MAGAZINE	MEDIA REPRESENTATI\	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	CANADIAN SPORTFISHING PRDCTN	MOTION PICTURE &amp	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	CONTROL SYSTEM INNOVATIONS	ELECTRIC EQUIP &amp	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	BIZ MAGAZINE	MEDIA REPRESENTATI\	DIGITAL BUSINESS DIREC	BURLINGTON		ON

	2012	CANADIAN SPORTFISHING PRDCTN	*MOTION PICTURE &amp*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2012	CONTROL SYSTEM INNOVATIONS	*ELECTRIC EQUIP &amp*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2012	TOWN PUBLISHING	*MEDIA REPRESENTATI*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2007	TOWN PUBLISHING INC		*VERNONS*	BURLINGTON	HALTON	ON
	2007	CANDIAN SPORT FISHING PRODUCTIONS INC		*VERNONS*	BURLINGTON	HALTON	ON
	2007	CONTROL SYSTEM INNOVATORS		*VERNONS*	BURLINGTON	HALTON	ON
	2002	ECLIPSE COLOUR INT LTD		*VERNONS*	BURLINGTON	HALTON	ON
	1997	ETRATECH DESIGN INC		*VERNONS*	BURLINGTON	HALTON	ON
1-59 Odd FAIRWOOD PLACE EAST	2007	ALL RESIDENTIAL		*VERNONS*	BURLINGTON	HALTON	ON
	2002	ALL RESIDENTIAL		*VERNONS*	BURLINGTON	HALTON	ON
	1997	ALL RESIDENTIAL		*VERNONS*	BURLINGTON	HALTON	ON
	1992	ALL RESIDENTIAL		*VERNONS*	BURLINGTON	HALTON	ON
	1987	ALL RESIDENTIAL		*VERNONS*	BURLINGTON	HALTON	ON
	1982	ALL RESIDENTIAL		*VERNONS*	BURLINGTON	HALTON	ON
	1977	ALL RESIDENTIAL		*VERNONS*	BURLINGTON	HALTON	ON
	1972	ALL RESIDENTIAL		*VERNONS*	BURLINGTON	HALTON	ON
	1967	ALL RESIDENTIAL		*VERNONS*	BURLINGTON	HALTON	ON
	1960	STREET NOT LISTED		*VERNONS*	BURLINGTON	HALTON	ON
	1957	STREET NOT LISTED		*VERNONS*	BURLINGTON	HALTON	ON
9 FAIRWOOD PLACE EAST	1997	GRAPHIC ENCOUNTER		*VERNONS*	BURLINGTON	HALTON	ON
15 FAIRWOOD PLACE EAST	1967	RESIDENTIAL (1 TENANT)		*VERNONS*	BURLINGTON	HALTON	ON
19 FAIRWOOD PLACE EAST	1967	RESIDENTIAL (1 TENANT)		*VERNONS*	BURLINGTON	HALTON	ON
53 FAIRWOOD PLACE EAST	2021	DUTCHMAN'S LANDSCAPING	*GARDEN CENTERS*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2017	DUTCHMAN'S LANDSCAPING	*LANDSCAPING SVCS*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2012	DUTCHMAN'S LANDSCAPING	*LANDSCAPE CONTRACT*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2007	DUTCHMAN'S LANDSCAPING		*VERNONS*	BURLINGTON	HALTON	ON
	2002	DUTCHMAN'S LANDSCAPING		*VERNONS*	BURLINGTON	HALTON	ON
1-19 FAIRWOOD PLACE WEST	2021	NO LISTING FOUND		*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2017	NO LISTING FOUND		*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2012	NO LISTING FOUND		*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
1-19 Odd FAIRWOOD PLACE WEST	2002	ALL RESIDENTIAL		*VERNONS*	BURLINGTON	HALTON	ON
	1992	ALL RESIDENTIAL		*VERNONS*	BURLINGTON	HALTON	ON
	1987	ALL RESIDENTIAL		*VERNONS*	BURLINGTON	HALTON	ON
	1960	STREET NOT LISTED		*VERNONS*	BURLINGTON	HALTON	ON
	1957	STREET NOT LISTED		*VERNONS*	BURLINGTON	HALTON	ON
15 FAIRWOOD PLACE WEST	2007	RESIDENTIAL (1 TENANT)		*VERNONS*	BURLINGTON	HALTON	ON
	1997	RESIDENTIAL (1 TENANT)		*VERNONS*	BURLINGTON	HALTON	ON
	1982	RESIDENTIAL (1 TENANT)		*VERNONS*	BURLINGTON	HALTON	ON
	1977	RESIDENTIAL (1 TENANT)		*VERNONS*	BURLINGTON	HALTON	ON
	1972	RESIDENTIAL (1 TENANT)		*VERNONS*	BURLINGTON	HALTON	ON
19 FAIRWOOD PLACE WEST	2007	RESIDENTIAL (1 TENANT)		*VERNONS*	BURLINGTON	HALTON	ON
	1997	RESIDENTIAL (1 TENANT)		*VERNONS*	BURLINGTON	HALTON	ON
	1982	RESIDENTIAL (1 TENANT)		*VERNONS*	BURLINGTON	HALTON	ON
	1977	RESIDENTIAL (1 TENANT)		*VERNONS*	BURLINGTON	HALTON	ON
	1972	RESIDENTIAL (1 TENANT)		*VERNONS*	BURLINGTON	HALTON	ON
979-987 LASALLE PARK ROAD	2021	NO LISTING FOUND		*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2012	NO LISTING FOUND		*DIGITAL BUSINESS DIREC*	BURLINGTON		ON

	2007	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
	2002	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
	1997	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
	1992	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
	1987	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
	1982	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
979 LASALLE PARK ROAD	**1977**	**GREEN'S FLOWER SHOP**		*VERNONS*	BURLINGTON	HALTON	ON
979-987 LASALLE PARK ROAD	**1977**	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
979 LASALLE PARK ROAD	**1977**	**OLD FRIENDS ANTIQUES**		*VERNONS*	BURLINGTON	HALTON	ON
	1972	**GREEN'S FLOWER SHOP**		*VERNONS*	BURLINGTON	HALTON	ON
979-987 LASALLE PARK ROAD	**1972**	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
979 LASALLE PARK ROAD	**1967**	**GREEN'S FLOWER SHOP**		*VERNONS*	BURLINGTON	HALTON	ON
979-987 LASALLE PARK ROAD	**1967**	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
	1960	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
	1957	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
982 LASALLE PARK ROAD	**2017**	**ROBINSON DE PUGA INTERIORS**	*INTERIOR DESIGN SVCS*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
2 MASONRY COURT	**2021**	**BHC**	*WIRE HARNESSES-ELEC*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2021	**COUGAR SHOES INC**	*SHOES-WHOLESALE*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2017	**BHC**	*COMPUTERS & EL*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2017	**GP2 INC**	*MUSICAL INSTRUMEN*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2012	**BHC**	*ELECTRIC EQUIP &amp*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2007	**BHC**		*VERNONS*	BURLINGTON	HALTON	ON
	2002	**ADDRESS NOT LISTED**		*VERNONS*	BURLINGTON	HALTON	ON
	1997	**STREET NOT LISTED**		*VERNONS*	BURLINGTON	HALTON	ON
	1992	**STREET NOT LISTED**		*VERNONS*	BURLINGTON	HALTON	ON
	1987	**STREET NOT LISTED**		*VERNONS*	BURLINGTON	HALTON	ON
	1982	**STREET NOT LISTED**		*VERNONS*	BURLINGTON	HALTON	ON
	1977	**STREET NOT LISTED**		*VERNONS*	BURLINGTON	HALTON	ON
	1972	**STREET NOT LISTED**		*VERNONS*	BURLINGTON	HALTON	ON
	1967	**STREET NOT LISTED**		*VERNONS*	BURLINGTON	HALTON	ON
	1960	**STREET NOT LISTED**		*VERNONS*	BURLINGTON	HALTON	ON
	1957	**STREET NOT LISTED**		*VERNONS*	BURLINGTON	HALTON	ON
1 PLAINS ROAD EAST	**2021**	**SUN COUNTRY LEISURE PRODUCTS**	*FURNITURE-OUTDOOR*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2017	**MURRAY'S VARIETY**	*ALL OTHER GENERAL M*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2012	**MURRAY'S VARIETY**	*ALL OTHER GENERAL M*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2007	**MURRAY'S VARIETIES**		*VERNONS*	BURLINGTON	HALTON	ON
	2002	**MURRAY'S VARIETIES**		*VERNONS*	BURLINGTON	HALTON	ON
1-91 PLAINS ROAD EAST	**2002**	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
1 PLAINS ROAD EAST	**1997**	**MURRAY'S VARIETIES**		*VERNONS*	BURLINGTON	HALTON	ON
1-91 PLAINS ROAD EAST	**1997**	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
1 PLAINS ROAD EAST	**1992**	**MURRAY'S HOME VARIETIES**		*VERNONS*	BURLINGTON	HALTON	ON
1-91 PLAINS ROAD EAST	**1992**	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
1 PLAINS ROAD EAST	**1987**	**MURRAY'S VARIETIES**		*VERNONS*	BURLINGTON	HALTON	ON
1-91 PLAINS ROAD EAST	**1987**	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
1 PLAINS ROAD EAST	**1982**	**MURRAY' VARIETY**		*VERNONS*	BURLINGTON	HALTON	ON
1-91 PLAINS ROAD EAST	**1982**	**ALL RESIDENTIAL**		*VERNONS*	BURLINGTON	HALTON	ON
1 PLAINS ROAD EAST	**1977**	**MURRAY'S VARIETY**		*VERNONS*	BURLINGTON	HALTON	ON

1-91 PLAINS ROAD EAST	1977	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
1 PLAINS ROAD EAST	1972	MURRAY'S VARIETY		VERNONS	BURLINGTON	HALTON	ON
	1967	RUDOLPH'S VARIETY STORE		VERNONS	BURLINGTON	HALTON	ON
1-91 PLAINS ROAD EAST	1967	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
1 PLAINS ROAD EAST	1960	RUDOLF'S VARIETY STORE		VERNONS	BURLINGTON	HALTON	ON
1-91 PLAINS ROAD EAST	1960	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1957	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
2 PLAINS ROAD EAST	2017	SOL EXOTICA	UNCLASSIFIED	DIGITAL BUSINESS DIREC	BURLINGTON		ON
3 PLAINS ROAD EAST	2017	SUN COUNTRY LEISURE PRODUCTS	ALL OTHER GENERAL M	DIGITAL BUSINESS DIREC	BURLINGTON		ON
5 PLAINS ROAD EAST	2021	HYPE SYSTEMS INC	COMPUTERS-SYSTEM D	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	1957	DE LA SALLE CLEANERS		VERNONS	BURLINGTON	HALTON	ON
14 PLAINS ROAD EAST	2021	ESSO	ALTERNATIVE FUELS	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	TIM HORTONS	COFFEE SHOPS	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	CIRCLE K	CONVENIENCE STORES	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	TIM HORTONS	SNACK & NONALC	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	MAC'S CONVENIENCE STORE	CONVENIENCE STORES	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	MAC'S CONVENIENCE STORES LTD	CONVENIENCE STORES	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2007	MAC'S CONVENIENCE STORE		VERNONS	BURLINGTON	HALTON	ON
	2002	MAC'S CONVENIENCE		VERNONS	BURLINGTON	HALTON	ON
	1997	MAC'S CONVENIENCE STORE		VERNONS	BURLINGTON	HALTON	ON
	1987	MORE ESSO SERVICE		VERNONS	BURLINGTON	HALTON	ON
	1987	MOORE AUTO SERVICE		VERNONS	BURLINGTON	HALTON	ON
	1982	ALDERSHOT AUTOMOTIVE SELF SERVICE STALTION		VERNONS	BURLINGTON	HALTON	ON
	1977	THOMPSON JACK SLEF SERV ESSO STATION		VERNONS	BURLINGTON	HALTON	ON
	1972	LA SALLE ESSO SERV STN		VERNONS	BURLINGTON	HALTON	ON
	1967	BURL ESSO NO 2		VERNONS	BURLINGTON	HALTON	ON
	1960	LLOYD'S ESSO SERVICE STATION		VERNONS	BURLINGTON	HALTON	ON
	1957	JIM & ED'S SERVICE CENTER		VERNONS	BURLINGTON	HALTON	ON
15 PLAINS ROAD EAST	2021	ATM	AUTOMATED TELLER M	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	RBC ROYAL BANK	REAL ESTATE LOANS	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	RBC ROYAL BANK	COMMERCIAL BANKIN	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	ACCELERATED CONNECTIONS	UNCLASSIFIED	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	ACCELERATED CONNECTIONS	UNCLASSIFIED	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	ROYAL BANK FINANCIAL GROUP	COMMERCIAL BANKIN	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2007	RBC		VERNONS	BURLINGTON	HALTON	ON
	2007	ACCELERATED CONNECTIONS		VERNONS	BURLINGTON	HALTON	ON
	2002	ROYAL BANK OF MONTREAL		VERNONS	BURLINGTON	HALTON	ON
	1997	ROYAL BANK OF CANADA		VERNONS	BURLINGTON	HALTON	ON
	1992	ROYAL BANK OF CANADA		VERNONS	BURLINGTON	HALTON	ON
	1987	ROYAL BANK OF CANADA		VERNONS	BURLINGTON	HALTON	ON
	1982	THE ROYAL BANK OF CANADA		VERNONS	BURLINGTON	HALTON	ON
	1977	ROYAL BANK OF CANADA		VERNONS	BURLINGTON	HALTON	ON
	1972	THE ROYAL BANK OF CANADA		VERNONS	BURLINGTON	HALTON	ON
	1967	ROYAL BANK OF CANADA		VERNONS	BURLINGTON	HALTON	ON
	1960	ROYAL BANK OF CANADA		VERNONS	BURLINGTON	HALTON	ON
	1957	ROYAL BANK OF CANADA		VERNONS	BURLINGTON	HALTON	ON
18 PLAINS ROAD EAST	1957	LA SALLE RESTR		VERNONS	BURLINGTON	HALTON	ON

20 PLAINS ROAD EAST	2021	RUSSELL WILLIAMS RESTAURANTS	*FOODS-CARRY OUT*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2017	RUSSELL WILLIAMS RESTAURANTS	*FULLSERVICE RESTAUR*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2012	RUSSELL WILLIAMS RESTAURANTS	*FULL-SERVICE RESTAUI*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2007	RUSSELL WILLIAMS RESTAURANT LTD		*VERNONS*	BURLINGTON	HALTON	ON
	2002	RUSSEL WILLIAMS RESTAURANTS LTD		*VERNONS*	BURLINGTON	HALTON	ON
	1997	RUSSELL WILLIAMS		*VERNONS*	BURLINGTON	HALTON	ON
	1992	RUSSELL WILLIAMS RESTAURANTS LTD		*VERNONS*	BURLINGTON	HALTON	ON
	1987	RUSSELL WILLIAMS RESTAURANTS LTD		*VERNONS*	BURLINGTON	HALTON	ON
	1982	RUSSELL WILLIAMS RESTAURANT		*VERNONS*	BURLINGTON	HALTON	ON
	1977	RUSSELL WILLIAMS RESTAURANT		*VERNONS*	BURLINGTON	HALTON	ON
	1972	RUSSELL WILLIAMS RESTRAURANT		*VERNONS*	BURLINGTON	HALTON	ON
	1967	RUSSELL WILLIAMS RESTR		*VERNONS*	BURLINGTON	HALTON	ON
	1957	MARGARET'S BTY SALON		*VERNONS*	BURLINGTON	HALTON	ON
26 PLAINS ROAD EAST	2017	GOLDEN SCISSORS ALTERATIONS	*OTHER CLOTHING STOI*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2012	GOLDEN SCISSORS ALTERATIONS	*OTHER CLOTHING STOI*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2007	GOLDEN SCISSORS ALTERATIONS		*VERNONS*	BURLINGTON	HALTON	ON
	2002	SMOOTHIE KINGS		*VERNONS*	BURLINGTON	HALTON	ON
	1982	MADY'S HAIR FASHIONS		*VERNONS*	BURLINGTON	HALTON	ON
	1977	MADY'S AHIR FASHIONS		*VERNONS*	BURLINGTON	HALTON	ON
	1972	MADY'S HAIR FASHIONS		*VERNONS*	BURLINGTON	HALTON	ON
	1967	MADY'S HAIR FASHIONS		*VERNONS*	BURLINGTON	HALTON	ON
	1960	MARGARET'S BTY SALON		*VERNONS*	BURLINGTON	HALTON	ON
27 PLAINS ROAD EAST	1967	ALDERSHOT LANDSCAPE & CONTRACTING LTD		*VERNONS*	BURLINGTON	HALTON	ON
	1960	ALDERSHOT LANDSCAPING		*VERNONS*	BURLINGTON	HALTON	ON
28 PLAINS ROAD EAST	2017	HASTY MARKET	*SUPERMARKETS &amp*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2017	KREATIVE KHAOS PIERCING	*ALL OTHER PERSONAL*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2012	KREATIVE KHAOS PIERCING	*ALL OTHER PERSONAL*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2012	FARAH FOOD LTD-HASTY MARKET	*SUPERMARKETS &amp*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2007	KREATIVE KHAOS PIERCINGS		*VERNONS*	BURLINGTON	HALTON	ON
	1997	FARAH FOOD LTD		*VERNONS*	BURLINGTON	HALTON	ON
	1997	HASTY MARKET CORP		*VERNONS*	BURLINGTON	HALTON	ON
	1987	TARA TRAVEL INC		*VERNONS*	BURLINGTON	HALTON	ON
	1982	NEPTUNE MARINE		*VERNONS*	BURLINGTON	HALTON	ON
	1977	MOBY DICK SUPER SUB		*VERNONS*	BURLINGTON	HALTON	ON
	1972	STONEY CREEK DAIRIES LTD		*VERNONS*	BURLINGTON	HALTON	ON
	1967	STONEY CREEK DAIRIES LTD		*VERNONS*	BURLINGTON	HALTON	ON
	1960	ALDERSHOT FLORIST		*VERNONS*	BURLINGTON	HALTON	ON
	1957	ALDERSHOT FLORIST		*VERNONS*	BURLINGTON	HALTON	ON
30 PLAINS ROAD EAST	2021	BETTER BUSINESS MACHINES	*COPYING & DUPL*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2017	BETTER BUSINESS MACHINES	*OFFICE EQUIP MERCHA*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2012	BETTER BUSINESS MACHINES	*OFFICE EQUIP MERCHA*	*DIGITAL BUSINESS DIREC*	BURLINGTON		ON
	2007	BETTER BUSINESS MACHINES		*VERNONS*	BURLINGTON	HALTON	ON
	2002	BETTER BUSINESS BUREAU		*VERNONS*	BURLINGTON	HALTON	ON
	1992	DEREK'S MOBILT TV SERVICE APPLIANCES		*VERNONS*	BURLINGTON	HALTON	ON
	1987	PHOTO LAB		*VERNONS*	BURLINGTON	HALTON	ON
	1977	PHOTO LAB		*VERNONS*	BURLINGTON	HALTON	ON
	1972	SWEET-N-KLEEN LAUNDRETTE		*VERNONS*	BURLINGTON	HALTON	ON

	1967	SWEET-N-KLEEN LAUNDRETTE		VERNONS	BURLINGTON	HALTON	ON
	1960	SWEET-N-KLEEN LAUNDRETTE		VERNONS	BURLINGTON	HALTON	ON
	1957	SWEET-N-KLEEN LAUNDRETTE		VERNONS	BURLINGTON	HALTON	ON
32 PLAINS ROAD EAST	1977	HORTECH RESEARCH LTD		VERNONS	BURLINGTON	HALTON	ON
34 PLAINS ROAD EAST	2017	PIZZA ROYALE	LIMITEDSERVICE RESTA	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	MIN A MART	ALL OTHER GENERAL M	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2007	VARIETY MIN-A-MART		VERNONS	BURLINGTON	HALTON	ON
	2002	STONEY CREEK DAIRY & VARIETY STORE		VERNONS	BURLINGTON	HALTON	ON
	1997	STONEY CREEK DAIRY & VARIETY STORE		VERNONS	BURLINGTON	HALTON	ON
	1992	STONEY CREEK DAIRY & VARIETY STORE		VERNONS	BURLINGTON	HALTON	ON
	1987	STONEY CREEK DAIRY & VARIETY		VERNONS	BURLINGTON	HALTON	ON
	1982	STONEY CREEK DAIRY & VARIETY STORE		VERNONS	BURLINGTON	HALTON	ON
	1977	STONEY CREEK DAIRIES LTD STORES		VERNONS	BURLINGTON	HALTON	ON
	1972	THOMSON'S DRUG STORE		VERNONS	BURLINGTON	HALTON	ON
	1967	DRUG STORE		VERNONS	BURLINGTON	HALTON	ON
	1960	HUFFMAN'S DRUG STORE		VERNONS	BURLINGTON	HALTON	ON
35 PLAINS ROAD EAST	1992	WINDSHIELD DOCTOR		VERNONS	BURLINGTON	HALTON	ON
	1992	O'REILLEY PAT AUTO LTD		VERNONS	BURLINGTON	HALTON	ON
	1987	SEARS RENT A CAR		VERNONS	BURLINGTON	HALTON	ON
	1987	WINDSHIELD DOCTOR		VERNONS	BURLINGTON	HALTON	ON
	1987	BUDGET RENT A CAR		VERNONS	BURLINGTON	HALTON	ON
	1982	SEARS RENT A CAR		VERNONS	BURLINGTON	HALTON	ON
	1982	BUDGET RENT A CAR		VERNONS	BURLINGTON	HALTON	ON
	1977	ALDERSHOT LANDSCPAE CONTRACTORS LTD		VERNONS	BURLINGTON	HALTON	ON
	1972	ALDERSHOT LANDSCAPE		VERNONS	BURLINGTON	HALTON	ON
	1960	JIM & ED'S SERV STN		VERNONS	BURLINGTON	HALTON	ON
50 PLAINS ROAD EAST	2017	CLAIRMONT R	ELECTRICAL CONTRS	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	CLAIMONT, R	ELECTRICAL CONTRS	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	ROBERT CLAIRMONT & SONS	ELECTRICAL CONTRS; E	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2007	ROBERT CLAIRMONT & SONS CONTRACTING		VERNONS	BURLINGTON	HALTON	ON
	2002	ROBERT & SONS		VERNONS	BURLINGTON	HALTON	ON
	1997	CLAIRMONT & SONS CONTRACTING		VERNONS	BURLINGTON	HALTON	ON
	1992	BURLINGTON CAPE CORAL		VERNONS	BURLINGTON	HALTON	ON
	1992	CLAIRMONT & SONS CONTRACTING		VERNONS	BURLINGTON	HALTON	ON
53 PLAINS ROAD EAST	2021	SOLID GOLD	FOODS-CARRY OUT	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	SOLID GOLD	FULLSERVICE RESTAUR	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	SOLID GOLD	FULL-SERVICE RESTAUI	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2007	SOLID GOLD		VERNONS	BURLINGTON	HALTON	ON
	2002	SOLID GOLD		VERNONS	BURLINGTON	HALTON	ON
	1997	SOLID GOLD		VERNONS	BURLINGTON	HALTON	ON
	1992	SOLID GOLD		VERNONS	BURLINGTON	HALTON	ON
	1987	BENJIES MOTOR HOTEL		VERNONS	BURLINGTON	HALTON	ON
	1982	BENJIES MOTEL & DINING LOUNGE		VERNONS	BURLINGTON	HALTON	ON
	1977	JOLLY 6 PENCE MOTEL & TAVERN		VERNONS	BURLINGTON	HALTON	ON
	1972	PARK LANE MOTEL		VERNONS	BURLINGTON	HALTON	ON
	1967	PARK LANE MOTEL		VERNONS	BURLINGTON	HALTON	ON
	1960	PARK LANE MOTEL		VERNONS	BURLINGTON	HALTON	ON

	1957	PARK LANE MOTEL		VERNONS	BURLINGTON	HALTON	ON
70 PLAINS ROAD EAST	2012	MURRAY WHOLESALE CASH & CARRY	OFFICE SUPPLIES MERC	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2007	MURRAY WHOLESALE CASH & CARRY		VERNONS	BURLINGTON	HALTON	ON
	2002	MURRAY WHOLESALE CASH & CARRY		VERNONS	BURLINGTON	HALTON	ON
	1997	MURRAY WHOLESALE GIFT SOUVENIRS		VERNONS	BURLINGTON	HALTON	ON
	1992	MURRAY WHOLESALE GIFT SOUVENIRS		VERNONS	BURLINGTON	HALTON	ON
	1987	WHOLESALE GIFT SOUVENIRS		VERNONS	BURLINGTON	HALTON	ON
	1982	MURRAY WHOLESALE		VERNONS	BURLINGTON	HALTON	ON
	1977	MURRAY WHOLSESALE GIFTS		VERNONS	BURLINGTON	HALTON	ON
	1972	ELAINE BEAUTY SALON		VERNONS	BURLINGTON	HALTON	ON
71 PLAINS ROAD EAST	1987	AVIS RENT A CAR		VERNONS	BURLINGTON	HALTON	ON
	1987	BURLINGTON RIDE CENTER		VERNONS	BURLINGTON	HALTON	ON
	1987	BURLINGTON SUZUKI		VERNONS	BURLINGTON	HALTON	ON
	1977	SEARS RENT A CAR		VERNONS	BURLINGTON	HALTON	ON
	1977	BUDGET RENT A CAR		VERNONS	BURLINGTON	HALTON	ON
	1960	SERVICE STATION		VERNONS	BURLINGTON	HALTON	ON
91 PLAINS ROAD EAST	2021	ABBEY STAINED GLASS	GLASS-STAINED &	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	EIGHTH EMPIRE TATTOOS PRCNGS	TATTOOING	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	KIPPLINGS HAIR SALON	BEAUTY SALONS	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	PETROPARTNERS	OTHER PETROLEUM M	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	FENWORTH FLORIDA HOMES CONDO	TRAVEL AGENCIES	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	KREATIVE KHAOS TATTOOING	ALL OTHER PERSONAL	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	KLIPPINGS HAIR SALON	BEAUTY SALONS	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	ABBEY STAINED GLASS	OTHER BUILDING MAT	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	FENWORTH TRAVEL	TRAVEL AGENCIES	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	PETROPARTNERS	OTHER PETROLEUM M	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	FENWORTH FLORIDA HOMES & CONDO	TRAVEL AGENCIES	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	FENWORTH TRAVEL WAREHOUSE	TRAVEL AGENCIES	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	KLIPPINGS HAIR SALON	BEAUTY SALONS	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	ABBEY STAINED GLASS	OTHER BUILDING MAT	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2007	ABBEY STAINED GLASS		VERNONS	BURLINGTON	HALTON	ON
	2007	KLIPPINGS HAIR SALON INC		VERNONS	BURLINGTON	HALTON	ON
	2002	SPANISH TOUCH		VERNONS	BURLINGTON	HALTON	ON
	2002	ABBEY STAINED GLASS		VERNONS	BURLINGTON	HALTON	ON
	2002	PETRO PARTNERS		VERNONS	BURLINGTON	HALTON	ON
	1997	PETRO APARTMENTS		VERNONS	BURLINGTON	HALTON	ON
	1997	VIKING NORSTAR DEVELOPMENT CORP		VERNONS	BURLINGTON	HALTON	ON
	1992	NATURE'S BASKET NATURAL FOODS		VERNONS	BURLINGTON	HALTON	ON
	1987	GARDNER OFFICE EQUIPMENT		VERNONS	BURLINGTON	HALTON	ON
	1982	SIR LOIN STEAKS		VERNONS	BURLINGTON	HALTON	ON
	1982	HURLEY INSURANCE BROKER LTD		VERNONS	BURLINGTON	HALTON	ON
	1982	MUNEL ENTERPRISES		VERNONS	BURLINGTON	HALTON	ON
	1982	THE MUNRO GROUP		VERNONS	BURLINGTON	HALTON	ON
91-99 PLAINS ROAD EAST	1977	ROYAL MOTEL		VERNONS	BURLINGTON	HALTON	ON
91 PLAINS ROAD EAST	1972	GLEN COURT MOTEL		VERNONS	BURLINGTON	HALTON	ON
	1960	GLEN COURT MOTEL		VERNONS	BURLINGTON	HALTON	ON
	1957	GLEN COURT MOTEL		VERNONS	BURLINGTON	HALTON	ON

1-29 PLAINS ROAD WEST	**1997**	**ALL RESIDENTIAL**	*VERNONS*	BURLINGTON	HALTON	ON
	1992	**ALL RESIDENTIAL**	*VERNONS*	BURLINGTON	HALTON	ON
	1982	**ALL RESIDENTIAL**	*VERNONS*	BURLINGTON	HALTON	ON
	1977	**ALL RESIDENTIAL**	*VERNONS*	BURLINGTON	HALTON	ON
	1967	**ALL RESIDENTIAL**	*VERNONS*	BURLINGTON	HALTON	ON
	1967	**WEST PLAINS SUPERTEST SERV STN**	*VERNONS*	BURLINGTON	HALTON	ON
	1960	**ALL RESIDENTIAL**	*VERNONS*	BURLINGTON	HALTON	ON
2 PLAINS ROAD WEST	**1960**	**CONNIE'S COFFEE SHOP**	*VERNONS*	BURLINGTON	HALTON	ON
	1957	**YOUR FRIENDLY COFFEE SHOP**	*VERNONS*	BURLINGTON	HALTON	ON
6 PLAINS ROAD WEST	**1957**	**BARBER**	*VERNONS*	BURLINGTON	HALTON	ON
7 PLAINS ROAD WEST	**2021**	**NICHE FOR DESIGN**	*MAPPING SERVICES (W* DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	**JERRY'S AUTOMOTIVE**	*AUTOMOBILE INSPECT* DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	**JERRY'S AUTOMOTIVE**	*ALL OTHER AUTOMOTI* DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	**RAY'S AUTO CTR TOWING**	*MOTOR VEHICLE TOWI* DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	**JERRY'S AUTOMOTIVE**	*GENERAL AUTOMOTIV* DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	**RAY'S AUTO CTR & TOWING**	*MOTOR VEHICLE TOWI* DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2007	**JERRY'S AUTO**	*VERNONS*	BURLINGTON	HALTON	ON
	2007	**RAY'S AUTO CENTRE & TOWING**	*VERNONS*	BURLINGTON	HALTON	ON
	2002	**JERRY'S AUTO**	*VERNONS*	BURLINGTON	HALTON	ON
	2002	**RAY'S AUTO CENTER & TOWING**	*VERNONS*	BURLINGTON	HALTON	ON
	1997	**JERRY'S AUTO**	*VERNONS*	BURLINGTON	HALTON	ON
	1992	**TED'S SERVICE CENTER**	*VERNONS*	BURLINGTON	HALTON	ON
	1992	**PLAINS WEST SUPERTEST**	*VERNONS*	BURLINGTON	HALTON	ON
	1987	**TED'S SERVICE CENTER**	*VERNONS*	BURLINGTON	HALTON	ON
	1987	**PLAINS WEST PETRO-CANADA**	*VERNONS*	BURLINGTON	HALTON	ON
	1982	**TED'S SERVICE CENTER**	*VERNONS*	BURLINGTON	HALTON	ON
	1982	**PLAIN WEST BP SERVICE STATION**	*VERNONS*	BURLINGTON	HALTON	ON
	1977	**TED'S SERVICE CENTER**	*VERNONS*	BURLINGTON	HALTON	ON
	1977	**PLAINS WEST BP SERVICE STATION**	*VERNONS*	BURLINGTON	HALTON	ON
	1972	**PLAINS WEST SUPERTEST SERV STN**	*VERNONS*	BURLINGTON	HALTON	ON
	1967	**JOE'S BARBER SHOP**	*VERNONS*	BURLINGTON	HALTON	ON
	1960	**ABC TAXI**	*VERNONS*	BURLINGTON	HALTON	ON
	1960	**ALEX'S SUPERTEST STN**	*VERNONS*	BURLINGTON	HALTON	ON
	1960	**LA BELLE SNACK BAR**	*VERNONS*	BURLINGTON	HALTON	ON
	1957	**SERVICE STN**	*VERNONS*	BURLINGTON	HALTON	ON
	1957	**GEORGE'S LUNCH ROOM**	*VERNONS*	BURLINGTON	HALTON	ON
8 PLAINS ROAD WEST	**1960**	**DE LA SALLE CLEANERS**	*VERNONS*	BURLINGTON	HALTON	ON
	1957	**RUDOLF'S VARIETY STORE**	*VERNONS*	BURLINGTON	HALTON	ON
12 PLAINS ROAD WEST	**1982**	**ALDERSHOT RECREATIONS EQUIPMENT RENTAL LTD**	*VERNONS*	BURLINGTON	HALTON	ON
	1977	**MURRAY'S RESTAURANT**	*VERNONS*	BURLINGTON	HALTON	ON
	1972	**MARY'S LUNCH**	*VERNONS*	BURLINGTON	HALTON	ON
	1967	**MARY'S LUNCH**	*VERNONS*	BURLINGTON	HALTON	ON
14 PLAINS ROAD WEST	**1987**	**GINO MOBILE REPAIR LTD**	*VERNONS*	BURLINGTON	HALTON	ON
	1987	**GREER DAN ENTERPRISES LTD**	*VERNONS*	BURLINGTON	HALTON	ON
	1982	**ALDERSHOT TRANSPORTATION INC**	*VERNONS*	BURLINGTON	HALTON	ON
	1982	**ALDERSHOT CARRY-ALL SERVICE LTD**	*VERNONS*	BURLINGTON	HALTON	ON
	1977	**ALDERSHOT CARRY-ALL SERVICE LTD**	*VERNONS*	BURLINGTON	HALTON	ON

	1977	ALDERSHOT RECREATIONAL EQUIPMENT RENTAL LTD		VERNONS	BURLINGTON	HALTON	ON
	1977	ALDERSHOT STEVEDORING & FORWARDING LTD		VERNONS	BURLINGTON	HALTON	ON
	1977	BURLINGTON EQUIPMENT RENTAL LTD		VERNONS	BURLINGTON	HALTON	ON
	1972	BURL EQUIP RENTL LTD		VERNONS	BURLINGTON	HALTON	ON
	1972	ALDERSHOT CONTRS EQUIP RENTL		VERNONS	BURLINGTON	HALTON	ON
	1972	ALDERSHOT FORWARDING LTD		VERNONS	BURLINGTON	HALTON	ON
	1972	ALDERSHOT CARRY-ALL LTD		VERNONS	BURLINGTON	HALTON	ON
	1967	ALDERSHOT CARRY-ALL-LTD		VERNONS	BURLINGTON	HALTON	ON
	1967	ALDERSHOT STEVEDORING & FORWARDING LTD		VERNONS	BURLINGTON	HALTON	ON
	1967	ALDERSHOT CONTRS EQUIPMENT RENTAL LTD		VERNONS	BURLINGTON	HALTON	ON
	1967	BURLINGTON EQUIPMENT RENTAL LTD		VERNONS	BURLINGTON	HALTON	ON
	1960	ALDERSHOT EQUIP RENTAL LTD		VERNONS	BURLINGTON	HALTON	ON
	1957	ALDERSHOT EQUIP RENTAL LTD		VERNONS	BURLINGTON	HALTON	ON
15 PLAINS ROAD WEST	2021	REHAB LINK	PHYSIOTHERAPISTS	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	FITNESS FIRM	EXERCISE & PHYSI	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	REHAB LINK	OFFICES OF MISC HEAL	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	REGISTERED DIETITIAN	OFFICES OF MISC HEAL	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	REHAB LINK PHYSIO	OFFICES OF MISC HEAL	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	FITNESS FIRM	DIET & WEIGHT R	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	REHAB LINK	VOCATIONAL REHABILI	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	FITNESS FIRM	DIET & WEIGHT R	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2007	REHAB LINK		VERNONS	BURLINGTON	HALTON	ON
	2007	MR B'S SMOOTHIES & WRAPS		VERNONS	BURLINGTON	HALTON	ON
	2007	NUTRIENT BEGINNINGS		VERNONS	BURLINGTON	HALTON	ON
	2007	THE FITNESS FIRM		VERNONS	BURLINGTON	HALTON	ON
	2002	REHAB LINK		VERNONS	BURLINGTON	HALTON	ON
	2002	NUTRIENT BEGINNINGS		VERNONS	BURLINGTON	HALTON	ON
	2002	THE FITNESS FIRM		VERNONS	BURLINGTON	HALTON	ON
	1997	FITNESS UNLIMITED		VERNONS	BURLINGTON	HALTON	ON
	1992	OLIVER TWIST ROOM		VERNONS	BURLINGTON	HALTON	ON
	1992	BEN HUR STEAK HOUSE		VERNONS	BURLINGTON	HALTON	ON
	1987	CANADA POST		VERNONS	BURLINGTON	HALTON	ON
	1987	BEN HUR STEAK HOUSE & TAVERN		VERNONS	BURLINGTON	HALTON	ON
	1982	CANADA POST OFFICE		VERNONS	BURLINGTON	HALTON	ON
	1982	BEN HUR STEAK HOUSE & TAVERN		VERNONS	BURLINGTON	HALTON	ON
	1977	CANADA POST DEPOT		VERNONS	BURLINGTON	HALTON	ON
	1977	BEN HUR STEAK HOUSE & TAVERN		VERNONS	BURLINGTON	HALTON	ON
	1972	THE RED BARN		VERNONS	BURLINGTON	HALTON	ON
	1967	CEDAR GROCE MOBILE HOMES SALES LTD		VERNONS	BURLINGTON	HALTON	ON
	1960	CEDAR GROVE MOBILE HOME SALES LTD		VERNONS	BURLINGTON	HALTON	ON
18 PLAINS ROAD WEST	2021	REMEDY'SRX	PHARMACIES; DENTIST	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	REMEDY'SRX-ALDERSHOT VLG PHARM	PHARMACIES	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	LA SALLE PARK RETIREMENT CMNTY	RETIREMENT PLANNIN	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	18 PLAINS ROAD WEST FACILITY	RETIREMENT PLANNIN	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	FIT FOR LIFE PHYSIOTHERAPY	PHYSIOTHERAPISTS; AL	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	DENTISTRY AT LASALLE	DENTISTS	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	ALDERSHOT AUDIOLOGY	HEARING AIDS; AUDIO	DIGITAL BUSINESS DIREC	BURLINGTON		ON

	2021	KHANNA SWATI DDS	DENTISTS	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	SOLARIS OPTICAL	OPTICIANS; OPTICAL G	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	ALDERSHOT AUDIOLOGY	OFFICES OF SPECIALTY	DIGITAL BUSINESS DIREC	BURLINGTON		ON
24 PLAINS ROAD WEST	1987	ARTISTIC TINTING		VERNONS	BURLINGTON	HALTON	ON
26 PLAINS ROAD WEST	1987	D & B STEEL LTD		VERNONS	BURLINGTON	HALTON	ON
28 PLAINS ROAD WEST	1987	UNIQUE RESTORATIONS		VERNONS	BURLINGTON	HALTON	ON
29 PLAINS ROAD WEST	2021	PHARMASAVE	PHARMACIES; DENTIST	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	U-HAUL NEIGHBORHOOD DEALER	TRUCK-DEALERS-USED,	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	HAUSER CO STORES	FURNITURE-DEALERS-F	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	HASTY MARKET	CONVENIENCE STORES	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	TIM HORTONS	DOUGHNUTS; COFFEE	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	TIM HORTONS	SNACK & NONALC	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	FOREVER SCRAPBOOKS	OFFICE SUPPLIES &am	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	HAUSER CO STORES	FURNITURE STORES	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	HASTY MARKET	SUPERMARKETS &amp	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	TIM HORTONS	SNACK & NONALC	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	HAUSER FACTORY SVC	UNCLASSIFIED	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	FOREVER SCRAPBOOKS	OFFICE SUPPLIES &am	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	HAUSER CO STORES	FURNITURE STORES	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2007	FOREVER SCRAPBOOKS		VERNONS	BURLINGTON	HALTON	ON
	2007	HAUSER FACTORY SERVICE		VERNONS	BURLINGTON	HALTON	ON
	2007	TIM HORTONS DONUTS		VERNONS	BURLINGTON	HALTON	ON
	2002	TIM HORTON'S DONUTS		VERNONS	BURLINGTON	HALTON	ON
	2002	CROFT'S CASUAL SPORTSWEAR		VERNONS	BURLINGTON	HALTON	ON
	2002	FOOTWEAR FACTORY OUTLET		VERNONS	BURLINGTON	HALTON	ON
	2002	HAUSER FACTORY OUTLET		VERNONS	BURLINGTON	HALTON	ON
	1997	TIM HORTONS DONUTS		VERNONS	BURLINGTON	HALTON	ON
	1997	NATURE'S BASKET NATURAL FOODS		VERNONS	BURLINGTON	HALTON	ON
	1997	HAUSER FACTORY OUTLET		VERNONS	BURLINGTON	HALTON	ON
30 PLAINS ROAD WEST	1972	ALDERSHOT INDL INSTALLATIONS		VERNONS	BURLINGTON	HALTON	ON
34 PLAINS ROAD WEST	1972	GILMORE LTD		VERNONS	BURLINGTON	HALTON	ON
38 PLAINS ROAD WEST	1972	BECKER'S MILK CO LTD		VERNONS	BURLINGTON	HALTON	ON
39 PLAINS ROAD WEST	1972	REAL ESTATE		VERNONS	BURLINGTON	HALTON	ON
54 PLAINS ROAD WEST	1972	BP OIL CO LTD		VERNONS	BURLINGTON	HALTON	ON
70 PLAINS ROAD WEST	1972	CANADIAN TIRE CORPN		VERNONS	BURLINGTON	HALTON	ON
85 PLAINS ROAD WEST	1972	TOTEM TRLR SLS LTD		VERNONS	BURLINGTON	HALTON	ON
88 QUEENS MARY AVENUE	2021	NO LISTING FOUND		DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	NO LISTING FOUND		DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	NO LISTING FOUND		DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2007	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	2002	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1997	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1992	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1987	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1982	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1977	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1972	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON

	1967	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1960	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
	1957	ADDRESS NOT LISTED		VERNONS	BURLINGTON	HALTON	ON
1016-1063 WATERDOWN ROAD	2007	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	2002	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1997	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1992	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1982	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1977	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1972	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1967	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1960	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
	1957	ALL RESIDENTIAL		VERNONS	BURLINGTON	HALTON	ON
1017 WATERDOWN ROAD	1992	MACISSAC & MACISSAC		VERNONS	BURLINGTON	HALTON	ON
	1972	CANADA SUB PO		VERNONS	BURLINGTON	HALTON	ON
1018 WATERDOWN ROAD	1997	HALTON ADOLESCENT SUPPORT		VERNONS	BURLINGTON	HALTON	ON
	1992	HALTON ADOLESCENT SUPPORT		VERNONS	BURLINGTON	HALTON	ON
1021 WATERDOWN ROAD	2021	DEE SIGNS	SEWING CONTRACTOR	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	DEE SIGNS	SIGN MFG	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	BAYSHORE TOOL & EQUIPMENT	HOME & GARDEN	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2007	BAYSHORE TOOL & EQUIPMENT		VERNONS	BURLINGTON	HALTON	ON
	2002	BAYSHORE TOOL & EQUIPMENT		VERNONS	BURLINGTON	HALTON	ON
	1972	NEELANDS REFRIG LTD		VERNONS	BURLINGTON	HALTON	ON
	1967	NEELANDS REFRIG		VERNONS	BURLINGTON	HALTON	ON
	1960	NEELANDS REFRIG		VERNONS	BURLINGTON	HALTON	ON
	1957	POST OFFICE		VERNONS	BURLINGTON	HALTON	ON
1022 WATERDOWN ROAD	2021	ABLE LIVING SVC INC	SPEECH PATHOLOGIST	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	CORPORATE TRAVEL SUITES	MOTELS & HOTEL	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	ANTEC APPRAISAL GROUP	APPRAISERS	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	ABLE LIVING SVC INC	HUMAN RIGHTS ORGA	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	WILKINSON ENGINEERING INC	ENGINEERING SVCS	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	CORPORATE TRAVEL SUITES	ROOMING & BOA	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	ROYAL CITY SOCCER CLUB	RECREATIONAL &	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	WITINSON ENGINEERING	ENGINEERING SVCS	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	CHRISTIAN HORIZONS	RELIGIOUS ORGANIZAT	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	WILKINSON ENGINEERING LTD	UNCLASSIFIED	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	WILKINSON ENGINEERING INC	ENGINEERING SVCS	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	ALL THE BEST PAVING LTD	POURED CONCRETE ST	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	ROYAL CITY SOCCER CLUB	RECREATIONAL &	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	TRI POINT MEDICAL INC	MISC AMBULATORY HE	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	ONTARIO MOBILITY SVC	MEDICAL EQUIP MERC	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2007	DOCTORS OFFICE		VERNONS	BURLINGTON	HALTON	ON
	2007	ONTARIO MOBILITY SERVICES		VERNONS	BURLINGTON	HALTON	ON
	2007	ALL THE BEST PAVING LTD		VERNONS	BURLINGTON	HALTON	ON
	2007	WILIKINSON ENGINEERING		VERNONS	BURLINGTON	HALTON	ON
	2007	PARTICIPATION HOUSE		VERNONS	BURLINGTON	HALTON	ON
	2007	CHRISTIAN HORIZONS		VERNONS	BURLINGTON	HALTON	ON

	2007	ROYAL CITY SOCCER		VERNONS	BURLINGTON	HALTON	ON
	2002	DOCTOR		VERNONS	BURLINGTON	HALTON	ON
	2002	ONTARIO MOBILITY SERVICE		VERNONS	BURLINGTON	HALTON	ON
	2002	ALL THE BEST PAVING LTD		VERNONS	BURLINGTON	HALTON	ON
	2002	WILKINSON ENGINEERING		VERNONS	BURLINGTON	HALTON	ON
	2002	TRIPOINT MEDICAL INC		VERNONS	BURLINGTON	HALTON	ON
	1997	WILIKINSON		VERNONS	BURLINGTON	HALTON	ON
	1997	FORENSIC ENGINEERING INC		VERNONS	BURLINGTON	HALTON	ON
	1997	FORENCO INC		VERNONS	BURLINGTON	HALTON	ON
	1992	FORENSIC ENGINEERING INC		VERNONS	BURLINGTON	HALTON	ON
	1992	WILIKONSON ENGINEERING INC		VERNONS	BURLINGTON	HALTON	ON
	1987	MARTIN'S BARBER SHOP		VERNONS	BURLINGTON	HALTON	ON
	1987	WILKINSON ENGINEERING LTD		VERNONS	BURLINGTON	HALTON	ON
	1987	FORENSIC ENGINEERING INC		VERNONS	BURLINGTON	HALTON	ON
	1987	WILKINSON & ASSOC LTD		VERNONS	BURLINGTON	HALTON	ON
	1982	MARTIN'S BARBER SHOP		VERNONS	BURLINGTON	HALTON	ON
	1982	WILKINSON ENGINEERING LTD		VERNONS	BURLINGTON	HALTON	ON
	1982	WILKINSON & ASSOC LTD		VERNONS	BURLINGTON	HALTON	ON
	1977	WILKINSON & ASSOC		VERNONS	BURLINGTON	HALTON	ON
	1977	WILKINSON ENGINEERING LTD		VERNONS	BURLINGTON	HALTON	ON
	1977	MARTIN'S BARBER SHOP		VERNONS	BURLINGTON	HALTON	ON
	1972	DOCTOR		VERNONS	BURLINGTON	HALTON	ON
	1972	MARTIN'S BARBER SHOP		VERNONS	BURLINGTON	HALTON	ON
	1972	PHOENIX & ASSOC LTD		VERNONS	BURLINGTON	HALTON	ON
	1972	CONSULTING ENGINEER		VERNONS	BURLINGTON	HALTON	ON
	1972	REAL ESTATE		VERNONS	BURLINGTON	HALTON	ON
	1967	DOCTOR		VERNONS	BURLINGTON	HALTON	ON
	1967	PHOENIX CONSULTING ENG		VERNONS	BURLINGTON	HALTON	ON
	1967	MARTIN BARBER SHOP		VERNONS	BURLINGTON	HALTON	ON
	1960	BARBER		VERNONS	BURLINGTON	HALTON	ON
	1960	SHERWOOD CLEANERS & CONFY		VERNONS	BURLINGTON	HALTON	ON
	1960	PORTEOUS & SONS		VERNONS	BURLINGTON	HALTON	ON
	1960	DOCTOR		VERNONS	BURLINGTON	HALTON	ON
	1957	BARBER		VERNONS	BURLINGTON	HALTON	ON
	1957	DOCTOR		VERNONS	BURLINGTON	HALTON	ON
	1957	PORTEOUS & SONS		VERNONS	BURLINGTON	HALTON	ON
1025 WATERDOWN ROAD	2021	FABER OOSTDYK	NOTARIES-PUBLIC; ASS	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2021	BIRTH BABY NEEDS	BABY ACCESSORIES	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	VAN DER WOERD FABER	ALL OTHER LEGAL SVCS	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	ABCA BETTER CLEANER	JANITORIAL SVCS	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	VAN DER WOERD & FARBER	OFFICES OF LAWYERS	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2007	SERENDIPITY SALON		VERNONS	BURLINGTON	HALTON	ON
	2007	VAN DER WOERD & FABER & SOLICITORS		VERNONS	BURLINGTON	HALTON	ON
	2007	MERLE NORMAN COSMETICS		VERNONS	BURLINGTON	HALTON	ON
	1997	ABC - A BETTER CLEANER		VERNONS	BURLINGTON	HALTON	ON
	1997	FOOTWEAR FACTORY OUTLET		VERNONS	BURLINGTON	HALTON	ON
	1992	M & S DISTRIBUTING		VERNONS	BURLINGTON	HALTON	ON

	1992	SMITH'S SANITATION SUPPLY CO		VERNONS	BURLINGTON	HALTON	ON
	1992	TROY JOHNSON & ASSOC LTD		VERNONS	BURLINGTON	HALTON	ON
	1992	ABC - A BETTER CLEANER		VERNONS	BURLINGTON	HALTON	ON
	1987	KARBELT SALES CO		VERNONS	BURLINGTON	HALTON	ON
	1987	ABC - A BETTER CLEANER		VERNONS	BURLINGTON	HALTON	ON
	1987	TROY & ASSOC LTD		VERNONS	BURLINGTON	HALTON	ON
	1982	KARBELT SALES CO		VERNONS	BURLINGTON	HALTON	ON
	1982	DANIEL STEEL INSTALLATION LTD		VERNONS	BURLINGTON	HALTON	ON
1036 WATERDOWN ROAD	2007	A BETTER SKID-STEER SERVICE		VERNONS	BURLINGTON	HALTON	ON
	1997	SKYLAWN GARDEN		VERNONS	BURLINGTON	HALTON	ON
1044 WATERDOWN ROAD	2017	BURLINGTON FIRE HALL 3	FIRE PROTECTION	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	BURLINGTON PRO FIREFIGHTERS	LABOR UNIONS &	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	BURLINGTON PRO FIREFIGHTERS	LABOR UNIONS &	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2007	BURLINGTON FIRE HALL		VERNONS	BURLINGTON	HALTON	ON
	2007	BURLINGTON PROFESSIONAL FIREFIGHTERS ASSOC		VERNONS	BURLINGTON	HALTON	ON
	2002	ST JOHN AMBULANCE SERVICE		VERNONS	BURLINGTON	HALTON	ON
	2002	BURLINGTON PROFESSIONAL FIREFIGHTERS ASSOC		VERNONS	BURLINGTON	HALTON	ON
	1997	FIRE STATION		VERNONS	BURLINGTON	HALTON	ON
	1992	FIRE STATION		VERNONS	BURLINGTON	HALTON	ON
	1992	ST JOHN AMBULANCE ASSOC		VERNONS	BURLINGTON	HALTON	ON
	1987	FIRE HALL		VERNONS	BURLINGTON	HALTON	ON
	1982	FIRE HALL		VERNONS	BURLINGTON	HALTON	ON
	1982	ST JOHN AMBULANCE		VERNONS	BURLINGTON	HALTON	ON
	1982	POLICE PRECINCT		VERNONS	BURLINGTON	HALTON	ON
	1977	FIRE HALL		VERNONS	BURLINGTON	HALTON	ON
	1977	POLICE PRECINCT NO 1		VERNONS	BURLINGTON	HALTON	ON
	1972	POLICE DEPT		VERNONS	BURLINGTON	HALTON	ON
	1972	FIRE HALL NO 3		VERNONS	BURLINGTON	HALTON	ON
	1960	FIRE HALL NO 3		VERNONS	BURLINGTON	HALTON	ON
1048 WATERDOWN ROAD	2021	ST JOHN AMBULANCE	FIRST AID SERVICE	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2017	ST JOHN AMBULANCE	AMBULANCE SVCS	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2012	ST JOHN AMBULANCE	BUSINESS ASSOCIATIOI	DIGITAL BUSINESS DIREC	BURLINGTON		ON
	2007	ST JOHN AMBULANCE ASSOC		VERNONS	BURLINGTON	HALTON	ON
	1997	ST JOHN AMBULANCE ASSN		VERNONS	BURLINGTON	HALTON	ON
	1987	ST JOHN AMBULANCE ASSOC		VERNONS	BURLINGTON	HALTON	ON
1060 WATERDOWN ROAD	1957	HOWARD CONCRETE & MATERIALS		VERNONS	BURLINGTON	HALTON	ON

ERIS City Directory Search

as of 05/08/2023

Project Property: 1026 Cooke Boulevard - 1026 Cooke Boulevard, Burlington, ON L7T 4A8 CA

ERIS Order No: 23041300087

Search Coverage: 2021,2017,2012(DIGITAL BUSINESS DIRECTORY)
2007,2002,1997,1992,1987,1982,1977,1972,1967,1960,1957(VERNONS)

Street Range: 982-992 of BIRCHWOOD AVENUE, BURLINGTON

Site Comments:

ADDRESS	FACILITIES
982-992 BIRCHWOOD AVENUE, BURLINGTON	ALL RESIDENTIAL (1957-2007); NO LISTING FOUND (2021)
990 BIRCHWOOD AVENUE, BURLINGTON	DENTIST (1957-1960); DENTAL SURGEON (1972-1987); SANAVOK LTD (1987-1997); SANOVAK LTD (1992); DOCTOR'S OFFICE (1992-1997); DOCTOR (2002); CIPPARONE, E A DDS (2012)
992 BIRCHWOOD AVENUE, BURLINGTON	DENTIST (1960-1982); DENTAL SURGEON (1972-1987); DOCTOR (1992-2002); DOCTOR'S OFFICE (1997-2007); DRYSDALE, DOLORES DDS (2012); CONFIDENT BRIGHT SMILES (2017); DRYSDALE DOLORES DDS (2017)

ERIS City Directory Search

as of 05/08/2023

Project Property: 1026 Cooke Boulevard - 1026 Cooke Boulevard, Burlington, ON L7T 4A8 CA
ERIS Order No: 23041300087

Search Coverage: 2021,2017,2012(DIGITAL BUSINESS DIRECTORY)
2007,2002,1997,1992,1987,1982,1977,1972,1967,1960,1957(VERNONS)
Street Range: 1022-1072, 1019-1045 of CLEARVIEW AVENUE, BURLINGTON
Site Comments:

ADDRESS	FACILITIES
1022-10721019-1045 CLEARVIEW AVENUE, BURLINGTON	NO LISTING FOUND (2021)
1022-1072, 1019-1045 CLEARVIEW AVENUE, BURLINGTON	ALL RESIDENTIAL (1957-2007)
1025 CLEARVIEW AVENUE, BURLINGTON	A STREAMLINE MOBILE WASH (2012-2017)
1045 CLEARVIEW AVENUE, BURLINGTON	RED PANT PRODUCTIONS (2017)
1061 CLEARVIEW AVENUE, BURLINGTON	PLYMOUTH BRETHREN CHURCH (1967-1997); PLYMOUTH BRETHEREN CHURCH (2002)

ERIS City Directory Search

as of 05/08/2023

Project Property: 1026 Cooke Boulevard - 1026 Cooke Boulevard, Burlington, ON L7T 4A8 CA
ERIS Order No: 23041300087

Search Coverage: 2021,2017,2012(DIGITAL BUSINESS DIRECTORY)
2007,2002,1997,1992,1987,1982,1977,1972,1967,1960,1957(VERNONS)
Street Range: 1025-1074,1026 of COOKE BOULEVARD, BURLINGTON
Site Comments:

ADDRESS	FACILITIES
1025-1074 COOKE BOULEVARD, BURLINGTON	No Listing (1957-1992); NO LISTINGS WITHIN RADIUS (1982)
1026 COOKE BOULEVARD, BURLINGTON	ADDRESS NOT LISTED (1997-2002); DESIGNS (2007); CONTROTECH AUTOMATION (2007-2017); D DE SIGNS (2012-2017); MEGBROOK HOLDINGS INC (2017-2021); BURLINGTON STEEL SYSTEMS (2021); EVERIK INTERNATIONAL INC (2021); K D INSTALLATIONS (2021)
1038 COOKE BOULEVARD, BURLINGTON	DELUCA ROOFING INC (2002); LEXTONER.COM (2002-2017); BURLINGTON PUMP INC (2002-2021); O'DELL ASSOCIATES (2002-2021); DELUCA ROOFING (2007); TEKSMART (2007); O'DELL ASSOC (2007-2017); TEKSMART INC (2012); DE LUCA ROOFING INC (2012-2021); O'DELL ASSOCIATE (2017)
1047 COOKE BOULEVARD, BURLINGTON	ETRATECH DESIGNS INC (2002); ETRATECH INC (2012-2017); GENTHERM ELECTRONICS (2021)
1050 COOKE BOULEVARD, BURLINGTON	BRANTFORD SUB ASSEMBLY (1997); BHC CABLE ASSEMBLERS INC (2002); INVESTIGATIVE SCIENCE (2002); PRIMARY FLUID INC (2002); THERAPY HEALTH CARE INC (2007-2012); INVESTIGATIVE SCIENCE INC (2007-2021); PRIMARY FLUID SYSTEMS INC (2007-2021)
1062 COOKE BOULEVARD, BURLINGTON	MEDGAR SALES (2007); CATEGORY 5 IMAGING LTD (2007-2021); MEDGAR SALES LTD (2012); MEDGAR LIGHTING GROUP INC (2012-2017); LAUREL OAK MARKETING LTD (2017)
1074 COOKE BOULEVARD, BURLINGTON	ETRATECH DESIGN INC (1997); ECLIPSE COLOUR INT LTD (2002); CANDIAN SPORT FISHING PRODUCTIONS INC (2007); CONTROL SYSTEM INNOVATORS (2007); TOWN PUBLISHING INC (2007); TOWN PUBLISHING (2012); BIZ MAGAZINE (2012-2017); CANADIAN SPORTFISHING PRDCTN (2012-2017); CONTROL SYSTEM INNOVATIONS (2012-2017); PV LABS (2021)

ERIS City Directory Search

as of 05/08/2023

Project Property: 1026 Cooke Boulevard - 1026 Cooke Boulevard, Burlington, ON L7T 4A8 CA
ERIS Order No: 23041300087

Search Coverage: 2021,2017,2012(DIGITAL BUSINESS DIRECTORY)
2007,2002,1997,1992,1987,1982,1977,1972,1967,1960,1957(VERNONS)
Street Range: 1-59 Odd of FAIRWOOD PLACE EAST, BURLINGTON
Site Comments:

ADDRESS	FACILITIES
1-59 Odd FAIRWOOD PLACE EAST, BURLINGTON	No Listing (1957-1960); ALL RESIDENTIAL (1967-2007)
9 FAIRWOOD PLACE EAST, BURLINGTON	GRAPHIC ENCOUNTER (1997)
15 FAIRWOOD PLACE EAST, BURLINGTON	RESIDENTIAL (1 TENANT) (1967)
19 FAIRWOOD PLACE EAST, BURLINGTON	RESIDENTIAL (1 TENANT) (1967)
53 FAIRWOOD PLACE EAST, BURLINGTON	DUTCHMAN'S LANDSCAPING (2002-2021)

ERIS City Directory Search

as of 05/08/2023

Project Property: 1026 Cooke Boulevard - 1026 Cooke Boulevard, Burlington, ON L7T 4A8 CA
ERIS Order No: 23041300087

Search Coverage: 2021,2017,2012(DIGITAL BUSINESS DIRECTORY)
2007,2002,1997,1992,1987,1982,1977,1972,1967,1960,1957(VERNONS)
Street Range: 1-19 Odd of FAIRWOOD PLACE WEST, BURLINGTON
Site Comments:

ADDRESS	FACILITIES
1-19 FAIRWOOD PLACE WEST, BURLINGTON	NO LISTING FOUND (2012-2021)
1-19 Odd FAIRWOOD PLACE WEST, BURLINGTON	No Listing (1957-1960); ALL RESIDENTIAL (1987-2002)
15 FAIRWOOD PLACE WEST, BURLINGTON	RESIDENTIAL (1 TENANT) (1972-2007)
19 FAIRWOOD PLACE WEST, BURLINGTON	RESIDENTIAL (1 TENANT) (1972-2007)

ERIS City Directory Search

as of 05/08/2023

Project Property: 1026 Cooke Boulevard - 1026 Cooke Boulevard, Burlington, ON L7T 4A8 CA
ERIS Order No: 23041300087

Search Coverage: 2021,2017,2012(DIGITAL BUSINESS DIRECTORY)
2007,2002,1997,1992,1987,1982,1977,1972,1967,1960,1957(VERNONS)
Street Range: 979-987 of LASALLE PARK ROAD, BURLINGTON
Site Comments:

ADDRESS	FACILITIES
979 LASALLE PARK ROAD, BURLINGTON	GREEN'S FLOWER SHOP (1967-1977); OLD FRIENDS ANTIQUES (1977)
979-987 LASALLE PARK ROAD, BURLINGTON	ALL RESIDENTIAL (1957-2007); NO LISTING FOUND (2012-2021)
982 LASALLE PARK ROAD, BURLINGTON	ROBINSON DE PUGA INTERIORS (2017)

ERIS City Directory Search

as of 05/08/2023

Project Property: 1026 Cooke Boulevard - 1026 Cooke Boulevard, Burlington, ON L7T 4A8 CA
ERIS Order No: 23041300087

Search Coverage: 2021,2017,2012(DIGITAL BUSINESS DIRECTORY)
2007,2002,1997,1992,1987,1982,1977,1972,1967,1960,1957(VERNONS)
Street Range: 2 of MASONRY COURT, BURLINGTON
Site Comments:

ADDRESS	FACILITIES
2 MASONRY COURT, BURLINGTON	No Listing (1957-1997); ADDRESS NOT LISTED (2002); BHC (2007-2021); GP2 INC (2017); COUGAR SHOES INC (2021)

ERIS City Directory Search

as of 05/08/2023

Project Property: 1026 Cooke Boulevard - 1026 Cooke Boulevard, Burlington, ON L7T 4A8 CA
ERIS Order No: 23041300087

Search Coverage: 2021,2017,2012(DIGITAL BUSINESS DIRECTORY)
2007,2002,1997,1992,1987,1982,1977,1972,1967,1960,1957(VERNONS)
Street Range: 1-91 of PLAINS ROAD EAST, BURLINGTON
Site Comments:

ADDRESS	FACILITIES
1 PLAINS ROAD EAST, BURLINGTON	RUDOLF'S VARIETY STORE (1960); RUDOLPH'S VARIETY STORE (1967); MURRAY'S VARIETY (1972-2017); MURRAY' VARIETY (1982); MURRAY'S VARIETIES (1987-2007); MURRAY'S HOME VARIETIES (1992); SUN COUNTRY LEISURE PRODUCTS (2021)
1-91 PLAINS ROAD EAST, BURLINGTON	ALL RESIDENTIAL (1957-2002)
2 PLAINS ROAD EAST, BURLINGTON	SOL EXOTICA (2017)
3 PLAINS ROAD EAST, BURLINGTON	SUN COUNTRY LEISURE PRODUCTS (2017)
5 PLAINS ROAD EAST, BURLINGTON	DE LA SALLE CLEANERS (1957); HYPE SYSTEMS INC (2021)
14 PLAINS ROAD EAST, BURLINGTON	JIM & ED'S SERVICE CENTER (1957); LLOYD'S ESSO SERVICE STATION (1960); BURL ESSO NO 2 (1967); LA SALLE ESSO SERV STN (1972); THOMPSON JACK SLEF SERV ESSO STATION (1977); ALDERSHOT AUTOMOTIVE SELF SERVICE STALTION (1982); MOORE AUTO SERVICE (1987); MORE ESSO SERVICE (1987); MAC'S CONVENIENCE STORE (1997-2017); MAC'S CONVENIENCE (2002); MAC'S CONVENIENCE STORES LTD (2012); TIM HORTONS (2017-2021); CIRCLE K (2021); ESSO (2021)
15 PLAINS ROAD EAST, BURLINGTON	ROYAL BANK OF CANADA (1957-1997); THE ROYAL BANK OF CANADA (1972-1982); ROYAL BANK OF MONTREAL (2002); RBC (2007); ACCELERATED CONNECTIONS (2007-2017); ROYAL BANK FINANCIAL GROUP (2012); RBC ROYAL BANK (2017-2021); ATM (2021)
18 PLAINS ROAD EAST, BURLINGTON	LA SALLE RESTR (1957)
20 PLAINS ROAD EAST, BURLINGTON	MARGARET'S BTY SALON (1957); RUSSELL WILLIAMS RESTR (1967); RUSSELL WILLIAMS RESTRAURANT (1972); RUSSELL WILLIAMS RESTAURANT (1977-1982); RUSSELL WILLIAMS RESTAURANTS LTD (1987-1992); RUSSELL WILLIAMS (1997); RUSSEL WILLIAMS RESTAURANTS LTD (2002); RUSSELL WILLIAMS RESTAURANT LTD (2007); RUSSELL WILLIAMS RESTAURANTS (2012-2021)
26 PLAINS ROAD EAST, BURLINGTON	MARGARET'S BTY SALON (1960); MADY'S HAIR FASHIONS (1967-1982); MADY'S AHIR FASHIONS (1977); SMOOTHIE KINGS (2002); GOLDEN SCISSORS ALTERATIONS (2007-2017)
27 PLAINS ROAD EAST, BURLINGTON	ALDERSHOT LANDSCAPING (1960); ALDERSHOT LANDSCAPE & CONTRACTING LTD (1967)
28 PLAINS ROAD EAST, BURLINGTON	ALDERSHOT FLORIST (1957-1960); STONEY CREEK DAIRIES LTD (1967-1972); MOBY DICK SUPER SUB (1977); NEPTUNE MARINE (1982); TARA TRAVEL INC (1987); FARAH FOOD LTD (1997); HASTY MARKET CORP (1997); KREATIVE KHAOS PIERCINGS (2007); FARAH FOOD LTD-HASTY MARKET (2012); KREATIVE KHAOS PIERCING (2012-2017); HASTY MARKET (2017)
30 PLAINS ROAD EAST, BURLINGTON	SWEET-N-KLEEN LAUNDRETTE (1957-1972); PHOTO LAB (1977-1987); DEREK'S MOBILT TV SERVICE APPLIANCES (1992); BETTER BUSINESS BUREAU (2002); BETTER BUSINESS MACHINES (2007-2021)
32 PLAINS ROAD EAST, BURLINGTON	HORTECH RESEARCH LTD (1977)
34 PLAINS ROAD EAST, BURLINGTON	HUFFMAN'S DRUG STORE (1960); DRUG STORE (1967); THOMSON'S DRUG STORE (1972); STONEY CREEK DAIRIES LTD STORES (1977); STONEY CREEK DAIRY & VARIETY STORE (1982-2002); STONEY CREEK DAIRY & VARIETY (1987); VARIETY MIN-A-MART (2007); MIN A MART (2012); PIZZA ROYALE (2017)
35 PLAINS ROAD EAST, BURLINGTON	JIM & ED'S SERV STN (1960); ALDERSHOT LANDSCAPE (1972); ALDERSHOT LANDSCPAE CONTRACTORS LTD (1977); BUDGET RENT A CAR (1982-1987); SEARS RENT A CAR (1982-1987); WINDSHIELD DOCTOR (1987-1992); O'REILLEY PAT AUTO LTD (1992)

50 PLAINS ROAD EAST, BURLINGTON	BURLINGTON CAPE CORAL (1992); CLAIRMONT & SONS CONTRACTING (1992-1997); ROBERT & SONS (2002); ROBERT CLAIRMONT & SONS CONTRACTING (2007); CLAIMONT, R (2012); ROBERT CLAIRMONT & SONS (2012); CLAIRMONT R (2017)
53 PLAINS ROAD EAST, BURLINGTON	PARK LANE MOTEL (1957-1972); JOLLY 6 PENCE MOTEL & TAVERN (1977); BENJIES MOTEL & DINING LOUNGE (1982); BENJIES MOTOR HOTEL (1987); SOLID GOLD (1992-2021)
70 PLAINS ROAD EAST, BURLINGTON	ELAINE BEAUTY SALON (1972); MURRAY WHOLSESALE GIFTS (1977); MURRAY WHOLESALE (1982); WHOLESALE GIFT SOUVENIRS (1987); MURRAY WHOLESALE GIFT SOUVENIRS (1992-1997); MURRAY WHOLESALE CASH & CARRY (2002-2012)
71 PLAINS ROAD EAST, BURLINGTON	SERVICE STATION (1960); BUDGET RENT A CAR (1977); SEARS RENT A CAR (1977); AVIS RENT A CAR (1987); BURLINGTON RIDE CENTER (1987); BURLINGTON SUZUKI (1987)
91 PLAINS ROAD EAST, BURLINGTON	GLEN COURT MOTEL (1957-1972); HURLEY INSURANCE BROKER LTD (1982); MUNEL ENTERPRISES (1982); SIR LOIN STEAKS (1982); THE MUNRO GROUP (1982); GARDNER OFFICE EQUIPMENT (1987); NATURE'S BASKET NATURAL FOODS (1992); PETRO APARTMENTS (1997); VIKING NORSTAR DEVELOPMENT CORP (1997); PETRO PARTNERS (2002); SPANISH TOUCH (2002); ABBEY STAINED GLASS (2002-2021); KLIPPINGS HAIR SALON INC (2007); FENWORTH FLORIDA HOMES & CONDO (2012); FENWORTH TRAVEL WAREHOUSE (2012); KLIPPINGS HAIR SALON (2012-2017); PETROPARTNERS (2012-2017); FENWORTH FLORIDA HOMES CONDO (2017); FENWORTH TRAVEL (2017); KREATIVE KHAOS TATTOOING (2017); EIGHTH EMPIRE TATTOOS PRCNGS (2021); KIPPLINGS HAIR SALON (2021)
91-99 PLAINS ROAD EAST, BURLINGTON	ROYAL MOTEL (1977)

ERIS City Directory Search

as of 05/08/2023

Project Property: 1026 Cooke Boulevard - 1026 Cooke Boulevard, Burlington, ON L7T 4A8 CA
ERIS Order No: 23041300087

Search Coverage: 2021,2017,2012(DIGITAL BUSINESS DIRECTORY)
2007,2002,1997,1992,1987,1982,1977,1972,1967,1960,1957(VERNONS)
Street Range: 1-29 of PLAINS ROAD WEST, BURLINGTON
Site Comments:

ADDRESS	FACILITIES
1-29 PLAINS ROAD WEST, BURLINGTON	ALL RESIDENTIAL (1960-1997); WEST PLAINS SUPERTEST SERV STN (1967)
2 PLAINS ROAD WEST, BURLINGTON	YOUR FRIENDLY COFFEE SHOP (1957); CONNIE'S COFFEE SHOP (1960)
6 PLAINS ROAD WEST, BURLINGTON	BARBER (1957)
7 PLAINS ROAD WEST, BURLINGTON	GEORGE'S LUNCH ROOM (1957); SERVICE STN (1957); ABC TAXI (1960); ALEX'S SUPERTEST STN (1960); LA BELLE SNACK BAR (1960); JOE'S BARBER SHOP (1967); PLAINS WEST SUPERTEST SERV STN (1972); PLAINS WEST BP SERVICE STATION (1977); TED'S SERVICE CENTER (1977-1992); PLAIN WEST BP SERVICE STATION (1982); PLAINS WEST PETRO-CANADA (1987); PLAINS WEST SUPERTEST (1992); JERRY'S AUTO (1997-2007); RAY'S AUTO CENTER & TOWING (2002); RAY'S AUTO CENTRE & TOWING (2007); RAY'S AUTO CTR & TOWING (2012); JERRY'S AUTOMOTIVE (2012-2021); RAY'S AUTO CTR TOWING (2017); NICHE FOR DESIGN (2021)
8 PLAINS ROAD WEST, BURLINGTON	RUDOLF'S VARIETY STORE (1957); DE LA SALLE CLEANERS (1960)
12 PLAINS ROAD WEST, BURLINGTON	MARY'S LUNCH (1967-1972); MURRAY'S RESTAURANT (1977); ALDERSHOT RECREATIONS EQUIPMENT RENTAL LTD (1982)
14 PLAINS ROAD WEST, BURLINGTON	ALDERSHOT EQUIP RENTAL LTD (1957-1960); ALDERSHOT CARRY-ALL-LTD (1967); ALDERSHOT CONTRS EQUIPMENT RENTAL LTD (1967); ALDERSHOT STEVEDORING & FORWARDING LTD (1967-1977); BURLINGTON EQUIPMENT RENTAL LTD (1967-1977); ALDERSHOT CARRY-ALL LTD (1972); ALDERSHOT CONTRS EQUIP RENTL (1972); ALDERSHOT FORWARDING LTD (1972); BURL EQUIP RENTL LTD (1972); ALDERSHOT RECREATIONAL EQUIPMENT RENTAL LTD (1977); ALDERSHOT CARRY-ALL SERVICE LTD (1977-1982); ALDERSHOT TRANSPORTATION INC (1982); GINO MOBILE REPAIR LTD (1987); GREER DAN ENTERPRISES LTD (1987)
15 PLAINS ROAD WEST, BURLINGTON	CEDAR GROVE MOBILE HOME SALES LTD (1960); CEDAR GROCE MOBILE HOMES SALES LTD (1967); THE RED BARN (1972); CANADA POST DEPOT (1977); BEN HUR STEAK HOUSE & TAVERN (1977-1987); CANADA POST OFFICE (1982); CANADA POST (1987); BEN HUR STEAK HOUSE (1992); OLIVER TWIST ROOM (1992); FITNESS UNLIMITED (1997); NUTRIENT BEGINNINGS (2002-2007); THE FITNESS FIRM (2002-2007); REHAB LINK (2002-2021); MR B'S SMOOTHIES & WRAPS (2007); FITNESS FIRM (2012-2021); REGISTERED DIETITIAN (2017); REHAB LINK PHYSIO (2017)
18 PLAINS ROAD WEST, BURLINGTON	ALDERSHOT AUDIOLOGY (2017-2021); 18 PLAINS ROAD WEST FACILITY (2021); DENTISTRY AT LASALLE (2021); FIT FOR LIFE PHYSIOTHERAPY (2021); KHANNA SWATI DDS (2021); LA SALLE PARK RETIREMENT CMNTY (2021); REMEDY'SRX (2021); REMEDY'SRX-ALDERSHOT VLG PHARM (2021); SOLARIS OPTICAL (2021)
24 PLAINS ROAD WEST, BURLINGTON	ARTISTIC TINTING (1987)
26 PLAINS ROAD WEST, BURLINGTON	D & B STEEL LTD (1987)
28 PLAINS ROAD WEST, BURLINGTON	UNIQUE RESTORATIONS (1987)
29 PLAINS ROAD WEST, BURLINGTON	NATURE'S BASKET NATURAL FOODS (1997); HAUSER FACTORY OUTLET (1997-2002); TIM HORTONS DONUTS (1997-2007); CROFT'S CASUAL SPORTSWEAR (2002); FOOTWEAR FACTORY OUTLET (2002); TIM HORTON'S DONUTS (2002); HAUSER FACTORY SERVICE (2007); FOREVER SCRAPBOOKS (2007-2017); HAUSER FACTORY SVC (2012); HAUSER CO STORES (2012-2021); TIM HORTONS (2012-2021); HASTY MARKET (2017-2021); PHARMASAVE (2021); U-HAUL NEIGHBORHOOD DEALER (2021)
30 PLAINS ROAD WEST, BURLINGTON	ALDERSHOT INDL INSTALLATIONS (1972)

34 PLAINS ROAD WEST, BURLINGTON	GILMORE LTD (1972)
38 PLAINS ROAD WEST, BURLINGTON	BECKER'S MILK CO LTD (1972)
39 PLAINS ROAD WEST, BURLINGTON	REAL ESTATE (1972)
54 PLAINS ROAD WEST, BURLINGTON	BP OIL CO LTD (1972)
70 PLAINS ROAD WEST, BURLINGTON	CANADIAN TIRE CORPN (1972)
85 PLAINS ROAD WEST, BURLINGTON	TOTEM TRLR SLS LTD (1972)

ERIS City Directory Search

as of 05/08/2023

Project Property: 1026 Cooke Boulevard - 1026 Cooke Boulevard, Burlington, ON L7T 4A8 CA
ERIS Order No: 23041300087

Search Coverage: 2021,2017,2012(DIGITAL BUSINESS DIRECTORY)
2007,2002,1997,1992,1987,1982,1977,1972,1967,1960,1957(VERNONS)
Street Range: 88 of QUEENS MARY AVENUE, BURLINGTON
Site Comments:

ADDRESS	FACILITIES
88 QUEENS MARY AVENUE, BURLINGTON	ADDRESS NOT LISTED (1957-2007); NO LISTING FOUND (2012-2021)

ERIS City Directory Search

as of 05/08/2023

Project Property: 1026 Cooke Boulevard - 1026 Cooke Boulevard, Burlington, ON L7T 4A8 CA
ERIS Order No: 23041300087

Search Coverage: 2021,2017,2012(DIGITAL BUSINESS DIRECTORY)
2007,2002,1997,1992,1987,1982,1977,1972,1967,1960,1957(VERNONS)
Street Range: 1016-1063 of WATERDOWN ROAD, BURLINGTON
Site Comments:

ADDRESS	FACILITIES
1016-1063 WATERDOWN ROAD, BURLINGTON	ALL RESIDENTIAL (1957-2007)
1017 WATERDOWN ROAD, BURLINGTON	CANADA SUB PO (1972); MACISSAC & MACISSAC (1992)
1018 WATERDOWN ROAD, BURLINGTON	HALTON ADOLESCENT SUPPORT (1992-1997)
1021 WATERDOWN ROAD, BURLINGTON	POST OFFICE (1957); NEELANDS REFRIG (1960-1967); NEELANDS REFRIG LTD (1972); BAYSHORE TOOL & EQUIPMENT (2002-2012); DEE SIGNS (2017-2021)
1022 WATERDOWN ROAD, BURLINGTON	BARBER (1957-1960); PORTEOUS & SONS (1957-1960); DOCTOR (1957-2002); SHERWOOD CLEANERS & CONFY (1960); MARTIN BARBER SHOP (1967); PHOENIX CONSULTING ENG (1967); CONSULTING ENGINEER (1972); PHOENIX & ASSOC LTD (1972); REAL ESTATE (1972); MARTIN'S BARBER SHOP (1972-1987); WILKINSON & ASSOC (1977); WILKINSON ENGINEERING LTD (1977-2012); WILKINSON & ASSOC LTD (1982-1987); FORENSIC ENGINEERING INC (1987-1997); WILIKONSON ENGINEERING INC (1992); FORENCO INC (1997); WILIKINSON (1997); ONTARIO MOBILITY SERVICE (2002); TRIPOINT MEDICAL INC (2002); WILKINSON ENGINEERING (2002); ALL THE BEST PAVING LTD (2002-2012); DOCTORS OFFICE (2007); ONTARIO MOBILITY SERVICES (2007); PARTICIPATION HOUSE (2007); ROYAL CITY SOCCER (2007); WILIKINSON ENGINEERING (2007); CHRISTIAN HORIZONS (2007-2012); ONTARIO MOBILITY SVC (2012); TRI POINT MEDICAL INC (2012); ROYAL CITY SOCCER CLUB (2012-2017); WILKINSON ENGINEERING INC (2012-2017); WITINSON ENGINEERING (2017); ABLE LIVING SVC INC (2017-2021); CORPORATE TRAVEL SUITES (2017-2021); ANTEC APPRAISAL GROUP (2021)
1025 WATERDOWN ROAD, BURLINGTON	DANIEL STEEL INSTALLATION LTD (1982); KARBELT SALES CO (1982-1987); TROY & ASSOC LTD (1987); ABC - A BETTER CLEANER (1987-1997); M & S DISTRIBUTING (1992); SMITH'S SANITATION SUPPLY CO (1992); TROY JOHNSON & ASSOC LTD (1992); FOOTWEAR FACTORY OUTLET (1997); MERLE NORMAN COSMETICS (2007); SERENDIPITY SALON (2007); VAN DER WOERD & FABER & SOLICITORS (2007); ABCA BETTER CLEANER (2012); VAN DER WOERD & FARBER (2012); VAN DER WOERD FABER (2017); BIRTH BABY NEEDS (2021); FABER OOSTDYK (2021)
1036 WATERDOWN ROAD, BURLINGTON	SKYLAWN GARDEN (1997); A BETTER SKID-STEER SERVICE (2007)
1044 WATERDOWN ROAD, BURLINGTON	FIRE HALL NO 3 (1960-1972); POLICE DEPT (1972); POLICE PRECINCT NO 1 (1977); FIRE HALL (1977-1987); POLICE PRECINCT (1982); ST JOHN AMBULANCE (1982); ST JOHN AMBULANCE ASSOC (1992); FIRE STATION (1992-1997); ST JOHN AMBULANCE SERVICE (2002); BURLINGTON PROFESSIONAL FIREFIGHTERS ASSOC (2002-2007); BURLINGTON FIRE HALL (2007); BURLINGTON PRO FIREFIGHTERS (2012-2017); BURLINGTON FIRE HALL 3 (2017)
1048 WATERDOWN ROAD, BURLINGTON	ST JOHN AMBULANCE ASSOC (1987-2007); ST JOHN AMBULANCE ASSN (1997); ST JOHN AMBULANCE (2012-2021)
1060 WATERDOWN ROAD, BURLINGTON	HOWARD CONCRETE & MATERIALS (1957)

APPENDIX G: OTHER GOVERNMENT RECORDS

Ministry of the Environment, Conservation and Parks

Access and Privacy Office

12th Floor
40 St. Clair Avenue West
Toronto ON M4V 1M2
Tel: (416) 314-4075

Ministère de l'Environnement, de la Protection de la nature et des Parcs

Bureau de l'accès à l'information et de la protection de la vie privée

12e étage
40, avenue St. Clair ouest
Toronto ON M4V 1M2
Tél. : (416) 314-4075

June 21, 2023

Hongshen Chen
B.I.G. Consulting Inc.
505 Consumers Road, Unit 804
Toronto, Ontario M2J 4V8
HChen@brownfieldigi.com

Dear Hongshen Chen:

RE: **MECP FOI A-2023-03281, Your Reference BIGC-ENV-605A – Decision Letter**

This letter is in response to your request made pursuant to the Freedom of Information and Protection of Privacy Act (the Act) relating to 1026 Cooke Boulevard, Burlington.

After a thorough search through the files of the ministry's Halton Peel District Office, Environmental Assessment and Permissions Division (EAPD), Environmental Monitoring and Reporting Branch (EMRB), Environmental Investigations and Enforcement Branch (EIEB), and Safe Drinking Water Branch (SDW) no records were located responsive to your request. **This file is now closed.**

You may request a review of my decision within 30 days from the date of this letter by contacting the Information and Privacy Commissioner/Ontario at http://www.ipc.on.ca. Please note there may be a fee associated with submitting the appeal.

If you have any questions, please contact Adeolu Paul-Taiwo at adeolu.paul-taiwo@ontario.ca.

Yours truly,

ORIGINAL SIGNED BY

Ryan Gunn
Manager (A), Access and Privacy Office

Hongshen Chen

From: Public Information Services <publicinformationservices@tssa.org>
Sent: May 29, 2023 10:12 AM
To: Hongshen Chen
Subject: RE: Request for Environmental Information

Hello,

NO RECORD FOUND IN CURRENT DATABASE

Thank you for your request for confirmation of public information. TSSA has performed a preliminary search of TSSA's current database.

- We confirm that there are no records in our database of any **fuel storage tanks** at the subject address(es).

This is not a confirmation that there are no records in the archives. For a further search in our archives, please submit an application for release of public information (PI Form) through TSSA's new Service Prepayment Portal. The associated fee must be paid via credit card (Visa or MasterCard) through a secure site.
Please follow the steps below to access the new application(s) and Service Prepayment Portal:

1. Click Release of Public Information - TSSA - TSSA and click "need a copy of a document";
2. Select the appropriate application, download it and complete it in full; and
3. Proceed to page 3 of the application and click the link TSSA Service Prepayment Portal under payment options (the link will take you the secure site to pay for the release via credit card).

Accessing the Service Prepayment Portal:

1. Select new or existing customer (*if you are an existing customer, you will need your account # & postal code to access your account);
2. Select the program area: AD (Amusement Devices), BPV (Boilers and Pressure Vessels), ED (Elevating Devices), FS (Fuels Services), OE (Operating Engineers) or SKI (Ski Lifts) and click continue;
3. Enter the application form number (obtained from bottom left corner of application form) and click continue;
    a. When selecting the application form number from the drop-down menu, please make sure you select the application that begins with "PI" (i.e. PI-FS, PI-BPV etc.);
4. Complete the primary contact information section;
5. Complete the fees section;
6. Upload your completed application; and
7. Upload supporting documents (if required) and click continue.

Once all steps have been successfully completed, you will receive your receipt via email.
Questions? Please contact TSSA's Public Information Release team at publicinformationservices@tssa.org.
Although TSSA believes the information provided pursuant to your request is accurate, please note that TSSA does not warrant this information in any way whatsoever.

Kind regards,

Kimberly Gage | Public Information Agent
Legal
345 Carlingview Drive
Toronto, Ontario M9W 6N9
Tel: +1 416-734-3348 | Fax: +1 416-734-3568 | E-Mail: kgage@tssa.org
www.tssa.org

From: Hongshen Chen <HChen@brownfieldigi.com>
Sent: Monday, May 29, 2023 9:35 AM
To: Public Information Services

Winner of 2022 5-Star Safety Cultures Award

<publicinformationservices@tssa.org>
Subject: Request for Environmental Information

[CAUTION]: This email originated outside the organisation.
Please do not click links or open attachments unless you recognise the source of this email and know the content is safe.

Hello Madam/Sir,

I would like to submit a request for Environmental Information for the following properties in Burlington, Ontario:

1. 1026 Cooke Boulevard (Site)
2. 1038 Cooke Boulevard
3. 1025 Cooke Boulevard
4. 53 Plains Road East
5. 35 Plains Road East
6. 15 Plains Road East
7. 1021 Waterdown Road
8. 1025 Waterdown Road
9. 1029 Waterdown Road
10. 1033 Waterdown Road

As part of our historical review for a Phase One ESA, I am requesting that the Technical Standards and Safety Authority (TSSA), Safety Fuel Division, review its database to identify to us any records of aboveground/underground storage tanks, spills, incidents, complaints, notices, tanks removals and/or remediation, etc. with the TSSA for the above-mentioned site.

Your earliest attention to this matter is much appreciated. For your convenience, you may email me or call me with any information you may have for the properties.

Thanks,

Hongshen Chen
Environmental Scientist

B.I.G. Consulting Inc.
505 Consumers Road, Suite 804
Toronto, Ontario M2J 4V8, Canada
Mobile: 647-918-9753
Office: 416-214-4880
Email: HChen@brownfieldigi.com
Website: www.bigconsultinginc.com



This electronic message and any attached documents are intended only for the named recipients. This communication from the Technical Standards and Safety Authority may contain information that is privileged, confidential or otherwise protected from disclosure and it must not be disclosed, copied, forwarded or distributed without authorization. If you have received this message in error, please notify the sender immediately and delete the original message.

APPENDIX H: AERIAL PHOTOGRAPHS/FIRE INSURANCE PLANS



B.I.G. CONSULTING INC.

t: (416) 214 - 4880 f: (416) 551 - 2633
12-5500 Tomken Rd.
Mississauga, ON L4W 2Z4
Canada

bigconsultinginc.com

LEGEND

SITE BOUNDARY

IMAGERY OBTAINED FROM THE CITY OF BURLINGTON ARCHIVES, DATE 1934

TITLE AND LOCATION

1934 AERIAL PHOTOGRAPH
PHASE ONE ESA
1026 COOKE BOULEVARD,
BURLINGTON, ONTARIO

PROJECT NO.	DWN.
BIGC-ENV-605A	T.S.
SCALE	CK.
NOT TO SCALE	E.L.
DATE	FIG NO.
JUNE 2023	H-1



B.I.G. CONSULTING INC.

t: (416) 214 - 4880 f: (416) 551 - 2633
12-5500 Tomken Rd.
Mississauga, ON L4W 2Z4
Canada

bigconsultinginc.com

LEGEND

SITE BOUNDARY

IMAGERY OBTAINED FROM THE CITY OF BURLINGTON ARCHIVES, DATE 1962

TITLE AND LOCATION

1962 AERIAL PHOTOGRAPH
PHASE ONE ESA
1026 COOKE BOULEVARD,
BURLINGTON, ONTARIO

PROJECT NO.	DWN.
BIGC-ENV-605A	T.S.
SCALE	CK.
NOT TO SCALE	E.L.
DATE	FIG NO.
JUNE 2023	H-2



B.I.G. CONSULTING INC.

t: (416) 214 - 4880 f: (416) 551 - 2633
12-5500 Tomken Rd.
Mississauga, ON L4W 2Z4
Canada

bigconsultinginc.com

LEGEND

SITE BOUNDARY

IMAGERY OBTAINED FROM THE CITY OF BURLINGTON ARCHIVES, DATE 1979

TITLE AND LOCATION

1979 AERIAL PHOTOGRAPH
PHASE ONE ESA
1026 COOKE BOULEVARD,
BURLINGTON, ONTARIO

PROJECT NO.	DWN.
BIGC-ENV-605A	T.S.
SCALE	CK.
NOT TO SCALE	E.L.
DATE	FIG NO.
JUNE 2023	H-3



B.I.G. CONSULTING INC.

t: (416) 214 - 4880 f: (416) 551 - 2633
12-5500 Tomken Rd.
Mississauga, ON L4W 2Z4
Canada

bigconsultinginc.com

LEGEND


SITE BOUNDARY

IMAGERY OBTAINED FROM THE CITY OF BURLINGTON ARCHIVES, DATE 1995

TITLE AND LOCATION

1995 AERIAL PHOTOGRAPH
PHASE ONE ESA
1026 COOKE BOULEVARD,
BURLINGTON, ONTARIO

PROJECT NO.	DWN.
BIGC-ENV-605A	T.S.
SCALE	CK.
NOT TO SCALE	E.L.
DATE	FIG NO.
JUNE 2023	H-4



B.I.G. CONSULTING INC.

t: (416) 214 - 4880 f: (416) 551 - 2633
12-5500 Tomken Rd.
Mississauga, ON L4W 2Z4
Canada

bigconsultinginc.com

LEGEND

SITE BOUNDARY


IMAGERY OBTAINED FROM GOOGLE EARTH, DATE 2004

TITLE AND LOCATION

2004 AERIAL PHOTOGRAPH

PHASE ONE ESA
1026 COOKE BOULEVARD,
BURLINGTON, ONTARIO

PROJECT NO.	DWN.
BIGC-ENV-605A	T.S.
SCALE	CK.
NOT TO SCALE	E.L.
DATE	FIG NO.
JUNE 2023	H-5



B.I.G. CONSULTING INC.

t: (416) 214 - 4880 f: (416) 551 - 2633
12-5500 Tomken Rd.
Mississauga, ON L4W 2Z4
Canada

bigconsultinginc.com

LEGEND

SITE BOUNDARY

IMAGERY OBTAINED FROM GOOGLE EARTH, DATE 2018

TITLE AND LOCATION

2018 AERIAL PHOTOGRAPH
PHASE ONE ESA
1026 COOKE BOULEVARD,
BURLINGTON, ONTARIO

PROJECT NO.	DWN.
BIGC-ENV-605A	T.S.
SCALE	CK.
NOT TO SCALE	E.L.
DATE	FIG NO.
JUNE 2023	H-6



opta
INFORMATION INTELLIGENCE

enviroscan







An SCM Company

175 Commerce Valley Drive W
Markham, Ontario L3T 7Z3

T: 905-882-6300
W: www.optaintel.ca

Report Completed By:

Midori

Site Address:

1026 Cooke Boulevard, Burlington, ON, Canada

Project No:

BIGCENV605A

Opta Order ID:

126541

Requested by:

Travis Van Holst
BIG Consulting Inc.

Date Completed:

4/19/2023 9:11:04 AM

Project Name: 1026 Cooke Boulevard


Project #: BIGCENV605A

ENVIROSCAN Report

Search Area: 1026 Cooke Boulevard, Burlington, ON, Canada

Requested by:
Travis Van Holst
Date Completed: 04/19/2023 09:11:04

enviroscan
OPTA INFORMATION INTELLIGENCE



This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

Opta Historical Environmental Services Enviroscan™ Terms and Conditions

Report

The documents (hereinafter referred to as the "Documents") to be released as part of the report (hereinafter referred to as the "Report") to be delivered to the purchaser as set out above are documents in Opta's records relating to the described property (hereinafter referred to as the "Property"). Opta makes no representations or warranties respecting the Documents whatsoever, including, without limitation, with respect to the completeness, accuracy or usefulness of the Documents, and does not represent or warrant that these are the only plans and reports prepared in association with the Property or in Opta's possession at the time of Report delivery to the purchaser. The Documents are current as of the date(s) indicated on them. Interpretation of the Documents, if any, is by inference based upon the information which is apparent and obvious on the face of the Documents only. Opta does not represent, warrant or guarantee that interpretations other than those referred to do not exist from other sources. The Report will be prepared for use by the purchaser of the services as shown above hereof only.

Disclaimer

Opta disclaims responsibility for any losses or damages of any kind whatsoever, whether consequential or other, however caused, incurred or suffered, arising directly or indirectly as a result of the services (which services include, but are not limited to, the preparation of the Report provided hereunder), including but not limited to, any losses or damages arising directly or indirectly from any breach of contract, fundamental or otherwise, from reliance on Opta Reports or from any tortious acts or omissions of Opta's agents, employees or representatives.

Entire Agreement

The parties hereto acknowledge and agree to be bound by the terms and conditions hereof. The request form constitutes the entire agreement between the parties pertaining to the subject matter hereof and supersedes all prior and contemporaneous agreements, negotiations and discussions, whether oral or written, and there are no representations or warranties, or other agreements between the parties in connection with the subject matter hereof except as specifically set forth herein. No supplement, modification, waiver, or termination of the request shall be binding, unless confirmed in writing by the parties hereto.

Governing Document

In the event of any conflicts or inconsistencies between the provisions hereof and the Reports, the rights and obligations of the parties shall be deemed to be governed by the request form, which shall be the paramount document.

Law

This agreement shall be governed by and construed in accordance with the laws of the Province of Ontario and the laws of Canada applicable therein.

ENVIROSCAN Report

Report Index

Requested by:
Travis Van Holst
Date Completed: 04/19/2023 09:11:04

OPTA INFORMATION INTELLIGENCE

Page	Report Title
6	(1971) Volume: Burlington Firemap: 9
8	(1971) Volume: Burlington Firemap: 10
10	(1971) Volume: Burlington Firemap: 11
12	(1971) Volume: Burlington Firemap: 11
13	(2006) Inspection Report - 2006 HALTON CONDO CORPORATION #416 1026 COOKE BL BURLINGTON ON L7T4A8 (distance = 104 metres*)

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



Project Name: 1026 Cooke Boulevard

Project #: BIGCENV605A

ENVIROSCAN Report


1971 Volume: Burlington Firemap: 9
Burlington Plan: 296 (1971)
Sheet: 9 (1971)

Requested by:
Travis Van Holst
Date Completed: 04/19/2023 09:11:04

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

FIP Locator Map
The detailed FIP is on the following page




ENVIROSCAN Report

1971 Volume: Burlington Firemap: 9
Burlington Plan: 296 (1971)
Sheet: 9 (1971)

Requested by:
Travis Van Holst
Date Completed: 04/19/2023 09:11:04

OPTA INFORMATION INTELLIGENCE



Project Name: 1026 Cooke Boulevard

Project #: BIGCENV605A

ENVIROSCAN Report


1971 Volume: Burlington Firemap: 10
Burlington Plan: 296 (1971)
Sheet: 10 (1971)

Requested by:
Travis Van Holst
Date Completed: 04/19/2023 09:11:04

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

FIP Locator Map
The detailed FIP is on the following page




ENVIROSCAN Report

1971 Volume: Burlington Firemap: 10
Burlington Plan: 296 (1971)
Sheet: 10 (1971)

Requested by:
Travis Van Holst
Date Completed: 04/19/2023 09:11:04

OPTA INFORMATION INTELLIGENCE



This plan is the property of the CANADIAN UNDERWRITERS' ASSOCIATION, unauthorized reproduction prohibited and is loaned on the following conditions: that the plan is to be kept in good order, that it is to be used only in connection with business of Companies, Members of the Canadian Underwriters' Association and is to be returned on request to the CANADIAN UNDERWRITERS' ASSOCIATION.

COPYRIGHT REGISTERED AT OTTAWA
BY THE
CANADIAN UNDERWRITERS' ASSOCIATION


ENVIROSCAN Report

1971 Volume: Burlington Firemap: 11
Burlington Plan: 296 (1971)
Sheet: 11 (1971)

Requested by:
Travis Van Holst
Date Completed: 04/19/2023 09:11:04

enviroscan
OPTA INFORMATION INTELLIGENCE

FIP Locator Map
The detailed FIP is on the following page




This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

ENVIROSCAN Report

1971 Volume: Burlington Firemap: 11
Burlington Plan: 296 (1971)
Sheet: 11 (1971)

Requested by:
Travis Van Holst
Date Completed: 04/19/2023 09:11:04

OPTA INFORMATION INTELLIGENCE



ENVIROSCAN Report


1971 Volume: Burlington Firemap: 11
Burlington Plan: 296 (1971)
Sheet: 11 (1971)

Requested by:
Travis Van Holst
Date Completed: 04/19/2023 09:11:04

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

FIP Locator Map
The detailed FIP is on the following page




ENVIROSCAN Report

1971 Volume: Burlington Firemap: 11
Burlington Plan: 296 (1971)
Sheet: 11 (1971)

Requested by:
Travis Van Holst
Date Completed: 04/19/2023 09:11:04

OPTA INFORMATION INTELLIGENCE



Inspection Report - 2006 HALTON CONDO CORPORATION #416 1026 COOKE BL BURLINGTON ON L7T4A8

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



CGI All Risk
INSPECTION REPORT

Supplement/s attached: ☐ Yes # of : ☒ No

1.0 BASIC INFORMATION

Insured:	Halton condo Corporation #416	**Policy Number**	
Date of survey (YYYY/MM/DD):	2006/03/22	**CGI Loss Control Specialist:**	Ian Morris
Person Contacted: Position	Bryan C Schimacher - Condo President	**Telephone No.**	(905) 681 9679
Mailing Address if Different for risk:	(unit # street # & name)	(City, Town, Village)	**CGI AIS No.: 72577356 Tracking No.: 5609981**
Location Surveyed:	1026 Cooke Blvd (unit # street # & name)	Burlington (City, Town, Village)	Ontario (Province) L7T 4A8 (postal code)
Secondary address (If any)	(unit # street # & name)	(City, Town, Village)	(Province) (postal code)
IBC Territory Code	91	**IBC Building Ind. Code: 7417**	**SR/MA File No.**
Underwriter:		**Broker:**	

The ***CGI Risk Score*** and comments contained in this report are based on conditions and practices observed during our survey and other pertinent data supplied by management personnel at the risk.

Recommendations in this report are made to point out those areas where remedial action could have the beneficial effect of making the above premises safer and thus more desirable from an underwriting standpoint.

Thank you for choosing CGI to perform this inspection. Please do not hesitate to contact us if we can be of any further assistance.

2.0 *CGI Risk Score*

	1	2	3	4	5	6	7	8	9
Property	☐	☒	☐	☐	☐	☐	☐	☐	☐
Liability	☐	☒	☐	☐	☐	☐	☐	☐	☐
Crime	☐	☐	☒	☐	☐	☐	☐	☐	☐

(1=Excellent & 9=Poor)

Comments

The building appears structurally sound and in good condition. It receives regular care and maintenance and building services are in good working order.

General Liability issues appeared safe with no unusual features or hazards noted.

This risk is not deemed to be a target for career criminals. Both the security alarm systems and the physical security appear appropriate for the occupancies.

RISK ALERT ISSUED: ☐ **Yes** ☒ **No** **IF YES, DESCRIBE** (*A risk alert is a telephone notification to the Inspection requestor, of a situation which could imminently cause a serious loss. A Critical Recommendation will be issued to address the situation.)*

Committed to Service Excellence

CGI reports, prepared in compliance with commonly accepted risk control standards existing at the time services are rendered, are developed from an inspection of the premises and/or from data supplied by or on behalf of the Purchaser. CGI does not purport to list all hazards. While changes and modifications referred to in the reports are designed to upgrade protection and loss prevention of the premises, CGI assumes no responsibility for management and control of these activities. CGI will not be responsible to the Purchaser for any losses or damages, whether consequential or other, however caused, incurred of suffered, as a result of the services being provided.

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

Meaning of the CGI Risk **•Score:** The CGI Score is a grading of the risk inspected versus other risks in this class. Similar to the "Commercial" Fire Protection Grading system in design, there is range of 9 categories, with a grading or "score" of 1 being the most desirable. The CGI Score is based on a number of objective criteria pertaining to the risk at the time of our survey, tempered with the experienced judgement of our Loss Control Specialist. As a general guideline, the scores mean the following criteria:

1-3	Risks in this range are well maintained, with no apparent moral hazards or management problems. Undesirable features are non-existent and recommendations, if any, are desirable. Risks in this category are excellent (no deficiencies) to better than average for their class.
4-6	The maintenance of Risks in this range is considered average. Moral hazards are not apparent, but there may be possible management problems (e.g. poor housekeeping). Undesirable features noted are correctable, and recommendations will vary from desirable to important. Risks in this category are considered average for their class.
7-9	Risks in this range tend to be poorly maintained. Moral hazards and management problems (e.g. poor housekeeping and maintenance, poor attitude) are evident. Significant undesirable conditions are present and cannot or will not be corrected. Critical Recommendations may be present. Risks in this category are significantly below average for their class with little or no indication for improvement.

3.0 REMARKS

This non sprinklered risk is comprised of 5 units, 2 of which are owned by the same person (the contact), and 1 which is vacant. Units #1 & #2 are open to each other. It is situated north of Plains Line, and west of King Road in Burlington, in a modern commercial and light industrial area.

The contact was prompt in keeping the appointment and was cooperative and friendly throughout.

Unit interiors were too small to allow a good interior photo.

4.0 RECOMMENDATIONS

Please note that these recommendations are classified as either ☐ **Critical,** ☐ **Important, or** ☐ **Desirable Improvement**. **"Critical"** recommendations are those aimed at correcting undesirable feature/s which, if left unattended, could cause a serious loss and should be rectified immediately. This class of recommendation is only used in extreme situations. **"Important"** recommendations are intended to highlight undesirable feature/s which if left unattended, could cause a serious loss and should be rectified as soon as possible. **"Desirable Improvement"** recommendations are those aimed at correcting an undesirable feature which can be improved when feasible, to help reduce the risk of a loss.

☒ Listed below	or	☐ None

2006-1 ☐ Critical ☒ Important ☐ Desirable Improvement

In unit #5 Controtech Automation and Unit #4 Vacant but with equipment being moved in, 2 class 2A10BC portable fire extinguishers, with ULC or equivalent labelling should be wall mounted in easily visible, readily accessable locations, 1 at the front and 1 at the rear of the unit, in compliance with NFPA #10 code standard requirements. Similarly, Unit #1, #2 and unit #5 should have a portable fire extinguisher located on the mezzanine.

2006-2 ☐ Critical ☒ Important ☐ Desirable Improvement

Sliptreads or other similar traction devices should be installed on the wooden stairs to the mezzanine in unit #5 Controtech Automation, order to reduce exposure to slip, trip and fall hazards.

2006-3 ☐ Critical ☒ Important ☐ Desirable Improvement

All portable fire extinguishers in units #1 & #2 should be serviced and tagged on an annual basis, by an authorized serviced contractor, to ensure good working order in compliance with N.F.P.A. # 10 Code standard requirements.

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

2006-4 ☐ Critical ☐ Important ☐ Desirable Improvement	

2006-5 ☐ Critical ☐ Important ☐ Desirable Improvement	

5.0 OCCUPANCY INFORMATION

The Insured is:	☒ Owner Occupant	☐ Non-occupant building owner	☐ Tenant
Insured's Occupancy Description: Industrial Condominium Owners Corporation			
IBC Code: 7417	IBC Subcode: 00	Premises Intrusion Alarm: --	
Special Hazard Code(s): 0		Description:	
Special Hazard Code(s): 0		Description:	
Name of building owner(if not Insured):	Insured		Number of years bldg. Owned: 4
Number of years at this location:4	Area occupied (sq. m): 1263		Business hours:
Days per week: --	Annual Revenue (optional):		Payroll (optional):
Previous loss history past 3 years ☐ Yes ☒ No ☐ Undetermined		Previous loss history past 6 years ☐ Yes ☒ No ☐ Undetermined	
Explain loss history: None			
Insured Values: Property: $1,100,000		Contents: $N/A	
Combustibility of Occupancy: M3		Susceptibility of Occupancy: S3-Moderate Damage	

Occupancy: **Major Tenant is:** ☐ Insured or ☒ See Major Tenant Below			☐ refer to Occupancy Specific Supplement
Major Tenant in Building	Combustibility Code: M3		Susceptibility Code: S3-Moderate Damage
Name: Unit #3 - Deluca Roofing		Area occupied (sq.m): 253	IBC Code: 7417
Occupancy Description: Storage of materials for a roofing contractor. Shingles, patent coverings, tarps, tools, spreaders, and associated equipment are safely stored on metal racks around the perimeter of the unit. Aisles are designated by yellow paint lines on the floor. Occasionally company vehicles are stored overnight. 3 persons are emp loyed and all work is carried out off-site. Housekeeping is good throughout.			IBC Sub Code:
Special Hazard Code(s): 0		Description:	
Special Hazard Code(s): 0		Description:	
Previous loss history past 3 years ☐ Yes ☒ No ☐ Undetermined		Previous loss history past 6 years ☐ Yes ☒ No ☐ Undetermined	
Number of years at this location: 4		Premises Intrusion Alarm: Acceptable	
Other Classes of Occupants			
DESCRIBE PARTITION WALLS BETWEEN TENANTS: Blank concrete block			
Name: Unit #1 - D. Designs.		Area occupied (sq.m): 253	IBC Code: 5190
Occupancy Description: 2 staff work setting up embroidery machines for use on tee shirts, baseball hats and other custom wear. The machines are new and in very good condition and are safely arranged. No deficiencies were noted and housekeeping is excellent.			IBC Sub Code: 00
Special Hazard Code(s): 0		Description:	
Special Hazard Code(s): 0		Description:	

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

Previous loss history past 3 years ☐ Yes ☒ No ☐ Undetermined	Previous loss history past 6 years ☐ Yes ☒ No ☐ Undetermined	
Number of years at this location: 4	Premises Intrusion Alarm: Acceptable	
Name: Unit #2 - Megabrock Holdings Inc	Area occupied (sq.m): 253	IBC Code: 6610
Occupancy Description: Office occupancy for an investment holding company. Offices at the front with an open warehouse to the rear containng stock for the embroidery business in Unit #1. At time of inspection a Greyhound type bus was stored, and the contact stated this was a one-time instance for a few days. Housekeeping is excellent throughout.		IBC Sub Code: 00
Special Hazard Code(s): 0	Description:	
Special Hazard Code(s): 0	Description:	
Previous loss history past 3 years ☐ Yes ☒ No ☐ Undetermined	Previous loss history past 6 years ☐ Yes ☒ No ☐ Undetermined	
Number of years at this location: 4	Premises Intrusion Alarm: Acceptable	
Areas not surveyed:	☒ For additional tenants see attached list	
Comments: No unusual hazards associated with this type of occupancy.		

6.0 BUILDING CONSTRUCTION (IBC Major Construction Class 2)

Building condition:	☐ Above Average	☒ Average	☐ Moderate deficiencies	☐ Major deficiencies	
Year built: (yyyy)	2002	Area occupied by insured (sq. m): 1263		Combustibility of Building M3	
Ground floor area (sq. m):	1263 sq. m	Total floor area (excl. bsmt.)		1263 sq. m	
Height (excluding basement):	3.6 & 5.5 m	Number of Stories: 1 (above grade)			
Basement: ☐ Yes ☒ No		Area of basement: 0 (sq. m)		Total area: 1263 sq. m	
Additions (year & brief description):	None				
Renovations (year & brief description):	None				
Wall construction:	Reinforced Concrete % ( )	Masonry: 100%: (Concrete Block)	Non Combustible: %: ( )	Brick/stone veneer: %: ( )	Wood frame: %: ( )
	Other: %, Describe:				
	Insulation:				
	Panels in Walls: Glass: %	Combustible: %	Non Combustible: %		
Floor Construction:	Concrete: 100%	Concrete on metal pan: %	Wood joist: %		
	Other: %, Describe:				
Roof Type:	☒ Flat	☐ Quonset	☐ Peaked	☐ Other:	
Roof Construction:	☐ Concrete: %	☒ Steel deck: 100%	☐ Wood joist: %	☐ Steel/Steel: %	
	☐ Other Combustible: %		☐ Other Non Combustible: %		
Roof Surface:	☒ Tar & Gravel: 100%	☐ Metal: %	☐ Asphalt Shingles: %	☐ Wood Shakes: %	
	☐ Rubber membrane: %	☐ Other Combustible: %	☐ Other Non Combustible: %		
Resurfaced:	☒ No	☐ Yes	Date:		
Interior Finish Walls:	Combustible:	Ordinary Damage Material: %	Special Damage Material: %		
	Non Combustible: 30%		Open: 70%		
Interior Finish Ceilings:	Combustible:	Ordinary Damage Material: %	Special Damage Material: %		
	Non Combustible: 30%		Open: 70%		

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

Vertical Openings:	☐ None	☒ Stairs:	Protection Type: walls-0hr, doors-0hr hrly. rate	☐ Elevator:	Protected: ☐ Yes ☐ No
	☐ Escalator: ☐ Open ☐ Enclosed	☐ Atrium:	% of Grade Floor	# of Floors:	
	☐ Other:				
Horizontal Separation:	Major Partition Construction:	☐ Not Applicable	☐ Frame	☐ Drywall on Studs	
		☒ Concrete Block		☐ Other:	
	Proper Opening Protection:	☒ Yes	☐ No	☐ Not Applicable	
Mezzanines: ☐ No ☒ Yes	Combustible: 100%	Non Combustible: %			
	Mezzanines Percentage of Floor below: 8 % (if over 25% treated as an additional floor)				
Combustible Concealed Spaces:	☒ No	☐ Yes	If yes, %, and describe:		
Concealed space properly protected:	☐ No	☐ Yes	☒ Not applicable	Comment:	
Building Description:	Shopping Mall: ☐ Yes ☒ No	Industrial Mall: ☐ Yes ☒ No	Strip Mall: ☐ Yes ☒ No		
	Stand Alone: ☒ Yes ☐ No	Other, Describe:			
Building Construction Comments: General repairs made as needed on an ongoing basis.					

7.0 FIRE EXPOSURES (Within 50m of risk) ☐ None

Exposing Structures Within 50m:

	Distance	Height	Construction of Exposure Facing Wall	Exposure Occupancy Hazard	Exposure Hazard Description	Exposure Comb. Code	Opening in Facing Wall of Risk Yes	No
Front	*Open* m	_____ sto.	--	--		--	☐	☐
Rear	*29* m	*1* sto.	Combustible	Light (L1,L2)	Dwelling	L2	☒	☐
Left	*Open* m	_____ sto.	--	--		--	☐	☐
Right	*36* m	*1* sto.	Masonry	Medium (M3,M4)	Multi tenant commercial	M3	☒	☐

Exposing Structure Addresses:

Front:	*N/A*	Left:	*N/A*
Rear:	*Unknown*	Right:	*1038 Cooke*
Comments: _____			

8.0 COMMON HAZARDS (Heating, electrical, plumbing)

HEATING:

Forced warm air:	☐ Electric %	☒ Gas 30%	☐ Oil %	Solid Fuel %	Other: *HVAC*
Suspended unit heaters:	☐ Electric %	☒ Gas 70%	☐ Oil %		Other: _____
Portable heaters:	☐ Electric %	☐ Gas %	☐ Oil %	Solid Fuel %	Other: _____
Hot water/steam	☐ Electric %	☐ Gas %	☐ Oil %	Solid Fuel %	Other: _____
Solid Fuel Burning:	Non-Hazardous: %, Describe _____		Hazardous: %, Describe _____		
Other Hazardous:	%	Describe _____			
Other Non-Hazardous:	%	Describe _____			
Electric baseboard units:	☐ %				
Installation Appears Safe:	☒ Yes	☐ No	Describe: _____		
Unheated	☐ %	Borrowed Heat: ☐ %			
Boiler: ☐ Yes ☒ No	Age: _____ and Make: _____		Date of last Boiler Inspection: (yyyy/mm/dd) _____		
Appliances enclosed in a non-combustible room:	☐ Yes	☐ No	☒ Not required		
Combustible materials stored in the room:	☐ Yes	☐ No	☒ Not applicable		

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

Heating Fuel Tanks:	☒ None	☐ Inside	☐ Outside	☐ Above ground	☐ Below ground	Age (yyyy) _____ Capacity (L) _____
Fill and vent piping: Inside	☒ N/A	☐ No	☐ Yes, _____			
Chimneys:	☐ Masonry	☐ ULC Factory built	☐ Unlabelled pre-fab	☒ Other: *Direct Vent & Type "B" gas vents*		
	☒ Standard	☐ Non-standard _____				
Installation defects:	☒ None	☐ Moderate	☐ Major, _____			
Installation replaced:	☒ No	☐ Yes	(yyyy) _____ and _____%			
30% Air Conditioned	Type:	☒ Roof-Top	☐ Central	☐ Other: _____		
Comments: *Standard equipment which appears in good working order.*						

ELECTRICAL:

Type:	☒ Conduit	☒ BX	☐ Non-metallic	☐ Knob & Tube _____	☐ Other: _____
Temporary wiring or extension cords:	☒ No	☐ Yes _____			
Overcurrent protection:	☒ Circuit Breakers	Fuses:	☐ Ordinary	☐ Type P	☐ Type D ☐ Other: _____
Installation defects:	☒ None	☐ Moderate	☐ Major		
Installation (wiring) replaced:	☒ No	☐ Yes	(yyyy)_____ and _____%		
Installation Appears Safe:	☒ Yes	☐ No	Describe: _____		
Partial changes/extensions:	☒ No	☐ Yes	Describe: _____		
Comments: *Unobstructed access to main electrical area. 1m clearance zone maintained around main electrical switching area.*					

PLUMBING:

Type:	☒ Copper	☐ Galvanized	☒ Plastic	☐ Other: _____
Installation Replaced:	☒ No	☐ Yes	(yyyy) _____ and _____%	
Condition:	☒ Good	☐ Fair	☐ Poor _____	
Installation appears safe:	☒ Yes	☐ No: _____		
Comments: *All visible piping is in good condition with no signs of corrosion or leaking.*				

SMOKING:

Smoking Restricted:	☒ Yes	☐ No			
"No Smoking" Signs posted:	☐ Yes	☒ No	Enforced:	☒ Yes	☐ No
Comments: *No smoking within the building.*					

HOUSEKEEPING:

☒ Good	☐ Average	☐ Poor	☐ Unacceptable
Comments: *Lighting is in good condition, and aisles are unobstructed. Appropriate cleanliness for this type of occupancy.*			

9.0 FIRE PROTECTION

PUBLIC:

F.U.S. Protection Class: 3	Primary Responding Fire Department: *Burlington*			Bldg. Prot. Code (NS or AS): 2
☒ Full time	☐ Part Time/Volunteer			☐ Composite
Distance to Fire Department:	2 km			
Roads: ☒ Paved ☐ Unpaved	Accessible Year-round: ☒ Yes ☐ No			Congested/Inaccessible: ☐ Yes ☒ No
Water Supply:	☒ Public	☐ Private		
Number of Hydrants:	2 within 155 m,	_____ within 156 - 305 m,	_____ Over 305 m,	☐ None

PRIVATE:

The following appeared to be satisfactory:

	Yes	No		Date Last Serviced	Comments

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

Portable Extinguishers	☐	☒		_____	*See Recs.*
Standpipe/Inside Hoses	☐	☐	N/A ☒	_____	_____
Watchman Service	☐	☐	N/A ☒	_____	_____
Fire Detection System:	☒ None	☐ Full	☐ Partial, Describe:	_____	
i) Type of Detectors:	_____				
ii) Detector location:	Describe: _____				
iii) Maintenance contract:	Yes ☐	No ☐	Company: _____	Telephone #: _____	
iv) Connected to:	☐ ULC Listed Station	☐ Unlisted Service	☐ Fire/Police Department	☐ Local only	
	☐ Other: _____				
Name of Company:	_____				
Automatic Sprinkler Protection:	☒ None	☐ Full Premises	☐ Partial (describe): _____		
	Sprinkler Supplement Attached	☐ Yes	☒ No (Sprinkler System Not Tested or Evaluated)		
Fire Protection Comments: _____					

10.0 ALL RISK:

Information Confirmed by: ☒ Person Contacted or: _____

EARTHQUAKE

What is the earthquake zone:	0		
Is there any earthquake history in the area:	☒ No	☐ Yes	☐ Undetermined
If **Yes**, describe history _____			
Significant exterior wall or foundation cracks noted?	☒ No	☐ Yes	Describe: _____
Sagging?	☒ No	☐ Yes	Describe: _____
Comments: _____			

FLOOD

Is this establishment located on a flood plain:	☒ No	☐ Yes	
Is it located near a body of water:	☒ No	☐ Yes	Describe: _____
Distance to nearest body of water:	_____	☒ None determined	
Is there a history of flooding:	☒ No	☐ Yes	If **yes**, give history: _____
Evidence of water damage:	☒ No	☐ Yes	Describe: _____
Years knowledge of risk: 4			
Comments: The contact is not aware of any flood history in this local neighborhood.			

WATER DAMAGE

Plumbing is:	☒ Copper	☐ Galvanized	☒ Plastic	☐ Other	Describe: _____
Is there evidence of corrosion:			☒ No	☐ Yes	Describe: _____
Is the building sprinklered:			☒ No	☐ Yes	Comment: _____
Is stock susceptible to water damage:			☐ No	☐ Yes	Describe: *N/A*

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

Are all window/skylight openings adequately sealed:	☒ Yes	☐ No	Describe: _____
Does water main pass under building:	☒ No	☐ Yes	Describe: _____
Is the roof covering adequate:	☒ Yes	☐ No	Most recent roof repair date: _____
Inside and/or roof storage tanks/process equipment:	☒ No	☐ Yes	Describe: _____
Tanks/equipment satisfactorily controlled:	☐ No	☐ Yes	If Either Describe: *N/A*
Is there use of: ☒ Skids ☒ Shelving	☐ Floor Drains		☐ Covers over stock/equipment
Sewer Backup claim in the last three years:	☒ No	☐ Yes	☐ Describe: _____
Comments: No unusual water damage hazards present			

COLLAPSE AND/OR SEWER BACKUP

Is there any history of collapse:	☒ No	☐ Yes	Describe: _____
Is there any history of sewer back-up:	☒ No	☐ Yes	Describe: _____
Are sewer back-up protection devices in place:	☒ No	☐ Yes	Describe: _____
Comments: _____			

ADDITIONAL PERILS

If Yes, Describe:

Is lightning protection in place:		☐ No	☒ Yes	Describe: *Normal electrical grounding through the circuit breaker panel.*		
Is risk located within 5 km of airport:		☒ No	☐ Yes	Beneath a flight path:	☐ Yes	☒ No
Is the yard fenced:	☒ No	☐ Yes	Are gates locked when the premises are closed:		☐ Yes	☐ No
Is the yard and the exterior of the building lit:		☐ No	☒ Yes	Describe: Wall mounted lights		
Is the risk located in a high wind/hail area:		☒ No	☐ Yes	Describe: _____		
Are there visible signs of vandalism at the risk:		☒ No	☐ Yes	Describe: _____		
In the area:		☒ No	☐ Yes	Describe: _____		
Is the risk protected from Impact exposure:	Automobile	☐ No	☒ Yes	Describe: By sidewalk		
	Aircraft	☒ No	☐ Yes	Describe: _____		
	Train	☒ No	☐ Yes	Describe: _____		
	Boat	☒ No	☐ Yes	Describe: _____		
Comments: **AP perils appear normal.**						

11.0 BASIC PREMISES LIABILITY

The following appeared to be satisfactory: If No Describe		
Stairs, Ramps & Handrails:	Yes ☒ No ☐ N/A ☐	Comments: *To mezzanines*
Floor Surfaces & Coverings:	Yes ☒ No ☐ N/A ☐	Comments: *Standard materials in safe condition*
Walls & Ceilings:	Yes ☒ No ☐ N/A ☐	Comments: *No deficiencies noted.*
Interior & Exterior Lighting:	Yes ☒ No ☐ N/A ☐	Comments: *Bright and even illumination.*
Emergency Lighting:	Yes ☒ No ☐ N/A ☐	Comments: _____
Interior & Exterior Housekeeping:	Yes ☒ No ☐ N/A ☐	Comments: *Good housekeeping..*
Washrooms:	Yes ☒ No ☐ N/A ☐	Comments: *In good working order.*
Sidewalks, Yards & Parking Lots:	Yes ☒ No ☐ N/A ☐	Comments: *Ingood condition*

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

Fire Exits:	Yes ☒	No ☐	N/A ☐	Comments: *Adequate number, placement and width.*
Fire Alarm System (s):	Yes ☐	No ☐	N/A ☒	Comments: _____
Snow & Ice Removal:	Yes ☒	No ☐	N/A ☐	Comments: *By contractor Copy of Liability insurance on file*
Elevating devices:	Yes ☐	No ☐	N/A ☒	Comments: _____
Satellite Dishes:	Yes ☐	No ☐	N/A ☒	Comments: *None*
Exterior Signs:	Yes ☒	No ☐	N/A ☐	Comments: *Secure and in good condition.*
CO detectors where required:	Yes ☐	No ☐	N/A ☒	Comments: _____
Swimming Pool:	Yes ☐	No ☐	N/A ☒	Comments: _____
Other:	Yes ☐	No ☐	N/A ☒	Comments: _____
Comments: *No unusual concerns regarding Basic Premises Liability.*				

12.0 BASIC CRIME

☐ Refer to Expanded Crime Supplement

Crime Experience	☒ Low	☐ Moderate	☐ High		
Type of Neighbourhood:	☒ Commercial	☐ Industrial	☐ Rural	☐ Residential	☐ Isolated
Neighbourhood appears to be:	☒ Stable	Changing via:	☐ Expansion/growth	☐ Renovation	☐ Deterioration
Comments: *Steady volume of traffic during the daytime.*					

BUSINESS

Automatic Teller Machine:	☒ No	☐ Yes		
Safe on Premises:	☒ No	☐ Yes	☐ Unable to Determine	
Guard Service:	☒ No	☐ Yes	☐ Unable to Determine	Describe: _____
Typical Stock:	N/A			
Smash & Grab exposure:	☒ No	☐ Yes	☐ Unable to Determine	
Comments: _____				

GENERAL PROTECTION

The following appeared to be satisfactory: If No Describe

Exterior Lighting:	☒ Yes	☐ No	☐ N/A	Comments: _____
Interior Lighting:	☒ Yes	☐ No	☐ N/A	Comments: _____
Roof Accessibility:	☒ Yes	☐ No	☐ N/A	Comments: _____
Police Patrols:	☐ Yes	☐ No	☒ N/A	Comments: _____
Yard Fenced:	☐ Yes	☐ No	☒ N/A	Describe: _____
Comments: GP appears standard.				

SECURITY ALARM SYSTEM

Premises alarm system in use:	☐ N/A	☒ Yes	☐ No	☐ Disconnected	Date Installed: (yyyy)2002
Applies to:	☒ Building	☐ Insured Tenant	☐ Other, Describe: _____		
Alarm System is:	☒ Acceptable	☐ Unacceptable (see rec.)			
Monitored by:	☐ ULC Listed Station	☒ Unlisted Station	☐ Local Alarm	☐ Unknown	☐ Unable to Determine
Comments: Each unit has an acceptable security alarm system.					

PHYSICAL PROTECTION

Door locks:	☒ Deadbolt	☐ Spring	☒ Panic	☒ Other: *Interior padlocks*
Windows Protected:	☒ No	☐ Yes	☐ N/A	If **yes**, describe _____

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

Other Openings:	☒ No	☐ Yes	Protected:	☐ No	☐ Yes
Comments: _____					

OTHER COMMENTS:

_____

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

APPENDIX I: SITE PHOTOGRAPHS



Photo 1: Frontage of the Site Building, facing southwest.



Photo 2: Exterior of the Site Building, facing south.



Photo 3: Interior of Unit 1 of the Site Building.




Photo 4: Interior of Unit 2 of the Site Building.



Photo 5: Interior of Unit 3 of the Site Building.



Photo 6: Interior of Unit 4 of the Site Building.



Photo 7: Interior of Unit 5 of the Site Building.



Photo 8: A non-PCB liquid transformer located in the eastern portion of the Site.



Photo 9: The property located at 1038 Cooke Boulevard, north adjacent, facing northwest.



Photo 10: Industrial properties northwest of the Site, facing southwest.



Photo 11: Residential property located at 1117 Masonry Court, north of the site, facing north.



Photo 12: Residential properties west of the Site, facing southeast.



Photo 13: Jerry's Automotive located at 7 Plains Road West, approximately 90 m south of the Site.



Photo 14: Esso gas station located at 14 Plains Road East, approximately 100 m southeast of the Site.



Photo 15: Residential properties south of the Site, facing east.



Photo 16: Commercial and residential properties east of the Site, facing north.